
Title List of Documents Made Publicly Available

February 1-28, 1983

Office of Administration
U.S. Nuclear Regulatory Commission

RETURN TO GOV. DOCS. CLERK



Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

February 1-28, 1983

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Numberix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	397
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71	405
Licensing of Independent Spent Fuel Storage — Docket 72	409
Nondocketed Items	
10 CFR — Commission Meeting Records	411
ACRS — Advisory Committee on Reactor Safeguards	411
COMMISSION — NRC Commissioners	412
CONTRACT — NRC Contracts and Modifications	413
FOIA — Freedom of Information Act Requests and Releases	420
GEN TECH IS — Generic Technical Issues	427
I&E — Inspection and Enforcement	428
MISC — Public Document Room Miscellaneous	428
NUREG — NUREG Reports and Related Correspondence	429
ORG — Correspondence with Other Organizations	432
PR — Proposed Rule	432
PRM — Petition for Rulemaking	436
PROJ — Projects - Predocket Licensing	438
PT 21 — Noncompliance Reports and Related Correspondence	438
QA999 — Quality Assurance Inspections	438
REGGD — Regulatory Guides	442
RES — Research and Technical Assistance Reports	442
REVIEW GROUP — NRC Research Review Groups	443
SECY — Position Papers Before the Commission	444
STATE PROG — State Programs	444
TOPREP — Vendor Reports and Related Correspondence	446
WASTE MGT — Nuclear Waste Management	448
XPORTLIC — Export and Import Licenses	450
Personal Author Index	455
Corporate Source Index	485
Report Number Index	519
Cross Reference of Enclosures to Principal Documents	521
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

- ① P. Operating license stage documents & correspondence
- ② 8203090028 ③ Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
- ④ MILLS, L.M. ⑤ Tennessee Valley Authority. ⑥ 82/03/04. ⑦ VASSALLO, D.B. Operating Reactors Branch 2. ⑧ 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.
- ⑨ ⑩ ⑪ ⑫

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

- 10CFR — Commission Meeting Records
- ACRS — Advisory Committee on Reactor Safeguards
- COMMISSION — NRC Commissioners
- CONTRACT — NRC Contracts and Modifications
- DISCLOSURE — Financial Disclosure Information
- FOIA — Freedom of Information Act Requests and Releases
- GEN TECH IS — Generic Technical Issues

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

① NUREG—NUREG Reports and Related Correspondence

② 8203090207

③ NUREG/CR-1672 V02

④ { RISK ASSESSMENT METHODOLOGY DEVELOPMENT FOR WASTE ISOLATION
IN GEOLOGIC MEDIA. Technical Review of Documents
NUREG/CR-1262, NUREG/CR-1376, NUREG/CR-1377, NUREG/CR-1397 &
NUREG/CR-1608.

⑤ STEVENS, C.A., FULLWOOD, R.A., BASIN, S.L. Science Applications, Inc.

⑥ FIN B-6694. SAI-262-81-PA. 82/02/28. Division of Risk Analysis.

⑦ 123 p. Available at NRC. \$6.00. 12176:217.

⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮

- vii

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27			40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	
27-039	Sheffield, IL, U S Ecology, Inc	1	40-8675	Energy Fuels Nuclear, Inc , Denver, CO	
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc	1	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	
27-048	Richland, WA, U S Ecology, Inc	1	40-8693	Ogle Petroleum, Inc., Santa Barbara, CA	
Domestic Licensing of Source Material — Docket 40			40-8697	Rocky Mountain Energy Co., Denver, CO	
40-0017	Dow Chemical Co , Midland, MI	1	40-8698	Plateau Resources, Ltd , Grand Junction, CO	
40-0086	W R Grace & Co , Pompton Plains, NJ	2	40-8709	Westinghouse Electric Corp , Ogden, UT	
40-0215	S. F. Appliance, Ltd., Morris, IL	2	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	
40-0299	Union Carbide Corp , Grand Junction, CO	2	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8743	Conoco, Inc , Denver, CO	
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8745	Ogle Petroleum, Inc., Casper, WY	
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2	40-8768	Kerr-McGee Nuclear Corp , Oklahoma City, OK	
40-2259	Pathfinder Mines Corp , Riverton, WY	3	40-8779	Army, Dept of, Tooele, UT	
40-3149	Fenton Art Glass Co , Williamstown, WV	3	40-8783	Uranerz USA, Inc., Casper, WY	
40-3453	Atlas Mineral, Inc , Denver, CO	3	40-8786	Uranium Resources, Inc., Richardson, TX	
40-4492	Federal-American Partners, Riverton, WY	3	40-8787	Michigan, Univ of, Ann Arbor, MI	
40-5738	Virginia, Univ of, Charlottesville, VA	3	40-8792	Edison Institute, Dearborn, MI	
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	3	40-8798	Hitchcock Industries, Inc., Minneapolis, MN	
40-7455	Whittaker Metals, Los Angeles, CA	3	40-8799	Udylite/Sel-Rex, Warren, MI	
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	3	40-8822	Omaha Public Power District, Omaha, NE	
40-8064	Exxon Minerals Co. USA, Houston, TX	3	40-8829	Wyoming Fuel Co , Lakewood, CO	
40-8084	Rio Algom Corp , Moab, UT	4	Domestic Licensing of Production and Utilization Facilities — Docket 50		
40-8102	Exxon Co. USA, Houston, TX	4	50-2	Univ of Michigan Research Reactor	
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-3	Indian Point Station, Unit 1	
40-8452	Bear Creek Uranium Co , Casper, WY	4	50-5	Pennsylvania State Univ, Research Reactor	
40-8483	Day & Zimmerman, Inc , Parsons, KS	4	50-10	Dresden Nuclear Power Station, Unit 1	
40-8502	Wyoming Mineral Corp., Lakewood, CO	4	50-29	Yankee-Rowe Nuclear Power Station	
40-8584	Minerals Exploration Co., Los Angeles, CA	4	50-54	Union Carbide Research Reactor	
40-8626	Moraine Valley Community College, Palos Hills, IL	5	50-67	McMaster Univ Research Reactor	

Docket	Name	Page	Docket	Name	Page
50-70	General Electric Test Reactor	12	50-250	Turkey Point Plant, Unit 3	50
50-72	Univ. of Utah Research Reactor	12	50-251	Turkey Point Plant, Unit 4	52
50-73	General Electric Nuclear Test Reactor	12	50-254	Quad-Cities Station, Unit 1	54
50-89	General Atomic Co.	12	50-255	Palisades Nuclear Plant	57
50-111	North Carolina State Univ. Research Reactor	12	50-259	Browns Ferry Nuclear Power Station, Unit 1	59
50-112	Univ. of Oklahoma Research Reactor	12	50-260	Browns Ferry Nuclear Power Station, Unit 2	62
50-113	Univ. of Arizona Research Reactor	12	50-261	H. B. Robinson Plant, Unit 2	65
50-124	Virginia Polytech Institute Training Reactor	12	50-263	Monticello Nuclear Generating Plant	68
50-128	Texas A&M Univ. Research Reactor	13	50-264	Dow Chemical Co.	70
50-131	Omaha Veterans Administration Hospital Research Reactor	13	50-265	Quad-Cities Station, Unit 2	70
50-133	Humboldt Bay Power Plant, Unit 3	14	50-266	Point Beach Nuclear Plant, Unit 1	73
50-139	Univ. of Washington Research Reactor	14	50-267	Fort St. Vrain Nuclear Generating Station	74
50-142	UCLA Training Reactor	14	50-269	Oconee Nuclear Station, Unit 1	78
50-155	Big Rock Point Nuclear Plant	16	50-270	Oconee Nuclear Station, Unit 2	80
50-156	Univ. of Wisconsin Research Reactor	20	50-271	Vermont Yankee Nuclear Power Station	83
50-160	Georgia Institute of Technology Research Reactor	20	50-272	Salem Nuclear Generating Station, Unit 1	85
50-163	General Atomic Co.	20	50-274	U.S. Geological Survey Research Reactor	87
50-170	National Naval Medical Center	20	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	87
50-186	Univ. of Missouri Research Reactor	21	50-277	Peach Bottom Atomic Power Station, Unit 2	91
50-187	Space Radiation Research Reactor	21	50-278	Peach Bottom Atomic Power Station, Unit 3	93
50-192	Univ. of Texas Research Reactor	21	50-280	Surry Power Station, Unit 1	96
50-193	Rhode Island & Providence Plantations, AEC	21	50-281	Surry Power Station, Unit 2	98
50-201	West Valley Reprocessing Plant	21	50-282	Prairie Island Nuclear Station, Unit 1	101
50-206	San Onofre Nuclear Station, Unit 1	21	50-285	Fort Calhoun Station, Unit 1	103
50-213	Haddam Neck Plant	25	50-286	Indian Point Station, Unit 3	105
50-219	Oyster Creek Nuclear Power Plant	27	50-287	Oconee Nuclear Station, Unit 3	111
50-220	Nine Mile Point Nuclear Station, Unit 1	29	50-288	Reed College Research Reactor	114
50-228	Aerotest Radiography & Research Reactor	31	50-289	Three Mile Island Nuclear Station, Unit 1	114
50-237	Dresden Nuclear Power Station, Unit 2	31	50-290	Proof Test Facility	120
50-238	Nuclear Ship Savannah	35	50-293	Pilgrim Nuclear Power Station, Unit 1	120
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35	50-294	Michigan State Univ. Research Reactor	123
50-245	Millstone Nuclear Power Station, Unit 1	38	50-295	Zion Nuclear Power Station, Unit 1	123
50-247	Indian Point Station, Unit 2	41	50-296	Browns Ferry Nuclear Power Station, Unit 3	126
50-249	Dresden Nuclear Power Station, Unit 3	47	50-297	North Carolina State Univ. PULSTAR Reactor	129

Docket	Name	Page	Docket	Name	Page
50-298	Cooper Nuclear Station	129	50-346	Davis-Besse Nuclear Power Station, Unit 1	224
50-301	Point Beach Nuclear Plant, Unit 2	131	50-348	Joseph M. Farley Nuclear Plant, Unit 1	227
50-302	Crystal River Nuclear Plant, Unit 3	133	50-352	Limerick Generating Station, Unit 1	229
50-304	Zion Nuclear Power Station, Unit 2	136	50-353	Limerick Generating Station, Unit 2	231
50-305	Kewaunee Nuclear Power Plant	138	50-354	Hope Creek Nuclear Station, Unit 1	233
50-306	Prairie Island Nuclear Station, Unit 2	140	50-355	Hope Creek Nuclear Station, Unit 2	234
50-309	Maine Yankee Atomic Power Plant	142	50-358	William H. Zimmer Nuclear Station, Unit 1	234
50-311	Salem Nuclear Generating Station, Unit 2	145	50-361	San Onofre Nuclear Station, Unit 2	240
50-312	Rancho Seco Nuclear Generating Station	147	50-362	San Onofre Nuclear Station, Unit 3	244
50-313	Arkansas Nuclear One, Unit 1	150	50-363	Forked River Nuclear Station, Unit 1	247
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	154	50-364	Joseph M. Farley Nuclear Plant, Unit 2	247
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	157	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	249
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	161	50-367	Bailly Generating Station	253
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	165	50-368	Arkansas Nuclear One, Unit 2	253
50-320	Three Mile Island Nuclear Station, Unit 2	169	50-369	William B. McGuire Nuclear Station, Unit 1	257
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	172	50-370	William B. McGuire Nuclear Station, Unit 2	259
50-322	Shoreham Nuclear Power Station	176	50-373	LaSalle County Station, Unit 1	261
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	181	50-374	LaSalle County Station, Unit 2	265
50-324	Brunswick Steam Electric Plant, Unit 2	183	50-375	Nuclear Examination Reactor	268
50-325	Brunswick Steam Electric Plant, Unit 1	186	50-382	Waterford Generating Station, Unit 3	268
50-326	Univ. of California at Irvine Research Reactor	189	50-387	Susquehanna Steam Electric Station, Unit 1	272
50-327	Sequoyah Nuclear Plant, Unit 1	190	50-388	Susquehanna Steam Electric Station, Unit 2	276
50-328	Sequoyah Nuclear Plant, Unit 2	192	50-389	St. Lucie Plant, Unit 2	278
50-329	Midland Plant, Unit 1	194	50-390	Watts Bar Nuclear Plant, Unit 1	281
50-330	Midland Plant, Unit 2	198	50-391	Watts Bar Nuclear Plant, Unit 2	283
50-331	Duane Arnold Energy Center	202	50-395	Virgil C. Summer Nuclear Station, Unit 1	286
50-333	James A. Fitzpatrick Nuclear Power Plant	204	50-397	WPPSS Nuclear Project, Unit 2	289
50-334	Beaver Valley Power Station, Unit 1	207	50-400	Shearon Harris Nuclear Power Plant, Unit 1	291
50-335	St. Lucie Plant, Unit 1	209	50-401	Shearon Harris Nuclear Power Plant, Unit 2	293
50-336	Millstone Nuclear Power Station, Unit 2	212	50-402	Shearon Harris Nuclear Power Plant, Unit 3	295
50-338	North Anna Power Station, Unit 1	214	50-403	Shearon Harris Nuclear Power Plant, Unit 4	296
50-339	North Anna Power Station, Unit 2	217	50-404	North Anna Power Station, Unit 3	296
50-341	Enrico Fermi Atomic Power Plant, Unit 2	219	50-405	North Anna Power Station, Unit 4	296
50-344	Trojan Nuclear Plant	222	50-406	Tuskegee Institute Research Reactor	296

Docket	Name	Page	Docket	Name	Page
50-409	La Crosse Boiling Water Reactor	296	STN-50-470	CESSAR System 80	365
50-410	Nine Mile Point Nuclear Station, Unit 2	297	STN-50-482	Wolf Creek Generating Station	365
50-412	Beaver Valley Power Station, Unit 2	300	STN-50-483	Callaway Plant, Unit 1	367
50-413	Catawba Nuclear Station, Unit 1	301	STN-50-485	Sterling Power Nuclear Project, Unit 1	368
50-414	Catawba Nuclear Station, Unit 2	303	STN-50-486	Callaway Plant, Unit 2	369
50-416	Grand Gulf Nuclear Station, Unit 1	306	STN-50-488	Perkins Nuclear Station, Unit 1	369
50-417	Grand Gulf Nuclear Station, Unit 2	311	STN-50-489	Perkins Nuclear Station, Unit 2	369
50-423	Millstone Nuclear Power Station, Unit 3	312	STN-50-490	Perkins Nuclear Station, Unit 3	369
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	314	STN-50-491	Cherokee Nuclear Station, Unit 1	370
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	315	STN-50-492	Cherokee Nuclear Station, Unit 2	370
50-434	Surry Power Station, Unit 3	316	STN-50-493	Cherokee Nuclear Station, Unit 3	371
50-435	Surry Power Station, Unit 4	316	50-496	Montague Nuclear Power Station, Unit 1	371
STN-50-437	Floating Nuclear Plant	316	50-497	Montague Nuclear Power Station, Unit 2	371
50-438	Bellefonte Nuclear Plant, Unit 1	317	STN-50-498	South Texas Project, Unit 1	371
50-439	Bellefonte Nuclear Plant, Unit 2	319	STN-50-499	South Texas Project, Unit 2	373
50-440	Perry Nuclear Power Plant, Unit 1	321	50-500	Davis-Besse Nuclear Power Station, Unit 2	374
50-441	Perry Nuclear Power Plant, Unit 2	325	50-501	Davis-Besse Nuclear Power Station, Unit 3	374
50-443	Seabrook Nuclear Station, Unit 1	330	STN-50-506	Koshkonong Nuclear Plant, Unit 3	374
50-444	Seabrook Nuclear Station, Unit 2	335	STN-50-508	WPPSS Nuclear Project, Unit 3	374
50-445	Comanche Peak Steam Electric Station, Unit 1	340	STN-50-509	WPPSS Nuclear Project, Unit 5	376
50-446	Comanche Peak Steam Electric Station, Unit 2	343	50-513	WPPSS Nuclear Project, Unit 4	376
STN-50-447	CESSAR-238	345	50-514	Pebble Springs Nuclear Plant, Unit 1	376
STN-50-454	Byron Station, Unit 1	346	50-515	Pebble Springs Nuclear Plant, Unit 2	376
STN-50-455	Byron Station, Unit 2	350	STN-50-518	Hartsville Nuclear Plant, Unit 1	377
STN-50-456	Braidwood Station, Unit 1	355	STN-50-519	Hartsville Nuclear Plant, Unit 2	378
STN-50-457	Braidwood Station, Unit 2	357	STN-50-520	Hartsville Nuclear Plant, Unit 3	378
50-458	River Bend Station, Unit 1	359	STN-50-521	Hartsville Nuclear Plant, Unit 4	378
50-459	River Bend Station, Unit 2	360	50-522	Skagit Nuclear Power Project, Unit 1	379
50-460	WPPSS Nuclear Project, Unit 1	361	50-523	Skagit Nuclear Power Project, Unit 2	379
50-461	Clinton Power Station, Unit 1	362	STN-50-528	Palo Verde Nuclear Station, Unit 1	380
50-462	Clinton Power Station, Unit 2	364	STN-50-529	Palo Verde Nuclear Station, Unit 2	383
50-466	Allens Creek Nuclear Station, Unit 1	365	STN-50-530	Palo Verde Nuclear Station, Unit 3	385
50-467	Allens Creek Nuclear Station, Unit 2	365	50-537	Clinch River Breeder Reactor	387

Docket	Name	Page	Docket	Name	Page
STN-50-546	Marble Hill Nuclear Station, Unit 1	390	70-1062	Todd Shipyards Corp , Galveston, TX	401
STN-50-547	Marble Hill Nuclear Station, Unit 2	392	70-1100	Combustion Engineering, Inc , Windsor, CT	401
STN-50-553	Phipps Bend Nuclear Station, Unit 1	394	70-1113	General Electric Co , Wilmington, NC	401
STN-50-554	Phipps Bend Nuclear Station, Unit 2	395	70-1143	Westinghouse Electric Corp , Pittsburgh, PA	401
STN-50-556	Black Fox Station, Unit 1	395	70-1151	Westinghouse Electric Corp , Pittsburgh, PA	401
STN-50-557	Black Fox Station, Unit 2	395	70-1193	Kerr-McGee Nuclear Corp., Oklahoma, OK	402
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	396	70-1201	Babcock & Wilcox Co , Lynchburg, VA	402
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	396	70-1257	Exxon Nuclear Co , Inc., Richland, WA	402
STN-50-599	Carroll Facility I	397	70-1362	Hahnemann Medical College & Hospital, Philadelphia, PA	402
STN-50-600	Carroll Facility II	397	70-1418	Michigan, Univ of, Ann Arbor, MI	402
Domestic Licensing of Special Nuclear Material — Docket 70			70-1621	Duquesne Light Co., Pittsburgh, PA	403
70-0025	Rockwell International Corp., Canoga Park, CA	397	70-1719	Youngstown Hospital Association, Youngstown, OH	403
70-0027	Babcock & Wilcox Co., Lynchburg, VA	397	70-1739	Tri-State Motor Transit Co., Joplin, MO	403
70-0033	Texas Instruments, Inc , Attleboro, MA	397	70-1856	Michigan, Univ of, Ann Arbor, MI	403
70-0036	Combustion Engineering, Inc., Windsor, CT	397	70-1866	MacMurray College, Jacksonville, IL	403
70-0113	Pennsylvania State Univ., University Park, PA	397	70-1936	Texas A&M Univ., College Station, TX	403
70-0124	Teledyne Isotopes, Inc., Westwood, NJ	397	70-2199	Veterans Administration Medical Center, Washington, DC	403
70-0135	Babcock & Wilcox, Co., Apollo, PA	398	70-2467	Good Samaritan Hospital, Pottsville, PA	403
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	398	70-2479	Transnuclear, Inc., Falls Church, VA	403
70-0146	Spencer Chemical Co., Kansas City, MO	399	70-2677	Good Samaritan Hospital, Downers Grove, IL	403
70-0212	Iowa, Univ of, Iowa City, IA	399	70-2864	Michigan, Univ. of, Ann Arbor, MI	403
70-0223	California, Univ. of, Los Angeles, CA	399	70-2932	Texas Utilities Generating Co., Dallas, TX	403
70-0250	Boeing Co., Seattle, WA	399	70-2937	Pennsylvania Power & Light, Allentown, PA	404
70-0364	Babcock & Wilcox, Co., Apollo, PA	399	70-2945	Union Electric Co., St. Louis, MO	404
70-0371	UNC Naval Products, Inc., Uncasville, CT	399	70-2946	Louisiana Power & Light Co., New Orleans, LA	404
70-0398	Commerce, Dept. of, Washington, DC	400	70-2949	Arizona Public Service Co., Phoenix, AZ	404
70-0470	National Aeronautics & Space Administration, Greenbelt, MD	400	70-2950	Washington Public Power Supply System, Richland, WA	404
70-0687	Union Carbide Corp., Tuxedo, NY	400	70-2957	Florida Power & Light Co., Miami, FL	404
70-0734	GA Technologies, Inc., San Diego, CA	400	70-2960	Kansas Gas & Electric Co., Wichita, KS	404
70-0754	General Electric Co , Pleasanton, CA	400			
70-0820	United Nuclear Corp., Wood River Junction, RI	401			

Docket	Name	Page	Docket	Name	Page
70-2964	Consumers Power Co , Jackson, MI	404	71-9006	Model 500-SU, Automation Industries, Inc	406
70-2965	Consumers Power Co , Jackson, MI	404	71-9007	Model 520, Automation Industries, Inc.	407
70-2968	Cleveland Electric Illuminating Co , Cleveland, OH	404	71-9010	Model NLI-1/2, NL Industries, Inc	407
70-2973	Commonwealth Edison Co., Chicago, IL	404	71-9015	Model. TN-8, -8L, No Users	407
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71			71-9021	Model: 750, Technical Operations, Inc	407
71-0345	Carolina Power & Light Co	405	71-9027	Model. 741 & 741E, Technical Operations, Inc	407
71-0476	Texas, State of	405	71-9032	Model 650, Technical Operations Inc	407
71-0491	Mid-Con Inspection Services, Inc	405	71-9033	Model 660 & 660E, Technical Operations Inc	407
71-5450	Model RCC, -1, -2, -3, -4, Westinghouse Electric Corp	405	71-9036	Model. C-1, Source Production & Equipment Co	407
71-5805	Model: CNS-3-55, Chem-Nuclear Systems, Inc	405	71-9039	Model 715, Technical Operations, Inc	407
71-5814	Model: NRBK-41, -42, & -43, Energy, Dept of	405	71-9044	Model GE-1600, General Electric Co	407
71-5926	Model: GE-100, General Electric Co	405	71-9053	Model 683, Technical Operations Inc	407
71-5957	Model. BMI-1, Battelle Columbus Laboratory	405	71-9056	Model Spec 2-T, Source Production & Equipment Co	407
71-6144	Model: B-2, U S Ecology	405	71-9079	Model HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp	408
71-6272	Model 6272, U S. Ecology	405	71-9081	Model CNSI 1-13C, Chem-Nuclear Systems, Inc	408
71-6346	Model FSV-1, General Atomic Co.	405	71-9094	Model CNS 14-195-H, Chem-Nuclear Systems, Inc	408
71-6347	Model FSV-3, General Atomic Co.	405	71-9096	Model CNS 21-300, Chem-Nuclear Systems, Inc.	408
71-6386	Model 235R001, Energy, Dept of	405	71-9107	Model 771, Technical Operations, Inc	408
71-6400	Model. 6400, Westinghouse Electric Corp	405	71-9110	Model MX-IC-100, Magnaflux Corp	408
71-6441	Model D2G, Power Unit, Energy, Dept of	406	71-9126	Model 20, 20A, 50, 50A, Gamma Industries	408
71-6550	Model 6-GS-1, Energy. Dept of	406	71-9127	Model 100, 100A, 200, 200A, Gamma Industries	408
71-6574	Model. HN-200, Hittman Nuclear & Development Corp	406	71-9128	Model C-8, Gamma Industries	408
71-6642	Model 4.5 Ton CF, Energy, Dept of	406	71-9132	Model T-3, Energy, Dept of	408
71-6679	Model 6679, U.S Ecology	406	71-9135	Model. Century S & SA, Cen. Univ S & SA, Gamma Industries	408
71-6697	Model GE-8500, General Electric Co	406			
71-6698	Model NFS-4, Nuclear Fuel Services, Inc.	406			
71-6717	Model: 6717-B, Gamma Industries	406			
71-6771	Model SN-1, Metropolitan Edison Co.	406			
71-9001	Model IF-300, General Electric Co.	406			

Docket	Name	Page	Docket	Name	Page
71-9137	Model. 820, Technical Operations, Inc.	408	71-9157	Model IR-100, Industrial Nuclear Co	409
71-9138	Model. 78-D-1458, Navy, Dept of	408	71-9158	Model GPU-80, General Public Utilities	409
71-9139	Model. 589, General Electric Co	408	71-9167	Model 3206B, 3227B & 3218, Amersham Corp	409
71-9148	Model 770, Technical Operations, Inc	408	71-9168	Model CNS 8-120B, Chem-Nuclear Systems, Inc	409
71-9150	Model. PAT-2, Energy, Dept of	408	71-9855	Model: ORNL DOT Spec 6M Special Form Package, Energy, Dept of	409
71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	409	Licensing of Independent Spent Fuel Storage — Docket 72		
71-9156	Model IR-50, Industrial Nuclear Co.	409	72-0002	Virginia Electric & Power Co	409

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27			Ogle Petroleum, Inc., Casper, WY	40-8745	
Barnwell, SC, Chem-Nuclear Systems, Inc	27-047	1	Ogle Petroleum, Inc., Santa Barbara, CA	40-8693	
Richland, WA, U S Ecology, Inc	27-048	1	Omaha Public Power District, Omaha, NE	40-8822	
Sheffield, IL, U S Ecology, Inc	27-039	1	Pathfinder Mines Corp., Riverton, WY	40-2259	
Domestic Licensing of Source Material — Docket 40			Pathfinder Mines Corp., Shirley Basin, WY	40-6622	
Army, Dept of, Tooele, UT	40-8779	6	Plateau Resources, Ltd., Grand Junction, CO	40-8698	
Atlas Mineral, Inc., Denver, CO	40-3453	3	Rio Algom Corp., Moab, UT	40-8084	
Bear Creek Uranium Co., Casper, WY	40-8452	4	Rocky Mountain Energy Co., Broomfield, CO	40-8380	
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	5	Rocky Mountain Energy Co., Denver, CO	40-8697	
Conoco, Inc., Denver, CO	40-8743	6	S. F. Appliance, Ltd., Morris, IL	40-0215	
Day & Zimmerman, Inc., Parsons, KS	40-8483	4	Tennessee Valley Authority, Chattanooga, TN	40-1341	
Dow Chemical Co., Midland, MI	40-0017	1	Teton Exploration Drilling Co., Inc., Casper, WY	40-8728	
Edison Institute, Dearborn, MI	40-8792	7	Udylite/Sel-Rex, Warren, MI	40-8799	
Energy Fuels Nuclear, Inc., Denver, CO	40-8675	5	Union Carbide Corp., Grand Junction, CO	40-0299	2
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	5	Uranciz USA, Inc., Casper, WY	40-8783	6
Exxon Co. USA, Houston, TX	40-8102	4	Uranium Resources, Inc., Richardson, TX	40-8786	6
Exxon Minerals Co. USA, Houston, TX	40-8064	3	Virginia, Univ of, Charlottesville, VA	40-5738	3
Federal-American Partners, Riverton, WY	40-4492	3	W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Fenton Art Glass Co., Williamstown, WV	40-3149	3	Westinghouse Electric Corp., Ogden, UT	40-8709	5
Hitchcock Industries, Inc., Minneapolis, MN	40-8798	7	Whittaker Metals, Los Angeles, CA	40-7455	3
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Wyoming Fuel Co., Lakewood, CO	40-8829	7
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	3	Wyoming Mineral Corp., Lakewood, CO	40-8502	4
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	6	Domestic Licensing of Production and Utilization Facilities — Docket 50		
Michigan, Univ of, Ann Arbor, MI	40-8787	6	Aerotest Radiography & Research Reactor	50-228	31
Minerals Exploration Co., Los Angeles, CA	40-8584	4	Allens Creek Nuclear Station, Unit 1	50-466	365
Moraine Valley Community College, Palos Hills, IL	40-8626	5	Allens Creek Nuclear Station, Unit 2	50-467	365
Nuclear Dynamics, Inc., Phoenix, AZ	40-8663	5	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	314
Nuclear Metals, Inc., Concord, MA	40-0672	2	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	315
			Arkansas Nuclear One, Unit 1	50-313	150

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One, Unit 2	50-368	253	Comanche Peak Steam Electric Station, Unit 1	50-445	340
Bailly Generating Station	50-367	253	Comanche Peak Steam Electric Station, Unit 2	50-446	343
Beaver Valley Power Station, Unit 1	50-334	207	Cooper Nuclear Station	50-298	129
Beaver Valley Power Station, Unit 2	50-412	300	Crystal River Nuclear Plant, Unit 3	50-302	133
Bellefonte Nuclear Plant, Unit 1	50-438	317	Davis-Besse Nuclear Power Station, Unit 1	50-346	224
Bellefonte Nuclear Plant, Unit 2	50-439	319	Davis-Besse Nuclear Power Station, Unit 2	50-500	374
Big Rock Point Nuclear Plant	50-155	16	Davis-Besse Nuclear Power Station, Unit 3	50-501	374
Black Fox Station, Unit 1	STN-50-556	395	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	87
Black Fox Station, Unit 2	STN-50-557	395	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	181
Braidwood Station, Unit 1	STN-50-456	355	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	154
Braidwood Station, Unit 2	STN-50-457	357	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	157
Browns Ferry Nuclear Power Station, Unit 1	50-259	59	Dow Chemical Co	50-264	70
Browns Ferry Nuclear Power Station, Unit 2	50-260	62	Dresden Nuclear Power Station, Unit 1	50-10	8
Browns Ferry Nuclear Power Station, Unit 3	50-296	126	Dresden Nuclear Power Station, Unit 2	50-237	31
Brunswick Steam Electric Plant, Unit 1	50-325	186	Dresden Nuclear Power Station, Unit 3	50-249	47
Brunswick Steam Electric Plant, Unit 2	50-324	183	Duane Arnold Energy Center	50-331	202
Byron Station, Unit 1	STN-50-454	346	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	172
Byron Station, Unit 2	STN-50-455	350	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	249
Callaway Plant, Unit 1	STN-50-483	367	Enrico Fermi Atomic Power Plant, Unit 2	50-341	219
Callaway Plant, Unit 2	STN-50-486	369	Floating Nuclear Plant	STN-50-437	316
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	161	Forked River Nuclear Station, Unit 1	50-363	247
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	165	Fort Calhoun Station, Unit 1	50-285	103
Carroll Facility I	STN-50-599	397	Fort St. Vrain Nuclear Generating Station	50-267	74
Carroll Facility II	STN-50-600	397	General Atomic Co	50-163	20
Catawba Nuclear Station, Unit 1	50-413	301	General Atomic Co	50-89	12
Catawba Nuclear Station, Unit 2	50-414	303	General Electric Nuclear Test Reactor	50-73	12
SSAR System 80	STN-50-470	365	General Electric Test Reactor	50-70	12
Crooke Nuclear Station, Unit 1	STN-50-491	370	Georgia Institute of Technology Research Reactor	50-160	20
Crooke Nuclear Station, Unit 2	STN-50-492	370	GESSAR-238	STN-50-447	345
Crooke Nuclear Station, Unit 3	STN-50-493	371	Grand Gulf Nuclear Station, Unit 1	50-416	306
	50-537	387	Grand Gulf Nuclear Station, Unit 2	50-417	311
	50-461	362	H. B. Robinson Plant, Unit 2	50-261	65
	50-462	364	Haddam Neck Plant	50-213	25

Name	Docket	Page	Name	Docket	Page
Hartsville Nuclear Plant, Unit 1	STN-50-518	377	National Naval Medical Center	50-170	20
Hartsville Nuclear Plant, Unit 2	STN-50-519	378	Nine Mile Point Nuclear Station, Unit 1	50-220	29
Hartsville Nuclear Plant, Unit 3	STN-50-520	378	Nine Mile Point Nuclear Station, Unit 2	50-410	297
Hartsville Nuclear Plant, Unit 4	STN-50-521	378	North Anna Power Station, Unit 1	50-338	214
Hope Creek Nuclear Station, Unit 1	50-354	233	North Anna Power Station, Unit 2	50-339	217
Hope Creek Nuclear Station, Unit 2	50-355	234	North Anna Power Station, Unit 3	50-404	296
Humboldt Bay Power Plant, Unit 3	50-133	14	North Anna Power Station, Unit 4	50-405	296
Indian Point Station, Unit 1	50-3	7	North Carolina State Univ. PULSTAR Reactor	50-297	129
Indian Point Station, Unit 2	50-247	41	North Carolina State Univ. Research Reactor	50-111	12
Indian Point Station, Unit 3	50-286	105	Nuclear Examination Reactor	50-375	268
James A. Fitzpatrick Nuclear Power Plant	50-333	204	Nuclear Ship Savannah	50-238	35
Joseph M. Farley Nuclear Plant, Unit 1	50-348	227	Oconee Nuclear Station, Unit 1	50-269	78
Joseph M. Farley Nuclear Plant, Unit 2	50-364	247	Oconee Nuclear Station, Unit 2	50-270	80
Kewaunee Nuclear Power Plant	50-305	138	Oconee Nuclear Station, Unit 3	50-287	111
Koshkonong Nuclear Plant, Unit 3	STN-50-506	374	Omaha Veterans Administration Hospital Research Reactor	50-131	13
La Crosse Boiling Water Reactor	50-409	296	Oyster Creek Nuclear Power Plant	50-219	27
LaSalle County Station, Unit 1	50-373	261	Palisades Nuclear Plant	50-255	57
LaSalle County Station, Unit 2	50-374	265	Palo Verde Nuclear Station, Unit 1	STN-50-528	380
Limerick Generating Station, Unit 1	50-352	229	Palo Verde Nuclear Station, Unit 2	STN-50-529	383
Limerick Generating Station, Unit 2	50-353	231	Palo Verde Nuclear Station, Unit 3	STN-50-530	385
Maine Yankee Atomic Power Plant	50-309	142	Peach Bottom Atomic Power Station, Unit 2	50-277	91
Marble Hill Nuclear Station, Unit 1	STN-50-546	390	Peach Bottom Atomic Power Station, Unit 3	50-278	93
Marble Hill Nuclear Station, Unit 2	STN-50-547	392	Pebble Springs Nuclear Plant, Unit 1	50-514	376
McMaster Univ. Research Reactor	50-67	12	Pebble Springs Nuclear Plant, Unit 2	50-515	376
Michigan State Univ. Research Reactor	50-294	123	Pennsylvania State Univ. Research Reactor	50-5	8
Midland Plant, Unit 1	50-329	194	Perkins Nuclear Station, Unit 1	STN-50-488	369
Midland Plant, Unit 2	50-330	198	Perkins Nuclear Station, Unit 2	STN-50-489	369
Millstone Nuclear Power Station, Unit 1	50-245	38	Perkins Nuclear Station, Unit 3	STN-50-490	369
Millstone Nuclear Power Station, Unit 2	50-336	212	Perry Nuclear Power Plant, Unit 1	50-440	321
Millstone Nuclear Power Station, Unit 3	50-423	312	Perry Nuclear Power Plant, Unit 2	50-441	325
Montague Nuclear Power Station, Unit 1	50-496	371	Phipps Bend Nuclear Station, Unit 1	STN-50-553	394
Montague Nuclear Power Station, Unit 2	50-497	371	Phipps Bend Nuclear Station, Unit 2	STN-50-554	395
Monticello Nuclear Generating Plant	50-263	68			

Name	Docket	Page	Name	Docket	Page
Pilgrim Nuclear Power Station, Unit 1	50-293	120	St. Lucie Plant, Unit 1	50-335	209
Point Beach Nuclear Plant, Unit 1	50-266	73	St. Lucie Plant, Unit 2	50-389	278
Point Beach Nuclear Plant, Unit 2	50-301	131	Sterling Power Nuclear Project, Unit 1	STN-50-485	368
Prairie Island Nuclear Station, Unit 1	50-282	101	Surry Power Station, Unit 1	50-280	96
Prairie Island Nuclear Station, Unit 2	50-306	140	Surry Power Station, Unit 2	50-281	98
Provo Test Facility	50-290	120	Surry Power Station, Unit 3	50-434	316
Quad Cities Station, Unit 1	50-254	54	Surry Power Station, Unit 4	50-435	316
Quad Cities Station, Unit 2	50-265	70	Susquehanna Steam Electric Station, Unit 1	50-387	272
Rancho Seco Nuclear Generating Station	50-312	147	Susquehanna Steam Electric Station, Unit 2	50-388	276
Reed College Research Reactor	50-288	114	Texas A&M Univ. Research Reactor	50-128	13
Rhodes Island & Providence Plantations AEC	50-193	21	Three Mile Island Nuclear Station, Unit 1	50-289	114
River Bend Station, Unit 1	50-458	359	Three Mile Island Nuclear Station, Unit 2	50-320	169
River Bend Station, Unit 2	50-459	360	Trojan Nuclear Plant	50-344	222
Robert F. Kennedy Jr. Nuclear Plant, Unit 1	50-244	35	Turkey Point Plant, Unit 3	50-250	50
Salem Nuclear Generating Station, Unit 1	50-272	55	Turkey Point Plant, Unit 4	50-251	52
Salem Nuclear Generating Station, Unit 2	50-311	145	Tuskegee Institute Research Reactor	50-406	296
San Onofre Nuclear Station, Unit 1	50-206	21	U.S. Geological Survey Research Reactor	50-274	87
San Onofre Nuclear Station, Unit 2	50-361	240	UCLA Training Reactor	50-142	14
San Onofre Nuclear Station, Unit 3	50-362	244	Union Carbide Research Reactor	50-54	12
Seabrook Nuclear Station, Unit 1	50-443	330	Univ. of Arizona Research Reactor	50-113	12
Seabrook Nuclear Station, Unit 2	50-444	335	Univ. of California at Irvine Research Reactor	50-326	189
Sequoyah Nuclear Plant, Unit 1	50-327	190	Univ. of Michigan Research Reactor	50-2	7
Sequoyah Nuclear Plant, Unit 2	50-328	192	Univ. of Missouri Research Reactor	50-186	21
Sharon Harris Nuclear Power Plant, Unit 1	50-400	291	Univ. of Oklahoma Research Reactor	50-112	12
Sharon Harris Nuclear Power Plant, Unit 2	50-401	293	Univ. of Texas Research Reactor	50-192	21
Sharon Harris Nuclear Power Plant, Unit 3	50-402	295	Univ. of Utah Research Reactor	50-72	12
Sharon Harris Nuclear Power Plant, Unit 4	50-403	296	Univ. of Washington Research Reactor	50-139	14
Shoreham Nuclear Power Station	50-322	176	Univ. of Wisconsin Research Reactor	50-156	20
Skagit Nuclear Power Project, Unit 1	50-522	379	Vermont Yankee Nuclear Power Station	50-271	83
Skagit Nuclear Power Project, Unit 2	50-523	379	Virgil C. Summer Nuclear Station, Unit 1	50-395	286
South Texas Project, Unit 1	STN-50-498	371	Virginia Polytech Institute Training Reactor	50-124	12
South Texas Project, Unit 2	STN-50-499	373	Waterford Generating Station, Unit 3	50-382	268
Space Radiation Research Reactor	50-187	21	Watts Bar Nuclear Plant, Unit 1	50-390	281

Name	Docket	Page	Name	Docket	Page
Watts Bar Nuclear Plant, Unit 2	50-391	283	Florida Power & Light Co , Miami, FL	70-2957	404
West Valley Reprocessing Plant	50-201	21	GA Technologies, Inc , San Diego, CA	70-0734	400
William B McGuire Nuclear Station, Unit 1	50-369	257	General Electric Co , Pleasanton, CA	70-0754	400
William B McGuire Nuclear Station, Unit 2	50-370	259	General Electric Co , Wilmington, NC	70-1113	401
William H Zimmer Nuclear Station, Unit 1	50-358	234	Good Samaritan Hospital, Downers Grove, IL	70-2677	403
Wolf Creek Generating Station	STN-50-482	365	Good Samaritan Hospital, Pottsville, PA	70-2467	403
WPPSS Nuclear Project, Unit 1	50-460	361	Hahnemann Medical College & Hospital, Philadelphia, PA	70-1362	402
WPPSS Nuclear Project, Unit 2	50-397	289	Iowa, Univ. of, Iowa City, IA	70-0212	399
WPPSS Nuclear Project, Unit 3	STN-50-508	374	Kansas Gas & Electric Co , Wichita, KS	70-2960	404
WPPSS Nuclear Project, Unit 4	50-513	376	Kerr-McGee Nuclear Corp , Oklahoma City, OK	70-1193	402
WPPSS Nuclear Project, Unit 5	STN-50-509	376	Louisiana Power & Light Co., New Orleans, LA	70-2946	404
Yankee-Rowe Nuclear Power Station	50-29	10	MacMurray College, Jacksonville, IL	70-1866	403
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	396	Michigan, Univ. of, Ann Arbor, MI	70-2864	403
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	396	Michigan, Univ. of, Ann Arbor, MI	70-1418	402
Zion Nuclear Power Station, Unit 1	50-295	123	Michigan, Univ. of, Ann Arbor, MI	70-1856	403
Zion Nuclear Power Station, Unit 2	50-304	136	National Aeronautics & Space Administration, Greenbelt, MD	70-0470	400
Domestic Licensing of Special Nuclear Material—Docket 70			Nuclear Fuel Services, Inc., Erwin, TN	70-0143	398
Arizona Public Service Co , Phoenix, AZ	70-2949	404	Pennsylvania Power & Light, Allentown, PA	70-2937	404
Babcock & Wilcox Co., Apollo, PA	70-0135	398	Pennsylvania State Univ., University Park, PA	70-0113	397
Babcock & Wilcox Co., Apollo, PA	70-0364	397	Rockwell International Corp., Canoga Park, CA	70-0025	397
Babcock & Wilcox Co., Lynchburg, VA	70-1201	402	Spencer Chemical Co , Kansas City, MO	70-0146	399
Babcock & Wilcox Co , Lynchburg, VA	70-0027	399	Teledyne Isotopes, Inc., Westwood, NJ	70-0124	397
Boeing Co., Seattle, WA	70-0250	399	Texas A&M Univ., College Station, TX	70-1936	403
California, Univ. of, Los Angeles, CA	70-0223	399	Texas Instruments, Inc., Attleboro, MA	70-0033	397
Cleveland Electric Illuminating Co , Cleveland, OH	70-2968	404	Texas Utilities Generating Co , Dallas, TX	70-2932	403
Combustion Engineering, Inc , Windsor, CT	70-1100	401	Todd Shipyards Corp., Galveston, TX	70-1062	401
Combustion Engineering, Inc., Windsor, CT	70-0036	397	Transnuclear, Inc., Falls Church, VA	70-2479	403
Commerce, Dept. of, Washington, DC	70-0398	400	Tri-State Motor Transit Co., Joplin, MO	70-1739	403
Commonwealth Edison Co , Chicago, IL	70-2973	404	UNC Naval Products, Inc., Uncasville, CT	70-0371	399
Consumers Power Co., Jackson, MI	70-2965	404	Union Carbide Corp , Tuxedo, NY	70-0687	400
Consumers Power Co., Jackson, MI	70-2964	404	Union Electric Co., St. Louis, MO	70-2945	404
Duquesne Light Co , Pittsburgh, PA	70-1621	403			
Exxon Nuclear Co , Inc., Richland, WA	70-1257	402			

Name	Docket	Page	Name	Docket	Page
United Nuclear Corp , Wood River Junction, RI	70-0820	401	Model B-2, U.S Ecology	71-6144	405
Veterans Administration Medical Center, Washington, DC	70-2199	403	Model: BMI-1, Battelle Columbus Laboratory	71-5957	405
Washington Public Power Supply System, Richland, WA	70-2950	404	Model C-1, Source Production & Equipment Co	71-9036	407
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	401	Model C-8, Gamma Industries	71-9128	408
Westinghouse Electric Corp., Pittsburgh, PA	70-1151	401	Model: Century S & SA, Cen Univ. S & SA, Gamma Industries	71-9135	408
Youngstown Hospital Association, Youngstown, OH	70-1719	403	Model CNS 14-195-H, Chem-Nuclear Systems, Inc	71-9094	408
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71			Model CNS 21-300, Chem-Nuclear Systems, Inc	71-9096	408
Carolina Power & Light Co	71-0345	405	Model: CNS 8-120B, Chem-Nuclear Systems, Inc.	71-9168	409
Mid-Con Inspection Services, Inc	71-0491	405	Model. CNS-3-55, Chem-Nuclear Systems, Inc	71-5805	405
Model 100, 100A, 200, 200A, Gamma Industries	71-9127	408	Model CNSI 1-13C, Chem-Nuclear Systems, Inc	71-9081	408
Model 20, 20A, 50, 50A, Gamma Industries	71-9126	408	Model D2G Power Unit, Energy, Dept of	71-6441	406
Model 235R001, Energy, Dept. of	71-6386	405	Model FSV-1, General Atomic Co	71-6346	405
Model 3206B, 3227B & 3218, Amersham Corp	71-9167	409	Model FSV-3, General Atomic Co	71-6347	405
Model. 4 5 Ton CF, Energy, Dept of	71-6642	406	Model GE-100, General Electric Co	71-5926	405
Model 500-SU, Automation Industries, Inc.	71-9006	406	Model GE-1600, General Electric Co	71-9044	407
Model 520, Automation Industries, Inc	71-9007	407	Model GE-8500, General Electric Co	71-6697	406
Model 589, General Electric Co	71-9139	408	Model GPU 80, General Public Utilities	71-9158	409
Model 6-GS-1, Energy, Dept. of	71-6550	406	Model HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp	71-9079	408
Model 6272, U.S Ecology	71-6272	405	Model HN-100, Series 3, Hittman Nuclear & Development Corp	71-9151	409
Model: 6400, Westinghouse Electric Corp	71-6400	405	Model HN-200, Hittman Nuclear & Development Corp	71-6574	406
Model 650, Technical Operations, Inc	71-9032	407	Model IF-300, General Electric Co	71-9001	406
Model 660 & 660E, Technical Operations, Inc.	71-9033	407	Model IR-100, Industrial Nuclear Co	71-9157	409
Model 6679, U.S Ecology	71-6679	406	Model IR-50, Industrial Nuclear Co	71-9156	409
Model 6717-B, Gamma Industries	71-6717	406	Model. MX-IC-100, Magnaflux Corp	71-9110	408
Model 683, Technical Operations, Inc.	71-9053	407	Model NFS-4, Nuclear Fuel Services, Inc	71-6698	406
Model 715, Technical Operations, Inc	71-9039	407	Model NLI-1/2, NL Industries, Inc	71-9010	407
Model 741 & 741E, Technical Operations, Inc	71-9027	407	Model NRBK-41, -42 & -43, Energy, Dept of	71-5814	405
Model. 750, Technical Operations, Inc	71-9021	407	Model ORNL DOT Spec 6M Special Form Package, Energy, Dept of	71-9855	409
Model 770, Technical Operations, Inc.	71-9148	408	Model. PAT-2, Energy, Dept. of	71-9150	408
Model 771, Technical Operations, Inc	71-9107	408	Model RCC -1, -2, -3, -4, Westinghouse Electric Corp	71-5450	405
Model 78-D-1458, Navy, Dept. of	71-9138	408			
Model: 820, Technical Operations, Inc	71-9137	408			

Name			Name		
	Docket	Page		Docket	Page
Model SN-1, Metropolitan Edison Co	71-6771	406	Texas, State of	71-0476	405
Model Spec 2-T, Source Production & Equipment Co	71-9056	407	Licensing of Independent Spent Fuel Storage — Docket 72		
Model T-3, Energy, Dept of	71-9132	408	Virginia Electric & Power Co	72-0002	409
Model TN-8, -8L, No Users	71-9015	407			

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8302010600 Forwards IE Insp Rept 27-0039/82-02 on 821214-15 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/01/17 SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering) 2pp 16978 130

--8302010608 IE Insp Rept 27-0039/82-02 on 821214-15 No noncompliance noted Major areas inspected organizational changes, audits, security, instrumentation, training, air sampling program & environ monitoring
SCHUMACHER, M C Division of Emergency Preparedness & Operational Support JANUSKA, A O Region 3, Office of Director 83/01/14 5pp 16978 132

8302010667 Joint motion for extension of continuance of proceeding until 830502 to provide addl time for settlement negotiations Certificate of Svc encl
WETTERHAHN, M J US Ecology, Inc (Formerly Nuclear Engineering) LESSER, R P Hearing Branch 3 83/01/28 Atomic Safety and Licensing Board Panel 3pp 16974 136

8302240397 Summary of steering committee 830117 meeting re Sheffield tritium migration study & 830118 site visit w/USGS Rept on borehole dilution testing at site encl
SIEFKEN, D L Low Level Waste Licensing Branch 83/01/28 HAWKINS, E F Low Level Waste Licensing Branch 4pp 17289 247

--8302240400 "Borehole Dilution Testing Study, Sheffield Low Level Radwaste Disposal Site"
+ Law Engineering Testing Co 83/01/07 31pp 17289 251

8302180433 Order granting NRC & applicant joint motion for continuance until 830502 to provide time for settlement negotiations
GOODHOPE, A C Atomic Safety and Licensing Board Panel 83/02/16 Office of the Executive Legal Director 1p 17215 178

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC

8302250439 Forwards summary of disposition of SNM for CY82 for License 12-13536-01 Total of 11,619 g disposed
PURVIS, J Chem-Nuclear Systems, Inc 83/01/27 MARTIN, J D Division of Waste Management 28pp 17303 169

8302240359 "Analyses of Soils From Commercial Radwaste Disposal Sites at Barnwell, SC & Hanford, WA," conference paper
PICIULO, P L, SHEA, C E, BARLETTA, R E Brookhaven National Laboratory 8302240359 83/02/22 NRC - No Detailed Affiliation Given 8pp 17290 127

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

8302404036 Forwards Waste Packaging Insp Rept 15000046/82-01 on 820804 Noncompliance noted
BOOK, H E Division of Radiological Safety & Safeguards Program 83/01/25 ORELLA, A Safeguards & Materials Program Branch 1p 17017 233

--8302404048 Waste Packaging Insp Rept 15000046/82-01 on 820804 Noncompliance noted one drum of low-specific activity radwaste found badly distorted near top w/no seal between drum & lid & ring bolt lug broken
WAITE, J A Washington, State of THOMAS, R D, BOOK, H E Division of Radiological Safety & Safeguards Program 83/01/21 19pp 17017 234

8302250007 Comments on technical aspects of proposed revised amend to License 16-19204-01 for disposal of SNM at low level waste disposal facility, in response to 830107 ltr Closure plan will be submitted by 830228
SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering) 83/01/25 SHAFFNER, J Low Level Waste Licensing Branch 2pp. 17302 309

8302280059 Forwards corrected copy of Amend 3 to License 16-19204-01 w/o encl
HAWKINS, E F Low Level Waste Licensing Branch 83/02/18 SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering) 1p

8302240359 "Analyses of Soils From Commercial Radwaste Disposal Sites at Barnwell, SC & Hanford, WA," conference paper
PICIULO, P L, SHEA, C E, BARLETTA, R E Brookhaven National Laboratory 8302240359 83/02/22 NRC - No Detailed Affiliation Given 8pp 17290 127

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO, MIDLAND, MI

8302040434 Submits followup to 821214 meeting in response to proposed consolidation plan involving Bay City, MI & Midland thorium storage sites Technical & economic feasibility of reducing vol of stored matl will be evaluated
CROYLE, R H Dow Chemical Co 83/01/03 BRUCHMANN, G Michigan, State of 5pp 17042 324

DOCKET 40-0086 W R GRACE & CO, POMPTON PLAINS, NJ

8302280094 Forwards "Radiological Survey of WR Grace Property, Wayne, NJ," final rept
BERGER, J D Oak Ridge Associated Univ 83/01/31 CRON, W Division of Fuel Cycle & Material Safety 1p 17320 020

8302070303 Forwards "Radiological Survey of WR Grace Property, Wayne, NJ"
MARTIN, T T Division of Engineering & Technical Programs FIN A-9093 83/02/01 HOBLEY, B W R Grace & Co 1p. 17030 111

--8302070306 "Radiological Survey of WR Grace Property, Wayne, NJ"
FRAME, P W Oak Ridge Associated Univ FIN A-9093 83/01/31 Division of Fuel Cycle & Material Safety 18pp 17030 112

8302250204 Responds to 820930, 1115 & 1206 ltrs re potential contamination of aquifer on WR Grace site. Recommendations re radioactive matl removal will be addressed after Oak Ridge Associated Univs final survey rept reviewed
KINNEHAN, J D Region 1, Office of Director 83/02/07 BARTOLOZZI, A R Wayne, NJ 2pp 17293 113

--8302250210 Ack receipt of final rept of radiological surveys of Sheffield Brook area Recommendations re disposition of radioactive matl requested
BARTOLOZZI, A R Wayne, NJ 82/11/15 KINNEHAN, J D Region 1, Office of Director 1p 17293 115

--8302250214 Forwards consultant rept re Sheffield Brook surveys
BARTOLOZZI, A R Wayne, NJ 82/12/06 KINNEHAN, J D Region 1, Office of Director 6pp 17293 116

--8302250219 Comments on Wayne Township Council Resolution 235 re WR Grace & Co property & forwards response to M Reznikoff concerns
DIRCKS, W J Office of the Executive Director for Operations 82/09/29. ROE, R A House of Rep. 5pp 17293 122

DOCKETED ITEMS

3

DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY

8302090578 Forwards completed tables for effluent monitoring rept for Jul-Sept 1982
POYSER, R W Pathfinder Mines Corp 83/01/24 SOLLENBERGER, D
Uranium Recovery Licensing Branch 1p 17108 341

--8302090580 Completed surface water quality & monitor well tables for Jul-Sept 1982
* Pathfinder Mines Corp 83/01/24 3pp 17108 342

8302140208 Notifies that preliminary review indicates that 821217 renewal application acceptable Request for addl info on specific details will be forwarded during renewal review process
PETTENQILL, H J Uranium Recovery Field Office 83/01/24
Pathfinder Mines Corp 1p 17145 327

8302180510 Informs of issuance of Amend 16 to License SUA-672, revising Conditions 25, 27 & 35 re bioassay & gamma survey programs
SMITH, R D Uranium Recovery Field Office 83/01/26 Pathfinder Mines Corp 3pp 17221 267

--8302180511 Summarizes findings of 820727-29 mill appraisal rept Significant weaknesses identified include training & procedures for radiation safety staff, bioassay program & contamination survey program
SOLLENBERGER, D Low Level Waste Licensing Branch PETTENQILL, H J Uranium Recovery Field Office 83/01/24 Low Level Waste Licensing Branch 11pp 17221 272

DOCKET 40-3149 FENTON ART GLASS CO , WILLIAMSTOWN, WV

8301250612 IE Insp Findings & Licensee Ack dtd 830105 of License SUB-491 Insp findings, no violations observed
BROWN, R A Region 2, Office of Director 83/01/05 1p 16904 332

DOCKET 40-3453 ATLAS MINERAL, INC , DENVER, CO

8302160409 Reviews Dames & Moore rept, "Groundwater Monitoring Project, U Mill Tailings Impoundment, Moab, UT " Monitoring schedule to be assigned to monitor wells not addressed Proper design & careful operation essential to success of pumpback sys
WILLIAMS, R E R E Williams & Associates, Inc 82/12/01, GARCIA, P Uranium Fuel Licensing Branch 3pp, 17173 051

8302100165 Notification of contract execution, Mod 2 to "Licensing Assistance/Geotechnical & Hydrological Evaluations, Atlas Minerals Mode Mill " Contractor: Geotechnical Engineers, Inc
FIELDER, J A Technical Assistance Contracts Branch, NRC-02-B2-038 83/01/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 17134 195

--8302100173 Mod 2, revising address for submission of invoices & incorporating revised Manual Chapter 3202 to "Licensing Assistance/Geotechnical & Hydrological Evaluations, Atlas Minerals Mode Mill "
CASTRO, O Geotechnical Engineers, Inc HQAN, T F Division of Contracts NRC-02-B2-038 83/01/03 1p 17134 196.

8302100008 Forwards "CO River Water & Groundwater Pb-210 Assay Results for Third Quarter 1982 "
EDWARDS, D L Atlas Minerals 83/01/20 SMITH, R D Uranium Recovery Licensing Branch 1p 17135 175.

--8302100016 "CO River Water & Groundwater Pb-210 Assay Results for Third Quarter 1982 "
* Atlas Minerals 83/01/20 1p. 17135 176

8302160518 Advises that Amend 10 to License SUA-917 exempt from fees.
GARCIA, P J., PETTENQILL, H J Uranium Recovery Field Office 83/01/26 MILLER, W O License Fee Management Branch, 1p 17176:308

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

8302170094 Requests inclusion of info provided by State of WY Land Quality Div hydrologist B Kearney in assessment & action on Federal American Partners request for reduction of groundwater monitoring around tailings area W/o encl
FRANCIS, E Wyoming, State of 83/01/13, GILLEN, D Uranium Recovery Licensing Branch 1p. 17191.081

DOCKET 40-5738 VIRGINIA, UNIV OF, CHARLOTTEVILLE, VA

8302150230 IE Insp Findings & Licensee Ack dtd 830119 of License SUB-657 Insp findings no violations observed
* Region 2, Office of Director 83/01/19 1p. 17149 271

DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

8302170386 Forwards one oversize map showing location of Piezometer T-5-2 Piezometer installed in northern abutment section of Embankment 5 on 821117 Aperture card is available in PDR
SMITH, J C Pathfinder Mines Corp 82/12/20 GARCIA, P Uranium Recovery Field Office 3pp 17195 259.

8302160515 Advises that recently issued Amend 11 to License SUA-442 exempt from fees
GARCIA, P J., PETTENQILL, H J Uranium Recovery Field Office 83/01/25 MILLER, W O License Fee Management Branch 1p. 17176 309

8302220049 Advises that Amend 10 to License SUA-442 re bioassay program exempt from fees.
SOLLENBERGER, D Low Level Waste Licensing Branch, 83/01/27 MILLER, W O, License Fee Management Branch 1p. 17227:332

8302220064 Informs that Amend 12 to License SUA-442 re QA program exempt from fees
SOLLENBERGER, D Low Level Waste Licensing Branch 83/01/27. MILLER, W O, License Fee Management Branch 1p. 17234 045

DOCKET 40-7459 WHITTAKER METALS, LOS ANGELES, CA

8302070018 Informs of plans to move radioactive matls & equipment from one restricted site to another & clean original site to meet current stds for unrestricted use.
COLLINS, T J Whittaker Corp 82/12/20 CROWE, W T. Division of Fuel Cycle & Material Safety 3pp. 17065 343

DOCKET 40-8027 KERR-MCQUEEN NUCLEAR CORP , OKLAHOMA CITY, OK

8302040009 Submits addl info re chemical characteristics of lime sludge, per 830113 discussion Moisture content approx 55%. Analyses performed on as-is basis
BHELLEY, W J Kerr-McQueen Corp 83/01/18, PAGE, R O Uranium Fuel Licensing Branch 2pp 17043 304

8302080120 Notification of contract execution, "Environ Assessment re Proposed Deep Well Injection of Liquid Raffinate by Kerr-McQueen U Hexafluoride Plant," awarded to DL Warner, Inc
MURPHY, L O Purchasing Section FIN B-7387-3 83/01/31. BROWN, R B Program Support Branch WYNARDEN, B D NRC - No Detailed Affiliation Given, 1p 17105 258

--8302080123 Contract: "Environ Assessment re Proposed Deep Well Injection of Liquid Raffinate by Kerr-McQueen U Hexafluoride Plant," awarded to DL Warner, Inc
WARNER, D L Don L Warner, Inc REBELLO, J E Division of Contracts FIN B-7387-3 83/01/31 5pp 17105:259

DOCKET 40-8064 EXXON MINERALS CO, USA, HOUSTON, TX

8302160508 Forwards 1982 fourth quarter rept, per License Condition 16
SHANNON, J B Exxon Nuclear Co., Inc (subs of Exxon Corp.) 83/01/28, LINEHAN, J J Uranium Recovery Licensing Branch, 2pp 17176 310

--8302160510 Fourth Quarter Rept for 1982.
* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 83/01/28. 9pp. 17176 312

8302160127 Advises of issuance of Amend 1 to License SUA-1064, changing License Condition 17 to ensure adequate surety of reclamation performance bond, Amend exempt from fees.
KALMAN, K L., LINEHAN, J J, Uranium Recovery Field Office 83/02/04, MILLER, W O, License Fee Management Branch, 1p 17160.250

DOCKETED ITEMS

DOCKET 40-8084 RIO ALGON CORP., MOAB, UT

8302010027 Informs that amend to extend expiration date for Source Matl License SUA-1119 will allow incorporation of recent licensing policies in renewal application Amend initiated by NRC & exempt from fees
WOOLSEY, R Uranium Recovery Field Office 02/12/03 MILLER, W D License Fee Management Branch 1pp 16989 341

8302220065 Advises that Amend 17 to License SUA-1119 re tailings embankments exempt from fees
WOOLSEY, R T, PETTENIGILL, H J Uranium Recovery Field Office 03/01/28 MILLER, W D License Fee Management Branch 1p 17234 050

8302220069 Informs that Amend 18 to License SUA-1119 re deletion of bicarbonate exempt from fees
WOOLSEY, R T, PETTENIGILL, H J Uranium Recovery Field Office 03/01/28 MILLER, W D License Fee Management Branch 1p 17234 051.

8302220531 Informs that preliminary review of renewal application for License SUA-1119, per 821122 ltr, acceptable Current license valid during renewal review process
LINEHAN, J J Uranium Recovery Field Office. 03/02/01. Rio Algon. Ltd 1p 17234 353

8302070470 Forwards regional ofc ltr & notice of violation explaining why Violation I, which involves exposures of two minors to concentrations of radioactive matl in excess of Part 20 limits, is Severity Level IV category W/o encl
JOHNSON, E H Region 4, Office of Director. 03/02/02 AXELRAD, J A Enforcement Staff 1p 17037 079

DOCKET 40-8102 EXXON CO USA, HOUSTON, TX

8302090256 Reviews Exxon 820903 ALARA audit rept for Jan-June 1982 No further licensing action necessary
JONES, B Z, PETTENIGILL, H J Uranium Recovery Field Office 12/12/04. Uranium Recovery Field Office 4pp 17117.357

1100182 Notification of contract execution, Mod 4 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation Exxon Highland U Mill" Contractor CO State Univ
LEIDY, J A Technical Assistance Contracts Branch 10-02-79-031-02 03/01/04 DAVIS, J. ROSSBACH, L Office of Nuclear Material Safety & Safeguards, Director 1p 17134 186

1302100190 Mod 4, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation Exxon Highland U Mill"
BROWN, J F Colorado State Univ HAGAN, T F Division of Contracts NRC-02-79-031-02 03/01/04 1p 17134 187

12140197 Advises of issuance of Amend 4 to Exxon Minerals Co License UUA-1310, revising License Conditions 12 & 28
SMITH, R D Uranium Recovery Field Office 03/01/31 Exxon Corp 1pp 17145 322

1302140203 Recommends that Conditions 12 & 28 to License SUA-1310 be revised to include modified proposal involving insp of tailings solution return pipeline for leakage or rupture insp will reduce negative environ impact
FLEMING, T E, PETTENIGILL, H J Uranium Recovery Field Office 03/01/31 Uranium Recovery Field Office 2pp 17145 324

02170303 Submits review of Exxon Highland U Mill ground & surface water chemical parameter data for Jan-Sept 1982 Data will be used for comparison of future ground & surface water chemical parameter data
FLEMING, T E, PETTENIGILL, H J Uranium Recovery Field Office 33/02/01 Uranium Recovery Field Office 3pp 17195 347

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO., BROOMFIELD, CO

02020400 Application for amend of License SUA-1228, deleting requirements in Condition 13 for offsite quarterly audit U production operations at R&D in situ leach site have ceased.
HERSLOFF, L W Rocky Mountain Energy Co 02/12/03 KALMAN, K Uranium Recovery Licensing Branch 2pp 16999 355

302170020 Forwards 1982 fourth quarter rept per License Condition 36
SPIELES, P R Rocky Mountain Energy Co 03/01/25 SMITH, D Uranium Recovery Licensing Branch 2pp. 17176 330

--8302170021 Fourth Quarter 1982 rept
* Rocky Mountain Energy Co 03/01/25 14pp 17176 332

8302240049 Fourth Quarter 1982 environ rept for Oct-Dec 1982
SPIELES, P R Rocky Mountain Energy Co 03/01/25 SMITH, D Uranium Recovery Licensing Branch 15pp 17260 320

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

8302090034 Advises of issuance of Amend 18 to License SUA-1310, deleting continuous airborne particulate monitoring requirement at site AQ-7 by revising License Condition 49
SMITH, R D Uranium Recovery Field Office 02/12/07 Bear Creek Uranium Co 2pp 17131 344

--8302090051 Recommends rev to License Condition 49, deleting continuous airborne particulate monitoring requirement
FLEMING, T E, PETTENIGILL, H J Uranium Recovery Field Office 02/12/07 Uranium Recovery Field Office 2pp 17131 346

8302170012 Forwards "Bear Creek Tailings 1982 Annual Dam Insp Rept"
MEDLOCK, R L Rocky Mountain Energy Co 03/01/31 SMITH, D Uranium Recovery Licensing Branch 1p 17190 301

--8302170014 "Bear Creek Tailings 1982 Annual Dam Insp Rept"
* Rocky Mountain Energy Co 03/01/31 10pp 17190 302

DOCKET 40-8463 DAY & ZIMMERMAN, INC., PARSONS, KS

8302150579 IE Insp Findings & Licensee Ack dtd 830111 of License SUB-1223 Insp findings no violations observed
SPITZBERG, D B Region 4, Office of Director 03/01/20 3pp 17155 344

DOCKET 40-8502 WYOMING MINERAL CORP., LAKEWOOD, CO

8302160450 Forwards "Irigaray Mine Site Quarterly Rept, Oct-Dec 1982"
RUTLEDGE, C Wyoming Mineral Corp 03/01/25 CHANCELLOR, R Wyoming, State of 1p 17172 041

--8302160454 "Irigaray Mine Site Quarterly Rept, Oct-Dec 1982"
* Wyoming Mineral Corp 03/01/25 180pp 17172 042

8302230276 "Irigaray Mine Site Quarterly Rept, Oct-Dec 1982 (second Reporting Quarter, 1982-83)"
RUTLEDGE, C Wyoming Mineral Corp 03/01/25 CHANCELLOR, R Wyoming, State of 77pp 17242 001

8302100073 Forwards "Water Quality Data on Excursion Wells, Irigaray Mine Site, 821001-830119"
RUTLEDGE, C Wyoming Mineral Corp 03/01/27 SMITH, D Uranium Recovery Licensing Branch 2pp 17135 125

--8302100079 "Water Quality Data on Excursion Wells, Irigaray Mine Site, 821001-830119"
* Wyoming Mineral Corp 03/01/27 1p 17135 127

8302240055 Advises that all environ licensing regulatory agency liaison activities relocated from Lakewood, CO to Pittsburgh, PA Environ & agency functions will be performed by C Rutledge
RUTLEDGE, T H Wyoming Mineral Corp 03/02/04 SMITH, D Uranium Recovery Licensing Branch 1p 17268 317

DOCKET 40-8584 MINERALS EXPLORATION CO., LOS ANGELES, CA

8302030040 Provides survey of land use within 5 miles of mill site, per License Condition 33 Use continues to be limited to seasonal grazing of livestock, recreational pursuits, transient oil & gas exploration & U mining
SNYDER, H L Union 76 Minerals Exploration Co 03/01/14 SMITH, R D Uranium Recovery Field Office 1p 17026 343

8302090554 Ack receipt of 821223 submittal re concurrent review of licensee application for U mill mod If modified tailings plan provided in next few wks, technical findings can be shared by Mar 1983
ACKERMAN, W C Wyoming, State of 03/01/20 SMITH, R D Uranium Recovery Field Office 1p 17108 345

DOCKETED ITEMS

5

8302170550 Submits review of Minerals Exploration Co Second Quarter 1982 environ monitoring data for Sweetwater U Mill With one exception, no radionuclide concentrations exceeded max permissible concentrations
JOHNSON, T L, LINEHAN, J J Uranium Recovery Field Office 83/01/28
PETTENGILL, H J Uranium Recovery Field Office 3pp 17197 139

DOCKET 40-8693 OGLE PETROLEUM, INC, SANTA BARBARA, CA

8302090497 Notices of change of address, effective 830201
CATHPOLE, O J Ogle Petroleum, Inc 83/01/20 Uranium Recovery
Licensing Branch 1p 17131 353

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO, DENVER, CO

8302170015 Forwards 1982 fourth quarter rept per License Condition 29.
SPIELES, P R Rocky Mountain Energy Co 83/01/25 SMITH, D Uranium
Recovery Licensing Branch 2pp 17176 351

--8302170017 Fourth Quarter Rept for 1982
* Rocky Mountain Energy Co 83/01/25 3pp 17176 353

DOCKET 40-8698 PLATEAU RESOURCES, LTD, GRAND JUNCTION, CO

8302230422 Forwards "Effluent Monitoring Rept, Jan-June 1982"
GERDEMAN, F W Plateau Resources, Ltd 83/01/05, Region 4, Office
of Director 1p 17246 130

--8302230439 "Effluent Monitoring Rept, Jan-June 1982"
* Plateau Resources, Ltd 83/01/05 28pp 17246 131

8302230211 EN-83-009 on 830222, notice of violation & civil penalty
issued in amount of \$4,000 for failure to properly evaluate
exposures to soluble U & exposure of workers in excess of
weekly limit for soluble U
FLACK, E, AYLARD, J Director's Office, Office of Inspection and
Enforcement 83/02/16 1p 17243 192

DOCKET 40-8709 WESTINGHOUSE ELECTRIC CORP, OGDEN, UT

8302230193 Corrected IE Insp Findings & Licensee Ack dtd 830118 of
License SMB-1347 Insp findings no violations observed Steps
taken to correct violations during last insp verified
SHOPENN, N M Region 4, Office of Director 83/01/18 2pp,
17245 162

8302150037 Forwards IE Insp Findings & Licensee Ack dtd 830118 of
License SMB-1347 No violations observed
SHOPENN, N M Region 4, Office of Director 83/02/08
WORCESTER, B A Westinghouse Electric Corp, 1p 17147 128

--8302150041 IE Insp Findings & Licensee Ack dtd 830118 of License
SMB-1347 Insp findings no violations observed.
SHOPENN, N M Region 4, Office of Director 83/01/18, 1p,
17147 129

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO, CLEVELAND, OH

8302010022 Informs that termination of Permit to Construct 79-682 not
necessary since facility constructed & operated in
authorized manner, in response to 821112 ltr re process
wastewater drain field at Collins Draw Project
MUELLER, T Wyoming, State of 83/01/10 LOUDERBACK, T E
Cleveland-Cliffs Iron Co 1p 16990 361

8302100035 Forwards recent company ltr to State of WY Dept of Environ
Quality re completion of restoration at Collins Dam Project,
per 830124 discussion
LOUDERBACK, T E Cleveland-Cliffs Iron Co 83/01/25, ROSS, F, NRC -
No Detailed Affiliation Given 4pp 17135 103

DOCKET 40-8728 TETON EXPLORATION DRILLING CO, INC, CASPER, WY

8302020086 Forwards 12th Quarterly Rept for License SUA-1373 & addl
summary data sheets
APPEL, R R Teton Exploration Drilling Co, Inc 83/01/18,
SMITH, R D Division of Waste Management 1p 16996 315

--8302020089 Submits 12th Quarterly Rept for pilot in situ U operation,
License SUA-1373 Activities included continued post-
restoration M Zone stability sampling, pond water level &
detection tube measurements & radiological monitoring
APPEL, R R, GARLINO, R A Teton Exploration Drilling Co, Inc
83/01/14 SMITH, R D Division of Waste Management 28pp
16996 316

8302220487 Requests addl info to continue radiological assessment of
tailings mgt alternative study Info specified in attached
"Principal Parameters for Radiological Assessment" should be
provided by 830213
PETTENGILL, H J Uranium Recovery Field Office 83/01/28
SNYDER, H L Minerals Exploration Co (subs of Union Oil Co of
California) 1pp 17237 347

8302240047 Forwards Apps B & C of 771028 rept, "Revised Final Rept on
Design of Tailings Retention Basin, Sweetwater U Project,
Sweetwater County WY for Minerals Exploration Co,"
inadvertently omitted from amend
SNYDER, H L Union 76 Minerals Exploration Co 83/02/07 HOWARD, T
Affiliation Unknown 16pp 17268 336

DOCKET 40-8626 MORRAINE VALLEY COMMUNITY COLLEGE, PALOS HILLS, IL

8302010625 IE Insp Findings & Licensee Ack dtd 830125 of License
SMB-1304 Insp findings no violations observed
OIBONS, D R Region 3, Office of Director 83/01/25 1p
16980 323

DOCKET 40-8663 NUCLEAR DYNAMICS, INC, PHOENIX, AZ

8302240044 Confirms that samples taken by State of WY, Dept of Environ
Quality, Land Quality Div for groundwater restoration
achieved min std of quality of use for all parameters w/many
parameters at baseline
OBI, E, K M Kerr-McGee Corp 83/01/24 Kerr-McGee Corp 19pp
17287 339

DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC, DENVER, CO

8302020381 Provides addl info requested by NRC re licensee request to
suspend monitoring activities at inactive Hanksville One
Boiling Station
BAKER, C E Energy Fuels Nuclear, Inc 83/01/21 GILLEN, D NRC -
No Detailed Affiliation Given 3pp 16997 007

--8302020384 "Monitoring Rept Through Sept 1982"
* Energy Fuels Nuclear, Inc 83/01/21 30pp 16997 010

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC, DENVER, CO

8302090025 Submits costs incurred & manhours expended in reviewing
820709 application for Amend 17 to License SUA-1358
GILLEN, D Uranium Recovery Field Office 82/12/08 MILLER, W D
License Fee Management Branch 1p 17119 151

8302090507 Informs of planned curtailment of activities & eventual
shutdown at White Mesa Mill Radiation safety staff will
assure compliance w/terms & conditions of License SUA-1358
until relief from monitoring is granted
BAKER, C E Energy Fuels Nuclear, Inc 83/01/25 GILLEN, D Office
of Nuclear Material Safety & Safeguards, Director 2pp 17108 339

8302160434 Advises of fee exemption for Amend 16 to License SUA-1358
GILLEN, D M, LINEHAN, J J Uranium Recovery Field Office 83/01/28
MILLER, W D License Fee Management Branch 1p 17172 245

8302160576 Comments on Energy Fuels Nuclear 821124 transmittal of
10CFR40.190 rept for Third Quarter 1982 Dose calculations
for background location & nearest resident location
acceptable Environ monitoring data will be reviewed later
BOLLENBERGER, D, MARTIN, D E Low Level Waste Licensing Branch
83/01/28 Low Level Waste Licensing Branch 3pp 17176 292

8302230215 EN-83-010 on 830222, notice of violation & civil penalty
issued in amount of \$4,000 re failure to properly evaluate
exposures to soluble U & exposure of worker in excess of
weekly limit for soluble U
FLACK, E, AYLARD, J Director's Office, Office of Inspection and
Enforcement 83/02/16 1p 17243 191

DOCKETED ITEMS

DOCKET 40-8743 CONOCO, INC., DENVER, CO

8302010069 Advises of conditional approval of proposal for reconstruction of Wash 2 over Pit 35N tailings disposal site.
ACKERMAN, H C Wyoming, State of 82/12/15 SMITH, R D Uranium
Recovery Licensing Branch App 16995 071

8302010073 Responds to outside agency comments on Sand Rock Mill
Project discussed on 821108 Add'l info available in State
Engineers Ofc transmittal
QUIGLEY, T W CONOCO, Inc (Continental Oil Co) 83/01/05
FLEMING, T HRC - No Detailed Affiliation Given 19pp 16995-052

8302240052 Forwards documents demonstrating land control of Pit 35N
area w/o encl.
QUIGLEY, T W CONOCO, Inc (Continental Oil Co) 82/02/02
FLEMING, T H Office of Nuclear Material Safety & Safeguards, Director
1p 17268 318

DOCKET 40-8745 OGLE PETROLEUM, INC., CASPER, WY

8302010017 Proposes that second pump test be run to demonstrate no
significant hydraulic communication between ore zone aquifer
& lower sand aquifer Pump tests will be patterned after pump
tests run at Mining Unit 1
CATCHPOLE, O J Ogle Petroleum, Inc 82/12/30 SMITH, R D Uranium
Recovery Field Office 2pp 16995.001

8302090497 Notifies of change of address, effective 830201
CATCHPOLE, O J Ogle Petroleum, Inc 83/01/20 Uranium Recovery
Licensing Branch 1p 17131 353

8302160412 Informs that OJ Catchpole has replaced OJ Hartman as
president & manager of mining at Bison Basin Mine
CATCHPOLE, O J Ogle Petroleum, Inc 83/01/21 SMITH, R D Uranium
Recovery Field Office 1p 17172 348

2170010 Provides trip rept of 830117 meeting w/Ogle Petroleum, Inc in
Denver, Co re Ogle 821230 proposal to conduct second Mining
Unit 2 aquifer pumping test
WILLIAMS, R E R E Williams & Associates, Inc 83/01/24 ROSS, F
Division of Waste Management 3pp 17176 358

2160418 Summary of 830117 meeting w/Ogle Petroleum, Inc in Denver, CO
a proposal to conduct second Mining Unit 2 aquifer pumping
test & to determine acceptable pump test methodology
ROSS, F W, LINEHAN, J J Uranium Recovery Field Office 83/01/25
Uranium Recovery Field Office App 17172 222

J 2090883 Forwards "Analysis of Mining Unit 2 Aquifer Test Data Using
Hantush Leaky Aquifer Techniques," per 830117 meeting w/NRC
consultants in Denver, Co
CATCHPOLE, O J Ogle Petroleum, Inc 83/01/27 SMITH, R D Uranium
Recovery Licensing Branch 1p 17121 275

- 1302090597 "Analysis of Mining Unit 2 Aquifer Test Data Using Hantush
Leaky Aquifer Techniques"
HOFFMAN, G L, PLAYTON, S J Hydro-Engineering 83/01/31 20pp
17137 177

2170299 Advises that Amend 14 to License SUA-1396 requiring Ogle
Petroleum, Inc to maintain bonds for reclamation,
decommissioning & restoration issued & is exempt from fees
YOUNG, Y A, LINEHAN, J J Uranium Recovery Field Office 83/01/28
MILLER, W D License Fee Management Branch 1p 17193 351.

DOCKET 40-8768 KERR-McCOE NUCLEAR CORP., OKLAHOMA CITY, OK

2170547 Submits review of ALARA rept for Kerr-McCoe O Sand ISL R&D
Project for period Mar-Aug 1982 Personnel exposures to
radon averaged less than applicable limits
WESTBROOK, K B, LINEHAN, J J Uranium Recovery Field Office
83/01/28 Uranium Recovery Field Office 5pp 17197 134

2160429 Lists contract costs incurred & manhours expended in
reviewing 820528 application for Amend 8 to License
SUA-1387
WESTBROOK, K B, LINEHAN, J J Uranium Recovery Field Office 83/02/01
MILLER, W D License Fee Management Branch 1p 17172 248

DOCKET 40-8779 ARMY, DEPT OF, TOOELE, UT

8302230287 IE Insp Findings & Licensee Ack dtd 830119 of Licensee
SUC-1371 Insp findings no violations observed
SHOPEAN, N M Region 4, Office of Director 83/01/19 2pp
17244 337

DOCKET 40-8783 URANERZ USA, INC., CASPER, WY

8302030035 Forwards data comparing in-house lab to contract lab, per
request
SONERVILLE, K O Uranerz USA, Inc 83/01/20 YOUNG, Y Uranium
Recovery Licensing Branch 4pp 17023 351

8302170301 Documents review of Uranerz USA, Inc 1982 third quarterly
rept on preoperational activities License condition
requirements met No further action required
YOUNG, Y A, LINEHAN, J J Uranium Recovery Field Office 83/01/24
Uranium Recovery Field Office 1p 17195 350

DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX

8302090210 Responds to 820812 ltr re fluid balance data, missing
monitoring data & as-built drawings for evaporation ponds
Preoperational & first quarter operational radon data should
be submitted within 30 days
LINEHAN, J J Uranium Recovery Field Office 82/12/02 Uranium
Resources, Inc 2pp 17132 065

8302160411 Forwards "U Resources, Inc North Platte Project Quarterly
Rept. 820715-821015"
PELIZZA, M S Uranium Resources, Inc 82/12/16 LINEHAN, J J
Uranium Recovery Licensing Branch 1p 17172 349

--8302160413 "U Resources, Inc North Platte Project Quarterly Rept,
820715-821015"
" Uranium Resources, Inc 82/12/16 63pp 17172 350

8302090185 Advises of issuance of Amend 6 to U Resources, Inc Source
Material License SUA-1400, modifying License Condition 17 re
restoration of production aquifer & other groundwaters
SMITH, D Region 4, Office of Director 83/01/03 Uranium
Resources, Inc 2pp 17132 094

8302030027 Forwards S McArt Eberline Radiation Protection Course
diploma & resume McArt also completed US Mine Safety &
Health Administration Radiation Protection Course
PELIZZA, M S Uranium Resources, Inc 83/01/06 LINEHAN, J J
Uranium Recovery Field Office 4pp 17028 356

8302030031 Responds to 821217 ltr Fluid level data for Well SM-1
intentionally not plotted for 820428 so presence would not
interfere w/overall water level trend displayed by graph
PELIZZA, M S Uranium Resources, Inc 83/01/06 LINEHAN, J J
Uranium Recovery Field Office 8pp 17028 348

8302160426 Lists contract costs incurred & manhours expended in
reviewing 820219 application for Amend 4 to License
SUA-1400
WESTBROOK, K B, LINEHAN, J J Uranium Recovery Field Office 83/02/01
MILLER, W D License Fee Management Branch 1p 17172 250

8302160427 Lists contract costs incurred & manhours expended in
reviewing 820208 application for Amend 3 to License
SUA-1400
WESTBROOK, K B, LINEHAN, J J Uranium Recovery Field Office 83/02/01
MILLER, W D License Fee Management Branch 1p 17172 249

8302160119 Advises of fee exemption for Amend 6 to License SUA-1400,
changing License Condition 17 to rescind requirement of
NRC written approval prior to starting & stopping specified
post-restoration groundwater stability monitoring
WESTBROOK, K B, LINEHAN, J J Uranium Recovery Field Office
83/02/02 MILLER, W D License Fee Management Branch 1p
17160 254

DOCKET 40-8787 MICHIGAN, UNIV OF, ANN ARBOR, MI

8302150126 IE Insp Findings & Licensee Ack dtd 830124-28 of Licensee
21-00215-04, 21-00215-05, SNM-1377, SNM-1529, SNM-1835 &
BUD-1398 Insp findings no violations observed
MULLAUER, J R Region 3, Office of Director 83/01/28 1p
17148 001

DOCKETED ITEMS

7

DOCKET 40-8792 EDISON INSTITUTE, DEARBORN, MI

B302180246 IE Insp Findings & Licensee Ack dtd B30210 of Licensee
SUC-1406 Insp findings no violations observed
SIMMONS, F Region 3, Office of Director 83/02/10 1p 17215 263

DOCKET 40-8798 HITCHCOCK INDUSTRIES, INC, MINNEAPOLIS, MN

B302010496 Ack receipt of B30119 ltr informing NRC of steps taken to
correct noncompliance noted in B21227 ltr re License
SMB-1404
WIEDEMAN, D O Region 3, Office of Director 83/01/28 GIRTZ, W M
Hitchcock Industries, Inc 1p 16977 034

--B302010502 Responds to NRC B21227 ltr re noncompliance noted in IE insp
on B21215 of License SMB-1404 Corrective actions Social
Security numbers submitted to monitoring svc on B30118 for
film badge exposure records
GIRTZ, W M Hitchcock Industries, Inc 83/01/19 WIEDEMAN, D O
Region 3, Office of Director 1p 16977 035

DOCKET 40-8799 UOYLITE/SEL-REX, WARREN, MI

B301290608 Discusses IE insp of License SMB-1405 on B30104 No
noncompliance noted. Major areas inspected procedures &
representative records, observations, independent measurements
& interviews w/personnel re radiation safety
SRENIANSKI, D Division of Engineering 83/01/19 GILSDORF, C
Hooker Chemical Co 1p 16904 358

DOCKET 40-8822 OMAHA PUBLIC POWER DISTRICT, OMAHA, NE

B302040026 Forwards summary of detailed analysis of potential effects
of U hexafluoride release on control room habitability, per
NRC B20903 ltr re issuance of License BMC-1420 for storing
U hexafluoride onsite
JONES, W C Omaha Public Power District 83/01/03 CLARK, R A
Operating Reactors Branch 3 4pp 17043 271

DOCKET 40-8829 WYOMING FUEL CO, LAKEWOOD, CO

B302220572 Forwards application for R&D source matl license for Crow
Butte U Project Fee encl
JONES, P C Wyoming Fuel Co 83/02/09 LINEHAN, J. Licensing Branch
1 2pp 17261 149

--B302220580 Vols I & II of application for R&D source matl license
for Crow Butte U Project Application fee encl W/16
oversize figures, Supporting documentation encl. Aperture
cards are available in PDR
* Wyoming Fuel Co 83/02/11, 500pp 17261 151

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B302220490 Forwards preliminary "Emergency Preparedness Evaluation
Rept." Plan requires extensive mod & addl info to resolve
inadequacies. Info should be resubmitted by B30315
THOMAS, C D Standardization & Special Projects Branch, 83/02/08
KERR, W F Michigan Univ of 2pp 17237 317 24X
Fiche 50-002, 83/02/08, B302220490

--B302220492 Preliminary "Emergency Preparedness Evaluation Rept.,"
* Division of Emergency Preparedness (Pre B30103) 83/01/31
21pp 17237 319 24X Fiche 50-002, 83/02/08, B302220490

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B302070216 Forwards revised Chapters 1-4 to safeguards contingency
plan, Rev withheld (ref 10CFR2 790 & 10CFR73.21)
O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/01/28
VAROA, S A. Operating Reactors Branch 1, 2pp. 17031.322 24X
Fiche 50-003, 83/01/28, B302070216.

B302040018 Releases public version of page changes to emergency plan
FELTON, J M Division of Rules and Records 83/01/31, Document
Management Branch 1p 17043 279 24X Fiche 50-003, 83/01/31,
B302040018

--B302040020 Forwards public version of page changes to emergency
plan, App A re site emergency roster
O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/01/10
HAYNES, R C Region 1, Office of Director 2pp 17043.280 24X
Fiche 50-003, 83/01/31, B302040018

--B302040025 Public version of page changes to emergency plan, App A re
site emergency roster
* Consolidated Edison Co of New York, Inc. 82/12/07 14pp
17043 282 24X Fiche 50-003, 83/01/31, B302040018

B301210340 Generic Ltr B3-04 to all licensees of operating reactors,
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340

B302080420 Responds to CF Soutar B21118 ltr re Rev 2 to security force
training & qualification plan, Changes consistent w/
provisions of 10CFR50.54(p) & do not decrease effectiveness
of plan
VAROA, S A Operating Reactors Branch 1 83/02/01, O'TOOLE, J
Consolidated Edison Co of New York, Inc 2pp 17074.327. 24X
Fiche 50-003, 83/02/01, B302080420

H General correspondence

B302240066 FOIA request for all prior & partial prior drafts & memos
of probabilistic safety study
BLUM, J M Union of Concerned Scientists 82/12/28, FELTON, J.
Division of Rules and Records 1p 17285.001 24X
Fiche 50-003, 82/12/28, B302240066

P Operating license stage documents & correspondence

B302010715 Forwards corrected Tech Spec Tables 4.4-1 submitted on
B21211 w/Amends 31 & 82 to Licenses DPR-5 & DPR-26,
respectively.
POLK, R J Operating Reactors Branch 1 83/01/12 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 3pp 16989.244 24X
Fiche 50-003, 83/01/12, B302010715

--B302010718 Corrected pages to Amends 31 & 82 to Licenses DPR-5 &
DPR-26, respectively, revising Table 4.4-1 (Page 8 of 14) &
Table 4.4-1 (Page 9 of 14) re containment isolation valves.
* Operating Reactors Branch 1, 83/01/12, 2pp. 16989 247 24X
Fiche 50-003, 83/01/12, B302010715

B302240073 Partial response to FOIA request for all prior & partial
prior drafts & memos of probabilistic safety study Forwards
documents listed in app Search for addl records in progress
FELTON, J M Division of Rules and Records 83/01/13, BLUM, J M
Union of Concerned Scientists 2pp 17285.002 24X
Fiche 50-000, 83/01/13, B302240073

--B302240082 "Accumulator Sys." revised draft chapter for PRA.
* Pickard, Lowe & Garrick, Inc. 81/01/06, 14pp. 17285.004 24X
Fiche 50-006, 83/01/13, B302240073

--B302240089 "Reactor Protection Sys." revised draft chapter for PRA.
* Pickard, Lowe & Garrick, Inc. 81/01/06 27pp 17285.018 24X
Fiche 50-000, 83/01/13, B302240073

B302240188 Addl response to FOIA request for all prior draft & partial
drafts of probabilistic safety study & all memos pertaining
to drafts, Documents available in PDR w/exception of Israel
to Hickman B01105 ltr
FELTON, J M Division of Rules and Records, 83/01/20 BLUM, J M.
Union of Concerned Scientists, 1p 17288.002, 24X
Fiche 50-003, 83/01/20, B302240188.

B302170316 Application to amend Licenses DPR-5 & DPR-26, revising Apps
A & B radiological effluent Tech Specs to omit 10CFR40.190
compliance requirement re U fuel cycle total dose.
O'TOOLE, J D Consolidated Edison Co. of New York, Inc 83/02/01.
VAROA, S A. Operating Reactors Branch 1, 2pp. 17184.004 24X
Fiche 50-003, 83/02/01, B302170316

--B302170317 Proposed Tech Spec changes re U fuel cycle total dose per
10CFR40.190 compliance requirement.
* Consolidated Edison Co of New York, Inc. 83/01/31, 93pp.
17184.006 24X Fiche 50-003, 83/02/01, B302170316

DOCKETED ITEMS

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

--8302220522 Provides preliminary acceptance of emergency procedure guidelines for implementation in plant-specific emergency procedures & outlines requirements for addl work
EISENHUT, D O Division of Licensing 83/02/04 WELLG, R W C-E
Operating Plants Owners Group 4pp 17290 249 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358.

8212060360 IE Info Notice 83-02, "Litorque H08C, H18C, H28C & H30C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

12060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

12060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

12060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

Operator Examinations

01310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

CKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

Security, medical, emergency & fire protection plans

8302180235 Forwards IE Safeguards Insp Repts 50-005/83-01 & 70-0113/83-01 on 830110-14 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/07
Pennsylvania State Univ 2pp 17212 085 24X
Fiche 50-005, 83/02/07, 8302180235

--8302180241 IE Safeguards Insp Repts 50-005/83-01 & 70-0113/83-01 on 830110-14 No noncompliance noted Major areas inspected nuclear matl control & accounting, physical inventory & verification & records & repts
ZIBULSKY, H Region 1, Office of Director GDDY, A T Region 4,
Office of Director 83/02/04 8pp 17212 087 24X
Fiche 50-005, 83/02/07, 8302180235

G Inspection reports, IE Bulletins & correspondence

8302180235 Forwards IE Safeguards Insp Repts 50-005/83-01 & 70-0113/83-01 on 830110-14 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/07
Pennsylvania State Univ 2pp 17212 085 24X
Fiche 50-005, 83/02/07, 8302180235

--8302180241 IE Safeguards Insp Repts 50-005/83-01 & 70-0113/83-01 on 830110-14 No noncompliance noted Major areas inspected nuclear matl control & accounting, physical inventory & verification & records & repts
ZIBULSKY, H Region 1, Office of Director GDDY, A T Region 4,
Office of Director 83/02/04 8pp 17212 087 24X
Fiche 50-005, 83/02/07, 8302180235

R Periodic operating reports & related correspondence

8302280188 Forwards "Twenty-Seventh Annual Progress Rept of PA State Univ Breasale Nuclear Reactor, Jul 1981 - June 1982 " Minor changes made at facility during CY82 listed
CUNNINGHAM, R O Pennsylvania State Univ 83/02/22 Director's
Office, Office of Inspection and Enforcement 1p 17312 287 24X
Fiche 50-005, 83/02/22, 8302280188

--8302280192 "Twenty-Seventh Annual Progress Rept of PA State Univ Breasale Nuclear Reactor, Jul 1981 - June 1982 " LEVINE, S H, TOTENBER, R E Pennsylvania State Univ 82/07/31
58pp 17312 288 24X Fiche 50-005, 83/02/22, 8302280188

DBCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs
PAJOWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC
No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs Revised index encl
LITERSKI, L A, PAJOWSKI, J E Commonwealth Edison Co 83/01/06
11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8302020458 Releases public version of revised Emergency Plan Implementing Procedure
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 16999 288 24X Fiche 50-010, 83/01/31, 8302020458

--8302020470 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 100-C11, "Environ Director (Checklist of Initial Generating Station Emergency Plan Responsibilities) " Receipt form encl
SCOTT, D J Commonwealth Edison Co 83/01/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 16999 289 24X
Fiche 50-010, 83/01/31, 8302020458

--8302020479 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 100-C11, "Environ Director (Checklist of Initial Generating Station Emergency Plan Responsibilities) " * Commonwealth Edison Co 83/01/03 6pp 16999 292 24X
Fiche 50-010, 83/01/31, 8302020458

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-111B guidelines valid
KEPPLER, J O Region 3, Office of Director 83/02/04 REED, C
Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

DOCKETED ITEMS

9

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPLER, J O Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302250358 Forwards IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/08 REED, C Commonwealth Edison Co 2pp 17291 154 24X Fiche 50-010, 83/02/08, 8302250358

--8302250244 IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted Major areas inspected emergency preparedness program, licensee actions on previously identified items & emergency plan
PHILLIPS, M P, OLGERSEN, W B, AXELSON, W L Division of Emergency Preparedness & Operational Support 83/02/03 16pp 17291 156 24X Fiche 50-010, 83/02/08, 8302250358

8302180447 Forwards IE Safeguards Insp Rept 50-010/83-04 on 830126-28 No noncompliance noted
MILLER, J R Division of Engineering 83/02/09 REED, C Commonwealth Edison Co 2pp 17208 196 24X Fiche 50-010, 83/02/09, 8302180447

--8302180451 IE Safeguards Insp Rept 50-010/83-04 on 830126-28 No noncompliance noted Major areas inspected facility organization & operation, measurement & controls & storage & internal controls Details withheld (ref 10CFR2 790)
MADEBA, T J, PIRTLE, O L, CREED, J R Division of Engineering 83/02/09 1p 17208 198 24X Fiche 50-010, 83/02/09, 8302180447

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOF-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOF-2, "Technical Support Manager"
NELLIS, C A, FLESSNER, R A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302180494 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records, 83/02/15 Document Management Branch 1p 17221 323 24X Fiche 50-010, 83/02/15, 8302180494

--8302180498 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-7, "Personnel Decontamination (Medical - Decontamination Area) (Primary Responsibility - Rad/Chem Director)"
SCOTT, D J Commonwealth Edison Co 83/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17221 324 24X Fiche 50-010, 83/02/15, 8302180494

--8302180508 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-7, "Personnel Decontamination (Medical - Decontamination Area) (Primary Responsibility - Rad/Chem Director)" Revised index encl
* Commonwealth Edison Co 83/01/12 12pp 17221 327 24X Fiche 50-010, 83/02/15, 8302180494

P Operating license stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08, Consolidated Edison Co of New York, Inc 1pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re BER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

--8302220204 Forwards SER re GE Topical Rept NEDO-24934, "Emergency Procedure Guidelines, Rev 2" Guidelines acceptable for implementation
EISENHUT, D O Division of Licensing 83/02/04 DENTON, T C-E Operating Plants Owners Group 2pp 17234 247 24X Fiche 50-000, 83/02/08, 8302080301

--8302220209 Safety evaluation of NEDO-24934, "Emergency Procedure Guidelines, Rev 2" Rept acceptable
* Office of Nuclear Reactor Regulation, Director 83/02/04 43pp 17234 249 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302230125 Ack receipt of 830111 ltr re qualifications of radiochemistry supervisory staff per ANSI Std N18 1-1971 T Gilman qualified as lead chemist, B McDonald will attend class to qualify as lead health physicist
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/16 SCOTT, D J Commonwealth Edison Co, 2pp, 17237 007 24X Fiche 50-010, 83/02/16, 8302230125

--8302230130 Responds to NRC request to document basis for qualifications of radiochemistry staff per ANSI Std N18 1-1971 Lead chemist need not meet 2-yr experience requirement.
SCOTT, D J Commonwealth Edison Co 83/01/11 OREGON, R L Region 3, Office of Director, 5pp 17237 009 24X Fiche 50-010, 83/02/16, 8302230125

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency.
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30, HIATT, S L, Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040032 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque HOBC, H18C, H28C & H38C Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp, 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302040294 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-16, 50-237/82-23 & 50-249/82-23
NORELIUS, C E Division of Project & Resident Programs 83/02/01, REED, C Commonwealth Edison Co 1p 17017 347 24X Fiche 50-010, 83/02/01, 8302040294

--8302040302 Responds to NRC 821222 ltr re violations noted in IE Insp Repts 50-010/82-16, 50-237/82-23 & 50-249/82-23 Corrective actions new computer installation & removal of computer console at station operator desk scheduled for Spring 1983.
DELGOURGE, L O Commonwealth Edison Co 83/01/21, KEPLER, J O, Region 3, Office of Director 2pp 17017 348 24X Fiche 50-010, 83/02/01, 8302040294

DOCKETED ITEMS

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin B1-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels".
BHARTI, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000, 83/02/08, 8302150528

8302250358 Forwards IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted.
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/08 REED, C Commonwealth Edison Co 2pp 17291 154 24X Fiche 50-010, 83/02/08, 8302250358

--8302250364 IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted. Major areas inspected emergency preparedness program licensee actions on previously identified items & emergency plan.
PHILLIPS, M P, PLOSKI, T J, SNELL, W O Division of Emergency Preparedness & Operational Support 83/02/03 16pp 17291 156 24X Fiche 50-010, 83/02/08, 8302250358

8302180447 Forwards IE Safeguards Insp Rept 50-010/83-04 on 830126-28 No noncompliance noted.
MILLER, J R Division of Engineering 83/02/09 REED, C Commonwealth Edison Co 2pp 17208 196 24X Fiche 50-010, 83/02/09, 8302180447

--8302180451 IE Safeguards Insp Rept 50-010/83-04 on 830126-28 No noncompliance noted. Major areas inspected facility organization & operation, measurement & controls & storage & internal controls. Details withheld (ref 10CFR2 790).
MAEDA, T J, PIRTLE, G L, CREED, J R Division of Engineering 83/02/09 1p 17208 198 24X Fiche 50-010, 83/02/09, 8302180447

8312060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units".
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8312060363

8312060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302".
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 110pp 17347 058 24X Fiche 50-000, 83/02/24, 8312060365

8312060366 IE Info Notice 83-06, "Nonidentical Replacement Parts".
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8312060366

Operator Examinations

101310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DL, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-29 YANKEE-ROQUE NUCLEAR POWER STATION

2. Security, medical, emergency & fire protection plans

8302010713 Advises that changes in security plan outlined in util B21101 ltr acceptable Encl to B21101 ltr withheld (ref 10CFR73 21).
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/28 KAY, J A Yankee Atomic Electric Co 2pp 16989 249 24X
Fiche 50-029, 83/01/28, 8302010713

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability". Svc list encl.
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302040600 Releases public version of revised emergency plan.
FELTON, J M Division of Rules and Records 83/02/02 Document Management Branch 1p 17042 046 24X Fiche 50-029, 83/02/02, 8302040600

--8302040605 Forwards public version of Rev 3 to emergency plan.
MARKT, D Yankee Atomic Electric Co 83/01/23 NRC - No Detailed Affiliation Given 2pp 17042 047 24X
Fiche 50-029, 83/02/02, 8302040600

--8302040609 Public version of Rev 3 to emergency plan.
* Yankee Atomic Electric Co 83/01/31 150pp 17042 049 24X
Fiche 50-029, 83/02/02, 8302040600

8302090310 Responds to 830113 ltr re splitting annual full-scale emergency exercise into two phases. Proposed change to emergency plan exercise acceptable, provided one fully integrated exercise conducted within each 3-yr period.
MARTIN, T T Division of Engineering & Technical Programs 83/02/02 HEIDER, L H Yankee Atomic Electric Co 1p 17071 017 24X
Fiche 50-029, 83/02/02, 8302090310

--8302090313 Requests review & consideration of proposed change to emergency plan exercise concept & format. Change consists of separately testing onsite & offsite emergency preparedness together w/ state interface & interaction.
HEIDER, L H Yankee Atomic Electric Co 83/01/13 HAYNES, R C Region 1, Office of Director 4pp 17071 018 24X
Fiche 50-029, 83/02/02, 8302090310

8302090330 Requests that licensee submit three copies of emergency plans & procedures, despite recent amend to 10CFR50 54(q) which requires licensee to submit only one copy to regional administrator.
MARTIN, T T Division of Engineering & Technical Programs 83/02/02 HEIDER, L H Yankee Atomic Electric Co 2pp 17071 001 24X
Fiche 50-029, 83/02/02, 8302090330

8302280496 Ack receipt of 830113 ltr informing NRC of addl info re steps taken to correct violations noted in IE Safeguards Insp Rept 50-029/81-04.
MARTIN, T T Division of Engineering & Technical Programs 83/02/23 HEIDER, L H Yankee Atomic Electric Co 1p 17309 125 24X
Fiche 50-029, 83/02/23, 8302280496

--8302280505 Clarifies util B10429 response to NRC B10413 ltr re violations noted in IE Safeguards Insp Rept 50-029/81-04 Encl withheld (ref 10CFR2 790).
HEIDER, L H Yankee Atomic Electric Co 83/01/13 HAYNES, R C Region 1, Office of Director 1p 17309 126 24X
Fiche 50-029, 83/02/23, 8302280496

P Operating license stage documents & correspondence

8302020130 Forwards draft Integrated Plant Safety Assessment Rept, Chapter 4, "Integrated Assessment Summary," "Risk Based Categorization of Yankee SEP Issues" & review of operating experience.
RUSSELL, W T Systematic Evaluation Program Branch 83/01/27 SEISS, C P ACRS - Advisory Committee on Reactor Safeguards 410pp 16997 150 24X Fiche 50-029, 83/01/27, 8302020130

--8302020136 "Risk-Based Categorization of Yankee SEP Issues".
AMICO, P, ATEFI, B, FERRELL, W Science Applications, Inc SAI-B3-115-WA 82/12/22 NRC - No Detailed Affiliation Given 116pp 16997 257 24X Fiche 50-029, 83/01/27, 8302020130

--8302020139 Review of Operating Experience History of Yankee Nuclear Power Station Through 1991 for NRC SEP.
CRAWFORD, A B, HARRINGTON, K H, CASADA, M L Oak Ridge National Laboratory ORNL/NSIC-204 83/01/31 Office of Nuclear Reactor Regulation, Director 187pp 16998 013 24X
Fiche 50-029, 83/01/27, 8302020130

8302070485 Forwards final SER re SEP Topic III-6, "Seismic Design Considerations". Plant capable of withstanding postulated seismic loads except for certain portions of structures, piping sys & mechanical & electrical equipment.
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/01 KAY, J A Yankee Atomic Electric Co 3pp 17039 226 24X
Fiche 50-029, 83/02/01, 8302070485

--8302070492 Safety evaluation re SEP Topic III-6, "Seismic Design Considerations". Facility generally capable of withstanding seismic loads w/ listed exceptions.
+ Office of Nuclear Reactor Regulation, Director 83/02/01 389pp 17039 229 24X Fiche 50-029, 83/02/01, 8302070485

--8302070499 "Local Soil Amplification Effects at Yankee Nuclear Plant Site, Rowe, MA".
VAN MARCKE, E, KAUSEL, E, BOUCHON, M Weston Geophysical Corp 82/03/31 113pp 17040 249 24X Fiche 50-029, 83/02/01, 8302070485

8302080157 Requests addl info to complete review of environmental qualification of safety-related electrical equipment. High energy line breaks outside containment necessitate review info requested within 30 days.
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/01 KAY, J A Yankee Atomic Electric Co 2pp 17058 361 24X
Fiche 50-029, 83/02/01, 8302080157

DOCKETED ITEMS

11

8302190045 Responds to NRC 821216 SER re environ qualification of safety-related electrical equipment Info corresponds to technical evaluation rept Categories I B, II A & II B
KAY, J A Yankee Atomic Electric Co 83/02/01 EISENHUT, D G, Division of Licensing 2pp 17147 124 24X Fiche 50-029, 83/02/01, 8302190045

8302070426 Summary of 830119-20 meetings w/util onsite re safety parameter display sys installation
DICK, O F, LYONS, J E Operating Reactors Branch 5 83/02/02 Operating Reactors Branch 5 6pp 17029 292 24X Fiche 50-029, 83/02/02, 8302070426

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08, Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302190318 Advises that NURE0-0737, Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," resolved Util analyses of LOFI Test L3-6 acceptable
EISENHUT, D G Division of Licensing 83/02/09 KAY, J A Yankee Atomic Electric Co 17pp 17148 203 24X Fiche 50-029, 83/02/09, 8302190318,

8302160296 Requests response to Generic Ltr 82-16 re NURE0-0737 Tech Specs within 60 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/10 KAY, J A Yankee Atomic Electric Co 2pp 17170 158 24X Fiche 50-029, 83/02/10, 8302160296

8302280282 Forwards addl info on NURE0-0737, Item II B 3, "Post-Accident Sampling," per 820804 request
KAY, J A Yankee Atomic Electric Co. 83/02/14 CRUTCHFIELD, D Operating Reactors Branch 5 16pp 17292 268 24X Fiche 50-029, 83/02/14, 8302280282

G Inspection reports, IE Bulletins & correspondence

8302010391 Informs that no Bunker-Ramo electrical penetrations which use hard epoxy module design installed or planned to be installed in safety-related sys at facility per IE Bulletin 82-04
HEIDER, L H Yankee Atomic Electric Co 83/01/13 HAYNES, R C Region 1, Office of Director 1p 16973 260 24X Fiche 50-029, 83/01/13, 8302010391

8302030574 Forwards IE Insp Rept 50-029/82-16 on 821213-20 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/21 HEIDER, L H Yankee Atomic Electric Co 2pp. 17008 016 24X Fiche 50-029, 83/01/21, 8302030574

--8302030581 IE Insp Rept 50-029/82-16 on 831213-20 No noncompliance noted Major areas inspected, Core XV & XVI post-refueling startup test rept, precritical checks & tests, zero power & power escalation test mods & control room tours
PETRONE, C, WEN, P, NORRHOLM, L Division of Engineering & Technical Programs 83/01/19 11pp 17008 018 24X Fiche 50-029, 83/01/19, 8302030574,

8302070344 Forwards IE Insp Rept 50-029/82-15 on 821116-1231 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/24 HEIDER, L H Yankee Atomic Electric Co 2pp 17029 234 24X Fiche 50-029, 83/01/24, 8302070344

--8302070346 Notice of violation from insp on 821116-1231
* Division of Project & Resident Programs 83/01/24, 2pp 17029 236 24X Fiche 50-029, 83/01/24, 8302070344,

--8302070357 IE Insp Rept 50-029/82-15 on 821116-1231 Noncompliance noted, failure to perform safety evaluations for sys mods associated w/incore instrumentation flux thimble paths & waste disposal sys instrumentation.
COLLINS, B J, OALLO, R M. Division of Project & Resident Programs 83/01/11, 17pp 17029, 238 24X Fiche: 50-029, 83/01/24, 8302070344

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiter torque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche: 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150686 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Procedures in place covering all facets of bolting/stud practices on bolted closures in RCPB All bolting cleaned prior to insp
HEIDER, L H Yankee Atomic Electric Co 83/01/31 HAYNES, R C Region 1, Office of Director 2pp 17194 113 24X Fiche 50-029, 83/01/31, 8302150686

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302280496 Ack receipt of 830113 ltr informing NRC of addl info re steps taken to correct violations noted in IE Safeguards Insp Rept 50-029/81-04
MARTIN, T T Division of Engineering & Technical Programs. 83/02/23 HEIDER, L H Yankee Atomic Electric Co 1p 17309 125, 24X Fiche 50-029, 83/02/23, 8302280496

--8302280505 Clarifies util B10429 response to NRC B10413 ltr re violations noted in IE Safeguards Insp Rept 50-029/81-04. Encl withheld (ref 10CFR2 790)
HEIDER, L H Yankee Atomic Electric Co 83/01/13 HAYNES, R C Region 1, Office of Director 1p 17309 126 24X Fiche 50-029, 83/02/23, 8302280496

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp. 17347 058, 24X Fiche: 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148, 24X Fiche. 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302230124 Forwards LER 83-001/03L-0
AUSTIN, H A Yankee Atomic Electric Co 83/02/06 HAYNES, R C, Region 1, Office of Director, 1p 17243 313 24X Fiche 50-029, 83/02/06, 8302230124

--8302230129 LER 83-001/03L-0 on 830106, relays K11A & K11B on main steam line 1 did not operate Caused by lack of continuity through terminal block TB-2 B Block replaced
RICE, D A Yankee Atomic Electric Co 83/02/04 Region 1, Office of Director 1p 17243 314 24X Fiche 50-029, 83/02/06, 8302230124

T Hearing transcripts on non-antitrust matters

8302250085 Transcript of ACRB SEP Subcommittee 830223 meeting in Washington, DC Pp 1-293 Supporting documentation encl.
* ACRB - Advisory Committee on Reactor Safeguards 83/02/23 395pp 17294 115 24X Fiche: 50-029, 83/02/23, 8302250085

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G, Division of Licensing 83/01/31, Consolidated Edison Co of New York, Inc 14pp 17347: 177, 24X Fiche. 50-000, 83/01/31, 8301310203

--B302150438 Responds to NRC 821215 ltr re violations noted in IE Insp Rept 50-124/82-01 Corrective actions procedure initiated for reactor audit & review & SAR will be submitted to radiation safety committee re manual control rod withdrawal
PARKINSON, T F Virginia Polytechnic Institute 83/01/11
LEWIS, R C Division of Project & Resident Programs 12pp
17158 206 24X Fiche 50-124, 83/01/27, 8302150434

--B302150446 Forwards IE Insp Rept 50-124/82-01 on 821117-19 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/12/15
PARKINSON, T F Virginia Polytechnic Institute 2pp 17158 218
24X Fiche 50-124, 83/01/27, 8302150434

--B302150453 Notice of violation from Insp on 821117-19
* Division of Project & Resident Programs 82/12/15 1p
17158 220 24X Fiche 50-124, 83/01/27, 8302150434

--B302150461 IE Insp Rept 50-124/82-01 on 821117-19 Noncompliance noted failure to perform 1981 annual audit of reactor operations & failure of radiation safety committee to review procedure re manual withdrawal of control rod
HARDIN, A K, HEHL, C W, DENIS, P R Division of Project & Resident Programs 82/12/14 5pp 17158 221 24X Fiche 50-124, 83/01/27, 8302150434

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B302150565 Forwards IE Safeguards Insp Rept 50-128/83-01 on 830103-07
No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/09 BERO, R R Texas A&M Univ, College Station, TX 2pp 17156 124 24X Fiche 50-128, 83/02/09, 8302150565

--B302150582 IE Safeguards Insp Rept 50-128/83-01 on 830103-07 No noncompliance noted Major areas inspected security plan/ implementing procedures, security organization, records & repts, testing & maint Details withheld (ref 10CFR73 21)
CALDWELL, R A, KELLY, J A Division of Resident, Reactor Project & Engineering Programs 83/02/01 1p 17156 126 24X
Fiche 50-128, 83/02/09, 8302150565

B302230501 Forwards IE Safeguards Insp Repts 50-128/83-02 & 70-1936/83-02 on 830103-07 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/17 BERO, R R Texas A&M Univ, College Station, TX 2pp 17257 243 24X Fiche 50-128, 83/02/17, 8302230501

--B302230517 IE Safeguards Insp Repts 50-128/83-02 & 70-1936/83-02 on 830103-07 No noncompliance noted Major areas inspected nuclear mat'l control & accountability measurement & controls & shipping & receiving Details withheld (ref 10CFR2 790)
CALDWELL, R A, KELLY, J A Division of Resident, Reactor Project & Engineering Programs 83/02/14 1p 17257 245 24X
Fiche 50-128, 83/02/17, 8302230501

P Operating license stage documents & correspondence

B302010592 Forwards experimental pulse test program for full FLIP TRIQA core for review & approval Program involves measurement of pulse core parameters necessary to establish operational pulsing core Fuel insp program included in program
FELTZ, D E Texas A&M Univ, College Station, TX 83/01/21
THOMAS, C D Standardization & Special Projects Branch 3pp
16978 104 24X Fiche 50-128, 83/01/21, 8302010592

--B302010607 Draft "Nuclear Science Ctr Reactor Post-Damage Test Program for Full FLIP TRIQA Core"
WATSON, R L Texas A&M Univ, College Station, TX 83/01/31
20pp, 16978 107 24X Fiche 50-128, 83/01/21, 8302010592

B302140131 Suppl to Jul 1979 application for renewal of License R-83, consisting of proposed changes to Tech Spec 3 B re primary coolant conditioning
FELTZ, D E Texas A&M Univ, College Station, TX 83/02/01
BERNARD, H Standardization & Special Projects Branch 1p
17140 054 24X Fiche 50-128, 83/02/01, 8302140131

--B302140136 Proposed changes to Tech Spec 3 B re primary coolant conditioning
* Texas A&M Univ, College Station, TX 83/02/01 2pp
17140 055 24X Fiche 50-128, 83/02/01, 8302140131

B302150504 Forwards "Nuclear Science Ctr Reactor Post-Damage Pulse Test for Full FLIP TRIQA Core," for review Plan approved w/minor changes by Reactor Safety Board on 830128
ROGERS, D Texas A&M Univ, College Station, TX 83/02/04
THOMAS, C D Standardization & Special Projects Branch 1p
17157 120 24X Fiche 50-128, 83/02/04, 8302150504

--B302150510 "Nuclear Science Ctr Reactor Post-Damage Pulse Test for Full FLIP TRIQA Core"
WATSON, R L Texas A&M Univ, College Station, TX 83/02/02
17pp 17157 121 24X Fiche 50-128, 83/02/04, 8302150504

G Inspection reports, IE Bulletins & correspondence

B302010592 Forwards experimental pulse test program for full FLIP TRIQA core for review & approval Program involves measurement of pulse core parameters necessary to establish operational pulsing core Fuel insp program included in program
FELTZ, D E Texas A&M Univ, College Station, TX 83/01/21
THOMAS, C D Standardization & Special Projects Branch 3pp
16978 104 24X Fiche 50-128, 83/01/21, 8302010592

--B302010607 Draft "Nuclear Science Ctr Reactor Post-Damage Test Program for Full FLIP TRIQA Core"
WATSON, R L Texas A&M Univ, College Station, TX 83/01/31
20pp 16978 107 24X Fiche 50-128, 83/01/21, 8302010592

B302150565 Forwards IE Safeguards Insp Rept 50-128/83-01 on 830103-07
No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/09 BERO, R R Texas A&M Univ, College Station, TX 2pp, 17156 124 24X Fiche 50-128, 83/02/09, 8302150565

--B302150582 IE Safeguards Insp Rept 50-128/83-01 on 830103-07 No noncompliance noted Major areas inspected security plan/ implementing procedures, security organization, records & repts, testing & maint Details withheld (ref 10CFR73 21)
CALDWELL, R A, KELLY, J A Division of Resident, Reactor Project & Engineering Programs 83/02/01 1p 17156 126 24X
Fiche 50-128, 83/02/09, 8302150565

B302230501 Forwards IE Safeguards Insp Repts 50-128/83-02 & 70-1936/83-02 on 830103-07 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/17 BERO, R R Texas A&M Univ, College Station, TX 2pp 17257 243 24X Fiche 50-128, 83/02/17, 8302230501

--B302230517 IE Safeguards Insp Repts 50-128/83-02 & 70-1936/83-02 on 830103-07 No noncompliance noted Major areas inspected nuclear mat'l control & accountability measurement & controls & shipping & receiving Details withheld (ref 10CFR2 790)
CALDWELL, R A, KELLY, J A Division of Resident, Reactor Project & Engineering Programs 83/02/14 1p 17257 245 24X
Fiche 50-128, 83/02/17, 8302230501

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B302070172 Forwards IE Safeguards Insp Rept 50-131/82-03 on 821122-24
No noncompliance noted
BEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/18 TURCOTLE, R L Vet Admin Hosp Omaha, NE 2pp 17062:337 24X Fiche 50-131, 83/01/18, 8302070172

--B302070180 IE Safeguards Insp Rept 50-131/82-03 on 821122-24 No noncompliance noted Major areas inspected security organization, records & repts, testing & maint & keys, locks & combinations & barriers Details withheld (ref 10CFR2 790)
CALDWELL, R A, KELLY, J A Region 4, Office of Director 82/12/30
1p 17062 339 24X Fiche 50-131, 83/01/18, 8302070172

G Inspection reports, IE Bulletins & correspondence

B302070172 Forwards IE Safeguards Insp Rept 50-131/82-03 on 821122-24
No noncompliance noted
BEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/18 TURCOTLE, R L Vet Admin Hosp Omaha, NE 2pp 17062:337 24X Fiche 50-131, 83/01/18, 8302070172

--B302070180 IE Safeguards Insp Rept 50-131/82-03 on 821122-24 No noncompliance noted Major areas inspected security organization, records & repts, testing & maint & keys, locks & combinations & barriers Details withheld (ref 10CFR2 790)
CALDWELL, R A, KELLY, J A Region 4, Office of Director 82/12/30
1p 17062 339 24X Fiche 50-131, 83/01/18, 8302070172

DOCKETED ITEMS

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302140034 Advises that provisions for annual independent audit of emergency preparedness program in accordance w/10CFR50.54(t) not warranted, per Generic Ltr 82-17 Plant shut down since Jul 1976 Potential for offsite release extremely low
CRANE, P A Pacific Gas & Electric Co 83/02/07 EISENHUT, D O Division of Licensing 2pp 17141 167 24X Fiche 50-133, 83/02/07, 8302140034

8302280421 Forwards IE Safeguards Insp Rept 50-133/83-01 on 830208-10 & notices of violation Rept & notices of violation withheld (refs 10CFR2 790 & 10CFR73 21)
NORDEHAUO, L R Division of Radiological Safety & Safeguards Program 83/02/24 CRANE, P A Pacific Gas & Electric Co 2pp 17309 165 24X Fiche 50-133, 83/02/24, 8302280421

P Operating license stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-16 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8302280421 Forwards IE Safeguards Insp Rept 50-133/83-01 on 830208-10 & notices of violation Rept & notices of violation withheld (refs 10CFR2 790 & 10CFR73 21)
NORDEHAUO, L R Division of Radiological Safety & Safeguards Program 83/02/24 CRANE, P A Pacific Gas & Electric Co 2pp 17309 165 24X Fiche 50-133, 83/02/24, 8302280421

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

R Periodic operating reports & related correspondence

8302030458 Forwards "Annual Rept for 1982"
CHALK, W S Washington, Univ of 83/01/28 Assistant Director
for Operating Reactors 1p 17008 086 24X Fiche 50-139, 83/01/28, 8302030458

--8302030463 "Annual Rept for 1982"
Washington, Univ of 83/01/28 4pp 17008 087 24X
Fiche 50-139, 83/01/28, 8302030458

DOCKET 50-142 UCLA TRAINING REACTOR

F Security, medical, emergency & fire protection plans

8302220050 Addl response to FOIA request for documents re UCLA lab & research reactors Forwards documents listed on Apps A & B App B documents partially withheld commercial & financial info (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 82/12/30 HIRSCH, D
CBS News, CBS, Inc 3pp 17240 329 24X Fiche 50-142, 82/12/30, 8302220050

--8302220063 Safeguards Insp Rept 50-111-16 on 710114 No noncompliance noted Major areas inspected audit of records, repts & source documents, review of written matl controls & accounting procedures & physical inventory of SNM
RIZZOLO, V N Atomic Energy Commission 71/01/25 7pp 17241 002 24X Fiche 50-142, 82/12/30, 8302220050

--8302220067 IE Safeguards Insp Repts 50-142/75-03 & 70-0223/75-01 on 750520 No noncompliance noted Major areas inspected review of records, repts, source documents & procedures & physical inventory of SNM
KOSARI, V BROCK, B L, MAKADA, O H Region 5, San Francisco, Office of the Director 75/05/18 7pp 17241 009 24X
Fiche 50-142, 82/12/30, 8302220050

--8302220071 Forwards IE Safeguards Insp Rept 50-142/75-02 & notice of violation.
ENQELKEN, R H Region 5, San Francisco, Office of the Director 75/05/28 BROWN, H V California, Univ of, Los Angeles 2pp 17241 016 24X Fiche 50-142, 82/12/30, 8302220050

--8302220073 Notice of violation from insp on 750520
Region 5, San Francisco, Office of the Director 75/05/28 1p 17241 018 24X Fiche 50-142, 82/12/30, 8302220050

--8302220076 Forwards IE Safeguards Insp Rept 50-142/75-02 for Univ of CA file
ENQELKEN, R H Region 5, San Francisco, Office of the Director 75/05/29 NRC - No Detailed Affiliation Given 1p 17241 019 24X Fiche 50-142, 82/12/30, 8302220050

--8302220080 Forwards IE Safeguards Insp Rept 50-142/75-02 on 750520 Licensee should revise security plan to include correction of problem areas
RIZZOLO, V N Region 5, San Francisco, Office of the Director 75/05/04 THORNBURG, H D Office of Inspection & Enforcement, Office of the Director 1p 17241 020 24X Fiche 50-142, 82/12/30, 8302220050

--8302220082 IE Safeguards Insp Rept 50-142/75-02 on 750520 Noncompliance noted required training & testing re health physics & lab procedures not provided
SCHUSTER, M D, RIZZOLO, V N Region 5, San Francisco, Office of the Director 75/06/03 6pp 17241 021 24X Fiche 50-142, 82/12/30, 8302220050

DOCKETED ITEMS

- 8302220086 Forwards IE Safeguards Insp Rept 50-142/76-01 on 760729-30 & notice of violation
RIZZOLO, V N Region 5, San Francisco, Office of the Director 76/08/13 2pp
17241 027 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220087 Notice of violation from insp on 760729-30 Info partially deleted
* Region 5, San Francisco, Office of the Director 76/08/13 1p
17241 029 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220091 Forwards IE Safeguards Insp Rept 50-142/76-01
RIZZOLO, V N Region 5, San Francisco, Office of the Director 76/08/13 RAY, O W Office of Inspection & Enforcement, Office of the Director 2pp 17241 030 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220095 IE Safeguards Insp Rept 50-142/76-01 Noncompliance noted one key lost & duplicated w/o corrective action being taken
SCHUSTER, H D, RIZZOLO, V N Region 5, San Francisco, Office of the Director 76/08/13 6pp 17241 032 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220098 Forwards IE Safeguards Insp Rept 50-142/77-02 & notices of violation & deviation
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 77/10/19 O'NEILL, R California, Univ. of, Los Angeles, 2pp
17241 038 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220102 Notice of violation from insp on 770921-22
* Region 5, San Francisco, Office of the Director 77/10/19 1p
17241 040 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220105 Notice of deviation from insp on 770921-22
* Region 5, San Francisco, Office of the Director 77/10/19 1p
17241 041 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220107 IE Safeguards Insp Rept 50-142/77-02 on 770921-22 Noncompliance noted door locks not of substantial const Info partially deleted
MORTENSEN, W P, NORDERHAUG, L R Region 5, San Francisco, Office of the Director 77/10/19 4pp 17241 042 24X
Fiche 50-142, 82/12/30, 8302220050
- 8302220110 Notice of deviation from insp on 781030-31
* Region 5, San Francisco, Office of the Director 78/12/18 1p
17241 048 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220113 IE Safeguards Insp Rept 50-142/78-03 on 781030-31, Noncompliance noted door locks not repaired
MORTENSEN, W P, NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 78/12/18 9pp 17241 049 24X
Fiche 50-142, 82/12/30, 8302220050
- 8302220116 Responds to 781218 1tr re violations noted in IE Safeguards Insp Rept 50-142/78-03 Corrective actions alarm sys revised & performance test of reactor room sys conducted weekly Info partially deleted
CATTION, I, California, Univ. of, Los Angeles 79/01/18
NORDERHAUG, L R Region 5, San Francisco, Office of the Director 2pp 17241 058, 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220119 Requests that 1tr be withheld from public disclosure, per 10CFR2 790 & responds to NRC 790730 request for info re SNM needs No SNM possessed in excess of formula quantity at any site Info partially deleted
CATTION, I California, Univ. of, Los Angeles 79/08/29 REID, R W Operating Reactors Branch 4 2pp, 17241:061 24X
Fiche 50-142, 82/12/30, 8302220050.
- 8302220122 Forwards IE Safeguards Insp Rept 50-142/79-03 on 790924-25, NORDERHAUG, L R Region 5, San Francisco, Office of the Director 79/10/10 O'NEIL, R California, Univ. of, Los Angeles 2pp, 17241.063 24X Fiche 50-142, 82/12/30, 8302220050
- 8302220124 IE Safeguards Insp Rept 50-142/79-03 on 790924-25 No noncompliance noted Major areas inspected security plan, protection of SNM, security organization, access control, alarm sys & keys & security program review.
POWER, E J., IVEY, L W, NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 79/10/18 5pp 17241:065, 24X
Fiche 50-142, 82/12/30, 8302220050.
- 8302220130 IE Safeguards Insp Rept 50-142/80-01 & 70-0223/80-01 on 800211-12 No noncompliance noted Major areas inspected compliance w/applicable sections of regulations
HAMADA, O, WIEDER, A., NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/02/25 3pp, 17241:072, 24X
Fiche 50-142, 82/12/30, 8302220050.
- 8302220135 Forwards IE Safeguards Insp Repts 50-142/80-01 & 70-0223/80-01 on 800211-12
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/02/26 BROWN, H V California, Univ. of, Los Angeles 2pp
17241 070 24X Fiche 50-142, 82/12/30, 8302220050.
- 8302230523 Forwards JR Miller marked-up memo to V Stello re impact of proposed safeguards upgrade rule on nonpower reactors Memo should have been referenced as exhibit in 830208 filing
BAY, J H Committee to Bridge the Gap 83/02/14 FRYE, J H Atomic Safety and Licensing Board Panel 5pp, 17237 270, 24X
Fiche 50-142, 83/02/14, 8302230523
- G. Adjudicatory correspondence
- 8302010492 Memorandum & Order advising that most key facts, conclusions & assumptions underlying NRC & UCLA fundamental positions are subj of genuine dispute Parties should confer for possible simplification or settlement of contentions.
LUEBKE, E A, FRYE, J H Atomic Safety and Licensing Board Panel 83/01/28, 2pp, 16981 072 24X Fiche 50-142, 83/01/28, 8302010492
- 8302090437 Motion for clarification of subj matter of 830223-24 prehearing conference on pending motions for summary disposition Certificate of Svc encl
WOODHEAD, C Hearing Branch 1 83/02/04, Atomic Safety and Licensing Board Panel 9pp, 17066, 255 24X Fiche 50-142, 83/02/04, 8302090437
- 8302090227 Memorandum & order ruling on NRC, UCLA & Committee to Bridge the Gap motions for summary disposition. Denies NRC & UCLA motions re Contentions V, XIX, VIII, XV, XII & XIV & UCLA, NRC & Gap motions re Contention XIII to extent noted
LUEBKE, E A, PARIS, D H, FRYE, J H Atomic Safety and Licensing Board Panel 83/02/08 Committee to Bridge the Gap 3Bpp 17070:203 24X Fiche 50-142, 83/02/08, 8302090227
- 8302090237 Memorandum & order ruling on NRC 830204 motion for clarification of purpose of prehearing conference Agenda for prehearing conference outlined
FRYE, J H Atomic Safety and Licensing Board Panel, 83/02/08 4pp 17069 352 24X Fiche 50-142, 83/02/08, 8302090237
- 8302160184 Proposes first conference for 830217 in Los Angeles, CA to comply w/ASLB 830128 memorandum & order Proposal for simplification of contentions through organization into like sub areas encl
HIRSCH, D, Committee to Bridge the Gap 83/02/09, Office of the Executive Legal Director, 3pp 17163 050 24X
Fiche 50-142, 83/02/09, 8302160184.
- 8302160193 Advises of topics which ASLB wishes to cover under Item 5 of agenda for 830223-24 prehearing conference. Contentions II & XVII will be explored to extent to which disputes exist re Committee to Bridge the Gap motion for summary disposition
FRYE, J H Atomic Safety and Licensing Board Panel, 83/02/10, WOODHEAD, C, Hearing Branch 1 CORMIER, W H California, Univ. of, Los Angeles NALIBOFF, L Santa Monica, CA, 1p, 17162 182 24X
Fiche 50-142, 83/02/10, 8302160193.
- 8302180408 Forwards omitted pages from Committee to Bridge the Gap response to NRC & applicant motions for summary disposition
HIRSCH, D Committee to Bridge the Gap 83/02/14, Atomic Safety and Licensing Board Panel, 1p 17214, 273, 24X
Fiche 50-142, 83/02/14, 8302180408.
- 8302180414 Omitted pages from Committee to Bridge the Gap response to NRC & applicant motions for summary disposition.
* Committee to Bridge the Gap, 83/02/14 Atomic Safety and Licensing Board Panel, 2pp, 17214, 274, 24X Fiche 50-142, 83/02/14, 8302180408
- 8302230523 Forwards JR Miller marked-up memo to V Stello re impact of proposed safeguards upgrade rule on nonpower reactors Memo should have been referenced as exhibit in 830208 filing
BAY, J H, Committee to Bridge the Gap 83/02/14, FRYE, J H Atomic Safety and Licensing Board Panel, 5pp 17237:270 24X
Fiche 50-142, 83/02/14, 8302230523.
- 8302160199 Advises that policy or rulemaking proceeding not yet established re replacement of highly enriched U w/low enriched U fuel for use in research & test reactors. Add info encl
WOODHEAD, C P, Hearing Branch 1, 83/02/15, HIRSCH, D, Committee to Bridge the Gap 4pp, 17163, 053 24X Fiche 50-142, 83/02/15, 8302160199.
- 8302170103 Lists questions ASLB wants answered re NUREG/CR-2079, "Analysis of Credible Accidents for Argonaut Reactors." Conclusions should be explained & justified w/o encl
WOODHEAD, C P, Hearing Branch 1, 83/02/15 HAWLEY, S Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 17182:315 24X Fiche 50-142, 83/02/16, 8302170103

DOCKETED ITEMS

P Operating license stage documents & correspondence

8302180255 Application to amend License R-71, reducing authorized possession limit of U-235 to less than 5,000 g
WESST, M F California, Univ of, Los Angeles 83/02/08 BERNARD, H
Standardization & Special Projects Branch 1p 17215 277 24X
Fiche: 50-142, 83/02/08, 8302180255

Q Inspection reports, IE Bulletins & correspondence

8302220050 Addl response to FOIA request for documents re UCLA lab & research reactors Forwards documents listed on App A & B
App B documents partially withheld commercial & financial info (re: FOIA Exemption 4)
FELTON, J M Division of Rules and Records 82/12/30 HIRSCH, D
CBS News, CBS, Inc 3pp 17240 329 24X Fiche 50-142, 82/12/30, 8302220050

--8302220063 Safeguards Insp Rept 80-111-16 on 710114. No noncompliance noted Major areas inspected audit of records, repts & source documents, review of written mat controls & accounting procedures & physical inventory of SNM
RIZZOLO, V N Atomic Energy Commission 71/01/25 7pp
17241 002 24X Fiche 50-142, 82/12/30, 8302220050

--8302220067 IE Safeguards Insp Repts 50-142/75-03 & 70-0223/75-01 on 750520 No noncompliance noted Major areas inspected review of records, repts, source documents & procedures & physical inventory of SNM
KOBORI, Y, BROCK, B L, HAMADA, O H Region 5, San Francisco, Office of the Director 75/05/18 7pp 17241-009 24X
Fiche: 50-142, 82/12/30, 8302220050

--8302220071 Forwards IE Safeguards Insp Rept 50-142/75-02 & notice of violation
ENKELKEN, R H Region 5, San Francisco, Office of the Director 75/05/28
BROWN, M V California, Univ of, Los Angeles 2pp
17241 016 24X Fiche 50-142, 82/12/30, 8302220050

--8302220073 Notice of violation from insp on 750520
* Region 5, San Francisco, Office of the Director 75/05/28 1p
17241 018 24X Fiche 50-142, 82/12/30, 8302220050

--8302220076 Forwards IE Safeguards Insp Rept 50-142/75-02 for Univ of CA file
ENKELKEN, R H Region 5, San Francisco, Office of the Director 75/05/28
NRC - No Detailed Affiliation Given 1p 17241 019
24X Fiche 50-142, 82/12/30, 8302220050

--8302220080 Forwards IE Safeguards Insp Rept 50-142/75-02 on 750520
Licensee should revise security plan to include correction of problem areas.
RIZZOLO, V N Region 5, San Francisco, Office of the Director 75/05/04
THORNBURG, H D Office of Inspection & Enforcement, Office of the Director 1p 17241 020 24X Fiche 50-142, 82/12/30, 8302220050

--8302220082 IE Safeguards Insp Rept 50-142/75-02 on 750520 Noncompliance noted required training & testing re health physics & lab procedures not provided
SCHUSTER, H D, RIZZOLO, V N Region 5, San Francisco, Office of the Director 75/06/03 6pp 17241 021 24X Fiche 50-142, 82/12/30, 8302220050

--8302220086 Forwards IE Safeguards Insp Rept 50-142/76-01 on 760729-30 & notice of violation
RIZZOLO, V N Region 5, San Francisco, Office of the Director 76/08/13
O'NEIL, R California, Univ of, Los Angeles 2pp
17241 027 24X Fiche 50-142, 82/12/30, 8302220050

7302220089 Notice of violation from insp on 760729-30 Info partially deleted
* Region 5, San Francisco, Office of the Director 76/08/13 1p
17241 029 24X Fiche 50-142, 82/12/30, 8302220050

302220091 Forwards IE Safeguards Insp Rept 50-142/76-01
RIZZOLO, V N Region 5, San Francisco, Office of the Director 76/08/13
RAY, O M Office of Inspection & Enforcement, Office of the Director 2pp 17241 030, 24X Fiche 50-142, 82/12/30, 8302220050

302220095 IE Safeguards Insp Rept 50-142/76-01 Noncompliance noted one key lost & duplicated w/o corrective action being taken
SCHUSTER, H D, RIZZOLO, V N Region 5, San Francisco, Office of the Director 76/08/13 6pp 17241-032 24X Fiche 50-142, 82/12/30, 8302220050

--8302220098 Forwards IE Safeguards Insp Rept 50-142/77-02 & notices of violation & deviation
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch, 77/10/19
O'NEIL, R California, Univ of, Los Angeles 2pp
17241 038 24X Fiche 50-142, 82/12/30, 8302220050

--8302220102 Notice of violation from insp on 770921-22
* Region 5, San Francisco, Office of the Director 77/10/19 1p
17241 040 24X Fiche 50-142, 82/12/30, 8302220050

--8302220105 Notice of deviation from insp on 770921-22
* Region 5, San Francisco, Office of the Director 77/10/19 1p
17241 041 24X Fiche 50-142, 82/12/30, 8302220050

--8302220107 IE Safeguards Insp Rept 50-142/77-02 on 770921-22
Noncompliance noted door locks not of substantial const info partially deleted
MORTENSEN, W P, NORDERHAUG, L R Region 5, San Francisco, Office of the Director 77/10/19 4pp 17241 042 24X
Fiche 50-142, 82/12/30, 8302220050

--8302220110 Notice of deviation from insp on 781030-31
* Region 5, San Francisco, Office of the Director 78/12/18 1p
17241 048 24X Fiche 50-142, 82/12/30, 8302220050

--8302220113 IE Safeguards Insp Rept 50-142/78-03 on 781030-31
Noncompliance noted door locks not repaired
MORTENSEN, W P, NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 78/12/18 9pp 17241 049 24X
Fiche 50-142, 82/12/30, 8302220050

--8302220116 Responds to 781218 ltr re violations noted in IE Safeguards Insp Rept 50-142/78-03 Corrective actions alarm sys revised & performance test of reactor room sys conducted weekly Info partially deleted
CATTON, I California, Univ of, Los Angeles 79/01/18
NORDERHAUG, L R Region 5, San Francisco, Office of the Director 2pp 17241 058 24X Fiche 50-142, 82/12/30, 8302220050

--8302220122 Forwards IE Safeguards Insp Rept 50-142/79-03 on 790924-25
NORDERHAUG, L R Region 5, San Francisco, Office of the Director 79/10/10
O'NEIL, R California, Univ of, Los Angeles 2pp
17241 063 24X Fiche 50-142, 82/12/30, 8302220050

--8302220124 IE Safeguards Insp Rept 50-142/79-03 on 790924-25 No noncompliance noted Major areas inspected security plan, protection of SNM, security organization, access control, alarm sys & keys & security program review
POWER, E J, IVEY, L W, NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 79/10/18 5pp 17241 065 24X
Fiche 50-142, 82/12/30, 8302220050

--8302220130 IE Safeguards Insp Rept 50-142/80-01 & 70-0223/80-01 on 800211-12 No noncompliance noted Major areas inspected compliance w/applicable sections of regulations
HAMADA, O, WIEDER, A, NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/02/25 3pp 17241 072 24X
Fiche 50-142, 82/12/30, 8302220050

--8302220135 Forwards IE Safeguards Insp Repts 50-142/80-01 & 70-0223/80-01 on 800211-12
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/02/26
BROWN, H V California, Univ of, Los Angeles 2pp
17241 070 24X Fiche 50-142, 82/12/30, 8302220050

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8302010660 Responds to 821030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73 40(d) & STS Twelve-month Physical Security Plan & Safeguards Contingency Plan audits performed per requirements
BORDINO, T C Consumers Power Co 83/01/27 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 16980 066 24X
Fiche 50-000, 83/01/27, 8302010660

8302140003 Informs that secondary activation point for public warning sys per 820204 ltr & IE Insp Rept 50-155/82-15 will not be installed Secondary siren activation location not required by regulation
BORDINO, T C Consumers Power Co 83/01/27 KEPLER, J O Region 3, Office of Director 1p 17142 163 24X Fiche 50-155, 83/01/27, 8302140003

DOCKETED ITEMS

17

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302280462 Forwards IE Mgt Meeting Rept 50-155/83-02 on 830114 No noncompliance noted
LITTLE, W B Division of Engineering 83/02/16 DEWITT, R B
Consumers Power Co 2pp 17309 220 24X Fiche 50-155, 83/02/16, 8302280462

--8302280466 IE Mgt Meeting Rept 50-155/83-02 on 830114 No noncompliance noted Major areas discussed concerns addressed in IE Insp Rept 50-155/82-13 re fire protection & licensee response
ULIE, J, RAMSEY, C, WILLIAMS, C C Region 3, Office of Director 83/02/12 2pp 17309 222 24X Fiche 50-155, 83/02/16, 8302280462

0 Adjudicatory correspondence

8302010577 Brief supporting ASLB 821029 initial decision ordering util to amend OL amend application in order that k-effective limitations in spent fuel pool would not exceed 0.95 NRC & util assumptions inconsistent Certificate of svc encl
SEMEL, H Christa-Marie SEMEL, H Antioch School of Law, Washington, DC 83/01/28 Atomic Safety and Licensing Appeal Panel 16pp 16977 055 24X Fiche 50-155, 83/01/28, 8302010577

8302140157 Forwards legible copy of 830131 brief in support of criticality order
O'NEILL, J O'Neill, J 83/02/04 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 17140 065 24X Fiche 50-155, 83/02/04, 8302140157

--8302140161 Brief in support of criticality order ASLB order requiring CPC to perform K eff analyses of spent fuel configurations in new racks under all conditions, required by regulations
O'NEILL, J O'Neill, J 83/01/31 Atomic Safety and Licensing Appeal Panel 23pp 17140 065 24X Fiche 50-155, 83/02/04, 8302140157

8302080201 Response to licensee 821216 brief supporting exceptions to ASLB 821029 criticality decision Supports reversal of portion of decision requiring application amend Opposes dismissal of underlying contention Certificate of Svc encl
BACHMANN, R O Hearing Branch 1 83/02/07 Atomic Safety and Licensing Appeal Panel 21pp 17058 117 24X Fiche 50-155, 83/02/07, 8302080201

8302090264 Order granting J O'Neill 830131 motion for leave to file brief out of time
BHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/07 O'Neill, J 1p 17070 247 24X Fiche 50-155, 83/02/07, 8302090264

8302180367 Motion for extension of time until 830331 to respond to util submittals in response to ASLB 820914 partial initial decision directing util to remedy emergency planning deficiencies FEMA review needed W/Certificate of Svc encl
GODDARD, R J Hearing Branch 3 83/02/14 Atomic Safety and Licensing Appeal Panel 4pp 17209 239 24X Fiche 50-155, 83/02/14, 8302180367

8302180303 Advises that NRC motion for extension of time in which to respond to ASLB 820914 order erroneously captioned before ASLB
GODDARD, R J Hearing Branch 2 83/02/15 BLOCH, P B, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 1p 17215 280 24X Fiche 50-155, 83/02/15, 8302180303

8302220402 Order scheduling 830324 oral argument in Bethesda, MD on util appeal of ASLB 821029 partial initial decision re neutron multiplication factor Each side allotted 1 h for presentation
BHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/17 2pp 17232 143 24X Fiche 50-155, 83/02/17, 8302220402

8302230597 Memorializes counsel understanding of status of upcoming meeting re future hearing schedule Related correspondence.
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/02/17 BLOCH, P B, PARRIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 17256 127 24X Fiche 50-155, 83/02/17, 8302230597

8302230610 Forwards util 830110 ltr to NRC transmitting Amend 2 to application for spent fuel rack addition, consolidated environ impact evaluation & description & safety analysis Related correspondence
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/02/17 BLOCH, P B, PARRIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 134pp 17254 061 24X Fiche 50-155, 83/02/17, 8302230610

H General correspondence

8302100374 Urges denial of util request to expand storage capacity & of operating permit for one of oldest plants in country.
ANDERSON, J Affiliation Unknown 83/02/07 NRC - No Detailed
Affiliation Given 2pp 17110 082 24X Fiche 50-155, 83/02/07, 8302100374

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R. Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8303180248 Informs that util 820208 submittal re environ qualification of electric equipment is responsive to deficiencies identified & provides technically sound bases for justification for continued operation.
ECCLESTON, K. T. Operating Reactors Branch 2 82/02/26 NOVAK, T M. Assistant Director for Operating Reactors 4pp 17196 328 24X Fiche 50-000, 83/01/18, 8302170019

--8303220416 Discusses electrical equipment qualification program justification for interim operation Sufficient supplemental info to support continued interim safe operation presented at meeting
ULIEL, J A Operating Reactors Branch 2 82/03/09 NOVAK, T M. Assistant Director for Operating Reactors 7pp 17196 293 24X Fiche 50-000, 83/01/18, 8302170019

--8303220475 Discusses util 830226 submittal re electrical equipment qualification program Deficiencies resulting from 90-day response to 810605 & 0701 ltr identified & resolved. Sufficient info exists to justify continued operation
JAFFE, D H Operating Reactors Branch 3 82/03/12 NOVAK, T M. Assistant Director for Operating Reactors 2pp 17196 302 24X Fiche 50-000, 83/01/18, 8302170019

--8303220476 Notifies that sufficient justification for continued operation of facility during ongoing equipment qualification review has been provided by util
NELSON, C C Operating Reactors Branch 3 82/03/11 NOVAK, T M. Assistant Director for Operating Reactors 9pp 17196 348 24X Fiche 50-000, 83/01/18, 8302170019

--8303240107 Advises that licensee provided in 820227 ltr sufficient justification for interim operation pending resolution of equipment qualification program
VISHNO, O S Operating Reactors Branch 4 82/03/18 NOVAK, T M. Assistant Director for Operating Reactors 3pp 17197 020 24X Fiche 50-000, 83/01/18, 8302170019

--8303240420 Advises that justification for continued operation during equipment environ qualification review subj to revisions agreed to is adequate
MARTIN, R E Operating Reactors Branch 3 82/03/16 NOVAK, T M. Assistant Director for Operating Reactors 16pp 17197 025 24X Fiche 50-000, 83/01/18, 8302170019

--8303290123 Informs that based on licensee 820226 ltr, facility is considered safe for continued operation until such time as equipment of questionable qualification in licensee 810904 submittal is qualified.
ROONEY, V L Operating Reactors Branch 2 82/03/09 NOVAK, T M. Assistant Director for Operating Reactors 1p 17196 362 24X Fiche 50-000, 83/01/18, 8302170019

--8302170076 Concludes that based on licensee 820211 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
FAIRFILL, M B Operating Reactors Branch 4 82/02/24 NOVAK, T M. Assistant Director for Operating Reactors 2pp 17196 173 24X Fiche 50-000, 83/01/18, 8302170019

--8302170089 Provides justification for interim operation pending resolution of equipment qualification program
WAGNER, P Operating Reactors Branch 4 82/03/03 NOVAK, T. Assistant Director for Licensing 2pp 17196 223 24X Fiche 50-000, 83/01/18, 8302170019

--8302170089 Provides justification for interim operation pending resolution of equipment qualification program
WAGNER, P Operating Reactors Branch 4 82/03/03 NOVAK, T. Assistant Director for Operating Reactors 2pp 17196 223 24X Fiche 50-000, 83/01/18, 8302170019

DOCKETED ITEMS

- 8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
HANNON, J H , THOMA, J NRC - No Detailed Affiliation Given
82/01/27 VARGA, S NRC - No Detailed Affiliation Given 10pp
17196 225 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170110 Discusses Franklin Research Ctr review of licensee responses to SER re environ qualification of electrical equipment.
Franklin Research Ctr concerns resolved & adequate bases in place for interim operations
ENGLE, L. Operating Reactors Branch 3 82/01/27 CLARK, R
Operating Reactors Branch 3 4pp 17196 235 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170114 Amend 7 to License NPF-4, authorizing results of tests for Barton transmitters be submitted for NRC review
PARR, D D Light Water Reactors Branch 3 78/07/03 2pp
17196 239 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170118 Safety evaluation supporting Amend 7 to License NPF-4
e Light Water Reactors Branch 3 78/07/03 2pp 17196 241 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170123 Package of four comments indicating adequate or inadequate justification for interim operation re environ qualification of electrical equipment.
PADOVANI, M L. NRC - No Detailed Affiliation Given 82/01/27
NRC - No Detailed Affiliation Given, 10pp 17196 255 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed
Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F.
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170161 Concludes that continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
VAN VLIET, J A Operating Reactors Branch 2 82/10/28
EISENHUT, D O Division of Licensing 2pp 17196 291 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170169 Concludes that based on re-evaluation of licensee justification, continued operation until completion of environ qualification program will not present undue risk to public health & safety
JAFFE, D H. Operating Reactors Branch 3 82/10/28 EISENHUT, D O
Division of Licensing. 2pp 17196 300 24X Fiche 50-000, 83/01/18, 8302170019.
- 8302170176 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
ECCLESTON, K T Operating Reactors Branch 2. 82/10/28
EISENHUT, D O Division of Licensing 2pp 17196 326 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170181 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
HEITNER, K. L. Operating Reactors Branch 3 82/10/28
EISENHUT, D O Division of Licensing 2pp 17196 346 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170188 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
FAIRTILE, M Operating Reactors Branch 4 82/10/28 EISENHUT, D O
Division of Licensing 1p 17196 357 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170192 Concludes that based on review of util 820211 ltr, continued operation does not constitute undue risk to public health & safety.
FAIRTILE, M B Operating Reactors Branch 4. 82/02/24 NOVAK, T M
Assistant Director for Licensing 2pp 17196 358 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170202 Concludes that licensee has provided sufficient technical justification during ongoing
ench 2 82/10/28 EISENHUT, D O
16 360. 24X
- 8302170204 Concludes that sufficient info has been provided in 820226 ltr to justify continued operation pending completion of environ qualification program
ORDENHUIS, M Operating Reactors Branch 1 82/10/28
EISENHUT, D O Division of Licensing 3pp 17197 016 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170212 Concludes that licensee 820315 ltr justifies continued operation until completion of environ qualification program
VISINGO, O S Operating Reactors Branch 4 82/10/28
EISENHUT, D O Division of Licensing 1p 17197 019 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170217 Concludes that based on licensee submittals, continued operation until completion of environ qualification program will not present undue risk to public health & safety
STEVENS, J A Operating Reactors Branch 3 82/10/28
EISENHUT, D O Division of Licensing 2pp 17197 023 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170240 Concludes that based on licensee 820225 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
WAGNER, P C Operating Reactors Branch 4 82/10/28 EISENHUT, D O
Division of Licensing 1p 17197 041 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170256 Concludes that licensee justification for continued operation until completion of environ qualification program acceptable based on review
THOMA, J Operating Reactors Branch 1 82/10/28 EISENHUT, D O
Division of Licensing 4pp 17197 044 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170262 Concludes that based on licensee 820603 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
BEVAN, R B Operating Reactors Branch 2 82/10/28 EISENHUT, D O
Division of Licensing 2pp 17197 050 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170270 Concludes that continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
NEIGHBORS, J D Operating Reactors Branch 1 82/10/28
EISENHUT, D O Division of Licensing 2pp 17197 052 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170276 Concludes that based on licensee 821027 submittal, continued operation until completion of qualification program will not present undue risk to public health & safety
ENGLE, L B Operating Reactors Branch 3 82/10/28 EISENHUT, D O
Division of Licensing 2pp 17197 054 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170282 Concludes that based on licensee 820127 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
MINER, S Operating Reactors Branch 4 82/10/28 EISENHUT, D O,
Division of Licensing 2pp 17197 076 24X Fiche 50-000, 83/01/18, 8302170019
- 8302170285 Concludes that based on licensee 820127 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
HEGNER, J D Operating Reactors Branch 2 82/10/28 EISENHUT, D O
Division of Licensing 2pp 17197 078 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170290 Concludes that based on licensee submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
SIEGEL, B L Operating Reactors Branch 2 82/10/28 EISENHUT, D O
Division of Licensing 2pp 17197 080 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302170293 Concludes that based on licensee 820127 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
DIARINI, D C Operating Reactors Branch 3 82/10/28
EISENHUT, D O Division of Licensing 3pp 17197 082 24X
Fiche 50-000, 83/01/18, 8302170019
- 8302010484 Concurs w/830104 determination that Tech Spec change request re on-call technical advisor involved single safety issue
Class II fee encl
BORDINE, T C Consumers Power Co 83/01/25 MILLER, W O License
Fee Management Branch 2pp 16981 026 24X Fiche 50-155, 83/01/25, 8302010484

DOCKETED ITEMS

19

8302010632 Forwards revised listing of SEP topics for which facility does not meet current licensing acceptance criteria, summary descriptions of differences for Topics III-2 & VI-1 & editorial correction of Topic III-10 A Response requested CRUTCHFIELD, D Operating Reactors Branch 5 83/01/27 VANDEWALLE, D J Consumers Power Co 8pp 16980 026 24X Fiche 50-155, 83/01/27, 8302010632

8302010636 Forwards application to amend License DPR-6 consisting of proposed Tech Spec changes modifying containment leak rate testing requirements BORDINE, T C Consumers Power Co 83/01/28 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16980 034 24X Fiche 50-155, 83/01/28, 8302010636

--8302010640 Application to amend License DPR-6 consisting of Tech Spec changes modifying containment leak testing requirements. DEWITT, R B Consumers Power Co 83/01/28 1p 16980 036 24X Fiche 50-155, 83/01/28, 8302010636

--8302010642 Proposed Tech Spec changes modifying containment leak rate testing requirements * Consumers Power Co 83/01/28 3pp 16980 037 24X Fiche 50-155, 83/01/28, 8302010636

8302010654 Forwards application to amend License DPR-6 consisting of proposed Tech Spec changes re area monitors. BORDINE, T C Consumers Power Co 83/01/28 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16979 170 24X Fiche 50-155, 83/01/28, 8302010654

--8302010661 Application to amend License DPR-6 consisting of proposed Tech Spec changes modifying info re area monitoring sys & operating requirements to make Tech Specs compatible w/STB for area monitors * Consumers Power Co 83/01/28 2pp 16979 171 24X Fiche 50-155, 83/01/28, 8302010654

--8302010671 Proposed Tech Spec changes modifying info re area monitoring sys & operating requirements to make Tech Specs compatible w/STB for area monitors * Consumers Power Co 83/01/28 3pp 16979 173 24X Fiche 50-155, 83/01/28, 8302010654

8302040078 Forwards response to NRC Draft Technical Rept. "Control of Heavy Loads." BORDINE, T C Consumers Power Co 83/01/28 CRUTCHFIELD, D Operating Reactors Branch 5 26pp 17021 197 24X Fiche 50-155, 83/01/28, 8302040078

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D G Division of Licensing, 83/02/08 Consolidated Edison Co of New York, Inc 1pp 17290: 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234, 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee, Svc list encl. EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234, 234 24X Fiche 50-000, 83/02/08, 8302080304

8302150319 Forwards supplemental evaluation of Rev 3 to 821104 physics methodology rept Rept acceptable as revised CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09, VANDEWALLE, D J Consumers Power Co 3pp 17148 199 24X Fiche 50-155, 83/02/09, 8302150319

--8302150323 Topical rept evaluation of Rev 3 to 821104 physics methodology rept, Rept acceptable as revised. BROOKS, W. NRC - No Detailed Affiliation Given 83/02/09 1p 17148 202 24X Fiche 50-155, 83/02/09, 8302150319

8302170295 Responds to 830430 revised NRC SER re SEP Topic III-10 A, "Thermal-Overload Protection for Motors of Motor-Operated Valves." Proposed bypass circuitry will be installed by end of 1983 refueling outage. TONER, K A Consumers Power Co, 83/02/14 CRUTCHFIELD, D Operating Reactors Branch 5, 6pp 17177 031 24X Fiche: 50-155, 83/02/14, 8302170295

8302240256 Forwards response to NRC 820713 request for addl info re unresolved safety issues, Status rept will be used in SEP integrated assessment TONER, K A Consumers Power Co 83/02/14, CRUTCHFIELD, D Operating Reactors Branch 5 30pp 17272 258 24X Fiche 50-155, 83/02/14, 8302240256

830220139 Responds to 821112 request for addl info re SEP Topic III-3 A, "Effects of Pipe Break on Structures, Sys & Components Inside Containment" Effects of pipe whip due to longitudinal breaks not analyzed in rigorous manner TONER, K A Consumers Power Co 83/02/15 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17233 204 24X Fiche 50-155, 83/02/15, 830220139

8302240163 Forwards repts re structural analysis of reactor bldg for predicting seismic response of support equipment, per SEP Topic III-6 Comments on NRC SER discussed Concerns re primary coolant loop will be addressed in later submittal VANDEWALLE, D J Consumers Power Co 83/02/15 CRUTCHFIELD, D Operating Reactors Branch 5 6pp, 17280, 266 24X Fiche 50-155, 83/02/15, 8302240163

--8302240169 "Seismic Safety Margin Evaluation, Alternative Response Evaluation, Reactor Bldg Internal Structure, Big Rock Point Nuclear Power Plant." * D'Appolonia Consulting Engineers, Inc 83/01/31, 77pp, 17280 272 24X Fiche 50-155, 83/02/15, 8302240163

--8302240174 "Evaluation of Concrete-to-Concrete & Steel-to-Concrete Joints, Seismic Safety Margin Evaluation of Safety-Related Structures, Big Rock Point Nuclear Power Plant." * D'Appolonia Consulting Engineers, Inc 83/02/15, 25pp, 17280 349 24X Fiche 50-155, 83/02/15, 8302240163

--8302240181 "Review & Evaluation of Steel Connections, Seismic Safety Margin Evaluation of Safety-Related Structures, Big Rock Point Nuclear Power Plant." * D'Appolonia Consulting Engineers, Inc, 83/02/15, 29pp, 17281 012, 24X Fiche 50-155, 83/02/15, 8302240163

8302230206 Updates status of stack gas monitoring sys, per NUREG-0737, Item II, F in Calif & testing of sys completed, Equipment problems evaluated Sys may not be operational by 830401 due to spare parts delivery problems. BORDINE, T C Consumers Power Co 83/02/16 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17243 212 24X Fiche 50-155, 83/02/16, 8302230206

8302230610 Forwards until 830110 ltr to NRC transmitting Amend 2 to application for spent fuel rack addition, consolidated environ impact evaluation & description & safety analysis Related correspondence GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co, 83/02/17 BLOCH, P B, PARRIS, O H, SHON, F J Atomic Safety and Licensing Board Panel, 134pp 17254 061 24X Fiche: 50-155, 83/02/17, 8302230610

8302230179 Responds to NRC final evaluation of SEP Topic V-4, "Piping & Safe-End Integrity" Insp of addl recirculation & core spray nozzles will be performed during 1983 refueling outage, SEP Topic V-4 resolved TONER, K A Consumers Power Co 83/02/18, CRUTCHFIELD, D Operating Reactors Branch 5, 1p 17249, 092 24X Fiche 50-155, 83/02/18, 8302230179

Q. Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities, Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency, Forwards App A documents, Document 31 available in PDR, FELTON, J H Division of Rules and Records, 82/12/30, HIATT, S L, Ohio Citizens for Responsible Energy 3pp 17045 144, 24X Fiche: 50-000, 82/12/30, 8302040039

--8302040032 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item. BUCHARSKI, L. Region 3, Office of Director 82/07/08, KEPPLER, J G Region 3, Office of Director, 15pp, 17045: 261, 24X Fiche: 50-000, 82/12/30, 8302040039

8302040281 Forwards IE Insp Rept 50-155/83-01 on 830103-07, No noncompliance noted MILLER, J R Division of Engineering, 83/01/20, DEWITT, R B, Consumers Power Co, 2pp 17020, 023, 24X Fiche: 50-155, 83/01/20, 8302040281

DOCKETED ITEMS

--8302040289 IE Insp Rept 50-155/83-01 on 830103-07 No noncompliance noted Major areas inspected effluent releases, effluent control instrumentation, solid radwaste transportation activities & records & regts of effluents
LOVENDALE, P. C., GREGER, L. R. Region 3, Office of Director
83/01/19 4pp 17020 025 24X Fiche 50-155, 83/01/20, 8302040289

8302150514 Forwards IE Insp Rept 50-155/82-20 on 821123-1231 No noncompliance noted.
STREETER, J. F. Division of Project & Resident Programs 83/01/25
DEWITT, R. B. Consumers Power Co 2pp 17156 243 24X
Fiche 50-155, 83/01/25, 8302150514

--8302150534 IE Insp Rept 50-155/82-20 on 821123-1231 No noncompliance noted Major areas inspected operational safety verification, monthly maint & surveillance observations & LER followups
WRIGHT, O. C., PARKER, M. E., BOYD, D. C. Division of Project & Resident Programs 83/01/21 5pp 17156:245 24X Fiche 50-155, 83/01/25, 8302150514.

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/26 Consolidated Edison Co of New York, Inc 11pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302140003 Informs that secondary activation point for public warning sys per 820204 ltr & IE Insp Rept 50-155/82-15 will not be installed. Secondary siren activation location not required by regulation
BORDINE, T. C. Consumers Power Co 83/01/27 KEPLER, J. O. Region 3, Office of Director 1p 17142 163 24X Fiche 50-155, 83/01/27, 8302140003

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/28 Consolidated Edison Co of New York, Inc. 109pp. 17144:001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/28 Consolidated Edison Co of New York, Inc. 110pp. 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPEARS, R. L. Division of Engineering. 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302280462 Forwards IE Mgt Meeting Rept 50-155/83-02 on 830114 No noncompliance noted
LITTLE, W. B. Division of Engineering 83/02/16 DEWITT, R. B. Consumers Power Co 2pp 17309.220 24X Fiche 50-155, 83/02/16, 8302280462

--8302280465 IE Mgt Meeting Rept 50-155/83-02 on 830114 No noncompliance noted Major areas discussed concerns addressed in IE Insp Rept 50-155/82-13 re fire protection & licensee response
ULIE, J., RAMSEY, C., WILLIAMS, C. C. Region 3, Office of Director. 83/02/12 2pp. 17309 222 24X Fiche 50-155, 83/02/16, 8302280462

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/02/18 Consolidated Edison Co of New York, Inc 110pp. 17347 191. 24X Fiche 50-000, 83/02/18, 8212060363

8302230179 Responds to NRC final evaluation of SEP Topic V-4, "Piping & Safe-End Integrity " Insp of add recirculation & core spray nozzles will be performed during 1983 refueling outage SEP Topic V-4 resolved
TOMER, K. A. Consumers Power Co 83/02/18 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 17243:092 24X Fiche 50-155, 83/02/18, 8302230179

12060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/02/24 Consolidated Edison Co of New York, Inc 11pp. 17347 058. 24X Fiche 50-000, 83/02/24, 8212060365

2060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/02/24 Consolidated Edison Co of New York, Inc. 112pp. 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302010259 Forwards LER 82-034/03L-0
BORDINE, T. C. Consumers Power Co 83/01/24 KEPLER, J. O. Region 3, Office of Director 1p 16974 054 24X Fiche 50-155, 83/01/24, 8302010259

--8302010263 LER 82-034/03L-0 on 821225, during routine plant tour, east-west position switch for reactor gantry crane found defective Caused by inadequate repair actuator arm on crane from last refueling outage Switch repaired on 821228
* Consumers Power Co 83/01/24 Region 3, Office of Director 1p 16974 055 24X Fiche 50-155, 83/01/24, 8302010259

8302040238 Forwards LER 82-035/03L-0
BORDINE, T. C. Consumers Power Co 83/01/28 KEPLER, J. O. Region 3, Office of Director 1p 17020 105 24X Fiche 50-155, 83/01/28, 8302040238

--8302040259 LER 82-035/03L-0 on 821231, main condensate water became mixed w/water in demineralized storage tank Caused by reverse flow path through flow meter FM2101 when solenoid control SV 4883 was de-energized to repair pump motor
* Consumers Power Co 83/01/28 Region 3, Office of Director 1p 17020 106 24X Fiche 50-155, 83/01/28, 8302040238

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

S Reportable occurrences, LERs & related correspondence

8302180412 PND-III-83-013 on 830210, box found in lab near research reactor w/message "bomb do not disturb " Bldg evacuated & box X-rayed & found empty Licensee & local law enforcement agencies investigating
STAPLETON, B., CREED, J., MILLER, J. Region 3, Office of Director 83/02/11 1p 17214 266 24X Fiche 50-156, 83/02/11, 8302180412

DOCKET 50-160 GEORGINA INST OF TECH RESEARCH REACTOR

S Reportable occurrences, LERs & related correspondence

8302150059 PAD-II-83-009 on 830131, inadvertent release of 70 uCi of Co-60 to city sewer sys occurred Caused by valve on closed filter loop of storage pool left open following maint activities Media interest expected
BARR, K., QIBSDON, A. F. Region 2, Office of Director 83/02/08 2pp 17148 031 24X Fiche 50-160, 83/02/08, 8302150059

DOCKET 50-163 GENERAL ATOMIC CO

R Periodic operating reports & related correspondence

8302250233 "Annual Rept for 1982 "
MURRAY, W. R. OA Technologies, Inc /General Atomic Co 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 7pp 17242 097 24X Fiche 50-163, 83/02/22, 8302250233

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

O Adjudicatory correspondence

8302010480 Memorandum & Order memorializing 821015 prehearing conference Admitted contentions set forth in app
HOYT, H. F. Atomic Safety and Licensing Board Panel 83/01/28 18pp 16981 050 24X Fiche 50-170, 83/01/28, 8302010480

8302240297 Requests NRC delay renewal of license until complete impact statements prepared & public hearing held
GILCHRIST, C. W., SCULL, D. L. Montgomery County, MD 83/02/15
PALLADINO, N. Commissioners 2pp 17274 079 24X
Fiche 50-170, 83/02/15, 8302240297

8302230530 Responds to 821029 request for brief summary of events which transpired during 821029 site visit
RICKARD, D C Defense, Dept of, Defense Nuclear Agency 83/02/18
HOYT, H Atomic Safety and Licensing Board Panel 4pp 17256 281
24X Fiche 50-170, 83/02/18, 8302230530

8302280279 Motion for summary disposition of Citizens for Nuclear Reactor Safety contentions No genuine issue of matl fact exists & dismissal warranted as matter of law
BACHMANN, R O Hearing Branch 1 83/02/25 Atomic Safety and Licensing Board Panel 4pp 17310 255 24X Fiche 50-170, 83/02/25, 8302280279

--8302280282 Statement of matl facts as to which there is no genuine issue to be heard in support of motion for summary disposition of Citizens for Nuclear Reactor Safety contentions
BACHMANN, R O Hearing Branch 1 83/02/25 Atomic Safety and Licensing Board Panel 13pp 17310 296 24X Fiche 50-170, 83/02/25, 8302280279

--8302280286 Affidavit of RE Carter supporting NRC motion for summary disposition of Citizens for Nuclear Reactor Safety contentions Certificate of Svc encl
CARTER, R E Division of Licensing 83/02/24 32pp 17310 309 24X Fiche 50-170, 83/02/25, 8302280279

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8302040624 Requests route approval for shipment of spent fuel from site to ID Falls, ID Request withheld (ref 10CFR2 790)
MCQUINTY, D M Missouri, Univ of, Columbia 82/03/23 HILLMAN, C Division of Safeguards 1p 17042 039 24X Fiche 50-186, 82/03/23, 8302040624

8302040437 Forwards schedule for spent fuel shipments Schedule withheld (ref 10CFR73 21)
MCQUINTY, D M Missouri, Univ of, Columbia 83/01/06 HILLMAN, C Physical Security Licensing Branch 1p 17042 320 24X Fiche 50-186, 83/01/06, 8302040437

R Periodic operating reports & related correspondence

8302230401 Forwards "Annual Rept, Jul 1981 - June 1982" Cancellation of planned performance appraisal will add to productivity w/no sacrifice in safety
ALGER, D M Missouri, Univ of, Columbia 83/02/16 PARTLOW, J O Operating Reactors Program Branch 1p 17297 101 24X Fiche 50-186, 83/02/16, 8302230401

--8302230484 "Annual Rept, Jul 1981 - June 1982"
* Missouri, Univ of, Columbia 83/02/16 103pp 17297 102 24X Fiche 50-186, 83/02/16, 8302230401

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8302070279 Ack receipt of 830124 ltr informing NRC of steps taken to correct violations noted in IE insp rept
BOOK, H E Division of Radiological Safety & Safeguards Program 83/01/31 CRANDELL, W Northrop Research & Technical Center 1p 17029 197 24X Fiche 50-187, 83/01/31, 8302070279

--8302070282 Responds to NRC 821124 ltr re violations noted in IE insp rept Corrective actions procedures written & approved for calibr of area radiation & air particulate monitors
CRANDELL, W E Northrop Research & Technical Center 83/01/24 WENSLAWSKI, F A Division of Radiological Safety & Safeguards Program 2pp 17029 198 24X Fiche 50-187, 83/01/31, 8302070279

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

P Operating license stage documents & correspondence

8302070256 Application for amend to 800103 renewal application for License R-92, requesting license renewal period of 20 yrs
BAUER, T L, KLEIN, D E, FOKKEN, Q J Texas, Univ of 83/01/27 BERNARD, H Standardization & Special Projects Branch 1p 17031 339 24X Fiche 50-192, 83/01/27, 8302070256

8302100367 Forwards eight oversize blueprints showing const & renovation plans for areas encompassing nuclear engineering teaching lab Aperture cards are available in PDR
BAUER, T L Texas, Univ of 83/02/07 BERNARD, H Standardization & Special Projects Branch 2pp 17112 063 24X Fiche 50-192, 83/02/07, 8302100367

8302100417 Forwards pages to be appended to Chapter 5 of SAR re two experimental facilities Co-60 irradiator maintained in reactor tank Subcritical assembly, separately licensed from reactor, included for completeness
BAUER, T L Texas, Univ of 83/02/07 BERNARD, H Standardization & Special Projects Branch 4pp 17112 195 24X Fiche 50-192, 83/02/07, 8302100417

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

G Inspection reports, IE Bulletins & correspondence

8302010369 Ack receipt of 830103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-193/82-02
STAROSTECKI, R Division of Project & Resident Programs. 83/01/18 DIMEGLIO, F Rhode Island & Providence Plantation 1p 16973 301 24X Fiche 50-193, 83/01/18, 8302010369

--8302010372 Responds to NRC 821215 ltr re violations noted in IE Insp Rept 50-193/82-02 Corrective actions storage area monitor modified to provide clearly audible alarm signal if accidental criticality occurs
DIMEGLIO, F Rhode Island & Providence Plantation 83/01/03 STAROSTECKI, R Division of Project & Resident Programs 2pp 16973 302 24X Fiche 50-193, 83/01/18, 8302010369

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

G Adjudicatory correspondence

8302230511 Forwards Amend 13 to Indemnity Agreement B-29, per ABLB B11231 memorandum & order directing filing of further info Certificate of Svc encl.
WOLF, J R Regulations Division 83/02/18 BRENNER, L, MORRIS, P A, HARBOUR, J Atomic Safety and Licensing Board Panel 4pp 17297 237 24X Fiche 50-201, 83/02/18, 8302230511

J Insurance & indemnity information

8302240034 Forwards Amend 13 to Indemnity Agreement B-29, per 830112 request, Amend reflects NRC order terminating NRB authority
JACK, H A New York, State of, Energy Research & Development Administration 83/02/10 SALTZMAN, J Assistant Director for State & License Relations 2pp 17275 013 24X Fiche 50-201, 83/02/10, 8302240034

8302230511 Forwards Amend 13 to Indemnity Agreement B-29, per ABLB B11231 memorandum & order directing filing of further info Certificate of Svc encl.
WOLF, J R Regulations Division 83/02/18 BRENNER, L, MORRIS, P A, HARBOUR, J Atomic Safety and Licensing Board Panel 4pp 17297 237 24X Fiche 50-201, 83/02/18, 8302230511

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302070025 Addl response to FOIA request for documents re packaging & transporting of spent nuclear fuel away from reactor sites by util Forwards Documents 1-27 Documents 28-31 withheld (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 82/11/23. RAPKIN, A, Illinois, State of 3pp 17062 013 24X Fiche 50-206, 82/11/23, 8302070025

--8302070027 Requests that P Reed be informed in advance of spent fuel shipments transiting OK
BURNETT, R F NRC - No Detailed Affiliation Given 79/11/02 MCCORMACK, O NRC - No Detailed Affiliation Given 1p 17062 021, 24X Fiche 50-206, 82/11/23, 8302070025

--8302070036 Forwards spent fuel route data for San Onofre, CA to Morris, IL Route changed at Greensburg, KS due to three bridges w/weight restrictions Fifty-four mile segment not surveyed by team W/o encl
BLACK, H Physical Security Development Branch. 79/11/21 HILLMAN, C Physical Security Licensing Branch. 2pp 17062 022 24X Fiche 50-206, 82/11/23, 8302070025

DOCKETED ITEMS

--B302070049 Forwards corrected P 12 to 791210 road transportation route, San Onofre, CA to Morris, IL erroneously reflecting route through MO rather than transiting IL Details withheld (ref 10CFR9 12)
MCCORKLE, O W Physical Security Licensing Branch 79/12/17
SEAMAN, W H Southern California Edison Co 2pp 17062 025 24X
Fiche 50-206, 82/11/23, B302070025

--B302070053 Forwards info re 103 shipments using Nuclear Assurance Corp casks Seven-day notice requirement for each shipment affects multiple shipping operations Last minute adjustments to specific schedules should be allowed
LADESICH, J Southern California Edison Co 80/01/03
NORDERHAUG, L Region 5, San Francisco, Office of the Director (B1/03/01) 13pp 17062 027 24X Fiche 50-206, 82/11/23, B302070025

--B302070062 Notifies of Shipment 268 of spent nuclear fuel to GE Morris storage facility on 800804
RADFORD, J K Southern California Edison Co 80/07/17 Region 5, San Francisco, Office of the Director 1p 17062 042 24X
Fiche 50-206, 82/11/23, B302070025

--B302070064 Notifies of Shipment 269 of spent nuclear fuel to GE Morris storage facility on 800805 Handwritten note encl
RADFORD, J K Southern California Edison Co 80/07/17 Region 5, San Francisco, Office of the Director 2pp 17062 043 24X
Fiche 50-206, 82/11/23, B302070025

--B302070066 Notifies of Shipment 268 of spent nuclear fuel to GE Morris storage facility on 800806
RADFORD, J K Southern California Edison Co 80/07/28 Region 5, San Francisco, Office of the Director 1p 17062 045 24X
Fiche 50-206, 82/11/23, B302070025

--B302070072 Notifies of shipment of spent nuclear fuel to GE Morris storage facility on 800805
RADFORD, J K Southern California Edison Co 80/07/28 Region 5, San Francisco, Office of the Director 1p 17062 046 24X
Fiche 50-206, 82/11/23, B302070025

--B302070078 Advises that util intends to resume shipments of irradiated reactor fuel in early Aug Two trucks will be used, departing initially 24-48 h apart, each making round trip & subsequent departure every 7 or 8 days
NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch 80/07/30 2pp 17062 047 24X
Fiche 50-206, 82/11/23, B302070025

--B302070082 Notifies of Shipment 269 of spent nuclear fuel to GE Morris storage facility on 800818
HANDSHUH, J W Southern California Edison Co 80/08/18 Region 5, San Francisco, Office of the Director 1p 17062 050 24X
Fiche 50-206, 82/11/23, B302070025

--B302070084 Notifies of Shipment 270 of spent nuclear fuel to GE Morris storage facility on 800820
HANDSHUH, J W Southern California Edison Co 80/08/13 Region 5, San Francisco, Office of the Director 1p 17062 051 24X
Fiche 50-206, 82/11/23, B302070025

--B302070089 Discusses survey of bypass routes for Springfield, IL Recommends bypass via US-24 for US-36 into IL for spent fuel shipments Route survey included visits to LLEA in IA, MO & IL
MITCHELL, H H NRC - No Detailed Affiliation Given 80/08/26
BLACK, H NRC - No Detailed Affiliation Given 2pp 17062 052 24X Fiche 50-206, 82/11/23, B302070025

--B302070102 Notifies of Shipment 271 of spent nuclear fuel to GE Morris storage facility on 800911
HANDSHUH, J W Consumers Power Co 80/09/05 Region 5, San Francisco, Office of the Director 1p 17062 055 24X
Fiche 50-206, 82/11/23, B302070025

--B302070109 Informs that staff advised to attach increased significance to selection of spent fuel shipment routes to avoid unnecessary stops & meet new DOT regulations Licensees encouraged to use state preferred highways
BURNETT, R F Division of Safeguards 80/11/17 SEAMAN, W H Southern California Edison Co 1p 17062 058 24X
Fiche 50-206, 82/11/23, B302070025

102070112 Requests that new route be submitted satisfying DOT requirements if transport of spent fuel to Morris facility resumed
MCCORKLE, O W Physical Security Licensing Branch 81/04/21
SEAMAN, W H Southern California Edison Co 1p 17062 079 24X
Fiche 50-206, 82/11/23, B302070025

--B302070117 Requests rev to approved route for shipping spent fuel from util to Morris storage facility in IL Armed escorts will be used along route Current route will be used until Feb 1982
Description of proposed route encl
LADESICH, J Southern California Edison Co 81/06/23
MCCORKLE, O W Physical Security Licensing Branch 2pp 17062 126 24X Fiche 50-206, 82/11/23, B302070025

--B302070128 Responds to B10408 note re shipments of spent nuclear fuel through Congressman Findley district Revised route requested on B10623 does not enter district Route in IL is Interstate 80
BURNETT, R F Division of Safeguards 81/09/14 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 4pp 17062 129 24X Fiche 50-206, 82/11/23, B302070025

--B302070134 Informs that B10623 request for rev to spent fuel route has been approved Arrangements made w/law enforcement agencies along route Info re arrangements & approved route encl
MCCORKLE, O W Physical Security Licensing Branch 81/08/07
SEAMAN, W H Southern California Edison Co 27pp 17062 133 24X
Fiche 50-206, 82/11/23, B302070025

B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340

B302150002 Forwards IE Safeguards Insp Rept 50-206/83-02 on B30110-14 No noncompliance noted Major area inspected physical protection program against radiological sabotage & theft of SRM Rept withheld (ref 10CFR2 790 & 73 21)
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 83/02/03 PAPAY, L T Southern California Edison Co 2pp 17155 233 24X Fiche 50-206, 83/02/03, B302150002

B302150332 Notifies that resources necessary to reply to Generic Ltrs 82-28 & 82-33, requesting identification of design for reactor coolant inventory sys & schedule for completion of requirements for emergency response capability, unavailable
BASKIN, K P Southern California Edison Co 83/02/10 EISENHUT, D G Division of Licensing 2pp 17157 255 24X Fiche 50-206, 83/02/10, B302150332

B302160391 Forwards Jan 1983 physical security plan Plan withheld (ref 10CFR73 21)
BASKIN, K P Southern California Edison Co 83/02/11 Office of Nuclear Reactor Regulation, Director 1p 17164 204 24X
Fiche 50-206, 83/02/11, B302160391

B302220378 Notifies that util will submit proposed change to address Generic Ltrs 82-17 & 82-23 re Tech Specs for performing audits of emergency preparedness programs & safeguards contingency plans by B30315
KRIEGER, R W Southern California Edison Co 83/02/17 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17232 227 24X
Fiche 50-206, 83/02/17, B302220378

J Insurance & indemnity information

B302180329 Forwards Endorsements 91-93 & 36 to NELIA Policies NF-146 & NS-282, respectively, Endorsements 80-82 to MAELU Policy NF-38, Endorsement 8 to NELIA Binders EB-10 & EB-81 & MAELU Binder XB-81 & Certificates M-87 & M-87
ROCCO, J Southern California Edison Co 83/02/14 DINITZ, I Antitrust & Economic Analysis Branch (Utility Finance) 38pp 17213 266 24X Fiche 50-206, 83/02/14, B302180329

P Operating license stage documents & correspondence

B302020353 FOIA request for Sandia Natl Lab rept detailing potential results of serious accidents at nuclear power plants & info re existing evacuation plans & other contingency safety measures at facilities
POLLOCK, D., HAYS, S Affiliation Unknown 82/11/08 Division of Rules and Records 2pp 16996 024 24X Fiche 50-206, 82/11/08, B302020353

B302020359 Responds to FOIA request for Sandia Natl Lab rept detailing results of accidents at nuclear power plants & info re evacuation plans at facilities Forwards Documents 2 & 3 listed in App A App B documents available in LPDR
FELTON, J M Division of Rules and Records 82/12/06 POLLOCK, D., HAYS, S Affiliation Unknown 3pp 16996 026 24X
Fiche 50-206, 82/12/06, B302020359

8302080100 Addl response to FOIA request for records re steam generators & steam turbines Forwards documents listed under Category A of App E Category B documents available in PDR
FELTON, J M Division of Rules and Records 82/12/17 LONG, D J
Winthrop, Stinson, Putnam & Roberts 5pp 17105 069 24X
Fiche 50-000, 82/12/17, 8302080100

--8302080127 Forwards request for addl info re steam generator tube integrity Questions specifically address tubes in U-bend region
EISENHUT, D O Division of Operating Reactors 76/12/14
GOLLER, K R Assistant Director for Operating Reactor Projects (Pre 791030) App 17105 145 24X Fiche 50-000, 82/12/17, 8302080100

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 13, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

8302020357 Forwards marked-up draft safety evaluation re SEP Topic III-1, "Quality Group Classification of Components & Sys" & Topic III-2, B, "Design Codes, Design Criteria & Load Combinations"
KRIEGER, R W Southern California Edison Co 83/01/26
CRUTCHFIELD, D Operating Reactors Branch 5 51pp 16994 116 24X
Fiche 50-206, 83/01/26, 8302020357

8302010652 Notification of 830217 meeting w/util in Bethesda, MD to discuss resolution of issues re seismic re-evaluation of unit (SEP Topic III-6)
PAULSON, W A Operating Reactors Branch 5 83/01/31 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16980 051 24X
Fiche 50-206, 83/01/31, 8302010652

8302020142 Forwards 98 oversize P&IDs, in response to NRC request for info to be used in performance of limited scope PRA on facility Aperture cards are available in PDR
KRIEGER, R W Southern California Edison Co 83/01/31
PAULSON, W A, MCKENNA, E NRC - No Detailed Affiliation Given 1p 16994 336 24X Fiche 50-206, 83/01/31, 8302020142

8302020241 Informs that revised assessment for SEP Topic II-4 F & revised 820817 repts re backfill conditions being prepared in response to 821201 request for addl info Submittal expected by 830218
KRIEGER, R W Southern California Edison Co 83/01/31
CRUTCHFIELD, D Operating Reactors Branch 5 1p 16994 335 24X
Fiche 50-206, 83/01/31, 8302020241

8302180233 Forwards draft evaluation of SEP Hydrology Topics II-3 A, II-3 B, II-3 B 1 & II-3 C, "Hydrological Considerations (SEP, II-3A, B, 1, C), San Onofre Nuclear Generating Station Unit 1," technical evaluation repts encl
PAULSON, W Operating Reactors Branch 5 83/01/31 DIETCH, R Southern California Edison Co 39pp 17215 020 24X
Fiche 50-206, 83/01/31, 8302180233

--8209160339 "Hydrological Considerations (SEP, II-3A, B, 1, C), San Onofre Nuclear Generating Station Unit 1," technical evaluation repts
SCHERRER, J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5297-423 82/09/14 STALEY, O NRC - No Detailed Affiliation Given 60pp 17215:039 24X
Fiche 50-206, 83/01/31, 8302180233

8302070429 Forwards evaluation of SEP Topic III-2 re wind & tornado loadings Portions of most structures unable to withstand postulated design basis tornado load of 250 mph wind & 1.5 psi pressure drop Response requested within 30 days
PAULSON, W Operating Reactors Branch 5 83/02/01 DIETCH, R Southern California Edison Co 13pp, 17061 105 24X
Fiche 50-206, 83/02/01, 8302070429

--8209080535 "Wind & Tornado Loadings (SEP III-2)," technical evaluation repts
AGARWAL, R Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5297-404 82/09/03 PERBINKO, D, NRC - No Detailed Affiliation Given 57pp 17061 118 24X
Fiche 50-206, 83/02/01, 8302070429

8302070612 Forwards final SER of SEP Topic VI-7 A 3, "ECSS Actuation Sys," based on 81118 technical evaluation & 830120 ltr Current licensing criteria for testing electrical portions of ECSS net
PAULSON, W A Operating Reactors Branch 5 83/02/01 DIETCH, R Southern California Edison Co 4pp 17034 267 24X
Fiche 50-206, 83/02/01, 8302070612

8302070615 Forwards final evaluation of SEP Topic III-4, B, "Turbine Missiles," reflecting 830120 info Evaluation will be basic input to, integrated safety assessment for facility
PAULSON, W A Operating Reactors Branch 5 83/02/01 DIETCH, R Southern California Edison Co 6pp 17035 046 24X
Fiche 50-206, 83/02/01, 8302070615

8302080015 Forwards draft, "Summary of San Onofre Unit 1 Safety Injection Piping Analysis," per SEP Topic III-6, "Seismic Design Considerations" Review & comments requested within 45 days of ltr receipt
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/01 DIETCH, R Southern California Edison Co 2pp 17058 201 24X
Fiche 50-206, 83/02/01, 8302080015

--8302080019 Draft "Summary of San Onofre Unit 1 Safety Injection Piping Analysis"
BUSCH, S L EG&O, Inc 83/01/20 NRC - No Detailed Affiliation Given 52pp 17059 203 24X Fiche 50-206, 83/02/01, 8302080015

8302090305 Notifies that util Comment 4 re intermediate-range nuclear instrumentation in 830120 ltr re SEP Topic VII-1 A should be disregarded
KRIEGER, R W Southern California Edison Co 83/02/07
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17070 241 24X
Fiche 50-206, 83/02/07, 8302090305

8302180466 Forwards summary of 36 SEP topics w/unresolved differences Proposed corrective actions & basis for actions should be submitted within 90 days of receipt of ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/07 DIETCH, R Southern California Edison Co 43pp 17215 194 24X
Fiche 50-206, 83/02/07, 8302180466

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp, 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSB (except Yankee Atomic Electric Co) re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302150184 Advises that submittal of proposed Tech Specs to support 760421 request for exemption from 10CFR50, App J, re containment leakage testing, will be delayed until 830415, in response to NRC 820803 ltr
KRIEGER, R W Southern California Edison Co 83/02/10
CRUTCHFIELD, D Operating Reactors Branch 5 1p 17147 222, 24X
Fiche 50-206, 83/02/10, 8302150184

8302150227 Advises that plans & schedule for qualification of replacement of safety-related equipment will be submitted by 830320, per 821130 SER
BASKIN, K P Southern California Edison Co 83/02/10
CRUTCHFIELD, D, Operating Reactors Branch 5 2pp, 17149 269 24X
Fiche 50-206, 83/02/10, 8302150227

8302150332 Notifies that resources necessary to reply to Generic Ltrs 82-28 & 82-33, requesting identification of design for reactor coolant inventory sys & schedule for completion of requirements for emergency response capability, unavailable.
BASKIN, K P Southern California Edison Co 83/02/10 EISENHUT, D O Division of Licensing 2pp 17157 255 24X Fiche 50-206, 83/02/10, 8302150332

DOCKETED ITEMS

8302220118 Notification of contract execution, Mod 3 to "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." Contractor St Louis Univ LITTLE, H. Administrative Contracts Branch. FIN 8-6898 83/02/10 VOLLMEYER, R. H. Division of Engineering JACKSON, R. NRC - No Detailed Affiliation Given 1p 17234 216 24X Fiche 50-206, 83/02/10, 8302220118

--8302220125 Mod 3, extending period of performance by 1 yr & adding requirement for monthly business ltr rept. to "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." HERRMANN, R. St Louis Univ REBELLO, J. E. Division of Contracts FIN 8-6898 83/02/10 3pp 17234 217 24X Fiche 50-206, 83/02/10, 8302220118

8302230400 Forwards final technical evaluation rept of SEP Topic VII-1 A, "Isolation of Reactor Protection Sys From Non-Safety Sys, Including Qualification of Isolation Devices." Present isolation schemes need justification PAULSON, R. H. Operating Reactors Branch 5 83/02/10 DIETCH, R. Southern California Edison Co 18pp 17247 251 24X Fiche 50-206, 83/02/10, 8302230400

8302160394 Forwards 27 oversize electrical & one line diagrams, in response to NRC request for info to be used in performing limited scope FRA on facility. Aperture cards are available in PDR KRIEGER, R. W. Southern California Edison Co 83/02/11 PAULSON, R. H. MCKENNA, E. NRC - No Detailed Affiliation Given 1p 17163 182 24X Fiche 50-206, 83/02/11, 8302160394

8302240308 Notification of 830224 meeting w/uttl & AE in Bethesda, MD to discuss licensee structural upgrade proposal WANG, A. B. Systematic Evaluation Program Branch 83/02/13 RUSSELL, W. T. Systematic Evaluation Program Branch. 1p 17284 352 24X Fiche 50-206, 83/02/13, 8302240308

8302180418 Submits update of schedule for post-TMI requirements for Items 1 A 3, I C 1, II B 2, II B 3, II D 1, II E 1 2, II F 1, II K 3 30, II K 3 31, III A 2 & III D 3 4, per request BASKIN, K. P. Southern California Edison Co 83/02/16 CRUTCHFIELD, D. Operating Reactors Branch 5 4pp 17214 288 24X Fiche 50-206, 83/02/16, 8302180418

8302250250 Submits comments on NRC 820201 SER for SEP Topic XV-5, "Loss of Normal Feedwater Flow." Auxiliary feedwater sys automatically initiated on low steam generator level KRIEGER, R. W. Southern California Edison Co 83/02/23 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 17292 285 24X Fiche 50-206, 83/02/23, 8302250250

G Inspection reports, IE Bulletins & correspondence

8302070278 Addl response to FOIA request for documents re EE Kent allegations concerning facilities FELTON, J. M. Division of Rules and Records 82/12/13 CARPENTER, T. Orange County Alliance for Survival 1p 17060 001 24X Fiche 50-206, 82/12/13, 8302070278

--8302070296 Confirms discussions re request for technical assistance concerning allegations by EE Kent EE Kent statement encl CRENSHAW, J. L. Region 5, Office of Director 82/10/29 EISENHUT, D. G. Division of Licensing 8pp 17060 249 24X Fiche 50-206, 82/12/13, 8302070278

8302040499 FOIA request for documents re special insp rept GARDE, B. Government Accountability Project 82/12/14 Office of Administration. 2pp 17042 262 24X Fiche 50-206, 82/12/14, 8302040499

8302130366 Forwards IE Insp Repts 50-206/82-34, 50-361/82-44 & 50-362/82-28 on 821116-1216 No noncompliance noted BISHOP, T. W. Division of Resident/Reactor Project & Engineering Programs 83/01/12 PAPAY, L. T. Southern California Edison Co 2pp 17157, 210 24X Fiche 50-206, 83/01/12, 8302130366

--8302150373 IE Insp Repts 50-206/82-34, 50-361/82-44 & 50-362/82-28 on 821116-1217 No noncompliance noted Major areas inspected GA program & station organization & administration, qualification of personnel & calibr of instrumentation STEWART, J. P., KIRSCH, D. F. Division of Resident/Reactor Project & Engineering Programs 83/01/10 9pp 17157 212 24X Fiche 50-206, 83/01/12, 8302150366

160457 Addl response to FOIA request for documents re EE Kent allegations concerning facilities, Forwards documents listed in Apps A & B Documents partially withheld (ref FOIA exemptions 5, 6 & 7) Tapes available in PDR FELTON, J. M. Division of Rules and Records 83/01/12 CARPENTER, T. Orange County Alliance for Survival 4pp 17175, 194 24X Fiche 50-206, 83/01/12, 8302160457

--8302160460 Submits notes taken at Region V 821014 mgt meeting re EE Kent allegations Considered actions listed Reporters raised questions re allegations Related info encl SHACKLETON, O. C. Region 5, Office of Director 82/10/14 Region 5, Office of Director 23pp 17175 197 24X Fiche 50-206, 83/01/12, 8302160457

8302040905 Partial response to FOIA request for documents re special insp rept Documents listed on encl app available in PDR in folders "FOIA-82-528 Carpenter." Search for addl documents in progress FELTON, J. M. Division of Rules and Records 83/01/13 GARDE, B. Government Accountability Project 3pp 17042 259 24X Fiche 50-206, 83/01/13, 8302040905

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/25 Consolidated Edison Co. of New York, Inc 18pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150002 Forwards IE Safeguards Insp Rept 50-206/83-02 on 830110-14 No noncompliance noted Major area inspected physical protection program against radiological sabotage & theft of SNM Rept withheld (rer 10CFR2.790 & 73.21) NORDENHAU, L. R. Division of Radiological Safety & Safeguards Program 83/02/03 PAPAY, L. T. Southern California Edison Co 2pp 17155 233 24X Fiche 50-206, 83/02/03, 8302150002

8302150112 Ack receipt of 830128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-36 Util submittal describing reassessment results & planned actions re operational radiation monitoring sys expected by 830501 BOOK, H. E. Division of Radiological Safety & Safeguards Program 83/02/04 PAPAY, L. T. Southern California Edison Co 1p 17146 144 24X Fiche 50-206, 83/02/04, 8302150112

--8302150120 Responds to NRC 821229 ltr re violations noted in IE Insp Rept 50-206/82-36 Corrective actions seven stack gas & particulate monitors calibr Current status of specific items requested in NRC 821229 ltr discussed PAPAY, L. T. Southern California Edison Co 83/01/28 ENDELKEN, R. H. Region 5, Office of Director 4pp 17146 145 24X Fiche 50-206, 83/02/04, 8302150112

8302230365 Forwards IE Insp Repts 50-206/83-03, 50-361/83-04 & 50-362/83-05 on 830117-21 & notice of violation BOOK, H. E. Division of Radiological Safety & Safeguards Program 83/02/04 PAPAY, L. T. Southern California Edison Co 2pp 17246 292 24X Fiche 50-206, 83/02/04, 8302230365

--8302230371 Notice of violation from insp on 830117-21 WENSLAWSKI, F. A. Division of Radiological Safety & Safeguards Program 83/02/04 1p 17246 294 24X Fiche 50-206, 83/02/04, 8302230365

--8302230378 IE Insp Repts 50-206/83-03, 50-361/83-04 & 50-362/83-05 on 830117-21 Noncompliance noted failure to submit 30-day special rept & one unresolved item involving meeting acceptance criteria of Reg Guide 4.13 YUHAS, O. P., WENSLAWSKI, F. A., BOOK, H. E. Division of Radiological Safety & Safeguards Program 83/02/03 9pp 17246 295 24X Fiche 50-206, 83/02/04, 8302230365

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

DOCKETED ITEMS

25

F Hearing transcripts on non-antitrust matters

8302070278 Addl response to FOIA request for documents re EE Kent allegations concerning facilities
FELTON, J M Division of Rules and Records 82/12/13 CARPENTER, T
Orange County Alliance for Survival 1p 17060 001 24X
Fiche 50-362, 82/12/13, 8302070278

--8302070285 Draft transcript of EE Kent taped 821015 interview in Dana Point, CA of allegations re weld const quality at facilities
Pp 1-257 Related into encl
SHACKLETON, D C, JOUKOFF, P V, KIRSCH, D F Director's Office,
Office of Inspection and Enforcement 82/10/15 243pp
17060 006 24X Fiche 50-206, 82/12/13, 8302070278

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLE, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKE1 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

8301190078 Forwards revised reporting procedure of security events Procedure withheld (ref 10CFR73 21)
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/01/07 MCCORMACK, G Licensing
Management Branch 3pp 16846 303 24X Fiche 50-000, 83/01/07,
8301190078

--8301190084 Requests review & comment on encl "NRC Notification of Serious Physical Security Events Procedure" Procedure withheld (ref 10CFR73 21)
GRAVES, R H Connecticut Yankee Atomic Power Co 81/11/10
JOYNER, J H Division of Engineering & Technical Inspection 1p
16046 306 24X Fiche 50-213, 83/01/07, 8301190078

8302030345 Discusses filing of copies of changes to emergency plans & procedures Util requested to continue submitting three copies to Region I or two copies to Region I w/one copy directly submitted to resident inspector
MARTIN, T T Division of Engineering & Technical Programs 83/01/24
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17006 108 24X Fiche 50-000, 83/01/24, 8302030345

8302010081 Releases public version of revised title pages to Emergency Plans
FELTON, J M Division of Rules and Records 83/01/26 Document
Management Branch 1p 16990 233 24X Fiche 50-000, 83/01/26,
8302010081

--8302010084 Forwards public version of revised title pages to Millstone & Haddam Neck Nuclear Power Plant Emergency Plans, including correction to site plan Figure 7-1c re lines of communication between emergency response ctrs
ST PIERRE, M Northeast Utilities 83/01/13 BAILEY, I NRC - Nn
Detailed Affiliation Given 1p 16990 234 24X
Fiche 50 000, 83/01/26, 8302010081

--8302010091 Public version of revised title page to Millstone Nuclear Plant Emergency Plan
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/01/13 1p 16990 235 24X Fiche 50-000, 83/01/26, 8302010081

--8302010097 Public version of revised title page to Haddam Neck Nuclear Plant Emergency Plan & correction to site plan Figure 7-1c re lines of communication between emergency response ctrs
* Connecticut Yankee Atomic Power Co 83/01/13 4pp 16990 236
24X Fiche, 50-000, 83/01/26, 8302010081

8302030033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17027 004 24X Fiche 50-000, 83/01/31,
8302030033

--8302030043 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4101 re unusual event actions, EPIP 4102 re alert & EPIP 4103 re site area emergency
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/01/07 EISENHUT, D O
Division of Licensing 2pp 17027 005 24X Fiche 50-000,
83/01/31, 8302030033

--8302030052 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4101 re unusual event actions, EPIP 4102 re alert & EPIP 4103 re site area emergency
* Connecticut Yankee Atomic Power Co * Northeast Nuclear Energy Co (subs of Northeast Utilities) * Northeast Utilities
82/12/15 653pp 17027 007 24X Fiche 50-000, 83/01/31,
8302030033

8302070566 Lists objectives of fire protection program PRA to quantify overall frequency of failure to achieve safe shutdown as result of fire at facilities
COUNSIL, W O Northeast Utilities COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/31 EISENHUT, D O Division of Licensing 2pp 17034 282 24X Fiche 50-000, 83/01/31, 8302070566

8302090304 Forwards addl info re control board fire analysis in support of util request for exemption from 10CFR50, App R requirements
COUNSIL, W O Connecticut Yankee Atomic Power Co 83/01/31
EISENHUT, D O Division of Licensing 39pp 17070 118 24X
Fiche 50-213, 83/01/31, 8302090304

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070198 Forwards Rev 9 to modified amended security plan Rev withheld (ref 10CFR2 790 & 73 21(b))
COUNSIL, W O Connecticut Yankee Atomic Power Co 83/02/03
CRUTCHFIELD, D Operating Reactors Branch 5 1p 17031 308 24X
Fiche 50-213, 83/02/03, 8302070198

8302230410 Forwards IE Insp Rept 50-213/82-22 on 821206-830102 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/02/07
COUNSIL, W O Connecticut Yankee Atomic Power Co 2pp 17245 323
24X Fiche 50-213, 83/02/07, 8302230410

--830223041B IE Insp Rept 50-213/82-22 on 821206-830102 No noncompliance noted Major areas inspected periodic & special repts, operating records, surveillance activities, physical security & radioactive waste sys controls
REBELQSKI, T, BRIGGS, L, ELBASSER, T C Division of Project & Resident Programs 83/02/02 15pp 17245 325 24X
Fiche 50-213, 83/02/07, 8302230410

8302160224 Recommends NRC prepare status rept of NRC contractor studies re radioactive iodine source terms & issue of potassium iodine Rept would help resolve issue for state & local emergency preparedness personnel
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/02/08 EISENHUT, D O
Division of Licensing 2pp 17166 292 24X Fiche 50-000, 83/02/08,
8302160224

J Insurance & indemnity information

8302020054 Forwards Endorsements 73 & 65 to NELIA Policy NF-15 & M&L Policy NF-39, respectively
BINISI, J M Marsh & McLennan, Inc / M & M Nuclear Consultants, Inc
Div 83/01/25 SALTZMAN, J B Assistant Director for State & License Relations 3pp 17004 333 24X Fiche 50-213, 83/01/25,
8302020054

P Operating license stage documents & correspondence

8302010301 Forwards addl reporting criteria for unplanned liquid radioactive releases New criteria cover specific types of potential liquid releases not presently covered Response requested by 830403
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/01/21 HAYNES, R C, Region 1,
Office of Director 7pp 16973 092 24X Fiche 50-000, 83/01/21,
8302010301

DOCKETED ITEMS

- 8302040278 Forwards response to NRC SER re environ qualification of safety-related electrical equipment Implementation guide should be provided for review or NRC should explain why document will not be provided
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/01/21
CRUTCHFIELD, D Operating Reactors Branch 5 208pp 17019 109 24X
Fiche 50-213, 83/01/21, 8302040278
- 8302040226 Forwards Amend's 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively & notice of issuance & availability
Amends reflect organizational changes Haddam Neck amend also approves change to upper range intake water temp sensor
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 COUNCIL, W O
Connecticut Yankee Atomic Power Co 5pp 17020 115 24X
Fiche 50-000, 83/01/26, 8302040226
- 8302040231 Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively, revising App B Tech Spec re organizational changes & changing upper range intake water temp sensor for Haddam Neck
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 23pp
17020 120 24X Fiche 50-000, 83/01/26, 8302040226
- 8302040240 Notice of issuance & availability of Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 2pp
17020 143 24X Fiche 50-000, 83/01/26, 8302040226
- 8302040283 Clarifies position stated in 820401 ltr re NUREG-0737, item I C 6, "Procedure to Verify Correct Performance of Operating Activities " Efforts underway to formalize procedure addressing second verification checklist for components
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/01/27
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17020 060 24X
Fiche 50-213, 83/01/27, 8302040283
- 8302040264 Forwards "Risk Based Categorization of Haddam Neck SEP Issues"
JOHNSON, B W Science Applications, Inc 83/01/28 BAJWA, S NRC -
No Detailed Affiliation Given 1p 17032 001. 24X
Fiche 50-213, 83/01/28, 8302070264
- 8302070269 "Risk Based Categorization of Haddam Neck SEP Issues "
AMICO, P, ATEFI, B, CHOI, M Science Applications, Inc
NRC-03-92-096 841-83-128-WA 83/01/28 NRC - No Detailed
Affiliation Given 142pp 17032 002 24X Fiche 50-213, 83/01/28,
8302070264
- 8302070384 Forwards response to NRC request for documentation of four open items re SEP Topic III-6, "Seismic Design Considerations " Final responses on structural analysis currently scheduled for submittal on or about 830207
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/01/28
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17030 038 24X
Fiche 50-213, 83/01/28, 8302070384
- 8302040200 Forwards request for addl info re NUREG-0737, item II K 3 23 concerning power to pump seals Response requested within 60 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/01 COUNCIL, W O
Connecticut Yankee Atomic Power Co 3pp 17021 331. 24X
Fiche 50-213, 83/02/01, 8302040200
- 8302070432 Application to amend License DPR-61, revising Tech Spec 3 4 re lowering of min temp required at given pressure during operational leak rate & hydrostatic testing Supporting technical data & Class III amend fee encl.
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/02/01
CRUTCHFIELD, D Operating Reactors Branch 5 5pp 17029 281 24X
Fiche 50-213, 83/02/01, 8302070432
- 8302070433 Proposed Tech Spec 3 4 re lowering of min temp required at given pressure during operational leak rate & hydrostatic testing
* Connecticut Yankee Atomic Power Co 83/02/01 3pp 17029 286
24X Fiche 50-213, 83/02/01, 8302070432
- 8302080202 Application for amend to License DPR-61, changing Tech Specs to incorporate lower min temp required at given pressure during operational leak rate testing & hydrostatic testing
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/02/01
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17058 109 24X
Fiche 50-213, 83/02/01, 8302080202
- 8302080208 Proposed revised Tech Spec 3 4 re min temp required at given pressure during operational leak rate testing & hydrostatic testing
* Connecticut Yankee Atomic Power Co 83/02/01 5pp 17058 112
24X Fiche 50-213, 83/02/01, 8302080202
- 8302100234 Forwards "Degraded Grid Protection for Class IE Power Sys," covering operator actions during degraded grid under non-LDOA conditions, per NRC 820709 ltr
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/02/03
CRUTCHFIELD, D Operating Reactors Branch 5 1p 17114 108 24X
Fiche 50-213, 83/02/03, 8302100234
- 8302100236 "Degraded Grid Protection for Class IE Power Sys "
GRACIE, R L Connecticut Yankee Atomic Power Co 82/12/21 5pp
17114 109 24X Fiche 50-213, 83/02/03, 8302100234
- 8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295
- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304
- 8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08,
8302090085
- 8302150644 Forwards B&W proprietary info affidavit & summary of 830131 telcon in response to 820126 request re peak linear heat generation rate Encl withheld (ref 10CFR2 790)
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/02/09
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17150 342 24X
Fiche 50-213, 83/02/09, 8302150644
- 8302240326 Application for amend to License DPR-61, deleting sections of ETS to eliminate duplication
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/02/15
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17274 050 24X
Fiche 50-213, 83/02/15, 8302240326
- 8302240329 Proposed changes to ETS, deleting sections to eliminate duplication
* Connecticut Yankee Atomic Power Co 83/02/28 19pp
17274 053 24X Fiche 50-213 83/02/15, 8302240326
- 8302240331 Comments on extension of SEP from Phase II to Phase III Integrated assessment concept should be applied to existing backlog of requirements currently being implemented at all operating reactors Handouts from 830204 meeting encl
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities COUNCIL, W O
Connecticut Yankee Atomic Power Co 83/02/15 ZERBE, J E Office of
Policy Evaluations 26pp 17274 018 24X Fiche 50-000, 83/02/15,
8302240331
- 8302280226 Informs that decision to reaffirm or withdraw request for hearing on environ qualification of safety-related electrical equipment will be determined within 30-day period following 830222 final rule effective date
COUNCIL, W O, SEARS, C F Northeast Utilities 83/02/22
EISENHUT, D O Division of Licensing 2pp 17304 353 24X
Fiche 50-000, 83/02/22, 8302280226
- G Inspection reports, IE Bulletins & correspondence
- 8302010565 Forwards Class III exemption fee omitted from util 820903 ltr re request for relief from ASME Code requirements for reactor coolant pump visual & volumetric insp of welds & internal surfaces
COUNCIL, W O, CAONETTA, J P Connecticut Yankee Atomic Power Co
83/01/19 DIGGS, R M License Fee Management Branch 2pp
16977 095 24X Fiche 50-213, 83/01/19, 8302010565
- 8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, USB & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design " Addl testing not warranted
TRAHMEL, C M Operating Reactors Branch 3 83/01/25 Operating
Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25,
8302160014
- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

DOCKETED ITEMS

27

830210651 Forwards SALP Repts for Sept 1981 - Aug 1982 Performance exhibits high level of mgt attention & involvement. Ample resources appear to be effectively used.
HAYNES, R C Region 1, Office of Director 83/01/27 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 16979 045 24X Fiche 50-000, 83/01/27, 830210651

--8302010662 SALP rept on 821013 One minor violation identified re inadequate document control of procedures. Policies adequately stated & understood. Records complete & well maintained.
* Region 1, Office of Director 82/10/13 27pp 16979 049 24X Fiche 50-000, 83/01/27, 8302010662

--8302010667 SALP rept on 821013 Troubleshooting & mad to computer sys ongoing Repts of computer failures decreased since last SALP.
* Region 1, Office of Director 82/10/13 28pp 16979 077 24X Fiche 50-000, 83/01/27, 8302010667

--8302010672 SALP rept on 821007 Geologic excavation & mapping by licensee accomplished. Const deficiencies thoroughly analyzed & promptly reported.
* Region 1, Office of Director 82/10/07 20pp 16979 107 24X Fiche 50-000, 83/01/27, 8302010672

--8302010677 SALP rept on 821020 Mgt attention & involvement w/nuclear safety consistently evident, licensee resources adequate & staff well trained.
* Region 1, Office of Director, 82/10/20 27pp 16979 131 24X Fiche 50-000, 83/01/27, 8302010677

--8302010679 Notifies of 821103 meeting to provide forum for candid discussions re util performance.
STAROSTECKI, R Division of Project & Resident Programs 82/10/27 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16979 160 24X Fiche 50-000, 83/01/27, 8302010679

--8302010682 Provides comments on 821103 meeting to ensure mutual understanding of detailed performance evaluation of utility.
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Connecticut Yankee Atomic Power Co 82/11/23 HAYNES, R C Region 1, Office of Director, 5pp 16979 162 24X Fiche 50-000, 83/01/27, 8302010682

8302100310 Forwards IE Insp Rept 50-213/82-24 on 821213-17 No noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 83/01/27 COUNCIL, W O Connecticut Yankee Atomic Power Co 2pp 17117 063 24X Fiche 50-213, 83/01/27, 8302100310

--8302100312 IE Insp Rept 50-213/82-24 on 821213-17 No noncompliance noted. Major areas inspected: licensee radiation protection program, previous insp findings, qualification & training, advance planning & preparation & audits.
MCBRIDE, M H, MOJTA, M J, SHANBAKY, M Division of Engineering & Technical Programs 83/01/24 5pp 17117 065 24X Fiche 50-213, 83/01/27, 8302100312

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361.

8302230410 Forwards IE Insp Rept 50-213/82-22 on 821206-830102 No noncompliance noted.
STAROSTECKI, R Division of Project & Resident Programs 83/02/07 COUNCIL, W O Connecticut Yankee Atomic Power Co 2pp 17243, 323 24X Fiche 50-213, 83/02/07, 8302230410

--8302230418 IE Insp Rept 50-213/82-22 on 821206-830102, No noncompliance noted. Major areas inspected: periodic & special repts, operating records, surveillance activities, physical security & radioactive waste sys controls.
REBELOWSKI, T, BRIGGS, L, ELBASSER, T G, Division of Project & Resident Programs 83/02/02, 15pp 17245 325 24X Fiche 50-213, 83/02/07, 8302230418.

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18, Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302070241 PND-I-83-006 on 830127, low specific activity radioactive matl arrived at Chem-Nuclear burial site in Barnwell, SC. Violations identified: crabs contained small quantity of water & drum contained 0.75 gallons of water.
* Region 1, Office of Director 83/02/01 1p 17031 296 24X Fiche 50-213, 83/02/01, 8302070241

8302130188 Forwards LER 83-002/03L-0
ORAVES, R H Connecticut Yankee Atomic Power Co 83/02/04 HAYNES, R C Region 1, Office of Director 1p 17155 226 24X Fiche 50-213, 83/02/04, 8302130188

--8302150193 LER 83-002/03L-0 on 830111, response to diesel generator EQ28 annunciator alarm revealed that diesel generator air compressor had thrown belt & sustained damage. Caused by broken connecting rods between crankshaft & piston.
OJINN, M D Connecticut Yankee Atomic Power Co 83/02/04 Region 1, Office of Director, 1p 17155 227 24X Fiche 50-213, 83/02/04, 8302150188

8302280459 Forwards LER 83-003/03L-0
ORAVES, R H Connecticut Yankee Atomic Power Co 83/02/15 HAYNES, R C Region 1, Office of Director 1p 17308 022 24X Fiche 50-213, 83/02/15, 8302280459

--8302280467 LER 83-003/03L-0 on 830122, while performing surveillance test of auxiliary feed pump flow capacity, IA pump flow measured 381 gpm. Cause under investigation.
TEST, R Z Connecticut Yankee Atomic Power Co 83/02/15 Region 1, Office of Director 1p 17308 023 24X Fiche 50-213, 83/02/15, 8302280459

V Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants for DLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche: 50-000, 83/01/31, 8301310203

8302280097 Responds to Generic Ltr 83-01 re requests for site visits for licensing/certification exams from Apr 1983 - Dec 1985. Estimated exam dates tentative.
COUNCIL, W O, SEARS, C F Connecticut Yankee Atomic Power Co COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/18 EISENHUT, D G Division of Licensing 5pp 17309 129 24X Fiche 50-000, 83/02/18, 8302280097

DDCKE1 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche, 50-000, 83/02/01, 8301210340

8302230135 Forwards IE Insp Rept 50-219/83-01 on 830101-31 No noncompliance noted.
STAROSTECKI, R Division of Project & Resident Programs 83/02/09 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 17243, 294 24X Fiche, 50-219, 83/02/09, 8302230135.

--8302230142 IE Insp Rept 50-219/83-01 on 830101-31 No noncompliance noted. Major areas inspected: plant operations, plant tours, logs & records, physical security, radiation protection & action on previously identified items.
COMOILL, C, THOMAS, J, TRIPP, L E, Division of Project & Resident Programs 83/02/08 11pp 17243 296 24X Fiche 50-219, 83/02/09, 8302230135

DOCKETED ITEMS

B302180077 Releases public version of revised emergency plan implementing procedures
FELTON J M Division of Rules and Records 83/02/14 Document
Management Branch 1p 66629 212 24X Fiche 50-219, 83/02/14, B302180077

--B302180082 Forwards public version of Rev 1 to Emergency Plan Implementing Procedures EPIP-26 re activation of technical support ctr & EPIP-27 re activation of operations support ctr Revised index encl
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/28 HAYNES, R C Region 1, Office of Director 3pp 17223 315 24X Fiche 50-219, 83/02/14, B302180077

--B302180087 Public version of Rev 1 to Emergency Plan Implementing Procedures EPIP-26 re activation of technical support ctr & EPIP-27 re activation of operations support ctr
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/28 HAYNES, R C Region 1, Office of Director 3pp 17223 315 24X Fiche 50-219, 83/02/14, B302180077

D Advisory Committee on Reactor Safeguards reports & correspondence

B302080459 Summary of ACRS Subcommittee on SEP B21026-27 meetings in Washington, DC re integrated plant safety assessment
* ACRS - Advisory Committee on Reactor Safeguards 82/12/09
ACRS - Advisory Committee on Reactor Safeguards 33pp 17108 077 24X Fiche 50-000, 82/12/09, B302080459

P Operating license stage documents & correspondence

B212030242 Forwards SER & "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 I & II B 4 for Oyster Creek Nuclear Generating Station"
CRUTCHFIELD, D Operating Reactors Branch 5 82/11/30 FIEDLER, P B General Public Utilities - GPU Service Corp 4pp 16306 270 24X Fiche 50-219, 82/11/30, B212030242

--B209030344 "Improvements in Training & Requalification Programs As Required by TMI Action Items I A 2 I & II B 4 for Oyster Creek Nuclear Generating Station" technical evaluation report
* Science Applications, Inc NRC-03-82-096 SAI-186-029-46 82/08/31 NRC - No Detailed Affiliation Given 15pp 16306 274 24X Fiche 50-219, 82/11/30, B212030242

B302020306 Forwards "Seismic Analysis of Reactor Vessel Internals," per B30121 telcon Analysis addresses questions raised by NRC during review of SEP Topic III-A re seismic considerations
MAOALY General Public Utilities - GPU Service Corp 83/01/24 CHALINA, O Systematic Evaluation Program Branch 1p 16993 301 24X Fiche 50-219, 83/01/24, B302020306

--B309020311 "Seismic Analysis of Reactor Vessel Internals" per PYRON, J W, SHABAZIAN, A, DATES, J H General Electric Co N8ED-55-0682 82/08/31 10pp 16993 302 24X Fiche 50-219, 83/01/24, B302020306

B302040262 Advises that radiological effluent Tech Specs & offsite dose calculation manual will be submitted by B30901, per util B20820 ltr
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/28 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17020 057 24X Fiche 50-219, 83/01/28, B302040262

B302280005 INTEGRATED PLANT SAFETY ASSESSMENT, SYSTEMATIC EVALUATION PROGRAM, OYSTER CREEK NUCLEAR GENERATING STATION Docket No. 50-219 (GPU Nuclear Corporation And Jersey Central Power & Light Company)
* Division of Licensing NUREG-0822 83/01/31 383pp Available at NRC \$12 00 17320 299, 24X Fiche 50-219, 83/01/31, B302280005

B302030089 Generic Ltr 83-08 to all Mark I containment licensees re need of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D G Division of Licensing 83/02/02 General Public Utilities - GPU Service Corp 5pp 17074 086 24X Fiche 50-000, 83/02/02, B302030089

B302040148 Forwards "Responses to NRC Questions for SEP Topic III-2 Wind & Tornado Loadings"
FIEDLER, P B General Public Utilities - GPU Service Corp 83/02/02 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17059 064 24X Fiche 50-219, 83/02/02, B302040148

B302050153 "Responses to NRC Questions for SEP Topic III-2 Wind & Tornado Loadings"
Burns & Roe Co 82/10/31 231pp 17059 066 24X Fiche 50-219, 83/02/02, B302050148

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, B302080295

B302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, B302080301

B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, B302080304

B302150621 Forwards remittance for Tech Spec Change Request 113, inadvertently omitted from change request package submittal
BAOQART, H General Public Utilities - GPU Service Corp 83/02/08 MILLER, W O License Fee Management Branch 1p 17151 307 24X Fiche 50-219, 83/02/08, B302150621

B302160231 Requests addl info within 30 days restating commitments re air filtration, single failure criteria & redundancy, per NUREG 0737, Item III D 3.4, "Control Room Habitability"
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 FIEDLER, P B Jersey Central Power & Light Co 2pp 17170 149 24X Fiche 50-219, 83/02/09, B302160231

B302160374 Requests documentation demonstrating long-term operability of purge & vent valves
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/10 FIEDLER, P B General Public Utilities - GPU Service Corp 8pp 17164 163 24X Fiche 50-219, 83/02/10, B302160374

B302180504 Application for amend to App B of License DPR-16, including Tech Spec Change Request 114 re environ monitoring
CLARK, P R General Public Utilities - GPU Service Corp 83/02/11 Office of Nuclear Reactor Regulation, Director 5pp 17214:154 24X Fiche 50-219, 83/02/11, B302180504

--B302180506 Proposed Tech Spec Change Request 114 re environ monitoring
* General Public Utilities - GPU Service Corp 83/02/11 86pp 17214 159 24X Fiche 50-219, 83/02/11, B302180504

B302220314 Advises that addl info re NUREG-0737, Items II F 1.4, "Containment Pressure Monitors," II F 1.5, "Containment Water Level Monitor" & II F 1.6, "Containment Hydrogen Monitor," per NRC B30106 request to be forwarded B30430
FIEDLER, P B General Public Utilities - GPU Service Corp 83/02/14 CRUTCHFIELD, D Operating Reactors Branch 5 1p 17230 152 24X Fiche 50-219, 83/02/14, B302220314

B302250234 Forwards description of remaining reviews performed to complete first phase of evaluation or control of heavy loads per Generic Ltr 81-07 Corrected pages to B10922 initial submittal encl
FIEDLER, P B General Public Utilities - GPU Service Corp 83/02/18 EISENHUT, D G Division of Licensing 45pp 17292 051 24X Fiche 50-219, 83/02/18, B302250234

B302240297 Forwards justification for schedule for completing NUREG-0737, Item II F 1, "Addl Accident Monitoring Instrumentation" Five mads expected to be completed prior to startup
KNUBEL, J General Public Utilities - GPU Service Corp 83/02/18 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17291 268 24X Fiche 50-219, 83/02/18, B302240297

B302280232 Documents util agreement to reissue App A Tech Spec for NRC convenience & clarification Request for Tech Specs reassurance will be exempt from license fees, per 10CFR170.22
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/22 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 17304 348 24X Fiche 50-219, 83/02/22, B302280232

G Inspection reports, IE Bulletins & correspondence

B212060398 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060398

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302040380 Discusses NRC concern re recent discoveries of intergranular stress corrosion cracking at several operating plants per Generic Ltr 81-04 Potential solutions include failure analysis/fracture mechanics & backlog weld repairs
FIEDLER, P B General Public Utilities - GPU Service Corp 83/02/04
MIRAGLIA, F J Assistant Director for Safety Assessment 2pp 17018 284 24X Fiche 50-219, 83/02/04, 8302040380

8302150266 Ack receipt of 830107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-22
STAROSTECKI, R Division of Project & Resident Programs 83/02/07
FIEDLER, P B General Public Utilities - GPU Service Corp 1p 17148 327 24X Fiche 50-219, 83/02/07, 8302150266

--8302180273 Responds to NRC 821207 ltr re violations noted in IE Insp Rept 50-219/82-22 Corrective actions all group shift supervisors informed of violation & how Tech Spec should be applied in future Tech Spec change will be submitted
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/07
STAROSTECKI, R Division of Project & Resident Programs 3pp 17148 328 24X Fiche 50-219, 83/02/07, 8302180266

8302230135 Forwards IE Insp Rept 50-219/83-01 on 830101-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/02/09
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 17243 294 24X Fiche 50-219, 83/02/09, 8302230135

--8302230142 IE Insp Rept 50-219/83-01 on 830101-31 No noncompliance noted Major areas inspected plant operations, plant tours, logs & records, physical security, radiation protection & action on previously identified items
COWGILL, C, THOMAS, J, TRIPP, L E Division of Project & Resident Programs 83/02/08 11pp 17243 296 24X Fiche 50-219, 83/02/09, 8302230135

8302170080 EN-82-036A on 821123, Commission notified of intent to issue notice of violation & proposed imposition of civil penalties in amount of \$40,000 based on inadequate valve operability surveillance testing
BARBER, O, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/02/15 1p 17181 353 24X Fiche 50-219, 83/02/15, 8302170080

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8302280213 Notifies that addl info re response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)," will be submitted by 830819
FIEDLER, P B General Public Utilities - GPU Service Corp 83/02/24
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 17305 260 24X Fiche 50-219, 83/02/24, 8302280213

8 Reportable occurrences, LERs & related correspondence

8302010145 Forwards LER 82-060/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/11
HAYNES, R C Region 1, Office of Director 3pp 16974 070 24X Fiche 50-219, 83/01/11, 8302010145

--8302010154 LER 82-060/03L-0 on 821210, reactor mode switch repositioned from shutdown to refuel while intermediate range monitor channels 16 & 17 out of svc Caused by personnel error Strict compliance w/Tech Specs emphasized
MURDOCK, R J General Public Utilities - GPU Service Corp 83/01/11 Region 1, Office of Director 1p 16974 073 24X Fiche 50-219, 83/01/11, 8302010145

8302070539 Forwards LER 82-064/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/28
HAYNES, R C Region 1, Office of Director 4pp 17034 102 24X Fiche 50-219, 83/01/28, 8302070539

--8302070546 LER 82-064/03L-0 on 821230, containment spray sys 1 declared inoperable due to high baffle plate differential pressure readings on 1-2 HX Caused by HX fouling HX inspected & cleaned & chlorination sys for emergency svc water repaired.
FITZGERALD, M J General Public Utilities - GPU Service Corp 83/01/28 Region 1, Office of Director 1p 17034 106 24X Fiche 50-219, 83/01/28, 8302070539

8302090344 Forwards LER 82-063/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/28
HAYNES, R C Region 1, Office of Director 2pp 17070 351 24X Fiche 50-219, 83/01/28, 8302090344

--8302090354 LER 82-063/03L-0 on 821227, operability of control rod drive pump A not demonstrated during 1-month period Caused by breakdown in administrative controls for surveillance test program Surveillance completed
WASHKO, D General Public Utilities - GPU Service Corp 83/01/28 Region 1, Office of Director 1p 17070 353 24X Fiche 50-219, 83/01/28, 8302090344

8302250216 Forwards LER 83-003/03L-0 Detailed event analysis encl
FIEDLER, P B General Public Utilities - GPU Service Corp 83/02/15
HAYNES, R C Region 1, Office of Director 3pp 17293 076 24X Fiche 50-219, 83/02/15, 8302250216

--8302250221 LER 83-003/03L-0 on 830118, during maint of control rod drive pump A, pump vent line broke off Core spray pump NZDIA wetdown & B pump inadvertently tripped Cause not stated
Pump removed from svc & motor tested
BINZ, R D General Public Utilities - GPU Service Corp 83/02/15 Region 1, Office of Director 1p 17293 079 24X Fiche 50-219, 83/02/15, 8302250216

V Operator Examinations

8302080027 Submits projected requests for site visits to conduct operator licensing exams through 831231, per Generic Ltr 83 01
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/28
EISENHUT, D G Division of Licensing 1p 17058 192 24X Fiche 50-219, 83/01/28, 8302080027

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKE1 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8302030209 Forwards IE Insp Rept 50-220/82-23 on 821205-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/21
RHODE, O K, Niagara Mohawk Power Corp 2pp 17001 327 24X Fiche 50-220, 83/01/21, 8302030209

--8302030215 IE Insp Rept 50-220/82-23 on 821205-31 No noncompliance noted Major areas inspected plant tours, observation of physical security, plant maint, emergency preparedness & licensee action on previous insp findings
HUDSON, S D, KIBTER, H B Division of Project & Resident Programs 83/01/12 9pp 17001 329 24X Fiche 50-220, 83/01/21, 8302030209

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl.
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

DOCKETED ITEMS

8302070378 Forwards results of App R safe shutdown analysis re 125-volt dc sys breaker coordination No addl mods required
Revs to administrative procedures necessary
MANOAN, C V Niagara Mohawk Power Corp 83/02/01 VASSALLO, D B
Operating Reactors Branch 2 4pp 17029 091 24X
Fiche 50-220, 83/02/01, 8302070378

J Insurance & indemnity information

8302070187 Forwards Endorsement 67 to MAELU Policy MF-46
RUSHMORE, J H Niagara Mohawk Power Corp 83/01/31 SALTZMAN, J
Assistant Director for State & License Relations 2pp 17031 303
24X Fiche 50-220, 83/01/31, 8302070187

8302070190 Forwards Endorsement 80 to NELIA Policy NF-161
RUSHMORE, J H Niagara Mohawk Power Corp 83/01/31 SALTZMAN, J
Assistant Director for State & License Relations 2pp 17031:305
24X Fiche 50-220, 83/01/31, 8302070190

P Operating license stage documents & correspondence

8302080039 FOIA request for nonproprietary Vols 1 & 2 of, "Review of Licensee Resolution of Outstanding Issues from NRC Equipment Environ Qualification, SER (F-11 & B-60)," technical evaluation rept
WETTERHAHN, M J Conner & Wetterhahn 82/11/05 Office of Administration 1p 17072 057 24X Fiche 50-220, 82/11/05, 8302080039

8302080063 Responds to FOIA request for nonproprietary Vols 1 & 2 of, "Review of Licensee Resolution of Outstanding Issues from NRC Equipment Environ Qualification, SER (F-11 & B-60)," technical evaluation rept
FELTON, J H Division of Rules and Records 82/12/30
WEYERHAEHN, M J Conner & Wetterhahn 1p 17072 068 24X
Fiche 50-220, 82/12/30, 8302080063

--8209020218 Forwards nonproprietary Vols 1 & 2 of, "Review of Licensee Resolution of Outstanding Issues from NRC Equipment Environ Qualification, SER (F-11 & B-60)," technical evaluation rept
CRANE, C J Franklin Institute/Franklin Research Center
NRC-03-79-118 82/08/26 BAJWA, S NRC - No Detailed Affiliation Given 2pp 17072 077 24X Fiche 50-220, 82/12/30, 8302080063

--8209020228 Nonproprietary Vols 1 & 2 of, "Review of Licensee Resolution of Outstanding Issues from NRC Equipment Environ Qualification, SER (F-11 & B-60)," technical evaluation rept
CRANE, C J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-464 82/08/26 LE, N B NRC - No Detailed Affiliation Given 729pp 17073 001 24X
Fiche 50-220, 82/12/30, 8302080063

8302040001 Forwards SER of util submittals re NUREG-0737, Items I, A 2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4.1, "Training for Mitigating Core Damage," technical evaluation rept
VASSALLO, D B Operating Reactors Branch 2 83/01/26 RHODE, G
Niagara Mohawk Power Corp 2pp 17043 315 24X
Fiche 50-220, 83/01/26, 8302040001

--8302040003 Safety evaluation of util submittals re NUREG-0737, Items I A 2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4.1, "Training for Mitigating Core Damage," Requirements met
* Office of Nuclear Reactor Regulation, Director 83/01/26 3pp 17043 317 24X Fiche 50-220, 83/01/26, 8302040001

--8302040006 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2.1 & II B 4 for Nine Mile Point Nuclear Station, Unit 1," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-029-36 82/08/18 NRC - No Detailed Affiliation Given 13pp 17043 320 24X Fiche 50-220, 83/01/26, 8302040001

8302010306 Forwards addl info re electric distribution sys, supplementing 820727 response to NRC 810202 request
MANOAN, C V Niagara Mohawk Power Corp 83/01/28 VASSALLO, D B
Operating Reactors Branch 2 12pp 16973 102 24X
Fiche 50-220, 83/01/28, 8302010306

8302140080 Advises that Tech Specs re Class IE protection packages for reactor protection motor generator sets will be submitted by 830601 rather than 830201 as committed to in 821201 ltr Delay due to unavailability of design info
MANOAN, C V Niagara Mohawk Power Corp 83/02/01 VASSALLO, D B
Operating Reactors Branch 2 1p 17141 199 24X
Fiche 50-220, 83/02/01, 8302140080

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests
commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D G Division of Licensing 83/02/02 General Public Utilities - GPU Service Corp 5pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302160389 Application for amend to License DPR-63 deleting ETS Sections 2.1.2, 2.2, 3.3, 1.3, 1.2, 4.0 & 6.0
MANOAN, C V Niagara Mohawk Power Corp 83/02/10 5pp 17164 211 24X Fiche 50-220, 83/02/10, 8302160389

--8302160392 Proposed ETS deleting Sections 2.1.2, 2.2, 3.3, 1.3, 1.2, 4.0 & 6.0
* Niagara Mohawk Power Corp 83/02/10 41pp 17164 216 24X
Fiche 50-220, 83/02/10, 8302160389

8302230216 Provides justification for operation w/o Tech Spec requirements of NUREG-0313, Rev 1, IV B 1.6(2) re coolant leakage Current capabilities afford operators opportunity to assess unidentified leakage situation
MANOAN, C V Niagara Mohawk Power Corp 83/02/17 VASSALLO, D B
Operating Reactors Branch 2 3pp 17245 118 24X
Fiche 50-220, 83/02/17, 8302230216

Q Inspection reports, IE Bulletins & correspondence

8302030209 Forwards IE Insp Rept 50-220/82-23 on 821205-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/21 RHODE, G K Niagara Mohawk Power Corp 2pp 17001 327 24X
Fiche 50-220, 83/01/21, 8302030209

--8302030215 IE Insp Rept 50-220/82-23 on 821205-31 No noncompliance noted Major areas inspected plant tours, observation of physical security, plant maint, emergency preparedness & licensee action on previous insp findings
HUSON, S D, KISTER, H B Division of Project & Resident Programs, 83/01/12 9pp 17001 329 24X Fiche 50-220, 83/01/21, 8302030209

8302010366 Ack receipt of 821222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-09
MARTIN, T Y Division of Engineering & Technical Programs 83/01/25 RHODE, G K, SEIBERT, C R Niagara Mohawk Power Corp 1p 16973 306 24X Fiche 50-220, 83/01/25, 8302010366

--8302010370 Responds to NRC 820723 ltr re violations noted in IE Insp Rept 50-220/82-09 Corrective actions qualification program for hiring prospective employees changed
LEHPOES, T E Niagara Mohawk Power Corp 82/12/22 HAYNEG, R C
Region I, Office of Director 1p 16973 307 24X
Fiche 50-220, 83/01/25, 8302010366

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 099 24X Fiche 50-000, 83/01/28, 8212060361

8302230677 Ack receipt of 830207 ltr informing NRC of steps taken to
correct violations noted in Insp Rept 50-220/82-11
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/15
RHODE, O. K. Niagara Mohawk Power Corp 1p 17259 284, 24X
Fiche 50-220, 83/02/15, 8302230677

--8302230679 Responds to NRC 830106 ltr re violations noted in IE Insp
Rept 50-220/82-11 Corrective actions all final radiographic
packages reviewed to verify proper identification
LEMPQES, T. E. Niagara Mohawk Power Corp 83/02/07 MARTIN, T. T.
Division of Engineering & Technical Programs 2pp 17259 285
24X Fiche 50-220, 83/02/15, 8302230677

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148, 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302140082 Forwards monthly operating rept for Jan 1983
LEMPQES, T. E. Niagara Mohawk Power Corp 83/02/07 Director's
Office, Office of Inspection and Enforcement 1p 17141, 215 24X
Fiche 50-220, 83/02/07, 8302140082

--8302140084 Monthly operating rept for Jan 1983
ROMAN, T. N. Niagara Mohawk Power Corp 83/02/01 6pp 17141 216
24X Fiche 50-220, 83/02/07, 8302140082

V. Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants
for DLs, NBS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses. Svc list encl
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 11pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302140074 Responds to Generic Ltr 83-01 re planning for operator
licensing
LEMPQES, T. E. Niagara Mohawk Power Corp 83/01/31 EISENHUT, D. O.
Division of Licensing 2pp 17142 115, 24X Fiche 50-220, 83/01/31,
8302140074

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8302150690 Forwards IE Safeguards Insp Rept 50-228/83-01 on 830207
No noncompliance noted.
NORDERHAUO, L. R. Division of Radiological Safety & Safeguards
Program 83/02/10 NEWACHECK, R. L. Aerotest Operations, 2pp
17153 311 24X Fiche 50-228, 83/02/10, 8302150690.

--8302150701 IE Safeguards Insp Rept 50-228/83-01 on 830207 No
noncompliance noted. Major areas inspected security plan,
protection of BNH, access control, alarm sys, keys & locks &
communications. Details withheld (ref 10CFR2.790).
SCHWARTZ, C. A. , SCHUSTER, M. D. Region 5, Office of Director
83/02/10 1p 17153 313, 24X Fiche 50-228, 83/02/10, 8302150690

G Inspection reports, IE Bulletins & correspondence

8302150690 Forwards IE Safeguards Insp Rept 50-228/83-01 on 830207
No noncompliance noted
NORDERHAUO, L. R. Division of Radiological Safety & Safeguards
Program 83/02/10, NEWACHECK, R. L. Aerotest Operations, 2pp
17153 311 24X Fiche 50-228, 83/02/10, 8302150690

--8302150701 IE Safeguards Insp Rept 50-228/83-01 on 830207. No
noncompliance noted. Major areas inspected security plan,
protection of BNH, access control, alarm sys, keys & locks &
communications. Details withheld (ref 10CFR2.790).
SCHWARTZ, C. A. , SCHUSTER, M. D. Region 5, Office of Director.
83/02/10 1p 17153 313 24X Fiche 50-228, 83/02/10, 8302150690.

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan
implementing procedures.
FELTON, J. M. Division of Rules and Records 83/01/27 Document
Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27,
8302040033

--8302040037 Forwards public version of revised Emergency Plan
Implementing Procedures ED-29 re meteorological maint
programs & ED-25 re computer codes for access to ODCB
programs
PAJOWSKI, J. E. Commonwealth Edison Co. 83/01/07 DENTON, H. R. NRC
- No Detailed Affiliation Given, 1p 17043 231, 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing
Procedures ED-29 re meteorological maint programs & ED-25
re computer codes for access to ODCB programs. Revised
index encl
LITERSKI, L. A. , PAJOWSKI, J. E. Commonwealth Edison Co. 83/01/06,
11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8302040458 Releases public version of revised Emergency Plan
Implementing Procedure
FELTON, J. M. Division of Rules and Records 83/01/31, Document
Management Branch 1p 16997 288 24X Fiche 50-010, 83/01/31,
8302040458

--8302040470 Forwards public version of Rev 1 to Emergency Plan
Implementing Procedure EPIP 100-C11, "Enviroms Director
(Checklist of Initial Generating Station Emergency Plan
Responsibilities)" Receipt form encl
SCOTT, D. J. Commonwealth Edison Co 83/01/07 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 3pp 16997 289 24X
Fiche 50-010, 83/01/31, 8302040458

--8302040479 Public version of Rev 1 to Emergency Plan Implementing
Procedure EPIP 100-C11, "Enviroms Director (Checklist of
Initial Generating Station Emergency Plan
Responsibilities)"
* Commonwealth Edison Co 83/01/03 6pp 16997 292 24X
Fiche 50-010, 83/01/31, 8302040458

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability." Svc list encl
EISENHUT, D. O. Division of Licensing, 83/02/01, Consolidated
Edison Co. of New York, Inc 11pp 17221 226, 24X
Fiche 50-000, 83/02/01, 8301210340.

8302080191 Forwards safety evaluation & exemption from requirements of
Section III, Q 3 of App R to 10CFR50 re fire protection for
safe shutdown capability, per util 820701 request
CRUTCHFIELD, D. Operating Reactors Branch 5, 83/02/02 DELGORD, E. L.
Commonwealth Edison Co 3pp 17038 141, 24X Fiche 50-237,
83/02/02, 8302080191

--8302080194 Exemption from requirements of Section III, Q 3 of App R to
10CFR50 re installation of fire detection sys & fixed fire
suppression sys in area, room or zone for which alternative
safe shutdown capability provided
EISENHUT, D. O. Division of Licensing, 83/02/02, Commonwealth
Edison Co. 4pp 17038 144 24X Fiche 50-237, 83/02/02, 8302080191.

--8302080197 Safety evaluation supporting exemption from requirements of
Section III, Q 3 of App R to 10CFR50 re fire protection of
safe shutdown capability.
* Office of Nuclear Reactor Regulation, Director, 83/02/02, 7pp.
17038 148 24X Fiche 50-237, 83/02/02, 8302080191.

8302080316 Responds to 821209 ltr re incident response plan & 820917
training session No new requirements requested for emergency
response facility Minor changes suggested as result of
meeting exercise NUREG-0696 & SECY-82-1118 guidelines valid.
KEPPLER, J. Q. Region 3, Office of Director 83/02/04 REED, C.
Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04,
8302080316

DOCKETED ITEMS

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
 REED, C Commonwealth Edison Co 82/12/09 KEPLER, J Q Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302250358 Forwards IE Insp Rpts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted
 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/08 REED, C Commonwealth Edison Co 2pp 17291 154 24X Fiche 50-010, 83/02/08, 8302250358

--8302250364 IE Insp Rpts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted Major areas inspected emergency preparedness program, licensee actions on previously identified items & emergency plan
 PHILLIPS, M P, GLOERSEN, W B, AXELSON, W L Division of Emergency Preparedness & Operational Support 83/02/03 16pp 17291 156 24X Fiche 50-010, 83/02/08, 8302250358

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
 MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
 NELLIS, C A, FLESSNER, R A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302180494 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17221 323 24X Fiche 50-010, 83/02/15, 8302180494

--8302180498 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-7, "Personnel Decontamination (Medical - Decontamination Area) (Primary Responsibility - Rad/Chem Director)"
 SCOTT, D J Commonwealth Edison Co 83/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17221 324 24X Fiche 50-010, 83/02/15, 8302180494

--8302180509 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-7, "Personnel Decontamination (Medical - Decontamination Area) (Primary Responsibility - Rad/Chem Director)" Revised index encl
 Commonwealth Edison Co 83/01/12 12pp 17221 327 24X Fiche 50-010, 83/02/15, 8302180494

12250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities Lists of locations encl
 SWARTZ, E D Commonwealth Edison Co 83/01/28 KEPLER, J Q Region 3, Office of Director 4pp 17291 074 24X Fiche 50-000, 83/02/18, 8302250349

D Advisory Committee on Reactor Safeguards reports & correspondence

302080480 Comments on ACRS Subcommittee on SEP 821130 meeting re licensee disagreement w/NRC position on SEP Topic VI-10 A, "Testing of Reactor Trip Sys & ESF, Including Response Time Testing"
 LIPINSKI, W C ACRS - Advisory Committee on Reactor Safeguards
 LIPINSKI, W C Argonne National Laboratory 82/12/02 SIESS, C P ACRS - Advisory Committee on Reactor Safeguards 3pp 17071:269 24X Fiche 50-000, 82/12/02, 8302080480

12080459 Summary of ACRS Subcommittee on SEP 821026-27 meetings in Washington, DC re integrated plant safety assessment
 ACRS - Advisory Committee on Reactor Safeguards 82/12/09
 *S - Advisory Committee on Reactor Safeguards 33pp 17108 077 24X Fiche 50-000, 82/12/09, 8302080459

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
 EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
 HANNON, J N, THOMA, J NRC - No Detailed Affiliation Given 82/01/27 VARGA, S NRC - No Detailed Affiliation Given 10pp 17196 225 24X Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation rpts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
 EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X Fiche 50-000, 83/01/18, 8302170019

8302010429 Forwards "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plants Drywell Temp Analysis" Analysis fulfills NRC request for info re equipment qualification temp profiles inside containment
 RAUSCH, T J Commonwealth Edison Co 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16974 180 24X Fiche 50-000, 83/01/25, 8302010429

--8302010434 "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plant Drywell Temp Analysis"
 HOANG, H X, ROGERS, A E General Electric Co NSEO-82-0682 82/11/30 13pp 16974 182 24X Fiche 50-000, 83/01/25, 8302010429

8302070215 Application for amend to License DPR-19 changing safety/relief actuating setpoint of Target Rock & Electromatic relief valves Class III license amend fee encl
 RAUSCH, T J Commonwealth Edison Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17031 316 24X Fiche 50-237, 83/02/01, 8302070215

--8302070220 Proposed Tech Specs changing safety/relief actuating setpoint
 Commonwealth Edison Co 83/02/01 3pp 17031 319 24X Fiche 50-237, 83/02/01, 8302070215

8302070274 Suppls 821019 ltr re justification for continued operation for SCAM resistance temp detectors in reactor water cleanup rooms, per 821229 & 830118 SERs for environ qualification of electrical equipment program
 RAUSCH, T J Commonwealth Edison Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17031 116 24X Fiche 50-000, 83/02/01, 8302070274

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
 EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - CPU Service Corp 3pp 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302170345 Responds to NRC concerns re safety-related sys not protected against effects of tornado-generated missiles per SEP Topic III-4 A Probability of tornado missile occurrence so small that shielding not warranted
 RAUSCH, T J Commonwealth Edison Co 83/02/03 GILBERT, R Operating Reactors Branch 5 5pp 17184 110 24X Fiche 50-237, 83/02/03, 8302170345

--8302170347 "Probabilistic Analysis of Tornado Missile Hazard for Dresden Nuclear Power Station"
 Commonwealth Edison Co 83/01/31 33pp 17184 115 24X Fiche 50-237, 83/02/03, 8302170345

8302080244 Notification of 830208 meeting w/util in Bethesda, MD to discuss licensee proposed approach re indication of crack in one 28-inch recirculation line
 DUDLEY, R F Operating Reactors Branch 5 83/02/04 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17057 163 24X Fiche 50-237, 83/02/04, 8302080244

8302100224 Forwards description, basis & justification for each setpoint chosen for reactor protection sys power monitoring sys, per 820723 ltr Proposed Tech Specs will be submitted by 830415
 RAUSCH, T J Commonwealth Edison Co 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 17115 116 24X Fiche 50-000, 83/02/04, 8302100224

8302100214 Application for amend to License DPR-19, changing Tech Specs to allow main steam radiation monitor trip level setpoints to be increased above 20% during operation
 RAUSCH, T J Commonwealth Edison Co 83/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17115 106 24X
 Fiche 50-237, 83/02/07, 8302100214

--8302100217 Proposed Tech Spec changes allowing main steamline radiation monitor setpoint increase above 20% during operation
 * Commonwealth Edison Co 83/02/07 7pp 17115 109 24X
 Fiche 50-237, 83/02/07, 8302100214

8302080299 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080299

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDD-24934, June 1982 Guidelines acceptable Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
 Fiche 50-000, 83/02/08, 8302080304

8302180296 Responds to 830119 ltr re BEP Topic III-2 concerning windload capacity of ventilation stack Mods not warranted because actual concrete strength does not govern ventilation stack loads & probability of 253 mph tornado low
 RAUSCH, T J Commonwealth Edison Co 83/02/09 GILBERT, R Operating Reactors Branch 5 2pp 17211 245 24X
 Fiche 50-237, 83/02/09, 8302180296

8302220330 Discusses schedule for util response re environ qualification of electrical equipment proprietary info Manufacturers contacted on timely response Status of final reporting will be provided by 830515
 RYBAK, B Commonwealth Edison Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17230 091 24X
 Fiche 50-000, 83/02/14, 8302220330

8302230125 Ack receipt of 830111 ltr re qualifications of radiochemistry supervisory staff per ANSI Std N18 1-1971 T Gilman qualified as lead chemist S McDonald will attend class to qualify as lead health physicist
 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/16 SCOTT, D J Commonwealth Edison Co 2pp 17257 007 24X Fiche 50-010, 83/02/16, 8302230125

--8302230130 Responds to NRC request to document basis for qualifications of radiochemistry staff per ANSI Std N18 1-1971 Lead chemist need not meet 2-yr experience requirement
 SCOTT, D J Commonwealth Edison Co 83/01/11 OREGOR, R L Region 3, Office of Director, 5pp 17257 009 24X Fiche 50-010, 83/02/16, 8302230125

8302250189 Application for amends to Licenses DPR-19 & DPR-25, incorporating multiple changes to Tech Specs re administrative controls
 RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17293 007 24X
 Fiche 50-237, 83/02/17, 8302250189

--8302250192 Proposed Tech Spec changes re administrative controls
 * Commonwealth Edison Co 83/02/17 24pp 17293 010 24X
 Fiche 50-237, 83/02/17, 8302250189

8302250212 Application for amend to Licenses DPR-29 & DPR-30, revising Tech Specs to incorporate changes to corporate & station organizations
 RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 17293 082 24X
 Fiche 50-237, 83/02/17, 8302250212

--8302250218 Proposed Tech Specs re administrative controls
 * Commonwealth Edison Co 83/02/17 17pp 17293 085 24X
 Fiche 50-237, 83/02/17, 8302250212

8302280192 Advises that review of 830121 final rule on environ qualification of safety-related electrical equipment incomplete Determination whether to reaffirm or withdraw hearing request will be provided by 830324
 STEPTOE, P P Isham, Lincoln & Beale 83/02/23 EISENHUT, D O Division of Licensing 1p 17306 076 24X Fiche 50-000, 83/02/23, 8302280192

8302280087 Notification of 830302 meeting w/util in Bethesda, MD to describe proposed approach on second group of crack indications
 GILBERT, R A Operating Reactors Branch 5 83/02/24 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17307 182 24X
 Fiche 50-237, 83/02/24, 8302280087

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
 Forwards App A documents Document 31 available in PDR
 FELTON, J. M. Division of Rules and Records 82/12/30 HIATT, B L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
 Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
 SUCHARSKI, L. Region 3, Office of Director 82/07/08
 KEPPLER, J O. Region 3, Office of Director 13pp 17045 281 24X
 Fiche 50-000, 82/12/30, 8302040332

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design " Addl testing not warranted
 TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55, IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
 SPESSARD, R L. Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302040294 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-16, 50-237/82-23 & 50-249/82-23
 NORELIUS, C. E. Division of Project & Resident Programs 83/02/01 REED, C. Commonwealth Edison Co 1p 17017 347 24X
 Fiche 50-010, 83/02/01, 8302040294

--8302040302 Responds to NRC 821222 ltr re violations noted in IE Insp Repts 50-010/82-16, 50-237/82-23 & 50-249/82-23 Corrective actions new computer installation & removal of computer console at station operator desk scheduled for Spring 1983
 DELGEORGE, L O Commonwealth Edison Co 83/01/21 KEPPLER, J O Region 3, Office of Director, 2pp 17017 348 24X
 Fiche 50-010, 83/02/01, 8302040294

8302080277 Submits updated installation status rept of safe shutdown path supports, per IE Bulletin 79-14 All remaining hangers will be installed by 831231, w/exception of Quad Cities safety relief valve line
 RAUSCH, T J Commonwealth Edison Co 83/02/01 KEPPLER, J O Region 3, Office of Director 4pp 17056 337 24X Fiche 50-000, 83/02/01, 8302080277

DOCKETED ITEMS

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (s) of IE Bulletin 83-03, "Flow Blockage of Cooling Water to Safety-Related Systems Components by Asiatic Clams & Mussels".
SWARTZ, E. D. Commonwealth Edison Co 83/02/08 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000, 83/02/08, 8302150528

8302250358 Forwards IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/02/08 REED, C. Commonwealth Edison Co 2pp 17291 154 24X Fiche 50-010, 83/02/08, 8302250358

--8302250364 IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted. Major areas inspected emergency preparedness program, licensee actions on previously identified items & emergency plan.
PHILLIPS, H. P., PLOSKI, T. J., SNELL, W. Q. Division of Emergency Preparedness & Operational Support 83/02/03 16pp 17291 156 24X Fiche 50-010, 83/02/08, 8302250358

8302150587 EN-83-008 on 830216, notices of violation & proposed imposition of civil penalties in amount of \$120,000 will be issued. Action based on lack of controls over distribution of safety list & failure to maintain containment integrity.
BARBER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/02/11 2pp 17156 117 24X Fiche 50-000, 83/02/11, 8302150587.

8302280426 Forwards IE Insp Repts 50-237/82-30 & 50-249/82-31 on 821206-07, 14-17, 830103-05 & 07 & notice of violation.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/02/14 REED, C. Commonwealth Edison Co 2pp 17307 329. 24X Fiche 50-237, 83/02/14, 8302280426

--8302280430 Notice of violation from insp on 821206-07, 14-17, 830103-05 & 07.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/02/14 1p 17307-331 24X Fiche 50-237, 83/02/14, 8302280426

--8302280438 IE Insp Repts 50-237/82-30 & 50-249/82-31 on 821206-07, 14-17, 830103-05 & 07 Noncompliance noted failure to prevent transfer of contaminated mail from controlled to uncontrolled area.
PAUL, R. A., GRANT, W. B., GREGER, L. R. Region 3, Office of Director. 83/02/14 14pp 17307 332 24X Fiche 50-237, 83/02/14, 8302280426

8302180445 Discusses IE insp on 821004-07, 12-1112, 1206 & 08 & forwards notice of violation & proposed imposition of civil penalty.
KEPPLER, J. Q. Region 3, Office of Director 83/02/16 O'CONNOR, J. J. Commonwealth Edison Co 3pp 17215 135 24X Fiche 50-237, 83/02/16, 8302180445

--8302180455 Notice of violation & proposed imposition of civil penalty in amount of \$20,000 Noncompliance noted primary containment integrity not maintained for 33 days & authorities not notified within specified time.
KEPPLER, J. Q. Region 3, Office of Director. 83/02/16 3pp 17215 138 24X Fiche 50-237, 83/02/16, 8302180445

8302180491 Discusses IE insp on 820816-1103 & forwards notice of violation & proposed imposition of civil penalty.
KEPPLER, J. Q. Region 3, Office of Director 83/02/16 O'CONNOR, J. J. Commonwealth Edison Co 4pp. 17214 127 24X Fiche 50-000, 83/02/16, 8302180491

--8302180496 Notice of violation & proposed imposition of civil penalty in amount of \$100,000. Noncompliance noted weakness in QA program, including lack of controls over distribution of safety classification list.
KEPPLER, J. Q. Region 3, Office of Director 83/02/16 3pp 17214 131 24X Fiche 50-000, 83/02/16, 8302180491

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units".
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191. 24X Fiche 50-000, 83/02/18, 8212060363

112060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302".
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc. 111pp. 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

2060366 IE Info Notice 83-06, "Nonidentical Replacement Parts".
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302190600 Forwards monthly operating repts for Jan 1983.
SCOTT, D. J. Commonwealth Edison Co 83/02/01 Director's Office, Office of Inspection and Enforcement 1p 17155 347 24X
Fiche 50-237, 83/02/01, 8302190600

--8302190606 Monthly operating repts for Jan 1983.
SCHRÖDER, B. A. Commonwealth Edison Co 83/02/01 13pp 17155 348 24X Fiche 50-237, 83/02/01, 8302190600

B Reportable occurrences, LERs & related correspondence

8302010147 Forwards LER 83-001/03L-0.
SCOTT, D. J. Commonwealth Edison Co 83/01/18 KEPPLER, J. Q. Region 3, Office of Director 1p 16974 155 24X Fiche 50-237, 83/01/18, 8302010147

--8302010152 LER 83-001/03L-0 on 830101, cracked weld discovered at feedwater heater 2D2 emergency spill to normal drain line connector. Caused by excessive movement of drain line. Weld will be repaired during upcoming refueling outage.
CHRISTEL, B. Commonwealth Edison Co 83/01/18 Region 3, Office of Director 1p 16974 156 24X Fiche 50-237, 83/01/18, 8302010147

8302010269 Forwards LER 82-058/03L-0.
SCOTT, D. J. Commonwealth Edison Co 83/01/19 KEPPLER, J. Q. Region 3, Office of Director 1p 16973 139 24X Fiche 50-237, 83/01/19, 8302010269

--8302010276 LER 82-058/03L-0 on 821226, small leak found on reactor water cleanup line 2-12018 8-inch-A between 2-1201-1350 & 988 valves. Cause unknown. Pipe will be examined when section replaced during 1983 refueling outage.
RHEE, S. Commonwealth Edison Co 83/01/19 Region 3, Office of Director 1p 16973 140 24X Fiche 50-237, 83/01/19, 8302010269

8302010376 Forwards LER 83-003/03L-0.
SCOTT, D. J. Commonwealth Edison Co 83/01/19 KEPPLER, J. Q. Region 3, Office of Director 1p 16973 293 24X Fiche 50-237, 83/01/19, 8302010376

--8302010381 LER 83-003/03L-0 on 830108, during surveillances DIS 1400-51 DCS 6600-1, diesel generator low water pressure alarm received. Caused by bad low cooling water pressure switch. Switch replaced w/Class 9012 Type OAW-S.
SCHRÖDER, B. A. Commonwealth Edison Co 83/01/19 Region 3, Office of Director 1p 16973 294 24X Fiche 50-237, 83/01/19, 8302010376

8302040058 Forwards LER 82-059/03L-0.
SCOTT, D. J. Commonwealth Edison Co 83/01/25 KEPPLER, J. Q. Region 3, Office of Director 1p 17020 145 24X Fiche 50-237, 83/01/25, 8302040058

--8302040070 LER 82-059/03L-0 on 821231, valve A02-1601-55 closed w/o operator action. Caused by deteriorated diaphragm in solenoid on air operator. Solenoid replaced & valve operability verified.
WEE, D. T. Commonwealth Edison Co 83/01/25 Region 3, Office of Director 1p 17020 146 24X Fiche 50-237, 83/01/25, 8302040058

8302040387 Forwards LER 83-008/01T-0.
SCOTT, D. J. Commonwealth Edison Co 83/01/28 KEPPLER, J. Q. Region 3, Office of Director 1p 17017 337 24X Fiche 50-237, 83/01/28, 8302040387

--8302040391 LER 83-008/01T-0 on 830115, during inservice insp, ultrasonic exam of recirculation suction line B safe-end to elbow weld detected rejectable indication at weld root. Cause unknown. Investigation underway.
HYLKAR, R. Commonwealth Edison Co 83/01/28 Region 3, Office of Director 2pp 17017 338 24X Fiche 50-237, 83/01/28, 8302040387

8302160154 Forwards updated LER 82-034/03X-1.
SCOTT, D. J. Commonwealth Edison Co 83/02/01 KEPPLER, J. Q. Region 3, Office of Director 1p 17162 218 24X Fiche 50-237, 83/02/01, 8302160154

--8302160159 Updated LER 82-034/03X-1 on 820726, during power operation, pinhole leak discovered in HPCI drain pot drainline to main condenser. Caused by erosion. Segment of pipe replaced w/Schedule 80 carbon steel pipe.
ANANDAPPA, A. Commonwealth Edison Co 83/02/01 Region 3, Office of Director 2pp 17162 219 24X Fiche 50-237, 83/02/01, 8302160154

DOCKETED ITEMS

35

8302160190 Forwards LER 83-005/03L-0
SCOTT, D J Commonwealth Edison Co 83/02/04 KEPPLER, J O Region
3, Office of Director 1p 17162 212 24X Fiche 50-237, 83/02/04,
8302160190

--8302160198 LER 83-005/03L-0 on 830112, during refueling outage, while
local leak rate testing, outboard MSIV 2-203-2B leaking in
excess of Tech Specs Caused by valve packing leakage Packing
tightened
RHEE, S Commonwealth Edison Co 83/02/04 Region 3, Office of
Director 1p 17162 213 24X Fiche 50-237, 83/02/04, 8302160190

8302160222 Forwards LER 83-004/03L-0
SCOTT, D J Commonwealth Edison Co 83/02/04 KEPPLER, J O Region
3, Office of Director 1p 17166 295 24X Fiche 50-237, 83/02/04,
8302160222

--8302160226 LER 83-004/03L-0 on 830113, during core unloading operations,
grapple control rod interlock would intermittently clear
while grapple was over core Caused by grapple not
maintaining full contact w/rail Limit switch adjusted
COEN, R W Commonwealth Edison Co 83/02/04 Region 3, Office
of Director 1p 17166 296 24X Fiche 50-237, 83/02/04,
8302160222

8302150596 PNO-111-83-012 on 830204, crack indication in weld between
torus wall & catwalk support beam identified during magnetic
particle testing Cause unknown Licensee evaluating crack
indication Unit in shutdown since 830118
DANIELSON, D, LITTLE, W Region 3, Office of Director 83/02/07
1p 17156 110, 24X Fiche 50-237, 83/02/07, 8302150596

8302230703 Forwards LER 83-011/01T-0
SCOTT, D J Commonwealth Edison Co 83/02/15 KEPPLER, J O Region
3, Office of Director 1p 17259 287 24X Fiche 50-237, 83/02/15,
8302230703

--8302230706 LER 83-011/01T-0 on 830203, during refueling outage,
nondestructive test on new fillet weld discovered crack
between torus shell & ring girder separating bays 8 & 9
Cause unknown Investigation underway
TANO WEE, D Commonwealth Edison Co 83/02/15 Region 3, Office
of Director 2pp 17259 288 24X Fiche 50-237, 83/02/15,
8302230703

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLS, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347, 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

P. Operating license stage documents & correspondence

8302100101 Forwards Amend 10 to License NB-1 & notice of issuance &
availability Amend revises Tech Specs to reflect
administrative changes
EISENHUT, D O Division of Licensing 83/02/02, QUERRY, J E South
Carolina, State of 3pp 17135 083 24X Fiche 50-238, 83/02/02,
8302100101

--8302100105 Amend 10 to License NB-1, revising Tech Specs to reflect
administrative changes.
EISENHUT, D O Division of Licensing 83/02/02 7pp 17135 086
24X Fiche 50-238, 83/02/02, 8302100101

--8302100110 Notice of issuance & availability of Amend 10 to License
NB-1
EISENHUT, D O Division of Licensing 83/02/02 2pp 17135 095
24X Fiche 50-238, 83/02/02, 8302100101

DOCKET 50-244 ROBERT EMMET QUINNA NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8212210331 Provides addl info to better prepare shift crews operating
nuclear power plants for questions NRC duty officer may ask
during telephone notifications, Revised event notification
form encl.
STAROSTECKI, R Division of Project & Resident Programs 82/12/16
MAIER, J E Rochester Gas & Electric Corp. 6pp, 16497 020, 24X
Fiche: 50-244, 82/12/16, 8212210331

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070365 Act receipt of 821229 ltr informing NRC of steps taken to
correct violations noted in IE Emergency Preparedness
Appraisal Rept 50-244/B1-22
MARTIN, T T Division of Engineering & Technical Programs 83/02/02
MAIER, J E Rochester Gas & Electric Corp 1p 17030 097 24X
Fiche 50-244, 83/02/02, 8302070365

--8302070367 Responds to NRC 821007 ltr re violations noted in IE
Emergency Preparedness Appraisal Rept 50-244/B1-22
Corrective actions: emergency planning info provided to
residents living within 10 mile emergency planning zone.
MAIER, J E Rochester Gas & Electric Corp. 82/12/29 SMITH, O H
Division of Emergency Preparedness & Operational Support. 1p
17030 098. 24X Fiche 50-244, 83/02/02, 8302070365

--8302070370 "To Our Neighbors in Wayne County, RE Quinna Nuclear Power
Plant Emergency Planning Info"
BRI008, P W. Rochester Gas & Electric Corp. MORIN, L. Monroe
County, NY DECKER, M. Wayne County, NY 82/12/29 12pp.
17030 099 24X Fiche 50-244, 83/02/02, 8302070365

8302150620 Forwards Amend 56 to License DPR-18 & notice of issuance
& availability Amend authorizes Tech Spec changes to bring
audits of emergency & security plans in compliance w/
10CFR50.54 & 73.40
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 MAIER, J E
Rochester Gas & Electric Corp 3pp 17151 317, 24X
Fiche 50-244, 83/02/09, 8302150620

--8302150629 Amend 56 to License DPR-18, authorizing Tech Spec changes to
bring audits of emergency & security plans in compliance w/
10CFR50.54 & 73.40(d)
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 4pp
17151 320 24X Fiche 50-244, 83/02/09, 8302150620

--8302150633 Notice of issuance & availability of Amend 56 to License
DPR-18
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 2pp.
17151 324, 24X Fiche 50-244, 83/02/09, 8302150620

8302230426 Forwards revised Pp 3, 4, 3-b & 5-b & to security plan.
Pages withheld (ref 10CFR73.21)
MAIER, J E Rochester Gas & Electric Corp 83/02/15 CRUTCHFIELD, D.
Operating Reactors Branch 5 1p 17246 123, 24X
Fiche 50-244, 83/02/15, 8302230426.

8302230714 Advises that XN-NF-79-49(P), Rev 1, treats upper plenum
injection & should be referenced in docket info fulfill
821213 commitment
MAIER, J E Rochester Gas & Electric Corp. 83/02/17 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 17248 346, 24X
Fiche 50-244, 83/02/17, 8302230714

P Operating license stage documents & correspondence

8302020343 Addl response to FOIA request for seven categories of info.
Forwards documents listed in App A Addl comments provided.
Documents also available in PDR Search for addl documents in
progress
FELTON, J M Division of Rules and Records. 82/12/13
SCHLISSEL, D A New York, State of 3pp 16999 119, 24X
Fiche: 50-000, 82/12/13, 8302020343.

8302040382 Responds to request for info on solid, liquid & gaseous
wastewater which would result from proposed steam generator
sleaving program
MAIER, J E Rochester Gas & Electric Corp 83/01/31. CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 17018 281 24X
Fiche: 50-244, 83/01/31, 8302040382

8302070270 Forwards "Deer Creek Overflow Flooding Study," per SEP Topic
II 3 B, "Flooding Potential & Protection Requirements,"
SEP Topics II 3 B, II 3 B, I, II 3 C & II 3 A considered
complete
MAIER, J E Rochester Gas & Electric Corp 83/01/31 CRUTCHFIELD, D.
Operating Reactors Branch 5 2pp. 17031 126, 24X
Fiche: 50-244, 83/01/31, 8302070270

--8302070275 "Deer Creek Overflow Flooding Study, SEP Topic II-3.B,"
* Rochester Gas & Electric Corp 83/01/31 17pp. 17031:128
24X Fiche: 50-244, 83/01/31, 8302070270

DOCKETED ITEMS

- 8302140116 Forwards info reaffirming justification for continued operation, in response to NRC 821213 ltr, per IE Bulletin 79-01B, "Environ Qualification of Electrical Equipment"
- MAIER, J E Rochester Gas & Electric Corp 83/02/01 CRUTCHFIELD, D
Operating Reactors Branch 5 6pp 17142 069 24X
Fiche 50-244, 83/02/01, 8302140116
- 8302140122 "Radiation Effects on Organic Matls in Nuclear Plants," final rept.
- BRUCE, M B, DAVIS, M V Georgia Institute of Technology EPRI RP 1707-3 83/02/01 6pp 17142 075 24X Fiche 50-244, 83/02/01, 8302140116
- 8302140073 Forwards addl info re containment purging/venting, per NRC 811215 request No vital equipment located in exhaust portion of purge sys in intermediate bldg upper level east end
- MAIER, J E Rochester Gas & Electric Corp. 83/02/04 CRUTCHFIELD, D
Operating Reactors Branch 5 5pp 17142 117 24X
Fiche 50-244, 83/02/04, 8302140073
- 8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
- EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295
- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
- EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304
- 8302090085 Generic Ltr 83-10D to all licensees w/Hestinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
- EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085
- 8302150620 Forwards Amend 56 to License DPR-18 & notice of issuance & availability Amend authorizes Tech Spec changes to bring audits of emergency & security plans in compliance w/ 10CFR50 54 & 73 40
- CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 MAIER, J E
Rochester Gas & Electric Corp 3pp 17151 317 24X
Fiche 50-244, 83/02/09, 8302150620
- 8302150629 Amend 56 to License DPR-18, authorizing Tech Spec changes to bring audits of emergency & security plans in compliance w/ 10CFR50 54 & 73 40(d)
- CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 4pp
17151 320 24X Fiche 50-244, 83/02/09, 8302150620
- 8302150633 Notice of issuance & availability of Amend 56 to License DPR-18
- CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 2pp
17151 324 24X Fiche 50-244, 83/02/09, 8302150620
- 8302160261 Advises that no potential exists for containment overpressurization from main steam line break w/continued feedwater addition, per util 800430 & 820201 ltrs re SEP Topics VI-2 D & IV-3, in response to IE Bulletin 80-04
- CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 MAIER, J E
Rochester Gas & Electric Corp 2pp 17164 091 24X
Fiche 50-244, 83/02/09, 8302160261
- 8302160266 Safety evaluation re main steam line break w/continued feedwater addition No potential for containment overpressurization exists No further action re IE Bulletin 80-04 required
- Office of Nuclear Reactor Regulation, Director 83/02/09 7pp
17164 093 24X Fiche 50-244, 83/02/09, 8302160261
- 8212200054 "PHR Main Steam Line Break W/Continued Feedwater Addition, RE Ulina Nuclear Power Plant," technical evaluation rept
- VOSSBURY, F W, HERRICK, R C Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-146 82/12/15 HEARN, P NRC -
No Detailed Affiliation Given 24pp 17164 100 24X
Fiche 50-244, 83/02/09, 8302160261
- 8302205002 Advises that Class III fee submitted w/820809 application for operation at both current & reduced primary sys pressure & temp will be refunded. Action based on util withdrawing application before commencement of NRC review
- MILLER, W D License Fee Management Branch 83/02/18 MAIER, J E
Rochester Gas & Electric Corp 1p 17234 348 24X
Fiche 50-244, 83/02/18, 8302205002
- 8302230350 Forwards application for amend to License DPR-18, changing Tech Spec 3 1 4 re max coolant activity
- MAIER, J E Rochester Gas & Electric Corp 83/02/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17246 203 24X
Fiche 50-244, 83/02/18, 8302230350
- 8302230363 Application for amend to License DPR-18, changing Tech Spec 3 1 4 re max coolant activity
- MAIER, J E Rochester Gas & Electric Corp 83/02/18 2pp
17246 204 24X Fiche 50-244, 83/02/18, 8302230360
- 8302230367 Proposed Tech Spec 3 1 4 re max coolant activity
- Rochester Gas & Electric Corp 83/02/18 61pp 17246 210
24X Fiche 50-244, 83/02/18, 8302230360
- 8302230495 Describes cable penetration mod to be performed during spring refueling outage scheduled for late Mar 1983 No Tech Spec mod required
- MAIER, J E Rochester Gas & Electric Corp 83/02/18 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 17246 189 24X
Fiche 50-244, 83/02/18, 8302230495
- 8302280406 Requests info within 15 days of receipt of ltr re operability of large-diameter Pratt purge & vent valves & maint of sealed purge & vent valves Info will determine action to modify, suspend or revoke license
- CRUTCHFIELD, D Operating Reactors Branch 5 83/02/23 MAIER, J E
Rochester Gas & Electric Corp 6pp 17309 151 24X
Fiche 50-244, 83/02/23, 8302280406
- 8302280453 Forwards request for addl info to complete post-implementation review of NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 6, "Containment Hydrogen Monitor"
- CRUTCHFIELD, D Operating Reactors Branch 5 83/02/23 MAIER, J E
Rochester Gas & Electric Corp 10pp 17308 012 24X
Fiche 50-244, 83/02/23, 8302280453
- G Inspection reports, IE Bulletins & correspondence
- 8302030568 Forwards IE Insp Rept 50-244/82-21 on 821206-31 No noncompliance noted
- STAROSTECKI, R Division of Project & Resident Programs 83/01/20
MAIER, J E Rochester Gas & Electric Corp 2pp 17008 109 24X
Fiche 50-244, 83/01/20, 8302030568
- 8302030576 IE Insp Rept 50-244/82-21 on 821206-31 No noncompliance noted Major areas inspected plant operations, surveillance testing, steam generator tube rupture procedure review, LER & followup of licensee actions on previous insp findings
- ZIMMERMAN, R P, KISTER, H B Division of Project & Resident Programs 83/01/15 7pp 17008 111 24X Fiche 50-244, 83/01/20, 8302030568
- 8302160014 Summary of 830120 meeting w/utls, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
- TRAMMELL, C H Operating Reactors Branch 3 83/01/25 Operating
Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014
- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
- JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Oarheads" Svc list encl
- JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360
- 8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
- JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361
- 8302140116 Forwards info reaffirming justification for continued operation, in response to NRC 821213 ltr, per IE Bulletin 79-01B, "Environ Qualification of Electrical Equipment"
- MAIER, J E Rochester Gas & Electric Corp 83/02/01 CRUTCHFIELD, D
Operating Reactors Branch 5 6pp 17142 069 24X
Fiche 50-244, 83/02/01, 8302140116
- 8302140122 "Radiation Effects on Organic Matls in Nuclear Plants," final rept
- BRUCE, M B, DAVIS, M V Georgia Institute of Technology EPRI RP 1707-3 83/02/01 6pp 17142 075 24X Fiche 50-244, 83/02/01, 8302140116

8302070365 Ack receipt of 821229 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-244/81-22
MARTIN, T T Division of Engineering & Technical Programs 83/02/02
MAIER, J E Rochester Gas & Electric Corp 1p 17030 097 24X
Fiche 50-244, 83/02/02, 8302070365

--8302070367 Responds to NRC 821007 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-244/81-22
Corrective actions emergency planning info provided to residents living within 10 mile emergency planning zone
MAIER, J E Rochester Gas & Electric Corp 82/12/29 SMITH, O H
Division of Emergency Preparedness & Operational Support 1p
17030 098 24X Fiche 50-244, 83/02/02, 8302070365

--8302070370 "To Our Neighbors in Wayne County, RE Ginna Nuclear Power Plant Emergency Planning Info"
BRIGGS, P U Rochester Gas & Electric Corp MORIN, L Monroe
County, NY DECKER, M Wayne County, NY 82/12/29 12pp
17030 099 24X Fiche 50-244, 83/02/02, 8302070365

8302180305 Ack receipt of 821229 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-19
Changing of gate locks on high radiation areas should be completed by 830312
MARTIN, T T Division of Engineering & Technical Programs 83/02/02
MAIER, J E Rochester Gas & Electric Corp 2pp 17211 229 24X
Fiche 50-244, 83/02/02, 8302180305

--8302180312 Responds to NRC 821207 ltr re violations noted in IE Insp Rept 50-244/82-19 Corrective actions handholes cut in wire gates barricading locked areas normally used in auxiliary bldg
MAIER, J E Rochester Gas & Electric Corp 82/12/29 MARTIN, T T
Division of Engineering & Technical Programs 2pp 17211, 231
24X Fiche 50-244, 83/02/02, 8302180305

8302090439 Ack receipt of 830111 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-23
MARTIN, T T Division of Engineering & Technical Programs 83/02/03
MAIER, J E Rochester Gas & Electric Corp 1p 17066 251 24X
Fiche 50-244, 83/02/03, 8302090439

--8302090441 Responds to NRC 821213 ltr re violations noted in IE Insp Rept 50-244/82-23 Corrective actions SNM physical inventory will be performed at 6-month intervals not to exceed 12 months
MAIER, J E Rochester Gas & Electric Corp 83/01/11 MARTIN, T T
Division of Engineering & Technical Programs 2p 17066 252 24X
Fiche 50-244, 83/02/03, 8302090439

8302160261 Advises that no potential exists for containment overpressurization from main steam line break w/continued feedwater addition per util 800430 & 820201 ltrs re SEP Topics VI-2 D & IV-3, in response to IE Bulletin 80-04
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 MAIER, J E
Rochester Gas & Electric Corp 2pp 17164 091 24X
Fiche 50-244, 83/02/09, 8302160261

--8302160266 Safety evaluation re main steam line break w/continued feedwater addition No potential for containment overpressurization exists. No further action re IE Bulletin 80-04 required
* Office of Nuclear Reactor Regulation, Director 83/02/09. 7pp
17164 093 24X Fiche 50-244, 83/02/09, 8302160261

--8212200054 "PWR Main Steam Line Break W/Continued Feedwater Addition, RE Ginna Nuclear Power Plant," technical evaluation rept
VOEBURY, F W, HERRICK, R C Franklin Institute/Franklin Research Center, MRC-03-81-130 TER-C5906-146 82/12/15 HEARN, P NRC -
No Detailed Affiliation Given 24pp 17164 100 24X
Fiche 50-244, 83/02/09, 8302160261

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302030378 RO 83-006/01 on 830120, alarm received in control room indicating low screenhouse water level of 20 ft, rendering fire suppression water sys inoperable Addl info will be presented in 14-day written rept
SPECTOR, S M Rochester Gas & Electric Corp 83/01/21 HAYNES, R C
Region 1, Office of Director 1p 17005 202 24X
Fiche 50-244, 83/01/21, 8302030378

8302070557 RO 83-008/01 on 830125, emergency diesel generator start relay (R-1, R-2) indicating lights found off, causing loss of permissive start relays Caused by personnel error Relays reset Memo will be issued describing incident
SPECTOR, S M Rochester Gas & Electric Corp 83/01/26 HAYNES, R C
Region 1, Office of Director 2pp 17034 144 24X
Fiche 50-244, 83/01/26, 8302070557

8302230556 Forwards LER 83-006/01T-0
MAIER, J E Rochester Gas & Electric Corp 83/02/04 HAYNES, R C.
Region 1, Office of Director 1p 17257 001 24X
Fiche 50-244, 83/02/04, 8302230556

--8302230570 LER 83-006/01T-0 on 830120, screen house suction bay water level dropped below suction of motor driven & diesel driven fire pumps, rendering fire suppression sys inoperable Caused by frazil ice in circulating water pump suction
BODINE, J C Rochester Gas & Electric Corp 83/02/03 Region 1,
Office of Director 2pp 17257 002 24X Fiche 50-244, 83/02/04,
8302230556

8302230569 Forwards LER 83-002/03L-0
MAIER, J E Rochester Gas & Electric Corp 83/02/04 HAYNES, R C
Region 1, Office of Director 1p 17255 045 24X
Fiche 50-244, 83/02/04, 8302230569

--8302230586 LER 83-002/03L-0 on 830103, during performance of ISI-7, main steam snubber 160 identified as inoperable Caused by piston rod detachment from piston. Snubber replaced
BODINE, J C Rochester Gas & Electric Corp 83/02/04 Region 1,
Office of Director 1p 17255 046 24X Fiche 50-244, 83/02/04,
8302230569

8302230715 Forwards LER 83-001/03L-0
MAIER, J E Rochester Gas & Electric Corp 83/02/04 HAYNES, R C.
Region 1, Office of Director 1p 17257 307 24X
Fiche 50-244, 83/02/04, 8302230715

--8302230723 LER 83-001/03L-0 on 830104, valve 9626A found mispositioned in closed position Possible causes include human error & deliberate tampering No positive conclusion reached even after exhaustive investigation
BODINE, J C Rochester Gas & Electric Corp 83/02/03 Region 1,
Office of Director 3pp 17257 308 24X Fiche 50-244, 83/02/04,
8302230715

8302180292 Forwards LER 83-003/03L-0
MAIER, J E Rochester Gas & Electric Corp 83/02/07 HAYNES, R C
Region 1, Office of Director 1p 17211 243 24X
Fiche 50-244, 83/02/07, 8302180292

--8302180298 LER 83-003/03L-0 on 830108, containment vessel sump A isolation valve ADV-1728 failed to close on command Cause unknown Valve diaphragm replaced & Leak Tests PT-23 23 & PT-2 5 performed satisfactorily.
BODINE, J C Rochester Gas & Electric Corp 83/02/07 Region 1,
Office of Director 1p 17211 244 24X Fiche 50-244, 83/02/07,
8302180292

8302180330 Forwards LER 83-008/01T-0
MAIER, J E Rochester Gas & Electric Corp 83/02/08 HAYNES, R C.
Region 1, Office of Director 1p 17213 262 24X
Fiche 50-244, 83/02/08, 8302180330

--8302180337 LER 83-008/01T-0 on 830125, emergency diesel generator 1A start relay indicating lights, R-1 & R-2, found off, causing loss of permissive start relays Caused by personnel failure to follow procedures Shift supervisors addressed on subj
BODINE, J C Rochester Gas & Electric Corp 83/02/08 Region 1,
Office of Director 3pp 17213 263 24X Fiche 50-244, 83/02/08,
8302180330

8302230667 Forwards LER 83-004/03L-0
MAIER, J E Rochester Gas & Electric Corp 83/02/11 HAYNES, R C.
Region 1, Office of Director 1p 17257 330 24X
Fiche 50-244, 83/02/11, 8302230667

DOCKETED ITEMS

--8302230674 LER 83-004/03L-0 on 830114, check valve 862B declared inoperable after failing to close promptly during test of containment spray sys Maint performed on valve Valve retested satisfactorily Revised test method developed
BODINE, J C Rochester Gas & Electric Corp 83/02/11 Region 1,
Office of Director 1p 17257 331 24X Fiche 50-244, 83/02/11,
8302230667

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-245 HILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8301190078 Forwards revised reporting procedure of security events Procedure withheld (ref 10CFR73 21)
COUNSIL, W O Connecticut Yankee Atomic Power Co. COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/01/07 MCCORKLE, G Licensing
Management Branch 3pp 16846 303 24X Fiche 50-000, 83/01/07,
8301190078

8302030345 Discusses filing of copies of changes to emergency plans & procedures until requested to continue submitting three copies to Region I or two copies to Region I w/one copy directly submitted to resident inspector
MARTIN, T T Division of Engineering & Technical Programs 83/01/24,
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp 17006 108 24X Fiche 50-000, 83/01/24, 8302030345.

8302010081 Releases public version of revised title pages to Emergency Plans
FELTON, J M Division of Rules and Records 83/01/26 Document
Management Branch 1p 16990 233 24X Fiche 50-000, 83/01/26,
8302010081

--8302010084 Forwards public version of revised title pages to Millstone & Haddam Neck Nuclear Power Plant Emergency Plans, including correction to site plan Figure 7-1c re lines of communication between emergency response ctrs
ST PIERRE, M Northeast Utilities 83/01/13 BAILEY, I NRC - No
Detailed Affiliation Given 1p 16990 234 24X
Fiche 50-000, 83/01/26, 8302010081

--8302010091 Public version of revised title page to Millstone Nuclear Plant Emergency Plan
* Northeast Nuclear Energy Co (subs. of Northeast Utilities)
83/01/13 1p 16990 233 24X Fiche 50-000, 83/01/26, 8302010081

8302030233 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/26 Document
Management Branch 1p 17023 289 24X Fiche 50-245, 83/01/26,
8302030233

--8302030250 Forwards public version of revised Emergency Plan Implementing Procedures EPIP 4308, "Waterford, State & Tri-Town Radio Operation" & EPIP 4612, "Waterford, State & Tri-Town Radio Test"
COUNSIL, W O, CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities
83/01/18 EISENHUT, D O Division of Licensing. 1p 17023 290
24X Fiche 50-245, 83/01/26, 8302030233

-8302030262 Public version of revised Emergency Plan Implementing Procedures EPIP 4308, "Waterford, State & Tri-Town Radio Operation" & EPIP 4612, "Waterford, State & Tri-Town Radio Test" Revised index encl
MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/05 18pp, 17023 291. 24X
Fiche: 50-245, 83/01/26, 8302030233

302090174 Responds to 821104 ltr re Rev 12 to modified amended security plan Proposed changes acceptable Encls to util ltr withheld (ref 10CFR73 21),
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/28 COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
17132 105 24X Fiche 50-245, 83/01/28, 8302090174

8302030033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p. 17027 004. 24X Fiche 50-000, 83/01/31,
8302030033

--8302030043 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4101 re unusual event actions, EPIP 4102 re alert & EPIP 4103 re site area emergency
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/01/07 EISENHUT, D O
Division of Licensing 2pp 17027 005 24X Fiche 50-000,
83/01/31, 8302030033

--8302030052 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4101 re unusual event actions, EPIP 4102 re alert & EPIP 4103 re site area emergency
* Connecticut Yankee Atomic Power Co * Northeast Nuclear Energy Co (subs of Northeast Utilities) * Northeast Utilities
82/12/15 683pp 17027 007 24X Fiche 50-000, 83/01/31,
8302030033

8302070566 Lists objectives of fire protection program PRA to quantify overall frequency of failure to achieve safe shutdown as result of fire at facilities
COUNSIL, W O Northeast Utilities COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/31 EISENHUT, D O Division of Licensing 2pp 17034 282 24X Fiche 50-000, 83/01/31, 8302070566

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302040517 Accepts changes to Rev 9 of modified amended security plan, submitted by util 821103 ltr Encl to util ltr withheld (ref 10CFR73 21)
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/01 COUNSIL, W O
Northeast Utilities 3pp 17043 359 24X Fiche 50-245, 83/02/01,
8302040517

8302150498 Responds to 830106 request for evaluation of draft SER re fire protection & denial of util requests for exemption from App R Working-Level meeting requested to clarify misunderstandings & close remaining open issues
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities 83/02/02
EISENHUT, D O Division of Licensing 2pp 17156 326 24X
Fiche 50-245, 83/02/02, 8302150498

8302100227 Forwards supplemental SER re fire protection for auxiliary boiler blast wall Issue satisfactorily resolved & closed
SHEA, J J Operating Reactors Branch 5 83/02/07 COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
17114 123 24X Fiche 50-245, 83/02/07, 8302100227

--8302100231 Supplemental SER re fire wall between auxiliary boiler (Zone T-9), generator room (Zone T-7) & related structural mods Item acceptable Issue closed
* Office of Nuclear Reactor Regulation, Director 83/02/07 2p
17114 125 24X Fiche 50-245, 83/02/07, 8302100227

8302160224 Recommends NRC prepare status rept of NRC contractor study re radioactive iodine source terms & issue of potassium iodine Rept would help resolve issue for state & local emergency preparedness personnel
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/02/08 EISENHUT, D O
Division of Licensing 2pp 17166 292 24X Fiche 50-000, 83/02/06
8302160224

8302160125 Responds to 821103 ltr re changes to security plan Changes to Revs 11 & 13 consistent w/provisions of 10CFR50 54 & acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
17160 291 24X Fiche 50-245, 83/02/09, 8302160125

8302180174 Ack receipt of 821230 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-245/82-01 & 50-336/82-01
MARTIN, T T Division of Engineering & Technical Programs 83/02/10
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17215 349 24X Fiche 50-245, 83/02/10, 8302180174

DOCKETED ITEMS

39

--8302180184 Responds to NRC 820611 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-245/82-01 & 50-336/82 01 Corrective actions extremity monitoring devices placed in emergency kits & trend analyses program developed COUNCIL, W O , CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 82/12/30 SMITH, O H Division of Emergency Preparedness & Operational Support 4pp 17215 351 24X Fiche 50-245, 83/02/10, 8302180174

8302250497 Determines that changes to physical security plan proposed in 821118 ltr do not decrease security effectiveness & may be submitted for formal review CRUTCHFIELD, D Operating Reactors Branch 5 83/02/18 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 17303 138 24X Fiche 50-245, 83/02/18, 8302250497

D Advisory Committee on Reactor Safeguards reports & correspondence

8302080480 Comments on ACRS Subcommittee on SEP 821130 meeting re licensee disagreement w/NRC position on SEP Topic VI-10 A. "Testing of Reactor Trip Sys & ESF, Including Response Time Testing" LIPINSKI, W C ACRS - Advisory Committee on Reactor Safeguards LIPINSKI, W C Argonne National Laboratory 82/12/02 GIESB, C P ACRS - Advisory Committee on Reactor Safeguards 3pp 17071 269 24X Fiche 50-000, 82/12/02, 8302080480

8302080459 Summary of ACRS Subcommittee on SEP 821026-27 meetings in Washington, DC re integrated plant safety assessment * ACRS - Advisory Committee on Reactor Safeguards 82/12/09 ACRS - Advisory Committee on Reactor Safeguards 33pp 17108 077 24X Fiche 50-000, 82/12/09, 8302080459

P Operating license stage documents & correspondence

8302010491 Forwards response to NRC SER re environ qualification of electrical equipment COUNCIL, W O , CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/01/19 CRUTCHFIELD, D Operating Reactors Branch 5 247pp 16982 078, 24X Fiche 50-245, 83/01/19, 8302010491

8302010301 Forwards addl reporting criteria for unplanned liquid radioactive releases New criteria cover specific types of potential liquid releases not presently covered Response requested by 830403 COUNCIL, W O Connecticut Yankee Atomic Power Co, COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/01/21 HAYNES, R C Region 1, Office of Director 7pp 16973 092 24X Fiche 50-000, 83/01/21, 8302010301

8302040226 Forwards Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively & notice of issuance & availability Amends reflect organizational changes Haddam Neck amend also approves change to upper range intake water temp sensor CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 COUNCIL, W O Connecticut Yankee Atomic Power Co 5pp 17020 115 24X Fiche 50-000, 83/01/26, 8302040226

--8302040231 Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively, revising App B Tech Spec re organizational changes & changing upper range intake water temp sensor for Haddam Neck CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 23pp 17020 120 24X Fiche 50-000, 83/01/26, 8302040226

--8302040240 Notice of issuance & availability of Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 2pp 17020 143 24X Fiche 50-000, 83/01/26, 8302040226

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment. Requests commitment to submit results of plant-unique calculations which formed bases for mod. Svc list encl EISENHUT, D O Division of Licensing, 83/02/02 General Public Utilities - OPU Service Corp 5pp, 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl EISENHUT, D O Division of Licensing 83/02/08, Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl EISENHUT, D O Division of Licensing, 83/02/08 Commonwealth Edison Co 4pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302160197 Forwards request for addl info within 45 days of ltr date re monitoring of electric power to reactor protection sys. CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities), 3pp, 17163 057 24X Fiche 50-245, 83/02/09, 8302160197

8302220427 Notifies that completion date for mods necessary to correct inadequacies associated w/equipment installed per NUREG-0737, Items II F 1.1 & II F 1.2 extended to 830901 Vendor isotopical calibr rept received later than expected COUNCIL, W O , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/02/11 CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 3 2pp 17232 130 24X Fiche 50-245, 83/02/11, 8302220427

8302220155 Forwards "Startup Physics Testing Program for Cycle 9," summary rept COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/02/14 CRUTCHFIELD, D Operating Reactors Branch 5 1p 17233 138 24X Fiche 50-245, 83/02/14, 8302220155

--8302220160 "Startup Physics Testing Program for Cycle 9," summary rept. * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/28 3pp 17233 139 24X Fiche 50-245, 83/02/14, 8302220155

8302240331 Comments on extension of SEP from Phase II to Phase III Integrated assessment concept should be applied to existing backlog of requirements currently being implemented at all operating reactors Handouts from 830204 meeting encl COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities COUNCIL, W O Connecticut Yankee Atomic Power Co, 83/02/15 ZERBE, J E Office of Policy Evaluations 26pp 17274 018, 24X Fiche 50-000, 83/02/15, 8302240331

8302280145 Forwards request for addl info re TMI Action Item II K 3 2B, "Qualification of Accumulators on Automatic Depressurization Sys," to complete review Info should be submitted by 830603 CRUTCHFIELD, D Operating Reactors Branch 5 83/02/18, COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp, 17306 081 24X Fiche 50-245, 83/02/18, 8302280145

8302280226 Informs that decision to reaffirm or withdraw request for hearing on environ qualification of safety-related electrical equipment will be determined within 30-day period following 830222 final rule effective date COUNCIL, W O , SEARS, C F Northeast Utilities 83/02/22, EISENHUT, D O Division of Licensing 2pp, 17304 353 24X Fiche 50-000, 83/02/22, 8302280226

8302280490 Advises that 821028 revised BWR Owners Group study re NUREG-0737, Item II, K 3 1B, "Mod of Automatic Depressurization Sys Logic," applicable to facility. No further action required. COUNCIL, W O , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/02/22, EISENHUT, D O Division of Licensing 2pp, 17309 127 24X Fiche 50-245, 83/02/22, 8302280490

0 Inspection reports, IE Bulletins & correspondence

8302160014 Summary of 830120 meeting w/utis, Bechtel, Franklin Research Ctr URS & Computech Engineering Bvcs re IE Bulletin 80-11, "Masonry Wall Design." Addl testing not warranted TRAMMELL, C M Operating Reactors Branch 3, 83/01/25 Operating Reactors Branch 3 25pp, 17171 227, 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/01/26 Consolidated Edison Co of New York, Inc, 118pp, 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

DOCKETED ITEMS

8302010651 Forwards SALP Repts for Sept 1981 - Aug 1982 Performance exhibits high level of mgt attention & involvement. Ample resources appear to be effectively used.
HAYNES, R C Region 1, Office of Director 83/01/27 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 16979 045 24X Fiche 50-000, 83/01/27, 8302010651

--8302010662 SALP rept on 821013 One minor violation identified re inadequate document control of procedures. Policies adequately stated & understood. Records complete & well maintained.
* Region 1, Office of Director 82/10/13 27pp 16979 049 24X Fiche 50-000, 83/01/27, 8302010651

--8302010679 Notifies of 821103 meeting to provide forum for candid discussions re util performance.
STARDSTECKI, R Division of Project & Resident Programs 82/10/27 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16979 160 24X Fiche 50-000, 83/01/27, 8302010651

--8302010682 Provides comments on 821103 meeting to ensure mutual understanding of detailed performance evaluation of util.
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Connecticut Yankee Atomic Power Co 82/11/23 HAYNES, R C Region 1, Office of Director 5pp 16979 162 24X Fiche 50-000, 83/01/27, 8302010651

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030198 Ack receipt of 821229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-13 & 50-336/82-13
MARTIN, T T Division of Engineering & Technical Programs 83/01/31 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 17001 321 24X Fiche 50-245, 83/01/31, 8302030198

--8302030202 Responds to NRC 820806 ltr re violations noted in IE Insp Repts 50-245/82-13 & 50-336/82-13. Corrective actions procedures being revised re translation of design requirements into drawings.
COUNCIL, W O, CAONETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 82/12/29 MARTIN, T T Division of Engineering & Technical Programs 2pp 17001 322 24X Fiche 50-245, 83/01/31, 8302030198

8302150543 Forwards IE Insp Repts 50-245/82-24 & 50-336/82-26 on 821228-30 & notice of violation.
MARTIN, T T Division of Engineering & Technical Programs 83/01/31 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17156 103 24X Fiche 50-245, 83/01/31, 8302150543

--8302150551 Notice of violation from insp on 821228-30
* Division of Engineering & Technical Programs 83/01/31 1p 17156 105 24X Fiche 50-245, 83/01/31, 8302150543

--8302150559 IE Insp Repts 50-245/82-24 & 50-336/82-26 on 821228-30 Noncompliance noted failure to perform annual audit of applicable criteria of App B to 10CFR50 re transportation packages.
CLEMONS, SHANBAKY, M Region 1, Office of Director 83/01/27 4pp 17156 106 24X Fiche 50-245, 83/01/31, 8302150543

8302180174 Ack receipt of 821230 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-245/82-01 & 50-336/82-01
MARTIN, T T Division of Engineering & Technical Programs 83/02/10 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17215 349 24X Fiche 50-245, 83/02/10, 8302180174

--8302180184 Responds to NRC 820611 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-245/82-01 & 50-336/82-01. Corrective actions extremity monitoring devices placed in emergency kits & trend analysis program developed.
COUNCIL, W O, CAONETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 82/12/30 SMITH, O H Division of Emergency Preparedness & Operational Support, 4pp 17215 351 24X Fiche 50-245, 83/02/10, 8302180174

8302230522 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-245/81-13
MARTIN, T T Division of Engineering & Technical Programs 83/02/10 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 17257 276 24X Fiche 50-245, 83/02/10, 8302230522

--8302230532 Responds to NRC 811001 ltr re violations noted in IE Insp Rept 50-245/81-13. Corrective actions requirements to calculate & record average control insertion times on RE Form 1051-3 will remain as part of required data reduction.
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/01/12 BRUNNER, E J Region 1, Office of Director 1p 17257 277 24X Fiche 50-245, 83/02/10, 8302230522

8302230385 Forwards "ASME Class I, II & III Inservice Insp Rept, 1982 " MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/02/15 HAYNES, R C Region 1, Office of Director 1p 17247 007 24X Fiche 50-245, 83/02/15, 8302230385

--8302230391 "ASME Class I, II & III Inservice Insp Rept, 1982 " * Northeast Utilities 83/02/15 39pp 17247 008 24X Fiche 50-245, 83/02/15, 8302230385

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302030093 Forwards revised LER 82-027/03L-1 Detailed event analysis encl
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/01/28 HAYNES, R C Region 1, Office of Director 3pp 17002 230 24X Fiche 50-245, 83/01/28, 8302030073

--8302030101 Revised LER 82-027/03L-1 on 821111, automatic pressure relief time delay relays 287-104A & 287-104B timed out above Tech Spec limit. Caused by instrument setpoint drift due to high control room temp. Time delay relays reset.
THULL, T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/28 Region 1, Office of Director 1p 17002 233 24X Fiche 50-245, 83/01/28, 8302030093

8302030582 Forwards LER 83-001/03L-0 Detailed event analysis encl
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/01/28 HAYNES, R C Region 1, Office of Director 2pp 17009 002 24X Fiche 50-245, 83/01/28, 8302030582

--8302030588 LER 83-001/03L-0 on 830103, pressure switch 261-30A tripped below Tech Spec limit during main steam line low pressure functional & calibr test. Caused by setpoint trip switch reset.
THULL, T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/28 Region 1, Office of Director 1p 17009 004 24X Fiche 50-245, 83/01/28, 8302030582

8302100444 Forwards LER 83-002/03L-0 Detailed event analysis encl
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/02/03 HAYNES, R C Region 1, Office of Director 2pp 17117 167 24X Fiche 50-245, 83/02/03, 8302100444

--8302100447 LER 83-002/03L-0 on 830104, pressure switch 2205-1621B tripped above Tech Spec limit. Caused by setpoint drift. Switch recalibr & tested satisfactorily.
THULL, T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/03 Region 1, Office of Director 1p 17117 169 24X Fiche 50-245, 83/02/03, 8302100444

DOCKETED ITEMS

V Operator Examinations

8302280097 Responds to Generic Ltr 83-01 re requests for site visits for licensing/certification exams from Apr 1983 - Dec 1985
Estimated exam dates tentative
COUNCIL, W O, SEARS, C F Connecticut Yankee Atomic Power Co
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/18 EISENHUT, D O Division of Licensing 5pp
17309 129 24X Fiche 50-000, 83/02/18, 8302280097

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

F. Security, medical, emergency & fire protection plans

8302080431 Board Notification 83-7 forwards testimony re emergency planning & accident consequences w/o encl
EISENHUT, D O Division of Licensing 83/01/26 PALLADINO, N J., GILINSKY, V., AHEARNE, J F Commissioners 5pp 17074 318 24X Fiche 50-247, 83/01/26, 8302080431

8302070216 Forwards revised Chapters 1-4 to safeguards contingency plan Rev withheld (ref 10CFR2 790 & 10CFR73 21)
O'TOOLE, J D Consolidated Edison Co. of New York, Inc 83/01/28 VARGA, S A Operating Reactors Branch 1 2pp 17031, 322 24X Fiche 50-003, 83/01/28, 8302070216

8302040018 Releases public version of page changes to emergency plan.
FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch. 1p 17043 279 24X Fiche 50-003, 83/01/31, 8302040018

--8302040020 Forwards public version of page changes to emergency plan, App A re site emergency roster
O'TOOLE, J D Consolidated Edison Co. of New York, Inc 83/01/10 HAYNES, R C Region 1, Office of Director. 2pp 17043, 280. 24X Fiche 50-003, 83/01/31, 8302040018

--8302040023 Public version of page changes to emergency plan, App A re site emergency roster
* Consolidated Edison Co. of New York, Inc 82/12/07 14pp. 17043 282 24X Fiche 50-003, 83/01/31, 8302040018

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for QL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302080420 Responds to CF Soutar 821118 ltr re Rev 2 to security force training & qualification plan Changes consistent w/ provisions of 10CFR50 54(p) & do not decrease effectiveness of plan
VARGA, S A Operating Reactors Branch 1 83/02/01, O'TOOLE, J. Consolidated Edison Co. of New York, Inc. 2pp 17074:327 24X Fiche: 50-003, 83/02/01, 8302080420

8302160065 Apprises NRC of current status of pre-exercise activities associated w/ 830309 exercise
THOMAS, L M Federal Emergency Management Agency 83/02/07. DIRCKS, W J Office of the Executive Director for Operations 3pp. 17160 333 24X Fiche 50-247, 83/02/07, 8302160065

8302230377 Forwards IE Insp Rept 50-247/83-01 on 830103-31 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/07 O'TOOLE, J D Consolidated Edison Co. of New York, Inc. 2pp. 17246 304 24X Fiche 50-247, 83/02/07, 8302230377

--8302230394 IE Insp Rept 50-247/83-01 on 830103-31 Noncompliance noted housekeeping & cleanliness controls not established in area of component cooling pumps, charging pumps & 78-ft level mezzanine areas.
FOLEY, T, KOLTAY, P., KISTER, H. Division of Project & Resident Programs. 83/02/04 14pp. 17246:307 24X Fiche 50-247, 83/02/07, 8302230377

8302230467 Ack receipt of 830128 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-247/82-23
STAROSTECKI, R Division of Project & Resident Programs 83/02/14 O'TOOLE, J D Consolidated Edison Co. of New York, Inc 2pp. 17246, 036. 24X Fiche: 50-247, 83/02/14, 8302230467

--8302230498 Responds to NRC 821230 ltr re violations noted in IE Safeguards Insp Rept 50-247/82-23 Corrective actions personnel instructed re two-man rule for access to high radiation area Safeguards info deleted (ref 10CFR73 21)
O'TOOLE, J D Consolidated Edison Co. of New York, Inc 83/01/17 STAROSTECKI, R Division of Project & Resident Programs 4pp. 17246 039 24X Fiche 50-247, 83/02/14, 8302230467

O Adjudicatory correspondence

8302010604 Response to ASLB 830107 Memorandum & Order reformulating contentions under Commission Questions 3 & 4. Requests reconsideration of Order to reinstate Contentions 3, 2, 4, 5 & 4.6 Certificate of Svc encl.
HOLT, J Public Interest Research Group, New York 83/01/24, Atomic Safety and Licensing Board Panel 9pp. 16978:172 24X Fiche 50-247, 83/01/24, 8302010604

8302010517 Requests proposals for fair & efficient method for presenting intervenor, NRC & licensee testimony on Commission Questions 3 & 4 within 3-wk period Proposals must be received by 830207, Svc list encl.
GLEASON, J Atomic Safety and Licensing Board Panel 83/01/28 HOLT, J. Public Interest Research Group, New York BLUM, J. M. Uni of Concerned Scientists MAIKISH, C J. Port Authority of New York New Jersey. 4pp 16977 294 24X Fiche: 50-247, 83/01/28, 8302010517

8302020345 Advises that Amend 1 to Probabilistic Safety Study sent to NRC. Two copies will be transmitted to ASLB. Copy to be sent directly to Judge Hill Related correspondence.
BRANDENBURG, B., COLARULLI, P F. Power Authority of the State of New York. COLARULLI, P F Morgan Associates 83/01/28 GLEASON, J. P. SHON, F. J., PARIS, O H Atomic Safety and Licensing Board Panel 1 16993 347 24X Fiche: 50-247, 83/01/28, 8302020345.

8302020254 Proposed schedule for Question 1 testimony. Testimony should be organized by substantive issues & ASLB questions Careful monitoring of length of cross-examination for each panel needed to ensure meeting schedule Certificate of Svc encl.
BRANDENBURG, B Consolidated Edison Co. of New York, Inc COLARULLI, P F Power Authority of the State of New York. COLARULLI, P F Morgan Associates. 83/01/31 9pp 16994 273 24X Fiche 50-247, 83/01/31, 8302020254

8302030164 Motion for expedited order compelling production of documents relied on by C Ferrow in testimony for Friends of the Earth/NY City Audubon Soc on Commission Question 1
BRANDENBURG, B Consolidated Edison Co. of New York, Inc COLARULLI, P F. Power Authority of the State of New York COLARULLI, P F Morgan Associates. 83/02/01. Atomic Safety and Licensing Board Panel 2pp 17002 010 24X Fiche: 50-247, 83/02/01, 8302030164

--8302030175 Memorandum supporting licensee motion for expedited order compelling production of documents relied on by C Ferrow in testimony Licensees entitled to any notes & draft manuscript chapters, Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co. of New York, Inc. COLARULLI, P F Power Authority of the State of New York. COLARULLI, P F Morgan Associates 83/02/01 Atomic Safety and Licensing Board Panel 19pp. 17002:012. 24X Fiche 50-247, 83/02/01, 8302030164.

8302070496 Order rescinding ASLB 830121 order appointing EE Hill as special assistant to ASLB per 10CFR2 722(a)(1).
GLEASON, J P. Atomic Safety and Licensing Board Panel 83/02/02. 1p 17036:316 24X Fiche 50-247, 83/02/02, 8302070496.

--8302070508 Notice of withdrawal of appearance in proceeding due to possible conflicts of interest.
HILL, E E Atomic Safety and Licensing Board Panel 83/02/02. 17036 317 24X Fiche: 50-247, 83/02/02, 8302070496.

8302070527 Order declining review of Director's Decision DD-82-12 which denied UCB 820804 petition for immediate shutdown due to emergency preparedness deficiencies Commissioner Decision CL-82-38 represents Commission views on issue.
CHILK, S. J. Office of the Secretary of the Commission 83/02/02. Office of Nuclear Reactor Regulation, Director. 2pp 17035, 254. 24X Fiche: 50-247, 83/02/02, 8302070527.

8302070559 Forwards Amend 1 to probabilistic safety study. Weatherman correlating copy of Amend 1 forwarded separately. Requests info re photocopying study in violation of encl agreement w/o amend. Related correspondence.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. COLARULLI, P. F. Power Authority of the State of New York, COLARULLI, P. F. Morgan Associates 83/02/02. BLUM, J. M. New York Univ 3pp 17035, 212 24X Fiche: 50-247, 83/02/02, 8302070559.

DOCKETED ITEMS

- 8302080003 Proposal for receiving evidence on Commission Questions 3 & 4 in response to ASLB 830128 mailgram Licensee witnesses should be scheduled early Intervenor should be required to designate representative witnesses Certificate of Svc encl HASSELL, D F Hearing Branch 1 83/02/04 6pp 17058 312 24X Fiche 50-247, 83/02/04, 8302080003
- 8302080225 Responds to 830128 request for hearing schedule Total time for cross-examination of State of NY witnesses should be limited to 6 5 h FEINBERG, J D New York, State of, Energy Office 83/02/04 OLEASON, J P, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 17057 260 24X Fiche 50-247, 83/02/04, 8302080225
- 8302090234 Memorandum & order formulating final contentions on Commission Questions 3 & 4 OLEASON, J P, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 83/02/07 27pp 17070 176 24X Fiche 50-247, 83/02/07, 8302090234
- 8302090244 Memorandum & order granting NY City Council 830114 request that council witnesses be scheduled during wk of 830301 in NY City OLEASON, J P Atomic Safety and Licensing Board Panel 83/02/07 New York, NY 2pp 17070 249 24X Fiche 50-247, 83/02/07, 8302090244
- 8302090449 Responds to request for documents SC Sholly inspected & copied at NRC office on 821214 Cost of copying documents given MOORE, J E Hearing Branch 1 83/02/07 COLARULLI, P F Morgan Associates 1p 17056 286 24X Fiche 50-247, 83/02/07, 8302090449
- 8302090454 Advises of charges for copying documents re SC Sholly request for documents MOORE, J E Hearing Branch 1 83/02/07 WEISS, E R Harmon & Weiss 1p 17066 242 24X Fiche 50-247, 83/02/07, 8302090454
- 8302160271 Motion for order striking parts of JF Meyer & W Trevor testimony re use of glow plugs, passive heat removal & core retention sys Raising such features after completion of Question 2 record prejudices utils. Certificate of Svc encl BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 83/02/07 Atomic Safety and Licensing Board Panel 8pp 17167 295 24X Fiche 50-247, 83/02/07, 8302160271
- 8302160324 Motion for order establishing schedule for witnesses under Commission Questions 3 & 4, limiting scope of testimony to be presented by NY City Council re ingestion emergency planning zone W/Certificate of Svc MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 83/02/07 Atomic Safety and Licensing Board Panel 12pp 17166 228 24X Fiche 50-247, 83/02/07, 8302160324
- 8302160366 Proposal for fair & efficient method for receiving evidence on Commission Questions 3 & 4 in response to ASLB 830129 mailgram POSNER, P Parents Concerned About Indian Point MOLT, J Public Interest Research Group, New York 83/02/07 10pp 17166 186 24X Fiche 50-247, 83/02/07, 8302160366
- 8302160367 Proposal for scheduling remaining testimony on Commission Questions 3 & 4, per ASLB 830128 mailgram Certificate of Svc encl BRANDENBURG, B Consolidated Edison Co of New York, Inc 83/02/07 16pp 17164 128 24X Fiche 50-247, 83/02/07, 8302160367
- 8302160399 Motion to modify schedule of ASLB hearings on Commission Question 1 Proposed mods would change order of consequence analysis testimony & intervenor testimony on PRA theory & methodology Certificate of Svc encl BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/07 OLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 8pp 17164 263 24X Fiche 50-247, 83/02/07, 8302160399
- 8302160306 Response in opposition to licensee 830201 motion to compel production of unpublished & unrevised manuscripts of witness C Perrow Documents of proprietary nature Publication against public interest HARTZMAN, R M Friends of the Earth HARTZMAN, R M Audubon Society 83/02/08 Atomic Safety and Licensing Board Panel 1p 17170 224 24X Fiche 50-247, 83/02/08, 8302160306
- 8302160311 Memorandum in opposition to licensee 830201 motion to compel production of documents of witness C Perrow Mats consist of unrevised rough drafts of work in progress & are not yet ready for disclosure Info of proprietary nature HARTZMAN, R M Friends of the Earth 83/02/08 Atomic Safety and Licensing Board Panel 4pp 17170 225 24X Fiche 50-247, 83/02/08, 8302160306
- 8302160318 Affirmation in opposition to licensee 830201 motion for expedited order compelling production of witness C Perrow documents No portion of witness testimony draws upon draft manuscript info HARTZMAN, R M Friends of the Earth 83/02/08 2pp 17170 229 24X Fiche 50-247, 83/02/08, 8302160306
- 8302160384 Response in opposition to UCS/NY PIRO 830124 motion for certification of two questions re proposed contentions Questions proposed for certification do not present major questions of policy Certificate of Svc encl BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 83/02/08 Atomic Safety and Licensing Board Panel 14pp 17164 180 24X Fiche 50-247, 83/02/08, 8302160384
- 8302160278 Motion to strike DN Pisello, RG Piccioni, HJ Geiger & VW Sidel prefilled testimony under Commission Question 1 & renewed motion to strike B Palenik & J Beyea testimony under Commission Questions 3 & 4 Certificate of Svc encl BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/07 Atomic Safety and Licensing Board Panel 11pp 17169 164 24X Fiche 50-247, 83/02/07, 8302160278
- 8302160372 Opposition to UCS/NY PIRO 830207 motion to strike testimony of B Cohen Allegation that Cohen testimony is subjective unfounded Certificate of Svc encl Related correspondence BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/09 OLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 4pp 17164 149 24X Fiche 50-247, 83/02/09, 8302160372
- 8302160395 Opposition to UCS/NY PIRO motion to strike RL DuPont testimony on Commission Question 1 Testimony addresses issues raised in testimony of other witnesses, not psychological stress issues Certificate of Svc encl COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/09 Atomic Safety and Licensing Board Panel 8pp 17164 193 24X Fiche 50-247, 83/02/09, 8302160395
- 8302170079 Forwards FEMA 830207 ltr to NRC advising of current status of pre-exercise activities for 830209 scheduled emergency planning exercise HASSELL, D F Hearing Branch 1 83/02/16 OLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 1p 17183 015 24X Fiche 50-247, 83/02/16, 8302170079
- 8302220393 Mailgram order appointing JA Laurenson as alternate ASLB member to make recommendations to ASLB re fair & efficient method for receiving evidence on Commission Questions 3 & 4 OLEASON, J P, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 83/02/17 Docketing & Services Branch 2pp 17232 029 24X Fiche 50-247, 83/02/17, 8302220393
- 8302220345 Mailgram order scheduling 830228 conference in New York, NY re procedures for fair & efficient method for receiving evidence on Commission Questions 3 & 4 LAURENSON, J A Atomic Safety and Licensing Board Panel 83/02/18 Docketing & Services Branch 2pp 17232 141 24X Fiche 50-247, 83/02/18, 8302220345
- 8302230552 Provides list of intended witnesses for 830301 hearing KAPLAN, C National Emergency Civil Liberties Committee 83/02/18 OLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 2pp 17257 080 24X Fiche 50-247, 83/02/18, 8302230552
- 8302230561 Application for issuance of subpoena directing RF Littlejohn to appear before ASLB during wk of 830228 to testify re NY City planning & preparedness for radiological emergency KAPLAN, C National Emergency Civil Liberties Committee 83/02/17 Atomic Safety and Licensing Board Panel 2pp 17257 082 24X Fiche 50-247, 83/02/18, 8302230552
- 8302230564 Application for issuance of subpoena directing B Ward to testify before ASLB at proceeding KAPLAN, C National Emergency Civil Liberties Committee 83/02/17 Atomic Safety and Licensing Board Panel 1p 17257 084 24X Fiche 50-247, 83/02/18, 8302230552
- 8302230572 Response in opposition to licensee 830207 motions objecting to NY City Council member testimony re Commission Questions 3 & 4 Licensees fail to make specific objections to specific proffered witnesses Certificate of Svc encl KAPLAN, C National Emergency Civil Liberties Committee 83/02/18 Atomic Safety and Licensing Board Panel 10pp 17257 085 24X Fiche 50-247, 83/02/18, 8302230552

- 8302280279 Forwards list of documents relied upon by JF Meyer & MT Pratt in preparing direct testimony on mitigation strategy for Commission Question 1
HASSELL, D F Hearing Branch 1 83/02/18 BLUM, J M New York Univ
COLARULLI, P F Morgan Associates BRANDENBERG, B Consolidated
Edison Co of New York, Inc 3pp 17313 023 24X
Fiche 50-247, 83/02/18, 8302280279
- 8302280163 Objection to NRC 830204 proposal for receiving evidence on Commission Questions 3 & 4 Opposes proposal to limit time of NRC witness Urbanik Certificate of Svc encl
FLEISHER, Z S West Branch Conservation Association 83/02/19 5pp
17305 319 24X Fiche 50-247, 83/02/19, 8302280163
- 8302280277 Motion to reinstate portion of Contention 3 2 re util workers F Fischer will testify on issue Prof qualifications encl
FLEISHER, Z S West Branch Conservation Association 83/02/19
Atomic Safety and Licensing Board Panel 3pp 17313 001 24X
Fiche 50-247, 83/02/19, 8302280277
- 8302240309 Suppl to NY City Council 830218 opposition to licensee actions re Council member witnesses under Commission Questions 3 & 4 Evidence re existing capability to implement relocation strategy should be heard w/Certificate of Svc
KAPLAN, C New York, NY 83/02/22 Atomic Safety and Licensing Board Panel 3pp 17271 329 24X Fiche 50-247, 83/02/22, 8302240309
- 8302240314 Motion to permit entry upon land controlled by licensees & to allow observance of 830309 emergency planning exercise from both Units 2 & 3 control rooms & from near-site emergency operations facility
HOLT, J Public Interest Research Group, New York 83/02/22
Consolidated Edison Co of New York, Inc 3pp 17271 360 24X
Fiche 50-247, 83/02/22, 8302240314
- 8302280372 Motion for preservation & production of certain documents re 830309 emergency exercise Record essential to give accurate picture of any exercise evaluation results
HOLT, J Public Interest Research Group, New York 83/02/22
Atomic Safety and Licensing Board Panel 3pp 17297 048 24X
Fiche 50-247, 83/02/22, 8302280372
- 8302250379 Urges reconsideration of decision not to hold any limited appearance hearings in NY City during wk of 830301-01 People should be heard
HOLT, J Public Interest Research Group, New York 83/02/21
GLEASON, J P, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17297 051 24X Fiche 50-247, 83/02/22, 8302250379
- 8302250383 Motion to permit entry on licensee controlled land to observe 830309 emergency planning exercise from control rooms & near-site emergency operations facility
HOLT, J Public Interest Research Group, New York 83/02/22
Power Authority of the State of New York 3pp 17297 052 24X
Fiche 50-247, 83/02/22, 8302250383
- 8302250387 Forwards R Seasonwein testimony on Commission Question 3 re emergency planning
BRODSKY, R L New York, State of 83/02/21 GLEASON, J P,
PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel
1p 17297 055 24X Fiche 50-247, 83/02/22, 8302250387
- 8302250392 Testimony of R Seasonwein on Commission Question 3 re emergency planning Large portion of population will comply if ordered to stay in homes during emergency Chaos could prevail if evacuation ordered
SEASONWEIN, R New York, State of 83/02/21 24pp 17297 056
24X Fiche 50-247, 83/02/22, 8302250392
- 8302250396 Supplemental testimony of BW Anderson re considerations for planning evacuation of handicapped persons Accessible bus survey encl
ANDERSON, S W Union of Concerned Scientists ANDERSON, S W
Public Interest Research Group, New York ANDERSON, S W
Westchester Peoples Action Coalition, Inc 83/02/21 10pp
17297 074 24X Fiche 50-247, 83/02/22, 8302250396
- 8302250399 Testimony of C Awalt re evacuation of mentally retarded patients in homes Neither o/c or homes contacted re emergency planning for nuclear accident
AWALT, C Parents Concerned About Indian Point AWALT, C
Westchester Peoples Action Coalition, Inc 83/02/18 2pp
17297 084 24X Fiche 50-247, 83/02/22, 8302250399
- 8302250405 Supplemental testimony of KT Erikson re emergency studies Emergency plans inadequate unless number of people who will overreact & number of emergency personnel who will not report to duty are taken into account
ERIKSON, K T Parents Concerned About Indian Point ERIKSON, K T
Union of Concerned Scientists ERIKSON, K T Public Interest Research Group, New York 83/02/21 4pp 17297 086 24X
Fiche 50-247, 83/02/22, 8302250405
- 8302250410 Testimony of S Hall Transport Workers Union has not been involved in any evacuation plan
HALL, S Parents Concerned About Indian Point HALL, S Union of Concerned Scientists HALL, S Public Interest Research Group, New York 83/02/17 1p 17297 090 24X Fiche 50-247, 83/02/22, 8302250410
- 8302250416 Testimony of JF Roden re inadequacy of procedures re Westchester portion of 10-mile evacuation area & personnel use. Roads cannot handle traffic Parents will not cooperate w/evacuation of children
RODEN, J F Parents Concerned About Indian Point 83/02/17 5pp
17297 091 24X Fiche 50-247, 83/02/22, 8302250416
- 8302250419 Testimony of A Cormican re evacuation of school children Evacuation plan should be rejected
CORMICAN, A Parents Concerned About Indian Point 83/02/17 6pp
17297 096 24X Fiche 50-247, 83/02/22, 8302250419
- 8302250425 Testimony of J Murphy Present emergency planning seriously deficient because plan does not prepare for exposure levels exceeding 100 rems or for internal contamination Certificate of Svc encl.
MURPHY, J Union of Concerned Scientists MURPHY, J Public Interest Research Group, New York 83/02/21 93pp 17297 102
24X Fiche 50-247, 83/02/22, 8302250425
- 8302280270 Forwards exhibits sponsored by NY State witnesses on emergency planning
FEINBERG, J D New York, State of, Energy Office 83/02/22
GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 18pp 17311 296 24X Fiche 50-247, 83/02/22, 8302280270
- 8302280187 Order amending svc list to reflect change of law clerks
GLEASON, J P Atomic Safety and Licensing Board Panel 83/02/23
1p 17306 057 24X Fiche 50-247, 83/02/23, 8302280187
- H General correspondence

- 8302240066 FOIA request for all prior & partial prior drafts & memos of probabilistic safety study
BLUM, J M Union of Concerned Scientists 82/12/28 FELTON, J
Division of Rules and Records 1p 17285 001 24X
Fiche 50-003, 82/12/28, 8302240066
- P Operating license stage documents & correspondence

- 8302150341 Advises that NUREG-0737, Action Items II B 3, II F 1, III A 1 2 & III D 3 4 will not be completed on schedule Estimated completion dates encl. Most administrative procedures revised to comply w/Generic Ltr 82-12 Corrected copy
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/23
VAROLA, S A Operating Reactors Branch 1 3pp 17157 207 24X
Fiche 50-247, 82/12/23, 8302150341
- 8302010715 Forwards corrected Tech Spec Tables 4.4-1 submitted on 821211 w/Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively
POLK, R J Operating Reactors Branch 1 83/01/12 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 3pp 16989 244 24X
Fiche 50-003, 83/01/12, 8302010715
- 8302010718 Corrected pages to Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, revising Table 4 4-1 (Page 8 of 14) & Table 4 4-1 (Page 9 of 14) re containment isolation valves
* Operating Reactors Branch 1 83/01/12 2pp 16989 247 24X
Fiche 50-003, 83/01/12, 8302010718
- 8302240073 Partial response to FOIA request for all prior & partial prior drafts & memos of probabilistic safety study Forwards documents listed in app Search for add records in progress
FELTON, J M Division of Rules and Records 83/01/13 BLUM, J M
Union of Concerned Scientists 2pp 17285 002 24X
Fiche 50-000, 83/01/13, 8302240073
- 8302240082 "Accumulator Sys." revised draft chapter for PRA
* Pickard, Lowe & Garrick, Inc 81/01/06 14pp 17285 004 24X
Fiche 50-000, 83/01/13, 8302240082
- 8302240089 "Reactor Protection Sys." revised draft chapter for PRA.
* Pickard, Lowe & Garrick, Inc 81/01/06 27pp 17285 018 24X
Fiche 50-000, 83/01/13, 8302240089
- 8302240095 Forwards draft sys writeups "Accumulator Sys" & "Reactor Protection Sys." to draft PRA.
LIBERATORIO, L Consolidated Edison Co of New York, Inc 81/01/16
OLSHAW, L NRC - No Detailed Affiliation Given 1p 17285 045
24X Fiche 50-000, 83/01/13, 8302240095

DOCKETED ITEMS

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
HANNON, J N NRC - No Detailed Affiliation Given 82/01/27. 24X
VARQA, S NRC - No Detailed Affiliation Given 10pp 17196 225
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170256 Concludes that licensee justification for continued operation until completion of environ qualification program acceptable based on review
THOMA, J Operating Reactors Branch 1 82/10/28 EISENHUT, D O Division of Licensing 4pp 17197 044 24X Fiche 50-000, 83/01/18, 8302170019

8302240188 Addl response to FOIA request for all prior draft & partial drafts of probabilistic safety study & all memos pertaining to drafts Documents available in PDR w/exception of Israel to Hickman 801103 ltr
FELTON, J M Division of Rules and Records 83/01/20 BLUM, J M Union of Concerned Scientists 1p 17288 302 24X
Fiche 50-003, 83/01/20, 8302240188

8302100307 Forwards response to NRC 820325 request for addl info re fuel storage bldg crane evaluation & verification of equipment insp info re special lifting devices will be submitted by 830729
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/01/31 VARQA, S A Operating Reactors Branch 1 16pp 17117 070 24X
Fiche 50-247, 83/01/31, 8302100307

8302160432 Requests escorted visitor access to site on 830210 for RJ Budnitz
VARQA, S A Operating Reactors Branch 1 83/01/31, O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 17172 246 24X
Fiche 50-247, 83/01/31, 8302160432

8302100230 Advises that 820920 Generic Ltr 82-16 re Tech Spec requirements for NUREG-0737 items, not received from NRC but other sources Response will be submitted by 830531 Generic ltrs should be issued directly to util
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/01 VARQA, S A Operating Reactors Branch 1 1p 17114 122 24X
Fiche 50-247, 83/02/01, 8302100230

8302170316 Application to amend Licenses DPR-5 & DPR-26, revising Apps A & B radiological effluent Tech Specs to omit 10CFR40 190 compliance requirement re U fuel cycle total dose
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/01 VARQA, S A Operating Reactors Branch 1 2pp 17184 004 24X
Fiche 50-003, 83/02/01, 8302170316

--8302170317 Proposed Tech Spec changes re U fuel cycle total dose per 10CFR40 190 compliance requirement
* Consolidated Edison Co of New York, Inc 83/01/31 95pp 17184.006 24X Fiche 50-003, 83/02/01, 8302170316

8302170306 Notification of contract execution "Indian Point Testimony of External Events," awarded to Future Resources Assoc, Inc
HOPPER, A M Administrative Contracts Branch FIN B-8641 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director
SULLIVAN, E NRC - No Detailed Affiliation Given 1p 17207 326 24X Fiche 50-247, 83/02/02, 8302170306

--8302170310 Contract "Indian Point Testimony of External Events," awarded to Future Resources Assoc, Inc
BUDNITZ, R J Future Resources Associates, Inc REBELLO, J E Division of Contracts FIN B-8641 83/02/02 5pp 17207 327 24X Fiche 50-247, 83/02/02, 8302170306

8302100166 Requests Class III Fee for 821217 application to amend License DPR-26, changing Tech Specs re severe hurricane condition
DIQOS, R M License Fee Management Branch 83/02/03 O'TOOLE, J D Consolidated Edison Co of New York, Inc 1p 17134 194 24X
Fiche 50-247, 83/02/03, 8302100166

8302150349 Provides update of containment bldg seismic capacity, including seismic reanalysis of Unit 2 containment bldg fragilities Reanalysis results indicate possibility of containment failure due to seismic event eliminated
BAYNE, J P Power Authority of the State of New York O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/04 VARQA, S A Operating Reactors Branch 1 9pp 17197 246 24X
Fiche 50-247, 83/02/04, 8302150349

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee justification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Hestinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item 11 K 3 S: "Automatic Trip of Reactor Coolant Pump" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302230002 Forwards Fee for Amend 83 to 821217 application Payment made under protest
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/15 VARQA, S A Operating Reactors Branch 1 1p 17243 268 24X
Fiche 50-247, 83/02/15, 8302230002

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302180229 Forwards IE Insp Rept 50-247/83-02 on 830110-14 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/02/04 O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 17215 281 24X Fiche 50-247, 83/02/04, 8302180229

--8302180232 Notice of violation from insp on 830110-14
* Division of Engineering & Technical Programs 83/02/04 1p 17215 283 24X Fiche 50-247, 83/02/04, 8302180229

--8302180236 IE Insp Rept 50-247/83-02 on 830110-14 Noncompliance noted failure to provide periodic general employee retraining
COGAN, N J, SHAW, E T, CAPTON, D L Division of Engineering & Technical Programs 83/02/02 10pp 17215 284 24X
Fiche 50-247, 83/02/04, 8302180229

8302230377 Forwards IE Insp Rept 50-247/83-01 on 830103-31 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/02/07 O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 17246 304 24X Fiche 50-247, 83/02/07, 8302230377

--8302230382 Notice of violation from insp on 830103-31
* Division of Project & Resident Programs 83/02/07 1p 17246 306 24X Fiche 50-247, 83/02/07, 8302230377

--8302230394 IE Insp Rept 50-247/83-01 on 830103-31 Noncompliance noted housekeeping & cleanliness controls not established in area of component cooling pumps, charging pumps & 78-ft level mezzanine areas
FOLEY, T, KOLYAY, P, KISTER, H Division of Project & Resident Programs 83/02/04 14pp 17246 307 24X Fiche 50-247, 83/02/07, 8302230377

DOCKETED ITEMS

45

8302220007 Ack receipt of 830117 ltr forwarding check in payment of civil penalties proposed in 821216 ltr
AKELRAD, J A Enforcement Staff 83/02/10 HAUSPURG, A
Consolidated Edison Co of New York, Inc 2pp 17233 306 24X
Fiche 50-247, 83/02/10, 8302220007

8302230467 Ack receipt of 830128 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-247/82-23
STAROSTECKI, R Division of Project & Resident Programs 83/02/14
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
17246 036 24X Fiche 50-247, 83/02/14, 8302230467

--8302230498 Responds to NRC 821230 ltr re violations noted in IE Safeguards Insp Rept 50-247/82-23 Corrective actions personnel restructured re two-man rule for access to high radiation area Safeguards info deleted (ref 10CFR73 21)
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/01/28
STAROSTECKI, R Division of Project & Resident Programs 4pp
17246 038 24X Fiche 50-247, 83/02/14, 8302230467

8302230652 Ack receipt of 830113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/82-20
STAROSTECKI, R Division of Project & Resident Programs 83/02/17
O'TOOLE, J D Consolidated Edison Co of New York, Inc 1p
17255 179 24X Fiche 50-247, 83/02/17, 8302230652

--8302230659 Responds to NRC 821129 ltr re violations noted in IE Insp Rept 50-247/82-20 Corrective actions addition of low suction pressure cut-offs for gas stripper feed pumps scheduled for completion by 830331
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/01/13
STAROSTECKI, R Division of Project & Resident Programs 2pp
17255 180 24X Fiche 50-247, 83/02/17, 8302230652

8302280179 Forwards "Steam Generator Exam Program & Results, 1982 Refueling & Maint Outage, Indian Point Unit 2," per Tech Spec 4.13 No filing fees required
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/17
VARQA, S A Operating Reactors Branch 1 1p 17312 194 24X
Fiche 50-247, 83/02/17, 8302280179

--8302280183 "Steam Generator Exam Program & Results, 1982 Refueling & Maint Outage, Indian Point Unit 2"
* Consolidated Edison Co of New York, Inc 82/12/31 41pp
17312 195 24X Fiche 50-247, 83/02/17, 8302280179.

8312060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8312060363

8312060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8312060366

R Periodic operating reports & related correspondence

8302230434 Forwards monthly operating rept for Jan 1983
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/15
MCDOCKALD, W O Management Information Branch 1p 17246 012 24X
Fiche 50-247, 83/02/15, 8302230434

--8302230441 Monthly operating rept for Jan 1983
EICH, E Consolidated Edison Co of New York, Inc 83/02/07 6pp
17246 013 24X Fiche 50-247, 83/02/15, 8302230434

B Reportable occurrences, LERs & related correspondence

8302010446 Forwards LER 82-038/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/10/01
HAYNES, R C Region 1, Office of Director 1p 16974 242 24X
Fiche 50-247, 82/10/01, 8302010446

--8302010449 LER 82-038/03L-0 on 820901, during normal operation, reactor containment fan cooler Unit 24 discovered not operating properly Caused by loose outboard fan bearing resulting in coupling failure Coupling replaced
HINRICHS, G Consolidated Edison Co of New York, Inc. 82/10/01
Region 1, Office of Director 2pp 16974 243 24X
Fiche 50-247, 82/10/01, 8302010446

8302010114 Forwards LER 82-049/99X-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/01/17
HAYNES, R C Region 1, Office of Director 1p 16974 147 24X
Fiche 50-247, 83/01/17, 8302010114

--8302010134 LER 82-049/99X-0 on 821218, during Cycle 5/6 refueling outage, ability of central control room to be totally isolated during accidents questioned because potential air leak paths identified All potential paths sealed
HINRICHS, G Consolidated Edison Co of New York, Inc 83/01/17
Region 1, Office of Director 2pp 16974 148 24X
Fiche 50-247, 83/01/17, 8302010114

8302150268 Forwards LER 82-050/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/01/31
HAYNES, R C Region 1, Office of Director 1p 17148 323 24X
Fiche 50-247, 83/01/31, 8302150268

--8302150278 LER 82-050/03L-0 on 821231, during startup following Cycle 5/6 refueling outage, amount of water in condensate storage tank reduced below Tech Specs Caused by efforts to minimize chloride concentration into steam generators
HINRICHS, G Consolidated Edison Co of New York, Inc 83/01/31
Region 1, Office of Director 2pp 17148 324 24X
Fiche 50-247, 83/01/31, 8302150268

8302030447 PND-1-83-005 on 830128, licensee noted increased seal injection flow to reactor coolant pump 23 Caused by O-ring failure on seal 1 Pump vendor recommended seal replacement
FOLEY, T, BAUNACK, W, GREENMAN, E Region 1, Office of Director
83/02/01 1p 17006 206 24X Fiche 50-247, 83/02/01, 8302030447

8302230468 Forwards LER 83-001/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/02/07
HAYNES, R C Region 1, Office of Director 1p 17246 096 24X
Fiche 50-247, 83/02/07, 8302230468

--8302230479 LER 83-001/03L-0 on 830108, MSIV MS-1-22 for steam generator 22 failed to close during valve closure testing Caused by jamming of valve disc against vertical wall of valve disc stop Vertical wall ground to increase clearance
HINRICHS, G Consolidated Edison Co of New York, Inc 83/02/07
Region 1, Office of Director 2pp 17246 097 24X
Fiche 50-247, 83/02/07, 8302230468

8302250420 RO 83-003 on 830213, RCS leakage from packing on valve 731 exceeded Tech Spec limit Subsequent analysis after hot shutdown determined leakage to be within Tech Specs Also reported per 10CFR21
JACKSON, C W Consolidated Edison Co of New York, Inc 83/02/14
HAYNES, R C Region 1, Office of Director 1p 17298 235 24X
Fiche 50-247, 83/02/14, 8302250420

T Hearing transcripts on non-antitrust matters

8302020424 Unofficial transcript of Commission 830127 affirmation/discussion & vote in Washington, DC re BECY-82-490A Pp 1-3
* Commissioners 83/01/27 5pp 16999 311 24X
Fiche 50-247, 83/01/27, 8302020424

8302010530 Forwards set of tables completing app to licensee testimony of WR Stratton, WA Rodger & TE Potter on Commission Question 1
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates, 83/01/28 OLEASON, J P Atomic Safety and Licensing Board Panel, 1p 16977 125 24X
Fiche 50-247, 83/01/28, 8302010530

--8302010536 Set of tables completing app to licensee testimony of WR Stratton, WA Rodger & TE Potter on Commission Question 1
* Consolidated Edison Co of New York, Inc * Power Authority of the State of New York 83/01/28 6pp 16977 126 24X
Fiche 50-247, 83/01/28, 8302010530

8302030165 Testimony of DM Pisello & RO Piccioni Several possible scenarios illustrating implications of long-term environment contamination following serious reactor accident presented Pro qualifications encl.
PISELLO, D M, PICCIONI, R G Friends of the Earth PISELLO, D M. New York City Audubon Society 83/01/31 29pp. 17008 050 24X
Fiche 50-247, 83/01/31, 8302030165

8302030184 Testimony of C Perrow Nuclear power plant production sys characteristics force inevitable conclusion that serious accidents will occur which design engineers could not anticipate & which operators cannot avoid
PERROW, C Friends of the Earth PERROW, C New York City Audubon Society PERROW, C Yale Univ 83/01/31 15pp 17002 104 24X
Fiche 50-247, 83/01/31, 8302030184

8302030199 Testimony of HJ Geiger & VH Bidel Formulating adequate medical care response to major radiological release impossible since scenario consequences variable Prof qualifications encl.
GEIGER, H J, BIDL, V W Friends of the Earth GEIGER, H J New York City Audubon Society 83/01/31 54pp 17004 233 24X
Fiche 50-247, 83/01/31, 8302030199

DOCKETED ITEMS

8302030210 Testimony of I Levi that methodology in probabilistic safety study for making probabilistic assessments inadequate to justify reposing confidence in Study assessments Prof qualifications encl
LEVI, I Friends of the Earth LEVI, I New York City Audubon Society 83/01/31 53pp 17001 107 24X Fiche 50-247, 83/01/31, 8302030210

8302030539 Forwards corrected pages to 830126 direct testimony of JF Meyer & WT Pratt re Question 1 concerning risk reduction values for filtered vented containment sys & separate containment vent vol
MOORE, J E Hearing Branch 1. 83/02/02 GLEASON, J P, PARIB, D H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17007 155 24X Fiche 50-247, 83/02/02, 8302030539

--8302030546 Corrected testimony of JF Meyer & WT Pratt on Commission Question 1 re risk reduction values for filtered vented containment sys & separate containment vent vol
MEYER, J F, PRATT, W T NRC - No Detailed Affiliation Given 83/02/02 4pp 17007 156 24X Fiche 50-247, 83/02/02, 8302030539

8302090224 Forwards errata to licensee testimony on Commission Question 1, Contention 1.1 & ASLB Question 1.1
BRANDENBURG, B. Consolidated Edison Co of New York, Inc COLARULLI, P F. Power Authority of the State of New York COLARULLI, P F. Morgan Associates 83/02/06 GLEASON, J P, SHON, F J, PARIB, D H Atomic Safety and Licensing Board Panel 1p 17070 276 24X Fiche 50-247, 83/02/06, 8302090224

--8302090230 Errata to licensee testimony on Commission Question 1, Contention 1.1 & ASLB Question 1.1
* Consolidated Edison Co of New York, Inc * Power Authority of the State of New York 83/02/06 3pp 17070 277 24X Fiche 50-247, 83/02/06, 8302090224

8302090272 Testimony of SC Sholly re Commission Question 1 & ASLB Question 1.1 on consequences of accidents at plants
Consequence Model CRACIT & application to calculation of consequences of accidents discussed w/prof qualifications
SHOLLY, S C Union of Concerned Scientists SHOLLY, S C Public Interest Research Group, New York 83/02/07 46pp 17070.048 24X Fiche 50-247, 83/02/07, 8302090272

--8302090279 Testimony of RK Weatherwax on probabilistic safety study
Substantial controversy surrounds completeness & accuracy of study Questions remain re sophisticated procedures used in rept Certificate of Svc encl
WEATHERWAX, R K Union of Concerned Scientists WEATHERWAX, R K Public Interest Research Group, New York 83/02/07 24pp 17070 094 24X Fiche 50-247, 83/02/07, 8302090272

8302100215 Transcript of 830208 hearing in White Plains, NY Pp 6, 941-7, 161 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/08 419pp 17115 130 24X Fiche 50-247, 83/02/08, 8302100215

8302140077 Transcript of 830209 hearing in White Plains, NY Pp 7, 162-7, 478 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/09 390pp 17142 172 24X Fiche 50-247, 83/02/09, 8302140077

8302150705 Transcript of 830210 hearing in White Plains, NY Pp 7, 479-7, 709 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/10. 355pp 17152 021 24X Fiche 50-247, 83/02/10, 8302150705

8302170277 Forwards errata to licensee testimony of TE Potter on ASLB Question 1.3
BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F. Power Authority of the State of New York. COLARULLI, P F. Morgan Associates 83/02/10 GLEASON, J P, SHON, F J, PARIB, D H Atomic Safety and Licensing Board Panel 1p 17178-215 24X Fiche 50-247, 83/02/10, 8302170277

8302170280 Errata to licensee testimony of TE Potter on ASLB Question 1.3
POTTER, T E Consolidated Edison Co of New York, Inc POTTER, T E Power Authority of the State of New York. 83/02/10 2pp 17178.216 24X Fiche 50-247, 83/02/10, 8302170277

8302150294 Transcript of 830211 hearing in White Plains, NY Pp 7, 710-898 Supporting documentation encl.
Atomic Safety and Licensing Board Panel 83/02/11 261pp 149 001. 24X Fiche 50-247, 83/02/11, 8302150294

170260 Forwards errata to licensee testimony of WR Stratton, Rodger & TE Potter re Question 1
BRANDENBURG, B. Consolidated Edison Co of New York, Inc COLARULLI, P F. Power Authority of the State of New York. COLARULLI, P F. Morgan Associates 83/02/14 GLEASON, J P, SHON, F J, PARIB, D H Atomic Safety and Licensing Board Panel 1p 17187 092 24X Fiche 50-247, 83/02/14, 8302170260

--8302170268 Errata to licensee testimony of WR Stratton, WA Rodger & TE Potter re Question 1
STRATTON, W R, RODGER, W A, POTTER, T E Consolidated Edison Co of New York, Inc 83/02/14 1p 17187 093 24X Fiche 50-247, 83/02/14, 8302170260

8302170283 Forwards errata to util testimony of RL DuPont on Commission Question 1
COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/14 GLEASON, J P, SHON, F J, PARIB, D H Atomic Safety and Licensing Board Panel 1p 17185 148 24X Fiche 50-247, 83/02/14, 8302170283

--8302170287 Errata to util testimony of RL DuPont on Commission Question 1
DUPONT, R L Power Authority of the State of New York 83/02/14 1p 17185 149 24X Fiche 50-247, 83/02/14, 8302170283

8302180381 Supplemental testimony of P Helbraun re ability of preschools to transport staff & children to designated areas Evacuation plan does not deal w/problem Related correspondence
HELBRAUN, P Rockland Citizens for Safe Energy 83/02/14 2pp 17209 180 24X Fiche 50-247, 83/02/14, 8302180381

--8302180384 Supplemental testimony of A Gromack re recreational program within 10-mile emergency planning zone Certificate of Svc encl Related correspondence
GROMACK, A Rockland Citizens for Safe Energy 83/02/14 6pp 17209 182 24X Fiche 50-247, 83/02/14, 8302180381

8302170157 Transcript of 830215 hearing in White Plains, NY Pp 7, 899-8, 172 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/15 327pp 17180 316 24X Fiche 50-247, 83/02/15, 8302170157

8302180240 Transcript of 830216 hearing in White Plains, NY Pp 8, 173-8, 461 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/16 512pp 17212 102 24X Fiche 50-247, 83/02/16, 8302180240

8302220241 Transcript of 830217 hearing in White Plains, NY Pp 8, 462-8, 689 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/17 565pp 17230 159 24X Fiche 50-247, 83/02/17, 8302220241

8302230471 Forwards supplemental testimony of NY State witnesses on Commission Questions 3 & 4 re emergency planning Related correspondence
FEINBERG, J D New York, State of 83/02/18 GLEASON, J P, PARIB, D H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17246 081 24X Fiche 50-247, 83/02/18, 8302230471

--8302230477 Testimony of DB Davidoff & LB Crech on Commission Questions 3 & 4 re emergency planning Related correspondence
DAVIDOFF, D B, CRECH, L B New York, State of 83/02/21 14pp 17246 082 24X Fiche 50-247, 83/02/18, 8302230471

8302230683 Transcript of 830218 hearing in White Plains, NY Pp 8, 689-8, 922 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/18 380pp 17258 221 24X Fiche 50-247, 83/02/18, 8302230683

8302280377 Forwards NRC & FEMA supplemental testimony on Commission Questions 3 & 4 Certificate of Svc encl
HASSELL, D F Hearing Branch 1 83/02/18 Atomic Safety and Licensing Board Panel 5pp 17309 231 24X Fiche 50-247, 83/02/18, 8302280377

--8302280380 Supplemental testimony of JR Sears re Commission Question 3
Open items do not change conclusion that emergency plans & procedures form adequate basis for onsite preparedness
SEARS, J R EP Licensing Branch 83/02/18 4pp 17309 256 24X Fiche 50-247, 83/02/18, 8302280377

--8302280384 Forwards FEMA supplemental testimony on Commission Questions 3 & 4
HASSELL, D F Federal Emergency Management Agency 83/02/14, HASSELL, D F Hearing Branch 2 1p 17309 260 24X Fiche 50-247, 83/02/18, 8302280377

--8302280390 Supplemental testimony of P McIntire, R Kowieski & JH Keller re Commission Questions 3 & 4 Transmits rept on status of plan revs, equipment purchases & training re significant deficiencies in five planning stds identified in Jul 1982
MCINTIRE, P, KOWIESKI, R, KELLER, J H Federal Emergency Management Agency. 83/02/14 99pp 17309 261 24X Fiche 50-247, 83/02/18, 8302280377

DOCKETED ITEMS

47

- 8302240320 Supplemental testimony of LA Cohen, CH Jackson, O Liebler & WA Monti re onsite emergency planning Discusses recent enhancements to alert/notification & backup communication sys Certificate of Svc encl Related correspondence COHEN, L A, JACKSON, C W, LIEBLER, O Consolidated Edison Co of New York, Inc 83/02/22 9pp 17274 001 24X Fiche 50-247, 83/02/22, 8302240320
- 8302250372 Motion for preservation & production of certain documents re 830309 emergency exercise Record essential to give accurate picture of any exercise evaluation results HOLT, J Public Interest Research Group, New York 83/02/22 Atomic Safety and Licensing Board Panel 3pp 17297 048 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250387 Forwards R Seasonwein testimony on Commission Question 3 re emergency planning BRODSKY, R L New York, State of 83/02/21 GLEASON, J P, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17297 055 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250392 Testimony of R Seasonwein on Commission Question 3 re emergency planning Large portion of population will comply if ordered to stay in homes during emergency Chaos could prevail if evacuation ordered SEASONWEIN, R New York, State of 83/02/21 24pp 17297 056 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250396 Supplemental testimony of SW Anderson re considerations for planning evacuation of handicapped persons Accessible bus survey encl ANDERSON, S W Union of Concerned Scientists ANDERSON, S W Public Interest Research Group, New York ANDERSON, S W Westchester Peoples Action Coalition, Inc 83/02/21 10pp 17297 074 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250399 Testimony of C Awalt re evacuation of mentally retarded patients in homes Neither of or homes contacted re emergency planning for nuclear accident AWALT, C Parents Concerned About Indian Point AWALT, C Westchester Peoples Action Coalition, Inc 83/02/18 2pp 17297 084 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250405 Supplemental testimony of KT Erikson re emergency studies Emergency plans inadequate unless number of people who will overreact & number of emergency personnel who will not report to duty are taken into account ERIKSON, K T Parents Concerned About Indian Point ERIKSON, K T Union of Concerned Scientists ERIKSON, K T Public Interest Research Group, New York 83/02/21 4pp 17297 086 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250410 Testimony of S Hall Transport Workers Union has not been involved in any evacuation plan HALL, S Parents Concerned About Indian Point HALL, S Union of Concerned Scientists HALL, S Public Interest Research Group, New York 83/02/17 1p 17297 090 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250416 Testimony of JF Rodan re inadequacy of procedures re Westchester portion of 10-mile evacuation area & personnel Use Roads cannot handle traffic Parents will not cooperate w/evacuation of children RODAN, J F Parents Concerned About Indian Point 83/02/17 5pp 17297 091 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250419 Testimony of A Cormican re evacuation of school children. Evacuation plan should be rejected CORMICAN, A Parents Concerned About Indian Point, 83/02/17. 6pp 17297 096 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250425 Testimony of J Murphy Present emergency planning seriously deficient because plan does not prepare for exposure levels exceeding 100 rems or for internal contamination Certificate of Svc encl MURPHY, J Union of Concerned Scientists MURPHY, J Public Interest Research Group, New York 83/02/21 93pp 17297 102, 24X Fiche: 50-247, 83/02/22, 8302250372
- 8302280168 Supplemental testimony of MS Della Rocca, BE Podwal & PL Rosenblatt re emergency planning Relationship of plan to existing procedures & facilities, communication w/officials & evacuation routes discussed W/Certificate of Svc DELIA ROCCA, M., PODWAL, B E, ROSENBLATT, P L Consolidated Edison Co of New York, Inc. 83/02/22 24pp 17306, 008 24X Fiche: 50-247, 83/02/22, 8302280168
- 8302250235 Forwards corrected 830125 testimony of WH Spataro, Pp 6, 551-53 & 6, 559. LEVINE, J J Morgan Associates, LEVINE, J J Power Authority of the State of New York 83/02/23 GLEASON, J P, SHON, F J, PARRIS, D H Atomic Safety and Licensing Board Panel 1p, 17292.342 24X Fiche 50-247, 83/02/23, 8302250235
- 8302280240 Corrected 830125 testimony of WH Spataro, Pp 6, 551-53 & 6, 559 SPATARO, W H Power Authority of the State of New York 83/02/23 4pp 17292 343 24X Fiche 50-247, 83/02/23, 8302250235
- 8302280093 Transcript of 830224 telephone conference in Washington, DC Pp 8, 923-8, 958 * Atomic Safety and Licensing Board Panel 83/02/24 39pp 17307 138 24X Fiche 50-247, 83/02/24, 8302280093
- 8302280249 Transcript of 830224 telephone conference in Washington, DC Pp 8, 923-8, 958 * Atomic Safety and Licensing Board Panel 83/02/24. 36pp 17304 276 24X Fiche 50-247, 83/02/24, 8302280249
- U Congressional/Executive Correspondence
- 8302020283 Comments on NUREG-0880 re NRC policy statement on safety goals Commission should explain basis for CLI-82-38 assumption that plant poses no undue risk to public health & safety even though plant does not meet safety goal OTINGER, R L House of Rep 83/01/19 FALLADIO, N J Commissioners 2pp 16993 318 24X Fiche 50-247, 83/01/19, 8302020283
- V Operator Examinations
- 8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp, 17347 177 24X Fiche 50-000, 83/01/31, 8301310203
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3
- B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365
- F Security, medical, emergency & fire protection plans
- 8302040033 Releases public version of revised emergency plan Implementing procedures FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033
- 8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCB programs PAJOWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC - No Detailed Affiliation Given 1p 17043 231 24X Fiche 50-000, 83/01/27, 8302040033
- 8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCB programs Revised index encl LITERSKI, L A, PAJOWSKI, J E, Commonwealth Edison Co. 83/01/06, 11pp 17043 232 24X Fiche: 50-000, 83/01/27, 8302040033.
- 8302020458 Releases public version of revised Emergency Plan Implementing Procedure FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 16999, 288 24X Fiche: 50-010, 83/01/31, 8302020458.
- 8302020470 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 100-C11, "Environ Director (Checklist of Initial Generating Station Emergency Plan Responsibilities) " Receipt form encl SCOTT, D J Commonwealth Edison Co 83/01/07 DENTON, H R, Office of Nuclear Reactor Regulation, Director 3pp 16999:289 24X Fiche 50-010, 83/01/31, 8302020458
- 8302020479 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 100-C11, "Environ Director (Checklist of Initial Generating Station Emergency Plan Responsibilities) " * Commonwealth Edison Co 83/01/03 6pp 16999 292, 24X Fiche 50-010, 83/01/31, 8302020458

DOCKETED ITEMS

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for CL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080191 Forwards safety evaluation & exemption from requirements of Section III Q 3 of App R to 10CFR50 re fire protection for safe shutdown capability, per util 820701 request
CRUTCHFIELD, B Operating Reactors Branch 5 83/02/02 DELGROE, I
Commonwealth Edison Co 3pp 17058 141 24X Fiche 50-237,
83/02/02, 8302080191

--8302080194 Exemption from requirements of Section III Q 3 of App R to 10CFR50 re installation of fire detection sys & fixed fire suppression sys in area, room or zone for which alternative safe shutdown capability provided
EISENHUT, D O Division of Licensing 83/02/02 Commonwealth Edison Co 4pp 17058 144 24X Fiche 50-237, 83/02/02, 8302080191

--8302080197 Safety evaluation supporting exemption from requirements of Section III Q 3 of App R to 10CFR50 re fire protection of safe shutdown capability.
* Office of Nuclear Reactor Regulation, Director 83/02/02 9pp
17058 148 24X Fiche 50-237, 83/02/02, 8302080191

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-111B guidelines valid
KEPPLER, J O Region 3, Office of Director 83/02/04 REED, C
Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302250358 Forwards IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/08 REED, C Commonwealth Edison Co 2pp
17291, 154 24X Fiche 50-010, 83/02/08, 8302250358

--8302250364 IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted Major areas inspected emergency preparedness program, licensee actions on previously identified items & emergency plan
PHILLIPS, M P Division of Emergency Preparedness & Operational Support 83/02/03 16pp 17291 156 24X Fiche 50-010, 83/02/08, 8302250358

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X
Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager"
NELLIS, C A, FLEISSNER, R A Commonwealth Edison Co. 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

180494 Releases public version of revised emergency plan implementing procedure
TOM, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17221 323 24X Fiche 50-010, 83/02/15, 180494

82180498 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-7, "Personnel Decontamination (Medical - Decontamination Area) (Primary Responsibility - Rad/Chem Director)"
SCOTT, D J Commonwealth Edison Co 83/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17221 324 24X
Fiche 50-010, 83/02/15, 8302180494

--8302180508 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-7, "Personnel Decontamination (Medical - Decontamination Area) (Primary Responsibility - Rad/Chem Director)" Revised index encl
* Commonwealth Edison Co 83/01/12 12pp 17221 327 24X
Fiche 50-010, 83/02/15, 8302180494

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp
17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities Lists of locations encl
SWARTZ, E D Commonwealth Edison Co 83/01/28 KEPPLER, J O Region 3, Office of Director 4pp 17291 074 24X
Fiche 50-000, 83/02/18, 8302250349

P. Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
HANNON, J H NRC - No Detailed Affiliation Given 82/01/27
VAROAS, S NRC - No Detailed Affiliation Given 10pp 17196 225 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

8302010429 Forwards "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plants Drywell Temp Analysis" Analysis fulfills NRC request for info re equipment qualification temp profiles inside containment
RAUSCH, T J Commonwealth Edison Co 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16974 180 24X
Fiche 50-000, 83/01/25, 8302010429

--8302010434 "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plant Drywell Temp Analysis"
HODAKO, H, ROGERS, A E General Electric Co NSEO-82-0682
82/11/30 13pp 16974 182 24X Fiche 50-000, 83/01/25, 8302010429

8302070274 Suppl 821019 ltr re justification for continued operation for SCAM resistance temp detectors in reactor water cleanup rooms, per 821229 & 830118 SERs for environ qualification of electrical equipment program
RAUSCH, T J Commonwealth Edison Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17031 116 24X
Fiche 50-000, 83/02/01, 8302070274

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - OPU Service Corp 3pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302100224 Forwards description, basis & justification for each setpoint chosen for reactor protection sys power monitoring sys, per 820723 ltr Proposed Tech Specs will be submitted by 830415
RAUSCH, T J Commonwealth Edison Co 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 17115 116 24X
Fiche 50-000, 83/02/04, 8302100224

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for CL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 4pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 7pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302220330 Discusses schedule for util response re environ qualification of electrical equipment proprietary info Manufacturers contacted on timely response Status of final reporting will be provided by 830315
RYBAK, B Commonwealth Edison Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17230 091 24X Fiche 50-000, 83/02/14, 8302220330

8302230125 Ack receipt of 830111 ltr re qualifications of radiochemistry supervisory staff per ANSI Std N18.1-1971 T Gilman qualified as lead chemist & McDonald will attend class to qualify as lead health physicist
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/16 SCOTT, D J Commonwealth Edison Co 2pp, 17257 007 24X Fiche 50-010, 83/02/16, 8302230125

--8302230130 Responds to NRC request to document basis for qualifications of radiochemistry staff per ANSI Std N18.1-1971 Lead chemist need not meet 2-yr experience requirement
SCOTT, D J Commonwealth Edison Co 83/01/11 GREOR, R L Region 3, Office of Director 5pp 17257 009 24X Fiche 50-010, 83/02/16, 8302230130

8302250189 Application for amends to Licensee DPR-19 & DPR-25, incorporating multiple changes to Tech Specs re administrative controls
RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17293 007 24X Fiche 50-237, 83/02/17, 8302250189

--8302250192 Proposed Tech Spec changes re administrative controls
* Commonwealth Edison Co 83/02/17 24pp 17293 010 24X Fiche 50-237, 83/02/17, 8302250192

8302250212 Application for amend to Licensee DPR-29 & DPR-30, revising Tech Specs to incorporate changes to corporate & station organizations
RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17293 082 24X Fiche 50-237, 83/02/17, 8302250212

--8302250218 Proposed Tech Specs re administrative controls
* Commonwealth Edison Co 83/02/17 17pp 17293 085 24X Fiche 50-237, 83/02/17, 8302250218

8302260152 Advises that review of 830121 final rule on environ qualification of safety-related electrical equipment incomplete Determination whether to reaffirm or withdraw hearing request will be provided by 830324
STEPHENS, P P Isham, Lincoln & Beale 83/02/23 EISENHUT, D O Division of Licensing 1p 17306 076 24X Fiche 50-000, 83/02/23, 8302260152

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR.
FELTON, J M Division of Rules and Records. 82/12/30. HIATT, B L Ohio Citizens for Responsible Energy 3pp 17045:144 24X Fiche 50-000, 82/12/30, 8302040039.

--8302040332 Forwards 1991 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L. Region 3, Office of Director 82/07/08
KEPPLER, J O. Region 3, Office of Director. 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040332

8302160014 Summary of 830120 meeting w/utis, Bechtel, Franklin Research Ctr URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted.
TRAMELL, C. M. Operating Reactors Branch 3 83/01/23 Operating Reactors Branch 3. 25pp, 17171:227 24X Fiche 50-000, 83/01/23, 8302160014.

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiterque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people.
SPERSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302040294 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-16, 50-237/82-23 & 50-249/82-23
NORELIUS, C E Division of Project & Resident Programs 83/02/01. REED, C Commonwealth Edison Co 1p 17017 347 24X Fiche 50-010, 83/02/01, 8302040294

--8302040302 Responds to NRC 821222 ltr re violations noted in IE Insp Repts 50-010/82-16, 50-237/82-23 & 50-249/82-23 Corrective actions new computer installation & removal of computer console at station operator desk scheduled for Spring 1983
DELGEORGE, L O Commonwealth Edison Co 83/01/21 KEPPLER, J O Region 3, Office of Director 2pp 17017 348 24X Fiche 50-010, 83/02/01, 8302040294

8302080277 Submits updated installation status rept of safe shutdown path supports, per IE Bulletin 79-14 All remaining hangers will be installed by 831231, w/exception of Quad Cities safety relief valve line
RAUSCH, T J Commonwealth Edison Co 83/02/01 KEPPLER, J O Region 3, Office of Director 4pp 17056 337 24X Fiche 50-000, 83/02/01, 8302080277

8302150503 Ack receipt of 830114 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-249/82-28.
NORELIUS, C E. Division of Engineering 83/02/08 REED, C. Commonwealth Edison Co 1p 17157 116. 24X Fiche 50-249, 83/02/08, 8302150503.

--8302150516 Responds to NRC 821217 ltr re violations noted in IE Insp Rept 50-249/82-28 Safeguard existed to prevent use of SUBCPT2 because of requirement to use DTS 8080 to approve new computer program or revs to existing programs.
DELGEORGE, L O Commonwealth Edison Co 83/01/14 KEPPLER, J. O. Region 3, Office of Director. 3pp 17157:117 24X Fiche 50-249, 83/02/08, 8302150503

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin B1-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels."
SHWARTZ, E D Commonwealth Edison Co 83/02/08, DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp 17156 215 24X Fiche 50-000, 83/02/08, 8302150528

8302250358 Forwards IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/08 REED, C. Commonwealth Edison Co 2pp 17291 154 24X Fiche 50-010, 83/02/08, 8302250358

--8302250364 IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830103-07 No noncompliance noted. Major areas inspected: emergency preparedness program; licensee actions on previously identified items & emergency plan
PHILLIPS, M P, PLOSKI, T J, SNELL, W O. Division of Emergency Preparedness & Operational Support 83/02/03. 16pp. 17291 156. 24X Fiche 50-010, 83/02/08, 8302250358

8302150587 EN-83-008: on 830216, notices of violation & proposed imposition of civil penalties in amount of \$120,000 will be issued. Action based on lack of controls over distribution of safety list & failure to maintain containment integrity
BARBER, G, AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/02/11. 2pp 17156:117 24X Fiche 50-000, 83/02/11, 8302150587

DOCKETED ITEMS

8302280426 Forwards IE Insp Repts 50-237/82-30 & 50-249/82-31 on 821206-07, 14-17, 830103-05 & 07 & notice of violation
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/14 REED, C Commonwealth Edison Co 2pp
17307 329 24X Fiche 50-237, 83/02/14, 8302280426

--8302280430 Notice of violation from insp on 821206-07, 14-17, 830103-05 & 07
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/14 1p 17307 331 24X Fiche 50-237, 83/02/14, 8302280426

--8302280438 IE Insp Repts 50-237/82-30 & 50-249/82-31 on 821206-07, 14-17, 830103-05 & 07 Noncompliance noted failure to prevent transfer of contaminated matl from controlled to uncontrolled area
PAUL, R A, GRANT, W B, GREGOR, L R Region 3, Office of Director 83/02/14 14pp 17307 332 24X Fiche 50-237, 83/02/14, 8302280426

8302180491 Discusses IE insp on 820816-1103 & forwards notice of violation & proposed imposition of civil penalty
KEPPLER, J O Region 3, Office of Director 83/02/16 O'CONNOR, J J Commonwealth Edison Co 4pp 17214 127 24X Fiche 50-000, 83/02/16, 8302180491

--8302180496 Notice of violation & proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted weakness in QA program including lack of controls over distribution of safety classification list
KEPPLER, J O Region 3, Office of Director 83/02/16 3pp 17214 131, 24X Fiche 50-000, 83/02/16, 8302180491

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347-191 24X Fiche 50-000, 83/02/18, 8212060363

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361-148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150600 Forwards monthly operating repts for Jan 1983
SCOTT, D J Commonwealth Edison Co 83/02/01 Director's Office, Office of Inspection and Enforcement 1p 17155 347 24X Fiche 50-237, 83/02/01, 8302150600

--8302150606 Monthly operating repts for Jan 1983
SCHROEDER, B A Commonwealth Edison Co 83/02/01 13pp 17155 348 24X Fiche 50-237, 83/02/01, 8302150600

Reportable occurrences, LERs & related correspondence

8302080353 Forwards LER 83-001/03L-0
SCOTT, D J Commonwealth Edison Co 83/02/01 KEPPLER, J O Region 3, Office of Director 1p 17057 213 24X Fiche 50-249, 83/02/01, 8302080353

--8302080359 LER 83-001/03L-0 on 830104, source range monitor 24 high rod block found in excess of Tech Spec Caused by setpoint drift
Monitor readjusted & returned to svc
BEVERLY, K Commonwealth Edison Co 83/02/01 Region 3, Office of Director 1p 17057:214 24X Fiche 50-249, 83/02/01, 8302080353

8302080344 Forwards LER 83-003/03L-0
SCOTT, D J Commonwealth Edison Co 83/02/02 KEPPLER, J O Region 3, Office of Director 1p 17057 215 24X Fiche 50-249, 83/02/02, 1302080344

1302080356 LER 83-003/03L-0 on 830105, pinhole leak found on connecting pipe weld between 3-1201-10 inch A & 3-1292-2 inch A line
Cause undetermined Leak will be repaired during next outage of sufficient length
RHEE, S Commonwealth Edison Co 83/02/02 Region 3, Office of Director 1p 17057:216 24X Fiche 50-249, 83/02/02, 8302080344

02280518 Forwards LER 83-006/01T-0
SCOTT, D J Commonwealth Edison Co 83/02/18 KEPPLER, J O Region 3, Office of Director 1p 17309.043 24X Fiche 50-249, 83/02/18, 302280518

--8302280524 LER 83-006/01T-0 on 830208, LPCI pump suction valve MO3-1501-50 failed open Caused by auxiliary contact CR 105X failure in control circuitry of valve Contact replaced
COYLE, L Commonwealth Edison Co 83/02/18 Region 3, Office of Director 1p 17309 044 24X Fiche 50-249, 83/02/18, 8302280518

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8302010643 Requests postponement until 830215 of response dates to NRC fire protection draft safety evaluation ltrs Addl time needed to explore other response alternatives
UHRIO, R E Florida Power & Light Co 83/01/27 VOLLMER, R H Division of Engineering 1p 16980 063 24X Fiche 50-000, 83/01/27, 8302010643

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302070528 Application for amend to Licenses DPR-31 & DPR-41, proposing changes to Tech Spec P 6-12 re emergency & security plan audits per 10CFR50 54(t) & 10CFR73 40(d) as requested by Generic Ltrs 82-17 & 82-23, respectively
UHRIO, R E Florida Power & Light Co 83/02/01 EISENHUT, D O Division of Licensing 1p 17036 014 24X Fiche 50-250, 83/02/01, 8302070528

--8302070534 Proposed Tech Spec Page 6-12 re emergency & security plan audits
+ Florida Power & Light Co 83/02/01 1p 17036 015 24X Fiche 50-250, 83/02/01, 8302070528

8302180437 Requests extension until 830301 of response dates to NRC 830106 & 14 ltrs re fire protection draft safety evaluation
UHRIO, R E Florida Power & Light Co 83/02/15 EISENHUT, D O Division of Licensing 1p 17215 018 24X Fiche 50-000, 83/02/15, 8302180437

8302240216 Advises that extension to 830301 for response to draft safety evaluation of App R fire protection exemption requests acceptable per 830215 ltr
EISENHUT, D O Division of Licensing 83/02/18 UHRIO, R E Florida Power & Light Co 2pp 17288 239 24X Fiche 50-000, 83/02/18, 8302240216

P Operating license stage documents & correspondence

8302080100 Addl response to FOIA request for records re steam generators & steam turbines Forwards documents listed under Category A of App E Category B documents available in PDR
FELTON, J M Division of Rules and Records 82/12/17 LONG, D J Winthrop, Stimson, Putnam & Roberts 5pp 17105 069 24X Fiche 50-000, 82/12/17, 8302080100

--8302080127 Forwards request for addl info re steam generator tube integrity Questions specifically address tubes in U-bend region
EISENHUT, D O Division of Operating Reactors 76/12/14 GOLLER, K R Assistant Director for Operating Reactor Projects (Pre 791030) 6pp 17103 145 24X Fiche 50-000, 82/12/17, 8302080100

8302010606 Submits update to NUREG-0737, Items II B 3, "Post-Accident Sampling Sys," II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication" & II F 1, "Addl Accident Monitoring Instrumentation "
UHRIO, R E Florida Power & Light Co 83/01/28 VAROA, S A Operating Reactors Branch 1 2pp 16978 181 24X Fiche 50-250, 83/01/28, 8302010606

8302080355 Forwards corrected page to Amends 91 & 85 to Licenses DPR-31 & DPR-41, respectively
MCDONALD, D O Operating Reactors Branch 1 83/01/31 UHRIO, R E Florida Power & Light Co 2pp 17107 079 24X Fiche 50-250, 83/01/31, 8302080355

DOCKETED ITEMS

51

- 8302080357 Corrected P 2 to Amends 91 & 85 to Licenses DPR-31 & DPR-41, respectively re disposal of high level radwaste & spent fuel
VARGA, S A Operating Reactors Branch 1 83/01/31 2pp
17107 081 24X Fiche 50-250, 83/01/31, 8302080355
- 8302090518 Summary of 830126 meeting w/utl in Bethesda, MD re licensee screening criterion for pressurized thermal shock program
McDONALD, D O Operating Reactors Branch 1 83/01/31 Operating Reactors Branch 1 34pp 17117 278 24X Fiche 50-250, 83/01/31, 8302090518
- 8302070472 Provides justification for continued operation & qualification info for safety evaluation Category II A Items 35, 39 & 101, in response to NRC 821213 ltr re environ qualification of safety-related equipment Withheld
UHRIO, R E Florida Power & Light Co 83/02/01 VARGA, S A Operating Reactors Branch 1 2pp 17029 001 24X Fiche 50-250, 83/02/01, 8302070472
- 8302070528 Application for amend to Licenses DPR-31 & DPR-41, proposing changes to Tech Spec P 6-12 re emergency & security plan audits per 10CFR50 54(t) & 10CFR73 40(d) as requested by Generic Ltrs 82-17 & 82-23, respectively
UHRIO, R E Florida Power & Light Co 83/02/01 EISENHUT, D O Division of Licensing 1p 17036 014 24X Fiche 50-250, 83/02/01, 8302070528
- 8302070534 Proposed Tech Spec Page 6-12 re emergency & security plan audits
* Florida Power & Light Co 83/02/01 1p 17036 015 24X Fiche 50-250, 83/02/01, 8302070528
- 8302080106 Informs that debris screens on purge supply & exhaust valves will be installed during next refueling outage
Commitment meets SRP Section 6 & 4, Rev 1 & Branch Technical Position CBB 6-4, Rev 1 requirements
VARGA, S A Operating Reactors Branch 1 83/02/01 UHRIO, R E Florida Power & Light Co 2pp 17106 013 24X Fiche 50-250, 83/02/01, 8302080106
- 8302170432 Requests submittal, within 60 days, describing flux reduction measures initiated & addl measures being considered per pressurized thermal shock studies
VARGA, S A Operating Reactors Branch 1 83/02/01 UHRIO, R E Florida Power & Light Co 5pp 17205 149 24X Fiche 50-250, 83/02/01, 8302170432
- 8302070444 Requests exemption from 10CFR50 71(e)(3)(i) scheduler requirement to file annual FSAR rev by 830722 Proposed filing date of 831122 would facilitate FSAR update, reflecting more as-built configuration
UHRIO, R E Florida Power & Light Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17036 301 24X Fiche 50-250, 83/02/02, 8302070444
- 8302070305 Advises that arrangements made for consultant to perform new analysis per NUREG-0744, Rev 1, Generic Ltr 82-26, "Pressure Vessel Matl Fracture Toughness," to confirm previous conclusions re shelf energy Results expected by Aug 1983
UHRIO, R E Florida Power & Light Co 83/02/03 EISENHUT, D O Division of Licensing 1p 17029 124 24X Fiche 50-250, 83/02/03, 8302070305
- 8302070577 Forwards Class I & III fees for proposed license amend per NUREG-0737 Tech Specs
UHRIO, R E Florida Power & Light Co 83/02/03 MILLER, W O License Fee Management Branch 1p 17034 223 24X Fiche 50-250, 83/02/03, 8302070577
- 8302080295 Generic Ltr 83-09 to all operating reactor licensees; applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295
- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche: 50-000, 83/02/08, 8302080304
- 8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085
- 8302150479 Provides info re TMI Action Items II B, 3, "Post-Accident Sampling Sys" & II F 1 1 & II F 1 2, "Noble Gas Monitors/Iodine Particulate Sampling," per NRC request
UHRIO, R E Florida Power & Light Co 83/02/10 VARGA, S A Operating Reactors Branch 1 2pp 17157 088 24X Fiche 50-250, 83/02/10, 8302150479
- 8302150497 Application to amend Licenses DPR-31 & DPR-41, deleting App B ETS re aquatic monitoring & surveillance requirements & groundwater monitoring program Request for deletion of terrestrial biological monitoring programs will be provided
UHRIO, R E Florida Power & Light Co 83/02/10 EISENHUT, D O Division of Licensing 2pp 17156 324 24X Fiche 50-250, 83/02/10, 8302150497
- 8302240137 Requests info re any change in scheduler commitments for installation of debris screens pending resolution of operability concerns per long-term review of containment purge & vent valves Assessment of valve operability encl
VARGA, S A Operating Reactors Branch 1 83/02/10 UHRIO, R E Florida Power & Light Co 8pp 17268 295 24X Fiche 50-250, 83/02/10, 8302240137
- 8302180483 Forwards addl info on Guideline 4, "Special Lifting Devices" & Guideline 7, "Crane Design," per draft technical evaluation rept on control of heavy loads at facilities
UHRIO, R E Florida Power & Light Co 83/02/11 VARGA, S A Operating Reactors Branch 1 2pp 17210 361 24X Fiche 50-250, 83/02/11, 8302180483
- 8302230198 Submits addl info re ECCS valve position per 830104 ltr Plant change/mod package providing single continuous position indication for valves will be prepared
Implementation schedule for changes will be provided
UHRIO, R E Florida Power & Light Co 83/02/15 VARGA, S A Operating Reactors Branch 1 1p 17245 117 24X Fiche 50-250, 83/02/15, 8302230198
- 8302230145 Lists specific ETS covered by 830210 request for deletion of aquatic chemical, thermal & biotic monitoring requirements
UHRIO, R E Florida Power & Light Co 83/02/16 EISENHUT, D O Division of Licensing 1p 17243 223 24X Fiche 50-250, 83/02/16, 8302230145
- 0 Inspection reports, IE Bulletins & correspondence
- 8302160014 Summary of 830120 meeting w/utl, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 23pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014
- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360
- 8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361
- 8302150430 Ack receipt of 830121 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/82-39 & 50-251/82-39
DANCE, H C Division of Project & Resident Programs 83/02/09, UHRIO, R E Florida Power & Light Co 1p, 17148 132 24X Fiche 50-250, 83/02/09, 8302150430
- 8302150436 Responds to NRC 821222 ltr re violation noted in IE Insp Repts 50-250/82-39 & 50-251/82-39 Corrective actions: east entrance to auxiliary bldg, air conditioning duct opening & vehicle access gates posted correctly
UHRIO, R E Florida Power & Light Co 83/01/21 O'REILLY, J P Region 2, Office of Director 2pp 17148 133 24X Fiche 50-250, 83/02/09, 8302150436
- 8302150440 Forwards IE Insp Repts 50-250/82-39 & 50-251/82-39 on 821129-1203 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/12/22 UHRIO, R E Florida Power & Light Co 2pp 17148 135 24X Fiche 50-250, 83/02/09, 8302150440

DOCKETED ITEMS

--8302130448 Notice of violation from insp on 821129-1203
 * Division of Project & Resident Programs 82/12/22 1p
 17148 137 24X Fiche 50-250, 83/02/09, 8302150430

--8302150458 IE Insp Repts 50-250/82-39 & 50-251/82-39 on 821129-1203
 Noncompliance noted accessible areas in auxiliary bldg where
 radiation levels exceeded 5 m/h not posted
 HOSEY, C M, BARR, K P Division of Engineering & Radiological
 Safety Programs 82/12/20 6pp 17148 138 24X
 Fiche 50-250, 83/02/09, 8302150430

8302160205 Responds to IE Bulletin 82-04, "Deficiencies in Primary
 Containment Electrical Penetration Assemblies " Review of
 containment penetrations indicates no Bunker-Ramo electrical
 penetrations installed
 UHRIG, R E Florida Power & Light Co 83/02/09 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement 2pp
 17145 047 24X Fiche 50-250, 83/02/09, 8302160205

8302160241 Responds to IE Bulletin 82-04 re deficiencies in containment
 electrical penetration assemblies Bunker-Ramo electrical
 penetrations not in use at facility
 UHRIG, R E Florida Power & Light Co 83/02/10 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement 2pp
 17170 212 24X Fiche 50-250, 83/02/10, 8302160241

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/02/18 Consolidated Edison Co of New
 York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
 Very Low Level Radwaste - 10CFR20.302 " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/02/24 Consolidated Edison Co of New
 York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/02/24 Consolidated Edison Co of New
 York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302010118 Forwards LER 82-019/03L-0
 WILLIAMS, J W Florida Power & Light Co 83/01/21 O'REILLY, J P
 Region 2, Office of Director 1p 16974 150 24X
 Fiche 50-250, 83/01/21, 8302010118

--8302010130 LER 82-019/03L-0 on 821223, while performing full length rod
 control cluster periodic exercise, rod control cluster J3 of
 shutdown bank A failed to show proper movement Cause
 unknown Cluster performed normally during rod exercise
 BERRY, Z E Florida Power & Light Co 83/01/21 Region 2,
 Office of Director 1p 16974 151 24X Fiche 50-250, 83/01/21,
 8302010118

8302150063 Forwards LER 83-001/03L-0
 WILLIAMS, J W Florida Power & Light Co 83/02/07 O'REILLY, J P
 Region 2, Office of Director 1p 17147-007 24X
 Fiche 50-250, 83/02/07, 8302150063

--8302150070 LER 83-001/03L-0 on 830107, insp of leak revealed cracked
 weld on junction of 3C charging pump discharge line & line
 leading to safety relief valve 3-283C Cause undetermined
 Weld repaired
 BERRY, Z E Florida Power & Light Co 83/02/07 Region 2,
 Office of Director 1p 17147 008 24X Fiche 50-250, 83/02/07,
 8302150063

8302280345 Forwards LER 83-002/03L-0
 WILLIAMS, J W Florida Power & Light Co 83/02/17 O'REILLY, J P
 Region 2, Office of Director 1p 17308 084 24X
 Fiche 50-250, 83/02/17, 8302280345

--8302280351 LER 83-002/03L-0 on 830118, during Third & Fourth Quarters
 1982, testing of diesel fuel storage tank samples for
 viscosity, water & sediment levels missed Caused by
 oversight Sample taken & analyzed Levels acceptable
 BERRY, Z E Florida Power & Light Co 83/02/17 Region 2,
 Office of Director 2pp 17308 089 24X Fiche 50-250, 83/02/17,
 8302280345.

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants,
 for OLs, NSS vendors, reactor vendors & AE re certificates
 & revised format for reactor operator & senior reactor
 operator licenses Svc list encl
 EISENHUT, D G Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche 50-000, 83/01/31, 8301310203

DOCKE1 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

8302010643 Requests postponement until 830215 of response dates to NRC
 fire protection draft safety evaluation ltrs Addl time
 needed to explore other response alternatives
 UHRIG, R E Florida Power & Light Co 83/01/27 VOLLMER, R H
 Division of Engineering 1p 16980 063 24X Fiche 50-000, 83/01/27,
 8302010643

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
 applicants for OL & holders of CPs re regional workshop
 concerning Suppl I, NUREG-0737, "Requirements for Emergency
 Response Capability " Svc list encl
 EISENHUT, D G Division of Licensing 83/02/01 Consolidated
 Edison Co of New York, Inc 11pp 17221 226 24X
 Fiche 50-000, 83/02/01, 8301210340

8302070528 Application for amend to Licenses DPR-31 & DPR-41, proposing
 changes to Tech Spec P 6-12 re emergency & security plan
 audits per 10CFR50.54(t) & 10CFR73.40(d) as requested by
 Generic Ltrs 82-17 & 82-23, respectively
 UHRIG, R E Florida Power & Light Co 83/02/01 EISENHUT, D G
 Division of Licensing 1p 17036 014 24X Fiche 50-250, 83/02/01,
 8302070528

--8302070534 Proposed Tech Spec Page 6-12 re emergency & security plan
 audits
 * Florida Power & Light Co 83/02/01 1p 17036 015 24X
 Fiche 50-250, 83/02/01, 8302070528

8302180437 Requests extension until 830301 of response dates to NRC
 830106 & 14 ltrs re fire protection draft safety evaluation
 UHRIG, R E Florida Power & Light Co 83/02/18 EISENHUT, D G
 Division of Licensing 1p 17215 018 24X Fiche 50-000, 83/02/18,
 8302180437

8302240216 Advises that extension to 830301 for response to draft
 safety evaluation of App R fire protection exemption
 requests acceptable per 830215 ltr
 EISENHUT, D G Division of Licensing 83/02/18 UHRIG, R E Florida
 Power & Light Co 2pp 17288 239 24X Fiche 50-000, 83/02/18,
 8302240216

O Advisory Committee on Reactor Safeguards reports & correspondence

8302080363 Summary of ACRS Subcommittee on Reactor Operations 820929
 meeting in Washington, DC re low temp overpressurization &
 suppression pool or containment sump water contamination
 adverse effects on cooling pumps
 * ACRS - Advisory Committee on Reactor Safeguards 82/12/15
 ACRS - Advisory Committee on Reactor Safeguards 16pp 17107 123
 24X Fiche 50-000, 82/12/15, 8302080363

8302080268 Trip rept of 821108 visit to FL City, FL re inservice insp
 program
 BENDER, H ACRS - Advisory Committee on Reactor Safeguards
 83/02/04 IGNE, E G ACRS - Advisory Committee on Reactor
 Safeguards 8pp 17107 294 24X Fiche 50-251, 83/02/04, 8302080268

P Operating license stage documents & correspondence

8302080100 Addl response to FOIA request for records re steam
 generators & steam turbines Forwards documents listed under
 Category A of App E Category B documents available in PDR
 FELTON, J M Division of Rules and Records 82/12/17 LONG, D J
 Winthrop, Skimmon, Putnam & Roberts 5pp 17105 069 24X
 Fiche 50-000, 82/12/17, 8302080100

--8302080127 Forwards request for addl info re steam generator tube
 integrity Questions specifically address tubes in U-bend
 region
 EISENHUT, D G Division of Operating Reactors 76/12/14
 GOLLER, K R Assistant Director for Operating Reactor Projects (P)
 791030) 6pp 17103 145 24X Fiche 50-000, 82/12/17, 8302080100

DOCKETED ITEMS

63

8302010606 Submits update to NUREG-0737, Items II B 3, "Post-Accident Sampling Sys," II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication" & II F 1, "Add'l Accident Monitoring Instrumentation"
UHRIO, R E Florida Power & Light Co 83/01/28 VARQA, S A
Operating Reactors Branch 1 2pp 16978 181 24X
Fiche 50-250, 83/01/28, 8302010606

8302080355 Forwards corrected page to Amends 91 & 85 to Licenses DPR-31 & DPR-41, respectively
MCDONALD, D O Operating Reactors Branch 1 83/01/31 UHRIO, R E
Florida Power & Light Co 2pp 17107 079 24X
Fiche 50-250, 83/01/31, 8302080355

--8302080357 Corrected P 2 to Amends 91 & 85 to Licenses DPR-31 & DPR-41, respectively re disposal of high level radwaste & spent fuel
VARQA, S A Operating Reactors Branch 1 83/01/31 2pp
17107 081 24X Fiche 50-250, 83/01/31, 8302080355

8302090518 Summary of 830126 meeting w/uttl in Bethesda, MD re licensee screening criterion for pressurized thermal shock program.
MCDONALD, D O Operating Reactors Branch 1 83/01/31 Operating
Reactors Branch 1 34pp 17117 278 24X Fiche 50-250, 83/01/31,
8302090518

8302070472 Provides justification for continued operation & qualification info for safety evaluation Category II A Items 33, 39 & 101, in response to NRC 821213 ltr re environ qualification of safety-related equipment Withheld
UHRIO, R E Florida Power & Light Co 83/02/01, VARQA, S A
Operating Reactors Branch 1 2pp 17029 001 24X
Fiche 50-250, 83/02/01, 8302070472

8302070528 Application for amend to Licenses DPR-31 & DPR-41, proposing changes to Tech Spec P 6-12 re emergency & security plan audits per 10CFR50.54(f) & 10CFR73.40(d) as requested by
Generic Ltrs 82-17 & 82-23, respectively
UHRIO, R E Florida Power & Light Co 83/02/01 EISENHUT, D O
Division of Licensing 1p 17036 014 24X Fiche 50-250, 83/02/01,
8302070528

--8302070534 Proposed Tech Spec Page 6-12 re emergency & security plan audits
+ Florida Power & Light Co 83/02/01 1p. 17036 015 24X
Fiche 50-250, 83/02/01, 8302070528

8302080106 Informs that debris screens on purge supply & exhaust valves will be installed during next refueling outage
Commitment meets SRP Section 6.2.4, Rev 1 & Branch Technical
Position CSB 6-4, Rev 1 requirements
VARQA, S A Operating Reactors Branch 1 83/02/01 UHRIO, R E
Florida Power & Light Co 2pp 17106 013 24X
Fiche 50-250, 83/02/01, 8302080106

8302170432 Requests submittal, within 60 days, describing flux reduction measures initiated & add'l measures being considered per pressurized thermal shock studies
VARQA, S A Operating Reactors Branch 1 83/02/01, UHRIO, R E
Florida Power & Light Co 5pp 17205 149 24X
Fiche 50-250, 83/02/01, 8302170432

8302070444 Requests exemption from 10CFR50.71(e)(3)(i) scheduler requirement to file annual FSAR rev by 830722 Proposed
filing date of 831122 would facilitate FSAR update,
reflecting more as-built configuration
UHRIO, R E Florida Power & Light Co 83/02/02 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 17036 301 24X
Fiche 50-250, 83/02/02, 8302070444

8302070305 Advises that arrangements made for consultant to perform new analysis per NUREG-0744, Rev 1, Generic Ltr 82-26, "Pressure Vessel Metall Fracture Toughness," to confirm previous conclusions re shelf energy results expected by Aug 1983
UHRIO, R E Florida Power & Light Co 83/02/03, EISENHUT, D O
Division of Licensing 1p 17029 124 24X Fiche 50-250, 83/02/03,
8302070305

8302070577 Forwards Class I & III fees for proposed license amend per NUREG 0737 Tech Specs
UHRIO, R E Florida Power & Light Co 83/02/03, MILLER, W D
License Fee Management Branch 1p 17034 223, 24X
Fiche 50-250, 83/02/03, 8302070577

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08, Consolidated
Edison Co of New York, Inc 1pp. 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-100 to all licensees w/Westinghouse designed NSSB (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08,
8302090085

8302150479 Provides info re TMI Action Items II B 3, "Post-Accident Sampling Sys" & II F 1 i & II F 1 2, "Noble Gas Monitors/Iodine Particulate Sampling," per NRC request
UHRIO, R E Florida Power & Light Co 83/02/10 VARQA, S A
Operating Reactors Branch 1 2pp 17157 088 24X
Fiche 50-250, 83/02/10, 8302150479

8302150497 Application to amend Licenses DPR-31 & DPR-41, deleting App B ETS re aquatic monitoring & surveillance requirements & groundwater monitoring program, Request for deletion of terrestrial biological monitoring programs will be provided.
UHRIO, R E Florida Power & Light Co 83/02/10 EISENHUT, D O,
Division of Licensing, 2pp 17156 324 24X Fiche 50-250, 83/02/10,
8302150497

8302240137 Requests info re any change in scheduler commitments for installation of debris screens pending resolution of operability concerns per long-term review of containment purge & vent valves Assessment of valve operability encl
VARQA, S A Operating Reactors Branch 1 83/02/10, UHRIO, R E
Florida Power & Light Co 8pp 17268 255 24X
Fiche 50-250, 83/02/10, 8302240137

8302180299 Forwards summary of work & insp conducted to date to preclude foreign matl from entering steam generators (both primary & secondary sides) during const activities
UHRIO, R E Florida Power & Light Co 83/02/11 EISENHUT, D O,
Division of Licensing 5pp 17211 238 24X Fiche 50-251, 83/02/11,
8302180299

8302180483 Forwards add'l info on Guideline 4, "Special Lifting Devices" & Guideline 7, "Crane Design," per draft technical evaluation rept on control of heavy loads at facilities.
UHRIO, R E Florida Power & Light Co 83/02/11, VARQA, S A,
Operating Reactors Branch 1 2pp 17210 361 24X
Fiche 50-250, 83/02/11, 8302180483

8302230198 Submits add'l info re ECCB valve position per 830104 ltr. Plant change/mod package providing single continuous position indication for valves will be prepared.
Implementation schedule for changes will be provided.
UHRIO, R E Florida Power & Light Co 83/02/15 VARQA, S A,
Operating Reactors Branch 1 1p 17245 117 24X
Fiche 50-250, 83/02/15, 8302230198

8302230145 Lists specific ETS covered by 830210 request for deletion of aquatic chemical, thermal & biotic monitoring requirements.
UHRIO, R E Florida Power & Light Co 83/02/16 EISENHUT, D O,
Division of Licensing 1p 17243 223 24X Fiche 50-250, 83/02/16,
8302230145

G Inspection reports, IE Bulletins & correspondence

8302080100 Add'l response to FOIA request for records re steam generators & steam turbines Forwards documents listed under Category A of App E, Category B documents available in PDR.
FELTON, J M Division of Rules and Records 82/12/17 LONG, D. J.
Winthrop, Stimson, Putnam & Roberts 5pp 17103 0A9, 24X
Fiche 50-000, 82/12/17, 8302080100

--8302080122 Summary of 731121 meeting w/uttl & Westinghouse re new type of imperfection discovered in recent add'y current insps of dent steam generator tubes Investigation re listed unrevised safety questions recommended.
KINTNER, L L Division of Reactor Licensing (NRR-1975 only),
75/11/24 KHIEL, K Division of Reactor Licensing (NRR-1975 only),
6pp. 17105 137 24X Fiche 50-000, 82/12/17, 8302080100

8302160014 Summary of 830120 meeting w/uttl, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design." Add'l testing not warranted
TRAMMEL, C H Operating Reactors Branch 3 83/01/25, Operating
Reactors Branch 3 25pp 17171 227, 24X Fiche 50-000, 83/01/25,
8302160014

DOCKETED ITEMS

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/28, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150430 Ack receipt of 830121 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 50-250/82-39 &
50-251/82-39.
DANCE, H C Division of Project & Resident Programs 83/02/09
UHRIG, R E Florida Power & Light Co Ip. 17148 132 24X
Fiche 50-250, 83/02/09, 8302150430

--8302150436 Responds to NRC 821222 ltr re violation noted in IE Insp
Repts 50-250/82-39 & 50-251/82-39 Corrective actions east
entrance to auxiliary bldg, air conditioning duct opening &
vehicle access gates posted correctly
UHRIG, R E Florida Power & Light Co 83/01/21 O'REILLY, J P
Region 2, Office of Director 2pp 17148 133 24X
Fiche 50-250, 83/02/09, 8302150430

--8302150440 Forwards IE Insp Repts 50-250/82-39 & 50-251/82-39 on
821129-1203 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/12/22
UHRIG, R E Florida Power & Light Co 2pp 17148 135 24X
Fiche 50-250, 83/02/09, 8302150430

--8302150448 Notice of violation from insp on 821129-1203
* Division of Project & Resident Programs 82/12/22 1p
17148 137 24X Fiche 50-250, 83/02/09, 8302150430

--8302150458 IE Insp Repts 50-250/82-39 & 50-251/82-39 on 821129-1203
Noncompliance noted accessible areas in auxiliary bldg where
radiation levels exceeded 5 m/h not posted
ROSEY, C M, BARR, K P Division of Engineering & Radiological
Safety Programs 82/12/20 6pp 17148 138 24X
Fiche 50-250, 83/02/09, 8302150430

8302160205 Responds to IE Bulletin 82-04, "Deficiencies in Primary
Containment Electrical Penetration Assemblies " Review of
containment penetrations indicates no Bunker-Ramo electrical
penetrations installed
UHRIG, R E Florida Power & Light Co 83/02/09. DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
17163 047 24X Fiche 50-250, 83/02/09, 8302160205

8302160241 Responds to IE Bulletin 82-04 re deficiencies in containment
electrical penetration assemblies Bunker-Ramo electrical
penetrations not in use at facility
UHRIG, R E Florida Power & Light Co 83/02/10 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
17170 212 24X Fiche 50-250, 83/02/10, 8302160241

8302240080 Forwards safety evaluation & notice of granting of relief
from inservice insp requirement re reactor coolant pump
Alternate exams accepted
VARQA, S A Operating Reactors Branch I 83/02/14 UHRIG, R E
Florida Power & Light Co 2pp 17268 288 24X
Fiche 50-251, 83/02/14, 8302240080

--8302240085 Safety evaluation re request for relief from inservice insp
requirements concerning exam of reactor coolant pump
Alternative method of visual exam acceptable
* Operating Reactors Branch I 83/02/14 6pp 17268 291 24X
Fiche 50-251, 83/02/14, 8302240080

--8302240120 Notice of granting of relief from ASME Section XI inservice
insp requirements for welds & internal surfaces of reactor
coolant pump
VARQA, S A Operating Reactors Branch I 83/02/14 2pp
17268 297 24X Fiche 50-251, 83/02/14, 8302240080

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18, Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060355 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060365 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for ULs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27,
8302040033

--8302040037 Forwards public version of revised Emergency Plan
Implementing Procedures ED-29 re meteorological maint
programs & ED-25 re computer codes for access to QDCS
programs
PAJOWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC
- No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing
Procedures ED-29 re meteorological maint programs & ED-25
re computer codes for access to QDCS programs Revised
index encl
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp
17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8302040205 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17043 349 24X Fiche 50-254, 83/01/31,
8302040205

--8302040214 Forwards public version of Rev 9 to Emergency Plan
Implementing Procedures GEP 440-0, "Communications Sys" &
GEP 440-1, "Emergency Communication Facilities "
* Commonwealth Edison Co 83/01/19 DENTON, H R NRC - No
Detailed Affiliation Given 1p 17043 350 24X
Fiche 50-254, 83/01/31, 8302040205

--8302040220 Public version of Rev 9 to Emergency Plan Implementing
Procedures GEP 440-0, "Communications Sys" & GEP 440-1,
"Emergency Communication Facilities "
* Commonwealth Edison Co 83/01/19 8pp 17043 351 24X
Fiche 50-254, 83/01/31, 8302040205

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080365 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/02/02 Document
Management Branch 1p 17107 139 24X Fiche 50-254, 83/02/02,
8302080365

--8302080368 Forwards public version of Rev 9 to Emergency Plan
Implementing Procedure GEP 360-2, "Plant Evacuation &
Assembly " Revised index encl
* Commonwealth Edison Co 83/01/21 DENTON, H R NRC - No
Detailed Affiliation Given 2pp 17107 140 24X
Fiche 50-254, 83/02/02, 8302080365

--8302080372 Public version of Rev 9 to Emergency Plan Implementing
Procedure GEP 360-2, "Plant Evacuation & Assembly "
* Commonwealth Edison Co 83/01/21 2pp 17107 142 24X
Fiche 50-254, 83/02/02, 8302080365

DOCKETED ITEMS

55

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0692 & SECY-82-1118 guidelines valid KEPLER, J O Region 3, Office of Director 83/02/04 REED, C Commonwealth Edison Co App 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPLER, J O Region 3, Office of Director 3pp 17096 294 24X Fiche 50-000, 83/02/04, 8302080316

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J H Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
NELLS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities Lists of locations encl
SMARTZ, E D Commonwealth Edison Co 83/01/28 KEPLER, J O Region 3, Office of Director 4pp 17291 074 24X Fiche 50-000, 83/02/18, 8302250349

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
HANNON, J H NRC - No Detailed Affiliation Given 82/01/27, VARGAS, S NRC - No Detailed Affiliation Given 10pp 17196 225 24X Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAOLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X Fiche 50-000, 83/01/18, 8302170019

--8302170262 Concludes that based on licensee 820603 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
BEVAN, R B Operating Reactors Branch 2 82/10/28 EISENHUT, D O Division of Licensing 2pp 17197 050 24X Fiche 50-000, 83/01/18, 8302170019

8302010294 Advises of detailed evaluation of Technical Evaluation Repts attached to SERs re safety-related equipment, to determine nonproprietary nature of info info will be withheld until 830215 resolution
RAUSCH, T J Commonwealth Edison Co 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16973 114 24X Fiche 50-254, 83/01/25, 8302010294

8302010429 Forwards "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plants Drywell Temp Analysis" Analysis fulfills NRC request for info re equipment qualification temp profiles inside containment
RAUSCH, T J Commonwealth Edison Co 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16974 180 24X Fiche 50-000, 83/01/25, 8302010429

--8302010434 "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plant Drywell Temp Analysis"
HOANG, H Y, ROGERS, A E General Electric Co. NSE0-82-0682 82/11/30 13pp 16974 182 24X Fiche 50-000, 83/01/25, 8302010429.

8302070274 Suppls 821019 ltr re justification for continued operation for SCAM resistance temp detectors in reactor water cleanup rooms, per 821229 & 830118 SERs for environ qualification of electrical equipment program
RAUSCH, T J Commonwealth Edison Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17031 116 24X Fiche 50-000, 83/02/01, 8302070274

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - GPU Service Corp 5pp 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302100224 Forwards description, basis & justification for each setpoint chosen for reactor protection sys power monitoring sys, per 820723 ltr Proposed Tech Specs will be submitted by 830415
RAUSCH, T J Commonwealth Edison Co 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 17115 116 24X Fiche 50-000, 83/02/04, 8302100224

8302080275 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080275

8302080301 Generic Ltr 83-05 to BNR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302220330 Discusses schedule for util response re environ qualification of electrical equipment proprietary info Manufacturers contacted on timely response Status of final reporting will be provided by 830515
RYBAK, B Commonwealth Edison Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17230 091 24X Fiche 50-000, 83/02/14, 8302220330

8302250179 Forwards "Quad Cities Nuclear Station, Unit 1, Cycle 7 Startup Test Results"
RYBAK, B Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17293 049 24X Fiche 50-254, 83/02/17, 8302250179

--8302250183 "Quad-Cities Nuclear Power Station, Unit 1, Cycle 7 Startup Test Results"
* Commonwealth Edison Co 1D/TS2-B 83/02/17, 10pp 17293 051 24X Fiche 50-254, 83/02/17, 8302250179

8302250293 Forwards "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2," per Section XI of ASME Boiler & Pressure Vessel Code, 1980 Edition, including Winter 1980 addenda
RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17295 310 24X Fiche 50-254, 83/02/17, 8302250293

--8302250308 "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2"
* Commonwealth Edison Co 82/08/18 233pp. 17295 312. 24X Fiche 50-254, 83/02/17, 8302250293

DOCKETED ITEMS

8302250255 Forwards Suppl 9 to Rev 1 of Joseph Oat Corp "Licensing Rept on High Density Spent Fuel Reacts for Quad Cities Unit 1 & 2" Changes include reduction in number of storage cells to be installed & rev to spacing arrangement
RYBAK, B Commonwealth Edison Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp. 17292 130 24X
Fiche 50-254, 83/02/18, 8302250255

8302280152 Advises that review of 830121 final rule on environ qualification of safety-related electrical equipment incomplete Determination whether to reaffirm or withdraw hearing request will be provided by 830324
BTEPTOE, P P Isham, Lincoln & Beale 83/02/23 EISENHUT, D Q Division of Licensing 1p 17306 076 24X Fiche 50-000, 83/02/23, 8302280152

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
BUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J Q Region 3, Office of Director 13pp 17045 281 24X
Fiche: 50-000, 82/12/30, 8302040332

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPEESBARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302080277 Submits updated installation status rept of safe shutdown path supports, per IE Bulletin 79-14 All remaining hangers will be installed by 831231 w/exception of Quad Cities safety relief valve line
RAUSCH, T J Commonwealth Edison Co 83/02/01, KEPPLER, J Q Region 3, Office of Director 4pp 17056 337 24X Fiche 50-000, 83/02/01, 8302080277

8302100088 Forwards draft NRR input for upcoming SALP evaluation for CY82 based on program manager experience w/Comm Ed & input solicited from selected personnel involved w/licensing actions Review & comments requested by 830210
DEVAN, R Operating Reactors Branch 2 83/02/04, EISENHUT, D Q Division of Licensing SPEIB, T Division of Safety Technology, MATISON, R J Division of Systems Integration (post 811005) 7pp 17135 097 24X Fiche 50-254, 83/02/04, 8302100088

8302150528 Requests Delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels"
SWARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000, 83/02/08, 8302150528

8302280339 Forwards IE Insp Repts 50-254/82-23 & 50-255/82-25 on 821023-830107 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 83/02/10
REEU, C Commonwealth Edison Co 2pp 17313 079 24X
Fiche 50-254, 83/02/10, 8302280339

--8302280341 IE Insp Repts 50-254/82-23 & 50-255/82-25 on 821023-830107 No noncompliance noted Major areas inspected operational safety, plant scram, procedures, TMI action plan items, licensee meeting & refueling activities
CHRISTOTIMOS, N, DUPONT, S O, WALKER, R D Division of Project & Resident Programs 83/02/10 12pp 17313 081 24X
Fiche 50-254, 83/02/10, 8302280339

8302150587 EN-83-008 on 830216, notices of violation & proposed imposition of civil penalties in amount of \$120,000 will be issued Action based on lack of controls over distribution of safety list & failure to maintain containment integrity
BARBER, G Director's Office, Office of Inspection and Enforcement 83/02/11 2pp 17156 117 24X Fiche 50-000, 83/02/11, 8302150587

8302180491 Discusses IE insp on 820816-1103 & forwards notice of violation & proposed imposition of civil penalty
KEPPLER, J Q Region 3, Office of Director 83/02/16 O'CONNOR, J J Commonwealth Edison Co 4pp 17214 127 24X Fiche 50-000, 83/02/16, 8302180491

--8302180496 Notice of violation & proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted weakness in QA program, including lack of controls over distribution of safety classification list
KEPPLER, J Q Region 3, Office of Director 83/02/16 3pp 17214 131 24X Fiche 50-000, 83/02/16, 8302180491

8302250293 Forwards "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2," per Section XI of ASME Boiler & Pressure Vessel Code, 1980 Edition, including Winter 1980 addenda
RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17295 310 24X
Fiche 50-254, 83/02/17, 8302250293

--8302250308 "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2"
* Commonwealth Edison Co 82/08/18 233pp 17295 312 24X
Fiche 50-254, 83/02/17, 8302250293

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radioactive - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150044 Forwards monthly operating repts for Jan 1983
KALIVIANAKIS, N Commonwealth Edison Co 83/02/03 Director's Office, Office of Inspection and Enforcement 1p 17147 101 24X
Fiche 50-254, 83/02/03, 8302150044

--8302150048 Monthly operating repts for Jan 1983
BROOK, B, BUSS, R Commonwealth Edison Co 83/02/03 22pp 17147 102 24X Fiche 50-254, 83/02/03, 8302150044

8302150691 Forwards listing of changes, tests & experiments completed during Jan 1983
KALIVIANAKIS, N Commonwealth Edison Co 83/02/03 CASE, E O Office of Nuclear Reactor Regulation, Director 3pp 17150 359 24X Fiche 50-254, 83/02/03, 8302150691

S Reportable occurrences, LERs & related correspondence

8302010540 Forwards LER 82-039/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 83/01/10 KEPPLER, J Q Region 3, Office of Director 1p 16777 132 24X
Fiche 50-254, 83/01/10, 8302010540

DOCKETED ITEMS

--8302010553 LER 82-039/03L-0 on 821224, diesel generator 1/2 failed to start following preventive maint Caused by crack in 1/4-inch copper air line Crack due to crimp in right angle bend in line & fatigue failure at stress point New line rebuilt
REYNOLDS, S Commonwealth Edison Co 83/01/10 Region 3, Office of Director 1p 16977 133 24X Fiche 50-254, 83/01/10, 8302010540

8302040050 Forwards LER 83-004/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 83/01/24 KEPLER, J
Region 3, Office of Director 1p 17020 357 24X
Fiche 50-254, 83/01/24, 8302040050

--8302040054 LER 83-004/03L-0 on 830109, containment cooling loop A taken out or svc for preventive maint on RHR 1A HX New gaskets for inner head & drain line of HX installed to repair small leaks
EAGLE, J Commonwealth Edison Co 83/01/24 Region 3, Office of Director 1p 17020 358 24X Fiche 50-254, 83/01/24, 8302040050

8302040171 Forwards LER 83-003/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 83/01/24 KEPLER, J
Region 3, Office of Director 1p 17020 191 24X
Fiche 50-254, 83/01/24, 8302040171

--8302040187 LER 83-003/03L-0 on 830118, during reactor water level calibr Procedure DIS 10-1, switch LIS-1-263-98A tripped below Tech Specs Caused by instrument setpoint drift Level switch recalibr
FURB, A Commonwealth Edison Co 83/01/24 Region 3, Office of Director 1p 17020 192 24X Fiche 50-254, 83/01/24, 8302040171

8302080292 Forwards LER 83-005/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 83/01/28 KEPLER, J
Region 3, Office of Director 1p 17056 116 24X
Fiche 50-254, 83/01/28, 8302080292

--8302080297 LER 83-005/03L-0 on 830115, HPCI motor gear unit raised to normal high speed stop but returned to low speed stop when manual operation switch released Caused by failed power supply resistor Resistor & amplifier replaced
LHOU, H Commonwealth Edison Co 83/01/28 Region 3, Office of Director 3pp 17056 117 24X Fiche 50-254, 83/01/28, 8302080292

8302150114 Forwards LER 83-001/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 83/02/01 KEPLER, J
Region 3, Office of Director 1p 17195 237 24X
Fiche 50-254, 83/02/01, 8302150114

--8302150124 LER 83-001/03L-0 on 830104, diesel generator 1/2 tripped on high crankcase pressure signal Caused by lubricating oil splashing on pressure sensor upon startup Sensor replaced
KEPPEL, F Commonwealth Edison Co 83/02/01 Region 3, Office of Director 3pp 17195 238 24X Fiche 50-254, 83/02/01, 8302150114

8302280316 Forwards LER 83-002/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 83/02/14 KEPLER, J
Region 3, Office of Director 1p 17312 347 24X
Fiche 50-254, 83/02/14, 8302280316

--8302280321 LER 83-002/03L-0 on 830119, during HPCI operability test, motor speed changer would not move from low speed stop Caused by excessive friction Low speed stop post filed down until post merely rested against collar tab
EAGLE, J Commonwealth Edison Co 83/02/14 Region 3, Office of Director 3pp 17312 348 24X Fiche 50-254, 83/02/14, 8302280316

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSR vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-255 PALISADES NUCLEAR PLANT

D. NRC Draft/Final Environmental Statements, supp's & correspondence

8302070622 Notices that final review of FES completed & no substantial changes in facility design or environs identified Minor changes noted
VANDEHALL, D J Consumers Power Co 83/02/02 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17020 061 24X
Fiche 50-255, 83/02/02, 8302070622

F Security, medical, emergency & fire protection plans

8302010660 Responds to 821030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73.40(d) & 87B Twelve-month Physical Security Plan & Safeguards Contingency Plan audits performed per requirements
BORDINO, T C Consumers Power Co 83/01/27 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16980 066 24X
Fiche 50-000, 83/01/27, 8302010660

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302250278 Forwards IE Insp Rept 80-255/83-02 on 830119-20 No noncompliance noted
PAPERELLO, C J Division of Emergency Preparedness & Operational Support 83/02/07 DEWITT, R B Consumers Power Co 2pp 17291 294 24X Fiche 50-255, 83/02/07, 8302250278

--8302250283 IE Insp Rept 80-255/83-02 on 830119-20 No noncompliance noted, Major areas inspected open items remaining from emergency preparedness implementation appraisal & other items re emergency preparedness
FAGLIARD, J A, AXELSON, W L Division of Emergency Preparedness & Operational Support 83/01/31 5pp 17291 296 24X
Fiche 50-255, 83/02/07, 8302250278

8302290415 Forwards exemption from requirements of 10CFR50, App R re installation of fixed fire suppression sys in control room
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/08 VANDEHALL, D J Consumers Power Co 2pp 17246 109 24X
Fiche 50-255, 83/02/08, 8302290415

--8302290419 Exemption from 10CFR50, App R re installation of fixed fire suppression sys in control room
EISENHUT, D O Division of Licensing 83/02/03 Consumers Power Co 3pp 17246 111 24X Fiche 50-255, 83/02/08, 8302290415

8302290421 Forwards response to recommendations from NRC regulatory effectiveness review Response withheld (ref 10CFR73.21),
VANDEHALL, D J Consumers Power Co 83/02/18 CRUTCHFIELD, D Operating Reactors Branch 5 1p 17246 121 24X
Fiche 50-255, 83/02/18, 8302290421

P Operating license stage documents & correspondence

8302040121 Forwards "Reactor Internals Noise Monitoring Tests," 1982 Test results demonstrate that reactor core barrel tightly clamped w/no other anomalous vibrations during testing period Tech Spec requirements satisfied
JOHNSON, B D Consumers Power Co 83/01/17 KEPLER, J O Region 3, Office of Director 1p 17021 290 24X Fiche 50-255, 83/01/17, 8302040121

--8302040126 "Reactor Internals Noise Monitoring Test," 1982
* Consumers Power Co 83/01/31 36pp 17021 291 24X
Fiche 50-255, 83/01/17, 8302040121

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18, DENTON, H R, Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 13, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

8302040248 Forwards Amend 75 to License DPR-20, safety evaluation & notice of issuance & availability Amend changes App A Tech Spec provisions of Section 6, Administrative Controls re addition of nuclear activities plant organization
WAMBACH, T V Operating Reactors Branch 5 83/01/28 VANDEHALL, D J Consumers Power Co 3pp 17020 062 24X
Fiche 50-255, 83/01/28, 8302040248

DOCKETED ITEMS

--B302040251 Amend 75 to License DPR-20, changing Tech Specs App A, Section 6, Administrative Controls, to reflect addition of nuclear activities plant organization & organizational title changes
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/28 14pp
17020 065 24X Fiche 50-255, 83/01/28, B302040248

--B302040255 Safety evaluation supporting Amend 75 to License DPR-20
* Office of Nuclear Reactor Regulation, Director 83/01/28
23pp 17020 079 24X Fiche 50-255, 83/01/28, B302040248

--B302040257 Notice of issuance & availability of Amend 75 to License DPR-20
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/28 2pp
17020 102 24X Fiche 50-255, 83/01/28, B302040248

B302070439 Updates NUREG-0737, Item II F 1 i, "Noble Gas Effluent Monitor" Ventilation sys mods for monitoring potential airborne radioactivity include automatic isolation of V-79 exhaust sys to be completed by end of refueling outage
JOHNSON, B D Consumers Power Co 83/02/02 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 17031 016 24X
Fiche 50-255, 83/02/02, B302070439

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 1pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, B302080304

B302090072 Generic Ltr 83-108 to all licensees w/C-E designed NSSS re resolution of TMI Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consumers Power Co 32pp 17290 185 24X Fiche 50-000, 83/02/08, B302090072

B302160370 Informs of withdrawal of commitment to install flood alarm for water intake bldg in response to SEP Topic IX-3, "Station Bvc & Cooling Water Sys"
TOMER, K A Consumers Power Co 83/02/10 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17164 146 24X Fiche 50-255, 83/02/10, B302160370

B302180426 Commits to submit changes by B30315 to Tech Specs re station battery testing, per SEP Topic VIII-3 A, "Station Battery Capacity Test Requirements"
TOMER, K A Consumers Power Co 83/02/11 CRUTCHFIELD, D Operating Reactors Branch 5 1p 17215 188 24X Fiche 50-255, 83/02/11, B302180426

B302240273 Forwards status of SEP Topic VIII-4, "Electrical Penetrations of Reactor Containment," program to evaluate adequacy of penetration from overload & short circuit conditions Next status rept will be submitted by B30715
TOMER, K A Consumers Power Co 83/02/11 CRUTCHFIELD, D Operating Reactors Branch 5 16pp 17274 188 24X Fiche 50-255, 83/02/11, B302240273

B302280182 Forwards Amend 76 to License DPR-20 & notice of issuance & availability Amend approves change in testing frequency of emergency lighting inside containment
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/17
VANDEWALLE, D J Consumers Power Co 8pp 17306 047 24X
Fiche 50-255, 83/02/17, B302280182

--B302280191 Amend 76 to License DPR-20, approving change in testing frequency of emergency lighting inside containment from yearly to during each refueling outage.
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/17 4pp
17306 051 24X Fiche 50-255, 83/02/17, B302280182

--B302280195 Notice of issuance & availability of Amend 76 to License DPR-20
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/17 2pp
17306 055 24X Fiche 50-255, 83/02/17, B302280182

B302230380 Submits recommendations & formalized commitments re draft technical evaluation rept, "Control of Heavy Loads"
Procedure will be implemented to cover deviations from safe load paths
JOHNSON, B D Consumers Power Co 83/02/18 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 17246 329 24X
Fiche 50-255, 83/02/18, B302230380

Q Inspection reports, IE Bulletins & correspondence

B302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, B302040039

--B302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J G Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, B302040039

B302010534 Forwards IE Insp Rept 50-255/82-29 on B21214-17 & notice of violation
MILLER, J R Division of Engineering 83/01/14 DEWITT, R B
Consumers Power Co 2pp 16977 186 24X Fiche 50-255, 83/01/14, B302010534

--B302010544 Notice of violation from insp on B21214-17
MILLER, J R Division of Engineering 83/01/14 1p 16977 108
24X Fiche 50-255, 83/01/14, B302010534

--B302010554 IE Insp Rept 50-255/82-29 on B21214-17 Noncompliance noted failure to maintain liquid radwaste monitor operable
LOVENDALE, P C, GREGER, L R Region 3, Office of Director
83/01/14 7pp 16977 189 24X Fiche 50-255, 83/01/14, B302010534

B302010379 Forwards IE Insp Rept 50-255/82-30 on B21201-31 No noncompliance noted
STREET, J F Division of Project & Resident Programs 83/01/18
DEWITT, R B Consumers Power Co 2pp 16973 285 24X
Fiche 50-255, 83/01/18, B302010379

--B302010382 IE Insp Rept 50-255/82-30 on B21201-31 No noncompliance noted Major areas inspected routine resident insp program activities, including operations, surveillance, maint & maint records, procurement & independent insp
JORDENSEN, B L, MILLER, J R, BOYD, D C Division of Project & Resident Programs 83/01/17 6pp 16973 287 24X
Fiche 50-255, 83/01/18, B302010379

B302160014 Summary of B30120 meeting w/utilis, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMER, C M Operating Reactors Branch 3 83/01/25
Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, B302160014

B212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H30C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

B302030303 Advises of B30207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, B302030303

B302250278 Forwards IE Insp Rept 50-255/83-02 on B30119-20 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/07 DEWITT, R B Consumers Power Co 2pp 17291 294 24X Fiche 50-255, 83/02/07, B302250278

--B302250283 IE Insp Rept 50-255/83-02 on B30119-20 No noncompliance noted Major areas inspected open items remaining from emergency preparedness implementation appraisal & other items re emergency preparedness
PAOLARO, J A, AXELSON, W L Division of Emergency Preparedness & Operational Support 83/01/31 5pp 17291 296 24X
Fiche 50-255, 83/02/07, B302250278

DOCKETED ITEMS

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8302280371 Ack receipt of 830214 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-255/82-29
PAPERIELLO, C. J Division of Emergency Preparedness & Operational
Support 83/02/24 DEWITT, R B Consumers Power Co 1p
17309 141 24X Fiche 50-255, 83/02/24, 8302280371.

--8302280374 Responds to NRC 830114 ltr re violations noted in IE Insp
Rept 50-255/82-29 Corrective actions Procedure HP4.4 re
liquid release control will be revised & personnel
re instructed
VANDERWALLE, D J Consumers Power Co 83/02/14 KEPLER, J O
Region 3, Office of Director 1p 17309 142 24X
Fiche 50-255, 83/02/24, 8302280371

R Periodic operating reports & related correspondence

8302160247 Forwards monthly operating rept for Jan 1983
KENNEDY, D M Consumers Power Co 83/02/04 NRC - No Detailed
Affiliation Given 1p 17170 078 24X Fiche 50-255, 83/02/04,
8302160247

--8302160252 Monthly operating rept for Jan 1983
PETERSON, D A Consumers Power Co 83/02/01 4pp 17170 079
24X Fiche 50-255, 83/02/04, 8302160247

S Reportable occurrences, LERs & related correspondence

8302040135 Forwards LER 83-001/01T-0
JOHNSON, B D Consumers Power Co 83/01/26 KEPLER, J O Region 3,
Office of Director 1p 17020 189 24X Fiche 50-255, 83/01/26,
8302040135

--8302040144 LER 83-001/01T-0 on 830112, while raising boron concentration
in T-82B (B safety injection tank), tank became inoperable
due to low tank level Caused by high tank level & leakage
from loop check valve
* Consumers Power Co 83/01/26 Region 3, Office of Director
1p 17020 190 24X Fiche 50-255, 83/01/26, 8302040135,

8302080317 Forwards LER 83-002/03L-0
JOHNSON, B D Consumers Power Co 83/02/02, KEPLER, J O, Region 3,
Office of Director 1p 17056 302 24X Fiche 50-255, 83/02/02,
8302080317

--8302080319 LER 83-002/03L-0 on 821209, log record indicated T-102 gas
pressure at 8.2 psig, w/another occurrence of low pressure on
830119 Caused by leak in nitrogen sys supplying T-102 Search
for leak initiated
* Consumers Power Co 83/02/02 Region 3, Office of Director
2pp 17056 303 24X Fiche 50-255, 83/02/02, 8302080317

8302160173 Forwards LER 83-003/03L-0
JOHNSON, B D Consumers Power Co 83/02/07 KEPLER, J O Region 3,
Office of Director 1p 17162 179 24X Fiche 50-255, 83/02/07,
8302160173

--8302160177 LER 83-003/03L-0 on 830106, during normal operation, B safety
injection tank T-82B reached Tech Spec limit of 198 inches.
Caused by minor leakage past loop check valve & tank check
valve refill & drain valve Valves will be inspected.
* Consumers Power Co 83/02/07 Region 3, Office of Director,
1p 17162 181 24X Fiche 50-255, 83/02/07, 8302160173

8302160376 Forwards LER 83-004/03L-0
JOHNSON, B D Consumers Power Co 83/02/07, KEPLER, J O, Region
3, Office of Director 1p 17164 173 24X Fiche 50-255, 83/02/07,
8302160376.

--8302160381 LER 83-004/03L-0 on 830106, PCB leak rate calculation
indicated unidentified leakage exceeding Tech Spec Caused
by improperly seated CV-2056 Valve cycled & proper seal
obtained
* Consumers Power Co 83/02/07 Region 3, Office of Director
1p 17164 174 24X Fiche 50-255, 83/02/07, 8302160376

8302180376 Telecopy RD on 830204, number of openings in safety inject
refueling water tank support structure unaccounted for &
only one fan operating for each room cooler Caused by loss
of offsite power & diesel generator failure
KRICH, R M Consumers Power Co 83/02/07 Region 3, Office of
Director 4pp 17209 188 24X Fiche 50-255, 83/02/07, 8302180376

8302160250 Forwards LER 83-005/03L-0
JOHNSON, B D Consumers Power Co 83/02/08 KEPLER, J O Region
Office of Director 1p 17170 053 24X Fiche 50-255, 83/02/08,
8302160250

--8302160255 LER 83-005/03L-0 on 830110, discrepancies noted in 1981
results for snubber 63 Caused by fluid not being added since
1981 due to deficiency in surveillance procedure, snubber
replaced, Procedure revised
JOHNSON, B D Consumers Power Co 83/02/08 Region 3, Office
of Director 1p 17170 054 24X Fiche 50-255, 83/02/08, 8302160250

8302180248 Telecopy RD on 830129, operators discovered thermal overrun
for one room cooler fan in each of engineered safeguards
rooms tripped & wired incorrectly on 830131 Fan wiring
corrected
KRICH, R M Consumers Power Co 83/02/10 Region 3, Office of
Director 3pp 17215 264 24X Fiche 50-255, 83/02/10, 8302180248

8302280365 Forwards LER 83-006/01T-0
JOHNSON, B D Consumers Power Co 83/02/17 KEPLER, J O Region
Office of Director 1p 17309 320 24X Fiche 50-255, 83/02/17,
8302280365

--8302280383 LER 83-006/01T-0 on 830204, during AE review of BIRMT su
structure, discrepancies between support structure & as-built
documents noted Caused by failure to document const changes
in as-built documentation Mods underway.
* Consumers Power Co 83/02/17 Region 3, Office of Director
1p 17309 321 24X Fiche 50-255, 83/02/17, 8302280365

8302280386 Forwards LER 83-007/01T-0
JOHNSON, B D Consumers Power Co 83/02/17 KEPLER, J O Region
Office of Director 1p 17309 331 24X Fiche 50-255, 83/02/17,
8302280386

--8302280393 LER 83-007/01T-0 on 830204, during review of BEP topics
following LOCA w/concurrent loss of either diesel generator,
determined only one fan in each engineering safeguards room
cooler would operate Caused by design deficiency
* Consumers Power Co 83/02/17 Region 3, Office of Director
1p 17309 332 24X Fiche 50-255, 83/02/17, 8302280386

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicant
for OLS, NBS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl.
EISENHUT, D G Division of Licensing 83/01/31, Consolidated
Edison Co. of New York, Inc, 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-259 BROWN'S FERRY NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8302030057 Releases public version of revised radiological emergency
notification directory.
FELTON, J M Division of Rules and Records, 83/01/28, Document
Management Branch 1p 17026 344 24X Fiche 50-259, 83/01/28,
8302030057

--8302030062 Forwards public version of Rev B to radiological emergen
notification directory
MILLS, L H Tennessee Valley Authority, 83/01/06, DENTON, H R,
Office of Nuclear Reactor Regulation, Director, 5pp 17026 345
24X Fiche 50-259, 83/01/28, 8302030057

--8302030065 Public version of Rev B to radiological emergency
notification directory.
* Tennessee Valley Authority, 82/12/16 15pp 17026 351 24X
Fiche 50-259, 83/01/28, 8302030057

DOCKETED ITEMS

8302030627 Releases public version of revised radiological emergency notification directory
 FELTON, J M Division of Rules and Records 83/01/31 Document
 Management Branch 1p 17013 320 24X Fiche 50-259, 83/01/31,
 8302030627

--8302030628 Forwards public version of Rev 9 to radiological emergency notification directory
 MILLS, L M Tennessee Valley Authority 83/01/11 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 17013 321
 24X Fiche 50-259, 83/01/31, 8302030627

--8302030629 Public version of Rev 9 to radiological emergency notification directory
 SLIGER, E K Tennessee Valley Authority 83/01/06 5pp
 17013 322 24X Fiche 50-259, 83/01/31, 8302030627

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
 EISENHUT, D O Division of Licensing 83/02/01 Consolidated
 Edison Co of New York, Inc 11pp 17221 226 24X
 Fiche 50-000, 83/02/01, 8301210340

8302100330 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to add requirement to audit safeguards contingency plan at least once every 12 months per Generic Ltr 82-23
 MILLS, L M Tennessee Valley Authority 83/02/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 17116 314
 24X Fiche 50-259, 83/02/01, 8302100330

--8302100332 Proposed Tech Specs requiring audit of safeguards contingency plan at least once every 12 months
 * Tennessee Valley Authority 83/02/01 4pp 17116 316 24X
 Fiche 50-259, 83/02/01, 8302100330

8302140076 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21).
 MILLS, L M Tennessee Valley Authority 83/02/04 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 17141 212 24X
 Fiche 50-259, 83/02/04, 8302140076

8302170225 Grants exemption from 10CFR50 4B & App R to 10CFR50 requirements re fire protection, per 830426 request
 VASSALLO, D B Operating Reactors Branch 2 83/02/04 PARRIS, H G
 Tennessee Valley Authority 2pp 17193 360 24X
 Fiche 50-259, 83/02/04, 8302170225

--8302170229 Exemption from 10CFR50 4B & App R to 10CFR50 requirements re fire protection
 EISENHUT, D O Division of Licensing 83/02/04 Tennessee
 Valley Authority 7pp 17193 362 24X Fiche 50-259, 83/02/04,
 8302170225

8302150325 Forwards IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted
 VERRELLI, B Division of Project & Resident Programs 83/02/07
 PARRIS, H G Tennessee Valley Authority 2pp 17157 167 24X
 Fiche 50-259, 83/02/07, 8302150325

--8302150346 IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted Major areas inspected security plan & implementing procedures & security program audit Details withheld (ref 10CFR73 21)
 MOORE, D E Division of Emergency Preparedness & Materials Safety
 83/02/03 1p 17157 169 24X Fiche 50-259, 83/02/07, 8302150325

P. Operating license stage documents & correspondence

102010614 Forwards item-by-item description of responses to NRC 82102B conference call request for info re compliance w/NUREG-0612, Section 3.1, "General Provisions for Load Handling," requirements
 KAMMER, D S Tennessee Valley Authority 83/01/25 VASSALLO, D B
 Operating Reactors Branch 2 4pp 16980 273 24X
 Fiche 50-259, 83/01/25, 8302010614

8302070087 Forwards safety evaluation re NRC review of util response to NUREG 0737, Item II K.3 25, "Effect of Loss of AC Power on Pump Seals" Util endorsement of BWR Owners Group position considered acceptable & matter resolved
 VASSALLO, D B Operating Reactors Branch 2 83/01/25 PARRIS, H G
 Tennessee Valley Authority 2pp 17065 293 24X
 Fiche 50-259, 83/01/25, 8302070087

--8302070107 Safety evaluation re BWR Owners Group generic response to NUREG-0737, Item II K.3 25, "Effect of Loss of AC Power on Pump Seals" No mods to seal cooling for recirculation pumps required
 HODGES, W Operating Reactors Branch 2 82/12/01 5pp
 17065 295 24X Fiche 50-259, 83/01/25, 8302070087

830210066 Confirms 830125 telephone authorization for change to Tech Specs, per 830125 telecopied ltr License DPR-33 amended by revising Tech Specs to permit operation at levels up to 50% rated power from 830125-31
 LAINAS, G C Assistant Director for Operating Reactors 83/01/26
 PARRIS, H G Tennessee Valley Authority 2pp 16995 077 24X
 Fiche 50-259, 83/01/26, 830210066

8302010583 Confirms telcon re NRC review of Reload 5 license amend request Due to slip in schedule, period for NRC review must be reduced to 45 days Shutdown scheduled for mid-Apr 1983 w/startup scheduled for late Aug 1983
 MILLS, L M Tennessee Valley Authority 83/01/28 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16977 075
 24X Fiche 50-259, 83/01/28, 8302010583

8302090002 Application for amend to License DPR-33, changing Tech Specs to allow operation w/increased core flow for remainder of current operating cycle
 MILLS, L M Tennessee Valley Authority 83/02/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 17070 018
 24X Fiche 50-259, 83/02/01, 8302090002

--8302090004 Proposed Tech Specs to License DPR-33, allowing operation w/increased core flow for remainder of current operating cycle
 * Tennessee Valley Authority 83/02/01 5pp 17070 020 24X
 Fiche 50-259, 83/02/01, 8302090002

--8302090006 "Safety Review of Browns Ferry Nuclear Plant Unit 1 at Core Flow Conditions Above Rated Flow During Cycle 5"
 FISCHER, D L, ORIDLEY, R L General Electric Co NEDO-22135
 82/05/31 31pp 17070 025 24X Fiche 50-259, 83/02/01, 8302090002

8302100330 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to add requirement to audit safeguards contingency plan at least once every 12 months per Generic Ltr 82-23
 MILLS, L M Tennessee Valley Authority 83/02/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 17116 314
 24X Fiche 50-259, 83/02/01, 8302100330

--8302100332 Proposed Tech Specs requiring audit of safeguards contingency plan at least once every 12 months
 * Tennessee Valley Authority 83/02/01 4pp 17116 316 24X
 Fiche 50-259, 83/02/01, 8302100330

8302170488 Requests schedule for completing TMI Action Items II F 1 & II F 1.2 per Generic Ltrs 82-05 & 82-10 Justification for delay in installing monitors required
 VASSALLO, D B Operating Reactors Branch 2 83/02/01 PARRIS, H G
 Tennessee Valley Authority 3pp 17203 191 24X
 Fiche 50-259, 83/02/01, 8302170488

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
 EISENHUT, D O Division of Licensing 83/02/02 General Public
 Utilities - GPU Service Corp 5pp 17074 084 24X
 Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
 Edison Co 4pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 9pp 17234 234 24X
 Fiche 50-000, 83/02/08, 8302080304

DOCKETED ITEMS

61

8302230411 Application for amend to Licenses DPR-33, DPR-52 & DPR-6B, deleting environ reporting requirement
MILLS, L M Tennessee Valley Authority 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17247 218
24X Fiche 50-259, 83/02/11, 8302230411

--8302230414 Proposed Tech Specs deleting environ reporting requirements
* Tennessee Valley Authority 83/02/11 31pp 17247 220 24X
Fiche 50-259, 83/02/11, 8302230411

8302230143 Forwards revised Figure B 4-1a of FSAR for insertion
Existing Figure B 4-1a contains safeguards info & should be
destroyed
MILLS, L M Tennessee Valley Authority 83/02/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17243 217
24X Fiche 50-259, 83/02/17, 8302230143

8302230692 Responds to 830111 request to identify proprietary info in
technical evaluation repts on environ qualification of
electrical equipment Investigation still underway Partial
list of proprietary info encl
MILLS, L M Tennessee Valley Authority 83/02/17 VASSALLO, D B
Operating Reactors Branch 2 5pp 17248 328 24X
Fiche 50-259, 83/02/17, 8302230692

0 Inspection reports, IE Bulletins & correspondence

8302150021 Forwards IE Insp Repts 50-259/82-40, 50-260/82-40 &
50-296/82-40 on 821122-24 & 30-1203 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/05
PARRIS, H O Tennessee Valley Authority 2pp 17148 040 24X
Fiche 50-259, 83/01/05, 8302150021

--8302150024 IE Insp Repts 50-259/82-40, 50-260/82-40 & 50-296/82-40 on
821122-24 & 30-1203 No noncompliance noted Major areas
inspected IE Bulletin 82-03, Rev 1, observation of inservice
insp work & activities & review of procedures
COLEY, J L, BLAKE, J J Division of Project & Resident Programs
82/12/30 7pp 17148 042 24X Fiche 50-259, 83/01/05, 8302150021

8301180127 Forwards info requested in NRC 821115 ltr re IE Bulletin
80-04, "ESF Reset Controls"
MILLS, L M Tennessee Valley Authority 83/01/13 VASSALLO, D B
Operating Reactors Branch 2 3pp 16832 118 24X
Fiche 50-259, 83/01/13, 8301180127

8302150065 Updates 821209 response to IE Bulletin 82-03, "Stress
Corrosion Cracking in Thick Wall, Large Diameter Stainless
Steel, Recirculation Sys Piping at BWR Plants"
MILLS, L M Tennessee Valley Authority 83/01/14 O'REILLY, J P
Region 2, Office of Director 9pp 17145 334 24X
Fiche 50-259, 83/01/14, 8302150065

8302150671 Ack receipt of 830111 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/82-39,
50-260/82-39 & 50-296/82-39
LEWIS, R C Division of Project & Resident Programs 83/01/19
PARRIS, H O Tennessee Valley Authority 1p 17151 336 24X
Fiche 50-259, 83/01/19, 8302150671

--8302150681 Responds to NRC 821217 ltr re violations noted in IE Insp
Repts 50-259/82-39, 50-260/82-39 & 50-296/82-39 Corrective
actions observation & updating of radwaste packaging &
shipping program will be continued
MILLS, L M Tennessee Valley Authority 83/01/11 O'REILLY, J P
Region 2, Office of Director 3pp 17151 337 24X
Fiche 50-259, 83/01/19, 8302150671

--8302150698 Forwards IE Insp Repts 50-259/82-39, 50-260/82-39 &
50-296/82-39 on 821025-26 Enforcement action addressed in
JP O'Reilly 821217 ltr
VERRELLI, D M Division of Project & Resident Programs 82/12/17
PARRIS, H O Tennessee Valley Authority 2pp 17151 344 24X
Fiche 50-259, 83/01/19, 8302150671

--8302150710 IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-296/82-39 on
821025-26 Noncompliance noted Failure to ascertain that
closure devices of eight 55-gallon drums free from defects
COLLINS, T R, BARR, K P Division of Engineering & Radiological
Safety Programs 82/10/29 5pp 17191 346 24X
Fiche 50-259, 83/01/19, 8302150671

8302190610 Responds to IE Bulletin 82-04, "Deficiencies in Primary
Containment Electrical Penetration Assemblies" & NRC
821203 ltr Dunker-Remo Co electrical penetration assemblies
not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302190610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302100160 Forwards Franklin Research Ctr request for addl info on util
response to IE Bulletin 80-11 re masonry wall design
Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/01/28 PARRIS, H O
Tennessee Valley Authority 5pp 17134 265 24X
Fiche 50-259, 83/01/28, 8302100160

8302130309 Ack receipt of 821124 & 830110 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-259/82-33, 50-260/82-33 & 50-296/82-33 Interpretation of
ASME INP-6210 requirements will be provided
LEWIS, R C Division of Project & Resident Programs 83/01/28
PARRIS, H O Tennessee Valley Authority 1p 17148 222 24X
Fiche 50-259, 83/01/28, 8302130309

--8302130317 Responds to NRC 821021 ltr re violations noted in IE Insp
Repts 50-259/82-33, 50-260/82-33 & 50-296/82-33 Corrective
actions listing reflecting status of pump & valve test
program will be maintained in central location & updated
MILLS, L M Tennessee Valley Authority 83/01/10 O'REILLY, J P
Region 2, Office of Director, 3pp 17148 223 24X
Fiche 50-259, 83/01/28, 8302130309

--8302130326 Responds to NRC 821021 ltr re violations noted in IE Insp
Repts 50-259/82-33, 50-260/82-33 & 50-296/82-33 Corrective
actions all NDE procedures reviewed for compliance w/
applicable ASME Code specs
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P
Region 2, Office of Director 6pp 17148 226 24X
Fiche 50-259, 83/01/28, 8302130309

--8302150331 Forwards IE Insp Repts 50-259/82-33, 50-260/82-33 &
50-296/82-33 on 820928-1001 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/10/21
PARRIS, H O Tennessee Valley Authority 2pp 17148 232 24X
Fiche 50-259, 83/01/28, 8302150309

--8302150336 Notice of violation from insp on 820928-1001
* Division of Project & Resident Programs 82/10/21 2pp.
17148 234 24X Fiche 50-259, 83/01/28, 8302150309

--8302150342 IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-296/82-33 on
820928-1001 Noncompliance noted inadequate NDE procedures &
Failure to maintain summary status lists & increase test
frequency
OIRARD, E H, BLAKE, J J Division of Engineering & Radiological
Safety Programs 82/10/15 8pp 17148 236 24X
Fiche 50-259, 83/01/28, 8302150309

8302130325 Forwards IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01
& 50-296/83 01 on 830103-07 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/02/07
PARRIS, H O Tennessee Valley Authority 2pp 17157 167 24X
Fiche 50-259, 83/02/07, 8302130325

--8302150346 IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 &
50-296/83 01 on 830103-07 No noncompliance noted Major areas
inspected security plan & implementing procedures & security
program audit Details withheld (ref 10CFR73 21)
MOORE, D E, STANSBERRY, W W, MCQUIRE, D R. Division of Emergency
Preparedness & Materials Safety 83/02/03 1p 17157 169 24X
Fiche 50-259, 83/02/07, 8302150325

8302170505 Forwards draft input for BALP evaluation for CV82 Evaluation
based on experience w/licenses, util & input solicited from
staff Review & comments requested
CLARK, D Operating Reactors Branch 2 83/02/10 EISENHUT, D O
Division of Licensing SPEIS, T, MATSON, R J Division of Systems
Integration (post 81005) 7pp 17197 088 24X
Fiche 50-259, 83/02/10, 8302170505

DOCKETED ITEMS

8302230344 Forwards 830111 response to IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-296/82-39 & proposed imposition of civil penalties Response inadvertently sent to Region 1f
MILLER, L M Tennessee Valley Authority 83/02/10 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
17247, 001 24X Fiche 50-259, 83/02/10, 8302230344

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17341 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302010217 Forwards updated LER 82-057/03X-1
GREEN, H J Tennessee Valley Authority 83/01/26 O'REILLY, J P
Region 2, Office of Director 1p 16974 040 24X
Fiche 50-259, 83/01/26, 8302010217

--8302010227 Updated LER 82-057/03X-1 on 820816, coil for relay 16A-X72
failed Caused by coil burning out Coil replaced
MURPHY, D E Tennessee Valley Authority 83/01/26 Region 2,
Office of Director 2pp 16974 041 24X Fiche 50-259, 83/01/26,
8302010217

8302030567 Forwards LER 82-101/03L-0
GREEN, H J Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 1p 17008 013 24X
Fiche 50-259, 83/01/28, 8302030567

--8302030577 LFR 82-101/03L-0 on 821229, offgas post-treatment radiation
monitor L-RH-90-265 failed in downscale tripped condition
Caused by failed 15-volt regulator (GE 194X36361) Regulator
replaced & monitor returned to svc
CHAMBERS, G T Tennessee Valley Authority 83/01/28 Region 2,
Office of Director 2pp 17008 014 24X Fiche 50-259, 83/01/28,
8302030567

8302150139 PNO-11-83-008 on 830205, during turbine overspeed tests, scram
occurred resulting in initiation of main steam isolation
function & failure of one steam safety relief valve to
close Cause unknown Leakage vacuum breaker replaced
BUTCHER, R C, VERRELLI, D H Region 2, Office of Director 83/02/07
2pp 17147 249 24X Fiche 50-259, 83/02/07, 8302150139

8302150475 Telecopy message of RD 50-259/83006 on 830205, relief valve
PCV 1-22 failed to reset fully after actuation to control
reactor pressure Probably caused by excessive leakage of
pilot valve. Pilot valve & solenoid actuator replaced
JOHNS, G T Tennessee Valley Authority 83/02/07 Region 2,
Office of Director 1p 17157 112 24X Fiche 50-259, 83/02/07,
8302150475

8302170343 Forwards LER 83-001/03L-0
GREEN, H J Tennessee Valley Authority 83/02/10 O'REILLY, J P
Region 2, Office of Director 1p 17184 178 24X
Fiche 50-259, 83/02/10, 8302170343

--8302170348 LER 83-001/03L-0 on 830110, pressure switch 1-PE-75-7 found
to have setpoint of 174 psi Tech Spec requires setpoint to
be 165 + 10 psi Caused by setpoint drift Mercoid switch
recalibr
BASS, G Tennessee Valley Authority 83/02/10 Region 2, Office
of Director 2pp 17184 179 24X Fiche 50-259, 83/02/10,
8302170343

8302230609 Forwards LER 83-002/03L-0
GREEN, H J Tennessee Valley Authority 83/02/15 O'REILLY, J P
Region 2, Office of Director 1p 17255 202 24X
Fiche 50-259, 83/02/15, 8302230609

--8302230622 LER 83-002/03L-0 on 830117, during surveillance insp, control
rod 10-39 failed to operate at position 46 Probably caused
by crud accumulation in valve flow orifice Insert
directional control valve replaced
WINDO, M D Tennessee Valley Authority 83/02/15 Region 2,
Office of Director 2pp 17255 203 24X Fiche 50-259, 83/02/15,
8302230609

8302280354 Forwards LER 83-006/01T-0
GREEN, H J Tennessee Valley Authority 83/02/18 O'REILLY, J P
Region 2, Office of Director 1p 17311 085 24X
Fiche 50-259, 83/02/18, 8302280354

--8302280369 LER 83-006/01T-0 on 830205, following reactor scram, main
steam relief valve 1-1-22 manually opened & failed to close
On 830208, valve opened at 178 psig Caused by excessive pilot
valve leakage & broken bracket for pilot inlet tube
HOLDER, E Tennessee Valley Authority 83/02/18 Region 2,
Office of Director 2pp 17311 086 24X Fiche 50-259, 83/02/18,
8302280354

8302280472 Forwards LER 83-004/03L-0
GREEN, H J Tennessee Valley Authority 83/02/22 O'REILLY, J P
Region 2, Office of Director 1p 17309 237 24X
Fiche 50-259, 83/02/22, 8302280472

--8302280481 LER 83-004/03L-0 on 830124, recirculation pump 1A increases
speed, was manually tripped & would not restart Caused by
broken Heim joint within hydraulic coupler which allowed
full coupling of motor & generator joint replaced
WILLIAMSON, B T Tennessee Valley Authority 83/02/22 Region
2, Office of Director 2pp 17309 238 24X Fiche 50-259,
83/02/22, 8302280472

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for CLAs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHART, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

X Onsite Storage of Low Level Waste

8302090205 Forwards License 01-21075-01 & notice of issuance License
authorizes 5-yr term to receive, possess, store & transfer low
level radwaste at onsite storage facility
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
PARRIS, H O Tennessee Valley Authority 2pp 17132 069 24X
Fiche 50-259, 83/01/27, 8302090205

--8302090213 License 01-21075-01 for TVA, authorizing 5-yr term for
receipt, possession, storage & transfer of low level radwaste
at onsite storage facility
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
3pp 17132 070 24X Fiche 50-259, 83/01/27, 8302090205

--8302090222 Notice of issuance of License 01-21075-01 & negative
declaration for onsite storage of low level radwaste
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
3pp 17132 073 24X Fiche 50-259, 83/01/27, 8302090205

830220035 informs that FR notice, published 830203, re issuance of tails
license & negative declaration for onsite storage of low
level radwaste, contained typographical error Dockets should
be 30-19102, 90-259, 260 & 296
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/02/08
PARRIS, H O Tennessee Valley Authority 2pp 17227 346 24X
Fiche 50-259, 83/02/08, 830220035

DOCKET 90-260 BROWN'S FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8302030057 Releases public version of revised radiological emergency
notification directory
FELTON, J M Division of Rules and Records 83/01/28 Document
Management Branch 1p 17026 344 24X Fiche 50-259, 83/01/28,
8302030057

--8302030062 Forwards public version of Rev B to radiological emergency
notification directory
MILLER, L M Tennessee Valley Authority 83/01/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 17026 345
24X Fiche 50-259, 83/01/28, 8302030057

--8302030065 Public version of Rev B to radiological emergency
notification directory
Tennessee Valley Authority 82/12/16 15pp 17026 351 24X
Fiche 50-259, 83/01/28, 8302030057

8302030627 Releases public version of revised radiological emergency
notification directory
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17013 320 24X Fiche 50-259, 83/01/31,
8302030627

--8302030628 Forwards public version of Rev 9 to radiological emergency notification directory
MILLS, L M Tennessee Valley Authority 83/01/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17013 321
24X Fiche 50-259, 83/01/31, 8302030627

--8302030629 Public version of Rev 9 to radiological emergency notification directory
SLIOER, E K Tennessee Valley Authority 83/01/06 5pp
17013 322 24X Fiche 50-259, 83/01/31, 8302030627

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302100330 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to add requirement to audit safeguards contingency plan at least once every 12 months per Generic Ltr 82-23
MILLS, L M Tennessee Valley Authority 83/02/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17116 314
24X Fiche 50-259, 83/02/01, 8302100330

--8302100332 Proposed Tech Specs requiring audit of safeguards contingency plan at least once every 12 months
* Tennessee Valley Authority 83/02/01 4pp 17116 316 24X
Fiche 50-259, 83/02/01, 8302100330

8302140076 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/02/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17141 212 24X
Fiche 50-259, 83/02/04, 8302140076

8302170225 Grants exemption from 10CFR50 4B & App R to 10CFR50 requirements re fire protection, per 830626 request
VASSALLO, D B Operating Reactors Branch 2 83/02/04 PARRIS, H Q
Tennessee Valley Authority 2pp 17195 360 24X
Fiche 50-259, 83/02/04, 8302170225

--8302170229 Exemption from 10CFR50 4B & App R to 10CFR50 requirements re fire protection
EISENHUT, D O Division of Licensing 83/02/04 Tennessee Valley Authority 7pp 17195 362 24X Fiche 50-259, 83/02/04, 8302170225

8302150325 Forwards IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/02/07 PARRIS, H Q Tennessee Valley Authority 2pp 17197 167 24X
Fiche 50-259, 83/02/07, 8302150325

--8302150346 IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted Major areas inspected, security plan & implementing procedures & security program audit Details withheld (ref 10CFR73 21)
MOORE, D E Division of Emergency Preparedness & Materials Safety 83/02/03 1p 17157 169 24X Fiche 50-259, 83/02/07, 8302150325

F Operating license stage documents & correspondence

8302010614 Forwards item-by-item description of responses to NRC 82102B conference call request for info re compliance w/NUREG-0612, Section 3.1, "General Provisions for Load Handling," requirements
KAMMER, D S Tennessee Valley Authority 83/01/25 VASSALLO, D B
Operating Reactors Branch 2 4pp 16980 273 24X
Fiche 50-259, 83/01/25, 8302010614

8302070087 Forwards safety evaluation re NRC review of util response to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Util endorsement of BWR Owners Group position considered acceptable & matter resolved
VASSALLO, D B Operating Reactors Branch 2 83/01/25, PARRIS, H Q
Tennessee Valley Authority 2pp 17065 293 24X
Fiche 50-259, 83/01/25, 8302070087

--8302070107 Safety evaluation re BWR Owners Group generic response to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" No mods to seal cooling for recirculation pumps required
HODGES, W Operating Reactors Branch 2 82/12/01 5pp
17065 295 24X Fiche 50-259, 83/01/25, 8302070087

8302100330 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to add requirement to audit safeguards contingency plan at least once every 12 months per Generic Ltr 82-23
MILLS, L M Tennessee Valley Authority 83/02/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17116 314
24X Fiche 50-259, 83/02/01, 8302100330

--8302100332 Proposed Tech Specs requiring audit of safeguards contingency plan at least once every 12 months
* Tennessee Valley Authority 83/02/01 4pp 17116 316 24X
Fiche 50-259, 83/02/01, 8302100330

8302170498 Requests schedule for completing TMI Action Items II, F.1.1 & II F.1.2 per Generic Ltrs 82-05 & 82-10 Justification for delay in installing monitors required
VASSALLO, D B Operating Reactors Branch 2 83/02/01 PARRIS, H Q
Tennessee Valley Authority 3pp 17203 191 24X
Fiche 50-259, 83/02/01, 8302170498

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - OPU Service Corp 5pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302170165 Forwards NEDO-30053, "Evaluation of Recirculation Manifold Indications in Browns Ferry Nuclear Power Plant, Unit 2"
MILLS, L M Tennessee Valley Authority 83/02/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17180 222 24X
Fiche 50-260, 83/02/08, 8302170165

--8302170170 "Evaluation of Recirculation Manifold Indications in Browns Ferry Nuclear Power Plant, Unit 2"
RANGANATH, B General Electric Co NEDO-30053 83/02/28 30pp
14180 223 24X Fiche 50-260, 83/02/08, 8302170165

8302230411 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, deleting environ reporting requirement
MILLS, L M Tennessee Valley Authority 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17247 218
24X Fiche 50-259, 83/02/11, 8302230411

--8302230414 Proposed Tech Specs deleting environ reporting requirements.
* Tennessee Valley Authority 83/02/11 31pp 17247 226 24X
Fiche 50-259, 83/02/11, 8302230411

8302230143 Forwards revised Figure B 4-1a of FSAR for insertion
Existing Figure B 4-1a contains safeguards info & should be destroyed
MILLS, L M Tennessee Valley Authority 83/02/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17243 217
24X Fiche 50-259, 83/02/17, 8302230143

8302230682 Responds to 830111 request to identify proprietary info & technical evaluation repts on environ qualification of electrical equipment, investigation still underway. Partial list of proprietary info encl
MILLS, L M Tennessee Valley Authority 83/02/17, VASSALLO, D B
Operating Reactors Branch 2 5pp 17248 328 24X
Fiche 50-259, 83/02/17, 8302230682

DOCKETED ITEMS

0 Inspection reports, IE Bulletins & correspondence

8302150021 Forwards IE Insp Repts 50-259/82-40, 50-260/82-40 & 50-276/82-40 on 821122-24 & 30-1203 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/03
PARRIS, H Q Tennessee Valley Authority 2pp 1714B 040 24X
Fiche 50-259, 83/01/03, 8302150021

--8302150024 IE Insp Repts 50-259/82-40, 50-260/82-40 & 50-276/82-40 on 821122-24 & 30-1203 No noncompliance noted Major areas inspected IE Bulletin 82-03, Rev 1, observation of inservice insp work & activities & review of procedures
COLEY, J L, BLAKE, J J Division of Project & Resident Programs 82/12/30 7pp 1714B 042 24X Fiche 50-259, 83/01/03, 8302150021

8301180127 Forwards info requested in NRC 821115 ltr re IE Bulletin 80-04, "ESF Reset Controls"
MILLS, L M Tennessee Valley Authority 83/01/13 VASSALLO, D B Operating Reactors Branch 2 3pp 16832 118 24X
Fiche 50-259, 83/01/13, 8301180127

8302150065 Updates 821209 response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large Diameter Stainless Steel Recirculation Bys Piping at BWR Plants"
MILLS, L M Tennessee Valley Authority 83/01/14 O'REILLY, J P Region 2, Office of Director 9pp 1714B 354 24X
Fiche 50-259, 83/01/14, 8302150065

8302150671 Ack receipt of 830111 ltr (informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39
LEWIS, R C Division of Project & Resident Programs 83/01/19 PARRIS, H Q Tennessee Valley Authority 1p 17151 336 24X
Fiche 50-259, 83/01/19, 8302150671

--8302150681 Responds to NRC 821217 ltr re violations noted in IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 Corrective actions observation & updating of radwaste packaging & shipping program will be continued
MILLS, L M Tennessee Valley Authority 83/01/11 O'REILLY, J P Region 2, Office of Director 3pp 17151 337 24X
Fiche 50-259, 83/01/19, 8302150671

--8302150698 Forwards IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 on 821025-26 Enforcement action addressed in JP O'Reilly 821217 ltr
VERRELLI, D M Division of Project & Resident Programs 82/12/17 PARRIS, H Q Tennessee Valley Authority 2pp 17151 344 24X
Fiche 50-259, 83/01/19, 8302150671

--8302150710 IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 on 821025-26 Noncompliance noted, failure to ascertain that closure devices of eight 55-gallon drums free from defects
COLLINS, T R, BARR, K P Division of Engineering & Radiological Safety Programs 82/10/29 5pp 17151 346 24X
Fiche 50-259, 83/01/19, 8302150671

8302150035 Forwards rept of in-vessel insps on 820830 required by IE Bulletin 80-13. No abnormalities found
KAMMER, D S Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 17155:235 24X
Fiche 50-260, 83/01/24, 8302150035

8302150047 Advises that 20 jet pump beam holddown bolt assemblies replaced Svc life of improved assemblies will exceed svc life of facility, per NEDE-24362-1 IE Bulletin 80-07 no longer applicable
KAMMER, D S Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 1714B 035 24X
Fiche 50-260, 83/01/24, 8302150047

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302150610

212060339 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060339

212060360 IE Info Notice 83-02, "Limitation H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302100160 Forwards Franklin Research Ctr request for addl info on util response to IE Bulletin 80-11 re masonry wall design
Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/01/28 PARRIS, H Q Tennessee Valley Authority 5pp 17134 265 24X
Fiche 50-259, 83/01/28, 8302100160

8302150309 Ack receipt of 821124 & 830110 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 Interpretation of ASME 1WP-6210 requirements will be provided
LEWIS, R C Division of Project & Resident Programs 83/01/28 PARRIS, H Q Tennessee Valley Authority 1p 1714B 222 24X
Fiche 50-259, 83/01/28, 8302150309

--8302150317 Responds to NRC 821021 ltr re violations noted in IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 Corrective actions listing reflecting status of pump & valve test program will be maintained in central location & updated
MILLS, L M Tennessee Valley Authority 83/01/10 O'REILLY, J P Region 2, Office of Director 3pp 1714B 223 24X
Fiche 50-259, 83/01/28, 8302150309

--8302150326 Responds to NRC 821021 ltr re violations noted in IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 Corrective actions all NDE procedures reviewed for compliance w/ applicable ASME Code specs
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 6pp 1714B 226 24X
Fiche 50-259, 83/01/28, 8302150309

--8302150331 Forwards IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 on 820928-1001 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/10/21 PARRIS, H Q Tennessee Valley Authority 2pp 1714B 232 24X
Fiche 50-259, 83/01/28, 8302150309

--8302150336 Notice of violation from insp on 820928-1001
Division of Project & Resident Programs 82/10/21 2pp 1714B 234 24X Fiche 50-259, 83/01/28, 8302150309

--8302150342 IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 on 820928-1001 Noncompliance noted inadequate NDE procedures & failure to maintain summary status lists & increase test frequency
O'IRARD, E H, BLAKE, J J Division of Engineering & Radiological Safety Programs 82/10/15 8pp 1714B 236 24X
Fiche 50-259, 83/01/28, 8302150309

8302150325 Forwards IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/02/07 PARRIS, H Q Tennessee Valley Authority 2pp 17157 167 24X
Fiche 50-259, 83/02/07, 8302150325

--8302150346 IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted Major areas inspected security plan & implementing procedures & security program audit details withheld (ref 10CFR73.21)
MOORE, D E, STANSBERRY, W W, MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/02/03 1p 17157 169 24X
Fiche 50-259, 83/02/07, 8302150325

8302170505 Forwards draft input for SALP evaluation for CY82 Evaluation based on experience w/ licensee, util & input solicited from staff Review & comments requested
CLARK, D Operating Reactors Branch 2 83/02/10 EISENHUT, D O Division of Licensing SPEIS, T, MATTSO, R J Division of Systems Integration (post 811005) 7pp 17197 088 24X
Fiche 50-259, 83/02/10, 8302170505

8302230344 Forwards 830111 response to IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 & proposed imposition of civil penalties Response inadvertently sent to Region II.
MILLS, L M Tennessee Valley Authority 83/02/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 17247 001 24X Fiche 50-259, 83/02/10, 8302230344

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

DOCKETED ITEMS

65

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302140004 Forwards updated LER 82-026/03X-2
GREEN, H J Tennessee Valley Authority 83/01/31 O'REILLY, J P
Region 2, Office of Director ip 17142 155 24X
Fiche 50-260, 83/01/31, 8302140004

--8302140005 Updated LER 82-026/03X-2 on 820819, during refueling outage for preventive maint, recirculation sys hydraulic snubber
SSIA found low on fluid Caused by leakage at O-rings
Snubbers rebuilt O-ring seals replaced
HOLDER, E Tennessee Valley Authority 83/01/31 Region 2,
Office of Director 7pp 17142 156 24X Fiche 50-260, 83/01/31,
8302140004

8302140144 Forwards updated LER 82-035/03X-1
GREEN, H J Tennessee Valley Authority 83/01/31 O'REILLY, J P
Region 2, Office of Director ip 17140 167 24X
Fiche 50-260, 83/01/31, 8302140144

--8302140150 Updated LER 82-035/03X-1 on 821101, during refueling outage, while performing Surveillance Insp 4 & H-2, upper mechanical snubber on main steam line D found inoperable Snubber replaced Engineering analysis encl
HOLDER, E Tennessee Valley Authority 83/01/31 Region 2,
Office of Director 7pp 17140 168 24X Fiche 50-260, 83/01/31,
8302140144

8302170048 Telecopy message of RO 50-260-8302 on 830208, pressure switches PS-68-96, PS-3-74A & PS-3-74B found out of Tech Spec limits during performance of Surveillance instruction 4 2 B-7 Caused by setpoint drift Switches recalibr
JONES, O T Tennessee Valley Authority 83/02/09 Region 2,
Office of Director ip 17183 063 24X Fiche 50-260, 83/02/09,
8302170048

8302230567 Forwards revised LER 82-027/01X-1
GREEN, H J Tennessee Valley Authority 83/02/15 O'REILLY, J P,
Region 2, Office of Director ip 17256 250, 24X
Fiche 50-260, 83/02/15, 8302230567

--8302230578 Revised LER 82-027/01X-1 on 820901, during Cycle 4 refueling outage, 6 of 11 2-stage relief valves tested failed to lift within allowable 1% tolerance Cause will be determined by Target Rock Valves will be repaired, reset & retested
ORIFFIN, A Tennessee Valley Authority 83/02/15, Region 2,
Office of Director 3pp 17256 251 24X Fiche 50-260, 83/02/15,
8302230567

8302230192 FND-II-83-010 on 830216, while conducting integrated leak rate test, spurious signals on low reactor vessel water level & high drywell pressure initiated four core spray & RHR pumps & eight diesel generators Cause under investigation
BUTCHER, R C, CANTRELL, F S Region 2, Office of Director 83/02/17
2pp 17244 001 24X Fiche 50-260, 83/02/17, 8302230192

8302280175 Forwards LER 83-002/01T-0
GREEN, H J Tennessee Valley Authority, 83/02/18 O'REILLY, J P
Region 2, Office of Director ip 17305 268 24X
Fiche 50-260, 83/02/18, 8302280175

--8302280184 LER 83-002/01T-0 on 830208, during preparation for startup, pressure switches PS-68-96 switch 1, PS-3-74A switch 1 & PS-3-74B switches 1 & 2 operated at 199 7, 208, 43, 208 43 & 471.43, psi, respectively Caused by instrument drift
CHAMBERG, O Tennessee Valley Authority 83/02/18 Region 2,
Office of Director 3pp, 17305 269 24X Fiche 50-260, 83/02/18,
8302280175

V. Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licensees, Svc list encl
EISENHUT, D G Division of Licensing, 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

X Onsite Storage of Low Level Waste

8302090205 Forwards License 01-21075-01 & notice of issuance License authorizes 5-yr term to receive, possess, store & transfer low level radwaste at onsite storage facility
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
PARRIS, H O Tennessee Valley Authority 2pp 17132 068 24X
Fiche 50-259, 83/01/27, 8302090205

--8302090213 License 01-21075-01 for TVA, authorizing 5-yr term for receipt, possession, storage & transfer of low level radwaste at onsite storage facility
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
3pp 17132 070 24X Fiche 50-259, 83/01/27, 8302090205

--8302090222 Notice of issuance of License 01-21075-01 & negative declaration for onsite storage of low level radwaste
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
3pp 17132 073 24X Fiche 50-259, 83/01/27, 8302090205

8302220035 Informs that FR notice, published 830203, re issuance of matn license & negative declaration for onsite storage of low level radwaste, contained typographical error Dockets should be 30-19102, 50-259, 260 & 296
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/02/08
PARRIS, H O Tennessee Valley Authority, 2pp 17227 346, 24X
Fiche 50-259, 83/02/08, 8302220035

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8302150412 Forwards IE Insp Rept 50-261/82-33 on 820920-24 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/11/02
UTLEY, E E Carolina Power & Light Co 2pp 17157 151 24X
Fiche 50-261, 82/11/02, 8302150412

--8302150413 Notice of violation from insp on 820920-24
* Division of Project & Resident Programs 82/11/02 3pp,
17157 153 24X Fiche 50-261, 82/11/02, 8302150412

--8302150416 IE Insp Rept 50-261/82-33 on 820920-24, Noncompliance noted: failure to conduct & distribute audits within time required by Tech Specs, failure to respond to audits, failure to correctly categorize audit finding & store records
BELISLE, O A, JACKSON, L H, UPRIGHT, C M Division of Engineering & Radiological Safety Programs 82/10/21 10pp, 17157 156 24X
Fiche 50-261, 82/11/02, 8302150412

8302150374 Responds to NRC ltr re violations noted in IE Investigation Rept 50-261/82-33 Corrective actions corporate QA mgt will review audit schedule monthly & dedicated fire protection organization will ensure triannual fire insp
UTLEY, E E Carolina Power & Light Co 82/12/02 O'REILLY, J P
Region 2, Office of Director 7pp 17157 270 24X
Fiche 50-261, 82/12/02, 8302150374

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302100290 Application for amend to License DPR-23, proposing Tech Spec changes to incorporate radiological ETB & requirements to perform audits of emergency preparedness program & security plan per Generic Ltrs 82-17 & 82-23,
EURY, L W Carolina Power & Light Co 83/02/07 VARGA, S A,
Operating Reactors Branch 1, 2pp 17111 136 24X
Fiche 50-261, 83/02/07, 8302100290

--8302100293 Proposed Tech Specs incorporating radiological ETB & requirements to perform audits of emergency preparedness program & security plan
* Carolina Power & Light Co 83/02/07, 107pp 17111 138, 24X
Fiche 50-261, 83/02/07, 8302100290

G. Adjudicatory correspondence

8302070582 Request for reconsideration of ASLB 830121 order scheduling 830324 special prehearing conference & setting 830224 as date to file contentions Affidavit of svc encl,
KIRVEN, J Affiliation Unknown 83/02/02 Atomic Safety and
Licensing Board Panel 4pp 17035 023 24X Fiche 50-261, 83/02/02,
8302070582

DOCKETED ITEMS

8302080252 Motion for reconsideration of ASLB 830101 order establishing prehearing conference dates Current date undercuts ability to prepare suppl fully & fairly Order received 1 wk after issuance Affidavit of Svc encl
MATTHEWS, B A Affiliation Unknown 83/02/03 Atomic Safety and Licensing Board Panel 5pp 17057 098 24X Fiche 50-261,83/02/03, 8302080252

8302160344 Response opposing Hartsville Group & Concerned Fools of Darlington County motions to extend dates for filing contentions & for prehearing conference Time allowed for filing more than enough W/Certificate of Svc
TROWBRIDGE, G F Carolina Power & Light Co TROWBRIDGE, G F Shaw, Pittman, Potts & Troubridge 83/02/10 Atomic Safety and Licensing Board Panel 7pp 17166 270 24X Fiche 50-261,83/02/10, 8302160344

8302170271 Order ruling on requests for changes to special prehearing conference schedule Hearing date & place remain unchanged Time extended until 830301 for petitioners to file contentions
MARQUILLES, M B Atomic Safety and Licensing Board Panel 83/02/15 3pp 17178 218 24X Fiche 50-261,83/02/15, 8302170271

8302180389 Response to Hartsville Group & Concerned Fools of Darlington County 830202 & 03 motions for continuance & request for reconsideration of order scheduling prehearing conference One-wk extension should be granted Certificate of Svc encl
KARHAN, M Hearing Branch 1 83/02/16 Atomic Safety and Licensing Board Panel 3pp 17209 352 24X Fiche 50-261,83/02/16, 8302180389

P Operating license stage documents & correspondence

8302170434 Requests submittal, within 60 days, describing flux reduction measures initiated & addl measures being considered per pressurized thermal shock studies
VARGA, S A Operating Reactors Branch 1 83/02/01 UTLEY, E E Carolina Power & Light Co 5pp 17205 144 24X Fiche 50-261,83/02/01, 8302170434

8302090117 Advises that NRR has rendered amended fee determination stating that review of steam generator replacement program will involve review of complex issue rather than significant hazards consideration as stated in NRC 821230 ltr
MILLER, W D License Fee Management Branch 83/02/03 EURY, L W Carolina Power & Light Co 1p 17119 322 24X Fiche 50-261,83/02/03, 8302090117

8302170030 Forwards safety evaluation re purge/vent valve isolation dependability criteria of NUREG-0737, Items II E 4 2 6 & II E 4 2 7 Requirements for both items met
VARGA, S A Operating Reactors Branch 1 83/02/04 UTLEY, E E Carolina Power & Light Co 2pp 17191 041 24X Fiche 50-261,83/02/04, 8302170030

--8302170040 Safety evaluation of implementation of purge/vent valve isolation dependability criteria in Items II E 4 2 6 & II E 4 2 7 of NUREG-0737 Requirements met
FIELDS, M Operating Reactors Branch 1 83/02/04 1p 17191 043 24X Fiche 50-261,83/02/04, 8302170030

8302090434 Requests extension until 830701 to make post-accident sampling sys fully operational per NUREG-0737, Item II B 3 Extension will allow addl sys evaluation, field change resolution & implementation & final testing
HURFORD, W J Carolina Power & Light Co 83/02/07, VARGA, S A Operating Reactors Branch 1 2pp 17066 249 24X Fiche 50-261,83/02/07, 8302090434

8302100290 Application for amend to License DPR-23, proposing Tech Spec changes to incorporate radiological ETS & requirements to perform audits of emergency preparedness program & security plan per Generic Ltrs 82-17 & 82-23
EURY, L W Carolina Power & Light Co 83/02/07 VARGA, S A Operating Reactors Branch 1 2pp 17111 136 24X Fiche 50-261,83/02/07, 8302100290

--8302100293 Proposed Tech Specs incorporating radiological ETS & requirements to perform audits of emergency preparedness program & security plan
* Carolina Power & Light Co 83/02/07 107pp 17111 138 24X Fiche 50-261,83/02/07, 8302100290

8302160466 Informs that response to 820405-07 audit of procedures & training for pressurized thermal shock meets objectives
VARGA, S A Operating Reactors Branch 1 83/02/07, UTLEY, E E Carolina Power & Light Co 2pp 17176 290 24X Fiche 50-261,83/02/07, 8302160466

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for GL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000,83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000,83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5: "Automatic Trip of Reactor Coolant Pumps " Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000,83/02/08, 8302090085

8302150046 Documents results of 830125 meeting between util & NRC to resolve pressurized thermal shock issue Requests another meeting in early Mar to discuss methods of obtaining addl thermal margin in reactor core design
UTLEY, E E Carolina Power & Light Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 17146 011 24X Fiche 50-261,83/02/09, 8302150046

8302150617 Requests extension of out-of-svc period for B svc water booster pump from 24 h to 48 h Extension needed to complete repair to pump casing, due to vibration problem Pump casing will be replaced & pump returned to svc by 830209
STARKE, R B Carolina Power & Light Co 83/02/09 VARGA, S A Operating Reactors Branch 1 O'REILLY, J P Region 2, Office of Director 2pp 17151 315 24X Fiche 50-261,83/02/09, 8302150617

8302150709 Requests integrated schedule for issuance of steam generator repair license amend taking into account hearing process, per 830106 amend request Util should be ready to commence repair activities by Nov 1983
ZIMMERMAN, S R Carolina Power & Light Co 83/02/09 VARGA, S A Operating Reactors Branch 1 2pp 17151 357 24X Fiche 50-261,83/02/09, 8302150709

8302170387 Notification of 830302 meeting w/util in Bethesda, MD to discuss licensing organization, mgt of licensing open items & steam generator replacement scheduling
REGUA, O Operating Reactors Branch 1 83/02/09 VARGA, S A Operating Reactors Branch 1 2pp 17195 291 24X Fiche 50-261,83/02/09, 8302170387

8302180161 Forwards response to 821210 request for addl info re util submittal on NUREG-0737, Item II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication"
HURFORD, W J Carolina Power & Light Co 83/02/09, VARGA, S A Operating Reactors Branch 1 6pp 17216 118 24X Fiche 50-261,83/02/09, 8302180161

8302170075 Forwards request for addl info re TMI Items I A 2 1 4 & II B 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training & Qualification," & "Training for Mitigating Core Damage," respectively
VARGA, S A Operating Reactors Branch 1 83/02/10, UTLEY, E E Carolina Power & Light Co 3pp 17191 078 24X Fiche 50-261,83/02/10, 8302170075

8302150205 Reaffirms 810521 justification for operation re environ qualification of safety-related electrical equipment in response to NRC 830105 ltr & 830124 telcon
UTLEY, E E Carolina Power & Light Co 83/02/11, VASSALLO, D B Operating Reactors Branch 2 1p 17150 030 24X Fiche 50-261,83/02/11, 8302150205

8302180033 Summary of 830125 meeting w/util re pressurized thermal shock issue, Viewgraphs encl
REGUA, O Operating Reactors Branch 1 83/02/11 Operating Reactors Branch 1 58pp 17227 042 24X Fiche 50-261,83/02/11, 8302180033

8302180351 Forwards "Offsite Dose Calculation Manual" for use w/radiological ETS transmitted on 830207 Methodology to be placed on five blank pages will be finalized by 830415
ZIMMERMAN, S R Carolina Power & Light Co 83/02/11 VARGA, S A Operating Reactors Branch 1, 1p, 17211 007 24X Fiche 50-261,83/02/11, 8302180351

--8302180352 "Offsite Dose Calculation Manual"
* Carolina Power & Light Co 83/02/11 142pp 17211 008, 24X Fiche 50-261,83/02/11, 8302180351

DOCKETED ITEMS

8302250494 Forwards request for addl info for post-implementation review of NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re containment pressure, water level & hydrogen monitors Guidance encl Response requested within 30 days
VARQA, S A Operating Reactors Branch 1 83/02/14 UTLEY, E E
Carolina Power & Light Co 10pp 17303 146 24X
Fiche 50-261, 83/02/14, 8302250494

8302230270 Requests that all assumptions & info sources be documented for computer model & analyses performed as part of A-49, "Pressurized Thermal Shock," program Results should satisfy plant-specific analysis requirement
ZIMMERMAN, S R Carolina Power & Light Co 83/02/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp 17243 349
24X Fiche 50-261, 83/02/21, 8302230270

8302280360 Forwards corrected 830209 ltr in response to 830201 request for info presented in 830125 meeting re pressurized thermal shock Due to collating error, last page of Attachment 6 was omitted
ZIMMERMAN, S R Carolina Power & Light Co 83/02/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17311 088
24X Fiche 50-261, 83/02/24, 8302280360

--8302280363 Corrected ltr re pressurized thermal shock (PTS) Facility will not reach NRC PTS criteria until 1993 or later
UTLEY, E E Carolina Power & Light Co 83/02/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 52pp 17311 090
24X Fiche 50-261, 83/02/24, 8302280360

G Inspection reports, IE Bulletins & correspondence

8302150412 Forwards IE Insp Rept 50-261/82-33 on 820920-24 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/11/02
UTLEY, E E Carolina Power & Light Co 2pp 17157 151 24X
Fiche 50-261, 82/11/02, 8302150412

--8302150413 Notice of violation from insp on 820920-24
+ Division of Project & Resident Programs 82/11/02, 3pp
17157 153 24X Fiche 50-261, 82/11/02, 8302150412

--8302150416 IE Insp Rept 50-261/82-33 on 820920-24 Noncompliance noted failure to conduct & distribute audits within time required by Tech Specs, failure to respond to audits, failure to correctly categorize audit finding & store records
BELISLE, G A, JACKSON, L H, UPRIGHT, C M Division of Engineering & Radiological Safety Programs 82/10/21 10pp 17157 156 24X
Fiche 50-261, 82/11/02, 8302150412

8302150374 Responds to NRC ltr re violations noted in IE Investigation Rept 50-261/82-33 Corrective actions, corporate QA mgt will review audit schedule monthly & dedicated fire protection organization will ensure triannual fire insp
UTLEY, E E Carolina Power & Light Co 82/12/02 O'REILLY, J P
Region 2, Office of Director 7pp 17157 270 24X
Fiche 50-261, 82/12/02, 8302150374

8302150499 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-33
Response to notice of violation did not address total scope of Audit GAA/20-28 Concern 3 re E-15 & 18 deficiencies
LEWIS, R C Division of Project & Resident Programs 82/12/15
UTLEY, E E Carolina Power & Light Co 2pp 17156 328 24X
Fiche 50-261, 82/12/15, 8302150499

8302150290 Responds to NRC 821215 ltr re violations noted in IE Insp Rept 50-261/82-33 Corrective actions videotape on quality performance developed & used in training & Tech Spec revs & incoming regulatory requirements will be monitored by QA/QC
UTLEY, E E Carolina Power & Light Co 82/12/31 O'REILLY, J P
Region 2, Office of Director 3pp 17148 288 24X
Fiche 50-261, 82/12/31, 8302150290

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc. 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150380 Ack receipt of 821231 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-33
Violation E will be withdrawn & records revised accordingly
LEWIS, R C Division of Project & Resident Programs 83/01/27
UTLEY, E E Carolina Power & Light Co 1p 17158 174 24X
Fiche 50-261, 83/01/27, 8302150380

8212060360 IE Info Notice 83-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp, 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instrument Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150055 Forwards response to 821004 request for addl info re IE Bulletin 80-11, "Masonry Wall Design" Request 11 of technical evaluation re masonry wall mods completed
Analysis of missile shield wall expected by 830301
ZIMMERMAN, S R Carolina Power & Light Co. 83/02/04 VARQA, S A
Operating Reactors Branch 1 33pp 17146 164 24X
Fiche 50-261, 83/02/04, 8302150055

8302150028 Ack receipt of resubmitted 830113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-34
O'REILLY, J P Region 2, Office of Director 83/02/08, UTLEY, E
Carolina Power & Light Co 1p 17148 052 24X
Fiche 50-261, 83/02/08, 8302150028

--8302150031 Resubmits response to NRC 830103 ltr re violations not IE Insp Rept 50-261/82-34 Corrective actions, personnel counseled & necessity to maintain radiation monitoring device within high radiation area re-emphasized,
STARKEY, R B Carolina Power & Light Co 83/01/13, O'REILLY, J
Region 2, Office of Director 2pp, 17148 053 24X
Fiche 50-261, 83/02/08, 8302150028

8302150263 Responds to NRC 821210 request for addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels" Black water contains tannic acid from decaying organic matl
FURR, B J Carolina Power & Light Co 83/02/08 JORDAN, E L
Division of Engineering & Quality Assurance (Pre 830103), 2pp, 17148 331, 24X Fiche: 50-261, 83/02/08, 8302150263

8302150013 Ack receipt of 830203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-41
LEWIS, R C Division of Project & Resident Programs, 83/02/10
UTLEY, E E Carolina Power & Light Co 1p 17145 335, 24X
Fiche 50-261, 83/02/10, 8302150013

--8302150014 Responds to NRC 830107 ltr re violations noted in IE Insp Rept 50-261/82-41 Corrective actions, secondary chemistry monitoring program modified & Administrative Instruction 11 & re freeze protection sys revised
STARKEY, R B Carolina Power & Light Co. 83/02/03 O'REILLY, J
Region 2, Office of Director 3pp, 17145 336 24X
Fiche 50-261, 83/02/10, 8302150013

--8302150017 Forwards IE Insp Rept 50-261/82-41 on 821111-1210 & not of violation
LEWIS, R C Division of Project & Resident Programs, 83/01/07
UTLEY, E E Carolina Power & Light Co 2pp, 17145 339 24X
Fiche 50-261, 83/02/10, 8302150013

--8302150018 Notice of violation from insp on 821111-1210
+ Division of Project & Resident Programs 83/01/07, 2pp
17145 341 24X Fiche: 50-261, 83/02/10, 8302150013

--8302150022 IE Insp Rept 50-261/82-41 on 821111-1210 Noncompliance noted failure to take adequate corrective action re freeze protection & failure to establish chemistry procedures
WEISE, B, BENIS, P Division of Project & Resident Programs, 83/01/05 11pp, 17145 343, 24X Fiche: 50-261, 83/02/10, 8302150013

8302150079 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-37
LEWIS, R C Division of Project & Resident Programs 83/02/10,
UTLEY, E E Carolina Power & Light Co 1p, 17147 289, 24X
Fiche 50-261, 83/02/10, 8302150079

--8302150093 Responds to NRC 821223 ltr re violations noted in IE Insp Rept 50-261/82-37, Corrective actions: valve DQ-AB-10 closed w/operating work procedures to be revised by 830430 & low pressure alarm on backup nitrogen sys installed
STARKEY, R B Carolina Power & Light Co. 83/01/21, O'REILLY, J
Region 2, Office of Director, 4pp 17147 290, 24X
Fiche: 50-261, 83/02/10, 8302150079

--8302150109 Forwards IE Insp Rept 50-261/82-37 on 821011-1110 & not of violation & deviation,
LEWIS, R C Division of Project & Resident Programs 82/12/23,
UTLEY, E E Carolina Power & Light Co 2pp, 17147 294, 24X
Fiche: 50-261, 83/02/10, 8302150079

--8302150113 Notice of violation from insp on 821011-1110,
+ Division of Project & Resident Programs, 82/12/23, 1p,
17147 296 24X Fiche: 50-261, 83/02/10, 8302150079

DOCKETED ITEMS

--8302150118 Notice of deviation from insp on 821011-1110
 * Division of Project & Resident Programs 82/12/23 1p
 17147 298 24X Fiche 50-261,83/02/10,8302150079

--8302150128 IE Insp Rept 50-261/82-37 on 821011-1110 Noncompliance
 noted failure to reprim auxiliary feedwater flow indication,
 inadequate equipment control & failure to install low
 pressure alarm
 WEISE, S., BEMIS, P. Division of Project & Resident Programs
 82/12/15 12pp 17147 299 24X Fiche 50-261,83/02/10,8302150079

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co of New
 York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
 Very Low Level Radwaste - 10CFR20 302" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

R Periodic operating reports & related correspondence

8302170065 Forwards monthly operating rept for Jan 1983
 STARKEY, R. B. Carolina Power & Light Co 83/02/09 DEYOUNG, R. C.
 Director's Office, Office of Inspection and Enforcement 1p
 17182 317 24X Fiche 50-261,83/02/09,8302170065

--8302170070 Monthly operating rept for Jan 1983
 NORRIS, H. R. Carolina Power & Light Co 83/02/02 3pp.
 17182 318 24X Fiche 50-261,83/02/09,8302170065

G Reportable occurrences, LERs & related correspondence

8302010319 RD on 821220, reactor trip circuit breaker A failed to trip
 when trip signal initiated. Caused by sticking undervoltage
 relay. Relay replaced. Contacts cleaned.
 STARKEY, R. B. Carolina Power & Light Co 83/01/19 O'REILLY, J. P.
 Region 2, Office of Director 8pp 16973 080 24X
 Fiche 50-261,83/01/19,8302010319.

02150677 Forwards updated LER 81-027/03X-1
 STARKEY, R. B. Carolina Power & Light Co 83/02/08 O'REILLY, J. P.
 Region 2, Office of Director 1p 17194 118 24X
 Fiche 50-261,83/02/08,8302150677

--8302150683 Updated LER 81-027/03X-1 on 811115, RHR pump A declared
 inoperable due to 4 gpm leak resulting from pump shaft seal
 failure. Caused by incorrect seal matl. RHR pump A repaired w/
 correct seals.
 COV, H. T. Carolina Power & Light Co 83/02/08 Region 2, Office
 of Director 3pp 17154 119. 24X Fiche 50-261,83/02/08,
 8302150677

8302280217 Forwards LER 83-001/01L-0
 STARKEY, R. B. Carolina Power & Light Co 83/02/21 O'REILLY, J. P.
 Region 2, Office of Director 1p 17305 254 24X
 Fiche 50-261,83/02/21,8302280217

1302280222 LER 83-001/01L-0 on 830107, HWH-3 would not automatically
 restart on safety injection signal concurrent w/station
 blackout event w/out flow alarm signal present. Annunciator
 procedures revised. Mod for permanent repairs developed.
 COV, H. T. Carolina Power & Light Co 83/02/21 Region 2, Office
 of Director 3pp 17305 255 24X Fiche 50-261,83/02/21,
 8302280217

Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants
 for CLs, NSB vendors, reactor vendors & AE re certificates
 & revised format for reactor operator & senior reactor
 operator licenses. Svc list encl
 EISENHUT, D. G. Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347: 177 24X
 Fiche 50-000,83/01/31,8301310203

DOCKET 50-263 MONTECELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

8302040207 Forwards SER 50-263/82-17 supporting Jul 1982 emergency
 plan. Plan meets stds of 10CFR50 47(b) & App E to 10CFR50
 HIND, J. A. Division of Emergency Preparedness & Operational Support
 83/01/20 LARSON, C. E. Northern States Power Co 2pp 17021 334
 24X Fiche 50-263,83/01/20,8302040207

--8302040212 SER 50-263/82-17 supporting Jul 1982 emergency plan
 PATTERSON, J. P., SMITH, M. J., AXELSON, W. L. Division of Emergency
 Preparedness & Operational Support 83/01/14 28pp 17021 336
 24X Fiche 50-263,83/01/20,8302040207

8302030012 Releases public version of revised emergency plan
 implementing procedures
 FELTON, J. M. Division of Rules and Records 83/01/26 Document
 Management Branch 1p 17041 094 24X Fiche 50-000,83/01/26,
 8302030012

--8302030018 Forwards public version of revised emergency plan
 implementing procedures, including Procedures EPIP 1.1.3 re
 startup operation or emergency offsite facility & EPIP 1.1.6 re
 emergency organization shift turnover
 HARD, E. C. Northern States Power Co 83/01/20 Region 3, Office
 of Director 1p 17041 095 24X Fiche 50-000,83/01/26,
 8302030012

--8302030023 Public version of revised emergency plan implementing
 procedures, including Procedures EPIP 1.1.3 re startup
 operation of emergency offsite facility & EPIP 1.1.6 re
 emergency organization shift turnover
 HUDSON, G., HARD, E. Northern States Power Co 83/01/20 46pp
 17041 096 24X Fiche 50-000,83/01/26,8302030012

8302030025 Releases public version of revised emergency response plan
 implementing procedures
 FELTON, J. M. Division of Rules and Records 83/01/26 Document
 Management Branch 1p 17041 004 24X Fiche 50-263,83/01/26,
 8302030025

--8302030030 Forwards public version of revised emergency response plan
 implementing procedures, including Procedures A 2-420 re
 containment atmosphere radiochemical analysis & A 2-404 re
 airborne iodine sampling & analysis. Revised index encl
 HARD, E. C. Northern States Power Co 83/01/18 Region 3, Office
 of Director 8pp 17041 005 24X Fiche 50-263,83/01/26,
 8302030025

--8302030036 Public version of revised emergency response plan
 implementing procedures, including Procedures A 2-420 re
 containment atmosphere radiochemical analysis & A 2-404 re
 airborne iodine sampling & analysis
 FEY, F. L. Northern States Power Co 83/01/06 48pp 17041 011
 24X Fiche 50-263,83/01/26,8302030025

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
 applicants for CL & holders of CPs re regional workshop
 concerning Suppl 1, NUREG-0737, "Requirements for Emergency
 Response Capability" Svc list encl
 EISENHUT, D. G. Division of Licensing 83/02/01 Consolidated
 Edison Co of New York, Inc 11pp 17221 226 24X
 Fiche 50-000,83/02/01,8301210340

8302170108 Informs that 821210 request re changes to security
 plan acceptable
 VASSALLO, D. B. Operating Reactors Branch 2 83/02/07 HUSOLF, D. M.
 Northern States Power Co 1p 17191 105 24X Fiche 50-263,
 83/02/07,8302170108

8302150502 Suppl 820430 ltr re request for exemption from scheduler
 requirements per 10CFR50 48, App R. Extensive improvements in
 fire protection features made. Mods detailed
 HUSOLF, D. Northern States Power Co 83/02/08 Office of Nuclear
 Reactor Regulation, Director 8pp 17153 298 24X
 Fiche 50-263,83/02/08,8302150502

J Insurance & indemnity information

8302150548 Forwards Endorsements 44, 53 & 46 to NELIA Policies NF-174,
 NF-197 & MAELU Policies MF-31 & MF-68, respectively
 Endorsements 1, 2 & 3 to Certificates N-17, M-17, N-36, M-36,
 N-37 & M-37 also encl
 JOHNSON, R. O. Northern States Power Co 83/02/07 DINI, T. I.
 Antitrust & Economic Analysis Branch (Utility Finance) 59pp
 17196 152 24X Fiche 50-000,83/02/07,8302150548

DOCKETED ITEMS

8302150628 Requests review of govt indemnity agreements for Licenses DPR-42, DPR-60 & DPR-22 re refund due for unexpired term JOHNSON, R O Northern States Power Co 83/02/07 DINITZ, I Antitrust & Economic Analysis Branch (Utility Finance) 1p 17151 306 24X Fiche 50-000, 83/02/07, 8302150628

F Operating license stage documents & correspondence

8208040366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments EISENHUT, D O Division of Licensing 82/07/20 PALLADINO, N J Commissioners 4pp 17043 001 24X Fiche 50-000, 82/07/20, 8208040366

8302040513 Forwards revised "Process Control Program for Waste Solidification" Affidavit for withholding encl Program withheld (ref 10CFR2 790) MUSOLF, D Northern States Power Co 83/01/27 Office of Nuclear Reactor Regulation, Director 1p 17014 001 24X Fiche 50-263, 83/01/27, 8302040513

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - GPU Service Corp 5pp 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302150491 Forwards addl info re NUREG-0737, Items I A 2 1 & I D 4 re upgraded reactor operator & senior reactor operator & mitigating core damage training programs, respectively MUSOLF, D Northern States Power Co 83/02/06 Office of Nuclear Reactor Regulation, Director 3pp 17156 315 24X Fiche 50-263, 83/02/06, 8302150491

8302150491 Forwards addl info re NUREG-0737, Items I A 2 1 & I D 4 re upgraded reactor operator & senior reactor operator & mitigating core damage training programs, respectively MUSOLF, D Northern States Power Co 83/02/06 Office of Nuclear Reactor Regulation, Director 3pp 17156 315 24X Fiche 50-263, 83/02/06, 8302150491

8302150505 Responds to 830105 request for addl info re increased allowable deviation for main steam line area temp switch setpoint Since entire steam tunnel reaches 212 F for small break, 200 F setpoint provides adequate protection MUSOLF, D Northern States Power Co 83/02/07 Office of Nuclear Reactor Regulation, Director 2pp 17157 140 24X Fiche 50-263, 83/02/07, 8302150505

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302150359 Reaffirms that facility can continue safe operation during resolution of environ qualification deficiencies for Category I b & II, a equipment items Equipment will function as required during accident conditions MUSOLF, D Northern States Power Co 83/02/08 Office of Nuclear Reactor Regulation, Director 2pp 17157 277 24X Fiche 50-263, 83/02/08, 8302150359

8302170072 Advises that 820726 & 830127 process control program acceptable w/commitment to revise Paragraph 2 B i re sampling requirements as listed VASSALLO, D B Operating Reactors Branch 2 83/02/08 MUSOLF, D M Northern States Power Co 2pp 17191 076 24X Fiche 50-263, 83/02/08, 8302170072

8302170128 Requests remittance of fee for NRC review of 810706 application for amend to License DPR-22, approving repair to recirculation sys piping & authorizing resumption of power under certain conditions MILLER, W O License Fee Management Branch 83/02/09 MUSOLF, D M Northern States Power Co 1p 17191 119 24X Fiche 50-263, 83/02/09, 8302170128

8302180139 Forwards application for amend to License DPR-22, changing Tech Specs to add new limiting conditions for operation & surveillance requirements for setpoints & turbine bypass valve on high reactor water level instrumentation MUSOLF, D Northern States Power Co 83/02/15 Office of Nuclear Reactor Regulation, Director 1p 17216 140 24X Fiche 50-263, 83/02/15, 8302180139

--8302180143 Application for amend to License DPR-22, changing Tech Sp to add new limiting conditions for operation & surveillance requirements for setpoints & turbine bypass valve on high reactor water level instrumentation MUSOLF, D Northern States Power Co 83/02/15 1p 17216 141 24X Fiche 50-263, 83/02/15, 8302180139

--8302180146 Proposed Tech Specs re limiting conditions for operation surveillance requirements for setpoints & turbine bypass valve on high reactor water level instrumentation. * Northern States Power Co 83/02/15 24pp 17216 142 24X Fiche 50-263, 83/02/15, 8302180139

8302240296 Forwards check to complete fee payment for 821210 amend to License DPR-22 re recirculation sys leakage, per NRC 830209 ltr MUSOLF, D Northern States Power Co 83/02/15 MILLER, W O License Fee Management Branch, 2pp 17274 077 24X Fiche 50-263, 83/02/15, 8302240296

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of document re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L Ohio Citizens for Responsible Energy, 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plant consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item BUCHARSKI, L Region 3, Office of Director 82/07/08 KEPPLER, J O Region 3, Office of Director 13pp 17045 281, 24 Fiche 50 000, 82/12/30, 8302040339

8302040207 Forwards SER 50-263/82-17 supporting Jul 1982 emergency plan meets stds of 10CFR50 47(b) & App E to 10CFR50. HIND, J A Division of Emergency Preparedness & Operational Support 83/01/20 LARSON, C E Northern States Power Co 2pp, 17021 324, 24X Fiche 50-263, 83/01/20, 8302040207

--8302040212 SER 50-263/82-17 supporting Jul 1982 emergency plan. PATTERSON, J P, SMITH, M J, AXELSON, W L Division of Emergency Preparedness & Operational Support, 83/01/14, 28pp 17021 336, 24X Fiche 50-263, 83/01/20, 8302040207

8302040359 Forwards IE Insp Rept 50-263/82-16 on 821213-17 No noncompliance noted LITTLE, W S Division of Engineering 83/01/21 LARSON, C E Northern States Power Co 2pp 17019 038, 24X Fiche 50-263, 83/01/21, 8302040359

--8302040360 IE Insp Rept 50-263/82-16 on 821213-17. No noncompliance noted Major areas inspected licensee action on previous items, licensed & nonlicensed employee training, surveillance, calibr, GA & licensed employee requalification training FARRELL, R E, PESCHEL, J M, HAWKINS, F C Division of Engineering, 83/01/17 11pp 17019 040 24X Fiche 50-263, 83/01/21, 8302040359

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

DOCKETED ITEMS

8302150521 Forwards IE Insp Rept 50-263/82-14 on 821005-1208 No noncompliance noted
LITTLE, W B Division of Engineering 83/01/26 GILBERTS, D E
Northern States Power Co 2pp 17156 224 24X
Fiche 50-263, 83/01/26, 8302150521

--8302150532 IE Insp Rept 50-263/82-14 on 821005-1208 No noncompliance noted Major areas inspected inservice insp activities, including program & procedure review, observation of activities & review of exam documentation
KEY, W J, WARD, K D, DANIELSON, D H Region 3, Office of Director
83/01/21 16pp 17156 225 24X Fiche 50-263, 83/01/26, 8302150521

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp. 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche: 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR30.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp. 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302080274 Notices of 830218 enforcement conference in Glenn Elynn, IL to discuss breach of primary containment for 13-day period in Dec 1982
NOELIUS, C E Division of Project & Resident Programs. 83/02/03
LARBON, C E Northern States Power Co 1p 17056, 345. 24X
Fiche: 50-263, 83/02/03, 8302080274

8302180265 Advises tha no Bunker-Ramo electrical penetrations installed or planned to be installed at facility, in response to IE Bulletin 82-04
LARBON, C E Northern States Power Co 83/02/11 KEPLER, J O
Region 3, Office of Director. 1p. 17215:259 24X
Fiche 50-263, 83/02/11, 8302180265

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347.191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 11pp 17347 058 24X Fiche. 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp. 17361:148 24X Fiche 50-000, 83/02/24, 8212060366

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc. 14pp. 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-264 DOW CHEMICAL CO

F. Security, medical, emergency & fire protection plans

8302020422 Releases public version of Emergency Plan
FELTON, J M Division of Rules and Records 83/01/27. Document
Management Branch. 1p 16999, 321 24X Fiche 50-264, 83/01/27, 8302020422.

--8302020428 Forwards public version of Emergency Plan, originally submitted in Oct 1982
KOCHER, C W. Dow Chemical Co. 83/01/10 Office of Nuclear Reactor Regulation, Director. 1p. 16999:322 24X
Fiche. 50-264, 83/01/27, 8302020422

--8302020432 Public version of Emergency Plan, originally submitted in Oct 1982
* Dow Chemical Co 82/09/07 20pp 16999 323 24X
Fiche 50-264, 83/01/27, 8302020422

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs
PAJOWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC
- No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs Revised index encl
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp
17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8302040205 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17043 349 24X Fiche 50-254, 83/01/31, 8302040205

--8302040214 Forwards public version of Rev 9 to Emergency Plan Implementing Procedures GEP 440-0, "Communications Sys" & GEP 440-1, "Emergency Communication Facilities "
* Commonwealth Edison Co 83/01/19 DENTON, H R NRC - No Detailed Affiliation Given 1p 17043 350 24X
Fiche 50-254, 83/01/31, 8302040205

--8302040220 Public version of Rev 9 to Emergency Plan Implementing Procedures GEP 440-0, "Communications Sys" & GEP 440-1, "Emergency Communication Facilities "
* Commonwealth Edison Co 83/01/19 8pp 17043 351 24X
Fiche 50-254, 83/01/31, 8302040205

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche. 50-000, 83/02/01, 8301210340

8302080365 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/02 Document
Management Branch 1p 17107 139 24X Fiche 50-254, 83/02/02, 8302080365.

--8302080368 Forwards public version of Rev 9 to Emergency Plan Implementing Procedure GEP 360-2, "Plant Evacuation & Assembly " Revised index encl
* Commonwealth Edison Co. 83/01/21 DENTON, H R NRC - No Detailed Affiliation Given 2pp 17107:140. 24X
Fiche 50-254, 83/02/02, 8302080365

--8302080372 Public version of Rev 9 to Emergency Plan Implementing Procedure GEP 360-2, "Plant Evacuation & Assembly "
* Commonwealth Edison Co 83/01/21 2pp. 17107 142 24X
Fiche 50-254, 83/02/02, 8302080365

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-111B guidelines valid
KEPLER, J O Region 3, Office of Director. 83/02/04 REED, C
Commonwealth Edison Co 4pp. 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities, Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPLER, J O Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

DOCKETED ITEMS

71

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J. H. Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOF-2, "Technical Support Manager"
MCORE, R. D. Commonwealth Edison Co 83/01/03 DENTON, H. R. NRC - No Detailed Affiliation Given 1p 17223 219 24X Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOF-2, "Technical Support Manager"
NELLS, C. A. Commonwealth Edison Co 83/02/02 48pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302250349 Advises that R. Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/02/18 REED, C. Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250341 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities. Lists of locations encl
SHARTZ, E. D. Commonwealth Edison Co 83/01/28 KEPPLER, J. O. Region 3, Office of Director 4pp 17291 074 24X Fiche 50-000, 83/02/18, 8302250349

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D. O. Division of Licensing 83/01/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
HARRISON, J. H. NRC - No Detailed Affiliation Given 82/01/27 VARGAS, B. NRC - No Detailed Affiliation Given 10pp 17196 225 24X Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed. Requests justification for continued operation of each group by 821008 & 15, respectively.
EISENHUT, D. O. Division of Licensing 82/09/24 HIRAGLIA, F. Assistant Director for Safety Assessment, 4pp 17196 265 24X Fiche 50-000, 83/01/18, 8302170019

--8302170262 Concludes that based on licensee 820603 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
BFVAN, R. B. Operating Reactors Branch 2 82/10/28 EISENHUT, D. O. Division of Licensing 2pp 17197 050 24X Fiche 50-000, 83/01/18, 8302170019

8302010294 Advises of detailed evaluation of Technical Evaluation Repts attached to BERs re safety-related equipment, to determine nonproprietary nature of info. Info will be withheld until 830215 resolution.
RAUSCH, T. J. Commonwealth Edison Co 83/01/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 16973 114 24X Fiche 50-254, 83/01/25, 8302010294

8302010429 Forwards "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plants Drywell Temp Analysis." Analysis fulfills NRC request for info re equipment qualification temp profiles inside containment
RAUSCH, T. J. Commonwealth Edison Co 83/01/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 16974 180 24X Fiche 50-000, 83/01/25, 8302010429

--8302010434 "Dresden 2 & 3 & Quad Cities 1 & 2 Nuclear Power Plant Drywell Temp Analysis."
HOANG, H. Y. General Electric Co N800-82-0682 82/11/30 13pp 16974 182 24X Fiche 50-000, 83/01/25, 8302010429

8302080303 Application to amend License DPR-30, increasing by 10% allowable linear heat generation rate limit for barrier fuel assemblies scheduled to undergo control rod withdrawal ramp test in late Feb 1983
RAUSCH, T. J. Commonwealth Edison Co 83/01/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 17056 046 24X Fiche 50-254, 83/01/27, 8302080303

8302070274 Supplis 821019 ltr re justification for continued operation for SCAM resistance temp detectors in reactor water cleanup rooms, per 821229 & 830118 BERs for environ qualification of electrical equipment program
RAUSCH, T. J. Commonwealth Edison Co 83/02/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 10pp 17031 116 24X Fiche 50-000, 83/02/01, 8302070274

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod. Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/02 General Public Utilities - OPU Service Corp 3pp 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302100224 Forwards description, basis & justification for each setpoint chosen for reactor protection sys power monitoring sys, per 820723 ltr Proposed Tech Specs will be submitted by 830415.
RAUSCH, T. J. Commonwealth Edison Co 83/02/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 14pp 17115 116 24X Fiche 50-000, 83/02/04, 8302100224

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guidelines program Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re BER of "Emergency Procedure Guidelines, Rev 2," NEDQ-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/08 Commonwealth Edison Co 4pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302220330 Discusses schedule for util response re environ qualification of electrical equipment proprietary info. Manufacturers contacted on timely response. Status of final reporting will be provided by 830515
RYBAK, B. Commonwealth Edison Co 83/02/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17230 091 24X Fiche 50-000, 83/02/14, 8302220330

8302250293 Forwards "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2," per Section XI of ASME Boiler & Pressure Vessel Code, 1980 Edition, including Winter 1980 addenda
RAUSCH, T. J. Commonwealth Edison Co 83/02/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17295 310 24X Fiche 50-254, 83/02/17, 8302250293

--8302250308 "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2"
* Commonwealth Edison Co 82/08/18 233pp 17295 312 24X Fiche 50-254, 83/02/17, 8302250293

8302250295 Forwards Suppl 9 to Rev 1 of Joseph Dat Corp "Licensing Rept on High Density Spent Fuel Racks for Quad Cities Unit 1 & 2." Changes include reduction in number of storage cells to be installed & rev to spacing arrangement
RYBAK, B. Commonwealth Edison Co 83/02/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 17pp 17292 130 24X Fiche 50-254, 83/02/18, 8302250295

8302280152 Advises that review of 830121 final rule on environ qualification of safety-related electrical equipment incomplete. Determination whether to reaffirm or withdraw hearing request will be provided by 830324.
STEPTOE, P. P. Isham, Lincoln & Beale 83/02/23 EISENHUT, D. O. Division of Licensing 1p 17306 076 24X Fiche 50-000, 83/02/23, 8302280152

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L Ohio Citizens for Responsible Energy 3pp 17045 144. 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, USB & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design." Addl testing not warranted TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 23pp 17171:227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023-160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H30C Gearheads." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc. 110pp 17074 075 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people SPEISARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187. 24X Fiche 50-000, 83/01/28, 8302030303

8302080277 Submits updated installation status rept of safe shutdown path supports, per IE Bulletin 79-14 All remaining hangers will be installed by 831231, w/exception of Quad Cities safety relief valve line RAUSCH, T J Commonwealth Edison Co 83/02/01 KEPLER, J O Region 3, Office of Director. 4pp 17056:337 24X Fiche 50-000, 83/02/01, 8302080277

8302100088 Forwards draft NRR input for upcoming SALP evaluation for CV82 based on program manager experience w/Comm Ed & input solicited from selected personnel involved w/licensing actions Review & comments requested by 830210 BEVAN, R. Operating Reactors Branch 2 83/02/04 EISENKUT, D O Division of Licensing, SPEIS, T Division of Safety Technology MATTSON, R J Division of Systems Integration (post 811005) 7pp 17135 097 24X Fiche 50-254, 83/02/04, 8302100088.

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels " SHWARTZ, E D Commonwealth Edison Co. 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17196 215 24X Fiche 50-000, 83/02/08, 8302150528.

8302280339 Forwards IE Insp Repts 50-254/82-23 & 50-265/82-25 on 821023-830107 No noncompliance noted BREETER, J F Division of Project & Resident Programs. 83/02/10. REED, C Commonwealth Edison Co 2pp 17313 079. 24X Fiche 50-254, 83/02/10, 8302280339

--8302280341 IE Insp Repts 50-254/82-23 & 50-265/82-25 on 821023-830107 No noncompliance noted Major areas inspected: operational safety, plant scram procedures, TMI action plan items, licensee meeting & refueling activities CHRISTOTHOS, N., DUPONT, S O., WALKER, R D. Division of Project & Resident Programs 83/02/10. 12pp 17313 081 24X Fiche 50-254, 83/02/10, 8302280339

8302150587 EN-83-008 on 830216, notices of violation & proposed imposition or civil penalties in amount of \$120,000 will be issued Action based on lack of controls over distribution of safety list & failure to maintain containment integrity BARBER, O Director's Office, Office of Inspection and Enforcement 83/02/11 2pp 17156 117 24X Fiche 50-000, 83/02/11, 8302150587

8302180491 Discusses IE insp on 820816-1103 & forwards notice of violation & proposed imposition of civil penalty KEPLER, J O Region 3, Office of Director 83/02/16 O'CONNOR, J J Commonwealth Edison Co 4pp 17214 127 24X Fiche 50-000, 83/02/16, 8302180491

--8302180496 Notice of violation & proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted weakness in QA program, including lack of controls over distribution of safety classification list KEPLER, J O Region 3, Office of Director 83/02/16 3pp 17214 131 24X Fiche 50-000, 83/02/16, 8302180491

8302250293 Forwards "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2," per Section VI of ASME Boiler & Pressure Vessel Code, 1980 Edition, including Winter 1980 addenda RAUSCH, T J Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17295 310 24X Fiche 50-254, 83/02/17, 8302250293

--8302250308 "Inservice Insp & Testing Program, Second 10-Yr Program, Quad Cities Nuclear Power Station Units 1 & 2 " Commonwealth Edison Co 82/08/18 233pp 17295 312 24X Fiche 50-254, 83/02/17, 8302250293

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150014 Forwards monthly operating repts for Jan 1983 KALIVIANAKIS, N Commonwealth Edison Co 83/02/03 Director's Office, Office of Inspection and Enforcement 1p 17147 101 24X Fiche 50-254, 83/02/03, 8302150014

--8302150048 Monthly operating repts for Jan 1983 BROOK, B., BUSS, R Commonwealth Edison Co 83/02/03 22pp 17147 102 24X Fiche 50-254, 83/02/03, 8302150044

8302150571 Forwards listing of changes, tests & experiments completed during Jan 1983 KALIVIANAKIS, N Commonwealth Edison Co 83/02/03 CASE, E O Office of Nuclear Reactor Regulation, Director 3pp 17190 359 24X Fiche 50-254, 83/02/03, 8302150671.

S Reportable occurrences, LERs & related correspondence

8302010132 Forwards LER 83-001/03L-0 KALIVIANAKIS, N Commonwealth Edison Co 83/01/07 KEPLER, J O Region 3, Office of Director 1p 16977 022 24X Fiche 50-265, 83/01/07, 8302010132

--8302010140 LER 82-001/03L-0, on 830102, offgas radiation monitor 1 failed Caused by faulty resistor in power supply to monitor Resistor replaced MISAKI, A L Commonwealth Edison Co 83/01/07 Region 3, Office of Director 1p 16977.023 24X Fiche 50-265, 83/01/07, 8302010132

8302040304 Forwards LER 83-003/03L-0 KALIVIANAKIS, N Commonwealth Edison Co 83/01/24 KEPLER, J Region 3, Office of Director 1p 17018 190 24X Fiche 50-265, 83/01/24, 8302040304

DOCKETED ITEMS

73

--8302040321 LER 83-003/03L-0 on 830110, traversing incore probe 4 ball valve failed to fully close as travelling incore probe returned to shield. Caused by crud buildup in internals, allowing valve to only partially close. Ball valve cleaned. HELLER, J. Commonwealth Edison Co. 83/01/24. Region 3, Office of Director. 1p. 17018 191. 24X. Fiche 50-265, 83/01/24, 8302040304.

8302040374 Forwards LER 83-002/03L-0 KALIVIANAKIS, N. Commonwealth Edison Co. 83/01/24. KEPLER, J. G. Region 3, Office of Director. 1p. 17017 340. 24X. Fiche 50-265, 83/01/24, 8302040374.

--8302040397 LFR 83-002/03L-0 on 830106, significant increase in condensate pump discharge conductivity noted. Caused by loose screw-in filter elements which allowed resins to pass. Filters tightened & resin trap replaced. BENRENS, P. Commonwealth Edison Co. 83/01/24. Region 3, Office of Director. 1p. 17017 341. 24X. Fiche 50-265, 83/01/24, 8302040394.

8302160151 Forwards LER 83-004/03L-0 KALIVIANAKIS, N. Commonwealth Edison Co. 83/02/04. KEPLER, J. G. Region 3, Office of Director. 1p. 17162 215. 24X. Fiche 50-265, 83/02/04, 8302160151.

--8302160158 LER 83-004/03L-0 on 830116, containment cooling loop B taken out of svc for maint on RHR. HX 28 Bellows seal replaced on pipe from primary side of HX through secondary side & through exterior of HX for draining primary side. COOK, D. Commonwealth Edison Co. 83/02/04. Region 3, Office of Director. 1p. 17162 216. 24X. Fiche 50-265, 83/02/04, 8302160151.

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, PPS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/01/31. Consolidated Edison Co. of New York, Inc. 14pp. 17347 177. 24X. Fiche 50-000, 83/01/31, 8301310203.

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/01. Consolidated Edison Co. of New York, Inc. 11pp. 17221 226. 24X. Fiche 50-000, 83/02/01, 8301210340.

8302090421 Responds to NRC 830117 ltr transmitting draft safety evaluation denying App R exemption requests. Meeting requested to discuss technical accuracy of evaluation prior to inception of NRR rgt appeal process. Agenda submitted. FAY, C. W. Wisconsin Electric Power Co. 83/02/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17066 247. 24X. Fiche 50-266, 83/02/07, 8302090421.

Q Adjudicatory correspondence

8302070506 Initial decision authorizing Director of NRR to issue OL ahead re repair of steam generator tubes. Tubes explosively plugged cannot be sleeved or brazed joints employed. Leak limits apply. BLOCH, P. B.; PAXTON, H. C.; KLINE, J. R. Atomic Safety and Licensing Board Panel. 83/02/04. 41pp. 17037 013. 24X. Fiche 50-266, 83/02/04, 8302070506.

8302140020 Memorializes 830131 telcon resolving open procedural question re inadvertent use of proprietary data in responding to ASLB & WI Environ Decade exam. DAYIS, F. X. General Electric Co. 83/02/04. BLOCH, P. B. Atomic Safety and Licensing Board Panel. 3pp. 17141 189. 24X. Fiche 50-266, 83/02/04, 8302140020.

8302180427 Exceptions to ASLB 830204 initial decision. Affidavit of Helling encl. ANGERSON, R. Wisconsin's Environmental Decade. 83/02/14. Commissioners. 4pp. 17215 184. 24X. Fiche 50-266, 83/02/14, 8302180427.

I Financial information

8302240159 Forwards 1982 financial statements & 1983 cash flow projection providing guarantee of retrospective premiums. REMMEL, J. G. Wisconsin Electric Power Co. 83/02/15. SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance). 14pp. 17280 252. 24X. Fiche 50-266, 83/02/15, 8302240159.

P Operating license stage documents & correspondence

8302020223 Forwards exemption from scheduler requirements of 10CFR50.44(c)(3)(iii) for RCS high point gas vent installation, per 820618 request. Svc list encl. CLARK, R. A. Operating Reactors Branch 3. 83/01/25. FAY, C. W. Wisconsin Electric Power Co. 3pp. 16999 198. 24X. Fiche 50-266, 83/01/25, 8302020223.

--8302020226 Exemption from 10CFR50.44(c)(3)(iii) scheduler requirements re RCS high point gas vent installation. EISENHUT, D. G. Division of Licensing. 83/01/25. Wisconsin Electric Power Co. 4pp. 16999 203. 24X. Fiche 50-266, 83/01/25, 8302020223.

8302010595 Discusses need for further delay in determining proprietary nature of SER re environ qualification of safety-related electrical equipment. Final determination delayed until 830201 due to absence of key personnel. BURSTEIN, S. Wisconsin Electric Power Co. 83/01/26. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 16978 127. 24X. Fiche 50-266, 83/01/26, 8302010595.

8302030566 Submits justification for continued operation of equipment identified as deficient due to lack of environ qualification, in response to NRC 821222 request. BURSTEIN, S. Wisconsin Electric Power Co. 83/01/26. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 7pp. 17008 126. 24X. Fiche 50-266, 83/01/26, 8302030566.

8302170013 Forwards request for addl info to complete post-implementation review of NUREG-0737, Items II F.1.4, II, F.1.5 & II F.1.6 re containment monitors. Response requested within 30 days. CLARK, R. A. Operating Reactors Branch 3. 83/02/02. FAY, C. W. Wisconsin Electric Power Co. 10pp. 17190 291. 24X. Fiche 50-266, 83/02/02, 8302170013.

8302220044 Informs that review of 801223 & 821228 responses to NUREG-0737, Item II K.3.25, "Loss of AC Power to Reactor Coolant Pump Seals," adequately demonstrates integrity of reactor coolant pump seals. Item resolved. CLARK, R. A. Operating Reactors Branch 3. 83/02/04. FAY, C. W. Wisconsin Electric Power Co. 3pp. 17227 333. 24X. Fiche 50-266, 83/02/04, 8302220044.

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 11pp. 17290 247. 24X. Fiche 50-000, 83/02/08, 8302080295.

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 9pp. 17234 234. 24X. Fiche 50-000, 83/02/08, 8302080304.

8302180410 Advises that installation of addl supports for auxiliary feedwater sys piping & components rescheduled to June 1983, due to conflicts w/other plant mods. FAY, C. W. Wisconsin Electric Power Co. 83/02/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17157 149. 24X. Fiche 50-266, 83/02/11, 8302180410.

8302230236 Forwards response to NRC Question Attachments 1-2 "Evaluation of Overhead Handling Sys W/Respect to NUREG-0554" & 1-3 "Seismic Analysis Methodology for Overhead Handling Sys," per NUREG-0612. FAY, C. W. Wisconsin Electric Power Co. 83/02/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 7pp. 17245 029. 24X. Fiche 50-266, 83/02/15, 8302230236.

DOCKETED ITEMS

8302280366 Forwards revised justification for continued operation, correcting 830126 submittal in response to NRC 821227 BSR re environ qualification of safety-related electrical equipment
 FAY, C W Wisconsin Electric Power Co 83/02/18 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 12pp 17310 341 24X
 Fiche 50-266, 83/02/18, 8302280366

8302280194 Advises that review underway for final rule 10CFR50.49 re environ qualification of safety-related electrical equipment Determination of request for hearing will be decided by 830324
 FAY, C W Wisconsin Electric Power Co 83/02/21 DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D G
 Division of Licensing 1p 17306 075 24X Fiche 50-266, 83/02/21, 8302280194

8302280156 Submits addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys." in response to NRC 821222 request Standardized test matrix will be completed by 830401
 FAY, C W Wisconsin Electric Power Co 83/02/21 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 3pp 17306 034 24X
 Fiche 50-266, 83/02/21, 8302280156

8302280310 Forwards "Incorporation of Westinghouse Model for Upper Plenum Injection in 1981 Evaluation Model WREFLOOD Code"
 FAY, C W Wisconsin Electric Power Co 83/02/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 3pp 17311 014 24X
 Fiche 50-266, 83/02/22, 8302280310

--8302280312 "Incorporation of Westinghouse Model for Upper Plenum Injection in 1981 Evaluation Model WREFLOOD Code"
 * Westinghouse Electric Corp. 83/02/22 83pp 17311 017 24X
 Fiche 50-266, 83/02/22, 8302280310

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
 Forwards App A documents Document G1 available in PDR
 FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L
 Ohio Citizens for Responsible Energy 3pp 17045 144 24X
 Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
 SUCHARSKI, L. Region 3, Office of Director 82/07/08
 KEPLER, J G. Region 3, Office of Director 13pp 17045 281 24X
 Fiche 50-000, 82/12/30, 8302040039

8302010603 Forwards revised Table 1 to correct typographical error re two 10-inch check valve identification numbers in 820811 response to IE Bulletin 82-02 re degradation of RCPB fasteners
 BURSTEIN, S Wisconsin Electric Power Co 83/01/24 KEPLER, J G
 Region 3, Office of Director 3pp 16978 138 24X
 Fiche 50-266, 83/01/24, 8302010603

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibre of Liquid Level Instruments" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
 SPESBARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302080320 Suppls previous responses to IE Bulletin 79-14 re conformance of as-built safety-related piping sys to as-designed seismic analysis & acceptance criteria Next rept will be submitted by Apr 1983
 FAY, C W Wisconsin Electric Power Co 83/01/31 KEPLER, J G
 Region 3, Office of Director 2pp 17056 305 24X
 Fiche 50-266, 83/01/31, 8302080320

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302280545 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-21 & 50-301/82-21
 STREETER, J F Division of Project & Resident Programs 83/02/18
 BURSTEIN, S Wisconsin Electric Power Co 1p 17309 033 24X
 Fiche 50-266, 83/02/18, 8302280545

--8302280552 Responds to NRC 830103 ltr re violations noted in IE Insp Repts 50-266/82-21 & 50-301/82-21 Corrective actions ICP 10.7 permanently revised & classified as minor procedure & precaution added to RP-1C to warn of effect of fuel temp
 FAY, C W Wisconsin Electric Power Co 83/02/02 KEPLER, J G
 Region 3, Office of Director 3pp 17309 034 24X
 Fiche 50-266, 83/02/18, 8302280545

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302170153 Forwards monthly operating repts for Jan 1983
 FAY, C W Wisconsin Electric Power Co 83/02/09 Office of Nuclear Reactor Regulation, Director 1p 17180 140 24X
 Fiche 50-266, 83/02/09, 8302170153

--8302170155 Monthly operating repts for Jan 1983
 FAY, C W Wisconsin Electric Power Co 83/02/04 8pp 17180 141 24X
 Fiche 50-266, 83/02/09, 8302170153

S Reportable occurrences, LERs & related correspondence

8302180195 Forwards LER 83-001/03L-0
 FAY, C W Wisconsin Electric Power Co 83/02/09 KEPLER, J G
 Region 3, Office of Director 1p 17216 001 24X
 Fiche 50-266, 83/02/09, 8302180195

--8302180205 LER 83-001/03L-0 on 830104, during normal operation, panel D-400 became inoperable Caused by failed power supply Power supply replaced w/upgraded components
 FAY, C W Wisconsin Electric Power Co 83/02/09 Region 3, Office of Director 2pp 17216 002 24X Fiche 50-266, 83/02/09, 8302180195

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
 EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 1pp 17347 177 24X
 Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-247 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8302230689 Forwards IE Insp Rept 50-267/82-26 on 821115-16 No noncompliance noted
 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/02/11 LEE, D R Public Service Co of Colorado 2pp 17257 315 24X Fiche 50-267, 82/02/11, 8302230689

DOCKETED ITEMS

75

--B302230693 IE Insp Rept 50-267/82-26 on 821115-16 No noncompliance noted Major areas inspected insp at facility & time spent at St Luke Hosp prior to & during medical emergency drill
MONTGOMERY, J., DICKERSON, M. W., PLUMLEE, G. L. Division of Resident, Reactor Project & Engineering Programs 82/01/04 8pp
17257 317 24X Fiche 50-267, 82/02/11, 8302230689

B302040614 Provides advance notification of spent fuel shipment from Facility to ID Chemical Processing Plant in Scoville, ID scheduled for June 1982 Encl withheld (ref 10CFR73 72)
WAREMBOURG, D. Public Service Co. of Colorado 82/06/18
COLLINS, J. T., KELLY, J. Region 4, Office of Director 1p
17042 040 24X Fiche 50-267, 82/06/18, 8302040614

B302080040 Notices of spent fuel shipments scheduled for Jul 1982 Encl withheld (ref 10CFR73 37)
WAREMBOURG, D. Public Service Co. of Colorado 82/06/24
COLLINS, J. T. Region 4, Office of Director 1p 17108 010 24X
Fiche 50-267, 82/06/24, 8302080040

B302080095 Forwards revised schedule for spent fuel shipments from plant to ID Chemical Processing Plant in Sept 1982 Schedule withheld
WAREMBOURG, D. Public Service Co. of Colorado 82/08/24
COLLINS, J. T. Region 4, Office of Director 1p 17106 101 24X
Fiche 50-267, 82/08/24, 8302080095

B302080089 Provides advance notification of spent fuel shipments from plant to ID Chemical Processing Plant in Oct 1982 Encl withheld (ref 10CFR73 21)
WAREMBOURG, D. Public Service Co. of Colorado 82/09/22
COLLINS, J. T., KELLY, J. Region 4, Office of Director 1p
17106 103 24X Fiche 50-267, 82/09/22, 8302080089

B302070144 Provides advance notification of spent fuel shipments from plant to Scoville, ID for Nov 1982 Encl withheld (ref 10CFR 790)
WAREMBOURG, D. Public Service Co. of Colorado 82/10/26
COLLINS, J. T. Region 4, Office of Director 1p 17065 355 24X
Fiche 50-267, 82/10/26, 8302070144

B302040350 Forwards summary of meeting w/CO Dept of Disaster Emergency Svcs, CO Dept of Health, FEMA & Natl Weather Svc re emergency preparedness & early warning sys
WAREMBOURG, D. W. Public Service Co. of Colorado 83/01/07
MAISEN, G. L. Division of Resident, Reactor Project & Engineering Programs 14pp 17029 219 24X Fiche 50-267, 83/01/07, 8302040350

B302080099 Forwards route overview depicting planned check call frequency for forthcoming shipment of strategic quantity of SNM Encl withheld (ref 10CFR73 21)
RUTENBERG, E. Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.) 83/01/11 HILLMAN, C. URC - No Detailed Affiliation Given
2pp 17106 034 24X Fiche 50-267, 83/01/11, 8302080099

B302020943 Releases public version of Issue B to Emergency Plan Implementing Procedure
FELTON, J. M. Division of Rules and Records 83/01/26 Document
Management Branch 1p 16999 001 24X Fiche 50-267, 83/01/26, 8302020943

--B302020048 Forwards public version of Issue B to Emergency Plan Implementing Procedure RERP-PCC, "Personnel Control Ctr Procedure"
WAREMBOURG, D. W. Public Service Co. of Colorado 82/12/21
EISENHUT, D. G. Division of Licensing ROHRER, D. Director's Office, Office of Inspection and Enforcement COLLINS, J. T. Region 4, Office of Director 1p 16999 002 24X Fiche 50-267, 83/01/26, 8302020043

--B302070031 Public version of Issue B to Emergency Plan Implementing Procedure RERP-PCC, "Personnel Control Ctr Procedure"
Revised Index encl
WAREMBOURG, D. W. Public Service Co. of Colorado 82/12/20 105pp
16999 006 24X Fiche 50-267, 83/01/26, 8302070031

B302230472 Forwards IE Insp Rept 50-267/83-02 on 830110-14 No noncompliance noted
MAISEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/01/27 LEE, D. R. Public Service Co. of Colorado 2pp
17246 027 24X Fiche 50-267, 83/01/27, 8302230472

--B302230478 IE Insp Rept 50-267/83-02 on 830110-14 No noncompliance noted Major areas inspected organization & administration, safety committee activities, fire prevention/protection program & implementation & previously identified open items
REDAND, R. T., MURPHY, M. E., WESTERMAN, T. F. Division of Resident, Reactor Project & Engineering Programs 83/01/26 7pp
17246 029 24X Fiche 50-267, 83/01/27, 8302230472

B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc. 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

B302150256 Responds to 830121 ltr by providing clarification on alleged discrepancies in License DPR-34 Major discrepancy involves inadvertent elimination of subparagraph heading in License Condition 2 C 4(4) in Amend 25
MAISEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/01 LEE, D. R. Public Service Co. of Colorado 3pp
17148 341 24X Fiche 50-267, 83/02/01, 8302150256

--B302150261 Corrected Pp 3, 4 & 5 of Amend 25 to License DPR-34, rectifying 820302 issuance re physical protection of SNM & implementation of safeguards contingency plan
Region 4, Office of Director 83/02/01 3pp 17148 344 24X
Fiche 50-267, 83/02/01, 8302150261

B302090535 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/02/03 Document
Management Branch 1p 17122 001 24X Fiche 50-267, 83/02/03, 8302090535

--B302090539 Forwards public version of revised emergency plan implementing procedures, including Procedures RERP CR-ALERT re control room alert, site emergency & general emergency procedure & RERP-ECP re executive command post procedure
WAREMBOURG, D. W. Public Service Co. of Colorado 83/01/06
COLLINS, J. T. Region 4, Office of Director 2pp 17122 003 24X
Fiche 50-267, 83/02/03, 8302090539

--B302090543 Public version of revised emergency plan implementing procedures, including Procedures RERP CR-ALERT re control room alert, site emergency & general emergency procedure & RERP-ECP re executive command post procedure
WAREMBOURG, D. W. Public Service Co. of Colorado 83/01/03 56pp
17122 005 24X Fiche 50-267, 83/02/03, 8302090543

B302170032 Requests remittance of fees re issuance of Amends 30 & 31 on 830104 & 20, respectively, in response to 820611 request to revise security plan & 830103 request to revise Tech Specs allowing disabling of protection sys moisture monitors
DICKS, R. M. License Fee Management Branch 83/02/10 LEE, D. R. Public Service Co. of Colorado 2pp 17191 033 24X
Fiche 50-267, 83/02/10, 8302170032

B302250003 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 83/02/16 Document
Management Branch 1p 17298 242 24X Fiche 50-267, 83/02/16, 8302250003

--B302250009 Forwards public version of Issue 3 to Emergency Plan Implementing Procedure RERP-FIELD, "Field Monitoring Procedure"
WAREMBOURG, D. W. Public Service Co. of Colorado 83/01/31
COLLINS, J. T. Region 4, Office of Director 1p 17298 243 24X
Fiche 50-267, 83/02/16, 8302250009

--B302250016 Public version of Issue 3 to Emergency Plan Implementing Procedure RERP-FIELD, "Field Monitoring Procedure"
WAREMBOURG, D. W. Public Service Co. of Colorado 83/02/01 46pp
17298 244 24X Fiche 50-267, 83/02/16, 8302250016

F Operating license stage documents & correspondence

B302070352 Responds to 821119 request for addl info re masonry block walls Mods to walls w/Dur-D-Wall discrepancy will be completed by 830315
BREV, H. L. Public Service Co. of Colorado 83/01/11 CLARK, R. A. Operating Reactors Branch 3 3pp 17029 214 24X
Fiche 50-267, 83/01/11, 8302070352

B302070355 Submits clarifications & corrections to 821229 ltr re NUREG-0412, "Control of Heavy Loads"
BREV, H. L. Public Service Co. of Colorado 83/01/14 CLARK, R. A. Operating Reactors Branch 3 3pp 17029 208 24X
Fiche 50-267, 83/01/14, 8302070355

B302070554 Forwards pages & corrections inadvertently omitted from OL through incorporation of Amend 30 to Tech Specs to clarify discrepancies noted in identical license documents held by both organizations Review requested
WAREMBOURG, D. Public Service Co. of Colorado 83/01/21
COLLINS, J. T. Region 4, Office of Director 8pp 17034 119 24X
Fiche 50-267, 83/01/21, 8302070554

DOCKETED ITEMS

8302070479 Informs that licensee 811211 request to eliminate Segment 2 fuel assembly from post-irradiated fuel element surveillance program acceptable Supplemental destructive exams should be substituted Commitment to exams requested
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/01/24 LEE, O R Public Service Co of Colorado 8pp 17035 049 24X Fiche 50-267, 83/01/24, 8302070479

8302150098 Summarizes 830117 meeting clarifying present requirements for reporting to Div of Security Unless otherwise specified in regulations, all communications & repts should be submitted to Region IV, per 10CFR30.4
COLLINS, J T Region 4, Office of Director 83/01/27 LEE, O R Public Service Electric & Gas Co of New Jersey 2pp 17146 154 24X Fiche 50-267, 83/01/27, 8302150098

8302030335 Forwards amend fee for Tech Spec change, per util 830106 ltr WARENSOUR, D Public Service Co of Colorado 83/01/28 BIGGS, R M License Fee Management Branch 2pp 17001 288 24X Fiche 50-267, 83/01/28, 8302030335

8302150618 Forwards QA-A16402, "Irradiation-Induced Creep in Graphite Review," per NRC request for summary of H-451 graphite creep tests upon completion Results of nondestructive post-irradiation exam also encl
BREV, H L Public Service Co of Colorado 83/01/28 WAGNER, P C Division of Resident, Reactor Project & Engineering Programs 2pp 17154 165 24X Fiche 50-267, 83/01/28, 8302150618

--8302150622 "Irradiation-Induced Creep in Graphite Review"
PRICE, R J QA Technologies, Inc /General Atomic Co QA-A16402 81/08/31 73pp 17154 167 24X Fiche 50-267, 83/01/28, 8302150618

--8302150630 "Test Rept Nondestructive Exam of FBV Fuel Test Element FTE-1"
* QA Technologies, Inc /General Atomic Co 706599 82/09/20 27pp 17154 241 24X Fiche 50-267, 83/01/28, 8302150618

8302150256 Responds to 830121 ltr by providing clarification on alleged discrepancies in License DPR-34 Major discrepancy involves inadvertent elimination of subparagraph heading in License Condition 2 C 4(4) in Amend 25
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/01 LEE, O R Public Service Co of Colorado 3pp 17148 341 24X Fiche 50-267, 83/02/01, 8302150256

--8302150261 Corrected Pp 3,4 & 5 of Amend 25 to License DPR-34, rectifying 820302 issuance re physical protection of ENM & implementation of safeguards contingency plan
* Region 4, Office of Director 83/02/01 3pp 17148 344 24X Fiche 50-267, 83/02/01, 8302150256

8302100083 Requests fee within 15 days for 821015 amend to application re update of inservice insp & testing program Tech Spec surveillance requirements
MILLER, H Q License Fee Management Branch 83/02/03 LEE, O R Public Service Co of Colorado 1p 17134 361 24X Fiche 50-267, 83/02/03, 8302100083

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for GL & holders of CP for C-E PHRS re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17270 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302230318 Informs of re-evaluation of power-to-fly events occurring during Cycles 1 & 2 under revised Safety Limit SL 3 I to answer staff inquiries re technical basis for action More detailed reanalysis of calculations will be performed
WARENSOUR, D Public Service Co of Colorado 83/02/09 COLLINS, J T Region 4, Office of Director 1p 17248 073 24X Fiche 50-267, 83/02/09, 8302230318

8302170032 Requests remittance of fees re issuance of Amends 30 & 31 on 830104 & 20, respectively, in response to 820611 request to revise security plan & 830103 request to revise Tech Specs allowing disabling of protection sys moisture monitors
BIGGS, R M License Fee Management Branch 83/02/10 LEE, O R Public Service Co of Colorado 2pp 17191 033 24X Fiche 50-267, 83/02/10, 8302170032

8302230174 Commits to rounding fuel surveillance program One fuel rod from cracked segment 2 fuel element sectioned & examined using metallographic techniques to confirm predicted fuel performance
LEE, O R Public Service Co of Colorado 83/02/10 COLLINS, J T Region 4, Office of Director 2pp 17245 166 24X Fiche 50-267, 83/02/10, 8302230174

8302250232 Advises that oil containing radioactive matl within valves of App B, Table II to 10CFR30 will be released for unrestricted use
BORST, F J Public Service Co of Colorado 83/02/10 COLLINS, J T Region 4, Office of Director 2pp 17292 104 24X Fiche 50-267, 83/02/10, 8302250232

8302250251 Requests extension of time to review 821202 request for commitment to limit max control rod drive mechanism temp to 215 F & orifice valve position to min open position of 40% Round basis for commitments not apparent
LEE, O R Public Service Co of Colorado 83/02/11 COLLINS, J T Region 4, Office of Director 1p 17292 284 24X Fiche 50-267, 83/02/11, 8302250251

Q Inspection Reports, IE Bulletins & correspondence

8302230689 Forwards IE Insp Rept 50-267/82-26 on 821115-14 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/02/11 LEE, O R Public Service Co of Colorado 2pp 17257 315 24X Fiche 50-267, 82/02/11, 8302230689

--8302230693 IE Insp Rept 50-267/82-26 on 821115-14 No noncompliance noted Major areas inspected insp of facility & time spent at St Luke Hosp prior to & during medical emergency drill
MONIGOMERY, J, DICKERSON, M W, PLUMLEE, G L Division of Resident, Reactor Project & Engineering Programs 82/01/04 6pp 17257 317 24X Fiche 50-267, 82/02/11, 8302230689

8302070349 Ack receipt of 821206 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/82-24 Corrective actions will be reviewed during next insp
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/01/18 LEE, O R Public Service Co of Colorado 1p 17029 233 24X Fiche 50-267, 83/01/18, 8302070349

8302070410 Ack receipt of 821103 & 29 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/82-19
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/01/18 LEE, O R Public Service Co of Colorado 1p 17029 255 24X Fiche 50-267, 83/01/18, 8302070410

8302030464 Forwards IE Insp Rept 50-267/82-31 on 821201-31 & notice of violation
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/01/21 LEE, O R Public Service Co of Colorado 2pp 17006 166 24X Fiche 50-267, 83/01/21, 8302030464

--8302030468 Notice of violation from insp on 821201-31
* Division of Resident, Reactor Project & Engineering Programs 83/01/21 3pp 17006 168 24X Fiche 50-267, 83/01/21, 8302030464

--8302030475 IE Insp Rept 50-267/82-31 on 821201-31 Noncompliance noted failure to follow plant operating procedures & failure to meet Tech Spec requirement
DICKERSON, M W, PLUMLEE, G L, WESTERMAN, R F Division of Resident, Reactor Project & Engineering Programs 83/01/17 18pp 17006 171 24X Fiche 50-267, 83/01/21, 8302030464

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302230472 Forwards IE Insp Rept 50-267/83-02 on 830110-14 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/01/27 LEE, O R Public Service Co of Colorado 2pp 17246 027 24X Fiche 50-267, 83/01/27, 8302230472

--8302230478 IE Insp Rept 50-267/83-02 on 830110-14 No noncompliance noted Major areas inspected organization & administration, safety committee activities, fire prevention/protection program & implementation & previously identified open items
REDANO, R T, MURPHY, M E, WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 83/01/26 7pp 17246 029 24X Fiche 50-267, 83/01/27, 8302230472

8212060360 IE Info Notice 83-02, "Litorque H08C, H18C, H28C & H38C Overheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

DOCKETED ITEMS

77

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230694 Forwards SALP Rept 50-267/82-28 for Sept 1981 - Aug 1982
NRC concurs w/comments in 821220 ltr Resident inspector will
continue to monitor actions in area of personnel errors &
failure to follow procedures
COLLINS, J T Region 4, Office of Director 83/01/31 LEE, O R
Public Service Co of Colorado 2pp 17259 243 24X
Fiche 50-267, 83/01/31, 8302230694

--8302230688 Forwards SALP Rept 50-267/82-28 for Oct 1981 - Aug 1982
Performance analyses to be discussed onsite on 821214
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 82/12/03 LEE, O R Public Service Co of Colorado
2pp 17259 250 24X Fiche 50-267, 83/01/31, 8302230688

--8302230692 SALP Rept 50-267/82-28 for Sept 1981 - Aug 1982 Licensing
personnel should anticipate LNR type questions in generic
lters, IE bulletins & keep abreast of NRC policy matters
WESTERMAN, T F, MADSEN, O L Division of Resident, Reactor Project
& Engineering Programs 82/11/18 32pp 17259 252 24X
Fiche 50-267, 83/01/31, 8302230692

8302160281 Ack receipt of 830119 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-267/82-27
Corrective actions will be reviewed during future insp
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 83/02/02 LEE, O R Public Service Co of Colorado 1p
17170 116 24X Fiche 50-267, 83/02/02, 8302160281

8302100083 Requests fee within 15 days for 821015 amend to application
re update of inservice insp & testing program Tech Spec
surveillance requirements
MILLER, W O License Fee Management Branch 83/02/03 LEE, O R
Public Service Co of Colorado 1p 17134 361 24X
Fiche 50-267, 83/02/03, 8302100083

8302230696 Informs of new program to enable more timely notification of
insp results by Vendor Program Branch Repts will be
forwarded through NRC resident inspector, w/encl distribution
ticket info in vendor repts should be used in assessments
COLLINS, J T Region 4, Office of Director 83/02/16 LEE, O R
Public Service Co of Colorado 2pp 17248 322 24X
Fiche 50-267, 83/02/16, 8302230696

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302070491 Forwards monthly operating rept for Dec 1982.
WAREHBOURG, D Public Service Co of Colorado 83/01/10
Director's Office, Office of Inspection and Enforcement 1p
17036 065 24X Fiche 50-267, 83/01/10, 8302070491

8302230641 Forwards "Semiannual Effluent Release Rept, Jul-Dec 1982"
BORST, F J Public Service Co of Colorado 83/02/02 COLLINS, J T
Region 4, Office of Director 3pp 17254 202 24X
Fiche 50-267, 83/02/02, 8302230641

--8302230646 "Semiannual Effluent Release Rept, Jul-Dec 1982"
* Public Service Co of Colorado, 83/02/28 195pp 17254 205
24X Fiche 50-267, 83/02/02, 8302230646

8302220157 Forwards monthly operating rept for Jan 1983
WAREHBOURG, D Public Service Co of Colorado 83/02/08
Director's Office, Office of Inspection and Enforcement 1p
17232 061 24X Fiche 50-267, 83/02/08, 8302220157

--8302220159 Monthly operating rept for Jan 1983.
MCBRIDE, L M Public Service Co of Colorado 83/02/08 5pp
17232-062 24X Fiche 50-267, 83/02/08, 8302220159

B Reportable occurrences, LERs & related correspondence

8302160246 PNG-IV-82-047 on 821209, abnormal degradation in
RCPB identified & leak between secondary & primary side
of steam generator module B-2-3 discovered Investigation
underway
WESTERMAN, T F, MADSEN, O L Region 4, Office of Director 82/12/10
1p 17170 262 24X Fiche 50-267, 82/12/10, 8302160246

8302070574 Forwards LER 82-054/03L-0 Detailed event analysis encl
WAREHBOURG, D Public Service Co of Colorado 83/01/28
COLLINS, J T Region 4, Office of Director 4pp 17034 218 24X
Fiche 50-267, 83/01/28, 8302070574

--8302070579 LER 82-054/03L-0 on 821229, outlet temps exceeded 120 F limit
when reactor became critical during isolation of svc water
flow to PCRV cooling water HX Caused by lack of cooling
source Design change initiated
FULLER, C Public Service Co of Colorado 83/01/28 Region 4,
Office of Director 1p 17034 222 24X Fiche: 50-267, 83/01/28,
8302070574

8302070584 Forwards LER 82-053/03L-0 Detailed event analysis encl
WAREHBOURG, D Public Service Co of Colorado 83/01/28
COLLINS, J T Region 4, Office of Director 4pp 17035 202 24X
Fiche 50-267, 83/01/28, 8302070584

--8302070591 LER 82-053/03L-0 on 821229, fuel storage well pressure
exceeded atmospheric pressure while reactor was shut down
Caused by one gas compressor being out of svc for maint and
other pumping less than capacity Compressors repaired.
FULLER, C Public Service Co of Colorado, 83/01/28 Region 4,
Office of Director 1p 17035 206 24X Fiche 50-267, 83/01/28,
8302070584

8302070618 Forwards LER 82-052/03L-0 Detailed event analysis encl
WAREHBOURG, D Public Service Co of Colorado 83/01/28
COLLINS, J T Region 4, Office of Director 3pp 17035 068 24X
Fiche 50-267, 83/01/28, 8302070618

--8302070623 LFR 82-052/03L-0 on 821229-830111, eight Class I hydraulic
shock suppressors found inoperable Caused by improper
reservoir orientation or lack of oil Snubbers either
rebuilt, tested, reinstalled or replaced w/qualified spares
FULLER, C, Public Service Co of Colorado 83/01/28 Region 4,
Office of Director 1p 17035 073 24X Fiche 50-267, 83/01/28,
8302070618

8302150001 Forwards LER 83-003/03L-0 Detailed event analysis encl
WAREHBOURG, D, CLAYTON, G J, FULLER, C Public Service Co of
Colorado 83/02/03 COLLINS, J T Region 4, Office of Director.
7pp 17147 093 24X Fiche 50-267, 83/02/03, 8302150001

--8302150003 LER 83-003/03L-0 on 14 separate occasions, total primary
coolant oxidants exceeded acceptable limits, Oxidant
offgassing caused by increasing temps during normal reactor
startup & rise to power Oxidant concentration reduced
FULLER, C, Public Service Co of Colorado 83/02/03 Region 4,
Office of Director 1p 17147 100 24X Fiche 50-267, 83/02/03,
8302150001

8302150574 Forwards LER 83-002/03L-0 Detailed event analysis encl
WAREHBOURG, D Public Service Co of Colorado 83/02/03
COLLINS, J T Region 4, Office of Director 3pp 17155 241 24X
Fiche 50-267, 83/02/03, 8302150574

--8302150593 LER 83-002/03L-0, on 830104, seven unsampled releases made
from reactor bldg sump on 821221 & 22 Caused by personnel
error Daily sample taking resumed on 821223 Responsible
personnel retrained
FULLER, C Public Service Co of Colorado 83/02/03 Region 4,
Office of Director 1p. 17155 246 24X Fiche: 50-267, 83/02/03,
8302150574

8302170344 Forwards revised LER 82-052/03L-1 Detailed event analysis
encl.
WAREHBOURG, D Public Service Co of Colorado, 83/02/07
COLLINS, J T Region 4, Office of Director 3pp. 17184, 153 24X
Fiche 50-267, 83/02/07, 8302170344

--8302170349 Revised LER 82-052/03L-1, during 821229-830111, eight Class I
hydraulic shock suppressors found inoperable, Caused by
improper reservoir orientation or lack of oil due to pipe
movement, Snubbers rebuilt, tested & reinstalled or replaced.
FULLER, C Public Service Co of Colorado 83/02/07, Region 4,
Office of Director 1p 17184, 158 24X Fiche: 50-267, 83/02/07,
8302170344

DOCKETED ITEMS

8302230720 Discusses recent steam generator tube leak info on 771130 leak probably irrelevant since causes of recent leaks different
WAGNER, P Division of Resident, Reactor Project & Engineering Programs 83/02/15 TRAMMELL, C Operating Reactors Branch 3 2pp 17257 287 24X Fiche 50-267, 83/02/15, 8302230720

8302250378 PNO-IV-83-007 on 830215, loss of noninterruptible instrument bus resulted in automatic loop 11 shutdown followed by manual scram upon loss of instrument indications. Caused by internal power fuse failure in B inverter Fuse replaced
WEBSTERMAN, T F, MADSEN, G L Region 4, Office of Director 83/02/22 1p 17297 217 24X Fiche 50-267, 83/02/22, 8302250378

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & NE re certificates & revised format for reactor operator & senior reactor operator licensees. Bvc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302250256 Submits proposed schedule for plant site Category 5 exam visits, in response to 830101 ltr
MARENBOURG, D W Public Service Co of Colorado 83/02/04 EISENHUT, D O Division of Licensing 1p 17292 129 24X Fiche 50-267, 83/02/04, 8302250256

100KE1 50-269 OCONEE NUCLEAR STATION, UNIT 1

8210120650 Releases public version of rev to emergency plan manual
FELTON, J M Division of Rules and Records 82/09/23 Document Management Branch 1p 15684 339 24X Fiche 50-269, 82/09/23, 8210120650

--8210120652 Forwards public version of Revision 5 to emergency plan manual.
TUCKER, H B Duke Power Co 82/09/14 O'REILLY, J P Region 2, Office of Director 1p 15684 340 24X Fiche 50-269, 82/09/23, 8210120650

--8210120656 Public version of revised emergency plan implementing procedures, including Procedures PF/D/B/2003/04 re establishment & insp of technical support ctr & CP/3/A/2002/05 re post-accident caustic injection into LPIS
* Duke Power Co 82/09/30 85pp 15684 341 24X Fiche 50-269, 82/09/23, 8210120650

--8210120658 Public version of Rev 5 to emergency plan
SMITH, J E Duke Power Co 82/09/01 162pp 15685 066 24X Fiche 50-269, 82/09/23, 8210120650

8302040497 Releases public version of rev to emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/28 Document Management Branch 1p 17046 298 24X Fiche 50-269, 83/01/28, 8302040497

--8302040504 Forwards public version of Rev 7 to emergency plan & Rev 11 to emergency plan implementing procedures Receipt forms encl
TUCKER, H B, MCINTOSH, J T Duke Power Co 83/01/07 O'REILLY, J P Region 2, Office of Director GLOVER, R M Office of Nuclear Reactor Regulation, Director 3pp 17046 299 24X Fiche 50-269, 83/01/28, 8302040497

--8302040506 Public version of Rev 7 to emergency plan
SMITH, J E Duke Power Co 82/12/14 16pp 17046 302 24X Fiche 50-269, 83/01/28, 8302040497

--8302040511 Public version of revised emergency plan implementing procedures, including Procedure AP/D/B/1000/07 re offsite dose calculations by control room personnel or emergency coordinator during LOCA
CAMPBELL, J J, EDWARDS, N Duke Power Co 82/12/07 46pp 17046 322 24X Fiche 50-269, 83/01/28, 8302040497

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for GL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Bvc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302220052 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document Management Branch 1p 17233 324 24X Fiche 50-269, 83/02/14, 8302220052

--8302220055 Forwards public version of Rev 83-1 to emergency plan implementing procedures, including Procedure CP/D/B/2003/02 re estimate of failed fuel based on I-131 concentration
Receipt form encl
TUCKER, H B Duke Power Co 83/01/27 O'REILLY, J P Region 2, Office of Director 2pp 17233 325 24X Fiche 50-269, 83/02/14, 8302220052

--8302220059 Public version of Rev 83-1 to emergency plan implementing procedures, including Procedure CP/D/B/2003/02 re estimate of failed fuel based on I-131 concentration
COV, S A Duke Power Co 83/01/10 72pp 17233 327 24X Fiche 50-269, 83/02/14, 8302220052

J Insurance & indemnity information

8302090413 Requests reimbursement of pro rata portion of indemnity fees paid due to termination of NRC indemnification under Price-Anderson Act on 821115
HOUSE, D R Duke Power Co 83/02/04 SALTZMAN, J Antitrust & Economic Analysis Branch (Utility Finance) 1p 17070 362 24X Fiche 50-000, 83/02/04, 8302090413

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302170089 Provides justification for interim operation pending resolution of equipment qualification program
WAGNER, P Operating Reactors Branch 4 82/03/03 NOVAK, T Assistant Director for Licensing 2pp 17196 223 24X Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation reports are expected to be completed. Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X Fiche 50-000, 83/01/18, 8302170019

--8302170240 Concludes that based on licensee 820225 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
WAGNER, P C Operating Reactors Branch 4 82/10/28 EISENHUT, D O Division of Licensing 1p 17197 041 24X Fiche 50-000, 83/01/18, 8302170019

8302010498 Forwards final evaluation of pressurizer safety & relief valve piping sys per NUREG-0737, Item 11 D 1 Mods to reduce piping sys stresses below FSAR spec will be performed during next refueling outage. Plant safety not affected
TUCKER, H B Duke Power Co 83/01/21 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 16981 074 24X Fiche 50-269, 83/01/21, 8302010498

8302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to B&W plants, for use as starting point for addl detailed technical discussions between NRC & B&W Owners Group representatives
CAINAS, G C Assistant Director for Operating Reactors 83/01/31 WALLACE, E Babcock & Wilcox Operating Plants Owners Group WALLACE, E General Public Utilities - GPU Service Corp 6pp 17134 100 24X Fiche 50-000, 83/01/31, 8302100257

8302220467 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nuclear Station, Units 1, 2 & 3," informal rept
UDVA, C EOG, Inc FIN A-6429 8302220467 83/01/31 EHAMI, H Division of Systems Integration (post 811005) 15pp 17239 358 24X Fiche 50-269, 83/01/31, 8302220467

8302070504 Confirms info provided to NRC at 830114 meeting re flui reduction programs associated w/pressurized thermal shock Units predicted to exceed NRC screening criteria through operating life
TUCKER, H B Duke Power Co 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 14pp 17076 347 24X Fiche 50-269, 83/02/03, 8302070504

8302140168 Discusses encl response to util 820525 submittal re proposed water inventory monitoring sys, based on considerations behind Dec 1982 orders on instrumentation to detect inadequate core cooling (NUREG-0737, Item 11 F 2) DIRCKS, W J Office of the Executive Director for Operations 83/02/07 AHEARNE, J F Commissioners 1p 17144 160 24X Fiche 50-269, 83/02/07, 8302140168

--8302140173 Responds to conversation w/Commissioner Ahearne re status of review of 820525 submittal on instrumentation to detect inadequate core cooling (Item 11 F 2) & relationship w/Dec 1982 order Sys does not meet requirements STOLZ, J F Operating Reactors Branch 4 83/02/01 TUCKER, H B Duke Power Co 3pp 17221 219 24X Fiche 50-269, 83/02/07, 8302140169

--8207240433 Forwards questions arising during review of util submittal describing proposed water inventory monitoring sys Generic review incomplete due to apparent reluctance on part of util to supply info Sys unsatisfactory ANDERSON, R L Oak Ridge National Laboratory 82/09/15 HUANG, T Core Performance Branch 4pp 17144 164 24X Fiche 50-269, 83/02/07, 8302140168

--8302140174 Discusses response to util 820525 submittal re proposed water inventory monitoring sys & relationship to Dec 1982 order on instrumentation to detect inadequate core cooling Response should be expedited AHEARNE, J Commissioners 83/01/20 DIRCKS, W J Office of the Executive Director for Operations 1p 17144 169 24X Fiche 50-269, 83/02/07, 8302140168

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D Q Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080334 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support or licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D Q Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302090098 Generic Ltr 83-10F to all licensees w/B&W designed NSSS (except TMI) re resolution of TMI Action Item 11 K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl EISENHUT, D Q Division of Licensing 83/02/08 Duke Power Co 23pp 17298 291 24X Fiche 50-000, 83/02/08, 8302090098

8302160490 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising radiological effluent Tech Specs to incorporate design mods Mods reduce environ impact of effluent releases ALARA per App 1, 10CFR20 requirements TUCKER, H B Duke Power Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 7pp 17214 009 24X Fiche 50-269, 83/02/09, 8302160480

--8302160484 Proposed Tech Specs re radiological effluent controls TUCKER, H B Duke Power Co 83/02/09 67pp 17214 016 24X Fiche 50-269, 83/02/09, 8302160480

8302160236 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, allowing use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during performance of leak tests of connected sys TUCKER, H B Duke Power Co 83/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 17170 121 24X Fiche 50-269, 83/02/10, 8302160236

--8302160242 Proposed Tech Specs allowing use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during performance of leak tests of connected sys when RCS pressure/temp limits controlling * Duke Power Co 83/02/10 10pp 17170 124 24X Fiche 50-269, 83/02/10, 8302160236

8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level VAN VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J Operating Reactors Branch 4 3pp 17303 098 24X Fiche 50-000, 83/02/17, 8302250102

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20 will be forwarded in Apr 1983 ELI, IOT, J L, ROWLAND, G B Duke Power Co 83/02/18 DIRKEL, R Office of Nuclear Reactor Regulation, Director 2pp 17296 215 24X Fiche 50-000, 83/02/18, 8302250391

--8307250400 Rev OA to Nuclear Guide 1 61, "Damping Values for Seismic Design of Nuclear Power Plants" * Duke Power Co 83/01/06 7pp 17296 217 24X Fiche 50-000, 83/02/18, 8302250391

--8302250406 Rev 19 to Nuclear Guide 1 84, "Design & Fabrication Code Case Acceptability, ASME Section III, Div 1" WYKE, T F Duke Power Co 83/01/06 12pp 17296 224 24X Fiche 50-000, 83/02/18, 8302250391

--8307250411 Rev 19 to Nuclear Guide 1 85, "Mats Code Case Acceptability, ASME Section III, Div 1" WYKE, T F Duke Power Co 83/01/06 11pp 17296 237 24X Fiche 50 000, 83/02/18, 8302250391

--8302250417 Rev 1A to Nuclear Guide 1 111, "Methods for Estimating Atmospheric Transport & Dispersion of Gaseous Effluents in Routine Releases From Light-Water-Cooled Reactors" EMMONDS, R F Duke Power Co 83/01/06 49pp 17296 248 24X Fiche 50-000, 83/02/18, 8302250391

--8302250424 Rev 1A to Nuclear Guide 1 143, "Design Guidance for Radwaste Mgt Sys, Structures & Components Installed in Light-Water-Cooled Nuclear Power Plants" MILLER, R E, SNOW, A L Duke Power Co 83/01/06 14pp 17296 297 24X Fiche 50-000, 83/02/18, 8302250391

--8302250436 Rev 1 to Nuclear Guide 1 147, "Inservice Insp Code Case Acceptability, ASME Section XI, Div 1" DALTON, D W Duke Power Co 83/01/06 7pp 17294 311 24X Fiche 50-000, 83/02/18, 8302250391

--8302250440 Rev 1 to Nuclear Guide 4 7, "General Site Suitability Criteria for Nuclear Power Stations" GALLEHER, G A, HENRICKS, J R, HAGER, S B Duke Power Co 83/01/06 34pp 17296 318 24X Fiche 50-000, 83/02/18, 8302250391

8302240062 Notifies that decision to reaffirm or withdraw request for hearing re order imposing environ qualification requirements will be made within 30 days following review of 830222 final rule CARR, A V Duke Power Co 83/02/21 EISENHUT, D Q NRC - No Detailed Affiliation Given 1p 17275 020 24X Fiche 50-269, 83/02/21, 8302240062

8302280325 Application for amend to Licenses DPR-38, DPR-47 & DPR-55 revising Tech Specs re reactor vessel surveillance capsule withdrawal schedule Class III & 1 fees encl TUCKER, H B Duke Power Co 83/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 17308 067 24X Fiche 50-269, 83/02/23, 8302280325

--8302280327 Proposed Tech Spec changing reactor vessel surveillance capsule withdrawal schedule * Duke Power Co 83/02/23 2pp 17308 070 24X Fiche 50-269, 83/02/23, 8302280325

8302250371 Supplemental application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs to provide curves based on mats properties previously provided & revised set of operator guidance TUCKER, H B Duke Power Co 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17297 195 24X Fiche 50-269, 83/02/24, 8302250371

--8302250375 Proposed Tech Specs providing curves based on mats properties previously provided & revised set of operator guidance * Duke Power Co 83/02/24 14pp 17297 198 24X Fiche 50-269, 83/02/24, 8302250371

G Inspection reports, IE Bulletins & correspondence

8302150327 Responds to IE Bulletin 82-04 re Bunker-Ramo electrical penetrations Electrical penetrations at facilities mfg by Viking Corp No Bunker-Ramo penetrations installed TUCKER, H B Duke Power Co 83/01/12 O'REILLY, J P Region 2, Office of Director 1p 17148 174 24X Fiche 50-269, 83/01/12, 8302150327

8302160014 Summary of 830120 meeting w/utilis, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted TRAMMELL, C H Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212040358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212040358

DOCKETED ITEMS

8302150165 Forwards IE Insp Repts 50-269/83-02, 50-270/83-02 & 50-287/83-02 on 830104-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/27
TUCKER, H B Duke Power Co 2pp 17147 228 24X
Fiche 50-269, 83/01/27, 8302150165

--8302150171 IE Insp Repts 50-269/83-02, 50-270/83-02 & 50-287/83-02 on 830104-06 No noncompliance noted Major areas inspected
licensee action on previous unresolved items, inspector
followup items & LERs
ECONOMOS, W J, BLAKE, J J Division of Project & Resident Programs
83/01/25 7pp 17147 230 24X Fiche 50-269, 83/01/27, 8302150165

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150608 Forwards IE Enforcement Meeting Repts 50-269/83-05, 50-270/83-05 & 50-287/83-05 on 830107
O'REILLY, J P Region 2, Office of Director 83/01/31 TUCKER, H B
Duke Power Co 1p 17151 308 24X Fiche 50-269, 83/01/31, 8302150608

--8302150619 IE Enforcement Meeting Repts 50-269/83-05, 50-270/83-05 & 50-287/83-05 on 830107 Major areas discussed corrective
actions re licensee finding two manual containment
isolation instrument air valves open from 821206-12
LFWIB, R C Division of Project & Resident Programs 83/01/27
2pp 17151 309 24X Fiche 50-269, 83/01/31, 8302150608

8302220418 Forwards "B&W 177 Fuel Assembly Owners Group Safe End Task
Force Rept on Generic Investigation of HPI/HJ Nozzle
Component Cracking " Recommended inservice insp program
implemented at Units 2 & 3 w/augmented program for Unit 1
TUCKER, H B Duke Power Co 83/02/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 2pp 17232 229 24X Fiche 50-269, 83/02/15, 8302220418

8220423 "B&W 177 Fuel Assembly Owners Group Safe End Task Force
Rept on Generic Investigation of HPI/HJ Nozzle Component
Cracking
* Babcock & Wilcox Co 77-1140611-00 83/02/15 70pp
17232 232 24X Fiche 50-269, 83/02/15, 8302220418

02250398 Forwards addl info re 821004 request for relief from
hydrostatic inservice insp requirements of Section XI of
ASME Boiler & Pressure Vessel Code
TUCKER, H B Duke Power Co 83/02/17 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 15pp 17296 197 24X Fiche 50-269, 83/02/17, 8302250398

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radiowaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 099 24X Fiche 50-000, 83/02/24, 8212060365

R Periodic operating reports & related correspondence

8302180374 Forwards monthly operating repts for Jan 1983
TUCKER, H B Duke Power Co 83/02/15 Director's Office, Office
of Inspection and Enforcement 1p 17209 320 24X
Fiche 50-269, 83/02/15, 8302180374

--8302180377 Monthly operating repts for Jan 1983
REAVIS, J A Duke Power Co 83/02/15 16pp 17209 321 24X
Fiche 50-269, 83/02/15, 8302180374

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen
recombiner is likely to malfunction following exposure
to elevated temp, high humidity environ Replacement part
identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J
Region 4, Office of Director, 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

8302030466 Forwards LER 83-001/01T-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 83/01/25 O'REILLY, J P Region 2,
Office of Director 3pp 17006 162 24X Fiche 50-269, 83/01/25,
8302030466

--8302030473 LER 83-001/01T-0 on 830111, evaluation determined that single
failure in Keowee Hydro Woodward governor sys could prevent
automatic actuation or emergency power Caused by design
deficiency in switching logic Operators informed
PETTY, J C Duke Power Co 83/01/25 Region 2, Office of
Director 1p 17006 165 24X Fiche 50-269, 83/01/25, 8302030466

8302030425 Forwards LER 83-002/01T-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 83/01/26 O'REILLY, J P Region 2,
Office of Director 2pp 17005 221 24X Fiche 50-269, 83/01/26,
8302030425

--8302030434 LER 83-002/01T-0 on 830112, overhead emergency power path
from Keowee Hydro units to transformer CT-1 made inoperable
w/o testing alternate (underground) path within 1 h Caused
by personnel error Personnel counseled
PETTY, J C Duke Power Co 83/01/26 Region 2, Office of
Director 1p 17005 223 24X Fiche 50-269, 83/01/26, 8302030425

8302280412 Forwards LER 83-003/03L-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 83/02/18 O'REILLY, J P Region 2,
Office of Director 2pp 17309 158 24X Fiche 50-269, 83/02/18,
8302280412

--8302280418 LER 83-003/03L-0 on 830120, engineering safeguards channels
A & B & C reactor bldg narrow-range pressure transmitter
drifted out of calibr Caused by deficient procedures
Channels recalibr & procedures changed
PETTY, J C Duke Power Co 83/02/18 Region 2, Office of
Director 1p 17309 160 24X Fiche 50-269, 83/02/18, 8302280412

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for GLS, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302240058 Responds to Generic Ltr 83-01 Operator licensing exam
schedules listed
TUCKER, H B Duke Power Co 83/02/21 EISENHUT, D O Division of
Licensing 2pp 17281 041 24X Fiche 50-000, 83/02/21, 8302240058

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8210120650 Releases public version of rev to emergency plan manual
FELTON, J M Division of Rules and Records 82/09/23 Document
Management Branch 1p 15684 339 24X Fiche 50-269, 82/09/23,
8210120650

--8210120652 Forwards public version of Revision 5 to emergency plan
manual
TUCKER, H B Duke Power Co 82/09/14 O'REILLY, J P Region 2,
Office of Director 1p 15684 340 24X Fiche 50-269, 82/09/23,
8210120650

--8210120655 Public version of revised emergency plan implementing
procedures, including Procedures PT/O/B/2000/04 re
establishment & insp of technical support ctr &
CP/3/A/2002/05 re post-accident caustic injection into LPIS
* Duke Power Co 82/09/30 85pp 15684 341 24X
Fiche 50-269, 82/09/23, 8210120650

--8210120658 Public version of Rev 5 to emergency plan
SMITH, J E Duke Power Co 82/09/01 162pp 15685 066 24X
Fiche 50-269, 82/09/23, 8210120650

8302040497 Releases public version of rev to emergency plan &
emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/28 Document
Management Branch 1p 17046 298 24X Fiche 50-269, 83/01/28,
8302040497

--8302040504 Forwards public version of Rev 7 to emergency plan & Rev II
to emergency plan implementing procedures Receipt forms
encl
TUCKER, H B, MCINTOSH, J T Duke Power Co 83/01/07
O'REILLY, J P Region 2, Office of Director GLOVER, R M Office
of Nuclear Reactor Regulation, Director 3pp 17046 299 24X
Fiche 50-269, 83/01/28, 8302040497,

DOCKETED ITEMS

81

--8302040506 Public version of Rev 7 to emergency plan
SMITH, J E Duke Power Co 82/12/14 16pp 17046 302 24X
Fiche 50-269, 83/01/28, 8302040497

--8302040511 Public version of revised emergency plan implementing
procedures, including Procedure AP/D/B/1000/07 re offsite
dose calculations by control room personnel or emergency
coordinator during LOCA
CAMPELLE, J, EDWARDS, N Duke Power Co 82/12/09 46pp
17046 322 24X Fiche 50-269, 83/01/28, 8302040497

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability." Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302220052 Releases public version of revised emergency plan
implementing procedures
FELTOW, J M Division of Rules and Records 83/02/14 Document
Management Branch 1p 17233 324 24X Fiche 50-269, 83/02/14,
8302220052

--8302220055 Forwards public version of Rev 83-1 to emergency plan
implementing procedures, including Procedure CP/D/B/2003/02
re estimate of failed fuel based on I-131 concentration
Receipt form encl
TUCKER, H B Duke Power Co 83/01/27 O'REILLY, J P Region 2,
Office of Director 2pp 17233 325 24X Fiche 50-269, 83/02/14,
8302220052

--8302220059 Public version of Rev 83-1 to emergency plan implementing
procedures, including Procedure CP/D/B/2003/02 re estimate
of failed fuel based on I-131 concentration
COY, S A Duke Power Co 83/01/10 72pp 17233 327 24X
Fiche 50-269, 83/02/14, 8302220052

J. Insurance & indemnity information

8302090413 Requests reimbursement of pro rata portion of indemnity
fees paid due to termination of NRC indemnification under
Price-Anderson Act on 821115
HOUSE, D R Duke Power Co 83/02/04 SALTZMAN, J Antitrust &
Economic Analysis Branch (Utility Finance) 1p 17070 362 24X
Fiche 50-000, 83/02/04, 8302090413

P. Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170069 Provides justification for interim operation pending
resolution of equipment qualification program
WAGNER, P Operating Reactors Branch 4 82/03/03 NOVAK, T
Assistant Director for Licensing 2pp 17196 223 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by
which technical evaluation repts are expected to be
completed Requests justification for continued operation of
each group by 821008 & 18, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170240 Concludes that based on licensee 820225 submittal, continued
operation until completion of environ qualification program
will not present undue risk to public health & safety
WAGNER, P C Operating Reactors Branch 4 82/10/28 EISENHUT, D O
Division of Licensing 1p 17197 041 24X Fiche 50-000,
83/01/18, 8302170019

8302010498 Forwards final evaluation of pressurizer safety & relief
valve piping sys. per NUREG-0737, Item II, D 1. Mods to reduce
piping sys stresses below FBAR spec will be performed during
next refueling outage Plant safety not affected
TUCKER, H B Duke Power Co 83/01/21 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 3pp 16981 074 24X Fiche 50-269, 83/01/21, 8302010498

8302100257 Forwards confirmatory study on applicability of pressurized
thermal shock screening criteria to B&W plants, for use as
starting point for addl detailed technical discussions
between NRC & B&W Owners Group representatives
LAINAS, O C Assistant Director for Operating Reactors 83/01/31
WALLACE, E Babcock & Wilcox Operating Plants Owners Group
WALLACE, E General Public Utilities - CPU Service Corp 4pp,
17134 100 24X Fiche 50-000, 83/01/31, 8302100257

8302220467 "Adequacy of Station Electric Distribution Sys Voltage,
Dconee Nuclear Station, Units 1, 2 & 3," informal rept
UDY, A C EG&G, Inc FIN A-6429 8302220467 83/01/31 EMAMI, H
Division of Systems Integration (post 811005) 15pp 17239 358,
24X Fiche 50-269, 83/01/31, 8302220467

8302100049 Lists info to be included in util submittal re status of
Facility & of program which ensures that screening criterion
for pressurized thermal shock not exceeded at OL expiration
STOLZ, J F Operating Reactors Branch 4 83/02/02 TUCKER, H B
Duke Power Co 4pp 17135 130 24X Fiche 50-270, 83/02/02,
8302100049

8302070504 Confirms info provided to NRC at 830114 meeting re flux
reduction programs associated w/pressurized thermal shock.
Units predicted to exceed NRC screening criteria through
operating life
TUCKER, H B Duke Power Co 83/02/03 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 14pp 17036 347 24X Fiche 50-269, 83/02/03, 8302070504.

8302140168 Discusses encl response to util 820525 submittal re
proposed water inventory monitoring sys. based on
considerations behind Dec 1982 orders on instrumentation to
detect inadequate core cooling (NUREG-0737, Item II F 2)
DIRCKS, W J Office of the Executive Director for Operations
83/02/07 AHEARNE, J F Commissioners 1p 17144 160 24X
Fiche 50-269, 83/02/07, 8302140168

--8302140173 Responds to conversation w/Commissioner Ahearne re status of
review of 820525 submittal on instrumentation to detect
inadequate core cooling (Item II F 2) & relationship w/Dec
1982 order Sys does not meet requirements
STOLZ, J F Operating Reactors Branch 4 83/02/01 TUCKER, H B
Duke Power Co 3pp 17221 217 24X Fiche 50-269, 83/02/07,
8302140168

--8207240433 Forwards questions arising during review of util submittal
describing proposed water inventory monitoring sys. Generic
review incomplete due to apparent reluctance on part of util
to supply info Sys unsatisfactory
ANDERSON, R L Oak Ridge National Laboratory 82/09/15, HUANG, T
Core Performance Branch 4pp 17144 164 24X
Fiche 50-269, 83/02/07, 8302140168

--8302140174 Discusses response to util 820525 submittal re proposed
water inventory monitoring sys & relationship to Dec 1982
order on instrumentation to detect inadequate core cooling
Response should be expedited
AHEARNE, J, Commissioners 83/01/20 DIRCKS, W J Office of the
Executive Director for Operations 1p 17144 169 24X
Fiche 50-269, 83/02/07, 8302140168

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions Ability to use code must be
demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234, 24X
Fiche 50-000, 83/02/08, 8302080304

8302090098 Generic Ltr 83-10F to all licensees w/B&W designed NSSS
(except TH1) re resolution of TH1 Action Item II K 3.5,
"Automatic Trip of Reactor Coolant Pumps" Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08, Duke Power Co,
23pp 17298 271 24X Fiche 50-000, 83/02/08, 8302090098.

8302180480 Application to amend Licensee DPR-38, DPR-47 & DPR-55,
revising radiological effluent Tech Specs to incorporate
design mods. Mods reduce environ impact of effluent releases
ALARA per App 1, 10CFR20 requirements
TUCKER, H B Duke Power Co 83/02/09 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 7pp 17214 009 24X Fiche 50-269, 83/02/09, 8302180480.

DOCKETED ITEMS

--8302180484 Proposed Tech Specs re radiological effluent controls
TUCKER, H B Duke Power Co 83/02/09 67pp 17214 016 24X
Fiche 50-269, 83/02/09, 8302180480

8302160236 Application for amend to Licenses DPR-38, DPR-47 & DPR-55,
allowing use of RCS inservice leak & hydrostatic test
heatup & cooldown limitations during performance of leak
tests of connected sys
TUCKER, H B Duke Power Co 83/02/10 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 1p 17170 121 24X Fiche 50-269, 83/02/10, 8302160236

--8302160232 Proposed Tech Specs allowing use of RCS inservice leak &
hydrostatic test heatup & cooldown limitations during
performance of leak tests of connected sys when RCS
pressure/temp limits controlling
* Duke Power Co 83/02/10 10pp 17170 124 24X
Fiche 50-269, 83/02/10, 8302160236

8302250102 Notification of 830223 meeting w/B&W regulatory response
group in Bethesda, MD to discuss small break LOCA procedures
& maint or proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302250102

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20
will be forwarded in Apr 1983
ELLIOTT, J L, ROWLAND, O B Duke Power Co 83/02/18 BRKEL, R
Office of Nuclear Reactor Regulation, Director 2pp 17296 215
24X Fiche 50-000, 83/02/18, 8302250391

--8302250424 Rev 1A to Nuclear Guide 1 143, "Design Guidance for Radwaste
Mgt Sys, Structures & Components Installed in
Light-Water-Cooled Nuclear Power Plants"
MILLER, R E, SNOW, A L Duke Power Co 83/01/06 14pp
17296 297 24X Fiche 50-000, 83/02/18, 8302250391

--8302250436 Rev 1 to Nuclear Guide 1 147, "Inservice Insp Code Case
Acceptability, ASME Section XI, Div 1"
DALTON, D W Duke Power Co 83/01/06 7pp 17296 311 24X
Fiche 50-000, 83/02/18, 8302250391

8302240062 Notifies that decision to reaffirm or withdraw request for
hearing re order imposing environ qualification requirements
will be made within 30 days following review of 830222 final
rule
CARR, A V Duke Power Co 83/02/21 EISENHUT, D O NRC - No
Detailed Affiliation Given 1p 17275 020 24X
Fiche 50-269, 83/02/21, 8302240062

8302280325 Application for amend to Licenses DPR-38, DPR-47 & DPR-55
revising Tech Specs re reactor vessel surveillance capsule
withdrawal schedule Class III & I fees encl
TUCKER, H B Duke Power Co 83/02/23 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 3pp 17308 067 24X Fiche 50-269, 83/02/23, 8302280325

--8302280327 Proposed Tech Spec changing reactor vessel surveillance
capsule withdrawal schedule
* Duke Power Co 83/02/23 2pp 17308 070 24X
Fiche 50-269, 83/02/23, 8302280325

8302290371 Supplemental application for amend to Licenses DPR-38, DPR-47
& DPR-55, revising Tech Specs to provide curves based on
matls properties previously provided & revised set of
operator guidance
TUCKER, H B Duke Power Co 83/02/24 DENTON, H R Office of
Nuclear Reactor Regulation, Director 3pp 17297 195 24X
Fiche 50-269, 83/02/24, 8302290371

--8302290375 Proposed Tech Specs providing curves based on matls
properties previously provided & revised set of operator
guidance
* Duke Power Co 83/02/24 14pp 17297 198 24X
Fiche 50-269, 83/02/24, 8302290371

G Inspection reports, IE Bulletins & correspondence

8302150327 Responds to IE Bulletin 82-04 re Bunker-Ramo electrical
penetrations Electrical penetrations at facilities mfg by
Viking Corp No Bunker-Ramo penetrations installed
TUCKER, H B Duke Power Co 83/01/12 O'REILLY, J P Region 2,
Office of Director 1p 17148 174, 24X Fiche 50-269, 83/01/12,
8302150327

8302160014 Summary of 830120 meeting w/utilis, Bechtel, Franklin Research
Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11,
"Masonry Wall Design" Addl testing not warranted
FRANKEL, L C M Operating Reactors Branch 3 83/01/25 Operating
Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25,
8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150165 Forwards IE Insp Repts 50-269/83-02, 50-270/83-02 &
50-287/83-02 on 830104-06 No noncompliance noted
DAME, H C Division of Project & Resident Programs 83/01/27
TUCKER, H B Duke Power Co 2pp 17147 228 24X
Fiche 50-269, 83/01/27, 8302150165

--8302150171 IE Insp Repts 50-269/83-02, 50-270/83-02 & 50-287/83-02 on
830104-06 No noncompliance noted Major areas inspected
licensee action on previous unresolved items, inspector
followup items & LERs
ECONOMOS, H, BLAKE, J J Division of Project & Resident Programs
83/01/25 7pp 17147 230 24X Fiche 50-269, 83/01/27, 8302150165

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC
Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150608 Forwards IE Enforcement Meeting Repts 50-269/83-05,
50-270/83-05 & 50-287/83-05 on 830107
O'REILLY, J P Region 2, Office of Director 83/01/31 TUCKER, H B
Duke Power Co 1p 17151 308 24X Fiche 50-269, 83/01/31,
8302150608

--8302150619 IE Enforcement Meeting Repts 50-269/83-05, 50-270/83-05 &
50-287/83-05 on 830107 Major areas discussed corrective
actions re licensee finding two manual containment
isolation instrument air valves open from 821206-12
LWIS, R C Division of Project & Resident Programs 83/01/27
2pp 17151 309 24X Fiche 50-269, 83/01/31, 8302150608

8302220418 Forwards "B&W 177 Fuel Assembly Owners Group Safe End Test
Force Rept on Generic Investigation of HPI/MU Nozzle
Component Cracking" Recommended inservice insp program
implemented at Units 2 & 3 w/augmented program for Unit 1
TUCKER, H B Duke Power Co 83/02/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 2pp 17232 229 24X Fiche 50-269, 83/02/15, 8302220418

8302250398 Forwards addl info re 821004 request for relief from
hydrostatic inservice insp requirements of Section XI of
ASME Boiler & Pressure Vessel Code
TUCKER, H B Duke Power Co 83/02/17 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 15pp 17296 197 24X Fiche 50-269, 83/02/17, 8302250398

8212060343 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060343

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302180374 Forwards monthly operating repts for Jan 1983
TUCKER, H B Duke Power Co 83/02/15 Director's Office, Office
of Inspection and Enforcement 1p 17209 320 24X
Fiche 50-269, 83/02/15, 8302180374

--8302180377 Monthly operating repts for Jan 1983
REAVIS, J A Duke Power Co 83/02/15 16pp 17209 321 24X
Fiche 50-269, 83/02/15, 8302180374

DOCKETED ITEMS

83

5 Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301010203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, PSS vendors, reactor vendors & AC re certificates & revised format for reactor operator & senior reactor operator licensees Svc list encl EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 1pp 17347 177 24X Fiche 50-000, 83/01/31, 8301010203

8302240068 Responds to Generic Ltr 83-01 Operator licensing exam schedules listed TUCKER, H B Duke Power Co 83/02/21 EISENHUT, D O Division of Licensing 2pp 17281 041 24X Fiche 50-000, 83/02/21, 8302240068

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 1pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302090336 Requests that licensees submit three copies of emergency plans & procedures, despite recent amend to 10CFR50.54(i) which requires licensees to submit only one copy to regional administrator MARTIN, T T Division of Engineering & Technical Programs 83/02/02 MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 17070 280 24X Fiche 50-271, 83/02/02, 8302090336

8302100340 Releases public version of revised page of table of contents FELTON, J M Division of Rules and Records 83/02/03 Document Management Branch 1p 17135 134 24X Fiche 50-271, 83/02/03, 8302100340

--8302100043 Forwards public version of Rev 5 to Page 7 of table of contents Receipt form encl MARKT, D Yankee Atomic Electric Co MARKT, D Vermont Yankee Nuclear Power Corp 83/01/28 NRC - No Detailed Affiliation Given 2pp 17135 135 24X Fiche 50-271, 83/02/03, 8302100040

--8302100046 Public version of Rev 5 to Page 7 of table of contents, * Yankee Atomic Electric Co * Vermont Yankee Nuclear Power Corp 83/01/31 1p 17135 137 24X Fiche 50-271, 83/02/03, 8302100040

8302250347 Forwards addl info re physical characteristics of primary & alternate emergency operations facilities (EOF), per 830214 request Primary EOF located 35 miles from plant ctr SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/02/22 VASSALLO, D B Operating Reactors Branch 2 2pp 17291 177 24X Fiche 50-271, 83/02/22, 8302250347

F Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302290123 Informs that based on licensee 820226 ltr, facility is considered safe for continued operation until such time as equipment of questionable qualification in licensee 810904 submittal is qualified RODNEY, V L Operating Reactors Branch 2 82/03/09 NOVAK, T M Assistant Director for Operating Reactors 1p 17196 362 24X Fiche 50 000, 83/01/18, 8302170019

--8302170127 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively EISENHUT, D O Division of Licensing 82/09/24 MIRAOLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X Fiche 50-000, 83/01/18, 8302170019

--8302170202 Concludes that licensee has provided sufficient technical basis to support continued operation during ongoing equipment qualification review RODNEY, V L Operating Reactors Branch 2 82/10/28 EISENHUT, D O Division of Licensing 2pp 17196 360 24X Fiche 50-000, 83/01/18, 8302170019

8302030618 Requests addl info re BWR feedwater nozzle cracking & sparger replacement Post-outage rept of NDT should include analyses of leakage collection data & reasons for conclusions drawn Info requested within 30 days of NDT VASSALLO, D B Operating Reactors Branch 2 83/01/26 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 17013 327 24X Fiche 50-271, 83/01/26, 8302030618

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant unique-calculations which formed bases for mod Svc list encl EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - OPU Service Corp 5pp 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 1pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDD-24934, June 1982 Guidelines acceptable Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302140114 Application for Proposed Change 114 to License DPR-28 consisting of change to Tech Specs to allow use of manual valve to effect primary containment isolation HEIDER, L H Vermont Yankee Nuclear Power Corp 83/02/08 Office of Nuclear Reactor Regulation, Director 3pp 17141 206 24X Fiche 50-271, 83/02/08, 8302140114

--8302140118 Proposed Change 114 to Tech Specs, Table 4.7.2 a allowing use of manual valve to effect primary containment isolation * Vermont Yankee Nuclear Power Corp 83/02/08 1p 17141 209 24X Fiche 50-271, 83/02/08, 8302140114

8302240015 Forwards Amend 74 to License DPR-28, safety evaluation & notice of issuance & availability Amend changes Tech Specs for one-time use of manual valve to accomplish primary containment isolation, not to exceed 72 h RODNEY, V L Operating Reactors Branch 2 83/02/14 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 17288 022 24X Fiche 50-271, 83/02/14, 8302240015

--8302240017 Amend 74 to License DPR-28, changing Tech Specs to permit one-time use of manual valve to accomplish primary containment isolation, not to exceed 72 h VASSALLO, D B Operating Reactors Branch 2 83/02/14 4pp 17288 024 24X Fiche 50-271, 83/02/14, 8302240015

--8302240021 Safety evaluation supporting Amend 74 to License DPR-28 * Office of Nuclear Reactor Regulation, Director 83/02/14 3pp, 17288 028 24X Fiche 50-271, 83/02/14, 8302240015

--8302240026 Notice of issuance & availability of Amend 74 to License DPR-28 VASSALLO, D B Operating Reactors Branch 2 83/02/14 2pp, 17288 031 24X Fiche 50-271, 83/02/14, 8302240015

DOCKETED ITEMS

8302250164 Forwards "VT Yankee Cycle 10 Core Performance Analysis Rept, Jan 1983 " Proposed change to Tech Spec unnecessary Reload does not constitute unreviewed safety question
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/02/22
VASSALLO, D B Operating Reactors Branch 2 2pp 17293 242 24X
Fiche 50-271, 83/02/22, 8302250164

--8302250167 "VT Yankee Cycle 10 Core Performance Analysis, Jan 1983 "
CACCIAPQUILL, R, BERGERON, P A, SCHULTZ, S P Vermont Yankee Nuclear Power Corp YAE-1342 83/02/09 9pp 17293 245 24X
Fiche 50-271, 83/02/22, 8302250164

8302250242 Application for amend to License DPR-28, consisting of Proposed Change 113 to Tech Specs 3 12 & 4 12 to enhance spiral unloading & reload of reactor core
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/02/22 Office
Fiche 50-271, 83/02/22, 8302250242 3pp 17292 329 24X

--8302250247 Proposed Change 113 to Tech Specs 3 12 & 4 12 to enhance spiral unloading & reload of reactor core
Vermont Yankee Nuclear Power Corp 83/02/22 9pp 17292 332 24X
Fiche 50-271, 83/02/22, 8302250242

8302250403 Proposed Change 111 to License DPR-28, allowing reactor mode switch to be placed in startup w/low pressure range monitors disconnected during refueling outage testing
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/02/22 Office
Fiche 50-271, 83/02/22, 8302250403 3pp 17297 022 24X

--8302250407 Proposed Tech Specs re limiting safety sys setting, average power range monitor flur scram trip setting & reactor protection sys instrument requirements
Vermont Yankee Nuclear Power Corp 83/02/22 7pp 17297 025 24X
Fiche 50-271, 83/02/22, 8302250403

Q Inspection reports, IE Bulletins & correspondence

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design " Addl testing not warranted
TRAMIELLO, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X
Fiche 50-000, 83/01/25, 8302160014

8302160358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X
Fiche 50-000, 83/01/26, 8302160358

02010426 Ack receipt of 821112 ltr informing NRC of steps taken in response to 821015 notice of violation & proposed imposition of civil penalties per IE Insp Rept 50-271/82-07 Response acceptable based on listed understandings
HAYNES, R C Region 1, Office of Director, 83/01/26 MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 16978 090 24X
Fiche 50-271, 83/01/26, 8302010426

8212060360 IE Info Notice 83-02, "Limitorque H03C, H10C, H20C & H30C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X
Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X
Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X
Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Redwaste - 10CFR20.202 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X
Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X
Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302160240 Forwards monthly operating rept for Jan 1983
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/02/09 Office
Fiche 50-271, 83/02/09, 8302160240 1p 17170 214 24X

--8302160244 Monthly operating rept for Jan 1983
BURGER, F J Vermont Yankee Nuclear Power Corp 83/02/09 7pp
17170 215 24X
Fiche 50-271, 83/02/09, 8302160240

S Reportable occurrences, LERs & related correspondence

8302010312 Forwards LER 82-026/03L-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/01/19
HAYNES, R C Region 1, Office of Director 1p 16973 051 24X
Fiche 50-271, 83/01/19, 8302010312

--8302010318 LER 82-026/03L-0 on 821220, while shifting from reactor bldg closed cooling water H4 B to A, closed cooling water temp rapidly dropped 20 F Caused by increased efficiency of HX upon cleaning
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/01/19
Region 1, Office of Director 1p 16973 052 24X
Fiche 50-271, 83/01/19, 8302010312

8302010192 Forwards LER 83-001/01T-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/01/21
HAYNES, R C Region 1, Office of Director 1p 16974 009 24X
Fiche 50-271, 83/01/21, 8302010192

--8302010199 LER 83-001/01T-0 on 830107, containment isolation valves failed to close when operator attempted to secure nitrogen flow Caused by accumulation of ferrous metal particles on magnet providing valve position indication Valves cleaned
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/01/21
Region 1, Office of Director 2pp 16974 010 24X
Fiche 50-271, 83/01/21, 8302010192

8302010290 Forwards LER 83-002/02T-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/01/21
HAYNES, R C Region 1, Office of Director 1p 16973 087 24X
Fiche 50-271, 83/01/21, 8302010290

--8302010297 LER 83-002/02T-0 on 830108, discovered leak in 2-inch stainless steel schedule 160 isolable section of reactor drain line Cause unknown Leaking elbow replaced w/304L type stainless steel matl per NUREG-0313 requirements
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/01/21
Region 1, Office of Director 2pp 16973 088 24X
Fiche 50-271, 83/01/21, 8302010290

8302230593 Forwards LER 83-005/01P-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/02/04
HAYNES, R C Region 1, Office of Director, 1p 17256 124 24X
Fiche 50-271, 83/02/04, 8302230593

--8302230606 LER 83-005/01P-0 on 830203, while attempting to reduce flg through nitrogen makeup line, V-16-20-20 & 220 failed to close Cause unknown No attempt made to inspect or repair due to questions on acceptability of manual isolation
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/02/04
Region 1, Office of Director 2pp 17256 125 24X
Fiche 50-271, 83/02/04, 8302230593

8302250382 Forwards LER 83-003/03L-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/02/09
HAYNES, R C Region 1, Office of Director 1p 17297 214 24X
Fiche 50-271, 83/02/09, 8302250382

--8302250389 LER 83-003/03L-0 on 830114, low temp alarm on diesel generator A coolant jacket sounded Engine starting time exceeded Tech Specs Caused by dirt in check valve on excess fuel oil line from diesel injectors to fuel oil day tanks
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/02/09
Region 1, Office of Director 2pp 17297 215 24X
Fiche 50-271, 83/02/09, 8302250382

8302230413 Forwards human factors evaluation of 820424 feedwater transient Response to recommendations & comments requested within 60 days
STAROSTECKI, R Division of Project & Resident Programs 83/02/11
MURPHY, W P Vermont Yankee Nuclear Power Corp 7pp 17246 334 24X
Fiche 50-271, 83/02/11, 8302230413

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, ISS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302070076 Partial response to FOIA request for 22 categories of documents. Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App B documents completely withheld (ref FOIA Exemption 5)
FEITMAN, J M Division of Rules and Records 82/12/21 SHOLLY, B
Union of Concerned Scientists 6pp 17063 005 24X
Fiche 50-272, 82/12/21, 8302070076

--8302070096 Documents 821112 & 13 discussions w/RE Shepherd re IE investigation of potential sabotage at facility IE
Investigation Rept 50-272/80-22 prepared FBI & NJ State police investigating incident
RESNER, M E Office of Inspector & Auditor 80/11/14 Office of
Inspector & Auditor 1p 17064 007 24X Fiche 50-000, 82/12/21, 8302070096

--8302070103 Documents 801118 contact w/R Kurweil of US Atty Dfc in Camden, NJ re potential sabotage at facility Kurweil out of town & will return call
RESNER, M E Office of Inspector & Auditor 80/11/19 Office of
Inspector & Auditor 1p 17064 008 24X Fiche 50-000, 82/12/21, 8302070103

--8302070110 Documents 801120 discussion w/R Kurweil of US Atty Dfc in Camden, NJ re possible sabotage at facility Copy of amend to AEC regulations re sabotage of nuclear facilities codified as 42USC2284 will be forwarded
RESNER, M E Office of Inspector & Auditor 80/11/21 Office of
Inspector & Auditor 1p 17064 009 24X Fiche 50-000, 82/12/21, 8302070110

--8302070123 Documents 801113 telcon w/L Norrholm re potential sabotage at facility Ramifications re sodium chloride contamination of hydrating addition tank & subsequent contamination of auxiliary feedwater sys discussed
RESNER, M E Office of Inspector & Auditor 80/11/23 Office of
Inspector & Auditor 2pp 17064 010 24X Fiche 50-000, 82/12/21, 8302070123

--8302070129 Documents 801114 telcon w/J Camera of FBI re potential sabotage at facility Union problems & acts of vandalism existed prior to 800910 incident
RESNER, M E Office of Inspector & Auditor 80/11/25 Office of
Inspector & Auditor 1p 17064 012 24X Fiche 50-000, 82/12/21, 8302070129

--8302070134 Forwards Section 236 to Atomic Energy Act of 1954, including amend re sabotage of nuclear facilities, codified as 42USC2284, per 801120 telcon IE Investigation Rept 50-272/80-22 available
KURWEIL, J J Office of Inspector & Auditor 80/11/25
KURWEIL, J J Justice, Dept of, Attorney General's Office 2pp, 17064 013 24X Fiche 50-000, 82/12/21, 8302070134

--8302070142 Advises that no addl action planned re Region I investigation of potential sabotage at facility, pending request from R Kurweil, Assistant US Atty, Camden, NJ
FORTUNA, R A Office of Inspector & Auditor 80/11/26 ORIER, B H
Region I, Philadelphia, Office of the Director 1p 17064 015, 24X Fiche 50-000, 82/12/21, 8302070142

8302010706 Notification 83-06 of 830208 meeting w/util in King of Prussia, PA to discuss ongoing security program improvements & possible lifting of selected confirmatory action ltr conditions
TRAPP, L E Division of Project & Resident Programs 83/01/27
Division of Project & Resident Programs 1p 16989 281 24X
Fiche 50-272, 83/01/27, 8302010706

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302100003 Responds to 821124 request for approval of alternate means of storage of safeguards info. Considering location of container, method acceptable per 10CFR73.21
VAROA, S A Operating Reactors Branch 1 83/02/03 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 2pp 17135 181, 24X Fiche 50-272, 83/02/03, 8302100003

8302250329 Forwards IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20 No noncompliance noted
MARTIN, T Y Division of Engineering & Technical Programs 83/02/10
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 17291 095 24X Fiche 50-272, 83/02/10, 8302250329

--8302250333 IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20 No noncompliance noted Major areas inspected followup of emergency preparedness items identified in previous insp on 830520-22 & public notification sys
SMITH, R H, COHEN, I, CROCKER, H W Region I, Office of Director 83/02/09 13pp 17291 097, 24X Fiche 50-272, 83/02/10, 8302250333

8302250024 Forwards refund due from 820622 application for amend re protection of fire barrier penetrations Addl sum requested re 821007 application for deferral of pressurizer surveillance for Unit 1 & drop test for Unit 2
MILLER, W O License Fee Management Branch 83/02/18 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 2pp 17299 361, 24X Fiche 50-272, 83/02/18, 8302250024

8302280180 Forwards rept of safeguards effectiveness review conducted on 821202-11 Response to Section 2 2 areas of concerns requested within 30 days of receipt of ltr Rept withheld (ref 10CFR73.21)
VAROA, S A Operating Reactors Branch 1 83/02/24 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 2pp 17305 262 24X Fiche 50-272, 83/02/24, 8302280180

J Insurance & indemnity information

8302240019 Forwards Endorsements 44 & 56 to ANI/MAELU Policies MF-90 & NF-230, respectively
GOLDEN, M P Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc, Div 83/02/18 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17273 270 24X Fiche 50-272, 83/02/18, 8302240019

P Operating license stage documents & correspondence

8212210244 Application for amend to Licenses DPR-70 & DPR-75 modifying fuel enrichment for reactor cores & new & spent fuel racks to 4.05 weight % U-235 Nonproprietary analysis uncl Proprietary analysis withheld (ref 10CFR2.790)
LIDEN, E A Public Service Electric & Gas Co of New Jersey, 82/12/03 VAROA, S A Operating Reactors Branch 1, 13pp 16483 001 24X Fiche 50-272, 82/12/03, 8212210244

8302020351 Forwards plant-specific data re safety & relief valve performance & adequacy of associated piping & block valves Plans for valve & piping mods identified in review & implementation schedule also included
LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/01/03 VAROA, S A Operating Reactors Branch 1 8pp 16994 016 24X Fiche 50-272, 83/01/03, 8302020351

8302020280 Forwards comments on Science Applications, Inc 820923 draft final rept, "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events," per Generic Ltr 82-32.
LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/01/13 VAROA, S A Operating Reactors Branch 1 2pp 16993 326 24X Fiche 50-272, 83/01/13, 8302020280

8302020271 Submits results of investigation of interaction between pressurizer water level high protection Channels I & III & of Channel III malfunction interaction caused by hydraulic cross-connection Malfunction caused by failed transmitter.
LIDEN, E A Public Service Electric & Gas Co of New Jersey, 83/01/21 VAROA, S A Operating Reactors Branch 1 2pp 16993 345 24X Fiche 50-272, 83/01/21, 8302020271

8302070258 Forwards response to 830121 request for addl info re application to amend DL increasing allowable fuel enrichment in facilities.
LIDEN, E A Public Service Electric & Gas Co. of New Jersey, 83/01/26, VAROA, S A, Operating Reactors Branch 1 3pp, 16994 261 24X Fiche 50-272, 83/01/26, 8302070258

8302020025 Forwards addl Class I amend fee for Tech Spec changes re full enrichment on duplicate unit per 830106 response
LIDEN, E A Public Service Electric & Gas Co. of New Jersey 83/01/27 MILLER, W O License Fee Management Branch, 1p 16994 340 24X Fiche 50-272, 83/01/27, 8302020025

DOCKETED ITEMS

8302180497 Application for amend to Licenses DPR-70 & DPR-75, changing Tech Specs to establish sys operability requirements for transfer functions of ECCS semiautomatic switchover from safety injection of recirculation during LOCA
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/01/27 VARQA, S A Operating Reactors Branch 1 4pp 17210 281
24X Fiche 50-272, 83/01/27, 8302180497

--8302180499 Proposed Tech Specs re ESF actuation sys instrumentation & semiautomatic switchover from injection to recirculation
* Public Service Electric & Gas Co of New Jersey 83/01/27
62pp 17210 285 24X Fiche 50-272, 83/01/27, 8302180497

8302160075 Forwards SER of NUREG-0737, Item II D 2 2 re design review of plant shielding & corrective actions for access to vital areas NUREG-0737 requirements met
VARQA, S A Operating Reactors Branch 1 83/01/31 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 5pp 17160 328
24X Fiche 50-272, 83/01/31, 8302160075

8302090386 Responds to NRC request for evaluation of proprietary nature of SER re environ qualification of safety-related electrical equipment Proprietary matl remains proprietary
Nonproprietary matl remains available for public release
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/02/01 VARQA, S A Operating Reactors Branch 1 2pp 17067 015
24X Fiche 50-272, 83/02/01, 8302090386

8302150623 Forwards proprietary & nonproprietary Rev 4 to "Environ Qualification Review Rept, Vols 1 & 2" Rev includes new data re Class IE instrumentation & electrical equipment
Proprietary version withheld (ref 10CFR2 790)
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/02/03 VARQA, S A Operating Reactors Branch 1 3pp 17154 269
24X Fiche 50-272, 83/02/03, 8302150623

--8302150631 Rev 4 to "Environ Qualification Review Rept, Vols 1 & 2"
* Public Service Electric & Gas Co of New Jersey 82/12/22
292pp 17154 281 24X Fiche 50-272, 83/02/03, 8302150623

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PNRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D Q Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D Q Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

3302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NBS (except Yankee Atomic Electric Co) re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D Q Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302220385 Forwards "Control Room Design Review Program Plan," to meet NRC final requirements issued in Suppl 1 of NUREG-0737
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/02/14 VARQA, S A Operating Reactors Branch 1 1p 17232 152
24X Fiche 50-272, 83/02/14, 8302220385

--8302220389 "Control Room Design Review Program Plan"
* Public Service Electric & Gas Co of New Jersey 82/11/30
70pp 17232 153 24X Fiche 50-272, 83/02/14, 8302220385

8302250024 Forwards refund due from 820622 application for amend re protection of fire barrier penetrations Addl sum requested re 821007 application for deferral of pressurizer surveillance for Unit 1 & drop test for Unit 2
MILLER, W D License Fee Management Branch 83/02/18 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 2pp 17299 361
24X Fiche 50-272, 83/02/18, 8302250024

G Inspection reports, IE Bulletins & correspondence

8302070076 Partial response to FOIA request for 22 categories of documents Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App B documents completely withheld (ref FOIA Exemption 5).
FELTON, J M Division of Rules and Records 82/12/21 SKOLLY, S
Union of Concerned Scientists 4pp 17063 005 24X
Fiche 50-272, 82/12/21, 8302070076

--8302070096 Documents 821112 & 13 discussions w/RE Shepherd re IE investigation of potential sabotage at facility IE
Investigation Rept 50-272/80-22 prepared FBI & NJ State
police investigating incident
RESNER, M E Office of Inspector & Auditor 80/11/14 Office of
Inspector & Auditor 1p 17064 007 24X Fiche 50-000, 82/12/21,
8302070076

--8302070103 Documents 801118 contact w/R Kurweil of US Atty Ofc in Camden, NJ re potential sabotage at facility Kurweil out of town & will return call
RESNER, M E Office of Inspector & Auditor 80/11/19 Office of
Inspector & Auditor 1p 17064 008 24X Fiche 50-000, 82/12/21,
8302070076

--8302070110 Documents 801120 discussion w/R Kurweil of US Atty Ofc in Camden, NJ re possible sabotage at facility Copy of amend to AEC regulations re sabotage of nuclear facilities codified as 42USC2284 will be forwarded
RESNER, M E Office of Inspector & Auditor 80/11/21 Office of
Inspector & Auditor 1p 17064 009 24X Fiche 50-000, 82/12/21,
8302070076

--8302070123 Documents 801113 telcon w/L Norrholm re potential sabotage at facility Ramifications re sodium chloride contamination of hydrazine addition tank & subsequent contamination of auxiliary feedwater sys discussed
RESNER, M E Office of Inspector & Auditor 80/11/23 Office of
Inspector & Auditor 2pp 17064 010 24X Fiche 50-000, 82/12/21,
8302070076

--8302070129 Documents 801114 telcon w/J Camera of FBI re potential sabotage at facility Union problems & acts of vandalism existed prior to 800710 incident
RESNER, M E Office of Inspector & Auditor 80/11/25 Office of
Inspector & Auditor 1p 17064 012 24X Fiche 50-000, 82/12/21,
8302070076

--8302070136 Forwards Section 236 to Atomic Energy Act of 1954, including amend re sabotage or nuclear facilities, codified as 42USC2284, per 801120 telcon IE Investigation Rept 50-272/80-22 available
CUMMINGS, J J Office of Inspector & Auditor 80/11/25
KURWEIL, L R Justice, Dept of, Attorney General's Office 2pp
17064 013, 24X Fiche 50-000, 82/12/21, 8302070076

--8302070142 Advises that no addl action planned re Region I investigation of potential sabotage at facility, pending request from R Kurweil, Assistant US Atty, Camden, NJ
FORTUNA, R A Office of Inspector & Auditor 80/11/26 GRIER, D #
Region I, Philadelphia, Office of the Director 1p 17064 015
24X Fiche 50-000, 82/12/21, 8302070076

8301140412 Forwards SALP rept on 821101 for period Sept 1981 - Aug 1982 Rept discussed at 821123 meeting
HAYNES, R C Region I, Office of Director 83/01/11 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 3pp 16989 202
24X Fiche 50-272, 83/01/11, 8301140412

--8301140418 SALP rept on 821101 for period Sept 1981 - Aug 1982
Performance acceptable
* Region I, Office of Director 82/11/01 38pp 16989 203 24X
Fiche 50-272, 83/01/11, 8301140412

--8301140424 Forwards SALP board rept from review on 821101 Comments re rept to be discussed at 821123 meeting Written comments will be accepted within 20 days after meeting W/o encl
STAROSTECKI, R Division of Project & Resident Programs 82/11/19
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
1p 16989 241 24X Fiche 50-272, 83/01/11, 8301140412

--8302010025 Comments on 821101 SALP rept Comprehensive rept filed 821123 re actions taken concerning civil penalty imposed
Priorities will still be established w/nuclear safety being of paramount concern at all mgt levels
UDERITZ, R W Public Service Electric & Gas Co of New Jersey
82/12/16 STAROSTECKI, R Division of Project & Resident Programs
2pp 16989 242 24X Fiche 50-272, 83/01/11, 8301140412

8212060358 IC Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212040361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212040361

8302250329 Forwards IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/10 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 17291 095 24X Fiche 50-272, 83/02/10, 8302250329

--8302250333 IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20 No noncompliance noted Major areas inspected followup of emergency preparedness items identified in previous insp on 810520-22 & public notification sys
SMITH, R M, COHEN, I, CROCKER, H W Region 1, Office of Director 83/02/09 13pp 17291 097 24X Fiche 50-272, 83/02/10, 8302250329

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302220173 Forwards monthly operating rept for Jan 1983
MIDURA, H J Public Service Electric & Gas Co of New Jersey 83/02/10 Director's Office, Office of Inspection and Enforcement 1p 17233 116 24X Fiche 50-272, 83/02/10, 8302220173

--8302220177 Monthly operating rept for Jan 1983
MILLER, L K Public Service Electric & Gas Co of New Jersey 83/02/10 15pp 17233 117 24X Fiche 50-272, 83/02/10, 8302220173

S Reportable occurrences, LERs & related correspondence

8302070076 Partial response to FOIA request for 22 categories of documents Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App B documents completely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, B Union of Concerned Scientists 8pp 17063 005 24X Fiche 50-272, 82/12/21, 8302070076

--8302070200 Handwritten note re facility 820428 incident involving steam generator feedwater pump trip due to mispositioned isolation & vent valves Incident caused by sabotage Labor union contract negotiations in progress
* NRC - No Detailed Affiliation Given 82/06/30 1p 17065 043 24X Fiche 50-000, 82/12/21, 8302070076

--8302070228 PNS-I-82-009 on 820809, miscellaneous ac 115-volt distribution panel 12 lost power supply (station essential controls inverter 12) due to tripped position of inverter breaker Probably caused by sabotage Surveillances initiated
MARTIN, T T, KEIMIG, R R Region 1, Office of Director 82/08/16 1p 17065 089 24X Fiche 50-000, 82/12/21, 8302070076

8302010339 Forwards LER 83-001/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 83/01/19 HAYNES, R C Region 1, Office of Director 3pp 16973 008 24X Fiche 50-272, 83/01/19, 8302010339

--8302010344 LER 82-001/03L-0 on 830104, vital bus 18 tripped, rendering RHR loop inoperable Caused by differential relay protection Redundant RHR loop immediately placed in operation
FRAMM, R Public Service Electric & Gas Co of New Jersey, 83/01/19 Region 1, Office of Director 1p 16973 011 24X Fiche 50-272, 83/01/19, 8302010339

8302010195 Forwards LER 82-093/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 83/01/24 HAYNES, R C Region 1, Office of Director 3pp 16974 030 24X Fiche 50-272, 83/01/24, 8302010195

--8302010204 LER 82-093/03L-0 on 821225, plant vent gross activity monitor indication declared inoperable Daily grab samples of plant vent effluent not taken until 830104 violating ETS Caused by personnel error Procedures reviewed.
FRAMM, R Public Service Electric & Gas Co of New Jersey 83/01/24 Region 1, Office of Director 1p 16974 033 24X Fiche 50-272, 83/01/24, 8302010195

8302070300 LER 83-002/01P on 830106, due to planned maint on station power transformer 12, automatic starting feature on diesel fire pumps 1 & 2 was disabled. Transformer returned to svc on 830107 Automatic starting feature regained
MIDURA, H J Public Service Electric & Gas Co of New Jersey 83/01/25 HAYNES, R C Region 1, Office of Director, 1p 17029 096 24X Fiche 50-272, 83/01/25, 8302070300

8302070442 Forwards LER 83-002/01T-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey 83/01/27 HAYNES, R C Region 1, Office of Director 4pp 17036 302 24X Fiche 50-272, 83/01/27, 8302070442

--8302070446 LER 83-002/01T-0 on 830106, station power transformer 12 de-energized for planned maint Loss of power to automatic starting feature on both diesel fire pumps resulted Caused by oversight due to human error Personnel counseled
FRAMM, R Public Service Electric & Gas Co of New Jersey 83/01/27 Region 1, Office of Director 1p 17036 306 24X Fiche 50-272, 83/01/27, 8302070442

8302030268 PNO-I-83-004 on 830130, inadvertent safety injection occurred while cooling down to investigate reactor coolant pump motor failure Caused by malfunctioning computer indicating incorrect safety injection block permissive
SUMMERS, R, LAZARUS, W, TRIPP, L Region 1, Office of Director 83/01/31 1p 17001 290 24X Fiche 50-272, 83/01/31, 8302030268

8302280445 PNO-I-83-010 on 830222, during attempted transfer at 4kV group buses from station to auxiliary power transformers, 1F U160-volt bus de-energized, resulting in loss of reactor control pump 13 & control power for main feed pump 12
SUMMERS, R, LAZARUS, W, TRIPP, L Region 1, Office of Director 83/02/23 1p 17309 201 24X Fiche 50-272, 83/02/23, 8302280445

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses, Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp. 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR

R Periodic operating reports & related correspondence

8302070375 "Annual Rept 1982 "
* Interior, Dept of, Geological Survey 82/12/31 7pp 17030 095 24X Fiche 50-274, 82/12/31, 8302070375

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8210150452 Forwards reviews of procedures proposed by utility in emergency plans to consider meteorological conditions at facilities, in response to Task Order 1 of interagency agreement
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099 82/10/08 SPICKLER, I Office of Nuclear Reactor Regulation, Director, 1p 16951 303 24X Fiche 50-000, 82/10/08, 8210150452

--8210150459 "Evaluation of Procedures Proposed by FL Power & Light Co in Emergency Plans to Consider Meteorological Conditions in St Lucie Plant Coastal Environ "
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 304 24X Fiche 50-000, 82/10/08, 8210150452

--8301270044 "Evaluation of Procedures Proposed by Commonwealth Edison Co in Emergency Plans to Consider Meteorological Conditions in Zion Plant Coastal Environ "
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 307 24X Fiche 50 000, 82/10/08, 8210150452

DOCKETED ITEMS

--B301270051 "Evaluation of Procedures Proposed by Detroit Edison Co in Emergency Plans to Consider Meteorological Conditions in Enrico Fermi Site Coastal Environ"
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 4pp 16951 310 24X
Fiche 50-000, 82/10/08, 8210150452

--B301270060 "Evaluation of Procedures Proposed by PG&E in Emergency Plans to Consider Meteorological Conditions in Diablo Canyon Plant Coastal Environ"
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 314 24X
Fiche 50-000, 82/10/08, 8210150452

B30200337 Forwards IE Insp Rept 50-275/82-42 on 821202-B30101 No noncompliance noted
BISHOP, J. W. Division of Resident, Reactor Project & Engineering Programs 83/01/19 CRANE, P. A. Pacific Gas & Electric Co 1p 17029 169 24X Fiche 50-275, 83/01/19, 8302070337

--B302070339 IE Insp Rept 50-275/82-42 on 821202-B30101 No noncompliance noted Major areas inspected plant operations, surveillance testing, physical security, followup of allegations re RHR sys, maint & licensee audit program
CARLSON, J. D., MENDONCA, M. M., MORRILL, P. J. Division of Resident, Reactor Project & Engineering Programs 83/01/14 7pp 17029 169 24X Fiche 50-275, 83/01/19, 8302070337

B302030603 Releases public version of revised emergency plan implementing procedures
FELTON, J. H. Division of Rules and Records, 83/01/28 Document Management Branch, 1p 17013 096 24X Fiche 50-275, 83/01/28, 8302030603

--B302030605 Forwards public version of revised emergency plan implementing procedures, including Procedures EP 0-2 re establishment of onsite emergency organization & EF-5 re emergency equipment, instruments & supplies.
CRANE, P. A. Pacific Gas & Electric Co 83/01/07 ENGELKEN, R. H. Region 5, Office of Director 2pp 17013 097 24X
Fiche 50-275, 83/01/28, 8302030603

--B302030611 Public version of revised emergency plan implementing procedures, including Procedures EP 0-2 re establishment of onsite emergency organization & EF-5 re emergency equipment, instruments & supplies
WICKACK, L. F. Pacific Gas & Electric Co 83/01/04 81pp 17013 099 24X Fiche 50-275, 83/01/28, 8302030603

301210340 Generic Ltr B3 04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340.

B302150004 Forwards IE Safeguards Insp Rept 50-275/83-01 on 830117-21 & 27 No noncompliance noted Major area inspected physical protection program against radiological sabotage & theft of SNH Rept withheld (ref 10CFR2 790 & 73 21)
NORDERHAUG, L. R. Division of Radiological Safety & Safeguards program 83/02/02 CRANE, P. A. Pacific Gas & Electric Co 2pp 17146 006 24X Fiche 50-275, 83/02/02, 8302150004

B302090014 Forwards Rev 2 to security force training & qualification plan Rev withheld (ref 10CFR2 750)
CRANE, P. A. Pacific Gas & Electric Co 83/02/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17070 269, 24X Fiche 50-275, 83/02/04, 8302090014

B302090357 Forwards changes to Rev 11 of security plan Changes withheld (ref 10CFR73 21)
CRANE, P. A. Pacific Gas & Electric Co 83/02/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17070 354 24X Fiche 50-275, 83/02/04, 8302090357.

B302090428 Forwards Rev 2 to safeguards contingency plan Rev withheld (ref 10CFR73 21)
CRANE, P. A. Pacific Gas & Electric Co 83/02/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17066 240 24X Fiche 50-275, 83/02/04, 8302090428

B302230134 Forwards changes to security plan Changes withheld (ref 10CFR73 21)
CRANE, P. A. Pacific Gas & Electric Co 83/02/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 2pp 17243 277 24X Fiche 50-275, 83/02/17, 8302230134

G Adjudicatory correspondence

B302010464 Notice of substitution of Governor O Dukmejian for former Governor Brown as State of CA representative MJ Strumwasser notice of appearance & Certificate of Svc encl
STRUMWASSER, M. California, State of 83/01/28 5pp 16981 013 24X Fiche 50-275, 83/01/28, 8302010464

B302250337 Order requiring submittal by 830302 of names of persons who will present arguments at 830316 hearing in Bethesda, MD re appeals from ASLB 820831 initial decision authorizing full-power operation & from motions of intervenors
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/02/23 2pp 17291 056 24X Fiche 50-275, 83/02/23, 8302250337

B302280263 Forwards SE Turk notice of withdrawal from proceeding NRC represented by L.J. Chandler & J.R. Goldberg, whose notices of appearance were served on 830125 W/o encl
CHANDLER, L. J. Hearings Division 83/02/25 MOORE, T. B., BUCK, J. H., JOHNSON, R. Atomic Safety and Licensing Appeal Panel 2pp 17312 262 24X Fiche 50-275, 83/02/25, 8302280263

H General correspondence

B302160228 Opposes low power licensing of facilities until design audit completed
HARRELL, K. J. Affiliation Unknown 83/02/11 NRC - No Detailed Affiliation Given 1p 17166 294 24X Fiche 50-275, 83/02/11, 8302160228

P Operating license stage documents & correspondence

B302020476 Notification of 830128 meeting w/util & Teledyne Engineering Svcs in Bethesda, MD to discuss design & operation of component cooling water sys, including seismic/nonseismic interfaces & safety/non-safety interfaces
SCHIERL, H. C. Licensing Branch 3 83/01/18 KNIGHTON, Q. Licensing Branch 3 4pp 16999 270 24X Fiche 50-275, 83/01/18, 8302020476

B302090152 Documents info presented at 830113 independent design verification program meeting info replaces 821223 "Phase II Add'l Sample & Add'l Verification" draft interim technical rept, w/listed exceptions
COOPER, H. E. Teledyne Engineering Services 83/01/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co 3pp 17070 273 24X Fiche 50-275, 83/01/18, 8302090152

B302090182 Discusses independent design verification program civil/structural efforts Instruments Test Rig-6 published for historical purposes Engineers committed to perform RL Cloud review listed
COOPER, H. E. Teledyne Engineering Services DCN180N, E. T. Robert L. Cloud Associates, Inc 83/01/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co 3pp 17070 239 24X Fiche 50-275, 83/01/18, 8302090182

B302010037 Forwards transcript of 830106 meeting between NRC & individual re alleged safety deficiencies Notification of allegations transmitted to Commission by Board Notification
B3-03 dtd 830107 W/o encl
EISENHUT, D. O. Division of Licensing 83/01/19 COOPER, H. E. Teledyne Engineering Services 4pp 16990 348 24X
Fiche 50-275, 83/01/19, 8302010037

B302010431 Forwards "Wave Effects on Intake Structure" & "Investigation of Seawater Ingestion Into Auxiliary Saltwater Pump Room Due to Splash Runup During Design Flood Events at Diablo Canyon"
CRANE, P. A. Pacific Gas & Electric Co 83/01/19, KNIGHTON, Q. W. Licensing Branch 3 2pp 16974 196 24X Fiche 50-275, 83/01/19, 8302010431

--B302010432 "Wave Effects on Intake Structure at Diablo Canyon, Units 1 & 2"
MATSUDA, E. N. Pacific Gas & Electric Co 83/01/31 16pp 16974 198 24X Fiche 50-275, 83/01/19, 8302010431

--B302010433 "Investigation of Seawater Ingestion Into Auxiliary Saltwater Pump Room Due to Splash Runup During Design Flood Events at Diablo Canyon"
RYAN, P. J. Pacific Gas & Electric Co 83/01/31 26pp 16974 214 24X Fiche 50-275, 83/01/19, 8302010431

B302030107 Requests info necessary to calculate temp & pressure transients in Area GE of auxiliary bldg resulting from main steam line break in Area GW Info required for NRC comparison w/independent design verification program
KNIGHTON, Q. W. Licensing Branch 3 83/01/19 CRANE, P. A. Pacific Gas & Electric Co. 4pp 17023 357 24X Fiche 50-275, 83/01/19, 8302030107.

DOCKETED ITEMS

89

8302020002 Forwards current status of results re Phase I final rept for design verification program
CRANE, P A Pacific Gas & Electric Co 83/01/21 EISENHUT, D G
Division of Licensing 8pp 17004 341 24X Fiche 50-275, 83/01/21,
8302020002

8302090306 Notifies that first independent design verification program design of verification conducted on 821220 & second proposed for 830203 Initial plans provide for verifying min of two areas per wk Meeting announcements encl
REENY, R F Reedy, Herbert, Gibbons & Associates 83/01/25 FRAY, R
Bechtel Corp 3pp 17069 342 24X Fiche 50-275, 83/01/25,
8302090306

8302020493 Forwards request for remainder of info items requested at 821221 meeting Info not sent in 830104 submittal & is necessary to perform analyses
KNIGHTON, O W Licensing Branch 3 83/01/26 CRANE, P Pacific Gas & Electric Co 3pp 16996 341 24X Fiche 50-275, 83/01/26,
8302020493

8302080151 Board Notification 83-6 forwards info re independent design verification program status Info relevant to safety issue of plant design adequacy (ref Commission Order CLI-81-30)
EISENHUT, D G Division of Licensing 83/01/26 PALLADINO, N J,
GILINSEKY, V, AHEARNE, V Commissioners 4pp 17103 336 24X
Fiche 50-275, 83/01/26, 8302080151

--8302080155 Transcript of 830113 meeting w/util & Bechtel in San Francisco, CA re independent design verification program
* Commissioners 83/01/13 258pp 17104 045 24X
Fiche 50-275, 83/01/26, 8302080151

8302100094 Accepts Revs 1 & 2 to QA program submitted in response to NRC request for addl info & clarification
EISENHUT, D G Division of Licensing 83/01/26 CRANE, P A Pacific Gas & Electric Co 5pp 17135 041 24X Fiche 50-275, 83/01/26,
8302100094

8302090311 Forwards definitive schedule for 830204 independent design verification program design of verification Verification will be limited to control of spectra within intake structure & auxiliary bldg
REEDY, R F Reedy, Herbert, Gibbons & Associates 83/01/31 FRAY, R
Pacific Gas & Electric Co 2pp 17071 014 24X
Fiche 50-275, 83/01/31, 8302090311

8302170405 Notification of 830207-09 meetings w/util & EQ&O at site to discuss inservice testing program
BUCKLEY, J Licensing Branch 3 83/02/02 KNIGHTON, O W Licensing Branch 3 4pp 17195 249 24X Fiche 50-275, 83/02/02, 8302170405

8302090165 Informs that CF Bergeron approved as replacement for JM Oddo as S&I lead nuclear technology engineer Personnel change affects 3 2 & Figure 3-1 of Phase II program mgt plan CF Bergeron resume encl
CRAGIN, J G Teledyne Engineering Services 83/02/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 7pp 17070 262 24X Fiche 50-275, 83/02/03, 8302090165

8302230005 Board Notification 83-10 provides info items re independent design verification program
EISENHUT, D G Division of Licensing 83/02/03 PALLADINO, M J,
GILINSEKY, V, AHEARNE, J F Commissioners 6pp 17259 330 24X
Fiche 50-275, 83/02/03, 8302230005

--8302230006 Transcript of 830128 meeting re component cooling water sys Pp 1-183. Supporting documentation encl
* Office of Nuclear Reactor Regulation, Director 83/01/28
183pp 17260 092 24X Fiche 50-275, 83/02/03, 8302230005

8302090376 Forwards response to BNL 830126 requests for addl info, including info re as-built Young modulus of concrete in crane wall & interior concrete
CRANE, P A Pacific Gas & Electric Co 83/02/04 EISENHUT, D G
Division of Licensing 3pp 17071 090 24X Fiche 50-275, 83/02/04,
8302090376

8302140087 Responds to 830119 request re pressure & temp profile info Necessary info required by independent design verification program to perform analysis being compiled H/O encl
CRANE, P A Pacific Gas & Electric Co 83/02/04 EISENHUT, D G
Division of Licensing 1p 17141 214 24X Fiche 50-275, 83/02/04,
8302140087

8302140078 Forwards Interim Technical Rept 34, Rev 0, "Verification of Diablo Canyon Project Efforts"
KNIGHTON, J E Stone & Webster Engineering Corp 83/02/07,
DENTON, H R Office of Nuclear Reactor Regulation, Director
ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 17141 047 24X Fiche 50-275, 83/02/07,
8302140078

--8302140083 Interim Technical Rept 34, Rev 0, "Verification of Diablo Canyon Project Efforts"
SESTAK, F, STRATOU, D G Stone & Webster Engineering Corp.
83/02/04 42pp 17141 048 24X Fiche 50-275, 83/02/07, 8302140078

8302170400 Notification of 830214 meeting w/BNL in Bethesda, MD to provide status of seismic analysis efforts
SCHIERLING, H Licensing Branch 3 83/02/07 KNIGHTON, O W
Licensing Branch 3 4pp 17195 263 24X Fiche 50-275, 83/02/07,
8302170400

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08, Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302170027 Advises that Class III fee due for final review of 821221 application requesting relief from Tech Specs for 120 days to permit mods to fuel handling bldg
DIOGS, R M License Fee Management Branch 83/02/10 FURBUSH, M H
Pacific Gas & Electric Co 1p 17191 032 24X
Fiche 50-275, 83/02/10, 8302170027

8302170331 Requests relief from Tech Spec 3 4 1 2, Paragraph b, limiting condition for operation, to perform boron mixing & cool down test under natural circulation conditions using decay heat Supporting documentation encl
CRANE, P A Pacific Gas & Electric Co 83/02/10 KNIGHTON, O W
Licensing Branch 3 4pp 17183 359 24X Fiche 50-275, 83/02/10,
8302170331

8302170343 Forwards info re fuel storage tanks, per BNL 830204 request Also forwards info re mods to containment annulus steel framing per request
CRANE, P A Pacific Gas & Electric Co 83/02/11 EISENHUT, D G
Division of Licensing 4pp 17183 345 24X Fiche 50-275, 83/02/11,
8302170343

8302240286 Forwards "Diablo Canyon Unit 1 Independent Design Verification Program," Interim Technical Rept 32, Rev 0
DENISON, E Robert L Cloud Associates, Inc 83/02/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 17271 202 24X Fiche 50-275, 83/02/17, 8302240286

--8302240292 "Diablo Canyon Unit 1 Independent Design Verification Program," Interim Technical Rept 32, Rev 0
DENISON, E Robert L Cloud Associates, Inc HRAY, R Teledyne Engineering Services P 105-4-B39-032 R00 83/02/17 61pp
17271 203 24X Fiche 50-275, 83/02/17, 8302240286

8302280034 Submits sections & tables in Part 2 of Phase I final rept of design verification program, supporting Step 1 fuel load, per 821202 & 03 ltrs Revised sections on containment & auxiliary bldg will be submitted at later date
CRANE, P A Pacific Gas & Electric Co 83/02/17 EISENHUT, D G
Division of Licensing 253pp 17305 001 24X Fiche 50-275,
83/02/17, 8302280034

8302180292 Notifies of 830223 & 24 meetings w/S&W in Boston, MA to discuss Phase II addl verification & EOLs
COOPER, W E, CRAGIN, J G Teledyne Engineering Services 83/02/18
NRC - No Detailed Affiliation Given 1p 17215 275 24X
Fiche 50-275, 83/02/18, 8302180292

8302230398 Advises that Phase II status rept will not be issued on 830215 as scheduled Phase II issues being resolved by project & independent design verification program Rept to be submitted following issue resolution or reclassification.
CRANE, P A Pacific Gas & Electric Co 83/02/18 EISENHUT, D G
Division of Licensing 1p 17248 081 24X Fiche 50-275, 83/02/18,
8302230398

8302230420 Forwards fee required for issuance of Amend 3 to License DPR-76
CRANE, P A Pacific Gas & Electric Co 83/02/18 DIOGS, R M
License Fee Management Branch 1p 17246 120 24X
Fiche 50-275, 83/02/18, 8302230420

DOCKETED ITEMS

8302240014 Forwards program managers rept for third Friday Feb 1983
Acceptable statement re potential or apparent conflicts of
interest completed Design ofc verifications & corrective
action audits & reporting in progress
READY, R F R F Ready, Inc 83/02/18 COOPER, W E Teledyne
Engineering Services 6pp 17273 264 24X Fiche 50-275, 83/02/18,
8302240014

8302240278 Forwards "Diablo Canyon Unit 1 Independent Design
Verification Program, Electrical Equipment Analysis," Interim
Technical Rept 33, Rev O
DENTON, H R Robert L Cloud Associates, Inc 83/02/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric
Co 1p 17271 149 24X Fiche 50-275, 83/02/18, 8302240278

--8302240282 "Diablo Canyon Unit 1 Independent Design Verification
Program, Electrical Equipment Analysis," Interim Technical
Rept 33, Rev O
DENTON, H R Robert L Cloud Associates, Inc WRAY, R Teledyne
Engineering Services P 105-4-835-033 R00 83/02/18 51pp
17271 150 24X Fiche 50-275, 83/02/18, 8302240278

8302240280 Requests info from BNL analysis of containment annulus
structure re vertical response spectra for Model D &
horizontal annulus model info required for design
verification program
COOPER, W E, MYROLOT, C E Teledyne Engineering Services 83/02/18
SCHIERLING, H E Office of Nuclear Reactor Regulation, Director 1p
17274 072 24X Fiche 50-275, 83/02/18, 8302240280

8302220368 Agenda for 830224 & 25 meetings in San Francisco, CA to
discuss structural review
COOPER, W E, CRAIG, J O Teledyne Engineering Services 83/02/24
Teledyne Engineering Services 1p 17232 067 24X
Fiche 50-275, 83/02/24, 8302220368

G Inspection Reports, IE Bulletins & correspondence

8302230379 Forwards IE Insp Repts 50-275/82-41 & 50-323/82-19 on
821208-23 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/01/10 CRANE, P A Pacific Gas & Electric Co 2pp
17246 321 24X Fiche 50-275, 83/01/10, 8302230379

--8302230388 IE Insp Repts 50-275/82-41 & 50-323/82-19 on 821208-23 No
noncompliance noted Major areas inspected design &
procurement requirements for Super Strut matl installed for
Class IE raceway supports
MORRILL, P J, JOHNSON, A D, MENDONCA, M H Division of
Resident, Reactor Project & Engineering Programs 83/01/06 6pp
17246 323 24X Fiche 50-275, 83/01/10, 8302230379

8302070337 Forwards IE Insp Rept 50-275/82-42 on 821202-830101 No
noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/01/19 CRANE, P A Pacific Gas & Electric Co 1p
17029 168 24X Fiche 50-275, 83/01/19, 8302070337

--8302070339 IE Insp Rept 50-275/82-42 on 821202-830101 No noncompliance
noted Major areas inspected plant operations, surveillance
testing, physical security, followup of allegations re RHR
sys, maint & licensee audit program
CARLSON, J D, MENDONCA, M H, MORRILL, P J Division of
Resident, Reactor Project & Engineering Programs 83/01/14 9pp
17029 169 24X Fiche 50-275, 83/01/19, 8302070337

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358.

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302080176 Responds to IE Bulletin 82-04 Util review indicates that
hard epoxy electrical penetration assemblies mfg by Bunker-
Ramco Co have neither been installed nor are planned for
installation in containment at facilities
SCHUYLER, J O, CRANE, P A Pacific Gas & Electric Co 83/02/02
KNIGHTON, O W Licensing Branch 3 2pp 17058 337 24X
Fiche 50-275, 83/02/02, 8302080176

8302150004 Forwards IE Safeguards Insp Rept 50-275/83-01 on 830117-21 &
27 No noncompliance noted Major area inspected physical
protection program against radiological sabotage & theft of
SNM Rept withheld (ref 10CFR2 790 & 73 21)
MORRERHAUS, L R Division of Radiological Safety & Safeguards
Program 83/02/02 CRANE, P A Pacific Gas & Electric Co 2pp
17146 005 24X Fiche 50-275, 83/02/02, 8302150004

8302230657 Forwards IE Insp Repts 50-275/83-02 & 50-323/83-01 on
830103-21 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/02/09 CRANE, P A Pacific Gas & Electric Co 2pp
17255 054 24X Fiche 50-275, 83/02/09, 8302230657

--8302230666 IE Insp Repts 50-275/83-02 & 50-323/83-01 on 830103-21 No
noncompliance noted Major areas inspected const & mod
activities, including site tour, licensee actions on previous
items, mods to structural steel & pipe supports
BURDOCK, J F, HERNANDEZ, O, ZWETIG, O B Division of
Resident, Reactor Project & Engineering Programs 83/02/09 9pp
17255 036 24X Fiche 50-275, 83/02/09, 8302230657

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302140041 Submits Semimonthly Progress Rept 23 for 821211-830114 No
open item repts issued Acceptable statement re potential or
apparent conflicts of interest completed
READY, R F R F Ready, Inc 83/01/14 DENTON, H R Office of
Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5,
Office of Director MANEATIS, O A Pacific Gas & Electric Co 2pp
17141 161 24X Fiche 50-275, 83/01/14, 8302140041

8302030496 Forwards "Independent Design Verification Program,"
semimonthly status rept for Jan 1983
COOPER, W E Teledyne Engineering Services 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric
Co 1p 17007 175 24X Fiche 50-275, 83/01/28, 8302030496

--8302030501 "Independent Design Verification Program," semimonthly
status rept for Jan 1983
* Teledyne Engineering Services 83/01/28 106pp 17007 177
24X Fiche, 50-275, 83/01/28, 8302030496

8302040369 Forwards "Diablo Canyon Verification Program," Semimonthly
Rept 30 for 830111-24, per 011-81-30
CRANE, P A Pacific Gas & Electric Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director 1p 17018 315 24X
Fiche 50-275, 83/01/28, 8302040369

--8302040371 "Diablo Canyon Verification Program," Semimonthly Rept 30
for 830111-24
HOCH, J B Pacific Gas & Electric Co 83/01/28 61pp 17018 316
24X Fiche 50-275, 83/01/28, 8302040369

8302140110 Forwards "Annual Summary Rept on Monitoring & Reporting
Program at Diablo Canyon Power Plant During 1982 " &
"Thermal Effects Monitoring Program 1982 Annual Rept, Diablo
Canyon Power Plant "
THORNBERRY, R C Pacific Gas & Electric Co 83/01/28 JONES, K R
California, State of 2pp, 17140 202 24X Fiche 50-275, 83/01/28,
8302140110

--8302140115 "Annual Summary Rept on Monitoring & Reporting Program at
Diablo Canyon Power Plant During 1982 "
* Pacific Gas & Electric Co 82/12/31 48pp 17140 204 24X
Fiche 50-275, 83/01/28, 8302140110

--8302140117 "Thermal Effects Monitoring Program 1982 Annual Rept, Diablo
Canyon Power Plant "
* Pacific Gas & Electric Co B-82-408 83/01/31 155pp
17140 252, 24X Fiche, 50-275, 83/01/28, 8302140110

DOCKETED ITEMS

91

8302180112 Advises that no open item repts issued re const QA evaluation since Jan semimonthly rept
SESTAK, F Stone & Webster Engineering Corp 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric
Co 1p 17215 362 24X Fiche 50-275, 83/02/11, 8302180112

8302180277 Forwards "Independent Design Verification Program," semimonthly rept for Jan 1983 Change to distribution list submitted Changes in Program Procedure DCNPP-IDVP-PP-007 will be made at next rev
COOPER, H E Teledyne Engineering Services 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric
Co 1p 17211 277 24X Fiche 50-275, 83/02/11, 8302180277

--8302180281 "Independent Design Verification Program," semimonthly rept for Jan 1983
* Teledyne Engineering Services 83/02/11 133pp 17211 278
24X Fiche 50-275, 83/02/11, 8302180277

8302180488 Forwards semimonthly Open Item Repts 1113 & 6002 for Feb 1983 Deficiencies found in independent calculation for component cooling water pump & rupture restraints
DENISON, E Robert L. Cloud Associates, Inc 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric
Co 3pp 17210 352 24X Fiche 50-275, 83/02/11, 8302180488

8302180492 Submits semimonthly rept for Feb 1983 No open item repts issued
KRECHTING, J E Stone & Webster Engineering Corp 83/02/11
DENTON, H R Office of Nuclear Reactor Regulation, Director
ENGELKEN, R H Region 5, Office of Director MANEATIS, O A Pacific
Gas & Electric Co 1p 17211 001 24X Fiche 50-275, 83/02/11,
8302180492

8302230493 Forwards "Diablo Canyon Design Verification Program," 31st semimonthly status rept
CRANE, P A Pacific Gas & Electric Co 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
Region 5, Office of Director 1p 17245 196 24X
Fiche 50-275, 83/02/11, 8302230493

--8302230497 "Diablo Canyon Design Verification Program," 31st semimonthly status rept
HOCH, J D Pacific Gas & Electric Co 83/02/11 58pp 17245 197
24X Fiche 50-275, 83/02/11, 8302230493

S Reportable occurrences, LERs & related correspondence

8302180163 Forwards LER 83-001/03L O
SHIFFER, J D Pacific Gas & Electric Co 83/02/03 ENGELKEN, R H
Region 5, Office of Director 1p 17216 105 24X
Fiche 50-275, 83/02/03, 8302180163

--8302180175 LER 83-001/03L-O on 830107, during recorder check prior to fuel load, steam generator blowdown multipoint flow recorder 1-71 discovered inoperable Caused by broken print head drive string String replaced
KELLY, W J Pacific Gas & Electric Co 83/02/03 Region 5,
Office of Director 1p 17216 106 24X Fiche 50-275, 83/02/03,
8302180163

T Hearing transcripts on non-antitrust matters

8302080151 Board Notification 83-6 forwards info re independent design verification program status info relevant to safety issue of plant design adequacy (ref Commission Order CL1-81-301).
EISENHUT, D O Division of Licensing 83/01/26 PALLADINO, M. J.,
GILINSKY, V., AHEARNE, V Commissioners 4pp 17103 336 24X
Fiche 50-275, 83/01/26, 8302080151

--8302080155 Transcript of 830113 meeting w/ util & Bechtel in San Francisco, CA re independent design verification program
* Commissioners 83/01/13 238pp 17104 045 24X
Fiche 50-275, 83/01/26, 8302080151

8302230005 Board Notification 83-10 provides info items re independent design verification program
EISENHUT, D O Division of Licensing 83/02/03 PALLADINO, M. J.,
GILINSKY, V., AHEARNE, J F Commissioners. 6pp 17259.330 24X
Fiche 50-275, 83/02/03, 8302230005

--8302230006 Transcript of 830128 meeting re component cooling water sys
Pp 1-183 Supporting documentation encl
4 Office of Nuclear Reactor Regulation, Director 83/01/28
183pp 17260 092 24X Fiche 50-275, 83/02/03, 8302230005

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8302040393 Forwards revised Figure 6 2-2 to Tech Specs re health physics organization
GALLAGHER, J W Philadelphia Electric Co 83/01/28 STOLZ, J F
Operating Reactors Branch 4 2pp 17017 342 24X
Fiche 50-277, 83/01/28, 8302040393

--8302040399 Revised Figure 6 2-2 to Tech Specs re health physics organization
* Philadelphia Electric Co 83/01/28 1p 17017 344 24X
Fiche 50-277, 83/01/28, 8302040393

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for CL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302150445 Response to Philadelphia Electric Co & PSE&O 830124 motion to strike C Kefford affidavit suppl re expert qualifications Affidavit provides no relevant facts not considered by ASLARS W/Certificate of Svc
REIS, E J Hearing Branch 3 83/02/14, Commissioners 8pp
17158 194 24X Fiche 50-000, 83/02/14, 8302150445

8302280193 Order extending time until 830328 for Commission to act to review TMI & Peach Bottom intervenors 821227 petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 83/02/25
Commissioners 2pp 17306 099 24X Fiche 50-000, 83/02/25,
8302280193

P. Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170076 Concludes that based on licensee 820211 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
FAIRFIELD, M B Operating Reactors Branch 4 82/02/24 NOVAK, T. M
Assistant Director for Operating Reactors 2pp 17196 173 24X
Fiche 50 000, 83/01/18, 8302170019.

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24, MIRAOLIA, F.
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019.

--8302170188 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety.
FAIRFIELD, M B Operating Reactors Branch 4. 82/10/28 EISENHUT, D O
Division of Licensing 1p 17196 337 24X Fiche 50-000,
83/01/18, 8302170019

--8302170192 Concludes that based on review of util 820211 ltr, continued operation does not constitute undue risk to public health & safety
FAIRFIELD, M B, Operating Reactors Branch 4 82/02/24, NOVAK, T. M.
Assistant Director for Licensing 2pp, 17196.358 24X
Fiche 50-000, 83/01/18, 8302170019

DOCKETED ITEMS

830200071 Forwards safety evaluation approving plant-specific application of BWR Owners Group generic response to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals
STOLZ, J F Operating Reactors Branch 4 83/01/23 BAUER, E O
Philadelphia Electric Co 7pp 16978 343 24X
Fiche 50-277, 83/01/23, 830200071

8302040393 Forwards revised Figure 6 2-2 to Tech Specs re health physics organization
GALLAGHER, J W Philadelphia Electric Co 83/01/28 STOLZ, J F
Operating Reactors Branch 4 2pp 17017 342 24X
Fiche 50-277, 83/01/28, 8302040393

--8302040399 Revised Figure 6 2-2 to Tech Specs re health physics organization
* Philadelphia Electric Co 83/01/28 1p 17017 344 24X
Fiche 50-277, 83/01/28, 8302040399

8302040404 Forwards description of post-accident sampling capabilities at facilities, in response to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys."
DALTROFF, S L Philadelphia Electric Co 83/01/31 STOLZ, J F
Operating Reactors Branch 4 14pp 17014 005 24X
Fiche 50-277, 83/01/31, 8302040404

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests
commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public
Utilities - OPV Service Corp 5pp 17074 095 24X
Fiche 50-000, 83/02/02, 8302030089

8302100251 Forwards request for addl info re NUREG-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves," based on review of response to IE Bulletin 80-01 Info needed by 830408
STOLZ, J F Operating Reactors Branch 4 83/02/02 BAUER, E O
Philadelphia Electric Co 4pp 17134 106 24X
Fiche 50-277, 83/02/02, 8302100251

8302140086 Reaffirms justification for continued operation & submits info re Category I B, II A & II B items, per 821220 ltr forwarding safety evaluation for environ qualification of safety-related electrical equipment
DALTROFF, S L Philadelphia Electric Co 83/02/04 STOLZ, J F
Operating Reactors Branch 4 2pp 17140 200 24X
Fiche 50-277, 83/02/04, 8302140086

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-03 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDD-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302150654 Inform: that response to 830105 ltr requesting info for post-implementation review of NUREG-0737, Items II D 1, II F 1 4, II F 1 5 & II F 1 6 will be submitted by 830304
GALLAGHER, J W Philadelphia Electric Co 83/02/08 STOLZ, J F
Operating Reactors Branch 4 1p 17150 355 24X
Fiche 50-277, 83/02/08, 8302150654

8302180534 Forwards request for addl info re monitoring of electric power to reactor protection sys, based on review of 821108
STOLZ, J F Operating Reactors Branch 4 83/02/10 BAUER, E O
Philadelphia Electric Co 3pp 17221 246 24X
Fiche 50-277, 83/02/10, 8302180534

8302170329 Forwards application for amend to Licenses DPR-44 & DPR-56, deleting obsolete or redundant provisions in ETS, App B
BRADLEY, E J Philadelphia Electric Co 83/02/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p, 17185 130 24X
Fiche 50-277, 83/02/14, 8302170329

--8302170330 Application for amend to Licenses DPR-44 & DPR-56, deleting ETS & bases contained in App B of DLS
BOYER, V S Philadelphia Electric Co 83/02/10 8pp 17185 151
24X Fiche 50-277, 83/02/14, 8302170329

Inspection Reports, IE Bulletins & correspondence

8302010316 Forwards IE Insp Repts 50-277/82-23 & 50-278/82-22 on 821116-18 & 1208 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/17
DALTROFF, S L Philadelphia Electric Co 2pp 16973 058 24X
Fiche 50-277, 83/01/17, 8302010316

--8302010325 IE Insp Repts 50-277/82-23 & 50-278/82-22 on 821116-18 & 1208 No noncompliance noted Major areas inspected licensee action on previous insp finding & on implementation of NUREG-0737, Items I A 2 1 4, II B 4 & II B 2
JOHNSON, D, EAPEN, P, HAVERKAMP, D Division of Project & Resident Programs 83/01/14 13pp 16973 060 24X Fiche 50-277, 83/01/17, 8302010316

8302030418 Forwards IE Insp Repts 50-277/82-26 & 50-278/82-25 on 821214-17 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/21
DALTROFF, S L Philadelphia Electric Co 2pp 17005 114 24X
Fiche 50-277, 83/01/21, 8302030418

--8302030428 IE Insp Repts 50-277/82-26 & 50-278/82-25 on 821214-17 No noncompliance noted Major areas inspected status & licensee progress toward resolutions of significant finding identified during IE Insp Repts 50-277/82-11 & 50-278/82-11
D'NEILL, B, ROHE, C, BARR, K Division of Engineering & Technical Programs 83/01/19 8pp 17005 116 24X Fiche 50-277, 83/01/21, 8302030418

8302160314 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, V&B & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating
Reactors Branch 3 28pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160314

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302030105 Responds to IE Bulletin 82-04 No Bunker-Ramo Co electrical penetrations installed or planned to be installed in safety-related sys No further action required
GALLAGHER, J W Philadelphia Electric Co 83/01/26 HAYNES, R C
Region 1, Office of Director 2pp 17004 286 24X
Fiche 50-277, 83/01/26, 8302030105

8302100295 Forwards IE Enforcement Conference Repts 50-277/83-03 & 50-278/83-03 on 830118 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/26
DALTROFF, S L Philadelphia Electric Co 2pp 17112 254 24X
Fiche 50-277, 83/01/26, 8302100295

--8302100298 IE Enforcement Conference Repts 50-277/83-03 & 50-278/83-03 on 830118 No noncompliance noted Major areas discussed findings of previous insps re significant valve lineup errors resulting from violation of procedural controls
BLOOM, A R, MCCABE, E C Division of Project & Resident Programs 83/01/29 5pp 17112 256 24X Fiche 50-277, 83/01/26, 8302100295

8212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H20C & H30C Overheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302100405 Forwards IE Insp Repts 50-277/82-25 & 50-278/82-24 on 821201-830110 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/28
DALTROFF, S L Philadelphia Electric Co 2pp 17112 173 24X
Fiche 50-277, 83/01/28, 8302100405

--8302100409 Notice of violation from insp on 821201-830110
* Division of Project & Resident Programs 83/01/28 2pp
17112 175 24X Fiche 50-277, 83/01/28, 8302100405

DOCKETED ITEMS

93

--8302100414 IE Insp Repts 50-277/82-25 & 50-278/82-24 on 821201-830110
Noncompliance noted failure to follow Surveillance Procedure
ST 7 9 2 Administrative Procedure A-26
ALLOUGH, A R, MCCABE, E C Division of Project & Resident Programs
83/01/14 16pp 17112 177 24X Fiche 50-277, 83/01/28, 8302100405

8302140026 Updates 820520 ltr re schedule for mods to scram discharge
piping per IE Bulletin 89-17 Mods for Unit 2 completed in
Jul 1982 Schedules for Unit 3 vent cross-connect piping &
diverse instrumentation installation remain in effect
DALTROFF, S L Philadelphia Electric Co 83/02/04 STOLZ, J F
Operating Reactors Branch 4 2pp 17141 177 24X
Fiche 50-277, 83/02/04, 8302140026

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302280450 Ack receipt of 821021 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/82-20 &
50-278/82-19
MARTIN, T T Division of Engineering & Technical Programs 83/02/23
DALTROFF, S L Philadelphia Electric Co 2pp 17309 144 24X
Fiche 50-277, 83/02/23, 8302280450

--8302280469 Responds to NRC 820922 ltr re violations noted in IE Insp
Repts 50-277/82-20 & 50-278/82-19 Corrective actions prompt
rept will be issued for first local leak rate test failure
& 30-day followup rpt for other failures
DALTROFF, S L Philadelphia Electric Co 82/10/21 MARTIN, T T
Division of Engineering & Technical Programs 2pp 17309 146
24X Fiche 50-277, 83/02/23, 8302280460

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302180334 Forwards monthly operating repts for Jan 1983
COONEY, M J Philadelphia Electric Co 83/02/14 Director's
Office, Office of Inspection and Enforcement 1p 17210 008 24X
Fiche 50-277, 83/02/14, 8302180334

--8302180338 Monthly operating repts for Jan 1983
ALDEN, W H Philadelphia Electric Co 83/02/10 9pp 17210 009
24X Fiche 50-277, 83/02/14, 8302180334

8302240249 Forwards "Evaluation of Peach Bottom Atomic Power Station,
1982 "
BRUNNER, E J Division of Project & Resident Programs 83/02/17
TAYLOR, J M Division of Reactor Programs (Pre 830103) CASE, E O
Office of Nuclear Reactor Regulation, Director 1p 17272 291 24X
Fiche 50-277, 83/02/17, 8302240249

--8302240259 "Evaluation of Peach Bottom Atomic Power Station, 1982," re
plant safety, mgt sys & controls & improvement items
* Institute of Nuclear Power Operations 82/12/31 45pp
17272 292 24X Fiche 50-277, 83/02/17, 8302240249

B Reportable occurrences, LERs & related correspondence

8302030400 Forwards LER 83-001/01T-0 Detailed event analysis submitted
COONEY, M J Philadelphia Electric Co 83/01/18 HAYNES, R C
Region 1, Office of Director 3pp 17005 210 24X
Fiche 50-277, 83/01/18, 8302030400

--8302030408 LFR 83-001/01T-0 on 830104, OE type CR2940 switch for ECCB
room coolers failed during environ qualification testing
after radiation dose of 27 megarad Caused by radiation
induced embrittlement of nylon cam surface matl
COONEY, M J Philadelphia Electric Co 83/01/18 Region 1,
Office of Director 1p 17005 213 24X Fiche 50-277, 83/01/18,
8302030400

8302070520 RD 2-83-2/1P on 830120, during surveillance of control
room, indicating lights for RCIC inboard steam supply
isolation valve found not lit, due to open feed breaker
valve Caused by personnel error Feed breaker closed
ULLRICH, W T Philadelphia Electric Co 83/01/20 HAYNES, R C,
Region 1, Office of Director 2pp 17039 015 24X
Fiche 50-277, 83/01/20, 8302070520

8302090318 LER 82-044/03L-0 on 821229, torus water level recorder
LR-8027A went offscale & annunciated low level alarm before
returning to stable but lower level indication Caused by
accidental bump Transmitter calibr
COONEY, M J Philadelphia Electric Co 83/01/28 HAYNES, R C
Region 1, Office of Director 1p 17069 334 24X
Fiche 50-277, 83/01/28, 8302090318

8302090339 Forwards LER 83-002/01T-0 Detailed event analysis submitted
COONEY, M J Philadelphia Electric Co 83/01/28 HAYNES, R C
Region 1, Office of Director 3pp 17067 151 24X
Fiche 50-277, 83/01/28, 8302090339

--8302090349 LER 83-002/01T-0 on 830120, RCIC inboard steam supply
isolation valve found in open position Caused by operator
mistakenly removing feed from valve Operators counseled to
take better precautions
COONEY, M J Philadelphia Electric Co 83/01/28 Region 1,
Office of Director 1p 17067 154 24X Fiche 50-277, 83/01/28,
8302090339

8302150693 LER 82-045/03L-0 on 821230, while performing routine
decontamination of RHR pump room 2B, motor found wet to
extent considered inoperable Caused by personnel error
Supervisor instructed vendor in proper method
COONEY, M J Philadelphia Electric Co 83/01/28 HAYNES, R C
Region 1, Office of Director 1p 17153 310 24X
Fiche 50-277, 83/01/28, 8302150693

8302230146 Updated LER 82-036/01X-2 on 821024, relief valve 71J opened
during startup w/primary coolant pressure at 832 psid
Caused by steam cut pilot valve seat Valve replaced,
COONEY, M J Philadelphia Electric Co 83/02/02 HAYNES, R C
Region 1, Office of Director 1p 17246 023 24X
Fiche 50-277, 83/02/02, 8302230146

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8302040393 Forwards revised Figure 6 2-2 to Tech Specs re health
physics organization
GALLAGHER, J W Philadelphia Electric Co 83/01/28 STOLZ, J F
Operating Reactors Branch 4 2pp 17017 342 24X
Fiche 50-277, 83/01/28, 8302040393

--8302040399 Revised Figure 6 2-2 to Tech Specs re health physics
organization
* Philadelphia Electric Co 83/01/28 1p 17017 344 24X
Fiche 50-277, 83/01/28, 8302040393

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302150445 Response to Philadelphia Electric Co & PSE&O 830124
motion to strike C Kefford affidavit suppl re expert
qualifications, Affidavit provides no relevant facts
not considered by ASLABs H/Certificate of Svc
REIS, E J Hearing Branch 3 83/02/14 Commissioners 8pp
17159 194 24X Fiche 50-000, 83/02/14, 8302150445

DOCKETED ITEMS

8302280193 Order extending time until 830328 for Commission to act to review TH1 & Peach Bottom intervenors 821227 petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 83/02/25
Commissioners 2pp 17305 059 24X Fiche 50-000, 83/02/25,
8302280193

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D G Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170076 Concludes that based on licensee 820211 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
FAIRTILE, M B Operating Reactors Branch 4 82/02/24 NOVAK, T M Assistant Director for Operating Reactors 2pp 17196 173 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170127 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D G Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment App 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170188 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
FAIRTILE, M B Operating Reactors Branch 4 82/10/28 EISENHUT, D G Division of Licensing 1p 17196 357 24X Fiche 50-000,
83/01/18, 8302170019

--8302170192 Concludes that based on review of util 820211 ltr, continued operation does not constitute undue risk to public health & safety
FAIRTILE, M B Operating Reactors Branch 4 82/02/24 NOVAK, T M Assistant Director for Licensing 2pp 17196 358 24X
Fiche 50-000, 83/01/18, 8302170019

8302020071 Forwards safety evaluation approving plant-specific application of BWR Owners Group generic response to NUREG 0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals"
STOLZ, J F Operating Reactors Branch 4 83/01/25 BAUER, E G Philadelphia Electric Co 7pp 16998 341 24X
Fiche 50-277, 83/01/25, 8302020071

8302040393 Forwards revised Figure 6 2-2 to Tech Specs re health physics organization
GALLAGHER, J W Philadelphia Electric Co 83/01/28 STOLZ, J F Operating Reactors Branch 4 2pp 17017 342 24X
Fiche 50-277, 83/01/28, 8302040393

--8302040399 Revised Figure 6 2-2 to Tech Specs re health physics organization
Philadelphia Electric Co 83/01/28 1p 17017 344 24X
Fiche 50-277, 83/01/28, 8302040393

8302040404 Forwards description of post-accident sampling capabilities at facilities, in response to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys"
DALTROFF, S L Philadelphia Electric Co 83/01/31 STOLZ, J F Operating Reactors Branch 4 14pp 17014 005 24X
Fiche 50-277, 83/01/31, 8302040404

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D G Division of Licensing 83/02/02 General Public Utilities - QPU Service Corp 3pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302100251 Forwards request for addl info re NUREG-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves," based on review of response to IE Bulletin 80-01 info needed by 830408
STOLZ, J F Operating Reactors Branch 4 83/02/02 BAUER, E G Philadelphia Electric Co 4pp 17134 106 24X
Fiche 50-277, 83/02/02, 8302100251

8302140086 Reaffirms justification for continued operation & submits info re Category I B, II A & II D items, per 821220 ltr forwarding safety evaluation for environ qualification of safety-related electrical equipment
DALTROFF, S L Philadelphia Electric Co 83/02/04 STOLZ, J F Operating Reactors Branch 4 2pp 17140 200 24X
Fiche 50-277, 83/02/04, 8302140086

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders or CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBNR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302150654 Informs that response to 830105 ltr requesting info for post-implementation review of NUREG-0737, Items II D 1, II F 1 4, II F 1 5 & II F 1 6 will be submitted by 830304
GALLAGHER, J W Philadelphia Electric Co 83/02/08 STOLZ, J F Operating Reactors Branch 4 1p 17150 355 24X
Fiche 50-277, 83/02/08, 8302150654

8302180534 Forwards request for addl info re monitoring of electric power to reactor protection sys, based on review of 821108 submittal Response requested by 830330
STOLZ, J F Operating Reactors Branch 4 83/02/10 BAUER, E G Philadelphia Electric Co 3pp 17221 246 24X
Fiche 50-277, 83/02/10, 8302180534

8302170329 Forwards application for amend to Licenses DPR-44 & DPR-56, deleting obsolete or redundant provisions in ETS, App B
BRADLEY, E J Philadelphia Electric Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17185 150 24X
Fiche 50-277, 83/02/14, 8302170329

--8302170330 Application for amend to Licenses DPR-44 & DPR-56, deleting ETS & bases contained in App B of OLs
BOYER, V S Philadelphia Electric Co 83/02/10 8pp 17105 151 24X
Fiche 50-277, 83/02/14, 8302170329

G Inspection reports, IE Bulletins & correspondence

8302010316 Forwards IE Insp Repts 50-277/82-23 & 50-278/82-22 on 821116-18 & 1208 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/17 DALTROFF, S L Philadelphia Electric Co 2pp 16973 058 24X
Fiche 50-277, 83/01/17, 8302010316

--8302010325 IE Insp Repts 50-277/82-23 & 50-278/82-22 on 821116-18 & 1208 No noncompliance noted Major areas inspected licensee action on previous insp finding & on implementation of NUREG-0737, Items I A 2 1 4, II B 4 & II B 2
JOHNSON, D, EAPEN, P, HAVERKAMP, D Division of Project & Resident Programs 83/01/14 13pp 16973 060 24X Fiche 50-277, 83/01/17, 8302010316

8302030418 Forwards IE Insp Repts 50-277/82-26 & 50-278/82-25 on 821214-17 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/21 DALTROFF, S L Philadelphia Electric Co 2pp 17005 114 24X
Fiche 50-277, 83/01/21, 8302030418

--8302030428 IE Insp Repts 50-277/82-26 & 50-278/82-25 on 821214-17 No noncompliance noted Major areas inspected status & licensee progress toward resolutions of significant finding identified during IE Insp Repts 50-277/82-11 & 50-278/82-11
OWIEILL, B, ROWE, C, BARR, K Division of Engineering & Technical Programs 83/01/19 8pp 17005 116 24X Fiche 50-277, 83/01/21, 8302030418

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr,URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMWELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

B212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

8302030105 Responds to IE Bulletin 82-04 No Bunker-Ramo Co electrical
penetrations installed or planned to be installed in
safety-related sys No further action required
GALLAGHER, J W Philadelphia Electric Co 83/01/26 HAYNES, R C
Region 1, Office of Director 2pp 17004 286 24X
Fiche 50-277, 83/01/26, 8302030105

8302100295 Forwards IE Enforcement Conference Repts 50-277/83-03 &
50-278/83-03 on 830118 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/26
DALTROFF, S L Philadelphia Electric Co 2pp 17112 254 24X
Fiche 50-277, 83/01/26, 8302100295

--8302100298 IE Enforcement Conference Repts 50-277/83-03 & 50-278/83-03
on 830118 No noncompliance noted Major areas discussed
findings or previous insps re significant valve lineup
errors resulting from violation or procedural controls
BLUGUOH, A R, MCCABE, E C Division of Project & Resident Programs
83/01/26 5pp 17112 256 24X Fiche 50-277, 83/01/26, 8302100298

B212060360 IE Info Notice 83-02, "Limitorque H00C, H10C, H20C & H30C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

8302100405 Forwards IE Insp Repts 50-277/82-25 & 50-278/82-24 on
821201-B30110 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/28
DALTROFF, S L Philadelphia Electric Co 2pp 17112 173 24X
Fiche 50-277, 83/01/28, 8302100405

--8302100414 IE Insp Repts 50-277/82-25 & 50-278/82-24 on 821201-B30110
Noncompliance noted failure to follow Surveillance Procedure
ST 7 9 2 & Administrative Procedure A-26
BLUGUOH, A R, MCCABE, E C Division of Project & Resident Programs
83/01/14 16pp 17112 177 24X Fiche 50-277, 83/01/28, 8302100405

8302140026 Updates 820520 ltr re schedule for mods to scram discharge
piping per IE Bulletin 80-17 Mods for Unit 2 completed in
Jul 1982 Schedules for Unit 3 vent cross-connect piping &
diverse instrumentation installation remain in effect
DALTROFF, S L Philadelphia Electric Co 83/02/04 STOLZ, J F
Operating Reactors Branch 4 2pp 17141 177 24X
Fiche 50-277, 83/02/04, 8302140026

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

8302280460 Ack receipt of 821021 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-277/82-20 &
50-278/82-19
MARTIN, T T Division of Engineering & Technical Programs 83/02/23
DALTROFF, S L Philadelphia Electric Co 2pp 17309 144 24X
Fiche 50-277, 83/02/23, 8302280460

--8302280469 Responds to NRC 820922 ltr re violations noted in IE Insp
Repts 50-277/82-20 & 50-278/82-19 Corrective actions prompt
rept will be issued for first local leak rate test failure
& 30-day followup rept for other failures
DALTROFF, S L Philadelphia Electric Co 82/10/21 MARTIN, T T
Division of Engineering & Technical Programs 2pp 17309 146
24X Fiche 50-277, 83/02/23, 8302280460

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

R Periodic operating reports & related correspondence

8302180334 Forwards monthly operating repts for Jan 1983
COONEY, A R Philadelphia Electric Co 83/02/14 Director's
Office, Office of Inspection and Enforcement 1p 17210 008 24X
Fiche 50-277, 83/02/14, 8302180334

--8302180338 Monthly operating repts for Jan 1983
ALDEN, W H Philadelphia Electric Co 83/02/10 9pp 17210 009
24X Fiche 50-277, 83/02/14, 8302180334

8302240249 Forwards "Evaluation of Peach Bottom Atomic Power Station,
1982 " BRUNNEN, E J Division of Project & Resident Programs 83/02/17
TAYLOR, J M Division of Reactor Programs (Pre 830103) CASE, E O
Office of Nuclear Reactor Regulation, Director 1p 17272 291 24X
Fiche 50-277, 83/02/17, 8302240249

--8302240259 "Evaluation of Peach Bottom Atomic Power Station, 1982," re
plant safety, mgt sys & controls & improvement items
* Institute of Nuclear Power Operations 82/12/31 45pp
17272 292 24X Fiche 50-277, 83/02/17, 8302240249

S Reportable occurrences, LERs & related correspondence

8302010188 LER 82-016/03L-0 on 820831, while operating at power, loss of
position indication observed on motor operated steam supply
valve MO-3-13-131 to RCIC turbine Caused by grounded relay
coil Relay & control fuse replaced
* Philadelphia Electric Co 82/09/30 HAYNES, R C Region 1,
Office of Director 1p 16974 024 24X Fiche 50-278, 82/09/30,
8302010188

8302070521 LER 82-027/03L-0 on 821227, RCIC turbine throttle valve
tripped closed due to pump overspeed Caused by closed
suction valve following valve stroking section of
surveillance test Valve opened & tested successfully
COONEY, M J Philadelphia Electric Co 83/01/24 HAYNES, R C
Region 1, Office of Director 1p 17035 253 24X
Fiche 50-278, 83/01/24, 8302070521

8302070509 RO 3-83-2/IP on 830126, containment isolation valve MO-5244,
associated U/HPCI turbine exhaust line vacuum breaker, failed to
fully close during local leak rate testing Caused by
solidified lubricant in valve operator
ULRICH, W T Philadelphia Electric Co 83/01/28 HAYNES, R C
Region 1, Office of Director 3pp 17037 054 24X
Fiche 50-278, 83/01/28, 8302070509

8302070513 RO 3-83-6/IP on 830131, test valve between penetration
boundary, inboard & outboard containment isolation valve
exceeded Tech Spec leak rate Caused by improper seating of
manual valve Penetration isolated
ULRICH, W T Philadelphia Electric Co 83/02/01 HAYNES, R C
Region 1, Office of Director 2pp 17037 075 24X
Fiche 50-278, 83/02/01, 8302070513

8302090393 LER 83-001/03L-0 on 830103, setpoint of main steam line low
pressure switch A (PS-3-2-134A) found approx 33% below min
Tech Spec limit Caused by setpoint drift of Barksdale Model
B2126S pressure switch instrument recalibr
COONEY, M J Philadelphia Electric Co 83/02/02 HAYNES, R C
Region 1, Office of Director 1p 17069 333 24X
Fiche 50-278, 83/02/02, 8302090393

8302220401 LER 83-004/03L-0 on 830127, during power operation, torus
purge air supply AQ-3521-B did not fully close upon
completion of deairting operations Caused by piece of
plastic falling through pipe chase. Plastic removed
COONEY, M J Philadelphia Electric Co 83/02/04 HAYNES, R C
Region 1, Office of Director 1p 17232 068 24X
Fiche 50-278, 83/02/04, 8302220401

8302220121 Forwards LER 83-002/01T-0 Detailed event analysis submitted
COONEY, M J Philadelphia Electric Co 83/02/08 HAYNES, R C
Region 1, Office of Director 4pp 17233 270 24X
Fiche 50-278, 83/02/08, 8302220121

--8302220126 LER 83-002/01T-0 on 830126, during local leak rate testing of
HPCI breaker isolation valve, valve did not fully close &
HPCI declared inoperable Caused by solidified grease in
operator gear train Operator cleaned & successfully tested
COONEY, M J Philadelphia Electric Co 83/02/08 Region 1,
Office of Director 1p 17233 274 24X Fiche 50-278, 83/02/08,
8302220121

8302220106 Forwards LER 83-006/01T-0, Detailed event analysis submitted
COONEY, M J Philadelphia Electric Co 83/02/10 HAYNES, R C
Region 1, Office of Director 3pp 17233 105 24X
Fiche 50-278, 83/02/10, 8302220106

DOCKETED ITEMS

--8302220114 LER 83-006/01T-0 on 830131, during local leak rate testing of B containment atmosphere dilution nitrogen injection penetration, determined valve leaking excessively. Caused by scored seat & foreign matl Bonnet, stem & plug replaced. COONEY, M J Philadelphia Electric Co 83/02/10 Region 1, Office of Director 1p 17233 108 24X Fiche 50-278, 83/02/10, 8302220106

8302230202 RO 3-83-08/1P on 830214, three of eight MBIVs failed to pass Tech Spec limit of 11.5 SCFH & containment isolation valve MO 2-74 failed leak rate test. Caused by abnormal wear of valve internals. Valves to be inspected & repaired. FLETSCHMANN, R Philadelphia Electric Co 83/02/15 HAYNES, R C Region 1, Office of Director 2pp 17245 111 24X Fiche 50-278, 83/02/15, 8302230202

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for QLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl. EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302040476 Requests approval of route for planned irradiated fuel shipment from facility to BMI facility, West Jefferson, OH. DANESE, F L Nuclear Assurance Corp 82/11/19, Division of Safeguards 2pp 17059 297 24X Fiche 50-280, 82/11/19, 8302040476

8302080808 Forwards cover sheets to be inserted in 821008 application to amend Licenses DPR-32 & DPR-37, replacing safeguards contingency plan sections of physical security plan. STEWART, W L Virginia Electric & Power Co 83/01/03 CUNNINGHAM, E E Division of Fuel Cycle & Material Safety 3pp 17106 142 24X Fiche 50-280, 83/01/03, 8302080808

8302030614 Releases public version of revised page to emergency plan. FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17013 330 24X Fiche 50-280, 83/01/27, 8302030614

--8302030617 Forwards public version of revised P B 39 to emergency plan. STEWART, W L Virginia Electric & Power Co 83/01/07 O'REILLY, J P Region 2, Office of Director 2pp 17013 331 24X Fiche 50-280, 83/01/07, 8302030614

--8302030619 Public version of revised P B 39 to emergency plan. WILEON, J Virginia Electric & Power Co 82/12/16 2pp 17013 333 24X Fiche 50-280, 83/01/27, 8302030614

8302090068 Releases public version of corrected change to emergency plan. FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17119 183 24X Fiche 50-280, 83/01/27, 8302090068

--8302090074 Forwards public version of corrected Change 5 to emergency plan. STEWART, W L Virginia Electric & Power Co 83/01/06 O'REILLY, J P Region 2, Office of Director 1p 17119 184 24X Fiche 50-280, 83/01/27, 8302090068

--8302090078 Public version of corrected Change 5 to emergency plan. * Virginia Electric & Power Co 82/12/10 45pp 17119 185 24X Fiche 50-280, 83/01/27, 8302090068

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for QL & holders of CAs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" & Svc list encl. EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302080453 Requests addl info re requirements for implementation of Rev 4 to security plan, as result of comments made in Region II 821124 Insp Rep Rev & not approved until review complete. VARGA, S A Operating Reactors Branch 1 83/02/01 STEWART, W L Virginia Electric & Power Co 2pp 17107 345 24X Fiche 50-280, 83/02/01, 8302080453

8302070354 Forwards changes to nuclear security personnel training & qualification programs. Changes withheld (ref 10CFR73.21). STEWART, W L Virginia Electric & Power Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 1p 17029 211 24X Fiche 50-000, 83/02/02, 8302070354

8302150578 Ack receipt of 820120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-33 & 50-281/82-33. DANCE, H C Division of Project & Resident Programs 83/02/07 STEWART, W L Virginia Electric & Power Co 1p 17157 013 24X Fiche 50-280, 83/02/07, 8302150578

--8302150599 IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821101-05 Noncompliance noted failure to follow station procedures resulting in contamination & failure to post radioactive matl areas. ROSEY, C H, DEBS, B T, BARR, K P Division of Engineering & Radiological Safety Programs 82/12/13 10pp 17157 022 24X Fiche 50-280, 83/02/07, 8302150578

8302160260 Forwards proposed changes to security plans. Changes withheld (ref 10CFR73.21). STEWART, W L Virginia Electric & Power Co 83/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 1p 17169 237 24X Fiche 50-000, 83/02/10, 8302160260

8302230141 Forwards changes to security personnel training & qualification programs. Changes withheld (ref 10CFR73.21). STEWART, W L Virginia Electric & Power Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17243 293 24X Fiche 50-000, 83/02/16, 8302230141

8302250428 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Spec 6 5-3 to add specs for retention of annual audit records of emergency plan, security plan & implementing procedures. STEWART, W L Virginia Electric & Power Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 2pp 17296 357 24X Fiche 50-280, 83/02/18, 8302250428

--8302250435 Proposed changes to Tech Spec 6 5-3, adding specs for retention of annual audit records of emergency plan, security plan & implementing procedures. * Virginia Electric & Power Co 83/02/18 4pp 17296 359 24X Fiche 50-280, 83/02/18, 8302250428

J Insurance & indemnity information

8302010193 Forwards Endorsements 52 & 53 to MAELU Policies MF-57 & 96, respectively & Endorsements 49 & 41 to NELIA Policies NF-184 & 240, respectively. LOVING, L J Marsh & McLennan, Inc, & M & H Nuclear Consultants, Inc, Div 83/01/24 DINI, T I Antitrust & Economic analysis Branch (Utility Finance) 5pp 16974 025 24X Fiche 50-000, 83/01/24, 8302010193

8302150050 Forwards Endorsements 1, 2 & 3 to MAELU Certificates M-70, 28, 63 & 27 & NELIA Certificates N-70, 28, 63 & 27. PAINTER, B Virginia Electric & Power Co 83/02/09 DINI, T I Antitrust & Economic analysis Branch (Utility Finance) 76pp 17146 065 24X Fiche 50-000, 83/02/09, 8302150050

P Operating license stage documents & correspondence

8302080100 Addl response to FOIA request for records re steam generators & steam turbines. Forwards documents listed under Category A of App E. Category B documents available in PDR. FELTON, J M Division of Rules and Records 82/12/17 LONG, D J Winthrop, Stimson, Putnam & Roberts 5pp 17105 069 24X Fiche 50-000, 82/12/17, 8302080100

--8302080127 Forwards request for addl info re steam generator tube integrity. Questions specifically address tubes in U-bend region. EISENHUT, D G Division of Operating Reactors 76/12/14 GOLLER, K R Assistant Director for Operating Reactor Projects (Pri 791030) 6pp 17105 145 24X Fiche 50-000, 82/12/17, 8302080100

8302070076 Partial response to FOIA request for 22 categories of documents. Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR. App B documents completely withheld (ref FOIA Exemption 5). FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, S Union of Concerned Scientists 6pp 17063 005 24X Fiche 50-272, 82/12/21, 8302070076

DOCKETED ITEMS

97

--8302070148 Responds to Commissioner Ahearn requests during 810529 briefing on SECY-B1-240, draft NUREG-0771 & 0772 re accident source term assumptions Comments will be sought from outside NRC Detailed analysis encl
DICKS, W J Office of the Executive Director for Operations
8105/29 CHILK, S J Office of the Secretary of the Commission
11pp 17064 145 24X Fiche 50-000, 83/02/21, 8302070076

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D G Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate justification for continued operation re environ qualification of electrical equipment
HANNON, J N NRC - No Detailed Affiliation Given 82/01/27
VARQA, S NRC - No Detailed Affiliation Given 10pp 17196 225 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D G Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170270 Concludes that continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
NICHOLSON, J D Operating Reactors Branch 1 82/10/28
EISENHUT, D G Division of Licensing 2pp 17197 052 24X
Fiche 50-000, 83/01/18, 8302170019

8302070267 Advises that completion of B&W Owners Group test plan re seismic & environ qualification of acoustical monitoring sys scheduled for 830731, per util 811209 Rev 2 response to NUREG 0737, Item II D 3 Item will be updated in Rev 4
STEWART, W L Virginia Electric & Power Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 1p 17032 144 24X Fiche 50-280, 83/01/28, 8302070267

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co or New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Bvc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co or New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302180441 Application to amend Licenses DPR-32 & DPR-37, deleting nonradiological water quality Tech Specs 4.13.4 14 & 4.6.3 d
STEWART, W L Virginia Electric & Power Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 2pp 17215 119 24X
Fiche 50-280, 83/02/14, 8302180441

--8302180448 Proposed Tech Spec changes, deleting nonradiological water quality Tech Specs 4.13.4 14 & 4.6.3 d
* Virginia Electric & Power Co 83/02/14 5pp 17215 121 24X
Fiche 50-280, 83/02/14, 8302180441

8302250265 Forwards response to NUREG-0737, Item II F 1, "Add'l Accident Monitoring Instrumentation," per 830113 ltr Info details accuracies & time responses of containment post-accident monitoring equipment
STEWART, W L Virginia Electric & Power Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 10pp 17272 114 24X Fiche 50-280, 83/02/18, 8302250265

8302250428 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Spec 6.5-3 to add specs for retention of annual audit records of emergency plan, security plan & implementing procedures
STEWART, W L Virginia Electric & Power Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 2pp 17296 357 24X
Fiche 50-280, 83/02/18, 8302250428

--8302250435 Proposed changes to Tech Spec 6.5-3, adding specs for retention or annual audit records of emergency plan, security plan & implementing procedures
* Virginia Electric & Power Co 83/02/18 4pp 17296 359 24X
Fiche 50-280, 83/02/18, 8302250428

8302250344 Informs that util will determine, within 30-day period following 830222, whether to request hearing re orders imposing EP requirements
CHRISTMAN, J N Hutton & Williams 83/02/22 EISENHUT, D G Division of Licensing 1p 17291 071 24X Fiche 50-000, 83/02/22, 8302250344

8302280080 Informs that proprietary protection still required for pages in SER for environ qualification of safety-related electrical equipment transmitted in NRC 830126 ltr Justification will be provided by 830408
STEWART, W L Virginia Electric & Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 1p 17307 185 24X
Fiche 50-280, 83/02/22, 8302280080

8302280202 Forwards justification for continued operation for equipment in NRC Category II B (technical evaluation repts) Justification for equipment in Categories I B & II A will be provided by 830309
STEWART, W L Virginia Electric & Power Co 83/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 3pp 17306 072 24X
Fiche 50-280, 83/02/23, 8302280202

G Inspection reports, IE Bulletins & correspondence

8302080100 Add'l response to FOIA request for records re steam generators & steam turbines Forwards documents listed under Category A of App E Category B documents available in PDR
FELTON, J M Division of Rules and Records 82/12/17 LONO, D J Winthrop, Stinson, Putnam & Roberts 5pp 17105 069 24X
Fiche 50-000, 82/12/17, 8302080100

--8302080122 Summary of 751121 meeting w/utis & Westinghouse re new type of imperfection discovered in recent eddy current insps of dent steam generator tubes Investigation re listed unreviewed safety questions recommended
KINTNER, L L Division of Reactor Licensing (NRR-1975 only) 75/11/24 KINIEL, W Division of Reactor Licensing (NRR-1975 only) 4pp 17105 139 24X Fiche 50-000, 82/12/17, 8302080100

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque MOBC, HIBC, H2BC & H3BC Gearheads " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302090448 Forwards response to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations using hard epoxy module design not utilized
STEWART, W L Virginia Electric & Power Co 83/02/04 O'REILLY, J P Region 2, Office of Director 3pp 17066 243 24X
Fiche 50-000, 83/02/04, 8302090448

8302170238 Forwards corrected FR notice re granting of relief from ASME Code Section XI inservice insp requirements Notice corrects expiration date
VARQA, S A Operating Reactors Branch 1 83/02/04 STEWART, W L Virginia Electric & Power Co 2pp 17195 357 24X
Fiche 50-000, 83/02/04, 8302170238

--8302170243 Correction to notice of granting of relief from ASME Code Section XI inservice insp requirements. Expiration date corrected
VARQA, S A Operating Reactors Branch 1 83/02/04 1p 17195 359 24X Fiche 50-000, 83/02/04, 8302170238

8302150578 Ack receipt of 820120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-33 & 50-281/82-33
DANCE, H C Division of Project & Resident Programs 83/02/07 STEWART, W L Virginia Electric & Power Co 1p 17157 013 24X
Fiche 50-280, 83/02/07, 8302150578

DOCKETED ITEMS

--B302150585 Responds to NRC B21221 ltr re violations noted in IE Insp Repts 50-280/82-33 & 50-281/82-33 Corrective actions missing pipe caps from HX drain lines replaced & checked for further leakage & area posted w/required signs
STEWART, W L Virginia Electric & Power Co 83/01/20
O'REILLY, J P Region 2, Office of Director 4pp 17157 014 24X
Fiche 50-280, 83/02/07, B302150578

--B302150589 Forwards IE Insp Repts 50-280/82-33 & 50-281/82-33 on B21101-05 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/12/21
STEWART, W L Virginia Electric & Power Co 2pp 17157 018 24X
Fiche 50-280, 83/02/07, B302150578

--B302150592 Notice of violation from insp on B21101-05
* Division of Project & Resident Programs 82/12/21 2pp
17157 020 24X Fiche 50-280, 83/02/07, B302150578

--B302150599 IE Insp Repts 50-280/82-33 & 50-281/82-33 on B21101-05 Noncompliance noted failure to follow station procedures resulting in contamination & failure to post radioactive matl areas
HOSEY, C H, DEBS, B T, BARR, K P Division of Engineering & Radiological Safety Programs 82/12/13 10pp 17157 022 24X
Fiche 50-280, 83/02/07, B302150578

B302150198 Forwards suppl to requests for relief from ASME Section XI re 10-yr inservice insp Request relates to exam of nozzle dissimilar metal welds
STEWART, W L Virginia Electric & Power Co 83/02/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch I 3pp 17147 238 24X
Fiche 50-280, 83/02/09, B302150158

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice 83-08, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17341 148 24X Fiche 50-000, 83/02/24, B212060366

8 Reportable occurrences, LERs & related correspondence

B302010422 Forwards LERs 82-125/03L-0 & 82-127/03L-0
WILSON, J L Virginia Electric & Power Co 83/01/21 O'REILLY, J P
Region 2, Office of Director 1p 16974 248 24X
Fiche 50-280, 83/01/21, B302010422

--B302010423 LER 82-125/03L-0 on B21221, w/unit at full power, Periodic Test 21 revealed that output of loop A Delta T summator below acceptable limits Caused by instrument drift Summator recalibr & returned to svc
WILSON, J L Virginia Electric & Power Co 83/01/21 Region 2,
Office of Director 3pp 16974 250 24X Fiche 50-280, 83/01/21,
B302010422

--B302010424 LER 82-127/03L-0 on B21228, while gaseous release in progress, RR-175 indicated off-scale process vent gaseous radiation monitor RM-GW-102 Caused by failure of discriminator printed circuit board Board replaced
WILSON, J L Virginia Electric & Power Co 83/01/21 Region 2,
Office of Director 2pp 16974 253 24X Fiche 50-280, 83/01/21,
B302010422

B302070392 Forwards LER 83-001/03L-0 & updated LERs 81-054/03X-1 & 81-082/03X-1
WILSON, J L Virginia Electric & Power Co 83/01/27 O'REILLY, J P
Region 2, Office of Director 1p 17029 349 24X
Fiche 50-280, 83/01/27, B302070392

--B302070399 LER 83-001/03L-0 on B30112, at 100% power, radiation monitor recorder RR-100 failed low Caused by insulating film buildup on monitor selector contacts Contacts cleaned & recorder returned to svc,
WILSON, J L Virginia Electric & Power Co 83/01/27 Region 2,
Office of Director 2pp 17029 350 24X Fiche 50-280, 83/01/27,
B302070392

--B302070402 Updated LER 81-054/03X-1 on B10923, higher than normal activity detected in storm drain sys Caused by leaking of four tubes in HX bundle of 1-BR-E-10A & failure of auxiliary steam drain receiver pumps to prevent overflow
WILSON, J L Virginia Electric & Power Co 83/01/27 Region 2,
Office of Director 2pp 17029 352 24X Fiche 50-280, 83/01/27,
B302070392

--B302070407 Updated LER 81-082/03X-1 on B11231, during biweekly control rod assembly partial movement test PT-6, rod J-9 found inoperable Caused by connector pin in lift coil wiring not making electrical contact Pin adjusted & rod tested
WILSON, J L Virginia Electric & Power Co 83/01/27 Region 2,
Office of Director 2pp 17029 354 24X Fiche 50-280, 83/01/27,
B302070392

B302170345 Forwards LER 83-002/03L-0 & updated LER 82-126/03X-1
WILSON, J L Virginia Electric & Power Co 83/02/08 O'REILLY, J P
Region 2, Office of Director 1p 17187 125 24X
Fiche 50-280, 83/02/08, B302170345

--B302170371 LER 83-002/03L-0 on B30114, w/unit at full power, steam generator C level indication LT-1-495 drifted high Caused by leak in transmitter ref log condensate pot root valve Repairs will be performed during next outage
WILSON, J L Virginia Electric & Power Co 83/02/08 Region 2,
Office of Director 2pp 17187 126 24X Fiche 50-280, 83/02/08,
B302170345

--B302170375 Updated LER 82-126/03X-1 on B21223, rod position indication for control rod F-4 indicated erratically & fluctuated greater than 12 steps Cause unknown Erroneous signal suspected of being inside containment Testing underway
WILSON, J L Virginia Electric & Power Co 83/02/08 Region 2,
Office of Director 2pp 17187 128 24X Fiche 50-280, 83/02/08,
B302170345

B302230196 Forwards LER 82-129/03L-0
WILSON, J L Virginia Electric & Power Co 83/02/11 O'REILLY, J P
Region 2, Office of Director 1p 17245 159 24X
Fiche 50-280, 83/02/11, B302230196

--B302230203 LER 82-129/03L-0 on B21202, performance of Periodic Test 27 revealed amp reading for panel 1, circuit 23A not within acceptance criteria Caused by faulty thermostat Thermostat replaced
WILSON, J L Virginia Electric & Power Co 83/02/11 Region 2,
Office of Director 2pp 17245 160 24X Fiche 50-280, 83/02/11,
B302230196

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, B301310203

Y Dry Cask Independent Spent Fuel Storage Installations

B302080080 Forwards cover sheets to be inserted in B21008 application to amend Licenses DPR-32 & DPR-37, replacing safeguards contingency plan sections of physical security plan
STEWART, W L Virginia Electric & Power Co 83/01/03
CUNNINGHAM, E E Division of Fuel Cycle & Material Safety 3pp
17106 142 24X Fiche 50-280, 83/01/03, B302080080

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B302040476 Requests approval of route for planned irradiated fuel shipment from facility to GMI facility, West Jefferson, OH
DANFEL, F L Nuclear Assurance Corp 82/11/19 Division of
Safeguards 2pp 17059 297 24X Fiche 50-280, 82/11/19, B302040476

B302080080 Forwards cover sheets to be inserted in B21008 application to amend Licenses DPR-32 & DPR-37, replacing safeguards contingency plan sections of physical security plan
STEWART, W L Virginia Electric & Power Co 83/01/03
CUNNINGHAM, E E Division of Fuel Cycle & Material Safety 3pp
17106 142 24X Fiche 50-280, 83/01/03, B302080080

B302030614 Releases public version of revised page to emergency plan
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17013 330 24X Fiche 50-280, 83/01/27,
B302030614

DOCKETED ITEMS

99

--8302030617 Forwards public version of revised P B 39 to emergency plan
STEWART, W L Virginia Electric & Power Co 83/01/07
O'REILLY, J P Region 2, Office of Director 2pp 17013 331 24X
Fiche 50-280, 83/01/27, 8302030614

--8302030619 Public version of revised P B 39 to emergency plan
HILSON, J Virginia Electric & Power Co 82/12/16 2pp
17013 333 24X Fiche 50-280, 83/01/27, 8302030614

8302090068 Releases public version of corrected change to emergency
Plan
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17119 183 24X Fiche 50-280, 83/01/27,
8302090068

--8302090074 Forwards public version of corrected Change 5 to emergency
plan
STEWART, W L Virginia Electric & Power Co 83/01/06
O'REILLY, J P Region 2, Office of Director 1p 17119 184 24X
Fiche 50-280, 83/01/27, 8302090068

--8302090078 Public version of corrected Change 5 to emergency plan
* Virginia Electric & Power Co 82/12/10 68pp 17119 185 24X
Fiche 50-280, 83/01/27, 8302090068

8301210340 Generic Ltr 83-04 to all licensees of operating reactors.
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability." Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302030453 Requests addl info re requirements for implementation of Rev
6 to security plan, as result of comments made in Region II
B21124 Insp rept Rev 6 not approved until review complete
VAROA, S A Operating Reactors Branch 1 83/02/01 STEWART, W L
Virginia Electric & Power Co 2pp 17107 345 24X
Fiche 50-280, 83/02/01, 8302030453

8302070394 Forwards changes to nuclear security personnel training &
qualification programs Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director VAROA, S A
Operating Reactors Branch 1 1p 17029 211, 24X
Fiche 50-000, 83/02/02, 8302070394

8302190578 Ack receipt of 820120 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/82-33 &
50-281/82-33
DANCE, H C Division of Project & Resident Programs 83/02/07
STEWART, W L Virginia Electric & Power Co 1p 17157 013 24X
Fiche 50-280, 83/02/07, 8302190578

--8302190599 IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821101-05
Noncompliance noted failure to follow station procedures
resulting in contamination & failure to post radioactive
matl areas.
HOSEY, C M Division of Engineering & Radiological Safety Programs
82/12/13 10pp 17157 022 24X Fiche 50-280, 83/02/07,
8302190578

8302160260 Forwards proposed changes to security plans Changes withheld
(ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director VAROA, S A
Operating Reactors Branch 1 1p 17169 237 24X
Fiche 50-000, 83/02/10, 8302160260

8302230141 Forwards changes to security personnel training &
qualification programs Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p, 17243 293 24X
Fiche 50-000, 83/02/16, 8302230141

8302250428 Application for amend to Licenses DPR-32 & DPR-37, changing
Tech Spec 6 5-3 to add specs for retention of annual audit
records of emergency plan, security plan & implementing
procedures
STEWART, W L Virginia Electric & Power Co 83/02/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp, 17296 357,
24X Fiche: 50-280, 83/02/18, 8302250428

--8302250435 Proposed changes Tech Spec 6 5-3, adding specs for retention
of annual audit records of emergency plan, security plan &
implementing procedures
* Virginia Electric & Power Co 83/02/18 4pp 17296 359, 24X
Fiche 50-280, 83/02/18, 8302250428.

J Insurance & indemnity information

8302010193 Forwards Endorsements 52 & 53 to MAELU Policies MF-57 & 96,
respectively & Endorsements 68 & 41 to NELIA Policies MF-186
& 240, respectively
LOVINO, L J Marsh & McLennan, Inc. M & H Nuclear Consultants, Inc
Div 83/01/24 DINITZ, I Antitrust & Economic analysis Branch
(Utility Finance) 5pp 16974 025 24X Fiche 50-000, 83/01/24,
8302010193

8302150050 Forwards Endorsements 1, 2 & 3 to MAELU Certificates M-70,
28, 63 & 31 & NELIA Certificates 11-70, 28, 63 & 27
PAINTER, B Virginia Electric & Power Co 83/02/09 DINITZ, I
Antitrust & Economic analysis Branch (Utility Finance) 76pp
17146 065 24X Fiche 50-000, 83/02/09, 8302150050

P Operating license stage documents & correspondence

8302080100 Addl response to FOIA request for records re steam
generators & steam turbines Forwards documents listed under
Category A or App E Category B documents available in PDR
FELTON, J M Division of Rules and Records 82/12/17 LONGO, D J
Winthrop, Stimson, Putnam & Roberts 5pp 17105 069 24X
Fiche 50-000, 82/12/17, 8302080100

--8302080132 Trip rept of 770217 visit to Westinghouse, Tampa Div re
steam generator strain calculations for dented tubes &
cracked support plates & steam generator tube leaks at
Facility List of attendees & meeting agenda encl
STUART, R Engineering Branch (Pre 791030) 77/02/18
EISENHUT, D O Division of Operating Reactors 6pp 17105 151
24X Fiche 50-000, 82/12/17, 8302080100

8302070074 Partial response to FOIA request for 22 categories of
documents Forwards documents listed in App A Documents 12,
13, 16, 18, 19, 27 & 28 available in PDR App B documents
completely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, B
Union of Concerned Scientists 6pp 17063 005 24X
Fiche 50-281, 82/12/21, 8302070074

--8302070148 Responds to Commissioner Ahearne requests during 810329
briefing on SECY-81-240, draft NUREG-0771 & 0772 re accident
source term assumptions Comments will be sought from outside
NRC Detailed analysis encl
DIRCKS, W J Office of the Executive Director for Operations
81/06/29 CHILK, S J Office of the Secretary of the Commission
11pp 17064 145 24X Fiche 50-000, 82/12/21, 8302070074

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170096 Package of six comments indicating adequate or inadequate
justification for continued operation re environ
qualification of electrical equipment
HARRISON, J M NRC - No Detailed Affiliation Given 82/01/27
VAROA, S NRC - No Detailed Affiliation Given 10pp 17196 225
24X Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by
which technical evaluation repts are expected to be
completed Requests justification for continued operation of
each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche, 50-000, 83/01/18, 8302170019

--8302170270 Concludes that continued operation until completion of
licensee environ qualification program will not present
undue risk to public health & safety
MELCHBORS, J D Operating Reactors Branch 1 82/10/28
EISENHUT, D O Division of Licensing 2pp 17197 052, 24X
Fiche 50-000, 83/01/18, 8302170019

8302070267 Advises that completion of B&W Owners Group test plan re
seismic & environ qualification of acoustical monitoring sys
scheduled for 830731, per util 811207 Rev 2 response to
NUREG-0737, Item 11 D 3 Item will be updated in Rev 4
STEWART, W L Virginia Electric & Power Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 1p 17032, 144 24X Fiche 50-280, 83/01/28,
8302070267

DOCKETED ITEMS

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 1pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302180441 Application to amend Licenses DPR-32 & DPR-37, deleting nonradiological water quality Tech Specs 4 13, 4 14 & 6 3 d
STEWART, W L Virginia Electric & Power Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 2pp 17215 119 24X
Fiche 50-280, 83/02/14, 8302180441

--8302180448 Proposed Tech Spec changes, deleting nonradiological water quality Tech Specs 4 13, 4 14 & 6 3 d
* Virginia Electric & Power Co 83/02/14 5pp 17215 121 24X
Fiche 50-280, 83/02/14, 8302180448

8302250265 Forward's response to NUREC-0737, Item II F 1, "Add'l Accident Monitoring Instrumentation," per 830113 ltr Info details accuracies & time responses of containment post-accident monitoring equipment
STEWART, W L Virginia Electric & Power Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 10pp 17292 114 24X Fiche 50-280, 83/02/18, 8302250265

8302250428 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Spec 6 5-3 to add specs for retention of annual audit records of emergency plan, security plan & implementing procedures
STEWART, W L Virginia Electric & Power Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 2pp 17296 357 24X
Fiche 50-280, 83/02/18, 8302250428

--8302250435 Proposed changes to Tech Spec 6 5-3, adding specs for retention of annual audit records of emergency plan, security plan & implementing procedures
* Virginia Electric & Power Co 83/02/18 4pp 17296 359 24X
Fiche 50-280, 83/02/18, 8302250435

8302250344 Informs that util will determine, within 30-day period following 830222, whether to request hearing re orders imposing EP requirements
CHRISTIAN, J N Hunton & Williams 83/02/22 EISENHUT, D O Division of Licensing 1p 17291 071 24X Fiche 50-000, 83/02/22, 8302250344

8302280080 Informs that proprietary protection still required for pages in SER for environ qualification of safety-related electrical equipment transmitted in NRC 830126 ltr
Justification will be provided by 830408
STEWART, W L Virginia Electric & Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 1p 17307 185 24X
Fiche 50-280, 83/02/22, 8302280080

8302280202 Forward's justification for continued operation for equipment in NRC Category II B (technical evaluation repts).
Justification for equipment in Categories I B & II A will be provided by 830309.
STEWART, W L Virginia Electric & Power Co 83/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director VARQA, S A Operating Reactors Branch 1 3pp 17306 072 24X
Fiche 50-280, 83/02/23, 8302280202

G. Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03 "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302090448 Forward's response to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Bunker-Ramo electrical penetrations using hard epoxy module design not utilized
STEWART, W L Virginia Electric & Power Co 83/02/04 O'REILLY, J P Region 2, Office of Director 3pp 17066 243 24X
Fiche 50-000, 83/02/04, 8302090448

8302170238 Forward's corrected FR notice re granting of relief from ASME Code Section XI inservice insp requirements Notice corrects expiration date
VARQA, S A Operating Reactors Branch 1 83/02/04 STEWART, W L Virginia Electric & Power Co 2pp 17195 357 24X
Fiche 50-000, 83/02/04, 8302170238

--8302170243 Correction to notice of granting of relief from ASME Code Section XI inservice insp requirements Expiration date corrected
VARQA, S A Operating Reactors Branch 1 83/02/04 1p 17195 359 24X Fiche 50-000, 83/02/04, 8302170238

8302190578 Ack receipt of 820120 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-280/82-33 & 50-281/82-33
DANCE, H C Division of Project & Resident Programs 83/02/07 STEWART, W L Virginia Electric & Power Co 1p 17157 013 24X
Fiche 50-280, 83/02/07, 8302190578

--8302190585 Responds to NRC 821221 ltr re violations noted in IE Insp Repts 50-280/82-33 & 50-281/82-33 Corrective actions missing pipe caps from HX drain lines replaced & checked for further leakage & area posted w/required signs
STEWART, W L Virginia Electric & Power Co 83/01/20 O'REILLY, J P Region 2, Office of Director 4pp 17157 014 24X
Fiche 50-280, 83/02/07, 8302190578

--8302190589 Forward's IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821101-05 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/12/21 STEWART, W L Virginia Electric & Power Co 2pp 17157 018 24X
Fiche 50-280, 83/02/07, 8302190578

--8302190592 Notice of violation from insp on 821101-05
* Division of Project & Resident Programs 82/12/21 2pp 17157 020 24X Fiche 50-280, 83/02/07, 8302190578

--8302190599 IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821101-05 Noncompliance noted failure to follow station procedures resulting in contamination & failure to post radioactive mail areas
HOSEY, C M, DEBS, B T, BARR, K P Division of Engineering & Radiological Safety Programs 82/12/13 10pp 17157 022 24X
Fiche 50-280, 83/02/07, 8302190578

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302140262 Forward's LER 83-001/03L O & updated LERs 81-052/03X-1 & 81-074/03X-1
WILSON, J L Virginia Electric & Power Co 83/01/31 O'REILLY, J P Region 2, Office of Director 1p 17140 191 24X
Fiche 50-281, 83/01/31, 8302140062

--8302140066 LER 83-001/03L-0 on 830118, amp readings for heat tracing panel B, circuit 138, fell below acceptance criteria. Caused by excessive heat. Defective heat tracing replaced & tested. Design change prepared.
WILSON, J. L. Virginia Electric & Power Co. 83/01/31 Region 2, Office of Director 2pp 17140 192 24X Fiche 50-281, 83/01/31, 8302140062

--8302140069 Updated LER 81-052/03X-1 on 810815, valve MOV-SW-202A failed to close due to grounded motor. Grounding caused by flooding in sump. Motor replaced.
WILSON, J. L. Virginia Electric & Power Co. 83/01/31 Region 2, Office of Director 3pp 17140 194 24X Fiche 50-281, 83/01/31, 8302140062

--8302140072 Updated LER 81-074/03X-1 on 811120, higher than normal activity detected in storm drain sys. Caused by leaks from stripper feed steam heater due to failure of heater drain receiver & pumps to prevent overflow. Tubes plugged.
WILSON, J. L. Virginia Electric & Power Co. 83/01/31 Region 2, Office of Director 3pp 17140 197 24X Fiche 50-281, 83/01/31, 8302140062

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc. 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

Y Dry Cask Independent Spent Fuel Storage Installations

8302080080 Forwards cover sheets to be inserted in 821008 application to amend Licenses DPR-32 & DPR-37, replacing safeguards contingency plan sections of physical security plan.
STEWART, W. L. Virginia Electric & Power Co. 83/01/03 CUNNINGHAM, E. E. Division of Fuel Cycle & Material Safety 3pp 17106 142 24X Fiche 50-280, 83/01/03, 8302080080

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302030012 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/01/26 Document Management Branch 1p 17041 094 24X Fiche 50-000, 83/01/26, 8302030012

--8302030018 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.5 re startup operation of emergency offsite facility & EPIP 1.1.6 re emergency organization shift turnover.
WARD, E. C. Northern States Power Co. 83/01/20 Region 3, Office of Director 1p 17041 095 24X Fiche 50-000, 83/01/26, 8302030012

--8302030023 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.5 re startup operation of emergency offsite facility & EPIP 1.1.6 re emergency organization shift turnover.
HUDSON, Q. WARD, E. Northern States Power Co. 83/01/20, 46pp 17041 096 24X Fiche 50-000, 83/01/26, 8302030012

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl. 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc. 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302100197 Forwards exemption from 10CFR50, App R requirement to install fixed fire suppression sys in control room.
CLARK, R. A. Operating Reactors Branch 3 83/02/02 MUSOLF, D. M. Northern States Power Co. 3pp 17134 130 24X Fiche 50-282, 83/02/02, 8302100197

--8302100200 Exemption from 10CFR50, App R requirement to install fixed fire suppression sys in control room.
EISENHUT, D. O. Division of Licensing 83/02/02 Northern States Power Co. 4pp 17134 133 24X Fiche 50-282, 83/02/02, 8302100197

J Insurance & indemnity information

8302150548 Forwards Endorsements 64, 53 & 46 to NELIA Policies NF-174, NF-197 & MAFLU Policies MF-51 & MF-68, respectively. Endorsements 1, 2 & 3 to Certificates N-17, M-17, N-36, H-36, N-37 & H-37 also encl.
JOHNSON, R. O. Northern States Power Co. 83/02/07 DINI, T. I. Antitrust & Economic analysis Branch (Utility Finance) 59pp 17154 152 24X Fiche 50-000, 83/02/07, 8302150548

8302150528 Requests review of govt indemnity agreements for Licenses DPR-42, DPR-60 & DPR-22 re refund due for unexpired term.
JOHNSON, R. O. Northern States Power Co. 83/02/07 DINI, T. I. Antitrust & Economic analysis Branch (Utility Finance) 1p 17151 306 24X Fiche 50-000, 83/02/07, 8302150528

P Operating license stage documents & correspondence

8302080100 Addl response to FOIA request for records re steam generators & steam turbines. Forwards documents listed under Category A of App E. Category B documents available in PDR.
FELTON, J. M. Division of Rules and Records 82/12/17 LON, D. J. Winthrop, Stinson, Putnam & Roberts 5pp 17109 069 24X Fiche 50-000, 82/12/17, 8302080100

--8302080109 Summary of 741125 meeting w/util re steam generator tube corrosion. Agenda, list of attendees & viewgraphs encl.
KIRKNER, L. L. Atomic Energy Commission, Directorate of Licensing 74/12/06 Atomic Energy Commission, Directorate of Licensing 19pp 17105 074 24X Fiche 50-000, 82/12/17, 8302080100

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment.
EISENHUT, D. O. Division of Licensing 83/01/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302170123 Package of four comments indicating adequate or inadequate justification for interim operation re environ qualification of electrical equipment.
PADDOVAN, H. L. NRC - No Detailed Affiliation Given 82/01/27 NRC - No Detailed Affiliation Given 10pp 17196 255 24X Fiche 50 000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed. Requests justification for continued operation of each group by 821008 & 15, respectively.
EISENHUT, D. O. Division of Licensing 82/09/24 MIRAGLIA, F. Assistant Director for Safety Assessment 4pp 17196 263 24X Fiche 50 000, 83/01/18, 8302170019

--8302170293 Concludes that based on licensee 820127 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety.
DIAMINI, D. C. Operating Reactors Branch 3 82/10/28 EISENHUT, D. O. Division of Licensing 5pp 17197 082 24X Fiche 50 000, 83/01/18, 8302170019

8302070231 Forwards corrected Tech Spec Table 4.1-2A re ASME Code Class 1, 2 & 3 pump & valve Inservice Insp Program implementation, incorrectly issued w/830104 Amends 60 & 54 to Licenses DPR-42 & DPR-60, respectively.
DIAMINI, D. C. Operating Reactors Branch 3 83/01/25 MUSOLF, D. M. Northern States Power Co. 2pp 16999 190 24X Fiche 50-282, 83/01/25, 8302070231

--8302070239 Corrected Tech Spec Table 4.1-2A re ASME Code Class 1, 2 & 3 pump & valve Inservice Insp Program implementation, incorrectly issued w/830104 Amends 60 & 54 to Licenses DPR-42 & DPR-60, respectively.
Operating Reactors Branch 3 83/01/25 1p 16999 192 24X Fiche 50-282, 83/01/25, 8302070231

8302100185 Notification of 830211 meeting w/util in Bethesda, MD to resolve open items appearing in Amends 60 & 54 re inservice testing program for pumps & valves.
DIAMINI, D. C. Operating Reactors Branch 3 83/01/28 CLARK, R. A. Operating Reactors Branch 3 13pp 17134 164 24X Fiche 50-282, 83/01/28, 8302100185

--8302100189 Forwards Mechanical Engineering Branch positions on relief requests that remain under review in 820104 BER.
KNIGHT, J. P. Assistant Director for Core & Plant Systems 83/01/21 LATINAS, O. C. Assistant Director for Operating Reactors 4pp 17134 177 24X Fiche 50-282, 83/01/28, 8302100185

DOCKETED ITEMS

8302080144 Forwards suppl to 830128 info for review of safety evaluation methods topical rept re use of COBRA-1111/KIT to determine bounds for locked rotor & slow rod withdrawal analysis
MUSOLF, D M Northern States Power Co 83/01/31 Office of Nuclear Reactor Regulation, Director 3pp 17058 157 24X
Fiche 50-282, 83/01/31, 8302080144

8302160043 Forwards Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability Amend revises Tech Specs re steam generator tube surveillance & steam exclusion/auxiliary feedwater sys
DIAHILL, D C Operating Reactors Branch 3 83/02/02 MUSOLF, D M Northern States Power Co 3pp 17160 345 24X
Fiche 50-282, 83/02/02, 8302160043

--8302160052 Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs re steam generator tube surveillance, steam exclusion sys & auxiliary feedwater sys reporting requirements & administrative controls
CLARK, R A Operating Reactors Branch 3 83/02/02 27pp 17160 348 24X Fiche 50-282, 83/02/02, 8302160043

--8302160057 Safety evaluation supporting Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/02 14pp 17161 013 24X Fiche 50-282, 83/02/02, 8302160043

--8302160061 Notice of issuance & availability of Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively
CLARK, R A Operating Reactors Branch 3 83/02/02 2pp 17161 027 24X Fiche 50-282, 83/02/02, 8302160043

8302090415 Forwards AN-NF-79-49(P), Rev 1, "Reflex/UPI Analytical Model to Calculate Reflood Rates for PHRS W/Upper Plenum Injection, per NRC 821104 request Affidavit encl Rept withheld (ref 10CFR2 790)
MUSOLF, D Northern States Power Co 83/02/03 Office of Nuclear Reactor Regulation, Director App 17066 099 24X
Fiche 50-282, 83/02/03, 8302090415

8302150731 Notification of 830223 meeting w/util & Westinghouse in Bethesda, MD to discuss fuel assembly failure in spent fuel pool Agenda encl
DIAHILL, D C Operating Reactors Branch 3 83/02/07 CLARK, R A Operating Reactors Branch 3 3pp 17160 104 24X
Fiche 50-282, 83/02/07, 8302150731

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for CL & holders of CP for C-E PHRS re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17270 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 224 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Southern California Edison Co 31pp, 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302240334 Forwards corrected Tech Spec & Tech Spec pages omitted from Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively, issued 830202 Amends revise Tech Specs re steam generator tube surveillance & steam exclusion sys
DIAHILL, D C Operating Reactors Branch 3 83/02/15 MUSOLF, D M Northern States Power Co 3pp 17290 173 24X
Fiche 50-282, 83/02/15, 8302240334

--8302240337 Corrected Tech Specs & Tech Spec pages omitted from Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively Amends revise Tech Specs re steam generator tube surveillance & steam exclusion sys
* Office of Nuclear Reactor Regulation, Director 83/02/15 4pp 17290 175 24X Fiche 50-282, 83/02/15, 8302240334

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning GA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040032 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J G Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302050567 Forwards IE Insp Repts 50-282/82-24 & 50-306/82-24 on 821201-31 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 83/01/19, LARSON, C E Northern States Power Co 2pp 16977 077 24X
Fiche 50-282, 83/01/19, 8302050567

--8302050581 IE Insp Repts 50-282/82-24 & 50-306/82-24 on 821201-31 No noncompliance noted Major areas inspected followup of IE bulletins, safety verification, maint, surveillance, refueling activities, reactor trip & offsite review committee
FEJERABEND, C D, WILLIAMS, D L, REYES, L Division of Project & Resident Programs 83/01/10 9pp 16977 079 24X
Fiche 50-282, 83/01/19, 8302050567

8302020231 Forwards corrected Tech Spec Table 4 1-2A re ASME Code Class 1, 2 & 3 pump & valve Inservice Insp Program implementation, incorrectly issued w/830104 Amends 60 & 54 to Licenses DPR-42 & DPR-60, respectively
DIAHILL, D C Operating Reactors Branch 3 83/01/25 MUSOLF, D M Northern States Power Co 2pp 16999 190 24X
Fiche 50-282, 83/01/25, 8302020231

--8302020239 Corrected Tech Spec Table 4 1-2A re ASME Code Class 1, 2 & 3 pump & valve Inservice Insp Program implementation, incorrectly issued w/830104 Amends 60 & 54 to Licenses DPR-42 & DPR-60, respectively
* Operating Reactors Branch 3 83/01/25 1p 16999 192 24X
Fiche 50-282, 83/01/25, 8302020231

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50 94 & 50 55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302230427 Responds to Action Item 4 of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR" Exam of closure connections revealed no degradation
LARSON, C E Northern States Power Co 83/02/15, KEPPLER, J G Region 3, Office of Director, 2pp 17246 124 24X
Fiche 50-282, 83/02/15, 8302230427

8302230681 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-20 & 50-306/82-20
STREETER, J F Division of Project & Resident Programs 83/02/17 LARSON, C E Northern States Power Co, 1p 17257 332 24X
Fiche 50-282, 83/02/17, 8302230681

--8302230686 Responds to NRC 821227 ltr re violations noted in IE Insp Repts 50-282/82-20 & 50-306/82-20 Corrective actions cap on transmitter sensing line removed, lines labeled & warning signs placed
LARSON, C E Northern States Power Co 83/01/20 STREETER, J F, Division of Project & Resident Programs 2pp 17257 333 24X
Fiche 50-282, 83/02/17, 8302230681

DOCKETED ITEMS

103

B212060363 IE Info Notice B3-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice B3-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

S Reportable occurrences, LERs & related correspondence

B302040367 P&O-III-B3-007A on B30129, plant shut down to evaluate & repair 14 crack indications found in boric acid line Repair procedures being evaluated Resident inspectors monitoring activities
JACKLIN, I, DANIELSON, D, STREETER, J Region 3, Office of Director
B3/01/31 1p 17018 278 24X Fiche 50-285, 83/01/31, B302040367

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for CLS, NRS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B301310203

DOCNET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B302230575 Discusses schedule for activation of permanent emergency operations Facility Plant outage due to turbine problems delaying completion of training required to operate facility Task will be completed by B30201
JONES, W C Omaha Public Power District 83/01/07 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17256 249 24X Fiche 50-285, 83/01/07, B302230575

B302170016 Forwards IE Emergency Preparedness Appraisal Followup Rept 50-285/B2-27 on B21108-12 1 notice of violation
SEIDLE, W C Region 4, Office of Director 83/01/24 JONES, W C Omaha Public Power District 3pp 17181 304 24X Fiche 50-285, 83/01/24, B302170016

--B302170054 Notice of violation from Insp on B21108-12
Region 4, Office of Director 83/01/24 1p 17181 307 24X Fiche 50-285, 83/01/24, B302170054

--B302170061 IE Emergency Preparedness Appraisal Followup Rept 50-285/B2-27 on B21108-12 Noncompliance noted inadequate inventory of emergency plan supplies & equipment
JONES, W C, MONTGOMERY, J L, HACKNEY, C A Region 4, Office of Director 83/01/17 45pp 17181 308 24X Fiche 50-285, 83/01/24, B302170061

B302080007 Releases public version of rev to radiological emergency response plan
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17106 166 24X Fiche 50-285, 83/01/27, B302080007

--B302080010 Forwards public version of Rev 5 to radiological emergency response plan Receipt form encl
Omaha Public Power District 83/01/19 DENTON, H R NRC - No Detailed Affiliation Given 2pp 17106 167 24X Fiche 50-285, 83/01/27, B302080007

--B302080013 Public version of Rev 5 to radiological emergency response plan
Omaha Public Power District 82/12/15 56pp 17106 169 24X Fiche 50-285, 83/01/27, B302080007

B302230340 Forwards SALP Rept 50-285/B2-31 for Jul 1981 - Aug 1982
COLLINS, J T Region 4, Office of Director 83/01/27 JONES, W C Omaha Public Power District 2pp 17248 272 24X Fiche 50-285, 83/01/27, B302230340

--B302230342 Forwards SALP Rept 50-285/B2-31 for Jul 1981 - Aug 1982 Comments due by B21230
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/02 JONES, W C Omaha Public Power District 2pp 17248 274 24X Fiche 50-285, 83/01/27, B302230340

B302230349 Forwards response to SALP Rept 50-285/B2-31 for Jul 1981 - Aug 1982 Fire brigade increased to one drill for each shift per quarter, as of B20701
JONES, W C Omaha Public Power District 82/12/30 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 7pp 17248 304 24X Fiche 50-285, 83/01/27, B302230340

B301210340 Generic Ltr B3-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, B301210340

B302080271 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/02 Document Management Branch 1p 17107 268 24X Fiche 50-285, 83/02/02, B302080271

--B302080273 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-DSC-B re medical assistance & EPIP-TSC-I re activation of technical support ctr Receipt form encl
JONES, W C Omaha Public Power District 83/01/25 COLLINS, J T Region 4, Office of Director 2pp 17107 269 24X Fiche 50-285, 83/02/02, B302080271

--B302080279 Public version of revised emergency plan implementing procedures, including Procedures EPIP-DSC-B re medical assistance & EPIP-TSC-I re activation of technical support ctr
Omaha Public Power District 83/01/07 23pp 17107 271 24X Fiche 50-285, 83/02/02, B302080271

B302150087 Ack receipt of B21208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/B2-23
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/07 JONES, W C Omaha Public Power District 2pp 17146 327 24X Fiche 50-285, 83/02/07, B302150087

--B302150095 Responds to NRC B21108 ltr re violations noted in IE Insp Rept 50-285/B2-23 Corrective actions Health Physics Procedures HP-5, HP-9, HP-15 & EPIP-EDF-3 will be reviewed & revised or new procedures will be established.
JONES, W C Omaha Public Power District 82/12/08 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 7pp 17146 327 24X Fiche 50-285, 83/02/07, B302150087

B302170544 Releases public version of NRC notification of meeting w/FEMA & States of NE, KS, IA & MO in Kansas City, MO
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17197 128 24X Fiche 50-285, 83/02/15, B302170544

--B302170548 Forwards public version of notification of B30210 meeting w/FEMA, utility & States of NE, KS, IA & MO in Kansas City, MO to discuss potential generic problems involving emergency preparedness activities Agenda encl
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/26 JONES, W C Omaha Public Power District 3pp 17197 129 24X Fiche 50-285, 83/02/15, B302170544

B302220053 Releases public version of changes to radiological emergency response plan
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17234 042 24X Fiche 50-285, 83/02/15, B302220053

--B302220057 Forwards public version of changes to radiological emergency response plan W/o encl
JONES, W C Omaha Public Power District 83/01/20 COLLINS, J T Region 4, Office of Director 1p 17234 043 24X Fiche 50-285, 83/02/15, B302220053

P Operating license stage documents & correspondence

B302010030 Reviews till B11231 & B21217 responses to NUREG-0737, Item 11 K 3 28 re loss of ac power to reactor coolant pump seals integrity maint during loss of offsite power event adequately demonstrated, therefore response acceptable
CLARK, R A Operating Reactors Branch 3 83/01/17 JONES, W C Omaha Public Power District 2pp 16970 336 24X Fiche 50-285, 83/01/17, B302010030

DOCKETED ITEMS

8302010042 Informs that objectives of audit of procedures & training addressing pressurized thermal shock met. No further action re audit required.
CLARK, R A Operating Reactors Branch 3 83/01/19 JONES, W C
Omaha Public Power District 2pp 16995 075 24X
Fiche 50-285, 83/01/19, 8302010042

8302010710 Summary of 830113 meeting w/uttl & C-E in Bethesda, MD re util present status & plans concerning pressurized thermal shock.
TOURIGNY, E O Operating Reactors Branch 3 83/01/19 Operating Reactors Branch 3 28pp 16989 251 24X Fiche 50-285, 83/01/19, 8302010710

8302010415 Forwards Rev 1 to "Spent Fuel Storage Rack Mods" & responses to requests for addl info. Mods consist of elimination of Boreflay & change in rack structural design.
JONES, W C Omaha Public Power District 83/01/21 CLARK, R A
Operating Reactors Branch 3 1p 16980 067 24X
Fiche 50-285, 83/01/21, 8302010415

--8302010421 Rev 1 to "Spent Fuel Storage Rack Mods"
JONES, W C Omaha Public Power District 83/01/21 155pp
16980 068 24X Fiche 50-285, 83/01/21, 8302010415

8302010548 Forwards util plan for resolution of pressurized thermal shock issue. Planned fluence reduction measure assures that present radiographic test screening criteria for plates & axial welds will not be exceeded for 14 yrs.
JONES, W C Omaha Public Power District 83/01/26 CLARK, R A
Operating Reactors Branch 3 15pp 16979 176 24X
Fiche 50-285, 83/01/26, 8302010548

8302100296 Application to amend OL revising App J Tech Specs to incorporate Type C testing of generation M-44 & calculate max allowable leakage rate using 0.2% by weight of containment atmosphere per 24 h at 60 psig.
JONES, W C Omaha Public Power District 83/01/26 CLARK, R A
Operating Reactors Branch 3 2pp 17111 342 24X
Fiche 50-285, 83/01/26, 8302100296

--8302100301 Proposed Tech Spec rev incorporating Type C testing of generation M-44 & calculating max allowable leakage rate using 0.2% by weight of containment atmosphere per 24 h at 60 psig.
* Omaha Public Power District 83/01/26 25pp 17111 344 24X
Fiche 50-285, 83/01/26, 8302100296

8302070121 Forwards draft SER on NUREG-0737, Item II B 3, "Post-Accident Sampling Sys." Addl info requested, in order to complete review, within 60 days of draft SER receipt.
CLARK, R A Operating Reactors Branch 3 83/01/31 JONES, W C
Omaha Public Power District 102pp 17065 191 24X
Fiche 50-285, 83/01/31, 8302070121

8302080188 Advises of typographical error re exclusion area boundary thyroid dose in Section 14.14 4(7) of updated FSAR provided by 820722 ltr. Discrepancies on Figures 2 10-2 & 2 10-3 & thyroid dose will be corrected during 1983 annual update.
JONES, W C Omaha Public Power District 83/01/31 CLARK, R A
Operating Reactors Branch 3 1p 17059 007 24X
Fiche 50-285, 83/01/31, 8302080188

8302100022 Forwards request for addl info re Cycle B reload application, needed to complete review of 821122 request.
CLARK, R A Operating Reactors Branch 3 83/02/01 JONES, W C
Omaha Public Power District 4pp 17135 167 24X
Fiche 50-285, 83/02/01, 8302100022

8302100193 Forwards request for addl info needed to review util 821117 request re in-core detector string operability. Responses requested within 30 days of receipt of ltr.
CLARK, R A Operating Reactors Branch 3 83/02/02 JONES, W C
Omaha Public Power District 3pp 17134 155 24X
Fiche 50-285, 83/02/02, 8302100193

8302140194 Notification of 830217 meeting w/uttl in Bethesda, MD to discuss technical aspects of Cycle B reload application under review.
TOURIGNY, E O Operating Reactors Branch 3 83/02/02 CLARK, R A
Operating Reactors Branch 3 2pp 17145 320 24X
Fiche 50-285, 83/02/02, 8302140194

8302170439 Requests submittal, within 60 days, describing flux reduction measures initiated & addl measures being considered per pressurized thermal shock studies.
CLARK, R A Operating Reactors Branch 3 83/02/02 JONES, W C
Omaha Public Power District 3pp 17205 137 24X
Fiche 50-285, 83/02/02, 8302170439

8302150187 Application for amend to License DPR-40, changing Tech Specs re iodine spiking to replace section in 801114 application.
JONES, W C Omaha Public Power District 83/02/03 CLARK, R A
Operating Reactors Branch 3 1p 17147 180 24X
Fiche 50-285, 83/02/03, 8302150187

--8302150191 Revised proposed changes to Tech Specs lowering operating limit for radioactive iodine in RCS to 1.0 uCi/gm.
* Omaha Public Power District 83/02/03 15pp 17147 181 24X
Fiche 50-285, 83/02/03, 8302150187

8302150660 Forwards list of pages containing proprietary info in Franklin Research Ctr technical evaluation rept re electrical equipment qualification, per NRC 830111 request. Justification for withholding info provided. Affidavit encl.
JONES, W C Omaha Public Power District 83/02/04 CLARK, R A
Operating Reactors Branch 3 3pp 17150 351 24X
Fiche 50-285, 83/02/04, 8302150660

8302150695 Requests withdrawal of 821221 application to amend License DPR-40, defining max thermal power level NRC interpretation of average power level consistent w/util amend application intent. Facility within limits.
JONES, W C Omaha Public Power District 83/02/04 CLARK, R A
Operating Reactors Branch 3 1p 17150 357 24X
Fiche 50-285, 83/02/04, 8302150695

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee. Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090072 Generic Ltr 83-10B to all licensees w/C-E designed NSSS re resolution of TMI Action Item II K 3 B, "Automatic Trip of Reactor Coolant Pumps." Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consumers Power Co 32pp 17290 185 24X Fiche 50-000, 83/02/08, 8302090072

8302230576 Forwards justification for continued operation in response to 830111 ltr transmitting SER & technical evaluation rept re environ qualification of electrical equipment.
JONES, W C Omaha Public Power District 83/02/16 CLARK, R A
Operating Reactors Branch 3 4pp 17257 076 24X
Fiche 50-285, 83/02/16, 8302230576

G Inspection reports, IE Bulletins & correspondence

8302200221 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo penetration assemblies installed or planned for use at facility.
JONES, W C Omaha Public Power District 83/01/12 COLLINS, J T
Region 4, Office of Director 2pp 17233 132 24X
Fiche 50-285, 83/01/12, 8302200221

8302070589 Forwards IE Insp Rept 50-285/82-32 on 821201-31. No noncompliance noted.
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/20 JONES, W C Omaha Public Power District 2pp 17034 254 24X Fiche 50-285, 83/01/20, 8302070589

--8302070600 IE Insp Rept 50-285/82-32 on 821201-31. No noncompliance noted. Major areas inspected plant conditions during long-term shutdown, surveillance testing, maint, followup on previously identified items & NUREG-0737 items.
VANDELL, L A, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 83/01/18 8pp 17034 256 24X
Fiche 50-285, 83/01/20, 8302070589

8302170046 Forwards IE Emergency Preparedness Appraisal Followup Rept 50-285/82-27 on 821108-12 & notice of violation.
SEIDLE, W C Region 4, Office of Director 83/01/24 JONES, W C
Omaha Public Power District 3pp 17181 304 24X
Fiche 50-285, 83/01/24, 8302170046

--8302170054 Notice of violation from insp on 821108-12.
* Region 4, Office of Director 83/01/24 1p 17181 307 24X
Fiche 50-285, 83/01/24, 8302170046

--B302170061 IE Emergency Preparedness Appraisal Followup Rept 50-285/82-27 on B21108-12 Noncompliance noted inadequate inventory of emergency plan supplies & equipment
JOHNSON, W D , LONTGOMERY, J L , HACKNEY, C A Region 4, Office of Director 83/01/17 45pp 17181 308 24X Fiche 50-285, 83/01/24, B302170046

B212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B302230340 Forwards SALP Rept 50-285/82-31 for Jul 1981 - Aug 1982
COLLINS, J T Region 4, Office of Director 83/01/27 JONES, W C Omaha Public Power District 2pp 17248 272 24X Fiche 50-285, 83/01/27, B302230340

--B302230342 Forwards SALP Rept 50-285/82-31 for Jul 1981 - Aug 1982
Comments due by 821230
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/02 JONES, W C Omaha Public Power District 2pp 17248 274 24X Fiche 50-285, 83/01/27, B302230340

--B302230346 SALP Rept 50-285/82-31 for Jul 1981 - Aug 1982 Overall safety performance satisfactory
JOHNSON, W D , SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/02 28pp 17248 276 24X Fiche 50-285, 83/01/27, B302230340

B302230349 Forwards response to SALP Rept 50-285/82-31 for Jul 1981 - Aug 1982 Fire brigade increased to one drill for each shift per quarter, as of 820701
JONES, W C Omaha Public Power District 82/12/30 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 7pp 17248 304 24X Fiche 50-285, 83/01/27, B302230340

B212060360 IE Info Notice 83-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17141 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

B302070408 Provides results of confirmatory measurements on effluent radwaste samples collected during IE insp in Oct 1982, but not reported in IE Insp Rept 50-285/82-21 Documentation will appear in next confirmatory measurements insp rept
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/31 JONES, W C Omaha Public Power District 2pp 17029 256 24X Fiche 50-285, 83/01/31, B302070408

B302090583 Advises that response to IE Bulletin 80-11 & B30107 request for addl info re design criteria of masonry walls will be submitted by 830415
JONES, W C Omaha Public Power District 83/02/04 CLARK, R A Operating Reactors Branch 3 1p 17071 086 24X Fiche 50-285, 83/02/04, B302090583

B302150087 Ack receipt of B21208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/82-23
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/07 JONES, W C Omaha Public Power District 2pp 17146 327 24X Fiche 50-285, 83/02/07, B302150087

--B302150095 Responds to NRC B21108 ltr re violations noted in IE Insp Rept 50-285/82-23 Corrective actions Health Physics Procedures HP-5, HP-9, HP-15 & EPIP-EOP-3 will be reviewed & revised or new procedures will be established
JONES, W C Omaha Public Power District 82/12/08 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 7pp 17146 327 24X Fiche 50-285, 83/02/07, B302150087

B302230591 Notifies that program instituted to provide insp rept of vendors used at facilities Program assures notification of insp results Sample ticket used to flag significant problems encl Ack or receipt of rept requested on encl ticket
COLLINS, J T Region 4, Office of Director 83/02/16 JONES, W C Omaha Public Power District 3pp 17256 119 24X Fiche 50-285, 83/02/16, B302230591

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

R Periodic operating reports & related correspondence

B302220164 Forwards monthly operating rept for Jan 1983
JONES, W C Omaha Public Power District 83/02/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 17233 162 24X Fiche 50-285, 83/02/10, B302220164

--B302220168 Monthly operating rept for Jan 1983
MATTHEWS, T P , GATES, W G Omaha Public Power District 83/02/04 8pp 17233 163 24X Fiche 50-285, 83/02/10, B302220164

S Reportable occurrences, LERs & related correspondence

B302160258 PNO-IV-82-045A estimates indicate 4 to 5 wks needed for turbine repairs Refueling will commence immediately instead of on 830104
JOHNSON, W D , YANDELL, L A Region 4, Office of Director 82/12/07 1p 17170 238 24X Fiche 50-285, 82/12/07, B302160258

B302280378 Forwards LER 83-001/03L-0
JONES, W C Omaha Public Power District 83/02/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17309 240 24X Fiche 50-285, 83/02/18, B302280378

--B302280385 LER 83-001/03L-0 on 830119, during refueling outage, setpoint for one pressurizer code safety relief valve found beyond Tech Specs Caused by instrument drift Valve readjusted
ABEL, S L Omaha Public Power District 83/02/18 Region 4, Office of Director 4pp 17309 241 24X Fiche 50-285, 83/02/18, B302280378

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B301310203

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B302070341 Forwards IE Insp Rept 50-286/82-25 on B21216-B30115 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/24, IRONS, J C Power Authority of the State of New York 2pp 17029 310 24X Fiche 50-286, 83/01/24, B302070341

--B302070345 Notice of violation from Insp on B21216-B30115
* Division of Project & Resident Programs 83/01/24 1p 17029 312 24X Fiche 50-286, 83/01/24, B302070341

--B302070348 IE Insp Rept 50-286/82-23 on B21216-B30115 Noncompliance noted fire protection sys inoperable & failure to maintain transient log & details
KENNY, T J , KISTER, H Division of Project & Resident Programs 83/01/19 7pp 17029 313 24X Fiche 50-286, 83/01/24, B302070341

B302030424 Responds to B21202 request for info re emergency operations facility & alternate emergency operations facility (AEOP), Interim AEOP located approx 16 miles from facility
BAYNE, J P Power Authority of the State of New York 83/01/26, VARGAS, S A Operating Reactors Branch 1 2pp 17005 144 24X Fiche 50-286, 83/01/26, B302030424

B302080431 Board Notification 83-7 forwards testimony re emergency planning & accident consequences W/o encl
EISENHUT, D G Division of Licensing 83/01/26 PALLADINO, N J , OLSINSKY, V , HEARNE, J F Commissioners 9pp 17074 318 24X Fiche 50-247, 83/01/26, B302080431

DOCKETED ITEMS

830210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for GL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 830210340

830216005 Apprises NRC of current status of pre-exercise activities associated w/830309 exercise
THOMAS, L M Federal Emergency Management Agency 83/02/07
DIRCKS, W J Office of the Executive Director for Operations 3pp
17160 333 24X Fiche 50-247, 83/02/07, 830216005

8302230541 Forwards IE Safeguards Insp Rept 50-286/82-24 on 821213-17 & notice of violation Notice of violation withheld (ref 10CFR73 21)
MARTIN, T Division of Engineering & Technical Programs 83/02/08
BRUNS, J C Power Authority of the State of New York 2pp
17256 257 24X Fiche 50-286, 83/02/08, 8302230541

--8302230549 IE Safeguards Insp Rept 50-286/82-24 on 821213-17 Noncompliance noted failure to maintain documentation of personnel background screening Safeguards info deleted (ref 10CFR73 21)
MCKEOWN, L M, BAILEY, R J, ODDY, A T Region 1, Office of Director 83/02/08 4pp 17256 259 24X Fiche 50-286, 83/02/08, 8302230541

8302230445 Responds to NRC 830113 ltr re interim fire protection measures for facility Installation of equipment to provide permanent alternate power supply to listed pumps will be completed by end of current refueling outage
BAYNE, J P Power Authority of the State of New York 83/02/16
VARGA, S A Operating Reactors Branch 1 2pp 17246 073 24X
Fiche 50-286, 83/02/16, 8302230445

0 Adjudicatory correspondence

8302010604 Response to ASLB 830107 Memorandum & Order reformulating contentions under Commission Questions 3 & 4 Requests reconsideration of Order to reinstate Contentions 3, 2, 4, 5 & 4 & Certificate of Svc encl
HOLT, J Public Interest Research Group, New York 83/01/24
Atomic Safety and Licensing Board Panel 9pp 16978 172 24X
Fiche 50-247, 83/01/24, 8302010604

8302010517 Requests proposals for fair & efficient method for presenting intervenor, NRC & licensee testimony on Commission Questions 3 & 4 within 3-week period Proposals must be received by 830207 Svc list encl
GLEASON, J P Atomic Safety and Licensing Board Panel 83/01/28
HOLT, J Public Interest Research Group, New York BLUM, J M Union of Concerned Scientists MAIKISH, C J Port Authority of New York & New Jersey 4pp 16977 294 24X Fiche 50-247, 83/01/28, 8302010517

8302020345 Advises that Amend 1 to Probabilistic Safety Study sent to NRC Two copies will be transmitted to ASLB Copy to be sent directly to Judge Hill Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/01/28 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 1p 16993 347 24X Fiche 50-247, 83/01/28, 8302020345

8302020254 Proposed schedule for Question 1 testimony Testimony should be organized by substantive issues & ASLB questions Careful monitoring of length of cross-examination for each panel needed to ensure meeting schedule Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/01/31 9pp 16994 273 24X
Fiche: 50-247, 83/01/31, 8302020254

8302030164 Motion for expedited order compelling production of documents relied on by C Perrow in testimony for Friends of the Earth/NY City Audubon Soc on Commission Question 1
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/01 Atomic Safety and Licensing Board Panel 2pp 17002 010 24X Fiche 50-247, 83/02/01, 8302030164

--8302030175 Memorandum supporting licensee motion for expedited order compelling production of documents relied on by C Perrow in testimony Licensees entitled to any notes & draft manuscript chapters Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/01 Atomic Safety and Licensing Board Panel 19pp 17002 012 24X
Fiche: 50-247, 83/02/01, 8302030164

8302070496 Order rescinding ASLB 830121 order appointing EE Hill as special assistant to ASLB per 10CFR2 722(a)(1)
GLEASON, J P Atomic Safety and Licensing Board Panel 83/02/02
1p 17036 316 24X Fiche 50-247, 83/02/02, 8302070496

--8302070508 Notice of withdrawal of appearance in proceeding due to possible conflicts of interest
HILL, E E Atomic Safety and Licensing Board Panel 83/02/02 1p
17036 317 24X Fiche 50-247, 83/02/02, 8302070496

8302070527 Order declining review of Director's Decision DD-82-12 which denied UCS 820834 petition for immediate shutdown due to emergency preparedness deficiencies Commissioner Decision
CLL-82-3B represents Commission views on issue
CHILK, S J Office of the Secretary of the Commission 83/02/02
Office of Nuclear Reactor Regulation, Director 2pp 17035 254
24X Fiche 50-247, 83/02/02, 8302070527

8302070559 Forwards Amend 1 to probabilistic safety study Weatherwax correlating copy of Amend 1 forwarded separately Requests info re photocopying study in violation of encl agreement W/o amend Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/02 BLUM, J M New York Univ 3pp 17035 212 24X Fiche 50-247, 83/02/02, 8302070559

8302080003 Proposal for receiving evidence on Commission Questions 3 & 4, in response to ASLB 830128 mailgram Licensee witnesses should be scheduled early Intervenor should be required to designate representative witnesses Certificate of Svc encl
HASSELL, D F Hearing Branch 1 83/02/04 6pp 17058 312 24X
Fiche 50-247, 83/02/04, 8302080003

8302080225 Responds to 830128 request for hearing schedule Total time for cross-examination of State of NY witnesses should be limited to 6.5 h
FEINBERG, J D New York, State of, Energy Office 83/02/04
GLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 17057 260 24X Fiche 50-247, 83/02/04, 8302080225

8302090234 Memorandum & order formulating final contentions on Commission Questions 3 & 4
GLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 83/02/07 27pp 17070 176 24X Fiche 50-247, 83/02/07, 8302090234

8302090244 Memorandum & order granting NY City Council 830114 request that council witnesses be scheduled during wk of 830301 in NY City
GLEASON, J P Atomic Safety and Licensing Board Panel 83/02/07
New York, NY 2pp 17070 249 24X Fiche 50-247, 83/02/07, 8302090244

8302090449 Responds to request for documents SC Sholly inspected & copied at NRC ofcs on 821214 Cost of copying documents given
MOORE, J E Hearing Branch 1 83/02/07 COLARULLI, P F Morgan Associates 1p 17066 286 24X Fiche 50-247, 83/02/07, 8302090449

8302090454 Advises of charges for copying documents re SC Sholly request for documents
MOORE, J E Hearing Branch 1 83/02/07 WEISS, E R Harmon & Weiss 1p 17066 242 24X Fiche 50-247, 83/02/07, 8302090454

8302160271 Motion for order striking parts of JF Meyer & H Trevor testimony re use of glow plugs, passive heat removal & core retention sys Raising such features after completion of Question 2 record prejudices utils Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc
MORGAN, C Power Authority of the State of New York
MORGAN, C Morgan Associates 83/02/07 Atomic Safety and Licensing Board Panel 8pp 17167 295 24X Fiche 50-247, 83/02/07, 8302160271

8302160324 Motion for order establishing schedule for witnesses under Commission Questions 3 & 4, limiting scope of testimony to be presented by NY City Council re ingestion emergency planning zone II/Certificate of Svc
MORGAN, C Power Authority of the State of New York
MORGAN, C Morgan Associates 83/02/07 Atomic Safety and Licensing Board Panel 12pp 17166 228 24X Fiche 50-247, 83/02/07, 8302160324

8302160366 Proposal for fair & efficient method for receiving evidence on Commission Questions 3 & 4, in response to ASLB 830129 mailgram
POSNER, P Parents Concerned About Indian Point HOLT, J Public Interest Research Group, New York 83/02/07 10pp 17166 186 24X
Fiche 50-247, 83/02/07, 8302160366

8302160367 Proposal for scheduling remaining testimony on Commission Questions 3 & 4, per ASLB 830128 mailgram Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc 83/02/07
16pp 17164 129 24X Fiche 50-247, 83/02/07, 8302160367

8302160379 Motion to modify schedule of ASLB hearings on Commission Question 1 Proposed nods would change order of consequence analysis testimony & intervenor testimony on PRA theory & methodology Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/07 GLEASON, J P ,
SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 8pp
17161 263 24X Fiche 50-247, 83/02/07, 8302160379

8302160386 Response in opposition to licensee 830201 motion to compel production of unpublished & unrevised manuscripts of witness C Perrow Documents of proprietary nature Publication against public interest
HARTZMAN, R M Friends of the Earth HARTZMAN, R M Audubon Society
83/02/08 Atomic Safety and Licensing Board Panel 1p
17170 224 24X Fiche 50-247, 83/02/08, 8302160386

--8302160311 Memorandum in opposition to licensee 830201 motion to compel production of documents of witness C Perrow Matis consist of unrevised rough drafts of work in progress & are not yet ready for disclosure Info of proprietary nature
HARTZMAN, R M Friends of the Earth 83/02/08 Atomic Safety and Licensing Board Panel 4pp 17170 225 24X
Fiche 50-247, 83/02/08, 8302160386

--8302160318 Affirmation in opposition to licensee 830201 motion for expedited order compelling production of witness C Perrow documents No portion of witness testimony draws upon draft manuscript info
HARTZMAN, R M Friends of the Earth 83/02/08 2pp 17170 229
24X Fiche 50-247, 83/02/08, 8302160386

8302160384 Response in opposition to UCS/NY PIRG 830124 motion for certification of two questions re proposed contentions Questions proposed for certification do not present major questions of policy Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan Associates 83/02/08 Atomic Safety and Licensing Board Panel
14pp 17164 180 24X Fiche 50-247, 83/02/08, 8302160384

8302160278 Motion to strike DN Pisello, RO Piccioni, HJ Gelger & VW Sidel prefiled testimony under Commission Question 1 & renewed motion to strike B Palenik & J Beyea testimony under Commission Questions 3 & 4 Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/09 Atomic Safety and Licensing Board Panel 11pp 17169 164 24X Fiche 50-247, 83/02/09, 8302160278

8302160372 Opposition to UCS/NY PIRG 830207 motion to strike testimony of B Cohen Allegation that Cohen testimony is subjective unfounded Certificate of Svc encl Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/09 GLEASON, J P ,
SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 4pp
17161 149 24X Fiche 50-247, 83/02/09, 8302160372

8302160385 Opposition to UCS/NY PIRG motion to strike RL DuPont testimony on Commission Question 1 Testimony addresses issues raised in testimony of other witnesses, not psychological stress issues Certificate of Svc encl
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates 83/02/09 Atomic Safety and Licensing Board Panel 8pp 17164 193 24X Fiche 50-247, 83/02/09, 8302160385

8302170079 Forwards FEMA 830207 ltr to NRC advising of current status of pre-exercise activities for 830209 scheduled emergency planning exercise
HASSELL, D F Hearing Branch 1 83/02/16 GLEASON, J P , SHON, F J ,
PARIS, O H Atomic Safety and Licensing Board Panel 1p 17183 015
24X Fiche 50-247, 83/02/16, 8302170079

8302220393 Mailgram order appointing JA Laurensen as alternate ASLB member to make recommendations to ASLB re fair & efficient method for receiving evidence on Commission Questions 3 & 4
GLEASON, J P , PARIS, O H , SHON, F J Atomic Safety and Licensing Board Panel 83/02/17 Docketing & Services Branch 2pp
17232 029 24X Fiche 50-247, 83/02/17, 8302220393

8302220345 Mailgram order scheduling 830228 conference in New York, NY re procedures for fair & efficient method for receiving evidence on Commission Questions 3 & 4
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/02/18
Docketing & Services Branch 2pp 17232 141 24X
Fiche 50-247, 83/02/18, 8302220345

8302230552 Provides list of intended witnesses for 830301 hearing
KAPLAN, C National Emergency Civil Liberties Committee 83/02/18
GLEASON, J P , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 2pp 17257 080 24X Fiche 50-247, 83/02/18, 8302230552

--8302230561 Application for issuance of subpoena directing RF Littlejohn to appear before ASLB during wk of 830228 to testify re NY City planning & preparedness for radiological emergency
KAPLAN, C National Emergency Civil Liberties Committee 83/02/17
Atomic Safety and Licensing Board Panel 2pp 17257 082 24X
Fiche 50-247, 83/02/18, 8302230552

--8302230564 Application for issuance of subpoena directing B Hard to testify before ASLB at proceeding.
KAPLAN, C National Emergency Civil Liberties Committee 83/02/17
Atomic Safety and Licensing Board Panel 1p 17257 084 24X
Fiche 50-247, 83/02/18, 8302230552

--8302230572 Response in opposition to licensee 830207 motions objecting to NY City Council member testimony re Commission Questions 3 & 4 Licensees fail to make specific objections to specific proffered witnesses Certificate of Svc encl
KAPLAN, C National Emergency Civil Liberties Committee 83/02/18
Atomic Safety and Licensing Board Panel 10pp 17257 085 24X
Fiche 50-247, 83/02/18, 8302230552

8302280275 Forwards list of documents relied upon by JF Meyer & WT Pratt in preparing direct testimony on mitigation strategy for Commission Question 1
HASSELL, D F Hearing Branch 1 83/02/18 BLUM, J H New York Univ
COLARULLI, P F Morgan Associates BRANDENBURG, B Consolidated Edison Co of New York, Inc 3pp 17313 023 24X
Fiche 50-247, 83/02/18, 8302280275

8302280163 Objection to NRC 830204 proposal for receiving evidence on Commission Questions 3 & 4 Opposes proposal to limit time of NRC witness Urbanik Certificate of Svc encl
FLEISHER, Z S West Branch Conservation Association 83/02/19 5pp
17305 319 24X Fiche 50-247, 83/02/19, 8302280163

8302280277 Motion to reinstate portion of Contention 3 2 re util workers F Fischer will testify on issue Prof qualifications encl
FLEISHER, Z S West Branch Conservation Association 83/02/19
Atomic Safety and Licensing Board Panel 3pp 17313 001 24X
Fiche 50-247, 83/02/19, 8302280277

8302240309 Suppl to NY City Council 830218 opposition to licensee motions re Council member witnesses under Commission Questions 3 & 4 Evidence re existing capability to implement relocation strategy should be heard W/Certificate of Svc
KAPLAN, C New York, NY 83/02/22 Atomic Safety and Licensing Board Panel 3pp 17271 329 24X Fiche 50-247, 83/02/22, 8302240309

8302240314 Motion to permit entry upon land controlled by licensees & to allow observance of 830309 emergency planning exercise from both Units 2 & 3 control rooms & from near-site emergency operations facility
HOLT, J Public Interest Research Group, New York 83/02/22
Consolidated Edison Co of New York, Inc 3pp 17271 350 24X
Fiche 50-247, 83/02/22, 8302240314

8302250372 Motion for preservation & production of certain documents re 830309 emergency exercise Record essential to give accurate picture of any exercise evaluation results
HOLT, J Public Interest Research Group, New York 83/02/22
Atomic Safety and Licensing Board Panel 3pp 17297 048 24X
Fiche 50-247, 83/02/22, 8302250372

--8302250379 Urges reconsideration of decision not to hold any limited appearance hearings in NY City during wk of 830301-01 People should be heard
HOLT, J Public Interest Research Group, New York 83/02/21,
GLEASON, J P , PARIS, O H , SHON, F J , Atomic Safety and Licensing Board Panel 1p, 17297 051 24X Fiche 50-247, 83/02/22, 8302250372

--8302250383 Motion to permit entry on licensee controlled land to observe 830309 emergency planning exercise from control rooms & near-site emergency operations facility
HOLT, J Public Interest Research Group, New York 83/02/22
Power Authority of the State of New York 3pp 17297 052, 24X
Fiche 50-247, 83/02/22, 8302250372

8302280270 Forwards exhibits sponsored by NY State witnesses on emergency planning
FEINBERG, J D New York, State of, Energy Office, 83/02/22
GLEASON, J P , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 18pp 17311 296 24X Fiche 50-247, 83/02/22, 8302280270

DOCKETED ITEMS

8302280187 Order amending svc list to reflect change of law clerks
GLEASON, J P Atomic Safety and Licensing Board Panel 83/02/23 8302280187
1p 17306 037 24X Fiche 50-247,83/02/23,8302280187

General correspondence

8302240066 FOIA request for all prior & partial prior drafts & memos
of probabilistic safety study
BLUM, J M Union of Concerned Scientists 82/12/28 FELTON, J
Division of Rules and Records 1p 17285 001 24X
Fiche 50-286,82/12/28,8302240066

Insurance & indemnity information

8302150586 Forwards NELIA Certificate N-7 & MAELU Certificate M-7
DEFO, F H Power Authority of the State of New York 83/02/09
SALTZMAN, J Antitrust & Economic Analysis Branch (Utility Finance)
19pp 17154 001 24X Fiche 50-286,83/02/09,8302150586

Operating license stage documents & correspondence

8302240073 Partial response to FOIA request for all prior & partial
prior drafts & memos of probabilistic safety study Forwards
documents listed in app Search for addl records in progress
FELTON, J M Division of Rules and Records 83/01/13 BLUM, J M
Union of Concerned Scientists 2pp 17285 002 24X
Fiche 50-000,83/01/13,8302240073

8302240082 "Accumulator Sys," revised draft chapter for PRA
* Pickard, Lowe & Garrick, Inc 81/01/06 14pp 17285 004 24X
Fiche 50-030,83/01/13,8302240073

8302240089 "Reactor Protection Sys," revised draft chapter for PRA
* Pickard, Lowe & Garrick, Inc 81/01/06 27pp 17285 018 24X
Fiche 50-000,83/01/13,8302240073

8302240100 Rev 1 to "Reactor Protection Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/10 29pp 17285 046 24X
Fiche 50-000,83/01/13,8302240073

8302240105 Rev 1 to "Svc Water Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/10 66pp 17285 075 24X
Fiche 50-000,83/01/13,8302240073

8302240109 Rev 1 to "Auxiliary Feedwater Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 66pp 17285 141 24X
Fiche 50-000,83/01/13,8302240073

8302240113 Rev 1 to "Containment Spray Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 43pp 17285 209 24X
Fiche 50-000,83/01/13,8302240073

8302240131 Rev 1 to "Component Cooling Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 49pp 17285 232 24X
Fiche 50-000,83/01/13,8302240073

8302240138 Rev 1 to "Safeguards Actuation Sys (Safety Injection &
Containment Spray Actuation)," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 65pp 17285 300 24X
Fiche 50-000,83/01/13,8302240073

8302240144 Rev 1 to "Containment Fan Cooling (CF) Sys," draft chapter
to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 26pp 17285 004 24X
Fiche 50-000,83/01/13,8302240073

8302240150 Rev 1 to "Recirculation Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 117pp 17285 033
24X Fiche 50-000,83/01/13,8302240073

8302240154 Rev 1 to "Low Pressure Injection Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 37pp 17285 150 24X
Fiche 50-000,83/01/13,8302240073

8302240167 Rev 1 to "Accumulator Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 14pp 17286 187 24X
Fiche 50-000,83/01/13,8302240073

8302240173 Rev 1 to "Electric Power Sys," draft chapter to PRA
* Pickard, Lowe & Garrick, Inc 81/04/17 226pp 17286 201,
24X Fiche 50-000,83/01/13,8302240073

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT, D G Division of Licensing 85/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000,83/01/18,8302170019

--8302170096 Package of six comments indicating adequate or inadequate
justification for continued operation re environ
qualification of electrical equipment
HAWKINS, J H, THOMA, J NRC - No Detailed Affiliation Given
82/01/27 VARGA, S NRC - No Detailed Affiliation Given 10pp
17196 225 24X Fiche 50-000,83/01/18,8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by
which technical evaluation repts are expected to be
completed Requests justification for continued operation of
each group by 821005 & 15, respectively
EISENHUT, D G Division of Licensing 82/09/24 MIRAGLIA, F
Assistant Director for Safety Assessment 4pp 17196 263 24X
Fiche 50-000,83/01/18,8302170019

--8302170256 Concludes that licensee justification for continued
operation until completion of environ qualification program
acceptable based on review
THOMA, J Operating Reactors Branch 1 82/10/28 EISENHUT, D G
Division of Licensing 4pp 17197 044 24X Fiche 50-000,
83/01/18,8302170019

8302240188 Addl response to FOIA request for all prior draft & partial
drafts of probabilistic safety study & all memos pertaining
to drafts Documents available in PDR w/exception of Israel
to Hickman 831105 1tr
FELTON, J M Division of Rules and Records 83/01/20 BLUM, J M
Union of Concerned Scientists 1p 17285 302 24X
Fiche 50-286,83/01/20,8302240188

8302030323 Discusses proprietary info status of Franklin Research Ctr
Technical Evaluation Rept, "Environ Qualification of
Safety-Related Electrical Equipment" Specific rationale &
justification for proprietary status forthcoming
BAYNE, J P Power Authority of the State of New York 83/01/28
VARGA, S A Operating Reactors Branch 1 2pp 17001 276 24X
Fiche 50-286,83/01/28,8302030323

8302170306 Notification of contract execution "Indian Point Testimony
of External Events," awarded to Future Resources Assoc, Inc
HOPPER, A M Administrative Contracts Branch FIN 8-8641 83/02/02
DENTON, H R Office of Nuclear Reactor Regulation, Director
SULLIVAN, E NRC - No Detailed Affiliation Given 1p 17207 326
24X Fiche 50-247,83/02/02,8302170306

--8302170310 Contract "Indian Point Testimony of External Events,"
awarded to Future Resources Assoc, Inc
BUDNITZ, R J Future Resources Associates, Inc REBELLO, J E
Division of Contracts FIN 8-8641 83/02/02 5pp 17207 327
24X Fiche 50-247,83/02/02,8302170306

8302080218 Forwards responses to 821223 request for addl info re
masonry wall design Tornado loads not considered in wall
analysis Composite action not assumed in analysis to qualify
multi wythe block walls
BAYNE, J P Power Authority of the State of New York 83/02/04
VARGA, S A Operating Reactors Branch 1 5pp 17057 269 24X
Fiche 50-286,83/02/04,8302080218

8302150349 Provides update of containment bldg seismic capacity,
including seismic reanalysis of Unit 2 containment bldg
fragilities Reanalysis results indicate possibility of
containment failure due to seismic event eliminated
BAYNE, J P Power Authority of the State of New York Q'TODLE, J D
Consolidated Edison Co of New York, Inc 83/02/04 VARGA, S A
Operating Reactors Branch 1 9pp 17157 246 24X
Fiche 50-247,83/02/04,8302150349

8302150421 Forwards "Sys Interaction Study of Auxiliary Feedwater Sys,
Indian Point 3," in response to NRC 821202 ltr Schedule for
seismic qualification of auxiliary feedwater sys encl
BAYNE, J P Power Authority of the State of New York 83/02/07
VARGA, S A Operating Reactors Branch 1 7pp 17148 059 24X
Fiche 50-286,83/02/07,8302150421

--8302150424 'Sys Interaction Study of Auxiliary Feedwater Sys, Indian
Point 3 "
* Pickard, Lowe & Garrick, Inc 83/01/31 32pp 17148 066 24X
Fiche 50-286,83/02/07,8302150421

8302150740 Requests more definitive cause & evaluation of Tech Spec
amend request for surveillance of girth welds Response
requested within 30 days
VARGA, S A Operating Reactors Branch 1 83/02/07 BINCLAIR, L W
Power Authority of the State of New York 2pp 17160.052 24X
Fiche 50-286,83/02/07,8302150740

8302170436 Notices that re-evaluations of small-break LOCA & non-LOCA transients & accidents required in order to complete review of 830113 request for license amend Submittal requested within 2 wks
VARQA, S A Operating Reactors Branch 1 83/02/07 SINCLAIR, L W
Power Authority of the State of New York 2pp 17205 142 24X
Fiche 50-286, 83/02/07, 8302170436

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302240204 Forwards request for addl info re demonstration of operability of containment purge & vent valves against accident containment pressures Response expected by 830501
VARQA, S A Operating Reactors Branch 1 83/02/08 SINCLAIR, L W
Power Authority of the State of New York 4pp 17288 243 24X
Fiche 50-286, 83/02/08, 8302240204

8302180108 Forwards addl info re degraded grid protection for Class IE power sys. per NRC 820929 ltr
BAYNE, J P Power Authority of the State of New York 83/02/10
VARQA, S A Operating Reactors Branch 1 7pp 17216 193 24X
Fiche 50-286, 83/02/10, 8302180108

8302240183 Requests info obtained in 820922 telcon re masonry wall design be formally provided
VARQA, S A Operating Reactors Branch 1 83/02/11 SINCLAIR, L W
Power Authority of the State of New York 3pp, 17288, 255 24X
Fiche 50-286, 83/02/11, 8302240183

8302230282 Suppl previously submitted info re NUREG-0737, Items I A 1 3 1, I A 1 3 2, II B 2, II D 1 2, II F 1 1, II F 1 4 & III D 3 4
BAYNE, J P Power Authority of the State of New York 83/02/15
EISENHUT, D G Division of Licensing App. 17242 326 24X
Fiche 50-286, 83/02/15, 8302230282

8302230482 Comments on draft value impact analysis re proposed steam generator generic requirements Cost of condenser retubing, condensate polisher installation & copper bearing component replacement in feedtrain must be considered
BAYNE, J P Power Authority of the State of New York 83/02/15
EISENHUT, D G Division of Licensing 2pp 17257 071 24X
Fiche 50-000, 83/02/15, 8302230482

G. Inspection reports, IE Bulletins & correspondence

8302030584 Forwards IE Insp Rept 50-286/82-26 on 821220-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs, 83/01/21
BROWN, J C Power Authority of the State of New York 2pp
17007 356 24X Fiche 50-286, 83/01/21, 8302030584

--8302030591 IE Insp Rept 50-286/82-26 on 821220-22, No noncompliance noted, Major areas inspected: status of failure analysis & repair procedure for cracked upper shell to transition cone closure weld on four steam generators.
REYNOLDS, S D, DURR, J Division of Engineering & Technical Programs 83/11/19 6pp 17007 358 24X Fiche 50-286, 83/01/21, 8302030584

8302030084 Responds to Item 5a of IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Electrical penetrations supplied by Bunker-Ramo Co have not been nor will be installed
BROWN, J C Power Authority of the State of New York 83/01/24
HAYNES, R C Region I, Office of Director, 1p 17002, 225 24X
Fiche 50-286, 83/01/24, 8302030084

8302070341 Forwards IE Insp Rept 50-286/82-25 on 821216-830115 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/24
BROWN, J C Power Authority of the State of New York 2pp
17029 310 24X Fiche 50-286, 83/01/24, 8302070341

--8302070345 Notice of violation from insp on 821216-830115
* Division of Project & Resident Programs 83/01/24 1p
17029 312 24X Fiche 50-286, 83/01/24, 8302070341

--8302070348 IE Insp Rept 50-286/82-25 on 821216-830115 Noncompliance noted fire protection sys inoperable & failure to maintain transient log & details
KEANEY, T J, KISTER, H Division of Project & Resident Programs
83/01/19 9pp 17029 313 24X Fiche 50-286, 83/01/24, 8302070341

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095, 24X Fiche 50-000, 83/01/28, 8212060361

8302040243 Requests escorted visitor access for RJ Budnitz to visit site on 830210 Escort will be T Kenny, NRC resident inspector
VARQA, S A Operating Reactors Branch 1 83/01/31 SINCLAIR, L W
Power Authority of the State of New York 2pp 17042 351 24X
Fiche 50-286, 83/01/31, 8302040243

8302230341 Forwards IE Safeguards Insp Rept 50-286/82-24 on 821213-17 & notice of violation Notice of violation withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 83/02/08
BROWN, J C Power Authority of the State of New York 2pp,
17254 257 24X Fiche 50-286, 83/02/08, 8302230341

--8302230349 IE Safeguards Insp Rept 50-286/82-24 on 821213-17 Noncompliance noted failure to maintain documentation of personnel background screening Safeguards info deleted (ref 10CFR73 21)
MCKEOWN, L M, BAILEY, R J, ODDY, A T. Region I, Office of Director
83/02/08 4pp 17254 259 24X Fiche 50-286, 83/02/08, 8302230341

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

T Hearing transcripts on non-antitrust matters

8302020424 Unofficial transcript of Commission 830127 affirmation/discussion & vote in Washington, DC re BECY-82-490A Pp 1-3
* Commissioners, 83/01/27 3pp 16977 311 24X
Fiche 50-247, 83/01/27, 8302020424

8302010530 Forwards set of tables completing app to licensee testimony of WR Stratton, WA Rodger & TE Potter on Commission Question 1.
BRANDENBURG, B Consolidated Edison Co. of New York, Inc
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F, Morgan Associates 83/01/28 OLEASON, J P Atomic
Safety and Licensing Board Panel 1p, 16977 125 24X
Fiche 50-247, 83/01/28, 8302010530

DOCKETED ITEMS

--B302010536 Set of tables completing app to licensee testimony of WR Stratton, WA Rodger & TE Potter on Commission Question 1
* Consolidated Edison Co of New York, Inc * Power Authority of the State of New York 83/01/28 6pp 16977 126 24X
Fiche 50-247, 83/01/28, 8302010530

B302030165 Testimony of DM Pisello & RG Piccioni Several possible scenarios illustrating implications of long-term environ contamination following serious reactor accident presented
Pro qualifications encl
PISELLO, D M, PICCIONI, R G Friends of the Earth PISELLO, D M New York City Audubon Society 83/01/31 29pp 17008 050 24X
Fiche 50-247, 83/01/31, 8302030165

B302030184 Testimony of C Perrow Nuclear power plant production sys characteristics force inevitable conclusion that serious accidents will occur which design engineers could not anticipate & which operators cannot avoid
PERROW, C Friends of the Earth PERROW, C New York City Audubon Society PERROW, C Yale Univ 83/01/31 15pp 17002 104 24X
Fiche 50-247, 83/01/31, 8302030184

B302030199 Testimony of HJ Geiger & VW Sidel Formulating adequate medical care response to major radiological release impossible since scenario consequences variable Prof qualifications encl
GEIGER, H J, SIDEL, V W Friends of the Earth GEIGER, H J New York City Audubon Society 83/01/31 54pp 17004 233 24X
Fiche 50-247, 83/01/31, 8302030199

B302030210 Testimony of I Levi that methodology in probabilistic safety study for making probabilistic assessments inadequate to justify reposing confidence in Study assessments Prof qualifications encl
LEVI, I Friends of the Earth LEVI, I New York City Audubon Society 83/01/31 83pp 17001 107 24X Fiche 50-247, 83/01/31, 8302030210

B302030539 Forwards corrected pages to 830126 direct testimony of JF Meyer & WF Pratt re Question 1 concerning risk reduction values for filtered vented containment sys & separate containment vent vol
MOORE, J E Hearing Branch 1 83/02/02 GLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17007 195 24X Fiche 50-247, 83/02/02, 8302030539

--B302030546 Corrected testimony of JF Meyer & WF Pratt on Commission Question 1 re risk reduction values for filtered vented containment sys & separate containment vent vol
MEYER, J F, PRATT, W T NRC - No Detailed Affiliation Given 83/02/02 4pp 17007 156 24X Fiche 50-247, 83/02/02, 8302030539

B302090224 Forwards errata to licensee testimony on Commission Question 1, Contention 1 i & ASLB Question 1 i
BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/06 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 1p 17070 276 24X Fiche 50-247, 83/02/06, 8302090224

--B302090230 Errata to licensee testimony on Commission Question 1, Contention 1 i & ASLB Question 1 i
* Consolidated Edison Co of New York, Inc * Power Authority of the State of New York 83/02/06 3pp 17070 277 24X
Fiche 50-247, 83/02/06, 8302090224

B302090272 Testimony of SC Sholly re Commission Question 1 & ASLB Question 1 i on consequences of accidents at plants
Consequence Model CRACIT & application to calculation of consequences of accidents discussed w/prof qualifications
SHOLLY, S C Union of Concerned Scientists SHOLLY, S C Public Interest Research Group, New York 83/02/07 46pp 17070 048 24X
Fiche 50-247, 83/02/07, 8302090272

--B302090279 Testimony of RK Weatherwax on probabilistic safety study Substantial controversy surrounds completeness & accuracy of study Questions remain re sophisticated procedures used in rept. Certificate of Svc encl
WEATHERWAX, R K Union of Concerned Scientists WEATHERWAX, R K Public Interest Research Group, New York 83/02/07 24pp 17070 094 24X Fiche 50-247, 83/02/07, 8302090272

00215 Transcript of 830208 hearing in White Plains, NY Pp 6, 941-61 Supporting documentation encl
Atomic Safety and Licensing Board Panel 83/02/08 419pp
5 130 24X Fiche 50-247, 83/02/08, 8302100215

1077 Transcript of 830209 hearing in White Plains, NY Pp 7, 162-1 Supporting documentation encl
Atomic Safety and Licensing Board Panel 83/02/09 390pp.
172 24X Fiche 50-247, 83/02/09, 8302140077.

8302150705 Transcript of 830210 hearing in White Plains, NY Pp 7, 479-7, 707 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/10 355pp
17152 021 24X Fiche 50-247, 83/02/10, 8302150705

B302170277 Forwards errata to licensee testimony of TE Potter on ASLB Question 1 3
BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/10 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 1p 17178 215 24X Fiche 50-247, 83/02/10, 8302170277

--B302170280 Errata to licensee testimony of TE Potter on ASLB Question 1 3
POTTER, T E Consolidated Edison Co of New York, Inc POTTER, T F Power Authority of the State of New York 83/02/10 2pp
17178 216 24X Fiche 50-247, 83/02/10, 8302170277

B302190274 Transcript of 830211 hearing in White Plains, NY Pp 7, 710-7, 898 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/11 261pp
17149 001 24X Fiche 50-247, 83/02/11, 8302190274

B302170260 Forwards errata to licensee testimony of WR Stratton, WA Rodger & TE Potter re Question 1
BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/14 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 1p 17187 092 24X Fiche 50-247, 83/02/14, 8302170260

--B302170268 Errata to licensee testimony of WR Stratton, WA Rodger & TE Potter re Question 1
STRATTON, W R, RODGER, W A, POTTER, T E Consolidated Edison Co of New York, Inc 83/02/14 1p 17187 093 24X
Fiche 50-247, 83/02/14, 8302170260

B302170283 Forwards errata to util testimony of RL DuPont on Commission Question 1
COLARULLI, P F Power Authority of the State of New York COLARULLI, P F Morgan Associates 83/02/14 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 1p 17185 148 24X Fiche 50-247, 83/02/14, 8302170283

--B302170287 Errata to util testimony of RL DuPont on Commission Question 1
DUPONT, R L Power Authority of the State of New York 83/02/14 1p 17185 149 24X Fiche 50-247, 83/02/14, 8302170283

B302180381 Supplemental testimony of P Helbraun re ability of preschools to transport staff & children to designated areas Evacuation plan does not deal w/problem Related correspondence
HELBRAUN, P Rockland Citizens for Safe Energy 83/02/14 2pp
17209 180 24X Fiche 50-247, 83/02/14, 8302180381

--B302180384 Supplemental testimony of A Gramack re recreational programs within 10-mile emergency planning zone Certificate of Svc encl Related correspondence
GRAMACK, A Rockland Citizens for Safe Energy 83/02/14 6pp
17209 182 24X Fiche 50-247, 83/02/14, 8302180381

B302170157 Transcript of 830215 hearing in White Plains, NY Pp 7, 899-8, 172 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/15 327pp
17189 316 24X Fiche 50-247, 83/02/15, 8302170157

B302180240 Transcript of 830216 hearing in White Plains, NY Pp 8, 173-8, 461 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/16 512pp
17212 102 24X Fiche 50-247, 83/02/16, 8302180240

B302202041 Transcript of 830217 hearing in White Plains, NY Pp 8, 462-8, 688 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/17 565pp
17230 159 24X Fiche 50-247, 83/02/17, 8302202041

B302230471 Forwards supplemental testimony of NY State witnesses on Commission Questions 3 & 4 re emergency planning Related correspondence
FEINBERG, J D New York, State of 83/02/18 GLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17244 081 24X Fiche 50-247, 83/02/18, 8302230471

--B302230477 Testimony of DB Davidoff & LB Czech on Commission Questions 3 & 4 re emergency planning Related correspondence
DAVIDOFF, D B, CZECH, L B New York, State of 83/02/21 14pp
17244 082 24X Fiche 50-247, 83/02/18, 8302230471

DOCKETED ITEMS

11

- 8302230493 Transcript of 830218 hearing in White Plains, NY Pp 8, 689-8, 922 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/18 380pp
17259 221 24X Fiche 50-247, 83/02/18, 8302230683
- 8302230377 Forwards NRC & FEMA supplemental testimony on Commission Questions 3 & 4 Certificate of Svc encl
HASSELL, D F Hearing Branch 1 83/02/18 Atomic Safety and Licensing Board Panel 5pp 17309 251 24X Fiche 50-247, 83/02/18, 8302230377
- 8302280380 Supplemental testimony of JR Sears re Commission Question 3 Open items do not change conclusion that emergency plans & procedures form adequate basis for onsite preparedness
SEARS, J R EF Licensing Branch 83/02/18 4pp 17309 256 24X Fiche 50-247, 83/02/18, 8302280377
- 8302280384 Forwards FEMA supplemental testimony on Commission Questions 3 & 4
GLASS, S M Federal Emergency Management Agency 83/02/14
HASSELL, D F Hearing Branch 2 1p 17309 260 24X Fiche 50-247, 83/02/18, 8302280377
- 8302280390 Supplemental testimony of P McIntire, R Kowleski & JH Keller re Commission Questions 3 & 4 Transmits rept on status of plan revs, equipment purchases & training re significant deficiencies in five planning stds identified in Jul 1982
MCINTIRE, P, KOWLESKI, R, KELLER, J H Federal Emergency Management Agency 83/02/14 39pp 17309 261 24X Fiche 50-247, 83/02/18, 8302280377
- 8302240320 Supplemental testimony of LA Cohen, CW Jackson, G Liebler & WA Monti re onsite emergency planning Discusses recent enhancements to alert/notification & backup communication sys Certificate of Svc encl Related correspondence
COHEN, L A, JACKSON, C W, LIEBLER, G Consolidated Edison Co of New York, Inc 83/02/22 9pp 17274 001 24X Fiche 50-247, 83/02/22, 8302240320
- 8302250372 Motion for preservation & production of certain documents re 830309 emergency exercise Record essential to give accurate picture of any exercise evaluation results.
HGLT, J Public Interest Research Group, New York 83/02/22
Atomic Safety and Licensing Board Panel 3pp 17297 048 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250397 Forwards R Seasonwein testimony on Commission Question 3 re emergency planning
BRODSKY, R L New York, State of 83/02/21 GLEASON, J P, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 17297 055 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250392 Testimony of R Seasonwein on Commission Question 3 re emergency planning Large portion of population will comply if ordered to stay in homes during emergency Chaos could prevail if evacuation ordered
SEASONWEIN, R New York, State of 83/02/21 24pp 17297 056 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250396 Supplemental testimony of SW Anderson re considerations for planning evacuation of handicapped persons Accessible bus survey encl
ANDERSON, S W Union of Concerned Scientists ANDERSON, S W Public Interest Research Group, New York ANDERSON, S W Westchester Peoples Action Coalition, Inc 83/02/21 10pp 17297 074 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250397 Testimony of C Awalt re evacuation of mentally retarded patients in homes Neither of or homes contacted re emergency planning for nuclear accident
AWALT, C Parents Concerned About Indian Point AWALT, C Westchester Peoples Action Coalition, Inc 83/02/18 2pp 17297 084 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250405 Supplemental testimony of WT Erikson re emergency studies Emergency plans inadequate unless number of people who will overreact & number of emergency personnel who will not rept to duty are taken into account
ERIKSON, K T Parents Concerned About Indian Point ERIKSON, K T Union of Concerned Scientists ERIKSON, K T Public Interest Research Group, New York 83/02/21 4pp 17297 086 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250410 Testimony of S Hall Transport Workers Union has not been involved in any evacuation plan
HALL, S Parents Concerned About Indian Point HALL, S Union of Concerned Scientists HALL, S Public Interest Research Group, New York 83/02/17 1p 17297 090 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250416 Testimony of JF Roden re inadequacy of procedures re Westchester portion of 10-mile evacuation area & personnel use Roads cannot handle traffic Parents will not cooperate w/evacuation of children
RODEN, J F Parents Concerned About Indian Point 83/02/17 5pp 17297 091 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250419 Testimony of A Cormican re evacuation of school children
CORMICAN, A Parents Concerned About Indian Point 83/02/17 6pp 17297 096 24X Fiche 50-247, 83/02/22, 8302250372
- 8302250425 Testimony of J Murphy Present emergency planning seriously deficient because plan does not prepare for exposure levels exceeding 100 rems or for internal contamination Certificate of Svc encl
MURPHY, J Union of Concerned Scientists MURPHY, J Public Interest Research Group, New York 83/02/21 93pp 17297, 102 24X Fiche 50-247, 83/02/22, 8302250372
- 8302280160 Supplemental testimony of MS Della Rocca, BE Podwal & PL Rosenblatt re emergency planning Relationship of plan to existing procedures & facilities, communication w/officials & evacuation routes discussed w/Certificate of Svc
DELLA ROCCA, M, PODWAL, B E, ROSENBLATT, P L Consolidated Edison Co of New York, Inc 83/02/22 24pp 17306 008 24X Fiche 50-247, 83/02/22, 8302280160
- 8302250235 Forwards corrected 830125 testimony of WH Spataro, Pp 6, 551-53 & 6, 559
LEVINE, J J Morgan Associates LEVINE, J J Power Authority of the State of New York 83/02/23 GLEASON, J P, SHON, F J, PARRIS, O H Atomic Safety and Licensing Board Panel 1p 17292 342 24X Fiche 50-247, 83/02/23, 8302250235
- 8302250240 Corrected 830125 testimony of WH Spataro, Pp 6, 551-53 & 6, 559
SPATARD, W H Power Authority of the State of New York 83/02/23 4pp 17292 343 24X Fiche 50-247, 83/02/23, 8302250235
- 8302280093 Transcript of 830224 telephone conference in Washington, DC Pp 8, 823-8, 858
* Atomic Safety and Licensing Board Panel 83/02/24 39pp 17307 138 24X Fiche 50-247, 83/02/24, 8302280093
- 8302280249 Transcript of 830224 telephone conference in Washington, DC Pp 8, 923-8, 958
* Atomic Safety and Licensing Board Panel 83/02/24 36pp 17304 276 24X Fiche 50-247, 83/02/24, 8302280249
- U Congressional/Executive Correspondence

- 8302020283 Comments on NUREG-0880 re NRC policy statement on safety goals Commission should explain basis for CLI-82-38 assumption that plant poses no undue risk to public health & safety even though plant does not meet safety goal
OTTINGER, R L House of Rep 83/01/19 PALLADINO, N J Commissioners 2pp 16993, 318 24X Fiche 50-266, 83/01/19, 8302020283
- V Operator Examinations

- 8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, HSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203
- DOCKET 50-287 GCONEE NUCLEAR STATION, UNIT 3

- F Security, medical, emergency & fire protection plans

- 8210120650 Releases public version of rev to emergency plan manual
FELTON, J M Division of Rules and Records 82/09/23 Document Management Branch 1p 15684 339 24X Fiche 50-269, 82/09/23, 8210120650
- 8210120652 Forwards public version of Revision 5 to emergency plan manual
TUCKER, H B Duke Power Co 82/09/14 O'REILLY, J P Region 2, Office of Director 1p 15684-340 24X Fiche 50-269, 82/09/23, 8210120650

DOCKETED ITEMS

- B210120656 Public version of revised emergency plan implementing procedures, including Procedures PT/O/B/2000/04 re establishment & insp of technical support ctr & CP/3/A/2002/05 re post-accident caustic injection into LPIS
* Duke Power Co 82/09/30 85pp 15684 341 24X
Fiche 50-269, 82/09/23, B210120650
- B210120658 Public version of Rev 5 to emergency plan
SMITH, J E Duke Power Co 82/09/01 162pp 15685 066 24X
Fiche 50-269, 82/09/23, B210120650
- B302040497 Releases public version of rev to emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/28 Document
Management Branch 1p 17046 298 24X Fiche 50-269, 83/01/28, B302040497
- B302040504 Forwards public version of Rev 7 to emergency plan & Rev 11 to emergency plan implementing procedures Receipt forms encl
TUCKER, H B, MCINTOSH, J T Duke Power Co 83/01/07
O'REILLY, J P Region 2, Office of Director OLOVER, R M Office of Nuclear Reactor Regulation, Director 3pp. 17046 299 24X
Fiche 50-269, 83/01/28, B302040497
- B302040506 Public version of Rev 7 to emergency plan
SMITH, J E Duke Power Co 82/12/14 16pp 17046 302 24X
Fiche 50-269, 83/01/28, B302040497
- B302040511 Public version of revised emergency plan implementing procedures, including Procedure AP/O/B/1000/07 re offsite dose calculations by control room personnel or emergency coordinator during LOCA
CAMPBELL, J, EDWARDS, N Duke Power Co 82/12/09 46pp 17046 322 24X Fiche 50-269, 83/01/28, B302040497
- B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements For Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340
- B302220052 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records. 83/02/14 Document
Management Branch 1p 17233 324 24X Fiche 50-269, 83/02/14, B302220052
- B302220055 Forwards public version of Rev 83-1 to emergency plan implementing procedures, including Procedure CP/O/B/2003/02 re estimate of failed fuel based on I-131 concentration
Receipt form encl
TUCKER, H B Duke Power Co 83/01/27 O'REILLY, J P Region 2, Office of Director 2pp 17233 325 24X Fiche 50-269, 83/02/14, B302220052
- B302220059 Public version of Rev 83-1 to emergency plan implementing procedures, including Procedure CP/O/B/2003/02 re estimate of failed fuel based on I-131 concentration
COY, S A Duke Power Co 83/01/10 72pp 17233 327. 24X
Fiche 50-269, 83/02/14, B302220052
- J. Insurance & Indemnity Information
- B302090413 Requests reimbursement of pro rata portion of indemnity fees paid due to termination of NRC indemnification under Price-Anderson Act on 82115
HOUBE, D R Duke Power Co 83/02/04 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance). 1p 17070-362 24X
Fiche 50-000, 83/02/04, B302090413
- P. Operating license stage documents & correspondence
- B302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at B30106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing. 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, B302170019
- B302170089 Provides justification for interim operation pending resolution of equipment qualification program
WAGNER, P. Operating Reactors Branch 4 82/03/03 NOVAK, T. Assistant Director for Operating Reactors 2pp 17196 223 24X
Fiche 50-000, 83/01/18, B302170019.
- B302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by B21038 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50 000, 83/01/18, B302170019
- B302170240 Concludes that based on licensee B20225 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
WAGNER, P C Operating Reactors Branch 4 82/10/28 EISENHUT, D O Division of Licensing 1p 17197 041 24X Fiche 50-000, 83/01/18, B302170019
- B302010498 Forwards final evaluation of pressurizer safety & relief valve piping sys, per NUREG-0737, Item II D 1 Mods to reduce piping sys stresses below FSAR spec will be performed during next refueling outage Plant safety not affected
TUCKER, H B Duke Power Co 83/01/21 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 16981 074 24X Fiche 50-269, 83/01/21, B302010498
- B302010531 Forwards "Dconee 3, Cycle 7 Startup Testing Rept "
TUCKER, H B Duke Power Co 83/01/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 16977 196 24X Fiche 50-287, 83/01/24, B302010531
- B302010537 "Dconee 3, Cycle 7 Startup Testing Rept," consisting of zero power physics testing & power escalation testing
PRENELL, O M, COLLIER, J W Duke Power Co 83/01/24 26pp 16977 197 24X Fiche 50-287, 83/01/24, B302010531
- B302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to BSW plants, for use as starting point for addl detailed technical discussions between NRC & BSW Owners Group representatives
LAINAS, G C Assistant Director for Operating Reactors 83/01/31 WALI ACE, E Babcock & Wilcox Operating Plants Owners Group WALI ACE, E General Public Utilities - GPU Service Corp 6pp 17134 100 24X Fiche 50-000, 83/01/31, B302100257
- B302220467 "Adequacy of Station Electric Distribution Sys Voltages, Dconee Nuclear Station, Units 1, 2 & 3," informal rept
UDY, A C EO&G, Inc FIN A-6429 B302220467 83/01/31 EMAMI, H Division of Systems Integration (post B11005) 15pp 17239 358 24X Fiche 50-287, 83/01/31, B302220467
- B3023070504 Confirms info provided to NRC at B30114 meeting re flux reduction programs associated w/pressurized thermal shock
Units predicted to exceed NRC screening criteria through operating life
TUCKER, H B Duke Power Co 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 14pp 17036 347 24X Fiche 50-269, 83/02/03, B302070504
- B302140168 Discusses encl response to util B20525 submittal re proposed water inventory monitoring sys, based on considerations behind Dec 1982 orders on instrumentation to detect inadequate core cooling (NUREG-0737, Item II F 2)
DIRCKS, W J Office of the Executive Director for Operations 83/02/07 AHEARNE, J F Commissioners 1p 17144 160 24X
Fiche 50-269, 83/02/07, B302140168
- B302140173 Responds to conversation w/Commissioner Ahearne re status of review of B20525 submittal on instrumentation to detect inadequate core cooling (Item II F 2) & relationship w/Dec 1982 order Sys does not meet requirements
STOLZ, J F Operating Reactors Branch 4 83/02/01 TUCKER, H B Duke Power Co 3pp 17221 219 24X Fiche 50-269, 83/02/07, B302140168
- B209240433 Forwards questions arising during review of util submittal describing proposed water inventory monitoring sys Generic review incomplete due to apparent reluctance on part of util to supply info Sys unsatisfactory
ANDERSON, R L Oak Ridge National Laboratory 82/09/15 HUANG, Y Core Performance Branch 4pp 17144 164 24X
Fiche 50-269, 83/02/07, B302140168
- B302140174 Discusses response to util B20525 submittal re proposed water inventory monitoring sys & relationship to Dec 1982 order on instrumentation to detect inadequate core cooling
Response should be expedited
AHEARNE, J Commissioners 83/01/20 DIRCKS, W J Office of the Executive Director for Operations 1p 17144 169 24X
Fiche 50-269, 83/02/07, B302140168

DOCKETED ITEMS

113

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PURs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090098 Generic Ltr 83-10F to all licensees w/B&W designed NSSS (except TMI) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Duke Power Co
23pp 17298 291 24X Fiche 50-000, 83/02/08, 8302090098

8302180480 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising radiological effluent Tech Specs to incorporate design mods Mods reduce environ impact of effluent releases ALARA per App I, 10CFR20 requirements
TUCKER, H B Duke Power Co 83/02/09 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 7pp 17214 009 24X Fiche 50-269, 83/02/09, 8302180480

--8302180484 Proposed Tech Specs re radiological effluent controls
TUCKER, H B Duke Power Co 83/02/09 67pp 17214 016 24X
Fiche 50-269, 83/02/09, 8302180480

8302160236 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, allowing use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during performance of leak tests of connected sys
TUCKER, H B Duke Power Co 83/02/10 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 1p 17170 121 24X Fiche 50-269, 83/02/10, 8302160236

--8302160242 Proposed Tech Specs allowing use of RCS inservice leak & hydrostatic test heatup & cooldown limitations during performance of leak tests of connected sys when RCS pressure/temp limits controlling
* Duke Power Co 83/02/10 10pp 17170 124 24X
Fiche 50-269, 83/02/10, 8302160236

8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint or proper steam generator water level
VAND VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302250102

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20 will be forwarded in Apr 1983
ELLIOTT, J L., ROKLAND, G B Duke Power Co 83/02/18 DIRKEL, R
Office of Nuclear Reactor Regulation, Director 2pp 17296 215
24X Fiche 50-000, 83/02/18, 8302250391

--8302280424 Rev 1A to Nuclear Guide 1 143, "Design Guidance for Radwaste Mgt Sys, Structures & Components Installed in Light-Water-Cooled Nuclear Power Plants"
MILLER, R E., SNOW, A L Duke Power Co 83/01/04 14pp
17296 297 24X Fiche 50-000, 83/02/18, 8302250391.

--8302280436 Rev 1 to Nuclear Guide 1 147, "Inservice Insp Code Case Acceptability, ASME Section I, Div 1"
DALTON, D H Duke Power Co 83/01/06 7pp 17296 311 24X
Fiche 50-000, 83/02/18, 8302250391

8302240062 Notifies that decision to reaffirm or withdraw request for hearing re order imposing environ qualification requirements will be made within 30 days following review of 830222 final rule
CARR, A V Duke Power Co 83/02/21 EISENHUT, D G NRC - No
Detailed Affiliation Given 1p 17275 020 24X
Fiche 50-269, 83/02/21, 8302240062

8302280325 Application for amend to Licenses DPR-38, DPR-47 & DPR-55 revising Tech Specs re reactor vessel surveillance capsule withdrawal schedule Class III & I fees encl
TUCKER, H B Duke Power Co 83/02/23 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 3pp 17308 067 24X Fiche 50-269, 83/02/23, 8302280325

--8302280327 Proposed Tech Spec changing reactor vessel surveillance capsule withdrawal schedule
* Duke Power Co 83/02/23 2pp 17308 070 24X
Fiche 50-269, 83/02/23, 8302280325

8302290371 Supplemental application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs to provide curves based on matls properties previously provided & revised set of operator guidance
TUCKER, H B Duke Power Co 83/02/24 DENTON, H R Office of
Nuclear Reactor Regulation, Director 3pp 17297 195 24X
Fiche 50-269, 83/02/24, 8302250371

--8302250375 Proposed Tech Specs providing curves based on matls properties previously provided & revised set of operator guidance
* Duke Power Co 83/02/24 14pp 17297 198 24X
Fiche 50-269, 83/02/24, 8302250371

G Inspection reports, IE Bulletins & correspondence

8302150327 Responds to IE Bulletin 82-04 re Bunker-Ramo electrical penetrations Electrical penetrations at facilities mfg by Viking Corp No Bunker-Ramo penetrations installed
TUCKER, H B Duke Power Co 83/01/12 O'REILLY, J P Region 2,
Office of Director 1p 17148 174 24X Fiche 50-269, 83/01/12, 8302150327

8302160014 Summary of 830120 meeting w/utls, Bechtel, Franklin Research Ctr, VRB & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design " Addl testing not warranted
TRAMKELL, C H Operating Reactors Branch 3 83/01/25 Operating
Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150165 Forwards IE Insp Repts 50-269/83-02, 50-270/83-02 & 50-287/83-02 on 830104-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/27
TUCKER, H B Duke Power Co 2pp 17147 228 24X
Fiche 50-269, 83/01/27, 8302150165

--8302150171 IE Insp Repts 50-269/83-02, 50-270/83-02 & 50-287/83-02 on 830104-06 No noncompliance noted Major areas inspected licensee action on previous unresolved items, inspector followup items & LERs
ECONOMOS, N., BLAKE, J J Division of Project & Resident Programs
83/01/25 7pp 17147 230 24X Fiche 50-269, 83/01/27, 8302150165

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150608 Forwards IE Enforcement Meeting Repts 50-269/83-05, 50-270/83-05 & 50-287/83-05 on 830107
O'REILLY, J P Region 2, Office of Director 83/01/31 TUCKER, H B,
Duke Power Co 1p 17151 308 24X Fiche 50-269, 83/01/31, 8302150608

--8302150619 IE Enforcement Meeting Repts 50-269/83-05, 50-270/83-05 & 50-287/83-05 on 830107 Major areas discussed, corrective actions re licensee finding two manual containment isolation instrument air valves open from 821206-12
LEWIS, R C Division of Project & Resident Programs 83/01/27
2pp 17151 309 24X Fiche 50-269, 83/01/31, 8302150608.

8302220418 Forwards "B&W 177 Fuel Assembly Owners Group Safe End Task Force Rept on Generic Investigation of HPI/MU Nozzle Component Cracking " Recommended inservice insp program implemented at Units 2 & 3 w/augmented program for Unit 1
TUCKER, H B Duke Power Co 83/02/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 2pp 17232 229 24X Fiche 50-269, 83/02/15, 8302220418

8302250398 Forwards addl info re 821004 request for relief from hydrostatic inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code
TUCKER, H B Duke Power Co 83/02/17 DENTON, H R Office of
Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
Branch 4 18pp 17296 197 24X Fiche 50-269, 83/02/17, 8302250398

DOCKETED ITEMS

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302180374 Forwards monthly operating repts for Jan 1983
TUCKER, H B Duke Power Co 83/02/15 Director's Office, Office
of Inspection and Enforcement 1p 17209 320 24X
Fiche 50-269, 83/02/15, 8302180374

--8302180377 Monthly operating repts for Jan 1983
REAVIS, J A Duke Power Co 83/02/15 16pp 17209 321 24X
Fiche 50-269, 83/02/15, 8302180377

R Reportable occurrences, IERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen
recombiner is likely to malfunction following exposure
to elevated temp, high humidity environ Replacement part
identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17, COLLINS, J
Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302240068 Responds to Generic Ltr 83-01 Operator licensing exam
schedules listed
TUCKER, H B Duke Power Co 83/02/21 EISENHUT, D O Division of
Licensing 2pp 17281 041 24X Fiche 50-000, 83/02/21, 8302240068

DOCKET 50-289 REED COLLEGE RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8302070164 Releases public version of emergency plan
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17108 132 24X Fiche 50-289, 83/01/31,
8302070164

--8302070170 Forwards public version of emergency plan
KAY, M A Reed College 83/01/11 THOMAS, C O NRC - No Detailed
Affiliation Given 1p 17108 133 24X Fiche 50-289, 83/01/31,
8302070164

--8302070177 Public version of emergency plan
* Reed College, 82/11/01 30pp 17108 134 24X
Fiche 50-289, 83/01/31, 8302070164

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302040177 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17043 095 24X Fiche 50-289, 83/01/31,
8302040177

--8302040191 Forwards public version of revised Emergency Plan
Implementing Procedures 1004.2, "Alert" & 1004.31, "Airborne
Radioactivity Sampling & Analysis" Receipt form encl
NASH, B General Public Utilities - GPU Service Corp 83/01/12
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17043 096 24X Fiche 50-289, 83/01/31, 8302040177

--8302040198 Public version of revised Emergency Plan Implementing
Procedures 1004.2, "Alert" & 1004.31, "Airborne
Radioactivity Sampling & Analysis"
* General Public Utilities - GPU Service Corp 83/01/03 14pp
17043 097 24X Fiche 50-289, 83/01/31, 8302040177

8302090445 Releases public version of updated licensee info re status
of util negotiations w/State of PA to establish schedule
for 1983 annual exercise
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17108 348 24X Fiche 50-289, 83/01/31,
8302090445

--8302090452 Submits public version of updated info re status of util
negotiations w/State of PA to establish schedule for 1983
annual exercise & appropriate level of participation by
risk counties
HUKILL, H D General Public Utilities - GPU Service Corp
82/12/30 STOLZ, J F Operating Reactors Branch 4 1p
17108 349 24X Fiche 50-289, 83/01/31, 8302090445

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080175 Requests meeting w/NRC to clarify plant features re areas
where App R to 10CFR50 exemption requests have been denied
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/02
STOLZ, J F Operating Reactors Branch 4 1p 17058 339 24X
Fiche 50-289, 83/02/02, 8302080175

8302080382 Releases public version of revised administrative procedure
FELTON, J M Division of Rules and Records 83/02/02 Document
Management Branch 1p 17107 001 24X Fiche 50-289, 83/02/02,
8302080382

--8302080385 Public version of Rev 5 to Administrative Procedure 1053,
"Emergency Equipment Readiness"
NELSON, M A, TOOLE, R, HUKILL, H D General Public Utilities - GPU
Service Corp 83/01/17 41pp 17107 002 24X
Fiche 50-289, 83/02/02, 8302080382

8302090019 Releases public version of temporary change notice for rev
to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/03 Document
Management Branch 1p 17119 154 24X Fiche 50-289, 83/02/03,
8302090019

--8302090022 Public version of Temporary Change Notice 1-83-0007 for Rev
5 to Emergency Plan Implementing Procedure 1004.8,
"Callout of Onsite & Offsite Duty Roster Personnel"
NELSON, M A, ROSS, H J General Public Utilities - GPU Service
Corp 83/01/24 4pp 17119 155 24X Fiche 50-289, 83/02/03,
8302090019

8302250281 Forwards IE Insp Rept 50-289/83-01 on 830104-31 No
noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/02/10
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
17291 335 24X Fiche 50-289, 83/02/10, 8302250281

--8302250288 IE Insp Rept 50-289/83-01 on 830104-31 No noncompliance
noted Major areas inspected licensee action on previous insp
findings, plant operations, including steam generator repairs,
RCS pressure control testing & restart mode
COMIE, R, HAVERKAMP, D, THOMAS, C O Division of Project & Resident
Programs 83/02/09 12pp 17291 337 24X Fiche 50-289, 83/02/10,
8302250281

DOCKETED ITEMS

115

8302180018 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document
Management Branch 1p 17223 087 24X Fiche 50-289, 83/02/14,
8302180018

--8302180025 Public Version of Rev 2 to Emergency Plan Implementing Procedure 1004 S, Communication & Recordkeeping & Rev 3 to 1004 20, "Personnel/Vehicle Monitoring & Decontamination"
* General Public Utilities - GPU Service Corp 83/01/24 29pp
17223 088 24X Fiche 50-289, 83/02/14, 8302180018

8302240164 Informs that changes acceptable per 821130 ltr re Rev 16 to modified amended physical security plan Changes consistent w/provisions of 10CFR50.54(p) Effectiveness of plan not decreased
STOLZ, J Operating Reactors Branch 4 83/02/16 HUKILL, H D
General Public Utilities - GPU Service Corp 3pp 17288 270 24X
Fiche 50-289, 83/02/16, 8302240164

4 Adjudicatory correspondence

8301310336 Order extending time until 830202 for Commission to act to review ALAB-697
CHILK, S J Office of the Secretary of the Commission 83/01/26
Commissioners 1p 16963 094 24X Fiche 50-289, 83/01/26,
8301310336

8302010507 Forwards B&W Owners Group 830113 ltr to NRC re integral sys testing Ltr updates info previously provided
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Metropolitan Edison Co 83/01/27 EDLES, O J, BUCK, J H,
GOTCHY, R L Atomic Safety and Licensing Appeal Panel 6pp
16979 193 24X Fiche 50-289, 83/01/27, 8302010507

8302010510 Order extending time until 830202 for Commission to act to review ALAB-705
CHILK, S J Office of the Secretary of the Commission 83/01/27
Commissioners 1p 16978 067 24X Fiche 50-289, 83/01/27,
8302010510

8302020350 Forwards conclusions from independent investigation of Ltr Designated Individual VV certification in 1979 Entire rept provided to IE
TROWBRIDGE, O F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, O F
Metropolitan Edison Co 83/01/31 EDLES, O J, BUCK, J H, KOHL, C N
Atomic Safety and Licensing Appeal Panel 13pp 16994 080 24X
Fiche 50-289, 83/01/31, 8302020350

8302070550 Order extending time until 830216 for Commission to act to review ALAB-705
CHILK, S J Office of the Secretary of the Commission 83/02/02
Commissioners 1p 17034 112 24X Fiche 50-289, 83/02/02,
8302070550

8302070587 Motion for order directing util & NRC to present witnesses in reopened proceeding for UCS deposition prior to 830216
UCS should be given minimal opportunity for discovery
Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss
83/02/02 Atomic Safety and Licensing Appeal Panel 5pp
17035 027 24X Fiche 50-289, 83/02/02, 8302070587

8302070484 Responds to question re use of depositions of util & NRC witnesses Depositions may result in filing of direct testimony Certificate of Svc encl
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 83/02/03 EDLES, O, GOTCHY, R L, BUCK, J H Atomic Safety and Licensing Appeal Panel 4pp 17036 033 24X
Fiche: 50-289, 83/02/03, 8302070484

8302070544 Advises that time for Commission to review ALAB-697 expired Commission declined review Decision became final agency action on 830202
CHILK, S J Office of the Secretary of the Commission 83/02/03
Metropolitan Edison Co 1p 17038 362 24X Fiche 50-289, 83/02/03,
8302070544

8302080178 Response in opposition to UCS 830202 motion for order directing discovery against NRC & licensee Need for discovery not demonstrated Certificate of Svc encl
BAXTER, T A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/02/04, Atomic Safety and Licensing Appeal Panel 8pp 17058 325 24X Fiche 50-289, 83/02/04, 8302080178

8302090458 Answer opposing UCS 830202 motion for order directing NRC & licensee to make witnesses available for depositions before 830216 Request not justified Granting request would interfere w/preparation of testimony w/Certificate of Svc
CUTCHIN, J M Hearing Branch 4 83/02/04 Atomic Safety and Licensing Appeal Panel 8pp 17066 293 24X Fiche 50-289, 83/02/04,
8302090458

8302090253 Order extending time until 830214 for Commission to act to review ALAB-708
CHILK, S J Office of the Secretary of the Commission 83/02/07
Commissioners 1p 17070 248 24X Fiche 50-289, 83/02/07,
8302090253

8302090258 Order denying UCS 830202 motion for order directing NRC & util to present witnesses for deposition before 830216 due date for filing testimony Most issues to be addressed in reopened hearing considered before, so party positions known
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/07
Union of Concerned Scientists 4pp 17069 345 24X
Fiche 50-289, 83/02/07, 8302090258

8302160293 Forwards HD Hukill 830202 ltr to JF Stol: re proposed alternative method for ensuring that potential exposures from fuel handling accidents conform to current regulatory guidelines Fuel handling procedures revised w/svc list
ZAHLER, R E Shaw, Pittman, Potts & Trowbridge ZAHLER, R E
Metropolitan Edison Co 83/02/08 EDLES, O J, BUCK, J H,
GOTCHY, R L Atomic Safety and Licensing Appeal Panel 5pp
17170 092 24X Fiche 50-289, 83/02/08, 8302160293

8302160371 Proposes 830218 or 21 as possible dates for deposition of util witness
WEISS, E R Harmon & Weiss 83/02/09 TROWBRIDGE, O F Shaw, Pittman, Potts & Trowbridge 1p 17164 148 24X
Fiche 50-289, 83/02/09, 8302160371

8302160317 Forwards BAW-10154P, "B&W Small Break LOCA ECCS Evaluation Model," to be offered into evidence at upcoming hearing
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Metropolitan Edison Co 83/02/10 EDLES, O J, BUCK, J H,
GOTCHY, R L Atomic Safety and Licensing Appeal Panel 6pp
17163 198 24X Fiche 50-289, 83/02/10, 8302160317

--8302160330 Withdraws proprietary classification for BAW-10154P, "B&W Small Break LOCA ECCS Evaluation Model"
TAYLOR, J M Babcock & Wilcox Co 83/02/10 BERGOREN, J S
Standardization & Special Projects Branch 1p 17163 204 24X
Fiche 50-289, 83/02/10, 8302160317

--8211020469 "B&W Small Break LOCA ECCS Evaluation Model"
SAVAN, N K Babcock & Wilcox Co BAW-10154P 82/11/30 250pp
17163 205 24X Fiche 50-289, 83/02/10, 8302160317

8302170219 Proposes that UCS review licensee testimony to be received on 830216 before arrangements to depose licensee witness made, in response to 830207 ltr Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Metropolitan Edison Co 83/02/14 WEISS, E R Harmon & Weiss 4pp
17187 111 24X Fiche 50-289, 83/02/14, 8302170219

8302230585 Order extending time until 830218 for Commission to act to review ALAB-698
CHILK, S J Office of the Secretary of the Commission 83/02/14
Commissioners 1p 17248 341 24X Fiche 50-289, 83/02/14,
8302230585

8302170211 Agrees to review licensee testimony to determine whether all witnesses need be deposed, per 830214 ltr UCS deposition of witnesses set for 830222
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 83/02/15 BAXTER, T A Shaw, Pittman, Potts & Trowbridge
1p 17179 086 24X Fiche 50-289, 83/02/15, 8302170211

8302180321 Forwards EOL & LASL repts requested by ASL&B on boiler-condenser or feed & bleed cooling calculation referenced in staff testimony on Question 7 & 11. W/o encl
CUTCHIN, J M Hearing Branch 4 83/02/17 EDLES, O J, GOTCHY, R L,
BUCK, J H Atomic Safety and Licensing Appeal Panel 2pp
17213, 345 24X Fiche 50-289, 83/02/17, 8302180321

8302220397 Order advising parties to file comments by 830304 on util 830208 ltr outlining proposal to deviate from certain guidelines in ASL&B 811214 decision
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/17,
Metropolitan Edison Co 1p 17232 148 24X Fiche 50-289,
83/02/17, 8302220397

8302220340 Advises that time for Commission to review ALAB-708 expired Commission declined review Decision became final agency action on 830214
CHILK, S J Office of the Secretary of the Commission 83/02/18
Office of the Executive Legal Director 1p 17230 086 24X
Fiche 50-289, 83/02/18, 8302220340,

DOCKETED ITEMS

8302230660 Order CLI-83-3, denying UCS 821104 motion to hold evidentiary hearing on alleged ex parte communications between NRC & Commission Communications involved issues outside scope of hearing.
CHILKIS, J. Office of the Secretary of the Commission 83/02/18
Union of Concerned Scientists 5pp 17255 171 24X
Fiche 50-289, 83/02/18, 8302230660

8302230274 Requests for subpoenas directing CJ Heltemes & FH Rousome to testify at 830307 reopened hearing Heltemes & Rousome are NRC staff members who hold differing opinions on feed & bleed issue Certificate of Svc encl
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Harmon & Weiss 83/02/23 Atomic Safety and Licensing Appeal Panel 29pp
17291 179 24X Fiche 50-289, 83/02/23, 8302230274

8302230310 Forwards util 830128 ltr to NRC re SER & environ qualification info relates to Board Notification 82-133, "Environ Qualification of Safety-Related Electrical Equipment" Svc list encl
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge BAXTER, T. A. Metropolitan Edison Co. 83/02/23 Docketing & Services Branch 3pp 17291 009 24X Fiche 50-289, 83/02/23, 8302230310

8302280251 Answer opposing UCS 830223 request for subpoenas requiring attendance & testimony of CJ Heltemes & FH Rousome of NRC No exceptional circumstances shown No significant difference in NRC witness views or st.
CUTCHIN, J. M. Hearing Branch 4 83/02/25 Atomic Safety and Licensing Appeal Panel 6pp 17304 259 24X Fiche 50-289, 83/02/25, 8302280251

--8302280255 Affidavit of FH Rousome explaining why 820129 memo on feed & bleed issue for C-E applicants has no bearing on safety of TMI-1 operations Memo does not address design adequacy or licensing basis
ROMSDME, F. H. Assistant Director for Technology Review 83/02/25 3pp 17304 265 24X Fiche 50-289, 83/02/25, 8302280255

--8302280258 Affidavit of HL Ornstein re NRC position on feed & bleed issue OFC for Analysis & Evaluation of Operational Data position is that plant operation can & should continue w/concurrent efforts at testing Certificate of Svc encl
ORNSTEIN, H. L. Director's Office 83/02/24 6pp 17304 268 24X Fiche 50-289, 83/02/25, 8302280258

P Operating license stage documents & correspondence

8302020427 Partial response to FOIA request for documents written during or since June 1982 re causes or repair of steam generator problems at facility Forwards App A documents Addl documents available in LPDR
FELTOW, J. M. Division of Rules and Records 82/11/30 DOROSHOW, J. Three Mile Island Alert 2pp 17012 048 24X Fiche 50-289, 82/11/30, 8302020427

--8207140131 Summary of 820615 meeting w/util & Franklin Research Ctr in Parsippany, NJ re steam generator tube/tubesheet repair
RAJAN, J. R. Mechanical Engineering Branch 82/06/18 BOSNAK, R. J. Mechanical Engineering Branch 9pp 17012 053 24X Fiche 50-289, 82/11/30, 8302020427

--8302020430 'Degradation of Steam Generator Tubes at TMI-1'
JACOBBS, R. Operating Reactors Branch 4 MCCracken, C. Chemical Engineering Branch 82/11/30 2pp 17012 051 24X Fiche 50-289, 82/11/30, 8302020427

--8302020439 Discusses small break LOCA by steam generator tube rupture at facility. More tubes may be plugged than originally planned info re simultaneous tube break in both steam generators requested Summary of 820920 meeting encl
SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards 82/09/19 FRALEY, R. ACRS - Advisory Committee on Reactor Safeguards 4pp 17012 071 24X Fiche 50-289, 82/11/30, 8302020427

--8302020444 Forwards ltr from P Sheumon to R Fraley re small break LOCA by steam generator tube rupture W/o encl Extract from Commission 821006 briefing on certification status concerning overall plant status/schedule encl
HAJOS, R. R. ACRS - Advisory Committee on Reactor Safeguards, 82/09/30 MOELLER, D. ACRS - Advisory Committee on Reactor Safeguards, 2pp 17012 075 24X Fiche 50-289, 82/11/30, 8302020427

7070146 Addl response to FOIA request for five categories of documents. Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5). Info re item 4 available in i. No documents re item 5 located
TON, J. M. Division of Rules and Records 82/12/02 HIATT, B. Citizens for Responsible Energy 4pp 17065 325 24X
50-000, 82/12/02, 8302070146

--8302070153 Excerpts from ASLB 820308, 0419, 0614, 28 & 0726 meetings re effects or proposed restart on psychological health of residents in surrounding communities Article from Mind & Medicine, Vol 8, Number 3, dtd Apr 1981 encl
* IRC - No Detailed Affiliation Given 82/12/02 NRC - No Detailed Affiliation Given 11pp 17065 330 24X
Fiche 50-000, 82/12/02, 8302070146

8302010556 Application for amend to License DPR-50, consisting of Tech Spec Change Request 120 re engineered safeguards protection sys activation setpoints Certificate of Svc encl
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/01/21 STOLZ, J. F. Operating Reactors Branch 4 4pp 16977 117 24X
Fiche 50-289, 83/01/21, 8302010556

--8302010562 Tech Spec Change Request 120 re engineered safeguards protection sys activation setpoints
* General Public Utilities - GPU Service Corp 83/01/21 2pp 16977 121 24X Fiche 50-289, 83/01/21, 8302010556

8302010507 Forwards B&W Owners Group 830113 ltr to NRC re integral sys testing Ltr updates info previously provided
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge BAXTER, T. A. Metropolitan Edison Co. 83/01/27 EDLES, O. J., BUCK, J. H., GOTHCHY, R. L. Atomic Safety and Licensing Appeal Panel 6pp 16979 193 24X Fiche 50-289, 83/01/27, 8302010507

8302010407 Reaffirms util position that facility can be operated safely during resolution of environ qualification deficiencies as described in 810321 SER All IE equipment in harsh environ & required for safe shutdown qualified
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/01/28 STOLZ, J. F. Operating Reactors Branch 4 1p 16981 319 24X
Fiche 50-289, 83/01/28, 8302010407

8302090037 Forwards request for addl info re Rev 1 to licensee Topical Rept 03B on plant safety subsequent to recovery from once-through steam generator corrosion problems Meeting should be scheduled to resolve desulfurization issue
BENARDYA, V. Chemical Engineering Branch 83/01/28 STOLZ, J. Operating Reactors Branch 4 5pp 17108 351 24X
Fiche 50-289, 83/01/28, 8302090037

--8301070311 Requests addl info re util recommissioning activities on once-through steam generators for review of Topical Rept 008, Rev 1: "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair"
MACDONALD, D. D. Affiliation Unknown 83/01/03 BENARDYA, V. Chemical Engineering Branch 7pp 17108 356 24X
Fiche 50-289, 83/01/28, 8302090037

8302040390 Forwards "Overview of Progress in TMI-1 Tube Cleaning Experiment"
GREENAWAY, H. R. General Public Utilities - GPU Service Corp 83/01/31 MCCracken, C. NRC - No Detailed Affiliation Given 1p 17019 001 24X Fiche 50-289, 83/01/31, 8302040390

--8302040398 "Overview of Progress in TMI-1 Tube Cleaning Experiment"
BARNES, R. H. WENSKY, A. K., LATHOUSE, J. Battelle Memorial Institute, Columbus Laboratories 83/01/31 75pp 17019 002 24X
Fiche 50-289, 83/01/31, 8302040390

8302070448 Forwards Tech Spec Change Request 122 amending App A to License DPR-50
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/01/31 STOLZ, J. F. Operating Reactors Branch 4 1p 17036 252 24X
Fiche 50-289, 83/01/31, 8302070448

--8302070452 Tech Spec Change Request 122 adding Section 6.8.1, Item J re unit shift manning requirement procedures & changing Section 6.5.3.1, Items e & f re QA audits
HUKILL, H. D. General Public Utilities - GPU Service Corp 83/01/31 4pp 17036 253 24X Fiche 50-289, 83/01/31, 8302070448

--8302070455 Proposed Tech Spec Sections 6.5.3.1 re QA audits & 6.8.1 re unit shift manning requirement procedures
* General Public Utilities - GPU Service Corp 83/01/31 2pp 17035 257 24X Fiche 50-289, 83/01/31, 8302070448

8302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to B&W plants, for use as starting point for addl detailed technical discussions between NRC & B&W Owners Group representatives
LAINAS, O. C. Assistant Director for Operating Reactors 83/01/31 WALLACE, E. Bahcock & Wilcox Operating Plants Owners Group 6pp 17134 100 24X Fiche 50-000, 83/01/31, 8302100257

DOCKETED ITEMS

117

- 8302240039 Forwards findings of independent investigation of operator qualifications from 1979-82 Names, employee numbers, social security numbers & reactor operator/senior reactor operator license numbers deleted
AROLD, R C General Public Utilities - GPU Service Corp 83/01/31
CEYKUN, R C Office of International Programs, Director 1, 116pp
17261 043 24X Fiche 50-289, 83/01/31, 8302240039
- 8302080441 Board Notification 83-08 forwards info re allegation concerning util which appears to have nexus to issue of mgt competency &/or cheating issue in restart proceeding investigation underway
EISENHUT, D G Division of Licensing 83/02/01 PALLADINO, H J
GILINSEY, V, AKERNE, J F Commissioners App 17071 107 24X
Fiche 50-289, 83/02/01, 8302080441
- 8302020195 Requests relief from ASLB 811214 decision requiring upgrade of fuel handling bldg ventilation sys to include new ESF faster sys prior to first refueling outage Present sys adequate Assumption & key parameters encl
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/02
STOLZ, J F Operating Reactors Branch 4 3pp 17058 138 24X
Fiche 50-289, 83/02/02, 8302020195
- 8302090341 Forwards Tech Spec Change Request 123 to License DPR-50, allowing greater flexibility in steam generator tube repair methods
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/02
STOLZ, J F Operating Reactors Branch 4 1p 17067 155 24X
Fiche 50-289, 83/02/02, 8302090341
- 8302090351 Tech Spec Change Request 123 to License DPR-50, changing Tech Specs re steam generator tube repair methods
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/02 2pp 17067 156 24X Fiche 50-289, 83/02/02, 8302090351
- 8302090363 Proposed Tech Specs, allowing greater flexibility in steam generator tube repair methods
+ General Public Utilities - GPU Service Corp 83/02/02 5pp 17067 158 24X Fiche 50-289, 83/02/02, 8302090363
- 8302100188 Lists info to be included in util submittal re present status & program schedule for flux reduction per 830114 discussions
STOLZ, J F Operating Reactors Branch 4 83/02/02 HUKILL, H D
General Public Utilities - GPU Service Corp 6pp 17134 188 24X
Fiche 50-289, 83/02/02, 8302100188
- 8302080300 Forwards summary status rept for items requiring NRC certification prior to restart as result of NRC order & 790509 notice of hearing
AROLD, R C General Public Utilities - GPU Service Corp 83/02/03
CENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17055 134 24X Fiche 50-289, 83/02/03, 8302080300
- 8302100232 Forwards application to amend License DPR-50, incorporating Tech Spec Change Request 121 to allow higher limits of hydrogen or oxygen as long as gases kept below lower flammability limits
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/03
STOLZ, J F Operating Reactors Branch 4 2pp 17114 114 24X
Fiche 50-289, 83/02/03, 8302100232
- 8302100237 Application to amend License DPR-50, incorporating Tech Spec Change Request 121 to allow higher limits of hydrogen or oxygen as long as gases kept below flammability limits
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/03 1p 17114 116 24X Fiche 50-289, 83/02/03, 8302100237
- 8302100240 Tech Spec Change Request 121, allowing use of higher limits of hydrogen or oxygen as long as gases kept below lower flammability limits
+ General Public Utilities - GPU Service Corp 83/02/03 5pp 17114 117 24X Fiche 50-289, 83/02/03, 8302100232
- 83020402 Forwards responses to items discussed at 830107 meeting w/ NRC & ALL re unresolved issues resulting from technical evaluation rept on responses to issues raised in Generic Ltr 81-14
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/04
STOLZ, J F Operating Reactors Branch 4 9pp 17067 119 24X
Fiche 50-289, 83/02/04, 83020402
- 83021005 Forwards request for addl info re Topical Rept 008, Rev 1, "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair," submitted w/ licensee 821210 ltr
STOLZ, J F Operating Reactors Branch 4 83/02/07 HUKILL, H D
General Public Utilities - GPU Service Corp 9pp 17191 089 24X
Fiche 50-289, 83/02/07, 83021005
- 8302170111 Forwards request for refs listed in Topical Rept 008, Rev 1, per NRC 821220 ltr Refs necessary for preparation of technical evaluation rept
SHOOK, T Franklin Institute/Franklin Research Center
NRC 03-B1-130 83/01/07 RAJAN, J, MCCracken, C NRC - No
Detailed Affiliation Given 2pp 17191 098 24X
Fiche 50-289, 83/02/07, 8302170105
- 8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295
- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234-234 24X
Fiche 50-000, 83/02/08, 8302080304
- 8302150052 Forwards remittance for Tech Spec Change Request 123 dtw 830202
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/09
STOLZ, J F Operating Reactors Branch 4 1p 17147 048 24X
Fiche 50-289, 83/02/09, 8302150052
- 8302150651 Forwards responses to NRC 820708 & 1007 ltrs addressing open items from NUREG-0480 & NUREG-0733, Item III B 3 re post-accident sampling sys
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/09
STOLZ, J F Operating Reactors Branch 4 14pp 17151 024 24X
Fiche 50-289, 83/02/09, 8302150651
- 8302170404 Notification of 830224 meeting w/util & ORNL in Bethesda, MD to discuss inadequate core cooling instrumentation
VAN VLIEET, J Operating Reactors Branch 4 83/02/14 STOLZ, J
Operating Reactors Branch 4 2pp 17195 253 24X
Fiche 50-289, 83/02/14, 8302170404
- 8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level
VAN VLIEET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302250102
- 8302230175 Discusses unavailability of safety-grade, seismically qualified digital indicators required by restart rept, Section 2.1.1 & 4.3 Redundancy provided by computing saturation margin for each loop
HUKILL, H D General Public Utilities - GPU Service Corp 83/02/18
STOLZ, J F Division of Licensing 2pp 17245 164 24X
Fiche 50-289, 83/02/18, 8302230175
- 8302280224 Advises that 830131 ltr inadvertently referred to recipient as participant in 830210 meeting to evaluate chemical cleaning of steam generators Ltr should have been sent for info only
WEIMORE, J S General Public Utilities - GPU Service Corp 83/02/22
MCCracken, C Chemical Engineering Branch. 1p 17304 357 24X
Fiche 50-289, 83/02/22, 8302280224.
- G Inspection reports, IE Bulletins & correspondence

- 8302030417 Forwards IE Insp Rept 50-289/82-26 on 821112-1231 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/21
HUKILL, H D General Public Utilities - GPU Service Corp 2pp 17005 124 24X Fiche 50-289, 83/01/21, 8302030417
- 8302030429 IE Insp Rept 50-289/82-26 on 821112-1231 No noncompliance noted Major areas inspected action on previous insp findings, steam generator tube kinetic expansion performance & restart preoperational & startup testing
NICHOLAS, H., CONTE, R., GRAY, E Division of Engineering & Technical Programs 83/01/19 15pp 17005 126 24X Fiche 50-289, 83/01/21, 8302030417
- 8302070331 Forwards IE Insp Rept 50-289/82-28 on 821206-830104 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/01/24.
HUKILL, H D General Public Utilities - GPU Service Corp 2pp 17030 356 24X Fiche 50-289, 83/01/24, 8302070331

DOCKETED ITEMS

--8302070335 IE Insp Rept 50-289/82-28 on 821206-830104 No noncompliance noted Major areas inspected action on previous insp findings, plant operations, including steam generator repairs & LERs
 COKIE, R., YOUNG, F., KEINIG, R. Region 1, Office of Director
 83/01/21 5pp 17030 358 24X Fiche 50-289, 83/01/24, 8302070335

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc. 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150590 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/82-21
 STAROSTECKI, R. Division of Project & Resident Programs. 83/02/07
 HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp
 17156 113 24X Fiche 50-289, 83/02/07, 8302150590

--8302150603 Responds to NRC 821207 ltr re violations noted in IE Insp Rept 50-289/82-21 Corrective actions safety evaluation for safety valve position indications revised to include new scope of work
 HUKILL, H. D. General Public Utilities - GPU Service Corp
 83/01/20 HAYNES, R. C. Region 1, Office of Director 2pp
 17156 115 24X Fiche 50-289, 83/02/07, 8302150590

8302150634 Forwards response to NRC 821210 request for addl info re Items 4 & 5 of IE Bulletin 81-03 concerning flow blockage of cooling water to safety sys components by corbicula & mytilus sp. No immediate preventive action required
 HUKILL, H. D. General Public Utilities - GPU Service Corp 83/02/07
 JORDAN, E. L. Division of Engineering & Quality Assurance (Pre 830103) 4pp 17151 329 24X Fiche 50-289, 83/02/07, 8302150634

8302204995 Board Notification 83-09 provides results of annual SALP re licensee mgt capability, for use in restart hearing
 EISENHUT, D. O. Division of Licensing 83/02/07 PALLADINO, N., GILTHINSHY, V., AHFARNE, J. F. Commissioners 6pp 17236 333 24X Fiche 50-289, 83/02/07, 8302204995

8302160270 Forwards revised Table 5 Part B (2) on Page 5-2 covering enforcement data Some data inadvertently omitted from SALP input sent by 830120 ltr
 STAROSTECKI, R. Division of Project & Resident Programs 83/02/09
 ARHOLD, R. General Public Utilities - GPU Service Corp 1p
 17169 235 24X Fiche 50-289, 83/02/09, 8302160270

--8302160273 Corrected Page 5-2 of SALP rept for Oct 1981 - Sept 1982 * Region 1, Office of Director 82/11/22 1p 17169 235 24X Fiche 50-289, 83/02/09, 8302160270

8302180176 Ack receipt of 830113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/82-12
 MARTIN, T. T. Division of Engineering & Technical Programs 83/02/10
 HUKILL, H. D. General Public Utilities - GPU Service Corp 3pp
 17216 004 24X Fiche 50-289, 83/02/10, 8302180176

--8302180182 Responds to 821223 meeting w/NRC re violations noted in IE Insp Rept 50-289/82-12 Corrective actions until will ensure submittals consistent w/NRC guidance & will evaluate scenario to ensure adequate coverage of activities
 HUKILL, H. D. General Public Utilities - GPU Service Corp
 83/01/13 HAYNES, R. C. Region 1, Office of Director 9pp
 17216 006 24X Fiche 50-289, 83/02/10, 8302180176

8302250281 Forwards IE Insp Rept 50-289/83-01 on 830104-31 No noncompliance noted
 STAROSTECKI, R. Division of Project & Resident Programs 83/02/10
 HUKILL, H. D. General Public Utilities - GPU Service Corp 2pp
 17291:335 24X Fiche 50-289, 83/02/10, 8302250281

--8302250288 IE Insp Rept 50-289/83-01 on 830104-31 No noncompliance noted Major areas inspected: licensee action on previous insp findings, plant operations, including steam generator repairs, RCS pressure control testing & restart mode
 CONTE, R., HAVERKAMP, D., THONUS, L. Division of Project & Resident Programs 83/02/09 12pp 17291 337 24X Fiche 50-289, 83/02/10, 8302250281

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302230156 Forwards monthly operating rept for Jan 1983
 HUKILL, H. D. General Public Utilities - GPU Service Corp 83/02/15
 MCDONN, D. M. C. Division of Data Automation & Management Information 1p 17243 255 24X Fiche 50-289, 83/02/15, 8302230156

--8302230158 Monthly operating rept for Jan 1983
 EBYTH, C. W. General Public Utilities - GPU Service Corp 83/02/15
 12pp 17243 255 24X Fiche 50-289, 83/02/15, 8302230156

B Reportable occurrences, LFRs & related correspondence

8302030541 Forwards LER 82-016/03L-0
 HUKILL, H. D. General Public Utilities - GPU Service Corp 83/01/21
 HAYNES, R. C. Region 1, Office of Director 1p 17006 226 24X Fiche 50-289, 83/01/21, 8302030541

--8302030549 LER 82-016/03L-0 on 821272, during cold shutdown, fire barrier penetration seal 487 identified as having unacceptable void under cable tray support angle Temporary damming matl installed on both sides of seal
 STEPHENSON, C. J. General Public Utilities - GPU Service Corp
 83/01/21 Region 1, Office of Director 3pp 17006 227 24X Fiche 50-289, 83/01/21, 8302030541

8302090170 Forwards LER 83-001/03L-0
 HUKILL, H. D. General Public Utilities - GPU Service Corp 83/02/01
 HAYNES, R. C. Region 1, Office of Director 1p 17070 001 24X Fiche 50-289, 83/02/01, 8302090170

--8302090175 LER 83-001/03L-0 on 830101, during reactor bldg purge, station radiation monitor RM-A9, iodine channel, failed Caused by single channel analyzer circuit board failure Circuit board replaced & quarterly calibr performed
 STEPHENSON, C. J. General Public Utilities - GPU Service Corp
 83/02/01 Region 1, Office of Director 3pp 17070 002 24X Fiche 50-289, 83/02/01, 8302090170

8302180260 Telecopy of RO 83-003 on 830210, initial disassembly & insp of PCIV RC-RV2 revealed pilot valve piston & spring corroded in full open position Failure analysis initiated to determine cause & corrective actions
 D'TOOLE, K. J. General Public Utilities - GPU Service Corp 83/02/11
 HAYNES, R. C. Region 1, Office of Director 1p 17219 244 24X Fiche 50-289, 83/02/11, 8302180260

8302230225 Telecopy RO 83-003 on 830210, during insp of PORV RC-RV2, corrosion identified in Inconel & austenitic steel parts Pilot valve piston & spring also found corroded Cause under analysis
 D'TOOLE, K. J. General Public Utilities - GPU Service Corp 83/02/11
 HAYNES, R. C. Region 1, Office of Director 1p 17244 362 24X Fiche 50-289, 83/02/11, 8302230225

T Hearing transcripts on non-antitrust matters

8302010104 FOIA request for transcripts of lawsuit between General Public Utilis & BLM in Federal District Court, Southern District of NY
 WEISS, E. R. Union of Concerned Scientists 82/11/22 FELTON, J.
 Division of Rules and Records 1p 17061 071 24X Fiche 50-289, 82/11/22, 8302010104

8302160098 Notification of contract execution, Mod 2 to 'Transcription of THF Tapes' Contractor NR Gross & Co. Inc
 SMITH, P. A. Division of Contracts HRC-10-79-400 82/12/20
 SPRINGER, M. Office of Administration MCVEAUGH, H. NRC - No Detailed Affiliation Given 1p 17160 262 24X Fiche 50-289, 82/12/20, 8302160098

DOCKETED ITEMS

119

- B302010104 Mod 2. deobligating funds to "Transcription of 7MI Tapes"
 * Neal R. Gross & Co., Inc. SMITH, P. A. Division of Contracts
 IRC-10-79-400 82/12/20 1p 17160 263 24X
 Fiche 50-289, 82/12/20, B302010098
- B302010112 Responds to FOIA request for transcripts of lawsuit between
 General Public Utils & B&W in Federal District Court,
 Southern District of NY. Listed transcripts available in PDR
 for viewing only
 FELTON, J. M. Division of Rules and Records 82/12/21 WEISS, E. R.
 Harmon & Weiss 3pp 17061 072 24X Fiche 50-289, 82/12/21,
 B302010112
- B302010119 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 1
 Pp 1-187 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/01 189pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010123 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 2
 Pp 190-361 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/02 172pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010129 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 3
 Pp 352-537 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/03 176pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010135 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 4
 Pp 538-712 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/04 175pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010142 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 5
 Pp 713-833 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/05 118pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010148 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 6
 Pp 831-1,030 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/09 200pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010153 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 7
 Pp 1,031-1,130 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/10 100pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010156 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 8
 Pp 1,131-1,235 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/11 105pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010161 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 9
 Pp 1,236-1,337 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/12 102pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010166 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 10
 Pp 1,338-1,534 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/15 197pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010170 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 11
 Pp 1,535-1,715 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/16 181pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010177 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 12
 Pp 1,716-1,875 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/17 160pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010183 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 13
 Pp 1,876-2,039 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/18 164pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010202 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 14
 Pp 2,040-2,137 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/19 98pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010210 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 15
 Pp 2,138-2,311 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/22 174pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010216 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 16
 Pp 2,312-2,574 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/23 263pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010221 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 17
 Pp 2,575-2,690 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/24 106pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010226 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 18
 Pp 2,691-2,830 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/29 150pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010232 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 19
 Pp 2,831-2,923 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/11/30 93pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010238 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 20
 Pp 2,924-3,040 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/01 117pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010241 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 21
 Pp 3,041-3,215 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/02 175pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010256 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 22
 Pp 3,216-3,377 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/06 162pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010262 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 23
 Pp 3,378-3,559 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/07 182pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010268 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 24
 Pp 3,560-3,733 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/08 174pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010273 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 25
 Pp 3,734-3,906 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/09 173pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010278 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 26
 Pp 3,907-4,089 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/10 83pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010282 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 27
 Pp 4,090-4,178 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/13 189pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112
- B302010284 Transcript of lawsuit between General Public Utils & B&W in
 Federal District Court, Southern District of NY, Vol 28
 Pp 4,179-4,388 Transcript available in PDR for viewing only
 * IRC - No Detailed Affiliation Given 82/12/14 210pp
 17013 085 24X Fiche 50-289, 82/12/21, B302010112

DOCKETED ITEMS

8302010289 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 29
Pp 4, 369-4, 554 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/15 166pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

8302010291 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 30
Pp 4, 369-4, 746 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/16 192pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

8302010295 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 31
Pp 4, 747-4, 913 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/17 167pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

8302010299 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 32
Pp 4, 914-5, 102 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/20 187pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

8302010302 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 33
Pp 9, 103-5, 279 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/21 177pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

8302010305 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 34
Pp 5, 280-5, 445 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/22 167pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

82020041 Transcript of ACRS combined Subcommittees on Metal Components & TMI-1 830128 meeting in Washington, DC Pp 1-294
Supporting documentation encl
ACRS - Advisory Committee on Reactor Safeguards 83/01/29
11pp 16992 232 24X Fiche 50-289, 83/01/28, 8302020041

8170083 Transmittal of NRC supplemental testimony on issues identified by ASLAB
MCHIN, J H Hearing Branch 4 83/02/16 1p 17182 321 24X
Fiche 50-289, 83/02/16, 8302170083

82170087 Testimony of BW Sherrin & WL Jensen in response to ASLAB Questions 2, 4, 5, 6, 7, 9, 10 & 11 Results of RELAP5 computer code analysis demonstrate feed & bleed method will successfully provide core cooling
SHERIN, B W, JENSEN, W L Reactor Systems Branch 83/02/16 50pp
17182 322 24X Fiche 50-289, 83/02/16, 8302170083

82170090 Testimony of JS Hermiel in response to ASLAB Question 8 re inconsistencies & confusion in safety-grade status of components in emergency feedwater sys Components which will not be safety-grade at restart listed w/ Certificate of Svc
HERMIEL, J S Auxiliary Systems Branch 83/02/16 6pp
17183 009 24X Fiche 50-289, 83/02/16, 8302170083

820347 Forwards direct testimony on Issues 1 - 9 of ASLAB 821228 memorandum & Order ALAB-708 Certificate of Svc encl
XTER, T A Shaw, Pittman, Potts & Troubridge DAXTER, T A
Metropolitan Edison Co 83/02/16 EDLES, O J, BUCK, J H,
RCHY, R L Atomic Safety and Licensing Appeal Panel 6pp
233 020 24X Fiche 50-289, 83/02/16, 8302220347

82220359 Testimony of GR Capodanno on ALAB-708, Issue 1 re hot leg high point vent sizing Vents sized so sys failure would not constitute LOCA Prof qualifications encl
CAPODANNO, G R Metropolitan Edison Co 83/02/16 6pp
7233 026 24X Fiche 50-289, 83/02/16, 8302220347

82220362 Testimony of RC Jones & LC Lanese re ALAB-708, Issue 2 on use of hot leg vents in promoting natural circulation Vents will be used under inadequate core cooling conditions Prof qualifications encl
JONES, R C, LANESE, L C Metropolitan Edison Co 83/02/16 11pp
7233 033 24X Fiche 50-289, 83/02/16, 8302220347

82220365 Testimony of FF Manganaro re ALAB-708, Issue 3 on hot leg vent installation status Earliest date for mod completion estimated at 830531 Prof qualifications encl
MANGANARO, F F Metropolitan Edison Co 83/02/16 6pp
7233 044 24X Fiche 50-289, 83/02/16, 8302220347

8302220371 Testimony of RC Jones re ALAB-708, Issues 4 - 7 on ECCS evaluations & boiler-condenser cooling Analyses demonstrate adequacy of boiler-condenser cooling mode to remove decay heat Prof qualifications encl
JONES, R C Metropolitan Edison Co 83/02/16 27pp 17233 050
24X Fiche 50-289, 83/02/16, 8302220347

8302220375 Testimony of GR Capodanno & RJ Chisholm re ALAB-708, Issue 8 on safety-grade status of emergency feedwater sys Status of safety-grade classification of sys unchanged from previous submittal to ASLB & ASLAB Prof qualifications encl
CAPODANNO, G R, CHISHOLM, R J Metropolitan Edison Co 83/02/16 10pp 17233 077 24X Fiche 50-289, 83/02/16, 8302220347

8302220381 Testimony of RC Jones & LC Lanese re ALAB-708, Issue 9 on reliance on feed & bleed cooling Prof qualifications encl
JONES, R C, LANESE, L C Metropolitan Edison Co 83/02/16 10pp 17233 087 24X Fiche 50-289, 83/02/16, 8302220347

8302220387 Memorandum of law re ALAB-708, Issue 9 on reliance on feed & bleed cooling Reviews 1 explains testimony & position on feed & bleed
BAXTER, T A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 83/02/16 4pp 17233 097 24X
Fiche 50-289, 83/02/16, 8302220347

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302240039 Forwards findings of independent investigation of operator qualifications from 1979-82 Names, employee numbers, social security numbers & reactor operator/senior reactor operator license numbers deleted
ARNOLD, R C General Public Utilities - GPU Service Corp 83/01/31
DEYOUNG, R C Office of International Programs, Director 1, 116pp
17281 043 24X Fiche 50-289, 83/01/31, 8302240039

8302090407 Forwards Procedure 6210-ADM-2550 01, "Control of Exams for Units 1 & 2," Rev 0, in response to ASLB 820727 partial initial decision requiring procedure for routine sampling & review of exam answers for evidence of cheating
HAMIL, H D General Public Utilities - GPU Service Corp 83/02/07
STOL, J F Operating Reactors Branch 4 1p 17071 076 24X
Fiche 50-289, 83/02/07, 8302090407

8302090410 Procedure 6210-ADM-2550 01, "Control of Exams for Units 1 & 2," Rev 0
* General Public Utilities - GPU Service Corp 83/02/07 6pp
17071 077 24X Fiche 50-289, 83/02/07, 8302090407

DOCKET 50-290 PROOF TEST FACILITY

F Security, medical, emergency & fire protection plans

8302140076 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21)
MILLS, L H Tennessee Valley Authority 83/02/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17141 212 24X
Fiche 50-259, 83/02/04, 8302140076

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302100318 Ack receipt of 820519 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-293/82-02 & 50-293/82-03
MARTIN, T T Division of Engineering & Technical Programs 83/01/27
HARRINGTON, W D Boston Edison Co 3pp 17116 329 24X
Fiche 50-293, 83/01/27, 8302100318

8302100342 Responses to NRC 820429 ltr re violations noted in IE Insp Repts 50-293/82-02 & 50-293/82-03 Corrective actions
Gould Brush recorder recalibr Safeguards info deleted (ref 10CFR73 21)
HARRINGTON, W D Boston Edison Co 82/05/19 MARTIN, T T
Division of Engineering & Technical Programs 7pp 17116-332
24X Fiche 50-293, 83/01/27, 8302100318

DOCKETED ITEMS

121

8302220170 Forwards Rev 2 of safeguards contingency plan Rev withheld (ref 10CFR73 21)
HARRINGTON, W D Boston Edison Co 83/01/28 Office of Nuclear
Reactor Regulation, Director 1p 17233 134 24X
Fiche 50-293, 83/01/28, 8302220170

8302150350 Advises that loss of copy of physical security plan on 820505 constitutes violation Notice of violation forwarded as civil penalty imposed Response within 30 days required
HARRINGTON, W D Division of Engineering & Technical Programs 83/01/31
HARRINGTON, W D Boston Edison Co 2pp 17135 223 24X
Fiche 50-293, 83/01/31, 8302150350

--8302150358 Notice of violation from internal audit on 820506 Noncompliance noted site security plan missing from secondary alarm station & not yet located
Region I, Office of Director 83/01/31 1p 17155 225 24X
Fiche 50-293, 83/01/31, 8302150350

8302170066 Denies 820625 request for exemption from requirements of 10CFR53.4B & Section III C of App R to 10CFR50.1f extension necessary after details or configuration & completion schedules are known, request for exemption should be filed
EISENHUT, D O Division of Licensing 83/01/31 MORISI, A V Boston Edison Co 3pp 17191 072 24X Fiche 50-293, 83/01/31, 8302170066

8302170340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl I, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8302170340

8302080366 Requests Class III fee be remitted re util 821215 application resulting in Amend 66 to License DPR-35, changing Tech Specs on penetration fire barrier
DIOGOS, R M License Fee Management Branch 83/02/01 MORISI, A V Boston Edison Co 1p 17107 144 24X Fiche 50-293, 83/02/01, 8302080366

8302140090 Responds to NRC 830107 ltr re violations noted in IE Insp Rept 50-293/82-29 Corrective actions withheld (ref 10CFR73 21)
HARRINGTON, W D Boston Edison Co 83/02/04 STAROSTECKI, R Division of Project & Resident Programs 1p 17141 213 24X
Fiche 50-293, 83/02/04, 8302140090

General correspondence

8302090561 FOIA request for four categories of documents re Facility SHOTWELL, J Massachusetts, Commonwealth of, 82/11/08 Office of Administration 2pp 17131 311 24X Fiche 50-293, 82/11/08, 8302090561

Insurance & indemnity information

8302170261 Forwards summons / complaint re MA Caputo, et al vs Boston Edison Co Investigation commenced Info requested from util re 830225 incident at Facility & resulting radiation exposures
HARRINGTON, W D American Nuclear Insurers 83/02/08 SALTZMAN, J Assistant Director for State & Licensee Relations 11pp 17183 327 24X Fiche 50-293, 83/02/08, 8302170261

Operating license stage documents & correspondence

8302090590 Responds to FOIA request for four categories of documents re facility Forwards documents listed in app Documents also available in PDR
FELTGM, J M Division of Rules and Records 83/01/11 SHOTWELL, J Massachusetts, Commonwealth of, 2pp 17131 317 24X
Fiche 50-293, 83/01/11, 8302090590

--8312220893 Informs of IE study re P-32 & Fe-55 levels in aquatic environ Detectable concentration of Fe-55 found in one mussel Recommends program be discontinued Analysis should be performed as state program List of releases encl
MOTTAM, J J Region I, Philadelphia, Office of the Director (81/03/01) 81/10/22 COHEN, L K Reactor Radiological Safety Section 9pp 17131 316 24X Fiche 50-293, 83/01/11, 8302090590

--8302090594 Revises 811022 memo re Fe-55 & P-32 in marine pathway Sample containing Fe-55 taken from Sampling Site 15 on 800111 Result not related to LER re 800110 mussel sample
MOTTAM, J J Division of Emergency Preparedness & Operational Support 81/10/26 COHEN, L K Reactor Radiological Safety Branch 1p 17131 315 24X Fiche 50-293, 83/01/11, 8302090590

8302170019 Forwards documentation supporting justification for continued operation or operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302180248 Informs that util 820208 submittal re environ qualification of electric equipment is responsive to deficiencies identified & provides technically sound bases for justification for continued operation
ECCLESTON, K T Operating Reactors Branch 2 82/02/26 NOVAK, T H Assistant Director for Operating Reactors 4pp 17196 328 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170176 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
ECCLESTON, K T Operating Reactors Branch 2 82/10/28 EISENHUT, D O Division of Licensing 2pp 17196 326 24X
Fiche 50-000, 83/01/18, 8302170019

8302030289 Notifies that addl time required to complete NUREG-0737, Item II B 3, "Post-Accident Sampling," due to design mods, utilization of newly selected const contractor & integrated scheduling constraints Item will be completed by 840601
BALI ENTINE, J Boston Edison Co 83/01/28 VASSALLO, D B Operating Reactors Branch 2 1p 17001 261 24X Fiche 50-293, 83/01/28, 8302030289

8302080366 Requests Class III fee be remitted re util 821215 application resulting in Amend 66 to License DPR-35, changing Tech Specs on penetration fire barrier
DIOGOS, R M License Fee Management Branch 83/02/01 MORISI, A V Boston Edison Co 1p 17107 144 24X Fiche 50-293, 83/02/01, 8302080366

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - CPU Service Corp 5pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302160115 Notification 83-10 of 830214 mgt meeting w/util in Plymouth, MA to discuss plant operations & to tour site.
ELSASSER, T Division of Project & Resident Programs 83/02/03 Division of Project & Resident Programs 1p 17160 295 24X
Fiche 50-293, 83/02/03, 8302160115

8302080160 Provides justification for noncompliance w/NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Sys." Addition of auto switchover unnecessary Existing procedures adequate
HARRINGTON, W D Boston Edison Co 83/02/04 VASSALLO, D B Operating Reactors Branch 2 2pp 17058 359 24X
Fiche 50-293, 83/02/04, 8302080160

8302080192 Forwards fee for two Class II proposed Tech Spec changes contained in 830114 ltr
HARRINGTON, W D Boston Edison Co 83/02/04 VASSALLO, D B Operating Reactors Branch 2 1p 17058 358 24X
Fiche 50-293, 83/02/04, 8302080192

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

DOCKETED ITEMS

- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee. Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304
- 8302230190 Submits addl info re containment purge & vent isolation valves, per NRC 820730 request Jet & debris deflectors not installed in torus penetrations since objects are individually anchored
HARRINGTON, W D Boston Edison Co 83/02/15 VASSALLO, D B
Operating Reactors Branch 2 5pp 17245 095 24X
Fiche 50-293, 83/02/15, 8302230190
- 8302250058 Responds to 821220 ltr re review of NUREG-0737, Item I C 4, "Guidance in ANSI/ANS 3.2-1982" Plan developed to modify policy considering ALARA Corrective action will be submitted by 830513 Delay due impact of changes
HARRINGTON, W D Boston Edison Co 83/02/15 VASSALLO, D B
Operating Reactors Branch 2 1p 17293 340 24X
Fiche 50-293, 83/02/15, 8302250058
- 8302250423 Advises that until reviewing 10CFR50.49 re environ qualification of safety-related electrical equipment & will advise by 830324 whether to reaffirm or withdraw request for hearing
QAD, R K Ropes & Gray 83/02/22 EISENHUT, D O Division of Licensing 1p 17298 234 24X Fiche 50-293, 83/02/22, 8302250423
- 0 Inspection reports, IE Bulletins & correspondence
- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8302100318 Ack receipt of 820519 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-293/82-02 & 50-293/82-03
MARTIN, T T Division of Engineering & Technical Programs 83/01/27
HARRINGTON, W D Boston Edison Co 3pp 17116 329 24X
Fiche 50-293, 83/01/27, 8302100318
- 8302100342 Responds to NRC 820429 ltr re violations noted in IE Insp Repts 50-293/82-02 & 50-293/82-03 Corrective actions
Gould Brush recorder recalibr Safeguards info deleted (ref 10CFR73.21)
HARRINGTON, W D Boston Edison Co 82/05/19 MARTIN, T T
Division of Engineering & Technical Programs 7pp 17116 332 24X Fiche 50-293, 83/01/27, 8302100318
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H26C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360
- 8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361
- 8302140090 Responds to NRC 830107 ltr re violations noted in IE Insp Rept 50-293/82-29 Corrective actions withheld (ref 10CFR73.21)
HARRINGTON, W D Boston Edison Co 83/02/04 STAROSTEKL, R
Division of Project & Resident Programs 1p 17141 213 24X
Fiche 50-293, 83/02/04, 8302140090
- 1302230254 Forwards IE Insp Rept 50-293/83-03 on 821221-830124 No noncompliance noted
STAROSTEKL, R Division of Project & Resident Programs 83/02/07
HARRINGTON, W D Boston Edison Co 2pp 17245 001 24X
Fiche 50-293, 83/02/07, 8302230254
- 8302230259 IE Insp Rept 50-293/82-32 on 821221-830124 No noncompliance noted, Major areas inspected, followup on previous findings, operational safety verification, Followup of events & review of surveillance & maint activities
JOHNBOH, J, EICHENHOLZ, H, ELBASSER, T Division of Project & Resident Programs 83/02/04 18pp 17245 003 24X
Fiche 50-293, 83/02/07, 8302230254
- 8302170408 Notification of 830224 significant licensee meeting w/util in King of Prussia, PA to discuss licensee response to NRC order
ELBASSER, T Region 1, Office of Director 83/02/09 Region 1, Office of Director 1p 17195 245 24X Fiche 50-293, 83/02/09, 8302170408
- 8302230642 Provides addl response to IE Bulletin 80-11 re two refuelers in 820929 ltr, following tour on 820616 & 17 to observe block walls Engineering assessment of 11 walls indicates no localized wall failures due to jet impingement
HARRINGTON, W D Boston Edison Co 83/02/15 VASSALLO, D B
Operating Reactors Branch 2 2pp 17255 185 24X
Fiche 50-293, 83/02/15, 8302230642
- 8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Unit" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363
- 8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365
- 8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366
- R Periodic operating reports & related correspondence
- 8302090590 Responds to FOIA request for four categories of documents re Facility Forwards documents listed in app Documents also available in PDR
FELTON, J M Division of Rules and Records 83/01/11 SHOTWELL, J
Massachusetts, Commonwealth of 2pp 17131 313 24X
Fiche 50-293, 83/01/11, 8302090590
- 8302090605 'Environ Radiation Monitoring Program Dosimeter Placement' Collection Data Sheet, 800402-04
VERERAYE, CHIN, P, SWISBARD, Q Boston Edison Co 80/04/10 8pp 17131 325 24X Fiche 50-293, 83/01/11, 8302090590
- 8302090609 'Environ Radiation Monitoring Program Dosimeter Placement' Collection Data Sheet, 800929-30
SLODOWIE, M, CHIN, P Boston Edison Co 80/10/02 4pp 17131 333 24X Fiche 50-293, 83/01/11, 8302090590
- 8302093617 'Environ Radiation Monitoring Program Dosimeter Placement' Collection Data Sheet, 800630
CHIN, P, SWISBARD, Q Boston Edison Co 80/07/14 4pp 17131 337 24X Fiche 50-293, 83/01/11, 8302090590
- B Reportable occurrences, LERs & related correspondence
- 8302010335 LER 83-002/014-0 on 830116, while clearing off-normal alarm for flow comparators, average power range monitor Flux scram trip settings found in nonconservative direction Caused by drafting proportional amplifiers Settings checked daily
WHITNEY, Q O Boston Edison Co 83/01/17 HAYNES, R C Region 1
Office of Director 1p 16973 022 24X Fiche 50-293, 83/01/17, 8302010335
- 8302100398 Forwards LER 83-001/03L-0
MATHIS, C J Boston Edison Co 83/01/27 HAYNES, R C Region 1
Office of Director 1p 17111 281 24X Fiche 50-293, 83/01/27, 8302100398
- 8302100395 LER 83-001/03L-0 on 830105, inboard reactor water sample isolation valve AD-220-44 did not close Cause will be investigated during next outage
WHITNEY, Q O Boston Edison Co 83/01/27 Region 1, Office of Director 1p 17111 282 24X Fiche 50-293, 83/01/27, 8302100395
- 8302070464 Forwards LER 83-002/01T-0
MATHIS, C J Boston Edison Co 83/01/28 HAYNES, R C Region 1
Office of Director 1p 17037 077 24X Fiche 50-293, 83/01/28, 8302070464
- 8302070467 LER 83-002/01T-0 on 830116, flow ref off-normal alarm received Average power range monitor Flux scram trip settings affected Cause under investigation Flow inputs monitored & amplifier B recalibr
WHITNEY, Q O Boston Edison Co 83/01/28 Region 1, Office of Director 1p 17037 078 24X Fiche 50-293, 83/01/28, 8302070467
- 8302220391 Forwards LER 83-004/03L-0
MATHIS, C J Boston Edison Co 83/02/10 HAYNES, R C Region 1
Office of Director 1p 17232 180 24X Fiche 50-293, 83/02/10, 8302220391

DOCKETED ITEMS

123

--B302220375 LER 83-004/03L-0 on 830117, reactor pressure sys (RPS) breaker 5 ACB 1A overheated causing RPS A to trip & initiating half scram to reactor Caused by high internal resistance Breaker replaced
MITNER, G O Boston Edison Co 83/02/10 Region 1, Office of Director 1p 17232 151 24X Fiche 50-295, 83/02/10, 8302220391

B302220348 Forwards LER 83-003/03L-0
MATHIS, C J Boston Edison Co 83/02/11 HAYNES, R C Region 1, Office of Director 1p 17232 014 24X Fiche 50-295, 83/02/11, 8302220348

--B302220351 LER 83-003/03L-0 on 830113, during surveillance test, reactor water cleanup sys high rlpw isolation DPIS-1243 found out of calibr Caused by loose switch plant locking screw which allowed setpoint to drift Setpoint recalibr
MITNER, G O Boston Edison Co 83/02/11 Region 1, Office of Director 1p 17232 015 24X Fiche 50-295, 83/02/11, 8302220348

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, FS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

V Operator Examinations

B302250175 Requests licensing exams be administered to MW Mitchell & M Heimanmann Exams should be conducted during wk of 830320 or 24
WILKINSON, B W Michigan State Univ 83/02/18 Office of Nuclear Reactor Regulation, Director 1p 17293 061 24X Fiche 50-294, 83/02/18, 8302250175

--B302250177 Requests exam for senior reactor operator license
MITCHELL, M Michigan State Univ 83/02/18 Office of Nuclear Reactor Regulation, Director 1p 17293 062 24X Fiche 50-294, 83/02/18, 8302250175

--B302250180 Requests exam for reactor operator license
HEIMANN, M Michigan State Univ 83/02/18 Office of Nuclear Reactor Regulation, Director 1p 17293 063 24X Fiche 50-294, 83/02/18, 8302250175

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B210150452 Forwards reviews of procedures proposed by utils in emergency plans to consider meteorological conditions at facilities, in response to Task Order 1 of interagency agreement
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC 03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X Fiche 50-000, 82/10/08, 8210150452

--B301270044 Evaluation of Procedures Proposed by Commonwealth Edison Co in Emergency Plans to Consider Meteorological Conditions in Zion Plant Coastal Environ
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC 03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 307 24X Fiche 50-000, 82/10/08, 8210150452

B302030137 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/26 Document Management Branch 1p 17023 313 24X Fiche 50-295, 83/01/26, 8302030137

--B302030139 Forwards public version of Rev 9 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List"
PLINN, G Commonwealth Edison Co 83/01/17 DENTON, H R NRC - No Detailed Affiliation Given 1p 17023 314 24X Fiche 50-295, 83/01/26, 8302030137

--B302030143 Public version of Rev 9 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List" Revised index encl
Commonwealth Edison Co 83/01/14 9pp 17023 315 24X Fiche 50-295, 83/01/26, 8302030137

B302030226 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17013 343 24X Fiche 50-295, 83/01/27, 8302030226

--B302030238 Forwards public version of Rev 10 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group"
PLINN, G Commonwealth Edison Co 83/01/05 DENTON, H R NRC - No Detailed Affiliation Given 1p 17013 344 24X Fiche 50-295, 83/01/27, 8302030226

--B302030245 Public version of Rev 10 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group"
Commonwealth Edison Co 82/12/20 6pp 17013 345 24X Fiche 50-295, 83/01/27, 8302030226

B302030622 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17013 087 24X Fiche 50-295, 83/01/27, 8302030622

--B302030624 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 510-2, "Generating Station Emergency Plan Training Requirements for Rad/Chem Technicians"
PLINN, G Commonwealth Edison Co 82/12/23 DENTON, H R NRC - No Detailed Affiliation Given 1p 17013 088 24X Fiche 50-295, 83/01/27, 8302030622

--B302030626 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 510-2, "Generating Station Emergency Plan Training Requirements for Rad/Chem Technicians" Revised index encl
WILLIAMS, V S Commonwealth Edison Co 82/12/21 7pp 17013 089 24X Fiche 50-295, 83/01/27, 8302030622

B302040033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--B302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs
PAJOWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC - No Detailed Affiliation Given 1p 17043 231 24X Fiche 50-000, 83/01/27, 8302040033

--B302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs Revised index encl
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

B302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise, NUREG-0696 & SECY-82-1112 guidelines valid
KEPPLER, J O Region 3, Office of Director 83/02/04 REED, C, Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--B302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, G Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

B302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

DOCKETED ITEMS

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager " MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X Fiche 50-030, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager " MELLIS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302180518 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17221 249 24X Fiche 50-295, 83/02/15, 8302180518

--8302180520 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 410-1, "Onsite Support Ctr " Receipt form encl PLIKL, C Commonwealth Edison Co 83/01/21 DENTON, H R NRC - No Detailed Affiliation Given 3pp 17221 250 24X Fiche 50-295, 83/02/15, 8302180518

--8302180541 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 410-1, "Onsite Support Ctr " Revised index encl * Commonwealth Edison Co 83/01/21 4pp 17221 253 24X Fiche 50-295, 83/02/15, 8302180518

8302280349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request PAPERLELD, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302280349

--8302280361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities. Lists of locations encl SHARTZ, E B Commonwealth Edison Co 83/01/28 KEPPLER, J G Region 3, Office of Director 4pp 17291 074 24X Fiche 50-030, 83/02/18, 8302280349

P Operating license stage documents & correspondence

8302240073 Partial response to FOIA request for all prior & partial prior drafts & memos of probabilistic safety study. Forwards documents listed in app Search for addl records in progress FELTON, J M Division of Rules and Records 83/01/13 BLUM, J M Union of Concerned Scientists 2pp 17285:002 24X Fiche 50-000, 83/01/13, 8302240073

--8302240082 "Accumulator Sys." revised draft chapter for PRA * Pickard, Loue & Garrick, Inc 81/01/06 14pp 17285 004 24X Fiche 50-000, 83/01/13, 8302240073

--8302240087 "Reactor Protection Sys." revised draft chapter for PRA * Pickard, Loue & Garrick, Inc 81/01/06 27pp 17285 018 24X Fiche 50 000, 83/01/13, 8302240073

8302090135 Forwards Containment Sys Branch SER of util 800508 & 820923 analyses of main steam line break w/continued feedwater addition. Analyses acceptable VARQA, S A Operating Reactors Branch 1 83/01/26 DELGEORGE, L D Commonwealth Edison Co 2pp 17119 326 24X Fiche 50-295, 83/01/26, 8302090135

--8302090142 Containment Sys Branch SER supporting util 800508 & 820923 analyses of main steam line break w/continued feedwater addition * Containment Systems Branch 83/01/26 7pp 17119 328 24X Fiche 50-295, 83/01/26, 8302090135

--8212200078 "PWR Main Steam Line Break W/Continued Feedwater Addition (8-69), Zion Station Units 1 & 2," technical evaluation rept VOSSUR, F W Franklin Institute/Franklin Research Center. NRC-03-81-130 TER-C5506-144 82/12/15 HEARN, P NRC - No Detailed Affiliation Given. 24pp 17119:335 24X Fiche 80-295, 83/01/26, 8302090135.

8302090483 Forwards safety evaluation on post-accident sampling sys Plant meets five of 11 criteria in NUREG-0737, Item II. B 3 Deficiencies listed VARQA, S A Operating Reactors Branch 1. 83/01/27 DELGEORGE, L D Commonwealth Edison Co 22pp 17108 203 24X Fiche 50-295, 83/01/27, 8302090483

8302080386 Notification of 830228 meeting w/util in Bethesda, MD to discuss eval mgt program for upcoming reload NORRIS, J A Operating Reactors Branch 1 83/02/02 VARQA, S A Operating Reactors Branch 1 2pp 17107 360 24X Fiche 50-295, 83/02/02, 8302080386

8302280044 Forwards safety evaluation of util commitments to correct human engineering deficiencies Submittal inconsistent w/util verbal proposals Three deficiencies described Response due in 30 days VARQA, S A Operating Reactors Branch 1 83/02/04 DELGEORGE, L D Commonwealth Edison Co 2pp 17314 284 24X Fiche 50-295, 83/02/04, 8302280054

--8302280059 Safety evaluation re util commitments to correct human engineering deficiencies Commitments inconsistent w/util verbal proposals * Office of Nuclear Reactor Regulation, Director 83/02/04 6pp 17314 226 24X Fiche 50-295, 83/02/04, 8302280064

8302090457 Resubmits 830105 ltr re final rept on results of containment purge valve operability LENTINE, F O Commonwealth Edison Co 83/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17066 144 24X Fiche 50-295, 83/02/07, 8302090457

--8302090464 Forwards Analysis of 42-inch RIAB Class 75 Butterfly Valves, " final rept, Vol 1 Valve structural elements have sufficient stress margins to withstand loads imposed while valve closes from fully open position LENTINE, F O Commonwealth Edison Co 83/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17066 145 24X Fiche 50-295, 83/02/07, 8302090457

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302090385 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TH1 Action Item II K 3 5. "Automatic Trip of Reactor Coolant Pumps " Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302240228 Forwards request for addl info re NUREG-0737, Items II F 1 4, "Containment Pressure Monitors," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Info expected within 30 days of ltr receipt VARQA, S A Operating Reactors Branch 1 83/02/08 DELGEORGE, L D Commonwealth Edison Co 7pp 17289 190 24X Fiche 50-295, 83/02/08, 8302240228

8302180417 Application to amend Licenses DPR-39 & DPR-48, deleting all nonradiological water quality specs from App B Tech Specs LENTINE, F O Commonwealth Edison Co 83/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17215 126 24X Fiche 50-295, 83/02/10, 8302180417

8302230159 Requests withholding of mail provided to NRC & consultants for preparation of technical evaluation repts re environ qualification of electrical equipment Status of manufacturer reviews will be submitted by 830515 LENTINE, F O Commonwealth Edison Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17245 043 24X Fiche 50-295, 83/02/17, 8302230159

8302280400 Forwards "Residual Strength of Inconel 600 Tubes W/Longitudinal Discontinuities " LENTINE, F O Commonwealth Edison Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17309 346 24Y Fiche 50-295, 83/02/18, 8302280400

--8302280404 "Residual Strength of Inconel 600 Tubes W/Longitudinal Discontinuities " BEALEY, J A Westinghouse Electric Corp 82/12/31 41pp 17309 350 24X Fiche 50-295, 83/02/18, 8302280400

DOCKETED ITEMS

125

8302280152 Advises that review of 830121 final rule on environ-
qualification of safety-related electrical equipment
incomplete. Determination whether to reaffirm or withdraw
hearing request will be provided by 830324
STEPTOE, P P Isham, Lincoln & Beale 83/02/23 EISENHUT, D O
Division of Licensing 1p 17306 076 24X Fiche 50-000, 83/02/23,
8302280152

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents
re facilities Personal info deleted from documents re util/
contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTZ, J M Division of Rules and Records 82/12/30 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040032 Forwards 1981 comparison data for operating & const plants,
consisting of total numbers of noncompliance items, repts
issued, insp hours, severity levels, points & hours per rept &
item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302150432 Forwards IE Insp Repts 50-295/82-30 & 50-304/82-27 on
821205-13 & notice of violation Differing insp dates noted
throughout package
HIND, J A Division of Emergency Preparedness & Operational Support
83/01/17 REED, C Commonwealth Edison Co 3pp 17158 226 24X
Fiche 50-295, 83/01/17, 8302150432

--8302150437 Notice of violation from insp on 821206-16
HIND, J A Division of Emergency Preparedness & Operational
Support 83/01/12 1p 17158 229 24X Fiche 50-295, 83/01/17,
8302150432

--8302150450 IE Insp Repts 50-295/82-30 & 50-304/82-27 on 821206-16
Noncompliance noted failure to have approved procedure for
SAR determination required by Tech Spec 6.2 A 7
ROZAK, S, NICHOLSON, N A, OESTHANN, M J Division of Emergency
Preparedness & Operational Support 83/01/10 8pp 17158 230
24X Fiche 50-295, 83/01/17, 8302150432

8302010620 Ack receipt of 821202 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-295/81-32 &
50-304/81-30 Summary of 830112 meeting re clarification of
licensee action encl
KEPPLER, J O Region 3, Office of Director 83/01/24 REED, C
Commonwealth Edison Co 3pp 16980 292 24X Fiche 50-295, 83/01/24,
8302010620

--8302010629 Responds to NRC 821102 ltr re violations noted in IE Insp
Repts 50-295/81-32 & 50-304/81-30 Corrective actions
Awareness Day Program revised, drug policy meetings initiated
& presentation on harmful effects of drugs given
REED, C Commonwealth Edison Co 82/12/02 KEPPLER, J O Region
3, Office of Director 26pp 16980 297 24X
Fiche 50-295, 83/01/24, 8302010620

8212040358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212040358

8212040360 IE Info Notice 83-02, "Limitorque H08C, H10C, H20C & H30C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212040360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to
10CFR50.54 & 50.55 IE will conduct formal presentation
followed by question & answer session Requests that
participation be limited to three people
SPESCAARD, R L Division of Engineering 83/01/28 Commonwealth
Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302150528 Requests delay until 830328 to respond to NRC request for
supplemental info re Repts (a), (b), (c) & (e) of IE Bulletin
81-03, "Flow Blockage of Cooling Water to Safety-Related Sys
Components by Asiatic Clams & Mussels "
SHARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000, 83/02/08, 8302150528

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units. "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302170159 Forwards monthly operating repts for Jan 1983
GRAESSER, K L Commonwealth Edison Co 83/02/09 Director's
Office, Office of Inspection and Enforcement. 1p 17180 304 24X
Fiche 50-295, 83/02/09, 8302170159

--8302170163 Monthly operating repts for Jan 1983
AUSTIN, G Commonwealth Edison Co 83/02/09 11pp 17180 305
24X Fiche 50-295, 83/02/09, 8302170159

B Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen
recombiner is likely to malfunction following exposure
to elevated temp, high humidity environ Replacement part
identification will be provided to operators by 830218.
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J
Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

8302010173 Forwards LER 82-051/03L-0
GRAESSER, K L Commonwealth Edison Co 83/01/25 KEPPLER, J O
Region 3, Office of Director 1p 16974 020 24X
Fiche 50-295, 83/01/25, 8302010173

--8302010185 LER 82-051/03L-0 on 821225, steam generator 1A steam flow
channel IF-512 observed to be reading low w/ respect to
redundant steam flow channel IF-513 Caused by sensing line
plugging on transmitter IFT-512 Sensing line cleared.
CANINELL, P F Commonwealth Edison Co 83/01/25 Region 3,
Office of Director 1p 16974 021 24X Fiche 50-295, 83/01/25,
8302010173

8302180152 Forwards LER 83-002/01T-0
GRAESSER, K L Commonwealth Edison Co 83/02/10 KEPPLER, J O
Region 3, Office of Director 1p 17216 219 24X
Fiche: 50-295, 83/02/10, 8302180152

--8302180159 LER 83-002/01T-0 on 830131, diesel generator O failed to
accept load greater than 50% during operability check for
taking RHR 2A out of svc Caused by seized up Cooper-Bessemer
turbocharger ET-18EK9V Turbocharger replaced
FANNINO, O Commonwealth Edison Co 83/02/10, Region 3, Office
of Director 2pp 17216 220 24X Fiche 50-295, 83/02/10,
8302180152

8302250187 Forwards LER 83-001/03L-0
GRAESSER, K L Commonwealth Edison Co 83/02/17 KEPPLER, J O
Region 3, Office of Director, 1p 17293 036 24X
Fiche 50-295, 83/02/17, 8302250187

--8302250190 LER 83-001/03L-0 on 830123, containment purge exhaust stack
monitor IRTPR09A failed to respond to check source or to
manual bug Caused by stuck meter movement. Movement replaced
& pc board contacts cleaned
WILLIAMS, V S Commonwealth Edison Co 83/02/17 Region 3,
Office of Director 1p 17293 037 24X Fiche 50-295, 83/02/17,
8302250187

8302280470 Forwards LER 83-004/03L-0
GRAESSER, K L Commonwealth Edison Co 83/02/18 KEPPLER, J O
Region 3, Office of Director 1p 17309 230, 24X
Fiche: 50-295, 83/02/18, 8302280470

--8302280476 LER 83-004/03L-0 on 830121, during routine calibr,
containment ventilation gas monitor IRE-0012 found reading
low Caused by electronic instrument drift Radiation monitor
recalibr
WILLIAMS, V S Commonwealth Edison Co 83/02/18 Region 3,
Office of Director 1p 17309 231 24X Fiche: 50-295, 83/02/18,
8302280470

DOCKETED ITEMS

8302280329 Forwards updated LER 82-040/99X-2
 GRAESSER, K.L. Commonwealth Edison Co 83/02/18 KEPLER, J O
 Region 3, Office of Director 1p 17309 023 24X
 Fiche 50-295, 83/02/18, 8302280329

--8302280536 Updated LER 82-040/99X-2 on 821023.0A fire pump taken out
 of svc Seven days later pump still inoperable Caused by
 redundancy via svc water booster pumps Pump repaired
 NYKIEL, A Commonwealth Edison Co 83/02/18 Region 3, Office
 of Director 1p 17309 024 24X Fiche 50-295, 83/02/18,
 8302280536

8302280473 Forwards LER 83-005/03L-0
 GRAESSER, K.L. Commonwealth Edison Co 83/02/23 KEPLER, J O
 Region 3, Office of Director 1p 17308 063 24X
 Fiche 50-295, 83/02/23, 8302280473

--8302280480 LER 83-005/03L-0 on 830124. rad monitor IRT-PR-26 (asr
 eye for particulate) failed loc Caused by flooding of
 detector pig Personnel instructed to check moisture traps
 more frequently after startups
 JAKUBAITIS, T C Commonwealth Edison Co 83/02/23 Region 3,
 Office of Director 1p 17308 064 24X Fiche 50-295, 83/02/23,
 8302280473

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
 for DLs, NSS vendors, reactor vendors & AE re certificates
 & revised format for reactor operator & senior reactor
 operator licenses Svc list encl
 EISENHUT, D O Division of Licensing 83/01/31. Consolidated
 Edison Co of New York, Inc 11pp 17347 177. 24X
 Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8302030057 Releases public version of revised radiological emergency
 notification directory
 FELTON, J.M. Division of Rules and Records 83/01/28. Document
 Management Branch 1p 17026 344 24X Fiche 50-259, 83/01/28,
 8302030057

--8302030062 Forwards public version of Rev B to radiological emergency
 notification directory
 MILLS, L.M. Tennessee Valley Authority 83/01/06 DENTON, H R
 Office of Nuclear Reactor Regulation, Director. 5pp 17026 345
 24X Fiche 50-259, 83/01/28, 8302030057

--8302030065 Public version of Rev B to radiological emergency
 notification directory.
 * Tennessee Valley Authority 82/12/16 15pp 17026 351 24X
 Fiche 50-259, 83/01/28, 8302030057

8302030627 Releases public version of revised radiological emergency
 notification directory
 FELTON, J.M. Division of Rules and Records 83/01/31 Document
 Management Branch 1p 17013.320. 24X Fiche 50-259, 83/01/31,
 8302030627

--8302030628 Forwards public version of Rev 9 to radiological emergency
 notification directory
 MILLS, L.M. Tennessee Valley Authority 83/01/11 DENTON, H R
 Office of Nuclear Reactor Regulation, Director. 1p 17013 321
 24X Fiche 50-259, 83/01/31, 8302030627

--8302030629 Public version of Rev 9 to radiological emergency
 notification directory
 SLIOER, E.K. Tennessee Valley Authority 83/01/06 5pp
 17013.322 24X Fiche 50-259, 83/01/31, 8302030627.

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
 applicants for DL & holders of CPs re regional workshop
 concerning Suppl I, NUREG-0737, "Requirements for Emergency
 Response Capability" Svc list encl
 EISENHUT, D O Division of Licensing 83/02/01 Consolidated
 Edison Co. of New York, Inc 11pp. 17221-226 24X
 Fiche 50-000, 83/02/01, 8301210340.

8302100330 Application for amend to Licenses DPR-33, DPR-52 & DPR-68,
 changing Tech Specs to add requirement to audit safeguards
 contingency plan at least once every 12 months per Generic
 Ltr 82-23.
 MILLS, L.M. Tennessee Valley Authority 83/02/01. DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 2pp 17116 314
 24X Fiche 50-259, 83/02/01, 8302100330

--8302100332 Proposed Tech Specs requiring audit of safeguards
 contingency plan at least once every 12 months
 * Tennessee Valley Authority 83/02/01 4pp 17116 316 24X
 Fiche 50-259, 83/02/01, 8302100330

8302170225 Grants exemption from 10CFR50.4B & App R to 10CFR50
 requirements re fire protection, per 830426 request
 VASSALLO, D.B. Operating Reactors Branch 2 83/02/04 PARRIS, H O
 Tennessee Valley Authority 2pp 17195 360 24X
 Fiche 50-259, 83/02/04, 8302170225

--8302170229 Exemption from 10CFR50.4B & App R to 10CFR50 requirements re
 fire protection
 EISENHUT, D O Division of Licensing 83/02/04 Tennessee
 Valley Authority 7pp 17195 362 24X Fiche 50-259, 83/02/04,
 8302170225

8302150325 Forwards IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01
 & 50-276/83 01 on 830103-07 No noncompliance noted
 VERRELLI, D Division of Project & Resident Programs 83/02/07
 PARRIS, H O Tennessee Valley Authority 2pp 17157 167 24X
 Fiche 50-259, 83/02/07, 8302150325

--8302150346 IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 &
 50-276/83 01 on 830103-07 No noncompliance noted Major areas
 inspected security plan & implementing procedures & security
 program audit Details withheld (ref 10CFR73.21)
 MOORE, D.E. Division of Emergency Preparedness & Materials Safety
 83/02/03 1p 17157 169 24X Fiche 50-259, 83/02/07, 8302150325

P Operating license stage documents & correspondence

8302010614 Forwards item-by-item description of responses to NRC 821028
 conference call request for info re compliance w/NUREG-0612,
 Section 3.1, "General Provisions for Load Handling,"
 requirements
 KAMMER, D.B. Tennessee Valley Authority 83/01/25 VASSALLO, D.B.
 Operating Reactors Branch 2 4pp 16980 273 24X
 Fiche 50-259, 83/01/25, 8302010614

8302070087 Forwards safety evaluation re NRC review of util response to
 NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on
 Pump Seals." Util endorsement of BNR Owners Group position
 considered acceptable & matter resolved
 VASSALLO, D.B. Operating Reactors Branch 2 83/01/25 PARRIS, H O
 Tennessee Valley Authority 2pp 17065 293 24X
 Fiche 50-259, 83/01/25, 8302070087

--8302070107 Safety evaluation re BNR Owners Group generic response to
 NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on
 Pump Seals." No mods to seal cooling for recirculation
 pumps required
 MOORE, M. Operating Reactors Branch 2 82/12/01 5pp
 17065 295 24X Fiche 50-259, 83/01/25, 8302070087

8302100330 Application for amend to Licenses DPR-33, DPR-52 & DPR-68,
 changing Tech Specs to add requirement to audit safeguards
 contingency plan at least once every 12 months per Generic
 Ltr 82-23
 MILLS, L.M. Tennessee Valley Authority 83/02/01 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 2pp 17116 314
 24X Fiche 50-259, 83/02/01, 8302100330

--8302100332 Proposed Tech Specs requiring audit of safeguards
 contingency plan at least once every 12 months
 * Tennessee Valley Authority 83/02/01 4pp 17116 316 24X
 Fiche 50-259, 83/02/01, 8302100330

8302170488 Requests schedule for completing TMI Action Items II.F.1.1 &
 II.F.1.2 per Generic Ltrs 82-09 & 82-10 Justification for
 delay in installing monitors required
 VASSALLO, D.B. Operating Reactors Branch 2 83/02/01 PARRIS, H O
 Tennessee Valley Authority 3pp 17203 191 24X
 Fiche 50-259, 83/02/01, 8302170488

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re
 mod of vacuum breakers on Mark I containment Requests
 commitment to submit results of plant-unique calculations
 which formed bases for mod Svc list encl
 EISENHUT, D.O. Division of Licensing 83/02/02 General Public
 Utilities - CPU Service Corp 5pp. 17074 086 24X
 Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
 applicants for DL & holders of CP for C-E PWRs re review of
 C-E Owners Group emergency procedures guideline program Svc
 list encl.
 EISENHUT, D.O. Division of Licensing, 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302230411 Application for amend to Licenses DPR-33, DPR-52 & DPR-6B, deleting environ reporting requirement
MILLS, L M Tennessee Valley Authority 83/02/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17247 218 24X Fiche 50-259, 83/02/11, 8302230411

--8302230414 Proposed Tech Specs deleting environ reporting requirements
Tennessee Valley Authority 83/02/11 31pp 17247 220 24X Fiche 50-259, 83/02/11, 8302230414

8302230413 Forwards revised Figure 8 4-1a of FSAR for insertion Existing Figure 8 4-1a contains safeguards info & should be destroyed
MILLS, L M Tennessee Valley Authority 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17243 217 24X Fiche 50-259, 83/02/17, 8302230413

8302230682 Responds to 830111 request to identify proprietary info in technical evaluation repts on environ qualification of electrical equipment Investigation still underway Partial list of proprietary info encl
MILLS, L M Tennessee Valley Authority 83/02/17 VASSALLO, D B Operating Reactors Branch 2 5pp 17248 328 24X Fiche 50-259, 83/02/17, 8302230682

G Inspection reports, IE Bulletins & correspondence

8302150021 Forwards IE Insp Repts 50-259/82-40, 50-260/82-40 & 50-276/82-40 on 821122-24 & 30-1203 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/05 PARRIS, H G Tennessee Valley Authority 2pp 17148, 040 24X Fiche 50-259, 83/01/05, 8302150021

--8302150024 IE Insp Repts 50-259/82-40, 50-260/82-40 & 50-276/82-40 on 821122-24 & 30-1203 No noncompliance noted Major areas inspected IE Bulletin 82-03, Rev 1, observation of inservice insp work & activities & review of procedures
GLEW, J L, BLAKE, J J Division of Project & Resident Programs 82/12/30 7pp 17148 042 24X Fiche 50-259, 83/01/05, 8302150021

8301180127 Forwards info requested in NRC 821115 ltr re IE Bulletin 80-06, "ESF Reset Controls"
MILLS, L M Tennessee Valley Authority 83/01/13 VASSALLO, D B Operating Reactors Branch 2 3pp 16832 118 24X Fiche 50-259, 83/01/13, 8301180127

8302150065 Updates 821209 response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large Diameter Stainless Steel, Recirculation Sys Piping at BWR Plants"
MILLS, L M Tennessee Valley Authority 83/01/14 O'REILLY, J P Region 2, Office of Director 9pp 17149 334 24X Fiche 50-259, 83/01/14, 8302150065

8302150671 Ack receipt of 830111 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39
LEWIS, R C Division of Project & Resident Programs 83/01/19 PARRIS, H G Tennessee Valley Authority 1p 17151 336 24X Fiche 50-259, 83/01/19, 8302150671

--8302150681 Responds to NRC 821217 ltr re violations noted in IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 Corrective actions observation & updating of radwaste packaging & shipping program will be continued.
MILLS, L M Tennessee Valley Authority 83/01/11 O'REILLY, J P Region 2, Office of Director 3pp, 17151, 337 24X Fiche 50-259, 83/01/19, 8302150671

--8302150498 Forwards IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 on 821025-26 Enforcement action addressed in JP O'Reilly 821217 ltr
VERRELLI, D M Division of Project & Resident Programs 82/12/17 PARRIS, H G Tennessee Valley Authority 2pp, 17151, 344, 24X Fiche 50-259, 83/01/19, 8302150671

--8302150710 IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-276/82-39 on 821025-26 Noncompliance noted failure to ascertain that closure devices of eight 55-gallon drums free from defects
COLLINS, T R, BARR, K P Division of Engineering & Radiological Safety Programs 82/10/29 5pp 17151 346 24X Fiche 50-259, 83/01/19, 8302150671

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 17153-309 24X Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302100160 Forwards Franklin Research Ctr request for addl info on util response to IE Bulletin 80-11 re masonry wall design
Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/01/28 PARRIS, H G Tennessee Valley Authority 5pp 17134 265 24X Fiche 50-259, 83/01/28, 8302100160

8302150309 Ack receipt of 821124 & 830110 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 Interpretation of ASME IWP-6210 requirements will be provided
LEWIS, R C Division of Project & Resident Programs 83/01/28 PARRIS, H G Tennessee Valley Authority 1p 17148 222 24X Fiche 50-259, 83/01/28, 8302150309

--8302150317 Responds to NRC 821021 ltr re violations noted in IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 Corrective actions listing reflecting status of pump & valve test program will be maintained in central location & updated
MILLS, L M Tennessee Valley Authority 83/01/10 O'REILLY, J P Region 2, Office of Director 3pp 17148 223 24X Fiche 50-259, 83/01/28, 8302150309

--8302150326 Responds to NRC 821021 ltr re violations noted in IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 Corrective actions all NDE procedures reviewed for compliance w/ applicable ASME Code specs
MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 6pp 17148 226 24X Fiche 50-259, 83/01/28, 8302150309

--8302150331 Forwards IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 on 820928-1001 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/10/21 PARRIS, H G Tennessee Valley Authority 2pp 17148, 232, 24X Fiche 50-259, 83/01/28, 8302150309

--8302150336 Notice of violation from insp on 820928-1001
* Division of Project & Resident Programs 82/10/21 2pp 17148 234 24X Fiche 50-259, 83/01/28, 8302150309

--8302150342 IE Insp Repts 50-259/82-33, 50-260/82-33 & 50-276/82-33 on 820928-1001 Noncompliance noted inadequate NDE procedures & failure to maintain summary status lists & increase test frequency
OIRARD, E H, BLAKE, J J Division of Engineering & Radiological Safety Programs 82/10/15 8pp 17148, 236 24X Fiche 50-259, 83/01/28, 8302150309

8302150325 Forwards IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-276/83-01 on 830103-07 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/07 PARRIS, H G Tennessee Valley Authority 2pp 17157, 167, 24X Fiche 50-259, 83/02/07, 8302150325

DOCKETED ITEMS

--8302150346 IE Safeguards Insp Repts 50-259/83-01, 50-260/83-01 & 50-296/83-01 on 830103-07 No noncompliance noted Major areas inspected security plan & implementing procedures & security program audit Details withheld (ref 10CFR73 21)
MOORE, D E, STANSBERRY, W W, MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/02/03 1p 17157 169 24X
Fiche 50-259, 83/02/07, 8302150325

8302170505 Forwards draft input for SAMP evaluation for CY82 Evaluation based on experience w/ licensee, util & input solicited from staff Review & comments requested
CLARK, D Operating Reactors Branch 2 83/02/10 EISENHUT, D G Division of Licensing 83/02/10 MATSON, R J Division of Systems Integration (post 811005) 7pp 17197 088 24X
Fiche 50-259, 83/02/10, 8302170505

8302230344 Forwards 830111 response to IE Insp Repts 50-259/82-39, 50-260/82-39 & 50-296/82-39 & proposed imposition of civil penalties Response inadvertently sent to Region II
MILLS, L M Tennessee Valley Authority 83/02/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 17247 001 24X
Fiche 50-259, 83/02/10, 8302230344

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X
Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X
Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X
Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302070581 PHO-11-83-002 on 830116, during cold shutdown for maint., licensee placed Pump B & HX on RHR in svc & removed HX D & pump after routine RHR svc water sample indicated high activity Total of 15 mCi released
CANTRELL, F S, VERRELLI, D M Region 2, Office of Director 83/01/17 2pp 17035 207 24X
Fiche 50-296, 83/01/17, 8302070581

8302010141 Forwards LER 83-005/03L-0
GREEN, H J Tennessee Valley Authority 83/01/20 O'REILLY, J P Region 2, Office of Director 1p 16977 024 24X
Fiche 50-296, 83/01/20, 8302010141

--8302010167 LER 83-005/03L-0 on 821222, while performing monthly vibration tests on 480-volt reactor motor operator valve board motor generator sets, high vibration readings detected on 3DA set coupling Caused by excessive seal removal
* Tennessee Valley Authority 83/01/20 Region 2, Office of Director 2pp 16977 025 24X
Fiche 50-296, 83/01/20, 8302010141

8302010270 Forwards LER 82-067/03L-0
GREEN, H J Tennessee Valley Authority 83/01/21 O'REILLY, J P Region 2, Office of Director 1p 16977 017 24X
Fiche 50-296, 83/01/21, 8302010270

--8302010283 LER 82-067/03L-0 on 821225, coupling unit on diesel generator C lube oil pump found broken Caused by deterioration of coupling spider due to normal svc Pump mfg by Viking & coupling by Lovejoy Coupling replaced
PORTER, M R Tennessee Valley Authority 83/01/20 Region 2, Office of Director 2pp 16977 018 24X
Fiche 50-296, 83/01/21, 8302010270

8302030518 Forwards LER 82-068/03L-0
GREEN, H J Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17007 295 24X
Fiche 50-296, 83/01/28, 8302030518

--8302030527 LER 82-068/03L-0 on 821229, while performing Surveillance Insp & 2 B-69 (reactor high pressure), pressure switch had as-found 1125.9 psig setpoint Caused by pressure switch calibr drift Static-O-ring model pressure switch recalibr
IRBY, B J Tennessee Valley Authority 83/01/28 Region 2, Office of Director 3pp 17007 296 24X
Fiche 50-296, 83/01/28, 8302030518

8302140037 Forwards updated LER 82-055/03X-1
GREEN, H J Tennessee Valley Authority 83/01/31 O'REILLY, J P Region 2, Office of Director 1p 17140.177 24X
Fiche 50-296, 83/01/31, 8302140037

--8302140040 Updated LER 82-055/03X-1 on 821124, pressure switch PS-3-204D found w/setpoint of 1,125.9 psig Caused by calibr drift
Static O-ring Model 9N-AA19-X9-TT pressure switch recalibr
IRBY, B J Tennessee Valley Authority 83/01/31 Region 2, Office of Director 2pp 17140 178 24X
Fiche 50-296, 83/01/31, 8302140037

8302140017 Forwards LER 83-001/03L-0
GREEN, H J Tennessee Valley Authority 83/02/03 O'REILLY, J P Region 2, Office of Director 1p 17141 194 24X
Fiche 50-296, 83/02/03, 8302140017

--8302140021 LER 83-001/03L-0 on 830107, during surveillance testing drywell containment spray isolation valve 3-FCV-74-74 failed to operate Caused by fractured worm shaft clutch gear due to impact load New clutch gear installed
PORTER, M R Tennessee Valley Authority 83/02/03 Region 2, Office of Director 2pp 17141 195 24X
Fiche 50-296, 83/02/03, 8302140017

8302150167 Telecopy RO on 830207, reactor low water level switches found out of tolerance Caused by instrument drift Switches recalibr, tested & returned to svc Switches will be replaced w/analog transmitter/trip unit sys at later date
JONES, O T Tennessee Valley Authority 83/02/08 Region 2, Office of Director 1p 17147 219 24X
Fiche 50-296, 83/02/08, 8302150167

8302170142 Forwards LER 83-002/03L-0
GREEN, H J Tennessee Valley Authority 83/02/10 O'REILLY, J P Region 2, Office of Director 1p 17180 172 24X
Fiche 50-296, 83/02/10, 8302170142

--8302170148 LER 83-002/03L-0 on 830112, primary purge sys failed to achieve required flow rate of greater than 10% of design Caused by filter internals clogged w/sand dust from sandblasting New filters installed
MCPIERSON, B R Tennessee Valley Authority 83/02/10 Region 2, Office of Director 2pp 17180 173 24X
Fiche 50-296, 83/02/10, 8302170142

8302230618 Forwards LER 83-004/03L-0
GREEN, H J Tennessee Valley Authority 83/02/15 O'REILLY, J P Region 2, Office of Director 1p 17255 236 24X
Fiche 50-296, 83/02/15, 8302230618

--8302230628 LER 83-004/03L-0 on 830116, while in maint outage, RHR 3D HX leaked reactor coolant in RHR svc water Investigation revealed 12 dented tubes in HX, w/one tube leaking Cause under investigation
WATSON, M D Tennessee Valley Authority 83/02/15 Region 2, Office of Director 12pp 17255 237 24X
Fiche 50-296, 83/02/15, 8302230618

8302280338 Forwards LER 83-008/01T-0
GREEN, H J Tennessee Valley Authority 83/02/18 O'REILLY, J P Region 2, Office of Director 1p 17312 351 24X
Fiche 50-296, 83/02/18, 8302280338

--8302280340 LER 83-008/01T-0 on 830207, while performing SI 4 1 A-7, reactor protection sys water level switches 3-LIS-3-203 B & D switch 1 found out of tolerance Caused by setpoint drift Barton Model 288 switches recalibr & functionally tested
IRBY, B J Tennessee Valley Authority 83/02/18 Region 2, Office of Director 3pp 17312 352 24X
Fiche 50-296, 83/02/18, 8302280338

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

X Onsite Storage of Low Level Waste

8302090205 Forwards License 01-21075-01 & notice of issuance License authorizes 5-yr term to receive, possess, store & transfer low level radwaste at onsite storage facility
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27 PARRIS, M C Tennessee Valley Authority 2pp 17132 068 24X
Fiche 50-299, 83/01/27, 8302090205

--8302090213 License 01-21075-01 for TVA, authorizing 5-yr term for receipt, possession, storage & transfer of low level radwaste at onsite storage facility
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27 3pp 17132 070 24X
Fiche 50-299, 83/01/27, 8302090205

DOCKETED ITEMS

129

--B302090222 Notice of issuance of License 01-21075-01 & negative declaration for onsite storage of low level radwaste
RQUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/27
3pp 17132 073 24X Fiche 50-299, 83/01/27, 8302090205

B30220035 Informs that FR notice, published 830203, re issuance of matls license & negative declaration for onsite storage of low level radwaste, contained typographical error Dockets should be 30-19102, 50-259, 260 & 296
RQUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/02/08
PARRIS, H G Tennessee Valley Authority 3pp 17227 346 24X
Fiche 50-259, 83/02/08, 830220035

DOCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

2 Inspection reports, IE Bulletins & correspondence

B302150068 Ack receipt of B30113 & 26 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-111/82-02 & 50-277/82-01 Practices re stack monitor calibr & monthly radionuclide analysis or reactor water meet Tech Specs
VERRELL, D H Division of Project & Resident Programs 83/02/08
COCKRELL, R O North Carolina State Univ 1p 17147 001 24X
Fiche 50-111, 83/02/08, 8302150068

--B302150075 Responds to NRC 820421 ltr re violations noted in IE Insp Repts 50-111/82-02 & 50-277/82-01 Justification that present procedure re stack monitor sys provides capability of early detection of fuel clad failure submitted
COCKRELL, R O North Carolina State Univ 83/01/26 JULIAN, C
Region 2, Office of Director 3pp 17147 002 24X
Fiche 50-111, 83/02/08, 8302150068

--B302150082 Responds to NRC 830421 ltr re violation noted in IE Insp Repts 50-111/82-02 & 50-277/82-01 Justification for continued use of present stack gas monitor sys procedures provided
COCKRELL, R O North Carolina State Univ 83/01/13 JULIAN, C
Region 2, Office of Director 3pp 17147 004 24X
Fiche 50-111, 83/02/08, 8302150068

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

B302080043 Forwards copy of proposed route to be used for transport of spent reactor fuel to GE Morris facility in State of IL, per 821133 ltr Proposed route meets 10CFR73.37 Info should be incorporated in shipment plan Safeguards info deleted
BERR, T S Material Transfer Safeguards Licensing Branch 83/01/14
PILANT, J M Nebraska Public Power District 6pp 17106 263 24X
Fiche 50-298, 83/01/14, 8302080043

B302090091 Releases public version of licensee info re release of revised emergency planning info booklet
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17119 297 24X Fiche 50-298, 83/01/31, 8302090091

--B302090097 Submits public version of info that revised emergency planning info booklet dtd Nov 1982 will be issued shortly
LESSOR, L Nebraska Public Power District 82/12/08 NRC - No
Detailed Affiliation Given 1p 17119 298 24X
Fiche 50-298, 83/01/31, 8302090091

B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

B302090405 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/02 Document
Management Branch 1p 17074 360 24X Fiche 50-298, 83/02/02, 8302090405

--B302080408 Forwards public version of Rev 2 to Emergency Plan Implementing Procedures 5 7 11 & 5 7 22 W/o encl
PILANT, J M Nebraska Public Power District, 83/01/06
COLLINS, J T Region 4, Office of Director 1p 17074 361 24X
Fiche 50-298, 83/02/02, 8302080405

B302180055 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document
Management Branch 1p 17227 039 24X Fiche 50-298, 83/02/14, 8302180055

--B302180061 Forwards public version of revised Emergency Plan Implementing Procedures 5 7 2, 5 7 4, 5 7 5, 5 7 23, 5 7 24 & 5 7 26 W/o encl
PILANT, J M Nebraska Public Power District 83/01/26
COLLINS, J T Region 4, Office of Director 1p 17227 040 24X
Fiche 50-298, 83/02/14, 8302180055

B30220061 Releases public version of notification of 830210 meeting
FELTON, J M Division of Rules and Records 83/02/15 Document
Management Branch 1p 17234 046 24X Fiche 50-298, 83/02/15, 830220061

--B30220066 Submits public version of notification of 830210 meeting w/FEMA & States of NE, KS, IA & MO in Kansas City, MO to discuss potential generic problems re emergency preparedness activities at or near nuclear power stations Agenda encl.
HADSEN, O L Division of Resident, Reactor Project & Engineering Programs 83/01/26 PILANT, J M Nebraska Public Power District
3pp 17234 047, 24X Fiche 50-298, 83/02/15, 830220061

K Utility Final Safety Analysis Report (FSAR) & amends

B302280101 App B to Cooper updated FSAR, "Tech Specs"
* Nebraska Public Power District 83/01/19 1p, 17329 018 24X
Fiche 50-298, 82/01/19, 8302280101

B302280046 Forwards updated FSAR for Cooper Nuclear Station
PILANT, J M Nebraska Public Power District 83/01/19
VAGSALL, D B Operating Reactors Branch 2 2pp, 17323:001 24X
Fiche 50-298, 83/01/19, 8302280046

--B302280048 Updated FSAR for Cooper Nuclear Station
* Nebraska Public Power District 83/01/19 97pp, 17323 003
24X Fiche 50-298, 83/01/19, 8302280046

B302280050 Chapter 1 to Cooper updated FSAR, "Introduction & Summary"
* Nebraska Public Power District 83/01/19 121pp, 17323 100
24X Fiche 50-298, 83/01/19, 8302280050

B302280054 Chapter 2 to Cooper updated FSAR, "Station Site & Environs"
* Nebraska Public Power District 83/01/19 159pp, 17323 221
24X Fiche 50-298, 83/01/19, 8302280054

B302280056 Chapter 3 to Cooper updated FSAR, "Reactor"
* Nebraska Public Power District 83/01/19 182pp, 17324 020,
24X Fiche 50-298, 83/01/19, 8302280056

B302280058 Chapter 4 to Cooper updated FSAR, "RCS" Oversize drawing encl Aperture card available in PDR
* Nebraska Public Power District 83/01/19, 182pp, 17324 202,
24X Fiche 50-298, 83/01/19, 8302280058

B302280061 Chapter 5 to Cooper updated FSAR, "Containment."
* Nebraska Public Power District 83/01/19, 89pp, 17324:354, 24X
Fiche 50-298, 83/01/19, 8302280061,

B302280063 Chapter 6 to Cooper updated FSAR, "Core Standby Cooling Sys"
* Nebraska Public Power District 83/01/19 75pp, 17325:083, 24X
Fiche 50-298, 83/01/19, 8302280063.

B302280068 Chapter 7 to Cooper updated FSAR, "Control & Instrumentation"
* Nebraska Public Power District 83/01/19 496pp, 17325:161,
24X Fiche 50-298, 83/01/19, 8302280068

B302280070 Chapter 8 to Cooper updated FSAR, "Electric Power Sys."
* Nebraska Public Power District 83/01/19, 91pp, 17326:297, 24X
Fiche 50-298, 83/01/19, 8302280070

B302280073 Chapter 9 to Cooper updated FSAR, "Radwaste Sys"
* Nebraska Public Power District 83/01/19 77pp, 17327 028 24X
Fiche 50-298, 83/01/19, 8302280073

B302280075 Chapter 10 to Cooper updated FSAR, "Auxiliary Sys."
* Nebraska Public Power District 83/01/19 181pp, 17327 109,
24X Fiche 50-298, 83/01/19, 8302280075

B302280078 Chapter 11 to Cooper updated FSAR, "Power Conversion Sys"
* Nebraska Public Power District, 83/01/19 56pp, 17327:286 24X
Fiche 50-298, 83/01/19, 8302280078

B302280083 Chapter 12 to Cooper updated FSAR, "Structures & Shielding"
* Nebraska Public Power District 83/01/19 101pp, 17327:342
24X Fiche 50-298, 83/01/19, 8302280083

DOCKETED ITEMS

8302280086 Chapter 13 to Cooper updated FSAR, "Conduct of Operations "
 * Nebraska Public Power District 83/01/19 109pp 17328 083
 24X Fiche 50-298, 83/01/19, 8302280086

8302280088 Chapter 14 to Cooper updated FSAR, "Station Safety
 Analysis "
 * Nebraska Public Power District 83/01/19 156pp 17328 192
 24X Fiche 50-298, 83/01/19, 8302280088

8302280092 App A to Cooper updated FSAR, "Pressure Integrity of
 Piping & Equipment Pressure Parts "
 * Nebraska Public Power District 83/01/19 35pp 17328 348 24X
 Fiche 50-298, 83/01/19, 8302280092

8302280103 App C to Cooper updated FSAR, "Structural Loading
 Criteria "
 * Nebraska Public Power District 83/01/19 138pp 17329 023
 24X Fiche 50-298, 83/01/19, 8302280103

8302280104 App D to Cooper updated FSAR, "QA Program for Operation -
 Policy Document "
 * Nebraska Public Power District 83/01/19 74pp 17329 161 24X
 Fiche 50-298, 83/01/19, 8302280104

8302280106 App D1 to Cooper updated FSAR, "Const Phase QA Program "
 * Nebraska Public Power District 83/01/19 131pp 17329 235
 24X Fiche 50-298, 83/01/19, 8302280106

8302280110 App E to Cooper updated FSAR, "Elevated Release Point
 (ERP) Release Rate Limit Calculations."
 * Nebraska Public Power District 83/01/19 67pp 17330 006 24X
 Fiche 50-298, 83/01/19, 8302280110

8302280111 App F to Cooper updated FSAR, "Conformance to AEC ODC "
 * Nebraska Public Power District 83/01/19 20pp 17330 071 24X
 Fiche 50-298, 83/01/19, 8302280111

8302280115 App G to Cooper updated FSAR, "Station Nuclear Safety
 Operational Analysis "
 * Nebraska Public Power District 83/01/19 98pp 17330 094 24X
 Fiche 50-298, 83/01/19, 8302280115

8302280117 App H to Cooper updated FSAR, "Station Research,
 Development & Further Info, Requirements & Resolutions "
 * Nebraska Public Power District 83/01/19 38pp 17330 192 24X
 Fiche 50-298, 83/01/19, 8302280117

8302280119 App J to Cooper updated FSAR, "Inservice Insp Program "
 * Nebraska Public Power District 83/01/19 219pp 17330 230
 24X Fiche 50-298, 83/01/19, 8302280119

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for
 continued operation of operating reactors in response to
 questions raised at 830106 meeting re environ qualification
 of electrical equipment
 EISENHUT, D O Division of Licensing 83/01/18 DENIGAN, H R Office
 of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
 Fiche: 50-000, 83/01/18, 8302170019

--8302170123 Package of four comments indicating adequate or inadequate
 justification for interim operation re environ qualification
 of electrical equipment
 PADDOVAN, M L NRC - No Detailed Affiliation Given 82/01/27
 NRC - No Detailed Affiliation Given 10pp, 17196, 235, 24X
 Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by
 which technical evaluation repts are expected to be
 completed Requests justification for continued operation of
 each group by 821008 & 15, respectively
 EISENHUT, D O Division of Licensing, 82/09/24, MIRAGLIA, F
 Assistant Director for Safety Assessment, 4pp 17196 265 24X
 Fiche: 50-000, 83/01/18, 8302170019.

--8302170290 Concludes that based on licensee submittal, continued
 operation until completion of environ qualification program
 will not present undue risk to public health & safety
 SIEGEL, B L Operating Reactors Branch 2 82/10/28 EISENHUT, D O
 Division of Licensing, 2pp 17197 060 24X
 Fiche: 50-000, 83/01/18, 8302170019

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re
 mod of vacuum breakers on Mark I containment Requests
 commitment to submit results of plant-unique calculations
 which formed bases for mod Svc list encl.
 EISENHUT, D O Division of Licensing, 83/02/02, General Public
 Utilities - QPU Service Corp 3pp 17074 086 24X
 Fiche 50-000, 83/02/02, 8302030089

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
 applicants for OL & holders of CP for C-E PNRs re review of
 C-E Owners Group emergency procedures guideline program Svc
 list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
 (except LACBWR), applicants for OL & holders of CP re SER of
 "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
 1982 Guidelines acceptable Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
 Edison Co 6pp 17234 215 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re
 licensee qualification for performing safety analysis in
 support of licensing actions Ability to use code must be
 demonstrated by vendor or licensee Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 9pp 17234 234 24X
 Fiche 50-000, 83/02/08, 8302080304

8302170382 Lists applications which have been awaiting fee resolutions
 Fee should be remitted for changes re MAPLHOR limits for
 fuel assemblies w/exposure values exceeding Tech Specs
 DIOGSI, R M License Fee Management Branch 83/02/10 PILANT, J M
 Nebraska Public Power District 2pp 17193 345 24X
 Fiche 50-298, 83/02/10, 8302170382

8302250370 Forwards "Low-Low Set Relief Logic Sys & Lower MSIV Water
 Level Trip for Cooper Nuclear Station Unit 1," supplementing
 821217 ltr Approval of design change & Tech Specs requested
 by 830501 Rept withheld (ref 10CFR2 790) GE affidavit encl
 PILANT, J M Nebraska Public Power District 83/02/15
 VASSALLO, D B Operating Reactors Branch 2 4pp 17296 185 24X
 Fiche 50-298, 83/02/15, 8302250370

Q Inspection reports, IE Bulletins & correspondence

8302070529 Forwards IE Insp Rept 50-298/82-36 on 821206-10, notices
 of violation & deviation & IE mgt meeting rept
 MADSEN, G L Division of Resident, Reactor Project & Engineering
 Programs 83/01/18 PILANT, J M Nebraska Public Power District
 2pp 17038 297 24X Fiche 50-298, 83/01/18, 8302070529

--8302070533 Notice of violation from insp on 821206-10
 * Division of Resident, Reactor Project & Engineering Programs
 83/01/18 1p 17038 297 24X Fiche 50-298, 83/01/18, 8302070529

--8302070534 Notice of deviation from insp on 821206-10
 * Division of Resident, Reactor Project & Engineering Programs
 83/01/18 1p 17038 300 24X Fiche 50-298, 83/01/18, 8302070529

--8302070543 IE Insp Rept 50-298/82-36 on 821206-10 Noncompliance noted
 failure to follow requirements of approved requalification
 program & to conduct training as committed IE mgt meeting
 rept encl
 JAWDON, J P, MCCORDY, S L, JOHNSON, W D Division of Resident,
 Reactor Project & Engineering Programs 83/01/11 13pp
 17038 301 24X Fiche 50-298, 83/01/18, 8302070529

8302010676 Comments on SER & Technical Evaluation Rept for environ
 qualification of safety-related electrical equipment exposed
 to harsh environs, per IE Bulletin 79-018 Continued safe
 operation of facility reasonably assured
 PILANT, J M Nebraska Public Power District 83/01/24
 VASSALLO, D B Operating Reactors Branch 2 3pp 16979 199 24X
 Fiche 50-298, 83/01/24, 8302010676

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co of New
 York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060340 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
 Gearheads " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060340

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

DOCKETED ITEMS

131

8302030329 Ack receipt of 830126 ltr providing status of proposed mgt appraisal All three proposed firms meet necessary independence requirements
COLLINS, J T Region 4, Office of Director 83/01/31 JONES, C R
Nebraska Public Power District 1p 17001 290 24X
Fiche 50-298, 83/01/31, 8302030329

--8302030333 Submits progress rept & requests approval of three firms as independent, in response to Enforcement Action 82-46 & order modifying license
JONES, C R Nebraska Public Power District 83/01/26
COLLINS, J T Region 4, Office of Director 30pp 17001 291 24X
Fiche 50-298, 83/01/31, 8302030329

8302150107 Ack receipt of 830126 ltr providing status of proposed mgt appraisal per IE Insp Repts 50-298/82-09 & 50-298/82-11
Three firms proposed to pursue negotiations meet necessary independence requirements
COLLINS, J T Region 4, Office of Director 83/02/08 PILANT, J M
Nebraska Public Power District 1p 17146 149 24X
Fiche 50-298, 83/02/08, 8302150107

8302230668 Submits analysis results of confirmatory measurements on floor drain storage tank sample collected during NRC Oct 1982 Insp & not reported in IE Insp Rept 50-298/82-27
Disagreement in strontium results must be resolved
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/14 PILANT, J M Nebraska Public Power District 3pp 17255 051 24X Fiche 50-298, 83/02/14, 8302230668

8302230573 Notifies that program instituted to provide insp repts of vendors used at facilities Sample ticket used to flag significant problems encl Ack of receipt of rept requested on ticket
COLLINS, J T Region 4, Office of Director 83/02/16 PILANT, J M
Nebraska Public Power District 3pp 17255 176 24X
Fiche 50-298, 83/02/16, 8302230573

8302230309 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/82-30
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/17 PILANT, J M Nebraska Public Power District 1p 17243 332 24X Fiche 50-298, 83/02/17, 8302230309

--8302230310 Responds to NRC 821208 ltr re violations noted in IE Insp Rept 50-298/82-30 Corrective actions new computer printout developed to aid in tracking procedure review Tech Spec change will be proposed
PILANT, J M Nebraska Public Power District 83/01/21
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 3pp 17243 333 24X Fiche 50-298, 83/02/17, 8302230309

8302230718 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/82-33
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/17 PILANT, J M Nebraska Public Power District 1p 17248 342 24X Fiche 50-298, 83/02/17, 8302230718

--8302230724 Responds to NRC 821229 ltr re violations noted in IE Insp Rept 50-298/82-33 Corrective actions personnel instructed on correct method of completing Procedure NPE 10.1 data sheet & on use of process computer
PILANT, J M Nebraska Public Power District 83/01/20
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 3pp 17248 343 24X Fiche 50-298, 83/02/17, 8302230718

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302230376 EN-82-028A on 830218, order imposing civil monetary penalties in amount of \$112,000 issued to licensee based on failure to install prompt notification sys & three mail false statements Reduction of original penalty appropriate
ROSEANO, R, AYELRAD, J Director's Office, Office of Inspection and Enforcement 83/02/18, 1p 17248:091 24X Fiche 50-298, 83/02/18, 8302230376

8302230303 Ack receipt of 830207 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/82-26
Corrective actions will be reviewed during next insp
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/22 PILANT, J M Nebraska Public Power District 1p 17291 276 24X Fiche 50-298, 83/02/22, 8302230303

--8302230309 Responds to NRC 820728 ltr re violations noted in IE Insp Rept 50-298/82-26 Corrective actions essential 2400 & 7000 series relays replaced w/Nuclear Grade E relays
WILLIAMS, F E Nebraska Public Power District 83/02/07
COLLINS, J T Region 4, Office of Director 2pp 17291:277, 24X Fiche 50-298, 83/02/22, 8302230303

8212060355 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 110pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060355

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302230712 Forwards LER 82-026/03L-0 Detailed event analysis submitted.
LESSOR, L C Nebraska Public Power District 83/02/15, COLLINS, J T Region 4, Office of Director 2pp 17248, 347 24X
Fiche 50-298, 83/02/15, 8302230712

--8302230713 LER 82-026/03L-0: on 821222, diesel generators (alternate source of emergency power) not tested to demonstrate operability when 69-kV line taken out of svc for repairs
Cause not stated Operators informed of testing procedures
WIRE, K R Nebraska Public Power District 83/02/15 Region 4, Office of Director 1p 17248 349, 24X Fiche 50-298, 83/02/15, 8302230712

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302180362 Responds to Generic Ltr 83-01 re requests for site visits to conduct operator licensing exams or instructor certification exams (ICE) Program for ICE not established Schedule for site visits submitted
PILANT, J M Nebraska Public Power District 83/02/07
EISENHUT, D O Division of Licensing 2pp 17209 360 24X
Fiche 50-298, 83/02/07, 8302180362

DOCKET 90-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8301210310 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302090421 Responds to NRC 830117 ltr transmitting draft safety evaluation denying App R exemption requests. Meeting requested to discuss technical accuracy of evaluation prior to inception of NRR mgt appeal process Agenda submitted
FAY, C W Wisconsin Electric Power Co 83/02/07, DENTON, H R, Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 17066 247 24X
Fiche 50-266, 83/02/07, 8302090421

G Adjudicatory correspondence

8302070506 Initial decision authorizing Director of NRR to issue OL amend re repair of steam generator tubes Tubes explosively plugged cannot be sleeved or brazed joints employed Leak limits apply
BLOCH, P B, PAXTON, H C, KLINE, J R Atomic Safety and Licensing Board Panel 83/02/04 41pp 17037 013, 24X Fiche 50-266, 83/02/04, 8302070506

8302140020 Memorializes 830131 telcon resolving open procedural question re inadvertent use of proprietary data in responding to ASLB & HI Environ Decade exam.
DAVIS, F X General Electric Co 83/02/04, BLOCH, P B Atomic Safety and Licensing Board Panel 3pp 17141 189 24X
Fiche 50-266, 83/02/04, 8302140020

8302180427 Exceptions to ASLB 830204 initial decision Affidavit of Mailing encl.
ANDERSON, P Wisconsin's Environmental Decade 83/02/14 Commissioners 4pp 17215:184 24X Fiche 50-266, 83/02/14, 8302180427

DOCKETED ITEMS

I Financial information

8302240159 Forwards 1982 financial statements & 1983 cash flow projection providing guarantee of retrospective premiums
 REMMEL, J O Wisconsin Electric Power Co 83/02/15 SALTZMAN, J
 Antitrust & Economic Analysis Branch (Utility Finance) 14pp
 17280 232 24X Fiche 50-266, 83/02/15, 8302240159

P Operating license stage documents & correspondence

8302010593 Discusses need for further delay in determining proprietary nature of SER re environ qualification of safety-related electrical equipment Final determination delayed until 830201 due to absence of key personnel
 BURSTEIN, S Wisconsin Electric Power Co 83/01/26 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp 16978 127 24X
 Fiche 50-266, 83/01/26, 8302010593

8302030566 Submits justification for continued operation of equipment identified as deficient due to lack of environ qualification in response to NRC 821222 request
 BURSTEIN, S Wisconsin Electric Power Co 83/01/26 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 7pp 17008 126 24X
 Fiche 50-266, 83/01/26, 8302030566

8302170013 Forwards request for addl info to complete post-implementation review of NUREG-0737, Items II F 1 A, II F 1 B & II F 1 C re containment monitors Response requested within 30 days
 CLARK, R A Operating Reactors Branch 3 83/02/02 FAY, C W
 Wisconsin Electric Power Co 10pp 17190 291 24X
 Fiche 50-266, 83/02/02, 8302170013

8302090408 Discusses Cycle 10 reload Refueling shutdown for end of Cycle 9 planned to begin late Mar 1983 at burnup of approx 9,130 MWD/T plus/minus 500 MWD/T Core will consist of Westinghouse 14x14 optimized design & 14x14 std design fuel
 FAY, C W Wisconsin Electric Power Co 83/02/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp 17071 074 24X
 Fiche 50-301, 83/02/03, 8302090408

8302220044 Informs that review of 801223 & 821228 responses to NUREG-0737, Item II K 3 25, "Loss of AC Power to Reactor Coolant Pump Seals," adequately demonstrates integrity of reactor coolant pump seals Item resolved
 CLARK, R A Operating Reactors Branch 3 83/02/04 FAY, C W
 Wisconsin Electric Power Co 3pp 17227 333 24X
 Fiche 50-266, 83/02/04, 8302220044

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re license qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 9pp 17234 234 24X
 Fiche 50-000, 83/02/08, 8302080304

8302150410 Advises that installation of addl supports for auxiliary feedwater sys piping & components rescheduled to June 1983, due to conflicts w/other plant mods
 FAY, C W Wisconsin Electric Power Co 83/02/11 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp 17157 149 24X
 Fiche 50-266, 83/02/11, 8302150410

8302230236 Forwards response to NRC Question Attachments 1-2 "Evaluation of Overhead Handling Sys W/Respect to NUREG-0554" & 1-3 "Seismic Analysis Methodology for Overhead Handling Sys," per NUREG-0512
 FAY, C W Wisconsin Electric Power Co 83/02/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 7pp 17245 029 24X
 Fiche 50-266, 83/02/15, 8302230236

8302280366 Forwards revised justification for continued operation, correcting 830126 submittal in response to NRC 821227 BEK re environ qualification of safety-related electrical equipment
 FAY, C W Wisconsin Electric Power Co 83/02/18 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 12pp 17310 341 24X
 Fiche 50-266, 83/02/18, 8302280366

8302280154 Advises that review underway for final rule 10CFR50 49 re environ qualification of safety-related electrical equipment Determination of request for hearing will be decided by 830324
 FAY, C W Wisconsin Electric Power Co 83/02/21 DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D O
 Division of Licensing 1p 17306 075 24X Fiche 50-266, 83/02/21, 8302280154

8302280156 Submits addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys," in response to NRC 821222 request Standardized test matrix will be completed by 830401
 FAY, C W Wisconsin Electric Power Co 83/02/21 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 3pp 17306 034 24X
 Fiche 50-266, 83/02/21, 8302280156

8302280310 Forwards "Incorporation of Westinghouse Model for Upper Plenum Injection in 1981 Evaluation Model WREFLOOD Code"
 FAY, C W Wisconsin Electric Power Co 83/02/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 3pp 17311 014 24X
 Fiche 50-266, 83/02/22, 8302280310

--8302280312 "Incorporation of Westinghouse Model for Upper Plenum Injection in 1981 Evaluation Model WREFLOOD Code"
 * Westinghouse Electric Corp 83/02/22 53pp 17311 017 24X
 Fiche 50-266, 83/02/22, 8302280310

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
 Forwards App A documents Document 31 available in PDR
 FELTON, J H Division of Rules and Records 82/12/30 HATT, S L
 Ohio Citizens for Responsible Energy 3pp 17045 144 24X
 Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
 SUCHARSKI, L Region 3, Office of Director 82/07/08
 KEPPLER, J G Region 3, Office of Director 13pp 17045 281 24X
 Fiche 50-000, 82/12/30, 8302040039

8302010603 Forwards revised Table 1 to correct typographical error re two 10-inch check valve identification numbers in 820811 response to IE Bulletin 82-02 re degradation of RCPD fasteners
 BURSTEIN, S Wisconsin Electric Power Co 83/01/24 KEPPLER, J G
 Region 3, Office of Director 3pp 16978 138 24X
 Fiche 50-266, 83/01/24, 8302010603

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co of New
 York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitique H08C, H18C, H28C & H38C Gearheads" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50 54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
 SPESARD, R L Division of Engineering 83/01/28 Commonwealth
 Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302080320 Suppl previous responses to IE Bulletin 79-14 re conformance of as-built safety-related piping sys to as-designed seismic analysis & acceptance criteria Next rept will be submitted by Apr 1983
 FAY, C W Wisconsin Electric Power Co 83/01/31 KEPPLER, J G
 Region 3, Office of Director 2pp 17056 305 24X
 Fiche 50-266, 83/01/31, 8302080320

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co of New
 York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

DOCKETED ITEMS

1:

830220498 Notifies that Class III fee appropriate for 830119 application for relief from certain ASME Code Section XI requirements re second 10-yr insp
DIQOS, R M License Fee Management Branch 83/02/18 FAY, C W
Wisconsin Electric Power Co 1p 17234 349 24X
Fiche 50-301, 83/02/18, 830220498

8302280515 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-21 & 50-301/82-21
STREETER, J F Division of Project & Resident Programs 83/02/18
BURSTEIN, S Wisconsin Electric Power Co 1p 17309 033 24X
Fiche 50-266, 83/02/18, 8302280515

--8302280552 Responds to NRC 830103 ltr re violations noted in IE Insp Repts 50-266/82-21 & 50-301/82-21 Corrective actions ICP 10 7 permanently revised & classified as minor procedure & precaution added to RP-1C to warn of effect of fuel temp
FAY, C W Wisconsin Electric Power Co 83/02/02 KEPLER, J O
Region 3, Office of Director 3pp 17309 034 24X
Fiche 50-266, 83/02/18, 8302280552

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302170153 Forwards monthly operating repts for Jan 1983
FAY, C W Wisconsin Electric Power Co 83/02/09 Office of Nuclear Reactor Regulation, Director 1p 17180 140 24X
Fiche 50-266, 83/02/09, 8302170153

--8302170155 Monthly operating repts for Jan 1983
FAY, C W Wisconsin Electric Power Co 83/02/04 8pp 17180 141 24X
Fiche 50-266, 83/02/09, 8302170155

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8302150609 Forwards IE Safeguards Insp Rept 50-302/82-30 on 821112 & 29-30 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/12/17
HANCOCK, J A Florida Power Corp 2pp 17151 333 24X
Fiche 50-302, 82/12/17, 8302150609

--8302150614 IE Safeguards Insp Rept 50-302/82-30 on 821112 & 29-30 Noncompliance noted failure to conduct adequate search
Details withheld (ref 10CFR73 21)
TILLMAN, A, STETKA, T, MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 82/12/15 1p 17151 335 24X
Fiche 50-302, 82/12/17, 8302150609

8302030571 Responds to NRC ltr re violations noted in IE Insp Rept 50-302/82-25 & proposed imposition of civil penalty
Corrective actions procedure controls strengthened & employee/contractor awareness heightened. Penalty fee encl
HANCOCK, J A Florida Power Corp 83/01/26 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 5pp 17008 093 24X
Fiche 50-302, 83/01/26, 8302030571

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302150680 Ack receipt of 830126 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-25
AXELRAD, J A Enforcement Staff 83/02/07 HANCOCK, J A Florida Power Corp 1p 17153 043 24X Fiche 50-302, 83/02/07, 8302150680

--8302150688 Responds to NRC 821227 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-25 Corrective actions mgt & procedural controls strengthened
HANCOCK, J A Florida Power Corp 83/01/26 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp 17153 044 24X Fiche 50-302, 83/02/07, 8302150680

--8302150692 Forwards IE Safeguards Insp Rept 50-302/82-25 on 821001 & notice of violation Notice of violation withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 82/12/27
HANCOCK, J A Florida Power Corp 2pp 17153 046 24X
Fiche 50-302, 83/02/07, 8302150680

--8302150700 IE Safeguards Insp Rept 50-302/82-25 on 821001 Noncompliance noted failure to provide compensatory measures for accessed vital area door Details withheld (ref 10CFR73 21)
PERN, C D, STETKA, T F, MCGUIRE, D R Division of Engineering & Radiological Safety Programs 82/10/27 1p 17153 048 24X
Fiche 50-302, 83/02/07, 8302150680

8302170115 Forwards exemption from requirement to install fixed fire suppression sys in control room, in response to util 821229 request
FAIRFILL, M B Operating Reactors Branch 4 83/02/07 HANCOCK, J A Florida Power Corp 2pp 17191 110 24X Fiche 50-302, 83/02/07, 8302170115

--8302170119 Exemption from requirement to install fixed fire suppression sys in control room
EISENHUT, D O Division of Licensing 83/02/07 Florida Power Corp 3pp 17191 112 24X Fiche 50-302, 83/02/07, 8302170115

8302170166 Commits to install source range neutron flux monitor as part of process monitoring instrumentation at dedicated shutdown panel, per 10CFR90, App R Monitor will be installed in conjunction w/dedicated shutdown panel installation
BAYNARD, P Y Florida Power Corp 83/02/11 STOLZ, J F Licensing Branch 2 1p 17189 147 24X Fiche 50-302, 83/02/11, 8302170166

K Utility Final Safety Analysis Report (FSAR) & amends

8302030416 Forwards Rev 2 to FSAR, including Page 14-106 inadvertently omitted from Rev 1
WESTAFER, Q R Florida Power Corp 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17005 226 24X
Fiche 50-302, 83/01/28, 8302030416

--8302030419 Rev 2 to FSAR
Florida Power Corp 83/01/28 18pp 17005 227 24X
Fiche 50-302, 83/01/28, 8302030416

P Operating license stage documents & correspondence

8302070343 Addl response to FOIA request for seven categories of info
Forwards documents listed in App A Addl comments provided
Documents also available in PDR Search for addl documents in progress
FELTON, J M Division of Rules and Records 82/12/13
SCHLESSEL, D A New York, State of 5pp 16999 119 24X
Fiche 50-000, 82/12/13, 8302070343

8302020150 Forwards Amend 61 to License DPR-72, safety evaluation & notice of issuance & availability Amend defers certain monthly channel functional tests of engineered safeguards components
STOLZ, J F Operating Reactors Branch 4 83/01/24 HANCOCK, J A Florida Power Corp 2pp 16999 248 24X Fiche 50-302, 83/01/24, 8302020150

--8302020156 Amend 61 to License DPR-72, deferring certain monthly channel functional tests of engineered safeguards components
STOLZ, J F Operating Reactors Branch 4 83/01/24 7pp 16999 250 24X Fiche 50-302, 83/01/24, 8302020150

--8302020158 Safety evaluation supporting Amend 61 to License DPR-72
Office of Nuclear Reactor Regulation, Director 83/01/24 3pp 16999 257 24X Fiche 50-302, 83/01/24, 8302020150

--8302020162 Notice of issuance & availability of Amend 61 to License DPR-72
STOLZ, J F Operating Reactors Branch 4 83/01/24 2pp 16999 260 24X Fiche 50-302, 83/01/24, 8302020150

DOCKETED ITEMS

8302070268 Ack receipt of NRC 821227 ltr re NUREG-0737, Items I A 2 1 4 & II B. 4 New response date will be determined between util & appropriate NRC personnel
 WESTAFER, O R Florida Power Corp 83/01/28 STOLZ, J F Licensing Branch 2 1p 17032 145 24X Fiche 50-302, 83/01/28, 8302070268

8302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to B&W plants, for use as starting point for addl detailed technical discussions between NRC & B&W Owners Group representatives
 LAINAS, O C Assistant Director for Operating Reactors 83/01/31
 WALLACE, E Babcock & Wilcox Operating Plants Owners Group. 4pp
 17134 100 24X Fiche: 50-000, 83/01/31, 8302100257

8302150138 Application for amend to License DPR-72, consisting of Tech Spec Change Request 107, placing emergency feedwater ultrasonic flow indicators w/post-accident sampling instruments in Tech Spec 3 3 6 W/Certificate of Svc
 WESTAFER, O R Florida Power Corp 83/02/07 BENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17147 241 24X
 Fiche 50-302, 83/02/07, 8302150138

8302150145 Proposed Tech Specs re emergency feedwater ultrasonic flow indicator
 Florida Power Corp 83/02/07 5pp 17147 244 24X
 Fiche: 50-302, 83/02/07, 8302150138

8302160178 Confirms discussions w/NRC re starting date & expected duration for Refuel 4 & establishes schedule for Refuel 5
 Refuel 4 scheduled for 830319 Planned mods require 16 wks
 Cycle 5 begins approx 830709
 WESTAFER, O R Florida Power Corp 83/02/07 STOLZ, J F Licensing Branch 4. 1p 17161-195. 24X Fiche 50-302, 83/02/07, 8302160178

8302160265 Advises that proprietary data reviewed in plant technical evaluation rept on environ qualification of safety-related electrical equipment, Westinghouse equipment Items 62 & 63 no longer proprietary
 WESTAFER, O R Florida Power Corp. 83/02/07 STOLZ, J. F. Licensing Branch 2 1p 17169. 238 24X Fiche: 50-302, 83/02/07, 8302160265

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl.
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp. 17290 247 24X
 Fiche: 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee. Svc list encl
 EISENHUT, D. O Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 7pp 17234 234 24X
 Fiche: 50-000, 83/02/08, 8302080304

8302090098 Generic Ltr 83-10F to all licensees w/B&W designed NSSB (except TH1) re resolution of TH1 Action Item II, K 3 B, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Duke Power Co 23pp 17298 291 24X Fiche 50-000, 83/02/08, 8302090098

830220480 Requests needed parameters for flow & pressure, as supported by FBAR, for electrical surveillance requirement for electrical motor driven pump Info required for correction of Tech Spec 4 7.1.2, emergency feedwater sys
 FAIRFILL, M B Operating Reactors Branch 4 83/02/10 HANCOCK, J A Florida Power Corp 3pp 17235 359. 24X Fiche 50-302, 83/02/10, 830220480

830220215 Informs that licensee will submit info identifying electrical equipment important to safety & schedule for either qualification or replacement by 830520, per NRC
 830311 ltr
 AYWARD, P Y Florida Power Corp 83/02/11 STOLZ, J F. Operating Reactors Branch 4 2pp 17233. 147. 24X Fiche: 50-302, 83/02/11, 830220215.

8302170370 Provides further clarification of util 820309 & 0716 responses to Question 12 b per telcon request re Item I B.1. Piping & valving routed, oriented & protected from pipe whip, jet impingement damage.
 WESTAFER, O R Florida Power Corp. 83/02/14 STOLZ, J. F. Operating Reactors Branch 4 1p. 17187. 136. 24X Fiche 50-302, 83/02/14, 8302170370.

830220360 Notifies that B&W final rept re supplemental ECCS calculations will not be completed before 830301 Util will review & submit rept to NRC on or before 830404.
 AYWARD, P Y Florida Power Corp 83/02/15 LAINAS, O C. Assistant Director for Safety Assessment. 1p 17232-003 24X
 Fiche: 50-302, 83/02/15, 830220360.

8302220483 Requests written response re util assessment of operability of large-diameter Pratt purge & vent valves in light of NRC concerns & util intentions as to whether purge & vent valves will remain closed per SRP
 STOLZ, J F Operating Reactors Branch 4 83/02/16 HANCOCK, J A Florida Power Corp 2pp 17234 361 24X Fiche 50-302, 83/02/16, 8302220483

8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level
 VAN VLIEET, J Operating Reactors Branch 4 83/02/17 STOLZ, J Operating Reactors Branch 4 3pp 17303 098 24X
 Fiche 50-000, 83/02/17, 8302250102

8302230208 Responds to NRC 821227 ltr re NUREG-0737, Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage" Table of contents for related repts encl
 DAYNARD, P Y Florida Power Corp 83/02/21 STOLZ, J F Operating Reactors Branch 4 12pp 17243 196 24X Fiche 50-302, 83/02/21, 8302230208

G Inspection reports, IE Bulletins & correspondence

8302150609 Forwards IE Safeguards Insp Rept 50-302/82-30 on 821112 & 29-30 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
 LEWIS, R C Division of Project & Resident Programs 82/12/17 HANCOCK, J A Florida Power Corp 2pp 17151 333 24X
 Fiche 50-302, 82/12/17, 8302150609

--8302150614 IE Safeguards Insp Rept 50-302/82-30 on 821112 & 29-30 Noncompliance noted failure to conduct adequate search Detail withheld (ref 10CFR73 21)
 TILLMAN, A. STETKA, T. MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 82/12/15 1p 17151 335 24X
 Fiche 50-302, 82/12/17, 8302150609

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302030571 Responds to NRC ltr re violations noted in IE Insp Rept 50-302/82-25 & proposed imposition of civil penalty
 Corrective actions procedure controls strengthened & employee/contractor awareness heightened Penalty fee encl
 HANCOCK, J A Florida Power Corp 83/01/26 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 17008 093 24X Fiche 50-302, 83/01/26, 8302030571

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150680 Ack receipt of 830126 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-25
 AXELRAD, J A Enforcement Staff 83/02/07 HANCOCK, J A Florida Power Corp 1p. 17153 043 24X Fiche 50-302, 83/02/07, 8302150680

--8302150688 Responds to NRC 821227 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-25 Corrective actions mgt & procedural controls strengthened
 HANCOCK, J A Florida Power Corp 83/01/26 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 17153 044 24X Fiche 50-302, 83/02/07, 8302150680

--8302150692 Forwards IE Safeguards Insp Rept 50-302/82-25 on 821001 & notice of violation Notice of violation withheld (ref 10CFR73 21)
 LEWIS, R C Division of Project & Resident Programs 82/12/27 HANCOCK, J A Florida Power Corp 2pp 17153 046 24X
 Fiche 50-302, 83/02/07, 8302150680

--8302150700 IE Safeguards Insp Rept 50-302/82-25 on 821001 Noncompliance noted failure to provide compensatory measures for accessed vital area door Details withheld (ref 10CFR73 21)
 PERIHY, C D. STETKA, T F. MCQUIRE, D R Division of Engineering & Radiological Safety Programs 82/10/27 1p. 17153 048 24X
 Fiche 50-302, 83/02/07, 8302150680

8302170407 Ack receipt of 830126 ltr submitting payment of \$50,000 for civil penalties proposed by NRC 821227 ltr
 AVERAD, J A Enforcement Staff 83/02/07 HANCOCK, J A Florida Power Corp 3pp 17195 246 24X Fiche 50-302, 83/02/07, 8302170407

8302150058 Ack receipt of 820802 & 1001 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-10
 LEWIS, R C Division of Project & Resident Programs 83/02/09 HANCOCK, J A Florida Power Corp 1p 17146 336 24X Fiche 50-302, 83/02/09, 8302150058

--8302150067 Supplis 820802 response to NRC 820618 ltr re violations noted in IE Insp Rept 50-302/82-10 Corrective actions written test on compliance w/radiation & standing radiation work permits identified problem as isolated case
 BAYNARD, P Y Florida Power Corp 82/10/01 O'REILLY, J P Region 2, Office of Director 2pp 17146 337 24X Fiche 50-302, 83/02/09, 8302150058

--8302150071 Ack receipt of 820802 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-10
 LEWIS, R C Division of Project & Resident Programs 82/08/12 HANCOCK, J A Florida Power Corp 1p 17146 339 24X Fiche 50-302, 83/02/09, 8302150058

--8302150076 Responds to NRC 820618 ltr re violations noted in IE Insp Rept 50-302/82-10 Corrective actions special class 1 written test on compliance w/radiation & standing radiation work permits & general radiation protection practices provided
 MARDIS, D O Florida Power Corp 82/08/02 O'REILLY, J P Region 2, Office of Director 2pp 17146 340 24X Fiche 50-302, 83/02/09, 8302150058

--8302150085 Forwards IE Insp Rept 50-302/82-10 on 820427-0525 & notice of violation Description of actions taken or planned to improve effectiveness of mgt control sys requested
 LEWIS, R C Division of Project & Resident Programs 82/06/18 HANCOCK, J A Florida Power Corp 2pp 17146 342 24X Fiche 50-302, 83/02/09, 8302150058

--8302150089 Notice of violation from Insp on 820427-0525
 * Division of Project & Resident Programs 82/06/18 1p 17146 344 24X Fiche 50-302, 83/02/09, 8302150058

--8302150101 IE Insp Rept 50-302/82-10 on 820427-0525 Noncompliance noted failure to adhere to clothing requirements of standing radiation work permit
 STETKA, T F, SMITH, D W, BROWNLEE, V L Division of Project & Resident Programs 82/06/18 11pp 17146 345 24X Fiche 50-302, 83/02/09, 8302150058

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302230678 Requests relief from Article 1WB-2000 of ASME Code Section XI, 1974 edition re volumetric exam of nozzle welds Exam of full penetration welds of nozzles in vessels should be deferred until end or 10-yr insp interval
 WESTAFER, G R Florida Power Corp 83/02/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17259 241 24X Fiche 50-302, 83/02/21, 8302230678

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Redwaste - 10CFR20.302" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17341 148 24X Fiche 50-000, 83/02/24, 8212060366

R. Periodic operating reports & related correspondence

8302180327 Forwards monthly operating rept for Jan 1983
 BAYNARD, P Y Florida Power Corp 83/02/15 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 17210 001 24X Fiche 50-302, 83/02/15, 8302180327

--8302180332 Monthly operating rept for Jan 1983
 BOOART, D, Florida Power Corp 83/02/02 4pp 17210 002 24X Fiche 50-302, 83/02/15, 8302180327

S. Reportable occurrences, LERs & related correspondence

8302010220 Forwards LER 82-076/03L-0
 BAYNARD, P Y Florida Power Corp 83/01/19 O'REILLY, J P Region 2, Office of Director 1p 16974 043 24X Fiche 50-302, 83/01/19, 8302010220

--8302010229 LER 82-076/03L-0 on 821220, feedwater ultrasonic flow indicator FW-313-F1 & emergency feedwater train B discovered inoperable Caused by excessive heat in emergency feedwater line Line cooled Indicators will be replaced
 HUGHES, P O Florida Power Corp 83/01/19 Region 2, Office of Director 2pp 16974 044 24X Fiche 50-302, 83/01/19, 8302010220

8302010574 Forwards LER 83-001/01T-0
 WESTAFER, G R Florida Power Corp 83/01/20 O'REILLY, J P Region 2, Office of Director 1p 16977 049 24X Fiche 50-302, 83/01/20, 8302010574

--8302010578 LER 83-001/01T-0 on 830106, safety evaluation for 821215 failure or control complex radiation monitor RM-A5 revealed failure of RM-A5 to alarm in all failure modes constituted unreviewed safety question Caused by design inadequacy
 HUGHES, P O Florida Power Corp 83/01/20 Region 2, Office of Director 2pp 16977 050 24X Fiche 50-302, 83/01/20, 8302010574

8302030350 Forwards LER 82-077/03L-0
 WESTAFER, G R Florida Power Corp 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17005 356 24X Fiche 50-302, 83/01/28, 8302030350

--8302030353 LER 82-077/03L-0 on 821231, circuit breaker for DHV-6 found de-energized causing Loop B of LPIS to be inoperable Caused by personnel error Maint personnel accidentally tripped breaker Breaker closed upon discovery
 HUGHES, P O Florida Power Corp 83/01/28 Region 2, Office of Director 2pp 17005 357 24X Fiche 50-302, 83/01/28, 8302030350

8302280261 Forwards LER 83-002/03L-0
 WESTAFER, G R Florida Power Corp 83/02/15 O'REILLY, J P Region 2, Office of Director 1p 17312 284 24X Fiche 50-302, 83/02/15, 8302280261

--8302280268 LER 83-002/03L-0 on 830116, borated water storage tank level recorder BS-65-PR discovered inoperable Caused by loose drive cord on printer head Drive drum contacts tightened
 BUFEY, J L Florida Power Corp 83/02/15 Region 2, Office of Director 2pp 17312 285 24X Fiche 50-302, 83/02/15, 8302280261

8302280221 Forwards LER 83-003/03L-0
 WESTAFER, G R Florida Power Corp 83/02/17 O'REILLY, J P Region 2, Office of Director 1p 17304 358 24X Fiche 50-302, 83/02/17, 8302280221

--8302280227 LER 83-003/03L-0 on 830118, containment isolation valve (HUV-41) determined inoperable Cause unknown Valve scheduled for repair during next outage of sufficient duration
 HUGHES, P O Florida Power Corp 83/02/17 Region 2, Office of Director 2pp 17304 359 24X Fiche 50-302, 83/02/17, 8302280221

8302230502 Forwards EPA 821228 order changing NPDES Permit FLO000159 & 821228 notice of violation of modified permit Show cause order issued by EPA Licensee preparing response
 WESTAFER, G R Florida Power Corp 83/02/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 17245 184 24X Fiche 50-302, 83/02/21, 8302230502

8302280148 Forwards updated status of eight outstanding commitments re 800224 transient event Required final calibr & checkout of instrumentation added to Refuel IV outage schedule & will be completed prior to restart scheduled to begin 830319
 WESTAFER, G R Florida Power Corp 83/02/21 EISENHUT, D O Division of Licensing 2pp 17304 079 24X Fiche 50-302, 83/02/21, 8302280148

V. Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
 EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKETED ITEMS

8302180363 Submits tentative operator licensing schedule through 1985 in response to 830101 Generic Ltr 83-01 Exams scheduled for hot operator licenses or licenses upgraded from reactor operator to senior reactor operator
WEBSTER, G R Florida Power Corp 83/02/08 EISENHUT, D O
Licensing Branch 2 2pp 17210 183 24X Fiche 50-302, 83/02/08, 8302180363

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8210150452 Forwards reviews of procedures proposed by utils in emergency plans to consider meteorological conditions at facilities, in response to Task Order I of interagency agreement
VAN DER HOVEN Commerce, Dept. of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 SPICKLER, I Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X
Fiche 50-000, 82/10/08, 8210150452

--8301270044 "Evaluation of Procedures Proposed by Commonwealth Edison Co in Emergency Plans to Consider Meteorological Conditions in Zion Plant Coastal Environ"
VAN DER HOVEN Commerce, Dept. of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 307 24X
Fiche 50-000, 82/10/08, 8210150452

8302030137 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/26 Document Management Branch 1p 17023 313 24X Fiche 50-295, 83/01/26, 8302030137

--8307030139 Forwards public version of Rev 9 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List"
PLIM, G Commonwealth Edison Co 83/01/17 DENTON, H R NRC - No Detailed Affiliation Given 1p 17023 314 24X
Fiche 50-295, 83/01/26, 8302030137

--8302030143 Public version of Rev 9 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List" Revised index encl
* Commonwealth Edison Co 83/01/14 9pp 17023 315 24X
Fiche 50-295, 83/01/26, 8302030137

8302030226 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17013 343 24X Fiche 50-295, 83/01/27, 8302030226

--8302030238 Forwards public version of Rev 10 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group"
PLIM, G Commonwealth Edison Co 83/01/05 DENTON, H R NRC - No Detailed Affiliation Given 1p 17013 344 24X
Fiche 50-295, 83/01/27, 8302030226

--8302030245 Public version of Rev 10 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group"
* Commonwealth Edison Co 82/12/20 6pp 17013 345 24X
Fiche 50-295, 83/01/27, 8302030226

8302030622 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17013 087 24X Fiche 50-295, 83/01/27, 8302030622

--8302030624 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 510-2, "Generating Station Emergency Plan Training Requirements for Rad/Chem Technicians"
PLIM, G Commonwealth Edison Co 82/12/23 DENTON, H R NRC - No Detailed Affiliation Given 1p 17013 088 24X
Fiche 50-295, 83/01/27, 8302030622

--8302030626 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 510-2, "Generating Station Emergency Plan Training Requirements for Rad/Chem Technicians." Revised index encl
WILLIAMS, V S. Commonwealth Edison Co 82/12/21, 7pp 17013 089 24X Fiche 50-295, 83/01/27, 8302030622

8302040033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-27 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs
PAJUSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC - No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-27 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs Revised index encl
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-1118 guidelines valid
KEPPLER, J G Region 3, Office of Director 83/02/04 REED, C Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X
Fiche 50-000, 83/02/15, 8302180102

--8307180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
NELLS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302180518 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17221 249 24X Fiche 50-295, 83/02/15, 8302180518

--8302180520 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 410-1, "Onsite Support Ctr" Receipt form encl
PLIM, G Commonwealth Edison Co 83/01/21 DENTON, H R NRC - No Detailed Affiliation Given 3pp 17221 230 24X
Fiche 50-295, 83/02/15, 8302180518

--8302180541 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 410-1, "Onsite Support Ctr" Revised index encl
* Commonwealth Edison Co 83/01/21 4pp 17221 253 24X
Fiche 50-295, 83/02/15, 8302180518

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities Lists of locations encl
SHARTZ, E D Commonwealth Edison Co 83/01/28 KEPPLER, J G Region 3, Office of Director 4pp 17291 074 24X
Fiche 50-000, 83/02/18, 8302250349

P Operating license stage documents & correspondence

8302240073 Partial response to FOIA request for all prior & partial prior drafts & memos of probabilistic safety study Forwards documents listed in app Search for addl records in progress
FELTON, J M Division of Rules and Records 83/01/13 BLUM, J M Union of Concerned Scientists 2pp 17285 002 24X
Fiche 50-000, 83/01/13, 8302240073

DOCKETED ITEMS

137

--8302240082 'Accumulator Sys," revised draft chapter for PRA
* Pickard, Loue & Garrick, Inc 81/01/06 14pp 17285 004 24X
Fiche 50-030,83/01/13,8302240073

--8302240089 'Reactor Protection Sys," revised draft chapter for PRA
* Pickard, Loue & Garrick, Inc 81/01/06 27pp 17285 018 24X
Fiche 50-030,83/01/13,8302240073

8302090135 Forwards Containment Sys Branch SER of util 800508 & 820923
analyses of main steam line break w/continued feedwater
addition Analyses acceptable
VARGA, S A Operating Reactors Branch 1 83/01/26 DELGEORGE, L O
Commonwealth Edison Co 2pp 17119 326 24X Fiche 50-295,83/01/26,
8302090135

--8302090142 Containment Sys Branch SER supporting util 800508 & 820923
analyses of main steam line break w/continued feedwater
addition
* Containment Systems Branch 83/01/26 7pp 17119 328 24X
Fiche 50-295,83/01/26,8302090135

--8212200078 'PWR Main Steam Line Break W/Continued Feedwater Addition
(B-49), Zion Station Units 1 & 2," technical evaluation rept
VOSSBURY, F W Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5506-144 82/12/15 HEARN, P NRC - No
Detailed Affiliation Given 24pp 17119 335 24X
Fiche 50-295,83/01/26,8302090135

8302090483 Forwards safety evaluation on post-accident sampling sys
Plant meets five of 11 criteria in NUREG-0737, Item II B 3
Deficiencies listed
VARGA, S A Operating Reactors Branch 1 83/01/27 DELGEORGE, L O
Commonwealth Edison Co 22pp 17108 203 24X Fiche 50-295,
83/01/27,8302090483

8302080386 Notification of 830228 meeting w/util in Bethesda, MD to
discuss fuel mgt program for upcoming reload
NORRIS, J A Operating Reactors Branch 1 83/02/02 VARGA, S A
Operating Reactors Branch 1 2pp 17107 360 24X
Fiche 50-295,83/02/02,8302080386

8302280064 Forwards safety evaluation of util commitments to correct
human engineering deficiencies Submittal inconsistent w/util
verbal proposals Three deficiencies described Response due
in 30 days
VARGA, S A Operating Reactors Branch 1 83/02/04 DELGEORGE, L O
Commonwealth Edison Co 2pp 17314 284 24X Fiche 50-295,83/02/04,
8302280064

--8302280069 Safety evaluation re util commitments to correct human
engineering deficiencies Commitments inconsistent w/util
verbal proposals
* Office of Nuclear Reactor Regulation, Director 83/02/04 6pp
17314 285 24X Fiche 50-295,83/02/04,8302280064

8302090457 Resubmits 830105 ltr re final rept on results of containment
purge valve operability
LENTINE, F O Commonwealth Edison Co 83/02/07 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 17066 144 24X
Fiche 50-295,83/02/07,8302090457

--8302090464 Forwards "Analysis of 42-inch R1AB Class 75 Butterfly
Valves," final rept: Vol 1 Valve structural elements have
sufficient stress margins to withstand loads imposed while
valve closes from fully open position
LENTINE, F O Commonwealth Edison Co 83/01/05 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 17066 145
24X Fiche 50-295,83/02/07,8302090457

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Bvc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000,83/02/08,8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions Ability to use code must be
demonstrated by vendor or licensee Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000,83/02/08,8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed
NSSS (except Yankee Atomic Electric Co) re resolution of
TMI Action Item II.K 3.5, "Automatic Trip of Reactor Coolant
Pumps " Bvc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000,83/02/08,
8302090085

8302240228 Forwards request for addl info re NUREG-0737, Items II F 1.4,
"Containment Pressure Monitors," II F 1.5, "Containment
Water Level Monitor" & II F 1.6, "Containment Hydrogen
Monitor " Info expected within 30 days of ltr receipt
VARGA, S A Operating Reactors Branch 1 83/02/08 DELGEORGE, L O
Commonwealth Edison Co 9pp 17288 190 24X Fiche 50-295,83/02/08,
8302240228

8302180417 Application to amend Licenses DPR-39 & DPR-48, deleting all
nonradiological water quality specs from App B Tech Specs
LENTINE, F O Commonwealth Edison Co 83/02/10 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 17215 126 24X
Fiche 50-295,83/02/10,8302180417

8302230159 Requests withholding of matl provided to NRC & consultants
for preparation of technical evaluation repts re environ
qualification of electrical equipment Status of manufacturer
reviews will be submitted by 830515
LENTINE, F O Commonwealth Edison Co 83/02/17 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 17245 043 24X
Fiche 50-295,83/02/17,8302230159

8302280400 Forwards "Residual Strength of Inconel 600 Tubes
W/Longitudinal Discontinuities "
LENTINE, F O Commonwealth Edison Co 83/02/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 17309 346 24X
Fiche 50-295,83/02/18,8302280400

8302280152 Advises that review of 830121 final rule on environ
qualification of safety-related electrical equipment
incomplete Determination whether to reaffirm or withdraw
hearing request will be provided by 830324
STEPTOE, P P Isham, Lincoln & Beale 83/02/23 EISENHUT, D O
Division of Licensing 1p 17306 076 24X Fiche 50-000,83/02/23,
8302280152

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents
re facilities Personal info deleted from documents re util/
contractor employer allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17043 144 24X
Fiche 50-000,82/12/30,8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants,
consisting of total numbers of noncompliance items, repts
issued, insp hours, severity levels, points & hours per rept &
item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000,82/12/30,8302040039

8302150432 Forwards IE Insp Repts 50-295/82-30 & 50-304/82-27 on
821206-13 & notice of violation Differing insp dates noted
throughout package
HIND, J A Division of Emergency Preparedness & Operational Support,
83/01/17 REED, C Commonwealth Edison Co 3pp 17158 226 24X
Fiche 50-295,83/01/17,8302150432

--8302150437 Notice of violation from insp on 821206-16
HIND, J A Division of Emergency Preparedness & Operational
Support 83/01/12 1p 17158 229 24X Fiche 50-295,83/01/17,
8302150432

--8302150450 IE Insp Repts 50-295/82-30 & 50-304/82-27 on 821206-16,
Noncompliance noted failure to have approved procedure for
EBAR determination required by Tech Spec 6.2.A.7
ROZAK, S, NICHOLSON, N A, GEBMANN, M J Division of Emergency
Preparedness & Operational Support 83/01/10 8pp 17158 230
24X Fiche 50-295,83/01/17,8302150432

8302010620 Act receipt of 821202 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-295/81-32 &
50-304/81-30 Summary of 830112 meeting re clarification of
licensee action encl
KEPPLER, J O Region 3, Office of Director 83/01/24 REED, C,
Commonwealth Edison Co 5pp 16980 292 24X Fiche 50-295,83/01/24,
8302010620

--8302010627 Responds to NRC 821102 ltr re violations noted in IE Insp
Repts 50-295/81-32 & 50-304/81-30 Corrective actions
Awareness Day Program revised, drug policy meetings initiated
& presentation on harmful effects of drugs given
REED, C Commonwealth Edison Co 82/12/02 KEPPLER, J O Region
3, Office of Director 26pp 16980 277 24X
Fiche 50-295,83/01/24,8302010620

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Bvc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000,83/01/26,8212060358

DOCKETED ITEMS

8212060360 IE Info Notice 83-02, "Limiterque H0BC,H1BC,H2BC & H3BC
Oearheads " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to
10CFR50 B4 & 50 55 IE will conduct formal presentation
followed by question & answer session Requests that
participation be limited to three people
SPESSARD,R L Division of Engineering 83/01/28 Commonwealth
Edison Co 2pp 17008 187 24X Fiche 50-000,83/01/28,8302030303

8302150528 Requests delay until 830328 to respond to NRC request for
supplemental info re Rffs (a),(b),(c) & (e) of IE Bulletin
B1-03, "Flow Blockage of Cooling Water to Safety-Related Sys
Components by Asiatic Clams & Mussels "
SHARTZ,E D Commonwealth Edison Co 83/02/08 DENTON,H R Office
of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000,83/02/08,8302150528

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

R Periodic operating reports & related correspondence

8302170159 Forwards monthly operating repts for Jan 1983
GRAESSER,K L Commonwealth Edison Co 83/02/09, Director's
Office, Office of Inspection and Enforcement 1p 17180 304 24X
Fiche 50-295,83/02/09,8302170159

--8302170163 Monthly operating repts for Jan 1983
AUSTIN,G Commonwealth Edison Co 83/02/09, 11pp 17180 305
24X Fiche 50-295,83/02/09,8302170159

3 Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen
recombiner is likely to malfunction following exposure
to elevated temp,high humidity environ Replacement part
identification will be provided to operators by 830218
EMPEY,D C Rockwell International Corp 82/12/17 COLLINS,J
Region 4, Office of Director 4pp 17006-128 24X
Fiche 50-000,82/12/17,8302030495

8302040349 Forwards LER 83-002/01T-0
GRAESSER,K L Commonwealth Edison Co 83/01/28 KEPPLER,J O
Region 3, Office of Director 1p 17019 061 24X
Fiche 50-304,83/01/28,8302040349

-8302040353 LER 83-002/01T-0 on 830114,during power operation w/diesel
feed to bus 249 out of svc,spurious signal tripped & locked
all feeds to bus 247 Caused by mechanically jammed contact
annealing on reserve feed overcurrent relay
KAPLAN,S A Commonwealth Edison Co 83/01/28 Region 3, Office
of Director 2pp 17019 062 24X Fiche 50-304,83/01/28,
8302040349

8302080284 Forwards LER 82-001/03L-0
GRAESSER,K L Commonwealth Edison Co 83/02/02 KEPPLER,J O
Region 3, Office of Director 1p 17056 032 24X
Fiche 50-304,83/02/02,8302080284

-8302080287 LER 83-001/03L-0 on 830104,steam generator 2C steam pressure
lead/tag module 2PM-526B found out-of-tolerance high
Caused by instrument drift Module recaliber
CANTHELL,P F Commonwealth Edison Co 83/02/02 Region 3,
Office of Director, 1p 17056 033 24X Fiche 50-304,83/02/02,
8302080284

8302250193 Forwards LER 83-003/01T-0
GRAESSER,K L Commonwealth Edison Co 83/02/17 KEPPLER,J O
Region 3, Office of Director 1p 17293 005 24X
Fiche 50-304,83/02/17,8302250193

--8302250197 LER 83-003/01T-0 on 830124,while checking accuracy of
circulating water temp recorder 2TR-CW18,discovered recorder
to be inaccurate Caused by stuck pen & failed RTD Pen
repaired & RTD exchanged w/spare
STAINMER,F H Commonwealth Edison Co 83/02/17 Region 3,
Office of Director 1p 17293 006 24X Fiche 50-304,83/02/17,
8302250193

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees,applicants
for OL&S vendors,reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT,D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000,83/01/31,8301310203

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8302040287 Forwards IE Insp Rept 50-305/82-23 on 821129-1203,08-10
& 13 No noncompliance noted
PAPERIELLO,C J Division of Emergency Preparedness & Operational
Support 83/01/18 GIESLER,C W Wisconsin Public Service Corp
2pp 17018 156 24X Fiche 50-305,83/01/18,8302040287

--8302040303 IE Insp Rept 50-305/82-23 on 821129-1203,08-10 & 13 No
noncompliance noted Major areas inspected review of action
taken in response to emergency preparedness implementation
appraisal submitted on 821029
PAOLIARD,J A, SNELL,H W, ALEXSON,H L Division of Emergency
Preparedness & Operational Support 83/01/17 32pp 17018 158
24X Fiche 50-305,83/01/18,8302040287

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Supp 1,NUREG-0737, "Requirements for Emergency
Response Capability " Svc list encl
EISENHUT,D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000,83/02/01,8301210340

8302180407 Forwards IE Insp Rept 50-305/82-21 during Nov-Dec 1982 &
notices of violation & deviation
STREETER,J F Division of Project & Resident Programs 83/02/01
GIESLER,C W Wisconsin Public Service Corp 2pp 17214 276 24X
Fiche 50-305,83/02/01,8302180407

--8302180420 IE Insp Rept 50-305/82-21 during Nov-Dec 1982
Noncompliance noted failure to update svc water sys drawing
& mains in fig indication for RMS channel
NELSON,R L, REYES,L A Division of Project & Resident Programs
83/01/24 8pp 17214 280 24X Fiche 50-305,83/02/01,8302180407

8302100194 Accepts changes in Rev 3 to plant security force training &
qualification manual,listed in 820929 ltr
VARGA,S A Operating Reactors Branch 1 83/02/04 GIESLER,C W
Wisconsin Public Service Corp 2pp 17134 137 24X
Fiche 50-305,83/02/04,8302100194

P Operating license stage documents & correspondence

8302020347 Application for Amend 4B to License DPR-43,revising Tech
Specs Section 6,administrative controls,to reflect
reorganization of Nuclear Dept,effective 820601
GIESLER,C W Wisconsin Public Service Corp 83/01/13
GROTEHUIS,H NRC - No Detailed Affiliation Given 1p 16994 093
24X Fiche 50-305,83/01/13,8302020347

--8302020352 Proposed Tech Spec changes revising Section 6,administrative
controls to reflect reorganization of Nuclear Dept,
effective 820601
* Wisconsin Public Service Corp 83/01/13 19pp 16994 094
24X Fiche 50-305,83/01/13,8302020347

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT,D O Division of Licensing 83/01/18, DENTON,H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000,83/01/18,8302170019

DOCKETED ITEMS

139

--B302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed. Requests justification for continued operation of each group by 8/21/08 & 15, respectively.
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, B302170019

--B302170204 Concludes that sufficient info has been provided in B20226 ltr to justify continued operation pending completion of environ qualification program
GROTHENHUIS, M Operating Reactors Branch 1 82/10/28
EISENHUT, D O Division of Licensing 3pp 17197 016 24X
Fiche 50-000, 83/01/18, B302170019

B302080358 Forwards SER re main steam line break w/continued feedwater addition Util analysis acceptable
VARQA, S A Operating Reactors Branch 1 83/01/31 GIESLER, C W
Wisconsin Public Service Corp 2pp 17107 045 24X
Fiche 50-305, 83/01/31, B302080358

--B302080360 Safety evaluation supporting util analysis of PWR main steam line break w/continued feedwater addition
* Containment Systems Branch 83/01/31 7pp 17107 047 24X
Fiche 50-305, 83/01/31, B302080358

--B21200091 "PWR Main Steam Line Break W/Continued Feedwater Addition (B-49), Kewaunee Nuclear Power Plant," technical evaluation rept
VOSBURY, F W Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5906-148 82/12/15 HEARN, P NRC - No
Detailed Affiliation Given 25pp 66508 261 24X
Fiche 50-305, 83/01/31, B302080358

B302180054 Forwards SER & "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Vols 1 & 2," technical evaluation rept
VARQA, S A Operating Reactors Branch 1 83/02/02 GIESLER, C W
Wisconsin Public Service Corp 3pp 17224 001 24X
Fiche 50-305, 83/02/02, B302180054

--B302180056 SER on re-evaluation of "Environ Qualification of Safety-Related Electric Equipment" Deficiencies listed
* Equipment Qualification Branch 83/01/14 5pp 17224 004
24X Fiche 50-305, 83/02/02, B302180054

--B30180125 "Formal Issue Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Vols 1 & 2," technical evaluation rept
TOMAH, G J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5937-508 83/01/14 SHEMANSKI, P NRC - No
Detailed Affiliation Given 1,029pp 17224 009 24X
Fiche 50-305, 83/02/02, B302180054

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 7pp 17234 234 24X
Fiche 50-000, 83/02/08, B302080304

B302240190 Requests completion of Pratt purge & vent valve operability reviews & intentions to maintain SRP Section 6 & 2 4 re verification of closed vents
VARQA, S A Operating Reactors Branch 1 83/02/15 GIESLER, C W
Wisconsin Public Service Corp 5pp 17288 249 24X
Fiche 50-305, 83/02/15, B302240190

B302230466 Advises that copy of Technical Evaluation Rept C5257-532 required for preparation of 30-day response to SER, "Environ Qualification of Safety-Related Electrical Equipment" No proprietary info contained in SER
GIESLER, C W Wisconsin Public Service Corp 83/02/18 VARQA, S A
Operating Reactors Branch 1 2pp 17246 101 24X
Fiche 50-305, 83/02/18, B302230466

B302280166 Forwards justification for conservative application of Eiron plenum injection ECCS analysis to Kewaunee reload cores partially loaded w/Westinghouse fuel
GIESLER, C W Wisconsin Public Service Corp 83/02/22 VARQA, S A
Operating Reactors Branch 1 7pp 17306 001 24X
Fiche 50-305, 83/02/22, B302280166

G Inspection reports, IE Bulletins & correspondence

B302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, B302040039

--B302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHANSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J Q Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-030, 82/12/30, B302040039

B302040287 Forwards IE Insp Rept 50-305/82-23 on 821129-1203, 08-10 & 13 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/01/18 GIESLER, C W Wisconsin Public Service Corp
2pp 17018 156 24X Fiche 50-305, 83/01/18, B302040287

--B302040303 IE Insp Rept 50-305/82-23 on 821129-1203, 08-10 & 13 No noncompliance noted Major areas inspected review of action taken in response to emergency preparedness implementation appraisal submitted on 821029
PAOLIARD, J A, SNELL, W, AXELSON, W L Division of Emergency Preparedness & Operational Support 83/01/17 32pp 17018 158 24X
Fiche 50-305, 83/01/18, B302040287

B302040327 Forwards IE Mgt Meeting Rept 50-305/82-24 on 821214 No noncompliance noted
LITTLE, W S Division of Engineering 83/01/18 GIESLER, C W
Wisconsin Public Service Corp 2pp 17019 079 24X
Fiche 50-305, 83/01/18, B302040327

--B302040331 IE Mgt Meeting Rept 50-305/82-24 on 821214 No noncompliance noted Major areas discussed ASME Section XI inservice testing program for pumps & valves, including proposed Tech Spec Amend 25C & current inservice testing program review
WOMLO, P R, NELSON, R L, JACKIN, I N Division of Project & Resident Programs 83/01/10 3pp 17019 081 24X
Fiche 50-305, 83/01/18, B302040327

B212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X
Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice 83-02, "Limiter H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X
Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X
Fiche 50-000, 83/01/28, B212060361

B302030303 Advises of B30207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X
Fiche 50-000, 83/01/28, B302030303

B302040406 Ack receipt of B30124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/82-20.
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/01 GIESLER, C W Wisconsin Public Service Corp
1p 17017 334 24X Fiche 50-305, 83/02/01, B302040406

--B302040411 Responds to NRC 821223 ltr re violations noted in IE Insp Rept 50-305/82-20 Corrective actions containers for radioactive mats examined to ensure proper labeling
GIESLER, C W Wisconsin Public Service Corp 83/01/24
MILLER, J R Division of Emergency Preparedness & Operational Support 2pp 17017 335 24X
Fiche 50-305, 83/02/01, B302040406

B302180407 Forwards IE Insp Rept 50-305/82-21 during Nov-Dec 1982 & notices of violation & deviation
STREETER, J F Division of Project & Resident Programs 83/02/01
GIESLER, C W Wisconsin Public Service Corp 2pp 17214 276 24X
Fiche 50-305, 83/02/01, B302180407

--B302180411 Notice of violation from insp during Nov-Dec 1982
* Division of Project & Resident Programs 83/02/01 1p
17214 278 24X Fiche 50-305, 83/02/01, B302180407

DOCKETED ITEMS

--B302180416 Notice of deviation from insp during Nov-Dec 1982
 * Division of Project & Resident Programs 83/02/01 1p
 17214 279 24X Fiche 50-305, 83/02/01, B302180407

--B302180420 IE Insp Rept 50-305/82-21 during Nov-Dec 1982
 Noncompliance noted failure to update svc water sys drawing
 & maintain flow indication for RMS channel
 NELSON, R L, REYES, L A Division of Project & Resident Programs
 83/01/24 8pp 17214 280 24X Fiche 50-305, 83/02/01, B302180407

B321060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co of New
 York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B321060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
 Very Low Level Radwaste - 10CFR20 302" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B321060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

1 Periodic operating reports & related correspondence

B302160377 Forwards monthly operating rept for Jan 1983.
 GIESLER, C W Wisconsin Public Service Corp 83/02/10 Division
 of Data Automation & Management Information 1p 17164 175 24X
 Fiche 50-305, 83/02/10, B302160377

--B302160380 Monthly operating rept for Jan 1983
 RUITER, G H Wisconsin Public Service Corp 83/02/10 4pp
 17164 176 24X Fiche 50-305, 83/02/10, B302160377

2 Reportable occurrences, LERs & related correspondence

B302010343 Forwards LER 82-035/03L-1.
 GIESLER, C W Wisconsin Public Service Corp 83/01/24 KEPLER, J O
 Region 3, Office of Director 1p 16973 351 24X
 Fiche 50-305, 83/01/24, B302010343

--B302010350 LER 82-035/03L-1 on B21216, during full power operation,
 pinhole leak discovered in suction line from vol control
 tank to charging pumps Caused by vibrations & pulsations
 in associated piping Leak plugged
 * Wisconsin Public Service Corp 83/01/14 Region 3, Office of
 Director 1p 16973 352 24X Fiche 50-305, 83/01/24, B302010343

B302040340 Forwards LER 82-036/03L-0
 GIESLER, C W Wisconsin Public Service Corp 83/01/27 KEPLER, J O
 Region 3, Office of Director 1p 17018 252 24X
 Fiche 50-305, 83/01/27, B302040340

B302040347 LER 82-036/03L-0 on B21228, during startup following reactor
 trip, condensate water storage tank level fell below Tech
 Spec limit Caused by normal condensate water usage
 coincident w/demineralizer regeneration
 BERNHOFT, S L Wisconsin Public Service Corp 83/01/27 Region
 3, Office of Director 1p 17018 253 24X Fiche 50-305, 83/01/27,
 B302040340

B302080226 Forwards updated LER 82-030/01X-1
 GIESLER, C W Wisconsin Public Service Corp, 83/02/01 KEPLER, J O
 Region 3, Office of Director, 1p 17057 254 24X
 Fiche 50-305, 83/02/01, B302080226

B302080231 Updated LER 82-030/01X-1 on B21004, instrumentation lines
 found capped, rendering containment narrow- & wide-range
 pressure transmitters & containment vacuum breakers
 inoperable Caused by personnel error Caps removed
 SCHROCK, C A Wisconsin Public Service Corp, 83/02/01 Region
 3, Office of Director 5pp, 17057 255 24X Fiche 50-305,
 83/02/01, B302080226

B2150144 Forwards LER 83-001/03L-0
 GIESLER, C W Wisconsin Public Service Corp 83/02/04 KEPLER, J O
 Region 3, Office of Director 1p 17147 251 24X
 Fiche 50-305, 83/02/04, B302150144

--B302150191 LER 83-001/03L-0 on B30105, during full power operation,
 electrician performing maint pulled fuse to de-energize
 SV33379 which allowed caustic additive to drain from tank to
 suction of containment spray pumps
 BERNHOFT, S L Wisconsin Public Service Corp 83/02/04 Region
 3, Office of Director 2pp 17147 252 24X Fiche 50-305,
 83/02/04, B302150144

V Operator Examinations

B302040277 Notifies of administrative error in which senior reactor
 operator license renewal applications for AJ Ruege & RF Zube
 not submitted prior to license expiration on B20722 Licensed
 activities will not be performed until license renewal
 HINZ, D C Wisconsin Public Service Corp 83/01/26 STREETER, J
 Region 3, Office of Director 1p 17020 033 24X
 Fiche 50-305, 83/01/26, B302040277

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
 for OLS, AFS vendors, reactor vendors & AE re certificates
 & revised format for reactor operator & senior reactor
 operator licenses. Svc list encl
 EISENHUT, D O Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche 50-000, 83/01/31, B301310203

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B302030012 Releases public version of revised emergency plan
 implementing procedures
 FELTON, J M Division of Rules and Records 83/01/26 Document
 Management Branch 1p 17041 094 24X Fiche 50-000, 83/01/26,
 B302030012

--B302030018 Forwards public version of revised emergency plan
 implementing procedures, including Procedures EPIP 1 1 5 re
 startup operation of emergency offsite facility & EPIP 1 1 6
 re emergency organization shift turnover
 WARD, E C Northern States Power Co 83/01/20 Region 3, Office
 of Director 1p 17041 095 24X Fiche 50-000, 83/01/26,
 B302030012

--B302030023 Public version of revised emergency plan implementing
 procedures, including Procedures EPIP 1 1 5 re startup
 operation of emergency offsite facility & EPIP 1 1 6 re
 emergency organization shift turnover
 HUDSON, Q, WARD, E Northern States Power Co 83/01/20 46pp
 17041 096 24X Fiche 50-000, 83/01/26, B302030012

B301210340 Generic Ltr 83-04 to all licensees of operating reactors,
 applicants for OL & holders of CPs re regional workshop
 concerning Suppl 1, NUREG-0737, "Requirements for Emergency
 Response Capability" Svc list encl
 EISENHUT, D O Division of Licensing 83/02/01 Consolidated
 Edison Co of New York, Inc 11pp 17221 226 24X
 Fiche 50-000, 83/02/01, B301210340

B302100197 Forwards exemption from 10CFR50, App R requirement to
 install fixed fire suppression sys in control room
 CLARK, R A Operating Reactors Branch 3 83/02/02 HUSOLF, D M
 Northern States Power Co 3pp 17134 130 24X
 Fiche 50-282, 83/02/02, B302100197

--B302100200 Exemption from 10CFR50, App R requirement to install fixed
 fire suppression sys in control room
 EISENHUT, D O Division of Licensing 83/02/02 Northern States
 Power Co 4pp 17134 133 24X Fiche 50-282, 83/02/02, B302100197

J Insurance & indemnity information

B302150548 Forwards Endorsements 64.53 & 46 to NELIA Policies NF-174,
 NF-197 & MAELU Policies MF-51 & MF-68, respectively
 Endorsements 1, 2 & 3 to Certificates N-17, M-17, N-36, M-36,
 N-37 & M-37 also encl
 JOHNSON, R G Northern States Power Co 83/02/07 DINITZ, I
 Antitrust & Economic analysis Branch (Utility Finance) 59pp
 17156 152 24X Fiche 50-000, 83/02/07, B302150548

B302150628 Requests review of govt indemnity agreements for Licenses
 DPR-42, DPR-60 & DPR-22 re refund due for unexpired term
 JOHNSON, R G Northern States Power Co 83/02/07 DINITZ, I
 Antitrust & Economic analysis Branch (Utility Finance) 1p
 17151 306 24X Fiche 50-000, 83/02/07, B302150628

DOCKETED ITEMS

141

P Operating license stage documents & correspondence

8302080100 Addl response to FOIA request for records re steam generators & steam turbines Forwards documents listed under Category A of App E Category B documents available in PDR
FELTON, J M Division of Rules and Records 82/12/17 LONO, D J
Winthrop, Stimson, Putnam & Roberts 5pp 17105 069 24X
Fiche 50-000, 82/12/17, 8302080100

--8302080109 Summary of 741125 meeting w/util re steam generator tube corrosion Agenda, list of attendees & viewgraphs encl
KJINER, L L Atomic Energy Commission, Directorate of Licensing
74/12/05 Atomic Energy Commission, Directorate of Licensing
19pp 17105 074 24X Fiche 50-000, 82/12/17, 8302080100

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D G Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170123 Package of four comments indicating adequate or inadequate justification for interim operation re environ qualification of electrical equipment
PADOVAN, M L NRC - No Detailed Affiliation Given 82/01/27
NRC - No Detailed Affiliation Given 10pp 17196 255 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D G Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170293 Concludes that based on licensee 820127 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
DIANNI, D C Operating Reactors Branch 3 82/10/28
EISENHUT, D G Division of Licensing 5pp 17197 082 24X
Fiche 50-000, 83/01/18, 8302170019

8302020231 Forwards corrected Tech Spec Table 4 i-2A re ASME Code Class 1, 2 & 3 pump & valve Inservice Insp Program implementation, incorrectly issued w/830104 Amends 60 & 54 to Licenses DPR-42 & DPR-60, respectively
DIANNI, D C Operating Reactors Branch 3 83/01/25 MUSDOLF, D M Northern States Power Co 2pp 16999 190 24X
Fiche 50-282, 83/01/25, 8302020231

--8302020239 Corrected Tech Spec Table 4 i-2A re ASME Code Class 1, 2 & 3 pump & valve Inservice Insp Program implementation, incorrectly issued w/830104 Amends 60 & 54 to Licenses DPR-42 & DPR-60, respectively
* Operating Reactors Branch 3 83/01/25 1p 16999 192 24X
Fiche 50-282, 83/01/25, 8302020231

8302100185 Notification of 830211 meeting w/util in Bethesda, MD to resolve open items appearing in Amends 60 & 54 re inservice testing program for pumps & valves
DIANNI, D C Operating Reactors Branch 3 83/01/28 CLARK, R A Operating Reactors Branch 3 13pp 17134 164 24X
Fiche 50-282, 83/01/28, 8302100185

--8302100189 Forwards Mechanical Engineering Branch positions on relief requests that remain under review in 820104 SER
KNIGHT, J P Assistant Director for Core & Plant Systems
83/01/21 LAINAS, G C Assistant Director for Operating Reactors
6pp 17134 177 24X Fiche 50-282, 83/01/28, 8302100185

8302080144 Forwards suppl to 830128 info for review of safety evaluation methods topical rept re use of COBRA-III/MIT to determine bounds for locked rotor & slow rod withdrawal analysis
MUSDOLF, D M Northern States Power Co 83/01/31 Office of Nuclear Reactor Regulation, Director 3pp 17098 157 24X
Fiche 50-282, 83/01/31, 8302080144

8302160043 Forwards Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability Amend revises Tech Specs re steam generator tube surveillance & steam exclusion/auxiliary feedwater sys
DIANNI, D C Operating Reactors Branch 3 83/02/02 MUSDOLF, D M Northern States Power Co 3pp 17160 345 24X
Fiche 50-282, 83/02/02, 8302160043

--8302160052 Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs re steam generator tube surveillance, steam exclusion sys & auxiliary feedwater sys reporting requirements & administrative controls
CLARK, R A Operating Reactors Branch 3 83/02/02 27pp 17160 348 24X Fiche 50-282, 83/02/02, 8302160043

--8302160057 Safety evaluation supporting Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/02 14pp 17161 013 24X Fiche 50-282, 83/02/02, 8302160043

--8302160061 Notice of issuance & availability of Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively
CLARK, R A Operating Reactors Branch 3 83/02/02 2pp 17161 027 24X Fiche 50-282, 83/02/02, 8302160043

8302090415 Forwards XH-NF-79-49(P), Rev 1, "Reflex/UPI Analytical Model to Calculate Reflood Rates for PWRs W/Upper Plenum Injection," per NRC 821104 request Affidavit encl Rept withheld (ref 10CFR2.750)
MUSDOLF, D Northern States Power Co 83/02/03 Office of Nuclear Reactor Regulation, Director 4pp 17066 099 24X
Fiche 50-282, 83/02/03, 8302090415

8302150731 Notification of 830223 meeting w/util & Westinghouse in Bethesda, MD to discuss fuel assembly failure in spent fuel pool Agenda encl
DIANNI, D C Operating Reactors Branch 3 83/02/07 CLARK, R A Operating Reactors Branch 3 3pp 17160 104 24X
Fiche 50-282, 83/02/07, 8302150731

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for QL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Southern California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302240334 Forwards corrected Tech Spec & Tech Spec pages omitted from Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively, issued 830202 Amends revise Tech Specs re steam generator tube surveillance & steam exclusion sys
DIANNI, D C Operating Reactors Branch 3 83/02/15 MUSDOLF, D M Northern States Power Co 2pp 17290 173 24X
Fiche 50-282, 83/02/15, 8302240334

--8302240337 Corrected Tech Specs & Tech Spec pages omitted from Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively Amends revise Tech Specs re steam generator tube surveillance & steam exclusion sys
* Office of Nuclear Reactor Regulation, Director 83/02/15, 4pp 17290 173 24X Fiche 50-282, 83/02/15, 8302240334

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08, KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

DOCKETED ITEMS

8302010567 Forwards IE Insp Repts 50-282/82-24 & 50-306/82-24 on
821201-31 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 83/01/19
LARSON, C E Northern States Power Co 2pp 16977 077 24X
Fiche 50-282, 83/01/19, 8302010567

--8302010581 IE Insp Repts 50-282/82-24 & 50-306/82-24 on 821201-31. No
noncompliance noted Major areas inspected followup of IE
bulletins, safety verification, maint, surveillance, refueling
activities, reactor trip & offsite review committee
FEIERABEND, C D, WILLIAMS, D L, REYES, L Division of Project &
Resident Programs 83/01/10 9pp 16977 079 24X
Fiche 50-282, 83/01/19, 8302010557

8302020231 Forwards corrected Tech Spec Table 4 1-2A re ASME Code Class
1, 2 & 3 pump & valve Inservice Insp Program implementation,
incorrectly issued w/830104 Amends 60 & 54 to Licenses
DPR-42 & DPR-60, respectively
DIAHNI, D C Operating Reactors Branch 3 83/01/25 MUSOLF, D M
Northern States Power Co 2pp 16999 190 24X
Fiche 50-282, 83/01/25, 8302020231

--8302020239 Corrected Tech Spec Table 4 1-2A re ASME Code Class 1, 2 & 3
pump & valve Inservice Insp Program implementation,
incorrectly issued w/830104 Amends 60 & 54 to Licenses
DPR-42 & DPR-60, respectively
* Operating Reactors Branch 3 83/01/25 1p 16999 192 24X
Fiche 50-282, 83/01/25, 8302020231

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 11pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiterque H08C, H18C, H28C & H38C
Gearheads," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 10pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 11pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to
10CFR50 54 & 50 55 IE will conduct formal presentation
followed by question & answer session Requests that
participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth
Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302230427 Responds to Action Item 4 of IE Bulletin 82-02, "Degradation
of Threaded Fasteners in RCPs of PHR " Exam of closure
connections revealed no degradation
LARSON, C E Northern States Power Co 83/02/15 KEPLER, J G
Region 3, Office of Director 2pp 17246 124 24X
Fiche 50-282, 83/02/15, 8302230427

8302230681 Ack receipt of 830120 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-282/82-20 &
50-306/82-20
STREETER, J F Division of Project & Resident Programs 83/02/17
LARSON, C E Northern States Power Co 1p 17257 332 24X
Fiche 50-282, 83/02/17, 8302230681

8302230686 Responds to NRC 821227 ltr re violations noted in IE Insp
Repts 50-282/82-20 & 50-306/82-20. Corrective actions cap on
transmitter sensing line removed, lines labeled & warning
signs placed
LARSON, C E Northern States Power Co 83/01/20, STREETER, J F
Division of Project & Resident Programs 2pp 17257 333 24X
Fiche 50-282, 83/02/17, 8302230681

12060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 11pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363.

12060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
ry Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365.

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for GLS, RSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
ETSEKHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

8302070505 Responds to NRC 811007 ltr re violations noted in IE Health
Physics Appraisal Rept 50-309/81-01 Corrective actions
radiological control staff & training programs expanded to
provide addl technical support training
RANDAZZA, J B Maine Yankee Atomic Power Co 81/12/14 HAYNES, R C
Region 1, Philadelphia, Office of the Director (81/03/01) 12pp
17037 001 24X Fiche 50-309, 81/12/14, 8302070505

8302070562 Forwards replacement page for 830111 ltr, correcting
typographical errors in SALP rept Page should be substituted
for original No other changes made
STAROSTECKI, R Division of Project & Resident Programs 83/01/21
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 17034 171 24X
Fiche 50-309, 83/01/21, 8302070562

--8302070567 Forwards SALP rept for Aug 1981 - Jul 1982 Operational
performance acceptable & directed toward safe facility
operation
HAYNES, R C Region 1, Office of Director 83/01/11
RANDAZZA, J B Maine Yankee Atomic Power Co 3pp 17034 172 24X
Fiche 50-309, 83/01/21, 8302070562

--8302070572 SALP rept for Aug 1981 - Jul 1982 Overall performance
acceptable
* Region 1, Office of Director 82/09/20 38pp 17034 175 24X
Fiche 50-309, 83/01/21, 8302070562

--8302070586 Forwards SALP rept for Aug 1981 - Jul 1982 Meeting scheduled
for wk or 820927 to discuss plans to improve & assess plant
operations, design change/GA & emergency preparedness w/o
encl rept
STAROSTECKI, R Division of Project & Resident Programs 82/09/24
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 17034 213 24X
Fiche 50-309, 83/01/21, 8302070562

--8302070596 Comments on SALP rept for Aug 1981 - Jul 1982 Addl
corrective measures in areas of plant operations,
radiological controls, design control/GA, fire protection,
emergency preparedness, security & safeguards listed
RANDAZZA, J B Maine Yankee Atomic Power Co 82/10/15
STAROSTECKI, R Region 1, Office of Director 4pp 17034 214
24X Fiche 50-309, 83/01/21, 8302070562

8302010088 Confirms 831022 as date of CY83 emergency exercise
MARTIN, T T Division of Engineering & Technical Programs 83/01/27
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 16974 144 24X
Fiche 50-309, 83/01/27, 8302010088

8302100302 Forwards IE Insp Rept 50-309/82-24 on 821213-14 No
noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/27
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 17116 344 24X
Fiche 50-309, 83/01/27, 8302100302

--8302100303 IE Insp Rept 50-309/82-24 on 821213-14 No noncompliance
noted Major areas inspected followup on emergency
preparedness items from prior insp
SMITH, R H, CROCKER, H W Division of Emergency Preparedness &
Operational Support 83/01/26 5pp 17116 346 24X
Fiche 50-309, 83/01/27, 8302100302

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability " Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070519 Ack receipt of 821215 & 21 ltrs informing NRC of corrective
& preventive actions taken in response to Confirmatory
Action Ltr 82-27 Return to routine measures prescribed by
security plan acceptable
STAROSTECKI, R Division of Project & Resident Programs 83/02/02
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 17036 007 24X
Fiche 50-309, 83/02/02, 8302070519

DOCKETED ITEMS

143

--8302070526 Responds to NRC request for addl info re preliminary review of security measures, expansion of long-term review beyond security to related areas & unscheduled outages prior to long-term review, per Confirmatory Action Ltr 82-27
GARRITY, J H Maine Yankee Atomic Power Co 82/12/21 HAYNES, R C
Region 1, Office of Director 2pp 17036 009 24X
Fiche 50-309, 83/02/02, 8302070519

--8302070535 Provides status of tampering event & requests concurrence w/ relaxation of addl security measures taken Addl security measures instituted after discovery of tampering on 821118
listed Safeguards info deleted
GARRITY, J H Maine Yankee Atomic Power Co 82/12/15 HAYNES, R C
Region 1, Office of Director 3pp 17036 011 24X
Fiche 50-309, 83/02/02, 8302070519

8302230007 Advises that App R review of alternative shutdown for facility complete pending receipt of steam generator analysis
CLARK, R A Operating Reactors Branch 3 83/02/03 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 17241 347 24X
Fiche 50-309, 83/02/03, 8302230007

--8302230009 Exemption from App R of 10CFR50, allowing cold shutdown to be achieved in period greater than 72 h
EISENHUT, D O Division of Licensing 83/02/03 Maine Yankee
Atomic Power Co 3pp 17241 350 24X Fiche 50-309, 83/02/03, 8302230007

--8302230011 Safety evaluation re safe shutdown capability of facility
License exemption request re time to achieve cold shutdown acceptable
* Office of Nuclear Reactor Regulation, Director 83/02/03
12pp 17241 353 24X Fiche 50-309, 83/02/03, 8302230007

8302230430 Application for amend to License DPR-34, consisting of Proposed Change 99 to Tech Specs, revising frequency for performing independent audit of emergency & security plans & implementing procedures every 12 months
RANDAZZA, J B Maine Yankee Atomic Power Co 83/02/18 CLARK, R A
Operating Reactors Branch 3 2pp 17245 257 24X
Fiche 50-309, 83/02/18, 8302230430

--8302230442 Proposed Change 99 to Tech Specs, revising frequency for performing independent audit of emergency & security plans & implementing procedures every 12 months
* Maine Yankee Atomic Power Co 83/02/18 1p 17245 259 24X
Fiche 50-309, 83/02/18, 8302230430

G Adjudicatory correspondence

8302100219 Memorandum & order ruling on Sensible ME Power addl specific contentions & State of ME contentions Admits Power addl Contention 1 & ME addl Contention & All other addl contentions denied
LAZAR, R M Atomic Safety and Licensing Board Panel 83/02/08
Sensible Maine Power, 18pp 17114 035 24X Fiche 50-309, 83/02/08, 8302100219

8302220514 Informs that 821020 petition to revoke, suspend or modify DL pending demonstration of adequate financial resources to continue operation & provide for eventual decommissioning denied
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/02/14 MURRAY, P L Murray, Plumb & Murray 4pp 17235 327, 24X Fiche 50-309, 83/02/14, 8302220514

--8302220517 Director's Decision DD-83-3 denying Safe Power for ME 821020 petition to revoke, suspend or modify DL
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/02/14 4pp 17235 331 24X Fiche 50-309, 83/02/14, 8302220514

--8302220519 Notice of issuance & availability of Director's Decision DD-83-3 under 10CFR2 206, denying Safe Power for ME, et al request to revoke, suspend or modify DL
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/02/14 2pp 17235 335 24X Fiche 50-309, 83/02/14, 8302220514

8302220029 Notice of JM Outierrez withdrawal of appearance & RJ Goddard notice of appearance in proceeding Certificate of Svc encl.
OUTIERREZ, J M, GODDARD, R J Hearing Branch 3, 83/02/18 4pp
17233 171 24X Fiche 50-309, 83/02/18, 8302220029

8302230253 Forwards State of ME first set of interrogatories & request for production of documents Notice of appearance & Certificate of Svc encl
STERN, P Maine, State of 83/02/22 Docketing & Services Branch
3pp 17292 183 24X Fiche 50-309, 83/02/22, 8302230253

--8302230257 First set of interrogatories & requests for production of documents
AHRENS, P F, STERN, P Maine, State of 83/02/22 Maine Yankee
Atomic Power Co 82pp 17292 186 24X Fiche 50-309, 83/02/22, 8302230253

I Financial information

8302080288 Forwards statement of sources of funds for acquisition of nuclear fuel & const of electric property for 1982 & estimated capital requirements & sources for 1983
CRABTREE, R A Maine Yankee Atomic Power Co 83/02/03 BALTZMAN, J
Antitrust & Economic analysis Branch (Utility Finance) 3pp
17056 057 24X Fiche 50-309, 83/02/03, 8302080288

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8303220476 Notifies that sufficient justification for continued operation of facility during ongoing equipment qualification review has been provided by util
NELSON, C C Operating Reactors Branch 3 82/03/11 NOVAK, T M
Assistant Director for Operating Reactors 9pp 17196 348 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAQLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170181 Concludes that based on review, continued operation until completion of licensee environ qualification program will not present undue risk to public health & safety
HEITNER, K L Operating Reactors Branch 3 82/10/28
EISENHUT, D O Division of Licensing 2pp 17196 346 24X
Fiche 50-000, 83/01/18, 8302170019

8302100260 Forwards generic evaluation of radiological consequences of accidents while purging or venting at power (Multi-Plant Action Item 8-24), applicable to plant
CLARK, R A Operating Reactors Branch 3 83/01/19 GARRITY, J H
Maine Yankee Atomic Power Co 4pp 17134 096 24X
Fiche 50-309, 83/01/19, 8302100260

8302010085 Advises that util 821208 response to 820525-27 audit of procedures & training for pressurized thermal shock (PTS) reviewed Objectives of PTS audit met No further action required
CLARK, R A Operating Reactors Branch 3 83/01/23 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 16990 231, 24X
Fiche 50-309, 83/01/23, 8302010085

8302030469 Documents util plans for correcting feedwater sys problems recently encountered Summary of status of implementation of major aspects & results available encl
GARRITY, J H Maine Yankee Atomic Power Co 83/01/31 LAINAS, O C
Assistant Director for Operating Reactors 5pp 17006 152 24X
Fiche 50-309, 83/01/31, 8302030469

8302100492 Requests addl info re derivation of figures showing allowable power level w/inoperable CEA vs boron concentration included in shutdown margin definition
CLARK, R A Operating Reactors Branch 3 83/02/02 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 17143 269 24X
Fiche 50-309, 83/02/02, 8302100492

8302100496 Requests info discussed at 830121 meeting re pressurized thermal shock studies, particularly ME Yankee Atomic Co program intended to achieve significant flux reductions
CLARK, R A Operating Reactors Branch 3 83/02/02 GARRITY, J H
Maine Yankee Atomic Power Co 4pp 17143 265 24X
Fiche 50-309, 83/02/02, 8302100496

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

DOCKETED ITEMS

- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee. Svc list encl. EISENHUT, D. G. Division of Licensing 83/02/08. Consolidated Edison Co. of New York, Inc. 9pp 17234 234 24X. Fiche 50-000, 83/02/08, 8302080304.
- 8302090072 Generic Ltr 83-10B to all licensees w/C-E designed NSSR re resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Svc list encl. EISENHUT, D. G. Division of Licensing 83/02/08. Consumers Power Co. 32pp. 17290 185 24X. Fiche 50-000, 83/02/08, 8302090072.
- 8302200383 Submits addl info re relationship between COBRA IIIC & COBRA IV thermal-hydraulic models. In support of critical heat flux correlation review. Use of correlation w/other model using DNBR limit developed from COBRA IV justified. GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/16. CLARK, R. A. Operating Reactors Branch 3. 3pp 17232:145 24X. Fiche 50-309, 83/02/16, 8302200383.
- 8302200459 Provides status of ventilation stack & main steam line noble gas monitors, per TMI Action Item II.F.1.1. Measures for meeting requirement intent by monitoring w/hand held survey instruments remain in effect. GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/17. CLARK, R. A. Operating Reactors Branch 3. 2pp 17246:105 24X. Fiche 50-309, 83/02/17, 8302200459.
- 8302230304 Suppl 2 to Proposed Tech Spec Change 93 for License DPR-36, resubmitting changes originally proposed in 820929 ltr to replace Tech Spec changes proposed in 821118 ltr re Cycle 7 operation. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 83/02/18. CLARK, R. A. Operating Reactors Branch 3. 3pp 17243:334 24X. Fiche 50-309, 83/02/18, 8302230304.
- 8302230307 Proposed Tech Specs re Cycle 7 operation. * Maine Yankee Atomic Power Co. 83/02/18. 8pp 17243 339 24X. Fiche 50-309, 83/02/18, 8302230304.
- 8302230430 Application for amend to License DPR-36, consisting of Proposed Change 99 to Tech Specs, revising frequency for performing independent audit of emergency & security plans & implementing procedures every 12 months. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 83/02/18. CLARK, R. A. Operating Reactors Branch 3. 2pp 17243 257 24X. Fiche 50-309, 83/02/18, 8302230430.
- 8302230442 Proposed Change 99 to Tech Specs, revising frequency for performing independent audit of emergency & security plans & implementing procedures every 12 months. * Maine Yankee Atomic Power Co. 83/02/18. 1p. 17243:259 24X. Fiche 50-309, 83/02/18, 8302230430.
- 0 Inspection Reports, IE Bulletins & correspondence
- 8302070505 Responds to NRC B11007 ltr re violations noted in IE Health Physics Appraisal Rept 50-309/81-01. Corrective actions: radiological control staff & training programs expanded to provide addl technical support training. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 81/12/14. HAYNES, R. C. Region 1, Philadelphia, Office of the Director (B1/03/01) 12pp 17037 001 24X. Fiche 50-309, 81/12/14, 8302070505.
- 8302070562 Forwards replacement page for 830111 ltr, correcting typographical errors in SALP rept. Page should be substituted for original. No other changes made. STAROSTECKI, R. Division of Project & Resident Programs 83/01/21. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 1p. 17034:171. 24X. Fiche 50-309, 83/01/21, 8302070562.
- 8302070567 Forwards SALP rept for Aug 1981 - Jul 1982. Operational performance acceptable & directed toward safe facility operation. HAYNES, R. C. Region 1, Office of the Director 83/01/11. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 3pp 17034 172 24X. Fiche 50-309, 83/01/21, 8302070562.
- 8302070572 SALP rept for Aug 1981 - Jul 1982. Overall performance acceptable. * Region 1, Office of the Director 82/09/20. 38pp. 17034 175 24X. Fiche 50-309, 83/01/21, 8302070562.
- 8302070586 Forwards SALP rept for Aug 1981 - Jul 1982. Meeting scheduled for wk of 820927 to discuss plans to improve & assess plant operations, design change/GA & emergency preparedness w/o encl rept. STAROSTECKI, R. Division of Project & Resident Programs. 82/09/24. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 1p 17034 213 24X. Fiche 50-309, 83/01/21, 8302070562.
- 8302070596 Comments on SALP rept for Aug 1981 - Jul 1982. Addl corrective measures in areas of plant operations, radiological controls, design control/GA, fire protection, emergency preparedness, security & safeguards listed. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 82/10/19. STAROSTECKI, R. Region 1, Office of the Director 4pp 17034 214 24X. Fiche 50-309, 83/01/21, 8302070562.
- 8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design." Addl testing not warranted. TRAMMELL, C. K. Operating Reactors Branch 3. 83/01/25. Operating Reactors Branch 3. 25pp 17171 227 24X. Fiche 50-000, 83/01/25, 8302160014.
- 8312060358 IE Info Notice 83-01, "Ray Millar, Inc." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26. Consolidated Edison Co. of New York, Inc. 118pp 17023 160 24X. Fiche 50-000, 83/01/26, 8312060358.
- 8302100302 Forwards IE Insp Rept 50-309/82-24 on 821213-14. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/01/27. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 2pp 17116 344 24X. Fiche 50-309, 83/01/27, 8302100302.
- 8302100303 IE Insp Rept 50-309/82-24 on 821213-14. No noncompliance noted. Major areas inspected followup on emergency preparedness items from prior insp. SMITH, R. H., CROCKER, H. W. Division of Emergency Preparedness & Operational Support 83/01/26. 5pp 17116 346 24X. Fiche 50-309, 83/01/27, 8302100302.
- 8312060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28. Consolidated Edison Co. of New York, Inc. 109pp 17144 001 24X. Fiche 50-000, 83/01/28, 8312060360.
- 8312060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28. Consolidated Edison Co. of New York, Inc. 110pp 17074 095 24X. Fiche 50-000, 83/01/28, 8312060361.
- 8302150483 Forwards IE Insp Rept 50-309/82-24 on 821129-830104 & notice of violation. STAROSTECKI, R. Division of Project & Resident Programs 83/01/31. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 2pp 17156 282 24X. Fiche 50-309, 83/01/31, 8302150483.
- 8302150487 Notice of violation from insp on 821129-830104. * Division of Project & Resident Programs 82/01/31. 1p 17156 284 24X. Fiche 50-309, 83/01/31, 8302150483.
- 8302150495 IE Insp Rept 50-309/82-24 on 821129-830104. Noncompliance noted. Failure to carry radiation dose rate meter in high radiation area. SWETLAND, P., WIGGINS, J., GALLO, R. Division of Project & Resident Programs 83/01/19. 14pp 17156 285 24X. Fiche 50-309, 83/01/31, 8302150483.
- 8302180283 Forwards IE Insp Rept 50-309/82-13 on 820809-12. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/02/03. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 2pp 17211 252 24X. Fiche 50-309, 83/02/03, 8302180283.
- 8302180289 IE Insp Rept 50-309/82-13 on 820809-12. No noncompliance noted. Major areas inspected followup on response to IE Health Physics Appraisal Rept 50-309/81-01. GA-GC program re radwaste shipments & respiratory protection. COLLINS, D. J., WHITE, J. R., SHANBARY, M. M. Division of Engineering & Technical Programs 83/01/31. 11pp 17211 254 24X. Fiche 50-309, 83/02/03, 8302180283.
- 8302100416 Ack receipt of 830103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-16. STAROSTECKI, R. Division of Project & Resident Programs 83/02/04. RANDAZZA, J. B. Maine Yankee Atomic Power Co. 1p 17112 199 24X. Fiche 50-309, 83/02/04, 8302100416.
- 8302100421 Responds to NRC B21202 ltr re violations noted in IE Insp Rept 50-309/82-16. Corrective actions plant site procedure control sys revised. GARRITY, J. H. Maine Yankee Atomic Power Co. 83/01/03. HAYNES, R. C. Region 1, Office of the Director 2pp 17112:100. 24X. Fiche 50-309, 83/02/04, 8302100416.

8302250295 Forwards IE Insp Rept 50-309/82-27 on 821129-1207 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/02/10
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 17295 150 24X
Fiche 50-309, 83/02/10, 8302250295

--8302250300 IE Insp Rept 50-309/82-27 on 821129-1207 No noncompliance noted Major areas inspected review of allegations of improper maint & radiation protection practices
SWETLAND, P, GALLO, R Division of Project & Resident Programs 83/01/24 4pp 17295 152 24X Fiche 50-309, 83/02/10, 8302250295.

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302010308 Forwards updated LER 82-033/01X-2
GARRITY, J H Maine Yankee Atomic Power Co 83/01/21 Region 1, Office of Director 1p 16973 099 24X Fiche 50-309, 83/01/21, 8302010308

--8302010314 Updated LER 82-033/01X-2 on 821021, during fuel handling in spent fuel pool, inner surface of several spent fuel storage cells in Phase I spent fuel storage rack observed to be deformed & bulging into fuel storage space
LAFLAKHE, S J Maine Yankee Atomic Power Co 83/01/21 Region 1, Office of Director 2pp 16973 100 24X Fiche 50-309, 83/01/21, 8302010308

8302020243 Forwards request for addl info re offsite power supplies, to provide basis for evaluating 821214 low voltage condition.
CLARK, R A Operating Reactors Branch 3 83/01/24 GARRITY, J H. Maine Yankee Atomic Power Co 3pp 16999 187 24X
Fiche 50-309, 83/01/24, 8302020243

8302010504 PNO-I-83-003 on 830125, plant tripped as result of attempt to parallel two control element assembly drive motor generator sets out of phase due to split ground on dc power supplies. Containment temp & humidity increased
WIGGINS, J., KISTER, H Region 1, Office of Director 83/01/26 2pp 16978 088 24X Fiche 50-309, 83/01/26, 8302010504

8302070512 LER 83-002/01T-0 following reactor trip, leak in steam generator 2 feedline near inlet nozzle discovered. Plant placed in cold shutdown to determine cause of leak
WOOD, E C Maine Yankee Atomic Power Co 83/01/26 Region 1, Office of Director 1p 17037 074 24X Fiche 50-309, 83/01/26, 8302070512

8302010247 Updated PNO-I-83-003A on 830125, water hammer event occurred in feedwater supply piping to three steam generators during plant trip. Radiographic exam of welds & pipe stress analysis on feedwater piping will be conducted.
WIGGINS, J., KISTER, H Region 1, Office of Director 83/01/27 2pp 16974 050 24X Fiche 50-309, 83/01/27, 8302010247

8302250142 Summary of 830209 meeting w/util re 830125 feedwater line break event
HEITNER, K L Operating Reactors Branch 3 83/02/14 Operating Reactors Branch 3 98pp 17302 202 24X Fiche 50-309, 83/02/14, 8302250142

8302230554 Forwards info re resolution of recent feedwater sys event. Matl obtained from 830209 presentation in Bethesda, MD. Minor revs made & comments added. Description of water hammer test revised to reflect discussions during event
GARRITY, J H Maine Yankee Atomic Power Co 83/02/17 CLARK, R A Operating Reactors Branch 3 99pp 17261 048 24X
Fiche: 50-309, 83/02/17, 8302230554

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLs, K&S vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8302010706 Notification 83-06 of 830208 meeting w/util in King of Prussia, PA to discuss ongoing security program improvements & possible lifting of selected confirmatory action itr conditions
TRIPP, L E Division of Project & Resident Programs 83/01/27 Division of Project & Resident Programs 1p 16989 261 24X
Fiche 50-272, 83/01/27, 8302010706

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, 10CFR50-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D G Division of Licensing 83/02/01, Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche: 50-000, 83/02/01, 8301210340

8302100003 Response to 821124 request for approval of alternate means of storage of safeguards info. Considering location of container, method acceptable per 10CFR73.21
VARQA, S A Operating Reactors Branch 1 83/02/03 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 17135 181, 24X Fiche 50-272, 83/02/03, 8302100003

8302250329 Forwards IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/10, UDERITZ, R A Public Service Electric & Gas Co. of New Jersey, 2pp 17291 095 24X Fiche 50-272, 83/02/10, 8302250329

--8302250333 IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20. No noncompliance noted Major areas inspected: followup of emergency preparedness items identified in previous insp on 810520-22 & public notification sys
SHITH, R H Region 1, Office of Director 83/02/09 13pp 17291 097 24X Fiche 50-272, 83/02/10, 8302250329

8302250024 Forwards refund due from 820622 application for amend re protection of fire barrier penetrations. Addl sum requested re 821007 application for deferral of pressurizer surveillance for Unit 1 & drop test for Unit 2.
MILLER, W O License Fee Management Branch, 83/02/18 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 17299 361 24X Fiche 50-272, 83/02/18, 8302250024.

J Insurance & indemnity information

8302240019 Forwards Endorsements 44 & 56 to ANI/MAELU Policies MF-90 & NF-230, respectively
GOLDEN, M P Marsh & McLennan, Inc, M & H Nuclear Consultants, Inc Div 83/02/18 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17273 270 24X Fiche 50-272, 83/02/18, 8302240019

P Operating license stage documents & correspondence

8212210244 Application for amend to Licenses DPR-70 & DPR-75 modifying fuel enrichment for reactor cores & new & spent fuel racks to 4.05 weight % U-235. Nonproprietary analysis encl Proprietary analysis withheld (ref 10CFR2.790)
LIDEN, E A Public Service Electric & Gas Co. of New Jersey 82/12/03 VARQA, S A Operating Reactors Branch 1 13pp 16483 001, 24X Fiche 50-272, 82/12/03, 8212210244

8302020351 Forwards plant-specific data re safety & relief valve performance & adequacy of associated piping & block valves. Plans for valve & piping mods identified in review & implementation schedule also included.
LIDEN, E A Public Service Electric & Gas Co. of New Jersey 83/01/03 VARQA, S A Operating Reactors Branch 1 8pp, 16994 016 24X Fiche 50-272, 83/01/03, 8302020351

8302020280 Forwards comments on Science Applications, Inc 820923 draft final rept, "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events," per Generic Ltr 82-32
LIDEN, E A Public Service Electric & Gas Co. of New Jersey, 83/01/13 VARQA, S A Operating Reactors Branch 1 2pp, 16993 326 24X Fiche 50-272, 83/01/13, 8302020280

DOCKETED ITEMS

02020258 Forwards response to 830121 request for addl info re application to amend OL increasing allowable fuel enrichment in facilities
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/01/26 VARQA, S A Operating Reactors Branch 1 3pp 16994 261
 24X Fiche 50-272, 83/01/26, 8302020258

02020025 Forwards addl Class I amend fee for Tech Spec changes re Full enrichment on duplicate unit per 830106 response
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/01/27 MILLER, W D License Fee Management Branch 1p
 16994 340 24X Fiche 50-272, 83/01/27, 8302020025

02080045 Forwards Amend 17 to License DPR-75, safety evaluation & notice of issuance & availability. Amend allows licensee to delay installation of upper insp ports in steam generators until second refueling outage
 FISCHER, D G Operating Reactors Branch 1 83/01/27 UDERITZ, R A
 Public Service Electric & Gas Co. of New Jersey 4pp 17106:224
 24X Fiche 50-311, 83/01/27, 8302080045

8302080050 Amend 17 to License DPR-75, modifying License Condition 2 C 15(b) to allow licensee to delay installation of upper insp ports in steam generators until second refueling outage
 VARQA, S A Operating Reactors Branch 1 83/01/27 4pp
 17106 228 24X Fiche 50-311, 83/01/27, 8302080045

8302080054 Safety evaluation supporting Amend 17 to License DPR-75
 * Office of Nuclear Reactor Regulation, Director 83/01/27 2pp
 17106 232 24X Fiche 50-311, 83/01/27, 8302080045

8302080057 Notice of issuance & availability of Amend 17 to License DPR-75
 VARQA, S A Operating Reactors Branch 1 83/01/27 2pp
 17106:234 24X Fiche 50-311, 83/01/27, 8302080045

02180497 Application for amend to Licenses DPR-70 & DPR-75, changing Tech Specs to establish sys operability requirements for transfer functions of ECCS semiautomatic switchover from safety injection of recirculation during LOCA
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/01/27 VARQA, S A Operating Reactors Branch 1 4pp 17210 281
 24X Fiche 50-272, 83/01/27, 8302180497

8302180499 Proposed Tech Specs re EBF actuation sys instrumentation & semiautomatic switchover from injection to recirculation
 * Public Service Electric & Gas Co. of New Jersey 83/01/27
 62pp 17210 285 24X Fiche 50-272, 83/01/27, 8302180499

02160075 Forwards SER of NUREG-0737, Item II B.2.2 re design review of plant shielding & corrective actions for access to vital areas NUREG-0737 requirements met
 VARQA, S A Operating Reactors Branch 1 83/01/31 UDERITZ, R A
 Public Service Electric & Gas Co. of New Jersey 5pp 17160 328
 4X Fiche 50-272, 83/01/31, 8302160075

2180435 Application for amend to License DPR-75, revising Tech Specs re heat flux hot channel factor & control rod insertion limits Cycle 2 design, scheduled for startup in late May 1983, discussed Safety evaluation encl
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/01/31, VARQA, S A Operating Reactors Branch 1 7pp 17215 001
 24X Fiche: 50-311, 83/01/31, 8302180435

8302180439 Proposed Tech Specs re heat flux hot channel factor & control rod insertion limits
 * Public Service Electric & Gas Co. of New Jersey 83/01/31
 10pp 17215 008 24X Fiche 50-311, 83/01/31, 8302180435

2090386 Responds to NRC request for evaluation of proprietary nature of SER re environ qualification of safety-related electrical equipment Proprietary matl remains proprietary
 Proprietary matl remains available for public release
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/02/01 VARQA, S A Operating Reactors Branch 1 2pp 17067:013
 24X Fiche 50-272, 83/02/01, 8302090386.

2150623 Forwards proprietary & nonproprietary Rev 4 to "Environ Qualification Review Rept, Vols 1 & 2" Rev includes new data re Class IE instrumentation & electrical equipment proprietary version withheld (ref 10CFR2.790).
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/02/03 VARQA, S A Operating Reactors Branch 1 3pp 17154 268
 24X Fiche 50-272, 83/02/03, 8302150623.

8302150631 Rev 4 to "Environ Qualification Review Rept, Vols 1 & 2"
 * Public Service Electric & Gas Co. of New Jersey. 82/12/22
 292pp. 17154 281 24X Fiche 50-272, 83/02/03, 8302150623

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Quers Group emergency procedures guideline program Svc list encl
 EISENHUT, D G Division of Licensing 83/02/08 Consolidated
 Edison Co. of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
 EISENHUT, D G Division of Licensing 83/02/08 Consolidated
 Edison Co. of New York, Inc 7pp 17234 234 24X
 Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 S: "Automatic Trip of Reactor Coolant Pumps" Svc list encl
 EISENHUT, D G Division of Licensing 83/02/08 Southern
 California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302220289 Discusses 830201 meeting w/util re first periodic containment integrated leak rate test to be performed during first refueling outage
 MARTIN, T T Division of Engineering & Technical Programs 83/02/10
 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp
 17230 157 24X Fiche 50-311, 83/02/10, 8302220289

8302220385 Forwards "Control Room Design Review Program Plan," to meet NRC final requirements issued in Suppl 1 of NUREG-0737
 IDEN, E A Public Service Electric & Gas Co. of New Jersey
 83/02/14 VARQA, S A Operating Reactors Branch 1 1p 17232 152
 24X Fiche 50-272, 83/02/14, 8302220385

--8302220389 "Control Room Design Review Program Plan"
 * Public Service Electric & Gas Co. of New Jersey 82/11/30
 70pp 17232 153 24X Fiche 50-272, 83/02/14, 8302220385

8302250024 Forwards refund due from 820622 application for amend re protection of fire barrier penetrations Addl sum requested re 821007 application for deferral of pressurizer surveillance for Unit 1 & drop test for Unit 2
 MILLER, W D License Fee Management Branch 83/02/18 UDERITZ, R A
 Public Service Electric & Gas Co. of New Jersey 2pp 17299 361
 24X Fiche 50-272, 83/02/18, 8302250024

G Inspection reports, IE Bulletins & correspondence

8301140412 Forwards BALP rept on 821101 for period Sept 1981 - Aug 1982 Rept discussed at 821123 meeting
 HAYNES, R C Region 1, Office of Director 83/01/11 UDERITZ, R A
 Public Service Electric & Gas Co. of New Jersey 3pp 16989 202
 24X Fiche 50-272, 83/01/11, 8301140412

--8301140418 SALP rept on 821101 for period Sept 1981 - Aug 1982
 Performance acceptable
 * Region 1, Office of Director 82/11/01 38pp 16989 205 24X
 Fiche 50-272, 83/01/11, 8301140412

--8301140424 Forwards SALP board rept from review on 821101 Comments re rept to be discussed at 821123 meeting Written comments will be accepted within 20 days after meeting W/o encl
 STAROSTECKI, R Division of Project & Resident Programs 82/11/15
 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey
 1p 16959 241 24X Fiche 50-272, 83/01/11, 8301140412

--8302010025 Comments on 821101 SALP rept Comprehensive rept filed 821123 re actions taken concerning civil penalty imposed
 Priorities will still be established w/nuclear safety being of paramount concern at all mgt levels.
 UDERITZ, R W Public Service Electric & Gas Co. of New Jersey
 82/12/16 STAROSTECKI, R Division of Project & Resident Programs
 2pp 16989 242 24X Fiche 50-272, 83/01/11, 8301140412

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
 York, Inc 118pp. 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque HOBC, H1BC, H2BC & H3BC Gearheads" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
 York, Inc 109pp 17144, 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302250329 Forwards IE Insp Repts 50-272/83-03 & 50-311/83-02 on
830118-20 No noncompliance noted
MARLIN, T T Division of Engineering & Technical Programs 83/02/10
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
17291 095 24X Fiche 50-272, 83/02/10, 8302250329

--8302250333 IE Insp Repts 50-272/83-03 & 50-311/83-02 on 830118-20 No
noncompliance noted Major areas inspected followup of
emergency preparedness items identified in previous insp on
public notification sys
SMITH, R H, COHEN, I, CROCKER, H W Region 1, Office of Director
83/02/09 13pp 17291 097 24X Fiche 50-272, 83/02/10, 8302250329

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302220133 Forwards monthly operating rept for Jan 1983
MIDURA, H J Public Service Electric & Gas Co of New Jersey
83/02/10 Director's Office, Office of Inspection and Enforcement
ip 17233 275 24X Fiche 50-311, 83/02/10, 8302220133

--8302220138 Monthly operating rept for Jan 1983
MILLER, L K Public Service Electric & Gas Co of New Jersey
83/02/10 11pp 17233 276 24X Fiche 50-311, 83/02/10, 8302220133

S Reportable occurrences, LERs & related correspondence

8302070076 Partial response to FOIA request for 22 categories of
documents Forwards documents listed in App A Documents 12,
13, 16, 18, 19, 27 & 28 available in PDR App B documents
completely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, B
Union of Concerned Scientists 8pp 17063 005 24X
Fiche 50-311, 82/12/21, 8302070076

--8302070218 PNB-I-82-010 on 820816, manual isolation stop valve to air
start motors for 2C diesel generator found in shut position
Possibly caused by deliberate tampering Operability checks
of all rotating ECCS equipment conducted
TRIPP, L, KEIMIO, R R Region 1, Office of Director 82/08/17
2pp 17065 087 24X Fiche 50-000, 82/12/21, 8302070076

--8302070236 PNB-I-82-003 on 820428, at 100% power, one operating steam
generator feedwater pump tripped due to misaligned isolation
& vent valves Caused by sabotage Valves aligned Labor union
contract negotiations in progress
TRIPP, L E, GODY, A T, KEIMIO, R R Region 1, Office of Director
82/04/29 1p 17065 090 24X Fiche 50-000, 82/12/21, 8302070076

8302010303 Forwards LER 82-156/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
83/01/19 HAYNES, R C Region 1, Office of Director 3pp
16973 082 24X Fiche 50-311, 83/01/19, 8302010303

--8302010310 LER 82-156/03L-0 on 821229, control room operator observed
reactor coolant loop 23 flow channel III reading
erratically Caused by plugged transmitter sensing line
Sensing line backflushed Transmitter recalibr
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/01/19 Region 1, Office of Director. 1p 16973 085 24X
Fiche 50-311, 83/01/19, 8302010303

8302070457 Forwards LER 82-157/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
83/01/27 HAYNES, R C Region 1, Office of Director 3pp
17036 274 24X Fiche 50-311, 83/01/27, 8302070457

--8302070461 LER 82-157/03L-0 on 821231, operator discovered low pressure
carbon dioxide storage tank pressure less than required
285 psig Caused by sys refrigeration compressor failure
Switch cycled & recalibr
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/01/27 Region 1, Office of Director 1p 17036 277 24X
Fiche 50-311, 83/01/27, 8302070457

8302150501 Forwards LER 83-001/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
83/01/27 HAYNES, R C Region 1, Office of Director 3pp
17156 254 24X Fiche 50-311, 83/01/27, 8302150501

--8302150507 LER 83-001/03L-0 on 830106, reactor trip breaker A failed to
open following reactor trip Caused by malfunctioning breaker
undervoltage relay due to binding of relay mechanism by dirt
or corrosion Breaker replaced Periodic insp initiated
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/01/27 Region 1, Office of Director 1p 17156 257 24X
Fiche 50-311, 83/01/27, 8302150501

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8212210434 Responds to 821122 telcon request Responses to Generic Ltr
81-10 & recipients of emergency operations facility (EOP)
floor plans listed Final EOP comments due by 821230 Const/
renovation schedule to be established.
MATTINGOE, J J Sacramento Municipal Utility District 82/12/14
STOLZ, J F Operating Reactors Branch 4 2pp 16493 106 24X
Fiche 50-312, 82/12/14, 8212210434

8302030044 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17026 109 24X Fiche 50-312, 83/01/27,
8302030044

--8302030049 Forwards public version of revised emergency plan
implementing procedures, including Procedures AP 501 re
recognition & classification of emergency, AP 502 re
notification of unusual event & AP 503 re alert
MYERS, R Sacramento Municipal Utility District 83/01/05 NRC
- No Detailed Affiliation Given 2pp 17026 110, 24X
Fiche 50-312, 83/01/27, 8302030044

--8302030054 Public version of revised emergency plan implementing
procedures, including Procedures AP 501 re recognition &
classification of emergency, AP 502 re notification of
unusual event & AP 503 re alert
* Sacramento Municipal Utility District 82/11/10, 230pp
17026 112 24X Fiche 50-312, 83/01/27, 8302030044

8302010313 Responds to 821015 ltr re changes to Security Plan. Addl info
necessary to complete evaluation Requests response to encl
comments Comments withheld (ref 10CFR73 21)
STOLZ, J Operating Reactors Branch 4 83/01/31 MATTINGOE, J J
Sacramento Municipal Utility District 1p, 16973 086 24X
Fiche 50-312, 83/01/31, 8302010313

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302250305 Forwards documents relevant to issues under sua sponte
review. Documents include B&W 1977 Fuel Assembly Owners Group
safety task force rept on generic investigation of nozzle
component cracking
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Sacramento Municipal Utility District 83/02/23 ROSENTHAL, A B,
BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel
80pp 17299 223 24X Fiche 50-312, 83/02/23, 8302250305.

DOCKETED ITEMS

J. Insurance and indemnity information

8302240030 Forwards Certificates & Endorsements 1-3 to NELIA & MAELU Policies N-49 & M-49, respectively.
 MATTIMOE, J J Sacramento Municipal Utility District 83/02/03
 BALZHAN, J B Antitrust & Economic Analysis Branch (Utility Finance) 19pp 17274 356 24X Fiche 50-312, 83/02/03, 8302240030

F. Operating license stage documents & correspondence

8302020304 Application to amend License DPR-54, revising Tech Specs to assure operation in Cycle 6 core within applicable fuel design & performance criteria
 MATTIMOE, J J Sacramento Municipal Utility District 82/12/14
 EISENHUT, D O Office of Nuclear Reactor Regulation, Director 2pp 14994 168 24X Fiche 50-312, 82/12/14, 8302020304

--8302020310 Proposed Tech Specs 3 5 2.5 3.2 1-2.2 3-2.3-5 2-1 through 3 5 2-4 & 3 5 2-9 through 3 5 2 12 re control rod group & power distribution limits & reactor spec design features
 * Sacramento Municipal Utility District 82/12/14 16pp 14994 170 24X Fiche 50-312, 82/12/14, 8302020304

--8302020314 "Rancho Seco Unit 1 Cycle & Reload Rept."
 * Babcock & Wilcox Co BAW-1758 82/10/31 37pp 14994 186 24X Fiche 50-312, 82/12/14, 8302020304

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
 EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X Fiche 50-000, 83/01/18, 8302170019

--8302170123 Package of four comments indicating adequate or inadequate justification for interim operation re environ qualification of electrical equipment
 PADOVAN, M L NRC - No Detailed Affiliation Given 82/01/27
 NRC - No Detailed Affiliation Given 10pp 17196 255 24X Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
 EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X Fiche 50-000, 83/01/18, 8302170019

--8302170282 Concludes that based on licensee 820127 submittal, continued operation until completion of environ qualification program will not present undue risk to public health & safety
 MINER, S Operating Reactors Branch 4 82/10/28 EISENHUT, D O Division of Licensing 2pp 17197 076 24X Fiche 50-000, 83/01/18, 8302170019

1302150744 "Radiological Effluent Tech Specs (RETS) Implementation - Rancho Seco Nuclear Generating Plant," technical evaluation rept
 DUCE, B W, SERRANO, W, HANDLER, J W, EQ&O, Inc. FIN A-6459 8302150744 83/01/24 WILLIS, C Division of Systems Integration (post 811005) 50pp 17159 200 24X Fiche 50-312, 83/01/24, 8302150744

8302040208 Forwards "Containment Structural Post-Tensioning Sys Surveillance Test Rept (Eighth Yr Surveillance)" Rept results indicate that post-tensioning sys is functioning within limits specified in design criteria
 MATTIMOE, J J Sacramento Municipal Utility District 83/01/26 ENGELKEN, R H Region 5, Office of Director 1p 17020 199 24X Fiche 50-312, 83/01/26, 8302040208

-8302040213 "Containment Structural Post-Tensioning Sys Surveillance Test Rept (Eighth Yr Surveillance)"
 * Sacramento Municipal Utility District 82/12/31 96pp 17020 200 24X Fiche 50-312, 83/01/26, 8302040208

8302080256 Application for Amend 90 to License DPR-54, modifying Tech Specs re pressure-temp limits
 MATTIMOE, J J Sacramento Municipal Utility District 83/01/26 EISENHUT, D O Division of Licensing 2pp 17037 091 24X Fiche 50-312, 83/01/26, 8302080256

-8302080262 Proposed Tech Spec re pressure-temp limits
 * Sacramento Municipal Utility District 83/01/26 5pp 17037 093 24X Fiche 50-312, 83/01/26, 8302080256

8302040037 Advises that technical evaluation rept re environ qualification of safety-related electrical equipment contains matl considered proprietary (ref 10CFR2 790) Justification will be provided per NRC 830117 SER
 LATHAM, W K Sacramento Municipal Utility District 83/01/31 STOLZ, J F Operating Reactors Branch 4 1p 17023 324 24X Fiche 50-312, 83/01/31, 8302040037

8302040237 Advises that schedule for submission of B&W Owners Group Safe-End Task Force final rept will be submitted within 2 wks of receipt at district ofcs HPE nozzle insp program described in 821214 response to ALAB-703 & 830107 ltr
 LATHAM, W K Sacramento Municipal Utility District 83/01/31 STOLZ, J F Operating Reactors Branch 4 1p 17020 104 24X Fiche 50-312, 83/01/31, 8302040237

8302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to B&W plants, for use as starting point for addl detailed technical discussions between NRC & B&W Owners Group representatives
 LAJANAS, C C Assistant Director for Operating Reactors 83/01/31 WALLACE, E Babcock & Wilcox Operating Plants Owners Group 6pp 17134 100 24X Fiche 50-000, 83/01/31, 8302100257

8302100099 Lists info to be included in util submittal re present status & program schedules for flux reduction, per 830114 discussions
 STOLZ, J F Operating Reactors Branch 4 83/02/02 MATTIMOE, J J Sacramento Municipal Utility District 5pp 17135 001 24X Fiche 50-312, 83/02/02, 8302100099

8302080116 Notification of 830217 meeting w/util in Bethesda, MD to discuss proposed spent fuel pool expansion
 MINER, S Operating Reactors Branch 4 83/02/03 STOLZ, J F Operating Reactors Branch 4 2pp 17105 353 24X Fiche 50-312, 83/02/03, 8302080116

8302080161 Application to amend License DPR-54, requesting one-time only waiver from 18-month interval for normal refueling to 24-month interval due to extensive shutdowns for turbine rotor repairs, auxiliary feedwater spray header mod & tube leaks
 MATTIMOE, J J Sacramento Municipal Utility District 83/02/03 EISENHUT, D O Division of Licensing 3pp 17037 243 24X Fiche 50-312, 83/02/03, 8302080161

8302080162 Forwards addl info re low temp overpressurization protection sys not addressed in util 821104 response to NRC 820409 inquiry Proposed Tech Specs will be submitted upon resolution of subj concerns
 MATTIMOE, J J Sacramento Municipal Utility District 83/02/03 STOLZ, J F Operating Reactors Branch 4 7pp 17037 236 24X Fiche 50-312, 83/02/03, 8302080162

8302160218 Comments on Generic Ltr 82-32, "Potential Steam Generator Related Generic Requirements." Many recommended actions applicable to Westinghouse plants only
 MATTIMOE, J J Sacramento Municipal Utility District 83/02/03 EISENHUT, D O Division of Licensing 3pp 17163 179 24X Fiche 50-312, 83/02/03, 8302160218

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E FHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc, list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

8302090098 Generic Ltr 83-10F to all licensees w/B&W designed NBSS (except TH1) re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Duke Power Co 23pp 17298 291 24X Fiche 50-000, 83/02/08, 8302090098

8302150150 Documents info presented at 830114 meeting w/NRC in Bethesda, MD re pressurized thermal shock flux reduction programs, to provide addl clarification & schedule for submittal of info not currently available
 MATTIMOE, J J Sacramento Municipal Utility District 83/02/08 STOLZ, J F Operating Reactors Branch 4 16pp 17147 238 24X Fiche 50-312, 83/02/08, 8302150150

DOCKETED ITEMS

149

8302150533 Submits supplemental info re Test meters, thermocouple & acoustic monitors on electromagnetic & safety relief valves & visual indication via TV camera on top of pressurizer, per 830203 license waiver
MATTIHOE, J J Sacramento Municipal Utility District 83/02/08
EISENHUT, D G Division of Licensing 1p 17156 219 24X
Fiche 50-312, 83/02/08, 8302150533

8302250133 Forwards Amend 43 to License DPR-54, safety evaluation & notice of issuance & availability Amend revises offsite organizational chart
MINER, S Operating Reactors Branch 4 83/02/10 MATTIHOE, J J
Sacramento Municipal Utility District 3pp 17302 317 24X
Fiche 50-312, 83/02/10, 8302250133

--8302250138 Amend 43 to License DPR-54, changing Tech Specs to revise licensee offsite safety organization chart
STOLZ, J F Operating Reactors Branch 4 83/02/10 App
17302 320 24X Fiche 50-312, 83/02/10, 8302250133

--8302250143 Safety evaluation supporting Amend 43 to License DPR-54
* Office of Nuclear Reactor Regulation, Director 83/02/10. 2pp
17302 324 24X Fiche 50-312, 83/02/10, 8302250133

--8302250148 Notice of issuance & availability of Amend 43 to License DPR-54
STOLZ, J F Operating Reactors Branch 4 83/02/10. 2pp
17302 326 24X Fiche 50-312, 83/02/10, 8302250133

8302220319 Advises that addl info re inservice testing program relief requested in 821215 ltr will be mailed on 830304
MATTIHOE, J J Sacramento Municipal Utility District 83/02/15
EISENHUT, D G Division of Licensing 1p 17230 151 24X
Fiche 50-312, 83/02/15, 8302220319

8302230620 Application for amend to License DPR-54 consisting of changes to Tech Specs decreasing allowable diesel outages identified in NRC 821110 ltr
MATTIHOE, J J Sacramento Municipal Utility District 83/02/15
STOLZ, J F Operating Reactors Branch 4 2pp 17255 233 24X
Fiche 50-312, 83/02/15, 8302230620

--8302230629 Proposed Tech Spec 3 7 2 C providing limiting condition for operation allowing plant operation for 15 days following inoperability of one of two diesel generators Cold shutdown will follow if diesel not returned to svc at end of 15 days
* Sacramento Municipal Utility District. 83/02/15 1p
17255 235 24X Fiche 50-312, 83/02/15, 8302230620

8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098. 24X
Fiche 50-000, 83/02/17, 8302250102

8302250380 Application for Amend 92 to License DPR-54 deleting sections re water quality control as governed by State of CA Regional Water Quality Control Board from Tech Specs
MATTIHOE, J J Sacramento Municipal Utility District 83/02/17
EISENHUT, D G Division of Licensing 1p. 17277 223. 24X
Fiche 50-312, 83/02/17, 8302250380

--8302250386 Proposed Tech Specs deleting sections re water quality control as governed by State of CA Regional Water Quality Control Board
* Sacramento Municipal Utility District 83/02/17 12pp
17277 224 24X Fiche 50-312, 83/02/17, 8302250380

8302280209 Application for Amend 83 to License DPR-54, revising Tech Specs re reactor protection sys trip setting limits in response to NUREG-0737 & NRC 820920 ltr
MATTIHOE, J J Sacramento Municipal Utility District 83/02/17
EISENHUT, D G Division of Licensing 1p 17311 324 24X
Fiche 50-312, 83/02/17, 8302280209

--8302280214 Proposed Tech Specs re reactor protection sys trip setting limits, in response to NUREG-0737 & NRC 820920 ltr
* Sacramento Municipal Utility District 83/02/17 19pp.
17311 325 24X Fiche. 50-312, 83/02/17, 8302280209

8302230163 Forwards addl info re NUREG-0737, Item II E.1 i. "Auxiliary Feedwater Sys Review," in response to NRC 821208 ltr Summary of 721115 meeting w/util encl
MATTIHOE, J J Sacramento Municipal Utility District 83/02/18
STOLZ, J F Operating Reactors Branch 4 7pp 17245.059. 24X
Fiche 50-312, 83/02/18, 8302230163

--8302230172 Summary of 721115 meeting w/util & Bechtel in Bethesda, MD re tornado characteristics, offsite transportation of radioactive liquids, effluent monitoring & hydrogen detection in liquid holdup tanks following LOCA
BUCKLEY, B C Atomic Energy Commission - Deputy Director for Reactor Projects 73/01/17 DEYOUNG, R C Atomic Energy Commission - Deputy Director for Reactor Projects. App
17249 066 24X Fiche 50-312, 83/02/18, 8302230163

8302280043 Advises that justification for continued operation will be provided by 831015 Delay due to increased workload of current outage & scope of requested analysis Submittal date approx 90 days after scheduled completion of outage
MATTIHOE, J J Sacramento Municipal Utility District. 83/02/22
STOLZ, J F Operating Reactors Branch 4 1p 17307 198 24X
Fiche 50-312, 83/02/22, 8302280043

Q Inspection reports, IE Bulletins & correspondence

8302070281 Responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " No Bunker-Ramo assemblies purchased for facility
MATTIHOE, J J Sacramento Municipal Utility District. 83/01/17
ENGELKEN, R H. Region 5, Office of Director. 1p 17031 150. 24X
Fiche 50-312, 83/01/17, 8302070281

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitrophe H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp. 17144 001 24X Fiche 50-000, 83/01/28, 8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302090166 Forwards safety evaluation re util 790718, 1214 & 820419 requests for relief from inservice insp requirements, Grants relief in part.
STOLZ, J F Operating Reactors Branch 4 83/01/28 MATTIHOE, J J
Sacramento Municipal Utility District 3pp 17121 297 24X
Fiche 50-312, 83/01/28, 8302090166

--8302090172 Safety evaluation granting in part requests for relief from inservice insp requirements.
* Office of Nuclear Reactor Regulation, Director 83/01/28 14pp 17121 300 24X Fiche 50-312, 83/01/28, 8302090166

--8209030368 "Rancho Seco Nuclear Generating Station, Unit 1, Inservice Insp Program," technical evaluation rept
* Science Applications, Inc SAI-186-028-13 82/08/27. 37pp.
17121 310 24X Fiche 50-312, 83/01/28, 8302090166

8302230251 Forwards IE Insp Rept 50-312/82-45 on 821115-19, No noncompliance noted
BOOK, H E Division of Radiological Safety & Safeguards Program 83/02/02 MATTIHOE, J J Sacramento Municipal Utility District. 2pp.
17244 286 24X Fiche 50-312, 83/02/02, 8302230251

--8302230256 IE Insp Rept 50-312/82-45 on 821115-19 No noncompliance noted Major areas inspected lab quality control program, including independent confirmatory measurements involving Region V mobile lab
HAMADA, G H., TEMPLE, G M., NENSLAWSKI, F Division of Radiological Safety & Safeguards Program 83/02/01 10pp. 17244 288. 24X
Fiche 50-312, 83/02/02, 8302230251

8302230261 Forwards IE Insp Rept 50-312/83-02 on 830103-31 & notice of violation.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/02/10 MATTIHOE, J J Sacramento Municipal Utility District. 2pp 17244 348 24X Fiche 50-312, 83/02/10, 8302230261

--8302230264 Notice of violation from insp on 830103-31.
YOUNG, T Division of Resident, Reactor Project & Engineering Programs 83/02/10 1p 17244 350. 24X Fiche: 50-312, 83/02/10, 8302230261

--8302230271 IE Insp Rept 50-312/83-02 on 830103-31. Noncompliance noted - NRC not immediately notified of accidental, unplanned & uncontrolled radioactive release identified on 830120 from chemical analysis
CANTER, H L., O'BRIEN, J., YOUNG, T Division of Resident, Reactor Project & Engineering Programs 83/02/09. 11pp 17244 351. 24X
Fiche 50-312, 83/02/10, 8302230261

DOCKETED ITEMS

8302220529 Discusses IAEA 830121-22 insp per 830207 telcon
Identification for IAEA representatives participating in
830222 refueling outage encl H/a encl
STOLZ, J F Operating Reactors Branch 4 83/02/15 MATTIMOE, J J
Sacramento Municipal Utility District 3pp 17234 354 24X
Fiche 50-312, 83/02/15, 8302220529

8302230366 Forwards "B&W 177 Fuel Assembly Owners Group Safe End Task
Force Rept on Generic Investigation of HPI/MV Nozzle
Component Cracking," per util 830131 commitment Task force
recommendations endorsed w/exception of inservice insp
MATTIMOE, J J Sacramento Municipal Utility District 83/02/16
STOLZ, J F Operating Reactors Branch 4. 1p 17247 283 24X
Fiche 50-312, 83/02/16, 8302230366

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18. Consolidated Edison Co of New
York, Inc. 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302280197 Forwards Rev 7 to Surveillance Procedure 212 01A, in response
to IE Bulletin 81-03, "Flow Blockage of Cooling Water to
Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus
Sp (Mussel) "
MATTIMOE, J J Sacramento Municipal Utility District 83/02/18
JORDAN, E L Division of Safeguards & Inspection Programs (Post
830103) 1p 17312 171 24X Fiche 50-312, 83/02/18, 8302280197

--8302280201 Rev 7 to Surveillance Procedure 212 01A, "Nonradiological
Environ Protection Surveillance "
* Sacramento Municipal Utility District 82/08/09 13pp.
17312 179 24X Fiche 50-312, 83/02/18, 8302280197

8302250305 Forwards documents relevant to issues under sua sponte
review Documents include B&W 1977 Fuel Assembly Owners Group
safe-end task force rept on generic investigation of nozzle
component cracking
BAXTER, T A, Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Sacramento Municipal Utility District 83/02/23 ROSENTHAL, A S,
BUCK, J H, KOHL, C N. Atomic Safety and Licensing Appeal Panel
80pp 17295 223 24X Fiche 50-312, 83/02/23, 8302250305

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc. 110pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc. 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302170373 Forwards monthly operating rept for Jan 1983,
RODRIGUEZ, R J Sacramento Municipal Utility District 83/02/04
Director's Office, Office of Inspection and Enforcement 1p.
17183 320, 24X Fiche 50-312, 83/02/04, 8302170373

--8302170376 Monthly operating rept for Jan 1983
COLOMBO, R Sacramento Municipal Utility District 83/01/31 4pp
17183 321, 24X Fiche 50-312, 83/02/04, 8302170373

8302180149 Forwards corrected pages to 1981 semiannual effluent release
rept, reflecting lower calculated public exposure from
releases of radioactive liquid for Jan-June 1981. Original
values wrong due to error in computer program.
MATTIMOE, J J Sacramento Municipal Utility District, 83/02/07
Region 5, Office of Director 1p 17216:137, 24X
Fiche 50-312, 83/02/07, 8302180149

--8302180154 Corrected pages to 1981 semiannual effluent release rept
* Sacramento Municipal Utility District 83/02/07 2pp.
17216 138 24X Fiche 50-312, 83/02/07, 8302180149

B. Reportable occurrences, LERs & related correspondence

8302040259 Forwards LER 83-004/04T-0, Detailed event analysis submitted
MATTIMOE, J J, Sacramento Municipal Utility District 83/01/28,
ENGELKEN, R H Region 5, Office of Director. 2pp 17020 051, 24X
Fiche, 50-312, 83/01/28, 8302040259

--8302040276 LER 83-004/04T-0 on 830120, during transfer of tritiated
water from miscellaneous waste condensate tank A to
miscellaneous water holdup tank, overflow resulted, causing
contaminated water to enter effluent discharge
COLOMBO, R W Sacramento Municipal Utility District 83/01/28
Region 5, Office of Director 1p 17020 053 24X
Fiche 50-312, 83/01/28, 8302040259

8302230604 Forwards LER 83-003/03L-0 Detailed event analysis submitted
MATTIMOE, J J Sacramento Municipal Utility District 83/02/10
ENGELKEN, R H Region 5, Office of Director 2pp 17255 208 24X
Fiche 50-312, 83/02/10, 8302230604

--8302230613 LER 83-003/03L-0 on 830111, procedure to test RPS master
reactor trip relay KA & safety features actuation signal
analog channel logic buffer trip relay determined not to
meet Tech Spec Specs will be rewritten
COLOMBO, R W Sacramento Municipal Utility District 83/02/09
Region 5, Office of Director 1p 17255 210 24X
Fiche 50-312, 83/02/10, 8302230604

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for DLs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302150214 Lists operator license exam site visits through 851231,
per Generic Ltr 83-01
MATTIMOE, J, Sacramento Municipal Utility District 83/02/04
EISENHUT, D G Division of Licensing 1p 17190 031 24X
Fiche 50-312, 83/02/04, 8302150214

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

8302070374 Forwards IE Insp Repts 50-313/82-33 & 50-368/82-33 on
821115-19 & notice of violation
SEIDLE, W C Division of Resident, Reactor Project & Engineering
Programs 83/01/18 CAVANAUGH, W Arkansas Power & Light Co 2pp
17030 042 24X Fiche 50-313, 83/01/18, 8302070374

--8302070391 IE Insp Repts 50-313/82-33 & 50-368/82-33 on 821115-19
Noncompliance noted failure of plant safety committee to
investigate licensee identified Tech Spec violation &
failure to maintain penetration fire barriers functional
MURPHY, M E, STEWART, R C, MCCORRY, S L Division of Resident,
Reactor Project & Engineering Programs 83/01/06 10pp
17030 045 24X Fiche 50-313, 83/01/18, 8302070374

8302040060 Notification of 830216 meeting w/util & Nuclear Util Fire
Protection Group in Bethesda, MD to discuss util appeal of
NRC positions re fire protection App R exemption requests
LYNCH, O D T Operating Reactors Branch 3 83/01/26 CLARK, R A
Operating Reactors Branch 3 3pp 17043 176 24X
Fiche 50-313, 83/01/26, 8302040060

8302170509 Notification of cancellation of 830216 meeting w/util in
Bethesda, MD to appeal NRC positions re fire protection App
R exemption requests
LYNCH, O D T Operating Reactors Branch 3 83/01/26 CLARK, R A,
Operating Reactors Branch 3 1p 17197, 097, 24X
Fiche 50-313, 83/01/26, 8302170509

8302030391 Confirms 830124 & 25 telcons re discussions on App R appeal
meeting scheduled for 830128 Util understands NRC will grant
all exemption requests addressed in 821111 ltr
MARSHALL, J R Arkansas Power & Light Co 83/01/28, STOLZ, J F
Operating Reactors Branch 4 CLARK, R A, Operating Reactors Branch
3 2pp 17005 324 24X Fiche: 50-313, 83/01/28, 8302030391

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability " Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp, 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070462 Ack receipt of 821101 ltr informing NRC of steps taken to
resolve open items noted in IE Emergency Planning Insp
Repts 50-313/82-11 & 50-368/82-09
SEIDLE, W C Division of Resident, Reactor Project & Engineering
Programs 83/02/01 CAVANAUGH, W Arkansas Power & Light Co 2pp
17036:281 24X Fiche 50-313, 83/02/01, 8302070462

DOCKETED ITEMS

151

--B302070468 Responds to NRC 820928 ltr re open items noted in IE Emergency Planning Insp Repts 50-313/82-11 & 50-368/82-09 Schedule for resolving open items encl
MARSHALL, J R Arkansas Power & Light Co 82/11/01 COLLINS, J T
Region 4, Office of Director 6pp 17036 283 24X
Fiche 50-313, 83/02/01, 8302070462

B302070295 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/03 Document
Management Branch 1p 17041 210 24X Fiche 50-313, 83/02/03, 8302070295

--B302070297 Forwards public version of revised emergency plan implementing procedures, including Procedures 1903 31 re exclusion area evacuation & 1904 07 re protective action recommendations
* Arkansas Power & Light Co 83/01/26 NRC - No Detailed
Affiliation Given 2pp 17061 211 24X Fiche 50-313, 83/02/03, 8302070295

--B302070299 Public version of revised emergency plan implementing procedures, including Procedures 1903 31 re exclusion area evacuation & 1904 07 re protective action recommendations
LEVINE, J M Arkansas Power & Light Co 83/01/26 112pp
17061 213 24X Fiche 50-313, 83/02/03, 8302070295

B302080180 Ack receipt of 821231 ltr re security sys NRC pleased w/progress & completion of Phase II of security sys improvement program
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/03 CAVANAUGH, W Arkansas Power & Light Co 2pp
17059 319 24X Fiche 50-313, 83/02/03, 8302080180

B302160169 Forwards calculation illustrating possible constraints affecting cold shutdown w/loss of offsite power condition Facility unable to achieve cold shutdown per 10CFR50 App R
MARSHALL, J R Arkansas Power & Light Co 83/02/11 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 4pp 17162 072 24X Fiche 50-313, 83/02/11, 8302160169

--B302160171 "Reactor Vessel Head Cooldown During Natural Circulation Cooldown Transients"
BOHMAN, B L, TALLY, C W Babcock & Wilcox Co 86-1140819-00
83/02/08 18pp 17162 076 24X Fiche 50-313, 83/02/11, 8302160169

B302230588 Ack receipt of 830104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/14 CAVANAUGH, W Arkansas Power & Light Co 1p
17256 115 24X Fiche 50-313, 83/02/14, 8302230588

--B302230602 Responds to NRC 821105 ltr re violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18 Corrective actions health physics training sequences revised to specify retraining requirements & frequencies
MARSHALL, J R Arkansas Power & Light Co 83/01/04 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 3pp, 17256 116 24X Fiche 50-313, 83/02/14, 8302230588

B302170507 Releases public version of licensee B30114 ltr clarifying Amend & to emergency plan
FELTON, J M Division of Rules and Records 83/02/15 Document
Management Branch 1p 17197 095 24X Fiche 50-313, 83/02/15, 8302170507

--B302170517 Submits public version of info clarifying Amend & to emergency plan, in response to 821223 request Figure 10 will be amended by 830630 to identify responsible positions/titles for notification/communication function
MARSHALL, J R Arkansas Power & Light Co 83/01/14, SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p 17197 096 24X Fiche 50-313, 83/02/15, 8302170507

B302180223 Requests that 830216 appeal meeting be rescheduled, since NRC handling of partial suppression sys as generic issue does not relieve utility of having to address issue on individual basis Fire protection remains highest priority
MARSHALL, J R Arkansas Power & Light Co 83/02/15 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17215 301 24X Fiche 50-313, 83/02/15, 8302180223

H General correspondence

B302230499 Notifies that J Griffin designated senior nuclear mgt representative
CAVANAUGH, W, Arkansas Power & Light Co 83/02/16, CLARK, R A
Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 2pp 17246 198 24X Fiche 50-313, 83/02/16, 8302230499

P Operating license stage documents & correspondence

B302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--B3023240107 Advises that licensee provided in 820227 ltr sufficient justification for interim operation pending resolution of equipment qualification program
VISSINO, O B Operating Reactors Branch 4 82/03/15 NOVAK, T M
Assistant Director for Operating Reactors 3pp 17197 020 24X
Fiche 50-000, 83/01/18, 8302170019

--B302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 HIRAGLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--B302170212 Concludes that licensee 820315 ltr justifies continued operation until completion of environ qualification program.
VISSINO, O B Operating Reactors Branch 4 82/10/28
EISENHUT, D O Division of Licensing 1p 17197 019 24X
Fiche 50-000, 83/01/18, 8302170019

B302010046 Requests Tech Spec changes re key lock switches & leak testing to resolve purge valve issue info due within 45 days
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating
Reactors Branch 3 83/01/24 CAVANAUGH, W Arkansas Power & Light
Co 3pp 16990 305 24X Fiche 50-313, 83/01/24, 8302010046

B302010050 Forwards request for addl info re spent fuel pool expansion. Response requested within 10 days
STOLZ, J F Operating Reactors Branch 4, CLARK, R A Operating
Reactors Branch 3 83/01/24 CAVANAUGH, W Arkansas Power & Light
Co 3pp 16990, 302 24X Fiche 50-313, 83/01/24, 8302010050

B302070456 Forwards nine oversize P&IDs Drawing transmittal list encl Aperture cards are available in PDR
SHIVELY, C, Arkansas Power & Light Co 83/01/24 NRC - No
Detailed Affiliation Given 2pp 17061 103 24X
Fiche 50-313, 83/01/24, 8302070456

B302040077 Forwards SER & proprietary & nonproprietary versions of Vols 1 & 2, "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), AK Nuclear One, Unit 1," technical evaluation reft
YOHAN, O J Franklin Institute/Franklin Research Center, NRC-03-79-118 TER-C5257-310 82/12/28 BHEMANSKI, P NRC - No
Detailed Affiliation Given 1, 178pp 17047 015 24X
Fiche 50-313, 83/01/26, 8302040077

--B302040084 Safety evaluation re environ qualification of safety-related electrical equipment Continued operation until completion of environ qualification program determined not to present undue risk
* Office of Nuclear Reactor Regulation, Director 83/01/26, 6pp, 17047 009 24X Fiche 50-313, 83/01/26, 8302040077

--B301040296 Vols 1 & 2, "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), AK Nuclear One, Unit 1," technical evaluation reft
YOHAN, O J Franklin Institute/Franklin Research Center, NRC-03-79-118 TER-C5257-310 82/12/28 BHEMANSKI, P NRC - No
Detailed Affiliation Given 1, 178pp 17047 015 24X
Fiche 50-313, 83/01/26, 8302040077

B302080434 Forwards SER for environ qualification of safety-related electrical equipment Plans for qualification or replacement of equipment in Categories I, II A & II B & justification for continued operation requested within 90 days.
STOLZ, J F, Operating Reactors Branch 4 83/01/26, CAVANAUGH, W, Arkansas Power & Light Co 3pp 17071 121 24X
Fiche 50-313, 83/01/26, 8302080434

--B302080438 Safety evaluation of environ qualification of safety-related electrical equipment Continued operation will not present undue risk to public health & safety.
* Office of Nuclear Reactor Regulation, Director 83/01/26 6pp 17071 126 24X Fiche 50-313, 83/01/26, 8302080434

B302030405 Forwards corrected Page 9-2 of "Cycle & Reload Rept" submitted by 821119 ltr
MARSHALL, J R Arkansas Power & Light Co 83/01/27 STOLZ, J F, Operating Reactors Branch 4 1p 17005 215 24X
Fiche 50-313, 83/01/27, 8302030405

DOCKETED ITEMS

--B302030409 Corrected Page 9-2 of 821119 "Cycle & Reload Rept"
 * Arkansas Power & Light Co 83/01/27 1p 17005 216 24X
 Fiche 50-313,83/01/27,8302030405

B302070497 Advises that submittal of proposed Tech Spec changes re reporting of safety & relief valve challenges rescheduled to 830228, per NRC B20920 request (Generic Ltr 82-16).
 MARSHALL, J R Arkansas Power & Light Co 83/01/31 STDLZ, J F
 Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 17035 043 24X Fiche 50-313,83/01/31,8302070497.

B302070575 Responds to NRC B30105 ltr requesting schedule for providing addl info re proposed spent fuel storage expansion info will be provided by 830215
 MARSHALL, J R Arkansas Power & Light Co 83/01/31 STDLZ, J F
 Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3, 1p, 17034 292 24X Fiche 50-313,83/01/31,8302070575

B302070609 Informs of change in specific pump trip criteria per IE Bulletin 79-05C Use of pump trip criteria will be implemented w/implementation of emergency operating procedures as part of THF Item I C 1.
 MARSHALL, J R Arkansas Power & Light Co, 83/01/31 STDLZ, J F
 Operating Reactors Branch 4 2pp 17034:272, 24X
 Fiche 50-313, 83/01/31, 8302070609

B302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to B&W plants, for use as starting point for addl detailed technical discussions between NRC & B&W Owners Group representatives
 LATINAS, G C Assistant Director for Operating Reactors 83/01/31
 WALLACE, E. Babcock & Wilcox Operating Plants Owners Group App 17134 100, 24X Fiche 50-000, 83/01/31, 8302100257.

B302090252 Forwards interpretation of facility conformance to ODC 13, 54 & 57 & present schedule for resolving Unresolved Safety Issue A-47, Subtask 1, "Steam Generator & Reactor Vessel Overfill Transients"
 DIRCKS, W J Office of the Executive Director for Operations, 83/02/01
 AHEARNE, J F Commissioners 12pp 17117:344 24X
 Fiche 50-313, 83/02/01, 8302090252

--B302090261 Questions response to Ofc for Analysis & Evaluation of Operational Data re:gt on B10408 overfill event
 AHEARNE, J F, Commissioners 82/12/02 DIRCKS, W J Office of the Executive Director for Operations 1p 17117.356 24X
 Fiche 50-313, 83/02/01, 8302090262

B302100006 Forwards request for addl info re spent fuel pool expansion schedule for submittal of info due in 10 days
 STDLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3, 83/02/01
 CAVANAUGH, W Arkansas Power & Light Co 4pp, 17135 177 24X Fiche 50-313, 83/02/01, 8302100006

B302160522 Forwards request for addl info re completion of post-implementation review of NUREG-0737, Items II.F.1.4, II.F.1.5 & II.F.1.6 re containment monitors. Response requested within 60 days
 CLARK, R A Operating Reactors Branch 3 STDLZ, J F Operating Reactors Branch 4 83/02/02
 CAVANAUGH, W Arkansas Power & Light Co 10pp 17176 295 24X Fiche 50-313, 83/02/02, 8302160522

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08, Consolidated
 Edison Co. of New York, Inc. 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, 8302080295

B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co. of New York, Inc 9pp 17234 234, 24X
 Fiche 50-000, 83/02/08, 8302080304

B302090098 Generic Ltr 83-10F to all licensees w/B&W designed NSSS (except THF) re resolution of THF Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps." Svc list encl.
 EISENHUT, D O. Division of Licensing, 83/02/08 Duke Power Co 23pp 17298, 291, 24X Fiche 50-000, 83/02/08, 8302090098.

B302160168 Advises that addl info re proposed spent fuel storage expansion will be provided by 830225, in response to NRC 830125 ltr
 MARSHALL, J R Arkansas Power & Light Co, 83/02/08 STDLZ, J F
 Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3, 1p 17162 068, 24X Fiche 50-313, 83/02/08, 8302160168

8302160149 Advises that addl info re proposed spent fuel storage expansion will be provided by 830225, in response to NRC 830201 ltr
 MARSHALL, J R Arkansas Power & Light Co 83/02/10 STDLZ, J F
 Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3, 1p 17162 217 24X Fiche 50-313, 83/02/10, 8302160149

8302180430 Forwards corrected Page 8-11, Figure 8-10 of 821119 Cycle 6 reload rept
 MARSHALL, J R Arkansas Power & Light Co 83/02/11 STDLZ, J F
 Operating Reactors Branch 4 1p 17215 180 24X
 Fiche 50-313, 83/02/11, 8302180430

--B302180436 Corrected Page 8-11, Figure 8-10 to B21119 Cycle 6 reload rept
 * Babcock & Wilcox Co 83/02/11 1p 17215 181 24X
 Fiche 50-313, 83/02/11, 8302180430

8302180469 Application for amend to Licenses DPR-51 & NPF-6, deleting nonradiological water quality surveillance requirements from ETS
 GRIFFIN, J M. Arkansas Power & Light Co 83/02/15 STDLZ, J F
 Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 3pp 17214 084 24X Fiche 50-313, 83/02/15, 8302180469

--B302180472 Revised ETS, deleting nonradiological water quality surveillance requirements
 * Arkansas Power & Light Co 83/02/15 34pp 17214 087 24X
 Fiche 50-313, 83/02/15, 8302180469

8302220236 Informs of delay in submittal of supplemental ECCS calculations for NUREG-0630 fuel cladding swelling & rupture models, originally scheduled for submittal on 830215
 Calculations will be submitted by 830315
 MARSHALL, J R Arkansas Power & Light Co 83/02/15 STDLZ, J F
 Operating Reactors Branch 4 1p 17230 136 24X
 Fiche 50-313, 83/02/15, 8302220236

8302220275 Application to amend License DPR-51, updating 790222 request to change Tech Specs re acoustic emission exam of reactor coolant pump flywheel
 GRIFFIN, J M Arkansas Power & Light Co 83/02/15 STDLZ, J F
 Operating Reactors Branch 4 4pp 17230 139 24X
 Fiche 50-313, 83/02/15, 8302220275

--B302220280 Revised Tech Spec change re acoustic emission exam methodology to test reactor coolant pump flywheels
 * Arkansas Power & Light Co 83/02/15 1p 17230 143 24X
 Fiche 50-313, 83/02/15, 8302220275

8302220354 Responds to B21208 request for addl info re NUREG-0737, Item II K 3 17, "ECCS Outages re Core Damage" No outages occurred within past 5 yrs
 MARSHALL, J R Arkansas Power & Light Co 83/02/15 STDLZ, J F
 Operating Reactors Branch 4 1p 17232 004 24X
 Fiche 50-313, 83/02/15, 8302220354

8302240404 Forwards request for addl info within 10 days re proposed spent fuel pool expansion discussed in 821105 ltr
 STDLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/02/15
 CAVANAUGH, W Arkansas Power & Light Co, 4pp 17288 330 24X Fiche 50-313, 83/02/15, 8302240404

8302230403 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs Sections 3, 4, 5 & 6 re spent fuel pool expansion Class IV fee encl
 CAVANAUGH, W Arkansas Power & Light Co 83/02/17 STDLZ, J F
 Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17246, 346 24X Fiche 50-313, 83/02/17, 8302230403

--B302230408 Proposed changes to Tech Specs Sections 3, 4, 5 & 6 re spent fuel pool expansion
 * Arkansas Power & Light Co 83/02/17 17pp, 17246 348 24X
 Fiche 50-313, 83/02/17, 8302230403

8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level
 VAN VLIET, J Operating Reactors Branch 4 83/02/17 STDLZ, J.
 Operating Reactors Branch 4 3pp 17303 098 24X
 Fiche 50-000, 83/02/17, 8302250102

G Inspection reports, IE Bulletins & correspondence

8302010251 Forwards IE Insp Repts 50-313/82-29 & 50-368/82-27 on 820907-17 No noncompliance noted
 COLLINS, J T Region 4, Office of Director 82/12/02
 CAVANAUGH, W Arkansas Power & Light Co 2pp 16973 143 24X
 Fiche 50-313, 82/12/02, 8302010251

DOCKETED ITEMS

163

--8302010258 IE Insp Repts 50-313/82-29 & 50-368/82-27 on 820907-17 No noncompliance noted Major areas inspected review of licensee actions & commitments in response to IE bulletins. insp repts, NUREG-0737 items & NRC generic ltrs
JOHNSON, E H Region 4, Office of Director JAUDON, J P Division of Resident, Reactor Project & Engineering Programs TRAMMELL, C M Office of Nuclear Reactor Regulation, Director 82/11/24 14pp
16973 145 24X Fiche 50-313, 82/12/02, 8302010251

8302070425 Forwards IE Insp Repts 50-313/82-35 & 50-368/82-35 on 821206-10 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/03 CAVANAUGH, W Arkansas Power & Light Co 2pp
17029 272 24X Fiche 50-313, 83/01/03, 8302070425

--8302070431 IE Insp Repts 50-313/82-35 & 50-368/82-35 on 821206-10 No noncompliance noted Major areas inspected audit implementation program, surveillance testing, calibr control program & calibr
MURPHY, M E, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 83/01/09 4pp 17029 274 24X
Fiche 50-313, 83/01/03, 8302070425

8302030315 Provides list of interim actions re approach to review & control of ltrs & commitments to NRC & development of regulatory response & commitment control program
MARSHALL, J R Arkansas Power & Light Co 83/01/14 COLLINS, J T Region 4, Office of Director 5pp 17001 271, 24X
Fiche 50-313, 83/01/14, 8302030315

8302070374 Forwards IE Insp Repts 50-313/82-33 & 50-368/82-33 on 821115-19 & notice of violation
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/18 CAVANAUGH, W Arkansas Power & Light Co 2pp
17030 042 24X Fiche 50-313, 83/01/18, 8302070374

--8302070382 Notice of violation from insp on 821115-19
* Division of Resident, Reactor Project & Engineering Programs, 83/01/18 1p 17030 044 24X Fiche 50-313, 83/01/18, 8302070374

--8302070391 IE Insp Repts 50-313/82-33 & 50-368/82-33 on 821115-19 Noncompliance noted failure of plant safety committee to investigate licensee identified Tech Spec violation & failure to maintain penetration fire barriers functional
MURPHY, M E, STEWART, R C, MCCORRY, B L Division of Resident, Reactor Project & Engineering Programs 83/01/06 10pp, 17030 045 24X Fiche 50-313, 83/01/18, 8302070374

8302070471 Forwards IE Insp Repts 50-313/82-34 & 50-368/82-34 on 821201-31 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/24 CAVANAUGH, W Arkansas Power & Light Co 2pp, 17036 018 24X Fiche 50-313, 83/01/24, 8302070471

--8302070479 IE Insp Repts 50-313/82-34 & 50-368/82-34 on 821201-31 No noncompliance noted Major areas inspected surveillance, long-term shutdown & preparation for refueling, operational safety verification & LER followup
CALLAN, L J, CUMMINS, J E, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 83/01/19 9pp 17036 020 24X Fiche 50-313, 83/01/24, 8302070471

8302070551 Forwards IE Insp Rept 50-313/82-39 on 821227-29 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/24 CAVANAUGH, W Arkansas Power & Light Co 2pp 17034 113 24X Fiche 50-313, 83/01/24, 8302070551

--8302070556 IE Insp Rept 50-313/82-39 on 821227-29 No noncompliance noted Major areas inspected NDE of steam generator tubing
TOMLINSON, D P, JOHNSON, W D, HUNNICUTT, D M Division of Resident, Reactor Project & Engineering Programs 83/01/19 4pp, 17034, 115 24X Fiche 50-313, 83/01/24, 8302070551

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023, 160 24X Fiche, 50-000, 83/01/26, 8212060358

8302010481 Ack receipt of 820929 & 1124 ltrs informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-313/82-14 & 50-368/82-11
SEIDLE, W C, Division of Resident, Reactor Project & Engineering Programs 83/01/27, CAVANAUGH, W Arkansas Power & Light Co. 1p 16982 063 24X Fiche 50-313, 83/01/27, 8302010481

--8302010489 Responds to NRC 821025 ltr re violations noted in IE Insp Repts 50-313/82-14 & 50-368/82-11 Corrective actions
Procedure 1609, 003, "Radioactive Mail Shipments," revised to ensure certification attached to shipping papers
MARSHALL, J R Arkansas Power & Light Co 82/11/24 SEIDLE, W C, Division of Resident, Reactor Project & Engineering Programs, 3pp 16982 064, 24X Fiche 50-313, 83/01/27, 8302010481,

--8302010477 Responds to NRC 821025 ltr re deviations noted in IE Insp Repts 50-313/82-14 & 50-368/82-11 Corrective actions mods during current refueling outage to be completed as scheduled & review of LOCA procedures completed
MARSHALL, J R Arkansas Power & Light Co 83/01/07 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp, 16982 069 24X Fiche 50-313, 83/01/27, 8302010481

--8302010501 Informs of investigation initiated to determine validity of deviation noted in IE Insp Repts 50-313/82-14 & 50-368/82-11 re NUREG-0576, Item 2.1 & b, "Design of Plant Shielding"
MARSHALL, J R Arkansas Power & Light Co 82/09/29 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 7pp 16982 071 24X Fiche 50-313, 83/01/27, 8302010481

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302070438 Submits results of strontium analysis of isidur radioactive effluent sample omitted from IE Insp Repts 50-313/82-12 & 50-368/82-25 Analysis performed by NRC Radiological & Environ Sciences Lab, necessitating omission.
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/31 CAVANAUGH, W Arkansas Power & Light Co 3pp 17031 013 24X Fiche 50-313, 83/01/31, 8302070438

8302070409 Informs of change in specific pump trip criteria per IE Bulletin 79-03C Use of pump trip criteria will be implemented w/implementation of emergency operating procedures as part of TMI Item I C 1
MARSHALL, J R Arkansas Power & Light Co 83/01/31 STOLZ, J F Operating Reactors Branch 4 2pp 17034 272 24X
Fiche 50-313, 83/01/31, 8302070409

8302070462 Ack receipt of 821101 ltr informing NRC of steps taken to resolve open items noted in IE Emergency Planning Insp Repts 50-313/82-11 & 50-368/82-09
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/01 CAVANAUGH, W Arkansas Power & Light Co. 2pp, 17036 281 24X Fiche 50-313, 83/02/01, 8302070462

--8302070468 Responds to NRC 820928 ltr re open items noted in IE Emergency Planning Insp Repts 50-313/82-11 & 50-368/82-09 Schedule for resolving open items encl.
MARSHALL, J R Arkansas Power & Light Co 82/11/01 COLLINS, J T Region 4, Office of Director 6pp 17036 283 24X
Fiche 50-313, 83/02/01, 8302070462

8302070541 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-32 & 50-368/82-31
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs, 83/02/03 CAVANAUGH, W Arkansas Power & Light Co. 1p, 17034 156 24X Fiche 50-313, 83/02/03, 8302070541

--8302070552 Responds to NRC 821223 ltr re violations noted in IE Insp Repts 50-313/82-32 & 50-368/82-31 Corrective actions combustibles removed, colored fire retardant located for use in identification & weekly insp conducted
MARSHALL, J R Arkansas Power & Light Co 83/01/20 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 17034 157 24X Fiche 50-313, 83/02/03, 8302070541

8302150116 Submits updated info re status of ongoing steam generator tube inservice insps Once-through steam generator tube sheet maps, defective tube summary & summary of operational history of previous cycle encl
MARSHALL, J R Arkansas Power & Light Co 83/02/07 STOLZ, J. F. Operating Reactors Branch 4 29pp 17147 050 24X
Fiche 50-313, 83/02/07, 8302150116

8302150238 Advises that 100% insp of core fuel assembly holddown springs performed on 821231, per 810213 commitment No failures occurred during Cycle 5 operation.
MARSHALL, J R Arkansas Power & Light Co 83/02/08 STOLZ, J F Operating Reactors Branch 4 2pp 17149 278 24X
Fiche 50-313, 83/02/08, 8302150238

8302230588 Ack receipt of 830104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/14 CAVANAUGH, W Arkansas Power & Light Co. 1p 17256 115 24X Fiche, 50-313, 83/02/14, 8302230588

DOCKETED ITEMS

8302230602 Responds to NRC 821105 ltr re violations noted in IE Insp Repts 50-313/82-21 & 50-348/82-18 Corrective actions health physics training sequences revised to specify retraining requirements & frequencies
MARSHALL, J R Arkansas Power & Light Co 83/01/04 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 3pp
17256 116 24X Fiche 50-313, 83/02/14, 8302230588

830220275 Application to amend License DPR-51, updating 790222 request to change Tech Specs re acoustic emission exam of reactor coolant pump flywheel
BRIFFIN, J M Arkansas Power & Light Co 83/02/15 STOLZ, J F
Operating Reactors Branch 4. 4pp 17230 139 24X
Fiche 50-313, 83/02/15, 830220275

8302220280 Revised Tech Spec change re acoustic emission exam methodology to test reactor coolant pump flywheels
* Arkansas Power & Light Co 83/02/15 1p 17230 143. 24X
Fiche 50-313, 83/02/15, 8302220275

830230538 Informs of new program to enable more timely notification of Insp results by Vendor Program Branch Repts will be forwarded through NRC resident inspector, w/encl distribution ticket Vendor rept info should be used in util assessments.
COLLINS, J T. Region 4, Office of Director 83/02/16. CAVANAUGH, W
Arkansas Power & Light Co 3pp 17256 310 24X
Fiche 50-313, 83/02/16, 8302230538

830206363 IE Info Notice 83-04, "Failure of Elma Power Supply Units," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

830206365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 115pp. 17347 058. 24X Fiche 50-000, 83/02/24, 8212060365.

830206366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp. 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

Periodic operating reports & related correspondence

8302030406 Forwards "Screen Monitoring Rept, Dec 1982"
MARSHALL, J R Arkansas Power & Light Co 83/01/26 STOLZ, J F
Operating Reactors Branch 4 1p 17005 149 24X
Fiche 50-313, 83/01/26, 8302030406

8302030411 "Screen Monitoring Rept, Dec 1982."
* Arkansas Power & Light Co. 83/01/20. 17pp. 17005 150. 24X
Fiche 50-313, 83/01/26, 8302030406

Reportable occurrences, LERs & related correspondence

8302070361 Forwards LER 83-001/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/01/26 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
17030:010 24X Fiche 50-313, 83/01/26, 8302070361.

8302070363 LER 83-001/03L-0 on 830110, pressurizer code relief valve setpoint averaged above Tech Spec limit during setpoint testing Cause unknown. Spring compression adjusted on test stand. Valve retested & acceptable results obtained
ROGERS, P. Arkansas Power & Light Co 83/01/26. Region 4,
Office of Director 1p 17030:011 24X Fiche: 50-313, 83/01/26, 8302070361.

8302170064 Forwards LER 83-002/03L-0.
MARSHALL, J R. Arkansas Power & Light Co 83/02/03 SEIDLE, W C
Region 4, Office of Director 1p 17183 025 24X
Fiche: 50-313, 83/02/03, 8302170064

8302170068 LER 83-002/03L-0 on 830107, leak discovered in threaded vent pipe on casing vent line for spent fuel pool circulation
P-40A On 830120, similar leak discovered on P-40B. Caused by fatigue failure due to stress & vibration Pipe replaced.
ROGERS, P. Arkansas Power & Light Co 83/02/04 Region 4,
Office of Director. 1p. 17183:026 24X Fiche: 50-313, 83/02/03, 8302170064

8302280447 Forwards LER 83-003/03L-0.
MARSHALL, J R Arkansas Power & Light Co. 83/02/15 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs. 1p
17309:249. 24X Fiche: 50-313, 83/02/15, 8302280447.

8302280455 LER 83-003/03L-0 on 830124, reactor bldg pressure transmitter PT-2405 found out of specified tolerance On 830126, pressure transmitter PT-2406 also found out of tolerance Cause not determined Instruments readjusted
ROGERS, P. Arkansas Power & Light Co 83/02/15 Region 4,
Office of Director 2pp 17309 210 24X Fiche 50-313, 83/02/15, 8302280447

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NRS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8302010663 Resubmits 821221 ltr forwarding Security Training & Qualification Plan Plan withheld (ref 10CFR73 21)
ALEXICH, M P American Electric Power Service Corp 82/12/21
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
16980 060 24X Fiche 50-315, 82/12/21, 8302010663

8302080278 Retransmits 821221 ltr re security training & qualification plan Encl withheld (ref 10CFR73 21)
ALEXICH, M P American Electric Power Service Corp 82/12/21
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17056 335 24X Fiche 50-315, 82/12/21, 8302080278

8302080029 Forwards public version of Procedure Temporary Sheet 2 to Rev 3 to Emergency Plan Implementing Procedure PMP 2080 EPP 006, "Initial Dose Assessments (Gaseous)"
* Indiana & Michigan Electric Co 83/01/12 GRIMES, B NRC - No Detailed Affiliation Given 1p 17106 154 24X
Fiche 50-315, 83/01/12, 8302080029

8302080042 Public version of Procedure Temporary Sheet 2 to Rev 3 to Emergency Plan Implementing Procedure PMP 2080 EPP 006, "Initial Dose Assessments (Gaseous)" Revised index encl
MURPHY, C E, TOWNLEY, E L Indiana & Michigan Electric Co 83/01/12 4pp 17106 155 24X Fiche 50-315, 83/01/12, 8302080029

8302090049 Releases public version of procedure temporary sheet to rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 17131 348 24X Fiche 50-315, 83/01/31, 8302090049

8302090055 Forwards public version of Procedure Temporary Sheet 1 to Rev 2 to Emergency Plan Implementing Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility"
* Indiana & Michigan Electric Co 83/01/20 GRIMES, B NRC - No Detailed Affiliation Given 1p 17131 349 24X
Fiche 50-315, 83/01/31, 8302090049

8302090062 Public version of procedure temporary sheet 1 to Rev 2 to Emergency Plan Implementing Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility"
* Indiana & Michigan Electric Co 83/01/20 3pp 17131 350 24X Fiche 50-315, 83/01/31, 8302090049

8302090105 Releases public version of procedure temporary sheets for emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 17119 302 24X Fiche 50-315, 83/01/31, 8302090105

8302090115 Forwards public version of procedure temporary sheets for emergency plan implementing procedures, including Procedures PMP 2081 EPP 008 re emergency medical plan guidelines & PMP 2080 EPP 014 re personnel injury
* Indiana & Michigan Electric Co. 83/01/12 NRC - No Detailed Affiliation Given 1p. 17119 303 24X Fiche 50-315, 83/01/31, 8302090105.

8302090125 Public version of procedure temporary sheets for emergency plan implementing procedures, including Procedures PMP 2081 EPP 008 re emergency medical plan guidelines & PMP 2080 EPP 014 re personnel injury
FRYER, J Indiana & Michigan Electric Co 83/01/12. 16pp
17119:304 24X Fiche 50-315, 83/01/31, 8302090105

DOCKETED ITEMS

155

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 1pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070625 Releases public version of revised emergency plan procedure
FELTON, J M Division of Rules and Records 83/02/01 Document
Management Branch 1p 17061 188 24X Fiche 50-315, 83/02/01,
8302070625

--8302070627 Forwards public version of Rev 6 to App A of emergency plan procedure, "Telephone Numbers for Key Plant Personnel" Receipt form encl
* Indiana & Michigan Electric Co 83/01/24 NRC - No Detailed
Affiliation Given 2pp 17061 189 24X Fiche 50-315, 83/02/01,
8302070625

--8302070628 Public version of Rev 6 to App A of emergency plan procedure, "Telephone Numbers of Key Plant Personnel"
* Indiana & Michigan Electric Co 83/01/24 14pp 17061 191
24X Fiche 50-315, 83/02/01, 8302070625

8302170412 Forwards Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amend allows roving fire patrol in areas when automatic carbon dioxide fire suppression sys isolated
WIGGINTON, D L Operating Reactors Branch 1 83/02/07 DOLAN, J
Indiana & Michigan Electric Co 2pp 17205 170 24X
Fiche 50-315, 83/02/07, 8302170412

--8302170416 Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively, changing Tech Specs to allow for roving fire watch patrol in areas affected when automatic carbon dioxide fire suppression sys temporarily isolated
VAROA, S A Operating Reactors Branch 1 83/02/07 12pp
17205 172 24X Fiche 50-315, 83/02/07, 8302170412

--8302170423 Safety evaluation supporting Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/07 2pp
17205 184 24X Fiche 50-315, 83/02/07, 8302170412

--8302170428 Notice of issuance & availability of Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively
VAROA, S A Operating Reactors Branch 1 83/02/07 2pp
17205 186 24X Fiche 50-315, 83/02/07, 8302170412

8302180030 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document
Management Branch 1p 17223 336 24X Fiche 50-315, 83/02/14,
8302180030

--8302180038 Forwards public version of revised emergency plan implementing procedures, including Procedures
PMP 2081 EPP 014 re offsite dose assessments &
PMP 2081 EPP 010 re radiation monitoring teams
* Indiana & Michigan Electric Co 83/02/02 NRC - No Detailed
Affiliation Given 1p 17223 337 24X Fiche 50-315, 83/02/14,
8302180030

--8302180042 Public version of revised emergency plan implementing procedures, including Procedures PMP 2081 EPP 014 re offsite dose assessments & PMP 2081 EPP 010 re activation of radiation monitoring items Revised index encl
* Indiana & Michigan Electric Co 83/02/02 26pp 17223 338
24X Fiche 50-315, 83/02/14, 8302180030

8302202031 Forwards revised pages to modified amended security plan Pages withheld (ref 10CFR73.21)
HUNTER, R S Indiana & Michigan Electric Co. 83/02/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17230 137
24X Fiche 50-315, 83/02/14, 8302202031

830220373 Discusses results of Prof Loss Control, Inc audit of facility fire protection program Procedures to correct deficiency re failure to develop written pre-fire plans developed
HERING, R F Indiana & Michigan Electric Co 83/02/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17232 336
24X Fiche 50-315, 83/02/15, 830220373

8302250073 Releases public version of revised emergency plan procedure
FELTON, J M Division of Rules and Records 83/02/16 Document
Management Branch 1p 17302 343 24X Fiche 50-315, 83/02/16,
8302250073

--8302250082 Forwards public version of Rev 3 to Emergency Plan Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility"
BEGOR, R Indiana & Michigan Electric Co 83/01/28 GRINES, B
NRC - No Detailed Affiliation Given 1p 17302 344, 24X
Fiche 50-315, 83/02/16, 8302250073

--8302250092 Public version of Rev 3 to Emergency Plan Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility" Revised index encl
* Indiana & Michigan Electric Co 83/01/28 1pp 17302 345
24X Fiche 50-315, 83/02/16, 8302250073

J Insurance & indemnity information

8302040256 Requests pro rata portion of indemnity payment fees reflecting current fee reduction be refunded.
ALEXICH, M P American Electric Power Service Corp 83/02/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17020 043 24X Fiche 50-315, 83/02/01, 8302040256

P Operating license stage documents & correspondence

8302080468 Requests remittance of Class I & III fees for NRC review of 82029 application for Tech Spec changes required by NUREG-0737, Item II F 1.6, "Containment Hydrogen Monitors."
MILLER, W O License Fee Management Branch 83/02/03 DOLAN, J
Indiana & Michigan Electric Co 1p 17072 034 24X
Fiche 50-315, 83/02/03, 8302080468

8302100313 Forwards fees for Amends 60 & 43 to Licenses DPR-58 & DPR-74, issued 820907
ALEXICH, M P American Electric Power Service Corp. 83/02/07
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17112 087 24X Fiche 50-315, 83/02/07, 8302100313

8302170412 Forwards Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amend allows roving fire patrol in areas when automatic carbon dioxide fire suppression sys isolated
WIGGINTON, D L Operating Reactors Branch 1 83/02/07 DOLAN, J
Indiana & Michigan Electric Co 2pp 17205 170 24X
Fiche 50-315, 83/02/07, 8302170412

--8302170416 Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively, changing Tech Specs to allow for roving fire watch patrol in areas affected when automatic carbon dioxide fire suppression sys temporarily isolated
VAROA, S A Operating Reactors Branch 1 83/02/07 12pp
17205 172 24X Fiche 50-315, 83/02/07, 8302170412

--8302170423 Safety evaluation supporting Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/07 2pp
17205 184 24X Fiche 50-315, 83/02/07, 8302170412

--8302170428 Notice of issuance & availability of Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively
VAROA, S A Operating Reactors Branch 1 83/02/07 2pp
17205 186 24X Fiche 50-315, 83/02/07, 8302170412

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 1pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licenses qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090095 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSB (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps." Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262, 24X Fiche: 50-000, 83/02/08,
8302090095

8302160124 Requests response to 820920 Generic Ltr 82-16 re NUREG-0737 Tech Spec Complete response within 60 days requested w/copy sent to Region III
VAROA, S A Operating Reactors Branch 1 83/02/08, DOLAN, J
Indiana & Michigan Electric Co. 2pp 17174 029, 24X
Fiche 50-315, 83/02/08, 8302160124

DOCKETED ITEMS

8302170004 Requests remittance of addl fees for NRC review of 820407 application for changes to Tech Specs re increase in spent fuel pool to be used for Cycle 4 reload
MILLER, W O License Fee Management Branch 83/02/09 DOLAN, J
Indiana & Michigan Electric Co Ip 17191 022 24X
Fiche 50-315, 83/02/09, 8302170004

G Inspection reports, IE Bulletins & correspondence

8302250301 Forwards addl info re masonry wall evaluation performed per IE Bulletin 80-11 Partition Wall 12-4049-W4 deleted from safety-related wall category
HUNTER, R S Indiana & Michigan Electric Co 82/11/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 17291 259
24X Fiche 50-315, 82/11/19, 8302250301

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040332

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 116pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150010 Forwards IE Insp Repts 50-315/82-24 & 50-316/82-24 on 821220-22 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/01/27 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 17147 149
24X Fiche 50-315, 83/01/27, 8302150010

--8302150012 IE Insp Repts 50-315/82-24 & 50-316/82-24 on 821220-22 No noncompliance noted Major areas inspected selected aspects of NUREG-0737 Item II B 2 re shielding for access to vital areas & status of other post-TMI action items
HUETER, L J, OREGON, L R Division of Emergency Preparedness & Operational Support 83/01/27 6pp 17147 151 24X
Fiche 50-315, 83/01/27, 8302150012

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302160284 Ack receipt of 830128 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-07 & 50-316/82-07
SPESSARD, R L Division of Engineering 83/02/11 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co Ip 17166 303 24X Fiche 50-315, 83/02/11, 8302160284

--8302160312 Responds to NRC 820427 ltr re violation noted in IE Insp Repts 50-315/82-07 & 50-316/82-07 Corrective actions: verification program re calculations from outside vendors for seismic Class I piping sys completed
HUNTER, R S Indiana & Michigan Electric Co 83/01/28
KEPPLER, J O Region 3, Office of Director 2pp 17166 304 24X
Fiche 50-315, 83/02/11, 8302160312

--8302160338 Responds to NRC 820427 ltr re violations noted in IE Insp Repts 50-315/82-07 & 50-316/82-07 Corrective actions, util reviewed consultant procedures for analysis in effect at time work was in progress & conducted audit.
HERINO, R F Indiana & Michigan Electric Co 82/10/29
KEPPLER, J O Region 3, Office of Director 3pp 17166 306 24X
Fiche 50-315, 83/02/11, 8302160338

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302250306 Ack receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-15 & 50-316/82-15
NORELIUS, C E Division of Project & Resident Programs 83/02/18
DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co Ip 17291 271 24X
Fiche 50-315, 83/02/18, 8302250306

--8302250311 Responds to NRC 821210 ltr re violations noted in IE Insp Repts 50-315/82-15 & 50-316/82-15 Corrective actions: surveillance test procedures revised to reflect language of Tech Spec
HUNTER, R S Indiana & Michigan Electric Co 83/01/10
KEPPLER, J O Region 3, Office of Director 4pp 17291 272 24X
Fiche 50-315, 83/02/18, 8302250311

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd)
82/12/10 STELLO, V Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302010333 Forwards LER 83-002/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/01/24 KEPPLER, J O
Region 3, Office of Director 1p 16973 006 24X
Fiche 50-315, 83/01/24, 8302010333

--8302010340 LER 83-002/03L-0 on 821223, while performing ice condenser tour, intermediate deck door discovered frozen shut Caused by plugged drain in air handling unit resulting in ice buildup & overflow Air handling unit repaired
KRAUSE, D F Indiana & Michigan Electric Co 83/01/24 Region 3, Office of Director 1p 16973 007 24X Fiche 50-315, 83/01/24, 8302010333

8302040079 Forwards LER 82-108/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/01/24 KEPPLER, J O
Region 3, Office of Director 1p 17020 329 24X
Fiche 50-315, 83/01/26, 8302040079

--8302040086 LER 82-108/03L-0 on 821227, security officer on tour found carbon dioxide switch for 4-KV switchgear room in isolate position w/no personnel in room Caused by misunderstanding of responsibility for requesting security guard
SVENSSON, B A Indiana & Michigan Electric Co 83/01/26 Region 3, Office of Director 1p 17020 330 24X Fiche 50-315, 83/01/26, 8302040079

8302040096 Forwards LER 83-003/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/01/24 KEPPLER, J O
Region 3, Office of Director 1p 17021 288 24X
Fiche 50-315, 83/01/26, 8302040096

--8302040100 LER 83-003/03L-0 on 830103, fire door 385 would not latch upon closing due to bent door knob spindle Cause undetermined Knob spindle replaced & door closer adjusted
ROBINSON, D Indiana & Michigan Electric Co 83/01/26 Region 3, Office of Director 1p 17021 289 24X Fiche 50-315, 83/01/26, 8302040096

8302080311 Requests cancellation of LERs 83-001/03L-0 & 83-002/03L-0 for Unit 1 & LERs 83-001/03L-0 & 83-003/01T-0 for Unit 2.
SMITH, W O Indiana & Michigan Electric Co 83/01/31 KEPPLER, J O
Region 3, Office of Director 1p 17036 172 24X
Fiche 50-315, 83/01/31, 8302080311

DOCKETED ITEMS

157

8302080321 Forwards LER 82-109/03L-0 & 82-110/03L-0 LERs previously submitted using 1983 Numbers 83-002/03L-0 & 83-001/03L-0, respectively
SMITH, W O Indiana & Michigan Electric Co 83/01/31 KEPLER, J O
Region 3, Office of Director ip 17056 307 24X
Fiche 50-315, 83/01/31, 8302080321

--8302080324 LER 82-109/03L-0 on 821223, operator discovered one intermediate deck door frozen shut Caused by plugged drain causing ice to build up & overflow in air handling unit Air handling unit repaired
KRAUSE, D F Indiana & Michigan Electric Co 83/01/27 Region 3, Office of Director ip 17056 308 24X Fiche 50-315, 83/01/31, 8302080321

--8302080326 LER 82-110/03L-0 on 821230, operator discovered one intermediate deck door frozen shut Cause undetermined Ice removed
CARP, M J Indiana & Michigan Electric Co 83/01/27 Region 3, Office of Director ip 17056 309 24X Fiche 50-315, 83/01/31, 8302080321

8302080236 RO on 830201, outlet valve of spray additive tank discovered in closed position Valve immediately opened
SMITH, W O Indiana & Michigan Electric Co 83/02/01 KEPLER, J O
Region 3, Office of Director ip 17057 190 24X
Fiche 50-315, 83/02/01, 8302080236

8302080263 Forwards LER 83-004/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/02/02 KEPLER, J O
Region 3, Office of Director ip 17057 013 24X
Fiche 50-315, 83/02/02, 8302080263

---8302080266 LER 83-004/03L-0 on 830109, during surveillance test on containment air recirculation fan HV-CEQ-1, fan breaker tripped Cause unknown Motor inspected, but no deficiencies discovered
CARTEAUX, P Indiana & Michigan Electric Co 83/02/02 Region 3, Office of Director ip 17057 014 24X Fiche 50-315, 83/02/02, 8302080263

8302150005 Forwards LER 83-005/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/02/03 KEPLER, J O
Region 3, Office of Director ip 17148 057 24X
Fiche 50-315, 83/02/03, 8302150005

--8302150006 LER 83-005/03L-0 on 830111, CD diesel engine declared inoperable due to fuel oil leak on front bank fuel injector pump 3 Cause not stated Galling on high pressure fitting detected Fuel oil pump & fuel injection line replaced
ROBINSON, D Indiana & Michigan Electric Co 83/02/03 Region 3, Office of Director ip 17148 058 24X Fiche 50-315, 83/02/03, 8302150005

8302160335 Forwards LERs 83-006/03L-0, 83-007/03L-0 & 83-008/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/02/08 KEPLER, J O
Region 3, Office of Director ip 17166 277 24X
Fiche 50-315, 83/02/08, 8302160335

--8302160337 LER 83-006/03L-0 on 830119, containment gaseous radiation monitor channel ERS-1305 declared inoperable due to fail high condition Caused by failed detector Detector replaced. Channel calibr. verified & returned to svc
PALMER, R A Indiana & Michigan Electric Co 83/02/08 Region 3, Office of Director ip 17166 278 24X Fiche 50-315, 83/02/08, 8302160335

--8302160340 LER 83-007/03L-0 on 830120, AB diesel fire door 319 would not close automatically when opened during normal operation Caused by wired open supply fan louvers to AB diesel, changing normal ventilation flow path configuration
CARTEAUX, P Indiana & Michigan Electric Co 83/02/08 Region 3, Office of Director ip 17166 279 24X Fiche 50-315, 83/02/08, 8302160335

--8302160342 LER 83-008/03L-0 on 830120, fire door 385 found unlatched during normal operation Caused by insufficient closer mechanism force Door closer mechanism adjusted.
CARTEAUX, P Indiana & Michigan Electric Co 83/02/08 Region 3, Office of Director ip 17166 280 24X Fiche 50-315, 83/02/08, 8302160335

8302180309 PNO-III-83-014 on 830211, higher than anticipated gaseous effluent release occurred while collecting sample from gas space from Unit 1 Second unplanned release from Unit 2 occurred while collecting coolant sample
HUEIER, L J, OREGIER, L R Region 3, Office of Director 83/02/11
ip 17211 228 24X Fiche 50-315, 83/02/11, 8302180309

8302250181 Forwards LER 83-009/01T-0
SMITH, W O Indiana & Michigan Electric Co 83/02/15 KEPLER, J O
Region 3, Office of Director 2pp 17293 044 24X
Fiche 50-315, 83/02/15, 8302250181

--8302250184 LER 83-009/01T-0 on 830201, operator found spray additive tank outlet valve sealed in closed position Caused by operators being distracted during performance of test Review of startup test procedure schedule underway
KRAUSE, D F Indiana & Michigan Electric Co 83/02/15 Region 3, Office of Director 3pp 17293 046 24X Fiche 50-315, 83/02/15, 8302250181

8302280382 Forwards updated LER 82-058/03X-1
SMITH, W O Indiana & Michigan Electric Co 83/02/17 KEPLER, J O
Region 3, Office of Director ip 17309 328 24X
Fiche 50-315, 83/02/17, 8302280382

--8302280387 Updated LER 82-058/03X-1 on 820721, during B&C leak rate tests, several valves exhibited excessive leakage causing total leak rate to exceed Tech Spec limit Caused by dirt & scale deposits on seating surfaces & valve seat erosion
PALMER, R A Indiana & Michigan Electric Co 83/02/17 Region 3, Office of Director 2pp 17309 329 24X Fiche 50-315, 83/02/17, 8302280382

8302280394 Forwards LER 83-022/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/02/17 KEPLER, J O
Region 3, Office of Director ip 17308 009 24X
Fiche 50-315, 83/02/17, 8302280394

--8302280409 LER 83-022/03L-0 on 830118, during normal operation, auxiliary cable vault (Zone 11) experienced inadvertent carbon dioxide discharge Actuation spurious Carbon dioxide tank main isolation isolated for 10 minutes
KRAUSE, D F Indiana & Michigan Electric Co 83/02/17 Region 3, Office of Director ip 17308 010 24X Fiche 50-315, 83/02/17, 8302280394

8302280413 Forwards LER 83-010/04T-0 Detailed event analysis submitted
SMITH, W O Indiana & Michigan Electric Co 83/02/18 KEPLER, J O
Region 3, Office of Director ip 17309 161 24X
Fiche 50-315, 83/02/18, 8302280413

--8302280416 LER 83-010/04T-0 on 830211, during planned gas sampling evolution, expected gas release of unexpected magnitude detected by vent stack gaseous monitor Caused by sample line drain valve inadvertently left open Valve closed
PALMER, R A Indiana & Michigan Electric Co 83/02/18 Region 3, Office of Director 3pp 17309 162 24X Fiche 50-315, 83/02/18, 8302280413

8302280401 Forwards LER 83-001/03L-0 (previously submitted as Unit 2 LER 83-022/03L-0)
SMITH, W O Indiana & Michigan Electric Co 83/02/22 KEPLER, J O
Region 3, Office of Director ip 17307 320 24X
Fiche 50-315, 83/02/22, 8302280401

--8302280410 LER 83-001/03L-0 on 830118, Unit 2 auxiliary cable vault experienced inadvertent carbon dioxide discharge, resulting in isolation of Unit 1 & 2 carbon dioxide tanks Valve closed & main isolation reopened
KRAUSE, D F Indiana & Michigan Electric Co 83/02/22 Region 3, Office of Director ip 17307 321 24X Fiche 50-315, 83/02/22, 8302280401

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8302010663 Resubmits 821221 ltr forwarding Security Training & Qualification Plan, Plan withheld (ref 10CFR73 21)
ALEXICH, M P American Electric Power Service Corp 82/12/21.
DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p.
16980 060 24X Fiche 50-315, 82/12/21, 8302010663

8302080278 Retransmits 821221 ltr re security training & qualification plan Encl withheld (ref 10CFR73 21)
ALEXICH, M P American Electric Power Service Corp. 82/12/21.
DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp.
17056 335 24X Fiche 50-315, 82/12/21, 8302080278

DOCKETED ITEMS

- 8302080029 Forwards public version of Procedure Temporary Sheet 2 to Rev 3 to Emergency Plan Implementing Procedure PMP 2080 EPP 005, "Initial Dose Assessments (Gaseous)" * Indiana & Michigan Electric Co 83/01/12 GRIMES,B NRC - No Detailed Affiliation Given 1p 17106 154 24X Fiche 50-315, 83/01/12, 8302080029
- 8302080042 Public version of Procedure Temporary Sheet 2 to Rev 3 to Emergency Plan Implementing Procedure PMP 2080 EPP 006, "Initial Dose Assessments (Gaseous)" Revised index encl MURPHY, C E ; TOWNLEY, E L. Indiana & Michigan Electric Co 83/01/12 4pp 17106 155 24X Fiche 50-315, 83/01/12, 8302080029
- 8302090049 Releases public version of procedure temporary sheet to rev to emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 17131 348 24X Fiche 50-315, 83/01/31, 8302090049
- 8302090055 Forwards public version of Procedure Temporary Sheet 1 to Rev 2 to Emergency Plan Implementing Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility" * Indiana & Michigan Electric Co 83/01/20. GRIMES, B. NRC - No Detailed Affiliation Given 1p 17131 349 24X Fiche 50-315, 83/01/31, 8302090049
- 8302090062 Public version of procedure temporary sheet 1 to Rev 2 to Emergency Plan Implementing Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility" * Indiana & Michigan Electric Co 83/01/20 3pp 17131 350 24X Fiche 50-315, 83/01/31, 8302090049
- 8302090105 Releases public version of procedure temporary sheets for emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 17119 302 24X Fiche 50-315, 83/01/31, 8302090105
- 8302090115 Forwards public version of procedure temporary sheets for emergency plan implementing procedures, including Procedures PMP 2081 EPP 008 re emergency medical plan guidelines & PMP 2080 EPP 014 re personnel injury * Indiana & Michigan Electric Co 83/01/12 NRC - No Detailed Affiliation Given 1p 17119 303 24X Fiche 50-315, 83/01/31, 8302090105
- 8302090125 Public version of procedure temporary sheets for emergency plan implementing procedures, including Procedures PMP 2081 EPP 008 re emergency medical plan guidelines & PMP 2080 EPP 014 re personnel injury FRYER, J Indiana & Michigan Electric Co 83/01/12 16pp 17119 304. 24X Fiche 50-315, 83/01/31, 8302090105
- 8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221-226 24X Fiche 50-000, 83/02/01, 8301210340.
- 8302070625 Releases public version of revised emergency plan procedure FELTON, J M Division of Rules and Records 83/02/01 Document Management Branch 1p 17061 188 24X Fiche 50-315, 83/02/01, 8302070625
- 8302070627 Forwards public version of Rev 4 to App A of emergency plan procedure, "Telephone Numbers for Key Plant Personnel" Receipt form encl * Indiana & Michigan Electric Co 83/01/24 NRC - No Detailed Affiliation Given 2pp. 17061 189 24X Fiche 50-315, 83/02/01, 8302070625
- 8302070628 Public version of Rev 4 to App A of emergency plan procedure, "Telephone Numbers for Key Plant Personnel" * Indiana & Michigan Electric Co 83/01/24. 14pp. 17061 191 24X Fiche 50-315, 83/02/01, 8302070625
- 8302170412 Forwards Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amend allows roving fire patrol in areas when automatic carbon dioxide fire suppression sys isolated WIGGINTON, D L. Operating Reactors Branch 1. 83/02/07 DOLAN, J Indiana & Michigan Electric Co 2pp 17205 170. 24X Fiche 50-315, 83/02/07, 8302170412
- 8302170416 Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively, changing Tech Specs to allow for roving fire watch patrol in areas affected when automatic carbon dioxide fire suppression sys temporarily isolated. VAROA, B A Operating Reactors Branch 1 83/02/07 12pp. 17205 172 24X Fiche 50-315, 83/02/07, 8302170412
- 8302170423 Safety evaluation supporting Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively * Office of Nuclear Reactor Regulation, Director 83/02/07 2pp 17205 184 24X Fiche 50-315, 83/02/07, 8302170412
- 8302170428 Notice of issuance & availability of Amends 68 & 50 to Licenses DPR-58 & DPR-74, respectively VAROA, B A Operating Reactors Branch 1 83/02/07 2pp 17205 186. 24X Fiche 50-315, 83/02/07, 8302170412
- 8302180030 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/02/14 Document Management Branch 1p 17223 336 24X Fiche 50-315, 83/02/14, 8302180030
- 8302180038 Forwards public version of revised emergency plan implementing procedures, including Procedures PMP 2081 EPP 014 re offsite dose assessments & PMP 2081 EPP 010 re radiation monitoring teams * Indiana & Michigan Electric Co 83/02/02 NRC - No Detailed Affiliation Given 1p 17223 337 24X Fiche 50-315, 83/02/14, 8302180030
- 8302180042 Public version of revised emergency plan implementing procedures, including Procedures PMP 2081 EPP 014 re offsite dose assessments & PMP 2081 EPP 010 re activation of radiation monitoring items Revised index encl * Indiana & Michigan Electric Co 83/02/02 26pp 17223 338 24X Fiche 50-315, 83/02/14, 8302180030
- 8302220231 Forwards revised pages to modified amended security plan Pages withheld (ref 10CFR73.21) HUNTER, R B Indiana & Michigan Electric Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17230 137 24X Fiche 50-315, 83/02/14, 8302220231
- 8302220373 Discusses results of Prof Loss Control, Inc audit of facility fire protection program Procedures to correct deficiency re failure to develop written pre-fire plans developed HERING, R F Indiana & Michigan Electric Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17232 336 24X Fiche 50-315, 83/02/15, 8302220373
- 8302250073 Releases public version of revised emergency plan procedure FELTON, J M Division of Rules and Records 83/02/16 Document Management Branch 1p 17302 343 24X Fiche 50-315, 83/02/16, 8302250073
- 8302250082 Forwards public version of Rev 3 to Emergency Plan Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility" BEGGER, R Indiana & Michigan Electric Co 83/01/28 GRIMES, B NRC - No Detailed Affiliation Given 1p 17302 344 24X Fiche 50-315, 83/02/16, 8302250073
- 8302250092 Public version of Rev 3 to Emergency Plan Procedure PMP 2081 EPP 022, "Activation & Operation of Emergency Operations Facility" Revised index encl * Indiana & Michigan Electric Co 83/01/28 11pp 17302 345 24X Fiche 50-315, 83/02/16, 8302250073
- J Insurance & indemnity information
- 8302040256 Requests pro rata portion of indemnity payment fees reflecting current fee reduction be refunded ALEXICH, M P American Electric Power Service Corp 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17020 043 24X Fiche 50-315, 83/02/01, 8302040256
- F Operating license stage documents & correspondence
- 8302080468 Requests remittance of Class I & III fees for NRC review of 820929 application for Tech Spec changes required by NUREG-0737, Item II F 1.6, "Containment Hydrogen Monitors" MILLER, W O License Fee Management Branch 83/02/03 DOLAN, J Indiana & Michigan Electric Co 1p 17072 034 24X Fiche 50-315, 83/02/03, 8302080468
- 8302140044 Requests generic review of PTS-PWR2 plant transient simulator code be reactivated, due to difficulty encountered in DC Cook Unit 2 Cycle 4 review CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/02/03 THOMAS, C O Standardization & Special Projects Branch 2pp 17140 175 24X Fiche 50-316, 83/02/03, 8302140044

DOCKETED ITEMS

159

8302100313 Forwards fees for Amends 60 & 43 to Licenses DPR-5B & DPR-74, issued 820909
ALFXICH, M P American Electric Power Service Corp 83/02/07
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17112 087 24X Fiche 50-315, 83/02/07, 8302100313

8302170412 Forwards Amends 48 & 50 to Licenses DPR-5B & DPR-74, respectively, safety evaluation & notice of issuance & availability Amend allows moving fire patrol in areas when automatic carbon dioxide fire suppression sys isolated
WIGGINTON, D L Operating Reactors Branch 1 83/02/07 DOLAN, J
Indiana & Michigan Electric Co 2pp 17205 170 24X
Fiche 50-315, 83/02/07, 8302170412

--8302170416 Amends 48 & 50 to Licenses DPR-5B & DPR-74, respectively, changing Tech Specs to allow for moving fire watch patrol in areas affected when automatic carbon dioxide fire suppression sys temporarily isolated
VAROA, S A Operating Reactors Branch 1 83/02/07 12pp
17205 172 24X Fiche 50-315, 83/02/07, 8302170412

--8302170423 Safety evaluation supporting Amends 48 & 50 to Licenses DPR-5B & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/07 2pp
17205 184 24X Fiche 50-315, 83/02/07, 8302170412

--8302170428 Notice of issuance & availability of Amends 48 & 50 to Licenses DPR-5B & DPR-74, respectively
VAROA, S A Operating Reactors Branch 1 83/02/07 2pp
17205 186 24X Fiche 50-315, 83/02/07, 8302170412

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302160124 Requests response to 820920 Generic Ltr 82-16 re NUREG-0737 Tech Specs Complete response within 60 days requested w/copy sent to Region III
VAROA, S A Operating Reactors Branch 1 83/02/08 DOLAN, J
Indiana & Michigan Electric Co 2pp 17174 029 24X
Fiche 50-315, 83/02/08, 8302160124

8302250004 Forwards revised P 2 of Amend 48 to License DPR-74, issued 830114 Thirty-day requirement changed to 90 days
WIGGINTON, D L Operating Reactors Branch 1 83/02/08 DOLAN, J
Indiana & Michigan Electric Co 2pp 17302 311 24X
Fiche 50-315, 83/02/08, 8302250004

--8302250013 Revised P 2 of Amend 48 to License DPR-74, issued 830114, changing 30 day requirement to 90 days
VAROA, S A Operating Reactors Branch 1 83/01/14 1p
17302 313 24X Fiche 50-315, 83/02/08, 8302250004

8302170004 Requests remittance of addl fees for NRC review of 820407 application for changes to Tech Specs re increase in spent fuel pool to be used for Cycle 4 reload
MILLER, W O License Fee Management Branch 83/02/09 DOLAN, J
Indiana & Michigan Electric Co 1p 17191 022 24X
Fiche 50-315, 83/02/09, 8302170004

Q Inspection reports, IE Bulletins & correspondence

8302250306 Forwards addl info re masonry wall evaluation performed per IE Bulletin 80-11 Partition Wall 12-4049-W4 deleted from safety-related wall category
HUNTER, R S Indiana & Michigan Electric Co 82/11/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 17291 259
24X Fiche 50-315, 82/11/19, 8302250306

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30, NIATT, B L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150010 Forwards IE Insp Repts 50-315/82-24 & 50-316/82-24 on 821220-22 No noncompliance noted
PAPERILLO, C J Division of Emergency Preparedness & Operational
Support 83/01/27 DOLAN, J E American Electric Power Service
Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 17147 149
24X Fiche 50-315, 83/01/27, 8302150010

--8302150012 IE Insp Repts 50-315/82-24 & 50-316/82-24 on 821220-22 No noncompliance noted Major areas inspected, selected aspects of NUREG-0737 Item II B 2 2 re shielding for access to vital areas & status of other post-TMI action items
HUETER, L J, GREGER, L R Division of Emergency Preparedness & Operational Support 83/01/27 6pp 17147 151 24X
Fiche 50-315, 83/01/27, 8302150010

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth
Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302160284 Ack receipt of 830128 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-07 & 50-316/82-07
SPESSARD, R L Division of Engineering 83/02/11 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 1p 17166 303 24X Fiche 50-315, 83/02/11, 8302160284

--8302160312 Responds to NRC 820427 ltr re violation noted in IE Insp Repts 50-315/82-07 & 50-316/82-07 Corrective actions verification program re calculations from outside vendors for seismic Class I piping sys completed
HUNTER, R S Indiana & Michigan Electric Co 83/01/28
KEPPLER, J O Region 3, Office of Director, 2pp, 17166 304 24X
Fiche 50-315, 83/02/11, 8302160284

--8302160338 Responds to NRC 820427 ltr re violations noted in IE Insp Repts 50-315/82-07 & 50-316/82-07 Corrective actions until reviewed consultant procedures for analysis in effect at time work was in progress & conducted audit
HERING, R F Indiana & Michigan Electric Co 82/10/29
KEPPLER, J O Region 3, Office of Director 5pp 17166 306 24X
Fiche 50-315, 83/02/11, 8302160284

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302250306 Ack receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-15 & 50-316/82-15
NORELIUS, C E Division of Project & Resident Programs, 83/02/18
DOLAN, J E American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 1p 17291 271 24X
Fiche 50-315, 83/02/18, 8302250306

DOCKETED ITEMS

--8302250311 Responds to NRC 821210 ltr re violations noted in IE Insp Repts 50-315/82-15 & 50-316/82-15 Corrective actions surveillance test procedures revised to reflect language of Tech Spec
HUNTER, R B Indiana & Michigan Electric Co 83/01/10
KEPPLER, J G Region 3, Office of Director 4pp 17291 272 24X
Fiche 50-315, 83/02/18, 8302250306

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

6 Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd)
82/12/10 STELLD, V Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302040195 Forwards LER 82-118/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/01/28 KEPPLER, J G
Region 3, Office of Director 1p 17020 193 24X
Fiche 50-316, 83/01/28, 8302040195

--8302040202 LER 82-118/03L-0 on 821229, power containment airborne monitor ER8-2400 high alarm setpoint for channel 2401 left at higher than allowable value during functional testing. Caused by nonconservative condition, increasing reading
PALMER, R A Indiana & Michigan Electric Co 83/01/28 Region 3, Office of Director 2pp 17020 194 24X Fiche 50-316, 83/01/28, 8302040195

8302080289 Forwards LER 82-116/03L-0 & 82-117/01T-0 LERs previously submitted using 1983 Numbers 83-001/03L-0 & 83-003/01T-0, respectively
SMITH, W G Indiana & Michigan Electric Co 83/01/31 KEPPLER, J G
Region 3, Office of Director 1p 17056 052 24X
Fiche 50-316, 83/01/31, 8302080289

--8302080294 LER 82-116/03L-0 on 821214, min average ice weight of sample baskets from radial rows 7, 8 & 9 found less than 1,220 lb/ basket at 93% level of confidence Caused by natural sublimation ice mass added to deficient row groups
PALMER, R A Indiana & Michigan Electric Co 83/01/27 Region 3, Office of Director 2pp 17056 053 24X Fiche 50-316, 83/01/31, 8302080289

--8302080298 LER 82-117/01T-0 on 821222, five relay timers exceeded tolerance allowed by Tech Spec Caused by instrument drift. Timers individually retested, Two timers readjusted
PALMER, R A Indiana & Michigan Electric Co 83/01/27 Region 3, Office of Director 2pp 17056 055 24X Fiche 50-316, 83/01/31, 8302080289

8302080311 Requests cancellation of LERs 83-001/03L-0 & 83-002/03L-0 for Unit 1 & LERs 83-001/03L-0 & 83-003/01T-0 for Unit 2
SMITH, W G Indiana & Michigan Electric Co 83/01/31, KEPPLER, J G
Region 3, Office of Director 1p 17056 172 24X
Fiche 50-315, 83/01/31, 8302080311

8302080327 Forwards LERs 83-006/03L-0, 83-007/03L-0, 83-008/03L-0, 83-009/03L-0 & 83-010/03L-0.
SMITH, W G Indiana & Michigan Electric Co 83/02/02 KEPPLER, J G
Region 3, Office of Director 1p 17056 314 24X
Fiche 50-316, 83/02/02, 8302080327

--8302080329 LER 83-006/03L-0 on 830104, during normal operation of Unit 1 & refueling of Unit 2, fire door 388 in Quad 2 would not fully close Caused by ventilation flow door closure mechanism adjusted & door operated satisfactorily.
CARTEAUX, P Indiana & Michigan Electric Co 83/02/02 Region 3, Office of Director 1p 17056 315 24X Fiche 50-316, 83/02/02, 8302080327

--8302080331 LER 83-007/03L-0 on 830105, during surveillance test, low pressure alarm XPA-152 for emergency air supply found to be actuating at less than 900 psig Cause not stated Design change submitted to replace Mercoid pressure switch.
PALMER, R A Indiana & Michigan Electric Co 83/02/02 Region 3, Office of Director 1p 17056 316 24X Fiche 50-316, 83/02/02, 8302080327

--8302080335 LER 83-008/03L-0 on 830106, while in operational Mode S, temporary seal for fire barrier penetration W-9391 to CD diesel discovered loose Cause not determined Temporary seal installed
CARTEAUX, P Indiana & Michigan Electric Co 83/02/02 Region 3, Office of Director 1p 17056 317 24X Fiche 50-316, 83/02/02, 8302080327

--8302080337 LER 83-009/03L-0 on 830117, during unit startup, several main steam safety valves found leaking Cause not stated Gags removed & valves declared operable Job orders written to repair valves during next outage of sufficient duration
CARTEAUX, P Indiana & Michigan Electric Co 83/02/02 Region 3, Office of Director 1p 17056 318 24X Fiche 50-316, 83/02/02, 8302080327

--8302080341 LER 83-010/03L-0 on 830118, during Mode 3, auxiliary cable vault north ventilation damper failed to close upon carbon dioxide actuation Caused by loose pilot piping Associated pipe hangers & fittings tightened
CARTEAUX, P Indiana & Michigan Electric Co 83/02/02 Region 3, Office of Director 1p 17056 319 24X Fiche 50-316, 83/02/02, 8302080327

8302150415 Forwards updated LER 82-113/01X-1
SMITH, W G Indiana & Michigan Electric Co 83/02/03 KEPPLER, J G
Region 3, Office of Director 1p 17157 142 24X
Fiche 50-316, 83/02/03, 8302150415

--8302150439 Updated LER 82-113/01X-1 on 821229, during ECCS flow balance test, flow rate of 300 gpm could not be obtained through train B of safety injection sys Caused by inadequate insp resulting in failure to locate unattached valve disc
BEILMAN, T P Indiana & Michigan Electric Co 83/02/03 Region 3, Office of Director 4pp 17157 143 24X Fiche 50-316, 83/02/03, 8302150415

8302180276 Forwards LER 83-011/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/02/07 KEPPLER, J G
Region 3, Office of Director 1p 17212 051 24X
Fiche 50-316, 83/02/07, 8302180276

--8302180285 LER 83-011/03L-0 on 830108, pressurizer PORV NRV-152 drifted closed & 114V-153 drifted part way closed Caused by low pressure on outlet of emergency air regulators Regulators adjusted & evaluation of PORV emergency air initiated
PALMER, R A Indiana & Michigan Electric Co 83/02/07 Region 3, Office of Director 2pp 17212 052 24X Fiche 50-316, 83/02/07, 8302180276

8302160268 Forwards LERs 83-012/03L-0, 83-013/03L-0 & 83-014/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/02/08 KEPPLER, J G
Region 3, Office of Director 1p 17170 258 24X
Fiche 50-316, 83/02/08, 8302160268

--8302160272 LER 83-012/03L-0 on 830126, exhaust leak identified on expansion joint on AB diesel engine turbocharger exhaust Cause undetermined Expansion joint replaced, Similar joints inspected No defects identified
ROBINSON, D Indiana & Michigan Electric Co 83/02/08 Region 3, Office of Director 1p 17170 259 24X Fiche 50-316, 83/02/08, 8302160268

--8302160279 LER 83-013/03L-0 on 830122, steam dump sys placed in manual during preparation for main turbine overspeed test, causing RCS temp to drop approx 2 F & pressurizer pressure to drop to 2,180 psig for approx 1 minute Caused by personnel error
KRAUSE, D F Indiana & Michigan Electric Co 83/02/08 Region 3, Office of Director 1p 17170 260 24X Fiche 50-316, 83/02/08, 8302160268

--8302160285 LER 83-014/03L-0 on 830124, steam generator 3 stop valve dump valve MRV-232 removed from svc to repair seat leakage Caused by need to repair valve Valve stem, plug, cage seat ring & gaskets replaced & valve returned to svc
CARTEAUX, P Indiana & Michigan Electric Co 83/02/08 Region 3, Office of Director 1p 17170 261 24X Fiche 50-316, 83/02/08, 8302160268

8302180226 Forwards LER 83-015/03L-0 & 83-016/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/02/11, KEPPLER, J G
Region 3, Office of Director 1p 17212 098 24X
Fiche 50-316, 83/02/11, 8302180226

--8302180230 LER 83-015/03L-0 on 830113, contractor personnel within reactor cable tunnel area w/o required number of fire watches Area vacated until proper number of fire watches established Procedure requirements reviewed
CASTLE, L W Indiana & Michigan Electric Co 83/02/11 Region 3, Office of Director 1p 17212 099 24X Fiche 50-316, 83/02/11, 8302180226

DOCKETED ITEMS

161

--8302180238 LER 83-016/03L-0 on 830113, several valves exhibited excessive leakage causing total leak rate to exceed limit. Caused by dirt & scale deposits on seating surfaces & erosion of valve seats. Valves cleaned & components replaced. PALMER, R. A. Indiana & Michigan Electric Co. 83/02/11 Region 3, Office of Director 2pp 17212 100 24X Fiche 50-316, 83/02/11, 8302180226

8302180309 PNO-111-83-014 on 830211, higher than anticipated gaseous effluent release occurred while collecting sample from gas space from Unit 1. Second unplanned release from Unit 2 occurred while collecting coolant sample. HUEIER, L. J., GREGER, L. R. Region 3, Office of Director 83/02/11 1p 17211 228 24X Fiche 50-315, 83/02/11, 8302180309

8302230557 Forwards LER 83-017/03L-0 SMITH, W. O. Indiana & Michigan Electric Co. 83/02/14 KEPLER, J. O. Region 3, Office of Director 1p 17257 004 24X Fiche 50-316, 83/02/14, 8302230557

--8302230571 LER 83-017/03L-0 on 830115, during performance of RHR sys isolation valve test in Mode 4, RHR cooldown valve IM0-128 closed above Tech Spec pressure. Caused by inaccurate wide-range indicator readings. PALMER, R. A. Indiana & Michigan Electric Co. 83/02/14 Region 3, Office of Director 2pp 17257, 005 24X Fiche 50-316, 83/02/14, 8302230557

8302250238 Forwards LER 83-018/03L-0 SMITH, W. O. Indiana & Michigan Electric Co. 83/02/16 KEPLER, J. O. Region 3, Office of Director 1p 17292 340 24X Fiche 50-316, 83/02/16, 8302250238

--8302250241 LER 83-018/03L-0 on 830117, lower containment gaseous & particulate radiation monitors ERS-2301 & ERS-2305, failed. Caused by loaded particulate filter paper. Daily filter change now part of routine for shift. KRAUSE, D. F. Indiana & Michigan Electric Co. 83/02/16 Region 3, Office of Director 1p 17292 341 24X Fiche 50-316, 83/02/16, 8302250238

8302280357 Forwards LERs 83-019/03L-0, 83-020/03L-0 & 83-021/03L-0 SMITH, W. O. Indiana & Michigan Electric Co. 83/02/17 KEPLER, J. O. Region 3, Office of Director 1p 17313 031 24X Fiche 50-316, 83/02/17, 8302280357

--8302280358 LER 83-019/03L-0 on 830118, during normal operation, auxiliary cable vault (Zone 11) experienced inadvertent carbon dioxide discharge w/detector alarming. Caused by moisture in base. Moisture removed & sys returned to svc. PALMER, R. A. Indiana & Michigan Electric Co. 83/02/17 Region 3, Office of Director 2pp 17313 032 24X Fiche 50-316, 83/02/17, 8302280357

--8302280362 LER 83-020/03L-0 on 830119, during startup operations, steam generator 2 stop valve MRV-220 found w/one pillar guide bearing displaced. Cause undetermined. Split ring retainers fabricated & tack welded into position. ROBINSON, D. Indiana & Michigan Electric Co. 83/02/17 Region 3, Office of Director 1p 17313 034 24X Fiche 50-316, 83/02/17, 8302280357

--8302280364 LER 83-021/03L-0 on 830122, component cooling water west HX outlet to miscellaneous svcs valve (CM0-416) failed to operate within inservice insp time limitations. Cause unknown. Valve packing & bushings lubed & exercised. ROBINSON, D. Indiana & Michigan Electric Co. 83/02/17 Region 3, Office of Director 1p 17313 035 24X Fiche 50-316, 83/02/17, 8302280357

8302280534 Forwards updated LER 82-093/03X-1, SMITH, W. O. Indiana & Michigan Electric Co. 83/02/17 KEPLER, J. O. Region 3, Office of Director 1p 17309 013 24X Fiche 50-316, 83/02/17, 8302280534.

--8302280541 Updated LER 82-093/03X-1 on 821121, following unit shutdown, RCS dose equivalent I-131 concentration exceeded Tech Spec limit. Cause not stated. Fuel shipping performed during refueling outage to identify potential leaking assemblies. PALMER, R. A. Indiana & Michigan Electric Co. 83/02/17 Region 3, Office of Director 3pp 17309 014 24X Fiche 50-316, 83/02/17, 8302280534

8302280349 Forwards LERs 83-001/03L-0 & 83-003/03L-0 SMITH, W. O. Indiana & Michigan Electric Co. 83/02/18 KEPLER, J. O. Region 3, Office of Director 1p 17313 026 24X Fiche 50-316, 83/02/18, 8302280349

--8302280352 LER 83-001/03L-0 on 830122, during overspeed testing of main turbine, centrifugal overspeed trip device failed to operate at 110% & 112% trip points. Caused by worn area between governor weight & distance ring. Rings & weights replaced. CARTEAUX, P. Indiana & Michigan Electric Co. 83/02/18 Region 3, Office of Director 1p 17313 027 24X Fiche 50-316, 83/02/18, 8302280349

--8302280355 LER 83-003/03L-0 on 830119, during heatup, pressurizer pressure Channel I indicated approx 35 psi higher than normal. Caused by pressure transmitter NPP-151 calibr drifting high by approx 25 psi. Transmitter calibr. PALMER, R. A. Indiana & Michigan Electric Co. 83/02/18 Region 3, Office of Director 1p 17313 028 24X Fiche 50-316, 83/02/18, 8302280349

8302280422 LER 83-022/03L-0 has been canceled. Rept inadvertently listed Unit 2. SMITH, W. O. Indiana & Michigan Electric Co. 83/02/22 KEPLER, J. O. Region 3, Office of Director 1p 17307 324 24X Fiche 50-316, 83/02/22, 8302280422

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSR vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl. EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8302010108 Releases public version of revised Emergency Plan implementing Procedures. FELTON, J. M. Division of Rules and Records 83/01/26 Document Management Branch 1p 16990 106 24X Fiche 50-317, 83/01/26, 8302010108

--8302010117 Forwards public version of revised Emergency Plan implementing Procedures, including Procedures ERPIP 4 4 7 2 re post-accident containment atmosphere sampling & ERPIP 4 4 7 3 re post-accident reactor coolant sampling. * Baltimore Gas & Electric Co. 83/01/12, CLARK, R. A. Assistant Director for Operating Reactors 1p 16990, 107, 24X Fiche 50-317, 83/01/26, 8302010108.

--8302010126 Public version of revised Emergency Plan implementing Procedures, including Procedures ERPIP 4 4 7 2 re post-accident containment atmosphere sampling & ERPIP 4 4 7 3 re post-accident reactor coolant sampling. * Baltimore Gas & Electric Co. 83/01/12 119pp. 16990 108 24X Fiche 50-317, 83/01/26, 8302010108.

8302070288 Releases public version of revised emergency plan implementing Procedures. FELTON, J. M. Division of Rules and Records 83/01/31 Document Management Branch 1p 17061 325 24X Fiche 50-317, 83/01/31, 8302070288

--8302070290 Forwards public version of revised emergency plan implementing Procedures, including Procedures ERPIP 3 5 re immediate action - personnel injury & ERPIP 4 1 12 re first aid team leader checklist. * Baltimore Gas & Electric Co. 83/01/19 CLARK, R. A. Assistant Director for Operating Reactors 1p 17061 326 24X Fiche 50-317, 83/01/31, 8302070288.

--8302070292 Public version of revised emergency plan implementing Procedures, including Procedures ERPIP 3 5 re immediate action - personnel injury & ERPIP 4 1 12 re first aid team leader checklist. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/01/10 49pp. 17061 327 24X Fiche 50-317, 83/01/31, 8302070288.

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl. EISENHUT, D. O. Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp. 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302080432 Releases public version of revised emergency plan implementing Procedures. FELTON, J. M. Division of Rules and Records 83/02/02 Document Management Branch 1p 17071 132 24X Fiche 50-317, 83/02/02, 8302080432

DOCKETED ITEMS

- B302080435 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 1 re initial notification, ERPIP 4 5 re protective actions & ERPIP 4 5 2 re access control Receipt form encl
* Baltimore Gas & Electric Co 83/01/27 CLARK, R A Assistant Director for Operating Reactors 1p 17071 133 24X
Fiche 50-317, 83/02/02, B302080432
- B302080440 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 1 re initial notification, ERPIP 4 5 re protective actions & ERPIP 4 5 2 re access control
* RUSSELL, L B Baltimore Gas & Electric Co 83/01/12 21pp 17071 134 24X Fiche 50-317, 83/02/02, B302080432
- B302180007 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document Management Branch 1p 17223 121 24X Fiche 50-317, 83/02/14, B302180007
- B302180010 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 2 re immediate action - LNG contingency & ERPIP 4 1 17 re security team
* Baltimore Gas & Electric Co 83/01/20 WELCH, S Director's Office, Office of Inspection and Enforcement 1p 17223:122 24X
Fiche 50-317, 83/02/14, B302180007
- B302180012 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 2 re immediate action - LNG contingency & ERPIP 4 1 17 re security team
* Baltimore Gas & Electric Co 83/01/12 20pp 17223 123 24X
Fiche 50-317, 83/02/14, B302180007
- B302180046 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document Management Branch 1p 17226 317 24X Fiche 50-317, 83/02/14, B302180046
- B302180050 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 1 re initial notification, ERPIP 4 5 1 re onsite personnel protection, accountability & evaluation & ERPIP 4 5 2 re access control
* Baltimore Gas & Electric Co 83/01/12 65pp 17226:318 24X
Fiche 50-317, 83/02/14, B302180046
- B302250041 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/16 Document Management Branch 1p 17303 197 24X Fiche 50-317, 83/02/16, B302250041
- B302250050 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 2 re immediate action - LNG contingency & ERPIP 4 1 17 re security team
* Baltimore Gas & Electric Co 83/01/20 CLARK, R A Assistant Director for Operating Reactors 1p 17303 198 24X
Fiche 50-317, 83/02/16, B302250041
- P Operating license stage documents & correspondence
- B302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at B30106 meeting re environ qualification of electrical equipment
EISENHUT, D G Division of Licensing 83/01/18, DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196:091 24X
Fiche 50-000, 83/01/18, B302170019
- B302220475 Discusses until B30226 submittal re electrical equipment qualification program Deficiencies resulting from 90-day response to B10605 & 0901 ltrs identified & resolved
Sufficient info exists to justify continued operation
JAFFE, D H Operating Reactors Branch 3, 82/03/12, NOVAK, T M Assistant Director for Operating Reactors 2pp 17196:302 24X
Fiche 50-000, 83/01/18, B302170019
- B302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed. Requests justification for continued operation of each group by B21008 & 15, respectively
EISENHUT, D G Division of Licensing 82/09/24, MIRAOLIA, F Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, B302170019
- B302170169 Concludes that based on re-evaluation of licensee justification, continued operation until completion of environ qualification program will not present undue risk to public health & safety
JAFFE, D H Operating Reactors Branch 3 82/10/28 EISENHUT, D G Division of Licensing 2pp 17196 300 24X Fiche 50-000, 83/01/18, B302170019
- B302070473 Submits results of endurance testing of auxiliary feedwater pump 23 prior to unit startup, per NRC 771107 & B10508 ltrs
ASH, R F Baltimore Gas & Electric Co 83/01/21 CLARK, R A Operating Reactors Branch 3 4pp 17036 029 24X
Fiche 50-317, 83/01/21, B302070473
- B302100113 Forwards Amends 80 & 63 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amend incorporates revised pressurizer level band into pressurizer limiting condition for operation
JAFFE, D H Operating Reactors Branch 3 83/01/25 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 17134 327 24X
Fiche 50-317, 83/01/25, B302100113
- B302100119 Amends 80 & 63 to Licenses DPR-53 & DPR-69, respectively, incorporating revised pressurizer level band into pressurizer limiting condition for operation & surveillance requirements
LAING, Q C Assistant Director for Operating Reactors 83/01/25 14pp 17134 330 24X Fiche 50-317, 83/01/25, B302100113
- B302100123 Safety evaluation supporting Amend 80 & 63 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 83/01/25 7pp 17134 344 24X Fiche 50-317, 83/01/25, B302100113
- B302100127 Notice of issuance & availability of Amends 80 & 63 to Licenses DPR-53 & DPR-69, respectively
CLARK, R A Operating Reactors Branch 3 83/01/25 2pp 17134 351 24X Fiche 50-317, 83/01/25, B302100113
- B302080354 Expresses satisfaction w/utl B21115 response to NRC B20706-08 audit of procedures & training for pressurized thermal shock No further action required
CLARK, R A Operating Reactors Branch 3 83/01/26 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17107 121 24X
Fiche 50-317, 83/01/26, B302080354
- B302090285 Forwards Conference Note 797 of B21222 meeting w/NRC & Bechtel in Gaithersburg, MD to discuss containment tendon surveillance program NRC confident of acceptability of final design
MOJIBOMERY, B S Baltimore Gas & Electric Co 83/02/01 CLARK, R A Operating Reactors Branch 3 3pp 17070 244, 24X
Fiche 50-317, 83/02/01, B302090285
- B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247, 24X
Fiche 50-000, 83/02/08, B302080295
- B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, B302080304
- B302090072 Generic Ltr 83-108 to all licensees w/C-E designed NSSS re resolution of TWI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consumers Power Co 32pp 17290 185 24X Fiche 50-000, 83/02/08, B302090072
- B302230507 Forwards response to B21216 ltr re safety evaluation for environ qualification of safety-related electrical equipment Adequate mechanism exists to call attention to new data affecting qualification status of equipment
LUNDVALL, A E Baltimore Gas & Electric Co 83/02/10 CLARK, R A Operating Reactors Branch 3 3pp 17246 200 24X
Fiche 50-317, 83/02/10, B302230507
- B302280174 Discusses vendor problems w/qualification testing program for noble gas steam effluent monitors. Compliance w/NUREG-0737, Item II F i will be accomplished as soon as possible, but not later than B40301
LUNDVALL, A E Baltimore Gas & Electric Co 83/02/18 CLARK, R A Operating Reactors Branch 3 2pp 17305 272, 24X
Fiche 50-317, 83/02/18, B302280174

DOCKETED ITEMS

163

G Inspection reports, IE Bulletins & correspondence

8302010380 Forwards IE Insp Repts 50-317/82-13 & 50-318/82-11 on 820311-14 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/17
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 16773 279 24X
Fiche 50-317, 83/01/17, 8302010380

--8302010384 IE Insp Repts 50-317/82-13 & 50-318/82-11 on 820311-14 No noncompliance noted Major areas inspected radiation safety program, including action on previously identified items, Unit 1 refueling activities & radwaste & effluent sys
PLUMLEE, K, SHANDAKY, M Division of Engineering & Technical Programs 83/01/12 4pp 16773 281 24X Fiche 50-317, 83/01/17, 8302010380

8302020205 Forwards safety evaluation & notice of grant of relief from ASME, Section XI inservice insp requirements re reactor vessel closure & cladding exam, hydrostatic tests, ultrasonic stud exam & increased leak testing
CLARK, R A Operating Reactors Branch 3 83/01/24 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 16799 207 24X
Fiche 50-317, 83/01/24, 8302020205

--8302020214 Safety evaluation supporting requests for relief from inservice insp requirements re reactor vessel closure & cladding exam, hydrostatic tests, ultrasonic stud exam & increased leak testing
* Office of Nuclear Reactor Regulation, Director 83/01/24 4pp 16799 210 24X Fiche 50-317, 83/01/24, 8302020205

--8302020219 Notice of grant of relief from ASME, Section XI inservice insp requirements re reactor vessel closure & cladding exam, hydrostatic tests, ultrasonic stud exam & increased leak testing
CLARK, R A Operating Reactors Branch 3 83/01/24 2pp 16799 214 24X Fiche 50-317, 83/01/24, 8302020205

8302010388 Ack receipt of 821217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-27 & 50-318/82-23
STAROSTECKI, R Division of Project & Resident Programs 83/01/25 LUNDVALL, A E Baltimore Gas & Electric Co 1p 16773 261 24X
Fiche 50-317, 83/01/25, 8302010388

--8302010392 Responds to NRC 821124 ltr re violations noted in IE Insp Repts 50-317/82-27 & 50-318/82-23 Corrective actions surveillance test procedure that checks operability of source range neutron flux monitors corrected
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/17, STAROSTECKI, R Division of Project & Resident Programs 2pp 16773 262 24X Fiche 50-317, 83/01/25, 8302010388

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302040265 Responds to request for addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components for Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)" All svc water & component cooling HX inspected & cleaned quarterly.
LUNDVALL, A E Baltimore Gas & Electric Co 83/01/27 JORDAN, E L Director's Office, Office of Inspection and Enforcement 2pp. 17020 037 24X Fiche 50-317, 83/01/27, 8302040265

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095, 24X Fiche 50-000, 83/01/28, 8212060361.

8302180249 Forwards IE Insp Repts 50-317/82-24 & 50-318/82-20 on 820913-17 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/02/02 LUNDVALL, A E Baltimore Gas & Electric Co 2pp. 17215 266, 24X
Fiche 50-317, 83/02/02, 8302180249

--8302180254 Notice of violation from insp on 820913-17
* Region 1, Office of Director 83/02/02 1p 17215, 268 24X
Fiche 50-317, 83/02/02, 8302180249

--8307180259 IE Insp Repts 50-317/82-24 & 50-318/82-20 on 820913-17 Noncompliance noted failure to establish procedures for administrative control of keys to high radiation areas
COLLINS, D J, SHANBAKY, M M Division of Engineering & Technical Programs 83/01/28 4pp 17215 269 24X Fiche 50-317, 83/02/02, 8302180249

8302080258 Comments on 821129 SALP rept for Oct 1981 - Sept 1982 & on util 821231 response Overall performance acceptable Minor grammatical changes made to rept
* Region 1, Office of Director 83/02/04 LUNDVALL, A E Baltimore Gas & Electric Co 4pp 17057 018 24X
Fiche 50-317, 83/02/04, 8302080258

--8302080261 SALP rept for Oct 1981 - Sept 1982
* Office of Director 82/12/14 53pp 17057 022 24X
Fiche 50-317, 83/02/04, 8302080258

--8302080267 Forwards SALP rept resulting from 821129 review. Meeting scheduled for 821214 to discuss SALP, w/o encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/08, LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17057 077 24X
Fiche 50-317, 83/02/04, 8302080258

--8302080272 Comments on 821214 onsite meeting w/NRC re SALP rept. Corrective actions include increasing staffing levels & improving drawing & documents control, staff analyses & procedures & facility change controls
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/31 HAYNES, R C Region 1, Office of Director 4pp 17057 079, 24X
Fiche 50-317, 83/02/04, 8302080258

8302150393 Forwards IE Insp Repts 50-317/82-30 & 50-318/82-27 on 821216-830111 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/02/09 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17158 152 24X
Fiche 50-317, 83/02/09, 8302150393

--8302150386 Notice of violation from insp on 821216-830111.
* Region 2, Office of Director 83/02/09 1p 17158 154 24X
Fiche 50-317, 83/02/09, 8302150393

--8302150393 IE Insp Repts 50-317/82-30 & 50-318/82-27 on 821216-830111 Noncompliance noted failure to document compliance w/administrative procedures
ARCHITZEL, R E, TRIMBLE, D C, MCCABE, E C Division of Project & Resident Programs 83/02/03 19pp 17158 155 24X
Fiche 50-317, 83/02/09, 8302150393

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18, Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302" Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302230162 Forwards monthly operating repts for Jan 1983, LOTITO, E M Baltimore Gas & Electric Co 83/02/17 Director's Office, Office of Inspection and Enforcement 1p 17245 046 24X
Fiche 50-317, 83/02/17, 8302230162

--8302230167 Monthly operating repts for Jan 1983
LOTITO, E M Baltimore Gas & Electric Co 83/02/15 10pp. 17245 047 24X Fiche 50-317, 83/02/17, 8302230162.

S Reportable occurrences, LERs & related correspondence

8302010198 Forwards LER 82-07B/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/01/17 HAYNES, R C Region 1, Office of Director 1p 16974 034, 24X
Fiche 50-317, 83/01/17, 8302010198

DOCKETED ITEMS

--8302010205 LER 82-078/03L-0 on 821218, containment particulate radiation monitor (CPRM) declared inoperable due to low count rate. Caused by failure of detector On 821220, CPM failed again due to detached signal lead from assembly board transformer JUNOE, M A, BASSO, L F Baltimore Gas & Electric Co 83/01/17 Region I, Office of Director 1p 16974 035 24X Fiche 50-317, 83/01/17, 8302010198

8302010330 Forwards LER 82-082/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/01/21 HAYNES, R C
Region I, Office of Director 1p 16973 001 24X
Fiche 50-317, 83/01/21, 8302010330

--8302010337 LER 82-082/03L-0 on 821227, noted continuous control element assembly motion inhibit (CMI) signal in effect causing CMI to be inoperable whenever control element assemblies moved. Cause unknown CMI alarm relay replaced WENDERLICH, R L, RAYNOR, J W Baltimore Gas & Electric Co. 83/01/21 Region I, Office of Director. 2pp 16973 002 24X Fiche 50-317, 83/01/21, 8302010330

8302010348 Forwards LER 82-084/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/01/21 HAYNES, R C
Region I, Office of Director 1p 16973 341 24X
Fiche 50-317, 83/01/21, 8302010348

--8302010354 LER 82-084/03L-0 on 821223, sequencer initiated alarm failed to clear when diesel generator 12 shut down. Caused by failure of breaker lever to operate auxiliary switch in cubicle due to displaced assembly. New assembly installed JUNOE, M A, BASSO, L F Baltimore Gas & Electric Co. 83/01/21 Region I, Office of Director 2pp 16973 342, 24X Fiche 50-317, 83/01/21, 8302010348

8302010383 Forwards LER 82-077/03L-0
RUSSELL, L B Baltimore Gas & Electric Co. 83/01/21 HAYNES, R C
Region I, Office of Director 1p 16973 277 24X
Fiche 50-317, 83/01/21, 8302010383

--8302010389 LER 82-077/03L-0 on 821224, computer failed, rendering in-core detector monitoring sys inoperable. Caused by high environ temp in computer room due to improper rotation of air conditioner condenser fan motor. Computer boot straggled. LAGIEWSKI, J S, RAYNOR, J W Baltimore Gas & Electric Co. 83/01/21 Region I, Office of Director 1p 16973 278 24X Fiche 50-317, 83/01/21, 8302010383

8302070379 Forwards LER 83-001/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/01/27 HAYNES, R C
Region I, Office of Director 1p 17030 030, 24X
Fiche 50-317, 83/01/27, 8302070379

--8302070390 LER 83-001/03L-0 on 830101, during normal operation, auxiliary feedwater flow indication to steam generator 12 indicated no flow w/both auxiliary feedwater pumps operating. Caused by cold solder connections at input connector plug PAVIS, O S, RAYNOR, J W Baltimore Gas & Electric Co 83/01/27 Region I, Office of Director 1p 17030 031 24X Fiche 50-317, 83/01/27, 8302070379.

8302070405 Forwards updated LER 82-040/01X-1.
RUSSELL, L B Baltimore Gas & Electric Co 83/01/27 HAYNES, R C
Region I, Office of Director 1p 17029 258 24X
Fiche 50-317, 83/01/27, 8302070405

--8302070418 Updated LER 82-040/01X-1: on 820805, pressurizer pressure transmitters for four safety channels removed from svc for calibr. Steam generator pressure transmitters also found out of calibr. Caused by leakage current paths due to high temp. WENDERLICH, R L, BASSO, L F Baltimore Gas & Electric Co 83/01/27 Region I, Office of Director. 2pp 17029 259 24X Fiche 50-317, 83/01/27, 8302070405

-O
electric Co. 83/01/27 HAYNES, R C
p 17029 290, 24X

uring power operation while
tuation sys AL
wn Sequential blocking
or repair
as & Electric Co
r 1p 17029 291 24X

YNEB, R C.

--8302090321 LER 82-083/03L-0 on 821229, reactor protective sys channel A trip units for low steam generator level, low pressure & thermal margin/low pressure bypassed for maint on pressure instrument Caused by transmitter output drift LAGIEWSKI, J S, HINKLE, L S Baltimore Gas & Electric Co 83/01/28 Region I, Office of Director 1p 17066 142 24X Fiche 50-317, 83/01/28, 8302090316

8302230605 Forwards LER 82-086/04X-0
RUSSELL, L B Baltimore Gas & Electric Co 83/01/28 HAYNES, R C
Region I, Office of Director 1p 17255 206 24X
Fiche 50-317, 83/01/28, 8302230605

--8302230616 LER 82-086/04X-0 on 821118 & 1214, oyster samples showed Ag-110m w/higher than background activity. Caused by natural tendency or oysters to bioconcentrate environ silver Releases within ETS limits BROBST, G E Baltimore Gas & Electric Co 83/01/28 Region I, Office of Director 1p 17255 207 24X Fiche 50-317, 83/01/28, 8302230605

8302090395 Forwards LER 83-004/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/01/31 HAYNES, R C
Region I, Office of Director 1p 17067 103 24X
Fiche 50-317, 83/01/31, 8302090395

--8302090399 LER 83-004/03L-0 on 830101, containment sump level alarm would not clear. Caused by dirt & debris which interfered w/level switch operation. Level switch tube flushed JUNOE, M A, RAYNOR, J W Baltimore Gas & Electric Co 83/01/31 Region I, Office of Director 1p 17067 104 24X Fiche 50-317, 83/01/31, 8302090395

8302180257 Forwards updated LER 82-001/03X-2
RUSSELL, L B Baltimore Gas & Electric Co 83/02/02 HAYNES, R C
Region I, Office of Director 1p 17214 356 24X
Fiche 50-317, 83/02/02, 8302180257

--8302180269 Updated LER 82-001/03X-2 on 820119, excessive leak rate past containment personnel air lock outer door lower handwheel shaft seal discovered. Seal packaging gland tightened & new packaging inserted JUNOE, M A, NEIR, P J Baltimore Gas & Electric Co 83/02/02 Region I, Office of Director 1p 17214 357 24X Fiche 50-317, 83/02/02, 8302180257

8302230463 Forwards LER 83-005/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/02/03 HAYNES, R C
Region I, Office of Director 1p 17246 103 24X
Fiche 50-317, 83/02/03, 8302230463

--8302230476 LER 83-005/03L-0 on 830106, during startup operations, pressurizer level deviated slightly from program level by more than plus/minus 5%. Caused by loading of main turbine generator RCB temp swings of 10 degrees not uncommon JUNOE, M A, Baltimore Gas & Electric Co 83/02/04 Region I, Office of Director 1p 17246 104 24X Fiche 50-317, 83/02/03, 8302230463

8302230303 Forwards LER 83-002/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/02/04 HAYNES, R C
Region I, Office of Director 1p 17243 347 24X
Fiche 50-317, 83/02/04, 8302230303

--8302230306 LER 83-002/03L-0 on 830106, containment sump valve MOV-5462 would not operate. Caused by defective Limitorque motor operator SHJ-00 Operator replaced w/spare. Defective motor operator disassembled to determine cause of failure LAGIEWSKI, J S, HINKLE, L S Baltimore Gas & Electric Co 83/02/04 Region I, Office of Director 1p 17243 348 24X Fiche 50-317, 83/02/04, 8302230303

8302230698 Forwards LER 83-007/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/02/04 HAYNES, R C
Region I, Office of Director 1p 17257 313 24X
Fiche 50-317, 83/02/04, 8302230698

--8302230701 LER 83-007/03L-0 on 830107, ECCS pump room fan 11 discharge damper discovered only partially open. Cause unknown. Damper & similar ECCS pump room ventilation dampers locked open PAVIS, O S Baltimore Gas & Electric Co 83/02/04 Region I, Office of Director 1p 17257 314 24X Fiche 50-317, 83/02/04, 8302230698

8302230227 RO 83-08 on 830205, during surveillance testing, control element assembly 26 reed switch position indicator erratically indicated position & declared inoperable. Cause unknown. Indicator stacks replaced RUSSELL, L B Baltimore Gas & Electric Co 83/02/08 HAYNES, R C
Region I, Office of Director 1p 17245 135 24X
Fiche 50-317, 83/02/08, 8302230227

DOCKETED ITEMS

165

B302250196 Forwards LER 83-003/03L-0
RUSSELL, L. B. Baltimore Gas & Electric Co 83/02/09 HAYNES, R. C
Region 1, Office of Director 1p 17292 361 24X
Fiche 50-317, 83/02/09, B302250196

--B302250199 LER 83-003/03L-0 on B30120, low individual cell voltage
discovered in one cell of 125-volt battery 22 during
surveillance testing Cause not determined Battery placed on
equalize charge & will be monitored until stabilized
WEINERLICH, R. L., BASSO, L. F. Baltimore Gas & Electric Co
Region 1, Office of Director 1p 17292 362 24X
Fiche 50-317, 83/02/09, B302250196

B302240195 Notification of B30224 meeting w/util in Bethesda, MD to
discuss recent actuations of EBF sys
JAFFE, D. H. Operating Reactors Branch 3 83/02/15 CLARK, R. A
Operating Reactors Branch 3 2pp 17288 247 24X
Fiche 50-317, 83/02/15, B302240195

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for DLs, NSB vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, B301310203

B302250408 Submits operator licensing exam schedule in response to NRC
B30111 Generic Ltr 83-01
LUNDVALL, A. E. Baltimore Gas & Electric Co 83/02/22 EISENHUT, D. O
Division of Licensing 2pp 17298 224 24X Fiche 50-317, 83/02/22,
B302250408

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

B302010108 Releases public version of revised Emergency Plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/01/26 Document
Management Branch 1p 16990 106 24X Fiche 50-317, 83/01/26,
B302010108

--B302010117 Forwards public version of revised Emergency Plan
implementing procedures, including Procedures ERPIP 4.4.7.2 re
post-accident containment atmosphere sampling &
ERPIP 4.4.7.3 re post-accident reactor coolant sampling.
* Baltimore Gas & Electric Co 83/01/12 CLARK, R. A. Assistant
Director for Operating Reactors 1p 16990 107 24X
Fiche 50-317, 83/01/26, B302010108

--B302010126 Public version of revised Emergency Plan Implementing
Procedures, including Procedures ERPIP 4.4.7.2 re
post-accident containment atmosphere sampling &
ERPIP 4.4.7.3 re post-accident reactor coolant sampling.
* Baltimore Gas & Electric Co 83/01/12, 119pp 16990 108 24X
Fiche 50-317, 83/01/26, B302010108

B302070288 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/01/31, Document
Management Branch 1p 17061 325 24X Fiche 50-317, 83/01/31,
B302070288

--B302070290 Forwards public version of revised emergency plan
implementing procedures, including Procedures ERPIP 3.5 re
immediate action - personnel injury & ERPIP 4.1.12 re
first aid team leader checklist
* Baltimore Gas & Electric Co 83/01/19 CLARK, R. A. Assistant
Director for Operating Reactors 1p 17061 326 24X
Fiche 50-317, 83/01/31, B302070288

--B302070292 Public version of revised emergency plan implementing
procedures, including Procedures ERPIP 3.5 re immediate
action - personnel injury & ERPIP 4.1.12 re first aid team
leader checklist
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/01/10, 49pp
17061.327 24X Fiche 50-317, 83/01/31, B302070288

B301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/01, Consolidated
Edison Co. of New York, Inc 11pp 17221.226 24X
Fiche 50-000, 83/02/01, B301210340

B302080432 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/02/02 Document
Management Branch 1p 17071 132 24X Fiche 50-317, 83/02/02,
B302080432

--B302080435 Forwards public version of revised emergency plan
implementing procedures, including Procedures ERPIP 3.1 re
initial notification, ERPIP 4.5 re protective actions &
ERPIP 4.5.2 re access control Receipt form encl
* Baltimore Gas & Electric Co 83/01/27 CLARK, R. A. Assistant
Director for Operating Reactors 1p 17071 133 24X
Fiche 50-317, 83/02/02, B302080432

--B302080440 Public version of revised emergency plan implementing
procedures, including Procedures ERPIP 3.1 re initial
notification, ERPIP 4.5 re protective actions & ERPIP 4.5.2
re access control
RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/12 21pp
17071 134 24X Fiche 50-317, 83/02/02, B302080432

B302180007 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/02/14 Document
Management Branch 1p 17223 121 24X Fiche 50-317, 83/02/14,
B302180007,

--B302180010 Forwards public version of revised emergency plan
implementing procedures, including Procedures ERPIP 3.2 re
immediate action - LNO contingency & ERPIP 4.1.17 re
security team
* Baltimore Gas & Electric Co 83/01/20 WELCH, B. Director's
Office, Office of Inspection and Enforcement 1p 17223 122 24X
Fiche 50-317, 83/02/14, B302180007,

--B302180012 Public version of revised emergency plan implementing
procedures, including Procedures ERPIP 3.2 re immediate
action - LNO contingency & ERPIP 4.1.17 re security team
* Baltimore Gas & Electric Co 83/01/12 20pp 17223 123 24X
Fiche 50-317, 83/02/14, B302180007

B302180046 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/02/14 Document
Management Branch 1p 17226 317 24X Fiche 50-317, 83/02/14,
B302180046,

--B302180050 Public version of revised emergency plan implementing
procedures, including Procedures ERPIP 3.1 re initial
notification, ERPIP 4.5.1 re onsite personnel protection,
accountability & evaluation & ERPIP 4.5.2 re access control.
* Baltimore Gas & Electric Co 83/01/12 65pp 17226 318 24X
Fiche 50-317, 83/02/14, B302180046,

B302250041 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records 83/02/16 Document
Management Branch 1p 17303 197, 24X Fiche 50-317, 83/02/16,
B302250041,

--B302250050 Forwards public version of revised emergency plan
implementing procedures, including Procedures ERPIP 3.2 re
immediate action - LNO contingency & ERPIP 4.1.17 re
security team
* Baltimore Gas & Electric Co 83/01/20 CLARK, R. A. Assistant
Director for Operating Reactors 1p 17303 198 24X
Fiche 50-317, 83/02/16, B302250041

F. Operating license stage documents & correspondence

B302100093 Forwards Amend 62 to License DPR-69, safety evaluation &
notice of issuance & availability Amend revises limiting
condition for operation of third train of auxiliary
feedwater sys
JAFFE, D. H. Operating Reactors Branch 3 83/01/18, LUNDVALL, A. E.
Baltimore Gas & Electric Co 3pp 17135.046 24X
Fiche 50-318, 83/01/18, B302100093

--B302100097 Amend 62 to License DPR-69, revising limiting conditions for
operation & surveillance requirements to reflect operability
of recently installed third train of auxiliary feedwater
sys
LAINAS, O. C. Assistant Director for Operating Reactors, 83/01/18
9pp, 17135 049, 24X Fiche 50-318, 83/01/18, B302100093

--B302100104 Safety evaluation supporting Amend 62 to License DPR-69
* Office of Nuclear Reactor Regulation, Director 83/01/18 5pp,
17135.058 24X Fiche 50-318, 83/01/18, B302100093,

DOCKETED ITEMS

--8302100109 Notice of issuance & availability of Amend 62 to License DPR-69
CLARK, R A Operating Reactors Branch 3 83/01/18 2pp
17135 063 24X Fiche 50-318, 83/01/18, 8302100093

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D G Division of Licensing, 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019.

--8303220475 Discusses until 820226 submittal re electrical equipment qualification program. Deficiencies resulting from 90-day response to 810605 & 0901 ltrs identified & resolved. Sufficient info exists to justify continued operation
JAFFE, D H Operating Reactors Branch 3 82/03/12 NOVAK, T M Assistant Director for Operating Reactors 2pp, 17196-302 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed. Requests justification for continued operation of each group by 821008 & 15, respectively.
EISENHUT, D G Division of Licensing 82/09/24. MIRAGLIA, F Assistant Director for Safety Assessment 4pp 17196 265. 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170169 Concludes that based on re-evaluation of licensee justification, continued operation until completion of environ qualification program will not present undue risk to public health & safety
JAFFE, D H Operating Reactors Branch 3 82/10/28 EISENHUT, D G Division of Licensing 2pp, 17196-300 24X Fiche 50-000, 83/01/18, 8302170019

8302010090 Forwards safety evaluation re Reactor Safety Study Methodology Applications Program Interim Reliability Evaluation Program will provide more rigorous analysis of current as-built plant configuration
CLARK, R A Operating Reactors Branch 3 83/01/20 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 16990 227 24X
Fiche 50-318, 83/01/20, 8302010090

--8302010101 Safety evaluation re Reactor Safety Study Methodology Applications Program Study did not include significant plant mods
* Office of Nuclear Reactor Regulation, Director 83/01/20 2pp 16990 229. 24X Fiche 50-318, 83/01/20, 8302010090

8302070473 Submits results of endurance testing of auxiliary feedwater pump 23 prior to unit startup, per NRC 771107 & 810508 ltrs
ASH, R F. Baltimore Gas & Electric Co 83/01/21. CLARK, R A Operating Reactors Branch 3 4pp, 17036 029 24X
Fiche 50-317, 83/01/21, 8302070473

8302100113 Forwards Amends 80 & 63 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability. Amend incorporates revised pressurizer level band into pressurizer limiting condition for operation
JAFFE, D H Operating Reactors Branch 3 83/01/25 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 17134 227. 24X
Fiche 50-317, 83/01/25, 8302100113

--8302100114 Amends 80 & 63 to Licenses DPR-53 & DPR-69, respectively, incorporating revised pressurizer level band into pressurizer limiting condition for operation & surveillance requirements
LAINAS, G C Assistant Director for Operating Reactors 83/01/25. 14pp, 17134 330 24X Fiche 50-317, 83/01/25, 8302100113

--8302100123 Safety evaluation supporting Amend 80 & 63 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director, 83/01/25 7pp 17134 344. 24X Fiche 50-317, 83/01/25, 8302100113

--8302100127 Notice of issuance & availability of Amends 80 & 63 to Licenses DPR-53 & DPR-69, respectively
CLARK, R A Operating Reactors Branch 3 83/01/25 2pp 17134 351 24X Fiche 50-317, 83/01/25, 8302100113

8302090319 Forwards response to questions re failure of auxiliary feedwater control valve during test, in support of Suppl 1 to Cycle 5 reload license application
LUNDVALL, A E Baltimore Gas & Electric Co, 83/01/28. CLARK, R A. Operating Reactors Branch 3 6pp, 17067 179. 24X
Fiche 50-318, 83/01/28, 8302090319

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for CL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090072 Generic Ltr 83-100 to all licensees w/C-E designed NSSS re resolution of TMI Action Item 11 K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consumers Power Co 32pp 17290 185 24X Fiche 50-000, 83/02/08, 8302090072

8302170334 Submits info re inverter problems, in response to NRC 830203 request
TIERNAN, J A Baltimore Gas & Electric Co 83/02/09 CLARK, R A Operating Reactors Branch 3 3pp 17184 101 24X
Fiche 50-318, 83/02/09, 8302170334

8302230507 Forwards response to 821216 ltr re safety evaluation for environ qualification of safety-related electrical equipment. Adequate mechanism exists to call attention to new data affecting qualification status of equipment
LUNDVALL, A E Baltimore Gas & Electric Co 83/02/10 CLARK, R A Operating Reactors Branch 3 3pp 17246 200 24X
Fiche 50-317, 83/02/10, 8302230507

8302280174 Discusses vendor problems w/qualification testing program for noble gas steam effluent monitors. Compliance w/NUREG-0737, Item 1 F 1 will be accomplished as soon as possible, but not later than 840301
LUNDVALL, A E Baltimore Gas & Electric Co 83/02/18 CLARK, R A Operating Reactors Branch 3 2pp 17305 272 24X
Fiche 50-317, 83/02/18, 8302280174

G Inspection reports, IE Bulletins & correspondence

8302010380 Forwards IE Insp Repts 50-317/82-13 & 50-318/82-11 on 820511-14 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/17 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 16973 279 24X
Fiche 50-317, 83/01/17, 8302010380

--8302010384 IE Insp Repts 50-317/82-13 & 50-318/82-11 on 820511-14 No noncompliance noted. Major areas inspected: radiation safety program, including action on previously identified items, Unit 1 refueling activities & radwaste & effluent sys
PLUNLEE, K, SHANGAKY, M Division of Engineering & Technical Programs 83/01/12 4pp 16973 281 24X Fiche 50-317, 83/01/17, 8302010380

8302030521 Forwards IE Insp Rept 50-318/82-26 on 821215-18 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/20 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17007 283 24X
Fiche 50-318, 83/01/20, 8302030521

--8302030525 IE Insp Rept 50-318/82-26 on 821215-18 No noncompliance noted. Major areas inspected: procedure review, local leak rate test & integrated leak rate test
PULLANI, S V Region 1, Office of Director NORRHOLM, L J Division of Engineering & Technical Programs 83/01/17 7pp 17007 285 24X Fiche 50-318, 83/01/20, 8302030521

8302020205 Forwards safety evaluation & notice of grant of relief from ASME Section XI inservice insp requirements re reactor vessel closure & cladding exam, hydrostatic tests, ultrasonic stud exam & increased leak testing
CLARK, R A Operating Reactors Branch 3 83/01/24 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 16999-207 24X
Fiche 50-317, 83/01/24, 8302020205

--8302020214 Safety evaluation supporting requests for relief from inservice insp requirements re reactor vessel closure & cladding exam, hydrostatic tests, ultrasonic stud exam & increased leak testing
* Office of Nuclear Reactor Regulation, Director 83/01/24 4pp 16999 210 24X Fiche 50-317, 83/01/24, 8302020205

DOCKETED ITEMS

167

--8302020219 Notice of grant of relief from ASME Section XI inservice insp requirements re reactor vessel closure & cladding exam, hydrostatic tests, ultrasonic stud exam & increased leak testing
CLARK, R A Operating Reactors Branch 3 83/01/24 2pp
16799 214 24X Fiche 50-317, 83/01/24, 8302020205

8302010388 Ack receipt of 821217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-27 & 50-318/82-23
STAROSTECKI, R Division of Project & Resident Programs 83/01/25
LUNDVALL, A E Baltimore Gas & Electric Co 1p 16973 261 24X
Fiche 50-317, 83/01/25, 8302010388

--8302010392 Responds to NRC 821124 ltr re violations noted in IE Insp Repts 50-317/82-27 & 50-318/82-23 Corrective actions surveillance test procedure that checks operability of source range neutron flux monitors corrected
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/17
STAROSTECKI, R Division of Project & Resident Programs 2pp
16973 262 24X Fiche 50-317, 83/01/25, 8302010388

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design " Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302040265 Responds to request for addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components for Coraculua Sp (Asiatic Clam) & Mytilus Sp (Mussel) " All svc water & component cooling IIX inspected & cleaned quarterly
LUNDVALL, A E Baltimore Gas & Electric Co 83/01/27 JORDAN, E L Director's Office, Office of Inspection and Enforcement 2pp
17020 037 24X Fiche 50-317, 83/01/27, 8302040265

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302180249 Forwards IE Insp Repts 50-317/82-24 & 50-318/82-20 on 820913-17 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/02/02
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17215 266 24X
Fiche 50-317, 83/02/02, 8302180249

--8302180254 Notice of violation from insp on 820913-17
* Region 1, Office of Director 83/02/02 1p 17215 268, 24X
Fiche 50-317, 83/02/02, 8302180249

--8302180259 IE Insp Repts 50-317/82-24 & 50-318/82-20 on 820913-17 Noncompliance noted failure to establish procedures for administrative control of keys to high radiation areas
COLLINS, D J, SHANBAKY, M M Division of Engineering & Technical Programs 83/01/28 4pp 17215 269 24X Fiche 50-317, 83/02/02, 8302180249

8302080258 Comments on 821129 SALP rept for Oct 1981 - Sept 1982 & on util 821231 response Overall performance acceptable Minor grammatical changes made to rept
HAYNES, R C Region 1, Office of Director 83/02/04 LUNDVALL, A E Baltimore Gas & Electric Co 4pp 17057 018 24X
Fiche 50-317, 83/02/04, 8302080258

--8302080261 SALP rept for Oct 1981 - Sept 1982
* Region 1, Office of Director 82/12/14 53pp 17057 022 24X
Fiche 50-317, 83/02/04, 8302080258

--8302080267 Forwards SALP rept resulting from 821129 review Meeting scheduled for 821214 to discuss SALP W/o encl
STAROSTECKI, R Division of Project & Resident Programs 82/12/08, LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17057 077 24X
Fiche 50-317, 83/02/04, 8302080258

--8302080272 Comments on 821214 onsite meeting w/NRC re BALP rept, Corrective actions include increasing staffing levels & improving drawing & documents control, staff analyses & procedures & facility change controls
LUNDVALL, A E Baltimore Gas & Electric Co 82/12/31 HAYNES, R C Region 1, Office of Director 4pp 17057 079 24X
Fiche 50-317, 83/02/04, 8302080258

8302150383 Forwards IE Insp Repts 50-317/82-30 & 50-318/82-27 on 821216-830111 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/02/09
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 17158 152 24X
Fiche 50-317, 83/02/09, 8302150383

--8302150393 IE Insp Repts 50-317/82-30 & 50-318/82-27 on 821216-830111 Noncompliance noted failure to document compliance w/administrative procedures
ARCHITZEL, R E, TRIMBLE, D C, MCCABE, E C Division of Project & Resident Programs 83/02/03 19pp 17158 155 24X
Fiche 50-317, 83/02/09, 8302150383

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302230162 Forwards monthly operating repts for Jan 1983
LOTITO, E M Baltimore Gas & Electric Co 83/02/17 Director's Office, Office of Inspection and Enforcement 1p 17245 046 24X
Fiche 50-317, 83/02/17, 8302230162

--8302230167 Monthly operating repts for Jan 1983,
LOTITO, E M Baltimore Gas & Electric Co 83/02/15 10pp
17245 047 24X Fiche 50-317, 83/02/17, 8302230162

B Reportable occurrences, LERs & related correspondence

8302010163 Forwards updated LER 82-008/03X-1,
RUSSELL, L B Baltimore Gas & Electric Co 83/01/19 HAYNES, R C Region 1, Office of Director 1p 16974 074 24X
Fiche 50-318, 83/01/19, 8302010163

--8302010175 Updated LER 82-008/03X-1 on 820212, during Mode 3, inner containment door would not latch, preventing outer door from opening Caused by failure of air mechanism due to broken cam follower, Overhaul performed
JUNOS, M A, WEIR, P J Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 16974 075 24X
Fiche 50-318, 83/01/19, 8302010163

8302010180 Forwards updated LER 82-042/03X-1,
RUSSELL, L B Baltimore Gas & Electric Co 83/01/19 HAYNES, R C Region 1, Office of Director 1p 16974 022 24X
Fiche 50-318, 83/01/19, 8302010180

--8302010189 Updated LER 82-042/03X-1, on 820824, during Mode 3 operation, inner door on normal personnel hatch to containment would not shut completely Caused by failed airlock mechanism due to broken cam follower Overhaul performed,
WENDERLICH, R L, WEIR, P J Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 16974 023 24X
Fiche 50-318, 83/01/19, 8302010180

8302010341 Forwards updated LER 82-041/03X-1
RUSSELL, L B Baltimore Gas & Electric Co 83/01/19 HAYNES, R C Region 1, Office of Director 1p 16973 013 24X
Fiche 50-318, 83/01/19, 8302010341

--8302010345 Updated LER 82-041/03X-1 on 820826, during surveillance testing, excessive leak rate past containment personnel airlock outer door gasket discovered Caused by decrease in force holding door shut Door operating mechanism adjusted
JUNOS, M A, WEIR, P J Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 16973 014 24X
Fiche 50-318, 83/01/19, 8302010341

DOCKETED ITEMS

- 8302010349 Forwards updated LER 82-037/03X-1
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/19 HAYNES, R C
 Region 1, Office of Director 1p 16973 339 24X
 Fiche 50-318, 83/01/19, 8302010349
- 8302010352 Updated LER 82-037/03X-1 on 820730, outer personnel airlock door opening mechanism failed preventing door from being closed Caused by failed airlock mechanism due to broken cam follower Overhaul of airlock mechanism performed
 WEIR, P J Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 16973 340, 24X Fiche 50-318, 83/01/19, 8302010349
- 8302010555 Forwards updated LER 82-012/03X-1
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/19 HAYNES, R C
 Region 1, Office of Director 1p 16977 123 24X
 Fiche 50-318, 83/01/19, 8302010555
- 8302010560 Updated LER 82-012/03X-1 on 810309, personnel access hatch doors opened simultaneously, On 810307 & 09, inner door failed in partially open position Caused by failed airlock mechanism due to broken cam follower Overhaul performed
 WENDERLICH, R L, WEIR, P J Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 16977 124, 24X
 Fiche 50-318, 83/01/19, 8302010555
- 8302010566 Forwards LER 83-005/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/19 HAYNES, R C
 Region 1, Office of Director 1p 16977, 093, 24X
 Fiche 50-318, 83/01/19, 8302010566
- 8302010571 LER 83-005/03L-0 on 830107, during surveillance testing, shutdown cooling flow lost When circulation actuation signal manually initiated, operating low pressure safety injection pump stopped Caused by inadequate procedure
 WENDERLICH, R L Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 16977, 094 24X Fiche: 50-318, 83/01/19, 8302010566.
- 8302090420 Forwards updated LER 81-035/03X-1
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/19 HAYNES, R C
 Region 1, Office of Director 1p 17066 238 24X
 Fiche 50-318, 83/01/19, 8302090420
- 8302090422 Updated LER 81-035/03X-1 on 810703, during normal operation, small leak discovered on reactor coolant charging header, Caused by row of pinhole porosity in original socket weld on drain line Header isolated & leak repaired
 JUNOE, M A, HUSEBY, D E Baltimore Gas & Electric Co 83/01/19 Region 1, Office of Director 1p 17066 239 24X
 Fiche 50-318, 83/01/19, 8302090420.
- 8302070593 Forwards LER 83-003/01T-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/26 HAYNES, R C
 Region 1, Office of Director 1p 17035:036, 24X
 Fiche 50-318, 83/01/26, 8302070593
- 8302070606 LER 83-003/01T-0 on 830112, air line supplying two auxiliary feedwater regulating valve I/Ps became disconnected causing valves AFW-4311 & AFW-4312 to fail open, Caused by improper installation of tubing connector Air line repaired.
 PAVIS, O S, BOWMAN, M E Baltimore Gas & Electric Co 83/01/26 Region 1, Office of Director 3pp 17035, 037 24X
 Fiche 50-318, 83/01/26, 8302070593
- 8302070421 Forwards LER 82-055/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/27 HAYNES, R C
 Region 1, Office of Director 1p 17035:040, 24X
 Fiche 50-318, 83/01/27, 8302070421
- 8302070427 LER 82-055/03L-0 on 821228, during Mode 5, vital ac inverter 22 failed, causing 120-volt ac vital bus 22 to de-energize. Caused by inverter 22 output fuse F-6 blowing due to use of improper fuse Facility Change 83-1001 initiated.
 JUNOE, M A, BASSO, L F Baltimore Gas & Electric Co 83/01/27 Region 1, Office of Director 2pp 17035:041 24X
 Fiche 50-318, 83/01/27, 8302070421
- 8302090188 Forwards LER 82-010/03X-1
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/27 HAYNES, R C
 Region 1, Office of Director 1p 17069, 356, 24X
 Fiche 50-318, 83/01/27, 8302090188
- 8302090203 Updated LER 82-010/03X-1 on 820212, following reactor trip, element assembly 19 discovered stuck at 8-inch withdrawn position Cause undetermined Control element assembly & associated bundle inspected.
 LAOIEWSKI, J. S., FILE, P A Baltimore Gas & Electric Co 83/01/27 Region 1, Office of Director 3pp 17069, 357, 24X
 Fiche 50-318, 83/01/27, 8302090188
- 8302090372 Forwards LER 83-002/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/01/31 HAYNES, R C
 Region 1, Office of Director 1p 17071 098 24X
 Fiche 50-318, 83/01/31, 8302090372
- 8302090377 LER 83-002/03L-0 on 830101, transmitter leads inadvertently lifted, causing pressure indicator PIC-103 to fail low Caused by technician error Cable reconnected Engineering review will be conducted
 LAOIEWSKI, J. S., RAYNOR, J W Baltimore Gas & Electric Co 83/01/31 Region 1, Office of Director 2pp 17071 099 24X
 Fiche 50-318, 83/01/31, 8302090372
- 8302230716 Forwards LER 83-001/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/02/03 HAYNES, R C
 Region 1, Office of Director 1p 17257 303 24X
 Fiche 50-318, 83/02/03, 8302230716
- 8302230722 LER 83-001/03L-0 on 830104, vital inverter 21 tripped causing loss of 21 vital instrument bus Caused by blown input fuse Fuse replaced
 PAVIS, O S, BASSO, L F Baltimore Gas & Electric Co 83/02/03 Region 1, Office of Director 1p 17257 306 24X
 Fiche 50-318, 83/02/03, 8302230716
- 8302100289 RKO-1-83-007 on 830203, both PORVs inadvertently opened & partial safety injection occurred Caused by operator error in de-energizing wrong reactor protective sys channel
 ARCHITZEL, R, JOHNSON, D, TRIPP, L Region 1, Office of Director 83/02/04 2pp 17116 360 24X Fiche 50-318, 83/02/04, 8302100289
- 8302230222 RO 83-07 (U-2) on 830203, inadvertent actuation of PORV occurred Caused when operator mistakenly de-energized Channel D of reactor protection cabinet Ruptured disc in pressurizer quench tank replaced
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/02/04 HAYNES, R C
 Region 1, Office of Director 2pp 17245 156 24X
 Fiche 50-318, 83/02/04, 8302230222
- 8302250188 Forwards LER 83-004/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/02/09 HAYNES, R C
 Region 1, Office of Director 1p 17293 034 24X
 Fiche 50-318, 83/02/09, 8302250188
- 8302250195 LER 83-004/03L-0 on 830112, while attempting to feed steam generators, auxiliary feedwater pump 22 failed to develop sufficient discharge pressure Caused by governor linkage being out of adjustment Linkage adjusted
 FARRELL, E V, PAVIS, O S Baltimore Gas & Electric Co 83/02/09 Region 1, Office of Director 1p 17293 035 24X
 Fiche 50-318, 83/02/09, 8302250188
- 8302250402 Forwards LER 83-009/03L-0
 RUSSELL, L. B. Baltimore Gas & Electric Co 83/02/10 HAYNES, R C
 Region 1, Office of Director 1p 17298 226 24X
 Fiche 50-318, 83/02/10, 8302250402
- 8302250404 LER 83-009/03L-0 on 830116, pressurizer level deviated from program band by more than +/-5% several times & pressurizer pressure decreased below 2,225 psia Caused by temp swings due to startup testing Tech Spec change requested
 JUNOE, M A Baltimore Gas & Electric Co 83/02/10 Region 1, Office of Director 2pp 17298 227 24X Fiche 50-318, 83/02/10, 8302250402
- 8302240199 Notification of 830224 meeting w/util in Bethesda, MD to discuss recent actuations of ESF sys
 JAFFE, D H Operating Reactors Branch 3 83/02/15 CLARK, R A
 Operating Reactors Branch 3 2pp 17288 247 24X
 Fiche 50-317, 83/02/15, 8302240199
- V Operator Examinations
- 8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
 EISENHUT, D O Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche 50-000, 83/01/31, 8301310203
- 8302230408 Submits operator licensing exam schedule in response to NRC 830111 Generic Ltr 83-01
 LUNDVALL, A E Baltimore Gas & Electric Co 83/02/22 EISENHUT, D O
 Division of Licensing 2pp 17298 224 24X Fiche 50-317, 83/02/22, 8302230408

DOCKETED ITEMS

169

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8302020094 Notification of contract execution, Mod 1 to "TMI-2 Fire Protection Evaluation" Contractor Rolf-Jensen & Assoc FLEEMOR, C Technical Assistance Contracts Branch FIN B-8632 83/01/11 VOLLMER, R Division of Engineering NOLAN, F NRC - No Detailed Affiliation Given 1p 16998 293 24X
Fiche 50-320, 83/01/11, 8302020094

--8302020102 Mod 1, modifying statement of work, increasing estimated total amount of contract & extending period of performance to 830228, to "TMI-2 Fire Protection Evaluation" WEBB, W A Rolf Jensen & Associates, Inc HAGAN, T F Division of Contracts FIN B-8632 83/01/11 2pp 16998 294 24X
Fiche 50-320, 83/01/11, 8302020094

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080031 Informs of mod to installation schedule for fire detection capability in chemical cleaning bldg, provided in 820715 ltr Installation completion extended until 830429 KANOA, B K General Public Utilities - GPU Service Corp 83/02/01 SNYDER, B J TMI Program Office 1p 17058 191 24X
Fiche 50-320, 83/02/01, 8302080031

8302250348 Forwards IE Insp Rept 50-320/83-02 on 830102-29, No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/02/10 KANOA, B K General Public Utilities - GPU Service Corp 2pp 17291 126 24X
Fiche 50-320, 83/02/10, 8302250348

--8302250355 IE Insp Rept 50-320/83-02 on 830102-29 No noncompliance noted Major areas inspected previous insp findings, IE bulletins, routine plant operations, LERS, operator training, crane insp, health physics review & reactor bldg entries WIEBE, J, BARR, K, MOSLAK, T Division of Project & Resident Programs 83/02/04 8pp 17291 127 24X
Fiche 50-320, 83/02/10, 8302250348

O Adjudicatory correspondence

8302150445 Response to Philadelphia Electric Co & PSE&O 830124 motion to strike C Kefford affidavit suppl re expert qualifications Affidavit provides no relevant facts not considered by ASLARS W/Certificate of Svc REISE, J Hearing Branch 3 83/02/14 Commissioners 8pp 17158 194 24X
Fiche 50-000, 83/02/14, 8302150445

8302280193 Order extending time until 830328 for Commission to act to review TMI & Peach Bottom Intervenor's 821227 petition for review of ALAB-701 CHILK, S J Office of the Secretary of the Commission 83/02/25 Commissioners 2pp 17306 059 24X
Fiche 50-000, 83/02/25, 8302280193

P Operating license stage documents & correspondence

8302250049 "Evaluation of TMI-2 Reactor Bldg Decontamination Process," informal rept DOUGHERTY, D, ADAMS, J W Brookhaven National Laboratory FIN A-3162 8302250049 82/12/31 JOHNSON, T C Office of Nuclear Material Safety & Safeguards, Director 72pp 17303 007 24X
Fiche 50-320, 82/12/31, 8302250049

8302010396 Forwards application for amend to License DPR-73, consisting of Amend 1 to Tech Spec Change Request 3B, changing App B ETS re aquatic monitoring program ARHOLD, R C General Public Utilities - GPU Service Corp 83/01/24 SNYDER, B J TMI Program Office 2pp 16973 180 24X
Fiche 50-320, 83/01/24, 8302010396

--8302010399 Application for amend to License DPR-73, consisting of Amend 1 to Tech Spec Change Request 3B, changing App B ETS re aquatic monitoring program ARHOLD, R C General Public Utilities - GPU Service Corp 83/01/24 2pp 16973 182 24X
Fiche 50-320, 83/01/24, 8302010396

--8302010402 Amend 1 to Tech Spec Change Request 3B, changing App B ETS re aquatic monitoring program * General Public Utilities - GPU Service Corp 83/01/24 70pp 16973 185 24X
Fiche 50-320, 83/01/24, 8302010396

8302020001 Requests extension of time period during which both airlock doors on both containment bldg airlocks may be open simultaneously during entire entry period Action required to expedite personnel through radiation field KANOA, B K General Public Utilities - GPU Service Corp 83/01/28, BARRETT, L TMI Program Office 3pp 17005 069 24X
Fiche 50-320, 83/01/28, 8302020001

8302040416 Forwards Rev 2 to "TMI-2 Recovery Program Estimates," per 820921 ltr Removal of fuel & debris to begin Jan 1985 & conclude by June 1985 Total program scheduled for completion by June 1988 ARHOLD, R C General Public Utilities - GPU Service Corp 83/01/31, DENTON, H R Office of Nuclear Reactor Regulation, Director 17017 253 24X
Fiche 50-320, 83/01/31, 8302040416

--8302040418 Rev 2, "TMI-2 Recovery Program Estimate" * General Public Utilities - GPU Service Corp 82/12/30 55pp 17017 257 24X
Fiche 50-320, 83/01/31, 8302040416

8302170112 Forwards list of 21 generic ltrs issued since 820707 Ltrs applicable to TMI-2 indicated by asterisk SNYDER, B J TMI Program Office 83/02/03 KANOA, B K General Public Utilities - GPU Service Corp App 17191 106 24X
Fiche 50-320, 83/02/03, 8302170112

8302170392 Notification of contract execution, Mod 6 to "Human Factors Evaluation of Control Room Design & Operator Performance at TMI-2" Contractor Essex Corp SMITH, P A Division of Contracts NRC-04-79-209 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director, BELTRACCHI, L NRC - No Detailed Affiliation Given 1p 17195 286 24X
Fiche 50-320, 83/02/04, 8302170392

--8302170395 Mod 6, establishing final indirect rates per contract Clause 34, to "Human Factors Evaluation of Control Room Design & Operator Performance at TMI-2" FOOTE, R C Essex Corp SMITH, P A Division of Contracts, NRC-04-79-209 83/02/04 2pp 17195 287 24X
Fiche 50-320, 83/02/04, 8302170392

8302220030 Comments on proposed action in 830128 ltr re reactor bldg airlocks use during recovery activities Proposed action to maintain open doors acceptable BARRETT, L H TMI Program Office 83/02/07 KANOA, B K General Public Utilities - GPU Service Corp 3pp 17227 349 24X
Fiche 50-320, 83/02/07, 8302220030

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302170379 Forwards Amend 1 to organization plan, Rev 6, amended to resolve NRC concerns re location of review & audit provisions of plan vis-a-vis Tech Specs Review & audit section deleted from plan & included w/Tech Spec Change 40 KANOA, B K General Public Utilities - GPU Service Corp 83/02/11, SNYDER, B J TMI Program Office 5pp 17183 340 24X
Fiche 50-320, 83/02/11, 8302170379

8302180261 Forwards supplemental response to NRC generic ltr requesting info on control of heavy loads Encl covers response to Section 2 f for activities inside reactor bldg through head removal KANOA, B K General Public Utilities - GPU Service Corp 83/02/14, SNYDER, B J TMI Program Office 14pp 17215 245 24X
Fiche 50-320, 83/02/14, 8302180261

8302180431 Advises that reactor vessel will be drained to 328-ft level on 830216 to allow ion chamber insertion into vessel chamber will perform survey of exterior to vessel to obtain radiation level readings KANOA, B K General Public Utilities - GPU Service Corp 83/02/14, BARRETT, L H TMI Program Office 1p 17215 179 24X
Fiche 50-320, 83/02/14, 8302180431

8302240271 Forwards Rev 2 to "Polar Crane Functional Description," updating min required crane functions & movements necessary for crane recovery KANOA, B K General Public Utilities - GPU Service Corp 83/02/17, BARRETT, L H TMI Program Office 1p 07274 204 24X
Fiche 50-320, 83/02/17, 8302240271

DOCKETED ITEMS

--8302240274 Rev 2 to "Polar Crane Functional Description "
 * General Public Utilities - GPU Service Corp 83/02/28 25pp
 17274 205 24X Fiche 50-320, 83/02/17, 8302240271

8302250088 Comments on GPU study "Solid Waste Disposal Categorization for TMI-2," in response to 830113 memo Licensee should initiate discussions w/state to ascertain types of wastes which will be accepted at Hanford site
 BROUNING, R E Division of Waste Management 83/02/17 SNYDER, B J TMI Program Office 5pp 17302 331. 24X Fiche 50-320, 83/02/17, 8302250088

8302240260 Forwards "SER for Polar Crane Load Test "
 KANGA, B K General Public Utilities - GPU Service Corp 83/02/18
 BARRETT, L H TMI Program Office 1p 17274 230 24X
 Fiche 50-320, 83/02/18, 8302240260

--8302240263 "SER for Polar Crane Load Test," Rev O
 * General Public Utilities - GPU Service Corp 83/02/14 46pp
 17274 231 24X Fiche 50-320, 83/02/18, 8302240260

8302250277 Application for amend to License DPR-73 consisting of Amend 2 to organization plan; Rev 6 Amend resolves NRC concerns re responsibility & authority of SRQ to advise of any nuclear safety issues not addressed
 KANGA, B K General Public Utilities - GPU Service Corp 83/02/22
 SNYDER, B J TMI Program Office 1p 17292 042 24X
 Fiche 50-320, 83/02/22, 8302250277

--8302250287 Proposed Tech Spec change, consisting of Amend 2 to organization plan; Rev 6, resolving NRC concerns re responsibility & authority of SRQ to advise of any safety issues not addressed w/adequate consideration
 * General Public Utilities - GPU Service Corp. 83/02/22 4pp
 17292 043 24X Fiche 50-320, 83/02/22, 8302250277

Q Inspection reports, IE Bulletins & correspondence

8302030487 Forwards IE Insp Rept 50-320/82-15 on 821207-830101 & notice of violation
 STAROSTECKI, R Division of Project & Resident Programs 83/01/21
 KANGA, B K General Public Utilities - GPU Service Corp 2pp
 17007 309 24X Fiche 50-320, 83/01/21, 8302030487

--8302030494 Notice of violation from insp on 821207-830101
 * Division of Project & Resident Programs 83/01/21 1p
 17007 311 24X Fiche 50-320, 83/01/21, 8302030487

--8302030502 IE Insp Rept 50-320/82-15 on 821207-830101 Noncompliance noted failure to use controlled special operating procedure
 WIEBE, J, BARR, K, MOSLAK, T Division of Project & Resident Programs 83/01/18 9pp 17007 312. 24X Fiche 50-320, 83/01/21, 8302030487

8302010347 Ack receipt of 830117 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/82-12
 STAROSTECKI, R Division of Project & Resident Programs 83/01/24
 KANGA, B K General Public Utilities - GPU Service Corp 2pp
 16973 344 24X Fiche 50-320, 83/01/24, 8302010347

--8302010353 Responds to NRC 821130 ltr re violations noted in IE Insp Rept 50-320/82-12 Corrective actions operating procedure in place to implement sampling Sampling frequency determined by work package
 KANGA, B K General Public Utilities - GPU Service Corp. 83/01/17
 HAYNES, R C Region 1, Office of Director 5pp 16973 346 24X
 Fiche 50-320, 83/01/24, 8302010347

83010355 Ack receipt of 820902 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/82-06 Based on response, failure of drum ring due to lug matl & considered beyond licensee QA item no longer noncompliance
 STAROSTECKI, R Division of Project & Resident Programs 83/01/24
 KANGA, B K General Public Utilities - GPU Service Corp 2pp
 16973 333 24X Fiche 50-320, 83/01/24, 8302010355

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp. 17023 160 24X Fiche 50-000, 83/01/26, 8212060358.

8212060360 IE Info Notice 83-02, "Limitation H08C, H18C, H28C & H38C Gearheads," Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp. 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230122 Forwards IE Insp Rept 50-320/82-16 on 821206-830114 No noncompliance noted
 STAROSTECKI, R Division of Project & Resident Programs 83/02/09
 KANGA, B K General Public Utilities - GPU Service Corp 2pp
 17243 315 24X Fiche 50-320, 83/02/09, 8302230122

--8302230128 IE Insp Rept 50-320/82-16 on 821206-830114 No noncompliance noted Major areas inspected action on IE bulletins & circulars, previously identified items of noncompliance & radiological protection program
 O'NEILL, B, MOSLAK, T, BARR, K Division of Project & Resident Programs 83/02/02 10pp 17243 317 24X Fiche 50-320, 83/02/09, 8302230122

8302230348 Forwards IE Insp Rept 50-320/83-02 on 830102-29 No noncompliance noted
 STAROSTECKI, R Division of Project & Resident Programs 83/02/10
 KANGA, B K General Public Utilities - GPU Service Corp 2pp
 17291 125 24X Fiche 50-320, 83/02/10, 8302230348

--8302230355 IE Insp Rept 50-320/83-02 on 830102-29 No noncompliance noted Major areas inspected previous insp findings, IE bulletins, routine plant operations, LERs, operator training, crane insp, health physics review & reactor bldg entries
 WIEBE, J, BARR, K, MOSLAK, T Division of Project & Resident Programs 83/02/04 8pp 17291 127 24X Fiche 50-320, 83/02/10, 8302230348

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302080107 Forwards TMI Program Ofc weekly status rept for wk of 830116-22
 BARRETT, L H TMI Program Office 83/01/24 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 5pp 17106 005 24X Fiche 50-320, 83/01/24, 8302080107

8302170100 Forwards TMI Program Ofc weekly status rept for wk of 830123-29
 BARRETT, L H TMI Program Office 83/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 7pp 17191 082 24X Fiche 50-320, 83/01/31, 8302170100

8302070326 "TMI-2 Groundwater Monitoring Program," for period ending 821220
 KANGA, B K General Public Utilities - GPU Service Corp 83/02/01
 BARRETT, L H TMI Program Office 38pp 17030 313 24X
 Fiche 50-320, 83/02/01, 8302070326

8302100107 Forwards TMI aquatic studies monthly rept for Dec 1982
 HICKEY, C R Environmental Engineering Branch 83/02/04 BAILEY, I Records Services & Facilities Branch 1p 17135 016 24X
 Fiche 50-320, 83/02/04, 8302100107

--8302100111 Forwards TMI environ controls monthly progress rept for Dec 1982
 TEITTT, R General Public Utilities - GPU Service Corp 83/01/25
 HICKEY, C NRC - No Detailed Affiliation Given 1p 17135 017
 24X Fiche 50-320, 83/02/04, 8302100107.

--8302100117 "TMI Aquatic Study," monthly rept for Dec 1982
 NARDACCI, O A Ichthyological Associates, Inc. 82/12/31 23pp
 17135 018 24X Fiche 50-320, 83/02/04, 8302100107

DOCKETED ITEMS

8302220012 Submits THF Program Ofc weekly status rept for wk of
830130-0205
BARRETT, L. H. THF Program Office 83/02/07 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director SNYDER, B. J. THF Program
Office 9pp 17233 295 24X Fiche 50-320, 83/02/07, 8302220012

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen
recombiner is likely to malfunction following exposure
to elevated temp, high humidity environ Replacement part
identification will be provided to operators by 830218
EMPREY, D. C. Rockwell International Corp 82/12/17 COLLINS, J
Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

8302020147 LER 82-031 has been canceled
MCKNIGHT, J. General Public Utilities - GPU Service Corp 83/02/01
Region 1, Office of Director 1p 16993 362 24X
Fiche 50-320, 83/02/01, 8302020147

8302020171 LER 82-026 has been canceled
MCKNIGHT, J. Metropolitan Edison Co 83/02/01 Region 1, Office
of Director 1p 16993 359 24X Fiche 50-320, 83/02/01, 8302020171

8302020302 LER 82-027 has been canceled
MCKNIGHT, J. Metropolitan Edison Co 83/02/01 Region 1, Office
of Director 1p 16993 311 24X Fiche 50-320, 83/02/01, 8302020302

8302230599 Forwarded LER 83-001/01L-0
KANQA, B. K. General Public Utilities - GPU Service Corp 83/02/02
HAYNES, R. C. Region 1, Office of Director 1p 17257 323 24X
Fiche 50-320, 83/02/02, 8302230599

--8302230699 LER 83-001/01L-0 on 830104, once-through steam generator
(OTSG) A pressure did not register change after filling
secondary side Caused by failure of pressure transmitters
Alternate pressure indications installed on OTSG A & B
CHAPLIN, S. D. General Public Utilities - GPU Service Corp
83/02/02 Region 1, Office of Director 3pp 17257 324 24X
Fiche 50-320, 83/02/02, 8302230699

8302180250 LER 83-003/01P on 830211, hourly fire watch not performed at
required frequency Cause not stated
KANQA, B. K. General Public Utilities - GPU Service Corp 83/02/14
HAYNES, R. C. Region 1, Office of Director 1p 17215 273 24X
Fiche 50-320, 83/02/14, 8302180250

8302350207 Forwarded LER 83-002/01L-0
KANQA, B. K. General Public Utilities - GPU Service Corp 83/02/14
HAYNES, R. C. Region 1, Office of Director 1p 17293 105 24X
Fiche 50-320, 83/02/14, 8302350207

--8302250211 LER 83-002/01L-0 on 830114, Heise gauge QR-PI-1 fell
from mount Caused by tie wraps broken by vibration
induced fatigue Gauge recaliber & remounted using heavy
duty tie wraps
CHAPLIN, S. D. General Public Utilities - GPU Service Corp
83/02/14 Region 1, Office of Director 3pp 17293 106 24X
Fiche 50-320, 83/02/14, 8302250207

T Hearing transcripts on non-antitrust matters

8302010104 FOIA request for transcripts of lawsuit between General
Public Utils & B&W in Federal District Court, Southern
District of NY
WEISS, E. R. Union of Concerned Scientists 82/11/22, FELTON, J
Division of Rules and Records 1p 17061 071 24X
Fiche 50-289, 82/11/22, 8302010104

8302160098 Notification of contract execution, Mod 2 to "Transcription
of THF Tapes " Contractor NR Gross & Co, Inc
SMITH, P. A. Division of Contracts NRC-10-79-400 82/12/20
SPRINGER, M. Office of Administration McVEAGH, H. NRC - No Detailed
Affiliation Given 1p 17160 262 24X Fiche 50-289, 82/12/20,
8302160098

--8302160104 Mod 2, deobligating funds, to "Transcription of THF Tapes "
* Neal R. Gross & Co, Inc. SMITH, P. A. Division of Contracts,
NRC-10-79-400 82/12/20 1p 17160 263 24X
Fiche 50-289, 82/12/20, 8302160098

8302010112 Responds to FOIA request for transcripts of lawsuit between
General Public Utils & B&W in Federal District Court,
Southern District of NY Listed transcripts available in PDR
for viewing only
FELTON, J. M. Division of Rules and Records 82/12/21 WEISS, E. R
Hamon & Weiss, 3pp 17061 072 24X Fiche 50-289, 82/12/21,
8302010112

--8302010119 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 1
Pp 1-189 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/01 189pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010123 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 2
Pp 190-361 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/02 172pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010129 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 3
Pp 362-537 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/03 176pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010135 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 4
Pp 538-712 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/04 175pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010142 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 5
Pp 713-830 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/05 118pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010148 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 6
Pp 831-1,030 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/09 200pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010153 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 7
Pp 1,031-1,130 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/10 100pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010156 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 8
Pp 1,131-1,235 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/11 105pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010161 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 9
Pp 1,236-1,337 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/12 102pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010166 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 10
Pp 1,338-1,534 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/15 177pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010170 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 11
Pp 1,535-1,715 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/16 181pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010177 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 12
Pp 1,716-1,875 Transcript available in PDR for viewing only.
* NRC - No Detailed Affiliation Given 82/11/17 160pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010183 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 13
Pp 1,876-2,039 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/18 164pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010202 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 14
Pp 2,040-2,137 Transcript available in PDR for viewing only.
* NRC - No Detailed Affiliation Given 82/11/19 98pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

--8302010210 Transcript of lawsuit between General Public Utils & B&W
Federal District Court, Southern District of NY, Vol 15
Pp 2,138-2,311 Transcript available in PDR for viewing only.
* NRC - No Detailed Affiliation Given 82/11/22 174pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112

DOCKETED ITEMS

- B302010216 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 16
Pp 2,312-2,574 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/23 263pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010221 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 17
Pp 2,575-2,680 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/24 106pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010226 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 18
Pp 2,681-2,830 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/29 150pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010232 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 19
Pp 2,831-2,923 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/11/30 93pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010238 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 20
Pp 2,924-3,040 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/01 117pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010241 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 21
Pp 3,041-3,215 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/02 175pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010256 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 22
Pp 3,216-3,377 Transcript available in PDR for viewing only.
* NRC - No Detailed Affiliation Given 82/12/06 162pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010262 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 23
Pp 3,378-3,559 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/07 182pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010268 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 24
Pp 3,560-3,733 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/08 174pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010273 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 25
Pp 3,734-3,906 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/09 173pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010278 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 26
Pp 3,907-3,989 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/10 83pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010282 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 27
Pp 3,990-4,178 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/13 189pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010284 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 28
Pp 4,179-4,388 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/14 210pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010289 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 29
Pp 4,389-4,554 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/15 166pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010291 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 30
Pp 4,555-4,746 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/16 192pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010295 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 31
Pp 4,747-4,913 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/17 167pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010299 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 32
Pp 4,914-5,102 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/20 189pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010302 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 33
Pp 5,103-5,277 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/21 177pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302010305 Transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY, Vol 34
Pp 5,280-5,446 Transcript available in PDR for viewing only
* NRC - No Detailed Affiliation Given 82/12/22 167pp
17013 085 24X Fiche 50-289, 82/12/21, 8302010112
- B302220462 Transcript of Advisory Panel on Decontamination of TMI-2
B30202 meeting in Harrisburg, PA Pp 110-208
* Advisory Council on Decontamination of TMI Unit 2 83/02/02
103pp 17240 011 24X Fiche 50-320, 83/02/02, 8302220462
- V Operator Examinations

- B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203
- B302090407 Forwards Procedure 6210-ADM-2550 01, "Control of Exams for Units 1 & 2," Rev 0, in response to ASLB 820727 partial initial decision requiring procedure for routine sampling & review of exam answers for evidence of cheating
HUXILL, H D General Public Utilities - GPU Service Corp 83/02/07
STQLZ, J F Operating Reactors Branch 4 1p 17071 076 24X
Fiche 50-289, 83/02/07, 8302090407
- B302090410 Procedure 6210-ADM-2550 01, "Control of Exams for Units 1 & 2," Rev 0
* General Public Utilities - GPU Service Corp 83/02/07 6pp
17071 077 24X Fiche 50-289, 83/02/07, 8302090407
- DOCKET 50-321 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

- B302150221 Forwards IE Insp Repts 50-321/82-43 & 50-366/82-41 on 82120-1219 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/10
KELLY, R J Georgia Power Co 2pp 17150 035 24X
Fiche 50-321, 83/01/10, 8302150221
- B302150234 IE Insp Repts 50-321/82-43 & 50-366/82-41 on 82120-1219 No noncompliance noted Major areas inspected Tech Spec compliance, operator performance, overall plant operations, QA practices & station & site security procedures
HOLMES-RAY, P, BROCKWILE, V L Division of Project & Resident Programs 83/01/07 4pp 17150 037 24X Fiche 50-321, 83/01/10, 8302150221
- B302150716 Forwards IE Insp Repts 50-321/82-44 & 50-366/82-39 on 821206-10 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/01/10
KELLY, R J Georgia Power Co 2pp 17153 030 24X
Fiche 50-321, 83/01/10, 8302150716
- B302150721 IE Insp Repts 50-321/82-44 & 50-366/82-39 on 821206-10 No noncompliance noted Major area inspected radiological emergency exercise
ANDREWS, D L, MARSTON, R R, JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/01/07 7pp 17153 032 24X
Fiche 50-321, 83/01/10, 8302150716
- B302150427 Ack receipt of B30107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-39 & 50-366/82-37
DANCE, H C Division of Project & Resident Programs 83/01/19
KELLY, R J Georgia Power Co 1p 17157 037 24X
Fiche 50-321, 83/01/19, 8302150427

--B302150488 IE Insp Repts 50-321/82-39 & 50-366/82-37 on 821028-1120
Noncompliance noted out of svc RHR svc water strainer outlet
valve 2E11-F116B found shut but unlocked & inlet valve
2F11-F1178 found locked open
HOLMES-RAY, P., CRLENJAK, R V., ROGOE, J F Division of Project &
Resident Programs 82/12/08 4pp 17157 043 24X
Fiche 50-321, 83/01/19, B302150427

B302150611 Act receipt of 821130 & 1230 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-321/82-32 & 50-366/82-30
DANCE, H C Division of Project & Resident Programs 83/01/19
KELLY, R J Georgia Power Co 1p 17154 146 24X
Fiche 50-321, 83/01/19, B302150611

--B302150659 IE Insp Repts 50-321/82-32 & 50-366/82-30 on 820828-0928
Noncompliance noted failure to follow HPCI surveillance
procedure, properly notify NRC & follow health physics
procedure
ROGERS, R F., HOLMES-RAY, P., BROWNLEE, V L Division of Project &
Resident Programs 83/10/25 4pp 17154 157 24X
Fiche 50-321, 83/01/19, B302150611

B302020336 Releases public version of revised Emergency Plan
Implementing Procedures
FELTON, J M Division of Rules and Records 83/01/28 Document
Management Branch 1p 16997 040 24X Fiche 50-321, 83/01/28,
B302020336

--B302020342 Forwards public version of revised Emergency Plan
Implementing Procedures, including Procedures HNP-8134 re
whole body counter sys, HNP-4530 re alert - shift supervisor
& HNP-4730 re general emergency - shift supervisor
NIX, H C Georgia Power Co 83/01/18 Office of Nuclear Reactor
Regulation, Director 1p 16997 041 24X Fiche 50-321, 83/01/28,
B302020336

--B302020346 Public version of revised Emergency Plan Implementing
Procedures, including Procedures HNP-8134 re whole body
counter sys, HNP-4530 re alert - shift supervisor & HNP-4730
re general emergency - shift supervisor
ROGERS, W H., NIX, H Georgia Power Co 83/01/06 108pp
16997 042 24X Fiche 50-321, 83/01/28, B302020336

B302120340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B302120340

B302180275 Requests confirmation of current revs to security plan, using
encl list of effective pages as guide Receipt form encl
QUCHAN, L T Georgia Power Co 83/02/11 STOLZ, J F Operating
Reactors Branch 4 3pp 17212 054 24X Fiche 50-321, 83/02/11,
B302180275

B302180123 Requests meeting on or after 830329 w/NRR to appeal for
reconsideration of NRC proposed denial of App R exemption
request Addl info forthcoming to clarify 820701 submittal
QUCHAN, L T Georgia Power Co 83/02/14 STOLZ, J F Operating
Reactors Branch 4 2pp 17216 182 24X Fiche 50-321, 83/02/14,
B302180123

P Operating license stage documents & correspondence

B302040250 Documents verbal commitment to make simulators available
for control room task analysis
BECKHAM, J T Georgia Power Co 83/01/20 STOLZ, J F Operating
Reactors Branch 4 1p 17020 047 24X Fiche 50-000, 83/01/20,
B302040250

B302020482 Notification of 830223-24 meetings w/util, EG&O & SCBI in
Atlanta, GA to discuss NRC questions re review of licensee
radiological effluent Tech Spec submittal
RIVENBARK, G W Operating Reactors Branch 4, 83/01/31 STOLZ, J F
Operating Reactors Branch 4 2pp 16999 267 24X
Fiche 50-321, 83/01/31, B302020482

B302040282 Notification of 830202 meeting w/util in Bethesda, MD to
discuss environ qualification program
RIVENBARK, G W Operating Reactors Branch 4 83/01/31 STOLZ, J F
Operating Reactors Branch 4 2pp 17042, 298 24X
Fiche 50-321, 83/01/31, B302040282

B302080384 Notification of 830216 meeting w/util in Bethesda, MD to
discuss average power range monitor rod block monitor
Tech Spec program prepared to improve operational
flexibility
RIVENBARK, G W Operating Reactors Branch 4 83/02/01 STOLZ, J F
Operating Reactors Branch 4 2pp 17108 001, 24X
Fiche 50-321, 83/02/01, B302080384

B302030089 Generic Ltr 83-08 to all Mark I containment licensees re
mod of vacuum breakers on Mark I containment Requests
commitment to submit results of plant-unique calculations
which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public
Utilities - CPU Service Corp 3pp 17074 086 24X
Fiche 50-000, 83/02/02, B302030089

B302100036 Forwards Amends 92 & 30 to Licenses DPR-57 & NPF-5,
respectively, safety evaluation & notice of issuance &
availability Amends revise Tech Specs by modifying numerical
values for reactor water levels & setpoints
RIVENBARK, G W Operating Reactors Branch 4 83/02/02 BECKHAM, J T
Georgia Power Co 2pp 17135 138 24X Fiche 50-321, 83/02/02,
B302100036

--B302100051 Amends 92 & 30 to Licenses DPR-57 & NPF-5, respectively,
revising Tech Specs to modify numerical values & setpoints
for reactor water levels measured by shroud water level
instruments
STOLZ, J F Operating Reactors Branch 4 83/02/02 23pp
17135 140 24X Fiche 50-321, 83/02/02, B302100036

--B302100060 Safety evaluation supporting Amends 92 & 30 to Licenses
DPR-57 & NPF-5, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/02 3pp
17135 158 24X Fiche 50-321, 83/02/02, B302100036

--B302100076 Notice of issuance & availability of Amends 92 & 30 to
Licenses DPR-57 & NPF-5, respectively
STOLZ, J F Operating Reactors Branch 4 83/02/02 2pp
17135 161 24X Fiche 50-321, 83/02/02, B302100036

B302220006 Forwards safety evaluation of B00603 response to request for
addl info re plant-specific applicability of generic
analysis GE 1978 generic analysis bounds effects of loss of
dc power source on LOCA peak cladding temp
STOLZ, J F Operating Reactors Branch 4 83/02/07 BECKHAM, J T
Georgia Power Co 2pp 17233 308 24X Fiche 50-321, 83/02/07,
B302220006

--B302220008 Safety evaluation re plant-specific applicability of 1978
GE generic analysis Analysis bounds effects of loss of dc
power source on LOCA peak cladding temp
* NRC - No Detailed Affiliation Given 83/02/07 2pp
17233 310 24X Fiche 50-321, 83/02/07, B302220006

B302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

B302080301 Generic Ltr 83-05 to BNR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re SER of
"Emergency Procedure Guidelines, Rev 2," NEDD-24934, June
1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 4pp 17234 245 24X Fiche 50-000, 83/02/08, B302080301

B302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions Ability to use code must be
demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234, 24X
Fiche 50-000, 83/02/08, B302080304

B302170527 Forwards request for addl info re NUREG-0737, Item II K.3 2B,
"Verify Qualification of Accumulators on Automatic
Depressurization Sys Valves" Response requested within 60
days of receipt
STOLZ, J F Operating Reactors Branch 4 83/02/08 BECKHAM, J T
Georgia Power Co 4pp 17197 115 24X Fiche 50-321, 83/02/08,
B302170527

B302170530 Forwards request for addl info re review of NUREG-0737, Items
I A 2 1 4, "Upgrading of Reactor Operator & Senior Operator
Training" & II B 4, "Training for Mitigating Core Damage"
Response requested within 30 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4, 83/02/08 BECKHAM, J T
Georgia Power Co 3pp 17197 123 24X Fiche 50-321, 83/02/08,
B302170530

B302160248 Application for amend to License DPR-57, revising Tech Specs
on reactor coolant leakage limiting conditions for
operation & surveillance requirements
CAUSEY, J C Georgia Power Co 83/02/10 STOLZ, J F Operating
Reactors Branch 4 2pp 17163 191 24X Fiche 50-321, 83/02/10,
B302160248

DOCKETED ITEMS

--B302160254 Proposed Tech Specs re reactor coolant leakage limiting conditions for operation & surveillance requirements
* Georgia Power Co 83/02/10 9pp 17163 193 24X
Fiche 50-321,83/02/10,8302160254

B302180287 Forwards corrected proposed Tech Specs re recirculation & RHR sys piping repairs submitted on B30210 Typographical errors contained in Paragraphs 2 a & 2 b of Page 3 6-B
CAUSEY, J C Georgia Power Co 83/02/11 STOLZ, J F Operating Reactors Branch 4 1p 17211 249 24X Fiche 50-321,83/02/11, 8302180287

--B302180290 Corrected proposed Tech Spec Page 3 6-B re reactor coolant leakage
* Georgia Power Co 83/02/11 2pp 17211 250 24X
Fiche 50-321,83/02/11,8302180290

B302180320 Advises that implementation of NUREG-0737, Items II F 1(1) re noble gas effluent monitor & II F 1(2) re sampling & analysis of plant effluents will be delayed until B30315 due to component failure
QUCHAN, L T Georgia Power Co 83/02/11 STOLZ, J F Operating Reactors Branch 4 2pp 17213 347 24X Fiche 50-321,83/02/11, 8302180320

B302240248 Forwards Amend 93 to License DPR-57, safety evaluation & notice of issuance & availability Amend adds license condition re insp plans for recirculation & RHR piping sys & changes Tech Spec leak detection requirements
STOLZ, J F Operating Reactors Branch 4 83/02/11 BECKHAM, J T Georgia Power Co 3pp 17288 091 24X Fiche 50-321,83/02/11, 8302240248

--B302240258 Amend 93 to License DPR-57, adding license condition re insp plans for recirculation & RHR piping sys & changing Tech Spec by augmenting leak detection requirements
STOLZ, J F Operating Reactors Branch 3 83/02/11 6pp 17288 094 24X Fiche 50-321,83/02/11,8302240248

--B302240264 Safety evaluation supporting Amend 93 to License DPR-57
* Office of Nuclear Reactor Regulation, Director 83/02/11 24pp 17288 100 24X Fiche 50-321,83/02/11,8302240248

--B302240268 Notice of issuance & availability of Amend 93 to License DPR-57
STOLZ, J F Operating Reactors Branch 4 83/02/11 2pp 17288 124 24X Fiche 50-321,83/02/11,8302240248

B302280057 Application for amend to License DPR-57, changing Tech Specs to provide immediate relief from primary containment oxygen concentration requirements
HEAD, O F Georgia Power Co 83/02/22, STOLZ, J F Operating Reactors Branch 4 3pp 17307 190 24X Fiche 50-321,83/02/22, 8302280057

--B302280062 Proposed Tech Spec changes providing immediate relief from primary containment oxygen concentration requirements
* Georgia Power Co 83/02/22 3pp 17307 193 24X
Fiche 50-321,83/02/22,8302280062

3 Inspection reports, IE Bulletins & correspondence

302190221 Forwards IE Insp Repts 50-321/82-43 & 50-366/82-41 on 821120-1219 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/10
KELLY, R J Georgia Power Co 2pp 17150 035 24X
Fiche 50-321,83/01/10,8302190221

--B302190234 IE Insp Repts 50-321/82-43 & 50-366/82-41 on 821120-1219 No noncompliance noted Major areas inspected Tech Spec compliance, operator performance, overall plant operations, QA practices & station & site security procedures
HOLMES-RAY, P, BROWNLEE, V L Division of Project & Resident Programs 83/01/07 4pp 17150 037 24X Fiche 50-321,83/01/10, 8302190234

B302190716 Forwards IE Insp Repts 50-321/82-44 & 50-366/82-39 on 821206-10 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/01/10
KELLY, R J Georgia Power Co 2pp 17153 030 24X
Fiche 50-321,83/01/10,8302190716

--B302190721 IE Insp Repts 50-321/82-44 & 50-366/82-39 on 821206-10 No noncompliance noted Major area inspected: radiological emergency exercise
ANDREWS, D L, MARSTON, R. R., JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/01/07 7pp 17153 032 24X
Fiche 50-321,83/01/10,8302190721

B302190427 Ack receipt of 830107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-39 & 50-366/82-37
DANCE, H C Division of Project & Resident Programs 83/01/19
KELLY, R J Georgia Power Co 1p 17157 037 24X
Fiche 50-321,83/01/19,8302190427

--B302190443 Responds to NRC 821209 ltr re violations noted in IE Insp Repts 50-321/82-39 & 50-366/82-37 Corrective actions verification performed to ensure proper valve positions
Procedure HNP-2-1117 re RHR - svc revised
QUCHAN, L T Georgia Power Co 83/01/07 O'REILLY, J P Region 2, Office of Director 2pp 17157 039 24X Fiche 50-321,83/01/19, 8302190443

--B302190455 Forwards IE Insp Repts 50-321/82-39 & 50-366/82-37 on 821028-1120 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/12/09
KELLY, R J Georgia Power Co 2pp 17157 041 24X
Fiche 50-321,83/01/19,8302190455

--B302190465 Notice of violation from insp on 821028-1120
* Division of Project & Resident Programs 82/12/09 1p 24X
Fiche 50-321,83/01/19,8302190465

--B302190488 IE Insp Repts 50-321/82-39 & 50-366/82-37 on 821028-1120 Noncompliance noted out of svc RHR svc water strainer outlet valve ZE11-F116B round shut but unlocked & inlet valve ZE11-F117B found locked open
HOLMES-RAY, P, CRIENJAK, R V, ROOSE, J F Division of Project & Resident Programs 82/12/08 4pp 17157 043 24X
Fiche 50-321,83/01/19,8302190488

B302190611 Ack receipt of 821130 & 1230 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-32 & 50-366/82-30
DANCE, H C Division of Project & Resident Programs 83/01/19
KELLY, R J Georgia Power Co 1p 17154 146 24X
Fiche 50-321,83/01/19,8302190611

--B302190627 Supply 821130 response to NRC 821130 ltr re violations noted in IE Insp Repts 50-321/82-32 & 50-366/82-30 Corrective actions need to reprimand deviations of safety nature to shift supervisor emphasized to individual involved
QUCHAN, L T Georgia Power Co 82/12/30 O'REILLY, J P Region 2, Office of Director 1p 17154 147 24X Fiche 50-321,83/01/19, 8302190627

--B302190640 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-321/82-32 & 50-366/82-30 Corrective actions operator reprimanded & instructed to follow plant procedures & instrument check performed
QUCHAN, L T Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 5pp 17154 148 24X Fiche 50-321,83/01/19, 8302190640

--B302190646 Forwards IE Insp Repts 50-321/82-32 & 50-366/82-30 on 820928-0928 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/26
KELLY, R J Georgia Power Co 2pp 17154 153 24X
Fiche 50-321,83/01/19,8302190646

--B302190652 Notice of violation from insp on 820828-0928
* Division of Project & Resident Programs 82/10/26 2pp 17154 155 24X Fiche 50-321,83/01/19,8302190652

--B302190659 IE Insp Repts 50-321/82-32 & 50-366/82-30 on 820828-0928 Noncompliance noted failure to follow HPCI surveillance procedure, properly notify NRC & follow health physics procedure
ROGERS, R F, HOLMES-RAY, P, BROWNLEE, V L Division of Project & Resident Programs 82/10/25 4pp 17154 157 24X
Fiche 50-321,83/01/19,8302190659

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000,83/01/26,8212060358

B302190042 Responds to IE Bulletin 82-03 re stress corrosion cracking in austenitic stainless steel in RHR recirculation sys piping Info re Items 1 & 4 submitted 821215 Info completes response
BECKHAM, J T Georgia Power Co 83/01/26 O'REILLY, J P Region 2, Office of Director 3pp 17148 049 24X Fiche 50-321,83/01/26, 8302190042

DOCKETED ITEMS

175

8302010512 Forwards info re analyses & repairs of recirculation & RHR sys piping welds Details of inservice insp discussed Util intends to return unit to power operation upon completion of current outage Meeting scheduled for 830201 to discuss subj
GUCHA, L T Georgia Power Co 83/01/27 STOLZ, J Operating Reactors Branch 4 4pp 16977 302 24X Fiche 50-321, 83/01/27, 8302010512

--8302010938 Responds to Items 2 & 3 of IE Bulletin 82-03 re stress corrosion cracking in austenitic stainless steel BWR recirculation sys piping Responses to Items 1 & 4 provided in util 821215 ltr Recirculation sys welds will be repaired
BECKHAM, J T Georgia Power Co 83/01/26 O'REILLY, J P Region 2, Office of Director 3pp 16977 326 24X Fiche 50-321, 83/01/27, 8302010512

--8302010550 Rev 0 to 'Design Rpt for Recirculation Sys & RHR Sys Weld Overlay Repairs & Flaw Evaluation at EI Hatch Nuclear Power Plant Unit 1 "
CHARNLEY, J E, REEVES, P E, RICCARDELLA, P NUTECH Engineers, Inc GPC-04-104 R00 83/01/31 97pp 16977 330 24X Fiche 50-321, 83/01/27, 8302010512

8212060360 IE Info Notice 83-02, "Limitique H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150423 Ack receipt of 830131 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Repts 50-321/82-36 & 50-366/82-34
LEWIS, R C Division of Project & Resident Programs 83/02/09 KELLY, R J Georgia Power Co 1p 17148 117 24X Fiche 50-321, 83/02/09, 8302150423

--8302150431 Responds to NRC 821227 ltr re violation & deviation noted in IE Insp Repts 50-321/82-36 & 50-366/82-34 Corrective actions QA audits scheduled for three vendors & QA program revised to provide annual QA audits re environ monitoring
GUCHA, L T Georgia Power Co 83/01/31 O'REILLY, J P Region 2, Office of Director 3pp 17148 118 24X Fiche 50-321, 83/02/09, 8302150423

--8302150435 Forwards IE Insp Repts 50-321/82-36 & 50-366/82-34 on 821130-1206 & notices of violation & deviation
LEWIS, R C Division of Project & Resident Programs 82/12/27 KELLY, R J Georgia Power Co 2pp 17148 121 24X Fiche 50-321, 83/02/09, 8302150423

--8302150441 Notice of violation from insp on 821130-1206 * Division of Project & Resident Programs 82/12/27 1p 17148 123 24X Fiche 50-321, 83/02/09, 8302150423

--8302150447 Notice of deviation from insp on 821130-1206 * Division of Project & Resident Programs 82/12/27 1p 17148 124 24X Fiche 50-321, 83/02/09, 8302150423

--8302150457 IE Insp Repts 50-321/82-36 & 50-366/82-34 on 821130-1206 Noncompliance noted failure to conduct annual QA audits of radioanalytical program & to develop program providing annual vendor QA audits re environ monitoring
CUNNINGHAM, A L, MONTGOMERY, D H Division of Engineering & Radiological Safety Programs 82/12/20 7pp 17148 125 24X Fiche 50-321, 83/02/09, 8302150423

8302240248 Forwards Amend 93 to License DPR-57, safety evaluation & notice of issuance & availability Amend adds license condition re insp plans for recirculation & RHR piping sys & changes Tech Spec 19ak detection requirements
STOLZ, J F Operating Reactors Branch 4 83/02/11 BECKHAM, J T Georgia Power Co 3pp 17288 091 24X Fiche 50-321, 83/02/11, 8302240248

--8302240258 Amend 93 to License DPR-57, adding license condition re insp plans for recirculation & RHR piping sys & changing Tech Spec by augmenting leak detection requirements
STOLZ, J F Operating Reactors Branch 3 83/02/11 6pp 17288 094 24X Fiche 50-321, 83/02/11, 8302240248

--8302240264 Safety evaluation supporting Amend 93 to License DPR-57 * Office of Nuclear Reactor Regulation, Director 83/02/11 24pp 17288 100 24X Fiche 50-321, 83/02/11, 8302240248

--8302240268 Notice of issuance & availability of Amend 93 to License DPR-57
STOLZ, J F Operating Reactors Branch 4 83/02/11 2pp 17288 124 24X Fiche 50-321, 83/02/11, 8302240248

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365.

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302160232 Forwards monthly operating repts for Jan 1983
NIX, H C Georgia Power Co 83/02/08 Director's Office, Office of Inspection and Enforcement 1p 17170 135 24X Fiche 50-321, 83/02/08, 8302160232

--8302160238 Monthly operating repts for Jan 1983
SEWEL, S K Georgia Power Co 83/02/03 10pp 17170 136 24X Fiche 50-321, 83/02/08, 8302160232

8302160243 Forwards monthly operating repts for Jan 1983
NIX, H C Georgia Power Co 83/02/08 NRC - No Detailed Affiliation Given 1p 17170 200 24X Fiche 50-321, 83/02/08, 8302160243

B Reportable occurrences, LERs & related correspondence

8302010393 Forwards LER 83-003/03L-0
NIX, H C Georgia Power Co 83/01/20 O'REILLY, J P Region 2, Office of Director 1p 16973 257 24X Fiche 50-321, 83/01/20, 8302010393

--8302010400 LER 83-003/03L-0 on 830105, NRC notified util of incorrect page in Tech Specs P 3 5-9 stated that six of seven instead of seven automatic depressurization valves should be operable Caused by personnel error in inserting wrong rev
TIPPS, S B Georgia Power Co 83/01/20 Region 2, Office of Director 2pp 16973 258 24X Fiche 50-321, 83/01/20, 8302010393

8302030288 Forwards updated LER 80-062/01X-1
NIX, H C Georgia Power Co 83/01/25 O'REILLY, J P Region 2, Office of Director 1p 17001 259 24X Fiche 50-321, 83/01/25, 8302030288

--8302030294 Updated LER 80-062/01X-1 on 800612, investigation of pavement deflection revealed settling of fill matl under svc water & RHR svc water lines Caused by improper compaction of area in front of intake structure Backfill replaced
SUMNER, H L Georgia Power Co 83/01/25 Region 2, Office of Director 1p 17001 260 24X Fiche 50-321, 83/01/25, 8302030288.

8302070386 Forwards LER 83-002/03L-0
TIPPS, S B Georgia Power Co 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 17030 040 24X Fiche 50-321, 83/01/27, 8302070386

--8302070388 LER 83-002/03L-0 on 830104, while performing hydraulic shock & sway arrestor insp & functional test surveillance procedure, snubber discovered inoperable Caused by component failure due to low hydraulic fluid Snubber replaced
TIPPS, S B Georgia Power Co 83/01/27 Region 2, Office of Director 1p 17030 041 24X Fiche 50-321, 83/01/27, 8302070386

8302140046 Forwards updated LER 79-076/01X-1
NIX, H C Georgia Power Co 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 17140 182 24X Fiche 50-321, 83/01/27, 8302140046

--8302140050 Updated LER 79-076/01X-1 on 790902, plant engineering personnel confirmed NSSS vendor info re cable separation irregularities in HPCI sys Caused by design error Cable will be rerouted per Design Change Request 79-379
SUMNER, H L Georgia Power Co 83/01/27 Region 2, Office of Director 2pp 17140 183 24X Fiche 50-321, 83/01/27, 8302140046.

DOCKETED ITEMS

8302150201 Forwards LER 83-001/03L-0
NIX,H C Georgia Power Co 83/01/27 O'REILLY,J P Region 2,
Office of Director 1p 17150 025 24X Fiche 50-321,83/01/27,
8302150201

--8302150209 LER 83-001/03L-0 on 830102,during surveillance procedure,
two control room ventilation bypass isolation valves would
not close within required 7 s Caused by instrument drift
Rate set valves adjusted
TIPPS,S B Georgia Power Co 83/01/27 Region 2, Office of
Director 1p 17190 026 24X Fiche 50-321,83/01/27,8302150201

8302150020 Forwards LER 83-004/03L-0
NIX,H C Georgia Power Co 83/02/03 O'REILLY,J P Region 2,
Office of Director 1p 17146 063 24X Fiche:50-321,83/02/03,
8302150020

--8302150025 LER 83-004/03L-0 on 830108,control room supply fan A found
inoperable.Caused by component failure due to inoperable
time delay relay & flow switch Relay & switch replaced &
returned to operable status Fan A returned to svc on 830111
TIPPS,S B Georgia Power Co 83/02/03 Region 2, Office of
Director 1p 17146 064 24X Fiche 50-321,83/02/03,8302150020

8302150152 Forwards LER 83-005/03L-0
NIX,H C Georgia Power Co 83/02/03 O'REILLY,J P Region 2,
Office of Director 1p 17147 216 24X Fiche 50-321,83/02/03,
8302150152

--8302150162 LER 83-005/03L-0 on 830106,power supply for standby gas
treatment fan 1A found inoperable Caused by power supply
breaker being off Breaker turned on
TIPPS,S B Georgia Power Co 83/02/03 Region 2, Office of
Director 2pp 17147 217 24X Fiche 50-321,83/02/03,8302150152

8302150190 Forwards updated LER 80-127/03X-1
NIX,H C Georgia Power Co 83/02/03 O'REILLY,J P Region 2,
Office of Director 1p 17147 158 24X Fiche 50-321,83/02/03,
8302150190

--8302150194 Updated LER 80-127/03X-1 on 801223,during research & in
preparation for 9 yr inservice insp,lack of hard
documentation proving visual insp of at least 50% of Class I
valve internals revealed Caused by inadequate procedures
SUMNER,H L Georgia Power Co 83/02/03 Region 2, Office of
Director 1p 17147 159 24X Fiche 50-321,83/02/03,8302150190

8302150287 Forwards updated LER 81-110/03X-1
NIX,H C Georgia Power Co 83/02/08 O'REILLY,J P Region 2,
Office of Director 1p 17148 268 24X Fiche 50-321,83/02/08,
8302150287

8302150302 Updated LER 81-110/03X-1 on 811001,u/unit in hot standby,
mainstack monitor found inoperative Caused by corrosion of
carbon vanes on pump B Vanes cleaned & reinstalled in pump
TIPPS,S B Georgia Power Co 83/02/08 Region 2, Office of
Director 2pp 17148 269 24X Fiche 50-321,83/02/08,8302150287

8302230223 Forwards LER 83-010/03L-0
NIX,H C Georgia Power Co 83/02/08 O'REILLY,J P Region 2,
Office of Director 1p 17245 136 24X Fiche 50-321,83/02/08,
8302230223

--8302230229 LER 83-010/03L-0 on 830110,during reactor coolant
instrumentation lines excess flow check valve operability
review,12 valves found inoperable.Caused by electrical &
mechanical component failures Valves repaired/replaced
TIPPS,S B Georgia Power Co 83/02/08 Region 2, Office of
Director 2pp 17245 137 24X Fiche 50-321,83/02/08,8302230223

8302230485 Forwards LER 83-008/03L-0
NIX,H C Georgia Power Co 83/02/10 O'REILLY,J P Region 2,
Office of Director 1p 17246 024 24X Fiche 50-321,83/02/10,
8302230485

--8302230494 LER 83-008/03L-0 on 830112,during performance of clean
wastewater processing procedure,personnel discharged
waste sample tank A to river before sample analyzed Caused
by personnel error Responsible individual reprimanded.
TIPPS,S B Georgia Power Co 83/02/10 Region 2, Office of
Director 2pp 17246:025 24X Fiche 50-321,83/02/10,8302230485

8302230308 Updated RO 50-321/1979-021 Rev 5 tritium levels discovered
in groundwater samples Cause attributed to slight shift of
main body of tritiated groundwater Gamma scans of 3,000 s
will be taken each time samples collected
NIX,H C Georgia Power Co 83/02/15 O'REILLY,J P Region 2,
Office of Director 3pp 17243 327 24X Fiche 50-321,83/02/15,
8302230308

8302280272 Forwards LER 83-012/03L-0
NIX,H C Georgia Power Co 83/02/15 O'REILLY,J P Region 2,
Office of Director 1p 17313 004 24X Fiche 50-321,83/02/15,
8302280272

--8302280278 LER 83-012/03L-0 on 830124,plant svc water pump 2A would not
start automatically on low header pressure Caused by failure
of pump motor start relay holding coil Relay replaced
TIPPS,S B Georgia Power Co 83/02/15 Region 2, Office of
Director 1p 17313 005 24X Fiche 50-321,83/02/15,8302280272

8302280343 Forwards updated LER 81-129/01X-1
NIX,H C Georgia Power Co 83/02/15 O'REILLY,J P Region 2,
Office of Director 1p 17308 076 24X Fiche 50-321,83/02/15,
8302280343

--8302280346 Updated LER 81-129/01X-1 on 811203,torus to reactor bldg
vacuum relief isolation valve failed to close Caused by
water accumulation in reactor bldg pressure sensing lines,
due to improper installation Design change implemented
SUMNER,H L Georgia Power Co 83/02/15 Region 2, Office of
Director 2pp 17308 077 24X Fiche 50-321,83/02/15,8302280343

8302280207 Forwards updated LER 82-089/01X-2
NIX,H C Georgia Power Co 83/02/17 O'REILLY,J P Region 2,
Office of Director 1p 17311 320 24X Fiche 50-321,83/02/17,
8302280207

--8302280223 Updated LER 82-089/01X-2 on 821104,during cold shutdown,
rejectable linear indications discovered on two RHR welds
& five recirculation welds Caused by intergranular stress
corrosion cracking Six welds repaired w/weld overlay method
SUMNER,H L Georgia Power Co 83/02/17 Region 2, Office of
Director 3pp 17311 321 24X Fiche 50-321,83/02/17,8302280207

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees,applicants
for CLS,MSS vendors,reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISERHUT,D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000,83/01/31,8301310203

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8301250435 Application for Amend 46 to OL application,consisting of
Rev 2B to FSAR Affidavit encl
SMITH,J L Long Island Lighting Co 82/12/30 DENTON,H R Office
of Nuclear Reactor Regulation, Director 3pp 16898 109 24X
Fiche 50-322,82/12/30,8301250435

8302030232 Forwards "Accident Source Term Plan," in response to 830112
request for definition for source term to be released to
environ as result of severe accidents
REIS,E J Hearing Branch 3 83/01/14 BRENNER,L , CARPENTER,J L ,
MORRIS,P A Atomic Safety and Licensing Board Panel 17pp
17001 161 24X Fiche 50-322,83/01/14,8302030232

8302040346 Certifies svc of Amend 46 to license application,consisting
of Rev 2B to FSAR, on 830121
GRUNSEICH,R W Long Island Lighting Co 83/01/26 1p 17019 064
24X Fiche 50-322,83/01/26,8302040346

8302020027 Informs that steam condensing mode deleted as operating
mode of RHR for all normal plant operations No design basis
transients or accidents for mitigation require use of
steam condensing mode of RHR sys
SMITH,J L Long Island Lighting Co 83/01/28 DENTON,H R Office
of Nuclear Reactor Regulation, Director 2pp 16994 343 24X
Fiche 50-322,83/01/28,8302020027

8302170482 Board Notification 83-1 forwards BNL draft rept,
"Identification of Seismically Risk-Sensitive Sys &
Components in Nuclear Power Plants - General Methodological
Approach "
EISERHUT,D G Division of Licensing FIN A-3397 83/02/01
PALLADINO,N J , GILINSKY,V , AHEARNE,J F Commissioners 134pp
17203 309 24X Fiche 50-000,83/02/01,8302170482

8302170011 Forwards audit repts on seismic & dynamic qualification of
safety-related equipment Repts also available in PDR
BAOCHI,G Equipment Qualification Branch 83/02/02 NOONAN,V S
Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000,83/02/02,8302170011

- B302170025 Trip rept of B20913-17 visit to facility to review seismic & dynamic qualification methods, procedures & results for safety-related mechanical & electrical equipment & observe field installation of equipment
LEE, A Equipment Qualification Branch 82/12/20 NOONAN, V
Equipment Qualification Branch 66pp 17203 191 24X
Fiche 50-000, 83/02/02, B302170011
- B302170034 Trip rept of B00707-10 visit to facility to review qualification methods, procedures & results for 34 Seismic Category I mechanical & electrical equipment & supporting structures
HOFMAYER, C H Equipment Qualification Branch 80/10/01
ROSTOCZY, Z R Equipment Qualification Branch 20pp 17205 257
24X Fiche 50-000, 83/02/02, B302170011
- B302170060 Trip rept of B01014-17 visit to facility to review qualification methods, procedures & results for Seismic Category I mechanical & electrical equipment & supporting structures
HOFMAYER, C H Equipment Qualification Branch 81/02/04
ROSTOCZY, Z R Equipment Qualification Branch 40pp 17205 277
24X Fiche 50-000, 83/02/02, B302170011
- B103160808 Trip rept of B01117-21 site visit in Ottawa, IL re seismic criteria implementation
CHEM, P Y Equipment Qualification Branch 81/02/25
ROSTOCZY, Z R Equipment Qualification Branch 43pp 17205 329
24X Fiche 50-000, 83/02/02, B302170011
- B104010266 Trip rept of B10316-20 site visit re qualification methods, procedures & results for selected safety-related mechanical & electrical equipment & supporting structures
LEE, A Equipment Qualification Branch 81/05/14 ROSTOCZY, Z R
Equipment Qualification Branch 7pp 17206 006 24X
Fiche 50 000, 83/02/02, B302170011
- B302170104 Forwards repts re 20 equipment items reviewed during B10316-20 site visit
REICH, M Brookhaven National Laboratory 81/06/25 ROSTOCZY, Z
Equipment Qualification Branch 45pp 17206 013 24X
Fiche 50 000, 83/02/02, B302170011
- B302170109 Forwards trip rept of B10406-10 visit to facility re dynamic qualification of equipment Util B10518 ltr did not satisfactorily answer all original open issues Util responses taken into account in encl reviews
REICH, M Brookhaven National Laboratory 81/06/29 ROSTOCZY, Z
Equipment Qualification Branch 54pp 17206 038 24X
Fiche 50-000, 83/02/02, B302170011
- B110190094 Trip rept for B10819-20 site visit to perform second seismic qualification review audit Program adequate Review including Phase III new load requalification will continue until scheduled completion in June 1982
LEE, A Equipment Qualification Branch 81/09/29 ROSTOCZY, Z R
Equipment Qualification Branch 5pp 17206 112 24X
Fiche 50-000, 83/02/02, B302170011
- B302170195 Forwards summary repts of six items audited during B10819-20 site visit
REICH, M Brookhaven National Laboratory 82/01/18 ROSTOCZY, Z
Equipment Qualification Branch 18pp 17206 132 24X
Fiche 50-000, 83/02/02, B302170011
- B302170197 Forwards summary repts for 24 equipment items reviewed during B10727-31 site visit
REICH, M Brookhaven National Laboratory 81/09/14 ROSTOCZY, Z
Equipment Qualification Branch 74pp 17206 143 24X
Fiche 50-000, 83/02/02, B302170011
- B110230003 Trip rept of seismic qualification review team B10602-03 site visit to Moscow, OH re plant seismic & dynamic qualification methods & field installation of equipment to verify equipment modeling used in qualification program
CHANG, T Y Equipment Qualification Branch 81/10/01
ROSTOCZY, Z R Equipment Qualification Branch 60pp 17206 217
24X Fiche 50-000, 83/02/02, B302170011
- B209150350 Trip rept of B20915-18 seismic qualification review team site visit re performance of plant site review for selected safety-related, mechanical & electrical equipment Revision to site visit rept encl W/o encl
ROSTOCZY, Z R Equipment Qualification Branch 82/08/30
MIRAOLIA, F Licensing Branch 3 2pp 17206 277, 24X
Fiche 50 000, 83/02/02, B302170011
- B302170210 Draft "Waterford III Seismic Qualification Review Team Visit Rept"
SINOH, J H, MACEK, R W, RUSSELL, M J EQ&G, Inc EQG-EA-5643 R01
DRFT 82/06/30 CHANG, T Y NRC - No Detailed Affiliation Given
51pp 17206 279 24X Fiche 50-000, 83/02/02, B302170011
- B111170512 Trip rept of B10728-30 site visit to Port Gibson, MS re review of seismic & dynamic qualification methods, procedures & results for selected mechanical & electrical equipment & of field installation to verify equipment modeling
CHANG, T Y Equipment Qualification Branch 81/10/22
ROSTOCZY, Z R Equipment Qualification Branch 57pp 17206 330
24X Fiche 50-000, 83/02/02, B302170011
- B302170218 Trip rept of B10914-18 & B20830-0903 visits to facility to review seismic & dynamic methods & results for safety-related mechanical & electrical equipment & observe field installation of equipment
BAGCHI, G Equipment Qualification Branch 82/12/13 NOONAN, V B
Equipment Qualification Branch 9pp 17207 025 24X
Fiche 50-000, 83/02/02, B302170011
- B302170223 "Waterford III Seismic Qualification Review Team Visit Rept (Second Visit)"
SINOH, J H, MACEK, R W EQ&G, Inc FIN A-6415 82/12/13 NRC -
No Detailed Affiliation Given 43pp 17207 034 24X
Fiche 50-000, 83/02/02, B302170011
- B302170227 "Audit of Pump & Valve Operability Assurance Program at St Lucie Nuclear Station, Unit 2," technical evaluation rept
MILLER, C F, HONNA, G EQ&G, Inc FIN A-6415 EQG-EA-5907
82/08/31 ROSTOCZY, Z R Division of Engineering 16pp
17207 077 24X Fiche 50-000, 83/02/02, B302170011
- B302170231 Trip rept of B20426-30 site visit to review safety-related electric & mechanical equipment
ROSTOCZY, Z R Equipment Qualification Branch 82/09/10
ADENBAM, E G Licensing Branch 4 39pp 17207 093 24X
Fiche 50-000, 83/02/02, B302170011
- B302170235 "Audit of Pump & Valve Operability Assurance Program at Palo Verde Nuclear Station, Unit 1," technical evaluation rept
MILLER, C F, HONNA, G EQ&G, Inc FIN A-6415 EQG-EA-6018
82/10/31 ROSTOCZY, Z R Division of Engineering 17pp
17207 132 24X Fiche 50-000, 83/02/02, B302170011
- B212070376 Forwards evaluation of B20809-13 site audit of safety-related electric & mechanical equipment Specific concerns should be resolved satisfactorily as package instead of providing piece meal submittal
NOONAN, V S Equipment Qualification Branch 82/11/24
YOUNG, L OOD, B J Licensing Branch 1 65pp 17207 195 24X
Fiche 50-000, 83/02/02, B302170011
- B302090364 Responds to B20727 telcon re periodic verification of proper instrument air quality Design of compressed gas sys assures proper instrument air quality & high degree of reliability to all safety-related pneumatic components
SMITH, J L Long Island Lighting Co 83/02/03 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 17070 327 24X
Fiche 50-322, 83/02/03, B302090364
- B302080295 Generic Ltr B3-09 to all operating reactor licensees, applicants for GL & holders of CP for C-E PHRs re review of C-E Quers Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295
- B302080301 Generic Ltr B3-05 to BWR licensees of operating reactors (except LACBWR), applicants for GL & holders of CP re SER of "Emergency Procedures Guidelines, Rev 2," NEDQ-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, B302080301
- B302160277 Advises that util will modify pneumatic pressure decay test to verify leak tight integrity of automatic depressurization sys accumulator sys by establishing test pressure after appropriate valve lineup achieved
SMITH, J L Long Island Lighting Co 83/02/08 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 17170 231 24X
Fiche 50-322, 83/02/08, B302160277
- B302150235 Discusses 16 findings from preliminary independent design review of facility Eleven responses received from util
LANDERS, D F Teledyne Engineering Services 83/02/11 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 17149 275
24X Fiche 50-322, 83/02/11, B302150235
- B302240191 Notification of B30216-17 meetings w/util in King of Prussia, PA to discuss operations QA procedures
WIGGINS, J Region 1, Office of Director 83/02/14 Region 1,
Office of Director. 2pp 17288 241 24X Fiche 50-322, 83/02/14,
B302240191

DOCKETED ITEMS

8302170529 Notification of 830218 meeting w/util in Bethesda, MD to discuss classification of sys. components & structures
CARUSO, R Licensing Branch 2 83/02/15 SCHWENCER, A Licensing Branch 2 4pp 17197 119 24X Fiche 50-322, 83/02/15, 8302170529

830220374 Confirms util understanding that, w/commitments made in 821216 ltr, NRC found util quality programs for operational phase acceptable, in response to 830110 ltr
POLLOCK, M S Long Island Lighting Co 83/02/15 NOVAK, T M Division or Licensing 1p 17232 226 24X Fiche 50-322, 83/02/15, 830220374

8302240023 Notification of 830301 meeting w/util & Teledyne in Bethesda, MD to discuss independent design verification program findings
CARUSO, R Licensing Branch 2 83/02/15 SCHWENCER, A Licensing Branch 2 4pp 17268 357 24X Fiche 50-322, 83/02/15, 8302240023

8302250037 Notification of location change for 830218 meeting w/util in Bethesda, MD to discuss classification of sys. components & structures Agenda encl
CARUSO, R Licensing Branch 2 83/02/15 SCHWENCER, A Licensing Branch 2 4pp 17299 356 24X Fiche 50-322, 83/02/15, 8302250037

8302280006 Forwards revised corporate organizational structure which will be in effect at fuel load Revs to be included in FSAR Rev 29 scheduled for submittal in near future
SMITH, J L Long Island Lighting Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 17291 230 24X Fiche 50-322, 83/02/18, 8302280006

8302290236 Responds to 830106 request for addl info re low pressure coolant injection, core spray & rev to FSAR reflecting unmonitored release points for turbine bldg atmosphere
SMITH, J L Long Island Lighting Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17292-048 24X Fiche 50-322, 83/02/18, 8302290236

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8302030241 Forwards NRC input to SER re compliance w/NUREG-0903 & testimony of JE Kennedy & VS Noonan on environ qualification (Suffolk County Contention 8/Shoreham Opponents Coalition Contention 19 (h)).
REPKA, D A Hearing Branch 3 83/01/17 BRENNER, L, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 25pp 17001-178 24X Fiche 50-322, 83/01/17, 8302030241

8302010542 Forwards monthly status listing of active safety-related equipment at qualification level, including balance of plant & NSSS equipment to assist NRC in review of SER Issue 8 re dynamic qualification
SMITH, J L Long Island Lighting Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 33pp 16983 022 24X Fiche 50-322, 83/01/28, 8302010542

8302100201 Forwards NSSS vendor (GE) comments on plant emergency procedures & util disposition of comments, per 830117 telcon agreement & SER Open Issue I C 7
SMITH, J L Long Island Lighting Co 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 17117 261 24X Fiche 50-322, 83/02/03, 8302100201

830220004 Forwards SER Suppl 3, NUREG-0420 W/o encl
SCHWENCER, A Licensing Branch 2 83/02/03 POLLOCK, M S Long Island Lighting Co 3pp 17233-316 24X Fiche 50-322, 83/02/03, 830220004

8302703012 Forwards addl commitment to SER Open Item 64 re loose parts monitoring sys Feedwater flow will be at least 50% of rated flow when calibr of loose parts monitoring sys sensors completed
SMITH, J L Long Island Lighting Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17291-027 24X Fiche 50-322, 83/02/14, 8302703012

8302270394 Notifies that channel box mgt program reviewed in response to 821007 ltr & SER Section 4 2 3 13 Program in general compliance w/Licensing Review Group II resolution of channel box deflection issue
SMITH, J L Long Island Lighting Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17232-031 24X Fiche 50-322, 83/02/16, 8302270394

8302250342 Forwards responses to 821229 SER Class IE environ qualification open items re util justification for interim operation w/three oversize drawings. Aperture cards are available in PDR
SMITH, J L Long Island Lighting Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17297-285 24X Fiche 50-322, 83/02/18, 8302250342

8302250429 Forwards Mark II hydrodynamic loads confirmatory program pipe mounted equipment evaluation - Phase I Rept presents current qualification levels for all motor operated valves on 30 piping subsystems, in response to supplemental SER
SMITH, J L Long Island Lighting Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17277 039 24X Fiche 50-322, 83/02/18, 8302250429

8302170477 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SHOREHAM NUCLEAR POWER STATION, UNIT NO 1 Docket No 50-322 (Long Island Lighting Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0420 S03 83/02/28 70pp Available at NRC 46 00 17197 309 24X Fiche 50-322, 83/02/28, 8302170477

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302100201 Forwards NSSS vendor (GE) comments on plant emergency procedures & util disposition of comments, per 830117 telcon agreement & SER Open Issue I C 7
SMITH, J L Long Island Lighting Co 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 17117 261 24X Fiche 50-322, 83/02/03, 8302100201

G Adjudicatory correspondence

8302030232 Forwards "Accident Source Term Plan," in response to 830112 request for definition for source term to be released to environ as result of severe accidents
REIS, E J Hearing Branch 3 83/01/14 BRENNER, L, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 17pp 17001 161 24X Fiche 50-322, 83/01/14, 8302030232

8302010079 Advises that NRC does not oppose admission of Suffolk County contention re implementation of Inservice Insp Program consistent w/NRC resolution of Halapatz issue Util working to produce commitment to NRC which would resolve contention
REPKA, D A Hearing Branch 3 83/01/28 BRENNER, L, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp 16974 137 24X Fiche 50-322, 83/01/28, 8302010079

8302020318 Advises that Shoreham Opponents Coalition adopts Suffolk County proposed findings of fact & conclusions of law on nine safety issues Certificate of Svc encl
LATHAM, S B Twomey, Latham & Shea LATHAM, S B Shoreham Opponents Coalition 83/01/28 BRENNER, L, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 16993-283 24X Fiche 50-322, 83/01/28, 8302020318

8302070325 Forwards particularization of concerns re consideration of aging in util Environ Qualification Program
LETSCHKE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHKE, K J Suffolk County, NY 83/01/28 REPKA, D A Hearing Branch 3 IRWIN, D P Hunton & Williams IRWIN, D P Long Island Lighting Co 6pp 16974 001 24X Fiche 50-322, 83/01/28, 8302070325

8302070501 Requests deferral of ASLB ruling on admissibility of Halapatz contention for at least 1 wk to permit possible final resolution of issue Util commitment re insp encl Certificate of Svc encl
IRWIN, D P Long Island Lighting Co IRWIN, D P, Hunton & Williams 83/01/28 6pp 17036-341 24X Fiche 50-322, 83/01/28, 8302070501

8302070495 Confirmation of 830224 conference of counsel in Hauppauge, NY re litigation of Phase II offsite emergency planning matters Specific topics to be reviewed listed
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/03 3pp 17036 313 24X Fiche 50-322, 83/02/03, 8302070495

8302070152 Advises that Shoreham Opponents Coalition adoption of Suffolk County proposed findings of fact & conclusions of law on nine safety issues would not support Shoreham taking exception to any ASLB initial decision
BORDENICK, B M Hearing Branch 3 83/02/04 BRENNER, L, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp 17032 339 24X Fiche 50-322, 83/02/04, 8302070152

8302080230 Responds to 830203 telcon re IE Insp Rept 50-322/83-02 & Suffolk County cross-examination plan & objects to ASLB decision requiring disclosure of documents & page refs
MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips MILLER, M S Suffolk County, NY 83/02/04 BRENNER, L, MORRIS, P A, CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp 17097 207 24X Fiche 50-322, 83/02/04, 8302080230

DOCKETED ITEMS

17

8302100258 Forwards JH Conran affidavit re testimony on Contention 7B
Testimony being provided prior to NRC counsel review
RAUSON, R J Hearing Branch 4 83/02/08 BRENNER, L, MORRIS, P A,
CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp
17110 131 24X Fiche 50-322, 83/02/08, 8302100258

--8302100262 Affidavit of JH Conran re changes to earlier testimony on
Contention 7B & changes in facts or circumstances
Substantive defect exists in util understanding of min
requirements to protect public health & safety
CQIRAN, J H Reliability & Risk Assessment Branch 83/02/09
33pp 17110 133 24X Fiche 50-322, 83/02/08, 8302100258

8302140149 Forwards resolution on Suffolk County Contention 32/
Shoreham Opponents Coalition Contention 19(F) re OE Series
100 & 200 electrical penetrations
LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips
LETSCHE, K J Suffolk County, NY 83/02/08 BRENNER, L,
CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel
1p 17140 155 24X Fiche 50-322, 83/02/08, 8302140149

--8302140152 Resolution on Suffolk County Contention 32/Shoreham
Opponents Coalition Contention 19(F) re OE Series 100 & 200
electrical penetrations
REPKA, D A Hearing Branch 3 IRWIN, D P Long Island Lighting Co
LETSCHE, K J Suffolk County, NY 83/02/01 6pp 17140 156
24X Fiche 50-322, 83/02/08, 8302140149

8302160369 Confirms EQ Greenman & JC Higgins as witnesses for 830222-23
readiness assessment team insp hearing
BORDENICK, B M Hearing Branch 3 83/02/10 BRENNER, L,
CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel
2pp 17164 144 24X Fiche 50-322, 83/02/10, 8302160369

8302160375 Cites areas of objection to proposed background section
(App A) of util proposed findings
LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips.
LANPHER, L C Suffolk County, NY 83/02/10 BRENNER, L,
CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel
2pp 17164 171 24X Fiche 50-322, 83/02/10, 8302160375

8302160358 Confirmatory memorandum & order confirming ASLB oral 830209
order directing parties to file statement of views on effect
upon proceeding of NRC witness JH Conran 830208 affidavit on
Suffolk County/Shoreham Opponents Coalition Contention 7B
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/11
Office of the Executive Legal Director 3pp 17169 198 24X
Fiche 50-322, 83/02/11, 8302160358

8302170092 Forwards NRC comments on applicant background of proceedings
statement & proposed opinion & findings of fact &
conclusions of law in form of partial initial decision
RAUSON, R J Hearing Branch 4 83/02/11 BRENNER, L, MORRIS, P A,
CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp
17182 001 24X Fiche 50-322, 83/02/11, 8302170092

--8302170097 Comments on util background of proceedings statement in util
proposed findings of fact
BORDENICK, B M Hearing Branch 3 83/02/11 37pp 17182 003
24X Fiche 50-322, 83/02/11, 8302170092

--8302170097 Proposed opinion on findings of fact & conclusions of law
in form of partial initial decision, Vol 1 & 2 Certificate of
Svc encl
REPKA, D A Hearing Branch 3 RAUSON, R J Hearing Branch 4
83/02/11 275pp 17182 040 24X Fiche 50-322, 83/02/11,
8302170092

8302170263 Confirmation of 830214 telcon w/NRC & ASLB re filing
schedules ASLB agreed to extension of time for util to file
reply to NRC proposed findings of fact due to late svc of
NRC filing Certificate of Svc encl
EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton &
Williams 83/02/14 4pp 17187 088 24X Fiche 50-322, 83/02/14,
8302170263

8302240009 Statement of views on JH Conran changes to earlier
testimony, in response to ASLB 830211 order Conran affidavit
should be received into evidence as amend to previous
testimony Certificate of Svc encl
RAUSON, R J Hearing Branch 4 83/02/22 19pp 17272.336 24X
Fiche 50-322, 83/02/22, 8302240009

8302240300 Submission re JH Conran affidavit & request to reopen
record ASLB should not rely on prior record that is no
longer accurate Conran changes of opinion are extremely
significant Certificate of Svc encl
LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick,
Lockhart, Hill, Christopher & Phillips 83/02/22 46pp 17273 298,
24X Fiche 50-322, 83/02/22, 8302240300

8302280247 Stipulation re Halapatz concern on potential sensitization
of reactor internal components/intergranular stress
corrosion cracking Util agrees to include procedures for
cracking detection
REPKA, D A Hearing Branch 3 IRWIN, D P Long Island Lighting Co.
LANPHER, L C Suffolk County, NY 83/02/22 8pp 17304 314 24X
Fiche 50-322, 83/02/22, 8302280247

--8302280254 Stipulation re Suffolk County Contention 23 on containment
isolation Tech Specs will be revised so that 6-inch & 4-inch
purge/vent valves will be used to conduct vacuum breaker
position testing w/inoperable position indicator
REPKA, D A Hearing Branch 3 IRWIN, D P Long Island Lighting Co
LANPHER, L C Suffolk County, NY 83/02/22 19pp 17304 322
24X Fiche 50-322, 83/02/22, 8302280247

--8302280260 Stipulation re Suffolk County Contention 32/Shoreham
Opponents Coalition Contention 19(F) re electrical
penetrations Util commits to maintain electrical
penetrations at nitrogen pressure of 25 psig
REPKA, D A Hearing Branch 3 IRWIN, D P Long Island Lighting Co
LETSCHE, K Suffolk County, NY 83/02/01 6pp 17304 337 24X
Fiche 50-322, 83/02/22, 8302280247

8302240313 Advises that Suffolk County resolved not to adopt or
implement radiological emergency plan County decided no plan
could protect public if accident occurred Plant cannot be
operated safely
COHALAN, P F Suffolk County, NY. 83/02/23 PALLADINO, N J,
GILINSKY, V, AHEARNE, J Commissioners 2pp 17271 332 24X
Fiche 50-322, 83/02/23, 8302240313

--8302240318 Motion to certify Suffolk County motion to terminate OL
proceeding, to Commission County decision not to adopt local
radiological emergency response time makes issue urgent
BROWN, H Suffolk County, NY BROWN, H Kirkpatrick, Lockhart,
Hill, Christopher & Phillips, 83/02/23 Atomic Safety and
Licensing Board Panel 3pp 17271 334 24X Fiche 50-322,
83/02/23, 8302240313

--8302240321 Motion to terminate OL proceeding Necessary emergency
preparedness to respond to nuclear accident does not & will
not exist Effective offsite emergency preparedness is
prerequisite to OL issuance
BROWN, H Suffolk County, NY BROWN, H Kirkpatrick, Lockhart,
Hill, Christopher & Phillips 83/02/23 Atomic Safety and
Licensing Board Panel 3pp 17271 337 24X
Fiche 50-322, 83/02/23, 8302240313

8302280273 Notice of intent to participate as interested municipality
per 10CFR2 715(c). Notices of appearance & Certificate of Svc
encl
LATHAM, S B Southampton, NY LATHAM, S B Twomey, Latham & Shea
83/02/23 Atomic Safety and Licensing Board Panel 6pp
17311 314 24X Fiche 50-322, 83/02/23, 8302280273

8302250264 Addresses Suffolk County 830223 ltr re OL hearings. Ltr
should be stricken from records No action should be taken
on emergency planning issue until conclusion reached re
motion to terminate licensing proceeding
REVELEY, W T Hunton & Williams REVELEY, W T Long Island Lighting
Co 83/02/24 PALLADINO, N J, GILINSKY, V, AHEARNE, J F
Commissioners 1p 17292 124 24X Fiche 50-322, 83/02/24,
8302250264

K Utility Final Safety Analysis Report (FSAR) & amends

8301250435 Application for Amend 46 to OL application, consisting of
Rev 28 to FSAR Affidavit encl.
SMITH, J L Long Island Lighting Co 82/12/30 DENTON, H R. Office
of Nuclear Reactor Regulation, Director 3pp 16898 109 24X
Fiche 50-322, 82/12/30, 8301250435

--8301250438 Rev 28 to FSAR Amend 46
4 Long Island Lighting Co 82/12/31 300pp 16898:112 24X
Fiche 50-322, 82/12/30, 8301250435

8302040346 Certifies svc of Amend 46 to license application, consisting
of Rev 28 to FSAR, on 830121
GRUNSEICH, R W Long Island Lighting Co 83/01/26 1p 17019:064
24X Fiche 50-322, 83/01/26, 8302040346

Q Inspection Reports, IE Bulletins & correspondence

8302030191 Forwards IE Insp Rept 50-322/83-02 on 830110-15 & notice of
violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/20.
POLLOCK, M S Long Island Lighting Co 3pp 17002:042 24X
Fiche 50-322, 83/01/20, 8302030191

DOCKETED ITEMS

--8302030194 Notice of violation from insp on 830110-15
 * Division of Project & Resident Programs 83/01/20 3pp
 17002 045 24X Fiche 50-322, 83/01/20, 8302030191.

--8302030197 IE Insp Rept 50-322/83-02 on 830110-15 Noncompliance noted
 failure to provide adequate verification of completed const
 in areas of control rod drive piping supports, pipe hangers
 & cable tray supports
 BATEMAN, W., CERNE, A., CONGILL, C. Division of Project & Resident
 Programs 83/01/19 40pp 17002 048 24X Fiche 50-322, 83/01/20,
 8302030191

8302010317 Forwards IE Insp Rept 50-322/82-33 on 821115-19 No
 noncompliance noted
 MARTIN, T. T. Division of Engineering & Technical Programs 83/01/24
 POLLACK, M. S. Long Island Lighting Co. 3pp 16973 023 24X
 Fiche 50-322, 83/01/24, 8302010317

--8302010322 IE Insp Rept 50-322/82-33 on 821115-19. No noncompliance
 noted. Major areas inspected: radiation protection & radwaste
 mgmt programs, IE Circular 81-07, organization & staffing,
 personnel selection & radiation worker training.
 NIMITZ, R. L., MCBRIDE, M. H., JANG, J. C. Region 1, Office of Director
 83/01/19 25pp 16973 026 24X Fiche 50-322, 83/01/24,
 8302010317

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
 York, Inc. 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
 Gearheads." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
 York, Inc. 109pp 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments."
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
 York, Inc. 110pp. 17074 095. 24X Fiche 50-000, 83/01/28, 8212060361

8302170125 Forwards request for addl info re containment line piping
 penetration odds, in support of applicant 800710 response to
 IE Bulletin 80-08. Response requested within 30 days.
 SCHWENGER, A. Licensing Branch 2 83/02/07 POLLACK, M. S. Long
 Island Lighting Co. 4pp 17191 115 24X Fiche 50-322, 83/02/07,
 8302170125.

8302180165 Forwards IE Insp Rept 50-322/83-01 on 830101-31. No
 noncompliance noted
 STAROSTECKI, R. Division of Project & Resident Programs 83/02/08
 POLLACK, M. S. Long Island Lighting Co. 2pp 17216 108 24X
 Fiche: 50-322, 83/02/08, 8302180165

--8302180171 IE Insp Rept 50-322/83-01 on 830101-31 No noncompliance
 noted. Major areas inspected: work activities, preoperational
 testing & plant staff activities, including tours, review of
 NRC circulars, vendor manuals & housekeeping
 HIGGINS, J. C., PETRONE, C. D., MCCABE, E. C. Division of Project &
 Resident Programs 83/02/07 8pp 17216 110 24X
 Fiche 50-322, 83/02/08, 8302180165

12060363 IE Info Notice 83-04, "Failure of Elms Power Supply Units."
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
 York, Inc. 110pp. 17347 191. 24X Fiche 50-000, 83/02/18, 8212060363

102280493 Ack receipt of 821201 ltr informing NRC of steps taken to
 correct violations noted in IE Insp Rept 50-322/82-26
 Engineering & design change repts older than 1 month should
 be incorporated into respective drawings
 STAROSTECKI, R. Division of Project & Resident Programs. 83/02/23
 POLLACK, M. S. Long Island Lighting Co. 2pp 17309:111 24X
 Fiche 50-322, 83/02/23, 8302280493

8302280501 Responds to NRC 821029 ltr re violations noted in IE Insp
 Rept 50-322/82-26 Corrective actions, samples of drawings
 reviewed. Discrepancies isolated. Cases. Drawings updated
 according to applicable procedures
 POLLACK, M. S. Long Island Lighting Co. 82/12/01. STAROSTECKI, R.
 Division of Project & Resident Programs 4pp 17309:113. 24X
 Fiche 50-322, 83/02/23, 8302280493

212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
 Very Low Level Radwaste - 10CFR20.302." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
 York, Inc. 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts."
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
 York, Inc. 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low
 voltage circuit breakers w/solid state trip devices Units
 from San Onofre 2 & 3 failed due to long-term degradation of
 filter capacitor C205 Suspect trip units should be tested
 DUVALL, D. D. Brown Boveri Corp (subs Brown Boveri & Co., Ltd.)
 82/12/10 STELLO, V. Director's Office, Office of Inspection and
 Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302010359 Interim deficiency rept re mineral insulated cable provided
 by Kanan Instrumentation for use w/high-range drywell area
 radiation monitors Initially reported on 821208 Specs
 revised Also reported per Part 21
 MILLIGAN, M. H. Long Island Lighting Co. 83/01/14 GRIER, B. H.
 Region 1, Office of Director 3pp 16973 328 24X
 Fiche 50-322, 83/01/14, 8302010359

8302100427 Interim deficiency rept re configuration of impulse tubing
 allowing for potential undrainable condensate accumulation
 Caused by downward slope of primary containment instrument
 line Tubing containment & sensing lines modified
 MILLIGAN, M. H. Long Island Lighting Co. 83/01/28 HAYNES, R. C.
 Region 1, Office of Director 2pp 17117 258 24X
 Fiche 50-322, 83/01/28, 8302100427

8302180202 Interim deficiency rept re telephone relays to protective
 relays mfg by GE Initially reported on 820407 Contact button
 separated from contact arm Visual insp of all Class IE date
 code & nendate code relays will be performed each month
 MILLIGAN, M. H. Long Island Lighting Co. 83/02/07 HAYNES, R. C.
 Region 1, Office of Director 2pp 17215 360 24X
 Fiche 50-322, 83/02/07, 8302180202

8302230200 Followup rept re deficient HMA type relays mfg by GE
 Initially reported on 821207 Survey of HMA relays mfg prior
 to & during 1974 conducted Relays will be replaced Survey &
 replacement will be completed by 830331
 MILLIGAN, M. H. Long Island Lighting Co. 83/02/07 HAYNES, R. C.
 Region 1, Office of Director 2pp 17245 115 24X
 Fiche 50-322, 83/02/07, 8302230200

T Hearing transcripts on non-antitrust matters

8301200107 Transcript of 830117 hearing in Hauppauge, NY
 Pp 18, 130-18, 300 Supporting documentation encl
 * Atomic Safety and Licensing Board Panel 83/01/17 238pp
 16863 250 24X Fiche 50-322, 83/01/17, 8301200107

8302030241 Forwards NRC input to SER re compliance w/NUREG-0803 &
 testimony of JE Kennedy & VS Noonan on environ qualification
 (Buffolk County Contention 8/Shoreham Opponents Coalition
 Contention 19 (h))
 REPAK, D. A. Hearing Branch 3 83/01/17 BRENNER, L., MORRIS, P. A.,
 CARPENTER, J. L. Atomic Safety and Licensing Board Panel 25pp
 17001 178 24X Fiche 50-322, 83/01/17, 8302030241

--8302030247 Testimony of JE Kennedy & VS Noonan re environ qualification
 (Buffolk County Contention 8/Shoreham Opponents Coalition
 Contention 19 (h))
 KENNEDY, J. E., NOONAN, V. S. Equipment Qualification Branch
 83/01/17 45pp 17001 203 24X Fiche 50-322, 83/01/17, 8302030241

8302020045 Transcript of 830131 OL hearing in Hauppauge, NY Pp 19, 542-
 19, 713 Supporting documentation encl
 * Atomic Safety and Licensing Board Panel 83/01/31 201pp.
 16991 098 24X Fiche 50-322, 83/01/31, 8302020045

8302030076 Transcript of 830201 OL hearing in Hauppauge, NY Pp 19, 714-
 19, 733
 * Atomic Safety and Licensing Board Panel 83/02/01 19pp
 17004 303 24X Fiche 50-322, 83/02/01, 8302030076

8302230435 Forwards corrected P 8 of RAT testimony filed on 830215
 EARLEY, A. F. Hunton & Williams EARLEY, A. F. Long Island Lighting
 Co. 83/02/17 BRENNER, L. Atomic Safety and Licensing Board Panel
 1p 17246 107 24X Fiche 50-322, 83/02/17, 8302230435

--8302230450 Corrected P 8 of RAT testimony filed on 830215
 * Long Island Lighting Co. 83/02/17 1p 17246 108 24X
 Fiche 50-322, 83/02/17, 8302230435

DOCKETED ITEMS

8302230936 Supplemental testimony of WJ Museler, TT Arrington & J Kelly re violations propounded in IE Insp Rept 50-322/83-02 Certificate of Svc encl Related correspondence
MUSELER, W J, ARRINGTON, T T, KELLY, J Long Island Lighting Co
83/02/22 Atomic Safety and Licensing Board Panel. 31pp
17296 313 24X Fiche 50-322, 83/02/22, 8302230936

8302240018 Transcript of 830222 hearing in Hauppauge, NY Pp 19, 734-19, 950
* Atomic Safety and Licensing Board Panel 83/02/22 257pp
17272 001 24X Fiche 50-322, 83/02/22, 8302240018

8302250377 Transcript of 830223 hearing in Hauppauge, NY Pp 19, 931-20, 230 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/23 295pp
17297 289 24X Fiche 50-322, 83/02/23, 8302250377

8302280096 Transcript of 830224 hearing in Hauppauge, NY Pp 20, 231-20, 344
* Atomic Safety and Licensing Board Panel 83/02/24 116pp
17307 204 24X Fiche 50-322, 83/02/24, 8302280096

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS/MSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co or New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302090152 Documents info presented at 830113 independent design verification program meeting info replaces 821223 "Phase II Addl Sample & Addl Verification" draft interim technical rept, u/listed exceptions
COOPER, W E Teledyne Engineering Services 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 3pp 17070 273 24X Fiche 50-275, 83/01/18, 8302090152

8302090182 Discusses independent design verification program civil/structural efforts Instruments Test Rig-6 published for historical purposes Engineers committed to perform RL Cloud review listed
COOPER, W E Teledyne Engineering Services DENISON, E T Robert L Cloud Associates, Inc 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 3pp 17070 259 24X Fiche 50-275, 83/01/18, 8302090182

8302010431 Forwards "Wave Effects on Intake Structure" & "Investigation of Seawater Ingestion into Auxiliary Saltwater Pump Room Due to Splash Runup During Design Flood Events at Diablo Canyon"
CRANE, P A Pacific Gas & Electric Co 83/01/19 KNIGHTON, G W Licensing Branch 3 2pp 16974 196 24X Fiche 50-275, 83/01/19, 8302010431

--8302010432 "Wave Effects on Intake Structure at Diablo Canyon, Units 1 & 2"
MATSUDA, E N Pacific Gas & Electric Co 83/01/31 16pp
16974 198 24X Fiche 50-275, 83/01/19, 8302010431

--8302010433 "Investigation of Seawater Ingestion into Auxiliary Saltwater Pump Room Due to Splash Runup During Design Flood Events at Diablo Canyon"
RYAN, P J Pacific Gas & Electric Co 83/01/31 26pp 16974:214
24X Fiche 50-275, 83/01/19, 8302010431

8302090306 Notifies that first independent design verification program design of verification conducted on 821220 & second proposed for 830203 Initial plans provide for verifying min of two areas per wk Meeting announcements encl
REEDY, R F Reedy, Herbert, Gibbons & Associates 83/01/25 FRAY, R Bechtel Corp 3pp 17069 342 24X Fiche 50-275, 83/01/25, 8302090306

8302100094 Accepts Revs 1 & 2 to QA program submitted in response to NRC request for addl info & clarification
EISENHUT, D G Division of Licensing 83/01/26 CRANE, P A Pacific Gas & Electric Co 5pp 17135 041 24X Fiche 50-275, 83/01/26, 8302100094

8302090311 Forwards definitive schedule for 830204 independent design verification program design of verification Verification will be limited to control of spectra within intake structure & auxiliary bldg
REEDY, R F Reedy, Herbert, Gibbons & Associates 83/01/31 FRAY, Pacific Gas & Electric Co 2pp 17071 014 24X
Fiche 50-275, 83/01/31, 8302090311

8302090165 Informs that CF Bergeron approved a replacement for JH O as S&W lead nuclear technology engineer Personnel change affects 3 2 & Figure 3-1 of Phase II program mgmt plan CF Bergeron resumes encl
CRAIGIN, J G Teledyne Engineering Services 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 7pp 17070 262 24X Fiche 50-275, 83/02/03, 8302090165

8302140078 Forwards Interim Technical Rept 34, Rev 0, "Verification of Diablo Canyon Project Efforts"
KRECHTIN, J E Stone & Webster Engineering Corp 83/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, O A Pacific Gas & Electric Co 1p 17141 047 24X Fiche 50-275, 83/02/07, 8302140078

--8302140053 Interim Technical Rept 34, Rev 0, "Verification of Diablo Canyon Project Efforts"
SESTAK, F, STRATOU, D C Stone & Webster Engineering Corp 83/02/04 42pp 17141 048 24X Fiche 50-275, 83/02/07, 8302140053

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co or New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Hestinghouse design NSSR re resolution of TMI Action Item II K 3 3, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D G Division of Licensing, 83/02/08 Baltimore Gas & Electric Co 30pp 17270 212 24X Fiche 50-000, 83/02/08, 8302090080

8302180252 Notifies of 830223 & 24 meetings w/S&W in Boston, MA to discuss Phase II addl verification & EOI
COOPER, W E, CRAIGIN, J G Teledyne Engineering Services 83/02/18 NRC - No Detailed Affiliation Given 1p 17215 275 24X
Fiche 50-275, 83/02/18, 8302180252

8302240280 Requests info from B&W analysis of containment annulus structure re vertical response spectra for Model D & horizontal annulus model info required for design verification program
COOPER, W E, MYROLOT, C E Teledyne Engineering Services 83/02/1 SCHIERLING, H E Office of Nuclear Reactor Regulation, Director 17274 072 24X Fiche 50-275, 83/02/18, 8302240280

8302220368 Agenda for 830224 & 25 meetings in San Francisco, CA to discuss structural review
COOPER, W E, CRAIGIN, J G Teledyne Engineering Services 83/02/2 Teledyne Engineering Services 1p 17232 067 24X
Fiche 50-275, 83/02/24, 8302220368

F Security, medical, emergency & fire protection plans

8210150452 Forwards reviews of procedures proposed by utility in emergency plans to consider meteorological conditions at facilities, in response to Task Order 1 of interagency agreement
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 SPICKLER, I Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X
Fiche 50-000, 82/10/08, 8210150452

--8301270050 "Evaluation of Procedures Proposed by PGE in Emergency Plans to Consider Meteorological Conditions in Diablo Canyon Plant Coastal Environ"
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 314 24X
Fiche 50 000, 82/10/08, 8210150452

8302030603 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/28 Management Branch 1p 17013 096 24X Fiche 50-275, 83/01/28, 8302030603

DOCKETED ITEMS

- B302030194 Notice of violation from insp on B30110-15
* Division of Project & Resident Programs 83/01/20 3pp
17002 048 24X Fiche 50-322, 83/01/20, B302030191
- B302030197 IE Insp Rept 50-322/83-02 on B30110-15 Noncompliance noted
failure to provide adequate verification of completed const
in areas of control rod drive piping supports, pipe hangers
& cable tray supports
BATEMAN, M., CERNE, A., COWHILL, C. Division of Project & Resident
Programs 83/01/19 40pp. 17002 048 24X Fiche 50-322, 83/01/20,
B302030191
- B302010317 Forwards IE Insp Rept 50-322/82-33 on B21115-19 No
noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs. 83/01/24
POLLOCK, M. S. Long Island Lighting Co 3pp 16973 023 24X
Fiche 50-322, 83/01/24, B302010317
- B302010322 IE Insp Rept 50-322/82-33 on B21115-19 No noncompliance
noted Major areas inspected radiation protection & radwaste
mgmt programs, IE Circular 81-07, organization & staffing,
personnel selection & radiation worker training
NIMITZ, R. L., MCBRIDE, M. H., JAMHO, J. C. Region 1, Office of Director
83/01/19 25pp. 16973 026 24X Fiche 50-322, 83/01/24,
B302010317.
- B212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358
- B212060360 IE Info Notice 83-02, "Limiterque H08C, H18C, H28C & H38C
Gearheads" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360
- B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361
- B302170125 Forwards request for addl info re containment line piping
penetration odds, in support of applicant B00710 response to
IE Bulletin 80-08 Response requested within 30 days
SCHWENGER, A. Licensing Branch 2 83/02/07 POLLOCK, M. S. Long
Island Lighting Co 4pp 17191 115. 24X Fiche 50-322, 83/02/07,
B302170125
- B302180165 Forwards IE Insp Rept 50-322/83-01 on B30101-31 No
noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/02/08
POLLOCK, M. S. Long Island Lighting Co 2pp 17216 108 24X
Fiche 50-322, 83/02/08, B302180165
- B302180171 IE Insp Rept 50-322/83-01 on B30101-31 No noncompliance
noted Major areas inspected work activities, preoperational
testing & plant staff activities, including tours, review of
NRC circulars, vendor manuals & housekeeping
HIDOLINS, J. C., PETRONE, C. D., MCCABE, E. C. Division of Project &
Resident Programs 83/02/07 8pp 17216 110 24X
Fiche 50-322, 83/02/08, B302180165
- B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363.
- B302280493 Ack receipt of B21201 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-322/82-26
Engineering & design change repts older than 1 month should
be incorporated into respective drawings
STAROSTECKI, R. Division of Project & Resident Programs 83/02/23
POLLOCK, M. S. Long Island Lighting Co 2pp. 17309 111 24X
Fiche 50-322, 83/02/23, B302280493
- B302280501 Responds to NRC B21029 ltr re violations noted in IE Insp
Rept 50-322/82-26 Corrective actions samples of drawings
reviewed Discrepancies isolated cases Drawings updated
according to applicable procedures.
POLLOCK, M. S. Long Island Lighting Co 82/12/01 STAROSTECKI, R.
Division of Project & Resident Programs. 4pp. 17309 113 24X
Fiche 50-322, 83/02/23, B302280493
- B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co. of New
York, Inc. 111pp 17347 098 24X Fiche 50-000, 83/02/24, B212060365
- B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366
- S Reportable occurrences, LERs & related correspondence
- B212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low
voltage circuit breakers w/solid state trip devices Units
from San Onofre 2 & 3 failed due to long-term degradation of
filter capacitor C205 Suspect trip units should be tested
DUVALL, D. D. Brown Boveri Corp (subs Brown Boveri & Co., Ltd.)
82/12/10 STELLD, V. Director's Office, Office of Inspection and
Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, B212140330
- B302010359 Interim deficiency rept re mineral insulated cable provided
by Kaman Instrumentation for use w/high-range drywell area
radiation monitors Initially reported on B21208 Specs
revised Also reported per Part 21
MILLIGAN, M. H. Long Island Lighting Co 83/01/14 GRIER, D. H.
Region 1, Office of Director 3pp 16973 328 24X
Fiche 50-322, 83/01/14, B302010359
- B302100427 Interim deficiency rept re configuration of impulse tubing
allowing for potential undrainable condensate accumulation
Caused by downward slope of primary containment instrument
line Tubing containment & sensing lines modified
MILLIGAN, M. H. Long Island Lighting Co 83/01/28 HAYNES, R. C.
Region 1, Office of Director 2pp 17117 258 24X
Fiche 50-322, 83/01/28, B302100427
- B302180202 Interim deficiency rept re telephone relays to protective
relays mfg by GE Initially reported on B20407 Contact button
separated from contact arm Visual insp of all Class IE date
code & nondate code relays will be performed each month
MILLIGAN, M. H. Long Island Lighting Co 83/02/07 HAYNES, R. C.
Region 1, Office of Director 2pp 17215 360 24X
Fiche 50-322, 83/02/07, B302180202
- B302230200 Followup rept re deficient HMA type relays mfg by GE
Initially reported on B21207 Survey of HMA relays mfg prior
to & during 1974 conducted Relays will be replaced Survey &
replacement will be completed by B30531
MILLIGAN, M. H. Long Island Lighting Co 83/02/07 HAYNES, R. C.
Region 1, Office of Director 2pp 17245 115 24X
Fiche 50-322, 83/02/07, B302230200
- T Hearing transcripts on non-antitrust matters
- B301200107 Transcript of B30117 hearing in Hauppauge, NY
Pp 18, 130-18, 300 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/01/17 238pp
16863 250 24X Fiche 50-322, 83/01/17, B301200107
- B302030241 Forwards NRC input to SER re compliance w/NURCO-0803 &
testimony of JE Kennedy & VS Noonan on environ qualification
(Suffolk County Contention 8/Shoreham Opponents Coalition
Contention 19 (h))
REPKA, D. A. Hearing Branch 3 83/01/17 BRENNER, L., MORRIS, P. A.,
CARPENTER, J. L. Atomic Safety and Licensing Board Panel 29pp
17001 178 24X Fiche 50-322, 83/01/17, B302030241
- B307030247 Testimony of JE Kennedy & VS Noonan re environ qualification
(Suffolk County Contention 8/Shoreham Opponents Coalition
Contention 19 (h))
KENNEDY, J. E., NOONAN, V. S. Equipment Qualification Branch
83/01/17 45pp 17001 203 24X Fiche 50-322, 83/01/17, B302030241
- B302020045 Transcript of B30131 DL hearing in Hauppauge, NY Pp 19, 542--
19, 713 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/01/31 201pp.
16991 098 24X Fiche 50-322, 83/01/31, B302020045
- B302030076 Transcript of B30201 DL hearing in Hauppauge, NY Pp 19, 714--
19, 733
* Atomic Safety and Licensing Board Panel 83/02/01 19pp
17004 303 24X Fiche 50-322, 83/02/01, B302030076
- B302230435 Forwards corrected P B of RAT testimony filed on B30215
EARLEY, A. F. Hutton & Williams EARLEY, A. F. Long Island Lighting
Co 83/02/17 BRENNER, L. Atomic Safety and Licensing Board Panel
1p 17245 107 24X Fiche 50-322, 83/02/17, B302230435
- B302230450 Corrected P B of RAT testimony filed on B30215
* Long Island Lighting Co 83/02/17 1p 17246 108 24X
Fiche 50-322, 83/02/17, B302230450

DOCKETED ITEMS

18

8302230336 Supplemental testimony of WJ Museler, TT Arrington & J Kelly re violations propounded in IE Insp Rept 50-322/83-02 Certificate of Svc encl Related correspondence
MUSELER, W J, ARRINGTON, T T, KELLY, J Long Island Lighting Co
83/02/22 Atomic Safety and Licensing Board Panel 31pp
17256 313 24X Fiche 50-322, 83/02/22, 8302230336

8302240018 Transcript of 830222 hearing in Hauppauge, NY Pp 19, 734-19, 950
* Atomic Safety and Licensing Board Panel 83/02/22 257pp
17272 001 24X Fiche 50-322, 83/02/22, 8302240018

8302250377 Transcript of 830223 hearing in Hauppauge, NY Pp 19, 951-20, 230 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/02/23 295pp
17297 289 24X Fiche 50-322, 83/02/23, 8302250377

8302280096 Transcript of 830224 hearing in Hauppauge, NY Pp 20, 231-20, 344
* Atomic Safety and Licensing Board Panel 83/02/24 116pp
17307 204 24X Fiche 50-322, 83/02/24, 8302280096

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKCT 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302090152 Documents info presented at 830113 independent design verification program meeting info replaces 821223 "Phase II Addl Sample & Addl Verification" draft interim technical rept. L/ listed exceptions
COOPER, W E Teledyne Engineering Services 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, Q A Pacific Gas & Electric Co 3pp 17070 273 24X Fiche 50-275, 83/01/18, 8302090152

8302090182 Discusses independent design verification program civil/ structural efforts Instruments Test Rig-6 published for historical purposes Engineers committed to perform RL Cloud review listed
COOPER, W E Teledyne Engineering Services DENISON, E T Robert L Cloud Associates, Inc 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, Q A Pacific Gas & Electric Co 3pp 17070 259 24X Fiche 50-275, 83/01/18, 8302090182

8302010431 Forwards "Wave Effects on Intake Structure" & "Investigation of Seawater Ingestion Into Auxiliary Saltwater Pump Room Due to Splash Runup During Design Flood Events at Diablo Canyon"
CRANE, P A Pacific Gas & Electric Co 83/01/19 KNIGHTON, Q W Licensing Branch 3 2pp 16974 196 24X Fiche 50-275, 83/01/19, 8302010431

--8302010432 'Wave Effects on Intake Structure at Diablo Canyon, Units 1 & 2'
MATSUDA, E N Pacific Gas & Electric Co 83/01/31 16pp
16974 198 24X Fiche 50-275, 83/01/19, 8302010431

--8302010433 'Investigation of Seawater Ingestion Into Auxiliary Saltwater Pump Room Due to Splash Runup During Design Flood Events at Diablo Canyon'
RYAN, P J Pacific Gas & Electric Co 83/01/31 26pp 16974 214 24X Fiche 50-275, 83/01/19, 8302010431

8302090306 Notifies that first independent design verification program design ofc verification conducted on 821220 & second proposed for 830203 Initial plans provide for verifying min of two areas per wk Meeting announcements encl
REEDY, R F Reedy, Herbert, Gibbons & Associates 83/01/25 FRAY, R Bechtel Corp 3pp 17069 342 24X Fiche 50-275, 83/01/25, 8302090306

8302100094 Accepts Revs 1 & 2 to QA program submitted in response to NRC request for addl info & clarification
EISENHUT, D G Division of Licensing 83/01/26, CRANE, P A Pacific Gas & Electric Co 5pp 17133 041 24X Fiche 50-275, 83/01/26, 8302100094

8302090311 Forwards definitive schedule for 830204 independent design verification program design ofc verification Verification will be limited to control of spectra within intake structure & auxiliary bldg
REEDY, R F Reedy, Herbert, Gibbons & Associates 83/01/31, FRAY, R Pacific Gas & Electric Co 2pp 17071 014, 24X
Fiche 50-275, 83/01/31, 8302090311

8302090165 Informs that CF Bergeron approved as replacement for JM Oddo as SN lead nuclear technology engineer Personnel change affects 3 2 & Figure 3-1 of Phase II program mgt plan CF Bergeron resume encl
CRAIGIN, J Q Teledyne Engineering Services 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, Q A Pacific Gas & Electric Co 7pp 17070 262 24X Fiche 50-275, 83/02/03, 8302090165

8302140078 Forwards Interim Technical Rept 34, Rev O, "Verification of Diablo Canyon Project Efforts"
KRECHTING, J E Stone & Webster Engineering Corp 83/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director MANEATIS, Q A Pacific Gas & Electric Co 1p 17141 047 24X Fiche 50-275, 83/02/07, 8302140078

--8302140053 Interim Technical Rept 34, Rev O, "Verification of Diablo Canyon Project Efforts"
BESTAK, F, STRATOULY, D C Stone & Webster Engineering Corp 83/02/04 42pp 17141 048 24X Fiche 50-275, 83/02/07, 8302140078

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program, Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/ Westinghouse designed NSSS re resolution of TMI Action Item ILK 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D G Division of Licensing, 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302180252 Notices of 830223 & 24 meetings w/ B&W in Boston, MA to discuss Phase II addl verification & EOLs
COOPER, W E, CRAIGIN, J Q Teledyne Engineering Services 83/02/18 NRC - No Detailed Affiliation Given 1p 17215 275 24X
Fiche 50-275, 83/02/18, 8302180252

8302240280 Requests info from BNL analysis of containment annulus structure re vertical response spectra for Model D & horizontal annulus model info required for design verification program
COOPER, W E, MYRLOT, C E Teledyne Engineering Services 83/02/18 SCHIERLING, H E Office of Nuclear Reactor Regulation, Director 1p 17274 072 24X Fiche 50-275, 83/02/18, 8302240280

8302220368 Agenda for 830224 & 25 meetings in San Francisco, CA to discuss structural review
COOPER, W E, CRAIGIN, J Q Teledyne Engineering Services, 83/02/24 Teledyne Engineering Services 1p 17232 067 24X
Fiche 50-275, 83/02/24, 8302220368

F Security, medical, emergency & fire protection plans

8210190452 Forwards reviews of procedures proposed by utility in emergency plans to consider meteorological conditions at facilities, in response to Task Order 1 of interagency agreement
VAN DER HOVEN Commerce, Dept. of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099, 82/10/08 SPICKLER, I. Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X
Fiche 50-000, 82/10/08, 8210190452

--8301270060 'Evaluation of Procedures Proposed by P&E in Emergency Plans to Consider Meteorological Conditions in Diablo Canyon Plant Coastal Environ'
VAN DER HOVEN Commerce, Dept. of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099, 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 314, 24X
Fiche 50-000, 82/10/08, 8210190452

8302030603 Releases public version of revised emergency plan implementing procedures
FELTON, J M. Division of Rules and Records, 83/01/28 Document Management Branch 1p 17013 096 24X Fiche 50-275, 83/01/28, 8302030603

DOCKETED ITEMS

--8302030605 Forwards public version of revised emergency plan implementing procedures, including Procedures EP G-2 re establishment of onsite emergency organization & EF-5 re emergency equipment, instruments & supplies
CRANE, P A Pacific Gas & Electric Co 83/01/07 ENGELKEN, R H
Region 3, Office of Director 2pp 17013 097 24X
Fiche 50-275, 83/01/28, 8302030603

--8302030611 Public version of revised emergency plan implementing procedures, including Procedures EP G-2 re establishment of onsite emergency organization & EF-5 re emergency equipment, instruments & supplies
WOMACK, L F Pacific Gas & Electric Co 83/01/04 81pp
17013 097 24X Fiche 50-275, 83/01/28, 8302030603

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl. NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302090014 Forwards Rev 2 to security force training & qualification plan Rev withheld (ref 10CFR2 790)
CRANE, P A Pacific Gas & Electric Co 83/02/04 DENTON, H R
Office of Nuclear Reactor Regulation Director 3pp 17070 269
24X Fiche 50-275, 83/02/04, 8302090014

8302090357 Forwards changes to Rev 11 of security plan Changes withheld (ref 10CFR73 21)
CRANE, P A Pacific Gas & Electric Co 83/02/04 DENTON, H R
Office of Nuclear Reactor Regulation Director 2pp 17070 354
24X Fiche 50-275, 83/02/04, 8302090357

8302090428 Forwards Rev 2 to safeguards contingency plan Rev withheld (ref 10CFR73 21)
CRANE, P A Pacific Gas & Electric Co 83/02/04 DENTON, H R
Office of Nuclear Reactor Regulation Director 2pp 17066 240
24X Fiche 50-275, 83/02/04, 8302090428

8302230134 Forwards changes to security plan Changes withheld (ref 10CFR73 21)
CRANE, P A Pacific Gas & Electric Co 83/02/17 DENTON, H R
Office of Nuclear Reactor Regulation Director 2pp 17243 277
24X Fiche 50-275, 83/02/17, 8302230134

Q Adjudicatory correspondence

8302010464 Notice of substitution of Governor Q Baumejian for former Governor Brown as State of CA representative MJ Strumwasser notice of appearance & Certificate of Svc encl
STRUMWASSER, M California, State of 83/01/28 5pp 16981 013
24X Fiche 50-275, 83/01/28, 8302010464

8302250337 Order requiring submittal by 830302 of names of persons who will present arguments at 830316 hearing in Bethesda, MD re appeals from ASLB 820831 initial decision authorizing full-power operation & from motions of intervenors
BHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/23
2pp 17291 056 24X Fiche 50-275, 83/02/23, 8302250337

8302280263 Forwards SE Turk notice of withdrawal from proceeding NRC represented by LJ Chandler & JR Goldberg, whose notices of appearance were served on 830125 w/o encl
CHANDLER, L J Hearings Division 83/02/25 MOORE, T S, BUCK, J H, JOHNSON, R Atomic Safety and Licensing Appeal Panel 2pp
17312 282 24X Fiche 50-275, 83/02/25, 8302280263

H General correspondence

8302160228 Opposes low power licensing of facilities until design audit completed
WARREN, K J Affiliation Unknown 83/02/11 NRC - No Detailed
Affiliation Given 1p 17166 294 24X Fiche 50-275, 83/02/11, 8302160228

8302270525 Responds to 830121 ltr expressing concern over delays in bringing facility on line Util estimates fuel loading by 830031, initial criticality by 830602 & power ascension program by 830430
DENTON, H R Office of Nuclear Reactor Regulation Director 83/02/16 CURTIS, D J Affiliation Unknown 5pp 17235 351 24X
Fiche 50-275, 83/02/16, 8302270525

--8302220525 Requests that facility be licensed & allowed to operate w/o further delay Position supported by members of Citizens for Adequate Energy in San Luis County & throughout State of CA
CURTIS, D J Affiliation Unknown 83/01/21 FALLADINO, N J Commissioners 1p 17235 355 24X Fiche 50-275, 83/02/16, 8302220525

J Insurance & indemnity information

8302020028 Forwards NELIA Certificate N-76 & MAELU Certificate M-76 evidencing secondary financial protection
CRANE, P A Pacific Gas & Electric Co 83/01/27 SALTZMAN, J D
Assistant Director for State & Licensee Relations 13pp 16994 345
24X Fiche 50-323, 83/01/27, 8302020028

G Inspection reports, IE Bulletins & correspondence

8302230377 Forwards IE Insp Repts 50-275/82-41 & 50-323/82-19 on 821208-23 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/01/10 CRANE, P A Pacific Gas & Electric Co 2pp
17246 321 24X Fiche 50-275, 83/01/10, 8302230377

--8302230388 IE Insp Repts 50-275/82-41 & 50-323/82-19 on 821208-23 No noncompliance noted Major areas inspected design & procurement requirements for Super Strut matl installed for Class IE roadway supports
MORRILL, P J, JOHNSON, A D, MENDONCA, M M Division of Resident, Reactor Project & Engineering Programs 83/01/06 6pp
17246 323 24X Fiche 50-275, 83/01/10, 8302230377

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H20C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302080176 Responds to IE Bulletin 82-04 Util review indicates that hard epoxy electrical penetration assemblies mfg by Bunker-Ramo Co have neither been installed nor are planned for installation in containment at facilities
SCHUYLER, J O, CRANE, P A Pacific Gas & Electric Co 83/02/02
KNIGHTON, G W Licensing Branch 3 2pp 17058 337 24X
Fiche 50-275, 83/02/02, 8302080176

8302230657 Forwards IE Insp Repts 50-275/83-02 & 50-323/83-01 on 830103-21 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/02/09 CRANE, P A Pacific Gas & Electric Co 2pp
17255 054 24X Fiche 50-275, 83/02/09, 8302230657

--8302230666 IE Insp Repts 50-275/83-02 & 50-323/83-01 on 830103-21 No noncompliance noted Major areas inspected const & mod activities, including site tour, licensee actions on previous items, mods to structural steel & pipe supports
BURDOHN, J F, HERNANDEZ, G, ZWETZIG, G B Division of Resident, Reactor Project & Engineering Programs 83/02/09 9pp
17255 056 24X Fiche 50-275, 83/02/09, 8302230657

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 118pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302140110 Forwards "Annual Summary Rept on Monitoring & Reporting Program at Diablo Canyon Power Plant During 1982" & "Thermal Effects Monitoring Program 1982 Annual Rept, Diablo Canyon Power Plant"
THORNBERRY, R C Pacific Gas & Electric Co 83/01/28 JONES, K R
California, State of 2pp 17140 202 24X Fiche 50-275, 83/01/28, 8302140110

DOCKETED ITEMS

18

--8302140115 "Annual Summary Rpt on Monitoring & Reporting Program at
Diablo Canyon Power Plant During 1982"
+ Pacific Gas & Electric Co 82/12/31 48pp 17140 204 24X
Fiche 50-275, 83/01/28, 8302140110

--8302140117 Thermal Effects Monitoring Program 1982 Annual Rpt, Diablo
Canyon Power Plant
+ Pacific Gas & Electric Co 82-02-408 83/01/31 155pp
17140 252 24X Fiche 50-275, 83/01/28, 8302140110

V Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants
for OLs, P&SS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 11pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKE1 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8302150321 Ack receipt of 830106 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 50-324/82-44 &
50-325/82-44
VERRELLI, D M Division of Project & Resident Programs 83/01/28
UTLEY, E E Carolina Power & Light Co 1p 17148 185 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150330 Responds to NRC 821206 ltr re violation noted in IE Insp
Repts 50-324/82-44 & 50-325/82-44 Corrective actions
required limiting conditions for operation & fire watch
established & functional test of fire detection performed.
BIETZ, C R Carolina Power & Light Co 83/01/06 O'REILLY, J P
Region 2, Office of Director 2pp 17148 186 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150339 Notice of violation from insp on 821015-1115
+ Division of Project & Resident Programs 82/12/06 1p
17149 190 24X Fiche 50-324, 83/01/28, 8302150321

--8302150345 IE Insp Repts 50-324/82-44 & 50-325/82-44 on 821015-1115
Noncompliance noted cable penetration fire stop seals in
cable spreading room removed for plant mod work & not
replaced
MYERS, D O OARTER, L W, BCMIS, P Division of Project & Resident
Programs 82/12/02 8pp 17148 191 24X Fiche 50-324, 83/01/28,
8302150321

8302170500 Forwards draft SER re App R exemption request Review of
draft for accuracy of technical content & notification of
corrections requested Options for appealing exemption
denials discussed
VASSALLO, D B Operating Reactors Branch 2 83/01/31 UTLEY, E E
Carolina Power & Light Co 3pp 17203 115 24X
Fiche 50-324, 83/01/31, 8302170500

--8302170506 Draft SER re App R exemption request Listed fire zones do
not provide required level of fire protection
+ Operating Reactors Branch 2 83/01/31 50pp 17203 118 24X
Fiche 50-324, 83/01/31, 8302170500

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8203220416 Discusses electrical equipment qualification program
justification for interim operation Sufficient supplemental
info to support continued interim safe operation presented
at meeting
VLIEL, J A Operating Reactors Branch 2 82/03/09 NOVAK, T M
Assistant Director for Operating Reactors 7pp 17196 293 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170127 Forwards tabulation of Group 2 & 3 plants showing dates by
which technical evaluation repts are expected to be
completed Requests justification for continued operation of
each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRACLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170161 Concludes that continued operation until completion of
licensee environ qualification program will not present
undue risk to public health & safety
VAN ULIEL, J A Operating Reactors Branch 2 82/10/28
EISENHUT, D O Division of Licensing 2pp 17196 291 24X
Fiche 50-000, 83/01/18, 8302170019

8302010468 Application to amend Licenses DPR-71 & DPR-62 revising Tech
Specs re digital instrumentation w/analog counterparts
EURY, L W Carolina Power & Light Co 83/01/26 VASSALLO, D B
Operating Reactors Branch 2 3pp 16981 336 24X
Fiche 50-324, 83/01/26, 8302010468

--8302010473 Proposed Tech Specs revising digital instrumentation
w/analog counterparts
+ Carolina Power & Light Co 83/01/26 67pp 16981 339 24X
Fiche 50-324, 83/01/26, 8302010468

8302100155 Advises that recommendations of NUREG-0737, Item II B 2 2 re
plant shielding satisfied & item considered closed
VASSALLO, D B Operating Reactors Branch 2 83/01/27 UTLEY, E E
Carolina Power & Light Co 4pp 17134 274 24X
Fiche 50-324, 83/01/27, 8302100155

8302010483 Forwards info re NUREG-0737, Item II B 3, "Post-Accident
Sampling," in response to NRC 820809 ltr Implementation of
actions will be completed per util 820423 ltr
ZIMMERMAN, S R Carolina Power & Light Co 83/01/28 VASSALLO, D B
Operating Reactors Branch 2 19pp 16981 277 24X
Fiche 50-324, 83/01/28, 8302010483

8302160093 Forwards request for addl info re qualification of automatic
depressurization sys accumulator sys per NUREG-0737, Item
II K 3 2B, in response to licensee 800117, 0214 & 811223 ltrs.
Response requested within 60 days
VASSALLO, D B Operating Reactors Branch 2 83/01/31 UTLEY, E E
Carolina Power & Light Co 4pp 17160 323 24X
Fiche 50-324, 83/01/31, 8302160093

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re
mod of vacuum breakers on Mark I containment Requests
commitment to submit results of plant-unique calculations
which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public
Utilities - OPU Service Corp 8pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302020208 Updates status of NUREG-0737, Item II E 4.2 7, "Containment
Isolation Dependability" Installation of automatic
isolation features for purge valves not warranted based on
low site boundary dose
ZIMMERMAN, S R Carolina Power & Light Co 83/02/03 VASSALLO, D B
Operating Reactors Branch 2 4pp 17035 032 24X
Fiche 50-324, 83/02/03, 8302020208

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Quenches Group emergency procedures guideline program, Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACSWR), applicants for OL & holders of CP re BER of
"Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable, Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co. 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301.

8302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions Ability to use code must be
demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302150602 Forwards response to 821108 request for addl info re 81070,
response to Generic Ltr 81-04 concerning BWR/coolant
pressure boundary piping (NUREG-0313, Rev 1)
UTLEY, E E Carolina Power & Light Co. 83/02/08 VASSALLO, D B
Operating Reactors Branch 2 97pp 17155 247 24X
Fiche 50-324, 83/02/08, 8302150602

DOCKETED ITEMS

8302150394 Revises completion schedule for NUREG-0737, Item II F 1 5, "Containment Water Level Monitoring" Item will be complete by 830401
UTLEY, E E Carolina Power & Light Co 83/02/10 EISENHUT, D G
Division of Licensing 1p 17158 102 24X Fiche 50-324, 83/02/10, 8302150394

8302150195 Commits to complete NUREG-0737, Item II D 3, "Safety/Relief Valve Position Indication Equipment," by final required date Delay incurred by logistics of restructuring test program to incorporate corrective actions
UTLEY, E E Carolina Power & Light Co 83/02/11 VASSALLO, D B
Operating Reactors Branch 2 1p 17147 160 24X
Fiche 50-324, 83/02/11, 8302150195

8302230615 Notifies that response to 820827 request for addl info re NUREG-0737, Item III D 3 4, "Control Room Habitability," rescheduled for submittal no later than 830228
ZIMMERMAN, S R Carolina Power & Light Co 83/02/16 VASSALLO, D B
Operating Reactors Branch 2 1p 17255 040 24X
Fiche 50-324, 83/02/16, 8302230615

8302240265 Informs that Item 9 re heat tracing on outdoor installation completed, satisfying requirements of THI Item II K 3 22, "Automatic Switchover of RCIC Sys Suction"
ZIMMERMAN, S R Carolina Power & Light Co 83/02/21, VASSALLO, D B
Operating Reactors Branch 2 1p 17274 290 24X
Fiche 50-324, 83/02/21, 8302240265

1 Inspection reports, IE Bulletins & correspondence

8302150687 Forwards IE Insp Repts 50-324/82-46 & 50-325/82-46 on 821214-17 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/05
UTLEY, E E Carolina Power & Light Co 2pp 17153 049 24X
Fiche 50-324, 83/01/05, 8302150687

--8302150694 IE Insp Repts 50-324/82-46 & 50-325/82-46 on 821214-17 No noncompliance noted Major areas inspected THI action items & radiation protection
ALBRIGHT, R H, BARR, K P Division of Engineering & Radiological Safety Programs 83/01/03 4pp 17153 051 24X
Fiche 50-324, 83/01/03, 8302150694

8302150477 Ack receipt of 830105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-42 & 50-325/82-42
O'REILLY, J P Region 2, Office of Director 83/01/24 UTLEY, E E
Carolina Power & Light Co 1p 17157 078 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150518 Responds to NRC 821210 ltr re violations noted in IE Insp Repts 50-324/82-42 & 50-325/82-42 Corrective actions all waste shipments voluntarily suspended until onsite prepared waste could be reinspected for excess moisture
DIETZ, C R Carolina Power & Light Co 83/01/05 O'REILLY, J P
Region 2, Office of Director 2pp 17157 079, 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150520 Forwards IE Insp Repts 50-324/82-42 & 50-325/82-42 on 821027-29 & notice of violation
O'REILLY, J P, Region 2, Office of Director 82/12/10 UTLEY, E E
Carolina Power & Light Co 2pp 17157 081 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150527 Notice of violation from insp on 821027-29
* Region 2, Office of Director 82/12/10 1p 17157 083 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150537 IE Insp Repts 50-324/82-42 & 50-325/82-42 on 821027-29 Noncompliance noted licensee consigned five 55-gallon drums of low-specific activity liquid radwaste to unauthorized person for land burial at Barnwell, SC site
PEERY, H W, BARR, K P Division of Engineering & Radiological Safety Programs 82/11/30 4pp 17157 084 24X
Fiche 50-324, 83/01/24, 8302150477

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design." Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/23 Operating Reactors Branch 3 28pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

821060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 821060358,

8302150080 Responds to IE Bulletin 80-13 Unit 1 core spray spargers & in-vessel piping visually inspected No indication of cracking noted
HONE, P W Carolina Power & Light Co 83/01/26 O'REILLY, J P
Region 2, Office of Director 1p 17146 358 24X
Fiche 50-324, 83/01/26, 8302150080

8302150064 Forwards IE Insp Repts 50-324/83-01 & 50-325/83-01 on 830104-07 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/27
UTLEY, E E Carolina Power & Light Co 2pp 17146 156 24X
Fiche 50-324, 83/01/27, 8302150064

--8302150072 IE Insp Repts 50-324/83-01 & 50-325/83-01 on 830104-07 No noncompliance noted Major areas inspected structural mods & addl safety-related pipe supports & restraints in response to IE Bulletin 79-14
LIU, W C, BLAKE, J J Division of Project & Resident Programs 83/01/23 4pp 17146 158 24X Fiche 50-324, 83/01/27, 8302150064

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H30C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150321 Ack receipt of 830106 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-324/82-44 & 50-325/82-44
VERRELLI, D M Division of Project & Resident Programs 83/01/28
UTLEY, E E Carolina Power & Light Co 1p 17148 185 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150330 Responds to NRC 821206 ltr re violation noted in IE Insp Repts 50-324/82-44 & 50-325/82-44 Corrective actions required limiting conditions for operation & fire watch established & functional test of fire detection performed
DIETZ, C R Carolina Power & Light Co 83/01/06 O'REILLY, J P
Region 2, Office of Director 3pp 17148 186 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150334 Forwards IE Insp Repts 50-324/82-44 & 50-325/82-44 on 821015-1115 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/12/06
UTLEY, E E Carolina Power & Light Co 2pp 17148 188 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150339 Notice of violation from insp on 821015-1115
* Division of Project & Resident Programs 82/12/06 1p 17148 190 24X Fiche 50-324, 83/01/28, 8302150321

--8302150345 IE Insp Repts 50-324/82-44 & 50-325/82-44 on 821015-1115 Noncompliance noted cable penetration fire stop seals in cable spreading room removed for plant mod work & not replaced
MYERS, D O, GARNER, L W, BEMIS, P Division of Project & Resident Programs 82/12/02 8pp 17148 191 24X Fiche 50-324, 83/01/28, 8302150321

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302230249 EN-83-011 on 830218, notice of violation & civil penalties issued in amount of \$600,000 based on violations re Tech Spec surveillance requirements for several safety sys & components & failure to correct identified problems
BARDER, O, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/02/18 1p 17244 310 24X Fiche 50-324, 83/02/18, 8302230249

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150542 Forwards monthly operating repts for Jan 1983
 DIEIZ, C R Carolina Power & Light Co 83/02/04 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement 1p
 17191 009 24X Fiche 50-324, 83/02/04, 8302150542

--8302150650 Monthly operating repts for Jan 1983
 HARRISON, F Carolina Power & Light Co 83/02/01 15pp
 17191 009 24X Fiche 50-324, 83/02/04, 8302150642

S Reportable occurrences, LERs & related correspondence

8301170409 Forwards updated LER 81-071/03L-1
 DIEIZ, C R Carolina Power & Light Co 83/01/05 O'REILLY, J P
 Region 2, Office of Director 1p 16813 121 24X
 Fiche 50-324, 83/01/05, 8301170409

--8301170414 Updated LER 81-071/03L-1 on 810729, primary containment
 atmospheric control suppression chamber water level range
 recorder 2-CAC-LR-2602 read high Caused by blockage in
 transmitter Blockage removed & transmitter recalibr
 PASTVA, M J Carolina Power & Light Co 83/01/05 Region 2,
 Office of Director 2pp 16813 122 24X Fiche 50-324, 83/01/05,
 8301170409

8302010087 Forwards updated LER 81-090/03L-2
 DIEIZ, C R Carolina Power & Light Co 83/01/17 O'REILLY, J P
 Region 2, Office of Director 1p 16974 141 24X
 Fiche 50-324, 83/01/17, 8302010087

--8302010092 Updated LER 81-090/03L-2 on 810817, suppression chamber
 water level indicator 2-CAC-LI-2601-3 indicated lower level
 than other suppression chamber indicator Caused by changes
 in trickle flow to wet ref leg indicator transmitter
 PASTVA, M J Carolina Power & Light Co 83/01/17 Region 2,
 Office of Director 2pp 16974 142 24X Fiche 50-324, 83/01/17,
 8302010087

8302010267 Forwards LER 82-142/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/17 O'REILLY, J P
 Region 2, Office of Director 1p 16973 141 24X
 Fiche 50-324, 83/01/17, 8302010267

--8302010277 LER 82-142/03L-0 on 821218, PCIV B32-F0588, located at
 RIP V-2418, found closed Caused by const personnel accidentally
 bumping valve &/or associated instrument piping Valve opened
 & personnel counseled
 PASTVA, M J Carolina Power & Light Co 83/01/17 Region 2,
 Office of Director 1p 16973 142 24X Fiche 50-324, 83/01/17,
 8302010267

8302010426 Forwards LER 82-141/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/17 O'REILLY, J P
 Region 2, Office of Director 1p 16980 277 24X
 Fiche 50-324, 83/01/17, 8302010426

--8302010434 LER 82-141/03L-0 on 821218, primary containment atmosphere
 oxygen analyzer 1-CAC-AT-1263-2 showed upscale indication of
 drywell oxygen concentration Caused by 1263-2 analyzer zero
 shift Analyzer calibr & returned to svc
 PASTVA, M J Carolina Power & Light Co 83/01/17 Region 2,
 Office of Director 1p 16980 278 24X Fiche 50-324, 83/01/17,
 8302010426

8302010080 Forwards LER 82-140/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/20 O'REILLY, J P
 Region 2, Office of Director 1p 16974 085 24X
 Fiche 50-324, 83/01/20, 8302010080

--8302010083 LER 82-140/03L-0 on 821221, primary containment atmosphere
 oxygen analyzer 2-CAC-AT-1263-2 showed step increase in
 drywell oxygen concentration Caused by zero shift due to
 analyzer being out of calibr & by small piping leak
 PASTVA, M J Carolina Power & Light Co 83/01/20 Region 2,
 Office of Director 1p 16974 086 24X Fiche 50-324, 83/01/20,
 8302010080

8302010454 Forwards LER 82-143/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/20 O'REILLY, J P
 Region 2, Office of Director 1p 16973 259 24X
 Fiche 50-324, 83/01/20, 8302010454

--8302010457 LER 82-143/03L-0 on 821220, reactor water cleanup
 differential flow indicator 2-031-R615 indicated downscale
 during routine surveillance Caused by partially plugged low
 side sensing line to FT-N041 & out of calibr transmitters
 PASTVA, M J Carolina Power & Light Co 83/01/20 Region 2,
 Office of Director 2pp 16973 260 24X Fiche 50-324, 83/01/20,
 8302010454

8302010281 Forwards LER 82-144/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/21 O'REILLY, J P
 Region 2, Office of Director 1p 16973 015 24X
 Fiche 50-324, 83/01/21, 8302010281

--8302010287 LER 82-144/03L-0 on 821223, routine surveillance revealed
 suppression chamber water temp recorder 2-CAC-TR-778 not
 recording temps on instrument chart paper Caused by
 defective print head solenoid & print mechanism rod
 PASTVA, M J Carolina Power & Light Co 83/01/21 Region 2,
 Office of Director 2pp 16973 016 24X Fiche 50-324, 83/01/21,
 8302010281

8302010371 Forwards LER 82-134/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/21 O'REILLY, J P
 Region 2, Office of Director 1p 16973 299 24X
 Fiche 50-324, 83/01/21, 8302010371

--8302010375 LER 82-134/03L-0 on 821222, trip module showed upscale
 indication of reactor level while local meter indicator of
 redundant instrument showed indication of 198 0 inches
 Caused by transmitter out of calibr due to instrument drift
 PASTVA, M J Carolina Power & Light Co 83/01/21 Region 2,
 Office of Director 1p 16973 300 24X Fiche 50-324, 83/01/21,
 8302010371

8302010563 Forwards LER 82-135/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/26 O'REILLY, J P
 Region 2, Office of Director 1p 16977 102 24X
 Fiche 50-324, 83/01/26, 8302010563

--8302010573 LER 82-135/03L-0 on 821227, low pressure microswitch of
 primary containment isolation sys HPCI steam supply pressure
 instrument 2-E41-PEL-N0010 would not actuate during Test
 PT-02 1 2P Caused by end of component life
 PASTVA, M J Carolina Power & Light Co 83/01/26 Region 2,
 Office of Director 1p 16977 103 24X Fiche 50-324, 83/01/26,
 8302010563

8302030410 Forwards LER 83-002/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/28 O'REILLY, J P
 Region 2, Office of Director 1p 17005 217 24X
 Fiche 50-324, 83/01/28, 8302030410

--8302030422 LER 83-002/03L-0 on 830102, during operation, suppression
 pool level indicators operability test PT-08 1 & revealed
 indicator 2-CAC-LR-2602 showed level of -31 inches Caused by
 change in trickle flow flow adjusted
 PASTVA, M J Carolina Power & Light Co 83/01/28 Region 2,
 Office of Director 2pp 17005 218 24X Fiche 50-324, 83/01/28,
 8302030410

8302030414 Forwards updated LER 82-144/03L-1
 DIEIZ, C R Carolina Power & Light Co 83/01/28 O'REILLY, J P
 Region 2, Office of Director 1p 17005 224 24X
 Fiche 50-324, 83/01/28, 8302030414

--8302030420 Updated LER 82-144/03L-1 on 821223, suppression chamber
 water temp recorder 2-CAC-TR-778 not recording temp on
 instrument chart paper Caused by defective print head
 solenoid & print mechanism push rod assembly
 PASTVA, M J Carolina Power & Light Co 83/01/28 Region 2,
 Office of Director 1p 17005 225 24X Fiche 50-324, 83/01/28,
 8302030414

8302030503 Forwards updated LER 81-090/03L-3
 DIEIZ, C R Carolina Power & Light Co 83/01/28 O'REILLY, J P
 Region 2, Office of Director 1p 17006 307 24X
 Fiche 50-324, 83/01/28, 8302030503

--8302030510 Updated LER 81-090/03L-3 on 810817 & 23, suppression
 chamber water level indicator 2-CAC-LI-2601-3 indicated
 lower level & on 810820, indicated higher level than other
 indicator Caused by changes in trickle flow to wet ref leg
 PASTVA, M J Carolina Power & Light Co 83/01/28 Region 2,
 Office of Director 1p 17006 308 24X Fiche 50-324, 83/01/28,
 8302030503

8302140042 Forwards LER 83-001/03L-0
 DIEIZ, C R Carolina Power & Light Co 83/01/31 O'REILLY, J P
 Region 2, Office of Director 1p 17142 136 24X
 Fiche 50-324, 83/01/31, 8302140042

--8302140049 LER 83-001/03L-0 on 830102 & 05, RCIC turbine exhaust
 diaphragm pressure high annunciator alarmed Caused by
 instrument drift on 830102 & moisture accumulation in
 switch housing on 830105
 PASTVA, M J Carolina Power & Light Co 83/01/31 Region 2,
 Office of Director 2pp 17142 137 24X Fiche 50-324, 83/01/31,
 8302140042

DOCKETED ITEMS

8302150172 Interim Part 21 rept re postulated pipe cracks Initially reported during Apr 1982 United Engineers & Constructors evaluating reactor bldg environ rept & developing corrective actions Final rept expected by 830331
DIFTZ,C R Carolina Power & Light Co 83/02/01 O'REILLY, J P
Region 2, Office of Director 1p 17147 227 24X
Fiche 50-324, 83/02/01, 8302150172

8302140010 Forwards LER 83-003/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/02 O'REILLY, J P
Region 2, Office of Director 1p 17141 197 24X
Fiche 50-324, 83/02/02, 8302140010

--8302140012 LER 83-003/03L-0 on 830103, following reactor scram due to group 1 isolation, suppression pool level found out of spec high at -26.5 inches Caused by operation of HPCI & safety relief valves for level & pressure control during event
PDUK,R M Carolina Power & Light Co 83/02/02 Region 2,
Office of Director 1p 17141 198 24X Fiche 50-324, 83/02/02,
8302140010

8302150023 Forwards updated LER 82-094/03L-1
DIFTZ,C R Carolina Power & Light Co 83/02/03 O'REILLY, J P
Region 2, Office of Director 1p 17147 142 24X
Fiche 50-324, 83/02/03, 8302150023

--8302150026 Updated LER 82-094/03L-1 on 820727, review of Source Range Monitor Sys Channel Functional Test PT-01 21 revealed that weekly surveillance during fuel handling did not reflect Mode 5 testing frequency Caused by oversight
PASTVA,M J Carolina Power & Light Co 83/02/03 Region 2,
Office of Director 1p 17147 143 24X Fiche 50-324, 83/02/03,
8302150026

8302150119 Forwards LER 83-004/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/04 O'REILLY, J P
Region 2, Office of Director 1p 17147 311 24X
Fiche 50-324, 83/02/04, 8302150119

--8302150129 LER 83-004/03L-0 on 830105, during jumper installation, reactor protection sys relay C72-K&C found melted around coil Caused by overheating of relay Relays to be inspected monthly until replaced w/improved components
PDUK,R M Carolina Power & Light Co 83/02/04 Region 2,
Office of Director 2pp 17147 312 24X Fiche 50-324, 83/02/04,
8302150129

8302170093 Forwards LER 83-005/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/09 O'REILLY, J P
Region 2, Office of Director 1p 17181 355 24X
Fiche 50-324, 83/02/09, 8302170093

--8302170101 LER 83-005/03L-0 on 830110, both personnel secondary containment airtight doors, located on 50-ft elevation northeast wall, found inoperable due to excessive leakage past seals Caused by damaged sealing gaskets
PASTVA,M J Carolina Power & Light Co 83/02/09 Region 2,
Office of Director 1p 17181 357 24X Fiche 50-324, 83/02/09,
8302170093

8302170178 Forwards LER 83-006/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/09 O'REILLY, J P
Region 2, Office of Director 1p 17183 075 24X
Fiche 50-324, 83/02/09, 8302170178

--8302170184 LER 83-006/03L-0 on 830114, primary containment atmosphere oxygen analyzer 2-CAC-AT-1263-2 indicated 0.5% step increase in drywell oxygen concentration Caused by instrument zero shift Monitors replaced & instrument recalibr.
PASTVA,M J Carolina Power & Light Co 83/02/09 Region 2,
Office of Director 1p 17183 076 24X Fiche 50-324, 83/02/09,
8302170178

1302170074 Forwards updated LER 82-144/03L-2
DIFTZ,C R Carolina Power & Light Co 83/02/10 O'REILLY, J P
Region 2, Office of Director 1p 17183 020 24X
Fiche 50-324, 83/02/10, 8302170074

--8302170084 Updated LER 82-144/03L-2 on 821223, suppression chamber water temp recorder 2-CAC-TR-778 on remote shutdown panel indicated expected temp indications, but did not record on instrument chart paper Caused by defective print solenoid
PASTVA,M J Carolina Power & Light Co 83/02/10 Region 2,
Office of Director, 2pp 17183 021 24X Fiche 50-324, 83/02/10,
8302170074

8302280219 RO 2-83-19, on 830211, air tubing to safety relief valve/ADS relief valve not supported per Tech Spec table Supports installed to allow short-term operation Long-term corrections to be completed during spring outage
DIFTZ,C R Carolina Power & Light Co 83/02/14 O'REILLY, J P
Region 2, Office of Director 1p 17304 361 24X
Fiche 50-324, 83/02/14, 8302280219

8302280066 Forwards LER 83-009/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/17 O'REILLY, J P
Region 2, Office of Director 1p 17307 188 24X
Fiche 50-324, 83/02/17, 8302280066

--8302280074 LER 83-009/03L-0 on 830118, reactor recirculation pump 2A tripped when pump motor generator set drive motor tripped Caused by actuation of motor generator set drive motor field overcurrent relay device 27 Trip signal reset
PASTVA,M J Carolina Power & Light Co 83/02/17 Region 2,
Office of Director 1p 17307 189 24X Fiche 50-324, 83/02/17,
8302280066

8302280502 Forwards LER 83-008/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/17 O'REILLY, J P
Region 2, Office of Director 1p 17309 065 24X
Fiche 50-324, 83/02/17, 8302280502

--8302280507 LER 83-008/03L-0 on 830118, during channel calibr & functional test, HPCI sys condensate storage tank low level instrument 2-E41-LSL-N003 failed to actuate within required tolerance Caused by debris in N003 vent line
PASTVA,M J Carolina Power & Light Co 83/02/17 Region 2,
Office of Director 1p 17309 066 24X Fiche 50-324, 83/02/17,
8302280502

8302230166 Forwards LER 83-007/03L-0
DIFTZ,C R Carolina Power & Light Co 83/02/18 O'REILLY, J P
Region 2, Office of Director 1p 17245 084 24X
Fiche 50-324, 83/02/18, 8302230166

--8302230169 LER 83-007/03L-0 on 830115, HPCI sys steam line high temp primary containment isolation sys isolation occurred, rendering HPCI sys inoperable Caused by personnel error due to instrument mislabeling Test signal removed
PASTVA,M J Carolina Power & Light Co 83/02/18 Region 2,
Office of Director 2pp 17245 085 24X Fiche 50-324, 83/02/18,
8302230166

U Congressional/Executive Correspondence

8302230076 Responds to 821119 ltr expressing concern re Raychem-Flamtrol issue & requesting info on Commission actions to resolve matter Issue will be handled as part of overall environ qualification review
PALLADIO,H J Commissioners 83/01/25 PANETTA, L E House of Rep 2pp 17259 295 24X Fiche 50-324, 83/01/25, 8302230076

--8302230082 Summary of 821130 meeting w/util re use of Raychem-Flamtrol cables NRC no longer considers all cables as being qualified for Class IE applications
VILLALVA, I Events Analysis Branch 82/12/02 MILLS, W R Events Analysis Branch 1p 17259 297 24X Fiche 50-324, 83/01/25,
8302230076

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUTZ, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8302150321 Ack receipt of 830106 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-324/82-44 & 50-325/82-44
VERRELLI, D H Division of Project & Resident Programs 83/01/28 UTLEY, E Carolina Power & Light Co 1p 17148 185 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150330 Responds to NRC 821206 ltr re violation noted in IE Insp Repts 50-324/82-44 & 50-325/82-44 Corrective actions required limiting conditions for operation & fire watch established & functional test of fire detection performed
DIFTZ,C R Carolina Power & Light Co 83/01/06 O'REILLY, J P
Region 2, Office of Director 2pp 17148 186 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150339 Notice of violation from insp on 821015-115
* Division of Project & Resident Programs 82/12/06 1p 17148 190 24X Fiche 50-324, 83/01/28, 8302150321

DOCKETED ITEMS

--8302150345 IE Insp Repts 50-324/82-44 & 50-325/82-44 on 821015-1115
Noncompliance noted cable penetration fire stop seals in
cable spreading room removed for plant mod work & not
replaced
MERS, D O Division of Project & Resident Programs 82/12/02
8pp 17148 191 24X Fiche 50-324, 83/01/28, 8302150321

8302170500 Forwards draft BER re App R exemption request Review of
draft for accuracy or technical content & notification of
corrections requested Options for appealing exemption
details discussed
VASSALLO, D B Operating Reactors Branch 2 83/01/31 UTLEY, E E
Carolina Power & Light Co 3pp 17203 115 24X
Fiche 50-324, 83/01/31, 8302170500

--8302170506 Draft BER re App R exemption request Listed fire zones do
not provide required level of fire protection
* Operating Reactors Branch 2 83/01/31 50pp 17203 118 24X
Fiche 50-324, 83/01/31, 8302170500

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 1pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8303220416 Discusses electrical equipment qualification program
justification for interim operation Sufficient supplemental
info to support continued interim safe operation presented
at meeting
VLIEL, J A Operating Reactors Branch 2 82/03/09 NOVAK, T M
Assistant Director for Operating Reactors 7pp 17196 293 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by
which technical evaluation repts are expected to be
completed Requests justification for continued operation of
each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRALIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170161 Concludes that continued operation until completion of
licensee environ qualification program will not present
undue risk to public health & safety
VAN VLIEL, J A Operating Reactors Branch 2 82/10/28
EISENHUT, D O Division of Licensing 2pp 17196 291 24X
Fiche 50 000, 83/01/18, 8302170019

8302010468 Application to amend Licenses DPR-71 & DPR-62 revising Tech
Specs re digital instrumentation w/analog counterparts
EURV, L W Carolina Power & Light Co 83/01/26 VASSALLO, D B
Operating Reactors Branch 2 3pp 16981 336 24X
Fiche 50-324, 83/01/26, 8302010468

--8302010473 Proposed Tech Specs revising digital instrumentation
w/analog counterparts
* Carolina Power & Light Co 83/01/26 67pp 16981 339 24X
Fiche 50-324, 83/01/26, 8302010468

8302100155 Advises that recommendations of NUREG-0737, Item II B 2 2 re
plant shielding satisfied & item considered closed
VASSALLO, D B Operating Reactors Branch 2 83/01/27 UTLEY, E E
Carolina Power & Light Co 4pp 17124 274 24X
Fiche 50-324, 83/01/27, 8302100155

8302010483 Forwards info re NUREG-0737, Item II B 3, "Post-Accident
Sampling," in response to NRC 820809 ltr Implementation of
actions will be completed per util 820423 ltr
ZIMMERMAN, S R Carolina Power & Light Co 83/01/28 VASSALLO, D B
Operating Reactors Branch 2 19pp 16981 277 24X
Fiche 50-324, 83/01/28, 8302010483

8302160093 Forwards request for addl info re qualification of automatic
depressurization sys accumulator sys per NUREG-0737, Item
II K.3 2B, in response to licensee 800117, 0214 & 811223 ltrs.
Response requested within 60 days
VASSALLO, D B Operating Reactors Branch 2 83/01/31 UTLEY, E E
Carolina Power & Light Co 4pp 17160 323 24X
Fiche 50-324, 83/01/31, 8302160093

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re
mod of vacuum breakers on Mark I containment Requests
commitment to submit results of plant-unique calculations
which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public
Utilities - GPU Service Corp 5pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302070208 Updates status of NUREG-0737, Item II E 4 2 7, "Containmen
Isolation Dependability" Installation of automatic
isolation features for purge valves not warranted based on
low site boundary dose
ZIMMERMAN, S R Carolina Power & Light Co 83/02/03 VASSALLO, D B
Operating Reactors Branch 2 4pp 17035 052, 24X
Fiche 50-324, 83/02/03, 8302070208

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 1pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re BER of
"Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions. Ability to use code must be
demonstrated by vendor or licensee. Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234, 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302150040 Application for amend to License DPR-71 supplementing
request for core spray sys surveillance interval extension
Request supersedes 821108 & 830106 submittals
UTLEY, E E Carolina Power & Light Co 83/02/08 VASSALLO, D B
Operating Reactors Branch 2 2pp 17155 228 24X
Fiche 50-325, 83/02/08, 8302150040

--8302150043 Proposed Tech Spec requesting one-time exemption from
Tech Spec 4.5.3.1 C 1 re core spray sys surveillance
* Carolina Power & Light Co 83/02/08 3pp 17155 230 24X
Fiche 50-325, 83/02/08, 8302150040

8302150602 Forwards response to 821108 request for addl info re B10
response to Generic Ltr 81-04 concerning BWR/coolant
pressure boundary piping (NUREG-0313, Rev 1)
UTLEY, E E Carolina Power & Light Co 83/02/08 VASSALLO, D B
Operating Reactors Branch 2 97pp 17155 247 24X
Fiche 50-324, 83/02/08, 8302150602

8302150394 Revises completion schedule for NUREG-0737, Item II F.1 :
"Containment Water Level Monitoring" item will be complete
by 830601
UTLEY, E E Carolina Power & Light Co 83/02/10 EISENHUT, D O
Division of Licensing 1p 17158 102 24X Fiche 50-324, 83/02/10,
8302150394

8302150195 Commits to complete NUREG-0737, Item II D 3, "Safety/Rel
Valve Position Indication Equipment," by final required
date Delay incurred by logistics of restructuring test
program to incorporate corrective actions.
UTLEY, E E Carolina Power & Light Co 83/02/11 VASSALLO, D B
Operating Reactors Branch 2 1p 17147, 160, 24X
Fiche 50-324, 83/02/11, 8302150195

8302230615 Notifies that response to 820827 request for addl info
NUREG-0737, Item II D 3 4, "Control Room Habitability,"
rescheduled for submittal no later than 830228
ZIMMERMAN, S R Carolina Power & Light Co 83/02/16 VASSALLO, D B
Operating Reactors Branch 2 1p 17255 040 24X
Fiche 50-324, 83/02/16, 8302230615

8302240265 Informs that Item 9 re heat tracing on outdoor installa
completed, satisfying requirements of TMI Item II K 3.22,
"Automatic Switchover of RCIC Sys Suction"
ZIMMERMAN, S R Carolina Power & Light Co 83/02/21 VASSALLO, D B
Operating Reactors Branch 2 1p 17274, 290, 24X
Fiche 50-324, 83/02/21, 8302240265.

DOCKETED ITEMS

A Inspection reports, IE Bulletins & correspondence

8302150687 Forwards IE Insp Repts 50-324/82-46 & 50-325/82-46 on 821214-17 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/05
UTLEY, E E Carolina Power & Light Co 2pp 17153 049 24X
Fiche 50-324, 83/01/05, 8302150687

--8302150694 IE Insp Repts 50-324/82-46 & 50-325/82-46 on 821214-17 No noncompliance noted Major areas inspected THJ action items
& radiation protection
ALBRIGHT, R M, BARR, K P Division of Engineering & Radiological Safety Programs 83/01/03 4pp 17153 051 24X
Fiche 50-324, 83/01/03, 8302150697

8302150477 Ack receipt of 830105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-42 & 50-325/82-42
O'REILLY, J P Region 2, Office of Director 83/01/24 UTLEY, E E Carolina Power & Light Co 1p 17157 078 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150516 Responds to NRC 821210 ltr re violations noted in IE Insp Repts 50-324/82-42 & 50-325/82-42 Corrective actions all waste shipments voluntarily suspended until onsite prepared waste could be reinspected for excess moisture
DIETZ, C R Carolina Power & Light Co 83/01/05, O'REILLY, J P, Region 2, Office of Director 2pp 17157 079 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150520 Forwards IE Insp Repts 50-324/82-42 & 50-325/82-42 on 821027-29 & notice of violation
O'REILLY, J P Region 2, Office of Director, 82/12/10 UTLEY, E E Carolina Power & Light Co 2pp 17157 081 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150527 Notice of violation from insp on 821027-29
* Region 2, Office of Director 82/12/10 1p 17157 083, 24X
Fiche 50-324, 83/01/24, 8302150477

--8302150537 IE Insp Repts 50-324/82-42 & 50-325/82-42 on 821027-29 Noncompliance noted licensee consigned five 55-gallon drums of low-specific activity liquid radwaste to unauthorized person for land burial at Barnwell, SC site.
PEERY, W W, BARR, K P Division of Engineering & Radiological Safety Programs 82/11/30 4pp 17157 084 24X
Fiche 50-324, 83/01/24, 8302150477

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 23pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150080 Responds to IE Bulletin 80-13 Unit 1 core spray spargers & in-vessel piping visually inspected No indication of cracking noted
HONE, P W Carolina Power & Light Co 83/01/26 O'REILLY, J P Region 2, Office of Director 1p 17146 358 24X
Fiche 50-324, 83/01/26, 8302150080

8302150064 Forwards IE Insp Repts 50-324/83-01 & 50-325/83-01 on 830104-07 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/27
UTLEY, E E Carolina Power & Light Co 2pp 17146 156 24X
Fiche 50-324, 83/01/27, 8302150064

--8302150072 IE Insp Repts 50-324/83-01 & 50-325/83-01 on 830104-07 No noncompliance noted Major areas inspected structural mods & addl safety-related pipe supports & restraints in response to IE Bulletin 79-14
LIN, W C, BLAKE, J J Division of Project & Resident Programs 83/01/29 6pp 17146 158 24X Fiche 50-324, 83/01/27, 8302150064

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 107pp 17144 001, 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150321 Ack receipt of 830106 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-324/82-44 & 50-325/82-44
VERRELLI, D M Division of Project & Resident Programs 83/01/28
UTLEY, E E Carolina Power & Light Co 1p 17148 185 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150330 Responds to NRC 821206 ltr re violation noted in IE Insp Repts 50-324/82-44 & 50-325/82-44 Corrective actions required limiting conditions for operation & fire watch established & functional test of fire detection performed
DIETZ, C R Carolina Power & Light Co 83/01/06 O'REILLY, J P Region 2, Office of Director 2pp 17148 186 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150334 Forwards IE Insp Repts 50-324/82-44 & 50-325/82-44 on 821015-1115 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/12/06
UTLEY, E E Carolina Power & Light Co 2pp 17148 188 24X
Fiche 50-324, 83/01/28, 8302150321

--8302150339 Notice of violation from insp on 821015-1115
* Division of Project & Resident Programs 82/12/06 1p 17148 190 24X Fiche 50-324, 83/01/28, 8302150321

--8302150345 IE Insp Repts 50-324/82-44 & 50-325/82-44 on 821015-1115 Noncompliance noted cable penetration fire stop seals in cable spreading room removed for plant mod work & not replaced
MYERS, D O, GARNER, L W, BEMIS, P Division of Project & Resident Programs 82/12/02 8pp 17148 191 24X Fiche 50-324, 83/01/28, 8302150321

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302230249 EN-83-011 on 830218, notice of violation & civil penalties issued in amount of \$600,000 based on violations re Tech Spec surveillance requirements for several safety sys & components & failure to correct identified problems
BARBER, O, A'ELRAD, J Director's Office, Office of Inspection and Enforcement 83/02/18 1p 17244 310 24X Fiche 50-324, 83/02/18, 8302230249

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150642 Forwards monthly operating repts for Jan 1983
DIETZ, C R Carolina Power & Light Co 83/02/04 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p, 17151 008 24X Fiche 50-324, 83/02/04, 8302150642

--8302150650 Monthly operating repts for Jan 1983
HARRISON, F Carolina Power & Light Co 83/02/01 15pp 17151 009 24X Fiche 50-324, 83/02/04, 8302150642

S Reportable occurrences, LERs & related correspondence

8302010601 Forwards updated LER 82-044/03L-2
DIETZ, C R Carolina Power & Light Co 83/01/17 O'REILLY, J P Region 2, Office of Director 1p 16978 141 24X
Fiche 50-325, 83/01/17, 8302010601

--8302010619 Updated LER 82-044/03L-2 on 820329, suppression chamber water level RT08 instrument 1-CAC-LR-2602 indicated incorrect water level Caused by change in trickle flow to wet ref leg of 2602 recorder transmitter
PASTVA, M J Carolina Power & Light Co 83/01/17 Region 2, Office of Director 2pp 16978 142 24X Fiche 50-325, 83/01/17, 8302010601

DOCKETED ITEMS

8302030385 RD on 830118, weld B32-Recirc-28-A-15 had two crack indications. Indications in heat-affected zone on pipe side on weld connecting right angle elbow to straight section of pipe. Investigation being conducted.
DIETZ, C R Carolina Power & Light Co 83/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 17005 345 24X
Fiche 50-325, 83/01/19, 8302030385

8302010234 Forwards LER 82-152/03L-0
DIETZ, C R Carolina Power & Light Co 83/01/20 O'REILLY, J P
Region 2, Office of Director 1p 16974 001 24X
Fiche 50-325, 83/01/20, 8302010234

--8302010240 LER 82-152/03L-0 on 821221, visual insp of main steam line secondary containment boot seals revealed hole in boot seal of main steam line A. Caused by thermal expansion & high ambient temps. Boot replaced.
PASTVA, M J Carolina Power & Light Co 83/01/20 Region 2,
Office of Director 1p 16974 032 24X Fiche 50-325, 83/01/20,
8302010240

8302010363 Forwards LER 82-125/03L-0
DIETZ, C R Carolina Power & Light Co 83/01/21 O'REILLY, J P
Region 2, Office of Director 1p 16973 308 24X
Fiche 50-325, 83/01/21, 8302010363

--8302010367 LER 82-125/03L-0 on 821222, during reactor scram recovery, following automatic start of four diesel generators, diesel generator 1 tripped & locked out on low lube oil pressure. Caused by air in sensing line of diesel pressure switch.
PASTVA, M J Carolina Power & Light Co 83/01/21 Region 2,
Office of Director 2pp 16973 309 24X Fiche 50-325, 83/01/21,
8302010367

8302010593 PHO-11-83-005 on 830126, through-wall pinhole leak found in 12-inch stainless steel recirculation sys riser pipe. SNRI NDE specialists performing manual ultrasonic exam to evaluate defect.
HEHL, C W, CROWLEY, B R Region 2, Office of Director 83/01/27
2pp 16978 102 24X Fiche 50-325, 83/01/27, 8302010593

8302030401 RD on 830127, leakage detected in heat affected zone on pipe side of weld connecting riser to safe end in area where arc strike appears. Evaluations continuing to determine failure mechanism.
DIETZ, C R Carolina Power & Light Co 83/01/27 O'REILLY, J P
Region 2, Office of Director 1p 17005 214 24X
Fiche 50-325, 83/01/27, 8302030401

8302010684 PHO-11-82-005A pinhole leak in 12-inch stainless steel recirculation sys riser piping discovered during insp per IE Bulletin 82-03. Cause undetermined. Investigation continuing.
HEHL, C W, CROWLEY, B R Region 2, Office of Director 83/01/28
1p 16979 044 24X Fiche 50-325, 83/01/28, 8302010684

8302030187 RD on 830127, leakage detected in heat affected zone on pipe side of weld connecting riser pipe to elbow. Evaluations continuing to determine failure mechanism. Situation will be reported in 14-day rept.
DIETZ, C R Carolina Power & Light Co 83/01/28 O'REILLY, J P
Region 2, Office of Director 1p 17002 103 24X
Fiche 50-325, 83/01/28, 8302030187

8302140134 Forwards LER 83-004/01T-0
DIETZ, C R Carolina Power & Light Co 83/02/01 O'REILLY, J P
Region 2, Office of Director 1p 17141 202 24X
Fiche 50-325, 83/02/01, 8302140134

--8302140142 LER 83-004/01T-0 on 830118, two crack indications found in heat affected zone on pipe side weld B32-Recirc-28-A-15. Cause attributed to intergranular stress corrosion cracking. Corrective actions under development.
PASTVA, M J Carolina Power & Light Co 83/02/01 Region 2,
Office of Director 1p 17141 203 24X Fiche 50-325, 83/02/01,
8302140142

8302150172 Interim Part 21 rept re postulated pipe cracks. Initially reported during Apr 1982. United Engineers & Constructors evaluating reactor bldg environ rept & developing corrective actions. Final rept expected by 830331.
DIETZ, C R Carolina Power & Light Co 83/02/01 O'REILLY, J P
Region 2, Office of Director 1p 17147 227 24X
Fiche 50-324, 83/02/01, 8302150172

8302170177 Forwards LER 83-001/01T-0
DIETZ, C R Carolina Power & Light Co 83/02/09 O'REILLY, J P
Region 2, Office of Director 1p 17183 077 24X
Fiche 50-325, 83/02/09, 8302170177

--8302170183 LER 83-001/01T-0 on 830126, single through-wall pin hole cracks found in heat affected zones on pipe sides of weld B32-Recirc-12-BR-H-4. Caused by intergranular stress corrosion cracking. Cracks will be repaired.
PASTVA, M J Carolina Power & Light Co 83/02/09 Region 2,
Office of Director 2pp 17183 078 24X Fiche 50-325, 83/02/09,
8302170177

8302170172 RD 2-83-16 on 830209, emergency bus E-2 de-energized to allow maint on 4,160-volt switchgear, thereby removing one of two power supplies to motor driven fire pump. Pump redundant battery source had less than required voltage.
DIETZ, C R Carolina Power & Light Co 83/02/10 O'REILLY, J P
Region 2, Office of Director 2pp 17180 219 24X
Fiche 50-325, 83/02/10, 8302170172

8302280250 Forwards LER 83-003/03L-0
DIETZ, C R Carolina Power & Light Co 83/02/15 O'REILLY, J P
Region 2, Office of Director 1p 17304 274 24X
Fiche 50-325, 83/02/15, 8302280250

--8302280257 LER 83-003/03L-0 on 830116, under reactor vessel insp revealed 17 low power range monitor detector cables separated from associated detectors. Caused by cables pulled loose from connectors during maint. Personnel informed.
PASTVA, M J Carolina Power & Light Co 83/02/15 Region 2,
Office of Director 1p 17304 275 24X Fiche 50-325, 83/02/15,
8302280250

8302240245 Forwards LER 83-002/03L-0
DIETZ, C R Carolina Power & Light Co 83/02/24 O'REILLY, J P
Region 2, Office of Director 1p 17272 288 24X
Fiche 50-325, 83/02/24, 8302240245

--8302240251 LER 83-002/03L-0 on 830114, during refueling outage, require ASME Section XI testing revealed six of 11 safety relief valves opened at higher than specified setpoints. Caused by corrosion buildup on pilot disc & seat surfaces.
PASTVA, M J Carolina Power & Light Co 83/02/24 Region 2,
Office of Director 2pp 17272 289 24X Fiche 50-325, 83/02/24,
8302240251

U Congressional/Executive Correspondence

8302230076 Responds to 821119 ltr expressing concern re Raychem-Flamtrak issue & requesting info on Commission actions to resolve matter. Issue will be handled as part of overall environ qualification review.
PALLADINO, N J Commissioners 83/01/25 PANETTA, L E House of
Rep 2pp 17259 275 24X Fiche 50-324, 83/01/25, 8302230076

--8302230082 Summary of 821130 meeting w/utill re use of Raychem-Flamtrak cables. NRC no longer considers all cables as being qualified for Class IE applications.
VILLALBA, I Events Analysis Branch 82/12/02 MILLS, W R Even
Analysis Branch 1p 17259 277 24X Fiche 50-324, 83/01/25,
8302230076

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicant for DLs, R&S vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
ETSENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-326 UNIV OF CALIFORNIA AT IRVINE RES. REACTOR

Q Inspection reports, IE Bulletins & correspondence

8302240144 Act receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-326/82-04.
BROOK, H E Division of Radiological Safety & Safeguards Program
83/02/15 HCOAUGH, J California, Univ of, Irvine 1p 17243 21
24X Fiche 50-326, 83/02/15, 8302240144

--8302230147 Responds to NRC 830105 ltr re violations noted in IE Insp Rept 50-326/82-04. Corrective actions reactor operations committee met on 821202 & 830107. Future meetings will be held on schedule.
LILLYMAN, W J California, Univ of, Irvine 83/02/02 Divis
of Radiological Safety & Safeguards Program 1p 17243 222 2
Fiche 50-326, 83/02/15, 8302230144

DOCKETED ITEMS

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

Security, medical, emergency & fire protection plans

301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

302190632 Ack receipt of 830201 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-327/82-31 & 50-328/82-31
VERRELLI, D M Division of Project & Resident Programs 83/02/10
PARRIS, H G Tennessee Valley Authority 1p 17154 133 24X
Fiche 50-327, 83/02/10, 8302150632

-8302150655 Responds to NRC 821229 ltr re violation noted in IE Insp Repts 50-327/82-31 & 50-328/82-31 Corrective actions worker badge properly signed, radiological incident rept filed & health physics training program conducted
MILLS, L M Tennessee Valley Authority 83/02/01 O'REILLY, J P
Region 2, Office of Director 3pp 17154 134 24X
Fiche 50-327, 83/02/10, 8302150632

-8302150678 IE Insp Repts 50-327/82-31 & 50-328/82-31 on 821106-1205 Noncompliance noted failure to train, determine prior dose & issue dosimetry to worker entering Unit 1 containment
FORD, E J, BUTLER, S D, QUICK, D R Division of Project & Resident Programs 82/12/29 6pp 17154 140 24X Fiche 50-327, 83/02/10, 8302150632

Insurance & indemnity information

302020009 Forwards Endorsement 30 to NFCLA Policy NF-247 & Endorsement 29 to MAELU Policy MF-102
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 83/01/21 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16992 058 24X Fiche 50-327, 83/01/21, 8302020009

Operating license stage documents & correspondence

302030053 Approves util 821227 request for withholding drawings referenced in OL amend request for vol reduction sys
Drawings contain trade secrets or proprietary info
ADENSA, E G Licensing Branch 4 83/01/27 PARRIS, H G Tennessee Valley Authority 3pp 17028 332 24X Fiche 50-327, 83/01/27, 302030053

3010587 Advises that updated FSAR will be submitted by 830415
MILLS, L M Tennessee Valley Authority 83/01/28 ADENSA, E
Licensing Branch 4 1p 16978 097 24X Fiche 50-327, 83/01/28, 302010587

02040041 Forwards proposed "Test Program to Demonstrate Operability in Spray Environ"
MILLS, L M Tennessee Valley Authority 83/01/31 ADENSA, E
Licensing Branch 4 1p 17020 393 24X Fiche 50-327, 83/01/31, 8302040041

8302040044 Proposed "Test Program to Demonstrate Operability in Spray Environ"
* Tennessee Valley Authority 83/01/31 3pp 17020 384 24X
Fiche 50-327, 83/01/31, 8302040044

02040056 Forwards revised Table 2 re operation of containment purge & venting sys for Mar & Apr 1982, per Amend 5 to SER
Previously submitted table contained erroneous data on containment entries
MILLS, L M Tennessee Valley Authority 83/01/31 ADENSA, E
Licensing Branch 4 2pp 17020 361 24X Fiche 50-327, 83/01/31, 8302040056

302070321 Forwards documentation of results of addl tests on Tayco igniter for permanent hydrogen mitigation sys & supporting basis for util belief that sys design adequate
MILLS, L M Tennessee Valley Authority 83/01/31, ADENSA, E
Licensing Branch 4 11pp 17029 197 24X Fiche 50-327, 83/01/31, 8302070321

302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 5: "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302150372 Forwards drawing depicting as-installed locations for igniters in ice condenser upper plenum for permanent hydrogen mitigation sys
MILLS, L M Tennessee Valley Authority 83/02/09 ADENSA, E
Licensing Branch 4 2pp 17157 190 24X Fiche 50-327, 83/02/09, 8302150372

8302160056 Advises that Class III fee appropriate for 821013 request for relief from ASME Section XI requirement to hydrostatically pressure test replacement portions of ERWC sys
DYGOS, R M License Fee Management Branch 83/02/10 PARRIS, H G
Tennessee Valley Authority 1p 17160 327 24X
Fiche 50-327, 83/02/10, 8302160056

8302230590 Notifies that util plans to remove ORNL on-line analyzer during Mar 1983 for installation of technical support ctr equipment in computer room
MILLS, L M Tennessee Valley Authority 83/02/17 ADENSA, E
Licensing Branch 4 1p 17255 205 24X Fiche 50-327, 83/02/17, 8302230590

8302280240 Forwards "Reactor Bldg Containment Integrated Leak Rate Test," conducted on 821208-09
MILLS, L M Tennessee Valley Authority 83/02/17 ADENSA, E
Licensing Branch 4 1p 17311 142 24X Fiche 50-327, 83/02/17, 8302280240

--8302280245 "Reactor Bldg Containment Integrated Leak Rate Test," conducted on 821203-09
* Tennessee Valley Authority 83/02/17 152pp 17311-144 24X
Fiche 50-327, 83/02/17, 8302280240

Q Inspection reports, IE Bulletins & correspondence

8302150153 Forwards IE Insp Repts 50-327/82-34 & 50-328/82-33 on 821213-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/05
PARRIS, H G Tennessee Valley Authority 2pp 17147 274 24X
Fiche 50-327, 83/01/05, 8302150153

--8302150181 IE Insp Repts 50-327/82-34 & 50-328/82-33 on 821213-16 No noncompliance noted Major areas inspected QC & confirmatory measurements, including review of radiochemical instrument calibr & QC program & review of radiochemical procedures
MONTGOMERY, D M, O'BSON, A F Division of Project & Resident Programs 83/01/04 6pp 17147 276 24X Fiche 50-327, 83/01/05, 8302150153

8302150296 Ack receipt of 821229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-25 & 50-328/82-24
LEWIS, R C Division of Project & Resident Programs 83/01/19
PARRIS, H G Tennessee Valley Authority 2pp 17148 251 24X
Fiche 50-327, 83/01/19, 8302150296

--8302150305 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-327/82-25 & 50-328/82-24 Corrective actions evaluation underway to modify or replace interlocks on doors A65 & A64 Preventive maint program established
MILLS, L M Tennessee Valley Authority 82/12/29 O'REILLY, J P
Region 2, Office of Director 3pp 17148 253 24X
Fiche 50-327, 83/01/19, 8302150296

--8302150311 Forwards IE Insp Repts 50-327/82-25 & 50-328/82-24 on 820906-1005 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/11/30
PARRIS, H G Tennessee Valley Authority 2pp 17148 256 24X
Fiche 50-327, 83/01/19, 8302150296

--8302150312 Notice of violation from insp on 820906-1005
* Division of Project & Resident Programs 82/11/30 1p
17148 258 24X Fiche 50-327, 83/01/19, 8302150296

DOCKETED ITEMS

191

--8302150320 IE Insp Repts 50-327/82-25 & 50-328/82-24 on 820906-1005 Noncompliance noted emergency gas treatment sys cleanup subvys not maintained Annulus door left open & obstructed by test equipment
FORD, E J , BUTLER, S D , COLLINS, T R Division of Project & Resident Programs 82/11/01 5pp 17148 259 24X
Fiche 50-327, 83/01/19, 8302150296

8302150463 Ack receipt of 830104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-28 & 50-328/82-28
LEWIS, R C Division of Project & Resident Programs 83/01/19
PARRIS, H O Tennessee Valley Authority 2pp 17157 092 24X
Fiche 50-327, 83/01/19, 8302150463

--8302150470 Responds to NRC 821206 ltr re violations noted in IE Insp Repts 50-327/82-28 & 50-328/82-28 Corrective actions valve 1-74-524 opened & RHR pump 1A-A inspected, safety-related equipment test procedure revised & door chain adjusted
KAMMER, D S Tennessee Valley Authority 83/01/04 O'REILLY, J P
Region 2, Office of Director 5pp 17157 054 24X
Fiche 50-327, 83/01/19, 8302150463

--8302150472 Forwards IE Insp Repts 50-327/82-28 & 50-328/82-28 on 821006-1105 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/12/06
PARRIS, H O Tennessee Valley Authority 2pp 17137 059 24X
Fiche 50-327, 83/01/19, 8302150463

--8302150478 Notice of violation from insp on 821006-1105
* Division of Project & Resident Programs 82/12/06 2pp
17157 061 24X Fiche 50-327, 83/01/19, 8302150463

--8302150482 IE Insp Repts 50-327/82-28 & 50-328/82-28 on 821006-1105 Noncompliance noted failure to maintain cognizance of sys status, failure to follow IMI-92-SRM-FT & failure to correct containment airlocks
FORD, E J , BUTLER, S D , QUICK, D R Division of Project & Resident Programs 82/12/01 9pp 17157 063 24X Fiche 50-327, 83/01/19, 8302150463

8302150510 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821903 ltr Dunbar-Reno Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150554 Submits revised response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Changeout of W-2 switches will be completed before startup after Unit 1 Cycle 2 refueling outage
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 1p 17156 148 24X
Fiche 50-327, 83/01/28, 8302150554

8302150632 Ack receipt of 830201 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-327/82-31 & 50-328/82-31
VERRELLI, D M Division of Project & Resident Programs 83/02/10
PARRIS, H O Tennessee Valley Authority 1p 17154 133 24X
Fiche 50-327, 83/02/10, 8302150632

--8302150655 Responds to NRC 821229 ltr re violation noted in IE Insp Repts 50-327/82-31 & 50-328/82-31 Corrective actions: worker badge properly signed, radiological incident rept filed & health physics training program conducted
MILLS, L M Tennessee Valley Authority 83/02/01 O'REILLY, J P
Region 2, Office of Director 3pp 17154 134 24X
Fiche 50-327, 83/02/10, 8302150632

--8302150653 Forwards IE Insp Repts 50-327/82-31 & 50-328/82-31 on 821106-1205 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/12/29
PARRIS, H O Tennessee Valley Authority 2pp 17154 137 24X
Fiche 50-327, 83/02/10, 8302150632

--8302150670 Notice of violation from insp on 821106-1205
* Division of Project & Resident Programs 82/12/27 1p
17154 139 24X Fiche 50-327, 83/02/10, 8302150632

--8302150678 IE Insp Repts 50-327/82-31 & 50-328/82-31 on 821106-1205 Noncompliance noted failure to train, determine prior dose & issue dosimetry to worker entering Unit 1 containment
FORD, E J , BUTLER, S D , QUICK, D R Division of Project & Resident Programs 82/12/27 8pp 17154 140 24X Fiche 50-327, 83/02/10, 8302150632

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302010368 RD 83-02 during functional test, discovered Ruskin Mfg Co vertical fire dampers will not completely close in ductwork w/high velocity air flow Installation of negator spring & positive blade latch recommended
GREEN, H J Tennessee Valley Authority 83/01/27 O'REILLY, J P
Region 2, Office of Director 2pp 16973 304 24X
Fiche 50-327, 83/01/27, 8302010368

8302030426 Forwards LER 82-144/03L-0
GREEN, H J Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 1p 17006 224 24X
Fiche 50-327, 83/01/28, 8302030426

--8302030439 LER 82-144/03L-0 on 821231, auxiliary bldg ventilation radiation monitor RM-70-101 declared inoperable due to loss of adequate flow Caused by tripped monitor pump motor starter switch Cause of overload not known
ROGERS, H R , HARDING, M R Tennessee Valley Authority 83/01/28
Region 2, Office of Director 1p 17006:225 24X
Fiche 50-327, 83/01/28, 8302030426

8302150524 Forwards LER 83-003/01T-0
GREEN, H J Tennessee Valley Authority, 83/02/04 O'REILLY, J P
Region 2, Office of Director 1p 17153 306 24X
Fiche 50-327, 83/02/04, 8302150524

--8302150536 LER 83-003/01T-0 on 830124, train A of ERCH effluent line radiation monitor (RM-70-133/140) declared inoperable due to alarm state Caused by inadequate surveillance instruction & Tech Spec misinterpretation
ROGERS, H R , HARDING, M R Tennessee Valley Authority, 83/02/04
Region 2, Office of Director 2pp 17153 307 24X
Fiche 50-327, 83/02/04, 8302150524

8302170141 Forwards LER 83-001/03L-0
GREEN, H J Tennessee Valley Authority 83/02/09 O'REILLY, J P
Region 2, Office of Director 1p 17180 175 24X
Fiche 50-327, 83/02/09, 8302170141

--8302170146 LER 83-001/03L-0 on 830113, during Mode 5, pressurizer safety valve 1-RV-48-565 not tested within setpoint lift setting limits Caused by relaxation of valve spring due to normal wear. New valve installed & tested
CARVER, A M , HARDING, M R Tennessee Valley Authority 83/02/09
Region 2, Office of Director 2pp 17180 176 24X
Fiche 50-327, 83/02/09, 8302170141

8302170182 RD-83-01 on 821214, diesel generator 28-B tripped on differential overcurrent On 821216, diesel generator 28-B started but failed to exceed 2,000-volt output. On 821219, diesel generator 18-B leaked oil from tes fitting
GREEN, H J Tennessee Valley Authority 83/02/09 O'REILLY, J P
Region 2, Office of Director 3pp 17180 131 24X
Fiche 50-327, 83/02/09, 8302170182

DOCKETED ITEMS

8302240254 Forwards LER 83-002/03L-0
GREEN, H J Tennessee Valley Authority 83/02/11 O'REILLY, J P
Region 2, Office of Director 1p 17273 361 24X
Fiche 50-327, 83/02/11, 8302240254

--8302240257 LER 83-002/03L-0 on 830115, two level switches discovered
out of tolerance during performance of Surveillance
Instruction 196 Caused by instrument drift for switch
1-LS-87-21 & bad micro switch for switch 1-LS-87-22
LUDWIG, W C , HARDING, M R Tennessee Valley Authority 83/02/11
Region 2, Office of Director 1p 17273 362 24X
Fiche 50-327, 83/02/11, 8302240254

8302240261 Forwards LER 83-009/01T-0
GREEN, H J Tennessee Valley Authority 83/02/11 O'REILLY, J P
Region 2, Office of Director 1p 17274 184 24X
Fiche 50-327, 83/02/11, 8302240261

--8302240266 LER 83-009/01T-0 on 830131, at 100% power, control rod
position indication sys inoperable when indicated position
for all rods deviated greater than 12 steps from actual
position Caused by degraded voltage conditions
CARVER, A H , HARDING, M R Tennessee Valley Authority 83/02/11
Region 2, Office of Director 1p 17274 185 24X
Fiche 50-327, 83/02/11, 8302240261

8302230109 Forwards LER 83-005/03L-0
GREEN, H J Tennessee Valley Authority 83/02/15 O'REILLY, J P
Region 2, Office of Director 1p 17243 269 24X
Fiche 50-327, 83/02/15, 8302230109

--8302230111 LER 83-005/03L-0 on 830117, turbine driven auxiliary
feedwater pump failed to achieve rated speed Caused by
electronic drift of signal converter gain potentiometer on
Woodward governor Potentiometer readjusted
HARDING, M R LUDWIG, W C Tennessee Valley Authority 83/02/15
Region 2, Office of Director 1p 17243 270 24X
Fiche 50-327, 83/02/15, 8302230109

8302230230 Forwards LER 83-010/03L-0
GREEN, H J Tennessee Valley Authority 83/02/16 O'REILLY, J P
Region 2, Office of Director 1p 17245 038 24X
Fiche 50-327, 83/02/16, 8302230230

--8302230233 LER 83-010/03L-0 on 830118, during performance of
surveillance instruction 7, diesel generator 1A-A tripped on
high water jacket temp Caused by ERCH valve 1-FCV-67-66
failing to open No cause found
LUDWIG, W C , HARDING, M R Tennessee Valley Authority 83/02/16
Region 2, Office of Director 1p 17245 039 24X
Fiche 50-327, 83/02/16, 8302230230

8302280150 Forwards LER 83-007/03L-0
GREEN, H J Tennessee Valley Authority 83/02/17 O'REILLY, J P
Region 2, Office of Director 1p 17306 077 24X
Fiche 50-327, 83/02/17, 8302280150

--8302280155 LER 83-007/03L-0 on 830119, w/unit in Mode 2, auxiliary
feedwater level control valve 1-LCV-3-164 failed to operate
Probably caused by dirty contacts Contacts cleaned
ROGERS, H R , HARDING, M R Tennessee Valley Authority 83/02/17
Region 2, Office of Director 1p 17306 078 24X
Fiche 50-327, 83/02/17, 8302280150

8302280159 Forwards LER 83-011/03L-0
GREEN, H J Tennessee Valley Authority 83/02/17 O'REILLY, J P
Region 2, Office of Director 1p 17306 037 24X
Fiche 50-327, 83/02/17, 8302280159

--8302280162 LER 83-011/03L-0 on 830120, one pressure switch for auxiliary
feedwater low suction pressure activation declared inoperable
due to failure to clear alarm Caused by failure of dual snap
Model 604 pressure switch contacts to reset Switch caller
ROGERS, H R , HARDING, M R Tennessee Valley Authority 83/02/17
Region 2, Office of Director 1p 17306 038 24X
Fiche 50-327, 83/02/17, 8302280159

8302280194 Forwards LER 83-012/03L-0
GREEN, H J Tennessee Valley Authority 83/02/18 O'REILLY, J P
Region 2, Office of Director 1p 17306 061 24X
Fiche 50-327, 83/02/18, 8302280194

--8302280200 LER 83-012/03L-0 on 830121, while in Mode 1, one feedwater
flow channel declared inoperable due to failing low Caused
by crossed sense lines to channel 1-FT-3-35A, due to
personnel error Lines corrected Personnel instructed
ROGERS, H R , HARDING, M R Tennessee Valley Authority 83/02/18
Region 2, Office of Director 1p 17306 062 24X
Fiche 50-327, 83/02/18, 8302280194

8302280457 Forwards LER 83-014/03L-0
GREEN, H J Tennessee Valley Authority 83/02/22 O'REILLY, J P
Region 2, Office of Director 1p 17309 215 24X
Fiche 50-327, 83/02/22, 8302280457

--8302280465 LER 83-014/03L-0 on 830122, kW meter for hydrogen recombiner
read offscale high Caused by failed active filter
LZFI-271105 due to aging Filter & potentiometer replaced
HARDING, M R , LUDWIG, W C Tennessee Valley Authority 83/02/22
Region 2, Office of Director 1p 17309 216 24X
Fiche 50-327, 83/02/22, 8302280457

V Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants
for DLs, MSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. or New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for DL & holders of CPs in regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. or New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302150632 Act receipt of 830201 ltr informing NRC of steps taken to
correct violation noted in IE Insp Repts 50-327/82-31 &
50-328/82-31
VERRELLI, D H Division of Project & Resident Programs 83/02/10
PARRIS, H O Tennessee Valley Authority 1p 17154 133 24X
Fiche 50-327, 83/02/10, 8302150632

--8302150655 Responds to NRC 821229 ltr re violation noted in IE Insp
Repts 50-327/82-31 & 50-328/82-31 Corrective actions worker
badge properly signed, radiological incident rept filed &
health physics training program conducted
MILLS, L M Tennessee Valley Authority 83/02/01 O'REILLY, J P
Region 2, Office of Director 3pp 17154 134 24X
Fiche 50-327, 83/02/10, 8302150632

--8302150678 IE Insp Repts 50-327/82-31 & 50-328/82-31 on 821106-1205
Noncompliance noted failure to train, determine prior dose &
issue dosimetry to worker entering Unit 1 containment
FORD, E J Division of Project & Resident Programs 82/12/29
4pp 17191 140 24X Fiche 50-327, 83/02/10, 8302150632

J Insurance & indemnity information

8302020009 Forwards Endorsement 30 to NELA Policy NF-247 & Endorsement
25 to MAELU Policy MF-102
DUCK, J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div
83/01/21 SALTZMAN, J Assistant Director for State & Licensee
Relations 3pp 16992 038 24X Fiche 50-327, 83/01/21, 8302020009

P Operating license stage documents & correspondence

8302030053 Approves until 821227 request for withholding drawings
referenced in OL amend request for vol reduction sys
Drawings contain trade secrets or proprietary info
ADENSAM, E O Licensing Branch 4 83/01/27 PARRIS, H O Tennessee
Valley Authority 3pp 17028 332 24X Fiche 50-327, 83/01/27,
8302030053

8302010587 Advises that updated FSAR will be submitted by 830415
MILLS, L M Tennessee Valley Authority 83/01/28 ADENSAM, E
Licensing Branch 4 1p 16978 097 24X Fiche 50-327, 83/01/28,
8302010587

8302040041 Forwards proposed "Test Program to Demonstrate Operability
in Spray Environ"
MILLS, L M Tennessee Valley Authority 83/01/31 ADENSAM, E
Licensing Branch 4 1p 17020 353 24X Fiche 50-327, 83/01/31,
8302040041

--8302040044 Proposed "Test Program to Demonstrate Operability in Spray
Environ"
" Tennessee Valley Authority 83/01/31 3pp 17020 354 24X
Fiche 50-327, 83/01/31, 8302040041

- 8302070321 Forwards documentation of results of addl tests on Tayco igniter for permanent hydrogen mitigation sys & supporting basis for util bolier? that sys design adequate
MILLS, L M Tennessee Valley Authority 83/01/31 ADENSAM, E
Licensing Branch 4 11pp 17029 157 24X Fiche 50-327, 83/01/31, 8302070321
- 8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
FISHER, J. D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295
- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
FISHER, J. D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304
- 8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item 11 K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
FISHER, J. D G Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085
- 8302150372 Forwards drawing depicting as-installed locations for igniters in ice condenser upper plenum for permanent hydrogen mitigation sys
MILLS, L M Tennessee Valley Authority 83/02/09 ADENSAM, E
Licensing Branch 4 2pp 1719/ 190 24X Fiche 50-327, 83/02/09, 8302150372
- 8302160084 Advises that Class III fee appropriate for 821013 request for relief from ASME Section I requirement to hydrostatically pressure test replacement portions of ERWC sys
DICKSON, R M License Fee Management Branch 83/02/10 PARRIS, H G
Tennessee Valley Authority 1p 17160 327 24X
Fiche 50-327, 83/02/10, 8302160084
- 8302240136 Forwards Amend 14 to License DPR-79, safety evaluation & notice of issuance & availability Amend changes license condition re control room design
ADENSAM, E G Operating Reactors Branch 4 83/02/16 PARRIS, H G
Tennessee Valley Authority 3pp 17288 289 24X
Fiche 50-328, 83/02/16, 8302240136
- 8302240143 Amend 14 to License DPR-79, changing condition of control room design to correct deficiencies of strip chart recorders Installation of data recording & logging equipment recommended
FISHER, J. D G Division of Licensing 83/02/16 2pp 17288 291
24X Fiche 50-328, 83/02/16, 8302240143
- 8302240148 Safety evaluation supporting Amend 14 to License DPR-79
* Office of Nuclear Reactor Regulation, Director 83/02/16 2pp
17288 295 24X Fiche 50-328, 83/02/16, 8302240148
- 8302240155 Notice of issuance & availability of Amend 14 to License DPR-79
ADENSAM, E G Operating Reactors Branch 4 83/02/16 2pp
17288 297 24X Fiche 50-328, 83/02/16, 8302240155
- 8302230590 Notifies that util plans to remove ORNL on-line analyzer during Mar 1983 for installation of technical support ctr equipment in computer room
MILLS, L M Tennessee Valley Authority 83/02/17 ADENSAM, E
Licensing Branch 4 1p 17255 205 24X Fiche 50-327, 83/02/17, 8302230590
- G Inspection reports, IE Bulletins & correspondence
- 8302030520 Provides info to satisfy requirements of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCFB of PWR Plants." Action Item 4 No indication of stress-corrosion cracking found
MARGALL, J R Arkansas Power & Light Co 82/12/31 COLLINS, J T
Region 4, Office of Director 3pp 17007 292 24X
Fiche 50-328, 82/12/31, 8302030520
- 8302190153 Forwards IE Insp Repts 50-327/82-34 & 50-328/82-33 on 821213-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/01/05
PARRIS, H G Tennessee Valley Authority 2pp 17147 274 24X
Fiche 50-327, 83/01/05, 8302190153
- 8302150181 IE Insp Repts 50-327/82-34 & 50-328/82-33 on 821213-16 No noncompliance noted Major areas inspected GC & confirmatory measurements, including review of radiochemical instrument calibr & GC program & review of radiochemical procedures
MONFORD, D M, O'BSON, A F Division of Project & Resident Programs 83/01/04 6pp 17147 276 24X Fiche 50-327, 83/01/05, 8302150181
- 8302190276 Ack receipt of 821229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-25 & 50-328/82-24
LEWIS, R C Division of Project & Resident Programs 83/01/19
PARRIS, H G Tennessee Valley Authority 2pp 17148 251 24X
Fiche 50-327, 83/01/19, 8302190276
- 8302150305 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-327/82-25 & 50-328/82-24 Corrective actions evaluation underway to modify or replace interlocks on doors A65 & A64 Preventive maint program established
MILLS, L M Tennessee Valley Authority 82/12/29 O'REILLY, J P
Region 2, Office of Director 3pp 17148 253 24X
Fiche 50-327, 83/01/19, 8302150305
- 8302150311 Forwards IE Insp Repts 50-327/82-25 & 50-328/82-24 on 820906-1005 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/11/30
PARRIS, H G Tennessee Valley Authority 2pp 17148 256 24X
Fiche 50-327, 83/01/19, 8302150311
- 8302150320 IE Insp Repts 50-327/82-25 & 50-328/82-24 on 820906-1005 Noncompliance noted emergency gas treatment sys cleanup subsys not maintained Annulus door left open & obstructed by test equipment
FORD, E J, BUTLER, S D, COLLINS, T R Division of Project & Resident Programs 82/11/01 9pp 17148 259 24X
Fiche 50-327, 83/01/19, 8302150320
- 8302150463 Ack receipt of 830104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-28 & 50-328/82-28
LEWIS, R C Division of Project & Resident Programs 83/01/19
PARRIS, H G Tennessee Valley Authority 2pp 17157 052 24X
Fiche 50-327, 83/01/19, 8302150463
- 8302150470 Responds to NRC 821206 ltr re violations noted in IE Insp Repts 50-327/82-28 & 50-328/82-28 Corrective actions valve 1-74-524 opened & RHR pump 1A-A inspected, safety-related equipment test procedure revised & door chain adjusted
KASHER, D S Tennessee Valley Authority 83/01/04 O'REILLY, J P
Region 2, Office of Director 5pp 17157 054 24X
Fiche 50-327, 83/01/19, 8302150470
- 8302150472 Forwards IE Insp Repts 50-327/82-28 & 50-328/82-28 on 821006-1105 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/12/06
PARRIS, H G Tennessee Valley Authority 2pp 17157 059 24X
Fiche 50-327, 83/01/19, 8302150472
- 8302150478 Notice of violation from insp on 821006-1105
* Division of Project & Resident Programs 82/12/06 2pp
17157 061 24X Fiche 50-327, 83/01/19, 8302150478
- 8302150482 IE Insp Repts 50-327/82-28 & 50-328/82-28 on 821006-1105 Noncompliance noted failure to maintain cognizance of sys status, failure to follow IMI-92-SRM-FT & failure to correct containment airlocks
FORD, E J, BUTLER, S D, QUICK, D R Division of Project & Resident Programs 82/12/01 9pp 17157 063 24X Fiche 50-327, 83/01/19, 8302150482
- 8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302150610
- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

DOCKETED ITEMS

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150554 Submits revised response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Changeout of W-2 switches will be completed before start-up after Unit 1 Cycle 2 refueling outage
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17156 148 24X Fiche 50-327, 83/01/28, 8302150554

8302190632 Ack receipt of 830201 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-327/82-31 & 50-328/82-31
VERRELL, D M Division of Project & Resident Programs 83/02/10
PARRIS, H G Tennessee Valley Authority 1p 17154 133 24X Fiche 50-327, 83/02/10, 8302150632

--8302150655 Responds to NRC 821229 ltr re violation noted in IE Insp Repts 50-327/82-31 & 50-328/82-31 Corrective actions worker badge properly signed, radiological incident rept filed & health physics training program conducted
MILLS, L M Tennessee Valley Authority 83/02/01 O'REILLY, J P Region 2, Office of Director 3pp 17154 134 24X Fiche 50-327, 83/02/10, 8302150655

--8302190663 Forwards IE Insp Repts 50-327/82-31 & 50-328/82-31 on 821106-1205 & notice of violation
VERRELL, D M Division of Project & Resident Programs 82/12/29
PARRIS, H G Tennessee Valley Authority 2pp 17154 137 24X Fiche 50-327, 83/02/10, 8302150663

--8302150670 Notice of violation from insp on 821106-1205
* Division of Project & Resident Programs 82/12/29 1p 17154 139 24X Fiche 50-327, 83/02/10, 8302150670

--8302150678 IE Insp Repts 50-327/82-31 & 50-328/82-31 on 821106-1205 Noncompliance noted failure to train/determine prior dose & issue dosimetry to worker entering Unit 1 containment
FORD, E J, BUTLER, S D, QUICK, D R Division of Project & Resident Programs 82/12/29 6pp 17154 140 24X Fiche 50-327, 83/02/10, 8302150678

12060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

1212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302030273 Forwards LER 82-142/03L-0
GREEN, H J Tennessee Valley Authority 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 17001 291 24X Fiche 50-328, 83/01/27, 8302030273

--8302030283 LER 82-142/03L-0 on 821229, while running Surveillance Instruction 166.1 for containment isolation valves, valves 2-FGV-68-305 failed to open Caused by faulty diaphragm Diaphragm replaced
LUDWIG, W C, HARDING, M R Tennessee Valley Authority 83/01/27 Region 2, Office of Director 1p 17001 252 24X Fiche 50-328, 83/01/27, 8302030273

8302030443 Revised final deficiency rept re geared limit switch covers melting in Electrodyn motor-operated valves Initially reported on 810224 Motor operators will be replaced Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17006 190 24X Fiche 50-328, 83/01/28, 8302030443

8302150544 Forwards LER 83-004/03L-0
GREEN, H J Tennessee Valley Authority 83/02/04 O'REILLY, J P Region 2, Office of Director 1p 17157 001 24X Fiche 50-328, 83/02/04, 8302150544

--8302150568 LER 83-004/03L-0 on 830107, boron concentration in refueling water storage tank discovered below 2,000 ppm limit Cause unknown Action initiated to revise procedures to ensure representative sampling
CARVER, A M, HARDING, M R Tennessee Valley Authority 83/02/04 Region 2, Office of Director 1p 17157 002 24X Fiche 50-328, 83/02/04, 8302150544

8302170182 RC-83-01 on 821214, diesel generator 2B-B tripped on differential overcurrent On 821216, diesel generator 2B-B started but failed to exceed 2,000-volt output On 821219, diesel generator 1B-B leaked oil from tee fitting
GREEN, H J Tennessee Valley Authority 83/02/09 O'REILLY, J P Region 2, Office of Director 3pp 17180 131 24X Fiche 50-327, 83/02/09, 8302170182

8302230551 Forwards LER 83-008/03L-0
GREEN, H J Tennessee Valley Authority 83/02/15 O'REILLY, J P Region 2, Office of Director 1p 17256 305 24X Fiche 50-328, 83/02/15, 8302230551

--8302230542 LER 83-008/03L-0 on 830118, while in Mode 1 during review of SI-90 32, discovered pressurized pressure channel 2-PS-68-334 out of tolerance on 821215 Cause unknown Channel monitored for bistable drift Setpoints reset
ROGERS, H R, HARDING, M R Tennessee Valley Authority 83/02/15 Region 2, Office of Director 1p 17256 306 24X Fiche 50-328, 83/02/15, 8302230551

8302280453 Forwards LER 83-006/03L-0
GREEN, H J Tennessee Valley Authority 83/02/17 O'REILLY, J P Region 2, Office of Director 1p 17309 224 24X Fiche 50-328, 83/02/17, 8302280453

--8302280471 LER 83-006/03L-0 on 830119, while in Mode 1, one main feedwater flow channel 2-FT-3-90A failed high Caused by frozen sense line, due to incorrect location of heat tracing thermocouples Thermocouples relocated
ROGERS, H R, HARDING, M R Tennessee Valley Authority 83/02/17 Region 2, Office of Director 1p 17309 225 24X Fiche 50-328, 83/02/17, 8302280453

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISEN, J T, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302240368 FOIA request for documents re 821121 IE insp rept
GARDE, B Government Accountability Project 82/12/14 Office of Administration 2pp 17289 222 24X Fiche 50-329, 82/12/14, 8302240368

8302080113 Board Notification 82-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic Safety and Licensing Board Panel 18pp 17105 335 24X Fiche 50-000, 82/12/30, 8302080113

8302080306 Comments on cost & safety issues Half of Unit 1 capacity used for Dow Chemical Co steam instead of electrical production Economic & safety problems caused by QA & const errors Supporting documentation encl
STAMIRIS, B Stamiris, B 83/01/30 DENTON, H Office of Nuclear Reactor Regulation, Director 13pp 17096 146 24X Fiche 50-329, 83/01/30, 8302080306

--8302080307 Forwards Gallagher 800121 memo re soil settlement problem for transmittal to ASLB members Further const should not be permitted until technical review complete
KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/05 THCRNBURGO, H D, Division of Reactor Operations Inspections 1p 17056 159 24X Fiche 50-329, 83/01/30, 8302080306

--8302080310 Forwards presentation matris distributed during 800116 meeting w/util & Bechtel re util response to 791119 supplemental 10CFR50.54(f) Questions 24-35
GALLAGHER, E J NRC - No Detailed Affiliation Given 80/01/21 FIDRELL, J O Region 3, Chicago, Reactor Construction & Engineering Support Branch 1p 17056 160 24X Fiche 50-329, 83/01/30, 8302080306

--B302060312 Discusses B20520 meeting w/Bechtel & util Licensee requested not to excavate below 0 duct bank Excavation discovered in progress B20728 Excavation involving relocation of fire line along svc water pump structure discovered on B20804 LAUSD SHANN, R B Region 3, Office of Director B2/08/24
SHAHER, W D Region 3, Office of Director Bpp 17056 161 24X
Fiche 50-329, B3/01/30, B302060306

B302030399 Forwards "Midland Vegetation Monitoring Program Preoperational Characterization of Vegetation & Vegetation Damage Syndromes in Vicinity of Midland Energy Ctr " COOK, J W Consumers Power Co B3/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17005 244 24X
Fiche 50-329, B3/01/31, B302030399

--B302030407 "Midland Vegetation Monitoring Program Preoperational Characterization of Vegetation & Vegetation Damage Syndromes in Vicinity of Midland Energy Ctr " * Consumers Power Co B2/12/30 46pp 17005 246 24X
Fiche 50-329, B3/01/31, B302030399

B302160187 'Seismic Margin Review Midland Energy Ctr Project, Vol VII Electrical, Control, Instrumentation & Mechanical Equipment Margins " CAMPBELL, R D, YEE, T, HARDY, G Structural Mechanics Associates SHA 13701 05R003 V07 B3/02/02 208pp 17161 213 24X
Fiche 50-329, B3/02/02, B302160187

B302180502 Forwards seismic margin review repts Vol I re methodology & criteria & Vol VII re electrical control instrumentation & mechanical equipment margins Encl incorporates NRC feedback from B10630 meeting & util B10725 ltr W/o encl COOK, J W Consumers Power Co B3/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17210 270 24X
Fiche 50-329, B3/02/04, B302180502

B302080275 Generic Ltr B3-09 to all operating reactor licensees, applicants for CL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl EISENHUT, D G Division of Licensing B3/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, B3/02/08, B302080275

B302090092 Generic Ltr B3-10E to all applicants w/DAW designed NSSB re resolution of TMI Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps " Bvc list encl EISENHUT, D G Division of Licensing B3/02/08 Consumers Power Co 25pp 17298 316 24X Fiche 50-000, B3/02/08, B302090092

B302250225 Requests authorization to begin auxiliary bldg underpinning Pier 11 const-related activities MILLER, D B Consumers Power Co B3/02/09 SHAHER, W D Region 3, Office of Director 1p 17293 064 24X Fiche 50-329, B3/02/09, B302250225

B302250245 Forwards proposed list of remedial soils work for B30214-0331 per NRC & util work authorization procedure Supplemental work activity list for Apr 1983 encl MILLER, D B Consumers Power Co B3/02/10 SHAHER, W D Region 3, Office of Director 13pp 17292 315 24X Fiche 50-329, B3/02/10, B302250245

B302160160 Authorizes proceeding w/remedial soil work activities (B207050387) scheduled for Feb 1983 Work activity list for Jan 1983 developed in compliance w/ASLB B20430 order encl SHAHER, W D Region 3, Office of Director B3/02/11 MILLER, D B Consumers Power Co 3pp 17162 061 24X Fiche 50-329, B3/02/11, B302160160

B302230492 Confirms B30118 conversation re util agreement that INPO self-initiated evaluation will be submitted to Region III w/INPO overview included Change necessitated by INPO request that participants submit evaluation first to INPO COOK, J W Consumers Power Co B3/02/11 KEPLER, J G Region 3, Office of Director 1p 17245 360 24X Fiche 50-329, B3/02/11, B302230492

B302230157 Discusses independent assessment of auxiliary bldg underpinning work on Piers W12 & E12 Based on observations & findings, assessment team of opinion that addl piers could be released for const LUCKS, A S Stone & Webster, Inc B3/02/14 KEPLER, J G Region 3, Office of Director 2pp 17243 293 24X Fiche 50-329, B3/02/14, B302230157

B302230161 Notifies that S&W & Parsons Brinckerhoff meet requirements of util Spec CC-100 re independence of assessment team for assessment of auxiliary bldg underpinning WILD, P A Stone & Webster, Inc B3/02/14 KEPLER, J G Region 3, Office of Director 2pp 17245 057 24X Fiche 50-329, B3/02/14, B302230161

B302240262 Forwards "QA Program Manual for Midland Nuclear Plant," Vol 1, Rev 13 COOK, J W Consumers Power Co B3/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17274 082 24X
Fiche 50-329, B3/02/14, B302240262

--B302240267 "QA Program Manual for Midland Nuclear Plant," Vol 1, Rev 13 COOK, J W, DEWITT, R B, LINCOLN, R C Consumers Power Co CPC-1-A Vol 1 R13 B3/02/17 99pp 17274 085 24X Fiche 50-329, B3/02/14, B302240262

B302230165 Forwards affidavits of members of S&W & Parsons Brinckerhoff assessment team who will perform independent assessment of auxiliary bldg underpinning work on Piers W12 & E12 LUCKS, A S Stone & Webster, Inc B3/02/15 KEPLER, J G Region 3, Office of Director 12pp 17245 072 24X Fiche 50-329, B3/02/15, B302230165

B302280169 Forwards "Midland Seismic Margin Earthquake Structural Evaluation Borated Water Storage Tank & Foundation," Vol VI COOK, J W Consumers Power Co B3/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17308 284 24X
Fiche 50-329, B3/02/16, B302280169

--B302280176 "Midland Seismic Margin Earthquake Structural Evaluation Borated Water Storage Tank & Foundation," Vol VI KENNEDY, R P, SHORT, S A, TONG, W Structural Mechanics Associates SHA 13701 05R003 V06 B2/11/30 83pp 17308 287 24X
Fiche 50-329, B3/02/16, B302280169

B302280239 Requests authorization to perform verification of post-tension loads in control tower, as part of remedial soils work MILLER, D B Consumers Power Co B3/02/16 SHAHER, W D Region 3, Office of Director 1p 17304 343 24X Fiche 50-329, B3/02/16, B302280239

B302230405 Confirms that listed environ qualification packages delivered separately to branch reviewer, per B30111-13 audit Programs detail process utilized in qualifying equipment for use in specific environ COOK, J W Consumers Power Co B3/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17247 005 24X
Fiche 50-329, B3/02/17, B302230405

B302230508 Forwards responses to NRC/EQ&O evaluation of util heavy load submittal Part I Responses to open items identified in B20816 technical evaluation rept will be submitted B30415 per B21001 telcon COOK, J W Consumers Power Co B3/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17246 171 24X
Fiche 50-329, B3/02/17, B302230508

B302250102 Notification of B30223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level VAN VLIET, J Operating Reactors Branch 4 B3/02/17 STOLZ, J Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, B3/02/17, B302250102

B302250230 Requests remedial soils work authorization for release of spring hanger for feedwater line & installation of temporary gauges during jacking MILLER, D B Consumers Power Co B3/02/17 SHAHER, W D Region 3, Office of Director 1p 17292 106 24X Fiche 50-329, B3/02/17, B302250230

B302280300 Requests authorization to begin work on "SWPS Underpinning Bldg Monitor-Install Conduit & Raceway " Review complete MILLER, D B Consumers Power Co B3/02/18 SHAHER, W D Region 3, Office of Director 1p 17313 039 24X Fiche 50-329, B3/02/18, B302280300

B302280527 Responds to B30217 request & forwards notarized S&W B21109 ltr to util concerning independent assessment of auxiliary bldg underpinning LUCKS, A S Stone & Webster, Inc B3/02/18 KEPLER, J G Region 3, Office of Director 4pp 17309 025 24X Fiche 50-329, B3/02/18, B302280527

B302280514 Lists remedial soils work activities scheduled for Feb 1983 Work activity list for B30214-0331 developed per ASLB B20430 order encl SHAHER, W D Region 3, Office of Director B3/02/22 MILLER, D B Consumers Power Co 6pp 17309 078 24X Fiche 50-329, B3/02/22, B302280514

B302170309 "Seismic Margin Review, Midland Energy Ctr Project-Methodology & Criteria," Vol 1, WESLEY, D A, CAMPBELL, R D, KENNEDY, R P Structural Mechanics Associates, SHA 13701 05R003 V01 B3/02/28 212pp 17178 229 24X Fiche 50-329, B3/02/28, B302170309

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302040093 Forwards "Sys Interaction Program for Midland Units 1 & 2," in response to NRC 820625 request & SER suppl (NUREG-0793) Rept also supp's applicant 821123 presentation to NRC
COOK, J W Consumers Power Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17021 253 24X
Fiche 50-329, 83/01/28, 8302040093

--8302040098 "Sys Interaction Program for Midland Units 1 & 2"
* Consumers Power Co 83/01/31 33pp 17021 255 24X
Fiche 50-329, 83/01/28, 8302040093

8302230241 Forwards proprietary info re CVN impact data for pressure vessel weld (W-70 as stated in plant FSAR to close SER Confirmatory Issue 11 Affidavit & summary of add'l data on sub'y also encl info withheld (ref 10CFR2 790)
COOK, J W Consumers Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 17242 349 24X
Fiche 50-329, 83/02/22, 8302230241

F Security, medical, emergency & fire protection plans

8302020445 Releases public version of notification of Emergency Plan exercise & appraisal postponement
FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 16999 298 24X Fiche 50-329, 83/01/31, 8302020445

--8302020451 Submits public version of notification of Emergency Plan exercise & appraisal postponement until sometime between Oct 1983 & Mar 1984, to fulfill timing requirements of 10CFR50, App E
COOK, J W Consumers Power Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16999 299 24X
Fiche 50-329, 83/01/31, 8302020445

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl I, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
CLSENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302040139 Add'l response to FOIA request for documents setting NRC policy re press releases in connection w/enforcement & licensing & media coverage of NRC hearings Review of remaining documents in progress
FELTON, J M Division of Rules and Records 83/01/12 HARTMAN, S Debevoise & Liberman 2pp 17043 338 24X Fiche 50-329, 83/01/12, 8302040139

--8302040161 Discusses pros & cons of permitting camera coverage of 780420-21 prehearing conference in Chicago, IL Coverage would not require amend of policy Procedure could be deemed unfair
YORE, J R Atomic Safety and Licensing Board Panel 78/03/28 KELLEY, J L, ROTHSCCHILD, I B Office of the Executive Legal Director 2pp 17043 344 24X Fiche 50-329, 83/01/12, 8302040139

8302040022 Further responses to 820830 Interrogatories Certificate of Svc encl
WILCOVE, M N Hearing Branch 2 83/01/14 Stamiris, B. 76pp 17021 101 24X Fiche 50-329, 83/01/14, 8302040022

8302040042 Response to 820913 Interrogatory Certificate of Svc encl
WILCOVE, M N Hearing Branch 2 83/01/14 Stamiris, B 21pp 17021 078 24X Fiche 50-329, 83/01/14, 8302040042

8302010503 Order extending time until 830207 for Commission to act to review ALAB-691
CHILK, S J Office of the Secretary of the Commission 83/01/28 Commissioners 1p 16981 322 24X Fiche 50-329, 83/01/28, 8302010503

8302080207 Response providing add'l info per agreement at Nov & Dec 1982 hearings Info includes list of Category I structures not included in seismic margin review, list of underground pipe & conduit hit by drill & quality improvement plan raw data
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 83/02/03 BECHHOEFER, C, COHAN, F P, HARBOR, J Atomic Safety and Licensing Board Panel 42pp 17058 057 24X
Fiche 50-329, 83/02/03, 8302080207

8302080212 Provides tentative agreement on witness scheduling for hearings starting on 830214, per 830202 telcon
STEPTOE, P P Isham, Lincoln & Beale 83/02/03 WILCOVE, M N Hearing Branch 2 2pp 17058 052 24X Fiche 50-329, 83/02/03, 8302080212

8302090247 Order extending time until 830214 for Commission to act to review ALAB-691
CHILK, S J Office of the Secretary of the Commission 83/02/07 Commissioners 1p 17070 257 24X Fiche 50-329, 83/02/07, 8302090247

8302180378 Forwards info util agreed to provide in Nov & Dec 1982 hearings, listed in 830203 ltr Certificate of Svc encl
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Consumers Power Co 83/02/14 BECHHOEFER, C, COHAN, F P, HARBOR, J Atomic Safety and Licensing Board Panel 26pp 17209 243 24X
Fiche 50-329, 83/02/14, 8302180378

--8302180382 Proposed transcript corrections for Nov & Dec 1982 hearings
* Consumers Power Co 83/02/14 48pp 17209 269 24X
Fiche 50-329, 83/02/14, 8302180378

8302220343 Statement of Commission CLI-83-2, closing record by declining review of issue of sanctions against util, Dow Chemical Co & counsel for improper conduct re preparations for show cause proceedings
CHILK, S J Office of the Secretary of the Commission 83/02/18 4pp 17228 002 24X Fiche 50-329, 83/02/18, 8302220343

G Inspection reports, IE Bulletins & correspondence

8302040039 Add'l response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/03 KEPLER, J G Region 3, Office of Director, 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARESKI, L Region 3, Office of Director 82/07/08 KEPLER, J G Region 3, Office of Director, 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302010617 Forwards IE Investigation Repts 50-329/82-13 & 50-330/82-13 on 820406-0617. No noncompliance noted
KEPLER, J G Region 3, Office of Director 83/01/18 COOK, J W Consumers Power Co 2pp 16978 259 24X Fiche 50-329, 83/01/18, 8302010617

--8302010623 IE Investigation Repts 50-329/82-13 & 50-330/82-13 on 820406-0617 No noncompliance noted Major areas inspected, underpinning instrumentation One oversize drawing encl Aperture card available in PDR
NEIL, C H, WARNICK, R F Region 3, Office of Director 82/09/14 143pp 16978 261 24X Fiche 50-329, 83/01/18, 8302010617

8302040225 Forwards IE Insp Repts 50-329/82-25 & 50-330/82-25 on 821129-30, 1201-03 & 08-10 No noncompliance noted
WARNICK, R F Region 3, Office of Director 83/01/20 COOK, J P Consumers Power Co 2pp 17020 107 24X Fiche 50-329, 83/01/20, 8302040225

--8302040235 IE Insp Repts 50-329/82-25 & 50-330/82-25 on 821129-30, 1201-03 & 08-10 No noncompliance noted Major areas inspected Class IE panels in auxiliary bldg, pipe hanger/snubber/restraints in containment & RCPB piping welding
SCHEIBELHUT, C, SIMON, J A, SATHER, A Region 3, Office of Director 83/01/20 6pp 17020 109 24X Fiche 50-329, 83/01/20, 8302040225

DOCKETED ITEMS

197

8302040323 Forwards IE Insp Repts 50-329/82-24 & 50-330/82-24 on 821125-1222 No noncompliance noted
WARNICK, R L Region 3, Office of Director 83/01/20 COOK, J W
Consumers Power Co 2pp 17018 192 24X Fiche 50-329, 83/01/20, 8302040323

--8302040330 IE Insp Repts 50-329/82-24 & 50-330/82-24 on 821125-1222 No noncompliance noted. Major areas inspected util const completion program, HVAC welder & procedure qualifications & allegations re electrical installation deficiencies
BURGESS, B L, COOK, R J, LANDSMAN, R B Region 3, Office of Director 83/01/14 5pp 17018 194 24X Fiche 50-329, 83/01/20, 8302040323

--8302040337 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 14 for 821219-25
LUCKS, A S Stone & Webster Engineering Corp 82/12/20 COOK, R NRC - No Detailed Affiliation Given 9pp 17018 199 24X
Fiche 50-329, 83/01/20, 8302040323

--8302040341 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 13 for 821212-18
LUCKS, A S Stone & Webster, Inc 82/12/20, COOK, R NRC - No Detailed Affiliation Given 9pp 17018 208 24X
Fiche 50-329, 83/01/20, 8302040323

--8302040343 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 12 for 821205-11
LUCKS, A S Stone & Webster, Inc 82/12/14 COOK, R NRC - No Detailed Affiliation Given 8pp 17018 217 24X
Fiche 50-329, 83/01/20, 8302040323

--8302040345 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 11 for 821128-1204
LUCKS, A S Stone & Webster, Inc 82/12/07 COOK, R NRC - No Detailed Affiliation Given 8pp 17018 225 24X
Fiche 50-329, 83/01/20, 8302040323

--8302040348 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 10 for 821121-27
LUCKS, A S Stone & Webster, Inc 82/11/29 COOK, R NRC - No Detailed Affiliation Given 8pp 17018 233 24X
Fiche 50-329, 83/01/20, 8302040323

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc. 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55. IE will conduct formal presentation followed by question & answer session. Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302080216 Forwards responses to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Final or status rept will be provided by 830731
COOK, J W Consumers Power Co 83/01/28 KEPLER, J G Region 3, Office of Director 125pp 17057 275 24X Fiche 50-329, 83/01/28, 8302080216

8302090451 EN-83-007 on 830208, notice of violation & proposed imposition of civil penalty in amount of \$120,000 to be issued Action based on failure to implement QA program re installation of electrical, mechanical & civil components
KILMOLER, O Director's Office, Office of Inspection and Enforcement 83/02/03 1p. 17066 287 24X Fiche 50-329, 83/02/03, 8302090451

8302250388 Forwards IE Insp Repts 50-329/82-26 & 50-330/82-26 on 821222-830121 No noncompliance noted
WARNICK, P F Region 3, Office of Director 83/02/11 COOK, J W Consumers Power Co. 2pp 17297 236 24X Fiche 50-329, 83/02/11, 8302250388

--8302250393 IE Insp Repts 50-329/82-26 & 50-330/82-26 on 821222-830121 No noncompliance noted. Major areas inspected remedial soils work, FIVP proof load, equipment qualification audit, auxiliary feedwater assembly & personnel safety
BURGESS, B L, COOK, R J, GARDNER, R N Region 3, Office of Director 83/02/11 7pp 17297 238 24X Fiche 50-329, 83/02/11, 8302250388

--8302250414 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 11 for 821219-25 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 82/12/28 COOK, R NRC - No Detailed Affiliation Given 9pp 17297 245 24X
Fiche 50-329, 83/02/11, 8302250388

--8302250421 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 15 for 821226-830101 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 83/01/05 COOK, R NRC - No Detailed Affiliation Given 7pp 17297 254 24X
Fiche 50-329, 83/02/11, 8302250388

--8302250427 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 16 for 830102-08 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 83/01/11 COOK, R NRC - No Detailed Affiliation Given 9pp 17297 261 24X
Fiche 50-329, 83/02/11, 8302250388

--8302250431 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 17 for 830109-15 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 83/01/18 COOK, R NRC - No Detailed Affiliation Given 10pp 17297 270 24X
Fiche 50-329, 83/02/11, 8302250388

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302250023 Board Notification 83-16 forwards notice of violation & proposed imposition of civil penalties re failure to implement adequate QA for installation of components in diesel generator bldg w/o encl
NOVAK, T M Assistant Director for Licensing 83/02/18 Atomic Safety and Licensing Board Panel 2pp 17302 300 24X
Fiche 50-329, 83/02/18, 8302250023

--8302250027 Forwards proposed civil penalty to be transmitted to board & parties w/o encl
EISENHUT, D G Division of Licensing 83/02/17 NOVAK, T M Assistant Director for Licensing 1p 17302 302 24X
Fiche 50-329, 83/02/18, 8302250023

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 118pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8 Reportable Occurrences, LERs & related correspondence

8302080305 Interim deficiency rept re underrated motor control ctr control circuit transformers could inadvertently supplied 50VA transformers Bechtel investigating root cause Next rept expected by 830506
COOK, J W Consumers Power Co 83/01/28 KEPLER, J G Region 3, Office of Director 9pp 17056 137 24X Fiche 50-329, 83/01/28, 8302080305

8302040307 Eighth interim deficiency rept re high energy line break analysis pipe whip restraint designs. Initially reported on 800917 Analysis complete on 92% of restraints Design drawings under rev Next rept due by 830506
COOK, J W Consumers Power Co 83/01/30 KEPLER, J G Region 3, Office of Director 9pp 17017 330 24X Fiche 50-329, 83/01/30, 8302040307

DOCKETED ITEMS

B302010329 Interim Rept 10 re underrated terminal strips on Limitorque valve operators Initially reported on B10213 All underrated terminal blocks replaced Next interim or final rept expected by B30316
COOK, J W Consumers Power Co BALLWEG, T, HUGHES, E M Bechtel Corp B3/01/30 KEPLER, J G Region 3, Office of Director 17pp 17019 084 24X Fiche 50-329, B3/01/30, B302040329

B302080205 Interim deficiency rept re loose locking clips Initially reported on B30104 Investigation revealed loose clips due to improper installation Condition determined not reportable under 10CFR21 Next rept expected by B30401
COOK, J W Consumers Power Co B3/01/30 KEPLER, J G Region 3, Office of Director 10pp 17058 099 24X Fiche 50-329, B3/01/30, B302080205

B302040328 Interim deficiency rept re accident temp effects on containment level measurement Investigation has limited need for corrective action to steam generator level transmitters Bechtel investigating string error Next rept by B30506
COOK, J W Consumers Power Co B3/02/01 KEPLER, J G Region 3, Office of Director 2pp 17018 237 24X Fiche 50-329, B3/02/01, B302040328

B302180456 Interim deficiency rept re O-related equipment cooled by non-Q HVAC sys Initially reported on B20625 Auxiliary bldg HVAC sys will be upgraded Next rept will be submitted by B30517
COOK, J W Consumers Power Co B3/02/09 KEPLER, J G Region 3, Office of Director 8pp 17210 262 24X Fiche 50-329, B3/02/09, B302180456

B302180500 Interim Deficiency Rept B3-02 re installation design of certain Class IE cabinets/panels Initially reported on B30112 Util verifying all cabinets/panels identified Final rept expected by B30516
COOK, J W Consumers Power Co B3/02/11 KEPLER, J G Region 3, Office of Director 8pp 17210 273 24X Fiche 50-329, B3/02/11, B302180500

T Hearing transcripts on non-antitrust matters

B302010557 Forwards CE McCracken testimony on Sinclair Contention 4
WRIGHT, N A Hearing Branch 2 B3/01/31 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16977 107 24X Fiche 50-329, B3/01/31, B302010557

--B302010564 Testimony of CE McCracken on Sinclair Contention 4 re degradation of steam tube integrity Measures taken to minimize steam generator corrosion due to water from cooling pond described
MCCRACKEN, C E Chemical Engineering Branch B3/01/31 8pp 16977 109 24X Fiche 50-329, B3/01/31, B302010557

B302170288 Transcript of B30214 hearing in Midland, MI Pp 11,229-11,458 Supporting documentation encl
* Atomic Safety and Licensing Board Panel B3/02/14 438pp 17177 112 24X Fiche 50-329, B3/02/14, B302170288

B302180378 Forwards info util agreed to provide in Nov & Dec 1982 hearings, listed in B30203 ltr Certificate of Svc encl
STEPDIE, P P Isham, Lincoln & Beale STEPDIE, P P Consumers Power Co B3/02/14 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 26pp 17209 243 24X Fiche 50-329, B3/02/14, B302180378

--B302180382 Proposed transcript corrections for Nov & Dec 1982 hearings
* Consumers Power Co B3/02/14 48pp 17209 269 24X Fiche 50-329, B3/02/14, B302180378

B302180390 Forwards testimony on Sinclair OL Contention 14
STEPDIE, P P Isham, Lincoln & Beale STEPDIE, P P Consumers Power Co B3/02/14 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 17210 032 24X Fiche 50-329, B3/02/14, B302180390

--B302180398 Testimony of DH Evans & DA Sommers re Sinclair OL Contention 14 Bechtel thermal performance study & plant cooling pond operation study not improperly influenced by data from substantially different climatic region
EVANS, D H, SOMMERS, D A Consumers Power Co EVANS, D H Bechtel Corp B3/02/10 23pp 17210 035 24X Fiche 50-329, B3/02/14, B302180390

--B302180403 Testimony of J Bradley re Sinclair OL Contention 1A on Dresden fogging & icing studies Conclusions in plant FEB re fog & ice not inconsistent w/Dresden cooling pond experience Certificate of Svc encl
BRADLEY, J Consumers Power Co BRADLEY, J Murray & Trettel, Inc B3/02/07 40pp 17210 057 24X Fiche 50-329, B3/02/14, B302180390

B302230676 Transcript of B30215 hearing in Midland, MI Pp 11,458-11,666 Supporting documentation encl
* Atomic Safety and Licensing Board Panel B3/02/15 246pp 17257 335 24X Fiche 50-329, B3/02/15, B302230676

B302230619 Transcript of B30216 hearing in Midland, MI Pp 11,667-11,870
* Atomic Safety and Licensing Board Panel B3/02/16 210pp 17255 255 24X Fiche 50-329, B3/02/16, B302230619

B302230665 Transcript of B30216 hearing in Midland, MI Pp 11,871-11,973
* Atomic Safety and Licensing Board Panel B3/02/16 106pp 17255 065 24X Fiche 50-329, B3/02/16, B302230665

B302230207 Transcript of B30217 hearing in Midland, MI Pp 11,970-12,179
* Atomic Safety and Licensing Board Panel B3/02/17 272pp 17244 003 24X Fiche 50-329, B3/02/17, B302230207

B302230214 Transcript of B30218 hearing in Midland, MI Pp 12,180-12,334
* Atomic Safety and Licensing Board Panel B3/02/18 178pp 17243 013 24X Fiche 50-329, B3/02/18, B302230214

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLS, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing B3/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, B3/01/31, B301310203

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

B302240368 FOIA request for documents re B21121 IE insp rept
OARDE, B Government Accountability Project B2/12/14 Office of Administration 2pp 17289 222 24X Fiche 50-329, B2/12/14, B302240368

B302080113 Board Notification B2-122A forwards USGS B21118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing B2/12/30 Atomic Safety and Licensing Board Panel 18pp 17105 335 24X Fiche 50-000, B2/12/30, B302080113

B302080306 Comments on cost & safety issues Half of Unit 1 capacity used for Du Chemical Co steam instead of electrical production Economic & safety problems caused by QA & const errors Supporting documentation encl
STAMIRIS, B Stamiris, B B3/01/30 DENTON, H Office of Nuclear Reactor Regulation, Director 13pp 17056 146 24X Fiche 50-329, B3/01/30, B302080306

--B302080307 Forwards Gallagher B00121 memo re soil settlement problem for transmittal to ASLB members Further const should not be permitted until technical review complete
KEPLER, J G Region 3, Chicago, Office of the Director B0/03/05 THORNBURG, H D Division of Reactor Operations Inspections 1p 17055 159 24X Fiche 50-329, B3/01/30, B302080306

--B302080310 Forwards presentation matls distributed during B00116 meeting w/util & Bechtel re util response to 791119 supplemental 10CFR50.54(f) Questions 24-35.
GALLAGHER, E J NRC - No Detailed Affiliation Given B0/01/21 FIGURELL, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 1p 17056 160 24X Fiche 50-329, B3/01/30, B302080306

--B302080312 Discusses B20520 meeting w/Bechtel & util Licensee requested not to excavate below G duct bank Excavation discovered in progress B20728 Excavation involving relocation of fire line along svc water pump structure discovered on B20804
LANDSMAN, B Region 3, Office of Director B2/08/24 SHAFER, W D Region 3, Office of Director 8pp 17056 161 24X Fiche 50-329, B3/01/30, B302080306

B302030399 Forwards "Midland Vegetation Monitoring Program Preoperational Characterization of Vegetation & Vegetation Damage Syndromes in Vicinity of Midland Energy Ctr"
COOK, J W Consumers Power Co B3/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17005 244 24X Fiche 50-329, B3/01/31, B302030399

DOCKETED ITEMS

199

--B302030407 'Midland Vegetation Monitoring Program Preoperational Characterization of Vegetation & Vegetation Damage Syndromes in Vicinity of Midland Energy Ctr
Consumers Power Co 8/2/12/30 46pp 17005 246 24X
Fiche 50-329, 83/01/31, 8302030399

B302160187 "Seismic Margin Review Midland Energy Ctr Project, Vol VII Electrical, Control, Instrumentation & Mechanical Equipment Margins
CAMPBELL, R D, YEE, T, HARDY, G Structural Mechanics Associates
SMA 13701 05R003 V07 83/02/02 208pp 17161 213 24X
Fiche 50-329, 83/02/02, 8302160187

B302180502 Forwards seismic margin review repts Vol I re methodology & criteria & Vol VII re electrical control instrumentation & mechanical equipment margins Encl incorporates NRC feedback from 810630 meeting & util 810725 ltr w/p encl
COOK, J W Consumers Power Co 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17210 270 24X
Fiche 50-329, 83/02/04, 8302180502

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

B302090092 Generic Ltr 83-10E to all applicants w/B&W designed NSSS re resolution of TMI Action, Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consumers Power Co 25pp 17298 316 24X Fiche 50-000, 83/02/08, 8302090092

B302250225 Requests authorization to begin auxiliary bldg underpinning for 11 const related activities
MILLER, D B Consumers Power Co 83/02/09 SHAFER, W D Region 3, Office of Director 1p 17293 054 24X Fiche 50-329, 83/02/09, 8302250225

B302250245 Forwards proposed list of remedial soils work for 830214-0531 per NRC & util work authorization procedure Supplemental work activity list for Apr 1983 encl
MILLER, D B Consumers Power Co 83/02/10 SHAFER, W D Region 3, Office of Director 13pp 17292 315 24X Fiche 50-329, 83/02/10, 8302250245

B302160160 Authorizes proceeding w/remedial soil work activities (20/0507/87) scheduled for Feb 1983 Work activity list for Jan 1983 developed in compliance w/ASLB 820430 order encl
SHAFER, W D Region 3, Office of Director 83/02/11 MILLER, D B Consumers Power Co 3pp 17162 061 24X Fiche 50-329, 83/02/11, 8302160160

B302230492 Confirms 830118 conversation re util agreement that INPO self-initiated evaluation will be submitted to Region III w/INPO overview included Change necessitated by INPO request that participants submit evaluation first to INPO
COOK, J W Consumers Power Co 83/02/11 KEPPNER, J O Region 3, Office of Director 1p 17245 360 24X Fiche 50-329, 83/02/11, 8302230492

B302230157 Discusses independent assessment of auxiliary bldg underpinning work on Piers W12 & E12 Based on observations & findings, assessment team of opinion that add'l piers could be released for const
LUCKS, A S Stone & Webster, Inc 83/02/14 KEPPNER, J O Region 3, Office of Director 2pp 17243 253 24X Fiche 50-329, 83/02/14, 8302230157

B302230161 Notifies that S&W & Parsons Brinckerhoff meet requirements of util Spec CC-100 re independence of assessment team for assessment of auxiliary bldg underpinning
WILCOX, P A Stone & Webster, Inc 83/02/14 KEPPNER, J O Region 3, Office of Director 2pp 17243 057 24X Fiche 50-329, 83/02/14, 8302230161

B302240262 Forwards "QA Program Manual for Midland Nuclear Plant," Vol I, Rev 13
COOK, J W Consumers Power Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17274 082 24X
Fiche 50-329, 83/02/14, 8302240262

--B302240267 "QA Program Manual for Midland Nuclear Plant," Vol I, Rev 13
COOK, J W, DEWITT, R B, LINCOLN, R C Consumers Power Co CPC-1-A Vol I R13 83/02/17 59pp 17274 085 24X Fiche 50-329, 83/02/14, 8302240267

B302230165 Forwards affidavits of members of S&W & Parsons Brinckerhoff assessment team who will perform independent assessment of auxiliary bldg underpinning work on Piers W12 & E12
LUCKS, A S Stone & Webster, Inc 83/02/15 KEPPNER, J O Region 3, Office of Director 12pp 17245 072 24X Fiche 50-329, 83/02/15, 8302230165

B302280169 Forwards "Midland Seismic Margin Earthquake Structural Evaluation Borated Water Storage Tank & Foundation," Vol VI
COOK, J W Consumers Power Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17308 284 24X
Fiche 50-329, 83/02/16, 8302280169

--B302280176 "Midland Seismic Margin Earthquake Structural Evaluation Borated Water Storage Tank & Foundation," Vol VI
KENNEDY, R P, SHORT, S A, TONG, W Structural Mechanics Associates, SMA 13701 05R003 V06 82/11/30 83pp 17308 287 24X
Fiche 50-329, 83/02/16, 8302280176

B302280239 Requests authorization to perform verification of post-tension loads in control tower, as part of remedial soils work
MILLER, D B Consumers Power Co 83/02/16 SHAFER, W D Region 3, Office of Director 1p 17304 343 24X Fiche 50-329, 83/02/16, 8302280239

B302230405 Confirms that listed environ qualification packages delivered separately to branch reviewer, per 830111-13 audit Programs detail process utilized in qualifying equipment for use in specific environ
COOK, J W Consumers Power Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17247 005 24X
Fiche 50-329, 83/02/17, 8302230405

B302230508 Forwards responses to NRC/EQ&O evaluation of util heavy load submittal Part I Responses to open items identified in 820816 technical evaluation rpt will be submitted 830415 per 821001 telcon
COOK, J W Consumers Power Co 83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17246 171 24X
Fiche 50-329, 83/02/17, 8302230508

B302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint or proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302250102

B302250230 Requests remedial soils work authorization for release of spring hanger for feedwater line & installation of temporary gauges during jacking
MILLER, D B Consumers Power Co 83/02/17 SHAFER, W D Region 3, Office of Director 1p 17292 106 24X Fiche 50-329, 83/02/17, 8302250230

B302280300 Requests authorization to begin work on, "SNPS Underpinning Bldg Monitor-Install Conduit & Raceway" Review complete
MILLER, D B Consumers Power Co 83/02/18 SHAFER, W D Region 3, Office of Director 1p 17313 039 24X Fiche 50-329, 83/02/18, 8302280300

B302280527 Responds to 830217 request & forwards notarized S&W 821107 ltr to util concerning independent assessment of auxiliary bldg underpinning
LUCKS, A S Stone & Webster, Inc 83/02/18 KEPPNER, J O Region 3, Office of Director 4pp 17309 025 24X Fiche 50-329, 83/02/18, 8302280527

B302280514 Lists remedial soils work activities scheduled for Feb 1983. Work activity list for 830214-0331 developed per ASLB 820430 order encl
SHAFER, W D Region 3, Office of Director 83/02/22 MILLER, D B Consumers Power Co 6pp 17309 078 24X Fiche 50-329, 83/02/22, 8302280514

B302170309 "Seismic Margin Review, Midland Energy Ctr Project-Methodology & Criteria," Vol I
WESLEY, D A, CAMPBELL, R D, KENNEDY, R P Structural Mechanics Associates SMA 13701 05R003 V01, 83/02/28 212pp 17178, 229, 24X Fiche 50-329, 83/02/28, 8302170309

E NRC Safety Evaluation Report (SER), suppls & correspondence

B302040093 Forwards "Sys Interaction Program for Midland Units 1 & 2," in response to NRC 820623 request & SER suppl (NUREG-0793) Rpt also suppls applicant 821123 presentation to NRC
COOK, J W Consumers Power Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17021 253, 24X
Fiche 50-329, 83/01/28, 8302040093

DOCKETED ITEMS

--830204098 'Sys. Interaction Program for Midland Units 1 & 2 "
Consumers Power Co 83/01/31 33pp 17021 255 24X
Fiche 50-329,83/01/28,830204098

8302230241 Forwards proprietary info re GVN impact data for pressure vessel weld WF-70 as stated in plant FSAR to close SER
Conformity Issue 11 Affidavit & summary of addl data on sub; also encl Intro withheld (ref 10CFR2 790)
COOK, J M Consumers Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 17242 349 24X
Fiche 50-329,83/02/22,8302230241

F Security, medical, emergency & fire protection plans

8302020445 Releases public version of notification of Emergency Plan exercise & appraisal postponement
FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 16999 298 24X Fiche 50-329,83/01/31, 8302020445

--8302020451 Submits public version of notification of Emergency Plan exercise & appraisal postponement until sometime between Oct 1983 & Mar 1984, to fulfill timing requirements of 10CFR50, App E
COOK, J M Consumers Power Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16999 299 24X
Fiche 50-329,83/01/31,8302020445

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for CL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000,83/02/01,8301210340

G Adjudicatory correspondence

8302040139 Addl response to FOIA request for documents setting NRC policy re press releases in connection w/enforcement & licensing & media coverage of NRC hearings Review of remaining documents in progress
FELTON, J M Division of Rules and Records 83/01/12 HARTMAN, S Debevoise & Liberman 2pp 17043 338 24X Fiche 50-329,83/01/12, 8302040139

--8302040161 Discusses pros & cons of permitting camera coverage of 780420-21 prehearing conference in Chicago, IL Coverage would not require amend of policy Procedure could be deemed unfair
YORE, J R Atomic Safety and Licensing Board Panel 78/03/28 KELLEY, J L, ROTHSCCHILD, I B Office of the Executive Legal Director 2pp 17043 344 24X Fiche 50-329,83/01/12,8302040139

8302040072 Further responses to 820830 interrogatory Certificate of Svc encl
WILCOVE, M N Hearing Branch 2 83/01/14 Stamiris, B 96pp 17021 101 24X Fiche 50-329,83/01/14,8302040022

8302040012 Response to 820913 interrogatory Certificate of Svc encl
WILCOVE, M N Hearing Branch 2 83/01/14 Stamiris, B 21pp 17021 078 24X Fiche 50-329,83/01/14,8302040042

8302010503 Order extending time until 830207 for Commission to act to review ALAB-691
CHILK, S J Office of the Secretary of the Commission 83/01/28 Commissioners 1p 16981 322 24X Fiche 50-329,83/01/28, 8302010503

8302080207 Response providing addl info per agreement at Nov & Dec 1982 hearings Info includes list of Category I structures not included in seismic margin review, list of underground pipe & conduit hit by drill & quality improvement plan raw data
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 83/02/03 BECHTOLD, C, COOK, J M, HARBOUR, J Atomic Safety and Licensing Board Panel 42pp 17058 057 24X
Fiche 50-329,83/02/03,8302080207

8302080212 Provides tentative agreement on witness scheduling for hearings starting on 830214, per 830202 telcon
STEPTOE, P P Isham, Lincoln & Beale 83/02/03 WILCOVE, M N Hearing Branch 2 2pp 17058 052 24X Fiche 50-329,83/02/03, 8302080212

8302020247 Order extending time until 830214 for Commission to act to review ALAB-691
CHILK, S J Office of the Secretary of the Commission 83/02/07 Commissioners 1p 17070 257 24X Fiche 50-329,83/02/07, 8302020247

8302180378 Forwards info util agreed to provide in Nov & Dec 1982 hearings, listed in 830203 ltr Certificate of Svc encl
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Consumers Power Co 83/02/14 BECHTOLD, C, COOK, J M, HARBOUR, J Atomic Safety and Licensing Board Panel 26pp 17209 243 24X
Fiche 50-329,83/02/14,8302180378

8302220343 Statement of Commission CL1-83-2, closing record by declining review or issue or sanctions against Util, Dow Chemical Co & counsel re improper conduct re preparations for show cause proceedings
CHILK, S J Office of the Secretary of the Commission 83/02/18 4pp 17228 002 24X Fiche 50-329,83/02/18,8302220343

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/ contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000,82/12/30,8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000,82/12/30,8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/04/08 SPICER, R L Division of Project & Resident Programs 2pp 17045 219 24X Fiche 50-000,82/12/30,8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50 000,82/12/30,8302040039

8302010617 Forwards IE Investigation Repts 50-329/82-13 & 50-330/82-17 on 820406-0617 No noncompliance noted
KEPLER, J O Region 3, Office of Director 83/01/18 COOK, J M Consumers Power Co 2pp 16978 259 24X Fiche 50-329,83/01/18, 8302010617

--8302010623 IE Investigation Repts 50-329/82-13 & 50-330/82-13 on 820406-0617 No noncompliance noted Major areas inspected underpinning instrumentation One oversize drawing encl
Aperture card available in PDR
WILL, C H, WARRICK, R F Region 3, Office of Director 82/09/14 143pp 16978 261 24X Fiche 50 329,83/01/18,8302010617

8302040225 Forwards IE Insp Repts 50 329/82-25 & 50-330/82-25 on 821127-30, 1201-03 & 08-10 No noncompliance noted
WARRICK, R F Region 3, Office of Director 83/01/20 COOK, J M Consumers Power Co 2pp 17020 107 24X Fiche 50-329,83/01/20, 8302040225

--8302040235 IE Insp Repts 50-329/82-25 & 50-330/82-25 on 821127-30, 1201-03 & 08-10 No noncompliance noted Major areas inspected Class IE panels in auxiliary bldg, pipe hanger/ snubber/restraints in containment, RCPD piping welding
SCHEIDT, C, SIKON, J A, SATHER, A Region 3, Office of Director 83/01/20 6pp 17020 109 24X Fiche 50-329,83/01/20, 8302040225

8302040323 Forwards IE Insp Repts 50 329/82-24 & 50-330/82-24 on 821125-1222 No noncompliance noted
WARRICK, R L Region 3, Office of Director 83/01/20 COOK, J M Consumers Power Co 2pp 17018 192 24X Fiche 50-329,83/01/20, 8302040323

--8302040330 IE Insp Repts 50-329/82-24 & 50-330/82-24 on 821125-1222 No noncompliance noted Major areas inspected util const completion program, HVAC welder & procedure qualifications & allegations re electrical installation deficiencies
BURGES, G L, COOK, J M, LANDSMAN, R B Region 3, Office of Director 83/01/14 3pp 17018 194 24X Fiche 50-329,83/01/20, 8302040323

--8302040337 Forwards independent assessment of auxiliary bldg underpinning, Weekly Rept 14 for 821129-25
LUCKS, A S Stone & Webster, Inc 82/12/20 COOK, R NRC - No Detailed Affiliation Given 9pp 17018 199 24X
Fiche 50-329,83/01/20,8302040323

DOCKETED ITEMS

201

--B302040341 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 13 for 821212-18
LUCKS, A S Stone & Webster, Inc 82/12/20 COOK, R NRC - No Detailed Affiliation Given 9pp 17018 208 24X
Fiche 50-329, 83/01/20, 8302040323

--B302040343 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 12 for 821205-11
LUCKS, A S Stone & Webster, Inc 82/12/14 COOK, R NRC - No Detailed Affiliation Given 8pp 17018 217 24X
Fiche 50-329, 83/01/20, 8302040323

--B302040345 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 11 for 821128-1204
LUCKS, A S Stone & Webster, Inc 82/12/07 COOK, R NRC - No Detailed Affiliation Given 8pp 17018 225 24X
Fiche 50-329, 83/01/20, 8302040323

--B302040348 Forwards independent assessment of auxiliary bldg underpinning Weekly Rept 10 for 821121-27
LUCKS, A S Stone & Webster, Inc 82/11/29 COOK, R NRC - No Detailed Affiliation Given 4pp 17018 233 24X
Fiche 50-329, 83/01/20, 8302040323

B212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

B212060360 IE Info Notice 83-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360.

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

B302030303 Advises of B30207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESERD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 18/ 24X Fiche 50-000, 83/01/28, 8302030303

B302080216 Forwards responses to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Final or status rept will be provided by 830731
COOK, J W Consumers Power Co 83/01/28 KEPLER, J O Region 3, Office of Director 125pp 17057 275 24X Fiche 50-329, 83/01/28, 8302080216

B302090451 EN-83-007 on 830208, notice of violation & proposed imposition of civil penalty in amount of \$120,000 to be issued Action based on failure to implement GA program re installation of electrical, mechanical & civil components
KLINGLER, O Director's Office, Office of Inspection and Enforcement 83/02/03 1p 17066 287 24X Fiche 50-329, 83/02/03, 8302090451

B302250398 Forwards IE Insp Repts 80-329/82-26 & 50-330/82-26 on 821222-830121 No noncompliance noted
WARNICK, P F Region 3, Office of Director 83/02/11 COOK, J W Consumers Power Co 2pp 17297 236 24X Fiche 50-329, 83/02/11, 8302250398

--B302250414 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 14 for 821219-25. Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 82/12/28 COOK, R NRC - No Detailed Affiliation Given 9pp 17297 243 24X
Fiche 50-329, 83/02/11, 8302250398

--B302250421 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 15 for 821226-830101 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 83/01/05 COOK, R NRC - No Detailed Affiliation Given 7pp 17297 254 24X
Fiche 50-329, 83/02/11, 8302250398

--B302250427 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 16 for 830102-08 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp 83/01/11, COOK, R NRC - No Detailed Affiliation Given 9pp 17297 261 24X
Fiche 50-329, 83/02/11, 8302250398

--B302250431 Forwards independent assessment of Auxiliary Bldg Underpinning Weekly Rept 17 for 830109-15 Minutes of daily meetings w/assessment team & site engineering personnel encl
LUCKS, A S Stone & Webster Engineering Corp. 83/01/18 COOK, R NRC - No Detailed Affiliation Given 10pp 17297 270 24X
Fiche 50-329, 83/02/11, 8302250398

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

B302250023 Board Notification 83-16 forwards notice of violation & proposed imposition of civil penalties re failure to implement adequate QA for installation of components in diesel generator bldg W/o encl
NOVAK, T M Assistant Director for Licensing 83/02/18 Atomic Safety and Licensing Board Panel 2pp 17302 300 24X
Fiche 50-329, 83/02/18, 8302250023

--B302250027 Forwards proposed civil penalty to be transmitted to board & parties N/a encl
ETENHUT, D O Division of Licensing 83/02/17, NOVAK, T M Assistant Director for Licensing 1p 17302, 302 24X
Fiche 50-329, 83/02/18, 8302250023

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste ~ 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366.

S Reportable occurrences, LERs & related correspondence

B302080305 Interim deficiency rept re underrated motor control ctr control circuit transformers could inadvertently supplied
NOVA transformers Bechtel investigating root cause Next rept expected by 830506
COOK, J W Consumers Power Co 83/01/28 KEPLER, J O Region 3, Office of Director 9pp 17056 137 24X Fiche 50-329, 83/01/28, 8302080305

B302040307 Eighth interim deficiency rept re high energy line break analysis pipe whip restraint designs initially reported on 800919 Analysis complete on 92% of restraints Design drawings under rev Next rept due by 830506
COOK, J W Consumers Power Co 83/01/30 KEPLER, J O Region 3, Office of Director 9pp 17017 350 24X Fiche 50-329, 83/01/30, 8302040307

B302040329 Interim Rept 10 re underrated terminal strips on Limitorque valve operators. Initially reported on 810213 All underrated terminal blocks replaced Next interim or final rept expected by 830316
COOK, J W Consumers Power Co BALLWED, T, HUQHEB, E M Bechtel Corp 83/01/30 KEPLER, J O Region 3, Office of Director 17pp 17019 084 24X Fiche 50-329, 83/01/30, 8302040329

B302080205 Interim deficiency rept re loose locking clips Initially reported on 830104 Investigation revealed loose clips due to improper installation Condition determined not reportable under 10CFR21 Next rept expected by 830401
COOK, J W Consumers Power Co 83/01/30 KEPLER, J O Region 3, Office of Director 10pp 17058 079 24X Fiche 50-329, 83/01/30, 8302080205

B302040328 Interim deficiency rept re accident temp effects on containment level measurement Investigation has limited need for corrective action to steam generator level transmitters. Bechtel investigating string error Next rept by 830506
COOK, J W Consumers Power Co 83/02/01 KEPLER, J O Region 3, Office of Director 2pp 17018 237 24X Fiche 50-329, 83/02/01, 8302040328

B302180456 Interim deficiency rept re Q-related equipment cooled by non-Q HVAC sys Initially reported on 820625 Auxiliary bldg HVAC sys will be upgraded Next rept will be submitted by 830317
COOK, J W Consumers Power Co 83/02/09 KEPLER, J O Region 3, Office of Director 8pp 17210 262 24X Fiche 50-329, 83/02/09, 8302180456

DOCKETED ITEMS

B302180500 Interim Deficiency Rept B3-02 re installation design of certain Class IE cabinets/panels. Initially reported on B30112 Util verifying all cabinets/panels identified Final rept expected by B30516
COOK, J. W. Consumers Power Co B3/02/11 KEPLER, J. O. Region 3, Office of Director Bpp 17210 273 24X Fiche 50-329, B3/02/11, B302180500

T Hearing transcripts on non-antitrust matters

B302010557 Forwards CE McCracken testimony on Sinclair Contention 4, HRIGHT, N. A. Hearing Branch 2 B3/01/31 BECHHOEFER, C. COWAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 16977 107 24X Fiche 50-329, B3/01/31, B302010557

--B302010564 Testimony of CE McCracken on Sinclair Contention 4 re degradation of steam tube integrity Measures taken to minimize steam generator corrosion due to water from cooling pond described
MCCRACKEN, C. E. Chemical Engineering Branch B3/01/31 Bpp 16977 109 24X Fiche 50-329, B3/01/31, B302010557

B302170288 Transcript of B30214 hearing in Midland, MI Pp 11,229-11,458 Supporting documentation encl
* Atomic Safety and Licensing Board Panel B3/02/14 438pp 17177 112 24X Fiche 50-329, B3/02/14, B302170288

B302180378 Forwards info util agreed to provide in Nov & Dec 1982 hearings, listed in B30203 ltr Certificate of Svc encl
STEPHENS, P. P. Isham, Lincoln & Beale B3/02/14 BECHHOEFER, C. Atomic Safety and Licensing Board Panel 26pp 17209 243 24X Fiche 50-329, B3/02/14, B302180378

--B302180382 Proposed transcript corrections for Nov & Dec 1982 hearings
* Consumers Power Co B3/02/14 48pp 17209 269 24X Fiche 50-329, B3/02/14, B302180378

B302180390 Forwards testimony on Sinclair OL Contention 14
STEPHENS, P. P. Isham, Lincoln & Beale STEPHENS, P. P. Consumers Power Co B3/02/14 BECHHOEFER, C. COWAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel 3pp 17210 032 24X Fiche 50-329, B3/02/14, B302180390

--B302180398 Testimony of DH Evans & DA Sommers re Sinclair OL Contention 14 Bechtel thermal performance study & plant cooling pond operation study not improperly influenced by data from substantially different climatic region
EVANS, D. H., SOMMERS, D. A. Consumers Power Co EVANS, D. H. Bechtel Corp B3/02/10 23pp 17210 035 24X Fiche 50-329, B3/02/14, B302180390

--B302180403 Testimony of J Bradley re Sinclair OL Contention 14 on Dresden fogging & icing studies Conclusions in plant FES re fog & ice not inconsistent w/Dresden cooling pond experience Certificate of Svc encl
BRADLEY, J. Consumers Power Co BRADLEY, J. Murray & Trettel, Inc B3/02/07 40pp 17210 057 24X Fiche 50-329, B3/02/14, B302180390

B302230674 Transcript of B30215 hearing in Midland, MI Pp 11,458-11,666 Supporting documentation encl
* Atomic Safety and Licensing Board Panel B3/02/15 246pp 17257 335 24X Fiche 50-329, B3/02/15, B302230674

B302230619 Transcript of B30216 hearing in Midland, MI Pp 11,667-11,870
* Atomic Safety and Licensing Board Panel B3/02/16 210pp 17255 255 24X Fiche 50-329, B3/02/16, B302230619

B302230665 Transcript of B30216 hearing in Midland, MI Pp 11,871-11,973
* Atomic Safety and Licensing Board Panel B3/02/16 106pp 17255 065 24X Fiche 50-329, B3/02/16, B302230665

B302230207 Transcript of B30217 hearing in Midland, MI Pp 11,970-12,179
* Atomic Safety and Licensing Board Panel B3/02/17 272pp 17244 003 24X Fiche 50-329, B3/02/17, B302230207

B302230214 Transcript of B30218 hearing in Midland, MI Pp 12,180-12,354
* Atomic Safety and Licensing Board Panel B3/02/18 178pp 17243 013 24X Fiche 50-329, B3/02/18, B302230214

V. Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D. O. Division of Licensing B3/01/31, Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X Fiche 50-000, B3/01/31, B301310203

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F Security, medical, emergency & fire protection plans

B302040442 Notification of canceled B30211 meeting w/util in Bethesda, MD to hear appeal of denied 10CFR50, App R exemption requests
APICELLA, F. L. Operating Reactors Branch 2 B3/01/19 VASSALLO, D. B. Operating Reactors Branch 2 2pp 17042 329 24X Fiche 50-331, B3/01/19, B302040442

B301210340 Generic Ltr B3-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl. I, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D. O. Division of Licensing B3/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X Fiche 50-000, B3/02/01, B301210340

B302100157 Summary of B30131 meeting w/util & Bechtel in Bethesda, MD re 10CFR50 App R exemption request
APICELLA, F. L. Operating Reactors Branch 2 B3/02/02 Operating Reactors Branch 2 3pp 17134 270 24X Fiche 50-331, B3/02/02, B302100157

B302180471 Forwards administrative control procedures & info re internal & boundary exemption requests, confirming B30131 discussions concerning request for exemption from 10CFR50, App R requirements Related drawings encl
ROOT, L. D. Iowa Electric Light & Power Co B3/02/15 DENTON, H. Office of Nuclear Reactor Regulation, Director 16pp 17214 225 24X Fiche 50-331, B3/02/15, B302180471

--B302180476 "Administrative Control Procedures - Control of Combustibles"
WILSON, D., MCCROCKER, R. A. Iowa Electric Light & Power Co B3/02/15 12pp 17214 253 24X Fiche 50-331, B3/02/15, B302180471

J Insurance & indemnity information

B301210025 Forwards Endorsement 56 to NELIA Policy NF-214 & Endorsement 46 to M&L Policy NF-72
SHEA, K. H. Lowenstein, Neuman, Reis, Axelrad & Toll B3/01/14 BALTZMAN, J. D. Assistant Director for State & Licensee Relations 3pp 16874 346 24X Fiche 50-331, B3/01/14, B301210025

P Operating license stage documents & correspondence

B302030089 Generic Ltr B3-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D. O. Division of Licensing B3/02/02 General Public Utilities - OPU Service Corp 5pp 17074 086 24X Fiche 50-000, B3/02/02, B302030089

B302080295 Generic Ltr B3-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D. O. Division of Licensing B3/02/08 Consolidated Edison Co. of New York, Inc 11pp 17290 247 24X Fiche 50-000, B3/02/08, B302080295

B302080301 Generic Ltr B3-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re GER of "Emergency Procedure Guidelines, Rev 2," NEDD-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D. O. Division of Licensing B3/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, B3/02/08, B302080301

B302080304 Generic Ltr B3-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D. O. Division of Licensing B3/02/08 Consolidated Edison Co. of New York, Inc 9pp 17234 234 24X Fiche 50-000, B3/02/08, B302080304

B302150279 Responds to NRC B21207 ltr re radiological effluent Tech Specs Formal submittal of proposed Tech Specs incorporating all changes expected by B30401
ROOT, L. D. Iowa Electric Light & Power Co B3/02/08 DENTON, H. Office of Nuclear Reactor Regulation, Director 3pp 17148 291 24X Fiche 50-331, B3/02/08, B302150279

--B302150283 Proposed radiological effluent Tech Specs incorporating NRC comments from B21103-04 meetings
* Iowa Electric Light & Power Co B3/02/08 23pp 17148 294 24X Fiche 50-331, B3/02/08, B302150279

8302170510 Forwards Amend B1 to License DPR-49, safety evaluation & notice of issuance & availability Amend consists of changes to Tech Specs to permit defueling & refueling while torus is drained
APICELLA, F Operating Reactors Branch 2 83/02/09 ARNOLD, D Iowa Electric Light & Power Co 2pp 17197 099 24X
Fiche 50-331, 83/02/09, 8302170510

--8302170514 Amend B1 to License DPR-49, changing Tech Specs to permit defueling & refueling while torus is drained or has reduced water vol
VASSALLO, D B Operating Reactors Branch 2 83/02/09 6pp 17197 101 24X Fiche 50-331, 83/02/09, 8302170510

--8302170519 Safety evaluation supporting Amend B1 to License DPR-49 + Office of Nuclear Reactor Regulation, Director 83/02/09 2pp 17197 107 24X Fiche 50-331, 83/02/09, 8302170510

--8302170523 Notice of issuance & availability of Amend B1 to License DPR-49
VASSALLO, D B Operating Reactors Branch 2 83/02/09 2pp 17197 109 24X Fiche 50-331, 83/02/09, 8302170510

8302240102 Forwards Amend B2 to License DPR-49 & notice of issuance & availability Amend changes Tech Specs incorporating revs to tables of containment isolation valves to reflect mod requirements of NUREG-0737, Item II B 3
VASSALLO, D B Operating Reactors Branch 2 83/02/09 ARNOLD, D Iowa Electric Light & Power Co 3pp 17268 278 24X
Fiche 50-331, 83/02/09, 8302240102

--8302240115 Amend B2 to License DPR-49, changing Tech Specs to incorporate revs to tables of containment isolation valves to reflect mod requirements of NUREG-0737, Item II B, 3, "Post-Accident Sampling."
VASSALLO, D B Operating Reactors Branch 2 83/02/09 3pp 17268 281 24X Fiche 50-331, 83/02/09, 8302240102

--8302240125 Notice of issuance & availability of Amend B2 to License DPR-49
VASSALLO, D B Operating Reactors Branch 2 83/02/09 2pp 17268 286 24X Fiche 50-331, 83/02/09, 8302240102

8302150174 Application to amend License DPR-49, consisting of proposed ETS Change EFS-29, deleting nonradiological environ water quality Tech Specs, consistent w/Federal Water Pollution Control Act of 1972
RODT, L D Iowa Electric Light & Power Co 83/02/10 DENTON, H. Office of Nuclear Reactor Regulation, Director 1p 17147 196 24X
Fiche 50-331, 83/02/10, 8302150174

--8302150179 Proposed ETS Change 29, deleting nonradiological environ water quality Tech Specs, consistent w/Federal Water Pollution Control Act of 1972 & ALAB-513
* Iowa Electric Light & Power Co 83/02/10 16pp 17147 197 24X Fiche 50-331, 83/02/10, 8302150174

8302150267 Responds to NRC 830117 ltr requesting addl info re util compliance w/NUREG-0737, Items II F 1, 4, II F 1 5 & II F 1 6 Extension of time requested in order to receive info from vendors Response expected by 830321
RODT, L D Iowa Electric Light & Power Co 83/02/11, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17148 326 24X
Fiche 50-331, 83/02/11, 8302150267

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document B1 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144, 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARESKI, L Region 3, Office of Director 82/07/08
KEFFLER, J Q Region 3, Office of Director 13pp 17045:281 24X
Fiche 50-000, 82/12/30, 8302040039

8302010110 Confirms 830210 meeting in Glen Ellyn, IL to discuss implementation status of Regulatory Performance Improvement Program
SPESBARD, R L Division of Project & Resident Programs, 83/01/24
ARNOLD, D Iowa Electric Light & Power Co 1p 16975 238 24X
Fiche 50-331, 83/01/24, 8302010110

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302080308 Forwards IE Insp Rept 50-331/82-18 on 821001-1130 & notice of violation
STREETER, J F Division of Project & Resident Programs 83/01/26
ARNOLD, D Iowa Electric Light & Power Co 2pp 17056 034 24X
Fiche 50-331, 83/01/26, 8302080308

--8302080309 Notice of violation from insp on 821001-1130
STREETER, J F Division of Project & Resident Programs 83/01/26
1p 17056 036 24X Fiche 50-331, 83/01/26, 8302080308

--8302080313 IE Insp Rept 50-331/82-18 on 821001-1130 Noncompliance noted failure to attach chain lock to pipe following performance of STP 41A006 on 821020
CLARDY, L S, JORDAN, M J, WALKER, R D Division of Project & Resident Programs 83/01/25 9pp 17056 037 24X
Fiche 50-331, 83/01/26, 8302080308

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060341 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESBARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302160280 Ack receipt of 830203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/82-11
SPESBARD, R L Division of Engineering 83/02/11, ARNOLD, D Iowa Electric Light & Power Co 1p 17170:117 24X
Fiche 50-331, 83/02/11, 8302160280

--8302160286 Responds to NRC 821108 ltr re violations noted in IE Insp Rept 50-331/82-11 Corrective actions safe method for controlling pump flow rate & discharge pressure identified & operability test for diesel oil transfer pumps modified
RODT, L D Iowa Electric Light & Power Co. 83/02/03 KEFFLER, J Q Region 3, Office of Director 2pp 17170, 118 24X
Fiche 50-331, 83/02/11, 8302160280

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060345 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148, 24X Fiche: 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150196 Forwards "Duane Arnold Energy Ctr Semiannual Rept on Environ Qualification Program for Safety-Related Electrical Equipment," in response to 821220 SEA Action consistent w/ NRC replacement parts policy described in Generic Ltr 82-09
RODT, L D Iowa Electric Light & Power Co 83/02/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17149, 284, 24X Fiche 50-331, 83/02/11, 8302150196

--8302150206 "Duane Arnold Energy Ctr Semiannual Rept on Environ Qualification Program for Safety-Related Electrical Equipment "
* Bechtel Corp 83/02/04 95pp 17149 287, 24X
Fiche 50-331, 83/02/11, 8302150196

DOCKETED ITEMS

8302220129 Forwards monthly operating rept for Jan 1983
MINECK, D L Iowa Electric Light & Power Co 83/02/14 Director's
Office, Office of Inspection and Enforcement 1p 17233 197 24X
Fiche 50-331, 83/02/14, 8302220129

--8302220134 Monthly operating rept for Jan 1983
WATSON, R Iowa Electric Light & Power Co 83/02/19 6pp
17233 198 24X Fiche 50-331, 83/02/14, 8302220129

B Reportable occurrences, LERs & related correspondence

8302040362 Forwards LER 82-083/03L-0
MINECK, D L Iowa Electric Light & Power Co 83/01/25 KEPLER, J O
Region 3, Office of Director 1p 17019 036 24X
Fiche 50-331, 83/01/25, 8302040362

--8302040364 LER 82-083/03L-0 on 821228, while conducting GC surveillance,
RHR sys hydraulic snubber found leaking hydraulic fluid &
declared inoperable. Caused by inservice seal degradation.
New snubber installed & inspected w/satisfactory results.
HILL, K L Iowa Electric Light & Power Co 83/01/25 Region 3,
Office of Director 1p 17019 037 24X Fiche 50-331, 83/01/25,
8302040362

8302080328 Forwards updated LER 82-075/03X-1
MINECK, D L Iowa Electric Light & Power Co 83/01/27 KEPLER, J O
Region 3, Office of Director 1p 17056 320 24X
Fiche 50-331, 83/01/27, 8302080328

--8302080330 Updated LER 82-075/03X-1 on 821106, during shutdown drywell
purge, PDIS-4305 opened R bldg to suppression chamber vacuum
breaker CV-4305 conservatively & would not reset to close
Caused by instrument drift
HILL, K L Iowa Electric Light & Power Co. 83/01/27 Region 3,
Office of Director 1p 17056 321 24X Fiche 50-331, 83/01/27,
8302080328

8302080245 Forwards LER 83-001/03L-0
MINECK, D L Iowa Electric Light & Power Co. 83/01/28 KEPLER, J O
Region 3, Office of Director 1p 17057 113 24X
Fiche 50-331, 83/01/28, 8302080245

--8302080260 LER 83-001/03L-0 on 830104, during surveillance testing, steam
discovered escaping from RCIC turbine hydraulic governor
valve HV-2406 Caused by gasket failure Gasket replaced
HILL, K L Iowa Electric Light & Power Co 83/01/28 Region 3,
Office of Director 1p 17057 114 24X Fiche 50-331, 83/01/28,
8302080245

8302230280 Forwards LER 83-003/03L-0
MINECK, D L Iowa Electric Light & Power Co 83/02/14 KEPLER, J O
Region 3, Office of Director 1p 17242 347 24X
Fiche 50-331, 83/02/14, 8302230280

--8302230283 LER 83-003/03L-0 on 830125, during surveillance testing,
Barton reactor low water level indicating switch L18-4592A
tripped out of spec Caused by instrument drift Switch
recalibr
HILL, K L Iowa Electric Light & Power Co 83/02/11 Region 3,
Office of Director 1p 17242 348 24X Fiche 50-331, 83/02/14,
8302230280

8302230452 Forwards updated LER 82-068/03X-1
MINECK, D L Iowa Electric Light & Power Co 83/02/14 KEPLER, J O
Region 3, Office of Director 1p 17246 071 24X
Fiche 50-331, 83/02/14, 8302230452

8302230462 Updated LER 82-068/03X-1 on 821014, during normal operation,
river water supply sys D traveling screen wash pump 1P-1128
found inoperable. Caused by failure of rubber coupling due to
degradation Coupling replaced.
HILL, K L Iowa Electric Light & Power Co 83/02/12 Region 3,
Office of Director 1p 17246 072 24X Fiche 50-331, 83/02/14,
8302230452

Operator Examinations

01310203 Generic Ltr 83-04 to all power reactor licensees, applicants
for DLs, NSB vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing, 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for DL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302170502 Forwards draft safety evaluation on App R exemption
requests Lists options available
VASSALLO, D B Operating Reactors Branch 2 83/02/02 SINCLAIR, L W
Power Authority of the State of New York 13pp 17203 168 24X
Fiche 50-333, 83/02/02, 8302170502

--8302170513 Draft safety evaluation of App R exemption requests re fire
zones Fire zones not in compliance listed
* Operating Reactors Branch 2 83/02/02 20pp 17203 171 24X
Fiche 50-333, 83/02/02, 8302170502

8302230601 Ack receipt of 830121 ltr informing NRC of steps taken to
correct violations noted in Health Physics Appraisal Rept
50-333/80-20
MARTIN, T T Division of Engineering & Technical Programs 83/02/15
MCNEILL, C A Power Authority of the State of New York 1p
17294 058 24X Fiche 50-333, 83/02/15, 8302230601

--8302230621 Responds to NRC 821102 ltr re violations noted in Health
Physics Appraisal Rept 50-333/80-20 Corrective actions
procedures for bioassay & whole body counting, radiological
surveys & radiation & contamination surveys implemented
MCNEILL, C A Power Authority of the State of New York 83/01/21,
MARTIN, T T Division of Engineering & Technical Programs 2pp
17294 059 24X Fiche 50-333, 83/02/15, 8302230601

J Insurance & indemnity information

8302070224 Forwards Endorsement 61 to NELIA Policy NF-208 & Endorsement
52 to MAELU Policy MF-77
DEEG, F H Power Authority of the State of New York 83/01/28
SALZMAN, J Antitrust & Economic analysis Branch (Utility Finance)
3pp 17031 300 24X Fiche 50-333, 83/01/28, 8302070224

8302150056 Forwards Endorsements 1, 2 & 3 to NELIA Certificate N-47 &
MAELU Certificate M-47
DEEG, F H Power Authority of the State of New York 83/02/09
SALZMAN, J Antitrust & Economic analysis Branch (Utility Finance)
19pp 17147 009 24X Fiche 50-333, 83/02/09, 8302150056

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for
continued operation of operating reactors in response to
questions raised at 830106 meeting re environ qualification
of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office
of Nuclear Reactor Regulation, Director 7pp, 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170123 Package of four comments indicating adequate or inadequate
justification for interim operation re environ qualification
of electrical equipment
PADOVANI, M L NRC - No Detailed Affiliation Given 82/01/27
NRC - No Detailed Affiliation Given 10pp 17196 255 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by
which technical evaluation repts are expected to be
completed Requests justification for continued operation of
each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAGLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170285 Concludes that based on licensee 820127 submittal, continued
operation until completion of environ qualification program
will not present undue risk to public health & safety
HEGNER, J D Operating Reactors Branch 2 82/10/28 EISENHUT, D O,
Division of Licensing 2pp 17197 078 24X
Fiche 50-000, 83/01/18, 8302170019

8302070289 Forwards safety evaluation of util submittals re NUREG-0737,
Items I A 2.1.4, "Upgrading of Reactor Operator & Senior
Reactor Operator Training" & II B 4.1, "Training for
Mitigating Core Damage"
VASSALLO, D B Operating Reactors Branch 2 83/01/25 SINCLAIR, L W
Power Authority of the State of New York 2pp 17065 306 24X
Fiche 50-333, 83/01/25, 8302070289

DOCKETED ITEMS

205

--8302070291 Safety evaluation of util submittals re NUREG-0737, Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II 3 4 1, "Training for Mitigating Core Damage" Requirements met
BAUNACK, W Operating Reactors Branch 2 83/01/25 3pp
17065 308 24X Fiche 50-333, 83/01/25, 8302070289

--8208310344 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4 for JA Fitzpatrick Nuclear Power Plant," technical evaluation rept
Science Applications, Inc NRC-03-82-096 SA1-186-029-49
82/08/25 NRC - No Detailed Affiliation Given 15pp
17065 311 24X Fiche 50-333, 83/01/25, 8302070289

8302010332 Forwards "Metallographic Investigation of Type 304 Stainless Steel Schedule 80 Pipe" & "Investigation of Flaws on Inside Surface of Type 304 Stainless Steel Schedule 80 Pipe"
BAYNE, J P Power Authority of the State of New York 83/01/26
VASSALLO, D B Operating Reactors Branch 2 2pp 16978 186 24X
Fiche 50-333, 83/01/26, 8302010332

8302030441 Forwards response to 820317 request for addl info on outages of ECCS per TMI Item II K 3 17 Encl rept revised to include ECCS or equipment failures which resulted in occurrence
BAYNE, J P Power Authority of the State of New York 83/01/26
VASSALLO, D B Operating Reactors Branch 2 40pp 17008 147 24X
Fiche 50-333, 83/01/26, 8302030441

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - GPU Service Corp 5pp 17074 086 24X
Fiche 50-000, 83/02/02, 8302030089

8302080159 Forwards reactor coolant & main steam line tunnel leakage detection sys performance evaluations after 5 yrs of operation Performance history of both sys excellent
BAYNE, J P Power Authority of the State of New York 83/02/02
VASSALLO, D B Operating Reactors Branch 2 3pp 17059 023 24X
Fiche 50-333, 83/02/02, 8302080159

8302170450 Forwards request for addl info for review of NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 Response requested within 30 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 83/02/02 SINCLAIR, L W
Power Authority of the State of New York 10pp 17205 090 24X
Fiche 50-333, 83/02/02, 8302170450

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to DWR licensees of operating reactors (except LACDWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," HEDD-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302150159 Forwards application for amend to License DPR-59, changing Tech Specs to delete all nonradiological spec sections & refs in App B, per Federal Water Pollution Act amends of 1972
BAYNE, J P Power Authority of the State of New York 83/02/10
VASSALLO, D B Operating Reactors Branch 2 1p 17147 163 24X
Fiche 50-333, 83/02/10, 8302150159

--8302150163 Application for amend to License DPR-59, changing Tech Specs to delete all nonradiological spec sections & refs in App B, per Federal Water Pollution Act amends of 1972
BAYNE, J P Power Authority of the State of New York 83/02/10
1p 17147 164 24X Fiche 50-333, 83/02/10, 8302150159

--8302150166 Proposed Tech Specs re nonradiological specs in App B
Power Authority of the State of New York 83/02/10 13pp
17147 165 24X Fiche 50-333, 83/02/10, 8302150159

8302230482 Comments on draft value impact analysis re proposed steam generator generic requirements Cost of condenser retubing, condensate polisher installation & copper bearing component replacement in feedtrain must be considered
BAYNE, J P Power Authority of the State of New York 83/02/15
EISENHUT, D O Division of Licensing 2pp 17257 071 24X
Fiche 50-000, 83/02/15, 8302230482

8302240029 Forwards application for amend to License DPR-59, proposing changes to Tech Specs re mgt organization & titles
BAYNE, J P Power Authority of the State of New York 83/02/18
VASSALLO, D B Operating Reactors Branch 2 2pp 17274 336 24X
Fiche 50-333, 83/02/18, 8302240029

--8302240032 Application for amend to License DPR-59, changing Tech Specs re mgt organization & titles
BAYNE, J P Power Authority of the State of New York 83/02/18
2pp 17274 338 24X Fiche 50-333, 83/02/18, 8302240029

--8302240036 Proposed Tech Specs re mgt organization & titles
Power Authority of the State of New York 83/02/18 16pp
17274 340 24X Fiche 50-333, 83/02/18, 8302240029

0 Inspection reports, IE Bulletins & correspondence

8302030436 Forwards IE Insp Rept 50-333/82-28 on 821201-31 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/01/19
MCNEILL, C A Power Authority of the State of New York 2pp
17006 207 24X Fiche 50-333, 83/01/19, 8302030436

--8302030445 Notice of violation from insp on 821201-31
Division of Project & Resident Programs 83/01/19 2pp
17006 209 24X Fiche 50-333, 83/01/19, 8302030436

--8302030456 IE Insp Rept 50-333/82-28 on 821201-31 Noncompliance noted failure to complete QC insp points, perform adequate QC matl receipt insp & use of unauthorized tags on safety-related matl
LINVILLE, J C, DOERFLINGER, L T, KISTER, H B Division of Project & Resident Programs 83/01/15 13pp 17006 211 24X
Fiche 50-333, 83/01/19, 8302030436

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 11pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302010443 Forwards addl info re IE Bulletin 80-11, "Masonry Wall Design," in response to NRC request
BAYNE, J P Power Authority of the State of New York 83/01/26
VASSALLO, D B Operating Reactors Branch 2 3pp 16974 245 24X
Fiche 50-333, 83/01/26, 8302010443

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 10pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 11pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302100429 Forwards IE Insp Rept 50-333/82-24 on 821101-10 No noncompliance noted Apps listing licensee strengths & weaknesses encl Response to App B (licensee weaknesses) due in 30 days
MARTIN, T T Division of Engineering & Technical Programs 83/01/28
BAYNE, J P Power Authority of the State of New York 7pp
17117 205 24X Fiche 50-333, 83/01/28, 8302100429

--8302100436 IE Insp Rept 50-333/82-24 on 821101-10 No noncompliance noted Major areas inspected design controls, plant mods, QA, drawing controls, records mgt & committee activities,
EAPEN, P K, WIGGINS, J T, BAUNACK, W Division of Engineering & Technical Programs 83/01/27 43pp 17117 212 24X
Fiche 50-333, 83/01/28, 8302100429

8302230401 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in Health Physics Appraisal Rept 50-333/80-20
MARTIN, T T Division of Engineering & Technical Programs 83/02/15
MCNEILL, C A Power Authority of the State of New York 1p
17234 058 24X Fiche 50-333, 83/02/15, 8302230401

DOCKETED ITEMS

--B302230621 Responds to NRC B21102 ltr re violations noted in Health Physics Appraisal Rept 50-333/80-20 Corrective actions procedures for bioassay & whole body counting, radiological surveys & radiation & contamination surveys implemented
MCNEILL, C A Power Authority of the State of New York 83/01/21
MARTIN, T T Division of Engineering & Technical Programs 2pp
17254 039 24X Fiche 50-333, 83/02/19, B302230601

B312060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp, 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B312060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B312060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

R. Periodic operating reports & related correspondence

B302080237 Forwards monthly operating rept for Jan 1983
CONVERSE, R J Power Authority of the State of New York 83/02/03
Director's Office, Office of Inspection and Enforcement 1p
17057 174 24X Fiche 50-333, 83/02/03, B302080239

--B302080242 Monthly operating rept for Jan 1983
COOK, J Power Authority of the State of New York 83/02/03
11pp 17057 175 24X Fiche 50-333, 83/02/03, B302080239

S Reportable occurrences, LERs & related correspondence

B302030396 Forwards LER 83-003/03L-0
MCNEILL, C A Power Authority of the State of New York 83/01/24
HAYNES, R C Region 1, Office of Director 1p 17005 292 24X
Fiche 50-333, 83/01/24, B302030396

--B302030402 LER 83-003/03L-0 on B30111, while conducting surveillance testing on core sparger to reactor vessel D/P switches
1ADP18-43A & B, instrument setpoints found to be less conservative than required Caused by Instrument drift
KEITH, H Power Authority of the State of New York 83/01/24
Region 1, Office of Director 1p 17005 293 24X
Fiche 50-333, 83/01/24, B302030396

B302030413 Forwards LER 83-002/03L-0
MCNEILL, C A Power Authority of the State of New York 83/01/24
HAYNES, R C Region 1, Office of Director 1p 17005 146 24X
Fiche 50-333, 83/01/24, B302030413

--B302030421 LER 83-002/03L-0 on B30109, standby gas treatment sys B humidity control heater out of svc for approx 3 h Caused by shorted silicon controlled rectifier to ground Silicon controlled rectifier removed
LISEND, R Power Authority of the State of New York 83/01/24
Region 1, Office of Director 1p 17005 147 24X
Fiche 50-333, 83/01/24, B302030413

B302030200 Forwards updated LER 82-043/03X-1.
MCNEILL, C A Power Authority of the State of New York 83/01/25
HAYNES, R C Region 1, Office of Director 1p 17001 324 24X
Fiche 50-333, 83/01/25, B302030200

--B302030205 Updated LER 82-043/03X-1 on B21226, MSIV D inboard & outboard 10X switch would not reset when tested. Caused by mismatch between switch activator & striker plate on outboard switch Striker plate reworked Activator reset.
KEITH, H Power Authority of the State of New York 83/01/25
Region 1, Office of Director 2pp 17001:325 24X
Fiche 50-333, 83/01/25, B302030200

B302230224 Telescopy ROs 83-029 & 83-008 on B30202, licensee informed by telcon that error made in ODDN base deck for Reload 4 Cycle 5 analysis. Caused by personnel error in performing licensing analysis. Tech Spec change initiated.
MCNEILL, C A Power Authority of the State of New York 83/02/03
Region 1, Office of Director 1p 17245 040 24X
Fiche 50-333, 83/02/03, B302230224

B302230295 Forwards LER 82-060/04T-0.
MCNEILL, C A Power Authority of the State of New York 83/02/03
HAYNES, R C Region 1, Office of Director 1p 17244 303 24X
Fiche 50-333, 83/02/03, B302230295

--B302230299 LER 82-060/04T-0 on B21230, number of fish impinged over 24 h period exceeded 20,000 Previous impingement samples measured less than 100 fish/24 h Caused by bad weather conditions during B21229-30 Submittal replaces LER 83-001
MULCAHEY, E Power Authority of the State of New York 83/02/03
Region 1, Office of Director 2pp 17244 304 24X
Fiche 50-333, 83/02/03, B302230295

B302230469 Forwards LER 83-005/03L-0
MCNEILL, C A Power Authority of the State of New York 83/02/03
HAYNES, R C Region 1, Office of Director 1p 17246 099 24X
Fiche 50-333, 83/02/03, B302230469

--B302230481 LER 83-005/03L-0 on B30120, 130-gallon unplanned release of laundry effluent occurred Caused by laundry drain tank A being placed in recirculation lineup w/dischage lineup still available Procedures revised
LOCY, R Power Authority of the State of New York 83/02/03
Region 1, Office of Director 1p 17246 100 24X
Fiche 50-333, 83/02/03, B302230469

B302230537 Forwards LER 82-059/03L-0
MCNEILL, C A Power Authority of the State of New York 83/02/03
HAYNES, R C Region 1, Office of Director 1p 17286 300 24X
Fiche 50-333, 83/02/03, B302230537

--B302230547 LER 82-059/03L-0 on B21226, MSIV B outboard 10X switch would not reset when tested per Tech Spec 3 1-1 Caused by mismatch between activation & striker plate in reset direction of valve travel Striker plate mechanically reworked
KEITH, H Power Authority of the State of New York 83/02/03
Region 1, Office of Director 1p 17256 301 24X
Fiche 50-333, 83/02/03, B302230537

B302230577 Forwards LER 83-005/03L-0
MCNEILL, C A Power Authority of the State of New York 83/02/03
HAYNES, R C Region 1, Office of Director 1p 17256 105 24X
Fiche 50-333, 83/02/03, B302230577

--B302230594 LER 83-005/03L-0 on B30120, unplanned release of laundry effluent occurred prior to sampling after laundry drain tank A placed in recirculation lineup w/dischage lineup still available Caused by personnel error Operator counseled
LOCY, R Power Authority of the State of New York 83/02/03
Region 1, Office of Director 1p 17256 106 24X
Fiche 50-333, 83/02/03, B302230577

B302230661 Forwards LER 83-004/03L-0
MCNEILL, C A Power Authority of the State of New York 83/02/03
HAYNES, R C Region 1, Office of Director 1p 17248 333 24X
Fiche 50-333, 83/02/03, B302230661

--B302230672 LER 83-004/03L-0 on B30117, control rod 18-27 found uncoupled & would not recouple Caused by bent uncoupling rod in control rod drive mechanism & loose inner filter Mechanism replaced w/rebuilt unit
LISEND, R Power Authority of the State of New York 83/02/03
Region 1, Office of Director 1p 17248 334 24X
Fiche 50-333, 83/02/03, B302230661

B302230687 Forwards updated LER 82-043/03X-2
MCNEILL, C A Power Authority of the State of New York 83/02/03
HAYNES, R C Region 1, Office of Director 1p 17248 359 24X
Fiche 50-333, 83/02/03, B302230687

--B302230691 Updated LER 82-043/03X-2 on B21226, MSIV D inboard 10X switch would not reset when tested Caused by misadjustment of inherent dead band outside reset point Switch activation adjusted further down on valve travel
KEITH, H Power Authority of the State of New York 83/02/03
Region 1, Office of Director 1p 17248 360 24X
Fiche 50-333, 83/02/03, B302230687

B302180300 Forwards LER 83-006/03L-0
MCNEILL, C A Power Authority of the State of New York 83/02/07
HAYNES, R C Region 1, Office of Director 1p 17211 233 24X
Fiche 50-333, 83/02/07, B302180300

--B302180306 LER 83-006/03L-0 on B30110, Wyle Labs notified until that as-found first & second actuations of relief valve D were out of Tech Spec tolerances of 1.094 to 1.116 psig Cause of setpoint drift unknown Problem under investigation
CONVERSE, R Power Authority of the State of New York 83/02/07
Region 1, Office of Director 1p 17211 234 24X
Fiche 50-333, 83/02/07, B302180300

B302230288 Forwards LER 83-008/01T-0
MCNEILL, C A Power Authority of the State of New York 83/02/07
HAYNES, R C Region 1, Office of Director 1p 17244 331 24X
Fiche 50-333, 83/02/07, B302230288

--8302230293 LER 83-008/017-0 on 830202, error in ODYN base deck for Reload 4 analysis caused delta critical power ratios for pressurization transients to be nonconservative. Caused by improper data input due to personnel error.
BIRCH, D. Power Authority of the State of New York 83/02/09
Region 1, Office of Director 5pp 17244 332 24X
Fiche 50-333, 83/02/09, 8302230293

8302230298 Forwards LER 83-007/031-0
MCNEIL, C. A. Power Authority of the State of New York 83/02/09
Region 1, Office of Director 1p 17244 298 24X
Fiche 50-333, 83/02/09, 8302230298

--8302230302 LER 83-007/031-0 on 830201, while testing reactor low water level scram switch 02-3-LIS-101D, setpoint found less conservative than Tech Spec requirement. Caused by instrument drift. Setpoint adjusted. Test frequency increased.
HARTFORD, K. Power Authority of the State of New York 83/02/09
Region 1, Office of Director 1p 17244 299 24X
Fiche 50-333, 83/02/09, 8302230298

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for QLS, KSS vendors, reactor vendors & AE re-certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302030499 Forwards IE Insp Rept 50-334/82-30 on 821129-1202 & notice of violation
HARTIG, T. T. Division of Engineering & Technical Programs 83/01/20
CAREY, J. J. Duquesne Light Co 2pp 17006 289 24X
Fiche 50-334, 83/01/20, 8302030499

--8302030506 Notice of violation from insp on 821129-1202
* Division of Engineering & Technical Programs 83/01/20 1p.
17006 291 24X Fiche 50-334, 83/01/20, 8302030499

--8302030511 IE Insp Rept 50-334/82-30 on 821129-1202 Noncompliance noted. Unapproved & unreviewed procedure implemented for emergency squad drills.
FINZEL, A., PLISCO, L., ANDERSON, C. J. Region 1, Office of Director 83/01/18 11pp 17006 292 24X Fiche 50-334, 83/01/20, 8302030499

8302030389 Forwards IE Insp Rept 50-334/82-29 on 821201-830103, No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/01/21
CAREY, J. J. Duquesne Light Co 2pp 17005 326 24X
Fiche 50-334, 83/01/21, 8302030389

--8302030397 IE Insp Rept 50-334/82-29 on 821201-830103 No noncompliance noted. Major areas inspected: document control program, plant operations, housekeeping, fire protection, radiological controls & physical security.
TROSKOSKI, W. M., LAZARUS, W. J., TRIPP, L. E. Division of Project & Resident Programs 83/01/19 15pp 17005 328 24X
Fiche 50-334, 83/01/21, 8302030389

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for QLS & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302160474 Releases public version of Vol 1 of emergency preparedness plan.
FELTON, J. M. Division of Rules and Records 83/02/04 Document Management Branch 1p 17175 350 24X Fiche 50-334, 83/02/04, 8302160474

--8302160476 Forwards public version of Issue 7, Rev 0 to emergency preparedness plan, Vol 1.
SIEBER, J. D. Duquesne Light Co 83/01/14, VARQA, S. A. Operating Reactors Branch 1 5pp 17175 351 24X Fiche 50-334, 83/02/04, 8302160474

--8302160479 Public version of Issue 7, Rev 0 to emergency preparedness plan, Vol 1.
LACEY, W. S. Duquesne Light Co 83/01/10 294pp 17175 356 24X
Fiche 50-334, 83/02/04, 8302160474

8302170440 Forwards Amend 63 to License DPR-66 & notice of issuance & availability. Amend changes Tech Spec to require audit of emergency & security plans at least once per 12 months.
VARQA, S. A. Operating Reactors Branch 1 83/02/07, CAREY, J. J. Duquesne Light Co 4pp 17204 083 24X Fiche 50-334, 83/02/07, 8302170440

--8302170459 Amend 63 to License DPR-66, changing Tech Specs to require audit of emergency & security plans at least once every 12 months.
VARQA, S. A. Operating Reactors Branch 1 83/02/07 4pp 17204 087 24X Fiche 50-334, 83/02/07, 8302170440

--8302170472 Notice of issuance & availability of Amend 63 to License DPR-66.
VARQA, S. A. Operating Reactors Branch 1 83/02/07 2pp 17204 091 24X Fiche 50-334, 83/02/07, 8302170440

8302160267 Forwards Rev 4 of training & qualification plan & Rev 10 & page changes to Rev 9 to physical security plan Revs & pages withheld (ref 10CFR73.21).
CAREY, J. J. Duquesne Light Co 83/02/09, VARQA, S. A. Operating Reactors Branch 1 3pp 17163 188 24X Fiche 50-334, 83/02/09, 8302160267

8302250282 Forwards IE Insp Rept 50-334/83-01 on 830104-31. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/09
CAREY, J. J. Duquesne Light Co 2pp 17291 349 24X
Fiche 50-334, 83/02/09, 8302250282

--8302250289 IE Insp Rept 50-334/83-01 on 830104-31. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, plant operations, housekeeping, fire protection, physical security & LER followup.
TROSKOSKI, W. M., LAZARUS, W. J., TRIPP, L. E. Division of Project & Resident Programs 83/02/09 15pp 17291 351 24X
Fiche 50-334, 83/02/09, 8302250282

8302240304 Releases public version of "Annual Emergency Preparedness Exercise 1983".
FELTON, J. M. Division of Rules and Records 83/02/16 Document Management Branch 1p 17287 067 24X Fiche 50-334, 83/02/16, 8302240306

--8302240311 Forwards public version of "Annual Emergency Preparedness Exercise 1983".
* Duquesne Light Co 83/01/26, VARQA, S. A. Operating Reactors Branch 1 2pp 17287 068 24X Fiche 50-334, 83/02/16, 8302240306

--8302240315 Public version of "Annual Emergency Preparedness Exercise 1983".
CAREY, J. J. Duquesne Light Co 83/01/26 208pp 17287 070 24X
Fiche 50-334, 83/02/16, 8302240306

P Operating license stage documents & correspondence

8302080073 Forwards Amend 62 to License DPR-66, safety evaluation, technical evaluation & notice of issuance & availability. Amend allows bypass of anticipatory reactor trip on turbine trip.
TAM, P. S. Operating Reactors Branch 1 83/01/26, CAREY, J. J. Duquesne Light Co 3pp 17106 236 24X Fiche 50-334, 83/01/26, 8302080073

--8302080077 Amend 62 to License DPR-66, allowing bypass of anticipatory reactor trip on turbine trip at 50% rated power or below.
VARQA, S. A. Operating Reactors Branch 1 83/01/26 6pp 17106 239 24X Fiche 50-334, 83/01/26, 8302080073

--8302080081 Safety evaluation supporting Amend 62 to License DPR-66.
* Office of Nuclear Reactor Regulation, Director 83/01/26 4pp 17106 245 24X Fiche 50-334, 83/01/26, 8302080073

--8302080082 "Deletion of Reactor Trip on Turbine Trip Below 50% Power, technical evaluation rept.
REEVES, W. E. Lawrence Livermore Laboratory 79/08/31 NRC - No Detailed Affiliation Given 4pp 17106 249 24X
Fiche 50-334, 83/01/26, 8302080073

--8302080085 Notice of issuance & availability of Amend 62 to License DPR-66.
VARQA, S. A. Operating Reactors Branch 1 83/01/26 2pp 17106 253 24X Fiche 50-334, 83/01/26, 8302080073

DOCKETED ITEMS

8302080302 Responds to SER For environ qualification of safety-related electrical equipment Deficiencies identified will not impair continued safe operation Reclassification of manufacturers info continuing Justification for continued operation encl CAREY, J J Duquesne Light Co 83/02/01 VARQA, S A Operating Reactors Branch 1 23pp 17056 009 24X Fiche 50-334, 83/02/01, 8302080302

8302080296 Forwards response to 821216 request for addl info re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 concerning instrument accuracy & related data for containment pressure, water level & hydrogen monitors CAREY, J J Duquesne Light Co 83/02/02 VARQA, S A Operating Reactors Branch 1 12pp 17056 120 24X Fiche 50-334, 83/02/02, 8302080296

8302150335 Forwards proprietary WCAP-10196, "Second Cycle Performance of Beaver Valley Unit 1 Fuel " Encl withheld (ref 10CER2 790) CAREY, J J Duquesne Light Co 83/02/02 VARQA, S A Operating Reactors Branch 1 1p 17146 141 24X Fiche 50-334, 83/02/02, 8302150335

8302170380 Forwards proposed Change Request 84 to License DPR-66, changing Tech Specs re administrative controls, to comply w/Generic Ltr 82-16 CAREY, J J Duquesne Light Co 83/02/07 VARQA, S A Operating Reactors Branch 1 1p 17187 117 24X Fiche 50-334, 83/02/07, 8302170380

--8302170381 Application for amend to License DPR-66, incorporating applicable recommendations of NUREG-0737 items in response to Generic Ltr 82-16 CAREY, J J Duquesne Light Co 83/02/07 2pp 17187 118 24X Fiche 50-334, 83/02/07, 8302170380

--8302170385 Proposed Tech Spec changes re administrative controls, to comply w/Generic Ltr 82-16 Safety evaluation encl * Duquesne Light Co 83/02/07 5pp 17187 120 24X Fiche 50-334, 83/02/07, 8302170380

8302170440 Forwards Amend 63 to License DPR-66 & notice of issuance & availability Amend changes Tech Spec to require audit of emergency & security plans at least once per 12 months VARQA, S A Operating Reactors Branch 1 83/02/07 CAREY, J J Duquesne Light Co 4pp 17204 083 24X Fiche 50-334, 83/02/07, 8302170440

--8302170459 Amend 63 to License DPR-66, changing Tech Specs to require audit of emergency & security plans at least once every 12 months VARQA, S A Operating Reactors Branch 1 83/02/07 4pp 17204 087 24X Fiche 50-334, 83/02/07, 8302170440

--8302170472 Notice of issuance & availability of Amend 63 to License DPR-66 VARQA, S A Operating Reactors Branch 1 83/02/07 2pp 17204 091 24X Fiche 50-334, 83/02/07, 8302170440

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304

02090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSB (except Yankee Atomic Electric Co) re resolution of FMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Southern California Edison Co. 31pp, 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

822030322 Forwards responses to NRC 830112 ltr re open items in sections 3 4, "Single Failure Criteria" & 3 5, "Seismic Design" of Technical Evaluation Rept EGG-EA-5826, "Reactor Vessel Overpressure Protection " CAREY, J J Duquesne Light Co 83/02/08 VARQA, S A Operating Reactors Branch 1 5pp 17230 146 24X Fiche 50-334, 83/02/08, 83022030322

8302170186 Forwards application for amend to License DPR-66, revising Tech Specs re rod position indication CAREY, J J Duquesne Light Co 83/02/09 VARQA, S A Operating Reactors Branch 1 2pp 17180 117 24X Fiche 50-334, 83/02/09, 8302170186

--8302170193 Application for amend to License DPR-66, revising Tech Specs re rod position indication CAREY, J J Duquesne Light Co 83/02/09 2pp 17180 119 24X Fiche 50-334, 83/02/09, 8302170186

--8302170196 Proposed Tech Specs re rod position indication * Duquesne Light Co 83/02/09 9pp 17180 121 24X Fiche 50-334, 83/02/09, 8302170186

8302202027 Forwards fee for 830207 Class II Tech Spec Change Request 84 STEBER, J D Duquesne Light Co 83/02/11 License Fee Management Branch 1p 17230 156 24X Fiche 50-334, 83/02/11, 8302202027

8302203070 Advises that util will be deviating from original design specs under which chemical addition pumps were originally procured per description in 800227 ltr CAREY, J J Duquesne Light Co 83/02/14 VARQA, S A Operating Reactors Branch 1 2pp 17232 338 24X Fiche 50-334, 83/02/14, 8302203070

Q Inspection reports, IE Bulletins & correspondence

8302030499 Forwards IE Insp Rept 50-334/82-30 on 821129-1202 & notice of violation MARTIN, T F Division of Engineering & Technical Programs 83/01/20 CAREY, J J Duquesne Light Co 2pp 17006 289 24X Fiche 50-334, 83/01/20, 8302030499

--8302030806 Notice of violation from insp on 821129-1202 * Division of Engineering & Technical Programs 83/01/20 1p 17006 291 24X Fiche 50-334, 83/01/20, 8302030499

--8302030511 IE Insp Rept 50-334/82-30 on 821129-1202 Noncompliance noted unapproved & unreviewed procedure implemented for emergency squad drills FINAEL, A, PLISCO, L, ANDERSON, C J Region 1, Office of Director 83/01/18 11pp 17006 292 24X Fiche 50-334, 83/01/20, 8302030499

8302030389 Forwards IE Insp Rept 50-334/82-29 on 821201-830103 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/01/21 CAREY, J J Duquesne Light Co 2pp 17005 326 24X Fiche 50-334, 83/01/21, 8302030389

--8302030397 IE Insp Rept 50-334/82-29 on 821201-830103 No noncompliance noted Major areas inspected document control program, plant operations, housekeeping, fire protection, radiological controls & physical security TROSKOSKI, W M, LAZARUS, W, TRIPP, L E Division of Project & Resident Programs 83/01/19 15pp 17005 328 24X Fiche 50-334, 83/01/21, 8302030389

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H20C & H30C Gearheads " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302160107 Notification 83-08 of 830215 meeting w/util in Shippingsport, PA to discuss SALP, TRIPP, L E Division of Project & Resident Programs 83/02/02 Division of Project & Resident Programs 1p 17160 236 24X Fiche 50-334, 83/02/02, 8302160107

8302100122 Requests remittance of Class III fee for review of util 821221 request for relief from requirements of Section XI of ASME Code re inservice insp for pumps & valves DUGES, R M License Fee Management Branch 83/02/03 CAREY, J J Duquesne Light Co 1p 17134 323 24X Fiche 50-334, 83/02/03, 8302100122

8302180440 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations " No Dunker-Ramo electrical penetration assemblies installed or planned for installation at facility
 CAREY, J J Duquesne Light Co 83/02/03 HAYNES, R C Region 1, Office of Director 2pp 17213 361 24X Fiche 50-334, 83/02/03, 8302180440

8302250282 Forwards IE Insp Rept 50-334/83-01 on 830104-31 No noncompliance noted
 STAROSTECKI, R Division of Project & Resident Programs 83/02/09
 CAREY, J J Duquesne Light Co 2pp 17291 349 24X
 Fiche 50-334, 83/02/09, 8302250282

--8302250289 IE Insp Rept 50-334/83-01 on 830104-31 No noncompliance noted Major areas inspected licensee action on previous insp findings, plant operations, housekeeping, fire protection, physical security & LER followup
 TROSKOSKI, W M, LAZARUS, W J, TRIPP, L E Division of Project & Resident Programs 83/02/09 15pp 17291 351 24X
 Fiche 50-334, 83/02/09, 8302250282

8302220255 Forwards fee for 821221 relief request from ASME Code requirements re inservice insp of pumps & valves
 BIERER, J D Duquesne Light Co 83/02/11 License Fee Management Branch 1p 17230 124 24X Fiche 50-334, 83/02/11, 8302220255

8302250185 Forwards addl info requested on 821214 re response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mtilus Sp (Mussel) "
 CAREY, J J Duquesne Light Co 83/02/14 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 17293 038 24X Fiche 50-334, 83/02/14, 8302250185

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302010666 Forwards "NPDES Discharge Monitoring Rept. Dec 1982 " FEITKNECHT, C Duquesne Light Co 83/01/28 REID, R W Operating Reactors Branch 4 3pp 16979 205 24X Fiche 50-334, 83/01/28, 8302010666

--8302010670 "NPDES Discharge Monitoring Rept. Dec 1982 " STEED, L S Duquesne Light Co 83/01/26 24pp 16979 208 24X
 Fiche 50-334, 83/01/28, 8302010666

8302280342 Forwards NPDES discharge monitoring repts for Jan 1983
 FEITKNECHT, C Duquesne Light Co 83/02/24 REID, R W Operating Reactors Branch 4 2pp 17313 063 24X Fiche 50-334, 83/02/24, 8302280342

--8302280347 NPDES discharge monitoring repts for Jan 1983
 * Duquesne Light Co 83/02/24 14pp 17313 065 24X
 Fiche 50-334, 83/02/24, 8302280342

S Reportable occurrences, LERs & related correspondence

8302040218 Part 21 rept re Pacific Scientific Co mechanical shock suppressors w/damaged internals Suppressors repaired, retested & certified acceptable
 WILD, P A Stone & Webster, Inc 82/12/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 17020 196 24X
 Fiche 50-334, 82/12/10, 8302040218

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp/high humidity environ Replacement part identification will be provided to operators by 830218
 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
 Fiche 50-000, 82/12/17, 8302030495

8302070076 Partial response to FOIA request for 22 categories of documents Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App B documents completely withheld (ref FOIA Exemption 3)
 FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, B Union of Concerned Scientists 6pp 17063 005 24X
 Fiche 50-281, 82/12/21, 8302070076

--8302070192 Forwards info re facility incidents concerning misalignment of high head safety injection isolation valve, per P Bobe 820324 request Incident possibly caused by sabotage
 MCCORKLE, O W Power Reactor Safeguards Licensing Branch 82/03/24 HELTEMES, C J Director's Office 2pp 17065 041 24X
 Fiche 50-000, 82/12/21, 8302070076

8302070576 Forwards LER 82-060/03L-0
 LACEY, W S Duquesne Light Co 83/01/25 HAYNES, R C Region 1, Office of Director 3pp 17034 293 24X Fiche 50-334, 83/01/25, 8302070576

--8302070583 LER 82-060/03L-0 on 821226, river water sys valve MOV-RW-106A failed to close from control room Caused by failed 11estarter due to broken forward contractor movable slide resulting from coil mounting binding Contractor replaced
 * Duquesne Light Co 83/01/13 Region 1, Office of Director 1p 17034 296 24X Fiche 50-334, 83/01/25, 8302070576

8302090368 Forwards LER 82-061/03L-0
 LACEY, W S Duquesne Light Co 83/01/25 HAYNES, R C Region 1, Office of Director 2pp 17070 323 24X Fiche 50-334, 83/01/25, 8302090368

--8302090378 LER 82-061/03L-0 on 821230, accumulator outside fill line isolation valve 81-41 found locked open On 821228, operator unintentionally left 81-41 open following completion of fill procedure Operator reprimanded
 * Duquesne Light Co 83/01/21 Region 1, Office of Director 2pp 17070 325 24X Fiche 50-334, 83/01/25, 8302090368

8302180443 Forwards LER 83-001/03L-0
 LACEY, W S Duquesne Light Co 83/02/02 HAYNES, R C Region 1, Office of Director 2pp 17215 128 24X Fiche 50-334, 83/02/02, 8302180443

--8302180450 LER 83-001/03L-0 on 830102, fire barrier penetration from east cable vault ceiling to containment purge duct room floor discovered unsealed Caused by area differential pressure Both penetration ends will be taped
 * Duquesne Light Co 83/01/25 Region 1, Office of Director 2pp 17215 130 24X Fiche 50-334, 83/02/02, 8302180443

8302180190 PNO-1-83-008 on 830212, failure in joint of instrument air line caused B MSIV to close Closure resulted in increase of steam flow in remaining steam lines & high steam pressure rate signal Safety injection 2 reactor trip initiated
 TROSKOSKI, W, LAZARUS, W Region 1, Office of Director 83/02/14 1p 17216 019 24X Fiche 50-334, 83/02/14, 8302180190

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
 EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8210150452 Forwards reviews of procedures proposed by utility in emergency plans to consider meteorological conditions at facilities, in response to Task Order 1 of interagency agreement
 VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 EPICKLER, I Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X
 Fiche 50-000, 82/10/08, 8210150452

--8210150459 "Evaluation of Procedures Proposed by FL Power & Light Co in Emergency Plans to Consider Meteorological Conditions in St Lucie Plant Coastal Environ "
 VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 304 24X
 Fiche 50-000, 82/10/08, 8210150452

DOCKETED ITEMS

8302010643 Requests postponement until 830215 of response dates to NRC fire protection draft safety evaluation ltrs Addl time needed to explore other response alternatives
UHRIO, R E Florida Power & Light Co 83/01/27 VOLLMER, R H
Division of Engineering 1p 16980 063 24X Fiche 50-000, 83/01/27, 8302010643

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302180437 Requests extension until 830301 of response dates to NRC 830106 & 14 ltrs re fire protection draft safety evaluation
UHRIO, R E Florida Power & Light Co 83/02/15 EISENHUT, D O
Division of Licensing 1p 17215 018 24X Fiche 50-000, 83/02/15, 8302180437

8302240216 Advises that extension to 830301 for response to draft safety evaluation of App R fire protection exemption requests acceptable per 830215 ltr
EISENHUT, D O Division of Licensing 83/02/18 UHRIO, R E Florida Power & Light Co. 2pp 17288 239 24X Fiche 50-000, 83/02/18, 8302240216

J Insurance & indemnity information

8302080273 Forwards Endorsement 44 to NELIA Policy NF-227 & Endorsement 35 to MAELU Policy MF-88
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div
82/12/23 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17056 342 24X Fiche 50-335, 82/12/23, 8302080273

8302070207 Forwards Endorsements 45 & 36 to NELIA Policy NF-227 & MAELU Policy MF-88, respectively
DUCK, J R Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div
83/01/24 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17031 310 24X Fiche 50-335, 83/01/24, 8302070207

P Operating license stage documents & correspondence

8302010013 Forwards SER re main steam line break w/continued feedwater addition Analysis acceptable
CLARK, R A Operating Reactors Branch 3 83/01/17 UHRIO, R E
Florida Power & Light Co. 2pp 16970 065 24X
Fiche 50-335, 83/01/17, 8302010013

8302010018 SER re main steam line break w/continued feedwater addition Analysis acceptable
* Office of Nuclear Reactor Regulation, Director 83/01/17 7pp, 16990 067 24X Fiche 50-335, 83/01/17, 8302010013

8212010094 "PWR Main Steam Line Break W/Continued Feedwater Addition (B-69), St Lucie Unit 1," technical evaluation rept
VOBBURY, F W, Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5506-138 82/11/24 HEARN, P NRC - No Detailed Affiliation Given 24pp 16990 074 24X
Fiche 50-335, 83/01/17, 8302010013

8302010576 Application to amend License DPR-67, App A Amend revises Tech Spec 3.1.1 re shutdown margin requirement Safety analysis repts re Cycle & reload encl
UHRIO, R E Florida Power & Light Co 83/01/20 EISENHUT, D O
Division of Licensing 2pp 16976 083 24X Fiche 50-335, 83/01/20, 8302010576

8302010582 Proposed changes to Tech Specs re shutdown margin requirement
* Florida Power & Light Co 83/01/24 4pp 16976 085 24X
Fiche 50-335, 83/01/20, 8302010576

8302010588 "St Lucie Unit 1 LOCA Analysis Using EXEM/PWR ECCS Model" KRAJICEK, J E, JENSEN, S E, STOUT, R B Exxon Nuclear Co., Inc (subs. of Exxon Corp.), XN-NF-82-98, 82/12/20, 47pp 16976 091 24X Fiche 50-335, 83/01/20, 8302010576

8302010599 Rev 1 to "St Lucie Unit 1 Cycle & SAR," HOLM, J B, LINDQUIST, T R, STOUT, R B Exxon Nuclear Co., Inc (subs. of Exxon Corp.), XN-NF-82-81 R01, 83/01/07 68pp 16976 137 24X Fiche 50-335, 83/01/20, 8302010576

8302010605 "Plant Transient Analysis for St Lucie Unit 1" NUTT, W T, COOKE, G C, STOUT, R B Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), XN-NF-82-99, 83/01/07 166pp, 16976 205 24X
Fiche 50-335, 83/01/20, 8302010576

8302010250 Advises that responses to NRC 830103 ltr re natural circulation cooldown will be provided by 830228
UHRIO, R E Florida Power & Light Co 83/01/24 CLARK, R A
Operating Reactors Branch 3 1p 16973 360 24X
Fiche 50-335, 83/01/24, 8302010250

8302020122 Forwards safety evaluation approving electrical, instrumentation & control design aspects of override of containment purge valve isolation
CLARK, R A Operating Reactors Branch 3 83/01/25 UHRIO, R E
Florida Power & Light Co 2pp 16999 216 24X
Fiche 50-335, 83/01/25, 8302020122

8302020126 Safety evaluation approving electrical, instrumentation & control design aspects of override of containment purge valve isolation
* NRC - No Detailed Affiliation Given 83/01/25 1p 16999 218 24X Fiche 50-335, 83/01/25, 8302020122

8301070317 "Technical Evaluation of Electrical, Instrumentation & Control Design Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Features for St Lucie Nuclear Generating Plant" COOPER, J H EOL, Inc 1183-4198 80/08/31 NRC - No Detailed Affiliation Given 16pp 16999 219 24X Fiche 50-335, 83/01/25, 8302020122

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090072 Generic Ltr 83-108 to all licensees w/C-E designed NSSR re resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consumers Power Co 32pp 17290 185 24X Fiche 50-000, 83/02/08, 8302090072

8302150007 Application for amend to License DPR-67, revising linear heat rate Tech Spec prior to unit restart following upcoming refueling outage
UHRIO, R E Florida Power & Light Co 83/02/08 EISENHUT, D O
Division of Licensing 2pp 17147 079 24X Fiche 50-335, 83/02/08, 8302150007

8302150008 Proposed Tech Spec revising linear heat rate prior to unit restart following upcoming refueling outage
* Florida Power & Light Co 83/02/08 12pp 17147 081 24X
Fiche 50-335, 83/02/08, 8302150007

8302230443 Application for amend to License DPR-67, revising surveillance requirements of 125-volt dc batteries in conjunction w/mods to sys
UHRIO, R E Florida Power & Light Co 83/02/16 EISENHUT, D O
Division of Licensing 3pp 17297 064 24X Fiche 50-335, 83/02/16, 8302230443

8302230451 Proposed Tech Specs 3/4 B 2.3 re battery surveillance requirements
* Florida Power & Light Co 83/02/16 4pp 17297 067 24X
Fiche 50-335, 83/02/16, 8302230443

8302230322 Forwards Class III fees for 830120, 0208 & 16 amend requests
UHRIO, R E Florida Power & Light Co 83/02/17 EISENHUT, D O
Division of Licensing 1p 17248 151 24X Fiche 50-335, 83/02/17, 8302230322

8302230437 Responds to 830118 request for addl info on post-implementation review of NUREG-0737, Items II F.1.4, II F.1.5 & II F.1.6 Request re accuracy of monitoring sys exceeds level of clarification required in NUREG-0737
UHRIO, R E Florida Power & Light Co 83/02/17 CLARK, R A
Operating Reactors Branch 3 1p 17245 256 24X
Fiche 50-335, 83/02/17, 8302230437

DOCKETED ITEMS

211

A Inspection Reports, IE Bulletins & correspondence

8302150422 Forwards IE Insp Repts 50-335/82-41 & 50-389/82-63 on 821111-1210 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/12
UHRIO, R E Florida Power & Light Co 2pp 17148 099 24X
Fiche 50-335, 83/01/12, 8302150422

--8302150428 IE Insp Repts 50-335/82-41 & 50-389/82-63 on 821111-1210 No noncompliance noted Major areas inspected maint, surveillance, procurement, operational safety verification, new fuel handling & operating procedure review
CLROD, S A, GIBB, H E, DANCE, H Division of Project & Resident Programs 83/01/11 16pp 17148 101 24X Fiche 50-335, 83/01/12, 8302150422

8302150696 Forwards IE Insp Repts 50-335/82-42 & 50-389/82-64 on 821210 No noncompliance noted Differing insp dates noted throughout package
DANCE, H C Division of Project & Resident Programs 83/01/12
UHRIO, R E Florida Power & Light Co 2pp 17152 001 24X
Fiche 50-335, 83/01/12, 8302150696

--8302150704 IE Insp Repts 50-335/82-42 & 50-389/82-64 on 821206-10 No noncompliance noted Major areas inspected previous enforcement matters, maint programs, test & experiments programs & licensee action on previous insp findings
SKINCR, P H, UPRIGHT, C M Division of Engineering & Radiological Safety Programs 83/01/10 6pp 17152 003 24X
Fiche 50-335, 83/01/12, 8302150696

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 11pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiterque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 10pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 11pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 11pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 12pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LFRs & related correspondence

8302010463 Forwards LER 82-068/03L-0
WILLIAMS, J W Florida Power & Light Co 83/01/19 O'REILLY, J P
Region 2, Office of Director 1p 16981 018 24X
Fiche 50-335, 83/01/19, 8302010463

--8302010467 LER 82-068/03L-0 on 821220, one of four redundant 120-volt ac instrument power buses was lost when 1A static inverter output breaker opened Cause not determined Inverter contacts cleaned & tested Inverter returned to svc
BRANNIN, J P Florida Power & Light Co 83/01/19 Region 2, Office of Director 1p 16981 019 24X Fiche 50-335, 83/01/19, 8302010463

8302010311 Forwards LER 82-070/03L-0
WILLIAMS, J W Florida Power & Light Co 83/01/24 O'REILLY, J P
Region 2, Office of Director 1p 16977 020 24X
Fiche 50-335, 83/01/24, 8302010311

--8302010320 LER 82-070/03L-0 on 821229, during routine testing, emergency safety features actuation & reactor protection sys channel B input for containment pressure failed Caused by failed 45-volt power supply Power supply replaced
ROTELLA, T S Florida Power & Light Co 83/01/24 Region 2, Office of Director 1p 16977 021 24X Fiche 50-335, 83/01/24, 8302010311

8302010477 Forwards LER 82-069/03L-0
WILLIAMS, J W Florida Power & Light Co 83/01/26 O'REILLY, J P
Region 2, Office of Director 1p 16981 024 24X
Fiche 50-335, 83/01/26, 8302010477

--8302010488 LER 82-069/03L-0 on 821227, control element assembly (CEA) 43 slipped 45 inches during periodic CEA exercise Cause not determined CEA 43 restored to normal position
HAMBY, M R Florida Power & Light Co 83/01/26 Region 2, Office of Director 1p 16981 025 24X Fiche 50-335, 83/01/26, 8302010477

8302140104 Forwards LER 82-071/03L-0
WILLIAMS, J W Florida Power & Light Co 83/01/31 O'REILLY, J P
Region 2, Office of Director 1p 17140 103 24X
Fiche 50-335, 83/01/31, 8302140104

--8302140109 LER 82-071/03L-0 on 821230, turbine & reactor tripped, resulting in DEQ I-131 spike Caused by open circuit in reactor protection sys trip logic due to 1A inverter frequency oscillator drift Circuit board replaced
ROTELLA, T S Florida Power & Light Co 83/01/31 Region 2, Office of Director 4pp 17140 106 24X Fiche 50-335, 83/01/31, 8302140104

8302140033 Forwards LER 83-005/03L-0
WILLIAMS, J W Florida Power & Light Co 83/02/03 O'REILLY, J P
Region 2, Office of Director 1p 17140 180 24X
Fiche 50-335, 83/02/03, 8302140033

--8302140035 LER 83-005/03L-0 on 830110, auxiliary feedwater pump discharge (MV-09-11) failed to operate during surveillance Caused by dirty Gould contacts Contacts cleaned
PARKS, B M Florida Power & Light Co 83/02/03 Region 2, Office of Director 1p 17140 181 24X Fiche 50-335, 83/02/03, 8302140033

8302140112 Forwards LER 83-001/03L-0
WILLIAMS, J W Florida Power & Light Co 83/02/03 O'REILLY, J P
Region 2, Office of Director 1p 17140 057 24X
Fiche 50-335, 83/02/03, 8302140112

--8302140119 LER 83-001/03L-0 on 830104, channel MC containment radiation isolation bistable found to trip at 10 117 R/h vice 10 R/h Tech Spec limit Cause of consolidated Control Model 6N8B-1 bistable drift undetermined Setpoint adjusted
PARKS, B M Florida Power & Light Co 83/02/03 Region 2, Office of Director 1p 17140 098 24X Fiche 50-335, 83/02/03, 8302140112

8302150355 Forwards LER 83-002/03L-0
WILLIAMS, J W Florida Power & Light Co 83/02/07 O'REILLY, J P
Region 2, Office of Director 1p 17157 268 24X
Fiche 50-335, 83/02/07, 8302150355

--8302150361 LER 83-002/03L-0 on 830106, pressurizer surge line sample containment isolation valve failed to close upon signal from remote switch Caused by mechanical freeze due to corrosion buildup between bonnet & stem Valve repaired
WEST, D Florida Power & Light Co 83/02/07 Region 2, Office of Director 1p 17157 269 24X Fiche 50-335, 83/02/07, 8302150355

8302150594 Forwards LER 83-003/03L-0
WILLIAMS, J W Florida Power & Light Co 83/02/07 O'REILLY, J P
Region 2, Office of Director 1p 17157 032 24X
Fiche 50-335, 83/02/07, 8302150594

--8302150604 LER 83-003/03L-0 on 830108, dose equivalent iodine exceeded Tech Spec limit of 1.0 uCi/g Caused by iodine spiking phenomenon in primary coolant due to transient resulting from power reduction below point of adding heat
WEST, D Florida Power & Light Co 83/02/07 Region 2, Office of Director 4pp 17157 033 24X Fiche 50-335, 83/02/07, 8302150594

8302170131 Forwards LER 83-004/03L-0
WILLIAMS, J W Florida Power & Light Co 83/02/09 O'REILLY, J P
Region 2, Office of Director 1p 17181 358 24X
Fiche 50-335, 83/02/09, 8302170131

DOCKETED ITEMS

02170135 LER 83-004/03L-0 on 830114, auxiliary feedwater pump C trip & throttle valve not manually reset Caused by operator oversight Operator counseled on correct trip operation
ALBES, S Florida Power & Light Co 83/02/09 Region 2, Office of Director 1p 17181 359 24X Fiche 50-335, 83/02/09, 8302170131

170154 Forwards updated LER 82-053/03X-1
LIAMBS, J W Florida Power & Light Co 83/02/11 O'REILLY, J P
Region 2, Office of Director 1p 17180 138 24X
Fiche 50-335, 83/02/11, 8302170154

02170160 Updated LER 82-053/03X-1 on 821108, while performing post-maintenance surveillance test of steam driven auxiliary feedwater pump 1C, steam supply valve MV-08-13 failed to open Caused by failed pump start switch Switch replaced
IRANMIN, J P Florida Power & Light Co 83/02/11 Region 2, Office of Director 1p 17180 139 24X Fiche 50-335, 83/02/11, 8302170154

080045 Forwards LER 83-008/03L-0
LIAMBS, J W Florida Power & Light Co 83/02/18 O'REILLY, J P
Region 2, Office of Director 1p 17307 196 24X
Fiche 50-335, 83/02/18, 8302280045

02280047 LER 83-008/03L-0 on 830128, while testing operability of containment fan coolers using staggered test basis, MVS-1D failed to start Caused by dirty breaker contacts at load
tr breaker Breaker overhauled & thoroughly cleaned
ALBES, S A Florida Power & Light Co 83/02/18 Region 2, Office of Director 1p 17307 197 24X Fiche 50-335, 83/02/18, 8302280045

erator Examinations

10203 Generic Ltr 83-06 to all power reactor licensees, applicants, OLs, NSB vendors, reactor vendors, & AE re certificates revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

80353 Submits response to Generic Ltr 83-01 re request to identify site visits to conduct operator licensing exams on reactor certification
FLORE, E Florida Power & Light Co 83/02/23 EISENHUT, D O
Division of Licensing 2pp 17311 060 24X Fiche 50-335, 83/02/23, 83020353

T 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

curity, medical, emergency & fire protection plans

90078 Forwards revised reporting procedure of security events procedures withheld (ref 10CFR73 21)
NSIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
NSIL, W O Northeast Utilities 83/01/07 MCCORMACK, O Licensing
Management Branch 3pp 16946 303 24X Fiche 50-000, 83/01/07, 8302030078

30345 Discusses filing of copies of changes to emergency plans & procedures Util requested to continue submitting three copies to Region I or two copies to Region I w/one copy actually submitted to resident inspector
FIN, T T Division of Engineering & Technical Programs 83/01/24
JNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17006 108 24X Fiche 50-000, 83/01/24, 8302030345

10081 Releases public version of revised title pages to Emergency
FELTON, J M Division of Rules and Records 83/01/26 Document
Management Branch 1p 16990 233 24X Fiche 50-000, 83/01/26, 83010081

010084 Forwards public version of revised title pages to Millstone Haddam Neck Nuclear Power Plant Emergency Plans, including instruction to site plan Figure 7-1c re lines of communication between emergency response centers
PIERRE, M Northeast Utilities 83/01/13 BAILEY, I NRC - No
failed Affiliation Given 1p 16990 234 24X
Fiche 50-000, 83/01/26, 8302010081

010091 Public version of revised title page to Millstone Nuclear Power Plant Emergency Plan
Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/01/13 1p 16990 235 24X Fiche 50-000, 83/01/26, 8302010091.

8302030233 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/26 Document
Management Branch 1p 17023 289 24X Fiche 50-245, 83/01/26, 8302030233

--8302030250 Forwards public version of revised Emergency Plan implementing Procedures EPIP 4308, "Waterford, State & Tri-Town Radio Operation" & EPIP 4612, "Waterford, State & Tri-Town Radio Test"
COUNCIL, W O, CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities
83/01/18 EISENHUT, D O Division of Licensing 1p 17023 290 24X Fiche 50-245, 83/01/26, 8302030233

--8302030262 Public version of revised Emergency Plan implementing Procedures EPIP 4308, "Waterford, State & Tri-Town Radio Operation" & EPIP 4612, "Waterford, State & Tri-Town Radio Test" Revised index encl
MROCK, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/03 18pp 17023 291 24X
Fiche 50-245, 83/01/26, 8302030233

8302090174 Responds to 821104 ltr re Rev 12 to modified amended security plan Proposed changes acceptable Encls to util ltr withheld (ref 10CFR73 21)
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/28 COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17132 105 24X Fiche 50-245, 83/01/28, 8302090174

8302030033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/31 Document
Management Branch 1p 17027 004 24X Fiche 50-000, 83/01/31, 8302030033

--8302030043 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4101 re unusual event actions, EPIP 4102 re alert & EPIP 4103 re site area emergency
COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W O Northeast Utilities 83/01/07 EISENHUT, D O
Division of Licensing 2pp 17027 005 24X Fiche 50-000, 83/01/31, 8302030033

--8302030052 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4101 re unusual event actions, EPIP 4102 re alert & EPIP 4103 re site area emergency
* Connecticut Yankee Atomic Power Co * Northeast Nuclear Energy Co (subs of Northeast Utilities) * Northeast Utilities
82/12/15 683pp 17027 007 24X Fiche 50-000, 83/01/31, 8302030033

8302070566 Lists objectives of fire protection program PRA to quantify overall frequency of failure to achieve safe shutdown as result of fire at facilities
COUNCIL, W O Northeast Utilities COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/31 EISENHUT, D O Division of Licensing 2pp 17034 282 24X Fiche 50-000, 83/01/31, 8302070566

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302040517 Accepts changes to Rev 9 of modified amended security plan, submitted by util 821103 ltr Encl to util ltr withheld (ref 10CFR73 21)
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/01 COUNCIL, W O
Northeast Utilities 3pp 17043 359 24X Fiche 50-245, 83/02/01, 8302040517

8302150498 Responds to 830106 request for evaluation of draft SER re fire protection & denial of util requests for exemption from App R Working-level meeting requested to clarify misunderstandings & close remaining open issues
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/02/02 EISENHUT, D O Division of Licensing 2pp 17156 326 24X
Fiche 50-245, 83/02/02, 8302150498

DOCKETED ITEMS

213

8302160224 Recommends NRC prepare status rept of NRC contractor studies re radioactive iodine source terms & issue of potassium iodine Rept would help resolve issue for state & local emergency preparedness personnel
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/02/08 EISENHUT, D O
Division of Licensing 2pp 17166 292 24X Fiche 50-000, 83/02/08, 8302160224

8302160125 Responds to 821103 ltr re changes to security plan changes to Revs 11 & 13 consistent w/provisions of 10CFR50.54 & acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/09 COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
17160 251 24X Fiche 50-245, 83/02/09, 8302160125

8302180174 Ack receipt of 821230 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-245/B2-01 & 50-336/B2-01
MARTIN, T T Division of Engineering & Technical Programs 83/02/10
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17215 349 24X Fiche 50-245, 83/02/10, 8302180174

--8302180184 Responds to NRC 820611 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-245/B2-01 & 50-336/B2-01 Corrective actions extremity monitoring devices placed in emergency kits & trend analyses program developed
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CAONETTA, J P Northeast Utilities 82/12/30
SMITH, G H Division of Emergency Preparedness & Operational Support 4pp 17215 351 24X Fiche 50-245, 83/02/10, 8302180174

8302230497 Determines that changes to physical security plan proposed in 821118 ltr do not decrease security effectiveness & may be submitted for formal review
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/18 COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p
17303 138 24X Fiche 50-245, 83/02/18, 8302230497

P Operating license stage documents & correspondence

8302010301 Forwards addl reporting criteria for unplanned liquid radioactive releases New criteria cover specific types of potential liquid releases not presently covered Response requested by 830403
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/01/21 HAYNES, R C Region 1, Office of Director 7pp 16973 092 24X Fiche 50-000, 83/01/21, 8302010301

8302040226 Forwards Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively & notice of issuance & availability Amends reflect organizational changes Haddam Neck amend also approves change to upper range intake water temp sensor
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 COUNCIL, W G
Connecticut Yankee Atomic Power Co 5pp 17020 115 24X
Fiche 50-000, 83/01/26, 8302040226

--8302040231 Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively, revising App B Tech Spec re organizational changes & changing upper range intake water temp sensor for Haddam Neck
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 23pp
17020 120 24X Fiche 50-000, 83/01/26, 8302040226

--8302040240 Notice of issuance & availability of Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 83/01/26 2pp
17020 143 24X Fiche 50-000, 83/01/26, 8302040226

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re license qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 7pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090072 Generic Ltr 83-108 to all licensees w/C-E designed NSSS re resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps" Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consumers Power Co 32pp 17290 185 24X Fiche 50-000, 83/02/08, 8302090072

8302230019 Forwards safety evaluation & supporting technical evaluation rept re containment purging & venting Request for addl info re outstanding issues of containment purge/vent review also encl Response requested within 45 days
CLARK, R A Operating Reactors Branch 3 83/02/09 COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp
17241 302 24X Fiche 50-336, 83/02/09, 8302230019

--8302230022 Safety evaluation re containment purging & venting Bvd j to implementation of listed actions, purge/vent sys design acceptable
* Office of Nuclear Reactor Regulation, Director 83/02/09 3pp
17241 306 24X Fiche 50-336, 83/02/09, 8302230019

--8302230027 Safety evaluation re override of containment purge isolation & other ESF actuation signals Design aspects acceptable
* Office of Nuclear Reactor Regulation, Director 83/02/09 2pp
17241 309 24X Fiche 50-336, 83/02/09, 8302230019

--8302230029 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals," technical evaluation rept
* Office of Nuclear Reactor Regulation, Director 83/02/09 7pp
17241 311 24X Fiche 50-336, 83/02/09, 8302230019

--8302230043 Safety evaluation approving purge/vent valve isolation dependability per NUREG-0737, Items II E 4.2, II E 4.6 & II E 4.7
* Office of Nuclear Reactor Regulation, Director 83/02/09 8pp
17241 318 24X Fiche 50-336, 83/02/09, 8302230019

8302180429 Informs that fuel vendor provided NRC w/technical rept describing revised computer code in fulfillment of NUREG-0737, Item II K 3.30 Small break LOCA model will be submitted by 830501
COUNCIL, W G SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/02/10
EISENHUT, D O Division of Licensing 2pp 17215 182 24X
Fiche 50-336, 83/02/10, 8302180429

8302220427 Notifies that completion date for mods necessary to correct inadequacies associated w/equipment installed per NUREG-0737, Items II F 1.1 & II F 1.2 extended to 830901 Vendor isotopical calibr rept received later than expected
COUNCIL, W G SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/02/11
CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 3 2pp 17232 130 24X Fiche 50-245, 83/02/11, 8302220427

8302280226 Informs that decision to reaffirm or withdraw request for hearing on environ qualification of safety-related electrical equipment will be determined within 30-day period following 830222 final rule effective date
COUNCIL, W G SEARS, C F Northeast Utilities 83/02/22
EISENHUT, D O Division of Licensing 2pp 17304 353 24X
Fiche 50-000, 83/02/22, 8302280226

8302280431 Forwards addl info re measurement uncertainties per NRC 820819 ltr Process equipment installed during Cycle 4/5 refueling outage provided excellent operating characteristics of modified channels w/minimal drift
COUNCIL, W G SEARS, C F Northeast Utilities COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/02/22 CLARK, R A Operating Reactors Branch 3, 28pp
17309 170 24X Fiche 50-336, 83/02/22, 8302280431

0 Inspection reports, IE Bulletins & correspondence

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr, URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design" Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000, 83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302010651 Forwards SALP Repts for Sept 1981 - Aug 1982 Performance exhibits high level of mgt attention & involvement Ample resources appear to be effectively used
HAYNES, R C Region 1, Office of Director 83/01/27 COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp
16979 045 24X Fiche 50-000, 83/01/27, 8302010651

--8302010667 SALP rept on 821013 Troubleshooting & mod to computer sys ongoing Repts of computer failures decreased since last SALP
* Region 1, Office of Director 82/10/13 28pp 16979:077 24X
Fiche 50 000, 83/01/27, 8302010651

DOCKETED ITEMS

--8302010677 Notifies of 821103 meeting to provide forum for candid discussions re util performance
STAROSTECKI, R Division of Project & Resident Programs 82/10/27
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16979 160 24X Fiche 50-000, 83/01/27, 8302010651

--8302010682 Provides comments on 821103 meeting to ensure mutual understanding of detailed performance evaluation of Util
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Connecticut Yankee Atomic Power Co 82/11/23 HAYNES, R C Region 1, Office of Director 5pp 16979 162 24X Fiche 50-000, 83/01/27, 8302010651

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads - Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments - Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030198 Ack receipt of 821229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-13 & 50-336/82-13
MARTIN, T T Division of Engineering & Technical Programs 83/01/31 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 17001 321 24X Fiche 50-245, 83/01/31, 8302030198

--8302030202 Responds to NRC 820806 ltr re violations noted in IE Insp Repts 50-245/82-13 & 50-336/82-13 Corrective actions procedures being revised re translation of design requirements into drawings
COUNCIL, W G, CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/29 MARTIN, T T Division of Engineering & Technical Programs 2pp 17001 322 24X Fiche 50-245, 83/01/31, 8302030198

8302150543 Forwards IE Insp Repts 50-245/82-24 & 50-336/82-26 on 821228-30 & Notice of Violation
MARTIN, T T Division of Engineering & Technical Programs 83/01/31 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17156 103 24X Fiche 50-245, 83/01/31, 8302150543

--8302150551 Notice of Violation from insp on 821228-30
* Division of Engineering & Technical Programs 83/01/31 1p 17156 105 24X Fiche 50-245, 83/01/31, 8302150543

--8302150559 IE Insp Repts 50-245/82-24 & 50-336/82-26 on 821228-30 Noncompliance noted Failure to perform annual audit of applicable criteria of App B to 10CFR50 re transportation packages
CLEMONS, SHANBAKY, M Region 1, Office of Director 83/01/27 4pp 17156 106 24X Fiche 50-245, 83/01/31, 8302150543

8302180174 Ack receipt of 821230 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-245/82-01 & 50-336/82-01
MARTIN, T T Division of Engineering & Technical Programs 83/02/10 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17215 349 24X Fiche 50-245, 83/02/10, 8302180174

--8302180184 Responds to NRC 820611 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-245/82-01 & 50-336/82-01 Corrective actions extremity monitoring devices placed in emergency kits & trend analyses program developed
COUNCIL, W G, CAGNETTA, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 82/12/30 SMITH, G H Division of Emergency Preparedness & Operational Support 4pp 17215 351 24X Fiche 50-245, 83/02/10, 8302180174

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units - Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 - Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts - Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302030338 Forwards LER 82-052/03L-0 Detailed event analysis encl
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 83/01/28 HAYNES, R C Region 1, Office of Director 2pp 17001 268 24X Fiche 50-336, 83/01/28, 8302030338

--8302030324 LER 82-052/03L-0 on 821231, leak found on discharge of C svc water pump B svc water - high-pressure safety injection (HPSI) pumps were lined up to Facility 11 emergency bus leaving one HPSI operable Caused by shutdown of C svc pump FILBURN, T P Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/28 Region 1, Office of Director 1p 17001 270 24X Fiche 50-336, 83/01/28, 8302030338

8302030332 Forwards LER 82-053/03L-0
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 83/01/28 HAYNES, R C Region 1, Office of Director 1p 17005 360 24X Fiche 50-336, 83/01/28, 8302030332

--8302030340 LER 82-053/03L-0 on 821228, while placing C reactor bldg closed cooling water (RBCCW) back in svc, operator failed to align B RBCCW w/svc water header Caused by personnel error Use of procedures re-emphasized w/dept personnel DUFFY, D Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/01/28 Region 1, Office of Director 2pp 17005 361 24X Fiche 50-336, 83/01/28, 8302030332

8302220349 RO on 830131, increased primary to secondary leakage rate noted in steam generator 1 Caused by expected erosion in leakage area & thermal cycling due to power transients & plant trips Leakage rate measurements on 830202 listed
COUNCIL, W G, SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/02/10 CLARK, R A Operating Reactors Branch 3 2pp 17232 012 24X Fiche 50-336, 83/02/10, 8302220349

8302280411 Forwards LER 83-001/03L-0
MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 83/02/18 HAYNES, R C Region 1, Office of Director 1p 17308 065 24X Fiche 50-336, 83/02/18, 8302280411

--8302280415 LER 83-001/03L-0 on 830121, plant computer malfunctioned & declared inoperable Caused by defective seek relay drive card Card replaced & computer operation restored
DESLANDES, K D Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/18 Region 1, Office of Director 1p 17308 066 24X Fiche 50-336, 83/02/18, 8302280411

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302280077 Responds to Generic Ltr 83-01 re requests for site visits for licensing/certification exams from Apr 1983 - Dec 1985 Estimated exam dates tentative
COUNCIL, W G, SEARS, C F Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/18 EISENHUT, D G Division of Licensing 5pp 17307 129 24X Fiche 50-000, 83/02/18, 8302280077

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Supp 1, NUREG-0737, "Requirements for Emergency Response Capability - Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302070354 Forwards changes to nuclear security personnel training & qualification programs Changes withheld (ref 10CFR73.21)
STEART, W L Virginia Electric & Power Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director VAROA, S A Operating Reactors Branch 1 1p 17029 211 24X Fiche 50-000, 83/02/02, 8302070354

DOCKETED ITEMS

215

8302160260 Forwards proposed changes to security plans Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 17169 237 24X
Fiche 50-000, 83/02/10, 8302160260

8302230141 Forwards changes to security personnel training & qualification programs Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17243 293 24X
Fiche 50-000, 83/02/16, 8302230141

♦ Adjudicatory correspondence

8302020315 Response to Louisa County, VA proposed contentions
Contentions on effects of ultimate solution of waste disposal & on consolidation are outside scope of hearing Certificate of Svc encl
BEVANSON, D T, MCCOURREN, H J Hearing Branch 1 83/02/01 Atomic
Safety and Licensing Board Panel 15pp 16993 286 24X
Fiche 50-338, 83/02/01, 8302020315

8302070518 Response opposing Concerned Citizens of Louisa County, VA
contentions Contentions untimely & no good cause shown
Contention 1 re NEPA requirements & Contention 2 re dry cask alternative should be deferred Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 Commissioners 12pp 17039 003 24X
Fiche 50-338, 83/02/01, 8302070518

8302070524 Response to Louisa County, VA contentions Contentions 1, I, IIB2, VB, VD, VF, VG, VH(4), VI & VJ(3) should be rejected & Contentions 2, IIIA, IIIB1, VA, VC, VE, VH(1-3) & VJ(1, 2 & 4) should be deferred Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 Commissioners 20pp 17038 277 24X
Fiche 50-338, 83/02/01, 8302070524

8302070530 Response opposing Concerned Citizens of Louisa County, VA
contentions Contentions untimely & no good cause shown
Contentions 1 & 4 should be deferred & Contentions 2, 3 & 5 denied Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 Commissioners 13pp 17038 314 24X
Fiche 50-338, 83/02/01, 8302070530

8302070540 Response to Louisa County, VA contentions Contentions 1, I, IIB, IVB, IVQ, IVI(4), IVJ, IVK(3), VA, VC & VI should be denied & Contentions 2, IIIA, IIIB, IIID1, IIIE, IVA, IVC, IVE, IVH, IVI(1-3), IVK(1, 2 & 4) & VB deferred w/Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 23pp 17038 337 24X Fiche 50-338, 83/02/01, 8302070540

8302070133 Response opposing Concerned Citizens of Louisa County, VA
proposed contentions Environ impacts of transportation of spent fuel from Surry considered at Surry OL stage
Certificate of Svc encl
MCCOURREN, H J Hearing Branch 1 83/02/03 Atomic Safety and Licensing Board Panel 13pp 17032 346 24X Fiche 50-338, 83/02/03, 8302070133

8302160348 Reply to util & NRC responses to Louisa County, VA
contentions Arguments that consequences of spent fuel transportation from Surry to North Anna beyond scope of hearing exit form over substance Certificate of Svc encl
COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 83/02/09 Commissioners 5pp 17166 265 24X
Fiche 50-338, 83/02/09, 8302160348

8302230625 Order admitting Louisa County, VA as party
HOLFE, S J Atomic Safety and Licensing Board Panel 83/02/18
Louisa County, VA 2pp 17294 199 24X Fiche 50-338, 83/02/18, 8302230625

8302230651 Order memorializing 830216 joint special prehearing conference in Bethesda, MD
HOLFE, S J Atomic Safety and Licensing Board Panel 83/02/18 4pp
17295 211 24X Fiche 50-338, 83/02/18, 8302230651

J Insurance & indemnity information

8302010193 Forwards Endorsements 52 & 53 to MAELU Policies MF-57 & 96, respectively & Endorsements 48 & 41 to NELA Policies NF-186 & 240, respectively
LOVINO, L J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 83/01/24 DINITZ, I Antitrust & Economic Analysis Branch (Utility Finance) 5pp 16974 025 24X Fiche 50-000, 83/01/24, 8302010193

8302150090 Forwards Endorsements 1, 2 & 3 to MAELU Certificates M-70, 2B, 63 & 27 & NELA Certificates N-70, 2B, 63 & 27
PAINTER, B Virginia Electric & Power Co 83/02/09 DINITZ, I
Antitrust & Economic Analysis Branch (Utility Finance) 76pp
17146 065 24X Fiche 50-000, 83/02/09, 8302150090

D Advisory Committee on Reactor Safeguards reports & correspondence

8302080363 Summary of ACRS Subcommittee on Reactor Operations 820929
meeting in Washington, DC re low temp overpressurization & suppression pool or containment sump water contamination adverse effects on cooling pumps
* ACRS - Advisory Committee on Reactor Safeguards 82/12/15
ACRS - Advisory Committee on Reactor Safeguards 16pp 17107 123
24X Fiche 50-000, 82/12/15, 8302080363

P Operating license stage documents & correspondence

8302020343 Addl response to FOIA request for seven categories of info
Forwards documents listed in App A Addl comments provided
Documents also available in PDR Search for addl documents in progress
FELTON, J M Division of Rules and Records 82/12/13
SCHLESSEL, D A New York, State of 5pp 16999 119 24X
Fiche 50-000, 82/12/13, 8302020343

--8302070348 Discusses 790222 telcon re possible loose metallic matl in RCS Util initiation of 11 Westinghouse recommendations prior to & during power operation should be verified
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/26 FERGUSON, J H Virginia Electric & Power Co 1p
16999 128 24X Fiche 50-000, 82/12/13, 8302020343

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D O Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170110 Discusses Franklin Research Ctr review of licensee response to SER re environ qualification of electrical equipment
Franklin Research Ctr concerns resolved & adequate bases in place for interim operations
ENOLE, L B Operating Reactors Branch 3 82/01/27 CLARK, R
Operating Reactors Branch 3 4pp 17196 235 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170114 Amend 7 to License NPF-4, authorizing results of tests for Barton transmitters be submitted for NRC review
PARR, O D Light Water Reactors Branch 3 78/07/03 2pp
17196 239 24X Fiche 50-000, 83/01/18, 8302170019

--8302170118 Safety evaluation supporting Amend 7 to License NPF-4
* Light Water Reactors Branch 3 78/07/03 2pp 17196 241 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D O Division of Licensing 82/09/24 MIRAOLIA, F
Assistant Director for Safety Assessment 4pp 17196 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170276 Concludes that based on licensee 821027 submittal, continued operation until completion of qualification program will not present undue risk to public health & safety.
ENOLE, L B Operating Reactors Branch 3 82/10/28 EISENHUT, D O, Division of Licensing 2pp 17197 094 24X Fiche 50-000, 83/01/18, 8302170019

8302100134 Forwards Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively, safety evaluation & notice of issuance & availability Amend revises Tech Specs based on reanalysis of LOCA-ECCS performance w/7% steam generator tube plugging.
ENOLE, L B Operating Reactors Branch 3 83/01/27 STEWART, W L, Virginia Electric & Power Co 3pp 17134 287 24X
Fiche 50-338, 83/01/27, 8302100134

--8302100141 Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively, revising heat flux hot channel factor based on reanalysis of LOCA-ECCS performance assuming 7% steam generator tube plugging
CLARK, R A Operating Reactors Branch 3 83/01/27 22pp
17134 290 24X Fiche 50-338, 83/01/27, 8302100134

--8302100146 Safety evaluation supporting Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively
* Office of Nuclear Reactor Regulation, Director 83/01/27 3pp, 17134 312 24X Fiche 50-338, 83/01/27, 8302100134

DOCKETED ITEMS

- B302100150 Notice of issuance & availability of Amends 45 & 28 to Licensees NPF-4 & NPF-7, respectively
CLARK, R A Operating Reactors Branch 3 83/01/27 2pp
17134 315 24X Fiche 50-338, 83/01/27, 8302100134
- B302070277 Advises that B&W seismic & environ qualification of acoustical monitoring sys, per NUREG-0737, Item II D 3, undergoing test plan development Completion expected by 830731 w/update in Rev 4 scheduled for 830331 completion
STEWART, W L Virginia Electric & Power Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 1p 17031 148 24X Fiche 50-338, 83/01/28, 8302070277
- B302090396 Forwards addl info re control of heavy loads, in areas of lifting devices & crane design Total dynamic loads imposed on slings well within acceptable limits Final verification on polar cranes will be provided by 830301
STEWART, W L Virginia Electric & Power Co 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 17067 105 24X Fiche 50-338, 83/02/04, 8302090396
- B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295
- B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234 24X Fiche 50-000, 83/02/08, 8302080304
- B302240344 Informs that util will determine, within 30-day period following 830222, whether to request hearing re orders imposing EP requirements
CHRISTMAN, J N Hutton & Williams 83/02/22 EISENHUT, D O Division of Licensing 1p 17291 071 24X Fiche 50-000, 83/02/22, 8302240344
- G Inspection reports, IE Bulletins & correspondence**
- B302150523 Act receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Item B re cladding defects revealed in small pin hole detected as violation
O'REILLY, J P Region 2, Office of Director 83/01/19 STEWART, W L Virginia Electric & Power Co 2pp 17156 084 24X Fiche 50-338, 83/01/19, 8302150523
- B302150535 Responds to NRC 821021 ltr re violations noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Corrective actions Periodic Tests 1-PT-52 2 & 2-PT-52 2 revised to provide correct change in reactor coolant inventory
STEWART, W L Virginia Electric & Power Co 82/11/24 O'REILLY, J P Region 2, Office of Director 4pp 17156 084 24X Fiche 50-338, 83/01/19, 8302150523
- B302150541 Confirms telcon re delay of response to IE Insp Repts 50-338/82-37 & 50-339/82-37 until 821124
STEWART, W L Virginia Electric & Power Co 82/11/22 O'REILLY, J P Region 2, Office of Director 1p 17156 090 24X Fiche 50-338, 83/01/19, 8302150523
- B302150558 Forwards IE Insp Repts 50-338/82-37 & 50-339/82-37 on 820920-24 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/10/21 LEASBUD, R M Virginia Electric & Power Co 2pp 17156 091 24X Fiche 50-338, 83/01/19, 8302150523
- B302150563 Notice of violation from insp on 820920-24
* Division of Project & Resident Programs 82/10/21 1p 17156 093 24X Fiche 50-338, 83/01/19, 8302150523
- B302150570 IE Insp Repts 50-338/82-37 & 50-339/82-37 on 820920-24 Noncompliance noted inadequate procedure for RCS leak rate surveillance & failure to issue startup rept for Cycle 2 for Unit 2
BURNETT, P Y, JAFFE, F Division of Engineering & Radiological Safety Programs 82/10/18 4pp 17156 094 24X Fiche 50-338, 83/01/19, 8302150523
- 12060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360
- 8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361
- 8302170238 Forwards corrected FR notice re granting of relief from ASME Code Section XI inservice insp requirements Notice corrects expiration date
VAROA, S A Operating Reactors Branch 1 83/02/04 STEWART, W L Virginia Electric & Power Co 2pp 17195 337 24X Fiche 50-000, 83/02/04, 8302170238
- B302170243 Correction to notice of granting of relief from ASME Code Section XI inservice insp requirements Expiration date corrected
VAROA, S A Operating Reactors Branch 1 83/02/04 1p 17195 339 24X Fiche 50-000, 83/02/04, 8302170238
- 8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363
- 8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365
- 8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366
- B Reportable occurrences, LFRs & related correspondence**
- 8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495
- 8302070372 Forwards LER 83-001/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31 O'REILLY, J P Region 2, Office of Director 1p 17029 360 24X Fiche 50-338, 83/01/31, 8302070372
- B302070376 LER 83-001/03L-0 on 830112, primary grade water isolation valve to blender 1-CH-217 remained open longer than Tech Spec requirements Caused by personnel error Responsible operator retrained
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31 Region 2, Office of Director 2pp 17029 361 24X Fiche 50-338, 83/01/31, 8302070376
- 8302140092 Forwards LER 83-002/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/01 O'REILLY, J P Region 2, Office of Director 1p 17142 164 24X Fiche 50-338, 83/02/01, 8302140092
- B302140098 LER 83-002/03L-0 830104, meteorological delta temp recorder determined out of tolerance Caused by instrument drift Recorder recalibr
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/01 Region 2, Office of Director 3pp 17142 167 24X Fiche 50-338, 83/02/01, 8302140092
- 8302170190 Forwards LER 83-003/03L-0,
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/09 O'REILLY, J P Region 2, Office of Director 1p 17179 089 24X Fiche 50-338, 83/02/09, 8302170190
- B302170200 LER 83-003/03L-0 on 830122, during Mode 5, RHR flow was lost for 4 minutes, Caused by failure of 15 kV A inverter to ac vital bus 1-III, de-energizing auxiliary relay for pressure channel P-1403 Vital bus 1-III & RHR flow restored
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/09 Region 2, Office of Director 2pp 17179 090 24X Fiche 50-338, 83/02/09, 8302170190

DOCKETED ITEMS

217

I Hearing transcripts on non-antitrust matters

8302180186 Transcript of 830216 special prehearing conference in Bethesda, MD Pp 1-79
* Atomic Safety and Licensing Board Panel 83/02/16 7Bpp
17216 022 24X Fiche 50-338, 83/02/16, 8302180186

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070354 Forwards changes to nuclear security personnel training & qualification programs Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17029 211 24X
Fiche 50-000, 83/02/02, 8302070354

8302160260 Forwards proposed changes to security plans Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17169 237 24X
Fiche 50-000, 83/02/10, 8302160260

8302230141 Forwards changes to security personnel training & qualification programs Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/02/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17243 293 24X
Fiche 50-000, 83/02/16, 8302230141

G Adjudicatory correspondence

8302020315 Response to Louisa County, VA proposed contentions Contentions on effects of ultimate solution of waste disposal & on consolidation are outside scope of hearing Certificate of Svc encl
SWANSON, D T, MCQUURREN, H J Hearing Branch 1 83/02/01 Atomic
Safety and Licensing Board Panel 15pp 16993 286 24X
Fiche 50-338, 83/02/01, 8302020315

8302070518 Response opposing Concerned Citizens of Louisa County, VA contentions Contentions untimely & no good cause shown Contention 1 re NEPA requirements & Contention 2 re dry cask alternative should be deferred Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 Commissioners 12pp 17039 003 24X
Fiche 50-338, 83/02/01, 8302070518

8302070524 Response to Louisa County, VA contentions Contentions 1, IIB2, VB, VD, VF, VQ, VH(4), VI & VJ(3) should be rejected & Contentions 2, IIIA, IIIB1, VA, VC, VE, VII(1 - 3) & VJ(1, 2 & 4) should be deferred Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 Commissioners 20pp 17038 277 24X
Fiche 50-338, 83/02/01, 8302070524

8302070530 Response opposing Concerned Citizens of Louisa, VA contentions Contentions untimely & no good cause shown Contentions 1 & 4 should be deferred & Contentions 2, 3 & 5 denied Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 Commissioners 13pp 17038 314 24X
Fiche 50-338, 83/02/01, 8302070530

8302070540 Response to Louisa County, VA contentions Contentions 1, IIC, IVB, IVD, IVF, IVO, IVI(4), IVJ, IVK(3), VA, VC & VI should be denied & Contentions 2, IIIA, IIIB1, IIID1, IIIE, IVA, IVC, IVE, IVH, IVI(1 - 3), IVK(1, 2 & 4) & VB deferred N/Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams 83/02/01 23pp 17038 337 24X Fiche 50-338, 83/02/01, 8302070540

8302070133 Response opposing Concerned Citizens of Louisa County, VA proposed contentions Environ impacts of transportation of spent fuel from Surry considered at Surry OL stage Certificate of Svc encl
MCQUURREN, H J Hearing Branch 1 83/02/03 Atomic Safety and Licensing Board Panel 13pp 17032 346 24X Fiche 50-338, 83/02/03, 8302070133

8302160348 Reply to util & NRC responses to Louisa County, VA contentions Arguments that consequences of spent fuel transportation from Surry to North Anna beyond scope of hearing await form over substance Certificate of Svc encl
COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 83/02/09 Commissioners 3pp 17166 265 24X
Fiche 50-338, 83/02/09, 8302160348

8302230625 Order admitting Louisa County, VA as party
WOLFE, S J Atomic Safety and Licensing Board Panel 83/02/18
Louisa County, VA 2pp 17254 199 24X Fiche 50-338, 83/02/18, 8302230625

8302230651 Order memorializing 830216 joint special prehearing conference in Bethesda, MD
WOLFE, S J Atomic Safety and Licensing Board Panel 83/02/18 4pp
17255 211 24X Fiche 50-338, 83/02/18, 8302230651

J Insurance & indemnity information

8302010193 Forwards Endorsements 52 & 53 to MAELU Policies MF-57 & 96, respectively & Endorsements 68 & 41 to NELIA Policies NF-186 & 240, respectively
LOVINO, L J Marsh & McLennan, Inc M & M Nuclear Consultants, Inc Div 83/01/24 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance) 3pp 16974 025 24X Fiche 50-000, 83/01/24, 8302010193

8302150050 Forwards Endorsements 1, 2 & 3 to MAELU Certificates M-70, 28, 63 & 27 & NELIA Certificates N-70, 28, 63 & 27
PAINTER, B Virginia Electric & Power Co 83/02/09 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance) 76pp, 17146 065 24X Fiche 50-000, 83/02/09, 8302150050

P Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D G Division of Licensing 83/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17196 091 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170110 Discusses Franklin Research Ctr review of licensee response to SER re environ qualification of electrical equipment. Franklin Research Ctr concerns resolved & adequate bases in place for interim operations.
ENGLE, L Operating Reactors Branch 3 82/01/27, CLARK, R Operating Reactors Branch 3 4pp 17196, 235 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates & which technical evaluation reports are expected to be completed Requests justification for continued operation of each group by 821008 & 15, respectively
EISENHUT, D G Division of Licensing 82/09/24 HIRAGLIA, F, Assistant Director for Safety Assessment 4pp 17196, 265 24X
Fiche 50-000, 83/01/18, 8302170019

--8302170276 Concludes that based on licensee 821027 submittal, continued operation until completion of qualification program will not present undue risk to public health & safety
ENGLE, L Operating Reactors Branch 3 82/10/28 EISENHUT, D G Division of Licensing 2pp 17197 054 24X Fiche 50-000, 83/01/18, 8302170019

8302100134 Forwards Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively, safety evaluation & notice of issuance & availability Amend revised Tech Specs based on reanalysis of LQCA-ECCB performance w/7% steam generator tube plugging
ENGLE, L Operating Reactors Branch 3 83/01/27 STEWART, W L Virginia Electric & Power Co 3pp 17134 287 24X
Fiche 50-338, 83/01/27, 8302100134

--8302100141 Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively, revising heat flux hot channel factor based on reanalysis of LQCA-ECCB performance assuming 7% steam generator tube plugging.
CLARK, R A Operating Reactors Branch 3 83/01/27, 22pp, 17134 290 24X Fiche 50-338, 83/01/27, 8302100134

DOCKETED ITEMS

--B302100146 Safety evaluation supporting Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively
 * Office of Nuclear Reactor Regulation, Director 83/01/27 3pp
 17134 312 24X Fiche 50-338, 83/01/27, B302100134

--B302100150 Notice of issuance & availability of Amends 45 & 28 to Licenses NPF-4 & NPF-7, respectively
 CLARK, R A Operating Reactors Branch 3 83/01/27 2pp
 17134 315 24X Fiche 50-338, 83/01/27, B302100134

B302070277 Advises that B&W seismic & environ qualification of acoustical monitoring sys, per NUREG-0737, Item 11 D 3, undergoing test plan development Completion expected by 830731 w/update in Rev 4 scheduled for 830331 completion
 STEWART, W L Virginia Electric & Power Co 83/01/28 DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D O
 Division of Licensing 1p 17031 148 24X Fiche 50-338, 83/01/28, B302070277

B302100078 Informs that request to amend License Condition 2 C(2)(e) granted & Class III refund being processed
 MILLER, W D License Fee Management Branch 83/02/03 STEWART, W L
 Virginia Electric & Power Co 1p 17134 362 24X
 Fiche 50-339, 83/02/03, B302100078

B302090396 Forwards addl info re control of heavy loads, in areas of lifting devices & crane design Total dynamic loads imposed on slings well within acceptable limits Final verification on polar cranes will be provided by 830301
 STEWART, W L Virginia Electric & Power Co 83/02/04 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp 17067 105 24X
 Fiche 50-338, 83/02/04, B302090396

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000, 83/02/08, B302080295

B302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 7pp 17234 234 24X
 Fiche 50-000, 83/02/08, B302080304

B302250344 Informs that util will determine, within 30-day period following B30222, whether to request hearing re orders imposing EP requirements
 CHRISTMAN, J M Hunton & Williams 83/02/22 EISENHUT, D O
 Division of Licensing 1p 17291 071 24X Fiche 50-000, 83/02/22, B302250344

0 Inspection reports, IE Bulletins & correspondence

B302150523 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Item B re cladding defects revealed in small pin hole deleted as violation
 O'REILLY, J P Region 2, Office of Director 83/01/19 STEWART, W L
 Virginia Electric & Power Co 2pp 17156 084 24X
 Fiche 50-338, 83/01/19, B302150523

--B302150535 Responds to NRC 821021 ltr re violations noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Corrective actions
 Periodic Tests 1-PT-52 2 & 2-PT-52 2 revised to provide correct change in reactor coolant inventory
 STEWART, W L Virginia Electric & Power Co 82/11/24
 O'REILLY, J P Region 2, Office of Director 4pp 17156 086 24X
 Fiche 50-338, 83/01/19, B302150523

--B302150541 Confirms telcon re delay of response to IE Insp Repts 50-338/82-37 & 50-339/82-37 until 821124.
 STEWART, W L Virginia Electric & Power Co 82/11/22
 O'REILLY, J P Region 2, Office of Director 1p 17156 090 24X
 Fiche 50-338, 83/01/19, B302150523

- B302150558 Forwards IE Insp Repts 50-338/82-37 & 50-339/82-37 on 820920-24 & notice of violation
 LEWIS, R C Division of Project & Resident Programs 82/10/21,
 LEASBURO, R H Virginia Electric & Power Co 2pp, 17156 091 24X
 Fiche 50-338, 83/01/19, B302150523

--B302150563 Notice of violation from insp on 820920-24
 * Division of Project & Resident Programs 82/10/21, 1p
 17156 093 24X Fiche 50-338, 83/01/19, B302150523

--B302150570 IE Insp Repts 50-338/82-37 & 50-339/82-37 on 820920-24 Noncompliance noted inadequate procedure for RCS leak rate surveillance & failure to issue startup rept for Cycle 2 for Unit 2
 BURRITT, P T, JAPE, F Division of Engineering & Radiological
 Safety Programs 82/10/18 6pp 17156 094 24X
 Fiche 50-338, 83/01/19, B302150523

B212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co of New
 York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice 83-02, "Limiterque H08C, H10C, H20C & H30C Gearheads " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

B302170238 Forwards corrected FR notice re granting of relief from ASME Code Section XI inservice insp requirements Notice corrects expiration date
 VARGA, S A Operating Reactors Branch 1 83/02/04 STEWART, W L
 Virginia Electric & Power Co 2pp 17195 357 24X
 Fiche 50-000, 83/02/04, B302170238

--B302170243 Correction to notice of granting of relief from ASME Code Section XI inservice insp requirements Expiration date corrected
 VARGA, S A Operating Reactors Branch 1 83/02/04 1p
 17195 359 24X Fiche 50-000, 83/02/04, B302170238

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co of New
 York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

B Reportable occurrences, LERs & related correspondence

B302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J
 Region 4, Office of Director 4pp 17006 128 24X
 Fiche 50-000, 82/12/17, B302030495

B302010176 Forwards LER 83-003/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 83/01/19
 O'REILLY, J P Region 2, Office of Director 1p 16974 012 24X
 Fiche 50-339, 83/01/19, B302010176

--B302010187 LER 83-003/03L-0 on B30104, middle level corner support temp for steam generator A indicated less than 225 F for 12 h
 Caused by condensation due to high secondary steam leakage from body-to-bonnet leak of blowdown isolation valve
 CARTWRIGHT, W R Virginia Electric & Power Co 83/01/19 Region
 2, Office of Director 7pp 16974 013 24X Fiche 50-339, 83/01/19, B302010176

B302010207 Forwards LER 83-004/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 83/01/19
 O'REILLY, J P Region 2, Office of Director 1p 16974 005 24X
 Fiche 50-339, 83/01/19, B302010207

--B302010214 LER 83-004/03L-0 on B30105, casing cooling pump B removed from svc Caused by need to repair small leak in discharge flange of pump Repair made & pump returned to svc
 CARTWRIGHT, W R Virginia Electric & Power Co 83/01/19 Region
 2, Office of Director 1p 16974 006 24X Fiche 50-339, 83/01/19, B302010207

DOCKETED ITEMS

8302010237 Forwards LER 83-008/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/19
O'REILLY, J P Region 2, Office of Director 1p 16973 353 24X
Fiche 50-339, 83/01/19, 8302010237

--8302010245 LER 83-008/03L-0 on 830107, during Mode 3, individual rod position indication deviated from group demand position by greater than 12 steps while withdrawing shutdown bank B Caused by instrument drift Rods recalibr
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/19 Region
2, Office of Director 2pp 16973 354 24X Fiche 50-339, 83/01/19, 8302010237

8302070309 Forwards LER 83-011/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/28
O'REILLY, J P Region 2, Office of Director 1p 17029 130 24X
Fiche 50-339, 83/01/28, 8302070309

--8302070314 LER 83-011/03L-0 on 831119, individual rod position indication deviated from group demand position by greater than 12 steps Caused by instrument drift Indicator channel for rods B-09 & 02 & F-06 recalibr
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/28 Region
2, Office of Director 2pp 17029 131 24X Fiche 50-339, 83/01/28, 8302070309

8302070340 Forwards LER 83-002/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/28
O'REILLY, J P Region 2, Office of Director 1p 17029 306 24X
Fiche 50-339, 83/01/28, 8302070340

--8302070342 LER 83-002/03L-0 on 830104, two of four 2H emergency diesel generator surveillance tests required by Tech Spec missed during Nov-Dec 1982 Caused by scheduling error Test frequency increased to meet Tech Spec requirements
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/28 Region
2, Office of Director 3pp 17029 307 24X Fiche 50-339, 83/01/28, 8302070340

8302140024 Forwards LER 83-010/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31
O'REILLY, J P Region 2, Office of Director 1p 17141 180 24X
Fiche 50-339, 83/01/31, 8302140024

--8302140027 LER 83-010/03L-0 on 830109, fire door 854-13 between control room air handler room & control room chiller room would not consistently close Caused by loose door hinges & out of adjustment reclosure device Hinges tightened
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31 Region
2, Office of Director 1p 17141 181 24X Fiche 50-339, 83/01/31, 8302140024

8302140031 Forwards LER 83-013/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31
O'REILLY, J P Region 2, Office of Director 1p 17142 109 24X
Fiche 50-339, 83/01/31, 8302140031

--8302140096 LER 83-013/03L-0 on 830113, during Mode 1, individual RPI for rod P-06 in control bank A deviated from group demand position by greater than 12 steps w/no rod motion Caused by dirty contacts on signal conditioning module
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31 Region
2, Office of Director 2pp 17142 110 24X Fiche 50-339, 83/01/31, 8302140031

8302140098 Forwards LER 83-009/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31
O'REILLY, J P Region 2, Office of Director 1p 17140 150 24X
Fiche 50-339, 83/01/31, 8302140098

--8302140095 LER 83-009/03L-0 on 830112, train A reactor trip breaker bypassed for more than allowed 2 h during solid state protection sys surveillance testing Cause due to necessity to replace damaged universal logic card
CARTWRIGHT, W R Virginia Electric & Power Co 83/01/31 Region
2, Office of Director 2pp 17140 151 24X Fiche 50-339, 83/01/31, 8302140098

8302140036 Forwards LER 83-005/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/01
O'REILLY, J P Region 2, Office of Director 1p 17141 165 24X
Fiche 50-339, 83/02/01, 8302140036

--8302140047 LER 83-003/03L-0 on 830108, valve monitoring sys cabinet de-energized for maint, causing loss of valve position indication for pressurizer safety & PDV's Caused by open breakers Breakers closed after maint
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/01 Region
2, Office of Director 1p 17141 166 24X Fiche 50-339, 83/02/01, 8302140036

8302170152 Forwards LER 83-016/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/09
O'REILLY, J P Region 2, Office of Director 1p 17180 134, 24X
Fiche 50-339, 83/02/09, 8302170152

--8302170158 LER 83-016/03L-0 on 830115 & 16, both open & closed containment isolation valves TV-S1-200 & TV-CC-204C, train A position indication lights found lit Caused by leaking steam generator chemical feed line vent valve
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/09 Region
2, Office of Director 3pp 17180 135 24X Fiche 50-339, 83/02/09, 8302170152

8302170220 Forwards LER 83-014/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/09
O'REILLY, J P Region 2, Office of Director 1p 17187 107 24X
Fiche 50-339, 83/02/09, 8302170220

--8302170226 LER 83-014/03L-0 on 830113, 18 & 25, svc water supply heads to Units 1 & 2 charging pump lube oil coolers & air compressors isolated to repair pinhole leaks Caused by aggressive water & bacterial reduction of mild steel piping
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/09 Region
2, Office of Director 3pp 17187 108 24X Fiche 50-339, 83/02/09, 8302170220

8302280486 Forwards LER 83-012/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/11
O'REILLY, J P Region 2, Office of Director 1p 17308 281, 24X
Fiche 50-339, 83/02/11, 8302280486

--8302280491 LER 83-012/03L-0 on 830114, delta T indicator associated w/delta T protection for loop A read 6% high Caused by failed relay card on delta T hot loop A TE-2412B, output card replaced
CARTWRIGHT, W R Virginia Electric & Power Co 83/02/11 Region
2, Office of Director 2pp 17308 282 24X Fiche 50-339, 83/02/11, 8302280486

T Hearing transcripts on non-antitrust matters

8302180186 Transcript of 830216 special prehearing conference in Bethesda, MD Pp 1-73
* Atomic Safety and Licensing Board Panel 83/02/16 78pp.
17216 022 24X Fiche 50-338, 83/02/16, 8302180186

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302080113 Board Notification 82-122A forwards US05 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake w/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30, Atomic
Safety and Licensing Board Panel 18pp 17105.335, 24X
Fiche 50-000, 82/12/30, 8302080113

8302040286 Notification of 830126 meeting w/util in Bethesda, MD to discuss proposed changes in operator staffing & nuclear review & audit group
LYNCH, M D Licensing Branch 1 83/01/24 YOUNGBLOOD, B J
Licensing Branch 1 3pp 17042 295 24X Fiche 50-341, 83/01/24, 8302040286

8302010404 Forwards Amend 46 to amended & substituted application for license, consisting of Amend 46 to FSAR
LANDGRAF, L C LeBoeuf, Lamb, Leiby & MacRae 83/01/31 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 16974:26B, 2
Fiche 50-341, 83/01/31, 8302010404

--8302010408 Amend 46 to amended & substituted application for license consisting of Amend 46 to FSAR
HEIDEL, C H Detroit Edison Co 83/01/26 2pp, 16974 269 24X
Fiche 50-341, 83/01/31, 8302010404

DOCKETED ITEMS

8302170482 Board Notification 83-1 forwards BNL draft rept, "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach" EISENHUT, D O Division of Licensing FIN A-3397 83/02/01 PALLADINO, N J Commissioners 134pp 17203 309 24X Fiche 50-000, 83/02/01, 8302170482

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant unique-calculations which formed bases for mod Svc list encl EISENHUT, D O Division of Licensing 83/02/02 General Public Utilities - OPU Service Corp 3pp 17074 086 24X Fiche 50-000, 83/02/02, 8302030089

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR BAQCHI, Q Equipment Qualification Branch 83/02/02 NOONAN, V S Equipment Qualification Branch 3pp 17205 188 24X Fiche 50-000, 83/02/02, 8302170011

8302170197 Forwards summary repts for 24 equipment items reviewed during 810727-31 site visit REICH, M Brookhaven National Laboratory 81/09/14 ROSZTOCZY, Z Equipment Qualification Branch 74pp 17206 143 24X Fiche 50-000, 83/02/02, 8302170197

8302170052 Forwards DET-15-03B, "Single Downcomer Chugging Lateral Load" Rept demonstrates that adequate margin exists in facility downcomer design to accommodate potential increases in single downcomer chugging load spec. TAUBER, H Duquesne Light Co 83/02/04 YOUNGBLOOD, B J Licensing Branch 1 1p 17181 283 24X Fiche 50-341, 83/02/04, 8302170052

8302170056 "Single Downcomer Chugging Lateral Load" TERAMOTO, C S, LEHNERT, R A, STEINERT, L D. NUTECH Engineers, Inc DET-15-03B R00 83/02/04 20pp, 17181 285 24X Fiche 50-341, 83/02/04, 8302170056

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl. EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re GER of "Emergency Procedure Guidelines, Rev 2," NEDD-24934, June 1982 Guidelines acceptable Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp, 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302170351 Forwards Certificate of Svc for Amend 46 to amended & substituted application for licenses MATHER, B R Detroit Edison Co 83/02/08 Office of Nuclear Reactor Regulation, Director 3pp 17184 148 24X Fiche 50-341, 83/02/08, 8302170351

8302220329 Forwards proposed station blackout test methodology to be used in lieu of simulated loss of ac power test to satisfy augmented training requirements of NUREG-0737, Item I Q 1 Tests jeopardize plant & public & involve unnecessary costs TAUBER, H Detroit Edison Co 83/02/14 YOUNGBLOOD, B J Licensing Branch 1 4pp, 17230 092 24X Fiche 50-341, 83/02/14, 8302220329

D NRC Draft/Final Environmental Statements, supp's & correspondence

8302040486 FOIA request for NUREG-0769, FEB for proposed facility operation & addendum to EIS DANIELSON, S K Affiliation Unknown 82/12/22 Office of Nuclear Reactor Regulation, Director 1p 17042 255 24X Fiche 50-341, 82/12/22, 8302040486

8302040490 Responds to FOIA request for NUREG-0769, FEB for proposed facility operation & addendum to EIS Forwards documents, w/o encls. FELTON, J M Division of Rules and Records 83/01/12, DANIELSON, S K Affiliation Unknown 1p 17042 255 24X Fiche 50-341, 83/01/12, 8302040490

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8302040130 Forwards Suppl 3 to SER, NUREG-0798 re operation of plant. w/o encl YOUNGBLOOD, B J Licensing Branch 1, 83/01/24 TAUBER, H Detroit Edison Co, 2pp 17043 143 24X Fiche 50-341, 83/01/24, 8302040130

8302170216 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ENRICO FERMI ATOMIC POWER PLANT, UNIT NO 2 Docket No 50-341 (Detroit Edison Company) * Office of Nuclear Reactor Regulation, Director NUREG-0798 803 83/01/31 190pp 17189 319 24X Fiche 50-341, 83/01/31, 8302170216

8302100092 Forwards SER, Suppl 3 (NUREG-0798, Suppl 3) w/o encl YOUNGBLOOD, B J Licensing Branch 1 83/02/04 TAUBER, H Detroit Edison Co 2pp 17134 359 24X Fiche 50-341, 83/02/04, 8302100092

F. Security, medical, emergency & fire protection plans

8210150452 Forwards reviews of procedures proposed by utils in emergency plans to consider meteorological conditions at facilities in response to Task Order 1 of interagency agreement VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 SPICKLER, I Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X Fiche 50-000, 82/10/08, 8210150452

83021270051 "Evaluation of Procedures Proposed by Detroit Edison Co in Emergency Plans to Consider Meteorological Conditions in Enrico Fermi Site Coastal Environ" VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-81-099 82/10/08 SPICKLER, I Office of Nuclear Reactor Regulation, Director 4pp 16951 310 24X Fiche 50-000, 82/10/08, 8210150452

8302040324 Forwards IE Safeguards Insp Rept 50-341/83-02 on 830112-14 No noncompliance noted MILLER, J R Division of Engineering 83/01/26 WELLS, D A Detroit Edison Co 2pp 17018 246 24X Fiche 50-341, 83/01/26, 8302040324

8302040339 IE Safeguards Insp Rept 50-341/83-02 on 830112-14 No noncompliance noted Major areas inspected security plan & implementing procedures, protected vital areas & testing & maint Details withheld (ref 10CFR73 21) MADEIRA, T J, CREED, J R Region 3, Office of Director 83/01/24 2pp 17018 248 24X Fiche 50-341, 83/01/26, 8302040324

8302020433 Releases public version of addenda to revised Radiological Emergency Response Plan Evacuation Time Estimates FELTON, J M Division of Rules and Records 83/01/31 Document Management Branch 1p 16999 300 24X Fiche 50-341, 83/01/31, 8302020433

8302020437 Forwards public version of Addenda 1 & 2 to revised Radiological Emergency Response Plan Evacuation Time Estimates TAUBER, H Detroit Edison Co 83/01/10 YOUNGBLOOD, B J Licensing Branch 1 2pp 16999 301 24X Fiche 50-341, 83/01/31, 8302020433

8302020440 Public version of Addenda 1 & 2 to revised Radiological Emergency Response Plan Evacuation Time Estimates * Detroit Edison Co 82/11/30 8pp 16999 303 24X Fiche 50-341, 83/01/31, 8302020433

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

O Adjudicatory correspondence

8302080110 Notifies of NRC intent to consider 820827 petition to intervene as request for action under 10CFR2 206 DENTON, H R Office of Nuclear Reactor Regulation, Director 83/01/24 BRAUNLICH, P E Monroe County, MI 2pp 17106 001 24X Fiche 50-341, 83/01/24, 8302080110

8302080114 Notice of request for action under 10CFR2 206 DENTON, H R Office of Nuclear Reactor Regulation, Director 83/01/24 2pp 17106 003 24X Fiche 50-341, 83/01/24, 8302080110

8302010499 Order extending time until 830218 for Commission to act to review ALAB-707 CHILK, S J Office of the Secretary of the Commission 83/01/29, Commissioners 1p 16981 323 24X Fiche 50-341, 83/01/29, 8302010499

8302160343 Brief appealing ASLB 821029 initial decision Monroe County has not adopted emergency evacuation plan Board findings on Contention B erroneous & should be reversed Certificate of Svc encl
HINDOCK, J R Citizens for Energy & Employment 83/02/09 Atomic Safety and Licensing Appeal Panel 11pp 17166 281 24X
Fiche 50-341, 83/02/09, 8302160343

8302180508 Forwards Suppl 3 to EER W/o encl
WOODHEAD, C P Hearing Branch 1 83/02/10 MILHOLLIN, O L,
MORRIS, P A, SCHINK, D R Atomic Safety and Licensing Board Panel
1p 17155 253 24X Fiche 50-341, 83/02/10, 8302180508

8302220309 Requests copy of NRC ltr accepting Monroe County petition to intervene as request for action under 10CFR2 206
Guidelines for submitting info per 10CFR2 206 requested
HINDOCK, J R Minock, J MINOCK, J R Citizens for Energy & Employment 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17230 153 24X Fiche 50-341, 83/02/16, 8302220309

H General correspondence

8302170378 Forwards document presented to Monroe County Board of Commissioners summarizing concerns over evacuation process, per Monroe County petition to intervene
HUMAH, I, BARRETT, M Affiliation Unknown 83/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17183 352 24X Fiche 50-341, 83/02/10, 8302170378

K Utility Final Safety Analysis Report (FSAR) & amends

8302010404 Forwards Amend 46 to amended & substituted application for license, consisting of Amend 46 to FSAR
LANDGRAF, L C LeBoeuf, Lamb, Leiby & MacRae 83/01/31 DENTON, H Office of Nuclear Reactor Regulation, Director 1p 16974 268 24X
Fiche 50-341, 83/01/31, 8302010404

--8302010408 Amend 46 to amended & substituted application for license, consisting of Amend 46 to FSAR
HEIDEL, C H Detroit Edison Co 83/01/26 2pp 16974 269 24X
Fiche 50-341, 83/01/31, 8302010404

--8302010413 Amend 46 to FSAR
* Detroit Edison Co 83/01/31 347pp 16974 271 24X
Fiche 50-341, 83/01/31, 8302010404

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTQI, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040151 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request. Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item.
SUCHAREKI, L. Region 3, Office of Director, 82/07/08.
KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302040350 Forwards IE Insp Rept 50-341/82-19 on 821209-10. No noncompliance noted
LITTLE, W S Division of Engineering, 83/01/19 WELLS, D A Detroit Edison Co 2pp 17018 254 24X Fiche 50-341, 83/01/19, 8302040350

--8302040352 IE Insp Rept 50-341/82-19 on 821209-10. No noncompliance noted Major areas inspected followup on licensee potential 10CFR50 55(e) rept that large percentage of previously QC inspected piping support installations found rejectable
VINI T, DANIELSON, D H Division of Engineering 83/01/13 7pp 17018 256 24X Fiche 50-341, 83/01/19, 8302040350

--8302040354 QA program for Wismer & Becker
* Detroit Edison Co 82/12/09 2pp 17018 263 24X
Fiche 50-341, 83/01/19, 8302040350

8302040141 Forwards IE Insp Rept 50-341/82-21 on 821220-22 No noncompliance noted
HIND, J A Division of Emergency Preparedness & Operational Support 83/01/21 WELLS, D A Detroit Edison Co 2pp 17017 222 24X
Fiche 50-341, 83/01/21, 8302040141

--8302040158 IE Insp Rept 50-341/82-21 on 821220-22. No noncompliance noted Major areas inspected preoperational radiological environ monitoring program, including mgt controls, program implementation & results & QC of sampling measurements
DESMAN, M J, SCHUMACHER, H C Region 3, Office of Director 83/01/17 8pp 17017 224 24X Fiche 50-341, 83/01/21, 8302040141

8302060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302040324 Forwards IE Safeguards Insp Rept 50-341/83-02 on 830112-14. No noncompliance noted
MILLER, J R Division of Engineering 83/01/26 WELLS, D A Detroit Edison Co 2pp 17018 246 24X Fiche 50-341, 83/01/26, 8302040324

--8302040339 IE Safeguards Insp Rept 50-341/83-02 on 830112-14 No noncompliance noted Major areas inspected security plan & implementing procedures, protected & vital areas & testing & maint Details withheld (ref 10CFR73 21)
MADEIRA, T J, CREED, J R Region 3, Office of Director, 83/01/24, 2pp 17018 248 24X Fiche 50-341, 83/01/26, 8302040324

8302060360 IE Info Notice 83-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/26, 8212060360

8302060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/26, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session. Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302180094 Forwards IE Insp Rept 50-341/82-20 on 821101-1231 & notice of violation
KNOP, R C Division of Project & Resident Programs, 83/02/01 WELLS, D A Detroit Edison Co, 2pp 17216 200 24X
Fiche 50-341, 83/02/01, 8302180094

--8302180101 Notice of violation from insp on 821101-1231
KNOP, R C Division of Project & Resident Programs 83/02/01 1p 17216 202 24X Fiche 50-341, 83/02/01, 8302180094

--8302180104 IE Insp Rept 50-341/82-20 on 821101-1231. Noncompliance noted Failure to accomplish QA activities in accordance w/procedures
LITTLE, D H, BYRON, P M, KONKALIN, J E Division of Project & Resident Programs 83/01/31 9pp 17216 203 24X
Fiche 50-341, 83/02/01, 8302180094

8302160292 Ack receipt of 821115 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/82-13
SPESSARD, R L Division of Engineering 83/02/11 WELLS, D A, Detroit Edison Co 1p 17170 154 24X Fiche 50-341, 83/02/11, 8302160292

--8302160299 Responds to NRC 821018 ltr re violations noted in IE Insp Rept 50-341/82-13 Corrective actions: test change notice will be issued against preoperational test procedure to include proper overpressure relief valve setpoint
WELLS, D A Detroit Edison Co, 82/11/13 SPESSARD, R L Division of Project & Resident Programs, 3pp 17170 155 24X
Fiche 50-341, 83/02/11, 8302160292

8302060363 IE Info Notice 83-04, "Failure of Elms Power Supply Units." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

DOCKETED ITEMS

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

3 Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.)
82/12/10 STELLD, V Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302040074 Interim deficiency rept re arc strikes on primary containment pipe penetration bellows Initially reported on 821123 Full scale facsimile bellows scheduled for onsite repair Next rept will be sent by 830422
WELLS, D A Detroit Edison Co 82/12/23 KEPLER, J O Region 3, Office of Director 2pp 17023 326 24X Fiche 50-341, 82/12/23, 8302040074

8302040090 Interim deficiency rept re Limitorque limit switch rotor failures due to tension stress buildup Initially reported on 820731 Corrective action plan not finalized Next rept will be submitted by 830427
WELLS, D A Detroit Edison Co 82/12/28 KEPLER, J O Region 3, Office of Director 2pp 17020 327 24X Fiche 50-341, 82/12/28, 8302040090

8302150240 Final deficiency rept re questionable QC acceptance of pipe hanger installation Initially reported on 821201 Util mgt met w/Region III to present plans for implementing actions outlined in 821210 confirmatory action ltr
WELLS, D A Detroit Edison Co 83/01/14 KEPLER, J O Region 3, Office of Director 2pp 17149 262 24X Fiche 50-341, 83/01/14, 8302150240

8302040116 Interim Deficiency Rept re missing Swagelok fittings in reactor vessel Initially reported on 821229 Missing Swagelok caps will be replaced & remaining caps tightened & tackwelded to prevent loosening Next rept due by 830527
WELLS, D A Detroit Edison Co 83/01/27 KEPLER, J O Region 3, Office of Director 2pp 17017 220 24X Fiche 50-341, 83/01/27, 8302040116

8302150029 Interim deficiency rept re defective scram accumulators on control rod drive in hydraulic control units Initially reported on 821117 Accumulator assemblies sent to GE for exam & replacement Next rept scheduled for 830418
WELLS, D A Detroit Edison Co 83/01/28 KEPLER, J O Region 3, Office of Director 1p 17147 141 24X Fiche 50-341, 83/01/28, 8302150029

7 Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-344 TROJAN NUCLEAR PLANT

7. Security, medical, emergency & fire protection plans

8302080137 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17104 303 24X Fiche 50-344, 83/01/27, 8302080137

8302080183 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-19.2 re operation of dedicated telephone sys & EP-27.1 re instructions for use of computer terminal
PUZEY, A M Portland General Electric Co. 82/11/23, CLARK, R A Office of Nuclear Reactor Regulation, Director 1p, 17104, 304, 24X Fiche 50-344, 83/01/27, 8302080183

--8302080187 Public version of revised emergency plan implementing procedures, including Procedures EP-19.2 re operation of dedicated telephone sys & EP-27.1 re instructions for use of computer terminals
Portland General Electric Co 82/11/08 89pp 17104 305 24X Fiche 50-344, 83/01/27, 8302080187

8302230237 Forwards IE Insp Rept 50-344/82-36 on 821206-830107 No noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/01/27 WITHERS, B D Portland General Electric Co 2pp 17245 021 24X Fiche 50-344, 83/01/27, 8302230237

--8302230240 IE Insp Rept 50-344/82-36 on 821206-830107 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, security, procurement, corrective actions & followup on LERs & previous insp findings
MALHROS, M H, DODDS, R T Division of Resident, Reactor Project & Engineering Programs 83/01/27 6pp 17245 023 24X Fiche 50-344, 83/01/27, 8302230237

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302100171 Advises that changes to security plan consistent w/ 10CFR50.54(p) Encl to util 821123 & 1213 ltrs withheld per 10CFR73.21
CLARK, R A Operating Reactors Branch 3 83/02/02 WITHERS, B D Portland General Electric Co 3pp 17134 191 24X Fiche 50-344, 83/02/02, 8302100171

8302240129 Suppl 821110 ltr transmitting Amend 77 to License NPF-1 Current design arrangements for containment ventilation isolation, ESF reset push buttons & annunciation of override of ESF sys not acceptable
CLARK, R A Operating Reactors Branch 3 83/02/03 WITHERS, B D Portland General Electric Co 3pp 17288 201 24X Fiche 50-344, 83/02/03, 8302240129

--8302240134 Safety evaluation supporting mods to override of containment purge isolation
Office of Nuclear Reactor Regulation, Director 83/02/03 2pp 17288 204 24X Fiche 50-344, 83/02/03, 8302240129

--8208060265 "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," technical evaluation report
SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-183 82/08/04 CALVO, J NRC - No Detailed Affiliation Given 33pp 17288 206 24X Fiche 50-344, 83/02/03, 8302240129

8302170273 Informs that NRC requested that FEMA rectify misinterpretation of NRC 801103 request & limit investigation to effects of volcanic eruptions on state & local emergency planning, in response to licensee 820730 ltr
CLARK, R A Operating Reactors Branch 3 83/02/07 WITHERS, B D Portland General Electric Co 2pp 17195 355 24X Fiche 50-344, 83/02/07, 8302170273

8302170274 Approves vault for storage of documents containing safeguards info, in response to licensee 821119 request
CLARK, R A Operating Reactors Branch 3 83/02/07, WITHERS, B D Portland General Electric Co 3pp 17195 352 24X Fiche 50-344, 83/02/07, 8302170274

8302230490 Forwards License Change Application 89 for amend to License NPF-1, changing radiological emergency plan & security plan at least once per 12 months
WITHERS, B D Portland General Electric Co 83/02/16, CLARK, R A Operating Reactors Branch 3 1p 17246 191 24X Fiche 50-344, 83/02/16, 8302230490

--8302230500 License Change Application 89 for amend to License NPF-1, changing Tech Specs to require audits of activities re radiological emergency plan & security plan at least once per 12 months
Portland General Electric Co 83/02/16 4pp 17246 192 24X Fiche 50-344, 83/02/16, 8302230490

--8302230504 Proposed Tech Specs requiring audits of activities re radiological emergency plan & security plan at least once per 12 months
Portland General Electric Co 83/02/16 4pp, 17246, 193 24X Fiche 50-344, 83/02/16, 8302230490

DOCKETED ITEMS

223

J Insurance & indemnity information

8302080227 Forwards Endorsement 98 to NELIA Policy NF-225 & Endorsement 50 to MAELU Policy HF-86
JOHANNSEN, E Portland General Electric Co 83/02/01 SALTZMAN, J
Office of State Programs, Director 3pp 17057 210 24X
Fiche 50-344, 83/02/01, 8302080227

P Operating license stage documents & correspondence

8302010386 Forwards qualification info for replacement of hydrogen vent valves, per 811002 & 820212 commitments
BROOK, D J Portland General Electric Co 83/01/25 CLARK, R A
Operating Reactors Branch 3 6pp 16973 271 24X
Fiche 50-344, 83/01/25, 8302010386

8302030108 Forwards License Change Application 50, Rev 1, requesting amend to License NPF-1 Change should become effective 2 months after receipt of NRC approval to allow time to revise offsite dose calculation manual Certificate of Svc encl
WITHERS, B D Portland General Electric Co 83/01/28 CLARK, R A
Operating Reactors Branch 3 1p 17002 138 24X
Fiche 50-344, 83/01/28, 8302030108

--8302030116 Rev 1 to License Change Application 50, requesting amend to License NPF-1 re offsite dose calculation manual
WITHERS, B D Portland General Electric Co 83/01/28 7pp
17002 140 24X Fiche 50-344, 83/01/28, 8302030116

--8302030121 Proposed Tech Spec changes re offsite dose calculation manual
* Portland General Electric Co 83/01/28 78pp 17002 147 24X
Fiche 50-344, 83/01/28, 8302030121

8302080163 Advises that milk samples no longer being taken from Skiloh Basin, Sampling Location 7, due to closing of dairy
WITHERS, B D Portland General Electric Co 83/02/03 CLARK, R A
Operating Reactors Branch 3 1p 17057 235 24X
Fiche 50-344, 83/02/03, 8302080163

8302240129 Supplis 821110 ltr transmitting Amend 77 to License NPF-1 Current design arrangements for containment ventilation isolation, EEF reset push buttons & annunciation of override of ESF sys not acceptable
CLARK, R A Operating Reactors Branch 3 83/02/03 WITHERS, B D
Portland General Electric Co 3pp 17288 201, 24X
Fiche 50-344, 83/02/03, 8302240129

--8302240134 Safety evaluation supporting mods to override of containment purge isolation
* Office of Nuclear Reactor Regulation, Director 83/02/03 2pp
17288 204 24X Fiche 50-344, 83/02/03, 8302240129

--8302080265 "Override & Reset of Control Circuitry in Ventilation/Purge Isolation / Other ESF Sys (B-24)," technical evaluation rept
SAROENT, I H Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-183 82/08/04 CALVO, J NRC - No
Detailed Affiliation Given 33pp 17288 206 24X
Fiche 50-344, 83/02/03, 8302240129

8302150713 Informs of intent to change test intervals for DPA & shutdown sequencers, as IE-qualified Agastat time delay relays installed Return to 18-month surveillance test frequency justified
WITHERS, B D Portland General Electric Co 83/02/04 CLARK, R A
Operating Reactors Branch 3 2pp 17191 359 24X
Fiche 50-344, 83/02/04, 8302150713

8302080275 Generic Ltr 83-09 to all operating reactor licensees, applicants for CL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247, 24X
Fiche 50-000, 83/02/08, 8302080275

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302180339 Forwards comments on value impact analysis contained in Generic Ltr 82-32 re proposed steam generator-related generic requirements Plant safety unaffected by proposed requirements, which should not be regulatory requirements
WITHERS, B D Portland General Electric Co 83/02/09 EISENHUT, D O
Division of Licensing 4pp 17213 258 24X Fiche 50-344, 83/02/09, 8302180339

8302230490 Forwards License Change Application 89 for amend to License NPF-1, changing radiological emergency plan & security plan at least once per 12 months
WITHERS, B D Portland General Electric Co 83/02/16 CLARK, R A
Operating Reactors Branch 3 1p 17246 191 24X
Fiche 50-344, 83/02/16, 8302230490

--8302230500 License Change Application 89 for amend to License NPF-1, changing Tech Specs to require audits of activities re radiological emergency plan & security plan at least once per 12 months
* Portland General Electric Co 83/02/16 4pp 17246 192 24X
Fiche 50-344, 83/02/16, 8302230490

--8302230506 Proposed Tech Specs requiring audits of activities re radiological emergency plan & security plan at least once per 12 months
* Portland General Electric Co 83/02/16 4pp 17246 193, 24X
Fiche 50-344, 83/02/16, 8302230490

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302230237 Forwards IE Insp Rept 50-344/82-36 on 821206-830107, No noncompliance noted
STERNBERG, D M Division of Resident Reactor Project & Engineering
Programs 83/01/27 WITHERS, B D Portland General Electric Co.
2pp 17245 021 24X Fiche 50-344, 83/01/27, 8302230237

--8302230240 IE Insp Rept 50-344/82-36 on 821206-830107 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, security, procurement, corrective actions & followup on IELRs & previous insp findings
MALIKROB, M H DODDS, R T Division of Resident Reactor Project & Engineering Programs 83/01/27 6pp 17245 023 24X
Fiche 50-344, 83/01/27, 8302230237

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H22C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230323 Forwards IE Insp Rept 50-344/83-01 on 830110-14, No noncompliance noted
BOOK, H C Division of Radiological Safety & Safeguards Program
83/02/01 WITHERS, B D Portland General Electric Co 2pp
17248 138 24X Fiche 50-344, 83/02/01, 8302230323

--8302230324 IE Insp Rept 50-344/83-01 on 830110-14 No noncompliance noted Major areas inspected radwaste sys, gaseous monitoring sys, including calibr, radioactive gaseous effluent releases, records & repts & review of RODs
GILLIS, M WENSLAWSKI, F A, BOOK, H E Division of Radiological Safety & Safeguards Program 83/02/01 11pp 17248, 140 24X
Fiche 50-344, 83/02/01, 8302230323

8302230315 Discusses protective measures taken to assure that safety-related process, instrument & sampling lines do not freeze during cold weather, in response to IE Bulletin 79-24 Permanent encl not necessary, due to adequate heat tracing.
WITHERS, B D Portland General Electric Co 83/02/11 ENOELKEN, R H
Region 5, Office of Director, 2pp 17248 312 24X
Fiche 50-344, 83/02/11, 8302230315

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

DOCKETED ITEMS

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

S Reportable occurrences, LERs & related correspondence

B302010398 Forwards LER 83-001/01T-0 Detailed event analysis encl
BROEHL, D J Portland General Electric Co 83/01/20 ENGELKEN, R H
Region 5, Office of Director 4pp 16973 162 24X
Fiche 50-344, 83/01/20, B302010398

--B302010403 LER 83-001/01T-0 on B30104, field insps & review of const records revealed as-built conditions of knock-out panel & wall-to-roof connection different than those considered in previous analyses for three masonry walls Mods underway
MODEEN, D J Portland General Electric Co 83/01/20 Region 5, Office of Director 10pp 16973-166 24X Fiche 50-344, 83/01/20, B302010398

B302010418 RD on B30108, 5 OB C1 noble gas released from auxiliary bldg Caused by south boric acid storage tank overflow loop seal liquid blowing out due to pressure buildup during pumping of boric acid evaporator concentrates
YURDT, C P Portland General Electric Co 83/01/21 ENGELKEN, R H
Region 5, Office of Director 1p 16974.257 24X
Fiche 50-344, 83/01/21, B302010418

B302010561 Forwards LER 82-022/03L-0 Detailed event analysis encl
YURDT, C P Portland General Electric Co 83/01/21 ENGELKEN, R H
Region 5, Office of Director 3pp 16977 097 24X
Fiche 50-344, 83/01/21, B302010561

--B302010569 LER 82-022/03L-0 on B21224, containment radioactive monitoring sys (PRM-1) inadvertently isolated for 30 h. Caused by chemistry technician error Sys restored & technician counseled
BAIR, G O Portland General Electric Co 83/01/21 Region 5, Office of Director 2pp 16977 100 24X Fiche 50-344, 83/01/21, B302010561

B302040274 Forwards rept re B30124 loss of power for security sys Rept withheld (ref 10CFR27.37(c))
WITHERS, B D Portland General Electric Co 83/01/28 ENGELKEN, R H
Region 5, Office of Director 1p 17020 034 24X
Fiche 50-344, 83/01/28, B302040274

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, B301310203

B302080172 Submits util prediction of need for site visits for operator licensing exams through 1985
WITHERS, B D Portland General Electric Co 83/02/03 EISENHUT, D G
Division of Licensing 2pp 17058 344 24X Fiche 50-344, 83/02/03, B302080172

DOCKET: 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B302080375 Releases public version of revised administrative procedure
FELTON, J M Division of Rules and Records 83/01/02 Document Management Branch 1p 17107, 104 24X Fiche 50-346, 83/01/02, B302080375

--B302080378 Forwards public version of Rev 4 to Administrative Procedure AD 1827.11, "Assembly, Accountability & Subsequent Evacuation" Revised index & receipt form encl
* Toledo Edison Co 83/01/25 Office of Nuclear Reactor Regulation, Director 2pp 17107, 105 24X Fiche 50-346, 83/01/02, B302080375

--B302080380 Public version of Rev 4 to Administrative Procedure AD 1827.11, "Assembly, Accountability & Subsequent Evacuation"
WATHER, R P, GREEN, W H, BRIDEN, D W Toledo Edison Co 83/01/19 14pp 17107 107 24X Fiche 50-346, 83/01/02, B302080375

B302040272 Forwards Rev 19 to industrial security plan Rev withheld (ref 10CFR73.21)
CROUSE, R P Toledo Edison Co 83/01/26 Office of Nuclear Reactor Regulation, Director 1p 17020 059 24X
Fiche 50-346, 83/01/26, B302040272

B302030207 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/01/28 Document Management Branch 1p 17013 296 24X Fiche 50-346, 83/01/28, B302030207

--B302030212 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure CI 1300 OB, "Emergency Control Ctr Activation"
* Toledo Edison Co 83/01/07 NRC - No Detailed Affiliation Given 4pp 17013 297 24X Fiche 50-346, 83/01/28, B302030207

--B302030214 Public version of Rev 5 to Emergency Plan Implementing Procedure EI 1300 OB, "Emergency Control Ctr Activation"
REED, G J, HELLS, C E, MURRAY, T D Toledo Edison Co 83/12/27 19pp 17013 301 24X Fiche 50-346, 83/01/28, B302030207

B301210340 Generic Ltr B3-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340

B302070630 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/02/01 Document Management Branch 1p 17062 245 24X Fiche 50-346, 83/02/01, B302070630

--B302070631 Forwards public version of Rev 6 to emergency plan Receipt form encl
* Toledo Edison Co 83/01/21 Office of Nuclear Reactor Regulation, Director 2pp 17062 246 24X Fiche 50-346, 83/02/01, B302070630

--B302070633 Public version of Rev 6 to emergency plan
MURRAY, T D Toledo Edison Co 83/01/11 84pp 17062 248 24X
Fiche 50-346, 83/02/01, B302070630

B302180064 Releases public version of revised health physics procedure
FELTON, J M Division of Rules and Records 83/02/14 Document Management Branch 1p 17227 025 24X Fiche 50-346, 83/02/14, B302180064

--B302180069 Forwards public version of Rev 4 to Health Physics Procedure HP 1604 01, "Personnel Decontamination" Receipt form & revised index encl
* Toledo Edison Co 83/02/01 NRC - No Detailed Affiliation Given 3pp 17227 026 24X Fiche 50-346, 83/02/14, B302180064

--B302180073 Public version of Rev 4 to Health Physics Procedure HP 1604 01, "Personnel Decontamination"
GEDDES, B L, BRIDEN, D W Toledo Edison Co 83/01/24 10pp 17227 029 24X Fiche 50-346, 83/02/14, B302180064

P Operating license stage documents & correspondence

B302090187 Forwards request for addl info re proposed change to Tech Spec 3.2.5 re flow/thermal power setpoint Response must be provided within 60 days of ltr date
STOLZ, J F Operating Reactors Branch 4 83/01/26 CROUSE, R P
Toledo Edison Co 3pp 17132 091 24X Fiche 50-346, 83/01/26, B302090187

B302030288 Forwards corrected B30111 ltr re proposed App B Tech Specs. First paragraph contained incorrect date
CROUSE, R P Toledo Edison Co 83/01/28 STOLZ, J F Operating Reactors Branch 4 1p 17005 208 24X Fiche 50-346, 83/01/28, B302030288

--B302030375 Corrected ltr responding to NRC B21221 ltr re proposed App B Tech Specs
CROUSE, R P Toledo Edison Co 83/01/11 STOLZ, J F Operating Reactors Branch 4 1p 17005 207 24X Fiche 50-346, 83/01/28, B302030388

DOCKETED ITEMS

226

8302070569 Forwards response to 821227 ltr re post-implementation review of NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6
CROUSE, R P Toledo Edison Co 83/01/28 STOLZ, J F Operating
Reactors Branch 4 11pp 17034 159 24X Fiche 50-346, 83/01/28,
8302070569

8302030176 Informs that requirement for operator administered checkoffs replaced w/requirement for shift technical advisor (STA) administered checkoffs Focus on STA administered checkoffs appropriate for STA in training
CROUSE, R P Toledo Edison Co 83/01/31 STOLZ, J F Operating
Reactors Branch 4 1p 17002 033 24X Fiche 50-346, 83/01/31,
8302030176

8302040063 Notifies that revised guidelines listed in 820615 Generic Ltr 82-12 incorporated into shift manning & overtime procedures per A DeAgazio request
CROUSE, R P Toledo Edison Co 83/01/31 EISENHUT, D O Division of
Licensing 1p 17023 325 24X Fiche 50-346, 83/01/31, 8302040063.

8302070250 Submits partial response to NRC 820923 ltr re control of heavy loads Response includes Items 2 1 3 re load handling procedures & 2 1 5 re special lifting procedures Remaining open items will be answered by 830401
CROUSE, R P Toledo Edison Co 83/01/31 STOLZ, J F Operating
Reactors Branch 4 2pp 17031 330 24X Fiche 50-346, 83/01/31,
8302070250

8302080207 Advises that installation of turbine bldg sump effluent line monitor should be completed by 831231 Radiological effluent Tech Specs submitted on 821223
CROUSE, R P Toledo Edison Co 83/01/31 STOLZ, J F Operating
Reactors Branch 4 1p 17058 036 24X Fiche 50-346, 83/01/31,
8302080207

8302100257 Forwards confirmatory study on applicability of pressurized thermal shock screening criteria to B&W plants, for use as starting point for addl detailed technical discussions between NRC & B&W Owners Group representatives
LATINAS, O C Assistant Director for Operating Reactors 83/01/31
WALLACE, E Babcock & Wilcox Operating Plants Owners Group 6pp
17134 100 24X Fiche 50-000, 83/01/31, 8302100257

8302080198 Forwards Rev 0 to "Davis-Besse Analysis & Evaluation of Safety/Relief Valve Discharge Sys per NRC NUREG-0737," technical rept. in response to Items II D 1 2 & II D 1 3
CROUSE, R P Toledo Edison Co 83/02/01 STOLZ, J F Operating
Reactors Branch 4 4pp 17051 001 24X Fiche 50-346, 83/02/01,
8302080198

--8302080206 Rev 0 to "Davis-Besse Analysis & Evaluation of Safety/Relief Valve Discharge Sys per NRC NUREG-0737," technical rept w/two oversize drawings Aperture cards are available in PDR
* Teledyne Engineering Services TR-5639-2 R00 83/01/31
176pp 17051 005 24X Fiche 50-346, 83/02/01, 8302080198.

8302080473 Forwards model Tech Specs for proposed amend to App A Tech Specs re DHR capability redundancy Mod requested to assure redundancy in Mode 3 Response requested within 45 days
w/o encl
STOLZ, J F Operating Reactors Branch 4 83/02/01 CROUSE, R P
Toledo Edison Co 2pp 17071 323 24X Fiche 50-346, 83/02/01,
8302080473

8302070369 Forwards response to 821227 request for info re plant computer sys & non-nuclear instrumentation-X power failure.
CROUSE, R P Toledo Edison Co 83/02/02 STOLZ, J F Operating
Reactors Branch 4 10pp 17030 020 24X Fiche 50-346, 83/02/02,
8302070369

8302070478 Forwards addl info on modified 821214 Code Relief Request 1 revising inservice testing program Basis for request listed.
Request per ASNE Section XI IHW re MSIVs MS-100 & MS-101
CROUSE, R P Toledo Edison Co 83/02/02 STOLZ, J F Operating
Reactors Branch 4, 3pp 17036 057 24X Fiche 50-346, 83/02/02,
8302070478

8302080223 Discusses steam generator tube failures at facility, in response to 821026 ltr Eighty-day outage in 1982 due to failure of auxiliary feedwater header inside generator No major maint anticipated in next 5 yrs
CROUSE, R P Toledo Edison Co 83/02/03 EISENHUT, D O Division of
Licensing 2pp 17057 266 24X Fiche 50-346, 83/02/03, 8302080223

8302080228 Submits update to status of NUREG-0737, Item II F 1 5, "Containment Water Level" Testing for environ & seismic qualification documentation complete Repts will be reviewed & submitted by 830615
CROUSE, R P Toledo Edison Co. 83/02/03 STOLZ, J F Operating
Reactors Branch 4 1p 17057 209 24X Fiche 50-346, 83/02/03,
8302080228

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302090098 Generic Ltr 83-10F to all licensees w/B&W designed NSSB (except TMI) re resolution of TMI Action Item II.K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Duke Power Co
23pp 17298 291 24X Fiche 50-000, 83/02/08, 8302090098

8302160172 Forwards addl info re training for mitigating core damage. Station superintendent receives adequate experience in regular duties which abrogates need for formal training for mitigating core damage
CROUSE, R P Toledo Edison Co 83/02/08 STOLZ, J F Operating
Reactors Branch 4 2pp 17162 177 24X Fiche 50-346, 83/02/08,
8302160172

8302170410 Notification of 830216 meeting w/util in Bethesda, MD to discuss util approach to integrated 5-yr schedule
DE AGAZIO, A Operating Reactors Branch 4 83/02/10 STOLZ, J
Operating Reactors Branch 4, 2pp 17195 243 24X
Fiche 50-346, 83/02/10, 8302170410

8302230290 Informs that scheduled 830301 submittal of proposed ECCB calculations using NUREG-0630 cladding models will be delayed until 830408 Delay due to anticipated late receipt of analysis from sponsoring utils
CROUSE, R P Toledo Edison Co 83/02/17 STOLZ, J F Operating
Reactors Branch 4 1p 17244 323 24X Fiche 50-346, 83/02/17,
8302230290

8302230102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level.
VAN VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302230102

8302280336 Forwards proposed Tech Spec changes re anticipatory reactor trip sys, boration sys temp & corrections to typographical errors in administration section
CROUSE, R P Toledo Edison Co 83/02/22 STOLZ, J F Operating
Reactors Branch 4 1p 17313 093 24X Fiche 50-346, 83/02/22,
8302280336

--8302280337 Proposed revs to Tech Spec re anticipatory reactor trip sys, boration sys temp & corrections to typographical errors in administrative section
* Toledo Edison Co 83/02/22 19pp 17313 094 24X
Fiche 50-346, 83/02/22, 8302280336

Q. Inspection reports, IE Bulletins & correspondence

8301180134 Forwards owner data repts for eddy current steam generator exam & weld supports, bolting & component inservice insp program exams conducted during 1982 refueling outage.
CROUSE, R P Toledo Edison Co 82/12/29 KEPPLER, J O Region 3,
Office of Director 5pp 16832 052 24X Fiche 50-346, 82/12/29,
8301180134

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency.
Forwards App A documents, Document 31 available in PDR.
FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L.
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039.

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director. 82/07/08.
KEPPLER, J O Region 3, Office of Director. 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040332

DOCKETED ITEMS

8302160014 Summary of 830120 meeting w/utills, Bechtel, Franklin Research Ctr,URS & Computech Engineering Svcs re IE Bulletin 80-11, "Masonry Wall Design " Addl testing not warranted
TRAMMELL, C M Operating Reactors Branch 3 83/01/25 Operating Reactors Branch 3 25pp 17171 227 24X Fiche 50-000,83/01/25, 8302160014

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000,83/01/26,8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESBARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17098 187 24X Fiche 50-000,83/01/28,8302030303

8302280494 Forwards IE Insp Rept 50-346/82-34 on 821201-30 & notice of violation
NORELIUS, C E Division of Project & Resident Programs 83/02/10 CROUSE, R P Toledo Edison Co 2pp 17309 117 24X Fiche 50-346,83/02/10,8302280494

--8302280498 Notice of violation from insp on 821201-30
NORELIUS, C E Division of Project & Resident Programs 83/02/10 1p 17309 119 24X Fiche 50-346,83/02/10,8302280494

--8302280503 IE Insp Rept 50-346/82-34 on 821201-30 Noncompliance noted failure to perform surveillance of axial power imbalance within Tech Spec limits
PEEBLES, T A , ROGERS, W O , REYES, L A Division of Project & Resident Programs 83/02/04 3pp 17309 120 24X Fiche 50-346,83/02/10,8302280494

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

8302280392 Act receipt of 821210 & 830131 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/82-21
SPESBARD, R L Division of Engineering 83/02/24 CROUSE, R P Toledo Edison Co 1p 17309 333 24X Fiche 50-346,83/02/24, 8302280392

--8302280396 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-346/82-21 Corrective actions: cable traceability procedures upgraded
CROUSE, R P Toledo Edison Co 83/01/31 NORELIUS, C E Division of Engineering 3pp 17309 334 24X Fiche 50-346,83/02/24, 8302280392

--8302280405 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-346/82-21 Corrective actions non-Class IE hanger walked down & verified & personnel training reviewed
CROUSE, R P Toledo Edison Co 82/12/10 NORELIUS, C E Division of Engineering 8pp 17309:337 24X Fiche 50-346,83/02/24, 8302280392

--8302280408 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-346/82-21 Due to multitude of organizations involved in preparation, response will be submitted by 821210
CROUSE, R P Toledo Edison Co 82/12/03 KEPLER, J G Region 3, Office of Director 1p 17309 345 24X Fiche 50-346,83/02/24, 8302280392

B Reportable occurrences, LERs & related correspondence

8302080136 Forwards revised LER 82-064/03X-1
MURRAY, T D Toledo Edison Co 83/01/27 KEPLER, J G Region 3, Office of Director 1p 17058 160 24X Fiche 50-346,83/01/27, 8302080136

--8302080142 Revised LER 82-064/03X-1 on 821129, while performing BT 9074 OI on component cooling water (CCW) train 1, CC1467 decay heat cooler CCM outlat valve would not open Caused by mfg error Flanged bearing installed
BLEY, T Toledo Edison Co 83/01/27 Region 3, Office of Director 2pp 17058 161 24X Fiche 50-346,83/01/27, 8302080136

8302100090 Discusses 801205 inadvertent safety feature actuation sys (SFAS) actuation Investigation of event revealed that hardwired electrical interconnections exist between circuitry w/SFAS instrument & logic channels
STOLZ, J F Operating Reactors Branch 4 83/01/31 CROUSE, R P Toledo Edison Co 3pp 17135 067 24X Fiche 50-346,83/01/31, 8302100090

--8302100096 Safety evaluation re electrical connections between redundant safety features actuation sys instrument channels Actions to be taken by util identified
* Office of Nuclear Reactor Regulation, Director 83/01/13 13pp 17135 070 24X Fiche 50-346,83/01/31,8302100090

8302150390 Forwards updated LER 82-065/03X-1
MURRAY, T D Toledo Edison Co 83/02/01 KEPLER, J G Region 3, Office of Director 1p 17157 240 24X Fiche 50-346,83/02/01, 8302150390

--8302150395 Updated LER 82-065/03X-1 on 821201, control room ventilation sys chlorine detector AE53588 taken out of svc w/o placing control room in recirculation mode Caused by personnel error Memo sent to responsible personnel
MURRAY, T D Toledo Edison Co 83/02/01 Region 3, Office of Director 3pp 17157 241 24X Fiche 50-346,83/02/01,8302150390

8302230510 Forwards LER 83-001/03L-0
MURRAY, T D Toledo Edison Co 83/02/11 KEPLER, J G Region 3, Office of Director 1p 17257 286 24X Fiche 50-346,83/02/11, 8302230510

--8302230515 LER 83-001/03L-0 on 830114, loss of power to loop 2 main feedwater block valve initiated feedwater transient Caused by control rod insertion from approx 75% to 79% Rods withdrawn
BERGER, C L Toledo Edison Co 83/02/11 Region 3, Office of Director 2pp 17257 287 24X Fiche 50-346,83/02/11,8302230510

8302230539 Forwards LER 83-002/03L-0
MURRAY, T D Toledo Edison Co 83/02/14 KEPLER, J G Region 3, Office of Director 1p 17256 344 24X Fiche 50-346,83/02/14, 8302230539

--8302230548 LER 83-002/03L-0 on 830114 & 15, after reactor trips, RCB dose equivalent 1-131 exceeded Tech Spec limit Caused by slight leakage of fission products through fuel cladding Caused by temp & pressure changes Situation monitored
RICHTER, L Toledo Edison Co 83/02/14, Region 3, Office of Director 6pp, 17256 345, 24X Fiche 50-346,83/02/14,8302230539,

8302280419 Forwards LER 83-003/03L-0
MURRAY, T D Toledo Edison Co 83/02/16 KEPLER, J G Region 3, Office of Director 1p 17309 134 24X Fiche 50-346,83/02/16, 8302280419

--8302280427 LER 83-003/03L-0 on 830119, MSIV MS100 failed to shut completely following reactor trip on 830118 Cause unknown Valves disassembled & inspected w/no problems found Valve tested & returned to svc
O'NEILL, J Toledo Edison Co 83/02/16 Region 3, Office of Director 3pp 17309 135 24X Fiche 50-346,83/02/16,8302280419

8302280433 Forwards LER 83-004/03L-0
MURRAY, T D Toledo Edison Co 83/02/17 KEPLER, J G Region 3, Office of Director 1p 17309 202 24X Fiche 50-346,83/02/17, 8302280433

--B302280437 LER 83-004/03L-0 on 830119, during cooldown, jumper on pressure switch PSH-RC2B4 had been left in place since B20823 Caused by lack of administrative control & design error Procedure rewritten to provide adequate switch
O'CONNOR, W Toledo Edison Co 83/02/17 Region 3, Office of Director 3pp 17309 703 24X Fiche 50-348, 83/02/17, B302280433

V. Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for QLS, NRS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co or New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B301310203

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B302010016 Releases public version of on-call schedule for 1983
FELTON, J M Division of Rules and Records 83/01/26 Document Management Branch 1p 16995 003 24X Fiche 50-348, 83/01/26, B302010016

--B302010021 Forwards public version of on-call schedule for 1983, per Administrative Procedure FRP-D-AP-4, "Control of Plant & Document Records"
HUDESPETH, J B Alabama Power Co 82/12/30 Office of Nuclear Reactor Regulation, Director 5pp 16995 004 24X Fiche 50-348, 83/01/26, B302010016

B302010026 Releases public version of on-call schedule for 1983
FELTON, J M Division of Rules and Records 83/01/26 Document Management Branch 1p 16995 095 24X Fiche 50-348, 83/01/26, B302010026

--B302010027 Forwards public version of on-call schedule for 1983, per Administrative Procedure FRP-D-AP-4, "Control of Plant Documents & Records"
HUDESPETH, J B Alabama Power Co 83/01/05 Office of Nuclear Reactor Regulation, Director 5pp 16995 096 24X Fiche 50-348, 83/01/26, B302010026

B302030059 Releases public version of rev to site emergency plan, radiation emergency medical plan & State of AL radiological emergency response plan
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17024 001 24X Fiche 50-348, 83/01/27, B302030059

--B302030063 Forwards public version of rev to site emergency plan, radiation emergency medical plan & State of AL radiological emergency response plan
HUDESPETH, J B Alabama Power Co 82/12/15 Office of Nuclear Reactor Regulation, Director 1p 17024 002 24X Fiche 50-348, 83/01/27, B302030059

--B302030068 Public version of rev to site emergency plan, radiation emergency medical plan & State of AL radiological emergency response plan
MCDONALD, R P, HAIRSTON, W O Alabama Power Co 82/12/06 B26pp 17024 003 24X Fiche 50-348, 83/01/27, B302030059

B302080012 Forwards summary of addl requests for relief from certain inservice insp requirements of ASME Code, Section XI, Articles IWA-5000, IWB-5000, IWC-5000, IWD-5000, IWE-2000 & IWF-2000
Relief requested by B30901
CLAYTON, F L Alabama Power Co 83/01/28 VARQA, S A Office of Nuclear Reactor Regulation, Director 30pp 17058 263 24X Fiche 50-364, 83/01/28, B302080012

--B302080017 Responds to SALP Repts 50-348/82-28 & 50-364/82-28 re lack of physical exams for fire brigade members & substandard welding & cutting fire prevention procedures. Present use of flame permits & exams adequate
CLAYTON, F L Alabama Power Co 83/02/02 O'REILLY, J P Region 2, Office of Director 6pp 17058 293 24X Fiche 50-364, 83/01/28, B302080012

B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for QL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, B301210340

B302090462 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/03 Document Management Branch 1p 17132 107 24X Fiche 50-348, 83/02/03, B302090462

--B302090467 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure GO-EIP-117, "Emergency Operations Facility Administrative Support"
CLAYTON, F L Alabama Power Co 83/01/24 VARQA, S A Assistant Director for Operating Reactors 1p 17132 108 24X Fiche 50-348, 83/02/03, B302090462

--B302090471 Public version of Rev 1 to Emergency Plan Implementing Procedure GO-EIP-117, "Emergency Operations Facility Administrative Support"
MCDONALD, J W Alabama Power Co 83/01/25 42pp 17132 109, 24X Fiche 50-348, 83/02/03, B302090462

M Antitrust correspondence

B302170265 Forwards AL Electric Cooperative response to AL Power Co motion for stay of mandate Certificate of Svc encl Related correspondence
MACQUINEAS, D B Volpe, Boskey & Lyons MACQUINEAS, D B Alabama Electric Cooperative, Inc 83/02/14 ZOLLER, N E Unknown Affiliation 4pp 17178 224 24X Fiche 50-348, 83/02/14, B302170265

P Operating license stage documents & correspondence

B302100103 Forwards Amend 28 to License NPF-2, safety evaluation & notice of issuance & availability Amend modifies effective date for mechanical snubber functional test from fourth to fifth refueling outage
REYES, E A Operating Reactors Branch 1 83/01/31 CLAYTON, F L Alabama Power Co 2pp 17135 006 24X Fiche 50-348, 83/01/31, B302100103

--B302100108 Amend 28 to License NPF-2, modifying effective date for mechanical snubber functional test from fourth to fifth refueling outage
VARQA, S A Operating Reactors Branch 1 83/01/31 4pp 17135 008 24X Fiche 50-348, 83/01/31, B302100103

--B302100112 Safety evaluation supporting Amend 28 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 83/01/31 2pp 17135 012 24X Fiche 50-348, 83/01/31, B302100103

--B302100115 Notice of issuance & availability of Amend 28 to License NPF-2
VARQA, S A Operating Reactors Branch 1 83/01/31 2pp 17135 014 24X Fiche 50-348, 83/01/31, B302100103

B302030344 Advises that util will submit results of review of available reactor vessel level sys (TMI Action Item IIF 2) per Generic Ltr 82-28 schedule
CLAYTON, F L Alabama Power Co 83/02/01 VARQA, S A Office of Nuclear Reactor Regulation, Director 1p 17005 359, 24X Fiche 50-348, 83/02/01, B302030344

B302090329 Forwards list of all licensing items requiring NRC approval in 1983 Status will be updated monthly to reflect addl submittals requiring NRC approval
CLAYTON, F L Alabama Power Co 83/02/01 VARQA, S A Office of Nuclear Reactor Regulation, Director 6pp, 17070 356 24X Fiche 50-348, 83/02/01, B302090329

B302100245 Supplemental request for administrative Tech Spec changes to Licenses NPF-2 & NPF-B Changes will allow for better scheduling of certain surveillance testing
CLAYTON, F L Alabama Power Co 83/02/01 VARQA, S A Office of Nuclear Reactor Regulation, Director 9pp 17114 065 24X Fiche 50-348, 83/02/01, B302100245

--B302100248 Proposed administrative Tech Spec changes which will allow for better scheduling of certain surveillance testing.
* Alabama Power Co 83/02/01 29pp, 17114 074 24X Fiche 50-348, 83/02/01, B302100245

B302140192 Forwards SER for environ qualification of safety-related electrical equipment Plans for qualification or replacement of unqualified equipment & schedule for corrective actions should be submitted within 90 days
VARQA, S A Operating Reactors Branch 1 83/02/04 CLAYTON, F L Alabama Power Co 3pp 17144 170 24X Fiche 50-348, 83/02/04, B302140192

--B302140200 SER re environ qualification of safety-related electrical equipment Actions required by util listed
* Equipment Qualification Branch 83/02/04 5pp, 17144 173, 24X Fiche 50-348, 83/02/04, B302140192

DOCKETED ITEMS

--8301210006 Nonproprietary "Review of Licensees Resolution of Outstanding Issues From NRC Equipment Environ Qualification SER (F-11 & B-60), JM Farley Nuclear Power Plant, Unit 1," technical evaluation rept
TOMAN, O J Franklin Institute/Franklin Research Center
NRC-03-79-118 YER-C5257-509 83/01/14 SHEMANSKI, P NRC - No
Detailed Affiliation Given 500pp 17144 178 24X
Fiche 50-348, 83/02/04, 8302140192

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche: 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-100 to all licensees w/Westinghouse designed NSSB (except Yankee Atomic Electric Co) re resolution of TMI Action Item II K 3 3, "Automatic Trip of Reactor Coolant Pumps," Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Southern
California Edison Co 31pp 17290 262 24X Fiche 50-000, 83/02/08, 8302090085

8302180247 Responds to 830103 request for addl info re boron concentration reduction in boron injection tank per util 821230 ltr Existing emergency operating procedure for small break LOCA not impacted by proposed change in concentration
CLAYTON, F L Alabama Power Co 83/02/11 VARGA, S A Division of
Licensing 3pp 17211 235 24X Fiche 50-348, 83/02/11, 8302180247

8302230387 Informs that portions of Franklin Research Ctr technical evaluation rept re environ qualification of safety-related equipment are proprietary
CLAYTON, F L Alabama Power Co 83/02/16 VARGA, S A Office of
Nuclear Reactor Regulation, Director 1p 17248 154 24X
Fiche 50-348, 83/02/16, 8302230387

Q Inspection reports, IE Bulletins & correspondence

7212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche: 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc. 109pp 17144 001 24X Fiche: 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc. 110pp 17074 095 24X Fiche: 50-000, 83/01/28, 8212060361

8302010539 Forwards requests for relief from Rev 1 of Inservice Insp Program for ASME Code Class 1, 2 & 3 components Granting of proposed relief requests by 830901 requested.
CLAYTON, F L Alabama Power Co 83/01/28 VARGA, S A Office of
Nuclear Reactor Regulation, Director 29pp, 16977-134, 24X
Fiche 50-348, 83/01/28, 8302010539

8302080012 Forwards summary of addl requests for relief from certain inservice insp requirements of ASME Code, Section XI, Articles IWA-5000, IWB-5000, IWC-5000, IWD-5000, IWE-5000 & IWF-5000
Relief requested by 830901
CLAYTON, F L Alabama Power Co 83/01/28 VARGA, S A Office of
Nuclear Reactor Regulation, Director 30pp 17058 263, 24X
Fiche: 50-344, 83/01/28, 8302080012

--8302080017 Responds to SALP Repts 50-348/82-28 & 50-364/82-28 re lack of physical exams for fire brigade members & standard welding & cutting fire prevention procedures Present use of flame permits & exams adequate
CLAYTON, F L Alabama Power Co, 83/02/02 O'REILLY, J P, Region
2, Office of Director 6pp 17058 293 24X Fiche: 50-364,
83/01/28, 8302080017

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302220127 Forwards monthly operating rept for Jan 1983
CLAYTON, F L Alabama Power Co 83/02/14 Division of Data
Automation & Management Information 1p 17233 144 24X
Fiche 50-348, 83/02/14, 8302220127

--8302220131 Monthly operating rept for Jan 1983
HAIRSTON, W O Alabama Power Co 83/02/02 4pp 17233 145 24X
Fiche 50-348, 83/02/14, 8302220127

S Reportable occurrences, LCRs & related correspondence

8302010099 Forwards LER 82-061/03L-0
CLAYTON, F L Alabama Power Co 83/01/20 Region 2, Office of
Director 1p 16974 083 24X Fiche 50-348, 83/01/20, 8302010099

--8302010103 LER 82-061/03L-0 on 821221, diesel generator 1B declared inoperable when generator failed to start during performance of diesel generator operability test Caused by fouling of air-start valves by lint-like substance Valves cleaned
HAIRSTON, W O Alabama Power Co 83/01/19 Region 2, Office of
Director 1p 16974 004 24X Fiche 50-348, 83/01/20, 8302010099

8302070613 Forwards LERs 82-062/03L-0, 82-063/03L-0 & 83-001/03L-0
CLAYTON, F L Alabama Power Co 83/01/28 Region 2, Office of
Director 1p 17035 064 24X Fiche 50-348, 83/01/28, 8302070613

--8302070614 LER 82-062/03L-0 on 821231, noble gas activity monitor R15 declared inoperable Caused by blown fuse Fuse replaced & monitor returned to svc
HAIRSTON, W O Alabama Power Co 83/01/28 Region 2, Office of
Director 1p 17035 065 24X Fiche 50-348, 83/01/28, 8302070613

--8302070617 LER 82-063/03L-0 on 821230, B train chlorine detector declared inoperable when control room supply damper would not close Caused by faulty solenoid valve Valve replaced
HAIRSTON, W O Alabama Power Co 83/01/28 Region 2, Office of
Director 1p 17035 066 24X Fiche 50-348, 83/01/28, 8302070613

--8302070620 LER 83-001/03L-0 on 830102, RCB subcooling monitor channel 2 declared inoperable following receipt of main control board alarms Caused by faulty printed circuit card Connector pins on card cleaned
HAIRSTON, W O Alabama Power Co 83/01/28 Region 2, Office of
Director 1p 17035 067 24X Fiche 50-348, 83/01/28, 8302070613

8302220174 Forwards LER 83-005/01T-0
CLAYTON, F L Alabama Power Co 83/02/11 Region 2, Office of
Director 1p 17233 191 24X Fiche 50-348, 83/02/11, 8302220174

--8302220199 LER 83-005/01T-0 on 830130, fuel cladding damage found on 11 Cycle 4 baffle fuel assemblies located at corner injection baffle joints Caused by vibrations induced by water jetting through baffle joints Design mod implemented
HAIRSTON, W O Alabama Power Co 83/02/11 Region 2, Office of
Director 2pp 17233 192 24X Fiche 50-348, 83/02/11, 8302220174

8302220363 Forwards LERs 83-003/03L-0 & 83-004/03L-0
CLAYTON, F L Alabama Power Co 83/02/11 Region 2, Office of
Director 1p 17233 004 24X Fiche 50-348, 83/02/11, 8302220363

--8302220367 LER 83-003/03L-0 on 830114, during calibr & functional test, B train chlorine detector declared inoperable due to failure of tape advance mechanism Caused by paper drive motor gear failure Paper drive replaced
HAIRSTON, W O Alabama Power Co 83/02/11, Region 2, Office of
Director 1p 17233 005 24X Fiche 50-348, 83/02/11, 8302220363

DOCKETED ITEMS

22

--830220372 LER 83-004/03L-0 on 830114, main steam safety valves
QIN11V010A, QIN11V010C, QIN11V011C & QIN11V012B declared
inoperable due to relief setpoint being out of tolerance
Caused by setpoint drift Valves readjusted
HAIRSTON, W O Alabama Power Co 83/02/11 Region 2, Office of
Director 1p 17233 006 24X Fiche 50-348, 83/02/11, 830220363

8302280211 RO on 830215, both trains of control room filtration unit &
A train penetration room filtration sys failed to meet Tech
Spec criteria for carbon efficiency Caused by
misinterpretation of Reg Guide 1 52
HAIRSTON, W O Alabama Power Co 83/02/16 O'REILLY, J P Region 2,
Office of Director 2pp 17304 362 24X Fiche 50-348, 83/02/16,
8302280211

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLS, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKE: 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

8302020408 FOIA request for NUREG/CR-2239, NUREG/CR-2723, NUREG-0773,
NUREG/CR-2326 & documents re CRAC Code developed by Sandia
ELLIOTT, C W Thomas & Hair 82/11/02 Office of Administration
1p 17009 083 24X Fiche 50-352, 82/11/02, 8302020408

8302020477 Partial response to FOIA request for SAND 81-1549
(NUREG/CR-2239), SAND 82-1110 (NUREG/CR-2723), NUREG-0773 &
NUREG/CR-2326 & all documents re CRAC Code Forwards draft
NUREG-0773 (NUREG/CR-2239) available in FOR
FELTON, J M Division of Rules and Records 82/12/02 ELLIOTT, C W,
Thomas & Hair 1p 17008 334 24X Fiche 50-352, 82/12/02,
8302020477

8302020413 Addl response to FOIA request for NUREG/CR-2239,
NUREG/CR-2723, NUREG-0773, NUREG/CR-2326 & Sandia documents re
CRAC Code NUREG/CR-2723 & NUREG/CR-2336 will be forwarded
FELTON, J M Division of Rules and Records 83/01/05 ELLIOTT, C W
Thomas & Hair 1p 17009 084 24X Fiche 50-352, 83/01/05,
8302020413

8302010031 Forwards request for addl info to complete review of Rev 1
to Design Assessment Rept Info should be provided within 7
working days from ltr receipt
SCHWENGER, A Licensing Branch 2 83/01/21 BAUER, E O
Philadelphia Electric Co 4pp 16990 352 24X
Fiche 50-352, 83/01/21, 8302010031

8302080156 Forwards addl info re heavy loads analysis in response to
830106 telcon w/uttl, EQ&O & NRC
KEMPER, J S Philadelphia Electric Co 83/01/31 EISENHUT, D O
Division of Licensing 5pp 17059 038 24X Fiche 50-352, 83/01/31,
8302080156

8302170482 Board Notification 83-1 forwards BNL draft rept:
"Identification of Seismically Risk-Sensitive Sys &
Components in Nuclear Power Plants - General Methodological
Approach"
EISENHUT, D O Division of Licensing FIN A-3397 83/02/01
PALLADINO, N J Commissioners 134pp. 17203 309 24X
Fiche 50-000, 83/02/01, 8302170482

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re BER of
"Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable, Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302180028 Notification of 830215 meeting w/uttl in Bethesda, MD to
discuss FSAR review items to be covered include control room
habitability & LOCA
MARTIN, R E Licensing Branch 2 83/02/08 SCHWENGER, A, Licensing
Branch 2 4pp 17221 339 24X Fiche 50-352, 83/02/08, 8302180028

8302250028 Notification of 830222 meeting w/BNL & uttl in Bethesda, MD
for BNL presentation of results of evaluation of applicant
PRA
MARTIN, R Licensing Branch 2 83/02/15 SCHWENGER, A, Licensing
Branch 2 3pp 17302 198 24X Fiche 50-352, 83/02/15, 8302250028

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302160481 Forwards Mechanical Engineering Branch draft BER input
discussing unresolved areas of review
SCHWENGER, A Operating Reactors Branch 2 83/02/07 BAUER, E O
Philadelphia Electric Co 76pp 17175 273 24X
Fiche 50-352, 83/02/07, 8302160481

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability," Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302150036 Forwards Affidavit of Svc re distribution of Rev 16 to FBAR
& Rev 2 to fire protection evaluation rept
BRADLEY, E J Philadelphia Electric Co 83/02/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 17146 003
24X Fiche 50-352, 83/02/09, 8302150036

8302250266 Forwards IE Insp Rept 50-352/82-16 on 821129-1210, notice
of violation & significant observations
MARTIN, T T Division of Engineering & Technical Programs 83/02/10,
KEMPER, J S Philadelphia Electric Co 3pp 17292 006 24X
Fiche 50-352, 83/02/10, 8302250266

--8302250268 Notice of violation from insp on 821129-1210
* Division of Engineering & Technical Programs 83/02/10 1p,
17292 009 24X Fiche 50-352, 83/02/10, 8302250268

--8302250273 IE Insp Rept 50-352/82-16 on 821129-1210 Noncompliance
noted computer program users manual for Program ECO-102 did
not have cover sheet to identify current program release
CHAUDHARY, S K, REYNOLDS, S D, NARRROW, L Region 1, Office of
Director 83/01/28 32pp 17292 010 24X Fiche 50-352, 83/02/10,
8302250266

O Adjudicatory correspondence

8302030454 Identifies documents responsive to 821229 request re NRC
review of facility PRA identified documents will be placed
in Poststown, PA LPDR.
HODGDON, A P Hearing Branch 2 83/01/20, ELLIOTT, C W, Thomas &
Hair, 2pp 17006 197 24X Fiche 50-352, 83/01/20, 8302030454

--8302030462 Requests assistance in obtaining documents re detailed
reliability analysis, residual risk & CRAC Code
ELLIOTT, C W, Thomas & Hair 82/12/29 HODGDON, A P Hearing
Branch 2 2pp 17006 199 24X Fiche 50-352, 83/01/20, 8302030454

8302030470 Submits info which should be included in joint rept on
informal discovery to be presented to ASLB on 830124 info
addresses status of informal discovery & estimated schedules
for issues in DES, FEB, SER & PRA review
HODGDON, A P Hearing Branch 2 83/01/21, WETTERHAHN, M J, Conner &
Wetterhahn 2pp 17006 132 24X Fiche 50-352, 83/01/21, 8302030470

--8301260211 Recommends BNL rept milestones for PRA review be changed fr
830218 to 830311 Delay due to diversion of resources to work
on hearing support for Indian Point plants.
SCHWENGER, A Licensing Branch 2 FIN A-3393 83/01/20
EISENHUT, D O Division of Licensing 2pp 17006 134 24X
Fiche 50-352, 83/01/21, 8302030470

--8212290219 Informs that milestone dates for submittal of final draft
PRA to NRC, receipt of NRC comments & submittal of camera
ready copy reset for 830204, 11 & 18, respectively Delay due
to need to divert resources to other projects
PAPAZOLOU, I A Brookhaven National Laboratory, 82/12/22
CHELLTAH, E S Reliability & Risk Assessment Branch, 1p
17006 136 24X Fiche 50-352, 83/01/21, 8302030470

8302010524 Forwards uttl 830127 press release re Unit 2 const plans.
Applicant will continue engineering & const work on Unit 2
to preserve option of completing unit in late 1988.
CONNER, T B Conner & Wetterhahn, CONNER, T B Philadelphia Electric
Co 83/01/28 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety
& Licensing Board Panel 3pp 16977 241 24X
Fiche 50-352, 83/01/28, 8302010524

DOCKETED ITEMS

8302080233 Forwards petition for reconsideration or certification for appeal w/o encl
SUGARMAN, R J Sugarman, R J SUGARMAN, R J Del-Aware Unlimited, Inc 83/02/02 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 17057 205 24X
Fiche 50-352, 83/02/02, 8302080233

8302080257 Petition for reconsideration of ASLB 830124 order denying Del-Aware Unlimited, Inc application to amend contentions, or alternatively, for certification ASLB refusal to consider major changes unjustifiably narrow Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman, R J 83/02/02 Atomic Safety and Licensing Board Panel, 8pp 17057 083 24X Fiche 50-352, 83/02/02, 8302080257

8302070516 Forwards Commonwealth Court of PA 830127 opinion supporting 821216 per curiam order reversing portions of PA Public Util Commission 820827 order Related correspondence
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 83/02/03 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 17pp 17037 057 24X Fiche 50-352, 83/02/03, 8302070516

8302080006 Confirms NRC agreement w/arrangements under which until produced documents in response to JA Dorsey 820826 informal discovery request made available to NRC Documents will be available for NRC exam in Philadelphia, PA until end of Feb HQ0030N, A P Hearing Branch 2 83/02/04 WETTERHAHN, M Conner & Wetterhahn WETTERHAHN, M Philadelphia Electric Co 1p 17058 311 24X Fiche 50-352, 83/02/04, 8302080006

8302090260 Order extending time until 830211 for Commission to act to review Director 821207 decision denying Del-Aware Unlimited 820706 petition
CHILK, S J Office of the Secretary of the Commission 83/02/04, Commissioners 1p 17070 243 24X Fiche 50-352, 83/02/04, 8302090260

8302160357 Memorandum & order rejecting Table S-3 of fuel cycle contention Commission statement of policy on Table S-3 precludes admission
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/10 Limerick Ecology Action 6pp 17167 324 24X Fiche 50-352, 83/02/10, 8302160357

8302160361 Memorandum & order continuing informal discovery, providing for further spec of conditionally admitted contentions & noting dismissal of Environ Coalition on Nuclear Power as party
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/10 12pp 17164 273 24X Fiche 50-352, 83/02/10, 8302160361

8302180419 Forwards petition to file late-filed contention re issue of current viability of river follower method in light of increased cost of const
SUGARMAN, R J Sugarman, R J SUGARMAN, R J Del-Aware Unlimited, Inc 83/02/14 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 17214, 305 24X
Fiche 50-352, 83/02/14, 8302180419

--8302180425 Petition to file late-filed contention on issue of current viability of river follower method in light of increased cost of const Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman, R J 83/02/14 Atomic Safety and Licensing Board Panel 5pp 17214 306 24X Fiche 50-352, 83/02/14, 8302180419

8302230488 Response opposing Del-Aware request for reconsideration or certification for appeal of ASLB 830124 memorandum & order denying Del-Aware application to add three new contentions Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/02/17 Atomic Safety and Licensing Board Panel 11pp 17246 001, 24X Fiche 50-352, 83/02/17, 8302230488

8302230559 Suggests use of procedure in which courtesy copies of orders having short deadlines sent to affected parties directly
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/02/18 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 17256 354 24X
Fiche 50-352, 83/02/18, 8302230559

8302230635 Order directing NRC & util to respond to Del-Aware 830202 petition for reconsideration or certification for appeal & 830214 petition to file late-filed contention Responses due by 830225
BRENNER, L Atomic Safety and Licensing Board Panel, 83/02/18 Del-Aware Unlimited, Inc 2pp 17255 226 24X
Fiche 50-352, 83/02/18, 8302230635

8302240022 Notice of appearance in proceeding Certificate of Svc encl
VOGLER, B H Hearing Branch 2 83/02/22 3pp 17275, 017 24X
Fiche 50-352, 83/02/22, 8302240022

K Utility Final Safety Analysis Report (FSAR) & amends

8302150236 Forwards Affidavit of Svc re distribution of Rev 16 to FSAR & Rev 2 to fire protection evaluation rept
BRADLEY, E J Philadelphia Electric Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17146 003
24X Fiche 50-352, 83/02/09, 8302150036

Q Inspection reports, IE Bulletins & correspondence

8302010397 Ack receipt of supplemental 821217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/81-17 & 50-353/81-15
STAROSTECKI, R Division of Project & Resident Programs 83/01/25
KEMPER, J S Philadelphia Electric Co 1p 16973 176 24X
Fiche 50-352, 83/01/25, 8302010397

--8302010401 Suppls response to NRC 820204 ltr re violations noted in IE Insp Repts 50-352/81-17 & 50-353/81-15 Corrective actions 100% insp performed on wall thickness violations of pipe spools
KEMPER, J S Philadelphia Electric Co 82/12/17 HAYNES, R C Region 1, Office of Director 3pp 16973 177 24X
Fiche 50-352, 83/01/25, 8302010397

8212060398 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060398

8212060360 IE Info Notice 83-02, "Limitique H08C, H10C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 093 24X Fiche 50-000, 83/01/28, 8212060361

8302190418 Forwards IE Insp Rept 50-352/83-01 on 830104-07 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/31
KEMPER, J S Philadelphia Electric Co 2pp 17148 144 24X
Fiche 50-352, 83/01/31, 8302190418

--8302190420 IE Insp Rept 50-352/83-01 on 830104-07 No noncompliance noted
Major areas inspected documentation for safety-related mechanical component receipt insp, storage, handling & in-process activities during installation
VARELA, A A, DURR, J P Division of Engineering & Technical Programs 83/01/28 4pp 17148 146 24X Fiche 50-352, 83/01/31, 8302190418

8302230266 Forwards IE Insp Rept 50-352/82-16 on 821129-1210, notice of violation & significant observations
MARTIN, T T Division of Engineering & Technical Programs 83/02/10
KEMPER, J S Philadelphia Electric Co 3pp 17292 006 24X
Fiche 50-352, 83/02/10, 8302230266

--8302230268 Notice of violation from insp on 821129-1210
+ Division of Engineering & Technical Programs 83/02/10 1p 17292 009 24X Fiche 50-352, 83/02/10, 8302230266

--8302230273 IE Insp Rept 50-352/82-16 on 821129-1210 Noncompliance noted computer program users manual for Program ECO-102 did not have cover sheet to identify current program release
CHAUDHARY, B K, REYNOLDS, B D, NARROW, L Region 1, Office of Director 83/01/28 32pp 17292 010 24X Fiche 50-352, 83/02/10, 8302230266

8302230474 Responds to IE Bulletin 82-04 "Deficiencies in Primary Containment Electrical Penetration Assemblies " No Bunker-Ramo electrical penetration assemblies in use at facilities
KEMPER, J S Philadelphia Electric Co 83/02/15 HAYNES, R C Region 1, Office of Director 2pp 17245 182 24X
Fiche 50-352, 83/02/15, 8302230474

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

DOCKETED ITEMS

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

B Reportable occurrences, LFRs & related correspondence

B212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low
voltage circuit breakers w/solid state trip devices Units
from San Onofre 2 & 3 failed due to long-term degradation of
filter capacitor C205 Suspect trip units should be tested
DUVAL, D D Brown Boveri Corp (subs Brown Boveri & Co, Ltd.)
82/12/10 STELLO, V Director's Office, Office of Inspection and
Enforcement 2pp 17023 284 24X Fiche 50-000,82/12/10,8212140330

B302230725 Deficiency Rept 70 re GE-supplied local instrument panel
piping diagram causing potentially incorrect interface
w/reactor pressure vessel instrumentation P&ID Piping will
be corrected Also reported per Part 21
KEMPER, J S Philadelphia Electric Co 83/02/14 HAYNES, R C
Region 1, Office of Director 1p 17257 297 24X
Fiche 50-352,83/02/14,8302230725

B302220341 Initial Deficiency Rept 67 re Rockwell Intl hydrogen
combiners Reported equipment failures during qualification
testing corrected per vendor instructions Also reported per
Part 21 by Rockwell Intl
KEMPER, J S Philadelphia Electric Co 83/02/15 HAYNES, R C
Region 1, Office of Director 2pp 17228 006 24X
Fiche 50-352,83/02/15,8302220341

--B302220346 Part 21 deficiency rept re failure of post-LOCA hydrogen
recombiner component switches during qualification testing
Initially reported on 821021 Switch should be eliminated
from circuit Field bulletin issued
EMPEY, D C Rockwell International Corp 82/11/03 COLLINS, J
Region 4, Office of Director 3pp 17228 010 24X
Fiche 50-352,83/02/15,8302220346

--B302220353 Part 21 deficiency rept re Timetrol SCR power controller
failure during qualification testing Initially reported on
821021 Timetrol unit should be replaced w/Halmar unit
Affected plants listed
EMPEY, D C Rockwell International Corp 82/11/03
COLLINS, J Region 4, Office of Director 3pp 17228 013 24X
Fiche 50-352,83/02/15,8302220353

B302280323 Submits editorial correction to Paragraph 4.2 in 810929
final deficiency rept re HVAC fabrication & installation
deficiencies
KEMPER, J S Philadelphia Electric Co 83/02/15 HAYNES, R C
Region 1, Office of Director 1p 17313 044 24X
Fiche 50-352,83/02/15,8302280323

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLs, NBS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000,83/01/31,8301310203

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

B208060366 Board Notification 82-70 notifies of differing prof opinion
re sensitization of BWR stainless steel weldments
EISENHUT, D G Division of Licensing 82/07/20 PALLADINO, N J
Commissioners, 4pp 17043 001 24X Fiche 50-000,82/07/20,
8208060366

B302020408 FOIA request for NUREG/CR-2239, NUREG/CR-2723, NUREG-0773,
NUREG/CR-2326 & documents re CRAC Code developed by Sandia,
ELLIOTT, C W Thomas & Hair, 82/11/02 Office of Administration
1p 17009 083 24X Fiche 50-352,82/11/02,8302020408

B302020177 Partial response to FOIA request for SAND 81-1549
(NUREG/CR-2239), SAND 82-1110 (NUREG/CR-2723), NUREG-0773 &
NUREG/CR-2326 & all documents re CRAC Code Forwards draft
NUREG-0773 NUREG/CR-2239 available in PDR
FELTON, J M Division of Rules and Records 82/12/02 ELLIOTT, C W
Thomas & Hair 1p 17008 334 24X Fiche 50-352,82/12/02,
8302020477

B302020413 Addl response to FOIA request for NUREG/CR-2239,
NUREG/CR-2723, NUREG-0773, NUREG/CR-2326 & Sandia documents re
CRAC Code NUREG/CR-2723 & NUREG/CR-2326 will be forwarded
FELTON, J M Division of Rules and Records 83/01/05 ELLIOTT, C W
Thomas & Hair 1p 17009 084 24X Fiche 50-352,83/01/05,
8302020413

B302010031 Forwards request for addl info to complete review of Rev 1
to Design Assessment Rept Info should be provided within 7
working days from ltr receipt
SCHWENGER, A Licensing Branch 2 83/01/21 BAUER, E O
Philadelphia Electric Co 4pp 16990 352 24X
Fiche 50-352,83/01/21,8302010031

B302010524 Forwards util 830127 press release re Unit 2 const plans
Applicant will continue engineering & const work on Unit 2
to preserve option of completing unit in late 1988
CONNER, T D Conner & Wetterhahn CONNER, T D Philadelphia Electric
Co 83/01/28 BRENNER, L, COLA, R F, MORRIS, P A Atomic Safety
and Licensing Board Panel 3pp 16977 241 24X
Fiche 50-352,83/01/28,8302010524

B302080156 Forwards addl info re heavy loads analysis in response to
830105 telcon w/util, E&O & NRC
KEMPER, J S Philadelphia Electric Co 83/01/31 EISENHUT, D G
Division of Licensing 3pp 17059 058 24X Fiche 50-352,83/01/31,
8302080156

B302170482 Board Notification 83-1 forwards DNL draft rept,
"Identification of Seismically Risk-Sensitive Sys &
Components in Nuclear Power Plants - General Methodological
Approach"
EISENHUT, D G Division of Licensing FIN A-3397 83/02/01
PALLADINO, N J Commissioners 134pp 17203 309 24X
Fiche 50-000,83/02/01,8302170482

B302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000,83/02/08,8302080295

B302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re BER of
"Emergency Procedures Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth
Edison Co 4pp 17234 245 24X Fiche 50-000,83/02/08,8302080301

E NRC Safety Evaluation Report (SER), supp & correspondence

B302160481 Forwards Mechanical Engineering Branch draft BER input
discussing unresolved areas of review
SCHWENGER, A Operating Reactors Branch 2 83/02/07 BAUER, E O
Philadelphia Electric Co 76pp 17175 273 24X
Fiche 50-352,83/02/07,8302160481

F Security, medical, emergency & fire protection plans

B301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000,83/02/01,8301210340

B302150036 Forwards Affidavit of Svc re distribution of Rev 16 to FBAR
& Rev 2 to fire protection evaluation rept
BRADLEY, E J Philadelphia Electric Co 83/02/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director, 3pp 17146 003
24X Fiche 50-352,83/02/09,8302150036

G Adjudicatory correspondence

B302030454 Identifies documents responsive to 821229 request re NRC
review of facility PRA Identified documents will be placed
in Pottstown, PA LPDR
HODGDON, A P Hearing Branch 2 83/01/20 ELLIOTT, C W Thomas &
Hair 2pp 17006 197 24X Fiche 50-352,83/01/20,8302030454

--B302030462 Requests assistance in obtaining documents re detailed
reliability analysis, residual risk & CRAC Code
ELLIOTT, C W Thomas & Hair 82/12/29 HODGDON, A P Hearing
Branch 2 2pp 17006 199 24X Fiche 50-352,83/01/20,8302030462

DOCKETED ITEMS

8302030470 Submits info which should be included in joint rept on informal discovery to be presented to ASLB on 830124 Info addresses status of informal discovery & estimated schedules for issues in DEB, FES, SER & PRA review
HODGSON, A P Hearing Branch 2 83/01/21 WETTERHAHN, M J Conner & Wetterhahn 2pp 17006 132 24X Fiche 50-352, 83/01/21, 8302030470

--8301260211 Recommends BNL rept milestone for PRA review be changed from 830218 to 830311 Delay due to diversion of resources to work on hearing support for Indian Point plants.
SCHWENCER, A Licensing Branch 2 FIN A-3393 83/01/20 EISENHUT, D O. Division of Licensing 2pp 17006 134 24X Fiche 50-352, 83/01/21, 8302030470

--8212290219 Informs that milestone dates for submittal of final draft PRA to NRR, receipt of NRC comments & submittal of camera ready copy reset for 830204, 11 & 18, respectively. Delay due to need to divert resources to other projects
PAPA200LOU, I A Brookhaven National Laboratory. 82/12/22 CHELLIAH, E S Reliability & Risk Assessment Branch. 1p 17006 136 24X Fiche 50-352, 83/01/21, 8302030470

8302010524 Forwards util 830127 press release re Unit 2 const plans Applicant will continue engineering & const work on Unit 2 to preserve option of completing unit in late 1988
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 83/01/28 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 16977 241 24X Fiche 50-352, 83/01/28, 8302010524

8302080233 Forwards petition for reconsideration or certification for appeal w/o encl.
SUGARMAN, R J Sugarmann, R J SUGARMAN, R J Del-Aware Unlimited, Inc 83/02/02 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 17057 205 24X Fiche 50-352, 83/02/02, 8302080233

8302080237 Petition for reconsideration of ASLB 830124 order denying Del-Aware Unlimited, Inc application to amend contentions, or alternatively, for certification ASLB refusal to consider major changes unjustifiably narrow Certificate of Svc encl.
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarmann, R J 83/02/02 Atomic Safety and Licensing Board Panel. 8pp 17057 063 24X Fiche 50-352, 83/02/02, 8302080237

8302070510 Forwards Commonwealth Court of PA 830127 opinion supporting 821215 per curiam order reversing portions of PA Public Util Commission 820827 order Related correspondence
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 83/02/03 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 17pp 17037 057 24X Fiche 50-352, 83/02/03, 8302070510

8302080006 Confirms NRC agreement w/arrangements under which util produced documents in response to JA Dorsey 820826 informal discovery request made available to NRC Documents will be available for NRC exam in Philadelphia, PA until end of Feb.
HODGSON, A P Hearing Branch 2 83/02/04 WETTERHAHN, M Conner & Wetterhahn WETTERHAHN, M Philadelphia Electric Co 1p 17058 311 24X Fiche 50-352, 83/02/04, 8302080006

8302090260 Order extending time until 830211 for Commission to act to review Director 821207 decision denying Del-Aware Unlimited 820706 petition
CHILKIS, J Office of the Secretary of the Commission 83/02/04 Commissioners 1p 17070 243 24X Fiche 50-352, 83/02/04, 8302090260

8302160357 Memorandum & order rejecting Table B-3 of fuel cycle contention Commission statement of policy on Table B-3 precludes admission
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/10 Limerick Ecology Action. 8pp 17167 324 24X Fiche 50-352, 83/02/10, 8302160357

8302160361 Memorandum & order continuing informal discovery, providing for further spec of conditionally admitted contentions & noting dismissal of Environ Coalition on Nuclear Power as party
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/10 12pp 17164 273 24X Fiche 50-352, 83/02/10, 8302160361

8302180419 Forwards petition to file late-filed contention re issue of current viability of river follower method in light of increased cost of const.
SUGARMAN, R J Sugarmann, R J SUGARMAN, R J Del-Aware Unlimited, Inc 83/02/14 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 17214 305 24X Fiche 50-352, 83/02/14, 8302180419

8302230488 Response opposing Del-Aware request for reconsideration or certification for appeal of ASLB 830124 memorandum & order denying Del-Aware application to add three new contentions Certificate of Svc encl.
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/02/17 Atomic Safety and Licensing Board Panel 11pp 17246 001 24X Fiche 50-352, 83/02/17, 8302230488

8302230559 Suggests use of procedure in which courtesy copies of orders having short deadlines sent to affected parties directly
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/02/18 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 17256 354 24X Fiche 50-352, 83/02/18, 8302230559

8302230635 Order directing NRC & util to respond to Del-Aware 830202 petition for reconsideration or certification for appeal & 830214 petition to file late-filed contention Responses due by 830225
BRENNER, L Atomic Safety and Licensing Board Panel 83/02/18 Del-Aware Unlimited, Inc 2pp 17255 226 24X Fiche 50-352, 83/02/18, 8302230635

8302240022 Notice of appearance in proceeding Certificate of Svc encl
VOGLER, B H Hearing Branch 2 83/02/22 3pp 17275 017 24X Fiche 50-352, 83/02/22, 8302240022

K Utility Final Safety Analysis Report (FSAR) & amends

8302190026 Forwards Affidavit of Svc re distribution of Rev 16 to FSAR & Rev 2 to fire protection evaluation rept
BRADLEY, E J Philadelphia Electric Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17146 003 24X Fiche 50-352, 83/02/09, 8302190026

G Inspection reports, IE Bulletins & correspondence

8302010377 Ack receipt of supplemental 821217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/81-17 & 50-353/81-15
STAROSTECKI, R Division of Project & Resident Programs 83/01/25 KEMPER, J S Philadelphia Electric Co 1p 16973 176 24X Fiche 50-352, 83/01/25, 8302010377

--8302010401 Suppls response to NRC 820204 ltr re violations noted in IE Insp Repts 50-352/81-17 & 50-353/81-15 Corrective actions 100% insp performed on wall thickness violations of pipe spoils
KEMPER, J S Philadelphia Electric Co 82/12/17 HAYNES, R C Region 1, Office of Director 3pp 16973 177 24X Fiche 50-352, 83/01/25, 8302010377

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230474 Responds to IE Bulletin 82-04 "Deficiencies in Primary Containment Electrical Penetration Assemblies " No Bunker-Ramo electrical penetration assemblies in use at facilities
KEMPER, J S Philadelphia Electric Co 83/02/15 HAYNES, R C Region 1, Office of Director 2pp 17245 182 24X Fiche 50-352, 83/02/15, 8302230474

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

DOCKETED ITEMS

233

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, B3/02/24, B212060366

B Reportable occurrences, LERs & related correspondence

B212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co, Ltd) B2/12/10 STELLO, V Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, B2/12/10, B212140330

B302230725 Deficiency Rept /O re GE-supplied local instrument panel piping diagram causing potentially incorrect interface w/reactor pressure vessel instrumentation P&ID Piping will be corrected Also reported per Part 21
KEMPER, J S Philadelphia Electric Co B3/02/14 HAYNES, R C Region 1, Office of Director 1p 17257 297 24X Fiche 50-352, B3/02/14, B302230725

B302220341 Initial Deficiency Rept 67 re Rockwell Intl hydrogen containers Reported equipment failures during qualification testing corrected per vendor instructions Also reported per Part 21 by Rockwell Intl
KEMPER, J S Philadelphia Electric Co B3/02/15 HAYNES, R C Region 1, Office of Director 2pp 17228 006 24X Fiche 50-352, B3/02/15, B302220341

B302280323 Submits editorial correction to Paragraph 4.2 in B10929 final deficiency rept re HVAC fabrication & installation deficiencies
KEMPER, J S Philadelphia Electric Co B3/02/15 HAYNES, R C Region 1, Office of Director 1p 17313 044 24X Fiche 50-352, B3/02/15, B302280323

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for GLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing B3/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, B3/01/31, B301310203

DOCKE: 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B302070411 Forwards "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River"
MITTL, R L Public Service Electric & Gas Co of New Jersey B3/02/01 SCHWENGER, A Licensing Branch 2 2pp 17071 024 24X Fiche 50-354, B3/02/01, B302070411

--B302090412 "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River"
Public Service Electric & Gas Co of New Jersey B3/01/31 46pp 17071 026 24X Fiche 50-354, B3/02/01, B302090412

B302030089 Generic Ltr B3-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment Requests commitment to submit results of plant-unique calculations which formed bases for mod Svc list encl
EISENHUT, D G Division of Licensing B3/02/02 General Public Utilities - GPU Service Corp. 5pp 17074 086 24X Fiche 50-000, B3/02/02, B302030089

B302220005 Advises that NRC Caseload Forecast Panel will visit plant on B30103-07 to obtain info re status of const.
SCHWENGER, A Licensing Branch 2 B3/02/10 MITTL, R L Public Service Electric & Gas Co of New Jersey 4pp 17233 312 24X Fiche 50-354, B3/02/10, B302220005

B302230531 Forwards addl info in response to NRC B11104 ltr re util request for authorization to use certain components designed to codes & stds for coolant pressure boundary equipment specified in 10CFR50.55a, Subsections C-F
MITTL, R L Public Service Electric & Gas Co of New Jersey B3/02/10 SCHWENGER, A Licensing Branch 2 15pp 17256 285 24X Fiche 50-354, B3/02/10, B302230531

G Adjudicatory correspondence

B302150445 Response to Philadelphia Electric Co & PSE&G B30124 motion to strike C Keford affidavit suppl re expert qualifications Affidavit provides no relevant facts not considered by ASLAs 4/Certificate of Svc
REIS, E J Hearing Branch 3 B3/02/14 Commissioners 8pp 17158 194 24X Fiche 50-000, B3/02/14, B302150445

B302280193 Order extending time until B30328 for Commission to act to review TH1 & Peach Bottom Intervenor B21227 petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission B3/02/25 Commissioners 2pp 17306 059 24X Fiche 50-000, B3/02/25, B302280193

H General correspondence

B302030585 Forwards revised distribution sheet for all NRC correspondence
MITTL, R L Public Service Electric & Gas Co of New Jersey B3/01/24 SCHWENGER, A Licensing Branch 2 2pp 17007 354 24X Fiche 50-354, B3/01/24, B302030585

I Inspection reports, IE Bulletins & correspondence

B212060358 IE Info Notice B3-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, B3/01/26, B212060358

B212060360 IE Info Notice B3-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, B3/01/28, B212060360

B212060361 IE Info Notice B3-03, "Caliber of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, B3/01/28, B212060361

B302070389 Forwards BALP rept for Sept 1981 - Aug 1982 Overall performance in const of facility acceptable
HAYNES, R C Region 1, Office of Director B3/02/02 MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp 17030 062 24X Fiche 50-354, B3/02/02, B302070389

--B302070394 Notices of B21207 site meeting to discuss BALP rept Written comments may be provided within 20 days following meeting
STAROSTECKI, R Division of Project & Resident Programs B2/11/22, MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp 17030 064 24X Fiche 50-354, B3/02/02, B302070389

--B302070396 BALP rept for Sept 1981 - Aug 1982
Region 1, Office of Director B2/11/08 29pp 17030 066 24X Fiche 50-354, B3/02/02, B302070389

--B302070398 Comments on BALP rept for Sept 1981 - Aug 1982 Rept provides fair assessment of performance
MARTIN, T J Public Service Electric & Gas Co of New Jersey, B2/12/27 STAROSTECKI, R Division of Project & Resident Programs, 2pp 17030 095 24X Fiche 50-354, B3/02/02, B302070389

B302100407 Ack receipt of B30120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/B2-15
STAROSTECKI, R Division of Project & Resident Programs B3/02/07 MARTIN, T J Public Service Electric & Gas Co of New Jersey 1p 17111 322 24X Fiche 50-354, B3/02/07, B302100407

--B302100412 Responds to NRC B21220 ltr re violations noted in IE Insp Rept 50-354/B2-15 Corrective actions all safety-related hanger drawings reviewed & QC personnel training sessions conducted
MARTIN, T J Public Service Electric & Gas Co of New Jersey, B3/01/20, HAYNES, R C Region 1, Office of Director 3pp 17111 323 24X Fiche 50-354, B3/02/07, B302100407

B302230598 Forwards IE Insp Rept 50-354/B3-01 on B30103-31. No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs B3/02/09 MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp 17256 129 24X Fiche 50-354, B3/02/09, B302230598

DOCKETED ITEMS

--B302230608 IE Insp Rept 50-354/83-01 on B30103-31 No noncompliance noted Major areas inspected installation of cable trays, HVAC ducts & supports, pipes & supports, structural steel & reactor vessel internals & licensee action on previous insps
BATEMAN, W. H., TRIPP, L. E. Division of Project & Resident Programs
83/02/09 8pp 17256 131 24X Fiche 50-354, 83/02/09, B302230598

R Periodic operating reports & related correspondence

B302230153 Advises that fuel load scheduled for Jan 1986 Const approx 60 6X complete
LANDRIEU, P. R. H. Public Service Electric & Gas Co. of New Jersey
83/01/07 TRIPP, L. E. Division of Project & Resident Programs 1p
17243 238 24X Fiche 50-354, 83/01/07, B302230153

B302230171 Advises that fuel load date scheduled for Jan 1986 Const approx 62 9X complete Unit 2 const abandoned Dec 1981
LANDRIEU, P. R. H. Public Service Electric & Gas Co. of New Jersey
83/02/07 TRIPP, L. E. Division of Project & Resident Programs 1p
17245 087 24X Fiche 50-354, 83/02/07, B302230171

S Reportable occurrences, LERs & related correspondence

B302010395 Interim deficiency rept re grout intrusion into drywell airgap Initially reported on B20920 Grout will be removed by B30225
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
83/01/18 HAYNES, R. C. Region 1, Office of Director 2pp
16973 255 24X Fiche 50-354, 83/01/18, B302010395

B302250201 Part 21 rept re possible thermostatic valve malfunction fail-safe to full cooling position in emergency diesel generators Lower overrun assemblies replaced w/ assemblies utilizing cotter pins to lock nut to stem
MORIARTY, J. M. Colt Industries, Inc. 83/02/15 KEPLER, J. O. Region 3, Office of Director 1p 17292 358 24X Fiche 50-354, 83/02/15, B302250201

B302280428 Significant const deficiency rept re emergency diesel generators Initially reported on B21213 Inadvertent contamination w/diesel fuel by elastomer seal (O ring), resulted in binding or malfunction Elastomer seals removed
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
83/02/15 HAYNES, R. C. Region 1, Office of Director 2pp
17307 327 24X Fiche 50-354, 83/02/15, B302280428

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B302090411 Forwards "Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River"
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey
83/02/01 SCHNEIDER, A. Licensing Branch 2 2pp 17071 024 24X Fiche 50-354, 83/02/01, B302090411

--B302090412 'Monitoring of Liquefied Natural Gas & Liquefied Petroleum Gas Shipping & Const Activities on DE River'
* Public Service Electric & Gas Co. of New Jersey 83/01/31 46pp 17071 026 24X Fiche 50-354, 83/02/01, B302090411

G Adjudicatory correspondence

302150445 Response to Philadelphia Electric Co & PSE&O B30124 motion to strike C. Keppford affidavit suppl re expert qualifications Affidavit provides no relevant facts not considered by ASL&B's W/Certificate of Svc
REIS, E. J. Hearing Branch 3 83/02/14 Commissioners 8pp
17158 194 24X Fiche 50-000, 83/02/14, B302150445

302280193 Order extending time until B30328 for Commission to act to review TMI & Peach Bottom intervenors B21227 petition for review of ALAB-701
CHILK, S. J. Office of the Secretary of the Commission 83/02/25 Commissioners 2pp 17306 059 24X Fiche 50-000, 83/02/25, B302280193

Q Inspection reports, IE Bulletins & correspondence

B212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/26 Consolidated Edison Co. of New York, Inc. 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice 83-02, "Limiterque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

S Reportable occurrences, LERs & related correspondence

B302010395 Interim deficiency rept re grout intrusion into drywell airgap Initially reported on B20920 Grout will be removed by B30225
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
83/01/18 HAYNES, R. C. Region 1, Office of Director 2pp
16973 255 24X Fiche 50-354, 83/01/18, B302010395

B302280428 Significant const deficiency rept re emergency diesel generators Initially reported on B21213 Inadvertent contamination w/diesel fuel by elastomer seal (O ring), resulted in binding or malfunction Elastomer seals removed
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey
83/02/15 HAYNES, R. C. Region 1, Office of Director 2pp
17307 327 24X Fiche 50-354, 83/02/15, B302280428

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B302280348 Discusses allegations that relevant documentation on welder qualification not discussed w/or made available to Region III at B20709 meeting List of documents or repts used at meeting encl
SYLVIA, B. P. Cincinnati Gas & Electric Co. 82/11/15 KEPLER, J. O. Region 3, Office of Director 3pp 17308 081 24X Fiche 50-358, 82/11/15, B302280348

B302180066 Addl response to FOIA request for documents re IE Insp Rept 50-358/B1-13 Forwards App A documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records 82/12/27 DEVINE, T., ROSENTHAL, J. Government Accountability Project 7pp 17216 225 24X Fiche 50-358, 82/12/27, B302180066

--B302180070 Submits TW Appellate charges against NRC investigator G Phillip re violation of law (ref 10CFR1250.3)
BELLIS, R., DEVINE, T., CLARK, L. Government Accountability Project 82/12/27 26pp 17216 234 24X Fiche 50-358, 82/12/27, B302180066

--B302180083 "Investigation re Apparent false Statements, Cincinnati Gas & Electric Co." draft
SCHOTT, J. R. Cincinnati Gas & Electric Co. BACI, P. E. Director's Office, Office of Inspection and Enforcement VANDEL, T. NRC - No Detailed Affiliation Given 79/05/24 17pp 17216 292 24X Fiche 50-358, 82/12/27, B302180066

--B302180111 Forwards minutes of premeeting U/P-W Industries re compliance to Spec H-2803 Gladstone Labs ltr w/independent opinion on supplied matl encl
CULVER, B. V. Cincinnati Gas & Electric Co. 80/04/14 MARSHALL, R. Cincinnati Gas & Electric Co. 15pp 17217 097 24X Fiche 50-358, 82/12/27, B302180066

--B302180115 "Investigation Program of Fillet Weld Size on P-W Industries Cable Pan Hangers"
* Foothill Electric Corp * Henry J. Kaiser Co. 80/08/22 233pp 17217 112 24X Fiche 50-358, 82/12/27, B302180066

--B302180120 Forwards "Hydrostatic/Pneumatic Test Rept RR-32"
RITTER, S. J. Cincinnati Gas & Electric Co. 80/01/23 Kaiser Engineers 5pp 17217 345 24X Fiche 50-358, 82/12/27, B302180066

--B302180124 "Hydrostatic/Pneumatic Test Rept RR-32"
* Cincinnati Gas & Electric Co. RR-32 79/03/06 11pp 17217 351 24X Fiche 50-358, 82/12/27, B302180066

--B302180130 Forwards "Hydrostatic/Pneumatic Test Rept RR-26"
RITTER, S. J. Cincinnati Gas & Electric Co. 79/02/27 Kaiser Engineers 4pp 17217 361 24X Fiche 50-358, 82/12/27, B302180066

--B302180132 "Hydrostatic/Pneumatic Test Rept RR-26"
* Cincinnati Gas & Electric Co. RR-26 79/02/26 11pp 17218 031 24X Fiche 50-358, 82/12/27, B302180066

--B302180137 Forwards "Hydrostatic/Pneumatic Test Rept RR-25"
RITTER, S. J. Cincinnati Gas & Electric Co. 80/04/02 Kaiser Engineers 2pp 17218 012 24X Fiche 50-358, 82/12/27, B302180066

--B302180140 "Hydrostatic/Pneumatic Test Rept RR-25"
* Cincinnati Gas & Electric Co. RR-25 79/03/05 13pp 17218 018 24X Fiche 50-358, 82/12/27, B302180066

DOCKETED ITEMS

2

--B302100144 Forwards "Hydrostatic/Pneumatic Test Rept RR-31 "
RITTER, S J Cincinnati Gas & Electric Co 79/10/09 Kaiser
Engineers 3pp 17218 031 24X Fiche 50-358, 82/12/27, B302180066

--B302100147 "Hydrostatic/Pneumatic Test Rept RR-31 "
+ Cincinnati Gas & Electric Co RR-31 79/03/14 14pp
17218 036 24X Fiche 50-358, 82/12/27, B302180066

--B302180151 Forwards "Hydrostatic/Pneumatic Test Rept RR-27 "
RITTER, S J Cincinnati Gas & Electric Co 79/09/28 Kaiser
Engineers 3pp 17218 050 24X Fiche 50-358, 82/12/27, B302180066

--B302180153 "Hydrostatic/Pneumatic Test Rept RR-27 "
+ Cincinnati Gas & Electric Co RR-27 79/03/01 15pp
17218 053 24X Fiche 50-358, 82/12/27, B302180066

--B302180158 Forwards "Hydrostatic/Pneumatic Test Rept RR-29 "
RITTER, S J Cincinnati Gas & Electric Co 79/10/09 Kaiser
Industries Corp 6pp 17218 068 24X Fiche 50-358, 82/12/27,
B302180066

--B302180160 "Hydrostatic/Pneumatic Test Rept RR-29 "
+ Cincinnati Gas & Electric Co RR-29 79/03/05 10pp
17218 074 24X Fiche 50-358, 82/12/27, B302180066

--B302180169 "Hydrostatic/Pneumatic Test Rept RR-28 " Related
documentation encl
+ Cincinnati Gas & Electric Co RR-28 79/03/02 143pp
17218 037 24X Fiche 50-358, 82/12/27, B302180066

--B302180185 Forwards "Hydrostatic/Pneumatic Test Rept RR-30 "
RITTER, S J Cincinnati Gas & Electric Co 79/10/09 Kaiser
Industries Corp 3pp 17218 230 24X Fiche 50-358, 82/12/27,
B302180066

--B302180188 "Hydrostatic/Pneumatic Test Rept RR-30 " Related
documentation encl
+ Cincinnati Gas & Electric Co RR-30 79/03/02 35pp
17218 235 24X Fiche 50-358, 82/12/27, B302180066

--B302180194 Forwards "Hydrostatic/Pneumatic Test Rept RR-33 "
RITTER, S J Cincinnati Gas & Electric Co 80/05/24 Kaiser
Industries Corp 4pp 17218 270 24X Fiche 50-358, 82/12/27,
B302180066

- B302180197 "Hydrostatic/Pneumatic Test Rept RR-33 "
+ Cincinnati Gas & Electric Co RR-33 79/09/27 11pp
17218 274 24X Fiche 50-358, 82/12/27, B302180066

--B302180205 "Flushing Procedure, Drain Sys "
WALD, J J, WOOD, R L Cincinnati Gas & Electric Co 77/07/06
520pp 17218 885 24X Fiche 50-358, 82/12/27, B302180066

- B302180211 "Separation of Electrical Equipment Plant Wide Field Audit
Procedure "
CARLTON, R F, SADOWSKI, R H Sargent & Lundy, Inc 80/02/08
11pp 17220 005 24X Fiche 50-358, 82/12/27, B302180066

B302080113 Board Notification BR-122A forwards USOB 821118 ltr
clarifying previous recommendations re recurrence of 1886
Charleston-type earthquake W/O encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic
Safety and Licensing Board Panel 18pp 17105 335 24X
Fiche 50-000, 82/12/30, B302080113

B302070035 Addl response to FOIA request for documents re IE Insp Rept
50-358/81-13 App A documents available in PDR App B
Documents 1-9 & 11-18 partially withheld (ref FOIA
Exemptions 6 & 7)
FELTON, J M Division of Rules and Records 83/01/04 DEVINE, T,
ROSENTHAL, J Government Accountability Project 5pp, 17124 001
24X Fiche 50-358, 83/01/04, B302090005

--B302090008 File transfer record transmitting Harpster personal file re
facility
GAMBLE, D Office of Inspector & Auditor, 81/03/09 HARPSTER, T,
CRATIG, J Director's Office, Office of Inspection and Enforcement
3pp 17124 006 24X Fiche 50-358, 83/01/04, B302090005

--B302090013 Discusses 800702 conversation w/P Dinsler re facility
Proprietary info deleted (ref 10CFR2 770) Related info encl.
DEVINE, T Government Accountability Project 80/07/02 CLARK, L
Government Accountability Project 1,218pp 17124, 009 24X
Fiche 50-358, 83/01/04, B302090005

--B302090023 Informs that M Hertzgaard contacted re release of work not
concerning witness interview Matter will be discussed
freely via telcon Work notes cannot be released Related info
encl
DEVINE, T Government Accountability Project 81/03/15
HCCARTEN, J Region 3, Chicago, Office of the Director (81/03/01)
314pp 17127 155 24X Fiche 50-358, 83/01/04, B302090005

B302010575 Forwards Bechtel B30105 ltr clarifying company relationship
w/Dillon, Read & Co, Inc No conflict of interest exists
between Bechtel & Dillon, Read contrary to allegations
resulting in order to show cause & suspension of const
DICKHONER, W H Cincinnati Gas & Electric Co 83/01/10
KEPPLER, J G Region 3, Office of Director 3pp 16977 052 24X
Fiche 50-358, 83/01/10, B302010575

B302010535 Amend 144 to OL application, consisting of Rev 6 to Environ
Rept
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/26 DENTON, H
Office of Nuclear Reactor Regulation, Director 4pp 16977 163
24X Fiche 50-358, 83/01/26, B302010535

B302040083 Forwards "Quality Confirmation Program, Status as of 821231, "
for review
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/27 KEPPLER, J G
Region 3, Office of Director 3pp 17021 223 24X
Fiche 50-358, 83/01/27, B302040083

--B302010087 "Quality Confirmation Program, Status as of 821231 "
SHAFFNER, J F Cincinnati Gas & Electric Co 83/01/27 23pp,
17021 226 24X Fiche 50-358, 83/01/27, B302040083

B302040247 Requests support & cooperation in B30124 team evaluation &
independent measurement verification of selected safety-
related structures, components & equipment Specific items
should be returned to as-constructed condition after test
KEPPLER, J G Region 3, Office of Director 83/01/27 BORGMANN, E A
Cincinnati Gas & Electric Co 2pp 17020 045 24X
Fiche 50-358, 83/01/27, B302040247

B302010545 Amend 145 to OL application, consisting of Rev 91 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16975 262
24X Fiche 50-358, 83/01/31, B302010545

B302080169 Forwards Bechtel B30131 response to NRC questions posed on
B30126 re order to show cause & order immediately suspending
const Response clarifies relationship between Dillon, Read
& Co & Bechtel
DICKHONER, W H Cincinnati Gas & Electric Co 83/01/31
KEPPLER, J G Region 3, Office of Director 3pp 17058 355 24X
Fiche 50-358, 83/01/31, B302080169

B302170482 Board Notification B3-1 forwards ONL draft rept,
"Identification of Seismically Risk-Sensitive Sys &
Components in Nuclear Power Plants - General Methodological
Approach "
EISENHUT, D O Division of Licensing FIN A-3397 83/02/01
PALADINO, N J Commissioners 134pp 17203 309 24X
Fiche 50-000, 83/02/01, B302170482

B302170011 Forwards audit repts on seismic & dynamic qualification of
safety-related equipment Repts also available in PDR
BACCHI, G Equipment Qualification Branch 83/02/02 NOONAN, V B
Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000, 83/02/02, B302170011

--B110230003 Trip rept of seismic qualification review team 810602-05
site visit to Moscow, OH re plant seismic & dynamic
qualification methods & field installation of equipment to
verify equipment modeling used in qualification program
CHAM, T Y Equipment Qualification Branch 81/10/01
RCSZTQCLY, Z R Equipment Qualification Branch 60pp 17206 217
24X Fiche 50-000, 83/02/02, B302170011

B302140006 Forwards Certificate of Svc of Amend 144 to application for
OL, in form of Rev 6 to environ rept
BORGMANN, E A Cincinnati Gas & Electric Co 83/02/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 10pp, 17142, 145
24X Fiche 50-358, 83/02/03, B302140006

B302150338 Forwards supplementary info re equipment environ
qualifications, per NRC 821129 request Rev 1 to B20716
environ qualification rept also encl, per LL Kintner request
BORGMANN, E A Cincinnati Gas & Electric Co 83/02/03 DENTON, H
Office of Nuclear Reactor Regulation, Director 297pp 17190, 045
24X Fiche 50-358, 83/02/03, B302150338

DOCKETED ITEMS

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302170037 Forwards Certificate of Svc of Amend 145 to OL application, consisting of Rev 91 to FSAR on 830131
BORGMANN, E A Cincinnati Gas & Electric Co 83/02/09 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 17183 023
24X Fiche 50-358, 83/02/09, 8302170037

8302180354 Ack receipt of 830114 ltr in response to 821227 request for details of audit program
HARNICK, R F Region 3, Office of Director 83/02/14 BORGMANN, E A
Cincinnati Gas & Electric Co 2pp 17211 002 24X
Fiche 50-358, 83/02/14, 8302180354

8302180356 Discusses self-initiated audits re QA program, HVAC, design control quality confirmation program, stress & hanger analysis for cable spread room & cable info sys program
List of proposed 1983 audits encl
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/14
HARNICK, R F Region 3, Office of Director 3pp 17211-004 24X
Fiche 50-358, 83/02/14, 8302180356

8302250134 Requests NRR assistance in assessment of magnitude of any deviations from design drawings & specs, FSAR or SER
NOVAK, T M Assistant Director for Licensing 83/02/16 JOHNSTON, W
Assistant Director for Matis & Qualif Engineering (Pre 830201)
KNIGHT, J Assistant Director for Comp & Structures Engineering (Pre 830201)
HOUSTON, R W Assistant Director for Radiation Protection 3pp 17302 314 24X Fiche 50-358, 83/02/16, 8302250134

C Utility Environmental Report (ER), amends & correspondence

8302010535 Amend 144 to OL application, consisting of Rev 6 to Environ Rept
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/26 DENTON, H
Office of Nuclear Reactor Regulation, Director 4pp 16977 163
24X Fiche 50-358, 83/01/26, 8302010535

8302010541 Rev 6 to Environ Rept
"Cincinnati Gas & Electric Co 83/01/31 19pp 16977 167 24X
Fiche 50-358, 83/01/26, 8302010535

8302140006 Forwards Certificate of Svc of Amend 144 to application for OL in form of Rev 6 to environ rept
BORGMANN, E A Cincinnati Gas & Electric Co 83/02/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 10pp 17142 143
24X Fiche 50-358, 83/02/03, 8302140006

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302230529 Forwards correspondence re site emergency planning, including ANL evaluation of SOPs for OH & Clermont County, OH Draft of Brown County, OH radiological emergency response plan distributed.
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Cincinnati Gas & Electric Co 83/02/17 ROSENTHAL, A S, EILPERIN, S F,
WILBUR, H A Atomic Safety and Licensing Appeal Panel 24pp
17257 246 24X Fiche 50-358, 83/02/17, 8302230529

I Adjudicatory correspondence

8302080285 Requests appearance during 821220 rehearing on rate case & during hearing on complaint case filed against util re inclusion of facility const costs Written interrogatories in lieu of appearance at hearings acceptable
KELLY, J F Ohio, State of 82/12/14 KEPLER, J G Region 3,
Office of Director 1p 17056 062 24X Fiche 50-358, 82/12/14,
8302080285

8302080293 Requests that NRC provide witness knowledgeable in area of PUC of OH 821105 order & opinion re const & impact on future const, as witness in 821220 complaint hearings W/o NRC witness, decision will be made on basis of incomplete record
SPRATLEY, N A Ohio, State of 82/11/29 KEPLER, J O Region 3,
Office of Director 53pp 17056 063 24X Fiche 50-358, 82/12/14,
8302080286

8302090095 Forwards notice of disclosure to be filed in Appellate vs NRC Civil Action 82-1829
PARRISH, R A Office of the General Counsel 82/12/27 DAVEY, J F
U S District Court, District of Columbia 1p 17118 001 24X
Fiche 50-358, 82/12/27, 8302090095

8302090100 Notice of disclosure of FOIA lawsuit re NRC documents concerning review of investigation rept on allegations made by plaintiff re facility const
BATES, J D U S District Court, District of Columbia 82/12/27
27pp 17118 002 24X Fiche 50-358, 82/12/27, 8302090095

8302090118 Requests that rept in consultation w/Ofc of General Counsel be prepared by Mar re Ofc of Special Counsel 801229 ltr
AHEARNE, J Commissioners 81/01/07 Office of Inspector &
Auditor 1p 17118 030 24X Fiche 50-358, 82/12/27, 8302090095,

8302090126 Discusses 810302 ltr to Ofc of Legal Counsel re scope of jurisdiction of Ofc of Special Counsel, Merit Sys Protection Board to require NRC to submit rept on T Appellate allegations of govt waste NRC not required to furnish rept
FITZGERALD, J A Office of the General Counsel 81/03/18
HEHRIE, J, GILINSKY, V, BRADFORD, J Commissioners 1p
17118 031 24X Fiche 50-358, 82/12/27, 8302090095

8302090137 Responds to 810302 ltr re authority of Ofc of Special Counsel, Merit Sys Protection Board to require NRC to furnish rept re T Appellate allegation of mismanagement & gross waste at facility
SINKS, L L Justice, Dept of 81/03/13 BICKWIT, L Office of the
General Counsel 4pp 17118 032 24X Fiche 50-358, 82/12/27,
8302090095

8302090005 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 App A documents available in PDR App B Documents 1-9 & 11-18 partially withheld (ref FOIA Exemptions 6 & 7)
FELTON, J M Division of Rules and Records 83/01/04 DEVINE, T
Government Accountability Project 3pp 17124 001 24X
Fiche 50-358, 83/01/04, 8302090005

8302090076 Affidavit of TH Harpster re adequacy of station staffing at facility JE Manning affidavit & related info encl
HARPSTER, T L Region 2, Atlanta, Office of the Director
79/05/22 63pp 17131 223 24X Fiche 50-358, 83/01/04, 8302090005

8302230412 Contentions 1 - 5 re diesel generator transmission gears, suppression pool structural malis, boiling water transports, ion exchange resin sys & electrolyte accretion problem
GILMAN, D Affiliation Unknown 83/01/21 Commissioners 5pp
17257 099 24X Fiche 50-358, 83/01/21, 8302230412

8302070522 Protests manner in which Region III is reviewing util proposal of Bechtel proposal to conduct third party program
Commission, not NRC staff, should decide if proposals satisfy
Commission 821112 order
BERNABEI, L, DEVINE, T Government Accountability Project
BERNABEI, L Miami Valley Power Project 83/01/31 PALLADINO, N J
Commissioners 11pp 17039 017 24X Fiche 50-358, 83/01/31,
8302070522

8302170294 Discusses concerns re NRC oversight of third-party nomination & util nomination of Bechtel to audit & propose solutions for QA breakdown at facility
DEVINE, T, BERNABEI, L Government Accountability Project 83/02/11
DIRKS, N J Office of the Executive Director for Operations 7pp
17178 208 24X Fiche 50-358, 83/02/11, 8302170294

8302230529 Forwards correspondence re site emergency planning, including ANL evaluation of SOPs for OH & Clermont County, OH Draft of Brown County, OH radiological emergency response plan distributed.
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Cincinnati Gas & Electric Co 83/02/17 ROSENTHAL, A S, EILPERIN, S F,
WILBUR, H A Atomic Safety and Licensing Appeal Panel 24pp
17257 246 24X Fiche 50-358, 83/02/17, 8302230529

8302230617 Order CLI-83-4, ruling on Miami Valley Power Project 820820 petition for reconsideration of Commission 820730 order, CLI-82-20 Partially requesting reconsideration denied Issue of whether project met stds for reopening record pursuant
CHILK, S J Office of the Secretary of the Commission 83/02/18
Miami Valley Power Project 3pp 17255 191 24X
Fiche 50-358, 83/02/18, 8302230617

DOCKETED ITEMS

H General correspondence

8302150494 Responds to 830110 ltr expressing opposition to reopening of hearings & to Bechtel involvement in third-party audit Reopening or public hearing pending before Commission & approval of Bechtel as auditor not yet issued
CUNNINGHAM, G H Office of the Executive Legal Director 83/02/10
BOJMAN, F C Affiliation Unknown 3pp 17156 320 24X
Fiche 50-358, 83/02/10, 8302150494

--8302150500 Opposes reopening of hearings & involvement of Bechtel in third-party audit
BOJMAN, F C Affiliation Unknown 83/01/10 PALLADINO, N
Commissioners 2pp 17156 323 24X Fiche 50-358, 83/02/10,
8302150494

K Utility Final Safety Analysis Report (FSAR) & amends

8302010545 Amend 145 to OL application, consisting of Rev 91 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16975 262
24X Fiche 50-358, 83/01/31, 8302010545

--8302010549 Rev 91 to FSAR
Cincinnati Gas & Electric Co 83/01/31 179pp 16975 264
24X Fiche 50-358, 83/01/31, 8302010545

8302170037 Forwards Certificate of Bvc of Amend 145 to OL application, consisting of Rev 91 to FSAR on 830131
BORGMANN, E A Cincinnati Gas & Electric Co 83/02/09 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 17183 023
24X Fiche 50-358, 83/02/09, 8302170037

D Advisory Committee on Reactor Safeguards reports & correspondence

8302180066 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 82/12/27 DEVINE, T
Government Accountability Project 7pp 17216 225 24X
Fiche 50-358, 82/12/27, 8302180066

--8302180078 Informs that acceptance criteria suitable for lead Mark II plants Present ECCS analysis contains adequate margins for assessing performance
CARSON, M U ACRS - Advisory Committee on Reactor Safeguards
7/9/03/13 HENDRIE, J M Commissioners 3pp 17223 314 24X
Fiche 50-358, 82/12/27, 8302180066

G Inspection reports, IE Bulletins & correspondence

8302250319 Forwards IE Mgt Meeting Rept 50-358/82-16 on 821122
WARNICK, R Region 3, Office of Director 83/02/11 BORGMANN, E A
Cincinnati Gas & Electric Co 2pp 17291 033 24X
Fiche 50-358, 82/02/11, 8302250319

--8302250320 IE Mgt Meeting Rept 50-358/82-16 on 821122 No noncompliance noted Major areas discussed licensee response to 820924 demand for info per 10CFR50.54(f) re petition to suspend const from Miami Valley Power Authority
HUNTER, D R, WARNICK, R F Region 3, Office of Director 82/02/10
3pp 17291 035 24X Fiche 50-358, 82/02/11, 8302250319

8302040432 Requests partial release of Stop Work Order 80-14 to remove hangers/supports installed by Reactor Controls, Inc as result of IE Insp Rept 50-358/80-14 Hanger & support design no longer acceptable per Sargent & Lundy design analysis.
BORGMANN, E A Cincinnati Gas & Electric Co 82/08/06 KEPLER, J Q
Region 3, Office of Director 1p 17017 331 24X
Fiche 50-358, 82/08/06, 8302040432

8302090095 Forwards notice of disclosure to be filed in Appellate vs NRC Civil Action 82-1829
PARRISH, R A Office of the General Counsel 82/12/27 DAVEY, J F
U S District Court, District of Columbia 1p 17118 001 24X
Fiche 50-358, 82/12/27, 8302090095

--8302090148 Forwards 810920 FOIA request for Inspector & Auditor 810807 rept, "Adequacy of IE Investigation 50-358/80-09 at WH Zimmer Nuclear Power Station " Rept does not contain any predecisional advice Request to withhold rept denied
CUMMINOS, J J Office of Inspector & Auditor 82/12/27
PALLADINO, N, OILINSKY, V, AHEARN, J Commissioners, 69pp
17118 036 24X Fiche 50-358, 82/12/27, 8302090095

--8302090157 Forwards IE rept, "Adequacy of IE Investigation 50-358/80-09 at WH Zimmer Nuclear Power Station " IE investigation of T Appellate allegation deficient Investigation failed to properly document results
CUMMINOS, J J Office of Inspector & Auditor 82/12/27
PALLADINO, N, OILINSKY, V, BRADFORD, J Commissioners 42pp
17118 110 24X Fiche 50-358, 82/12/27, 8302090095

--8302090159 "Adequacy of IE Investigation 50-358/80-09 at WH Zimmer Nuclear Power Station," special inquiry
* Office of Inspector & Auditor 82/12/27 46pp 17118 156
24X Fiche 50-358, 82/12/27, 8302090095

--8302090168 Forwards Govt Accountability Project/T Appellate allegation re IE & Ofc of Insp & Auditor investigation Related correspondence encl
* Office of Inspector & Auditor 82/03/24 Office of Inspector & Auditor 73pp 17118 342 24X Fiche 50-358, 82/12/27, 8302090095

--8302090173 Forwards review of welding records for IE investigation T Appellate allegations re facility
* Office of Inspector & Auditor 81/07/16, Office of Inspector & Auditor 18pp 17119 133 24X Fiche 50-358, 82/12/27, 8302090095

8302180066 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 82/12/27 DEVINE, T
ROSENTHAL, J Government Accountability Project, 7pp 17216 225
24X Fiche 50-358, 82/12/27, 8302180066

--8302180085 Forwards IE Insp Rept 50-358/78-06 on 780228 & 0301-03 Noncompliance noted
FIDORELLI, O Region 3, Chicago, Office of the Director, 78/03/22
BORGMANN, E A Cincinnati Gas & Electric Co 2pp 17216 315, 2
Fiche 50-358, 82/12/27, 8302180066

--8302180089 IE Insp Rept 50-358/78-06 on 780228 & 0301-03 No noncompliance noted Major areas inspected operational staffing, safety committee activity, plant procedures & preoperational test QA program
HARPBSTER, T L, WARNICK, R F Region 3, Chicago, Office of the Director 78/03/20, 4pp 17216 317 24X Fiche 50-358, 82/12/27, 8302180066

--8302180091 Forwards IE Insp Rept 50-358/78-20 on 780911-15, 21-22 & 1024-25 No noncompliance noted
KEPLER, J Q Region 3, Chicago, Office of the Director 78/11/11
BORGMANN, E A Cincinnati Gas & Electric Co 2pp 17216 321
24X Fiche 50-358, 82/12/27, 8302180066

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support, 82/02/05 KEPLER, J Q Region 3, Office of Director, 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
BUCHARSKI, L Region 3, Office of Director 82/07/08
KEPLER, J Q Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302090005 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 App A documents available in PDR App B Documents 1-9 & 11-18 partially withheld (ref FOIA Exemptions 6 & 7)
FELTON, J M Division of Rules and Records 83/01/04, DEVINE, T, ROSENTHAL, J Government Accountability Project 5pp 17124:001
24X Fiche 50-358, 83/01/04, 8302090005

DOCKETED ITEMS

- 8302090020 Various drafts from R Warrick files re allegations concerning facility
* NRC - No Detailed Affiliation Given 83/01/04 8pp
17127 147 24X Fiche 50-358, 83/01/04, 8302090005
- 8302090035 Requests recommendation to suspend CP Action based on organizational study recently completed of insp & investigations repts from Mar 1979 to date Related info encl
DEVINE, T, RUSLE, P, CLARK, L A Government Accountability Project 81/05/11
KEPPLER, J G Region 3, Chicago, Office of the Director (81/03/01) 66pp 17128 109 24X Fiche 50-358, 83/01/04, 8302090005
- 8302090044 Forwards draft IE Insp Rept 50-358/81-13, notice of violation & proposed imposition of civil penalty, cross-references & ltr to licensee
KEPPLER, J G Region 3, Office of the Director 83/01/04 THOMPSON, D Director's Office, Office of Inspection and Enforcement 53pp 17128 188 24X Fiche 50-358, 83/01/04, 8302090005
- 8302090052 Forwards revised draft IE Insp Rept 50-358/81-13 Final form of rept & recommendations will be sent by 831026 Various drafts from R Warrick files, handwritten notes from Streeter files & draft transcript encl
KEPPLER, J G Region 3, Chicago, Office of the Director (81/03/01) 81/10/08 STELLO, V Director's Office, Office of Inspection and Enforcement 1,035pp 17128 241 24X Fiche 50-358, 83/01/04, 8302090005
- 8302090060 Forwards IE Investigation Rept 50-358/79-21 on 790521-24 re licensee statements to ACRS Subcommittee on Staffing Investigation did not establish that licensee made false statements
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/31
GRIER, G Executive Officer for Operations Support 1p 17131 199 24X Fiche 50-358, 83/01/04, 8302090005
- 8302090064 Forwards IE Investigation Rept 50-358/79-21 on 790521-24 No noncompliance noted
KEPPLER, J G Region 3, Chicago, Office of the Director 79/07/31
BORGHANN, E A Cincinnati Gas & Electric Co 2pp 17131 200 24X Fiche 50-358, 83/01/04, 8302090005
- 8302090460 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 Forwards App A documents App B documents partially & completely withheld (ref FOIA Exemptions 3, 5, 6 & 7)
FELTON, J M Division of Rules and Records 83/01/10 DEVINE, T, ROSENTHAL, J Government Accountability Project 6pp 17123 214 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090478 Discusses 810603 review of HJ Kaiser Engineering, Inc GA nonconforming matl rept logs onsite Three files of nonconformance repts discovered stamped "Insp Rept," "void" or "closed" Sixty-two repts not actual insp repts
GAMBLE, D H, PUOLIA, A Office of Inspector & Auditor 81/06/15
Office of Inspector & Auditor 3pp 17123 222 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090485 Forwards US Atty, Southern District of OH 820604 request for investigation of 820527 water dousing of QC inspectors Addl resources for investigation requested due to number of recent serious allegations against util W/o encl
CUMMINGS, J J Office of Inspector & Auditor 82/06/17
PALLADINO, N Commissioners 1p 17123 225 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090488 Forwards IE draft rept of investigation to assist in evaluation of allegations, per 810807 telcon W/o encl
CUMMINGS, J J Office of Inspector & Auditor 81/05/18
TRACEY, A N U S District Court, Southern District of OH 1p 17123 226 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090491 Forwards IE rept of investigation during Jan-Nov 1981, Results of interviews re alteration or falsification of QC documentation included W/o encl
CUMMINGS, J J Office of Inspector & Auditor 81/12/03
TRACEY, A N U.S. District Court, Southern District of OH 1p. 17123 228 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090493 Notifies that computer listing re allegations received from Region III on 820503 Listing placed in appropriate investigation file on 820504
SINCLAIR, J R Office of Inspector & Auditor, 82/05/05 Office of Inspector & Auditor 1p 17123 229 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090496 Forwards Barnes 820602 ltr & N Palladino 820514 ltr Barnes notified of investigation & NRC regionalization W/o encl
CUMMINGS, J J Office of Inspector & Auditor 82/06/04, Commissioners 1p 17123 230 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090498 Forwards J Cummings 811118 memo forwarding interviews conducted during investigation Interviews will be sent to Subcommittee on Energy & Environ on 820713 W/o Kaiser Co 800815 ltr
KAMMERER, C Office of Congressional Affairs 82/07/12
PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 19pp 17123 231 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090501 Forwards interviews re potential falsification of records & correspondence between util & HJ Kaiser Co re QC organization Util 801107 memo requesting elimination of GA review encl Details withheld per FOIA Exemption 7(A)
CUMMINGS, J J Office of Inspector & Auditor 81/11/18 DAVIS, B Region 3, Chicago, Office of the Director (81/03/01) 21pp 17123 250 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090502 Summary of 810422 meeting w/US Atty in Cincinnati, OH re IE investigations of const project Little info or evidence of violations warranting DOJ attention revealed Details withheld (ref FOIA Exemption 7(A))
SINCLAIR, J R Office of Inspector & Auditor 81/05/05 Office of Inspector & Auditor 3pp 17123 323 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090505 Forwards 810920 statement Recipient name & statement withheld pending continued investigation (ref FOIA Exemption 7(A) & (C))
SCHNEBELIN, A A Office of Inspector & Auditor 81/05/27 Affiliation Unknown 12pp 17123 326 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090508 Ack receipt of 810909 ltr re investigation Criminal investigation will be discontinued until civil investigation completed DOJ 810926 ltr re parallel investigations encl Info deleted W/o stated encl
CUMMINGS, J J Office of Inspector & Auditor 81/09/17
HANLEY, P J U S District Court, Southern District of OH 2pp 17123 336 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090512 Forwards memo re interview & HJ Schweirs 801107 memo directing HJ Kaiser Co to turn over sys prior to completing certification
SINCLAIR, J R Office of Inspector & Auditor 81/11/09 BLAHA, J NRC - No Detailed Affiliation Given 1p 17123 340 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090520 Forwards Harpster interview connected w/ "Adequacy of IE Investigation 50-358/80-09 at Zimmer Nuclear Power Station " Interview also relevant to "Allegations re Deficient Const " Info deleted W/o encl
CUMMINGS, J J Office of Inspector & Auditor 82/06/24 DAVIS, B Region 3, Office of the Director 2pp 17123 342 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090524 Submits list of major issues in investigation Nonconformance repts missing from sys, 739 voided repts & discrepancies between hardware & QC documentation discussed Info deleted
GAMBLE, D Office of Inspector & Auditor 81/05/29 SCHNEBELIN, A Office of Inspector & Auditor 1p 17123 344 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090527 Discusses P Gwynn 810608 reporting of suspected etching of heat numbers on pipes Info deleted (ref FOIA Exemption 7(A) & (C)) Related documents encl
GAMBLE, D H, PUOLIA, A Office of Inspector & Auditor 81/06/19 Office of Inspector & Auditor 17pp 17123 345 24X Fiche 50-358, 83/01/10, 8302090460
- 8302090546 Forwards list of exhibits supplementing draft rept of investigation W/o encl
CUMMINGS, J J Office of Inspector & Auditor 81/08/26
TRACEY, A N U S District Court, Southern District of OH 1p 17123 227 24X Fiche 50-358, 83/01/10, 8302090460
- 8302040279 Notification of contract execution, Task Order 32 to "Technical Assistance to Support IE Personnel in Investigations of Incidents " Contractor Parameter, Inc
HOLZET, S Technical Assistance Contracts Branch FIN B-1302 83/01/21 BLAHA, J, LAUDAN, W Director's Office, Office of Inspection and Enforcement 1p 17042 301 24X Fiche 50-358, 83/01/21, 8302040279
- 8302040292 Ltr Contract NRC-05-82-249, "Technical Assistance to Support IE Personnel in Investigations of Incidents " Details terms of Task Order 32 re independent const insp of activities at plant Accepted by RA Lofy on 830121
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-1302 83/01/14 LOFFY, R A Parameter, Inc 8pp 17042 302 24X Fiche 50-358, 83/01/21, 8302040279
- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

DOCKETED ITEMS

8302150015 Forwards IE Rept 50-358/83-01 on 830111-13 No noncompliance noted
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/01/26 BORGMANN, E. A. Cincinnati Gas & Electric Co 2pp 17147 144 24X Fiche 50-358, 83/01/26, 8302150015

--8302150019 IE Insp Rept 50-358/83-01 on 830111-13 No noncompliance noted Major areas inspected radiation protection program, including organization, procedures & qualifications of rad/chem technicians
MILLER, D. E., OREGER, L. R. Division of Emergency Preparedness & Operational Support 83/01/25 2pp 17147 144 24X Fiche 50-358, 83/01/26, 8302150015

8212060360 IE Info Notice 83-02, "Limit torque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESBARD, R. L. Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Vary Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVAL, D. D. Brown Boveri Corp (subs Brown Boveri & Co., Ltd) 82/12/10 STELLO, V. Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302010638 Interim Deficiency Rept re RHR HX valves Initially reported on 820820 Completion date for mods will be delayed because of failure to receive all matl & stop work order Next rept will be submitted by 830401
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/01/20 KEPPLER, J. O. Region 3, Office of Director 1p 16980.040 24X Fiche 50-358, 83/01/20, 8302010638

8302010223 Interim Deficiency Rept re fire damper failures Initially reported on 821029 Util consulting w/AB1 to determine solution Hooks will probably be rotated to prevent blade interference Final rept will be submitted by 830315
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/01/21 KEPPLER, J. O. Region 3, Office of Director 2pp 16974.003 24X Fiche 50-358, 83/01/21, 8302010223

8302080291 Interim deficiency rept re lack of installation insp of non-Class IE cables in panels Initially reported on 821124. Revised const & insp procedures will be approved by 830228 Next rept will be submitted on 830729
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/01/25 KEPPLER, J. O. Region 3, Office of Director 2pp 17056.060. 24X Fiche 50-358, 83/01/25, 8302080291

8302080299 Interim deficiency rept re fittings w/high stress stamps & non-stamped stamps Initially reported on 820722. All fittings stamped by Kaiser scrapped All fittings w/high stress stamps will be reworked. Next rept by 830401.
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/01/27 KEPPLER, J. O. Region 3, Office of Director 2pp 17056.132. 24X Fiche 50-358, 83/01/27, 8302080299

8302040423 Interim deficiency rept re improper heat number used in transfer or structural steel Initially reported on 821126 Review of heat number identification ongoing Next rept will be provided by 830315
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/01/31 KEPPLER, J. O. Region 3, Office of Director 2pp 17017 332 24X Fiche 50-358, 83/01/31, 8302040423

8302080325 Interim deficiency rept re lack of insp records for Nelson studs for cable tray hangers Changes made to initial program outlined in util 821221 ltr to reflect lack of records for torquing of nuts on hanger ft Final rept due by 830228
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/01/31 KEPPLER, J. O. Region 3, Office of Director 2pp 17056 312. 24X Fiche 50-358, 83/01/31, 8302080325

8302150529 Interim deficiency rept re item E-35 electrical equipment foundation welding Initially reported on 830104 HJ Kaiser & util evaluating panel mounting welds to imbed plates & as-built mounting arrangements Final rept by 830331
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/01/31 KEPPLER, J. O. Region 3, Office of Director 2pp 17156.220 24X Fiche 50-358, 83/01/31, 8302150529

8302150377 Interim deficiency rept re lack of procedural qualification for pipe bends Initially reported on 821109 Rev to Procedure MCP-7 to be completed by 830211. Requalification effort to be conducted after issuance of rev.
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/02/04, KEPPLER, J. O. Region 3, Office of Director 2pp 17155.221 24X Fiche 50-358, 83/02/04, 8302150377

8302280435 Interim deficiency rept re lack of HJ Kaiser weld procedure qualification Welding review group formed to review revs of welding procedure specs & to develop qualification review package Next rept will be submitted by 830430
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/02/07 KEPPLER, J. O. Region 3, Office of Director 2pp 17307 348 24X Fiche 50-358, 83/02/07, 8302280435

8302180253 Interim Deficiency Rept M-40 re indeterminate heat treatment for small bore pipe Removal of pipe for destructive tests to determine heat treatment contingent upon NRC release of stop work order Followup rept to be submitted by 830415.
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/02/08, KEPPLER, J. O. Region 3, Office of Director 1p. 17215 276 24X Fiche 50-358, 83/02/08, 8302180253

8302180270 Interim deficiency rept re lack of QA program for fire protection sys installation Document & commitment review Underway Results should indicate that Branch Technical Position APCSR 9.5-1, App A, met Next rept due by 830430
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/02/08 KEPPLER, J. O. Region 3, Office of Director 1p 17212.063 24X Fiche 50-358, 83/02/08, 8302180270

8302180470 Interim Deficiency Rept 8-5 re Level I coatings Initially reported on 820928 Comprehensive investigation initiated to verify Svc Level I coating integrity Followup rept to be submitted by 830415
BORGMANN, E. A. Cincinnati Gas & Electric Co 83/02/09 KEPPLER, J. O. Region 3, Office of Director 1p 17214.362 24X Fiche 50-358, 83/02/09, 8302180470

8302180446 Interim deficiency rept re fire protection piping suspended from essential cable tray supports Initially reported on 821013 Audit of Sargent & Lundy corrective actions will be completed & rept submitted by 830415
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/11, KEPPLER, J. O. Region 3, Office of Director 2pp 17213.359. 24X Fiche. 50-358, 83/02/11, 8302180446

8302250193 Board Notification 83-15 forwards deficiency rept re alteration of welding procedures Interim rept will be submitted by 830401
EISENHUT, D. O. Division of Licensing 83/02/15 PALLADINO, N., GILINSKY, V., AHEARNE, J. F. Commissioners 4pp 17298 345 24X Fiche 50-358, 83/02/15, 8302250193

T Hearing transcripts on non-antitrust matters

8302180066 Adsl response to FOIA request for documents re IE Insp Rept 50-358/81-13 Forwards App A documents Documents also available in PDR
FELTON, J. H. Division of Rules and Records. 82/12/27 DEVINE, T. Government Accountability Project 7pp 17216.225. 24X Fiche. 50-358, 82/12/27, 8302180066

--8302180074 Partial transcripts of Schott & Bergmann before ACRB re backup svcs for technical staff
* ACRS - Advisory Committee on Reactor Safeguards. 82/12/27 24pp. 17216 264 24X Fiche. 50-358, 82/12/27, 8302180066.

DOCKETED ITEMS

Operator Examinations

0301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NRB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licensees Bvc list encl.
EISENHUT, D O Division of Licensing, 83/01/31, Consolidated Edison Co. of New York, Inc. 14pp 17347:177, 24X
Fiche: 50-000, 83/01/31, 8301310203.

0302280227 Responds to Generic Ltr 83-01 requesting projected dates for operator exam site visits Dates & number of candidates tentative.
CHITKARA, K K Cincinnati Gas & Electric Co 83/02/23, EISENHUT, D O Division of Licensing 1p 17304 352 24X
Fiche: 50-358, 83/02/23, 8302280227

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

Security, medical, emergency & fire protection plans

0301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Bvc list encl.
EISENHUT, D O Division of Licensing, 83/02/01, Consolidated Edison Co. of New York, Inc. 11pp 17221:226, 24X
Fiche: 50-000, 83/02/01, 8301210340.

0302180454 Repts status of emergency preparedness conditions per License Condition 2.C. Primary & backup meteorological towers & health physics computer sys fully operational Spanish brochure in emergency planning zone not warranted.
BASKIN, K P Southern California Edison Co, 83/02/04, KNIGHTON, O W Licensing Branch 3, 8pp, 17215:160, 24X Fiche: 50-361, 83/02/04, 8302180454

0302160391 Forwards Jan 1983 physical security plan. Plan withheld (ref 10CFR73.21)
BASKIN, K P Southern California Edison Co 83/02/11, Office of Nuclear Reactor Regulation, Director, 1p 17164 204, 24X
Fiche: 50-206, 83/02/11, 8302160391

Adjudicatory correspondence

0302020291 Expresses appreciation for meeting re possibility of participation in proceeding Hearing remains suspended. Further details re proceeding issues unavailable.
CHANDLER, L J Hearing Branch 2, 83/02/01, BRODIN, R F California, Univ of, San Francisco, 1p, 16993:316 24X Fiche: 50-361, 83/02/01, 8302020291.

0302020326 Forwards stipulation providing extension of OL conditions re offsite medical svcs.
CHANDLER, L J Hearing Branch 2, 83/02/01, KELLEY, J L Atomic Safety and Licensing Board Panel, 1p 16993:355 24X
Fiche: 50-361, 83/02/01, 8302020326

-8302020335 Stipulation that 820514 initial decision be amended to allow full power operation pending resolution of medical svcs issue for 6-month period from 830317 or from Commission issuance of decision on certified issues.
CHANDLER, L J Hearing Branch 2, PIGOTT, D R Southern California Edison Co, MCCLUNG, C E, Affiliation Unknown, 83/01/31 3pp 16993:356, 24X Fiche: 50-361, 83/02/01, 8302020335.

0302020605 Order approving 830131 stipulation amending ABLB 820514 initial decision to allow full power operation pending resolution of medical svcs issue for six months from 830317 or from date NRC decides issue.
KELLEY, J L Atomic Safety and Licensing Board Panel, 83/02/01 1p 17034:276, 24X Fiche: 50-361, 83/02/01, 8302020605

Insurance & indemnity information

0302180329 Forwards Endorsements 91-93 & 36 to NELIA Policies NF-146 & NS-282, respectively, Endorsements 80-82 to MAELU Policy MF-308, Endorsement B to NELIA Binders EB-10 & EB-81 & MAELU Binder XB-81 & Certificates N-87 & M-87.
ROCCO, J Southern California Edison Co, 83/02/14, DINITZ, I, Antitrust & Economic Analysis Branch (Utility Finance), 38pp, 17213:266 24X Fiche: 50-206, 83/02/14, 8302180329.

P Operating license stage documents & correspondence

8302020353 FOIA request for Sandia Natl Lab rept detailing potential results of serious accidents at nuclear power plants & info re existing evacuation plans & other contingency safety measures at facilities.
POLLOCK, D J, HAYS, S Affiliation Unknown, 82/11/08, Division of Rules and Records, 2pp 16996 024 24X Fiche: 50-206, 82/11/08, 8302020353

8302020359 Responds to FOIA request for Sandia Natl Lab rept detailing results of accidents at nuclear power plants & info re evacuation plans at facilities Forwards Documents 2 & 3 listed in App A App B documents available in LPDR.
FELTON, J H Division of Rules and Records, 82/12/06, POLLOCK, D J, HAYS, S Affiliation Unknown, 3pp 16996 026 24X
Fiche: 50-206, 82/12/06, 8302020359

8302010546 Forwards revised listing of ESB actuation sys (ESFAS) subgroup relays & ESFAS relays which changed categories, per 821220 Tech Spec change request, affecting subgroup relay component assignments.
BASKIN, K P Southern California Edison Co, 83/01/28, KNIGHTON, O W Licensing Branch 3, 26pp 16982 308 24X Fiche: 50-361, 83/01/28, 8302010546.

8302020004 Forwards fees for Amends 9 & 10 to License NPF-10, changing Tech Specs re mod to turbine overspeed.
BASKIN, K P Southern California Edison Co, 83/01/28, MILLER, W O License Fee Management Branch, 3pp 16994:337, 24X
Fiche: 50-361, 83/01/28, 8302020004

8302020142 Forwards 38 oversize P&IDs, in response to NRC request for info to be used in performance of limited scope PRA on facility Aperture cards are available in PDR.
KRIEGER, R M Southern California Edison Co, 83/01/31, PAULSON, W A, MCKENNA, E NRC - No Detailed Affiliation Given, 1p 16994:336 24X Fiche: 50-206, 83/01/31, 8302020142.

8302080164 Advises of error in Amends 13 & 2 to Licenses NPF-10 & NPF-15, respectively Amends issued on 821230, incorrectly changed Tech Specs re ESB response times Util will continue to operate on basis that amends did not change times.
BASKIN, K P Southern California Edison Co, 83/02/04, KNIGHTON, O W Licensing Branch 3, 2pp 17037 223 24X Fiche: 50-361, 83/02/04, 8302080164

---8302080168 Proposed corrected pages to Tech Spec Table 3.3-5 re ESB response times.
Southern California Edison Co, 83/02/04, 10pp, 17037 225 24X Fiche: 50-361, 83/02/04, 8302080164

8302170552 Summary of 830131 meeting w/util in Bethesda, MD re control room pressurization testing Util agreed to conduct full control room test within next 2 to 3 wks.
ROCCO, J Licensing Branch 3, 83/02/04, Licensing Branch 3, 5pp 17197 142 24X Fiche: 50-361, 83/02/04, 8302170552.

8302090010 Submits addl info requested in 830111 ltr re duration between occurrence of double ended guillotine break in high energy line feeding steam driven auxiliary feedwater pump & actuation of feedwater sys.
BASKIN, K P Southern California Edison Co, 83/02/07, KNIGHTON, O W Licensing Branch 3, 1p 17070:272, 24X Fiche: 50-361, 83/02/07, 8302090010.

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl.
EISENHUT, D O Division of Licensing, 83/02/08, Consolidated Edison Co of New York, Inc. 11pp, 17290:247, 24X
Fiche: 50-000, 83/02/08, 8302080295.

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Bvc list encl.
EISENHUT, D O Division of Licensing, 83/02/08, Consolidated Edison Co of New York, Inc. 9pp, 17234:234, 24X
Fiche: 50-000, 83/02/08, 8302080304.

8302090072 Generic Ltr 83-10B to all licensees w/C-E designed NSSS re resolution of TH1 Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Bvc list encl.
EISENHUT, D O Division of Licensing, 83/02/08, Consumers Power Co, 32pp 17290 185, 24X Fiche: 50-000, 83/02/08, 8302090072.

DOCKETED ITEMS

8302100280 Discusses fault identified in turbine high pressure governor valves 2 & 4 Valve closure satisfies Tech Spec 3.3.4 Util will implement gags for affected valves by 830210 W/one oversize drawing Aperture card is in PDR
BASKIN, K P Southern California Edison Co 83/02/08 KNIGHTON, Q W
Licensing Branch 3 3pp 17110 077 24X Fiche 50-361, 83/02/08, 8302100280

8302170555 Summary of 821104 meeting w/util & C-E in Bethesda, MD re natural circulation testing
RODD, H Licensing Branch 3 83/02/08 Licensing Branch 3 4pp.
17197 131 24X Fiche 50-361, 83/02/08, 8302170555

8302170558 Summary of 821227 & 830121 meetings w/util & C-E re util actions in response to spurious EBF actuation signal & recirculating actuation signal that occurred on 821217
RODD, H Licensing Branch 3 83/02/08 Licensing Branch 3 3pp
17197 137 24X Fiche 50-361, 83/02/08, 8302170558

8302180503 Summary of 830120 meeting w/util & Bechtel re auxiliary feedwater pump motor bearing qualification
RODD, H Licensing Branch 3 83/02/08 Licensing Branch 3 26pp
17221 283 24X Fiche 50-361, 83/02/08, 8302180503

8302140079 Submits update of info in util 821221 ltr re operability of post-accident sampling sys, per License Condition 2.C (19) Operating procedures & hands-on training will be completed by 830301
BASKIN, K P Southern California Edison Co 83/02/09 KNIGHTON, Q W
Licensing Branch 3 2pp 17141 098 24X Fiche 50-361, 83/02/09, 8302140079

8302250147 Summary of 821207-08 site meetings w/Southern CA Edison Co, San Diego Gas & Electric Co, City of Anaheim, CA & City of Riverside, CA re core protection calculation test program & inadequate core cooling instrumentation
RODD, H Licensing Branch 3 83/02/09 Licensing Branch 3 7pp.
17298 336 24X Fiche 50-361, 83/02/09, 8302250147

8302150053 Forwards C-E rept supporting proposed change to Tech Specs re emergency core cooling Document describes methodology, assumptions & results of C-E analysis to derive HPBI pump head requirement for 83% power.
BASKIN, K P Southern California Edison Co 83/02/10 KNIGHTON, Q W
Licensing Branch 3 19pp 17147 029 24X Fiche 50-361, 83/02/10, 8302150053

8302220118 Notification of contract execution, Mod 3 to "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." Contractor, St. Louis Univ
LITTLE, M Administrative Contracts Branch FIN B-6898, 83/02/10, VOLLMER, R H Division of Engineering JACKSON, R NRC - No Detailed Affiliation Given 1p. 17234 216 24X Fiche 50-206, 83/02/10, 8302220118

--8302220125 Mod 3, extending period of performance by 1 yr & adding requirement for monthly business ltr rept; to "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station."
HERRMANN, R St. Louis Univ REBELLO, J E Division of Contracts, FIN B-6898, 83/02/10 3pp. 17234 217 24X Fiche 50-206, 83/02/10, 8302220118

8302160249 Forwards proposed Tech Spec changes, increasing limit on ventilation unit flow for control room emergency air cleanup sys. Application for OL amends will be submitted during wk of 830228
BASKIN, K P Southern California Edison Co. 83/02/11, KNIGHTON, Q W
Licensing Branch 3 3pp 17170 059 24X Fiche 50-361, 83/02/11, 8302160249

--8302160256 Proposed Tech Spec changes, increasing limit on ventilation unit flow for control room emergency air cleanup sys
* Southern California Edison Co. 83/02/11. 17pp. 17170 062 24X Fiche 50-361, 83/02/11, 8302160249

8302250496 Informs of conclusions reached re auxiliary feedwater pump motor bearing qualification & CPC software error Change implementation schedules requested by 830218.
KNIGHTON, Q Licensing Branch 3. 83/02/14, DIETCH, R Southern California Edison Co. COTTON, O D, BERNATH, L. San Diego Gas & Electric Co. 4pp. 17303 139 24X Fiche 50-361, 83/02/14, 8302250496

8302180291 Suppls 830211 proposed change to Tech Spec 3.4.7.5 re control room emergency air cleanup sys. Operating procedures to be reviewed &/or revised by 830313 to ensure door closure following toxic gas isolation signal
BASKIN, K P Southern California Edison Co. 83/02/16, KNIGHTON, Q W
Licensing Branch 3 2pp. 17211 247 24X Fiche 50-361, 83/02/16, 8302180291

8302220334 Forwards Application 18 for amend to License NPF-10 & Application 4 for amend to License NPF-15, revising Tech Specs to allow mods to mitigate consequences of simultaneous occurrence of safety injection actuation signal
DIETCH, R Southern California Edison Co. 83/02/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17232 037 24X Fiche 50-361, 83/02/17, 8302220334

--8302220337 Applications 18 & 4 for amend to Licenses NPF-10 & NPF-15, respectively, revising Tech Specs to allow mods to mitigate consequences of simultaneous occurrence of safety injection & recirculation actuation signals
DIETCH, R Southern California Edison Co. COTTON, O D San Diego Gas & Electric Co. HOYT, Q W Anaheim, CA 83/02/17 4pp. 17232 039 24X Fiche 50-361, 83/02/17, 8302220334

--8302220339 Proposed Tech Specs allowing mods to mitigate consequences of simultaneous occurrence of safety injection actuation signal & recirculation actuation signal.
DIETCH, R Southern California Edison Co COTTON, O D San Diego Gas & Electric Co. HOYT, Q W Anaheim, CA 83/02/17 16pp. 17232 045 24X Fiche 50-361, 83/02/17, 8302220334

8302280280 Forwards applications for amend to Licenses NPF-10 & NPF-15, revising Tech Spec 6.8.4 d to allow addl improvements to post-accident sampling sys.
BASKIN, K P Southern California Edison Co. 83/02/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17313 045 24X Fiche 50-361, 83/02/24, 8302280280

--8302280284 Applications for amend to Licenses NPF-10 & NPF-15, revising Tech Spec 6.8.4 d to allow addl improvements to post-accident sampling sys
DIETCH, R Southern California Edison Co COTTON, O D San Diego Gas & Electric Co. HOYT, Q W Anaheim, CA 83/02/24 13pp. 17313 047 24X Fiche 50-361, 83/02/24, 8302280280

--8302280288 Proposed Tech Spec 6.8.4 d re post-accident sampling sys changes
* Southern California Edison Co. 83/02/24 3pp. 17313 060 24X Fiche 50-361, 83/02/24, 8302280280

G Inspection reports, IE Bulletins & correspondence

8302070278 Addl response to FOIA request for documents re EE Kent allegations concerning facilities
FELTON, J M. Division of Rules and Records. 82/12/13 CARPENTER, Orange County Alliance for Survival. 1p. 17060 001 24X Fiche 50-206, 82/12/13, 8302070278

--8302070296 Confirms discussions re request for technical assistance concerning allegations by EE Kent, EE Kent statement encl.
CREWS, J L Region 5, Office of Director. 82/10/29 EISENHUT, D Division of Licensing. 8pp 17060 249 24X Fiche 50-206, 82/12/13, 8302070278

8302040499 FOIA request for documents re special insp rept GARDE, B. Government Accountability Project. 82/12/14, Office Administration 2pp 17042 262 24X Fiche 50-206, 82/12/14, 8302040499

8302150366 Forwards IE Insp Repts 50-206/82-34, 50-361/82-44 & 50-362/82-28 on 821116-1216. No noncompliance noted.
BISHOP, T W Division of Resident/Reactor Project & Engineering Programs 83/01/12 PAPAY, L T Southern California Edison Co. 2pp 17157 210 24X Fiche 50-206, 83/01/12, 8302150366

--8302150373 IE Insp Repts 50-206/82-34, 50-361/82-44 & 50-362/82-28 821116-1217. No noncompliance noted. Major areas inspected: QA program & station organization & administration; qualification of personnel & calibr of instrumentation.
STEWART, J P, KIRBOCH, D F. Division of Resident/Reactor Project Engineering Programs. 83/01/10 9pp. 17157 212 24X Fiche 50-206, 83/01/12, 8302150366

8302160457 Addl response to FOIA request for documents re EE Kent allegations concerning facilities Forwards documents listed in Apps A & B Documents partially withheld (ref FOIA Exemptions 5, 6 & 7). Tapes available in PDR.
FELTON, J M. Division of Rules and Records. 83/01/12 CARPENTER, Orange County Alliance for Survival. 4pp 17175 194 24X Fiche 50-206, 83/01/12, 8302160457

--8302160460 Submits notes taken at Region V 821014 mgt meeting re EE Kent allegations. Considered actions listed. Reporters raised questions re allegations Related info encl
SHACKLETON, O C. Region 5, Office of Director. 82/10/14 Reg 5, Office of Director 23pp. 17175 199 24X Fiche 50-206, 83/01/12, 8302160457

DOCKETED ITEMS

8302040505 Partial response to FOIA request for documents re special Insp rept Documents listed on encl app available in PDR in folders "FOIA-82-828 Carpenter " Search for addl documents in progress.
FELTON, J. M. Division of Rules and Records 83/01/13 GARDE, B Government Accountability Project. 3pp 17042:259 24X Fiche: 50-206, 83/01/13, 8302040505

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc. 118pp 17023:160 24X Fiche: 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc. 109pp. 17144 001. 24X Fiche: 50-000, 83/01/28, 8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc. 110pp. 17074 095. 24X Fiche: 50-000, 83/01/28, 8212060361

8302230255 Forwards IE Insp Repts 50-361/82-43 & 50-362/82-35 on 821222-830119 & notice of violation.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/01/28. PAPAY, L. T. Southern California Edison Co 2pp. 17244:329 24X Fiche: 50-361, 83/01/28, 8302230255

-8302230258 Notice of violation from insp on 821222-830119
KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs 83/01/28. 1p. 17244:341. 24X Fiche: 50-361, 83/01/28, 8302230258

-8302230263 IE Insp Repts 50-361/82-43 & 50-362/82-35 on 821222-830119. Noncompliance noted failure to properly label container of radioactive matl.
CHAFEE, A., KIRSCH, D. Division of Resident, Reactor Project & Engineering Programs. 83/01/27. 6pp. 17244:342 24X Fiche: 50-361, 83/01/28, 8302230255

8302230365 Forwards IE Insp Repts 50-206/83-03, 50-361/83-04 & 50-362/83-05 on 830117-21 & notice of violation
BOOK, H. E. Division of Radiological Safety & Safeguards Program 83/02/04. PAPAY, L. T. Southern California Edison Co. 2pp. 17246:292 24X Fiche: 50-206, 83/02/04, 8302230365.

-8302230371 Notice of violation from insp on 830117-21.
WENSLAWSKI, F. A. Division of Radiological Safety & Safeguards Program 83/02/04. 1p. 17246:294. 24X Fiche: 50-206, 83/02/04, 8302230365.

-8302230378 IE Insp Repts 50-206/83-03, 50-361/83-04 & 50-362/83-05 on 830117-21. Noncompliance noted: failure to submit 30-day special rept & one unresolved item involving meeting acceptance criteria of Reg Guide 4.13.
YUHAB, P. P., WENSLAWSKI, F. A., BOOK, H. E. Division of Radiological Safety & Safeguards Program. 83/02/03 9pp 17246:295. 24X Fiche: 50-206, 83/02/04, 8302230365

8302230396 Forwards IE Insp Repts 50-361/83-02 & 50-362/83-02 on 830110-14 & notice of violation.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/04. PAPAY, L. T. Southern California Edison Co 2pp. 17247:269. 24X Fiche: 50-361, 83/02/04, 8302230396.

-8302230399 Notice of violation from insp on 830110-14
KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/04 2pp. 17247:271. 24X Fiche: 50-361, 83/02/04, 8302230396.

-8302230406 IE Insp Repts 50-361/83-02 & 50-362/83-02 on 830110-14. Noncompliance noted failure to maintain acceptable levels of housekeeping for Unit 2.
ECKHARDT, J. H., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/04 10pp. 17247:273. 24X Fiche: 50-361, 83/02/04, 8302230396.

8302230395 Forwards IE Insp Repts 50-361/82-45 & 50-362/82-37 on 821225-830123. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/09. PAPAY, L. T. Southern California Edison Co. 2pp. 17248:074. 24X Fiche: 50-361, 83/02/09, 8302230395.

-8302230404 IE Insp Repts 50-361/82-45 & 50-362/82-37 on 821225-830123. No noncompliance noted. Major areas inspected: LER review & independent insp effort.
PATE, R. J., MENDONCA, M. M., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/09. 5pp. 17248:076 24X Fiche: 50-361, 83/02/09, 8302230395.

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche: 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058. 24X Fiche: 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche: 50-000, 83/02/24, 8212060366.

B. Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVAL, D. D. Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.) 82/12/10 STELLIG, V. Director's Office, Office of Inspection and Enforcement. 2pp 17023 284 24X Fiche: 50-000, 82/12/10, 8212140330

8302010394 Forwards LERs 82-164/03L-0 & 82-166/03L-0 Detailed event analysis submitted
RAY, H. B. Southern California Edison Co 83/01/08 ENGELKEN, R. H. Region 5, Office of Director 3pp 16981 307 24X Fiche: 50-361, 83/01/08, 8302010394

--8302010405 LER 82-164/03L-0 on 821209, diesel generator 20002 failed to regulate at 60 Hz due to failure of electrical governor
Caused by burnt resistor in power supply for control unit
Power supply replaced
RAY, H. B. Southern California Edison Co 83/01/08 Region 5, Office of Director. 1p 16981:310 24X Fiche: 50-361, 83/01/08, 8302010394

--8302010412 LER 82-166/03L-0 on 821210, diesel generator 20003 rendered inoperable due to failure of electrical governor
Caused by burnt resistor in power supply for control unit
Governor power supply replaced
RAY, H. B. Southern California Edison Co 83/01/08 Region 5, Office of Director 1p 16981:311. 24X Fiche: 50-361, 83/01/08, 8302010394

8302010280 Forwards LER 82-168/03L-0 Detailed event analysis submitted
RAY, H. B. Southern California Edison Co 83/01/11. ENGELKEN, R. H. Region 5, Office of Director 2pp 16973 136 24X Fiche: 50-361, 83/01/11, 8302010280

--8302010285 LER 82-168/03L-0 on 821212, indicated position for shutdown control element assembly 12 went from 148 inches to 120 inches resulting in reactor trip
Caused by failure of reed switch, Switch replaced
No further corrective action planned.
RAY, H. B. Southern California Edison Co. 83/01/11 Region 5, Office of Director 1p 16973:138 24X Fiche: 50-361, 83/01/11, 8302010280

8302010668 Forwards LER 82-169/03L-0. Detailed event analysis submitted
RAY, H. B. Southern California Edison Co 83/01/11 ENGELKEN, R. H. Region 5, Office of Director 2pp 16979:202. 24X Fiche: 50-361, 83/01/11, 8302010668

--8302010674 LER 82-169/03L-0 on 821212, low pressure turbine stop valve 24V-2200R located on low pressure turbine 2 failed to fully close following turbine trip
Caused by galling between disc stub shaft & casing bore. Shaft machined.
RAY, H. B. Southern California Edison Co. 83/01/11. Region 5, Office of Director 1p. 16979:204. 24X Fiche: 50-361, 83/01/11, 8302010668

8302010138 Forwards LER 82-150/01T-0 Detailed event analysis submitted.
RAY, H. B. Southern California Edison Co. 83/01/12. ENGELKEN, R. H. Region 5, Office of Director. 2pp. 16974:152. 24X Fiche: 50-361, 83/01/12, 8302010138

--8302010150 LER 82-150/01T-0 on 821229, Kerotest valve incorrectly installed restricting flow through liquid radwaste monitor RT-7B13. Caused by improper installation. Valve realigned & liquid effluent releases sampled.
RAY, H. B. Southern California Edison Co 83/01/12. Region 5, Office of Director 1p. 16974:154. 24X Fiche: 50-361, 83/01/12, 8302010138.

DOCKETED ITEMS

8302010327 Forwards LER 82-170/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/01/13 ENGELKEN, R H
Region 5, Office of Director 2pp 16973 055 24X
Fiche 50-361, 83/01/13, 8302010327

--8302010346 LER 82-170/03L-0 on 821214, review of chart recordings of
RCS cold leg temp indicated heatup/cool-down rate limits
exceeded on three occasions. Caused by inability to properly
control shutdown cooling sys flow. Personnel counseled.
RAY, H B Southern California Edison Co 83/01/13 Region 5,
Office of Director 1p 16973 057 24X Fiche 50-361, 83/01/13,
8302010327

8302010159 Forwards LER 82-167/03L-0 Detailed event analysis submitted
RAY, H B, MORDY, W C Southern California Edison Co 83/01/17
ENGELKEN, R H Region 5, Office of Director 2pp 16974 160 24X
Fiche 50-361, 83/01/17, 8302010159

--8302010169 LER 82-167/03L-0 on 821218, w/both units in Mode 5, control
room emergency chiller E-336 tripped on high bearing temp &
declared inoperable. Caused by faulty solenoid valve for
motor oil cooling unit of chiller. Valve replaced.
RAY, H B, MORDY, W C Southern California Edison Co 83/01/17
Region 5, Office of Director 1p 16974 162 24X
Fiche 50-361, 83/01/17, 8302010159

8302010650 RO 83-004 on 830116, component cooling water train B declared
inoperable since HX saltwater outlet valve would not open.
Cause under investigation. Saltwater outlet valve restored to
operable status.
RAY, H B Southern California Edison Co 83/01/18, ENGELKEN, R H
Region 5, Office of Director 2pp 16979 235 24X
Fiche 50-361, 83/01/18, 8302010650

8302010471 PNS-V-83-003 on 830126, security guard accidentally
discharged newly issued revolver & caused superficial wounds
to right leg. Guard treated & held overnight at hosp for
observation.
MORTENSEN, H P, SCHUSTER, M D Region 5, Office of Director
83/01/27 1p 16981 302 24X Fiche 50-361, 83/01/27, 8302010471

8302130555 Forwards LER 82-173/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/01/27 ENGELKEN, R H
Region 5, Office of Director 2pp 17156 149 24X
Fiche 50-361, 83/01/27, 8302130555

--8302130564 LER 82-173/03L-0 on 821228, w/Units 2 & 3 in Modes 4 & 5,
respectively, emergency chiller E-335 failed to start &
declared inoperable. Caused by loose wire on low lube oil
pressure switch. Wire replaced & chiller declared operable.
RAY, H B Southern California Edison Co 83/01/27 Region 5,
Office of Director 1p 17156 151 24X Fiche 50-361, 83/01/27,
8302130555

8302130571 Forwards LER 82-174/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/01/27 ENGELKEN, R H
Region 5, Office of Director 2pp 17156 149 24X
Fiche 50-361, 83/01/27, 8302130571

--8302130580 LER 82-174/03L-0 on 821228, while in Mode 4, saltwater cooling
sys (SWCB) normal discharge valve ZHV-6495 failed to open,
rendering SWCB train B inoperable. Caused by mechanical
binding. Valve manually opened & exercised.
RAY, H B Southern California Edison Co 83/01/27 Region 5,
Office of Director 1p 17156 147 24X Fiche 50-361, 83/01/27,
8302130571

8302130276 Forwards LER 82-171/03L-0, Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/01/28 ENGELKEN, R H
Region 5, Office of Director 2pp 17148 317 24X
Fiche 50-361, 83/01/28, 8302130276

--8302130285 LER 82-171/03L-0 on 821231, operator insp revealed loss of
position indication for control element assembly 79 as
indicated by control element assembly calculator 1. Caused by
faulty reed switch. Reed switch replaced.
RAY, H B Southern California Edison Co 83/01/28 Region 5,
Office of Director 1p 17148 319 24X Fiche 50-361, 83/01/28,
8302130276

8302130322 Forwards LER 83-004/01T-0, Detailed event analysis encl.
RAY, H B Southern California Edison Co 83/01/28, ENGELKEN, R H
Region 5, Office of Director, 2pp 17148 162 24X
Fiche 50-361, 83/01/28, 8302130322

--8302130329 LER 83-004/01T-0 on 830116, component cooling water train D
declared inoperable. Caused by bent pickup contact in limit
switch LB-3 preventing valve from opening. Switch contact
repaired, valve exercised & tested satisfactorily.
RAY, H B Southern California Edison Co 83/01/28 Region 5,
Office of Director 1p 17148 184 24X Fiche 50-361, 83/01/28,
8302130322

8302130553 Forwards LERs 83-001/03L-0 & 83-002/03L-0 Detailed event
analysis submitted
RAY, H B Southern California Edison Co 83/01/28 ENGELKEN, R H
Region 5, Office of Director, App 17157 003 24X
Fiche 50-361, 83/01/28, 8302130553

--8302130566 LER 83-001/03L-0 on 830101, condensate tank 2T-120 water
level fell below acceptable limits. Caused by inadequate
makeup water control. Level restored & operators instructed
on tank operations.
RAY, H B Southern California Edison Co 83/01/28, Region 5,
Office of Director 1p 17157 007 24X Fiche 50-361, 83/01/28,
8302130553

--8302130577 LER 83-002/03L-0 on 830101, condensate tank T-121 water level
fell below acceptable limits. Caused by inadequate makeup
water control. Automatic level control sys will be installed
by Apr 1983.
RAY, H B Southern California Edison Co 83/01/28 Region 5,
Office of Director 1p 17157 008 24X Fiche 50-361, 83/01/28,
8302130553

8302070273 Forwards response to NRC 830114 request clarified by
830123 meeting re ESF activation sys event on 821217. Response
to 14 add'l questions, per NRC 830123 telcon also encl.
BASKIN, K P Southern California Edison Co 83/02/03 KNIGHTON, O M
Licensing Branch 3 123p 17031 151 24X Fiche 50-361, 83/02/03,
8302070273

8302130245 Forwards LER 83-006/03L-0, Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/02/03 ENGELKEN, R H
Region 5, Office of Director 2pp 17148 353 24X
Fiche 50-361, 83/02/03, 8302130245

--8302130261 LER 83-006/03L-0 on 830107, train B analyzer 2/3 AIT-9782D
failed to meet channel functional test per Tech Spec
Surveillance Requirement 4.3.2.1 & declared inoperable.
Caused by faulty sample cell. Cell replaced.
RAY, H B Southern California Edison Co 83/02/03 Region 5,
Office of Director 1p 17148 353 24X Fiche 50-361, 83/02/03,
8302130245

8302130433 Forwards LER 83-003/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/02/04 ENGELKEN, R H
Region 5, Office of Director 2pp 17158 202 24X
Fiche 50-361, 83/02/04, 8302130433

--8302130447 LER 83-003/03L-0 on 830107, core protection calculator A
failed as indicated by channel A DNBR trip, linear power
density trip lights, core protection lights & light
indication & alarm. Caused by power anomaly.
RAY, H B Southern California Edison Co 83/02/04 Region 5,
Office of Director 1p 17158 204 24X Fiche 50-361, 83/02/04,
8302130433

8302130231 Forwards LER 83-012/03L-0 Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/02/08 ENGELKEN, R H
Region 5, Office of Director 2pp 17215 293 24X
Fiche 50-361, 83/02/08, 8302130231

--8302130234 LER 83-012/03L-0 on 830108, emergency chiller E-336 failed
to start & declared inoperable. Caused by faulty program
timer. Timer replaced.
RAY, H B Southern California Edison Co 83/02/08, Region 5,
Office of Director 1p 17215 293 24X Fiche 50-361, 83/02/08,
8302130231

8302130237 Forwards LER 83-005/03L-0, Detailed event analysis submitted
RAY, H B Southern California Edison Co 83/02/08 ENGELKEN, R H
Region 5, Office of Director 2pp 17212 093 24X
Fiche 50-361, 83/02/08, 8302130237

--8302130239 LER 83-005/03L-0 on 830109, failure of core protection
calculator channel D indicated by lights on channel D DNBR
trip & linear power density trip & alarm. Cause unknown.
Channel D returned to svc.
RAY, H B Southern California Edison Co 83/02/08, Region 5,
Office of Director 1p 17212 097 24X Fiche 50-361, 83/02/08,
8302130237

8302230213 Forwards LER 83-007/03L-0,
RAY, H B Southern California Edison Co 83/02/10, ENGELKEN, R H
Region 5, Office of Director 1p 17293 080 24X
Fiche 50-361, 83/02/10, 8302230213

--8302230224 LER 83-007/03L-0 on 830111, iodine removal sys valve ZHV-5
failed Tech Spec surveillance test & was declared
inoperable. Caused by misaligned upper limit switch. Limit
switch readjusted & valve returned to svc.
RAY, H B Southern California Edison Co 83/02/10 Region 5,
Office of Director 1p 17293 081 24X Fiche 50-361, 83/02/10,
8302230213

DOCKETED ITEMS

8302250223 Forwards LER 83-008/03L-0

RAY, H. B. Southern California Edison Co. 83/02/11. ENOELKEN, R. H.
Region 5, Office of Director 2pp 17293:065. 24X
Fiche: 50-361, 83/02/11, 8302250223

--8302250226 LER 83-008/03L-0: on 830114, during Mode 1, Train 8 post-LOCA
hydrogen monitor 2AET-8111-2 failed to meet channel
functional test. Caused by faulty detector. Detector replaced.
Monitor returned to svc.
RAY, H. B. Southern California Edison Co. 83/02/11. Region 5,
Office of Director. 1p. 17293:067. 24X Fiche: 50-361, 83/02/11,
8302250223.

8302230332 PNO-V-83-007 on 830211, unit manually tripped from 50%
power following failure of steam bypass control valve
actuator due to water hammer. Repairs necessitate plant
shutdown until 830225
ECKHARDT, J. H., KIRBCH, D. F. Region 5, Office of Director 83/02/14,
1p. 17248:129. 24X Fiche: 50-361, 83/02/14, 8302230332

T. Hearing transcripts on non-antitrust matters

8302070278 Adfl response to FOIA request for documents re EE Kent
allegations concerning facilities
FELTON, J. M. Division of Rules and Records. 82/12/13. CARPENTER, T.
Orange County Alliance for Survival. 1p. 17060:001. 24X
Fiche: 50-361, 82/12/13, 8302070278.

--8302070285 Draft transcript of EE Kent taped 821015 interview in Dana
Point, CA of allegations re weld const quality at facilities.
Pp 1-257. Related info encl.
SHACKLETON, O. C., JOUKOFF, P. V., KIRBCH, D. F. Director's Office,
Office of Inspection and Enforcement 82/10/15 243pp.
17060:006. 24X Fiche: 50-206, 82/12/13, 8302070278.

V. Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants
for DLs, NBS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses. Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/01/31. Consolidated
Edison Co. of New York, Inc. 11pp. 17347:177. 24X
Fiche: 50-000, 83/01/31, 8301310203.

XCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

4. Application/construction stage documents & correspondence

8302250147 Summary of 821207-08 site meetings w/Southern CA Edison Co.,
San Diego Gas & Electric Co., City of Anaheim, CA & City of
Riverside, CA re core protection calculation test program &
inadequate core cooling instrumentation
RODD, H. Licensing Branch 3. 83/02/09. Licensing Branch 3. 7pp.
17298:356. 24X Fiche: 50-361, 83/02/09, 8302250147.

5. Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability." Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/02/01. Consolidated
Edison Co. of New York, Inc. 11pp. 17221:226. 24X
Fiche: 50-000, 83/02/01, 8301210340

8302180454 Repts status of emergency preparedness conditions per
License Condition 2. C. Primary & backup meteorological towers
& health physics computer sys fully operational. Spanish
brochure in emergency planning ions not warranted.
BASKIN, K. P. Southern California Edison Co. 83/02/04. KNIGHTON, O. W.
Licensing Branch 3. 8pp. 17215:160. 24X Fiche: 50-361, 83/02/04,
8302180454.

830140391 Forwards Jan 1983 physical security plan. Plan withheld
(ref 10CFR73.21).
BASKIN, K. P. Southern California Edison Co. 83/02/11. Office of
Nuclear Reactor Regulation, Director 1p 17164:204. 24X
Fiche: 50-206, 83/02/11, 830140391.

Adjudicatory correspondence

8302020291 Expresses appreciation for meeting re possibility of
participation in proceeding. Hearing remains suspended.
Further details re proceeding issues unavailable.
CHANDLER, L. J. Hearing Branch 2 83/02/01. BROWN, R. F. California,
Univ. of, San Francisco. 1p. 16993:916. 24X Fiche: 50-361,
83/02/01, 8302020291.

8302020326 Forwards stipulation providing extension of OL conditions re
offsite medical svcs
CHANDLER, L. J. Hearing Branch 2 83/02/01. KELLEY, J. L. Atomic
Safety and Licensing Board Panel 1p 16993:355. 24X
Fiche: 50-361, 83/02/01, 8302020326

--8302020335 Stipulation that 820514 initial decision be amended to
allow full power operation pending resolution of medical
svcs issue for 6-month period from 830317 or from Commission
issuance of decision on certified issues
CHANDLER, L. J. Hearing Branch 2 PIOTT, D. R. Southern California
Edison Co. MCCLUNG, C. E. Affiliation Unknown 83/01/31 3pp.
16993:356. 24X Fiche: 50-361, 83/02/01, 8302020326

8302070605 Order approving 830131 stipulation, amending ASLB 820514
initial decision to allow full power operation pending
resolution of medical svcs issue, for six months from 830317
or from date NRC decides issue
KELLEY, J. L. Atomic Safety and Licensing Board Panel 83/02/01. 1p
17034:276. 24X Fiche: 50-361, 83/02/01, 8302070605

J. Insurance & indemnity information

8302180329 Forwards Endorsements 91-93 & 96 to NELIA Policies NF-146 &
NB-282, respectively. Endorsements 80-82 to MAELU Policy
NF-38. Endorsement 8 to NELIA Binders EB-10 & EB-81
& MAELU Binder XB-81 & Certificates N-87 & M-87
RODD, J. Southern California Edison Co. 83/02/14. DINIY, I.
Antitrust & Economic Analysis Branch (Utility Finance). 38pp
17213:266. 24X Fiche: 50-206, 83/02/14, 8302180329

P. Operating license stage documents & correspondence

8302020353 FOIA request for Sandia Natl Lab rept detailing potential
results of serious accidents at nuclear power plants & info
re existing evacuation plans & other contingency safety
measures at facilities.
POLLOCK, D. Affiliation Unknown 82/11/08. Division of Rules and
Records 2pp 16996:024. 24X Fiche: 50-362, 82/11/08, 8302020353.

8302020359 Responds to FOIA request for Sandia Natl Lab rept detailing
results of accidents at nuclear power plants & info re
evacuation plans at facilities. Forwards Documents 2 & 3
listed in App A App B documents available in LPDR
FELTON, J. M. Division of Rules and Records 82/12/06. POLLOCK, D.
Affiliation Unknown 3pp 16996:026. 24X Fiche: 50-362, 82/12/06,
8302020359

8302010546 Forwards revised listing of EBF actuation sys (EBFAS)
subgroup relays & EBFAS relays which changed categories, per
821220 Tech Spec change request, affecting subgroup relay
component assignments
BASKIN, K. P. Southern California Edison Co. 83/01/28. KNIGHTON, O. W.
Licensing Branch 3. 26pp. 16982:358. 24X Fiche: 50-361, 83/01/28,
8302010546.

8302020030 Forwards Affidavit of Bvc certifying svc of Amend
Application 2 to License NPF-15 on 830125.
MEDFORD, M. D. Southern California Edison Co. 83/01/31.
KNIGHTON, O. W. Licensing Branch 3. 4pp. 16994:358. 24X
Fiche: 50-362, 83/01/31, 8302020030

8302020142 Forwards 38 oversize P&IDs, in response to NRC request
for info to be used in performance of limited scope PRA on
facility. Aperture cards are available in PDR.
KRIEGER, R. W. Southern California Edison Co. 83/01/31
PAULSON, W. A., MCKENNA, E. NRC - No Detailed Affiliation Given. 1p.
16994:356. 24X Fiche: 50-206, 83/01/31, 8302020142.

8302170561 Summary of 821103 meeting w/util re readiness of facility
for full power operation
RODD, H. Licensing Branch 3 83/02/08. Licensing Branch 3. 12pp.
17197:162. 24X Fiche: 50-362, 83/02/03, 8302170561.

8302080164 Advises of error in Amends 13 & 2 to Licenses NPF-10 &
NPF-15, respectively. Amends issued on 821230, incorrectly
changed Tech Specs re EBF response times. Util will continue
to operate on basis that amends did not change times
BASKIN, K. P. Southern California Edison Co. 83/02/04. KNIGHTON, O. W.
Licensing Branch 3. 2pp. 17057:223. 24X Fiche: 50-361, 83/02/04,
8302080164.

--8302080168 Proposed corrected pages to Tech Spec Table 3.3-5 re EBF
response times.
* Southern California Edison Co. 83/02/04. 10pp 17057:225.
24X Fiche: 50-361, 83/02/04, 8302080164

8302170552 Summary of 830131 meeting w/util in Bethesda, MD re control
room pressurization testing. Util agreed to conduct full
control room test within next 2 to 3 wks.
RODD, H. Licensing Branch 3. 83/02/04. Licensing Branch 3. 5pp
17197:142. 24X Fiche: 50-361, 83/02/04, 8302170552.

8302090010 Submits addl info requested in 830111 ltr re duration between occurrence of double ended guillotine break in high energy line feeding steam driven auxiliary feedwater pump & actuation of feedwater sys
BASKIN, K.P. Southern California Edison Co. 83/02/07. KNIGHTON, O.W. Licensing Branch 3. 1p. 17070 272. 24X Fiche. 50-361, 83/02/07, 8302090010

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D.O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 11pp. 17290 247. 24X Fiche. 50-000, 83/02/08, 8302080295.

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Svc list encl.
EISENHUT, D.O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 9pp. 17234, 234. 24X Fiche. 50-000, 83/02/08, 8302080304

8302090072 Generic Ltr 83-108 to all licensees w/C-E designed NSSB re resolution of TMI Action Item II K.3.5, "Automatic Trip of Reactor Coolant Pumps." Svc list encl.
EISENHUT, D.O. Division of Licensing. 83/02/08. Consumers Power Co. 32pp. 17290, 185. 24X Fiche. 50-000, 83/02/08, 8302090072

8302100280 Discusses fault identified in turbine high pressure governor valves 2 & 4. Valve closure satisfied Tech Spec 3.3.4 Util will implement gags for affected valves by 830210 W/one oversize drawing. Aperture card is in PDR
BASKIN, K.P. Southern California Edison Co. 83/02/08. KNIGHTON, O.W. Licensing Branch 3. 3pp. 17110 077. 24X Fiche. 50-361, 83/02/08, 8302100280

8302170538 Summary of 821227 & 830121 meetings w/util & C-E re util actions in response to spurious EBF actuation signal & recirculating actuation signal that occurred on 821217.
RODD, H. Licensing Branch 3. 83/02/08. Licensing Branch 3. 5pp. 17197 157. 24X Fiche. 50-361, 83/02/08, 8302170538.

8302180503 Summary of 830120 meeting w/util & Bechtel re auxiliary feedwater pump motor bearing qualification
RODD, H. Licensing Branch 3. 83/02/08. Licensing Branch 3. 26pp. 17221 283. 24X Fiche. 50-361, 83/02/08, 8302180503

8302140079 Submits update of info in util 821221 ltr re operability of post-accident sampling sys. per License Condition 2.C. (19) Operating procedures & hands-on training will be completed by 830301.
BASKIN, K.P. Southern California Edison Co. 83/02/09. KNIGHTON, O.W. Licensing Branch 3. 2pp. 17141 098. 24X Fiche. 50-361, 83/02/09, 8302140079.

8302150053 Forwards C-E rept supporting proposed change to Tech Specs re emergency core cooling. Document describes methodology, assumptions & results of C-E analysis to derive HPBI pump head requirement for 83% power.
BASKIN, K.P. Southern California Edison Co. 83/02/10. KNIGHTON, O.W. Licensing Branch 3. 19pp. 17147, 029. 24X Fiche. 50-361, 83/02/10, 8302150053

8302220118 Notification of contract execution. Mod 3 to "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." Contractor: St. Louis Univ.
LITTLE, M. Administrative Contracts Branch. FIN B-6598. 83/02/10. VOLLMER, R.H. Division of Engineering. 1p. 17234 216. 24X Fiche. 50-362, 83/02/10, 8302220118.

--8302220125 Mod 3, extending period of performance by 1 yr & adding requirement for monthly business ltr rept to "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station."
HERRMANN, R. St. Louis Univ. FIN B-6598. 83/02/10. 3pp. 17234 217. 24X Fiche. 50-362, 83/02/10, 8302220125

8302160249 Forwards proposed Tech Spec changes, increasing limit on ventilation unit flow for control room emergency air cleanup sys. Application for OL amends will be submitted during wk of 830228.
BASKIN, K.P. Southern California Edison Co. 83/02/11. KNIGHTON, O.W. Licensing Branch 3. 3pp. 17170 059. 24X Fiche. 50-361, 83/02/11, 8302160249.

--8302160256 Proposed Tech Spec changes, increasing limit on ventilation unit flow for control room emergency air cleanup sys
* Southern California Edison Co. 83/02/11. 17pp. 17170 062. 24X Fiche. 50-361, 83/02/11, 8302160249.

8302250496 Informs of conclusions reached re auxiliary feedwater pump motor bearing qualification & CPC software error. Change implementation schedules requested by 830218.
KNIGHTON, O. Licensing Branch 3. 83/02/14. DIETCH, R. Southern California Edison Co. COTTON, O.D., BERNATH, L. San Diego Gas & Electric Co. 6pp. 17303 139. 24X Fiche. 50-361, 83/02/14, 8302250496.

8302180291 Supple 830211 proposed change to Tech Spec 3/4.7.5 re control room emergency air cleanup sys. Operating procedures to be reviewed &/or revised by 830313 to ensure door closure following toxic gas isolation signal
BASKIN, K.P. Southern California Edison Co. 83/02/16. KNIGHTON, O.W. Licensing Branch 3. 2pp. 17211 247. 24X Fiche. 50-361, 83/02/16, 8302180291

8302220334 Forwards Application 18 for amend to License NPF-10 & Application 4 for amend to License NPF-15, revising Tech Specs to allow mods to mitigate consequences of simultaneous occurrence of safety injection actuation signal.
DIETCH, R. Southern California Edison Co. 83/02/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17232 037. 24X Fiche. 50-361, 83/02/17, 8302220334.

--8302220337 Applications 18 & 4 for amend to Licenses NPF-10 & NPF-15, respectively, revising Tech Specs to allow mods to mitigate consequences of simultaneous occurrence of safety injection & recirculation actuation signals
DIETCH, R. Southern California Edison Co. COTTON, O.D. San Diego Gas & Electric Co. HOYT, O.W. Anaheim, CA. 83/02/17. 6pp. 17232 039. 24X Fiche. 50-361, 83/02/17, 8302220334.

--8302220339 Proposed Tech Specs allowing mods to mitigate consequences of simultaneous occurrence of safety injection actuation signal & recirculation actuation signal.
DIETCH, R. Southern California Edison Co. COTTON, O.D. San Diego Gas & Electric Co. HOYT, O.W. Anaheim, CA. 83/02/17. 16pp. 17232 045. 24X Fiche. 50-361, 83/02/17, 8302220334.

8302280280 Forwards applications for amend to Licenses NPF-10 & NPF-15, revising Tech Spec 6.8.4.d to allow addl improvements to post-accident sampling sys.
BASKIN, K.P. Southern California Edison Co. 83/02/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17313 045. 24X Fiche. 50-361, 83/02/24, 8302280280.

--8302280284 Applications for amend to Licenses NPF-10 & NPF-15, revising Tech Spec 6.8.4.d to allow addl improvements to post-accident sampling sys.
DIETCH, R. Southern California Edison Co. COTTON, O.D. San Diego Gas & Electric Co. HOYT, O.W. Anaheim, CA. 83/02/24. 13pp. 17313 047. 24X Fiche. 50-361, 83/02/24, 8302280280.

--8302280288 Proposed Tech Spec 6.8.4.d re post-accident sampling sys changes
* Southern California Edison Co. 83/02/24. 3pp. 17313 060. 24X Fiche. 50-361, 83/02/24, 8302280280.

0. Inspection reports, IE Bulletins & correspondence

8302070278 Addl response to FOIA request for documents re EE Kent allegations concerning facilities.
FELTON, J.M. Division of Rules and Records. 82/12/13. CARPENTER, T. Orange County Alliance for Survival. 1p. 17060 001. 24X Fiche. 50-362, 82/12/13, 8302070278.

--8212010524 Discusses insp efforts re const & preoperational testing. No items discovered which would preclude issuance of OL at 5% of full power. Allegations of deficient welding & welding code requirements unsubstantiated
ENOKKEN, R.H. Region 3, Office of Director. 82/11/12. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 7pp. 17060 319. 24X Fiche. 50-362, 82/12/13, 8302070278.

--8302070296 Confirms discussions re request for technical assistance concerning allegations by EE Kent. EE Kent statement encl.
CREWB, J.L. Region 3, Office of Director. 82/10/29. EISENHUT, D.O. Division of Licensing. 1pp. 17060 249. 24X Fiche. 50-362, 82/12/13, 8302070278.

8302040499 FOIA request for documents re special insp rept.
GARDE, B. Government Accountability Project. 82/12/14. Office of Administration. 2pp. 17042 262. 24X Fiche. 50-362, 82/12/14, 8302040499.

8302150366 Forwards IE Insp Repts 50-206/82-34, 50-361/82-44 & 50-362/82-28 on 821116-1216. No noncompliance noted.
BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs. 83/01/12. PAPAY, L.T. Southern California Edison Co. 2pp. 17157 210. 24X Fiche. 50-206, 83/01/12, 8302150366.

DOCKETED ITEMS

--B302150373 IE Insp Repts 50-206/82-34, 50-361/82-44 & 50-362/82-28 on 821116-1217 No noncompliance noted Major areas inspected GA program & station organization & administration, qualification of personnel & caliber of instrumentation STEWART, J P, KIRSCH, D F Division of Resident Reactor Project & Engineering Programs 83/01/10 9pp 17157 212 24X Fiche 50-206, 83/01/12, 8302150366

B302160457 Addl response to FOIA request for documents re EE Kent allegations concerning facilities Forwards documents listed in Apps A & B Documents partially withheld (ref FOIA Exemptions 5, 6 & 7). Tapes available in PDR FELTON, J M Division of Rules and Records 83/01/12 CARPENTER, T Orange County Alliance for Survival App 17175 194 24X Fiche 50-362, 83/01/12, 8302160457

--B302160460 Submits notes taken at Region V 821014 mgt meeting re EE Kent allegations Considered actions listed Reporters raised questions re allegations Related info encl SHACKLETON, O C Region 5, Office of Director 82/10/14 Region 5, Office of Director 23pp 17175 199 24X Fiche 50-362, 83/01/12, 8302160457

B302040505 Partial response to FOIA request for documents re special insp rept Documents listed on encl app available in PDR in folders "FOIA-82-528 Carpenter" Search for addl documents in progress FELTON, J M Division of Rules and Records 83/01/13 GARDE, D Government Accountability Project 3pp 17042 259 24X Fiche 50-362, 83/01/13, 8302040505

B212060358 IE Info Notice 83-01, "Ray Miller, Inc" Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

B212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H28C & H38C Gearheads," Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments," Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361.

B302230255 Forwards IE Insp Repts 50-361/82-43 & 50-362/82-35 on 821222-830119 & notice of violation BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/01/28, PAPAY, L T Southern California Edison Co 2pp 17244 339 24X Fiche 50-361, 83/01/28, 8302230255

B302230263 IE Insp Repts 50-361/82-43 & 50-362/82-35 on 821222-830119 Noncompliance noted: failure to properly label container of radioactive matl CHAFFEE, A, KIRSCH, D Division of Resident Reactor Project & Engineering Programs 83/01/27 6pp 17244 342 24X Fiche 50-361, 83/01/28, 8302230255

B302230365 Forwards IE Insp Repts 50-206/83-03, 50-361/83-04 & 50-362/83-05 on 830117-21 & notice of violation, BOOK, H E Division of Radiological Safety & Safeguards Program 83/02/04, PAPAY, L T Southern California Edison Co 2pp 17246 292 24X Fiche 50-206, 83/02/04, 8302230365.

--B302230378 IE Insp Repts 50-206/83-03, 50-361/83-04 & 50-362/83-05 on 830117-21, Noncompliance noted, failure to submit 30-day special rept & one unresolved item involving meeting acceptance criteria of Reg Guide 4.13, YUHAS, Q P, WENSLAWSKI, F. A., BOOK, H E Division of Radiological Safety & Safeguards Program 83/02/03 9pp 17246 295 24X Fiche 50-206, 83/02/04, 8302230365

B302230396 Forwards IE Insp Repts 50-361/83-02 & 50-362/83-02 on 830110-14 & notice of violation BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/02/04, PAPAY, L T Southern California Edison Co 2pp 17247 269 24X Fiche 50-361, 83/02/04, 8302230396

--B302230406 IE Insp Repts 50-361/83-02 & 50-362/83-02 on 830110-14 Noncompliance noted, failure to maintain acceptable levels of housekeeping for Unit 2 ECKHARDT, J H, KIRSCH, D F Division of Resident Reactor Project & Engineering Programs 83/02/04 10pp 17247 273 24X Fiche 50-361, 83/02/04, 8302230396

B302230395 Forwards IE Insp Repts 50-361/82-45 & 50-362/82-37 on 821225-830123, No noncompliance noted BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/02/09, PAPAY, L T Southern California Edison Co 2pp 17248 074 24X Fiche 50-361, 83/02/09, 8302230395.

--B302230404 IE Insp Repts 50-361/82-45 & 50-362/82-37 on 821225-830123 No noncompliance noted Major areas inspected LER review & independent insp effort PATER, J, MENDONCA, M M, KIRSCH, D F Division of Resident Reactor Project & Engineering Programs 83/02/09 9pp 17248 076 24X Fiche 50-361, 83/02/09, 8302230395

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302" Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

B212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested DUVALL, D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.) 82/12/10 STELLD, V Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

B302010678 Forwards LER 82-008/03L-O Detailed event analysis submitted RAY, H B Southern California Edison Co 83/01/14 ENGELKEN, R H Region 5, Office of Director 2pp 16979 167 24X Fiche 50-362, 83/01/14, 8302010678

--B302010681 LER 82-008/03L-O on 821215, while in Mode 5, RCS chloride level exceeded limit of 0.15 ppm Caused by displacement of chloride from purification ion exchange resin to RCS Resin replaced RAY, H B Southern California Edison Co 83/01/14, Region 5, Office of Director 1p 16979 169 24X Fiche 50-362, 83/01/14, 8302010678

B302010471 PNS-V-83-003 on 830126, security guard accidentally discharged newly issued revolver & caused superficial wounds to right leg Guard treated & held overnight at hosp for observation MORTENSEN, W P, SCHUSTER, M D Region 5, Office of Director 83/01/27 1p 16981 302 24X Fiche 50-361, 83/01/27, 8302010471.

B302150147 Forwards LER 82-011/03L-O Detailed event analysis submitted RAY, H B Southern California Edison Co 83/01/28 ENGELKEN, R H Region 5, Office of Director 2pp 17147 213 24X Fiche 50-362, 83/01/28, 8302150147

--B302150155 LER 82-011/03L-O on 821217, during Mode 5, Zone 4i (cable spreading room) fire detectors removed from svc to permit repair of cables Caused by minor cable damage during const activities Cable replaced RAY, H B Southern California Edison Co 83/01/28 Region 5, Office of Director 1p 17147 215 24X Fiche 50-362, 83/01/28, 8302150147

B302150217 Forwards LER 82-010/03L-O Detailed event analysis submitted RAY, H B Southern California Edison Co 83/01/31 ENGELKEN, R H Region 5, Office of Director 2pp 17149 265 24X Fiche 50-362, 83/01/31, 8302150217

--B302150229 LER 82-010/03L-O on 821115, during surveillance testing, fire detection instrumentation found inoperable. Testing revealed need to replace/repair parts of sys Replacements/repairs expected to be complete in 90 days. RAY, H B Southern California Edison Co 83/01/31 Region 5, Office of Director 1p 17149 267 24X Fiche 50-362, 83/01/31, 8302150217

B302070273 Forwards responses to NRC 830114 request clarified by 830123 meeting re ESP activation sys event on 821217 Response to 14 addl questions per NRC 830123 telcon also encl BASKIN, K P Southern California Edison Co 83/02/03 KNIGHTON, O W Licensing Branch 3 123p 17031 151 24X Fiche 50-361, 83/02/03, 8302070273.

DOCKETED ITEMS

247

T Hearing transcripts on non-antitrust matters

8302070278 Addl response to FOIA request for documents re EE Kent allegations concerning facilities
FELTON, J. M. Division of Rules and Records 82/12/13 CARPENTER, T
Grange County Alliance for Survival 1p 17060 001 24X
Fiche 50-361, 82/12/13, 8302070278

--8302070285 Draft transcript of EE Kent taped 821015 interview in Dana Point, CA of allegations re weld const quality at facilities
Pp 1-257 Related info encl
SHACKLETON, D. C. Director's Office, Office of Inspection and Enforcement 82/10/15 243pp 17060 006 24X
Fiche 50-362, 82/12/13, 8302070278

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc. 14pp, 17347 177, 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8302030342 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-363/80-02
MARTIN, T. T. Division of Engineering & Technical Programs 83/01/28
CARROLL, J. T. Jersey Central Power & Light Co 1p, 17006 106 24X
Fiche 50-363, 83/01/28, 8302030342

--8302030365 Responds to NRC ltr re violations noted in IE Insp Rept 50-363/80-02, corrective actions, soil erosion control project at barge unloading facility completed
CLARK, P. R. General Public Utilities - GPU Service Corp 83/01/20
HAYNES, R. Region 1, Office of Director 1p 17006 107 24X
Fiche 50-363, 83/01/28, 8302030342

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
BACCHI, O. Equipment Qualification Branch 83/02/02 NGONAN, V. B.
Equipment Qualification Branch, 3pp, 17205 188, 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170034 Trip rept of 800707-10 visit to facility to review qualification methods, procedures & results for 34 Seismic Category I mechanical & electrical equipment & supporting structures
HOFMAYER, C. H. Equipment Qualification Branch 80/10/01
ROSTOCZY, Z. R. Equipment Qualification Branch 20pp 17205 257, 24X
Fiche 50-000, 83/02/02, 8302170011

F Security, medical, emergency & fire protection plans

8302010016 Releases public version of on-call schedule for 1983
FELTON, J. M. Division of Rules and Records 83/01/26, Document
Management Branch, 1p 16995 003, 24X Fiche: 50-348, 83/01/26, 8302010016

--8302010021 Forwards public version of on-call schedule for 1983, per Administrative Procedure FNP-O-AP-4, "Control of Plant & Document Records."
HUDEBETH, J. B. Alabama Power Co 82/12/30 Office of Nuclear
Reactor Regulation, Director, 3pp, 16995 004, 24X
Fiche 50-348, 83/01/26, 8302010016

8302010026 Releases public version of on-call schedule for 1983
FELTON, J. M. Division of Rules and Records 83/01/26, Document
Management Branch, 1p 16995 095, 24X Fiche: 50-348, 83/01/26, 8302010026

--8302010029 Forwards public version of on-call schedule for 1983, per Administrative Procedure FNP-O-AP-4, "Control of Plant Documents & Records."
HUDEBETH, J. B. Alabama Power Co 83/01/05 Office of Nuclear
Reactor Regulation, Director, 3pp 16995 096, 24X
Fiche 50-348, 83/01/26, 8302010026

8302030059 Releases public version of rev to site emergency plan, radiation emergency medical plan & State of AL radiological emergency response plan
FELTON, J. M. Division of Rules and Records, 83/01/27 Document
Management Branch 1p, 17024 001 24X Fiche: 50-348, 83/01/27, 8302030059

--8302030063 Forwards public version of rev to site emergency plan, radiation emergency medical plan & State of AL radiological emergency response plan
HUDEBETH, J. B. Alabama Power Co, 82/12/15 Office of Nuclear
Reactor Regulation, Director, 1p 17024 002 24X
Fiche 50-348, 83/01/27, 8302030059

--8302030068 Public version of rev to site emergency plan, radiation emergency medical plan & State of AL radiological emergency response plan
MC DONALD, R. P., HAIRSTON, W. O. Alabama Power Co 82/12/06 826pp, 17024 003, 24X Fiche: 50-348, 83/01/27, 8302030059

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D. O. Division of Licensing, 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp, 17221 226 24X
Fiche: 50-000, 83/02/01, 8301210340

8302090462 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records, 83/02/03 Document
Management Branch 1p 17132 107 24X Fiche: 50-348, 83/02/03, 8302090462

--8302090467 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 00-EIP-117, "Emergency Operations Facility Administrative Support"
CLAYTON, F. L. Alabama Power Co, 83/01/24, VARQA, S. A. Assistant
Director for Operating Reactors, 1p, 17132 108 24X
Fiche: 50-348, 83/02/03, 8302090462

--8302090471 Public version of Rev 1 to Emergency Plan Implementing Procedure 00-EIP-117, "Emergency Operations Facility Administrative Support."
MC DONALD, J. W. Alabama Power Co, 83/01/25 42pp, 17132 109, 24X
Fiche: 50-348, 83/02/03, 8302090462

H Antitrust correspondence

8302170265 Forwards AL Electric Cooperative response to AL Power Co motion for stay of mandate Certificate of Svc encl, Related correspondence.
MACQUINEAS, D. B. Volpe, Boskey & Lyons, MACQUINEAS, D. B. Alabama
Electric Cooperative, Inc. 83/02/14 ZOLLER, M. E. Unknown
Affiliation, 4pp, 17178 224 24X Fiche: 50-348, 83/02/14, 8302170265

F Operating license stage documents & correspondence

8302030344 Advises that util will submit results of review of available reactor vessel level sys (THI Action Item II, F. 2) per Generic Ltr 82-28 schedule.
CLAYTON, F. L. Alabama Power Co, 83/02/01, VARQA, S. A. Office of
Nuclear Reactor Regulation, Director 1p 17005 359, 24X
Fiche: 50-348, 83/02/01, 8302030344

8302090329 Forwards list of all licensing items requiring NRC approval in 1983 Status will be updated monthly to reflect addl submittals requiring NRC approval.
CLAYTON, F. L. Alabama Power Co, 83/02/01, VARQA, S. A. Office of
Nuclear Reactor Regulation, Director, 6pp, 17070 336, 24X
Fiche: 50-348, 83/02/01, 8302090329

8302100245 Supplemental request for administrative Tech Spec changes to Licenses NPF-2 & NPF-B, changes will allow for better scheduling of certain surveillance testing.
CLAYTON, F. L. Alabama Power Co 83/02/01, VARQA, S. A. Office of
Nuclear Reactor Regulation, Director, 9pp, 17114 065, 24X
Fiche: 50-348, 83/02/01, 8302100245

--8302100248 Proposed administrative Tech Spec changes which will allow for better scheduling of certain surveillance testing,
Alabama Power Co, 83/02/01 29pp 17114 074, 24X
Fiche: 50-348, 83/02/01, 8302100245

8302100175 Forwards SER for environ qualification of safety-related electrical equipment, Plans for qualification or replacement of unqualified equipment & schedule for corrective actions should be submitted within 90 days.
VARQA, S. A. Operating Reactors Branch 1 83/02/04, CLAYTON, F. L.
Alabama Power Co, 3pp, 17132 151 24X Fiche: 50-364, 83/02/04, 8302100175

DOCKETED ITEMS

--8302100179 SER re environ qualification of safety-related electrical equipment items requiring until attention identified.
* Equipment Qualification Branch 83/02/04. 5pp. 17132 154
24X Fiche: 50-364, 83/02/04, 8302100179.

--8301200219 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), JM Farley Nuclear Plant, Unit 2." final technical evaluation rept
TOMAN, O. J. Franklin Institute/Franklin Research Center
NRC-03-79-118. TER-CB297-318. 83/01/17. BHEMANSKI, P. NRC - No Detailed Affiliation Given. 37pp. 17132, 159 24X
Fiche: 50-364, 83/02/04, 8302100179.

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
EISENHUT, D. O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 11pp. 17290, 247. 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee. Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 7pp. 17234, 234. 24X
Fiche: 50-000, 83/02/08, 8302080304

8302090085 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSR (except Yankee Atomic Electric Co) re resolution of THE Action Item II H.3.5: "Automatic Trip of Reactor Coolant Pumps." Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/02/08. Southern California Edison Co. 31pp. 17290, 262 24X Fiche: 50-000, 83/02/08, 8302090085.

8302180247 Responds to 830103 request for addl info re boron concentration reduction in boron injection tank per util 821230 ltr. Existing emergency operating procedure for small break LOCA not impacted by proposed change in concentration
CLAYTON, F. L. Alabama Power Co. 83/02/11. VARQA, S. A. Division of Licensing. 3pp. 17211 235. 24X Fiche: 50-364, 83/02/11, 8302180247.

8302230197 Advises that util will implement mode to provide two upper head thermocouple inputs to subcooling monitor during next outage of sufficient duration but no later than second refueling outage, per NUREG-0737, item II.F.2.
CLAYTON, F. L. Alabama Power Co. 83/02/15. VARQA, S. A. Office of Nuclear Reactor Regulation, Director. 2pp. 17245, 041. 24X
Fiche: 50-364, 83/02/15, 8302230197

8302230387 Informs that portions of Franklin Research Ctr technical evaluation rept re environ qualification of safety-related equipment are proprietary.
CLAYTON, F. L. Alabama Power Co. 83/02/16. VARQA, S. A. Office of Nuclear Reactor Regulation, Director. 1p 17248, 154. 24X
Fiche 50-364, 83/02/16, 8302230387

G. Inspection reports, IE Bulletins & correspondence

8302150009 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Fasteners on closure connections routinely opened for component insp/maint during refueling outage. Results listed.
CLAYTON, F. L. Alabama Power Co. 83/01/17. O'REILLY, J. P. Region 2, Office of Director. 3pp. 17146, 008. 24X Fiche: 50-364, 83/01/17, 8302150009.

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/26. Consolidated Edison Co. of New York, Inc. 11pp. 17023, 160. 24X Fiche: 50-000, 83/01/26, 8212060358.

8212060360 IE Info Notice 83-02, "Limit torque H0BC, H1BC, H2BC & H3BC Gearheads." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28. Consolidated Edison Co. of New York, Inc. 10pp. 17144, 001. 24X Fiche: 50-000, 83/01/28, 8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28. Consolidated Edison Co. of New York, Inc. 11pp. 17074, 095. 24X Fiche: 50-000, 83/01/28, 8212060361

8302040358 EN-83-006; on 830202, notice of violation & proposed imposition of civil penalties to be issued. Action based on violation re inoperability of containment spray sys.
BARBER, O., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/01/28. 1p. 17019, 031. 24X Fiche: 50-364, 83/01/28, 8302040358.

8302080012 Forwards summary of addl requests for relief from certain inservice insp requirements of ASME Code, Section XI, Articles IWA-3000, IWB-3000, IWC-3000, IWD-3000, IWE-2000 & IWF-2000
Relief requested by 830901
CLAYTON, F. L. Alabama Power Co. 83/01/28. VARQA, S. A. Office of Nuclear Reactor Regulation, Director. 30pp. 17058 263 24X
Fiche 50-364, 83/01/28, 8302080012

--8302080017 Responds to BALP Repts 50-348/B2-28 & 50-364/B2-28 re lack of physical exams for fire brigade members & substandard welding & cutting fire prevention procedures. Present use of flame permits & exams adequate
CLAYTON, F. L. Alabama Power Co. 83/02/02. O'REILLY, J. P. Region 2, Office of Director. 6pp. 17058, 293 24X Fiche: 50-364, 83/01/28, 8302080012

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/18. Consolidated Edison Co. of New York, Inc. 11pp. 17347, 191. 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24. Consolidated Edison Co. of New York, Inc. 11pp. 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24. Consolidated Edison Co. of New York, Inc. 11pp. 17361 148. 24X Fiche: 50-000, 83/02/24, 8212060366

R. Periodic operating reports & related correspondence

8302220408 Forwards monthly operating rept for Jan 1983
CLAYTON, F. L. Alabama Power Co. 83/02/14. Management Information Branch. 1p. 17232, 136 24X Fiche: 50-364, 83/02/14, 8302220408.

--8302220413 Monthly operating rept for Jan 1983
HAIRSTON, W. O. Alabama Power Co. 83/02/03. 4pp. 17232, 137 24X
Fiche: 50-364, 83/02/14, 8302220408

S. Reportable occurrences, LERs & related correspondence

8302010516 Notifies of typographical error in 830106 ltr forwarding LER 81-010/03X-1 ltr mistakenly referred to LER 82-043/01X-1
CLAYTON, F. L. Alabama Power Co. 83/01/24. Region 2, Office of Director. 1p. 16977 298 24X Fiche 50-364, 83/01/24, 8302010516

8302230708 Forwards LER 83-003/03L-0
CLAYTON, F. L. Alabama Power Co. 83/02/16. Region 2, Office of Director. 1p. 17248, 357. 24X Fiche: 50-364, 83/02/16, 8302230708

--8302230711 LER 83-003/03L-0: on 830117, during performance of RHR valve inservice test, motor operated valve 8888B failed to reopen after being stroked closed. Caused by loose contacts in valve operator limiting switch. Contacts replaced
HAIRSTON, W. O. Alabama Power Co. 83/02/16. Region 2, Office of Director. 1p. 17248, 358. 24X Fiche: 50-364, 83/02/16, 8302230708

8302280211 RO, on 830215, both trains of control room filtration unit & A train penetration room filtration sys failed to meet Tech Spec criteria for carbon efficiency. Caused by misinterpretation of Reg Guide 1.52
HAIRSTON, W. O. Alabama Power Co. 83/02/16. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17304, 362. 24X Fiche: 50-364, 83/02/16, 8302280211.

8302280038 Forwards LER 83-002/03L-0
CLAYTON, F. L. Alabama Power Co. 83/02/17. Region 2, Office of Director. 1p. 17307, 199. 24X Fiche: 50-364, 83/02/17, 8302280038

--8302280042 LER 83-002/03L-0: on 830121, while attempting to increase accumulator nitrogen pressure, containment isolation valve failed to fully open. Caused by valve binding between cage & plug assembly. Cage & plug replaced
HAIRSTON, W. O. Alabama Power Co. 83/02/17. Region 2, Office of Director. 1p. 17307, 200 24X Fiche: 50-364, 83/02/17, 8302280038

DOCKETED ITEMS

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D. O. Division of Licensing 83/01/31. Consolidated
Edison Co. of New York, Inc 14pp. 17347 177 24X
Fiche: 50-000, 83/01/31, 8301310203

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8302150221 Forwards IE Insp Rpts 50-321/82-43 & 50-366/82-41 on 82120-1219. No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/01/10.
KELLY, R. J. Georgia Power Co. 2pp 17150:035. 24X
Fiche: 50-321, 83/01/10, 8302150221

--8302150234 IE Insp Rpts 50-321/82-43 & 50-366/82-41 on 82120-1219. No noncompliance noted. Major areas inspected: Tech Spec compliance, operator performance, overall plant operations, QA practices & station & site security procedures.
HOLMES-RAY, P. Division of Project & Resident Programs 83/01/07
4pp. 17150 037 24X Fiche: 50-321, 83/01/10, 8302150221.

8302150716 Forwards IE Insp Rpts 50-321/82-44 & 50-366/82-39 on 821206-10. No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/01/10
KELLY, R. J. Georgia Power Co. 2pp 17153:030 24X
Fiche: 50-321, 83/01/10, 8302150716

--8302150721 IE Insp Rpts 50-321/82-44 & 50-366/82-39 on 821206-10. No noncompliance noted. Major area inspected: radiological emergency exercise.
ANDREWS, D. L. Division of Emergency Preparedness & Materials Safety 83/01/07. 7pp 17153 032. 24X Fiche: 50-321, 83/01/10, 8302150716

8302150427 Ack receipt of 830107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-321/82-39 & 50-366/82-37
DANCE, H. C. Division of Project & Resident Programs 83/01/19
KELLY, R. J. Georgia Power Co. 1p 17157:038 24X
Fiche: 50-321, 83/01/19, 8302150427

--8302150488 IE Insp Rpts 50-321/82-39 & 50-366/82-37 on 821028-1120 Noncompliance noted: out of svc RHR svc water strainer outlet valve 2E11-F116B found shut but unlocked & inlet valve 2E11-F117B found locked open
HOLMES-RAY, P. Division of Project & Resident Programs. 82/12/08.
4pp 17157 043 24X Fiche: 50-321, 83/01/19, 8302150427

8302150611 Ack receipt of 821130 & 1230 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-321/82-32 & 50-366/82-30
DANCE, H. C. Division of Project & Resident Programs 83/01/19
KELLY, R. J. Georgia Power Co. 1p 17154:146. 24X
Fiche: 50-321, 83/01/19, 8302150611

--8302150659 IE Insp Rpts 50-321/82-32 & 50-366/82-30 on 820828-0928. Noncompliance noted: failure to follow HPCI surveillance procedure, properly notify NRC & follow health physics procedure
ROGERS, R. F. Division of Project & Resident Programs. 82/10/25
4pp 17154:157. 24X Fiche: 50-321, 83/01/19, 8302150611.

8302020336 Releases public version of revised Emergency Plan Implementing Procedures.
FELTON, J. M. Division of Rules and Records. 83/01/28. Document Management Branch. 1p. 16997:040. 24X Fiche: 50-321, 83/01/28, 8302020336.

--8302020342 Forwards public version of revised Emergency Plan Implementing Procedures, including Procedures HNP-8134 re whole body counter sys, HNP-4530 re alert - shift supervisor & HNP-4730 re general emergency - shift supervisor
NIX, H. C. Georgia Power Co. 83/01/18 Office of Nuclear Reactor Regulation, Director. 1p. 16997:041. 24X Fiche: 50-321, 83/01/28, 8302020336.

--8302020346 Public version of revised Emergency Plan Implementing Procedures, including Procedures HNP-8134 re whole body counter sys, HNP-4530 re alert - shift supervisor & HNP-4730 re general emergency - shift supervisor.
ROGERS, R. F. NIX, H. Georgia Power Co. 83/01/06. 108pp. 16997:042. 24X Fiche: 50-321, 83/01/28, 8302020336.

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221:226 24X
Fiche: 50-000, 83/02/01, 8301210340.

8302180275 Requests confirmation of current revs to security plan, using encl list of effective pages as guide. Receipt form encl
QUICHA, L. T. Georgia Power Co. 83/02/11. STOLZ, J. Operating Reactors Branch 4 3pp 17212 054 24X Fiche: 50-321, 83/02/11, 8302180275.

8302180123 Requests meeting on or after 830329 w/NRR to appeal for reconsideration of NRC proposed denial of App R exemption request Addl info forthcoming to clarify 820701 submittal.
QUICHA, L. T. Georgia Power Co. 83/02/14. STOLZ, J. F. Operating Reactors Branch 4 2pp. 17216 182 24X Fiche: 50-321, 83/02/14, 8302180123.

P. Operating license stage documents & correspondence

8302040250 Documents verbal commitment to make simulators available for control room task analysis.
BECKHAM, J. T. Georgia Power Co. 83/01/20. STOLZ, J. Operating Reactors Branch 4. 1p. 17020:047. 24X Fiche: 50-000, 83/01/20, 8302040250.

8302020482 Notification of 830223-24 meetings w/util, E&O & RCBI in Atlanta, GA to discuss NRC questions re review of licensee radiological effluent Tech Spec submittal
RIVENBARK, O. Operating Reactors Branch 4. 83/01/31. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 16999:267. 24X
Fiche: 50-321, 83/01/31, 8302020482.

8302040282 Notification of 830202 meeting w/util in Bethesda, MD to discuss environ qualification program
RIVENBARK, O. W. Operating Reactors Branch 4. 83/01/31. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17042:298. 24X
Fiche: 50-321, 83/01/31, 8302040282.

8302080384 Notification of 830216 meeting w/util in Bethesda, MD to discuss average power range monitor rod block monitor Tech Spec program prepared to improve operational flexibility.
RIVENBARK, O. W. Operating Reactors Branch 4. 83/02/01. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17108:001. 24X
Fiche: 50-321, 83/02/01, 8302080384

8302030089 Generic Ltr 83-08 to all Mark I containment licensees re mod of vacuum breakers on Mark I containment. Requests commitment to submit results of plant-unique calculations which formed bases for mod. Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/02 General Public Utilities - OPU Service Corp. 5pp. 17074:086. 24X
Fiche: 50-000, 83/02/02, 8302030089.

8302100036 Forwards Amends 92 & 30 to Licenses DPR-57 & NPF-5, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs by modifying numerical values for reactor water levels & setpoints.
RIVENBARK, O. W. Operating Reactors Branch 4. 83/02/02 BECKHAM, J. T. Georgia Power Co. 2pp. 17135:138 24X Fiche: 50-321, 83/02/02, 8302100036.

--8302100051 Amends 92 & 30 to Licenses DPR-57 & NPF-5, respectively, revising Tech Specs to modify numerical values & setpoints for reactor water levels measured by shroud water level instruments.
STOLZ, J. F. Operating Reactors Branch 4. 83/02/02. 23pp. 17135:140. 24X Fiche: 50-321, 83/02/02, 8302100036.

--8302100060 Safety evaluation supporting Amends 92 & 30 to Licenses DPR-57 & NPF-5, respectively
* Office of Nuclear Reactor Regulation, Director. 83/02/02. 3pp. 17135:158. 24X Fiche: 50-321, 83/02/02, 8302100036.

--8302100076 Notice of issuance & availability of Amends 92 & 30 to Licenses DPR-57 & NPF-5, respectively.
STOLZ, J. F. Operating Reactors Branch 4. 83/02/02. 2pp 17135:161. 24X Fiche: 50-321, 83/02/02, 8302100036.

8302080020 Application to amend License NPF-5 adding Tech Specs for instruments installed in post-accident monitoring instrument table.
* Georgia Power Co. 83/02/03. STOLZ, J. Operating Reactors Branch 4. 4pp. 17058:193. 24X Fiche: 50-366, 83/02/03, 8302080020.

DOCKETED ITEMS

- 8302080025 Proposed Tech Specs re post-accident monitoring instrumentation
* Georgia Power Co. 83/02/03. 2pp 17038.179 24X
Fiche: 50-366/83/02/03, 8302080025
- 8302200006 Forwards safety evaluation of 800603 response to request for addl info re plant-specific applicability of generic analysis OE 1978 generic analysis bounds effects of loss of dc power source on LOCA peak cladding temp
BTOLZ, J. F. Operating Reactors Branch 4. 83/02/07. BECKHAM, J. T. Georgia Power Co. 2pp. 17233.308. 24X Fiche: 50-321/83/02/07, 8302200006.
- 8302220008 Safety evaluation re plant-specific applicability of 1978 OE generic analysis Analysis bounds effects of loss of dc power source on LOCA peak cladding temp
* NRC - No Detailed Affiliation Given. 83/02/07. 2pp 17233.310. 24X Fiche: 50-321/83/02/07, 8302220008
- 8302080293 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program. Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 11pp 17290.247 24X
Fiche: 50-000/83/02/08, 8302080293
- 8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBHR), applicants for DL & holders of CP re BER of "Emergency Procedures Guidelines, Rev 2." NEDO-24934, June 1982. Guidelines acceptable Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 9pp 17234.245 24X Fiche: 50-000/83/02/08, 8302080301
- 8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Bvc list encl.
EISENHUT, D. O. Division of Licensing. 83/02/08. Consolidated Edison Co. of New York, Inc. 9pp 17234.234 24X
Fiche: 50-000/83/02/08, 8302080304
- 8302170827 Forwards request for addl info re NUREG-0737, Item 11 K.3 2B, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response requested within 60 days of receipt
BTOLZ, J. F. Operating Reactors Branch 4. 83/02/08. BECKHAM, J. T. Georgia Power Co. 4pp 17197.113. 24X Fiche: 50-321/83/02/08, 8302170827
- 8302170530 Forwards request for addl info re review of NUREG-0737, Items 1, A.2 1.4, "Upgrading of Reactor Operator & Senior Operator Training" & 11.3 4, "Training for Mitigating Core Damage." Response requested within 30 days of ltr receipt.
BTOLZ, J. F. Operating Reactors Branch 4. 83/02/08. BECKHAM, J. T. Georgia Power Co. 3pp 17197.123 24X Fiche: 50-321/83/02/08, 8302170530
- 8302250432 Requests that 830203 application for amend to License NRP-9 consisting of changes to Tech Specs re post-accident monitoring instrument list, be withdrawn from consideration
GUCHA, L. T. Georgia Power Co. 83/02/18. BTOLZ, J. F. Operating Reactors Branch 4. 1p 17294.016 24X Fiche: 50-366/83/02/18, 8302250432.
- G. Inspection reports, IE Bulletins & correspondence
- 8302150221 Forwards IE Insp Repts 50-321/82-43 & 50-366/82-41 on 821120-1219. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/01/10. KELLY, R. J. Georgia Power Co. 2pp. 17150.035. 24X
Fiche: 50-321/83/01/10, 8302150221
- 8302150234 IE Insp Repts 50-321/82-43 & 50-366/82-41 on 821120-1219. No noncompliance noted. Major areas inspected: Tech Spec compliance, operator performance, overall plant operations, QA practices & station & site security procedures.
HOLMES-RAY, P., BROWNLEE, V. L. Division of Project & Resident Programs. 83/01/07. 4pp. 17150.037 24X Fiche: 50-321/83/01/10, 8302150234.
- 8302150716 Forwards IE Insp Repts 50-321/82-44 & 50-366/82-39 on 821204-10. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/01/10. KELLY, R. J. Georgia Power Co. 2pp. 17153.030. 24X
Fiche: 50-321/83/01/10, 8302150716
- 8302150721 IE Insp Repts 50-321/82-44 & 50-366/82-39 on 821204-10. No noncompliance noted. Major area inspected: radiological emergency exercise.
ANDREWS, D. L., MARSTON, R. R., JENKINS, O. R. Division of Emergency Preparedness & Materials Safety. 83/01/07. 7pp. 17153.032. 24X
Fiche: 50-321/83/01/10, 8302150716.
- 8302150427 Ack receipt of 830107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-39 & 50-366/82-37
DANCE, H. C. Division of Project & Resident Programs. 83/01/19. KELLY, R. J. Georgia Power Co. 1p 17157.037 24X
Fiche: 50-321/83/01/19, 8302150427
- 8302150443 Responds to NRC 821209 ltr re violations noted in IE Insp Repts 50-321/82-39 & 50-366/82-37 Corrective actions: verification performed to ensure proper valve positions
Procedure HNP-2-1117 re RHR - svc revised
GUCHA, L. T. Georgia Power Co. 83/01/07. O'REILLY, J. P. Region 2, Office of Director. 2pp 17157.039 24X Fiche: 50-321/83/01/19, 8302150443
- 8302150455 Forwards IE Insp Repts 50-321/82-39 & 50-366/82-37 on 821028-1120 & notice of violation
DANCE, H. C. Division of Project & Resident Programs. 82/12/09. KELLY, R. J. Georgia Power Co. 2pp 17157.041 24X
Fiche: 50-321/83/01/19, 8302150455
- 8302150465 Notice of violation from insp on 821028-1120
* Division of Project & Resident Programs. 82/12/09. 1p 24X
Fiche: 50-321/83/01/19, 8302150465
- 8302150488 IE Insp Repts 50-321/82-39 & 50-366/82-37 on 821028-1120 Noncompliance noted: out of svc RHR svc water strainer outlet valve 2E11-F118 found shut but unlocked & inlet valve 2E11-F117B found locked open
HOLMES-RAY, P., CLENJAK, R. V., ROOGE, J. F. Division of Project & Resident Programs. 82/12/08. 4pp. 17157.043 24X
Fiche: 50-321/83/01/19, 8302150488
- 8302150611 Ack receipt of 821130 & 1230 ltrre informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-32 & 50-366/82-30
DANCE, H. C. Division of Project & Resident Programs. 83/01/19. KELLY, R. J. Georgia Power Co. 1p 17154.146 24X
Fiche: 50-321/83/01/19, 8302150611
- 8302150627 Supple 821130 response to NRC 821130 ltr re violations noted in IE Insp Repts 50-321/82-32 & 50-366/82-30 Corrective actions: need to retrain deviations of safety nature to shift supervisor emphasized to individual involved
GUCHA, L. T. Georgia Power Co. 82/12/30. O'REILLY, J. P. Region 2, Office of Director. 1p 17154.147 24X Fiche: 50-321/83/01/19, 8302150611.
- 8302150640 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-321/82-32 & 50-366/82-30 Corrective actions: operator reprimanded & instructed to follow plant procedures & instrument check performed
GUCHA, L. T. Georgia Power Co. 82/11/30. O'REILLY, J. P. Region 2, Office of Director. 5pp. 17154.148 24X Fiche: 50-321/83/01/19, 8302150611.
- 8302150646 Forwards IE Insp Repts 50-321/82-32 & 50-366/82-30 on 820828-0928 & notice of violation
DANCE, H. C. Division of Project & Resident Programs. 82/10/26. KELLY, R. J. Georgia Power Co. 2pp 17154.153 24X
Fiche: 50-321/83/01/19, 8302150611.
- 8302150692 Notice of violation from insp on 820828-0928
* Division of Project & Resident Programs. 82/10/26. 2pp. 17154.155. 24X Fiche: 50-321/83/01/19, 8302150611.
- 8302150639 IE Insp Repts 50-321/82-32 & 50-366/82-30 on 820828-0928 Noncompliance noted: failure to follow HPCI surveillance procedure, properly notify NRC & follow health physics procedure
ROGERS, R. F., HOLMES-RAY, P., BROWNLEE, V. L. Division of Project & Resident Programs. 82/10/25. 4pp 17154.157 24X
Fiche: 50-321/83/01/19, 8302150611.
- 8212040358 IE Info Notice 83-01, "Ray Miller, Inc." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/26. Consolidated Edison Co. of New York, Inc. 118pp. 17023.160. 24X Fiche: 50-000/83/01/26, 8212040358
- 8212040360 IE Info Notice 83-02, "Limitique HOBCHISC, H2BC & H2BC Overheads." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28. Consolidated Edison Co. of New York, Inc. 109pp. 17144.001. 24X Fiche: 50-000/83/01/28, 8212040360
- 8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28. Consolidated Edison Co. of New York, Inc. 110pp. 17074.095. 24X Fiche: 50-000/83/01/28, 8212060361

DOCKETED ITEMS

8302150702 Submits addl response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters " Installation of Model 1153B transmitters delayed until end of Cycle 4
OUCMA, L T Georgia Power Co. 83/01/31 O'REILLY, J P Region 2, Office of Director 1p 17150 358 24X Fiche 50-366, 83/01/31, 8302150702

8302150423 Ack receipt of 830131 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Repts 50-321/82-36 & 50-366/82-34
LEWIS, R C Division of Project & Resident Programs 83/02/09
KELLY, R J Georgia Power Co 1p 17148 117 24X Fiche 50-321, 83/02/09, 8302150423

--8302150431 Responds to NRC 821227 ltr re violation & deviation noted in IE Insp Repts 50-321/82-36 & 50-366/82-34 Corrective actions QA audits scheduled for three vendors & QA program revised to provide annual QA audits re environ monitoring.
OUCMA, L T Georgia Power Co 83/01/31, O'REILLY, J P Region 2, Office of Director, 3pp 17148 118 24X Fiche 50-321, 83/02/09, 8302150423

--8302150435 Forwards IE Insp Repts 50-321/82-36 & 50-366/82-34 on 821130-1206 & notices of violation & deviation
LEWIS, R C Division of Project & Resident Programs, 82/12/27.
KELLY, R J Georgia Power Co 2pp, 17148 121, 24X Fiche 50-321, 83/02/09, 8302150423

--8302150441 Notice of violation from insp on 821130-1206.
* Division of Project & Resident Programs, 82/12/27 1p 17148 123 24X Fiche 50-321, 83/02/09, 8302150423

--8302150449 Notice of deviation from insp on 821130-1206
* Division of Project & Resident Programs 82/12/27 1p, 17148 124 24X Fiche 50-321, 83/02/09, 8302150423

--8302150459 IE Insp Repts 50-321/82-36 & 50-366/82-34 on 821130-1206.
Noncompliance noted: failure to conduct annual QA audits of radioanalytical program & to develop program providing annual vendor QA audits re environ monitoring
CUNNINGHAM, A L, MONTGOMERY, D M Division of Engineering & Radiological Safety Programs, 82/12/20 7pp, 17148 125 24X Fiche 50-321, 83/02/09, 8302150423

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18, Consolidated Edison Co of New York, Inc 110pp, 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/02/24, Consolidated Edison Co of New York, Inc 111pp 17347 098, 24X Fiche 50-000, 83/02/24, 8212060365.

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24, Consolidated Edison Co of New York, Inc 112pp, 17361 148, 24X Fiche 50-000, 83/02/24, 8212060366.

R Periodic operating reports & related correspondence

8302160232 Forwards monthly operating repts for Jan 1983.
NIX, H C Georgia Power Co 83/02/08 Director's Office, Office of Inspection and Enforcement 1p, 17170 135, 24X Fiche 50-321, 83/02/08, 8302160232.

--8302160238 Monthly operating repts for Jan 1983.
SEWEL, S K Georgia Power Co, 83/02/03 10pp 17170 136, 24X Fiche 50-321, 83/02/08, 8302160232.

8302160243 Forwards monthly operating repts for Jan 1983.
NIX, H C Georgia Power Co, 83/02/08, NRC - No Detailed Affiliation Given 1p, 17170 200, 24X Fiche 50-321, 83/02/08, 8302160243.

S Reportable occurrences, LERs & related correspondence

8302010428 Forwards LER 82-135/03L-0.
NIX, H C Georgia Power Co, 83/01/18 O'REILLY, J P Region 2, Office of Director, 1p, 16974 176, 24X Fiche 50-366, 83/01/18, 8302010428.

--8302010430 LER 82-135/03L-0 on 821228, north wall of control room air lock breached & unattended during performance of control of transient combustibles. Caused by personnel error. Wall repaired & personnel counseled.
SUMNER, H L Georgia Power Co 83/01/18 Region 2, Office of Director 3pp, 16974 177, 24X Fiche 50-366, 83/01/18, 8302010428

8302070395 Forwards LER 82-136/03L-0
NIX, H C Georgia Power Co 83/01/25, O'REILLY, J P Region 2, Office of Director 1p, 17029 356 24X Fiche 50-366, 83/01/25, 8302070395.

--8302070400 LER 82-136/03L-0 on 821229, during surveillance testing, monitoring relay for reactor protection sys alternate supply found to actuate at 132.2 volts. Caused by overvoltage relay out of calibr due to instrument drift. Relay recalibr.
TIPPE, S B Georgia Power Co 83/01/25, Region 2, Office of Director 1p, 17029 357 24X Fiche 50-366, 83/01/25, 8302070395.

8302140169 Forwards LER 82-138/03L-0.
NIX, H C Georgia Power Co 83/01/25 O'REILLY, J P Region 2, Office of Director, 1p 17140 110, 24X Fiche 50-366, 83/01/25, 8302140169.

--8302140181 LER 82-138/03L-0 on 821229, while performing RCIC turbine exhaust diaphragm pressure instrument RT&C procedure, RCIC trip & throttle valve failed to trip. Caused by limit switch seipoint drift. Limit switch adjusted properly
TIPPE, S B Georgia Power Co, 83/01/25, Region 2, Office of Director 1p, 17140 111, 24X Fiche 50-366, 83/01/25, 8302140169.

8302030375 Forwards updated LER 80-159/03X-1.
NIX, H C Georgia Power Co, 83/01/27, O'REILLY, J P Region 2, Office of Director, 1p 17005 106 24X Fiche 50-366, 83/01/27, 8302030375

--8302030376 Updated LER 80-159/03X-1 on 801126, during manual start to diesel generator 2C failed. Caused by broken cotter pins that lock connecting rod nuts in place for cylinder 11, allowing separation from crankshaft. Engine repaired
TIPPE, S B Georgia Power Co, 83/01/27, Region 2, Office of Director, 3pp 17005 107 24X Fiche 50-366, 83/01/27, 8302030375.

8302030449 Forwards updated LER 80-164/03X-1.
NIX, H C Georgia Power Co, 83/01/27, O'REILLY, J P Region 2, Office of Director 1p, 17006 201, 24X Fiche 50-366, 83/01/27, 8302030449

--8302030460 Updated LER 80-164/03X-1 on 801210, attempt to pressurize drywell equipment drain sump to radwaste discharge piping failed due to excessive leakage past outboard isolation valve. Caused by valve gate not seating properly.
SUMNER, H L Georgia Power Co, 83/01/27, Region 2, Office of Director, 1p 17006 202 24X Fiche 50-366, 83/01/27, 8302030449.

8302030472 Forwards updated LER 81-127/03X-1.
NIX, H C Georgia Power Co 83/01/27, O'REILLY, J P Region 2, Office of Director, 1p 17006 137, 24X Fiche 50-366, 83/01/27, 8302030472.

--8302030484 Updated LER 81-127/03X-1 on 811216, during normal surveillance of diesel generator 2C, engine failed & declared inoperable. Caused by rod separating from crankshaft due to loss of one of two retaining bolts. Engine repaired.
TIPPE, S B Georgia Power Co, 83/01/27, Region 2, Office of Director, 3pp, 17006 138, 24X Fiche 50-366, 83/01/27, 8302030472.

8302030515 Forwards updated LER 79-088/03X-1.
NIX, H C Georgia Power Co 83/01/27, O'REILLY, J P Region 2, Office of Director, 1p 17007 299 24X Fiche 50-366, 83/01/27, 8302030515.

--8302030523 Updated LER 79-088/03X-1 on 790721, Surveillance Procedure HNP-2-3353E not completed due to failure of charcoal filter deluge sys to operate automatically. Caused by water pressure fluctuations. Water supplies changed.
SUMNER, H L Georgia Power Co, 83/01/27, Region 2, Office of Director, 3pp, 17007 300, 24X Fiche 50-366, 83/01/27, 8302030515

8302140160 Forwards LER 83-001/03L-0.
NIX, H C Georgia Power Co, 83/01/27, O'REILLY, J P Region 2, Office of Director, 1p, 17140 165, 24X Fiche 50-366, 83/01/27, 8302140160

--8302140165 LER 83-001/03L-0 on 830107, while performing ECGE status check procedure, drywell hydrogen oxygen analyzer discovered inoperative. Caused by moisture accumulation in regulator sensing line. Water removed, Pump diaphragms replaced.
TIPPE, S B Georgia Power Co 83/01/27, Region 2, Office of Director, 1p 17140 166 24X Fiche 50-366, 83/01/27, 8302140160.

DOCKETED ITEMS

8302140007 Forwards updated LER 82-112/01X-4.
NIX,H.C. Georgia Power Co. 83/02/01. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17142 141 24X Fiche 50-366,83/02/01,
8302140007.

--8302140015 Updated LER 82-112/01X-4. on 821009, Tech Spec testing
requirements not adequately met. Caused by plant procedures
not adequately testing automatic initiation logic of
respective plant sys. New procedures written & performed
SUMNER, H.L. Georgia Power Co. 83/02/01. Region 2, Office of
Director. 3pp. 17142 142 24X Fiche 50-366, 83/02/01, 8302140007

8302140028 Forwards updated LER 80-130/03X-1.
NIX,H.C. Georgia Power Co. 83/02/01. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17141:173 24X Fiche 50-366, 83/02/01,
8302140028

--8302140029 Updated LER 80-130/03X-1 on 800913, primary containment
hydrogen & oxygen analyzer found inoperable. Caused by
analyzer being out of calibr. Analyzer calibr.
TIPPS,B.B. Georgia Power Co. 83/02/01. Region 2, Office of
Director. Ip. 17141:174 24X Fiche:50-366,83/02/01,8302140028

8302140103 Forwards updated LER 80-073/03X-1.
NIX,H.C. Georgia Power Co. 83/02/01. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17142 106 24X Fiche 50-366,83/02/01,
8302140103

--8302140108 Updated LER 80-073/03X-1: on 800425, hydrogen combiner B
failed to start during test. Caused by temp controller
setpoint too close to sys trip setpoint. Procedure revised to
lower controller setpoint.
TIPPS,B.B. Georgia Power Co. 83/02/01. Region 2, Office of
Director. 2pp. 17142, 107, 24X Fiche: 50-366, 83/02/01, 8302140103

8302150091 Forwards updated LER 80-126/03X-1.
NIX,H.C. Georgia Power Co. 83/02/01. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17146:325 24X Fiche: 50-366, 83/02/01,
8302150091

--8302150104 Updated LER 80-126/03X-1 on 800824, primary containment
hydrogen & oxygen analyzer A discovered inoperable. Caused by
insufficient reagent gas flow through flowmeter. Gas flow
increased.
TIPPS,B.B. Georgia Power Co. 83/02/01. Region 2, Office of
Director. Ip. 17146:326 24X Fiche:50-366,83/02/01,8302150091.

8302150121 Forwards updated LER 80-150/03X-1.
NIX,H.C. Georgia Power Co. 83/02/01. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17147 314. 24X Fiche: 50-366, 83/02/01,
8302150121.

--8302150135 Updated LER 80-150/03X-1 on 801102, HPCI steamline pressure
A logic did not auto isolate until 89 psig. Possibly caused
by switches not environmentally qualified. Switches to be
replaced by Analog transmitter sys.
TIPPS,B.B. Georgia Power Co. 83/02/01. Region 2, Office of
Director. 2pp. 17147 315 24X Fiche: 50-366, 83/02/01, 8302150121

8302150241 Forwards updated LER 80-108/03X-1.
NIX,H.C. Georgia Power Co. 83/02/01. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17148 358 24X Fiche: 50-366, 83/02/01,
8302150241

--8302150232 Updated LER 80-108/03X-1, on 800720, J torus-to-drywell vacuum
breaker failed to open & on 800723, I breaker failed following
actuation. Caused by broken air supply lines at air
cylinders & faulty air control valve. Components replaced.
TIPPS,B.B. Georgia Power Co. 83/02/01. Region 2, Office of
Director. 2pp. 17148:359. 24X Fiche: 50-366, 83/02/01, 8302150241

8302150203 Forwards updated LER 80-094/03X-2.
NIX,H.C. Georgia Power Co. 83/02/03. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17150 027. 24X Fiche: 50-366, 83/02/03,
8302150203.

--8302150210 Updated LER 80-094/03X-2 on 800613, during routine
surveillance, torus to drywell vacuum breaker B would not
open. Caused by broken air supply line to air cylinder. Air
supply line & air control valve replaced.
TIPPS,B.B. Georgia Power Co. 83/02/03. Region 2, Office of
Director. 2pp. 17150:028. 24X Fiche: 50-366, 83/02/03, 8302150203

8302150481 Forwards updated LER 81-083/03X-1.
NIX,H.C. Georgia Power Co. 83/02/03. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17156:280 24X Fiche: 50-366, 83/02/03,
8302150481

--8302150490 Updated LER 81-083/03X-1 on 810902, post-accident monitoring
torus water level indicator A read higher than indicator B.
Caused by leaking equalizer valve which drained ref leg for
A torus water transmitter. Valve stem replaced.
TIPPS,B.B. Georgia Power Co. 83/02/03. Region 2, Office of
Director. Ip. 17156 281 24X Fiche 50-366, 83/02/03, 8302150481

8302150539 Forwards updated LER 81-101/03X-1
NIX,H.C. Georgia Power Co. 83/02/03. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17156 100 24X Fiche: 50-366, 83/02/03,
8302150539

--8302150549 Updated LER 81-101/03X-1 on 811024, while performing MSIV
trip test, outboard MSIVs B & D isolated too fast. Caused by
setpoint drift. Needle valves recalibr & MSIVs returned to
operable status.
TIPPS,B.B. Georgia Power Co. 83/02/03. Region 2, Office of
Director. 2pp. 17156 101 24X Fiche 50-366, 83/02/03, 8302150539

8302150672 Forwards updated LER 82-040/01X-1
NIX,H.C. Georgia Power Co. 83/02/03. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17154 100 24X Fiche 50-366, 83/02/03,
8302150672

--8302150682 Updated LER 82-040/01X-1 on 830107, current Tech Spec limits
for MCPR became nonconservative. Telcon w/NRC confirmed
actions to continue operation w/conservative MCPR limits in
place based on OE reanalysis.
SUMNER, H.L. Georgia Power Co. 83/02/03. Region 2, Office of
Director. 2pp. 17154 101 24X Fiche 50-366, 83/02/03, 8302150672

8302150073 Forwards updated LER 80-024/03X-1
NIX,H.C. Georgia Power Co. 83/02/08. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17146 339 24X Fiche 50-366, 83/02/08,
8302150073

--8302150077 Updated LER 80-024/03X-1 on 800308, during performance of
ASME operability test on RHR svc water pumps, D pump flow
dropped. Caused by debris drawn into suction of pump. Intake
structure cleaned & dredged.
TIPPS,B.B. Georgia Power Co. 83/02/08. Region 2, Office of
Director. Ip. 17146 360 24X Fiche 50-366, 83/02/08, 8302150073

8302150103 Forwards updated LER 81-046/03X-1
NIX,H.C. Georgia Power Co. 83/02/08. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17146 150 24X Fiche 50-366, 83/02/08,
8302150103

--8302150105 Updated LER 81-046/03X-1 on 810519, max attainable flow in
water pump 2C found to be 5,600 gpm while performing ASME
inservice operability test. Caused by normal operational
wear. Pump rebuilt & returned to svc.
TIPPS,B.B. Georgia Power Co. 83/02/08. Region 2, Office of
Director. Ip. 17146 151 24X Fiche 50-366, 83/02/08, 8302150103

8302150133 Forwards updated LER 80-147/03X-1
NIX,H.C. Georgia Power Co. 83/02/08. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17148 016, 24X Fiche: 50-366, 83/02/08,
8302150133

--8302150142 Updated LER 80-147/03X-1 on 801029, A & B post-accident
monitoring drywell hydrogen peroxide analyzers found
inoperable. Caused by combination of failures of related
equipment. Components associated w/analyzers repaired.
TIPPS,B.B. Georgia Power Co. 83/02/08. Region 2, Office of
Director. 2pp. 17148 017 24X Fiche 50-366, 83/02/08, 8302150133

8302150397 Forwards LER 83-002/03L-0.
NIX,H.C. Georgia Power Co. 83/02/08. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17158 100 24X Fiche: 50-366, 83/02/08,
8302150397

--8302150402 LER 83-002/03L-0 on 830118, primary containment isolation
reactor water level low-instrument channel B found out
of calibr. Caused by setpoint drift. Instrument recalibr.
TIPPS,B.B. Georgia Power Co. 83/02/08. Region 2, Office of
Director. Ip. 17158 101 24X Fiche: 50-366, 83/02/08, 8302150397

8302150506 Forwards updated LER 79-135/03X-1
NIX,H.C. Georgia Power Co. 83/02/08. O'REILLY,J.P. Region 2,
Office of Director. Ip. 17156 330. 24X Fiche 50-366, 83/02/08,
8302150506

--8302150517 Updated LER 79-135/03X-1 on 791219, power supply A for RCIC
steam leak detection sys failed. Caused by excess current
on 125-volt dc input to power supplies blowing fuses 7A &
7B. Fuses replaced.
TIPPS,B.B. Georgia Power Co. 83/02/08. Region 2, Office of
Director. 2pp. 17156 331 24X Fiche 50-366, 83/02/08, 8302150506

DOCKETED ITEMS

2

8302230702 Forwards LER 83-004/03L-0
NIX,H C Georgia Power Co 83/02/08 O'REILLY,J P Region 2,
Office of Director 1p 17248 317 24X Fiche 50-366,83/02/08,
8302230702

--8302230705 LER 83-004/03L-0 on 830113 & 20, standby gas treatment fan
failed to start automatically w/switch in run position
Caused by loose auxiliary switch mounting screw & failure of
filter train heater control latching relay Switch repaired
TIPPS,B B Georgia Power Co 83/02/08 Region 2, Office of
Director 2pp 17248 318 24X Fiche 50-366,83/02/08,8302230702

8302230210 Forwards updated LER 80-028/03X-1
NIX,H C Georgia Power Co 83/02/10 O'REILLY,J P Region 2,
Office of Director 1p 17243 193 24X Fiche 50-366,83/02/10,
8302230210

--8302230217 Updated LER 80-028/03X-1 on 800228,during instrument check,
drywell hydrogen dioxide analyzer B recorder gave erroneous
reading Caused by sys inleakage,Leak repaired & analyzer
calibr & returned to svc
TIPPS,B B Georgia Power Co 83/02/10 Region 2, Office of
Director 2pp 17243 194 24X Fiche 50-366,83/02/10,8302230210

8302230550 Forwards updated LER 82-018/03X-1
NIX,H C Georgia Power Co 83/02/10 O'REILLY,J P Region 2,
Office of Director 1p 17256 302 24X Fiche 50-366,83/02/10,
8302230550

--8302230563 Updated LER 82-018/03X-1 on 820308,evidence of main steam
pipe hanger embed plate pulling from ceiling found Caused by
concrete spalling around embed plate due to localized
detective matl &/or faulty installation
SUMNER,H L Georgia Power Co 83/02/10 Region 2, Office of
Director 2pp 17256 303 24X Fiche 50-366,83/02/10,8302230550

8302230700 Forwards updated LER 82-093/03X-1
NIX,H C Georgia Power Co 83/02/10 O'REILLY,J P Region 2,
Office of Director 1p 17248 320 24X Fiche 50-366,83/02/10,
8302230700

--8302230707 Updated LER 82-093/03X-1 on 820817,during normal full load,
low accumulator gas pressure of 955 psig found for control
rod 10-47 Accumulator declared inoperable Caused by slow
bleed down of accumulator pressure Accumulator recharged
TIPPS,B B Georgia Power Co 83/02/10 Region 2, Office of
Director 1p 17248 321 24X Fiche 50-366,83/02/10,8302230700

8302230231 Forwards updated LER 80-049/03X-1
NIX,H C Georgia Power Co 83/02/15 O'REILLY,J P Region 2,
Office of Director 1p 17245 036 24X Fiche 50-366,83/02/15,
8302230231

--8302230239 Updated LER 80-049/03X-1 on 830407,while performing standby
liquid control pump operability & relief valve test,BBLC
pump B discharge relief valve failed to operate at required
pressure Caused by setpoint drift
TIPPS,B B Georgia Power Co 83/02/15 Region 2, Office of
Director 1p 17245 037 24X Fiche 50-366,83/02/15,8302230231

8302280146 Forwards updated LER 80-129/03X-1
NIX,H C Georgia Power Co 83/02/15 O'REILLY,J P Region 2,
Office of Director 1p 17312 158 24X Fiche 50-366,83/02/15,
8302280146

--8302280246 Updated LER 80-129/03X-1 on 800918,while performing
increased surveillance on torus/drywell vacuum breakers,
breaker O failed to open upon actuation of test switch,
Caused by failure of air control valve Valve replaced
TIPPS,B B Georgia Power Co 83/02/15 Region 2, Office of
Director 2pp 17312 159 24X Fiche 50-366,83/02/15,8302280146

8302280131 Forwards LER 83-005/03L-0
NIX,H C Georgia Power Co 83/02/17 O'REILLY,J P Region 2,
Office of Director 1p 17306 088 24X Fiche 50-366,83/02/17,
8302280131

--8302280138 LER 83-005/03L-0 on 830128,during performance of routine
panel walkdown,2A recirculation pump discharge valve
position not illuminated Caused by circuit breaker being
in off position
TIPPS,B B Georgia Power Co 83/02/17 Region 2, Office of
Director 1p 17306 089 24X Fiche 50-366,83/02/17,8302280131

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees,applicants
for OLS,NBS vendors,reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses, Svc list encl.
EISENHUT,D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc. 14pp. 17347.177 24X
Fiche 50-000,83/01/31,8301310203

DOCKET 50-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PHRs re review of
C-E Owners Group emergency procedures guideline program, Svc
list encl.
EISENHUT,D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc. 11pp. 17290.247 24X
Fiche 50-000,83/02/08,8302080295

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees,applicants
for OLS,NBS vendors,reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl.
EISENHUT,D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc. 14pp. 17347.177 24X
Fiche 50-000,83/01/31,8301310203

DOCKET 50-368 ARKANASAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

8302070374 Forwards IE Insp Repts 50-313/82-33 & 50-368/82-33 on
821115-19 & notice of violation
SEIDLE,W C. Division of Resident, Reactor Project & Engineering
Programs 83/01/18 CAVANAUGH,W Arkansas Power & Light Co. 2pp
17030.042 24X Fiche 50-313,83/01/18,8302070374

--8302070382 Notice of violation from insp on 821115-19
* Division of Resident, Reactor Project & Engineering Programs,
83/01/18 1p. 17030 044 24X Fiche 50-313,83/01/18,8302070374

--8302070391 IE Insp Repts 50-313/82-33 & 50-368/82-33 on 821115-19,
Noncompliance noted failure of plant safety committee to
investigate licensee identified Tech Spec violation &
failure to maintain penetration fire barriers functional.
MURPHY,M E, WEBSTERMAN,T F, JOHNSON,W D Division of Resident,
Reactor Project & Engineering Programs. 83/01/06 10pp.
17030.045 24X Fiche 50-313,83/01/18,8302070374

8302040060 Notification of 830216 meeting w/util & Nuclear Util Fire
Protection Group in Bethesda,MD to discuss util appeal of
NRC positions re fire protection App R exemption requests
LYNCH,D O D T Operating Reactors Branch 3 83/01/26 CLARK,R.A.
Operating Reactors Branch 3 3pp. 17043.176 24X
Fiche 50-313,83/01/26,8302040060

8302170509 Notification of cancellation of 830216 meeting w/util in
Bethesda,MD to appeal NRC positions re fire protection App
R exemption requests.
LYNCH,D O D T Operating Reactors Branch 3 83/01/26 CLARK,R.A.
Operating Reactors Branch 3 1p 17197.097 24X
Fiche 50-313,83/01/26,8302170509

8302030391 Confirms 830124 & 25 telcons re discussions on App R appeal
meeting scheduled for 830128,Util understands NRC will grant
all exemption requests addressed in 821111 ltr.
MARSHALL,J R Arkansas Power & Light Co. 83/01/28 STOLZ,J F
Operating Reactors Branch 4 CLARK,R.A. Operating Reactors Branch
3 2pp 17005.324 24X Fiche 50-313,83/01/28,8302030391

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl i,NUREG-0737, "Requirements for Emergency
Response Capability," Svc list encl.
EISENHUT,D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc. 11pp 17221.226 24X
Fiche 50-000,83/02/01,8301210340

8302070462 Ack receipt of 821101 ltr informing NRC of steps taken to
resolve open items noted in IE Emergency Planning Insp
Repts 50-313/82-11 & 50-368/82-09.
SEIDLE,W C. Division of Resident, Reactor Project & Engineering
Programs 83/02/01 CAVANAUGH,W Arkansas Power & Light Co. 2pp.
17036.281 24X Fiche 50-313,83/02/01,8302070462

DOCKETED ITEMS

--8302070468 Responds to NRC 820928 ltr re open items noted in IE Emergency Planning Insp Repts 50-313/82-11 & 50-368/82-09 Schedule for resolving open items encl
MARSHALL, J. R. Arkansas Power & Light Co. 82/11/01 COLLINS, J. T. Region 4, Office of Director. 4pp 17036 283 24X
Fiche: 50-313, 83/02/01, 8302070468

8302080180 Ack receipt of 821231 ltr re security sys NRC pleased w/progress & completion of Phase II of security sys improvement program
SEIDLE, W. C. Division of Resident: Reactor Project & Engineering Programs. 83/02/03 CAVANAUGH, W. Arkansas Power & Light Co. 2pp 17058 319 24X Fiche: 50-313, 83/02/03, 8302080180

8302230588 Ack receipt of 830104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18
SEIDLE, W. C. Division of Resident: Reactor Project & Engineering Programs. 83/02/14 CAVANAUGH, W. Arkansas Power & Light Co. 1p 17256 115 24X Fiche: 50-313, 83/02/14, 8302230588

--8302230402 Responds to NRC 821105 ltr re violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18 Corrective actions: health physics training sequences revised to specify retraining requirements & frequencies
MARSHALL, J. R. Arkansas Power & Light Co. 83/01/04, SEIDLE, W. C. Division of Resident: Reactor Project & Engineering Programs. 3pp 17256 116 24X Fiche: 50-313, 83/02/14, 8302230588

8302170507 Releases public version of licensee 830114 ltr clarifying Amend 4 to emergency plan
FELTON, J. M. Division of Rules and Records. 83/02/15 Document Management Branch. 1p. 17197 095 24X Fiche: 50-313, 83/02/15, 8302170507

--8302170517 Submits public version of info clarifying Amend 6 to emergency plan, in response to 821223 request Figure 10 will be amended by 830630 to identify responsible positions/titles for notification/communication function
MARSHALL, J. R. Arkansas Power & Light Co. 83/01/14 SEIDLE, W. C. Division of Resident: Reactor Project & Engineering Programs. 1p 17197 096 24X Fiche: 50-313, 83/02/15, 8302170507

8302180223 Requests that 830216 appeal meeting be rescheduled, since NRC handling of partial suppression sys as generic issue does not relieve utility of having to address issue on individual basis Fire protection remains highest priority
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/15 BTOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 2pp. 17215 301. 24X Fiche: 50-313, 83/02/15, 8302180223

H General correspondence

8302230499 Notifies that J Griffin designated senior nuclear mgt representative
CAVANAUGH, W. Arkansas Power & Light Co. 83/02/16 CLARK, R. A. Operating Reactors Branch 3 BTOLZ, J. F. Operating Reactors Branch 4. 2pp. 17246 198. 24X Fiche: 50-313, 83/02/16, 8302230499

P. Operating license stage documents & correspondence

8302170019 Forwards documentation supporting justification for continued operation of operating reactors in response to questions raised at 830106 meeting re environ qualification of electrical equipment
EISENHUT, D. O. Division of Licensing. 83/01/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 7pp. 17196 091 24X Fiche: 50-000, 83/01/18, 8302170019

--8302240420 Advises that justification for continued operation during equipment environ qualification review suby to revisions agreed to is adequate
MARTIN, R. E. Operating Reactors Branch 3. 82/03/16 NOVAK, T. M. Assistant Director for Operating Reactors. 16pp. 17197-025 24X Fiche: 50-000, 83/01/18, 8302170019

--8302170129 Forwards tabulation of Group 2 & 3 plants showing dates by which technical evaluation repts are expected to be completed. Requests justification for continued operation of each group by 821008 & 15, respectively.
EISENHUT, D. O. Division of Licensing. 82/09/24, MIRAGLIA, F. Assistant Director for Safety Assessment. 4pp. 17196 265. 24X Fiche: 50-000, 83/01/18, 8302170019

--8302170217 Concludes that based on licensee submittals, continued operation until completion of environ qualification program will not present undue risk to public health & safety
STEVEN, J. A. Operating Reactors Branch 3. 82/10/28 EISENHUT, D. O. Division of Licensing. 2pp 17197:023. 24X Fiche: 50-000, 83/01/18, 8302170019

8302010699 Summary of 830110 meeting w/util & C-E re plant protection sys connector wiring mod
LYNCH, O. D. Operating Reactors Branch 3. 83/01/19 CLARK, R. A. Operating Reactors Branch 3. 32pp 16989 311 24X
Fiche: 50-368, 83/01/19, 8302010699

8302010046 Requests Tech Spec changes re key lock switches & leak testing to resolve purge valve issue Info due within 45 days
BTOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 83/01/24 CAVANAUGH, W. Arkansas Power & Light Co. 3pp 16990 305 24X Fiche: 50-313, 83/01/24, 8302010046

8302010050 Forwards request for addl info re spent fuel pool expansion Response requested within 10 days
BTOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 83/01/24 CAVANAUGH, W. Arkansas Power & Light Co. 3pp 16990 302 24X Fiche: 50-313, 83/01/24, 8302010050

8302010703 Summary of 821006 meeting w/util & C-E in Bethesda, MD re excessive growth in rate of closure of C-E 16x16 fuel shoulder gap
STEVEN, J. A. Licensing Branch 1. 83/01/26 Licensing Branch 1. 29pp 16989:282 24X Fiche: 50-368, 83/01/26, 8302010703

8302070497 Advises that submittal of proposed Tech Spec changes re reporting of safety & relief valve challenges rescheduled to 830228, per NRC 820920 request (Generic Ltr 82-16)
MARSHALL, J. R. Arkansas Power & Light Co. 83/01/31. BTOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 1p. 17035 043. 24X Fiche: 50-313, 83/01/31, 8302070497

8302070575 Responds to NRC 830105 ltr requesting schedule for providing addl info re proposed spent fuel storage expansion Info will be provided by 830215
MARSHALL, J. R. Arkansas Power & Light Co. 83/01/31 BTOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 1p 17034 292 24X Fiche: 50-313, 83/01/31, 8302070575

8302100006 Forwards request for addl info re spent fuel pool expansion Schedule for submittal of info due in 10 days
BTOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 83/02/01 CAVANAUGH, W. Arkansas Power & Light Co. 4pp 17135 177. 24X Fiche: 50-313, 83/02/01, 8302100006

8302160522 Forwards request for addl info re completion of post-implementation review of NUREG-0737, items II F 1.4, II F 1.5 & II F 1.6 re containment monitors Response requested within 60 days
CLARK, R. A. Operating Reactors Branch 3 BTOLZ, J. F. Operating Reactors Branch 4. 83/02/02 CAVANAUGH, W. Arkansas Power & Light Co. 10pp 17176 295 24X Fiche: 50-313, 83/02/02, 8302160522

8302090315 Responds to 821221 ltr re bypass of emergency feedwater sys auto start during Modes 3 & 6 Actions taken to restore sys to operable status redundant & unnecessary following maint Steam generator bypass use acceptable No mods proposed
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/03 CLARK, R. A. Operating Reactors Branch 3. 8pp 17071 006. 24X Fiche: 50-368, 83/02/03, 8302090315

8302150011 Application for amend to License NPF-6 Amend changes Tech Spec re diesel generator load block timing.
CAVANAUGH, W. Arkansas Power & Light Co. 83/02/03 CLARK, R. A. Operating Reactors Branch 3. 2pp 17146 197 24X
Fiche: 50-368, 83/02/03, 8302150011

--8302150016 Proposed Tech Spec re diesel generator load block timing
Arkansas Power & Light Co. 83/02/03. 76pp 17146 199 24X
Fiche: 50-368, 83/02/03, 8302150011

8302160519 Informs that 820528 request for Tech Spec change for resistance temp device response time surveillance requirements denied
CLARK, R. A. Operating Reactors Branch 3. 83/02/03 CAVANAUGH, W. Arkansas Power & Light Co. 2pp 17176 306. 24X
Fiche: 50-368, 83/02/03, 8302160519

8302150492 Informs that channel functional testing resumed 830201 due to expiration of License Amend 39 re deletion of channel functional tests during 830101-31, inclusive Tests will be conducted at rate of one per wk.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/04. CLARK, R. A. Operating Reactors Branch 3. 1p 17156 318 24X
Fiche: 50-368, 83/02/04, 8302150492

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Rev list encl
EISENHUT, D. O. Division of Licensing. 83/02/08. Consolidated Edison Co of New York, Inc. 11pp 17290 247. 24X
Fiche: 50-000, 83/02/08, 8302080295

DOCKETED ITEMS

2

B302080304 Generic Ltr B3-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/08 Consolidated Edison Co. of New York, Inc. 9pp. 17234 234 24X. Fiche: 50-000, 83/02/08, B302080304.

B302090072 Generic Ltr B3-10B to all licensees w/C-E designed NSSB re resolution of TMI Action Item I K 3.5. "Automatic Trip of Reactor Coolant Pumps." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/08 Consumers Power Co. 32pp. 17290 185 24X. Fiche: 50-000, 83/02/08, B302090072.

B302160168 Advises that addl info re proposed spent fuel storage expansion will be provided by B30225, in response to NRC B30125 ltr. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/08 BTOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 1p. 17162 068 24X. Fiche: 50-313, 83/02/08, B302160168.

B302160149 Advises that addl info re proposed spent fuel storage expansion will be provided by B30225, in response to NRC B30201 ltr. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/10 BTOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 1p. 17162 217 24X. Fiche: 50-313, 83/02/10, B302160149.

B302180467 Application for amend to Licenses DPR-31 & NPF-6, deleting nonradiological water quality surveillance requirements from ETB. GRIFFIN, J. M. Arkansas Power & Light Co. 83/02/15 BTOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17214 084 24X. Fiche: 50-313, 83/02/15, B302180467.

--B302180472 Revised ETB, deleting nonradiological water quality surveillance requirements. * Arkansas Power & Light Co. 83/02/15 34pp. 17214 087. 24X. Fiche: 50-313, 83/02/15, B302180469.

B302240404 Forwards request for addl info within 10 days re proposed spent fuel pool expansion discussed in B21105 ltr. BTOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 83/02/15 CAVANAUGH, W. Arkansas Power & Light Co. 4pp. 17288 390 24X. Fiche: 50-313, 83/02/15, B302240404.

B302220034 Informs of refund for B20628 Tech Spec change application re resistance temp device response time surveillance requirements. MILLER, W. G. License Fee Management Branch. 83/02/16 CAVANAUGH, W. Arkansas Power & Light Co. 1p. 17227 348. 24X. Fiche: 50-368, 83/02/16, B302220034.

B302230403 Application for amend to Licenses DPR-31 & NPF-6, changing Tech Specs Sections 3.4, 5 & 6 re spent fuel pool expansion. Class IV fee encl. CAVANAUGH, W. Arkansas Power & Light Co. 83/02/17. BTOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17246 346. 24X. Fiche: 50-313, 83/02/17, B302230403.

--B302230408 Proposed changes to Tech Specs Sections 3.4, 5 & 6 re spent fuel pool expansion. * Arkansas Power & Light Co. 83/02/17 17pp. 17246 348. 24X. Fiche: 50-313, 83/02/17, B302230403.

Q Inspection reports, IE Bulletins & correspondence

B302010251 Forwards IE Insp Repts 50-313/82-29 & 50-368/82-27 on B20907-17. No noncompliance noted. COLLINS, J. T. Region 4, Office of Director. 82/12/02 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 16973 143. 24X. Fiche: 50-313, 82/12/02, B302010251.

--B302010258 IE Insp Repts 50-313/82-29 & 50-368/82-27 on B20907-17. No noncompliance noted. Major areas inspected, review of licensee actions & commitments in response to IE bulletins, insp repts, NUREG-0737 items & NRC generic ltrs. JOHNSON, E. H. Region 4, Office of Director. JAUDON, J. P. Division of Resident, Reactor Project & Engineering Programs. TRAMMELL, C. M. Office of Nuclear Reactor Regulation, Director. 82/11/24. 14pp. 16973 145 24X. Fiche: 50-313, 82/12/02, B302010251.

B302070343 Forwards IE Investigation Rept 50-368/82-38 on B20608-10 & 16-17, 0806 & 0909. No noncompliance noted. Investigation did not develop evidence that Util intentionally submitted false statement re IE Bulletin 80-06. COLLINS, J. T. Region 4, Office of Director. 82/12/27. CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17029 322. 24X. Fiche: 50-368, 82/12/27, B302070343.

--B302070347 IE Investigation Rept 50-368/82-38 on B20608-10, 16-17, 0806 & 0909. No noncompliance noted. Major areas investigated: alleged mail false statement re IE Bulletin 80-06, "EBF Reset Controls." Personally identifiable info deleted. HERR, R. K. WARD, W. J. FITZGERALD, J. A. Region 4, Office of Director. 82/11/24. 25pp. 17029 324 24X. Fiche: 50-368, 82/12/27, B302070343.

B302070425 Forwards IE Insp Repts 50-313/82-35 & 50-368/82-35 on B21206-10. No noncompliance noted. BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/01/03 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17029 272 24X. Fiche: 50-313, 83/01/03, B302070425.

--B302070431 IE Insp Repts 50-313/82-35 & 50-368/82-35 on B21206-10. No noncompliance noted. Major areas inspected: audit implementation program, surveillance testing, calibr control program & calibr. MURPHY, M. E., JOHNSON, W. D. Division of Resident, Reactor Project & Engineering Programs. 83/01/05 4pp. 17029 274 24X. Fiche: 50-313, 83/01/03, B302070425.

B302030315 Provides list of interim actions re approach to review & control of ltrs & commitments to NRC & development of regulatory response & commitment control program. MARSHALL, J. R. Arkansas Power & Light Co. 83/01/14 COLLINS, J. T. Region 4, Office of Director. 5pp. 17001 271. 24X. Fiche: 50-313, 83/01/14, B302030315.

B302070374 Forwards IE Insp Repts 50-313/82-33 & 50-368/82-33 on B21115-19 & notice of violation. BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/01/18 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17030 042. 24X. Fiche: 50-313, 83/01/18, B302070374.

--B302070382 Notice of violation from insp on B21115-19. * Division of Resident, Reactor Project & Engineering Programs. 83/01/18 1p. 17030 044. 24X. Fiche: 50-313, 83/01/18, B302070374.

--B302070391 IE Insp Repts 50-313/82-33 & 50-368/82-33 on B21115-19. Noncompliance noted. Failure of plant safety committee to investigate licensee identified Tech Spec violation & failure to maintain penetration fire barriers functional. MURPHY, M. E., STEWART, R. C., MCCORDY, B. L. Division of Resident, Reactor Project & Engineering Programs. 83/01/06 10pp. 17030 045 24X. Fiche: 50-313, 83/01/18, B302070374.

B302070471 Forwards IE Insp Repts 50-313/82-34 & 50-368/82-34 on B21201-31. No noncompliance noted. BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/01/24. CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17036 018 24X. Fiche: 50-313, 83/01/24, B302070471.

--B302070475 IE Insp Repts 50-313/82-34 & 50-368/82-34 on B21201-31. No noncompliance noted. Major areas inspected: surveillance, long-term shutdown & preparation for refueling, operational safety verification & LER followup. CALLAN, L. J., CUMMINS, J. E., JOHNSON, W. D. Division of Resident, Reactor Project & Engineering Programs. 83/01/19. 9pp. 17036 020 24X. Fiche: 50-313, 83/01/24, B302070471.

B212060358 IE Info Notice B3-01, "Ray Miller, Inc." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/01/26 Consolidated Edison Co. of New York, Inc. 118pp. 17023 160. 24X. Fiche: 50-000, 83/01/26, B212060358.

B302010478 Ack receipt of B21217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-368/82-32. BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/01/27. CAVANAUGH, W. Arkansas Power & Light Co. 1p. 16981 020 24X. Fiche: 50-368, 83/01/27, B302010478.

--B302010490 Responds to NRC B21112 ltr re violations noted in IE Insp Rept 50-368/82-32. Corrective actions: procedural changes will be made to require preplanning re design change package installation. MARSHALL, J. R. Arkansas Power & Light Co. 82/12/17. BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 16981 021 24X. Fiche: 50-368, 83/01/27, B302010478.

B302010481 Ack receipt of B20929 & 1124 ltrs informing NRC of steps taken to correct violations & deviations noted in IE Insp Repts 50-313/82-14 & 50-368/82-11. BEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/01/27. CAVANAUGH, W. Arkansas Power & Light Co. 1p. 16982 063 24X. Fiche: 50-313, 83/01/27, B302010481.

DOCKETED ITEMS

--8302010489 Responds to NRC 821025 ltr re violations noted in IE Insp Repts 50-313/82-14 & 50-368/82-11. Corrective actions. Procedure 1403 003. "Radioactive Mat'l Shipments," revised to ensure certification attached to shipping papers. MARSHALL, J. R. Arkansas Power & Light Co. 82/11/24 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 5pp 16982 064 24X Fiche 50-313, 83/01/27, 8302010481.

--8302010497 Responds to NRC 821025 ltr re violations noted in IE Insp Repts 50-313/82-14 & 50-368/82-11. Corrective actions. mods during current refueling outage to be completed as scheduled & review of LOCA procedures completed. MARSHALL, J. R. Arkansas Power & Light Co. 83/01/07 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 2pp 16982 069 24X Fiche 50-313, 83/01/27, 8302010481.

--8302010501 Informs of investigation initiated to determine validity of deviation noted in IE Insp Repts 50-313/82-14 & 50-368/82-11 re NUREG-0578, Item 2.1.6.b, "Design of Plant Shielding." MARSHALL, J. R. Arkansas Power & Light Co. 82/09/29 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 7pp 16982 071 24X Fiche 50-313, 83/01/27, 8302010481.

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361.

8302070438 Submits results of strontium analysis of liquid radioactive effluent sample omitted from IE Insp Repts 50-313/82-12 & 50-368/82-23. Analysis performed by NRC Radiological & Environ Sciences Lab, necessitating omission. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/01/31. CAVANAUGH, W. Arkansas Power & Light Co. 3pp. 17031 013 24X Fiche 50-313, 83/01/31, 8302070438

8302070462 Ack receipt of 821101 ltr informing NRC of steps taken to resolve open items noted in IE Emergency Planning Insp Repts 50-313/82-11 & 50-368/82-09. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/01 CAVANAUGH, W. Arkansas Power & Light Co. 2pp 17036 281 24X Fiche 50-313, 83/02/01, 8302070462

--8302070468 Responds to NRC 820928 ltr re open items noted in IE Emergency Planning Insp Repts 50-313/82-11 & 50-368/82-09. Schedule for resolving open items encl. MARSHALL, J. R. Arkansas Power & Light Co. 82/11/01 COLLINS, J. T. Region 4, Office of Director. 6pp 17034 283. 24X Fiche 50-313, 83/02/01, 8302070462.

8302070541 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-32 & 50-368/82-31. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/03 CAVANAUGH, W. Arkansas Power & Light Co. 1p 17034 156 24X Fiche 50-313, 83/02/03, 8302070541.

--8302070552 Responds to NRC 821223 ltr re violations noted in IE Insp Repts 50-313/82-32 & 50-368/82-31. Corrective actions. combustibles removed, colored fire retardant located for use in identification & weekly insp conducted. MARSHALL, J. R. Arkansas Power & Light Co. 83/01/20 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 2pp 17034 157. 24X Fiche 50-313, 83/02/03, 8302070541.

8302180393 Responds to NRC 830118 ltr re violations noted in IE insp rept. Corrective action 800618 response to IE Bulletin 80-04 re-evaluated & submitted 820416 Interim actions to upgrade mgt controls implemented. Civil penalty payment encl. CAVANAUGH, W. Arkansas Power & Light Co. 83/02/03 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp. 17204 355. 24X Fiche 50-368, 83/02/03, 8302180391

8302170333 Requests description of actions taken to establish QA measures for proper selection, procurement & application of fastener lubricants & injection sealant compounds, per util 821231 response to IE Bulletin 82-02. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/10. CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17184 176. 24X Fiche 50-368, 83/02/10, 8302170333.

8302230588 Act receipt of 830104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/14 CAVANAUGH, W. Arkansas Power & Light Co. 1p 17256 119 24X Fiche 50-313, 83/02/14, 8302230588

--8302230602 Responds to NRC 821105 ltr re violations noted in IE Insp Repts 50-313/82-21 & 50-368/82-18. Corrective actions health physics training sequences revised to specify retraining requirements & frequencies. MARSHALL, J. R. Arkansas Power & Light Co. 83/01/04 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 3pp 17256 116 24X Fiche 50-313, 83/02/14, 8302230588

8302230538 Informs of new program to enable more timely notification of insp results by Vendor Program Branch. Repts will be forwarded through NRC resident inspector, w/encl distribution ticket. Vendor rept info should be used in util assessments. COLLINS, J. T. Region 4, Office of Director 83/02/16 CAVANAUGH, W. Arkansas Power & Light Co. 3pp 17256 310 24X Fiche 50-313, 83/02/16, 8302230538

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 100FR20 302 " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302170133 Forwards LER 83-001/03L-0. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/01 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 1p 17180 215 24X Fiche 50-368, 83/02/01, 8302170133

--8302170136 LER 83-001/03L-0 on 830106, during Mode 1, control room emergency air conditioner 2VE-1B failed surveillance test due to excessive compressor cycling. Caused by low freon due to leak on discharge relief valves. Valve will be replaced. ROGERS, P. Arkansas Power & Light Co. 83/02/01 Region 4, Office of Director 2pp 17180 216 24X Fiche 50-368, 83/02/01, 8302170133

8302170372 Forwards LER 83-003/03L-0. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/03 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 1p 17187 133 24X Fiche 50-368, 83/02/03, 8302170372

--8302170377 LER 83-003/03L-0 on 830109, alarm received on svc water monitor 2RITS-1493 for shutdown cooling HX, indicating tube leak. Cause undetermined. Tubes plugged. ROGERS, P. Arkansas Power & Light Co. 83/02/08 Region 4, Office of Director 2pp 17187 134 24X Fiche 50-368, 83/02/03, 8302170372

8302170232 Forwards LER 83-004/03L-0. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/04 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 1p 17187 102 24X Fiche 50-368, 83/02/04, 8302170232

--8302170237 LER 83-004/03L-0, on 830114, while in Mode 5, fire barrier penetration found unsealed. Probably caused by personnel error. Fire watch posted. Penetration sealed & inspected. ROGERS, P. Arkansas Power & Light Co. 83/02/04 Region 4, Office of Director 2pp 17187 103 24X Fiche 50-368, 83/02/04, 8302170232.

8302170063 Requests schedule for correction of core protection calculator software discrepancy noted in LER 82-026/03L-0. Response requested within 30 days. CLARK, R. A. Operating Reactors Branch 3 83/02/06 CAVANAUGH, W. Arkansas Power & Light Co. 3pp 17191 069. 24X Fiche 50-368, 83/02/06, 8302170063

8302230456 Forwards LER 83-002/03L-0. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/14 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 1p 17246 046. 24X Fiche 50-368, 83/02/14, 8302230456

DOCKETED ITEMS

20

--8302230473 LER 83-002/03L-0 on 830106, control room indication lost for intake structure exhaust fan 2VEE-25B Caused by opened fuse due to grounded motor power cable Cable replaced & exhaust fan returned to svc
ROGERS, P Arkansas Power & Light Co 83/02/01 Region 4,
Office of Director 1p 17246 047 24X Fiche 50-368, 83/02/14,
8302230456

8302230168 PNO-IV-83-006 on 830216, fire in startup transformer 3 caused manual trip from 5% power Transformer 2 placed in svc & fire promptly extinguished.
JOHNSON, W D, CUMMINS, J E Region 4, Office of Director 83/02/17
1p 17245 091 24X Fiche 50-368, 83/02/17, 8302230168

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Bvc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302150661 Forwards IE Insp Rept 50-369/82-44 on 821130-1202 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/07
TUCKER, H B Duke Power Co 2pp 17154 074 24X
Fiche 50-369, 83/01/07, 8302150661

--8302150665 IE Insp Rept 50-369/82-44 on 821130-1202 No noncompliance noted, Major areas inspected emergency preparedness exercise.
CLINE, W E, MARSTON, R R, JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/01/04 9pp, 17154 076, 24X
Fiche 50-369, 83/01/07, 8302150661

8302010641 Forwards supplemental pages to Rev 3 of Safeguards Contingency Plan, Pages withheld (ref 10CFR73, 21).
TUCKER, H B Duke Power Co 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16980 041 24X
Fiche 50-369, 83/01/25, 8302010641

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for QL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Bvc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221, 226, 24X
Fiche 50-000, 83/02/01, 8301210340

8302100212 Forwards Rev 14 to security plan re implementation of departmental reorganization Rev withheld (ref 10CFR2 790).
TUCKER, H B Duke Power Co 83/02/06, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17112 287, 24X
Fiche 50-369, 83/02/06, 8302100212

8302170300 Forwards IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on 830124-28 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/02/14,
TUCKER, H B Duke Power Co 2pp 17177 048 24X
Fiche 50-369, 83/02/14, 8302170300

--8302170304 IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on 830124-28 No noncompliance noted Major areas inspected security plan & implementing instructions & security organization response Details withheld (ref 10CFR73 21)
MCGUIRE, D R, TILLMAN, A, Division of Project & Resident Programs 83/02/11 1p, 17177 050, 24X Fiche 50-369, 83/02/14, 8302170300.

8302220032 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/02/14 Document
Management Branch, 1p, 17227 289 24X Fiche: 50-369, 83/02/14,
8302220032

--8302220040 Forwards public version of Rev 9 to emergency plan
TUCKER, H B Duke Power Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director, ADENBAM, E O Licensing Branch 4, 2pp, 17227, 290 24X Fiche: 50-369, 83/02/14, 8302220032

--8302220047 Public version of Rev 9 to emergency plan.
MCINTOSH, H D, Duke Power Co, 83/01/31, 40pp, 17227:292 24X
Fiche 50-369, 83/02/14, 8302220032.

8302220072 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document
Management Branch 1p, 17234 053 24X Fiche 50-369, 83/02/14,
8302220072

--8302220087 Forwards public version of revised emergency plan implementing procedures, including PT/O/A/4600/06 re exercises & drills & PT/O/A/4600/11 re function check of emergency vehicle & equipment
TUCKER, H B Duke Power Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director, ADENBAM, E O Licensing Branch 4 2pp 17234 054 24X Fiche 50-369, 83/02/14, 8302220072

--8302220093 Public version of revised emergency plan implementing procedures, including Procedures PT/O/A/4600/06 re exercises & drills & PT/O/A/4600/11 re function check of emergency vehicle & equipment
* Duke Power Co 83/01/17 117pp 17234 056 24X
Fiche 50-369, 83/02/14, 8302220072

J. Insurance & indemnity information

8302090413 Requests reimbursement of pro rata portion of indemnity fees paid due to termination of NRC indemnification under Price-Anderson Act on 821115
HOUSER, D R Duke Power Co 83/02/04 SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance) 1p, 17070 362 24X
Fiche 50-000, 83/02/04, 8302090413

8302100149 Amend 6 to Indemnity Agreement B-83, deleting Item 3 of attachment & substituting new Item 3 for Licenses 8NM-1773, 8NM-1885 & NPF-9
SALTZMAN, J. Assistant Director for State & Licensee Relations 83/02/04 1p, 17134 278 24X Fiche 50-369, 83/02/04, 8302100149.

8302250422 Forwards executed Amend 6 to Indemnity Agreement B-83
TUCKER, H B Duke Power Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director SALTZMAN, J Assistant Director for State & Licensee Relations 2pp, 17297 037 24X
Fiche 50-369, 83/02/16, 8302250422.

K Utility Final Safety Analysis Report (FSAR) & amends

8302230424 Application to amend Licenses NPF-9 & CPPR-84, consisting of Rev 45 to FSAR
TUCKER, H B Duke Power Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director, ADENBAM, E O Licensing Branch 4 2pp, 17245 260 24X Fiche 50-369, 83/02/16, 8302230424

--8302230431 Rev 45 to FSAR
* Duke Power Co, 83/02/16 66pp 17245 262 24X
Fiche 50-369, 83/02/16, 8302230424

P Operating license stage documents & correspondence

8302070332 Forwards steam generator monitoring programs, Mods to program subj to NRC approval
TUCKER, H B Duke Power Co 83/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director, ADENBAM, E O Licensing Branch 4 2pp, 17031 002 24X Fiche: 50-369, 83/02/03, 8302070332.

--8302070334 Steam generator monitoring programs.
* Duke Power Co, 83/02/03 9pp 17031:004 24X
Fiche 50-369, 83/02/03, 8302070332.

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing, 83/02/03, Atomic Safety and Licensing Board Panel 6pp 17143:293, 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utilis Generating Co, BC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators.
CHESTNUT, S H, Licensing Branch 1, 82/03/15, YOUNGBLOOD, B J, Licensing Branch 1 46pp, 17143:298, 24X Fiche 50-000, 83/02/03, 8302100512

8302150396 Submits response to NRC concerns re elimination of boron injection tank from facility Decision to reduce boron concentration due to difficulty in removing tank, 4/ten marked-up oversite drawings, Aperture cards are in PDR.
TUCKER, H B Duke Power Co 83/02/03, DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 2pp 17157, 113, 24X Fiche 50-370, 83/02/03, 8302150396

DOCKETED ITEMS

8302089295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PMRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc. 11pp 17290 247 24X
Fiche: 50-000, 83/02/08, 8302089295

8302089304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc. 9pp 17234 234 24X
Fiche: 50-000, 83/02/08, 8302089304

8302090083 Generic Ltr 83-10D to all licensees w/Westinghouse designed NSSS (except Yankee Atomic Electric Co) re resolution of TMI Action Item 11.K.3.3: "Automatic Trip of Reactor Coolant Pump" Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/08 Southern
California Edison Co. 31pp. 17290.262 24X Fiche 50-000, 83/02/08, 8302090083

8302170042 Forwards "Calculational Methodology for Equipment Qualification Radiation Dose," per 830131 telcon.
TUCKER, H. B. Duke Power Co. 83/02/14, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch 4. 1p. 17183 027. 24X Fiche: 50-369, 83/02/14, 8302170042

--8302170047 "Calculational Methodology for Equipment Qualification Radiation Dose."
Duke Power Co. 83/02/14 30pp. 17183-028 24X
Fiche 50-369, 83/02/14, 8302170047

8302170140 Forwards Rev 6 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," in response to NRC 830124 request for addl info.
TUCKER, H. B. Duke Power Co. 83/02/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch 4. 1p. 17193 186. 24X Fiche 50-369, 83/02/15, 8302170140

--8302170144 Rev 6 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station."
Duke Power Co. 83/02/15, 33pp 17193:187 24X
Fiche: 50-369, 83/02/15, 8302170140

8302230424 Application to amend Licenses NPF-9 & CPPR-84, consisting of Rev 43 to FBAR
TUCKER, H. B. Duke Power Co. 83/02/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch 4. 2pp. 17243 260 24X Fiche: 50-369, 83/02/16, 8302230424

8302240302 Application for amend to License NPF-9, authorizing transfer of spent fuel between Unit 1 & Unit 2. Original issuance of license for Unit 2 should include sub j provision
TUCKER, H. B. Duke Power Co. 83/02/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch 4. 3pp. 17273-345. 24X Fiche 50-369, 83/02/18, 8302240302

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20 will be forwarded in Apr 1983.
ELLIOTT, J. L. Duke Power Co. 83/02/18 BIRKEL, R. Office of Nuclear Reactor Regulation, Director. 2pp. 17296 219 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250400 Rev DA to Nuclear Guide 1.61: "Damping Values for Seismic Design of Nuclear Power Plants."
Duke Power Co. 83/01/06 7pp 17296:217 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250417 Rev 1A to Nuclear Guide 1.111, "Methods for Estimating Atmospheric Transport & Dispersion of Gaseous Effluents in Routine Releases from Light-Water-Cooled Reactors."
EDMONDS, R. F. Duke Power Co. 83/01/06 49pp. 17296-248 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250424 Rev 1A to Nuclear Guide 1.143, "Design Guidance for Radwaste Mgt Sys. Structures & Components Installed in Light-Water-Cooled Nuclear Power Plants"
MILLER, R. E. Duke Power Co. 83/01/06 14pp. 17296.297. 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250436 Rev 1 to Nuclear Guide 1.147, "Inservice Insp Code Case Acceptability, ASME Section XI, Div 1."
DALTON, D. W. Duke Power Co. 83/01/06. 7pp. 17296 311 24X
Fiche: 50-000, 83/02/18, 8302250391

8302240285 Discusses turbine trip test conducted during startup. Util agrees description of test in startup rept does not accurately portray test. Revised description encl
TUCKER, H. B. Duke Power Co. 83/02/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch 4. 3pp 17274 073 24X Fiche 50-369, 83/02/22, 8302240285

8302240332 Advises that cold leg RCS temp not justified on basis of pressurized thermal shock issue & App Q concerns. Addition of steam generator pressure instrumentation proposed
TUCKER, H. B. Duke Power Co. 83/02/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch 4. 5pp 17274 045 24X Fiche 50-369, 83/02/22, 8302240332

0 Inspection reports, IE Bulletins & correspondence

8302190661 Forwards IE Insp Rept 50-369/82-44 on 821130-1202 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/01/07
TUCKER, H. B. Duke Power Co. 2pp. 17154 074 24X
Fiche 50-369, 83/01/07, 8302190661

--8302190665 IE Insp Rept 50-369/82-44 on 821130-1202 No noncompliance noted. Major areas inspected: emergency preparedness exercise. CLINE, W. E., MARSTON, R. R., JENKINS, O. R. Division of Emergency Preparedness & Materials Safety 83/01/04 9pp 17154 076 24X
Fiche 50-369, 83/01/07, 8302190661

8302190669 Forwards IE Insp Repts 50-369/82-47 & 50-370/82-40 on 821120-1220 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/01/25
TUCKER, H. B. Duke Power Co. 2pp 17154 103 24X
Fiche: 50-369, 83/01/25, 8302190669

--8302190676 IE Insp Repts 50-369/82-47 & 50-370/82-40 on 821120-1220 No noncompliance noted. Major areas inspected: plant operations, surveillance testing, maint activities, IE bulletins & followup on previous inspector identified items.
ORDERS, W., IGNATONIS, A., KRUD, H. Division of Project & Resident Programs 83/01/25 5pp 17154 105 24X Fiche 50-369, 83/01/25, 8302190669

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc. 11Bpp 17023-160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp. 17074 095. 24X Fiche: 50-000, 83/01/28, 8212060361

8302190442 Ack receipt of IE Insp Repts 50-369/82-46 & 50-370/82-39 No proprietary info
TUCKER, H. B. Duke Power Co. 83/01/28 O'REILLY, J. P. Region 2, Office of Director 1p 17158.147 24X Fiche 50-369, 83/01/28, 8302190442

8302190526 Responds to IE Bulletin 82-04 re deficiencies in primary containment electrical penetration assemblies. No Bunker-Ramo electrical penetrations using hard epoxy module design installed or envisioned at facilities.
TUCKER, H. B. Duke Power Co. 83/02/01 O'REILLY, J. P. Region 2, Office of Director. 1p 17156-222 24X Fiche: 50-369, 83/02/01, 8302190526

8302190697 Ack receipt of IE Insp Rept 50-369/82-44 No proprietary info.
TUCKER, H. B. Duke Power Co. 83/02/02 O'REILLY, J. P. Region 2, Office of Director 1p. 17150:356. 24X Fiche: 50-369, 83/02/02, 8302190697

8302170300 Forwards IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on 830124-28. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/14
TUCKER, H. B. Duke Power Co. 2pp. 17177 048. 24X
Fiche: 50-369, 83/02/14, 8302170300

--8302170304 IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on 830124-28. No noncompliance noted. Major areas inspected: security plan & implementing instructions & security organization response. Details withheld (ref 10CFR73.21).
MCGUIRE, D. R., TILLMAN, A. Division of Project & Resident Programs. 83/02/11. 1p 17177.050. 24X Fiche: 50-369, 83/02/14, 8302170300.

DOCKETED ITEMS

25

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 11pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302180316 Forwards monthly operating rept for Jan 1983.
TUCKER, H. B. Duke Power Co 83/02/15 Director's Office, Office
of Inspection and Enforcement 1p 17213 392 24X
Fiche 50-369, 83/02/15, 8302180316

--8302180319 Monthly operating rept for Jan 1983.
REAVIS, J. A. Duke Power Co 83/02/15 6pp 17213 353. 24X
Fiche 50-369, 83/02/15, 8302180319

B Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low
voltage circuit breakers w/solid state trip devices Units
from San Onofre 2 & 3 failed due to long-term degradation of
filter capacitor C205 Suspect trip units should be tested.
DUVALL, D. B. Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.)
82/12/10 STELLD, V. Director's Office, Office of Inspection and
Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302140120 Forwards LER 82-082/03L-0
TUCKER, H. B. Duke Power Co 83/01/28 O'REILLY, J. P. Region 2,
Office of Director 1p 17140 103 24X Fiche 50-369, 83/01/28,
8302140120.

--8302140124 LER 82-082/03L-0 on 821231, while in Mode 5, three instrument
loops found out of tolerance Caused by differential pressure
transmitter drift Transmitters recalibr
NARDOCI, P. B. Duke Power Co 83/01/28 Region 2, Office of
Director 1p 17140 104 24X Fiche 50-369, 83/01/28, 8302140120.

8302230592 Forwards LER 83-002/03L-0
TUCKER, H. B. Duke Power Co 83/02/09 O'REILLY, J. P. Region 2,
Office of Director 1p 17256 122. 24X Fiche 50-369, 83/02/09,
8302230592

--8302230603 LER 83-002/03L-0 on 830110, while in Mode 1, pressurizer
heater group 1B failed to energize in manual & declared
inoperable Cause Under investigation Design defect indicated
in vacuum breaker contractor coil circuit.
NARDOCI, P. B. Duke Power Co 83/02/09 Region 2, Office of
Director 1p 17256 123. 24X Fiche 50-369, 83/02/09, 8302230592

8302280082 Forwards LER 83-003/03L-0
TUCKER, H. B. Duke Power Co 83/02/15 O'REILLY, J. P. Region 2,
Office of Director 1p 17307 186. 24X Fiche 50-369, 83/02/15,
8302280082

--8302280089 LER 83-003/03L-0 on 830117, during Mode 1 weekly sampling
collection, conventional waste water treatment composite
sampler found inoperable Caused by frozen sample line due to
improper installation of insulation, insulation reinstalled
NARDOCI, P. B. Duke Power Co 83/02/15 Region 2, Office of
Director 1p 17307 187 24X Fiche 50-369, 83/02/15, 8302280082.

V. Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants
for OLs, NBS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl.
EISENHUT, D. O. Division of Licensing, 83/01/31, Consolidated
Edison Co. of New York, Inc. 14pp. 17347 177. 24X
Fiche 50-000, 83/01/31, 8301310203.

8302240068 Responds to Generic Ltr 83-01, Operator licensing exam
schedules listed.
TUCKER, H. B. Duke Power Co 83/02/21 EISENHUT, D. O. Division of
Licensing, 2pp. 17281 041. 24X Fiche 50-000, 83/02/21, 8302240068.

DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302100512 Board Notification 83-11 forwards info indicating onset of
increased turbulence & acceleration of tube wear occurring
at feed flow rates of 50% for Model D/2 & D/3 steam
generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T. M. Assistant Director for Licensing, 83/02/03 Atomic
Safety and Licensing Board Panel 4pp 17143 293. 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co
SC Electric & Gas Co, Westinghouse, TVA & representatives of
Swedish nuclear power plant & Krsko in Bethesda, MD re
accelerated tube wear on Model D steam generators
CHESTNUT, S. H. Licensing Branch 1 82/03/15 YOUNGBLOOD, B. J.
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03,
8302100512.

8302150396 Submits response to NRC concerns re elimination of boron
injection tank from facility Decision to reduce boron
concentration due to difficulty in removing tank w/ten
marked-up oversize drawings Aperture cards are in PDR.
TUCKER, H. B. Duke Power Co 83/02/03 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director ADENBAM, E. O. Licensing Branch
4 2pp 17137 113. 24X Fiche 50-370, 83/02/03, 8302150396

8302150522 Responds to NRC concerns re elimination of boron injection
tank from facility, per 830128, 0201 & 02 telcons. Plant
considerations reducing Unit 1 boron concentration did not
involve concerns for public health/safety w/o encl drawings.
TUCKER, H. B. Duke Power Co. 83/02/03. DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch
4 2pp. 17136 082 24X Fiche 50-370, 83/02/03, 8302150522.

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PHRs re review of
C-E Owners Group emergency procedures guideline program. Svc
list encl.
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247. 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed
NBS re resolution of TMI Action Item 11 K 3.5, "Automatic
Trip of Reactor Coolant Pumps."
EISENHUT, D. O. Division of Licensing, 83/02/08, Baltimore Gas &
Electric Co 30pp. 17290 212 24X Fiche 50-000, 83/02/08,
8302090080.

8302170042 Forwards "Calculational Methodology for Equipment
Qualification Radiation Dose," per 830131 telcon.
TUCKER, H. B. Duke Power Co 83/02/14 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director ADENBAM, E. O. Licensing Branch
4. 1p. 17183 027. 24X Fiche 50-369, 83/02/14, 8302170042

--8302170047 "Calculational Methodology for Equipment Qualification
Radiation Dose"
* Duke Power Co. 83/02/14 30pp 17183 028. 24X
Fiche 50-369, 83/02/14, 8302170042

8302170327 Forwards until 830208 ltr to DDE providing comments on
proposed contract for disposal of spent nuclear fuel &/or
high level radwaste Affirms until intention to execute DOE
agreement per Section 302(b) of Waste Act of 1983.
TUCKER, H. B. Duke Power Co 83/02/14 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. ADENBAM, E. O. Licensing Branch
4. 13pp. 17184 161. 24X Fiche 50-370, 83/02/14, 8302170327.

8302170140 Forwards Rev 6 to "Analysis of Hydrogen Control Measures
at McGuire Nuclear Station," in response to NRC 830124
request for addl info.
TUCKER, H. B. Duke Power Co. 83/02/15 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director ADENBAM, E. O. Licensing Branch
4. 1p 17195 186. 24X Fiche 50-369, 83/02/15, 8302170140.

--8302170144 Rev 6 to "Analysis of Hydrogen Control Measures at McGuire
Nuclear Station"
* Duke Power Co. 83/02/15. 35pp 17195 187. 24X
Fiche 50-369, 83/02/15, 8302170140.

8302230424 Application to amend Licenses NPF-9 & CPPR-84, consisting of
Rev 45 to FBAR.
TUCKER, H. B. Duke Power Co. 83/02/16 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. 2pp. 17245 260. 24X
Fiche 50-369, 83/02/16, 8302230424.

DOCKETED ITEMS

8302230516 Forwards responses & clarifications to NRC concerns re B4C control rod surveillance, reactor vessel nozzle under clad cracking, natural circulation training, steam generator mod & control room design review
TUCKER, H B Duke Power Co 83/02/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4. 5pp 17256 356 24X Fiche 50-370, 83/02/18, 8302230516

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20 will be forwarded in Apr 1983.
ELLIOTT, J L Duke Power Co. 83/02/18 BIRKEL, R Office of Nuclear Reactor Regulation, Director. 2pp 17296 215 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250400 Rev DA to Nuclear Guide 1 61, "Damping Values for Seismic Design of Nuclear Power Plants."
* Duke Power Co 83/01/06 7pp 17296 217 24X
Fiche 50-000, 83/02/18, 8302250391

--8302250417 Rev 1A to Nuclear Guide 1 111, "Methods for Estimating Atmospheric Transport & Dispersion of Gaseous Effluents in Routine Releases from Light-Water-Cooled Reactors"
EDMONDS, R F Duke Power Co 83/01/06 49pp. 17296 248 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250424 Rev 1A to Nuclear Guide 1 143, "Design Guidance for Radwaste Mgt Sys, Structures & Components Installed in Light-Water-Cooled Nuclear Power Plants."
MILLER, R E. Duke Power Co. 83/01/06 14pp. 17296 297 24X
Fiche: 50-000, 83/02/18, 8302250391

--8302250436 Rev 1 to Nuclear Guide 1 147, "Inservice Insp Code Case Acceptability, ASME Section XI, Div 1"
DALTON, D W Duke Power Co 83/01/06 7pp 17296 311. 24X
Fiche 50-000, 83/02/18, 8302250391

8302240332 Advises that cold leg RCS temp not justified on basis of pressurized thermal shock issue & App Q concerns Addition of steam generator pressure instrumentation proposed
TUCKER, H B Duke Power Co. 83/02/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4. 5pp. 17274 045 24X Fiche 50-369, 83/02/22, 8302240332

8302280203 Responds to 10CFR50.49, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Plants." Any requirement for completion of further analysis to be included in OL as condition of exceeding 3% power level.
TUCKER, H B Duke Power Co 83/02/23 DENTON, H R. Office of Nuclear Reactor Regulation, Director. ADENBAM, E Q. Licensing Branch 4. 5pp. 17306 067 24X Fiche 50-370, 83/02/23, 8302280203

F Security, medical, emergency & fire protection plans

8302010641 Forwards supplemental pages to Rev 3 of Safeguards Contingency Plan Pages withheld (ref 10CFR73.21)
TUCKER, H B Duke Power Co 83/01/25. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p 16780 041. 24X
Fiche. 50-369, 83/01/25, 8302010641

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl.
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc. 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302100212 Forwards Rev 14 to security plan re implementation of departmental reorganization Rev withheld (ref 10CFR2 790)
TUCKER, H B. Duke Power Co 83/02/06 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p 17112 287 24X
Fiche: 50-369, 83/02/06, 8302100212

8302170300 Forwards IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on 830124-28. No noncompliance noted.
DANCE, M C Division of Project & Resident Programs 83/02/14. TUCKER, H B. Duke Power Co. 2pp. 17177 048. 24X
Fiche: 50-369, 83/02/14, 8302170300

--8302170304 IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on 830124-28. No noncompliance noted Major areas inspected: security plan & implementing instructions & security organization response. Details withheld (ref 10CFR73.21)
MCQUIRE, D R Division of Project & Resident Programs. 83/02/11. 1p 17177 050. 24X Fiche: 50-369, 83/02/14, 8302170300.

8302220032 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records. 83/02/14 Document Management Branch. 1p 17227 289 24X Fiche: 50-369, 83/02/14, 8302220032

--8302220040 Forwards public version of Rev 9 to emergency plan
TUCKER, H B Duke Power Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4. 2pp 17227 290 24X Fiche 50-369, 83/02/14, 8302220032

--8302220047 Public version of Rev 9 to emergency plan
MCINTOSH, M D Duke Power Co 83/01/31 40pp 17227 292 24X
Fiche 50-369, 83/02/14, 8302220032

8302220072 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/14 Document Management Branch 1p 17234 053 24X Fiche 50-369, 83/02/14, 8302220072

--8302220087 Forwards public version of revised emergency plan implementing procedures, including PT/D/A/4600/06 re exercises & drills & PT/D/A/4600/11 re function check of emergency vehicle & equipment
TUCKER, H B Duke Power Co 83/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4. 2pp 17234 054 24X Fiche: 50-369, 83/02/14, 8302220072

--8302220093 Public version of revised emergency plan implementing procedures, including Procedures PT/D/A/4600/06 re exercises & drills & PT/D/A/4600/11 re function check of emergency vehicle & equipment
* Duke Power Co. 83/01/17 117pp 17234 056 24X
Fiche 50-369, 83/02/14, 8302220072

J Insurance & indemnity information

8302090413 Requests reimbursement of pro rata portion of indemnity fees paid due to termination of NRC indemnification under Price-Anderson Act on 82115
HQUSE, D R Duke Power Co 83/02/04 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 1p 17070 362. 24X
Fiche 50-000, 83/02/04, 8302090413

8302100149 Amend 4 to Indemnity Agreement B-83, deleting Item 3 of attachment & substituting new Item 3 for Licensee SNM-1773, SNM-1885 & NPF-9
SALTZMAN, J. Assistant Director for State & Licensee Relations 83/02/04 1p 17134 278 24X Fiche 50-369, 83/02/04, 8302100149.

8302250422 Forwards executed Amend 4 to Indemnity Agreement B-83
TUCKER, H B. Duke Power Co 83/02/16 DENTON, H R. Office of Nuclear Reactor Regulation, Director SALTZMAN, J Assistant Director for State & Licensee Relations 2pp. 17297 037 24X
Fiche: 50-369, 83/02/16, 8302250422

K Utility Final Safety Analysis Report (FSAR) & amends

8302230424 Application to amend Licenses NPF-9 & CPPR-84, consisting of Rev 45 to FSAR
TUCKER, H B. Duke Power Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q. Licensing Branch 4. 2pp 17245 260. 24X Fiche 50-369, 83/02/16, 8302230424

--8302230431 Rev 45 to FSAR
* Duke Power Co 83/02/16 66pp 17245 262 24X
Fiche 50-369, 83/02/16, 8302230424

P. Operating license stage documents & correspondence

8302240285 Discusses turbine trip test conducted during startup. Util agrees description of test in startup rept does not accurately portray test Revised description encl.
TUCKER, H B Duke Power Co. 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4. 3pp 17274 073. 24X Fiche. 50-369, 83/02/22, 8302240285

Q. Inspection reports, IE Bulletins & Correspondence

8302150288 Ack receipt of 821203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/82-27 Acceptable alternate to ANS/ANS 56 re containment sys leakage testing not provided
LEWIS, R C. Division of Project & Resident Programs. 83/01/25 TUCKER, H B Duke Power Co. 1p 17157 192. 24X
Fiche: 50-370, 83/01/25, 8302150288.

--8302150295 Responds to NRC 821029 ltr re violations noted in IE Insp Rept 50-370/82-27. Evaluation performed to determine effect of outgassing of trapped air on test results. No corrective actions necessary
TUCKER, H B. Duke Power Co 82/12/03 O'REILLY, J. P. Region 2, Office of Director. 2pp 17157 193 24X Fiche: 50-370, 83/01/25, 8302150288

DOCKETED ITEMS

281

--8302150360 Forwards IE Insp Rept 50-370/82-27 on 820922-28 & notice of violation
DANCE, H C Division of Project & Resident Programs 82/10/29
TUCKER, H B Duke Power Co 2pp 17157 195 24X
Fiche 50-370, 83/01/25, 8302150288

--8302150298 Notice of violation from insp on 820922-28
+ Division of Project & Resident Programs 82/10/29 ip
17157 197 24X Fiche 50-370, 83/01/25, 8302150288

--8302150304 IE Insp Rept 50-370/82-27 on 820922-28 Noncompliance noted
Failure to reduce containment pressure to less than 85% of
integrated leak rate test pressure for at least 24 h prior
to performing test
WHITENER, H L, JAPE, F Division of Engineering & Radiological
Safety Programs 82/10/22 6pp 17157 198 24X
Fiche 50-370, 83/01/25, 8302150288

8302150669 Forwards IE Insp Repts 50-369/82-47 & 50-370/82-40 on
821120-1220 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/25
TUCKER, H B Duke Power Co 2pp 17154 103 24X
Fiche 50-369, 83/01/25, 8302150669

--8302150676 IE Insp Repts 50-369/82-47 & 50-370/82-40 on 821120-1220 No
noncompliance noted Major areas inspected plant operations,
surveillance testing, maint activities, IE bulletins &
followup on previous inspector identified items.
ORDERS, W., IGNATONIS, A., KRUG, H Division of Project & Resident
Programs 83/01/25 5pp 17154 103 24X Fiche 50-369, 83/01/25,
8302150669

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302150074 Forwards IE Insp Rept 50-370/83-05 on 830104-07 No
noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/26
TUCKER, H B Duke Power Co 2pp 17148 019 24X
Fiche 50-370, 83/01/26, 8302150074

--8302150084 IE Insp Rept 50-370/83-05 on 830104-07 No noncompliance
noted Major areas inspected, licensee action on previous
enforcement matters & independent insp effort
GIBBONS, T D, CONLON, T E Division of Project & Resident Programs
83/01/25 3pp 17148 021 24X Fiche 50-370, 83/01/26, 8302150074

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Overheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150442 Ack receipt of IE Insp Repts 50-369/82-46 & 50-370/82-39
No proprietary info
TUCKER, H B Duke Power Co 83/01/28 O'REILLY, J P Region 2,
Office of Director ip 17158 147 24X Fiche 50-369, 83/01/28,
8302150442

8302150612 Ack receipt of IE Insp Rept 50-370/82-38. No proprietary
info
TUCKER, H B Duke Power Co 83/01/28 O'REILLY, J P Region 2,
Office of Director ip 17156 279 24X Fiche 50-370, 83/01/28,
8302150612

8302150675 Ack receipt of IE Insp Rept 50-370/82-35 No proprietary
info
TUCKER, H B Duke Power Co 83/01/28 O'REILLY, J P Region 2,
Office of Director ip 17154 122 24X Fiche 50-370, 83/01/28,
8302150675

8302150526 Responds to IE Bulletin 82-04 re deficiencies in primary
containment electrical penetration assemblies No Bunker-
Ramo electrical penetrations using hard epoxy module design
installed or envisioned at facilities
TUCKER, H B Duke Power Co 83/02/01 O'REILLY, J P Region 2,
Office of Director ip 17156 222 24X Fiche 50-369, 83/02/01,
8302150526

8302170300 Forwards IE Safeguards Insp Repts 50-369/83-03 &
50-370/83-06 on 830124-28 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/02/14
TUCKER, H B Duke Power Co 2pp 17177 048 24X
Fiche 50-369, 83/02/14, 8302170300

--8302170304 IE Safeguards Insp Repts 50-369/83-03 & 50-370/83-06 on
830124-28 No noncompliance noted Major areas inspected
security plan & implementing instructions & security
organization response Details withheld (ref 10CFR73.21)
MCGUIRE, D R, TILLMAN, A Division of Project & Resident Programs
83/02/11 ip 17177 050 24X Fiche 50-369, 83/02/14, 8302170300

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363.

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts, "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366.

B Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low
voltage circuit breakers w/solid state trip devices Units
from San Onofre 2 & 3 failed due to long-term degradation of
filter capacitor C205. Suspect trip units should be tested
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd).
82/12/10 STELLO, V Director's Office, Office of Inspection and
Enforcement. 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for DLs, NBS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses. Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp. 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302240068 Responds to Generic Ltr 83-01 Operator licensing exam
schedules listed
TUCKER, H B Duke Power Co 83/02/21 EISENHUT, D O Division of
Licensing 2pp 17281 041 24X Fiche 50-000, 83/02/21, 8302240068

DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170011 Forwards audit repts on seismic & dynamic qualification of
safety-related equipment Repts also available in PDR.
BAGCHI, O Equipment Qualification Branch 83/02/02. NOONAN, V B
Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000, 83/02/02, 8302170011

--8103160808 Trip rept of 801117-21 site visit in Ottawa, IL re seismic
criteria implementation
CHEN, P Y Equipment Qualification Branch. 81/02/25.
ROBERTSON, Z R Equipment Qualification Branch 43pp 17205 325.
24X Fiche 50-000, 83/02/02, 8302170011

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACBHR), applicants for DL & holders of CP re BER of
"Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable Svc list encl
EISENHUT, D O, Division of Licensing. 83/02/08 Commonwealth
Edison Co 6pp. 17234 245. 24X Fiche 50-000, 83/02/08, 8302080301

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan
implementing procedures.
FELTON, J M Division of Rules and Records. 83/01/27. Document
Management Branch. ip 17043 230 24X Fiche 50-000, 83/01/27,
8302040033

--8302040037 Forwards public version of revised Emergency Plan
Implementing Procedures ED-29 re meteorological maint
programs & ED-25 re computer codes for access to ODCS
programs
FAUCHER, J E Commonwealth Edison Co. 83/01/07. DENTON, H. R. NRC
- No Detailed Affiliation Given ip. 17043 231. 24X
Fiche 50-000, 83/01/27, 8302040033

DOCKETED ITEMS

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to DDCB programs Revised index encl
LITERSKI, L. A. Commonwealth Edison Co. 83/01/06 11pp
17043-232 24X Fiche 50-000, 83/01/27, 8302040033

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221-226 24X
Fiche 50-000, 83/02/01, 8301210340.

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-1118 guidelines valid
KEPPLER, J. O. Region 3, Office of Director 83/02/04, REED, C. Commonwealth Edison Co. App. 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities. Requests contradictory to NRC directive for simplification.
REED, C. Commonwealth Edison Co. 82/12/09, KEPPLER, J. O. Region 3, Office of Director. 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302150647 Ack receipt of 830103 ltr transmitting util scope & objectives for facility emergency exercise rescheduled for Jul 1983. Site assembly w/accountability should be added to list of supporting objectives Meeting invitation accepted
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/08 REED, C. Commonwealth Edison Co. 1p 17150, 346 24X Fiche 50-373, 83/02/08, 8302150647

--8302150657 Forwards scope & objectives for 830322 emergency exercise Primary objective is to demonstrate capability to implement site emergency plan in cooperation w/State of IL plan for radiological accidents
NELLS, C. A. Commonwealth Edison Co. 83/01/03, HIND, J. Division of Emergency Preparedness & Operational Support. 3pp. 17150, 347, 24X Fiche 50-373, 83/02/08, 8302150647

8302180442 Forwards IE Safeguards Insp Rept 50-373/83-03 on 830110-14, HIND, J. A. Region 3, Office of Director 83/02/11, REED, C. Commonwealth Edison Co. 2pp 17215 174, 24X Fiche 50-373, 83/02/11, 8302180442.

--8302180457 IE Safeguards Insp Rept 50-373/83-03 on 830110-14 Noncompliance noted: failure to conduct testing of some search equipment & equipment lacked safeguard capability. Details withheld (ref 10CFR73.21)
BELANGER, J. L., KNICELEY, J. R., PIRTLE, O. L. Region 3, Office of Director. 83/02/10 2pp 17215 176 24X Fiche 50-373, 83/02/11, 8302180442

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 83/02/15, Document Management Branch 1p. 17223-218, 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager."
MOORE, R. D. Commonwealth Edison Co. 83/01/03 DENTON, H. R. NRC - No Detailed Affiliation Given. 1p 17223-219, 24X Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager."
NELLS, C. A. Commonwealth Edison Co. 83/02/02, 68pp 17223-220, 24X Fiche 50-000, 83/02/15, 8302180102.

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities per util 830128 request.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/18, REED, C. Commonwealth Edison Co. 2pp. 17291-072, 24X Fiche 50-000, 83/02/18, 8302250349.

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities. Lists of locations encl.
SHARTZ, E. D. Commonwealth Edison Co. 83/01/28, KEPPLER, J. O. Region 3, Office of Director. App. 17291-074, 24X Fiche 50-000, 83/02/18, 8302250349.

G Adjudicatory correspondence

8302180014 Completes NRC response to TC Fahnes 820324 petition & 820503 amend on behalf of State of IL under 10CFR2 206 Remaining parts of petition & amend per allegations re Unit 2 denied
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/02/09 HARTIGAN, N. Illinois, State of 1p 17207 332 24X Fiche 50-373, 83/02/09, 8302180014

--8302180020 Completes NRC response to 820428 petition on behalf of IL Friends of the Earth under 10CFR2 260 Remaining parts of petition per allegations re Unit 2 denied Director's Decision encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/02/09 ROEM, B. L. Friends of the Earth. 1p 17207, 334 24X Fiche 50-373, 83/02/09, 8302180014

--8302180023 Responds to 820728 petition on behalf of Citizens Against Nuclear Power under 10CFR2 206 Petition denied for reasons stated in encl Director's Decision
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/02/09 ODOOL, E. M. Citizens Against Nuclear Power 1p 17207 336 24X Fiche 50-373, 83/02/09, 8302180014

--8302180052 Director's Decision DD-83-1, denying remaining portions of petitions of State of IL & IL Friends of the Earth re allegations of poor const at facility.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/02/09 6pp 17207, 338 24X Fiche 50-373, 83/02/09, 8302180014

--8302180058 Notice of issuance of Director's Decision DD-83-1 under 10CFR2 206.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/02/09, 3pp 17207, 346 24X Fiche 50-373, 83/02/09, 8302180014

--8208130353 Trip rpt of 820726 meeting in Glen Ellyn, IL re safety implications of allegations concerning deficiencies in Zack Co QA & effect on HVAC sys ductwork & support design
TERAO, D. Mechanical Engineering Branch 82/07/30 BOENAK, R. J. Mechanical Engineering Branch 5pp 17208 099, 24X Fiche 50-373, 83/02/09, 8302180014

--8302180063 IE Insp Rpts 50-373/78-06 & 50-374/78-05 on 780306-14 Noncompliance noted, const practices re welding of electrical equipment supports
FOSTER, J. E., VANDEL, T. E., NAIDU, K. R. Region 3, Office of Director 78/04/24 19pp 17208 177 24X Fiche 50-373, 83/02/09, 8302180014.

H. General correspondence

8302010040 Ack receipt of 821209 ltr NRC will issue full rept explaining findings on safety of HVAC sys for facility re Citizens Against Nuclear Power 820728 petition
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/01/21 FAHNER, T. C. Illinois, State of. 2pp 16990 309 24X Fiche 50-373, 83/01/21, 8302010040

--8302010044 Forwards util 821222 response to 821203 ltr re HVAC independent review Steps taken to complete corrective actions & discrepancies identified by CF Braun Observation 02-83 encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/01/05, FAHNER, T. C. Illinois, State of 2pp 16990, 311, 24X Fiche 50-373, 83/01/21, 8302010040

K Utility Final Safety Analysis Report (FSAR) & amends

8302170187 Forwards Amend 62 to FSAR
SCHROEDER, C. W. Commonwealth Edison Co. 83/02/04, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. App. 17179 092 24X Fiche 50-373, 83/02/04, 8302170187

--8302170191 Amend 62 to FSAR
" Commonwealth Edison Co. 83/02/28 381pp 17179 096 24X Fiche 50-373, 83/02/04, 8302170187

8302280344 Forwards affidavit certifying distribution of Amend 62 to FSAR.
SCHROEDER, C. W. Commonwealth Edison Co. 83/02/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17308 079, 24X Fiche 50-373, 83/02/23, 8302280344.

P Operating license stage documents & correspondence

8302010286 Forwards "Verification Testing of Separation Between Class IE & Nonclass IE Power Cable in Raceways for Use in LaSalle Nuclear Generating Station - Units 1 & 2," for review. SCHROEDER, C W Commonwealth Edison Co. 83/01/28 SCHWENCER, A. Licensing Branch 2 1p 16973 117 24X Fiche 50-373, 83/01/28, 8302010286

--8302010292 "Verification Testing of Separation Between Class IE & Nonclass IE Power Cable in Raceways for Use in LaSalle Nuclear Generating Station - Units 1 & 2," Rev A. JOHNSON, F N, STENSON, T R, HAZELTINE, J Wyle Laboratories 83/01/20. 18pp 16973, 119 24X Fiche 50-373, 83/01/28, 8302010286

8302030097 Requests Class II fee remittance omitted from util 821118 & 1207 ltr requesting Amend 12 to License NPF-11 re exemption from primary containment inerting requirements. DIOGS, R M License Fee Management Branch. 83/01/28. DELGEORE, L D Commonwealth Edison Co 1p 17028 337 24X Fiche 50-373, 83/01/28, 8302030097

8302080199 Forwards Addendum 1 to "Verification Testing of Separation Between Class IE & Non-Class IE Power Cable in Raceways ." Temp monitoring will be provided during performance of test Comments requested by 830210 SCHROEDER, C W Commonwealth Edison Co. 83/02/04. SCHWENCER, A. Licensing Branch 2 2pp 17055, 001 24X Fiche: 50-373, 83/02/04, 8302080199

--8302080204 Addendum 1 to "Verification Testing of Separation Between Class IE & Non-Class IE Power Cable in Raceways for Use in LaSalle Nuclear Generating Station - Units 1 & 2" JOHNSON, F N, STENSON, T R, HAZELTINE, J Wyle Laboratories. 83/01/23 App. 17056 004 24X Fiche: 50-373, 83/02/04, 8302080199

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl. EISENHUT, D G Division of Licensing 83/02/08. Consolidated Edison Co of New York, Inc 11pp. 17290 247 24X Fiche: 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl. EISENHUT, D G. Division of Licensing. 83/02/08 Consolidated Edison Co of New York, Inc 9pp 17234 234. 24X Fiche 50-000, 83/02/08, 8302080304

8302230518 Suppls 821006 ltr re mod to diesel generator prelube oil pump per License Condition 2.C.21 b EMD MI 9466 mod will meet requirements in lieu of prelube pump installation SCHROEDER, C W. Commonwealth Edison Co. 83/02/14 SCHWENCER, A Licensing Branch 2. 7pp 17248, 350 24X Fiche: 50-373, 83/02/14, 8302230518

G Inspection reports, IE Bulletins & correspondence

8302040039 Adcl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re Util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR. FELTON, J M Division of Rules and Records. 82/12/30. HIATT, B. L. Ohio Citizens for Responsible Energy. 3pp. 17045, 144. 24X Fiche: 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80. HIND, J A. Division of Emergency Preparedness & Operational Support. 82/02/05. KEPPLER, J G Region 3, Office of Director. 23pp 17045, 219. 24X Fiche: 50-000, 82/12/30, 8302040039.

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request. Total insp hours for each facility added. HIND, J A Division of Emergency Preparedness & Operational Support. 82/06/08 SPEBBARD, R L Division of Project & Resident Programs 2pp. 17045, 279. 24X Fiche: 50-000, 82/12/30, 8302040039.

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item. BUCHARSKI, L Region 3, Office of Director 82/07/08. KEPPLER, J G. Region 3, Office of Director. 13pp. 17045, 281 24X Fiche: 50-000, 82/12/30, 8302040039.

8302010362 Forwards IE Insp Repts 50-373/82-52 & 50-374/82-20 on 821101-30 & notice of violation. STREETER, J F. Division of Project & Resident Programs. 83/01/19. REED, C Commonwealth Edison Co 2pp 16973, 311 24X Fiche: 50-373, 83/01/19, 8302010362

--8302010365 Notice of violation from insp on 821101-30. STREETER, J F. Division of Project & Resident Programs. 83/01/19. 1p 16973 313 24X Fiche 50-373, 83/01/19, 8302010362.

--8302010377 IE Insp Repts 50-373/82-52 & 50-374/82-20 on 821101-30. Noncompliance noted failure to follow radiation protection procedures. OULDEMOND, W, MADISON, A, RAQLIN, K Division of Project & Resident Programs 83/01/18. 13pp 16973 314 24X Fiche 50-373, 83/01/19, 8302010362.

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26. Consolidated Edison Co. of New York, Inc. 118pp 17023, 160. 24X Fiche 50-000, 83/01/26, 8212060358.

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28. Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche: 50-000, 83/01/28, 8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28. Consolidated Edison Co. of New York, Inc 110pp. 17074, 095 24X Fiche: 50-000, 83/01/28, 8212060361.

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55. IE will conduct formal presentation followed by question & answer session. Requests that participation be limited to three people. SPEBBARD, R L. Division of Engineering. 83/01/28. Commonwealth Edison Co 2pp 17008 187 24X Fiche: 50-000, 83/01/28, 8302030303.

8302040280 Forwards confirmatory measurements program data sheet for IE Insp Repts 50-373/82-53 & 50-374/82-21 for beta analysis of liquid sample not completed during onsite phase of insp. PAPERIELLO, C J Division of Emergency Preparedness & Operational Support. 83/02/01. REED, C Commonwealth Edison Co. 1p. 17020, 031. 24X Fiche: 50-373, 83/02/01, 8302040280

--8302040284 Confirmatory measurements program data sheet, to be inserted in IE Insp Repts 50-373/82-53 & 50-374/82-21 * Division of Emergency Preparedness & Operational Support 83/02/01. 1p. 17020, 032 24X Fiche 50-373, 83/02/01, 8302040280.

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels." SHWARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp 17156, 213. 24X Fiche: 50-000, 83/02/08, 8302150528.

8302170291 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-51 & 50-374/82-18. SPEBBARD, R L. Division of Engineering. 83/02/09. REED, C. Commonwealth Edison Co 1p. 17177, 057. 24X Fiche: 50-373, 83/02/09, 8302170291.

--8302170297 Responds to NRC 821222 ltr re violations noted in IE Insp Repts 50-373/82-51 & 50-374/82-18. Corrective actions: audit items requiring long-term corrective actions not closed out until all corrections complete. DELGEORE, L D. Commonwealth Edison Co. 83/01/20. KEPPLER, J G. Region 3, Office of Director. 3pp. 17177, 058. 24X Fiche: 50-373, 83/02/09, 8302170291.

8302170314 Ack receipt of 830203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-50 & 50-374/82-17. SPEBBARD, R L. Region 3, Office of Director. 83/02/09. REED, C. Commonwealth Edison Co. 1p 17177 004 24X Fiche 50-373, 83/02/09, 8302170314.

--8302170315 Responds to NRC 830106 ltr re violations noted in IE Insp Repts 50-373/82-50 & 50-374/82-17 Corrective actions: deficiency rept initiated on 821004 to record missing flow orifice & ensure that orifice will be installed. FARRAR, D L. Commonwealth Edison Co 83/02/03. KEPPLER, J G. Region 3, Office of Director 3pp 17177, 005. 24X Fiche: 50-373, 83/02/09, 8302170314.

DOCKETED ITEMS

8302180014 Completes NRC response to TG Fahnes 820324 petition & 820803 amend on behalf of State of IL under 10CFR2.206. Remaining parts of petition & amend per allegations re Unit 2 denied.
DENTON, H R. Office of Nuclear Reactor Regulation, Director
83/02/09. HARTIGAN, N. Illinois, State of ip 17207.332 24X
Fiche: 50-373, 83/02/09, 8302180014

--8302180065 IE Insp Repts 50-373/78-06 & 50-374/78-05 on 780306-14 Noncompliance noted: const practices re welding of electrical equipment supports.
FOSTER, J E, VANDEL, T E, NAIDU, K R. Region 3, Office of Director
78/04/24 19pp 17208.177 24X Fiche: 50-373, 83/02/09, 8302180014

8302180442 Forwards IE Safeguards Insp Rept 50-373/83-03 on 830110-14 HIND, J A. Region 3, Office of Director. 83/02/11. REED, C. Commonwealth Edison Co 2pp 17215.174. 24X Fiche: 50-373, 83/02/11, 8302180442.

--8302180457 IE Safeguards Insp Rept 50-373/83-03 on 830110-14. Noncompliance noted: failure to conduct testing of some search equipment & equipment lacked safeguard capability. Details withheld (ref 10CFR73.21).
BELANGER, J L, KNICELEY, J R, PIRTLE, G L. Region 3, Office of Director. 83/02/10. 2pp 17215.176 24X Fiche: 50-373, 83/02/11, 8302180442

8302280461 Forwards IE Insp Repts 50-373/82-40 & 50-374/82-10 on 820804-27 & notice of violation Description of overall mgt controls to improve QA recordkeeping required.
KEPPLER, J O. Region 3, Office of Director. 83/02/15. REED, C. Commonwealth Edison Co. 4pp 17308.024 24X Fiche: 50-373, 83/02/15, 8302280461

--8302280468 Notice of violation from insp on 820804-27 NORELIOUS, C. E. Division of Project & Resident Programs. 83/02/15. 3pp 17308.028. 24X Fiche: 50-373, 83/02/15, 8302280461.

--8302280474 IE Insp Repts 50-373/82-40 & 50-374/82-10 on 820804-27 Noncompliance noted: failure to conduct adequate QA audit; to develop adequate procedure for calibr of measuring & test equipment & to implement revs to QA procedures.
REIMANN, F W, LANKSBURY, R D, JACKIW, I N. Region 3, Office of Director. 83/02/04. 20pp. 17308.033 24X Fiche: 50-373, 83/02/15, 8302280461.

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Bvc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/18. Consolidated Edison Co. of New York, Inc. 110pp. 17347.191 24X Fiche: 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Bvc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24. Consolidated Edison Co. of New York, Inc. 111pp. 17347.058 24X Fiche: 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Bvc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24. Consolidated Edison Co. of New York, Inc. 112pp. 17361.148. 24X Fiche: 50-000, 83/02/24, 8212060366

B. Reportable occurrences, LERs & related correspondence

8302010122 Forwards LER 82-175/03L-0.
DIEDERICH, G J. Commonwealth Edison Co. 83/01/20. KEPPLER, J O. Region 3, Office of Director. ip. 16974.063 24X
Fiche: 50-373, 83/01/20, 8302010122

--8302010127 LER 82-175/03L-0: on 821224, div 2 position indicator of containment vacuum breaker IPC001B would not indicate closed. Cause undetermined. Work request written; insp performed & vacuum breaker repeatedly cycled.
MASTERSON, V. Commonwealth Edison Co. 83/01/20. Region 3, Office of Director. 3pp 16974.064. 24X Fiche: 50-373, 83/01/20, 8302010122

8302010373 Forwards LER 82-179/03L-0.
DIEDERICH, G J. Commonwealth Edison Co. 83/01/20. KEPPLER, J O. Region 3, Office of Director. ip. 16977.029. 24X
Fiche: 50-373, 83/01/20, 8302010373.

--8302010385 LER 82-179/03L-0. on 821224, lake blowdown flow recorder indicated incorrect readings. Caused by lake blowdown flow instrument probe being air-bound preventing correct signal from being transmitted. Mod issued to modify sys.
LIN, D L. Commonwealth Edison Co. 83/01/20. Region 3, Office of Director. 2pp 16977.030. 24X Fiche: 50-373, 83/01/20, 8302010373

8302080259 Forwards NPDES noncompliance for License NPF-11
DIEDERICH, G J. Commonwealth Edison Co. 83/01/20. KEPPLER, J O. Region 3, Office of Director. 2pp 17057.015 24X
Fiche: 50-373, 83/01/20, 8302080259

--8302080265 NPDES noncompliance notification on 830103, increase in iron discovered in waste solidification discharge tank. Caused by wastes from condensate polishing sys regeneration & buildup of solids in discharge tank. Mod initiated.
Commonwealth Edison Co. 83/01/11. ip 17057.017. 24X
Fiche: 50-373, 83/01/20, 8302080259

8302040261 Forwards LER 82-176/03L-0
DIEDERICH, G J. Commonwealth Edison Co. 83/01/26. KEPPLER, J O. Region 3, Office of Director. ip 17020.039 24X
Fiche: 50-373, 83/01/26, 8302040261

--8302040266 LER 82-176/03L-0 on 821228, while RHR B sys was in suppression pool cooling mode, excessive vibration noted on RHR 1B pump shaft. Caused by excessive wear on bearings. Bearings replaced.
HOUSTON, R W. Commonwealth Edison Co. 83/01/26. Region 3, Office of Director. 3pp 17020.040 24X Fiche: 50-373, 83/01/26, 8302040261

8302040260 Forwards LER 82-180/03L-0
DIEDERICH, G J. Commonwealth Edison Co. 83/01/27. KEPPLER, J O. Region 3, Office of Director. ip 17020.054 24X
Fiche: 50-373, 83/01/27, 8302040260

--8302040263 LER 82-180/03L-0. on 821230, review of Tech Spec Table 3.7 9-2 revealed several administrative & clerical errors. Caused by issuing Tech Specs prior to incorporation of final linework info. Table will be revised.
SPENCER, D. Commonwealth Edison Co. 83/01/27. Region 3, Office of Director. 2pp 17020.055 24X Fiche: 50-373, 83/01/27, 8302040260

8302040176 Forwards LER 82-177/03L-0
DIEDERICH, G J. Commonwealth Edison Co. 83/01/28. KEPPLER, J O. Region 3, Office of Director. ip 17021.327 24X
Fiche: 50-373, 83/01/28, 8302040176.

--8302040187 LER 82-177/03L-0 on 821230, RHR full flow test valve A 1E12-F024A did not close fully when sys was being shut down. Caused by unadjusted light switch cam on throttle valve. Closing torque switch replaced.
HOUSTON, R W. Commonwealth Edison Co. 83/01/28. Region 3, Office of Director. 2pp 17021.328 24X Fiche: 50-373, 83/01/28, 8302040176.

8302040333 Forwards LER 82-178/03L-0
DIEDERICH, G J. Commonwealth Edison Co. 83/01/28. KEPPLER, J O. Region 3, Office of Director. ip 17018.242 24X
Fiche: 50-373, 83/01/28, 8302040333

--8302040335 LER 82-178/03L-0 on 821230 & 31, low pressure alarms received for automatic depressurization sys valves B & C & U. Caused by blowback of drywell pneumatic air dryer 1B to drywell & leak in instrument nitrogen supply check valve.
PETERB, J. Commonwealth Edison Co. 83/01/28. Region 3, Office of Director. 3pp 17018.243 24X Fiche: 50-373, 83/01/28, 8302040333

8302140075 PNO-III-83-011, on 830203, fire discovered in turbine bldg in non-safety-related area. Fire extinguished in 5 minutes. No radioactive matl involved. Fire of suspicious origin.
CREED, J R, JACKIW, I N, STREETER, J F. Region 3, Office of Director. 83/02/03. ip. 17142.112 24X Fiche: 50-373, 83/02/03, 8302140075

8302180459 Forwards NPDES noncompliance notification for License NPF-11.
DIEDERICH, G J. Commonwealth Edison Co. 83/02/07. KEPPLER, J O. Region 3, Office of Director. 2pp 17215.132 24X
Fiche: 50-373, 83/02/07, 8302180459.

--8302180467 NPDES noncompliance notification on 830118, incident caused by wastes from Unit 2 condensate polishing sys regeneration & buildup of solids in discharge tank. Mod initiated to provide option for treatment of tanks.
DIEDERICH, G J. Commonwealth Edison Co. 83/02/07. ip 17215.134 24X Fiche: 50-373, 83/02/07, 8302180459

8302230209 Forwards updated LER 82-132/03X-1.
DIEDERICH, G J. Commonwealth Edison Co. 83/02/07. KEPPLER, J O. Region 3, Office of Director. ip. 17293.102. 24X
Fiche: 50-373, 83/02/07, 8302230209.

--8302250215 Updated LER 82-132/03X-1 on 821004, process radiation monitor for IB RHR svc water declared inoperable due to seal failure of sample pump Caused by either improper filling & venting or design problem Pump repaired & returned to svc
LUETT, W Commonwealth Edison Co 83/02/07, Region 3, Office of Director 2pp 17293 103 24X Fiche 50-373, 83/02/07, 8302250209

8302250395 Forwards revised LER 82-134/03X-1
DIEDERICH, O J Commonwealth Edison Co 83/02/08 KEPLER, J O
Region 3, Office of Director 1p 17296 212 24X
Fiche 50-373, 83/02/08, 8302250395

--8302250401 Revised LER 82-134/03X-1, on 821021, reactor bldg ventilation sys would not maintain required pressure Caused by all blades of supply fan IVRO1CB broken off Standby gas treatment sys started to maintain pressure
DUS, R Commonwealth Edison Co 83/02/08 Region 3, Office of Director 2pp 17296:213 24X Fiche 50-373, 83/02/08, 8302250395

8302250220 Forwards updated LER 82-067/03X-1
DIEDERICH, O J Commonwealth Edison Co 83/02/09 KEPLER, J O
Region 3, Office of Director, 1p 17293:071 24X
Fiche 50-373, 83/02/09, 8302250220

--8302250228 Updated 82-067/03X-1 on 820722, dampers OVE07YA & OVE09YA would not operate manually Caused by blown oil seal in actuator OF2-VE007B (damper OVE09YA). Actuators repaired & shop tested satisfactorily.
TOLBERT, R Commonwealth Edison Co 83/02/09 Region 3, Office of Director, 3pp 17293:072 24X Fiche 50-373, 83/02/09, 8302250220

8302250286 Forwards revised LER 82-090/03X-1,
DIEDERICH, O J Commonwealth Edison Co 83/02/09 KEPLER, J O
Region 3, Office of Director, 1p 17291:287 24X
Fiche 50-373, 83/02/09, 8302250286

--8302250296 Revised LER 82-090/03X-1 on 820820, during Startup Test Procedure 17, mechanical snubber found damaged Caused by application of excessive forces in lateral direction causing snubber to bend or twist Snubber replaced
SPENCER, D Commonwealth Edison Co 83/02/09 Region 3, Office of Director 2pp 17291 288 24X Fiche 50-373, 83/02/09, 8302250286,

8302250307 Forwards updated LER 82-153/03X-1
DIEDERICH, O J Commonwealth Edison Co 83/02/09 KEPLER, J O
Region 3, Office of Director 1p 17291:013 24X
Fiche 50-373, 83/02/09, 8302250307

--8302250319 Updated LER 82-153/03X-1 on 821118, steam & water leak discovered on reactor water cleanup pump B regenerative HX shell side relief line to HX socket weld junction, Cause unknown, Work Request L20566 generated to replace piping
WINTERHOFF, D Commonwealth Edison Co 83/02/09 Region 3, Office of Director 3pp 17291:014 24X Fiche 50-373, 83/02/09, 8302250307,

8302250168 Forwards LER 83-002/03L-0
DIEDERICH, O J Commonwealth Edison Co 83/02/10, KEPLER, J O
Region 3, Office of Director 1p 17294:007 24X
Fiche 50-373, 83/02/10, 8302250168,

--8302250173 LER 83-002/03L-0 on 830121, functional testing of HPCS keep filled pressure alarm not performed monthly from 820415 to 0922, Caused by personnel error. Tech Spec review will be completed by 830401.
CRAY, M A Commonwealth Edison Co 83/02/10, Region 3, Office of Director, 2pp 17294:008 24X Fiche 50-373, 83/02/10, 8302250168,

8302250390 Forwards LER 83-003/03L-0,
DIEDERICH, O J Commonwealth Edison Co 83/02/14 KEPLER, J O
Region 3, Office of Director 1p 17297:280 24X
Fiche 50-373, 83/02/14, 8302250390

--8302250397 LER 83-003/03L-0 on 830118, functional testing of condenser low vacuum MSIV isolation pressure switches not performed for Aug 1982 & calibr not performed for Third Quarter 1982. Caused by personnel error Review of Tech Specs in progress.
TRAINOR, A F Commonwealth Edison Co 83/02/14, Region 3, Office of Director 2pp 17297:281 24X Fiche 50-373, 83/02/14, 8302250390,

8302280376 Forwards LER 83-005/01T-0,
DIEDERICH, O J Commonwealth Edison Co 83/02/16 KEPLER, J O
Region 3, Office of Director, 1p 17309:243 24X
Fiche 50-373, 83/02/16, 8302280376,

--8302280381 LER 83-005/01T-0 on 830207, special temp switches mfg by Panalarm Div of Riley Co out of spec Caused by calibr between Riley modules & common indicator meter & failed temp compensator in module Modules replaced
WITTENBERG, K C Commonwealth Edison Co 83/02/16, Region 3, Office of Director 3pp 17309 246 24X Fiche 50-373, 83/02/16, 8302280376

8302280497 Forwards LER 83-004/03L-0
DIEDERICH, O J Commonwealth Edison Co 83/02/17 KEPLER, J O
Region 3, Office of Director 1p 17309 059 24X
Fiche 50-373, 83/02/17, 8302280497

--8302280506 LER 83-004/03L-0 on 830121, calibr of hydrogen recombiner temp instrumentation L18-HO-01 not performed in Apr 1982 Caused by surveillance requirement overlooked by personnel. Requirements reviewed.
TRAINOR, A F Commonwealth Edison Co 83/02/16, Region 3, Office of Director 2pp 17309 060 24X Fiche 50-373, 83/02/17, 8302280497

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Bvc list encl
EISENHUT, D O Division of Licensing 83/01/31, Consolidated Edison Co of New York, Inc. 14pp 17347:177 24X
Fiche 50-000, 83/01/31, 8301310203,

DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302010286 Forwards "Verification Testing of Separation Between Class IE & Nonclass IE Power Cable in Raceways for Use in LaBalle Nuclear Generating Station - Units 1 & 2," for review.
SCHRÖDER, C W Commonwealth Edison Co 83/01/28, SCHWENCER, A, Licensing Branch 2 1p 16973:117 24X Fiche 50-373, 83/01/28, 8302010286

--8302010292 "Verification Testing of Separation Between Class IE & Nonclass IE Power Cable in Raceways for Use in LaBalle Nuclear Generating Station - Units 1 & 2," Rev A,
JOHNSON, F N, STENSON, T R, HAZELTINE, J, Wyle Laboratories 83/01/20 18pp 16973:119 24X Fiche 50-373, 83/01/28, 8302010286

8302070460 Provides info re expected fuel load date, per D0 Eisenhut 820503 ltr, Fuel load expected in Aug 1983, w/o further extension to CP
SCHRÖDER, C W Commonwealth Edison Co 83/02/01 SCHWENCER, A, Licensing Branch 2 2pp 17036:279 24X Fiche 50-374, 83/02/01, 8302070460,

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR.
BAGCHI, O Equipment Qualification Branch, 83/02/02, NOONAN, V B, Equipment Qualification Branch 3pp 17205:198 24X
Fiche 50-000, 83/02/02, 8302170011,

--830160808 Trip rept of 80117-21 site visit in Ottawa, IL re seismic criteria implementation.
CHEN, P Y Equipment Qualification Branch 81/02/25
ROBERTSON, Z R Equipment Qualification Branch 43pp 17205:325 24X Fiche 50-000, 83/02/02, 8302170011

8302080199 Forwards Addendum 1 to "Verification Testing of Separation Between Class IE & Non-Class IE Power Cable in Raceways..."
Temp monitoring will be provided during performance of test Comments requested by 830210
SCHRÖDER, C W Commonwealth Edison Co 83/02/04, SCHWENCER, A, Licensing Branch 2 2pp 17033:001 24X Fiche 50-373, 83/02/04, 8302080199

--8302080204 Addendum 1 to "Verification Testing of Separation Between Class IE & Non-Class IE Power Cable in Raceways for Use in LaBalle Nuclear Generating Station - Units 1 & 2."
JOHNSON, F N, STENSON, T R, HAZELTINE, J, Wyle Laboratories 83/01/25 6pp 17056:004 24X Fiche 50-373, 83/02/04, 8302080199,

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program. Bvc list encl.
EISENHUT, D O Division of Licensing 83/02/08, Consolidated Edison Co of New York, Inc. 11pp 17290:247 24X
Fiche 50-000, 83/02/08, 8302080295,

DOCKETED ITEMS

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982, Guidelines acceptable BvC list encl.
EISENHUT, D O. Division of Licensing 83/02/08 Commonwealth Edison Co. 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301.

F. Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records 83/01/27. Document Management Branch. 1p 17043. 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint program & ED-25 re computer codes for access to ODCB program.
PAJOWSKI, J.E. Commonwealth Edison Co. 83/01/07 DENTON, H.R. NRC - No Detailed Affiliation Given. 1p. 17043. 231 24X Fiche. 50-000, 83/01/27, 8302040037

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCB programs. Revised index encl.
LITERBAK, L.A. Commonwealth Edison Co. 83/01/06. 11pp 17043: 232. 24X Fiche: 50-000, 83/01/27, 8302040039

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." BvC list encl.
EISENHUT, D O. Division of Licensing 83/02/01. Consolidated Edison Co. of New York, Inc. 11pp. 17221: 226 24X Fiche: 50-000, 83/02/01, 8301210340.

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session. No new requirements requested for emergency response facility. Minor changes suggested as result of meeting exercise. NUREG-0496 & SECY-82-1118 guidelines valid.
KEPPLER, J.O. Region 3, Office of Director. 83/02/04. REED, C. Commonwealth Edison Co. App. 17056 290. 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities. Requests contradictory to NRC directive for simplification
REED, C. Commonwealth Edison Co. 82/12/09. KEPPLER, J.O. Region 3, Office of Director 3pp 17056: 294 24X Fiche: 50-000, 83/02/04, 8302080316

8302150647 Ack receipt of 830103 ltr transmitting util scope & objectives for facility emergency exercise rescheduled for Jul 1983. Site assembly w/accountability should be added to list of supporting objectives. Meeting invitation accepted.
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support 83/02/08. REED, C. Commonwealth Edison Co. 1p. 17180: 346 24X Fiche. 50-373, 83/02/08, 8302150647

--8302150657 Forwards scope & objectives for 830322 emergency exercise. Primary objective is to demonstrate capability to implement site emergency plan in cooperation w/State of IL plan for radiological accidents
NELLIS, C.A. Commonwealth Edison Co. 83/01/03. HIND, J. Division of Emergency Preparedness & Operational Support. 3pp 17150. 347 24X Fiche: 50-373, 83/02/08, 8302150647.

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/02/15. Document Management Branch. 1p. 17223: 218. 24X Fiche: 50-000, 83/02/15, 8302180102.

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOF-2, "Technical Support Manager."
MOORE, R.D. Commonwealth Edison Co. 83/01/03. DENTON, H.R. NRC - No Detailed Affiliation Given. 1p. 17223. 219. 24X Fiche: 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOF-2, "Technical Support Manager."
NELLIS, C.A. Commonwealth Edison Co. 83/02/02. 48pp. 17223: 220 24X Fiche: 50-000, 83/02/15, 8302180102.

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support 83/02/18 REED, C. Commonwealth Edison Co. 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities. Lists of locations encl.
SHARTZ, E.D. Commonwealth Edison Co. 83/01/28 KEPPLER, J.O. Region 3, Office of Director App 17291 074 24X Fiche 50-000, 83/02/18, 8302250349

G. Adjudicatory correspondence

8302180014 Completes NRC response to TC Fahnes 820324 petition & 820503 amend on behalf of State of IL under 10CFR2 206. Remaining parts of petition & amend per allegations re Unit 2 denied.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/02/09 HARTIGAN, N. Illinois, State of 1p 17207: 332 24X Fiche: 50-373, 83/02/09, 8302180014

--8302180020 Completes NRC response to 820428 petition on behalf of IL Friends of the Earth under 10CFR2 206. Remaining parts of petition per allegations re Unit 2 denied. Director's Decision encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/02/09 ROURE, B.L. Friends of the Earth. 1p 17207: 334 24X Fiche: 50-373, 83/02/09, 8302180014

--8302180023 Responds to 820728 petition on behalf of Citizens Against Nuclear Power under 10CFR2 206. Petition denied for reasons stated in encl Director's Decision.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/02/09 ODOOL, E.M. Citizens Against Nuclear Power 1p. 17207. 336 24X Fiche 50-373, 83/02/09, 8302180014

--8302180052 Director's Decision DD-83-1, denying remaining portions of petitions of State of IL & IL Friends of the Earth re allegations of poor const at facility.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/02/09. 6pp 17207 338 24X Fiche 50-373, 83/02/09, 8302180014.

--8302180058 Notice of issuance of Director's Decision DD-83-1 under 10CFR2 206
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/02/09. 3pp. 17207: 346 24X Fiche: 50-373, 83/02/09, 8302180014

--8208130353 Trip rept of 820726 meeting in Glen Ellyn, IL re safety implications of allegations concerning deficiencies in Zack Co QA & effect on HVAC sys ductwork & support design
TERAO, D. Mechanical Engineering Branch. 82/07/30 BOSNAK, R.J. Mechanical Engineering Branch 3pp 17208: 099 24X Fiche. 50-373, 83/02/09, 8302180014

K. Utility Final Safety Analysis Report (FSAR) & amends

8302170187 Forwards Amend 62 to FSAR.
SCHROEDER, C.W. Commonwealth Edison Co. 83/02/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director App 17179 092 24X Fiche. 50-373, 83/02/04, 8302170187.

--8302170191 Amend 62 to FSAR.
Commonwealth Edison Co. 83/02/28. 38pp 17179: 096 24X Fiche. 50-373, 83/02/04, 8302170187

8302280344 Forwards affidavit certifying distribution of Amend 62 to FSAR.
SCHROEDER, C.W. Commonwealth Edison Co. 83/02/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17308: 079 24X Fiche. 50-373, 83/02/23, 8302280344

F. Operating license stage documents & correspondence

8302230518 Suppl 821006 ltr re mod to diesel generator prelube oil pump per License Condition 2.C. 21.b. EMD MI 9466 mod will meet requirements in lieu of prelube pump installation.
SCHROEDER, C.W. Commonwealth Edison Co. 83/02/14 SCHWENCER, A. Licensing Branch 2. 7pp. 17248 350. 24X Fiche 50-373, 83/02/14, 8302230518

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning GA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J. M. Division of Rules and Records 82/12/30 HIATT, S. L.
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1974-80
MIND, J. A. Division of Emergency Preparedness & Operational Support, 82/02/03. KEPPLER, J. Q. Region 3, Office of Director.
23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1974-81, per JJ Harrison request Total insp hours for each facility added
MIND, J. A. Division of Emergency Preparedness & Operational Support, 82/06/08. SPESSARD, R. L. Division of Project & Resident Programs 2pp 17045.279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
BUCHARSKI, L. Region 3, Office of Director. 82/07/08
KEPPLER, J. Q. Region 3, Office of Director 13pp 17045.281 24X
Fiche 50-000, 82/12/30, 8302040039.

8302010362 Forwards IE Insp Repts 50-373/82-52 & 50-374/82-20 on 821101-30 & notice of violation
STREETEER, J. F. Division of Project & Resident Programs 83/01/19.
REED, C. Commonwealth Edison Co 2pp. 16973.311. 24X
Fiche 50-373, 83/01/19, 8302010362

--8302010365 Notice of violation from insp on 821101-30
STREETEER, J. F. Division of Project & Resident Programs 83/01/19
1p 16973 313 24X Fiche 50-373, 83/01/19, 8302010362.

--8302010377 IE Insp Repts 50-373/82-52 & 50-374/82-20 on 821101-30.
Noncompliance noted failure to follow radiation protection procedures
GULDEMOND, W. MADISON, A. RAOLIN, K. Division of Project & Resident Programs 83/01/18 13pp 16973.314. 24X Fiche 50-373, 83/01/19, 8302010362

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/26. Consolidated Edison Co. of New York, Inc 118pp 17023 160. 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28. Consolidated Edison Co. of New York, Inc 107pp 17144.001. 24X Fiche 50-000, 83/01/28, 8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28. Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session. Requests that participation be limited to three people.
SPESSARD, R. L. Division of Engineering. 83/01/28. Commonwealth Edison Co 2pp. 17008.187 24X Fiche 50-000, 83/01/28, 8302030303.

8302040280 Forwards confirmatory measurements program data sheet for IE Insp Repts 50-373/82-53 & 50-374/82-21 for beta analysis of liquid sample not completed during onsite phase of insp.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support, 83/02/01 REED, C. Commonwealth Edison Co 1p. 17020.031. 24X Fiche 50-373, 83/02/01, 8302040280

--8302040284 Confirmatory measurements program data sheet, to be inserted in IE Insp Repts 50-373/82-53 & 50-374/82-21.
* Division of Emergency Preparedness & Operational Support.
83/02/01. 1p. 17020.032. 24X Fiche 50-373, 83/02/01, 8302040280.

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels"
BARTZ, E. D. Commonwealth Edison Co. 83/02/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17156.215. 24X
Fiche 50-000, 83/02/08, 8302150528.

8302170291 Ack receipt of 830120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-51 & 50-374/82-18
SPESSARD, R. L. Division of Engineering 83/02/09 REED, C. Commonwealth Edison Co. 1p 17177 037 24X Fiche 50-373, 83/02/09, 8302170291

--8302170297 Responds to NRC 821222 ltr re violations noted in IE Insp Repts 50-373/82-51 & 50-374/82-18 Corrective actions: audit items requiring long-term corrective actions not closed out until all corrections complete
DELOEOROE, L. O. Commonwealth Edison Co 83/01/20 KEPPLER, J. Q. Region 3, Office of Director 3pp 17177.038 24X
Fiche 50-373, 83/02/09, 8302170291

8302170314 Ack receipt of 830203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-50 & 50-374/82-17
SPESSARD, R. L. Region 3, Office of Director. 83/02/09. REED, C. Commonwealth Edison Co 1p 17177 004. 24X Fiche 50-373, 83/02/09, 8302170314

--8302170315 Responds to NRC 830106 ltr re violations noted in IE Insp Repts 50-373/82-50 & 50-374/82-17 Corrective actions.
Deficiency rept initiated on 821004 to record missing flow orifice & ensure that orifice will be installed.
FARRAR, D. L. Commonwealth Edison Co 83/02/03. KEPPLER, J. Q. Region 3, Office of Director 3pp 17177.005. 24X
Fiche 50-373, 83/02/09, 8302170314.

8302180014 Completes NRC response to TC Fahnes 820324 petition & 820503 amend on behalf of State of IL under 10CFR2.206. Remaining parts of petition & amend per allegations re Unit 2 denied.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/02/09. HARTMAN, N. Illinois, State of 1p 17207.332 24X
Fiche 50-373, 83/02/09, 8302180014

--8302180065 IE Insp Repts 50-373/78-06 & 50-374/78-05 on 780306-14
Noncompliance noted const practices re welding of electrical equipment supports.
FOSTER, J. E. VANDEL, T. E. NAIDU, K. R. Region 3, Office of Director 78/04/24. 19pp. 17208.177. 24X Fiche 50-373, 83/02/09, 8302180014

8302280461 Forwards IE Insp Repts 50-373/82-40 & 50-374/82-10 on 820804-27 & notice of violation. Description of overall mgt controls to improve GA recordkeeping required.
KEPPLER, J. Q. Region 3, Office of Director. 83/02/15. REED, C. Commonwealth Edison Co 4pp 17308 024 24X Fiche 50-373, 83/02/15, 8302280461

--8302280468 Notice of violation from insp on 820804-27.
NORELIUS, C. E. Division of Project & Resident Programs. 83/02/15 5pp. 17308.028. 24X Fiche 50-373, 83/02/15, 8302280461

--8302280474 IE Insp Repts 50-373/82-40 & 50-374/82-10 on 820804-27.
Noncompliance noted failure to conduct adequate GA audit; to develop adequate procedure for calibr of measuring & test equipment & to implement revs to GA procedures.
REIMANN, F. W. LANKSBURY, R. D. JACKIN, I. N. Region 3, Office of Director 83/02/04. 20pp 17308.033 24X Fiche 50-373, 83/02/11, 8302280461

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp. 17347.191 24X Fiche 50-000, 83/02/18, 8212060363.

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24 Consolidated Edison Co. of New York, Inc 111pp. 17347 058. 24X Fiche 50-000, 83/02/24, 8212060365.

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24 Consolidated Edison Co. of New York, Inc 112pp. 17361 148. 24X Fiche 50-000, 83/02/24, 8212060366.

B. Reportable occurrences, LERs & related correspondence

8302040053 Interim Deficiency Rept 82-08 re electrical penetration assembly butt splices Replacement modules for AWO cable Modules 2 & 6 ordered from Conax. Final rept will be provided on or about 830303
SCHROEDER, C. W. Commonwealth Edison Co. 83/01/24 KEPPLER, J. Q. Region 3, Office of Director. 2pp. 17020.359. 24X
Fiche 50-374, 83/01/24, 8302040053.

DOCKETED ITEMS

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for QLE, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Bvc list encl
EISENHUT, D O Division of Licensing 83/01/31, Consolidated
Edison Co. of New York, Inc. 14pp, 17347 177. 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

G Inspection Reports, IE Bulletins & correspondence

8302010458 Informs that ref to nonpenetrating radiation levels has been deleted in response to 830112 request to correct apparent error in IE Insp Rept 50-375/82-02
BOOK, H E. Division of Radiological Safety & Safeguards Program
83/01/27 REMLEY, M E Rockwell International Corp 1p. 169B1:296.
24X Fiche, 50-375, 83/01/27, 8302010458

--8302010465 Forwards corrected IE Insp Rept 50-375/82-02 on 821216. No noncompliance noted
BOOK, H E. Division of Radiological Safety & Safeguards Program
83/01/03 REMLEY, M E Rockwell International Corp 2pp
169B1 297. 24X Fiche: 50-375, 83/01/27, 8302010458

--8302010476 Corrected IE Insp Rept 50-375/82-02 on 821216 No noncompliance noted Major areas inspected licensee plan for dismantling L-85 facility, review preparation for dismantling & inspector familiarization w/facility layout
GARCIA, E M., MENSLAHSKI, F., BOOK, H. E. Division of Radiological Safety & Safeguards Program. 82/12/30 3pp. 169B1:299 24X
Fiche, 50-375, 83/01/27, 8302010458.

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A. Application/Construction stage documents & correspondence

8302080113 Board Notification 82-122A forwards USQB 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake. W/o encl
NOVAK, T M. Assistant Director for Licensing 82/12/30. Atomic
Safety and Licensing Board Panel. 18pp. 17105,335 24X
Fiche: 50-000, 82/12/30, 8302080113.

8302020255 Forwards Monthly Rept 17 re recruiting & upgrading of total corporate capability Nuclear Organization staffing status as of 830115 & status as of 810420 staffing commitments encl.
MAURIN, L V. Louisiana Power & Light Co 83/01/19 WILSON, J. NRC -
No Detailed Affiliation Given. 3pp. 16974,270 24X
Fiche: 50-382, 83/01/19, 8302020255

8302030532 Forwards documentation re progress &/or completion of all confirmatory items in Seismic Qualification Review Team audit, NBS-PE-25, "Boric Acid Tank Circulating Valve," only remaining confirmatory item.
MAURIN, L V. Louisiana Power & Light Co 83/01/21 NOVAK, T M.
Assistant Director for Licensing 206pp 17006,309. 24X
Fiche, 50-382, 83/01/21, 8302030532

8302030090 Requests addl info re nonmetallic matls in safety sys in harsh environs, supplementing 830103 ltr
NOVAK, T M. Assistant Director for Licensing. 83/01/24 MAURIN, L V.
Louisiana Power & Light Co. 2pp. 17028 338. 24X
Fiche: 50-382, 83/01/24, 8302030090.

8302010414 Forwards revised seismic qualification completion schedule.
MAURIN, L V. Louisiana Power & Light Co. 83/01/27. NOVAK, T M.
Assistant Director for Licensing. 32pp. 16981:245. 24X
Fiche: 50-382, 83/01/27, 8302010414.

8302010420 Forwards info re 830104-06 equipment qualification audit, including list of attendees, equipment selected for audit & documentation of comments One open & one confirmatory item noted.
MAURIN, L V. Louisiana Power & Light Co. 83/01/27. NOVAK, T M.
Assistant Director for Licensing 110pp. 16981,133. 24X
Fiche: 50-382, 83/01/27, 8302010420.

8302030075 Forwards responses to NRC draft technical evaluation rept re facility control of heavy loads, W/15 oversize drawings
Aperture cards are available in PDR.
MAURIN, L V. Louisiana Power & Light Co. 83/01/27. KNIGHTON, O.
Licensing Branch 3. 33pp. 17001,339. 24X Fiche: 50-382, 83/01/27, 8302030075.

8302030092 Forwards status list of all open & confirmatory items & addl items of interest
MAURIN, L V. Louisiana Power & Light Co 83/01/27 KNIGHTON, O.
Licensing Branch 3 4pp 17002 226 24X Fiche 50-382, 83/01/27, 8302030092

8302030118 Forwards revised pages from FSAR Sections 11.2 & 11.4
Changes reflect latest design considerations in radwaste mgt & will be incorporated into next FSAR amend
MAURIN, L V. Louisiana Power & Light Co 83/01/27. KNIGHTON, O.
Licensing Branch 3 27pp 17002 234 24X Fiche 50-382, 83/01/27, 8302030118

8302070616 Forwards proprietary & nonproprietary versions of, "Suppl to Waterford 3, Cycle 1, CPC/CEAC Phase II Software Verification Test"
MAURIN, L V. Louisiana Power & Light Co 83/01/27 KNIGHTON, O.
Licensing Branch 3. 4pp. 17035 215 24X Fiche 50-382, 83/01/27, 8302070616.

--8302070621 Nonproprietary version of, "Suppl to waterford 3, Cycle 1 CPC/CEAC Phase II Software Verification Test Rept."
Combustion Engineering, Inc. CEN-208(C)-NP 801 82/11/30.
7pp 17035 221 24X Fiche: 50-382, 83/01/27, 8302070616

8302090548 Suggests meeting in Washington, DC to discuss remaining open items on critical path for licensing items include fire protection, equipment & seismic qualification, preliminary safety info & licensee qualification.
KNIGHTON, O W Licensing Branch 3 83/01/28 MAURIN, L V. Louisiana Power & Light Co 3pp 17131,341 24X Fiche: 50-382, 83/01/28, 8302090548

8302100139 Notification of 830131-0204 meetings w/util & consultants in Bethesda, MD to discuss Tech Spec outstanding issues
WILSON, J H Licensing Branch 3. 83/01/31 KNIGHTON, O. Licensing Branch 3. 3pp. 17134,279 24X Fiche: 50-382, 83/01/31, 8302100139.

8302070523 Forwards info on seismic qualification of equipment supplementing util 830121 submittal. Info addresses specific items 6, 7 & 8 re resistor input card, Indicator 1151 & control element drive mechanism read switch position
MAURIN, L V. Louisiana Power & Light Co 83/02/01 NOVAK, T M.
Assistant Director for Licensing. 11pp 17035,237 24X
Fiche 50-000, 83/02/01, 8302070523

--8302070531 "A2 Nuclear Power Project 150-Inch Read Switch Position Transmitter & Litton Electrical Connector Seismic Qualification Test (Sine Sweep Testing)." Age considerations for seismic design & surveillance in mild environs encl.
HABLINGER, K H Combustion Engineering, Inc TR-EEB-442.
81/10/09 99pp. 17035,268 24X Fiche: 50-000, 83/02/01, 8302070523

8302070182 Forwards proprietary & nonproprietary "Responses to Questions on CESEC," per 820607 request. Proprietary rept withheld (ref 10CFR2 790)
MAURIN, L V. Louisiana Power & Light Co 83/02/02 KNIGHTON, O.
Licensing Branch 3. 6pp 17032,150. 24X Fiche: 50-382, 83/02/02, 8302070182

--8302070194 "Responses to Questions on CESEC"
Combustion Engineering, Inc CEN-234(C)-NP. 82/12/31. 180pp.
17032,156. 24X Fiche 50-382, 83/02/02, 8302070182.

8302070500 Forwards "Total Integrated Dose to GE Stations," radiation analysis rept; submitted as addl info re environ equipment qualification, per NRC 830127 request Addl relevant info also provided
MAURIN, L V. Louisiana Power & Light Co. 83/02/02. NOVAK, T M.
Assistant Director for Licensing 4pp. 17036 318. 24X
Fiche: 50-382, 83/02/02, 8302070500.

--8302070507 "Total Integrated Dose to GE Stations."
YANO, T L. Ebasco Services, Inc. (subs. of Enserch Corp).
83/02/01. 17pp. 17036:322 24X Fiche: 50-382, 83/02/02, 8302070500.

8302080023 Provides updated status/submittal schedule for closing out open licensing issues re environ & seismic qualification.
MAURIN, L V. Louisiana Power & Light Co. 83/02/02 KNIGHTON, O.
Licensing Branch 3 2pp. 17058 193. 24X Fiche: 50-382, 83/02/02, 8302080023

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment. Repts also available in PDR
BAGCHI, O. Equipment Qualification Branch. 83/02/02. NOODMAN, V B.
Qualification Branch 3pp 17205,188 24X
Fiche: 50-000, 83/02/02, 8302170011

DOCKETED ITEMS

--8209150350 Trip rept of 820915-18 seismic qualification review team site visit re performance of plant site review for selected safety-related, mechanical & electrical equipment Revision to site visit rept encl W/o encl
R08270CZY, Z R. Equipment Qualification Branch 82/08/30
MIRADOLIA, F. Licensing Branch 3 2pp 17206 277 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170210 Draft "Waterford III Seismic Qualification Review Team Visit Rept"
SINOH, J. N., MACEK, R. W., RUSSELL, M. J. EQ&O, Inc E00-EA-5643 R01
DRFT 82/04/30 CHANG, T. Y. NRC - No Detailed Affiliation Given
51pp 17206 277 24X Fiche 50-000, 83/02/02, 8302170011

--8302170218 Trip rept of 810914-18 & 820830-0903 visits to facility to review seismic & dynamic methods & results for safety-related mechanical & electrical equipment & observe field installation of equipment
BAOCHI, Q. Equipment Qualification Branch. 82/12/13 NOONAN, V. B
Equipment Qualification Branch 7pp 17207:025 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170223 "Waterford III Seismic Qualification Review Team Visit Rept (Second Visit)"
SINOH, J. N., MACEK, R. W. EQ&O, Inc FIN A-6415 82/12/13 NRC -
No Detailed Affiliation Given 43pp 17207:034 24X
Fiche 50-000, 83/02/02, 8302170011.

8302150684 Notifies that compliance w/NUREG-0737, Item II E. 4.2 re containment pressure setpoint (3.3 psig), has been calculated using explicit setpoint methodology per BER open item
Info will be included in FSAR Amend 31.
MAURIN, L. V. Louisiana Power & Light Co 83/02/07 KNIIGHTON, O.
Licensing Branch 3 2pp. 17154 115 24X Fiche 50-382, 83/02/07,
8302150684

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
EISENHUT, D. Q. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247. 24X
Fiche 50-000, 83/02/08, 8302080295

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed N88B re resolution of TMI Action Item II K 3.5. "Automatic Trip of Reactor Coolant Pumps." Bvc list encl
EISENHUT, D. Q. Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp. 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

8302160181 Forwards addl info re seismic qualification of equipment in response to 821213 memo All calculated stresses satisfy ASME Code Level B criteria
MCLENDON, Q. D. Louisiana Power & Light Co. 83/02/08 KNIIGHTON, O.
Licensing Branch 3. 61pp. 17162 317. 24X Fiche: 50-382, 83/02/08,
8302160181

8302160373 Amend to application for DL revising Tech Spec Sections 6.5.2 & 6.2.3 to require minutes of safety review committee meetings to be approved within 6 wks following meeting.
MAURIN, L. V. Louisiana Power & Light Co 83/02/11 KNIIGHTON, O. W.
Licensing Branch 3 2pp. 17164 153 24X Fiche: 50-382, 83/02/11,
8302160373.

--8302160378 Proposed Tech Spec changes revising Sections 6.5.2 & 6.2.3 to require minutes of safety review committee meetings to be approved within 6 wks following meeting.
* Louisiana Power & Light Co. 83/02/11. 8pp. 17164:155. 24X
Fiche: 50-382, 83/02/11, 8302160378

8302230440 Responds to Instrumentation & Control Bys Branch position re disabling of automatic ESF actuation sys function upon transfer to remote shutdown panel. Components will maintain automatic response capability save for boric acid pumps.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/11 KNIIGHTON, O.
Licensing Branch 3. 2pp 17245 361. 24X Fiche. 50-382, 83/02/11,
8302230440

8302280402 Confirms transmittal of repts of deficiencies on equipment qualification during Jan 1983 audit, in response to NRC 830128 request. Transmittal sufficient to close out Audit Item 25
MAURIN, L. V. Louisiana Power & Light Co 83/02/11. KNIIGHTON, O. W.
Operating Reactors Branch 3 1p. 17309:157 24X
Fiche: 50-382, 83/02/11, 8302280402.

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302030570 Forwards evaluation of effect of break size on consequences of steam line breaks w/concurrent loss of offsite power & analysis of feedwater line breaks Info should resolve BER confirmatory issues
MAURIN, L. V. Louisiana Power & Light Co 83/01/27. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 11pp 17008 096.
24X Fiche: 50-382, 83/01/27, 8302030570

8302150684 Notifies that compliance w/NUREG-0737, Item II E. 4.2 re containment pressure setpoint (3.3 psig), has been calculated using explicit setpoint methodology per BER open item
Info will be included in FSAR Amend 31
MAURIN, L. V. Louisiana Power & Light Co 83/02/07 KNIIGHTON, O.
Licensing Branch 3 2pp 17154 115 24X Fiche 50-382, 83/02/07,
8302150684

8302250116 Notification of 830218 meeting w/util, C-E & Ebasco in Bethesda, MD to discuss resolution of two BER confirmatory items in licensing review
WILSON, J. H. Licensing Branch 3 83/02/09 KNIIGHTON, O. W. Licensing Branch 3 3pp 17302:195 24X Fiche 50-382, 83/02/09, 8302250116.

F. Security, medical, emergency & fire protection plans

8302090548 Suggests meeting in Washington, DC to discuss remaining open items on critical path for licensing items include fire protection, equipment & seismic qualification, preliminary safety info & licensee qualification.
KNIIGHTON, O. W. Licensing Branch 3 83/01/28. MAURIN, L. V. Louisiana Power & Light Co 3pp 17131 341. 24X Fiche: 50-382, 83/01/28,
8302090548

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Bvc list encl
EISENHUT, D. Q. Division of Licensing 83/02/01. Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080214 Submits 45-day demonstration schedule of meteorological monitoring sys Bys design upgraded to meet NUREG-0654, App 2 criteria. CEPADAS will be operational by fuel load
MAURIN, L. V. Louisiana Power & Light Co. 83/02/02 KNIIGHTON, O. W.
Licensing Branch 3 3pp 17058 045 24X Fiche 50-382, 83/02/02,
8302080214

8302090405 Informs of emergency preparedness appraisal insp on 830222-0304 Emergency plan & emergency procedures & support document availability in work area requested Entrance interview scheduled for 830222.
MADBEN, Q. L. Division of Resident, Reactor Project & Engineering Programs. 83/02/03 MAURIN, L. V. Louisiana Power & Light Co. 2pp 17071 083 24X Fiche: 50-382, 83/02/03, 8302090405.

8302170041 Requests evaluation of expected plant response to 821211 fire at Union Carbide Corp plant, if plant had been at full operating power. Evaluation comparing expected behavior to anticipated occurrences expected within 30 days
EISENHUT, D. Q. Division of Licensing 83/02/03 MAURIN, L. V.
Louisiana Power & Light Co 8pp 17191 051 24X
Fiche: 50-382, 83/02/03, 8302170041.

8302250064 Notification of 830217 meeting w/util & consultants in Bethesda, MD to discuss submittal of info on remaining open & confirmatory items in area of fire protection
WILSON, J. Licensing Branch 3. 83/02/09 KNIIGHTON, O. W. Licensing Branch 3 3pp. 17302 359 24X Fiche 50-382, 83/02/09, 8302250064.

8302230335 Forwards responses to questions re proposed installation of Insulco/HEMYC Bys as fire protective envelope for Class IE electrical cables Insulco/HEMYC sys presentation data encl
MAURIN, L. V. Louisiana Power & Light Co. 83/02/14. NOVAK, T. M.
Assistant Director for Licensing 11pp 17247 048 24X
Fiche. 50-382, 83/02/14, 8302230335

--8302230339 "Comparison of HEMYC Bys Fire Test to Sandia 20-Ft Separation Test & CHED 9 5 1"
* Nuclear Energy Service, Inc. 83/02/14. 33pp. 17247 089 24X
Fiche 50-382, 83/02/14, 8302230335.

--8302230341 "Fire Qualification Test HEMYC Cable Wrap Bys as Installed by Insulco, Inc & Affiliated Co." final rept
* Insulco, Inc. CTP-1026. 83/06/01 85pp 17247 089 24X
Fiche: 50-382, 83/02/14, 8302230335.

--8302230348 Issue B of Procedure 8400.101, "Installation of Insulco/HEMYC Cable Tray Protection Bys - Straight Sections"
SPR1009, L. C. B&B Insulation Inc 82/11/29 13pp. 17247 182
24X Fiche 50-382, 83/02/14, 8302230335.

DOCKETED ITEMS

--8302230393 Issue B of Procedure 8400 102, "Installation of Insulco/HEMYC Cable Tray Protection Sys - Curved Section." SPRI008, L.C. B&B Insulation Inc. 82/11/29 9pp 17247 196 24X Fiche: 50-382, 83/02/14, 8302230393

--8302230398 Issue B of Procedure 8400 103, "Installation of Insulco/HEMYC Cable Tray Protection Sys onto Single or Multiple Conduits." SPRI008, L.C. B&B Insulation Inc. 82/11/29. 7pp 17247-204. 24X Fiche: 50-382, 83/02/14, 8302230398

--8302230368 Issue B of Procedure 8400 104, "Repair & Installation of Insulco/HEMYC Cable Tray Protection Sys Around Interferences & Obstructions." SPRI008, L.C. B&B Insulation Inc. 82/11/29 8pp 17247-210 24X Fiche: 50-382, 83/02/14, 8302230368

8302170449 Releases public version of revised emergency plan implementing procedures. FELTON, J.M. Division of Rules and Records. 83/02/15. Document Management Branch. 1p 17205:100. 24X Fiche: 50-382, 83/02/15, 8302170449

--8302170456 Forwards public version of revised Emergency Plan Implementing Procedures EP-1-010 re unusual event; EP-1-020 re alert & EP-1-030 re site emergency. MAURIN, L. Louisiana Power & Light Co. 83/01/31. KNIGHTON, G.W. Licensing Branch 3 1p. 17205:101. 24X Fiche: 50-382, 83/02/15, 8302170449.

--8302170461 Public version of revised Emergency Plan implementing Procedures EP-1-010 re unusual event; EP-1-020 re alert & EP-1-030 re site emergency. * Louisiana Power & Light Co. 83/01/26. 27pp 17205:102. 24X Fiche: 50-382, 83/02/15, 8302170449

8302250291 Forwards Rev 7 to physical security plan Rev withheld (ref 10CFR73.21). MAURIN, L.V. Louisiana Power & Light Co. 83/02/21. Office of Nuclear Reactor Regulation, Director 1p. 17291 290 24X Fiche: 50-382, 83/02/21, 8302250291.

Q. Adjudicatory correspondence

8302010543 Forwards EL Duncan affidavit re emergency info brochure, inadvertently omitted from 8 Duplassis & 8 Hunter affidavits. GROESCH, O.L. Joint Intervenor-Waterford. 83/01/26. WOLFE, B.J. Atomic Safety and Licensing Board Panel 1p. 16983:075. 24X Fiche: 50-382, 83/01/26, 8302010543

--8302010551 Affidavit of EL Duncan re emergency info brochure violates "keep it simple stupid principle." Both maps deficient as presented Brochure fails to speak directly to educ level of affected persons. DUNCAN, E.L. Joint Intervenor-Waterford 83/01/24. 31pp 16983:076. 24X Fiche: 50-382, 83/01/26, 8302010543

8302070532 Affidavit of EL Duncan re emergency info brochure. Brochure violates "keep it simple stupid principle." Method of brochure distribution faulty. Certificate of Svc encl Related correspondence. DUNCAN, E.L. Affiliation Unknown 83/01/26. 4pp. 17036:327 24X Fiche: 50-382, 83/01/26, 8302070532

8302020341 Inquires whether recipient wishes to remain on svc list. Svc list encl. Related correspondence. CHURCHILL, B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B.W. Louisiana Power & Light Co. 83/01/28. FONTANA, L.B. Joint Intervenor-Waterford 2pp. 16993:348. 24X Fiche: 50-382, 83/01/28, 8302020341.

8302020248 Order rejecting Joint Intervenor's brief. Clear, legible copy complying w/Commission Rules of Practice shall be filed by 830204. Original brief illegible. w/o Certificate of Svc & fails to show representative capacity & address. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 83/01/31. Joint Intervenor-Waterford. 2pp. 16994:328 24X Fiche: 50-382, 83/01/31, 8302020248

8302020278 Advises that applicant may present rebuttal testimony to Joint Intervenor's witness SM Hunter. Principle rebuttal witness would be DB Miles! Prof qualifications & svc list encl. CHURCHILL, B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B.W. Louisiana Power & Light Co. 83/01/31. WOLFE, B.J., FOREMAN, H., JORDAN, W.H. Atomic Safety and Licensing Board Panel 17pp. 16993:328. 24X Fiche: 50-382, 83/01/31, 8302020278.

8302070141 Forwards NRC 830203 ltr to util re 821211 chemical fire in plant vicinity Fire was subj of ASLB 821215 order TURK, B.E. Hearing Branch 1 83/02/03. WOLFE, B.J., FOREMAN, H., JORDAN, W.H. Atomic Safety and Licensing Board Panel 3pp 17032 336 24X Fiche: 50-382, 83/02/03, 8302070141

8302080246 Brief supporting Joint Intervenor's exceptions re Contentions 8/9 & 17/26 (1) & (2) Certificate of Svc encl GROESCH, O.L. Joint Intervenor-Waterford 83/02/04. Atomic Safety and Licensing Appeal Panel 49pp 17057 115 24X Fiche: 50-382, 83/02/04, 8302080246

8302140091 Notice of ASLAB reconstitution SF Eilperin, chairman & WR Johnson & CN Kohl, members SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel 83/02/10 1p. 17142 122. 24X Fiche: 50-382, 83/02/10, 8302140091

8302160360 Order accepting addl 14 pages filed w/Joint Intervenor's legible copy of brief. Addl pages will be treated as properly filed, but Joint Intervenor's admonished as to such future efforts. SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel 83/02/10 3pp 17169 201. 24X Fiche: 50-382, 83/02/10, 8302160360.

8302160175 Forwards ASLB meeting transcript (Pp 4, 027-4, 034) which incorporated two NRC 830203 ltrs re 821211 chemical fire near facility Svc instructions of encl provided WOLFE, B.J. Atomic Safety and Licensing Board Panel 83/02/14, STUCKY, S.W. Docketing & Services Branch 12pp. 17161 032. 24X Fiche: 50-382, 83/02/14, 8302160175

8302180413 Forwards loaner copy of 830211 hearing transcripts. Transcripts of 830208-11 hearings should be returned, once copies have been received by Univ of New Orleans LPDR W/o encl TURK, B.E. Hearing Branch 1 83/02/15. GROESCH, O.L. Joint Intervenor-Waterford 1p 17214 265 24X Fiche: 50-382, 83/02/15, 8302180413

8302200043 Forwards License SNM-1913, issued on 830210 & related matls. License does not relate to any issues being adjudicated & no ASLB action required. TURK, B.E. Hearing Branch 1. 83/02/18. WOLFE, B.J., JORDAN, W.H., FOREMAN, H. Atomic Safety and Licensing Board Panel. 22pp 17233:175. 24X Fiche: 50-382, 83/02/18, 8302200043

8302250430 Request for extension until 830325 to file brief in opposition to Joint Intervenor's exceptions Extension necessary because of time needed to prepare for three other NRC proceedings. Certificate of Svc encl CHURCHILL, B.W. Louisiana Power & Light Co. CHURCHILL, B.W. Shaw, Pittman, Potts & Trowbridge. 83/02/23. Atomic Safety and Licensing Appeal Panel 5pp. 17298 229 24X Fiche: 50-382, 83/02/23, 8302250430.

D. Advisory Committee on Reactor Safeguards reports & correspondence

8302090011 Summary of ACRS Subcommittee on Waterford 3 821109 meeting & site visit re operator training program, util staffing status & control room human factors program ZUDANS, Z. ACRS - Advisory Committee on Reactor Safeguards. ZUDANS, Z. Franklin Institute/Franklin Research Center. 82/11/12. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 17119. 176 24X Fiche: 50-382, 82/11/12, 8302090011.

8302080479 Summary of ACRS Waterford Unit 3 Subcommittee 821109 meeting in New Orleans, LA re training program & staffing inadequacies CATTON, I. ACRS - Advisory Committee on Reactor Safeguards 82/11/29. BUCCI, D. ACRS - Advisory Committee on Reactor Safeguards 2pp. 17071:274 24X Fiche: 50-382, 82/11/29, 8302080479.

8302080374 Summary of ACRS Waterford Unit 3 Subcommittee 821109 meeting w/util in New Orleans, LA re licensee's efforts to improve staffing, operator training & control room human factors mode for plant * ACRS - Advisory Committee on Reactor Safeguards 82/12/01. ACRS - Advisory Committee on Reactor Safeguards. 18pp 17107. 147 24X Fiche: 50-382, 82/12/01, 8302080374

G. Inspection reports, IE Bulletins & correspondence

8302070272 Responds to IE Info Notice 82-40 & IE Bulletin 82-04 Util has no Bunker-Ramo electrical penetration assemblies in use or planned for use at facility MAURIN, L.V. Louisiana Power & Light Co. 83/01/12. COLLINS, J.T. Region 4, Office of Director 4pp. 17032:146 24X Fiche: 50-382, 83/01/12, 8302070272.

DOCKETED ITEMS

8302070481 Forwards IE Insp Rept 50-382/82-29 on 821213-16. No noncompliance noted
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 83/01/13 MAURIN, L V Louisiana Power & Light Co 2pp 17036:037 24X Fiche 50-382, 83/01/13, 8302070481

--8302070486 IE Insp Rept 50-382/82-29 on 821213-16. No noncompliance noted Major areas inspected observation of work & review of procedures & records for safety-related structural steel & supports & review of site audit repts
JOHNSTON, C E, HUNNICUTT, D H, MULLIKIN, R P Division of Resident, Reactor Project & Engineering Programs 83/01/11 10pp 17036:039 24X Fiche 50-382, 83/01/13, 8302070481

8302030573 Forwards IE Insp Rept 50-382/82-27 on 820916-1031 & notice of violation
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 83/01/18 MAURIN, L V Louisiana Power & Light Co 2pp 17008:037 24X Fiche 50-382, 83/01/18, 8302030573.

--8302030580 Notice of violation from insp on 820916-1031
* Division of Resident, Reactor Project & Engineering Programs 83/01/18 2pp 17008:039 24X Fiche 50-382, 83/01/18, 8302030573

--8302030590 IE Insp Rept 50-382/82-27 on 820916-1031 Noncompliance noted failure to follow procedures during primary & secondary hydrostatic testing.
CONSTABLE, O L, CUMMINS, J E, FLIPPOT, A Division of Resident, Reactor Project & Engineering Programs 83/01/03 7pp 17008:041 24X Fiche 50-382, 83/01/18, 8302030573

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Bvc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/24 Consolidated Edison Co of New York, Inc 118pp 17023:160. 24X Fiche 50-000, 83/01/26, 8212060358

8302010505 Ack receipt of 821029 & 1222 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/82-18 W/o 821029 ltr
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 83/01/27 MAURIN, L V Louisiana Power & Light Co 1p. 16978:085 24X Fiche 50-382, 83/01/27, 8302010505.

--8302010520 Responds to NRC 821203 ltr re violations noted in IE Insp Rept 50-382/82-18 Corrective actions: Procedure ASP-I-3 "Indoctrination & Training," revised & training continuing on ongoing basis
MAURIN, L V Louisiana Power & Light Co 82/12/22 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs. 2pp 16978:086 24X Fiche 50-382, 83/01/27, 8302010505

8302030095 Forwards info requested by NRC at 810826 meeting, comparing preservice insp actually conducted on pressure vessel to Reg Guide 1.50 requirements.
MAURIN, L V Louisiana Power & Light Co 83/01/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17004:293 24X Fiche 50-382, 83/01/27, 8302030095

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Osmheads." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144:001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Caliber of Liquid Level Instruments." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/28 Consolidated Edison Co of New York, Inc. 110pp. 17074:095 24X Fiche 50-000, 83/01/28, 8212060361.

8302090405 Informs of emergency preparedness appraisal insp on 830222-0304 Emergency plan & emergency procedures & support document availability in work area requested. Entrance interview scheduled for 830222
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 83/02/03 MAURIN, L V Louisiana Power & Light Co 2pp. 17071:083 24X Fiche 50-382, 83/02/03, 8302090405.

8302230120 Responds to 830203 request for info re use of NRC mobile lab within protected area & while conducting confirmatory measurements insp on 830228-0304.
COLLINS, J T. Region 4, Office of Director. 83/02/14 MAURIN, L V Louisiana Power & Light Co. 2pp 17243:272. 24X Fiche 50-382, 83/02/14, 8302230120.

8302230365 Advises of program initiated to send copy of insp repts of vendors used at facilities. Repts will be forwarded w/o transmittal ltr through resident inspector w/distribution ticket used to flag significant problems.
COLLINS, J T. Region 4, Office of Director 83/02/16 MAURIN, L V Louisiana Power & Light Co 3pp. 17256:139. 24X Fiche 50-382, 83/02/16, 8302230365

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347:191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347:058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Bvc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361:148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302220265 Interim deficiency rept re Significant Const Deficiency 61 "Spurious EBF Actuation Sys Activation." Initially reported on 830111. Field change initiated to modify wiring of trip path logic to J3107 connectors. Final rept due by 830331.
MAURIN, L V Louisiana Power & Light Co 83/02/10 COLLINS, J T. Region 4, Office of Director 3pp 17230:119. 24X Fiche 50-382, 83/02/10, 8302220265

8302230301 Second interim rept of Significant Const Deficiency 60 re turnover documentation & inadequate hanger welds
Corrective action approx 85% complete. Next rept will be submitted by 830310
MAURIN, L V Louisiana Power & Light Co 83/02/14 COLLINS, J T. Region 4, Office of Director 1p. 17243:012. 24X Fiche 50-382, 83/02/14, 8302230301

8302230320 Interim deficiency rept re design application of break flanges at elevated temps Documentation review in progress.
Final rept will be submitted by 830228
MAURIN, L V Louisiana Power & Light Co 83/02/14 COLLINS, J T. Region 4, Office of Director 1p 17248:153 24X Fiche 50-382, 83/02/14, 8302230320

8302230345 Third interim deficiency rept re undersize welds on 1/2-11 schedule 160 pipe. Corrective action complete Engineering & QA reviewing & assembling documentation. Final rept will be submitted by 830321
MAURIN, L V Louisiana Power & Light Co 83/02/14 COLLINS, J T. Region 4, Office of Director 1p. 17248:311 24X Fiche 50-382, 83/02/14, 8302230345

8302280335 Informs that Final Deficiency Rept BCD 42 re HMA auxiliary relays reopened. Caused by inadequate reflection of scope of corrective action. Final rept expected by 830328.
MAURIN, L V Louisiana Power & Light Co 83/02/14 COLLINS, J T. Region 4, Office of Director 1p. 17309:012. 24X Fiche 50-382, 83/02/14, 8302280335

8302280329 Fourth Interim Deficiency Rept 54 re tube steel (HT 16600 laminations) Corrective action described in 820511 ltr not completed. Final rept will be submitted by 830318
MAURIN, L V Louisiana Power & Light Co 83/02/17 COLLINS, J T. Region 4, Office of Director. 1p. 17313:040. 24X Fiche 50-382, 83/02/17, 8302280329.

8302280333 Fourth Interim Deficiency Rept 55 re incorrect structural calculations for holdup & boric acid makeup tanks. Due to delays in const mod to tank supports, completion delayed to 830318. Final rept expected by 830330
MAURIN, L V Louisiana Power & Light Co 83/02/17 COLLINS, J T. Region 4, Office of Director. 1p. 17313:041. 24X Fiche 50-382, 83/02/17, 8302280333.

Y. Hearing transcripts on non-antitrust matters

8302150699 Transcript of 830208 hearing in New Orleans, LA. Pp 4, 024-4, 231. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/02/08. 243pp. 17153:055. 24X Fiche 50-382, 83/02/08, 8302150699.

8302150643 Transcript of 830209 hearing in New Orleans, LA. Pp 4, 232-4, 461. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/02/09. 262pp. 17151:040 24X Fiche 50-382, 83/02/09, 8302150643.

8302160289 Transcript of 830210 hearing in New Orleans, LA. Pp 4, 482-4, 736. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/02/10. 293pp. 17166:311 24X Fiche 50-382, 83/02/10, 8302160289.

DOCKETED ITEMS

8302160259 Transcript of 830211 hearing in New Orleans, LA. Pp 4, 737-4, 903
* Atomic Safety and Licensing Board Panel. 83/02/11 169pp
17169.244 24X Fiche 50-387, 83/02/11, 8302160259

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NRB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D G Division of Licensing. 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347.177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
BAGCHI, O. Equipment Qualification Branch. 83/02/02. NODNAN, V S
Equipment Qualification Branch 3pp 17205.188 24X
Fiche 50-000, 83/02/02, 8302170011.

--8104010266 Trip rept of 810316-20 site visit re qualification methods, procedures & results for selected safety-related mechanical & electrical equipment & supporting structures.
LEE, A Equipment Qualification Branch 81/03/14 ROBERTOCZY, Z R
Equipment Qualification Branch. 7pp 17206.006. 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170104 Forwards repts re 20 equipment items reviewed during 810316-20 site visit
REICH, M Brookhaven National Laboratory 81/06/25. ROBERTOCZY, Z.
Equipment Qualification Branch 45pp 17206.013 24X
Fiche 50-000, 83/02/02, 8302170011

--8110190094 Trip rept for 810819-20 site visit to perform second seismic qualification review audit Program adequate. Review including Phase III new load requalification will continue until scheduled completion in June 1982
LEE, A Equipment Qualification Branch 81/09/29 ROBERTOCZY, Z R.
Equipment Qualification Branch. 5pp 17206.112 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170195 Forwards summary repts of six items audited during 810819-20 site visit
REICH, M Brookhaven National Laboratory 82/01/18 ROBERTOCZY, Z
Equipment Qualification Branch 18pp 17206.132 24X
Fiche 50-000, 83/02/02, 8302170011

F Security, medical, emergency & fire protection plans

8302030267 Releases public version of util request that emergency plan & procedures controlled manuals be returned within 10 working days
FELTON, J. M. Division of Rules and Records. 83/01/26 Document
Management Branch 1p 17023.286 24X Fiche 50-387, 83/01/26, 8302030267.

--8302030276 Submits public version of request that emergency plan & procedures controlled manuals be returned within 10 working days.
WHARTON, J. T Pennsylvania Power & Light Co. 83/01/19
DENTON, H. R. NRC - No Detailed Affiliation Given 1p 17023.287
24X Fiche: 50-387, 83/01/26, 8302030267

8302020405 Releases public version of Temporary Change Notices
FELTON, J. M. Division of Rules and Records. 83/01/27 Document
Management Branch 1p 16999.345 24X Fiche: 50-387, 83/01/27, 8302020405.

--8302020410 Forwards public version of Temporary Change Notices 83-0021 through 83-0028 for Emergency Plan Implementing Procedures, including Procedures EP-IP-001 re emergency classification & EP-IP-021 re site emergency evacuation
* Pennsylvania Power & Light Co. 83/01/10. DENTON, H. R. NRC - No Detailed Affiliation Given. 1p. 16999.346. 24X
Fiche 50-387, 83/01/27, 8302020405.

--8302020418 Public version of Temporary Change Notices 83-0021 through 83-0028 for Emergency Plan Implementing Procedures, including Procedures EP-IP-001 re emergency classification & EP-IP-021 re site emergency evacuation.
* Pennsylvania Power & Light Co. 83/01/07. 8pp 16999.347. 24X
Fiche 50-387, 83/01/27, 8302020405.

8302070247 Application for Amend 16 to License NPF-14, revising Item 2 C 6 re fire protection program
CURTIS, N. W. Pennsylvania Power & Light Co 83/01/31 SCHWENCER, A
Licensing Branch 2 2pp 17031.285 24X Fiche 50-387, 83/01/31, 8302070247

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221.226 24X
Fiche 50-000, 83/02/01, 8301210340

8302090382 Requests continued submittal of three copies of changes to emergency plan & emergency plan implementing procedures
Dedicated controlled copies assure better coordination during accident situations
MARTIN, T T Division of Engineering & Technical Programs 83/02/02
KENYON, B D Pennsylvania Power & Light Co 2pp 17071.087 24X
Fiche: 50-387, 83/02/02, 8302090382

8302180222 Forwards IE Insp Rept 50-387/83-01 on 830110-14 No noncompliance noted
MARTIN, T T. Division of Engineering & Technical Programs 83/02/04
KENYON, B D Pennsylvania Power & Light Co 2pp 17215.303 24X
Fiche 50-387, 83/02/04, 8302180222

--8302180225 IE Insp Rept 50-387/83-01 on 830110-14 No noncompliance noted Major areas inspected, implementation of administration procedures, fire brigade training, observation of ignition source & combustible matl control & plant fire areas
FINKEL, A E, ANDERSON, C Division of Engineering & Technical Programs. 83/01/31 5pp 17215.305 24X Fiche 50-387, 83/02/04, 8302180222

8302170059 Informs that proposed changes to program for storage of safeguards info transmitted in 830111 ltr acceptable
SCHWENCER, A Licensing Branch 2 83/02/07 CURTIS, N W
Pennsylvania Power & Light Co 1p 17191.068. 24X
Fiche: 50-387, 83/02/07, 8302170059.

8302240146 Forwards Amend 10 to License NPF-14, safety evaluation & notice of issuance & availability Amend adds Fire Zone 1-28 & deletes Fire Zone 1-6A from Tech Spec 3.7 & 2 re sprinkler & spray sys operability
SCHWENCER, A Licensing Branch 2 83/02/10 CURTIS, N W.
Pennsylvania Power & Light Co 3pp 17288.277 24X
Fiche 50-387, 83/02/10, 8302240146

--8302240151 Amend 10 to License NPF-14, adding Fire Zone 1-28 & deleting Fire Zone 1-6A from Tech Spec 3.7 & 2 listing areas where spray & sprinkler sys shall be operable
SCHWENCER, A Licensing Branch 2 83/02/10 5pp 17288.280 24X
Fiche: 50-387, 83/02/10, 8302240146

--8302240156 Safety evaluation supporting Amend 10 to License NPF-14.
* Office of Nuclear Reactor Regulation, Director. 83/02/10 2pp 17288.285 24X Fiche 50-387, 83/02/10, 8302240146

--8302240160 Notice of issuance & availability of Amend 10 to License NPF-14.
SCHWENCER, A Licensing Branch 2 83/02/10 2pp 17288.287 24X
Fiche 50-387, 83/02/10, 8302240146

8302180251 Forwards Change B to security training & qualification plan Change withheld (ref 10CFR2.790).
CURTIS, N. W. Pennsylvania Power & Light Co 83/02/11 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p. 17215.274. 24X
Fiche: 50-387, 83/02/11, 8302180251

8302170485 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/02/15. Document
Management Branch 1p 17203.213. 24X Fiche: 50-387, 83/02/15, 8302170485

--8302170490 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-002, "Emergency Mgt Notifications" & Rev 0 to EP-IP-102, "Surveillance Testing of Emergency Communications Equipment."
* Pennsylvania Power & Light Co 83/01/28. SCHWENCER, A NRC - No Detailed Affiliation Given 1p. 17203.214. 24X
Fiche: 50-387, 83/02/15, 8302170485

--8302170497 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-002, "Emergency Mgt Notifications" & Rev 0 to EP-IP-102, "Surveillance Testing of Emergency Communications Equipment" Revised index encl.
* Pennsylvania Power & Light Co 83/01/20 94pp. 17203.215. 24X
Fiche: 50-387, 83/02/15, 8302170485

8302250021 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 83/02/16 Document
Management Branch 1p 17299 001 24X Fiche 50-387, 83/02/16,
8302250021

--8302250029 Forwards public version of Rev 1 to Emergency Plan
Implementing Procedure EP-IP-044, "Emergency Environ
Sampling " Revised table of contents & index encl
* Pennsylvania Power & Light Co 83/01/26 SCHWENCER, A NRC -
No Detailed Affiliation Given 6pp 17299 002 24X
Fiche 50-387, 83/02/16, 8302250021

--8302250035 Public version of Rev 1 to Emergency Plan Implementing
Procedure EP-IP-044, "Emergency Environ Sampling "
* Pennsylvania Power & Light Co 83/01/21 65pp 17299 008
24X Fiche 50-387, 83/02/16, 8302250021

Q Adjudicatory correspondence

8302020284 Forwards license amend, incorporating limiting condition
for operation restricting increases in unidentified leakage
w/o encl
CUTCHIN, J. M. Hearing Branch 4 83/02/01 MOORE, T. S.
ELTHERIN, B. F., BUCK, J. H. Atomic Safety and Licensing Appeal Panel
1p 16993 317 24X Fiche 50-387, 83/02/01, 8302020284

H General correspondence

8302150511 Comments on concerns expressed re plume & ingestion exposure
pathway emergency planning zones Concerns re radiological
emergency response plan for communities around facility will
be addressed by FEMA & PA Emergency Mgt Agency
HAYNES, R. C. Region 1, Office of Director 83/02/09 NEMETHY, E.
Affiliation Unknown 3pp 17156 250 24X Fiche 50-387, 83/02/09,
8302150511

P Operating license stage documents & correspondence

8208060366 Board Notification 82-70 notifies of differing prof opinion
re sensitization of BWR stainless steel weldments
EISENHUT, D. G. Division of Licensing 82/07/20 PALLADINO, N. J.
Commissioners 4pp, 17043 001 24X Fiche 50-000, 82/07/20,
8208060366

--8302040531 Presents rebuttal to SR Pawlicki 810414 memo to RH Vollmer
on differing prof opinion re generic sensitization of BWR
stainless steel weldments
MALAPATZ, J. Materials Engineering Branch 81/04/14 VOLLMER, R. H.
Division of Engineering 3pp 17043 009 24X
Fiche 50-387, 82/07/20, 8208060366

8302080113 Board Notification 82-122A forwards USGS 821118 ltr
clarifying previous recommendations re recurrence of 1886
Charleston-type earthquake w/o encl
NOVAK, T. H. Assistant Director for Licensing 82/12/30 Atomic
Safety and Licensing Board Panel 18pp 17105 335 24X
Fiche 50-000, 82/12/30, 8302080113

8302030403 Application to amend License NPF-14, consisting of proposed
Amend 18, revising Items 2.A, 2.B (2) & 2.C (9) re post-fuel
loading initial test program
CURTIS, N. W. Pennsylvania Power & Light Co 83/01/31 SCHWENCER, A.
Licensing Branch 2 3pp 17005 199 24X Fiche 50-387, 83/01/31,
8302030403

8302070247 Application for Amend 16 to License NPF-14, revising
Item 2.C & re fire protection program
CURTIS, N. W. Pennsylvania Power & Light Co 83/01/31, SCHWENCER, A.
Licensing Branch 2 2pp 17031 285 24X Fiche 50-387, 83/01/31,
8302070247

8302080406 Forwards Amend 7 to License NPF-14, safety evaluation &
notice of issuance & availability Amend revises Tech Specs
to be consistent w/NUREG-0313 & STB re RCB.
SCHWENCER, A. Licensing Branch 2. 83/01/31 CURTIS, N. W.
Pennsylvania Power & Light Co 3pp 17074 340 24X
Fiche 50-387, 83/01/31, 8302080406

--8302080409 Amend 7 to License NPF-14, revising Tech Specs 3.4.3.2 &
4.4.3.2.1 to be consistent w/NUREG-0313 & STB re RCB
SCHWENCER, A. Licensing Branch 2 83/01/31. 8pp 17074 345 24X
Fiche 50-387, 83/01/31, 8302080406.

--8302080413 Safety evaluation supporting Amend 7 to License NPF-14
* Office of Nuclear Reactor Regulation, Director 83/01/31 2pp
17074, 353 24X Fiche 50-387, 83/01/31, 8302080406

--8302080417 Notice of issuance & availability of Amend 7 to License
NPF-14
SCHWENCER, A. Licensing Branch 2 83/01/31 3pp 17074 355 24X
Fiche 50-387, 83/01/31, 8302080406

8302090309 Forwards application for Amend 19 to License NPF-14, changing
Tech Specs to allow expansion of operating region of power/
flow map for initial fuel cycle & sampling alignment to
either drywell or suppression pool
CURTIS, N. W. Pennsylvania Power & Light Co 83/02/03 SCHWENCER, A.
Licensing Branch 2. 2pp 17069 284 24X Fiche 50-387, 83/02/03,
8302090309

--8302090314 Application for Amend 19 to License NPF-14, revising Tech
Specs to allow expansion of operating region of power/
flow map for initial fuel cycle & sampling alignment to either
drywell or suppression pool.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/03 1p
17069 286 24X Fiche 50-387, 83/02/03, 8302090309

--8302090320 Proposed Tech Specs 2.2.1, 1.3.2.2, 4.2.2 & 3.3.4-2 re
reactor protection sys instrumentation, average power range
monitor & control rod block instrumentation setpoints.
* Pennsylvania Power & Light Co 83/02/03. 3pp 17069, 287 24X
Fiche 50-387, 83/02/03, 8302090309

--8302090323 "OE BWR Extended Load Line Limit Analysis for Busquehanna
Steam Electric Station Unit 1"
* General Electric Co NEDO-22128 82/05/31. 43pp 17069, 291,
24X Fiche 50-387, 83/02/03, 8302090309

--8302090332 Proposed Tech Specs 3.4.3 & 4.4.3 re RCS leakage detection
sys
* Pennsylvania Power & Light Co 83/02/03. 1p, 17069 332. 24X
Fiche 50-387, 83/02/03, 8302090309

8302160121 Provides daily highlight for 830204 Reactor power of 100%
achieved
PERCH, R. L. Licensing Branch 2 83/02/04, DENTON, H. R., CASE, E. G.,
CARTER, J. Office of Nuclear Reactor Regulation, Director 1p
17160 293 24X Fiche 50-387, 83/02/04, 8302160121

8302160050 Forwards Amend 9 to License NPF-14, safety evaluation &
notice of issuance & availability Amend allows 23
operational cycles on recirculation discharge valve
assemblies w/o motor brake
EISENHUT, D. G. Division of Licensing 83/02/07, CURTIS, N. W.
Pennsylvania Power & Light Co 3pp, 17160 336 24X
Fiche 50-387, 83/02/07, 8302160050

--8302160054 Amend 9 to License NPF-14, allowing 25 operational cycles
on recirculation discharge valve assemblies w/o motor brake
EISENHUT, D. G. Division of Licensing 83/02/07 2pp, 17160, 339,
24X Fiche: 50-387, 83/02/07, 8302160050.

--8302160060 Safety evaluation supporting Amend 9 to License NPF-14
* Office of Nuclear Reactor Regulation, Director 83/02/07. 2pp,
17160, 341 24X Fiche, 50-387, 83/02/07, 8302160050.

--8302160064 Notice of issuance & availability of Amend 9 to License
NPF-14
SCHWENCER, A. Licensing Branch 2. 83/02/07. 2pp 17160, 343. 24X
Fiche 50-387, 83/02/07, 8302160050

8302180026 Forwards Amend 8 to License NPF-14, safety evaluation &
notice of issuance & availability Amend makes administrative
corrections.
SCHWENCER, A. Licensing Branch 2 83/02/07. CURTIS, N. W.
Pennsylvania Power & Light Co 2pp 17221:343 24X
Fiche 50-387, 83/02/07, 8302180026

--8302180029 Amend 8 to License NPF-14, changing Tech Specs to
correct typographical errors
SCHWENCER, A. Licensing Branch 2 83/02/07 9pp, 17221, 345. 24X
Fiche 50-387, 83/02/07, 8302180026

--8302180034 Safety evaluation supporting Amend 8 to License NPF-14.
* Office of Nuclear Reactor Regulation, Director. 83/02/07 2pp
17221 354. 24X Fiche 50-387, 83/02/07, 8302180026.

--8302180037 Notice of issuance & availability of Amend 8 to License
NPF-14
SCHWENCER, A. Licensing Branch 2. 83/02/07. 2pp, 17221:356 24X
Fiche 50-387, 83/02/07, 8302180026.

DOCKETED ITEMS

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290:247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-08 to BWR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re BER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982, Guidelines acceptable, Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/08 Commonwealth
Edison Co 4pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301.

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions. Ability to use code must be demonstrated by vendor or licensee Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304.

8302150198 Forwards application for Amend 20 to License NPF-14, revising Tech Spec Table 3.3.3-1 re ECCS actuation instrumentation to correct typographical error.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/08 SCHWENCER, A.
Licensing Branch 2 1p 17130:022, 24X Fiche 50-387, 83/02/08, 8302150198

--8302150207 Application for Amend 20 to License NPF-14, revising Tech Spec Table 3.3.3-1 re ECCS actuation instrumentation to correct typographical error.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/08 1p
17130.023 24X Fiche 50-387, 83/02/08, 8302150198

--8302150212 Proposed Tech Spec Table 3.3.3-1 re ECCS actuation instrumentation, correcting typographical error
* Pennsylvania Power & Light Co 83/02/08 1p 17130 024 24X
Fiche 50-387, 83/02/08, 8302150198

8302150734 Notification of 830218 meeting w/util in Bethesda, MD to discuss dose calculations & reporting
PERCH, R. L. Licensing Branch 2 83/02/08 SCHWENCER, A. Licensing
Branch 2 3pp 17160 101 24X Fiche 50-387, 83/02/08, 8302150734

8302230634 Forwards determination of eligibility notification for four sites in Luzerne County, PA Sites considered eligible for inclusion in Natl Register of Historic Places
* Interior, Dept. of, National Park Service, 83/02/10 NRC - No
Detailed Affiliation Given 5pp 17255.249 24X
Fiche 50-387, 83/02/10, 8302230634

8302240146 Forwards Amend 10 to License NPF-14, safety evaluation & notice of issuance & availability, Amend adds Fire Zone 1-2B & deletes Fire Zone 1-4A from Tech Spec 3.7 & 2 re sprinkler & spray sys operability.
SCHWENCER, A. Licensing Branch 2 83/02/10 CURTIS, N. W.
Pennsylvania Power & Light Co 3pp 17288 277 24X
Fiche 50-387, 83/02/10, 8302240146

--8302240151 Amend 10 to License NPF-14, adding Fire Zone 1-2B & deleting Fire Zone 1-4A from Tech Spec 3.7 & 2 listing areas where spray & sprinkler sys shall be operable
SCHWENCER, A. Licensing Branch 2 83/02/10, 5pp, 17288 280, 24X
Fiche 50-387, 83/02/10, 8302240146

--8302240156 Safety evaluation supporting Amend 10 to License NPF-14
* Office of Nuclear Reactor Regulation, Director 83/02/10, 2pp,
17288-285, 24X Fiche 50-387, 83/02/10, 8302240146

--8302240160 Notice of issuance & availability of Amend 10 to License NPF-14
SCHWENCER, A. Licensing Branch 2 83/02/10 2pp 17288:287, 24X
Fiche 50-387, 83/02/10, 8302240146

8302280091 Forwards 503 oversize revised drawings per Reg Guide 1.70 Marked-up FSAR Table 1.7-1 encl. Aperture cards are available in PDR.
CODDINGTON, C. T. Pennsylvania Power & Light Co 83/02/11,
Commissioners, 12pp 17306 090, 24X Fiche 50-387, 83/02/11,
8302280091.

8302180019 Notification of 830218 meeting w/util in Bethesda, MD to discuss requirements for startup test rept.
PERCH, R. L. Licensing Branch 2 83/02/14, SCHWENCER, A. Licensing
Branch 2, 3pp, 17221 338, 24X Fiche 50-387, 83/02/14, 8302180019

8302250090 Notification of cancellation of 830218 meeting w/util in Bethesda, MD to discuss requirements for startup test rept
Meeting will be rescheduled
PERCH, R. L. Licensing Branch 2 83/02/14 SCHWENCER, A. Licensing
Branch 2 3pp 17302 328 24X Fiche 50-387, 83/02/14, 8302250090

G Inspection reports, IE Bulletins & correspondence

8302100288 Forwards IE Insp Repts 50-387/82-45 & 50-388/82-14 on 821201-830111 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/01/25
KENYON, B. D. Pennsylvania Power & Light Co 2pp 17112 007 24X
Fiche 50-387, 83/01/25, 8302100288

--8302100292 IE Insp Repts 50-387/82-45 & 50-388/82-14 on 821201-830111 No noncompliance noted Major areas inspected, preoperational test review & startup test witnessing, licensee event followup, Tech Spec compliance, open item & plant status
RHOADS, O. O., MCCANN, J. F., MCCABE, E. C. Division of Project & Resident Programs 82/01/24 9pp 17112 009 24X
Fiche 50-387, 83/01/25, 8302100288

8302100430 Forwards IE Insp Rept 50-387/82-43 on 821129-1203 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/01/25
KENYON, B. D. Pennsylvania Power & Light Co 2pp 17117.176, 24X
Fiche 50-387, 83/01/25, 8302100430

--8302100437 IE Insp Rept 50-387/82-43 on 821129-1203 No noncompliance noted Major areas inspected previous insp findings, IE Bulletin 80-10, radiation survey, chemical & radiochemical tests, radwaste sys mode & personnel exposure records
NIMITZ, R. L., COLLINS, D. J., SHANAKY, M. H. Division of Engineering & Technical Programs, 83/01/19 11pp 17117 178 24X
Fiche 50-387, 83/01/25, 8302100430

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023:160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc. 109pp 17144.001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074.093 24X Fiche 50-000, 83/01/28, 8212060361

8302030559 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/82-40 & 50-388/82-12
STAROSTECKI, R. Division of Project & Resident Programs 83/01/28
KENYON, B. D. Pennsylvania Power & Light Co 2pp, 17008.029 24X
Fiche 50-387, 83/01/28, 8302030559

--8302030564 Responds to NRC 821214 ltr re violations noted in IE Insp Repts 50-387/82-40 & 50-388/82-12 Corrective actions; requirement to verify suppression pool temp per Tech Spec Section 4.6.2 1.b 1 added to operating test procedure
KENYON, B. D. Pennsylvania Power & Light Co. 83/01/12
STAROSTECKI, R. Division of Project & Resident Programs 3pp,
17008 031 24X Fiche 50-387, 83/01/28, 8302030559

8302180222 Forwards IE Insp Rept 50-387/83-01 on 830110-14 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/04
KENYON, B. D. Pennsylvania Power & Light Co 2pp 17215 303 24X
Fiche 50-387, 83/02/04, 8302180222

--8302180225 IE Insp Rept 50-387/83-01 on 830110-14 No noncompliance noted Major areas inspected, implementation of administration procedures, fire brigade training, observation of ignition source & combustible mat control & plant fire areas.
FINKEL, A. E., ANDERSON, G. Division of Engineering & Technical Programs 83/01/31, 5pp 17215:305, 24X Fiche 50-387, 83/02/04,
8302180222.

8302280441 Forwards IE Insp Rept 50-387/82-42 on 821115-1222 No noncompliance noted
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/14
KENYON, B. D. Pennsylvania Power & Light Co. 2pp, 17307:330 24X
Fiche 50-387, 83/02/14, 8302280441.

DOCKETED ITEMS

27

--8302280446 IE Insp Rept 50-387/82-42 on 821115-1222 No noncompliance noted Major areas inspected licensee action on previous insp findings, administrative controls of startup testing, plateau review of heatup phase testing & calibr tests
PULLANI, B., PETRONE, C., CHUNG, J. W. Division of Engineering & Technical Programs 83/02/08 19pp 17307 352 24X
Fiche 50-387, 83/02/14, 8302280441

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302280547 Forwards annual personnel exposure rept for CY82 reflecting activities both before & after 820717 receipt of DL
KENYON, B. D. Pennsylvania Power & Light Co 83/02/22 HAYNES, R. C. Region 1, Office of Director 1pp 17309 138 24X
Fiche 50-387, 83/02/22, 8302280547.

--8302280553 Annual personnel exposure rept for CY82
* Pennsylvania Power & Light Co 83/02/22 2pp 17309 139 24X
Fiche 50-387, 83/02/22, 8302280547.

B Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
DUVALL, D. D. Brown Boveri Corp. (subs Brown Boveri & Co., Ltd.)
82/12/10 STELLO, V. Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-000, 82/12/10, 8212140330

8302010160 Forwards LER 82-078/03L-0
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/17 HAYNES, R. C. Region 1, Office of Director 1p 16974 163 24X
Fiche 50-387, 83/01/17, 8302010160

--8302010168 LER 82-078/03L-0 on 821218, during startup testing program, two jet pumps did not indicate flowrate Caused by failure of trapped in lines Air bled off & indicators returned to normal. Source of air could not be determined
MITCHELL, D. O. Pennsylvania Power & Light Co. 83/01/17 Region 1, Office of Director 1p 16974 164 24X Fiche 50-387, 83/01/17, 8302010160

8302010151 Forwards LER 83-001/01T-0
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/19 HAYNES, R. C. Region 1, Office of Director 1p 16974.157 24X
Fiche 50-387, 83/01/19, 8302010151

--8302010158 LER 83-001/01T-0 on 830109, main condenser offgas monitor train declared inoperable precipitating entry into action statement requiring grab sample be taken every 4 h. Sample not taken due to technician error
MITCHELL, D. O. Pennsylvania Power & Light Co. 83/01/19 Region 1, Office of Director 2pp 16974 158 24X Fiche: 50-387, 83/01/19, 8302010151

8302010351 RO on 821211, channels to loose parts monitoring sys determined inoperable due to erroneous data. Caused by incorrect low level alarm settings. Alarm levels reset.
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/19 HAYNES, R. C. Region 1, Office of Director 2pp 16977.027. 24X
Fiche 50-387, 83/01/19, 8302010351

8302010324 RO on 821207, fire detector 113-101 determined inoperable Cause undetermined. Plant mod required prior to installation of replacement since failed detector no longer in production.
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/20. HAYNES, R. C. Region 1, Office of Director. 2pp 16973.004. 24X
Fiche 50-387, 83/01/20, 8302010324.

8302030223 LER 83-002/01P-0 on 830120, during review of plant matrix, discovered monthly channel functional tests of MSIV closure position switches not performed Functional testing successfully completed
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/21 HAYNES, R. C. Region 1, Office of Director 1p 17001 338 24X
Fiche 50-387, 83/01/21, 8302030223.

8302030555 Forwards LER 82-079/03L-0
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/21 HAYNES, R. C. Region 1, Office of Director 1p. 17008 034. 24X
Fiche 50-387, 83/01/21, 8302030555

--8302030560 LER 82-079/03L-0 on 821222, during recovery from startup program test, RCS temp exceeded 100 F/h heatup rate Caused by operator error Event will be incorporated into operator training & requalification. Procedures revised
KUCZYNSKI, L. A. Pennsylvania Power & Light Co. 83/01/21. Region 1, Office of Director. 2pp 17008 035 24X Fiche 50-387, 83/01/21, 8302030555

8302030074 RO on 821221, unauthorized release of liquid radwaste discharged Caused by inadvertent aligning of C & D sample tanks to discharge line instead of laundry drain sample tanks. Release status board installed.
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/24. HAYNES, R. C. Region 1, Office of Director 2pp 17004.325 24X
Fiche 50-387, 83/01/24, 8302030074

8302030278 Forwards LER 82-081/03L-0.
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/25. HAYNES, R. C. Region 1, Office of Director 1p. 17001 253 24X
Fiche 50-387, 83/01/25, 8302030278

--8302030297 LER 82-081/03L-0 on 821226, while decreasing power during startup testing, four fuses blew in main reactor manual control sys. causing loss of red position display Caused by transient current surge Fuses replaced.
MITCHELL, D. O. Pennsylvania Power & Light Co. 83/01/25. Region 1, Office of Director. 2pp 17001 254 24X Fiche: 50-387, 83/01/25, 8302030278

8302030357 Forwards LER 82-080/03L-0
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/25 HAYNES, R. C. Region 1, Office of Director 1p. 17005 351. 24X
Fiche: 50-387, 83/01/25, 8302030357

--8302030361 LER 82-080/03L-0 on 821226, surveillance per Tech Spec 4.2 i could not be performed within time limits Caused by failure of nuclear steam sys processor due to interaction between transverse in-core probe switch position & processor
MITCHELL, D. O. Pennsylvania Power & Light Co. 83/01/25. Region 1, Office of Director 2pp 17005 352 24X Fiche: 50-387, 83/01/25, 8302030357

8302100418 Forwards LER 83-003/03L-0.
KEIBER, H. W. Pennsylvania Power & Light Co. 83/01/31. HAYNES, R. C. Region 1, Office of Director 1p 17117.022 24X
Fiche 50-387, 83/01/31, 8302100418

--8302100424 LER 83-003/03L-0 on 830101, required vacuum of HVAC Zone II, not maintained Caused by pressure fluctuations at exterior delta pressure sensor due to excessive high winds Vacuum setpoint raised to decrease sensitivity
* Pennsylvania Power & Light Co. 83/01/31 Region 1, Office of Director 2pp 17117.023 24X Fiche 50-387, 83/01/31, 8302100418.

8302230289 Forwards LER 83-002/01T-0.
KEIBER, H. W. Pennsylvania Power & Light Co. 83/02/02 HAYNES, R. C. Region 1, Office of Director. 1p. 17244 328 24X
Fiche 50-387, 83/02/02, 8302230289.

--8302230292 LER 83-002/01T-0 on 830119, main steam isolation valve closure surveillance not performed per Tech Specs. Caused by omission from implementing procedure Procedure performed.
MSIV position switches tested operable
MITCHELL, D. O. Pennsylvania Power & Light Co. 83/02/02 Region 1, Office of Director 2pp. 17244:329. 24X Fiche: 50-387, 83/02/02, 8302230289

8302230447 Forwards LER 83-004/03L-0
KEIBER, H. W. Pennsylvania Power & Light Co. 83/02/02 HAYNES, R. C. Region 1, Office of Director. 1p 17246 043 24X
Fiche 50-387, 83/02/02, 8302230447.

--8302230457 LER 83-004/03L-0 on 830103, during startup testing, diesel generator C failed to start. Caused by overvoltage trip due to incorrect setting for voltage regulator & relay picking up lower than expected. Procedures revised.
MITCHELL, D. O. Pennsylvania Power & Light Co. 83/02/02 Region 1, Office of Director 2pp 17246 044 24X Fiche: 50-387, 83/02/02, 8302230447

DOCKETED ITEMS

8302230133 Forwards LER 83-009/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/03 HAYNES, R C
 Region 1, Office of Director 1p 17243 274 24X
 Fiche 50-387, 83/02/03, 8302230133

--8302230139 LER 83-009/03L-0 on 830104, average power range monitor D declared inoperable after failing weekly functional test
 Caused by human error Channel gains adjusted
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/03 Region
 1, Office of Director 2pp 17243 275 24X Fiche 50-387,
 83/02/03, 8302230133

8302230694 Forwards LER 83-009/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/03 HAYNES, R C
 Region 1, Office of Director 1p 17257 327 24X
 Fiche 50-387, 83/02/03, 8302230694

--8302230697 LER 83-009/03L-0 on 830106, during startup testing program, unidentified RCS leakage exceeded 5 gpm Caused by valve packing failure Valve repacked
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/04 Region
 1, Office of Director 2pp 17257 328 24X Fiche 50-387,
 83/02/03, 8302230694

8302180245 Suppl to final deficiency rept re vertically installed Anchor-Darling check valves Satisfactory testing completed on 10 of 12 valves

CURTIS, M W Pennsylvania Power & Light Co 83/02/04 HAYNES, R C
 Region 1, Office of Director 2pp 17215 261 24X
 Fiche 50-387, 83/02/04, 8302180245

8302180273 Forwards LER 83-008/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/04 HAYNES, R C
 Region 1, Office of Director 1p 17212 059 24X
 Fiche 50-387, 83/02/04, 8302180273

--8302180282 LER 83-008/03L-0 on 830107, during startup test program, both control structure chlorine detectors declared inoperable due to failure of constant drip feature Caused by contaminated wick Wick replaced
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/04 Region
 1, Office of Director 1p 17212 060 24X Fiche 50-387, 83/02/04,
 8302180273,

8302180317 Forwards LER 83-006/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/04 HAYNES, R C
 Region 1, Office of Director 1p 17213 349 24X
 Fiche 50-387, 83/02/04, 8302180317

--8302180323 LER 83-006/03L-0 on 830108, RCS conductivity exceeded 2.0 micromhos/cm while in Operational Condition 2. Caused by inadvertent isolation of reactor water cleanup sys due to faulty relay module in control circuitry Module replaced
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/04 Region
 1, Office of Director 2pp 17213 350 24X Fiche 50-387,
 83/02/04, 8302180317

8302230333 Forwards LER 83-007/03L-0.

KEISER, H W Pennsylvania Power & Light Co 83/02/09 HAYNES, R C
 Region 1, Office of Director 1p 17248 267 24X
 Fiche 50-387, 83/02/09, 8302230333

--8302230338 LER 83-007/03L-0 on 830110, during startup testing, average power range monitor scram & rod block setpoints not in tolerance Caused by inherent qualities of xenon free startup causing excessive power peaking Setpoints adjusted
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/09 Region
 1, Office of Director 2pp 17248 270 24X Fiche 50-387,
 83/02/09, 8302230333

8302230380 Forwards LER 83-011/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/10 HAYNES, R C
 Region 1, Office of Director 1p 17232 223 24X
 Fiche 50-387, 83/02/10, 8302230380

--8302230386 LER 83-011/03L-0 on 830111, during startup test program, diesel generator C declared inoperable due to air start receiver pressure below 240 psig limit Caused by setpoint drift Setpoint recalibr
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/10 Region
 1, Office of Director 2pp 17232 224 24X Fiche 50-387,
 83/02/10, 8302230380

8302230528 LER 83-010/01P-0 on 830209, runout flow on feedwater pumps found in excess of 133% assumption in feedwater controller failure/max demand transient analysis. Feedwater motor speed changer reduced to limit flow. Stops will be adjusted
 KEISER, H W Pennsylvania Power & Light Co 83/02/10 HAYNES, R C
 Region 1, Office of Director 1p 17256 280 24X
 Fiche 50-387, 83/02/10, 8302230528

8302220165 Forwards LER 83-013/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/11 HAYNES, R C
 Region 1, Office of Director 1p 17233 135 24X
 Fiche 50-387, 83/02/11, 8302220165

--8302220172 LER 83-013/03L-0 on 830109, during startup test, channel A as-found data lost due to incorrect use of test equipment
 Caused by inadvertently inserting pressure regulator before pressure indicator Instrument recalibr
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/11 Region
 1, Office of Director 2pp 17233 136 24X Fiche 50-387,
 83/02/11, 8302220165

8302230398 Forwards LER 83-012/03L-0

KEISER, H W Pennsylvania Power & Light Co 83/02/11 HAYNES, R C
 Region 1, Office of Director 1p 17232 034 24X
 Fiche 50-387, 83/02/11, 8302230398

--8302220404 LER 83-012/03L-0 on 830113, during startup test program, reactor recirculation pump A tripped off Caused by defective transformer that had shorted secondary Transformer replaced Pump returned to svc
 MITCHELL, D O Pennsylvania Power & Light Co 83/02/11 Region
 1, Office of Director 1p 17232 035 24X Fiche 50-387, 83/02/11,
 8302230398

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Bvc list encl
 EISENHUT, D O Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche: 50-000, 83/01/31, 8301310203

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
 BAQCHI, O Equipment Qualification Branch 83/02/02 NODMAN, V S
 Equipment Qualification Branch 3pp 17205 188 24X
 Fiche: 50-000, 83/02/02, 8302170011

--8106010266 Trip rept of 810316-20 site visit re qualification methods, procedures & results for selected safety-related mechanical & electrical equipment & supporting structures
 LEE, A Equipment Qualification Branch 81/05/14 ROBERTOCZY, Z R
 Equipment Qualification Branch 7pp 17206 006 24X
 Fiche 50-000, 83/02/02, 8302170011

--8302170104 Forwards repts re 20 equipment items reviewed during 810316-20 site visit
 REICH, M Brookhaven National Laboratory 81/06/25 ROBERTOCZY, Z
 Equipment Qualification Branch 4pp 17206 013 24X
 Fiche 50-000, 83/02/02, 8302170011

--8110190094 Trip rept for 810819-20 site visit to perform second seismic qualification review audit Program adequate Review including Phase III new load requalification will continue until scheduled completion in June 1982
 LEE, A Equipment Qualification Branch 81/09/29 ROBERTOCZY, Z R
 Equipment Qualification Branch 5pp 17206 112 24X
 Fiche 50-000, 83/02/02, 8302170011

--8302170195 Forwards summary repts of six items audited during 810819-20 site visit
 REICH, M Brookhaven National Laboratory 82/01/18 ROBERTOCZY, Z
 Equipment Qualification Branch 18pp 17206 132 24X
 Fiche: 50-000, 83/02/02, 8302170011

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche: 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re BER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable. Bvc list encl
 EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
 Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

DOCKETED ITEMS

8302150616 Forwards State of PA Air Pollution Permit 40-302-0106 for temporary auxiliary boiler
CURTIS, N W Pennsylvania Power & Light Co 83/02/08 SCHWENCER, A
Licensing Branch 2 4pp 17154 161 24X Fiche 50-387, 83/02/08, 8302150616

8302150734 Notification of 830218 meeting w/uttl in Bethesda, MD to discuss dose calculations & reporting
PERCH, R L Licensing Branch 2 83/02/08 SCHWENCER, A Licensing Branch 2 3pp 17160 101 24X Fiche 50-387, 83/02/08, 8302150734

8302230634 Forwards determination of eligibility notification for four sites in Luzerne County, PA Sites considered eligible for inclusion in Natl Register of Historic Places
* Interior, Dept of: National Park Service 83/02/10 NRC - No Detailed Affiliation Given 5pp 17255 249 24X Fiche 50-387, 83/02/10, 8302230634

8302280091 Forwards 503 oversize revised drawings per Reg Guide 1 70 Marked-up FSAR Table 1 7-1 encl Aperture cards are available in PDR
CODDINGTON, C T Pennsylvania Power & Light Co 83/02/11 Commissioners 12pp 17306 090 24X Fiche 50-387, 83/02/11, 8302280091

F Security, medical, emergency & fire protection plans

8302030267 Releases public version of util request that emergency plan & procedures controlled manuals be returned within 10 working days
FELTON, J M Division of Rules and Records 83/01/26, Document Management Branch 1p 17023 286 24X Fiche 50-387, 83/01/26, 8302030267

--8302030276 Submits public version of request that emergency plan & procedures controlled manuals be returned within 10 working days
WHARTON, J T Pennsylvania Power & Light Co 83/01/19 DENTON, H R NRC - No Detailed Affiliation Given 1p 17023 287 24X Fiche 50-387, 83/01/26, 8302030267

8302020405 Releases public version of Temporary Change Notices
FELTON, J M Division of Rules and Records 83/01/27, Document Management Branch 1p 16999 345 24X Fiche 50-387, 83/01/27, 8302020405

--8302020410 Forwards public version of Temporary Change Notices 83-0021 through 83-0028 for Emergency Plan Implementing Procedures, including Procedures EP-IP-001 re emergency classification & EP-IP-021 re site emergency evacuation
* Pennsylvania Power & Light Co 83/01/10 DENTON, H R NRC - No Detailed Affiliation Given 1p 16999 346, 24X Fiche 50-387, 83/01/27, 8302020405

--8302020418 Public version of Temporary Change Notices 83-0021 through 83-0028 for Emergency Plan Implementing Procedures, including Procedures EP-IP-001 re emergency classification & EP-IP-021 re site emergency evacuation
* Pennsylvania Power & Light Co 83/01/07 8pp 16999 347 24X Fiche 50-387, 83/01/27, 8302020405

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Bvc list encl.
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226, 24X Fiche 50-000, 83/02/01, 8301210340

8302090382 Requests continued submittal of three copies of changes to emergency plan & emergency plan implementing procedures. Dedicated controlled copies assure better coordination during accident situations
MARTIN, T T Division of Engineering & Technical Programs 83/02/02 KENYON, B Pennsylvania Power & Light Co 2pp 17071 087 24X Fiche 50-387, 83/02/02, 8302090382

8302170059 Informs that proposed changes to program for storage of safeguards info transmitted in 830111 ltr acceptable
SCHWENCER, A Licensing Branch 2 83/02/07, CURTIS, N W Pennsylvania Power & Light Co 1p 17191 068 24X Fiche 50-387, 83/02/07, 8302170059

8302180251 Forwards Change B to security training & qualification plan. Change withheld (ref 10CFR2 790)
CURTIS, N W Pennsylvania Power & Light Co 83/02/11 DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p 17215 274, 24X Fiche 50-387, 83/02/11, 8302180251

8302170485 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/02/15, Document Management Branch 1p 17203 213 24X Fiche 50-387, 83/02/15, 8302170485

--8302170490 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-002, "Emergency Mgt Notifications" & Rev 0 to EP-IP-102, "Surveillance Testing of Emergency Communications Equipment"
* Pennsylvania Power & Light Co 83/01/28 SCHWENCER, A NRC - No Detailed Affiliation Given 1p 17203 214 24X Fiche 50-387, 83/02/15, 8302170485

--8302170497 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-002, "Emergency Mgt Notifications" & Rev 0 to EP-IP-102, "Surveillance Testing of Emergency Communications Equipment" Revised index encl
* Pennsylvania Power & Light Co 83/01/20 94pp 17203 213 24X Fiche 50-387, 83/02/15, 8302170485

8302250021 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/16, Document Management Branch 1p 17299 001 24X Fiche 50-387, 83/02/16, 8302250021

--8302250029 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-044, "Emergency Environ Sampling" Revised table of contents & index encl
* Pennsylvania Power & Light Co 83/01/26 SCHWENCER, A NRC - No Detailed Affiliation Given 6pp 17299 002 24X Fiche 50-387, 83/02/16, 8302250021

--8302250035 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-044, "Emergency Environ Sampling."
* Pennsylvania Power & Light Co 83/01/21, 65pp 17299 008 24X Fiche 50-387, 83/02/16, 8302250021

G Adjudicatory correspondence

8302020284 Forwards license amend, incorporating limiting condition for operation restricting increases in unidentified leakage w/o encl
CUTCHIN, J M Hearing Branch 4, 83/02/01 MOORE, T S, EILPERIN, S F., BUCK, J H Atomic Safety and Licensing Appeal Panel 1p 16993 317 24X Fiche 50-387, 83/02/01, 8302020284

H General correspondence

8302150511 Comments on concerns expressed re plums & ingestion exposure pathway emergency planning zones Concerns re radiological emergency response plan for communities around facility will be addressed by FEMA & PA Emergency Mgt Agency.
HAYNES, R C Region 1, Office of Director, 83/02/09 NEMETHY, E. Affiliation Unknown 3pp 17156 250, 24X Fiche 50-387, 83/02/09, 8302150511

F Operating license stage documents & correspondence

8302080113 Board Notification 82-122A, forwards USQB 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake w/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30, Atomic Safety and Licensing Board Panel, 18pp 17109 335 24X Fiche 50-000, 82/12/30, 8302080113

G Inspection reports, IE Bulletins & correspondence

8302100288 Forwards IE Insp Repts 50-387/82-45 & 50-388/82-14 on 821201-830111. No noncompliance noted
BTAROSFECKI, R Division of Project & Resident Programs, 83/01/25 KENYON, B D Pennsylvania Power & Light Co 2pp 17112 007, 24X Fiche 50-387, 83/01/25, 8302100288

--8302100292 IE Insp Repts 50-387/82-45 & 50-388/82-14 on 821201-830111 No noncompliance noted. Major areas inspected: preoperational test review & startup test witnessing, licensee event follow-up, Tech Spec compliance, open item & plant status
RHOADS, Q O., MCCANN, J F., MCCABE, E C Division of Project & Resident Programs 82/01/24 9pp 17112 009 24X Fiche 50-387, 83/01/25, 8302100288

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Bvc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160, 24X Fiche 50-000, 83/01/26, 8212060358

DOCKETED ITEMS

8212060360 IE Info Notice 83-02, "Limitorque H08C,H18C,H28C & H38C Gearheads " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030559 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/82-40 & 50-388/82-12
STAROSTECKI, R. Division of Project & Resident Programs. 83/01/28
KENYON, B. D. Pennsylvania Power & Light Co 2pp 17008 029. 24X
Fiche: 50-387, 83/01/28, 8302030559

--8302030564 Response to NRC 821214 ltr re violations noted in IE Insp Repts 50-387/82-40 & 50-388/82-12 Corrective actions requirement to verify suppression pool temp per Tech Spec Section 4.6.2.1 b.1 added to operating test procedure.
KENYON, B. D. Pennsylvania Power & Light Co. 83/01/12
STAROSTECKI, R. Division of Project & Resident Programs. 3pp
17008:031 24X Fiche 50-387, 83/01/28, 8302030559

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc. 110pp 17347:191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp. 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8 Reportable occurrences, LERs & related correspondence

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested
OWALL, D. D. Brown Boveri Corp (subs Brown Boveri & Co., Ltd.). 82/12/10 STELLG, V. Director's Office, Office of Inspection and Enforcement. 2pp. 17023:284 24X Fiche 50-000, 82/12/10, 8212140330

8302040288 Part 21 rept re stamped tubing sleeve used to house hot-cold electrical splice in Inconel N.L. heating cable assemblies High residual stress present in finished condition. Questionable circuits will be checked by Jan 1983
HARR, B. Nelson Electric Co. 82/12/15 COLLINS, J. Region 4, Office of Director. 3pp. 17020 048 24X Fiche 50-000, 82/12/15, 8302040288

8302180134 Final deficiency rept re inadequacies w/design, mfg & installation of Pacific Scientific shock suppressors & associated ITT Orinnell clamps. Initially reported on 820820 Specs & procedures revised Also reported per Part 21
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/04. HAYNES, R. C. Region 1, Office of Director. 4pp. 17216, 174 24X
Fiche 50-388, 83/02/04, 8302180134

8302180191 Final deficiency rept re inadequate restraint provided by pipe friction clamps anchors. Initially reported on 820723 Drawings revised & previously accepted friction clamps to be reinspected & reworked. Also reported per Part 21.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/04 HAYNES, R. C. Region 1, Office of Director. 4pp. 17215:355, 24X
Fiche: 50-388, 83/02/04, 8302180191

8302180245 Suppl to final deficiency rept re vertically installed Anchor-Darling check valves. Satisfactory testing completed on 10 of 12 valves.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/04 HAYNES, R. C. Region 1, Office of Director. 2pp. 17215:261. 24X
Fiche 50-387, 83/02/04, 8302180245

8302230291 Final deficiency rept re defects in Byron-Jackson recirculation pump lug welds Initially reported on 830106 Welds repaired & liquid penetrant examined. Also reported per Part 21.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/04 HAYNES, R. C. Region 1, Office of Director. 3pp 17244:325. 24X
Fiche 50-388, 83/02/04, 8302230291

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licensees Bvc list encl
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-389 BT LUCIE PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302020468 Notification of 830127 meeting w/util in Bethesda, MD to discuss remaining util actions & to assure all parties understand what needs to be done to support issuance of license
NERSES, V. Licensing Branch 3 83/01/18 KNIIGHTON, G. W. Licensing
Branch 3 3pp 16999 274 24X Fiche 50-389, 83/01/18, 8302020468

8302010522 Forwards proposed test abstract for performing natural circulation testing during Hot Ops II Abstract focuses on reducing impact of natural circulation testing at facility & meets requirements of NUREG-0737, Item I O 1
UHRIO, R. E. Florida Power & Light Co. 83/01/24 EISENHUT, D. O. Division of Licensing 2pp 16977 292 24X Fiche 50-389, 83/01/24, 8302010522

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
BAOCHI, O. Equipment Qualification Branch 83/02/02 NOONAN, V. B. Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170227 "Audit of Pump & Valve Operability Assurance Program at St Lucie Nuclear Station, Unit 2," technical evaluation rept
MILLER, C. F., HONMA, O. EGLO, Inc FIN A-6415 EGO-EA-3907
82/08/31 ROSZTOCZY, Z. R. Division of Engineering 16pp
17207 077 24X Fiche 50-000, 83/02/02, 8302170011

8302160219 Notification of 830223-24 mgt review meetings w/util at site to discuss licensed operator staffing & training & health physics organization
NERSES, V. Licensing Branch 3 83/02/03 KNIIGHTON, G. W. Licensing
Branch 3 4pp 17234 230 24X Fiche 50-389, 83/02/03, 8302160219

8302240003 Forwards Amend 4 to CPPR-144, safety evaluation & notice of issuance & availability Amend adds FL Municipal Power Agency as co-owner & co-applicant
EISENHUT, D. O. Division of Licensing 83/02/03 UHRIO, R. E. Florida
Power & Light Co 3pp 17288:011 24X Fiche 50-389, 83/02/03, 8302240003

--8302240004 Amend 4 to CPPR-144, adding FL Municipal Power Agency as co-owner & co-applicant
EISENHUT, D. O. Division of Licensing 83/02/03 1p 17288 014
24X Fiche: 50-389, 83/02/03, 8302240003

--8302240005 Safety evaluation supporting Amend 4 to CPPR-144
* Office of Nuclear Reactor Regulation, Director 83/02/03 2pp
17288:015 24X Fiche 50-389, 83/02/03, 8302240003

--8302240006 Requests correction of error in safety evaluation supporting Amend 4 to CPPR-144 Plant is utilization facility, not production facility Draft FR notice encl.
SCINTO, J. F. Office of the Executive Legal Director 83/01/25
VIC, J. NRC - No Detailed Affiliation Given 1p 17288.017 24X
Fiche 50-389, 83/02/03, 8302240003

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl.
EISENHUT, D. O. Division of Licensing 83/02/08, Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSB re resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps," Bvc list encl
EISENHUT, D. O. Division of Licensing. 83/02/08, Louisiana Power & Light Co. 28pp. 17314, 232 24X Fiche 50-000, 83/02/08, 8302090065

8302180422 Forwards list of drawings of raceway sys hand carried to NRC on 821222 for review, per 821012 commitment.
UHRIO, R. E. Florida Power & Light Co. 83/02/11 EISENHUT, D. O. Division of Licensing 2pp. 17215:192. 24X Fiche: 50-389, 83/02/11, 8302180422

DOCKETED ITEMS

2

8302180313 Forwards justification for not implementing, prior to core load, certain control panel mods, required as result of Human Factors Engineering Branch audit findings
UHRIG, R E Florida Power & Light Co 83/02/14 EISENHUT, D O
Division of Licensing 7pp 17211 150 24X Fiche 50-389, 83/02/14, 8302180313

8302250111 Notification of cancellation of 830215 meeting w/util in Bethesda, MD to discuss actions to be taken to complete axial growth & high burnup fission gas release actions prior to license issuance
NERSES, V Licensing Branch 3 83/02/15 KNIGHTON, G W Licensing Branch 3 3pp 17303 074 24X Fiche 50-389, 83/02/15, 8302250111

8302250486 Submits completion dates for engineering & const items (hardware items) not expected to be completed at core load, in response to 821008 ltr Info includes dates for fire protection & boron dilution alarms
NOVAK, T M Assistant Director for Licensing 83/02/15 UHRIG, R E Florida Power & Light Co 4pp 17303 165 24X Fiche 50-389, 83/02/15, 8302250486

8302280350 Forwards revised test abstract clarifying sections of proposed natural circulation testing plan Abstract focuses on reducing impact of test & meeting requirements of NUREG-0737, Item I Q 1
UHRIG, R E Florida Power & Light Co 83/02/23 EISENHUT, D O Division of Licensing 2pp 17313 029 24X Fiche 50-389, 83/02/23, 8302280350

8302280271 Forwards "Auxiliary Feedwater Sys Pump Endurance Test Rpt," demonstrating acceptability of pumps against bearing housing/oil temp & vibration & verifying pump performance
UHRIG, R E Florida Power & Light Co 83/02/25 EISENHUT, D O Division of Licensing 1p 17313 006 24X Fiche 50-389, 83/02/25, 8302280271

--8302280276 "Auxiliary Feedwater Sys Pump Endurance Test Rpt"
* Florida Power & Light Co 83/01/12 14pp 17313 007 24X Fiche 50-389, 83/02/25, 8302280271

E NRC Safety Evaluation Report (SER), supple & correspondence

8302160234 Provides results of evaluation of new electronic diesel generator load sequencing relays, undertaken per SER (NUREG-0843), Section B 3.1.1 New relays will be installed by end of first refueling
UHRIG, R E Florida Power & Light Co 83/02/10 EISENHUT, D O Division of Licensing 1p 17170 134 24X Fiche 50-389, 83/02/10, 8302160234

F Security, medical, emergency & fire protection plans

8210150452 Forwards reviews of procedures proposed by utility in emergency plans to consider meteorological conditions at facilities, in response to Task Order 1 of interagency agreement
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099 82/10/08 SPICKLER, I. Office of Nuclear Reactor Regulation, Director 1p 16951 303 24X Fiche 50-000, 82/10/08, 8210150452

--8210150459 "Evaluation of Procedures Proposed by FL Power & Light Co in Emergency Plans to Consider Meteorological Conditions in St Lucie Plant Coastal Environ"
VAN DER HOVEN Commerce, Dept of, Natl Oceanographic & Atmospheric Administration NRC-03-B1-099 82/10/08 Office of Nuclear Reactor Regulation, Director 3pp 16951 304 24X Fiche 50-000, 82/10/08, 8210150452

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1; NUREG-0737, "Requirements for Emergency Response Capability" Bvc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302170336 Informs that hard copy readout will be provided in Unit 2 control room Mod consists of feeding signal from Unit 1 control room meteorological cabinet into six-channel recorder in Unit 2 control room via telephone line
UHRIG, R E Florida Power & Light Co 83/02/08 EISENHUT, D O Division of Licensing 1p 17185 121 24X Fiche 50-389, 83/02/08, 8302170336

8302150706 Forwards revised fire protection sys commitment schedule & responses to NRC requests w/two oversize charts Aperture cards are available in PDR
UHRIG, R E Florida Power & Light Co 83/02/09 EISENHUT, D O Division of Licensing 12pp 17152 009 24X Fiche 50-389, 83/02/09, 8302150706

8302230149 Forwards info re proposed solution to security sys perimeter fence, per 821115 license conditions Info withheld (ref 106FR73 21)
UHRIG, R E Florida Power & Light Co 83/02/15 EISENHUT, D O Division of Licensing 2pp 17243 228 24X Fiche 50-389, 83/02/15, 8302230149

8302240127 Summary of 830127 meeting w/util in Bethesda, MD re implementation schedule for installation of fire protection hardware items & fire program for operation of plant beyond 5% power
NERSES, V Licensing Branch 3 83/02/15 Licensing Branch 3 4pp 17268 266 24X Fiche 50-389, 83/02/15, 8302240127

8302250486 Submits completion dates for engineering & const items (hardware items) not expected to be completed at core load, in response to 821008 ltr Info includes dates for fire protection & boron dilution alarms
NOVAK, T M Assistant Director for Licensing 83/02/15 UHRIG, R E Florida Power & Light Co 4pp 17303 165 24X Fiche 50-389, 83/02/15, 8302250486

J Insurance & indemnity information

8302080275 Forwards Endorsement 44 to NELIA Policy NF-227 & Endorsement 35 to MAELU Policy MF-88
DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 82/12/23 BALTZMAN, J Assistant Director for State & License Relations 3pp 17056 342 24X Fiche 50-335, 82/12/23, 8302080275

8302070207 Forwards Endorsements 45 & 36 to NELIA Policy NF-227 & MAELU Policy MF-88, respectively
DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 83/01/24 BALTZMAN, J Assistant Director for State & License Relations 3pp 17031 310 24X Fiche 50-335, 83/01/24, 8302070207

G Inspection reports, IE Bulletins & correspondence

8302150598 Forwards IE Insp Rept 50-389/82-45 on 821004-08, No noncompliance noted.
LEWIS, R C Division of Project & Resident Programs 82/11/09 UHRIG, R E Florida Power & Light Co 2pp 17156 259 24X Fiche 50-389, 82/11/09, 8302150598

--8302150607 IE Insp Rept 50-389/82-45 on 821004-08, No noncompliance noted Major areas inspected: onsite design activities, QA insp of mechanical supports/restraints, piping, electrical & instrumentation & potentially generic const deficiency rept.
WRIGHT, R W, DEBBAGE, A O, MCFARLAND, C R Division of Engineering & Radiological Safety Programs 82/11/08 18pp 17156 261 24X Fiche 50-389, 82/11/09, 8302150598

8302150308 Forwards IE Insp Rept 50-389/82-68 on 821212-17 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/01/06 UHRIG, R E Florida Power & Light Co 2pp 17148 244 24X Fiche 50-389, 83/01/06, 8302150308

--8302180316 IE Insp Rept 50-389/82-68 on 821212-17, No noncompliance noted Major area inspected: preoperational test program implementation
LANDIS, K D, JENISON, K M, JULIAN, C A Division of Project & Resident Programs 83/01/05 5pp 17148 246 24X Fiche 50-389, 83/01/06, 8302150308

8302150422 Forwards IE Insp Repts 50-335/82-41 & 50-389/82-63 on 821111-1210 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/12 UHRIG, R E Florida Power & Light Co 2pp 17148 099 24X Fiche 50-335, 83/01/12, 8302150422

--8302150428 IE Insp Repts 50-335/82-41 & 50-389/82-63 on 821111-1210, noncompliance noted Major areas inspected: maint; surveillance, procurement, operational safety verification; new fuel handling & operating procedure review.
ELROD, S A, BIBB, H E, DANCE, H Division of Project & Resident Programs 83/01/11 16pp 17148 101 24X Fiche 50-335, 83/01/12, 8302150422

8302150696 Forwards IE Insp Repts 50-335/82-42 & 50-389/82-64 on 821210, No noncompliance noted Differing insp dates noted throughout package
DANCE, H C Division of Project & Resident Programs 83/01/12 UHRIG, R E Florida Power & Light Co 2pp 17152 001 24X Fiche 50-335, 83/01/12, 8302150696

DOCKETED ITEMS

--8302150704 IE Insp Repts 50-335/82-42 & 50-389/82-64 on 821206-10 No noncompliance noted Major areas inspected previous enforcement matters, maint programs, test & experiments programs & licensee action on previous insp findings
SKINNER, P. H., UPRIGHT, C. M. Division of Engineering & Radiological Safety Programs 83/01/10 5pp. 17152 003 24X
Fiche 50-335, 83/01/12, 8302150496

8302150382 Forwards IE Insp Rept 50-389/82-60 on 821116-19 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/01/13
UHRIG, R. E. Florida Power & Light Co 2pp 17157 230 24X
Fiche 50-389, 83/01/13, 8302150382

--8302150385 Notice of violation from insp on 821116-19
* Division of Project & Resident Programs 83/01/13 1p.
17157 232 24X Fiche 50-389, 83/01/13, 8302150382

--8302150388 IE Insp Rept 50-389/82-60 on 821116-19 Noncompliance noted between 820511-14, two examples of undersize safety-related socket weld joints noted which had been visually inspected & accepted.
KLEINSORGE, W. P., BLAKE, J. J. Division of Engineering & Radiological Safety Programs 83/01/05 7pp. 17157 233 24X
Fiche 50-389, 83/01/13, 8302150382

8302150715 Forwards IE Insp Rept 50-389/82-65 on 821127-1203 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/01/19.
UHRIG, R. E. Florida Power & Light Co 2pp 17153 016 24X
Fiche 50-389, 83/01/19, 8302150715

--8302150720 IE Insp Rept 50-389/82-65 on 821127-1203 No noncompliance noted Major areas inspected: integrated & local leak rate testing, including exam of test controls, procedural review & test witnessing
WHITENER, M. L., JAPE, F. Division of Project & Resident Programs 83/01/13 8pp 17153:018 24X Fiche 50-389, 83/01/19, 8302150715.

8302150090 Forwards IE Insp Rept 50-389/82-03 on 830103-06, No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 83/01/24.
UHRIG, R. E. Florida Power & Light Co 2pp 17148 024 24X
Fiche 50-389, 83/01/24, 8302150090

--8302150102 IE Insp Rept 50-389/83-03 on 830103-06, No noncompliance noted Major areas inspected: procedure review, preoperational test results evaluation, review of SER confirmatory items per NUREG-0843, inspector followup items & plant tour
TAYLOR, P. A., KRUG, H., JAPE, F. Division of Project & Resident Programs 83/01/18. 5pp 17148 026 24X Fiche 50-389, 83/01/24, 8302150090.

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/26. Consolidated Edison Co. of New York, Inc. 118pp. 17023:160. 24X Fiche 50-000, 83/01/26, 8212060358

8302150258 Forwards IE Insp Rept 50-389/83-04 on 830103-07 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/01/26.
UHRIG, R. E. Florida Power & Light Co 2pp. 17148:334 24X
Fiche 50-389, 83/01/26, 8302150258

--8302150277 IE Insp Rept 50-389/83-04 on 830103-07 No noncompliance noted Major areas inspected: onsite design activity re nonconforming mechanical support/restraints & exam of QA insp & nonconformance records
DEBBAGE, A. Q., UPRIGHT, C. M. Division of Engineering & Radiological Safety Programs 83/01/24 5pp. 17148:336 24X
Fiche 50-389, 83/01/26, 8302150258.

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp. 17074:093. 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp. 17347:191. 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302010513 Forwards const/startup progress repts for Nov & Dec 1982
UHRIG, R. E. Florida Power & Light Co 83/01/24 EISENHUT, D. O
Division of Licensing 3pp 16977 299 24X Fiche 50-389, 83/01/24, 8302010513.

8302180460 Forwards "Const/Startup Progress Rept for Jan 1983 "
UHRIG, R. E. Florida Power & Light Co 83/02/15 EISENHUT, D. O
Division of Licensing 1p 17214 360 24X Fiche 50-389, 83/02/15, 8302180460

--8302180464 "Const/Startup Progress Rept for Jan 1983 "
* Florida Power & Light Co. 83/02/15 1p 17214 361 24X
Fiche 50-389, 83/02/15, 8302180460

G. Reportable occurrences, LERs & related correspondence

8302040288 Part 21 rept re stamped tubing sleeves used to house hot-cold electrical splice in Inconel M I heating cable assemblies
High residual stress present in finished condition
Questionable circuits will be checked by Jan 1983
KARR, B. Nelson Electric Co 82/12/15 COLLINS, J. Region 4, Office of Director 3pp. 17020 048 24X Fiche 50-000, 82/12/15, 8302040288

8302010444 Final deficiency rept re diesel generator fuel oil day tank overflow piping Initially reported on 821221 Piping redesigned to eliminate any water intrusion into diesel fuel oil day tank under backflushing conditions
UHRIG, R. E. Florida Power & Light Co 83/01/21. O'REILLY, J. P
Region 2, Office of Director 2pp 16974 240 24X
Fiche 50-389, 83/01/21, 8302010444

8302010447 Final deficiency rept re defective heat trace cabling
Initially reported on 821221 All heat trace sleeves of affected 08 Nelson electric batch will be subj to 100% nondestructive dye penetrant exam
UHRIG, R. E. Florida Power & Light Co 83/01/21 O'REILLY, J. P
Region 2, Office of Director 2pp 16981 320 24X
Fiche 50-389, 83/01/21, 8302010447

8302010452 Interim deficiency rept re ITT Barton pressure transmitters
Initially reported on 821221 Util, C-E & Ebasco Bvcs continuing evaluation Final rept to be submitted by 830228
UHRIG, R. E. Pennsylvania Power & Light Co. 83/01/21 O'REILLY, J. P
Region 2, Office of Director 1p 16981 318 24X
Fiche 50-389, 83/01/21, 8302010452

8302030098 Final Deficiency Rept re lack of documentation on Class 1 & 2 bolts & nuts Initially reported on 821013 Bolts for all Class 1, 2 & 3 flanges will be replaced per site QC procedures
UHRIG, R. E. Florida Power & Light Co 83/01/26 O'REILLY, J. P
Region 2, Office of Director 2pp 17004 291 24X
Fiche 50-389, 83/01/26, 8302030098

8302030427 Interim deficiency rept re insp of approx 240 small bore (2 inches & under) piping bands Initially reported on 821013 Insp complete Final response will be submitted by 830222 Results undergoing engineering evaluation
UHRIG, R. E. Florida Power & Light Co 83/01/26 O'REILLY, J. P
Region 2, Office of Director 1p. 17005, 220. 24X
Fiche 50-389, 83/01/26, 8302030427

8302030077 Final Deficiency Rept re Conax supplied ring tongue connector assemblies at electrical penetration terminals
Initially reported on 821110 Safety terminal block retaining nuts retorqued.
UHRIG, R. E. Florida Power & Light Co. 83/01/28 O'REILLY, J. P
Region 2, Office of Director 3pp 17002 129. 24X
Fiche 50-389, 83/01/28, 8302030077

8302170173 Interim Deficiency Rept 82-002 re fan belts on diesel generators 2A & 2B Initially reported on 820210 Engineering work on generators completed Final rept will be submitted by 830225
UHRIG, R. E. Florida Power & Light Co 83/02/08, O'REILLY, J. P
Region 2, Office of Director 1p 17180:218 24X
Fiche 50-389, 83/02/08, 8302170173

DOCKETED ITEMS

8302280128-Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals
Initially reported on 820630 Final rept will be submitted by 830225
UHR10,R.E. Florida Power & Light Co. 83/02/15 O'REILLY,J.P.
Region 2, Office of Director 1p 17307 201 24X
Fiche 50-389, 83/02/15, 8302280128

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, Applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT,D.O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302220001 Notification of contract execution, Mod 1 to "Review of Soil Exploration Results Beneath ERCW Pipelines & Electrical Duct Banks, Watts Bar Nuclear Plant" Contractor NDB
HOYLE,A. Administrative Contracts Branch FIN B-8604 82/08/30,
VOLLMER,R. Division of Engineering OUPA,D.C. NRC - No Detailed
Affiliation Given 1p. 17233 319 24X Fiche 50-390, 82/08/30,
8302220001

--8302220003 Mod 1, modifying statement of work & extending period of performance, to "Review of Soil Exploration Results Beneath ERCW Pipelines & Electrical Duct Banks, Watts Bar Nuclear Plant,"
SCIMITT,M.B. Commerce, Dept. of, National Bureau of Standards
REBELLO,J. Administrative Contracts Branch FIN B-8604,
82/08/30 4pp 17233 320 24X Fiche 50-390, 82/08/30, 8302220001

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
BAOCHI,O. Equipment Qualification Branch 83/02/02 NOONAN,V.B.
Equipment Qualification Branch, 3pp 17205 188 24X
Fiche 50-000, 83/02/02, 8302170011.

--8302170231 Trip rept of 820426-30 site visit to review safety-related electric & mechanical equipment
ROSTOCZY,Z.R. Equipment Qualification Branch. 82/09/10
ADENBAH,E.O. Licensing Branch 4 39pp 17207 093 24X
Fiche 50-000, 83/02/02, 8302170011

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK,T.M. Assistant Director for Licensing 83/02/03 Atomic
Safety and Licensing Board Panel. 6pp. 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co., SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT,S.H. Licensing Branch 1 82/03/15 YOUNGBLOOD,B.J.
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program, Svc list encl
EISENHUT,D.O. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp. 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSS re resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps,"
EISENHUT,D.O. Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp. 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302170051 Notification of 830301-03 caseload forecast meetings w/TVA in Sweetwater, TN to discuss projected fuel load dates
Agenda encl
KENYON,T.J. Licensing Branch 4 83/02/08 ADENBAH,E.O. Licensing
Branch 4 6pp. 17191 062 24X Fiche 50-390, 83/02/08, 8302170051

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT,D.O. Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp. 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340.

8302100415 Forwards rev to physical security plan Rev reflects utilization of power block concept Rev withheld (ref 10CFR73.21)
KAMMER,D.S. Tennessee Valley Authority 83/02/03 DENTON,H.R.
Office of Nuclear Reactor Regulation, Director. 1p 17117 257, 24
Fiche 50-390, 83/02/03, 8302100415

O Advisory Committee on Reactor Safeguards reports & correspondence

8302080111 Summary of ACRS Subcommittee on Watts Bar 820810 meeting in Washington, DC re application for DL
* ACRS - Advisory Committee on Reactor Safeguards 82/09/15
ACRS - Advisory Committee on Reactor Safeguards 21pp 17108 018
24X Fiche 50-390, 82/09/15, 8302080111

G Inspection reports, IE Bulletins & correspondence

8302150462 Forwards IE Insp Repts 50-390/82-42 & 50-391/82-39 on 821214-17 No noncompliance noted
VERRELLI,D.M. Division of Project & Resident Programs. 83/01/12
PARRIS,H.O. Tennessee Valley Authority. 2pp 17157 046 24X
Fiche 50-390, 83/01/12, 8302150462.

--8302150496 IE Insp Repts 50-390/82-42 & 50-391/82-39 on 821214-17 No noncompliance noted Major areas inspected independent insp effort, licensee identified items & inspector followup items
O'DONNAN,T.D., CONLON,T.E. Division of Engineering & Radiological
Safety Programs 83/01/10 4pp. 17157 048 24X
Fiche 50-390, 83/01/12, 8302150462

8302150658 Forwards IE Insp Repts 50-390/82-41 & 50-391/82-38 on 821121-1220 No noncompliance noted
VERRELLI,D.M. Division of Project & Resident Programs 83/01/12,
PARRIS,H.O. Tennessee Valley Authority 2pp 17154 085, 24X
Fiche 50-390, 83/01/12, 8302150658

--8302150662 IE Insp Repts 50-390/82-41 & 50-391/82-38 on 821121-1220 noncompliance noted Major areas inspected, followup on regional requests, licensee identified items & independent insp effort & licensee action on previous insp findings
HEATHERLY,T.L., FREDERICKSON,P. Division of Project & Resident
Programs. 83/01/12 5pp. 17154 087 24X Fiche 50-390, 83/01/12, 8302150658

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies;" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS,L.M. Tennessee Valley Authority. 83/01/24 O'REILLY,J.P.
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/26. Consolidated Edison Co. of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/28. Consolidated Edison Co. of New
York, Inc 109pp 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/28. Consolidated Edison Co. of New
York, Inc 110pp. 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150348 Ack receipt of 830117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32.
LEWIS,R.C. Division of Project & Resident Programs. 83/01/31
PARRIS,H.O. Tennessee Valley Authority. 1p 17157 170 24X
Fiche 50-390, 83/01/31, 8302150348

DOCKETED ITEMS

--8302150353 Responds to NRC 821102 ltr re violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32 Corrective actions
WBNM-QCP-1 26 revised to change overall responsibility for storage & housekeeping insp to const engineer for QC
MILLS,L M Tennessee Valley Authority 83/01/17 O'REILLY, J P.
Region 2, Office of Director 4pp 17157 171 24X
Fiche: 50-390, 83/01/31, 8302150348

--8302150359 Forwards IE Insp Repts 50-390/82-35 & 50-391/82-32 on 820821-0922 & notice of violation
LEHIS,R C. Division of Project & Resident Programs 82/11/02
PARRIS,H O. Tennessee Valley Authority 2pp 17157 173, 24X
Fiche 50-390, 83/01/31, 8302150348

--8302150362 Notice of violation from insp on 820821-0922
* Division of Project & Resident Programs 82/11/02, 2pp
17157 177 24X Fiche 50-390, 83/01/31, 8302150348

--8302150365 IE Insp Repts 50-390/82-35 & 50-391/82-32 on 820821-0922
Noncompliance noted mechanical deficiency not reported to supervisor by plant personnel identifying suspected motor-to-flange misalignment
HEATHERLY, Y L., QUICK, D R. Division of Project & Resident Programs, 82/10/22, 11pp 17157 179 24X Fiche 50-390, 83/01/31, 8302150348

8302280495 Forwards Rev B to "Technical Instruction TI-50A ASME Section XI Preservice Insp Program Unit 1" Requests for relief included in App E
MILLS,L M Tennessee Valley Authority 83/02/17 ADENSAM,E
Licensing Branch 4 1p 17308,087 24X Fiche 50-390, 83/02/17, 8302280495

--8302280500 Rev B to, "Technical Instruction TI-50A ASME Section XI Preservice Insp Program Unit 1"
DETHILL,D., SWALLOW,J M Tennessee Valley Authority 83/01/11
193pp 17308,088, 24X Fiche 50-390, 83/02/17, 8302280495

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc. 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc. 112pp. 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302160253 Supplemental deficiency rept re overhaul of component cooling sys pump discharge nozzles Initially reported on 830103. Completion of corrective action delayed until 830115 due to unanticipated problems
MILLS,L M Tennessee Valley Authority 82/12/09 O'REILLY, J P
Region 2, Office of Director 1p 17170 038 24X
Fiche: 50-390, 82/12/09, 8302160253

8302010243 Third Interim Deficiency Rept re diesel generator electrical equipment temp rating Initially reported on 820601 HVAC sys will be modified to reduce temp in areas of sub comp components
Next rept expected by 830622
MILLS,L M Tennessee Valley Authority, 83/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 16973 361, 24X
Fiche: 50-390, 83/01/19, 8302010243

8302010648 Fourth interim deficiency rept re engineering change review & handling Initially reported on 811215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution, Bellefonte sampling under evaluation
MILLS,L M Tennessee Valley Authority 83/01/19, O'REILLY, J P.
Region 2, Office of Director 2pp 16980, 049 24X
Fiche: 50-000, 83/01/19, 8302010648

8302010230 Seventh Interim Deficiency Rept re retrievable info used in piping analysis Initially reported on 810316 Data in Master Valve Status Repts updated Engineering procedure to control repts being developed. Next rept will be submitted by 830512
MILLS,L M Tennessee Valley Authority, 83/01/20, O'REILLY, J P.
Region 2, Office of Director 1p, 16974 046, 24X
Fiche: 50-390, 83/01/20, 8302010230

8302010598 Interim deficiency rept re failure to evaluate operator actions to realign ERCW Train A Initially reported on 820510 More complex analytical methods being used than initially planned Next rept expected by 830527
MILLS,L M Tennessee Valley Authority 83/01/20 O'REILLY, J P.
Region 2, Office of Director 1p 16978 129 24X
Fiche 50-390, 83/01/20, 8302010598

8302010233 Final deficiency rept re discrepancies in pipe rupture hardware Initially reported on 821006 Reanalysis of piping configuration proved that original thermal movements not excessive Deficiency not reportable under 10CFR50.55e
MILLS,L M Tennessee Valley Authority 83/01/21 O'REILLY, J P.
Region 2, Office of Director 2pp 16974 047 24X
Fiche 50-390, 83/01/21, 8302010233

8302010293 Final deficiency rept re analysis error by Gilbert Commonwealth Initially reported on 820518 Problems N3-67-21A & N3-67-22A reanalyzed incorporating correct response criteria Design changes completed Also reported per Part 21
MILLS,L M Tennessee Valley Authority 83/01/21 O'REILLY, J P
Region 2, Office of Director 2pp 16973 115 24X
Fiche 50-390, 83/01/21, 8302010293

8302010461 Final deficiency rept re failure to consider seismic & inertial loadings on ladders Initially reported on 820826 Item not considered reportable per 10CFR50.55(e) based on evaluation
MILLS,L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16981 305 24X
Fiche 50-390, 83/01/24, 8302010461

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 Info on Yellow Creek or Hartsville deferred until final decision re projects Next rept expected by 830531
MILLS,L M Tennessee Valley Authority 83/01/26 O'REILLY, J P
Region 2, Office of Director 3pp 16974 037 24X
Fiche 50-000, 83/01/26, 8302010215

8302010453 Tenth interim deficiency rept re failure of safety-related Westinghouse gate valves Initially reported on 801031 Mod in progress Next rept expected by 830622 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/01/26 O'REILLY, J P
Region 2, Office of Director 1p 16981 315 24X
Fiche 50-390, 83/01/26, 8302010453

8302010254 Final Deficiency Rept re design of axial supports for piping using lugs welded to pipe Initially reported on 810922 Lug criteria still meet ASME Code requirements All typical supports found to be adequate
MILLS,L M Tennessee Valley Authority 83/01/27 O'REILLY, J P
Region 2, Office of Director 2pp 16973 356 24X
Fiche: 50-390, 83/01/27, 8302010254

8302030459 First interim deficiency rept re auxiliary instrument room fire door failure Initially reported on 821229 Door failure & pressure limiting structural elements under evaluation
Next rept expected by 830520
MILLS,L M Tennessee Valley Authority 83/01/27 O'REILLY, J P
Region 2, Office of Director 2pp 17006 192 24X
Fiche 50-390, 83/01/27, 8302030459

8302030514 Fifth interim deficiency rept re failure of limit torque motor operators during valve closure Initially reported on 820126. Specific set of motor operators deficient not determined
Also reported per Part 21 Next rept expected by 830622
MILLS,L M Tennessee Valley Authority 83/01/27 O'REILLY, J P
Region 2, Office of Director 2pp 17007 303 24X
Fiche 50-390, 83/01/27, 8302030514

8302030498 Final deficiency rept re defective Westinghouse W-2 handswitch pull guides & pull guide covers Initially reported on 820604. Defective covers will be replaced & QC procedure revised. Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 2pp 17007 307 24X
Fiche 50-390, 83/01/28, 8302030498

8302140038 Third interim deficiency rept re questionable patches of plastic cement mortar Initially reported on 820429. Util currently investigating methods to determine if safety factors for anchors acceptable Next rept by 830429
MILLS,L M Tennessee Valley Authority 83/01/28 O'REILLY, J P.
Region 2, Office of Director 2pp, 17141 163 24X
Fiche 50-390, 83/01/28, 8302140038

8302070359 Final deficiency rept re repacking Westinghouse valves w/grafoil packing Initially reported on 820607 Correct valve packing procedures provided Nonconformance determined not reportable per 10CFR50.55(e)
MILLS,L M Tennessee Valley Authority, 83/01/31 O'REILLY, J P
Region 2, Office of Director 2pp, 17030 231 24X
Fiche: 50-390, 83/01/31, 8302070359

DOCKETED ITEMS

8302070595 Second interim deficiency rept re control of non-GA hex nuts. Initially reported on 821021. All 50 nuts recovered & replaced. Cause under investigation. Next rept will be submitted by 830630.
MILLS, L. M. Tennessee Valley Authority 83/01/31 O'REILLY, J. P.
Region 2, Office of Director 2pp 17034 265 24X
Fiche 50-390, 83/01/31, 8302070595

8302140071 Fourth interim deficiency rept re discrepancy in as-built vs as-analyzed piping sys. Initially reported on 810226. Unit 1 review & drawing revs complete. Unit 2 revs proceeding. Next rept expected by 830701.
MILLS, L. M. Tennessee Valley Authority 83/02/01 O'REILLY, J. P.
Region 2, Office of Director 2pp 17142 134 24X
Fiche 50-390, 83/02/01, 8302140071

8302140055 Suppl to final deficiency rept re improper weld attachment of shearing lugs. Initially reported on 801030. Completion date of corrective actions extended to 830215.
MILLS, L. M. Tennessee Valley Authority 83/02/02 O'REILLY, J. P.
Region 2, Office of Director 2pp 17142 125 24X
Fiche 50-390, 83/02/02, 8302140055

8302140059 Second interim deficiency rept re incomplete or undocumented checking of analysis. Initially reported on 820319. Independent review to be performed for all improper reviews. Next rept expected by 830624.
MILLS, L. M. Tennessee Valley Authority 83/02/03 O'REILLY, J. P.
Region 2, Office of Director 2pp 17142 128 24X
Fiche 50-390, 83/02/03, 8302140059

8302140068 Second interim deficiency rept re operating conditions used in piping analysis. Initially reported on 820318. Sampling program to determine scope & seriousness of problem established. Next rept expected by 830624.
MILLS, L. M. Tennessee Valley Authority 83/02/03 O'REILLY, J. P.
Region 2, Office of Director 2pp 17142 113 24X
Fiche 50-390, 83/02/03, 8302140068

8302140054 Final deficiency rept re unistrut clamps loaded in more than one direction. Initially reported on 820708. Condition not reportable under 10CFR50.55(e).
MILLS, L. M. Tennessee Valley Authority 83/02/04 O'REILLY, J. P.
Region 2, Office of Director 2pp 17140 189 24X
Fiche 50-390, 83/02/04, 8302140054

8302140129 First interim deficiency rept re improper overlapping analysis techniques. Initially reported on 830111. Terminal points unconservatively overlapped using snubbers; thus stiffness not included in analysis. Next rept by 830630.
MILLS, L. M. Tennessee Valley Authority 83/02/04 O'REILLY, J. P.
Region 2, Office of Director 2pp 17141 204 24X
Fiche 50-390, 83/02/04, 8302140129

8302140154 Final deficiency rept re omission of some movements in input to evaluate pipe interferences. Initially reported on 820519. Const Spec N3C-912 revised re evaluation of pipe clearances. Condition not reportable per 10CFR50.55(e).
MILLS, L. M. Tennessee Valley Authority 83/02/04 O'REILLY, J. P.
Region 2, Office of Director 2pp 17140 153 24X
Fiche 50-390, 83/02/04, 8302140154

8302140043 PNO-II-83-007: on 830204, unidentified caller telephoned in bomb threat identified device found near temporary bldg but contained no explosives. Proper authorities notified & threat considered hoax.
MCQUIRE, D. R. Region 2, Office of Director 83/02/07 2pp 17142 139 24X
Fiche 50-390, 83/02/07, 8302140043

8302130051 Second interim deficiency rept re failure to document certain piping analysis calculations. Initially reported on 820823. Review of analysis calculation packages to ensure proper documentation continuing. Next rept due by 830630.
MILLS, L. M. Tennessee Valley Authority 83/02/07 O'REILLY, J. P.
Region 2, Office of Director 2pp 17148 033 24X
Fiche 50-390, 83/02/07, 8302130051

8302130271 Fourth interim deficiency rept re errors in WERCO program distributed by AAA Technology. Initially reported on 820409. WERCO users manual made controlled computer program document. Next rept due by 830422.
MILLS, L. M. Tennessee Valley Authority 83/02/07 O'REILLY, J. P.
Region 2, Office of Director 3pp 17148 320 24X
Fiche 50-000, 83/02/07, 8302130271

8302130160 Fifth interim deficiency rept re foam seals in mechanical pipe sleeves. Initially reported on 811204. Investigations continue to determine integrity of silicone foam seals. Procedures under development. Next rept expected by 830624.
MILLS, L. M. Tennessee Valley Authority 83/02/08 O'REILLY, J. P.
Region 2, Office of Director 1p 17147 237 24X
Fiche 50-390, 83/02/08, 8302130160

8302170356 Third interim deficiency rept re grouted anchors & anchor bolt spacing violations. Initially reported on 820528. Evaluations to determine adequacy of anchorages in progress. Next rept expected by 830624.
MILLS, L. M. Tennessee Valley Authority 83/02/08 O'REILLY, J. P.
Region 2, Office of Director 2pp 17185 141 24X
Fiche 50-390, 83/02/08, 8302170356

8302230152 Final deficiency rept re inadequate QA program for masonry block work. Initially reported on 820902. Condition not reportable per 10CFR50.55(e).
MILLS, L. M. Tennessee Valley Authority 83/02/14 O'REILLY, J. P.
Region 2, Office of Director 2pp 17243 234 24X
Fiche 50-390, 83/02/14, 8302230152

8302230514 Final Deficiency Repts 50-390/82-96 & 50-391/82-92 re interpretation of radiographic test film on welded pipe by SHEPCO Tube Corp. Initially reported on 821001. Noncompliance not reportable under 10CFR50.55(e).
MILLS, L. M. Tennessee Valley Authority 83/02/14 O'REILLY, J. P.
Region 2, Office of Director 3pp 17257 282 24X
Fiche 50-390, 83/02/14, 8302230514

8302230647 Final deficiency rept re installation of pipe support w/inability to withstand thermal movement. Initially reported on 830117. Pipe sleeves will be cut flush to walls. Hanger engineering & QC units will receive add'l training.
MILLS, L. M. Tennessee Valley Authority 83/02/14 O'REILLY, J. P.
Region 2, Office of Director 2pp 17248 335 24X
Fiche 50-390, 83/02/14, 8302230647

8302230160 Interim deficiency rept re incorrect use of Category I (L) supports on pipes near water chillers. Initially reported on 830117. Deficiency under investigation. Next rept expected by 830306.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P.
Region 2, Office of Director 2pp 17245 044 24X
Fiche 50-390, 83/02/16, 8302230160

8302230343 First interim deficiency rept re supports not designed or modified per Engineering Change Notice 2575. Initially reported on 830118. Util reviewing all affected supports on auxiliary feedwater sys. Next rept expected by 830606.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P.
Region 2, Office of Director 2pp 17248 084 24X
Fiche 50-390, 83/02/16, 8302230343

8302280123 Third interim deficiency rept re auxiliary bldg platform design documentation. Initially reported on 820426. Drawing Series 48N1210 platforms redesigned. Next rept will be submitted by 830513.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P.
Region 2, Office of Director 2pp 17307 202 24X
Fiche 50-390, 83/02/16, 8302280123

8302280165 First interim deficiency rept re failure to provide bolt tightening requirements. Initially reported on 830120. Design documents under review. Plan for corrective action formulated. Next rept by 830621.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P.
Region 2, Office of Director 2pp 17305 361 24X
Fiche 50-390, 83/02/16, 8302280165

8302280142 Final deficiency rept re failure to inspect stud welds on flush-mounted embedded plates. Initially reported on 820812. QCP 4.07-1 revised to include insp of welded equipment during initial equipment setting.
MILLS, L. M. Tennessee Valley Authority 83/02/17 O'REILLY, J. P.
Region 2, Office of Director 2pp 17306 085 24X
Fiche 50-390, 83/02/17, 8302280142

V. Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applican for OL, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. BVC list encl.
EISENHUT, D. O. Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8302220001 Notification of contract execution, Mod 1 to "Review of Soil Exploration Results Beneath ERCW Pipelines & Electrical Duct Banks, Watts Bar Nuclear Plant" Contractor: NBS.
HOYLE, A. Administrative Contracts Branch. FIN 8-8604, 82/08/30
VOLLNER, R. Division of Engineering. QCP/TA, D C NRC - No Detail
Affiliation Given 1p 17233 319 24X
Fiche 50-390, 82/08/30, 8302220001

DOCKETED ITEMS

--B302220003 Mod 1, modifying statement of work & extending period of performance, to "Review of Soil Exploration Results Beneath ERCH Pipelines & Electrical Duct Banks, Watts Bar Nuclear Plant"
SCIMITT, M. B. Commerce, Dept. of, National Bureau of Standards
REBELLO, J. Administrative Contracts Branch FIN B-8604.
82/08/30 4pp 17233 320 24X Fiche 50-390, 82/08/30, B302220001

B302100512 Board Notification B3-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T. M. Assistant Director for Licensing, 83/02/03 Atomic
Safety and Licensing Board Panel 4pp 17143 293 24X
Fiche 50-000, 83/02/03, B302100512

--B302100522 Summary of B30219 meeting w/ORNL, ANL, TX Utils Generating Co., SC Electric & Gas Co., Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S. H. Licensing Branch 1 82/03/15 YOUNGBLOOD, S. J.
Licensing Branch 1 46pp. 17143 298 24X Fiche 50-000, 83/02/03, B302100512

B302080295 Generic Ltr B3-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Bvc list encl
EISENHUT, D. G. Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc. 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

B302090080 Generic Ltr B3-10C to all applicants w/Westinghouse designed NSSR re resolution of TMI Action Item IE K 3.5, "Automatic Trip of Reactor Coolant Pumps."
EISENHUT, D. G. Division of Licensing 83/02/08 Baltimore Gas & Electric Co. 30pp 17290 212 24X Fiche 50-000, 83/02/08, B302090080.

B302170051 Notification of B30301-03 caseload forecast meetings w/TVA in Sweetwater, TN to discuss projected fuel load dates.
Agenda encl
KENYON, T. J. Licensing Branch 4 83/02/08 ADENSAH, E. O. Licensing Branch 4. 4pp 17191 062 24X Fiche 50-390, 83/02/08, B302170051

F Security, medical, emergency & fire protection plans

B301210340 Generic Ltr B3-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1; NUREG-0737, "Requirements for Emergency Response Capability" Bvc list encl
EISENHUT, D. G. Division of Licensing 83/02/01, Consolidated
Edison Co. of New York, Inc. 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340

B302100415 Forwards rev to physical security plan Rev reflects utilization of power block concept Rev withheld (ref 10CFR73.21).
KAHMER, D. S. Tennessee Valley Authority, 83/02/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director, 1p 17117.257. 24X
Fiche 50-390, 83/02/03, B302100415

G Advisory Committee on Reactor Safeguards reports & correspondence

B302080111 Summary of ACRS Subcommittee on Watts Bar B30810 meeting in Washington, DC re application for DL.
* ACRS - Advisory Committee on Reactor Safeguards, 82/09/13
ACRS - Advisory Committee on Reactor Safeguards 21pp 17108.018.
24X Fiche 50-390, 82/09/13, B302080111.

H Inspection reports, IE Bulletins & correspondence

B302150462 Forwards IE Insp Repts 50-390/82-42 & 50-391/82-39 on 821214-17. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/01/12.
PARRIS, H. O. Tennessee Valley Authority, 2pp. 17157 046 24X
Fiche 50-390, 83/01/12, B302150462.

--B302150496 IE Insp Repts 50-390/82-42 & 50-391/82-39 on 821214-17. No noncompliance noted. Major areas inspected; independent insp effort; licensee identified items & inspector followup items.
O'BRYEN, T. D., CONLON, T. E. Division of Engineering & Radiological Safety Programs, 83/01/10, 4pp. 17157 048 24X
Fiche 50-390, 83/01/12, B302150462.

B302150458 Forwards IE Insp Repts 50-390/82-41 & 50-391/82-38 on 821121-1220. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs, 83/01/12
PARRIS, H. O. Tennessee Valley Authority 2pp. 17154 085. 24X
Fiche 50-390, 83/01/12, B302150458.

--B302150462 IE Insp Repts 50-390/82-41 & 50-391/82-38 on 821121-1220. No noncompliance noted. Major areas inspected; followup on regional requests; licensee identified items & independent insp effort & licensee action on previous insp findings.
HEATHERLY, T. L., FREDERICKSON, P. Division of Project & Resident Programs 83/01/12, 5pp 17154 087 24X Fiche 50-390, 83/01/12, B302150458

B302150610 Responds to IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L. M. Tennessee Valley Authority 83/01/24, O'REILLY, J. P.
Region 2, Office of Director 1p. 17153 309. 24X
Fiche 50-000, 83/01/24, B302150610

B212060358 IE Info Notice B3-01, "Ray Miller, Inc." Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/26 Consolidated Edison Co. of New York, Inc. 118pp 17023 160. 24X Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice B3-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28, Consolidated Edison Co. of New York, Inc. 109pp 17144.001. 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice B3-03, "Calibr of Liquid Level Instruments" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp. 17074.095 24X Fiche 50-000, 83/01/28, B212060361

B302150348 Ack receipt of B30117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32.
LEWIS, R. C. Division of Project & Resident Programs 83/01/31
PARRIS, H. O. Tennessee Valley Authority 1p. 17157.170. 24X
Fiche 50-390, 83/01/31, B302150348.

--B302150353 Responds to NRC B21102 ltr re violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32 Corrective actions:
WBNP-GCP-1.36 revised to change overall responsibility for storage & housekeeping insp to const engineer for GC.
MILLS, L. M. Tennessee Valley Authority, 83/01/17, O'REILLY, J. P.
Region 2, Office of Director 4pp. 17157.171. 24X
Fiche 50-390, 83/01/31, B302150348.

--B302150359 Forwards IE Insp Repts 50-390/82-35 & 50-391/82-32 on 820821-0922 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs, 82/11/02.
PARRIS, H. O. Tennessee Valley Authority, 2pp. 17157.175 24X
Fiche 50-390, 83/01/31, B302150348.

--B302150365 IE Insp Repts 50-390/82-35 & 50-391/82-32 on 820821-0922
Noncompliance noted; mechanical deficiency not reported to supervisor by plant personnel identifying suspected motor-to-flange misalignment
HEATHERLY, T. L., QUICK, D. R. Division of Project & Resident Programs, 82/10/22, 11pp. 17187 179 24X Fiche 50-390, 83/01/31, B302150348

B212060363 IE Info Notice B3-04, "Failure of Elma Power Supply Units" Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp. 17347.191. 24X Fiche 50-000, 83/02/18, B212060363.

B212060365 IE Info Notice B3-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24, Consolidated Edison Co. of New York, Inc. 111pp 17347.058. 24X Fiche 50-000, 83/02/24, B212060365.

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts." Bvc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103), 83/02/24 Consolidated Edison Co. of New York, Inc. 112pp. 17361.148 24X Fiche 50-000, 83/02/24, B212060366.

I Reportable occurrences, LERs & related correspondence

B302160253 Supplemental deficiency rept re overload of component cooling sys pump discharge nozzles Initially reported on 830103. Completion of corrective action delayed until 830115 due to anticipated problems.
MILLS, L. M. Tennessee Valley Authority 82/12/09, O'REILLY, J. P.
Region 2, Office of Director 1p 17170.058 24X
Fiche 50-390, 82/12/09, B302160253

DOCKETED ITEMS

281

8302010243 Third Interim Deficiency Rept re diesel generator electrical equipment temp rating Initially reported on 820601 HVAC sys will be modified to reduce temp in areas of sub; components Next rept expected by 830622
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 16973 361 24X
Fiche 50-390, 83/01/19, 8302010243

8302010648 Fourth interim deficiency rept re engineering change review & handling Initially reported on 811215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution Bellefonte sampling under evaluation
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P.
Region 2, Office of Director 2pp 16980 049 24X
Fiche 50-000, 83/01/19, 8302010648

8302010230 Seventh Interim Deficiency Rept re retrievable info used in piping analysis Initially reported on 810316 Data in Master Valve Status Repts updated Engineering procedure to control repts being developed Next rept will be submitted by 830312
MILLS, L M Tennessee Valley Authority 83/01/20 O'REILLY, J P.
Region 2, Office of Director 1p 16974 046 24X
Fiche 50-390, 83/01/20, 8302010230

8302010598 Interim deficiency rept re failure to evaluate operator actions to realign ERCW Train A Initially reported on 820310 More complex analytical methods being used than initially planned. Next rept expected by 830527
MILLS, L M Tennessee Valley Authority 83/01/20 O'REILLY, J P
Region 2, Office of Director 1p 16978 129 24X
Fiche: 50-390, 83/01/20, 8302010598

8302010233 Final deficiency rept re discrepancies in pipe rupture hardware Initially reported on 821006 Reanalysis of piping configuration proved that original thermal movements not excessive Deficiency not reportable under 10CFR50.55a
MILLS, L M Tennessee Valley Authority 83/01/21 O'REILLY, J P.
Region 2, Office of Director 2pp 16974 047 24X
Fiche: 50-390, 83/01/21, 8302010233

8302010293 Final deficiency rept re analysis error by Oilbert Commonwealth Initially reported on 820518 Problems NS-67-21A & NS-67-22A reanalyzed incorporating correct response criteria Design changes completed Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/01/21 O'REILLY, J P.
Region 2, Office of Director 2pp 16973 115 24X
Fiche: 50-390, 83/01/21, 8302010293

8302010461 Final deficiency rept re failure to consider seismic & inertial loadings on ladders Initially reported on 820826 Item not considered reportable per 10CFR50.55(e) based on evaluation
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16981 305, 24X
Fiche: 50-390, 83/01/24, 8302010461

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 Info on Yellow Creek or Hartsaville deferred until final decision re projects Next rept expected by 830531
MILLS, L M Tennessee Valley Authority 83/01/26 O'REILLY, J P
Region 2, Office of Director 3pp 16974 037, 24X
Fiche: 50-000, 83/01/26, 8302010215

8302010433 Tenth interim deficiency rept re failure of safety-related Westinghouse gate valves Initially reported on 81031 Mod in progress. Next rept expected by 830622 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority, 83/01/26 O'REILLY, J P
Region 2, Office of Director 1p. 16981 315, 24X
Fiche 50-390, 83/01/26, 8302010433.

8302010234 Final Deficiency Rept re design of axial supports for piping using lugs welded to pipe Initially reported on 810922 Lug criteria still meet ASME Code requirements. All typical supports found to be adequate
MILLS, L M Tennessee Valley Authority 83/01/27 O'REILLY, J P.
Region 2, Office of Director 2pp 16973 396 24X
Fiche: 50-390, 83/01/27, 8302010234

8302030459 First interim deficiency rept re auxiliary instrument room fire door failure Initially reported on 821229 Door failure & pressure limiting structural elements under evaluation
Next rept expected by 830520.
MILLS, L M Tennessee Valley Authority, 83/01/27 O'REILLY, J P.
Region 2, Office of Director, 2pp. 17006:192. 24X
Fiche 50-390, 83/01/27, 8302030459.

8302030514 Fifth interim deficiency rept re failure of Limitorque motor operators during valve closure. Initially reported on 820126 Specific set of motor operators deficient not determined Also reported per Part 21 Next rept expected by 830622.
MILLS, L M Tennessee Valley Authority, 83/01/27 O'REILLY, J P
Region 2, Office of Director, 2pp. 17007:303 24X
Fiche: 50-390, 83/01/27, 8302030514.

8302030498 Final deficiency rept re defective Westinghouse W-2 handswitch pull guides & pull guide covers Initially reported on 820604 Defective covers will be replaced & GC procedure revised Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/01/28, O'REILLY, J P.
Region 2, Office of Director 2pp 17007:307 24X
Fiche 50-390, 83/01/28, 8302030498

8302140038 Third interim deficiency rept re questionable patches of plastic cement mortar Initially reported on 820429 Util currently investigating methods to determine if safety factors for anchors acceptable. Next rept by 830429
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J. P.
Region 2, Office of Director 2pp. 17141 163 24X
Fiche 50-390, 83/01/28, 8302140038

8302070359 Final deficiency rept re repacking Westinghouse valves w/grafail packing Initially reported on 820607. Correct valve packing procedures provided. Nonconformance determined not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/01/31 O'REILLY, J. P.
Region 2, Office of Director 2pp. 17030 231. 24X
Fiche 50-390, 83/01/31, 8302070359

8302140071 Fourth interim deficiency rept re discrepancy in as-built vs as-analyzed piping sys. Initially reported on 810226. Unit 1 review & drawing revs complete. Unit 2 revs proceeding Next rept expected by 830701
MILLS, L M Tennessee Valley Authority 83/02/01 O'REILLY, J P
Region 2, Office of Director 2pp. 17142 134. 24X
Fiche 50-390, 83/02/01, 8302140071.

8302140055 Suppl to final deficiency rept re improper weld attachment of shearing lugs Initially reported on 801030. Completion date of corrective actions extended to 830215.
MILLS, L M Tennessee Valley Authority. 83/02/02 O'REILLY, J. P.
Region 2, Office of Director 1p. 17142, 125. 24X
Fiche 50-390, 83/02/02, 8302140055

8302140059 Second interim deficiency rept re incomplete or undocumented checking of analysis Initially reported on 820513 Independent review to be performed for all improper reviews. Next rept expected by 830624
MILLS, L M Tennessee Valley Authority 83/02/03 O'REILLY, J P
Region 2, Office of Director. 2pp. 17142 128. 24X
Fiche 50-390, 83/02/03, 8302140059

8302140068 Second interim deficiency rept re operating conditions used in piping analysis Initially reported on 820518 Sampling program to determine scope & seriousness of problem established. Next rept expected by 830624.
MILLS, L M Tennessee Valley Authority 83/02/03 O'REILLY, J. P.
Region 2, Office of Director 2pp 17142 113 24X
Fiche: 50-390, 83/02/03, 8302140068

8302140054 Final deficiency rept re unistrut clamps loaded in more than one direction Initially reported on 820708 Condition not reportable under 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority, 83/02/04. O'REILLY, J. P.
Region 2, Office of Director. 2pp 17140:189 24X
Fiche 50-390, 83/02/04, 8302140054.

8302140129 First interim deficiency rept re improper overlapping analysis techniques Initially reported on 830111 Terminal points unconservatively overlapped using snubbers; thus stiffness not included in analysis Next rept by 830630.
MILLS, L M Tennessee Valley Authority 83/02/04. O'REILLY, J. P.
Region 2, Office of Director. 2pp 17141:204 24X
Fiche: 50-390, 83/02/04, 8302140129

8302140154 Final deficiency rept re omission of some movements in input to evaluate pipe interferences Initially reported on 820519. Const Spec NSC-912 revised re evaluation of pipe clearances. Condition not reportable per 10CFR50.55(e).
MILLS, L M Tennessee Valley Authority 83/02/04. O'REILLY, J. P
Region 2, Office of Director 2pp. 17140:153 24X
Fiche: 50-390, 83/02/04, 8302140154

8302140043 PNO-11-83-007 on 830204, unidentified caller telephoned in bomb threat Identified device found near temporary bldg but contained no explosives Proper authorities notified & threat considered hoax.
MCQUIRE, D R Region 2, Office of Director. 83/02/07. 2pp. 17142:139 24X Fiche: 50-390, 83/02/07, 8302140043.

8302150051 Second interim deficiency rept re failure to document certain piping analysis calculations Initially reported on 820823 Review of analysis calculation packages to ensure proper documentation continuing Next rept due by 830630.
MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P.
Region 2, Office of Director. 2pp. 17148. 033 24X
Fiche: 50-390, 83/02/07, 8302150051.

DOCKETED ITEMS

8302150271 Fourth interim deficiency rept re errors in WERCO program distributed by AAA Technology Initially reported on 820409 WERCO users manual made controlled computer program document Next rept due by 830422
MILLS,L.M. Tennessee Valley Authority 83/02/07 O'REILLY, J.P.
Region 2, Office of Director 3pp 17148 320 24X
Fiche 50-000, 83/02/07, 8302150271

8302150160 Fifth interim deficiency rept re foam seals in mechanical pipe sleeves Initially reported on 811204. Investigations continue to determine integrity of silicone foam seals. Procedures under development Next rept expected by 830624
MILLS,L.M. Tennessee Valley Authority 83/02/08 O'REILLY, J.P.
Region 2, Office of Director 1p 17147 237 24X
Fiche 50-390, 83/02/08, 8302150160

8302170356 Third interim deficiency rept re grouted anchors & anchor bolt spacing violations Initially reported on 820528 Evaluations to determine adequacy of anchorages in progress Next rept expected by 830624
MILLS,L.M. Tennessee Valley Authority 83/02/08 O'REILLY, J.P.
Region 2, Office of Director 2pp 17189 141, 24X
Fiche 50-390, 83/02/08, 8302170356

8302230152 Final deficiency rept re inadequate QA program for masonry block work Initially reported on 820902. Condition not reportable per 10CFR50.55(e).
MILLS,L.M. Tennessee Valley Authority 83/02/14, O'REILLY, J.P.
Region 2, Office of Director 2pp 17243 236 24X
Fiche 50-390, 83/02/14, 8302230152

8302230514 Final Deficiency Repts 50-390/82-96 & 50-391/82-92 re interpretation of radiographic test film on welded pipe by SWEPSCO Tube Corp Initially reported on 821001. Noncompliance not reportable under 10CFR50.55(e).
MILLS,L.M. Tennessee Valley Authority 83/02/14 O'REILLY, J.P.
Region 2, Office of Director 3pp 17257 282 24X
Fiche 50-390, 83/02/14, 8302230514.

8302230647 Final deficiency rept re installation of pipe support w/inability to withstand thermal movement Initially reported on 830117 Pipe sleeve will be cut flush to walls. Hanger engineering & GC units will receive addl training
MILLS,L.M. Tennessee Valley Authority 83/02/14, O'REILLY, J.P.
Region 2, Office of Director 2pp 17248 335 24X
Fiche 50-390, 83/02/14, 8302230647.

8302230160 Interim deficiency rept re incorrect use of Category I (L) supports on pipes near water chillers Initially reported on 830117 Deficiency under investigation. Next rept expected by 830506.
MILLS,L.M. Tennessee Valley Authority 83/02/16 O'REILLY, J.P.
Region 2, Office of Director 2pp 17245 044 24X
Fiche 50-390, 83/02/16, 8302230160

8302280123 Third interim deficiency rept re auxiliary bldg platform design documentation Initially reported on 820426 Drawing Series 48N1210 platforms redesigned Next rept will be submitted by 830513.
MILLS,L.M. Tennessee Valley Authority 83/02/16 O'REILLY, J.P.
Region 2, Office of Director 2pp 17307 202 24X
Fiche 50-390, 83/02/16, 8302280123

8302280165 First interim deficiency rept re failure to provide bolt tightening requirements. Initially reported on 830120. Design documents under review Plan for corrective action formulated. Next rept by 830621
MILLS,L.M. Tennessee Valley Authority 83/02/16 O'REILLY, J.P.
Region 2, Office of Director 2pp 17305 361 24X
Fiche 50-390, 83/02/16, 8302280165

8302280142 Final deficiency rept re failure to inspect stud welds on flush-mounted embedded plates. Initially reported on 820812 GCP 4.07-1 revised to include insp of welded equipment during initial equipment setting.
MILLS,L.M. Tennessee Valley Authority 83/02/17, O'REILLY, J.P.
Region 2, Office of Director 2pp 17306 083 24X
Fiche 50-390, 83/02/17, 8302280142

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NRS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D.O. Division of Licensing 83/01/31, Consolidated
Edison Co. of New York, Inc. 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR.
BAQHILL, G. Equipment Qualification Branch 83/02/02 NOONAN, V.B.
Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170060 Trip rept of 801014-17 visit to facility to review qualification methods, procedures & results for Seismic Category I mechanical & electrical equipment & supporting structures
HOFMAYER, C.H. Equipment Qualification Branch 81/02/04, ROSENZWEIG, Z.R. Equipment Qualification Branch 40pp 17205 277, 24X Fiche 50-000, 83/02/02, 8302170011

F Security, medical, emergency & fire protection plans

8302010342 Forwards replacement sheets for Safeguards Contingency Plan Sheets withheld (ref 10CFR73.21)
DIXON, D.W. South Carolina Electric & Gas Co. 83/01/21 DENTON, H.R.
Office of Nuclear Reactor Regulation, Director 1p 16973 012 24X Fiche 50-395, 83/01/21, 8302010342

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl. 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl
EISENHUT, D.O. Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc. 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302170398 Forwards Amend 9 to License NPF-12, safety evaluation & notice of issuance & availability Amend provided for annual independent review of security plan & implementing procedures
ADENSAH, E.O. Licensing Branch 4 83/02/03 DIXON, D.W. South Carolina Electric & Gas Co. 2pp 17195 267 24X
Fiche 50-395, 83/02/03, 8302170398

--8302170399 Amend 9 to License NPF-12, providing for annual independent review of security plan & implementing procedures
ADENSAH, E.O. Licensing Branch 4 83/02/03 5pp 17195 269, 24X
Fiche 50-395, 83/02/03, 8302170398.

--8302170401 Safety evaluation supporting Amend 9 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 83/02/03 2pp 17195 274 24X Fiche 50-395, 83/02/03, 8302170398

--8302170402 Notice of issuance & availability of Amend 9 to License NPF-12
STAHL, C.R. Licensing Branch 4 83/02/03 2pp 17195 274 24X
Fiche 50-395, 83/02/03, 8302170398

8302100317 Forwards Amend 9 & replacement pages for physical security plan per Generic Ltr 82-14 Amend & pages withheld (ref 10CFR73.21)
DIXON, D.W. South Carolina Electric & Gas Co. 83/02/04 DENTON, H.R.
Office of Nuclear Reactor Regulation, Director 2pp 17116 321, 24X Fiche 50-395, 83/02/04, 8302100317

8302130712 Forwards IE Safeguards Insp Rept 50-395/82-61 on 821227-30. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs 83/02/07, DIXON, D.W. South Carolina Electric & Gas Co. 2pp 17153 026 24X
Fiche 50-395, 83/02/07, 8302130712.

--8302150717 IE Safeguards Insp Rept 50-395/82-61 on 821227-30. No noncompliance noted. Major areas inspected site orientation, review of security plan & implementing procedures & security organization/mgt. Details withheld (ref 10CFR73.21)
TILLMAN, A., STANSBERRY, W., MCQUIRE, D.R. Division of Emergency Preparedness & Materials Safety 83/02/04 1p 17153 028, 24X
Fiche 50-395, 83/02/07, 8302150712

8302180090 Releases public version of revised radiation emergency plan

FELTON, J.M. Division of Rules and Records 83/02/14, Document Management Branch 1p 17223 288, 24X Fiche 50-395, 83/02/14, 8302180090.

--8302180096 Forwards public version of Rev 9 to Radiation Emergency Plan EP-100.
DIXON, D.W. South Carolina Electric & Gas Co. 83/01/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 17223 289, 24X Fiche 50-395, 83/02/14, 8302180090.

DOCKETED ITEMS

--B302180099 Public version of Rev 9 to Radiation Emergency Plan EP-100
BEALE, K E South Carolina Electric & Gas Co 83/01/28 23pp
17223.291 24X Fiche 50-395, 83/02/14, 8302180090

J Insurance & indemnity information

B302080237 Forwards Amend 2 to Indemnity Agreement B-86 adding MAELU
Policy MF-108
DIXON, O W South Carolina Electric & Gas Co 82/08/18 DINTIZ, J P
Office of State Programs, Director 2pp 17097 187 24X
Fiche 50-395, 82/08/18, 8302080237

P Operating license stage documents & correspondence

B302030392 Forwards Rev 4 to "General Procedure for Inservice Testing
of Pumps," first interval insp program
DIXON, O W South Carolina Electric & Gas Co 83/01/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 17005.294.
24X Fiche 50-395, 83/01/27, 8302030392

--B302030398 Rev 4 to "General Procedure for Inservice Testing of
Pumps."
TUSKETT, J South Carolina Electric & Gas Co 83/01/13 27pp
17005 297 24X Fiche 50-395, 83/01/27, 8302030392

B302070594 Application for amend to License NPF-12, requesting extended
operation of facility in excess of 2,000 h Proprietary
& nonproprietary "VC Summer Interim Power Operation
Evaluation Rept" encl, Proprietary rept withheld
DIXON, O W South Carolina Electric & Gas Co 83/01/31. DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp. 17035 233
24X Fiche 50-395, 83/01/31, 8302070594

--B302070599 Application for withholding proprietary BOP-9 2-3009R, "VC
Summer Station Interim Power Operation Evaluation Rept."
Affidavit encl.
WIESEMANN, R A Westinghouse Electric Corp 83/01/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp 17035 236
24X Fiche 50-395, 83/01/31, 8302070594

--B302070602 Nonproprietary "VC Summer Station Interim Power Operation
Evaluation Rept"
* Westinghouse Electric Corp BOP-9, 2-3009R 83/01/31. 9pp
17035 244. 24X Fiche 50-395, 83/01/31, 8302070594

B302040361 Forwards rev to FSAR Section 13.2.2.4.1.3 re licensed
operator requalification training, per 10CFR50.54(i).
Approval requested
DIXON, O W South Carolina Electric & Gas Co 83/02/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp. 17018 271.
24X Fiche 50-395, 83/02/01, 8302040361

B302100223 Forwards "Seismic Confirmatory Program, VC Summer Nuclear
Station Unit 1," containing results of experimental phase,
per License Condition 2.C.25
DIXON, O W South Carolina Electric & Gas Co 83/02/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 1p 17110 190.
24X Fiche 50-395, 83/02/01, 8302100223

--B302100226 "Seismic Confirmatory Program, VC Summer Nuclear Station Unit
1."
* South Carolina Electric & Gas Co 83/02/28. 285pp. 17110:191
24X Fiche 50-395, 83/02/01, 8302100223.

B302100512 Board Notification 83-11 forwards info indicating onset of
increased turbulence & acceleration of tube wear occurring
at feed flow rates of 50% for Model D/2 & D/3 steam
generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing. 83/02/03. Atomic
Safety and Licensing Board Panel 6pp 17143:293. 24X
Fiche 50-000, 83/02/03, 8302100512

--B302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co,
SC Electric & Gas Co, Westinghouse, TVA & representatives of
Swedish nuclear power plant & Krsko in Bethesda, MD re
accelerated tube wear on Model D steam generators.
CHESTNUT, B. H Licensing Branch 1. 82/03/15 YOUNG, S. J.
Licensing Branch 1. 46pp. 17143:298 24X Fiche 50-000, 83/02/03,
8302100512

B302170398 Forwards Amend 9 to License NPF-12, safety evaluation &
notice of issuance & availability. Amend provides for annual
independent review of security plan & implementing
procedures.
ADENSAM, E O. Licensing Branch 4 83/02/03. DIXON, O. W. South
Carolina Electric & Gas Co. 2pp 17195.267. 24X
Fiche 50-395, 83/02/03, 8302170398.

--B302170399 Amend 9 to License NPF-12, providing for annual independent
review of security plan & implementing procedures
ADENSAM, E O Licensing Branch 4 83/02/03. 5pp 17195.269. 24
Fiche 50-395, 83/02/03, 8302170398

--B302170401 Safety evaluation supporting Amend 9 to License NPF-12.
* Office of Nuclear Reactor Regulation, Director 83/02/03 2pp
17195 274 24X Fiche 50-395, 83/02/03, 8302170398

--B302170402 Notice of issuance & availability of Amend 9 to License
NPF-12
STAHL, C R Licensing Branch 4 83/02/03. 2pp 17195.276 24X
Fiche 50-395, 83/02/03, 8302170398

B302160034 Forwards Amend 10 to License NPF-12, safety evaluation &
notice of issuance & availability Amend changes Tech Specs
re ESF actuation sys instrumentation
ADENSAM, E O Licensing Branch 4 83/02/04. DIXON, O. W South
Carolina Electric & Gas Co. 2pp 17170 341 24X
Fiche 50-395, 83/02/04, 8302160034

--B302160041 Amend 10 to License NPF-12, changing Tech Specs re ESF
actuation sys instrumentation
ADENSAM, E O Licensing Branch 4. 83/02/04. 4pp. 17170.343 24
Fiche 50-395, 83/02/04, 8302160034

--B302160046 Safety evaluation supporting Amend 10 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 83/02/04 3pp
17170 347. 24X Fiche 50-395, 83/02/04, 8302160034.

--B302160051 Notice of issuance & availability of Amend 10 to License
NPF-12.
ADENSAM, E O Licensing Branch 4 83/02/04. 4pp 17170 352 24
Fiche 50-395, 83/02/04, 8302160034

B302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Bvc
list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc. 11pp 17290:247. 24X
Fiche 50-000, 83/02/08, 8302080295

B302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions. Ability to use code must be
demonstrated by vendor or licensee. Bvc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

B302090085 Generic Ltr 83-10D to all licensees w/Westinghouse design
NBS8 (except Yankee Atomic Electric Co) re resolution of
THI Action Item II, K 3 5, "Automatic Trip of Reactor Coolant
Pumps" Bvc list encl.
EISENHUT, D O Division of Licensing. 83/02/08. Southern
California Edison Co 31pp 17290:262 24X Fiche 50-000, 83/02/08
8302090085

B302230432 Submits description of proposed mods to Westinghouse Steam
Generator Model D-3, per License Condition 2.C.14, Mod
summarized in "Westinghouse Preheat Steam-Generator-D2/D3
Design Mod Evaluation Package," Dec 1982 & addenda.
DIXON, O W South Carolina Electric & Gas Co 83/02/14 DENTON, H.
Office of Nuclear Reactor Regulation, Director. 8pp. 17246:160
24X Fiche 50-395, 83/02/14, 8302230432

B302220244 Informs that 830120 request for Tech Spec change should be
Action Statement 21 of Item 86 not Statement 14.
DIXON, O W South Carolina Electric & Gas Co 83/02/15. DENTON, H
Office of Nuclear Reactor Regulation, Director. 2pp. 17230:132.
24X Fiche 50-395, 83/02/15, 8302220244.

B302230381 Requests relief from ASME Section XI re hydrostatic testir
requirements for feedwater sys Steam generator & feedwater
piping mods described in util 830214 ltr tentatively
scheduled to begin 830308 Details of relief request encl
DIXON, O W South Carolina Electric & Gas Co. 83/02/18. DENTON, H.
Office of Nuclear Reactor Regulation, Director. 5pp. 17248 124.
24X Fiche 50-395, 83/02/18, 8302230381.

4 Inspection reports, IE Bulletins & correspondence

B302180649 Responds to IE Bulletin 82-04, "Deficiencies in Primary
Containment Electrical Penetration Assemblies" No
Bunker-Ramo electrical penetration assemblies used or
planned for use at facility
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/05.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17150:350. 24X
Fiche 50-395, 83/01/05, 8302180649

DOCKETED ITEMS

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
York, Inc. 110pp. 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302030392 Forwards Rev 4 to "General Procedure for Inservice Testing
of Pumps," first interval insp program
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/27 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 3pp 17005 294
24X Fiche: 50-395, 83/01/27, 8302030392

--8302030398 Rev 4 to "General Procedure for Inservice Testing of
Pumps"
TUSKETT, J. South Carolina Electric & Gas Co. 83/01/13 27pp
17003 297 24X Fiche 50-395, 83/01/13, 8302030398

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gears," Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc. 109pp. 17144 001 24X Fiche: 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc. 110pp. 17074 095. 24X Fiche 50-000, 83/01/28, 8212060361

8302150639 Informs that info necessary to resolve overlap criteria
issue per IE Bulletin 79-14 rescheduled for completion by
830228 due to more extensive effort required by contractor.
Final rept expected by 830304
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/28
O'REILLY, J. P. Region 2, Office of Director. 1p 17130 354 24X
Fiche: 50-395, 83/01/28, 8302150639

8302150712 Forwards IE Safeguards Insp Rept 50-395/82-61 on 821227-30
No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/07
DIXON, O. W. South Carolina Electric & Gas Co. 2pp. 17133 026 24X
Fiche: 50-395, 83/02/07, 8302150712

--8302150717 IE Safeguards Insp Rept 50-395/82-61 on 821227-30. No
noncompliance noted. Major areas inspected, site orientation,
review of security plan & implementing procedures & security
organization/mgt details withheld (ref 10CFR73.21)
TILLMAN, A., STANBERRY, W., MCQUIRE, D. R. Division of Emergency
Preparedness & Materials Safety 83/02/04, 1p. 17153 028 24X
Fiche: 50-395, 83/02/07, 8302150712

8212060363 IE Info Notice 83-04, "Failure of Eime Power Supply Units"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc. 110pp. 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc. 111pp. 17347 098. 24X Fiche: 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc. 112pp. 17361 148. 24X Fiche: 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302150132 Forwards monthly operating rept for Jan 1983
DIXON, O. W. South Carolina Electric & Gas Co. 83/02/10 Office of
Resource Management, Director 1p 17148 011 24X
Fiche: 50-395, 83/02/10, 8302150132.

--8302150136 Monthly operating rept for Jan 1983.
TAYLOR, O. J. South Carolina Electric & Gas Co. 83/02/10 4pp.
17148 012. 24X Fiche: 50-395, 83/02/10, 8302150132

8302250437 Forwards Technical Rept 82-2, "Seismic Activity Near VC
Summer Nuclear Station for Period Apr-June 1982."
DIXON, O. W. South Carolina Electric & Gas Co. 83/02/22 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p. 17297 001
24X Fiche: 50-395, 83/02/22, 8302250437.

--8302250442 "Seismic Activity Near VC Summer Nuclear Station for
Period Apr-June 1982"
TALMANI, P. South Carolina Univ. of. 82-2, 83/02/22. 19pp.
17297:002. 24X Fiche: 50-395, 83/02/22, 8302250442

B Reportable occurrences, LCRs & related correspondence

8302010111 Forwards LER 82-062/031-0 Detailed event analysis encl
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/19
O'REILLY, J. P. Region 2, Office of Director 2pp 16974 080 24X
Fiche 50-395, 83/01/19, 8302010111

--8302010120 LER 82-062/031-0 on 821220, seismic switch YM-1782 found to
have out-of-tolerance trip point on transverse sensor
Caused by setpoint drift on horizontal transverse sensor
Switch calibr & returned to svc
MCKINNEY, C. J. South Carolina Electric & Gas Co. 83/01/19
Region 2, Office of Director 1p 16974 082 24X
Fiche 50-395, 83/01/19, 8302010111

8302010139 Forwards LER 82-063/031-0 Detailed event analysis encl
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/19
O'REILLY, J. P. Region 2, Office of Director 2pp 16974 067 24X
Fiche 50-395, 83/01/19, 8302010139

--8302010162 LER 82-063/031-0 on 821220, isotopic iodine analysis not
performed within 6 h after plant went from 5% to 21%
thermal power within 1 h Caused by failure to notify
Chemistry Dept to perform analysis Procedure developed
FIEBBS, H. C. South Carolina Electric & Gas Co. 83/01/19 Region
2, Office of Director 1p 16974 069 24X Fiche 50-395, 83/01/19,
8302010139

8302010374 Forwards LER 82-065/031-0 Detailed event analysis encl.
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/21.
O'REILLY, J. P. Region 2, Office of Director 3pp 16973 293 24X
Fiche 50-395, 83/01/21, 8302010374

--8302010378 LER 82-065/031-0 on 821222, electrical power lost to Train A
radiation monitoring sys During investigation of loss of
power, maint personnel accidentally short circuited Train B
Caused by blown power fuses due to personnel error.
FIEBBS, H. C. South Carolina Electric & Gas Co. 83/01/21 Region
2, Office of Director 1p 16973 290 24X Fiche 50-395, 83/01/21,
8302010374

8302010584 Forwards LER 82-064/031-0 Detailed event analysis encl
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/21
O'REILLY, J. P. Region 2, Office of Director 2pp 16978 167 24X
Fiche 50-395, 83/01/21, 8302010584

--8302010591 LER 82-064/031-0 on 821223, nuclear sampling sys valves
9398A (B) failed to close within required isolation time
identified in Surveillance Requirement 4 & 4.3 Caused by
crud buildup on valve seats Crud buildup dislodged
MCKINNEY, C. J. South Carolina Electric & Gas Co. 83/01/21
Region 2, Office of Director 1p 16970 169 24X
Fiche: 50-395, 83/01/21, 8302010584

8302010155 Forwards LER 82-066/031-0 Detailed event analysis encl
DIXON, O. W. South Carolina Electric & Gas Co. 83/01/23
O'REILLY, J. P. Region 2, Office of Director 3pp 16974 076 24X
Fiche: 50-395, 83/01/23, 8302010155

--8302010165 LER 82-066/031-0 on 821226, during Mode 1 operation, reactor
bldg sump leakage detection sys declared inoperable when
high level alarm remained in alarm state. Caused by failure
of capacitance level detection sys. Sys recalibr
MCKINNEY, C. J. South Carolina Electric & Gas Co. 83/01/25
Region 2, Office of Director 1p 16974 079 24X
Fiche: 50-395, 83/01/25, 8302010155

8302070381 Forwards LER 83-001/01T-0. Detailed event analysis encl
DIXON, O. W. South Carolina Electric & Gas Co. 83/02/01
O'REILLY, J. P. Region 2, Office of Director 4pp 17030 032 24X
Fiche: 50-395, 83/02/01, 8302070381

--8302070383 LER 83-001/01T-0 on 830119, w/plant in Mode 1, three
refueling water storage tank level transmitters failed high
Caused by frozen instrument lines Transmitters thawed.
Insulated encls will be installed.
MCKINNEY, C. J. South Carolina Electric & Gas Co. 83/02/01.
Region 2, Office of Director 1p 17030 036 24X
Fiche: 50-395, 83/02/01, 8302070381

8302150656 Forwards LER 83-002/031-0 Detailed event analysis encl
DIXON, O. W. South Carolina Electric & Gas Co. 83/02/03
O'REILLY, J. P. Region 2, Office of Director 2pp 17134 092. 24X
Fiche 50-395, 83/02/03, 8302150656

--8302150666 LER 83-002/031-0 on 830109, while in Mode 1, main plant vent
exhaust sys flow rate indication failed low Caused by
corrosion on either fuse block or card edge connector of
mixing amplifier circuit board Circuit board cleaned
MCKINNEY, C. J. South Carolina Electric & Gas Co. 83/02/03
Region 2, Office of Director 1p 17134 094 24X
Fiche: 50-395, 83/02/03, 8302150656

DOCKETED ITEMS

8302150215 Forwards LER 83-004/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 83/02/07
O'REILLY, J P Region 2, Office of Director 2pp 17149 262 24X
Fiche 50-395, 83/02/07, 8302150215

--8302150223 LER 83-004/03L-0 on 830109, spurious inadequate core cooling
alarms received on Channel B of RCS subcooling margin
monitor Cause unknown Channel & sys re-energized on 830110 &
channel returned to svc on 830111
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/07
Region 2, Office of Director 1p 17149 264 24X
Fiche 50-395, 83/02/07, 8302150215

8302150613 Forwards LER 83-003/03L-0 Detailed event analysis encl.
DIXON, D W South Carolina Electric & Gas Co 83/02/07
O'REILLY, J P Region 2, Office of Director 3pp 17151 311 24X
Fiche 50-395, 83/02/07, 8302150613

--8302150624 LER 83-003/03L-0 on 830108 & 20, main control board
indication for steam generator A feedwater flow IF1-477
failed low caused by high instrument cabinet temp Power
supply card replaced & recalibr
FIELOB, H C South Carolina Electric & Gas Co 83/02/07 Region
2, Office of Director 1p 17151 314 24X Fiche 50-395, 83/02/07,
8302150613

8302150584 Forwards LER 83-005/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 83/02/09
O'REILLY, J P Region 2, Office of Director 2pp 17156 119 24X
Fiche 50-395, 83/02/09, 8302150584

--8302150595 LER 83-005/03L-0 on 830112, while in Mode 1, fire detector
zone DDD in svc water pump house failed to reset when
performing operational test Caused by grounded smoke
detector Ground cleared after head installed properly.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/09
Region 2, Office of Director 1p 17156 121 24X
Fiche 50-395, 83/02/09, 8302150584

8302170241 Forwards LER 83-006/03L-0 Detailed event analysis encl.
DIXON, D W South Carolina Electric & Gas Co 83/02/10
O'REILLY, J P Region 2, Office of Director 3pp 17187 097 24X
Fiche 50-395, 83/02/10, 8302170241.

--8302170244 LER 83-006/03L-0 on 830113, while in Mode 1, post-accident
hydrogen analyzer A declared inoperable Caused by excessive
heat damage to wiring & detector cell failing to adequately
insulate cover Cover, detector cell & wiring replaced
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/10
Region 2, Office of Director 1p 17187 100 24X
Fiche 50-395, 83/02/10, 8302170241

8302280196 Forwards LER 83-007/03L-0 Detailed event analysis encl
DIXON, D W South Carolina Electric & Gas Co 83/02/17
O'REILLY, J P Region 2, Office of Director 3pp 17306 063 24X
Fiche 50-395, 83/02/17, 8302280196.

--8302280198 LER 83-007/03L-0 on 830124, 9% discrepancy found between main
control board & control room evacuation panel (CREP)
indication for pressurized relief tank level. Caused by
instrument drift. CREP calibr & returned to svc
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/17.
Region 2, Office of Director 1p 17306 066 24X
Fiche 50-395, 83/02/17, 8302280196

V. Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OLs, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EIBENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302280479 Forwards info re plans for current & future operator license
exams, in response to 830111 Generic Ltr 83-01.
DIXON, D W South Carolina Electric & Gas Co. 83/02/22 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 4pp 17309:226.
24X Fiche: 50-395, 83/02/22, 8302280479.

DOCKET 50-397 WPPBS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8302090366 Forwards evaluation of containment pressure boundary matl
compliance w/QDC 51 Evaluation justifies revising NRQ lowest
svc metal temp values
BOUCHEY, G D Washington Public Power Supply System. 83/01/18,
SCHWENCER, A Office of Nuclear Reactor Regulation, Director 11pp
17070:312. 24X Fiche: 50-397, 83/01/18, 8302090366

8302040069 Forwards Suppl 3 to "Engineering Evaluation of WNP-2
Sacrificial Shield Wall " Rept closes all previous items &
discusses work performed to complete programs outlined in
original rept
MATLOCK, R H Washington Public Power Supply System 83/01/25
ENGLKEN, R H Region 5, Office of Director 2pp 17020 154 24X
Fiche 50-397, 83/01/25, 8302040069

--8302040102 Suppl 3 to "Engineering Evaluation of WPPB Unit 2
Sacrificial Shield Wall " *
Washington Public Power Supply System. 83/01/25 27pp
17020 156 24X Fiche 50-397, 83/01/25, 8302040069

--8302040110 Forwards "Engineering Evaluation of WPPB Unit 2 Sacrific
Shield Wall," constituting util corrective action plan
w/0 encl
RENBROER, D L Washington Public Power Supply System. 80/08/01.
ENGLKEN, R H Region 5, Office of Director 2pp. 17020 183 2.
Fiche 50-397, 83/01/25, 8302040069

--830204012B Forwards suppl to "Engineering Evaluation of WPPB Unit 2
Sacrificial Shield Wall " Suppl responds to questions raised
in 800806 meeting w/0 encl
RENBROER, D L Washington Public Power Supply System. 80/08/20.
ENGLKEN, R H Region 5, Office of Director 2pp 17020 185 2
Fiche 50-397, 83/01/25, 8302040069

8302020033 Requests response to 821223 request for addl info re fuel
rod corrosion measures be withheld per 10CFR2 790
BOUCHEY, G D Washington Public Power Supply System 83/01/26.
SCHWENCER, A Licensing Branch 2 2pp 17004 331 24X
Fiche 50-397, 83/01/26, 8302020033

8302230374 Forwards final suppl to 800801 "Engineering Evaluation of
Sacrificial Shield Wall," closing all previous items &
providing discussion of work performed to complete
previously outlined programs in Aug 1980 rept
BOUCHEY, G D Washington Public Power Supply System. 83/01/26.
SCHWENCER, A Licensing Branch 2 2pp 17248 095 24X
Fiche 50-397, 83/01/26, 8302230374

--8302230383 "Engineering Evaluation of Sacrificial Shield Wall," fir
suppl.
Washington Public Power Supply System 83/01/26 27pp
17248 097 24X Fiche 50-397, 83/01/26, 8302230374

8302230285 Responds to NRC 821209 request for addl info re
qualification of safety-related electrical equipment Item
10 re environ qualification of mechanical equipment to
be addressed w/electrical equipment during audit
BOUCHEY, G D Washington Public Power Supply System 83/01/31.
SCHWENCER, A Licensing Branch 2 75pp 17242 162. 24X
Fiche 50-397, 83/01/31, 8302230285

8302090388 Requests concurrence in delaying control room chiller
installation until 840531 Control room can be maintained
under all accident conditions if Seismic Category I standby
svc water sys left installed as backup for radwaste chiller
BOUCHEY, G D Washington Public Power Supply System 83/02/01
SCHWENCER, A Licensing Branch 2 1p. 17067 021 24X
Fiche 50-397, 83/02/01, 8302090388

8302100137 Notification of 830209 meeting w/util in Bethesda, MD to
discuss proposed operational QA procedures
AULICK, R Licensing Branch 2 83/02/04 SCHWENCER, A Licensing
Branch 2. 3pp 17134 282 24X Fiche 50-397, 83/02/04, 8302100137.

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EIBENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc. 11pp 17290 247. 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re SER of
"Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable Svc list encl
EIBENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co. 6pp. 17234 245. 24X Fiche 50-000, 83/02/08, 8302080301

8302140189 Notification of 830215-17 meetings w/util & E&O in
Richland, WA to discuss environ equipment qualification
audit
AULICK, R. Licensing Branch 2 83/02/08 SCHWENCER, A. Licensing
Branch 2 4pp. 17145:316 24X Fiche 50-397, 83/02/08, 8302140189

DOCKETED ITEMS

8302150189 Advances of necessity of capping three downcomers to eliminate LOCA jet loads on ECCB suction piping in wetwell. Capping will be accomplished by welding 1/4-inch plate to jet deflector.
BOUCHEY, O. D. Washington Public Power Supply System 83/02/08
SCHMENCER, A. Licensing Branch 2 1p 17147.162. 24X
Fiche: 50-397, 83/02/08, 8302150189

8302150397 Forwards addl info re containment out-of-roundness of shell plates per 821208 ltr. in response to KC Lew questions.
BOUCHEY, O. D. Washington Public Power Supply System 83/02/08
SCHMENCER, A. Licensing Branch 2 60pp 17156.020. 24X
Fiche: 50-397, 83/02/08, 8302150397.

8302150637 Forwards corrected Page 2 of 830118 evaluation of containment pressure boundary matls re QDC 31, correcting typographical error.
BOUCHEY, O. D. Washington Public Power Supply System 83/02/08.
SCHMENCER, A. Licensing Branch 2 2pp. 17150.344. 24X
Fiche: 50-397, 83/02/08, 8302150637

8302170391 Discusses actions taken re qualification of Raychem-Fiamtrol Cables per 821210 ltr. Receiving & test repts, shipping notices & interview notes reviewed. Application of cable from subj reel researched.
BOUCHEY, O. D. Washington Public Power Supply System 83/02/10
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp. 17183.349. 24X Fiche: 50-397, 83/02/10, 8302170391

8302230321 Requests written confirmation of telcon w/RH Nelson, R Auluck & R Giardina that backfitting of diesel generators w/air dryers by first refueling outage acceptable.
BOUCHEY, O. D. Washington Public Power Supply System 83/02/14
SCHMENCER, A. Licensing Branch 2 2pp 17257.241. 24X
Fiche: 50-397, 83/02/14, 8302230321.

8302250051 Notification of 830224 meeting w/util in Bethesda, MD to discuss internally generated missiles.
AULUCK, R. Licensing Branch 2. 83/02/16. SCHMENCER, A. Licensing Branch 2. 3pp 17303.004. 24X Fiche: 50-397, 83/02/16, 8302250051

8302250062 Notification of 830308 meeting w/util in Bethesda, MD to discuss estimated plant completion date.
AULUCK, R. Licensing Branch 2. 83/02/17. SCHMENCER, A. Licensing Branch 2. 3pp 17303.001. 24X Fiche: 50-397, 83/02/17, 8302250062

F. Security, medical, emergency & fire protection plans

8302030346 Forwards Rev 1 to, "Hanford Site Evacuation Time Assessment Study." Study provides technical basis for info included in emergency preparedness plan.
BOUCHEY, O. D. Washington Public Power Supply System 83/01/18
SCHMENCER, A. Licensing Branch 2. 1p 17006.001. 24X
Fiche: 50-397, 83/01/18, 8302030346.

--8302030351 Rev 1 to, "Hanford Site Evacuation Time Assessment Study."
MOGLER, R. D. Washington Public Power Supply System 82/09/30 104pp. 17006.002. 24X Fiche: 50-397, 83/01/18, 8302030346

8302230386 Forwards proposed mods to restricted area boundary, per 830120 telcon. Mods to be incorporated into FSAR Amend 29.
BOUCHEY, O. D. Washington Public Power Supply System 83/01/27.
SCHMENCER, A. Licensing Branch 2 2pp 17246.271. 24X
Fiche: 50-397, 83/01/27, 8302230386.

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/01. Consolidated Edison Co. of New York, Inc. 11pp 17221.226. 24X
Fiche: 50-000, 83/02/01, 8301210340.

8302250020 Notification of 830922-23 meetings w/Oage-Babcock Assoc & util in Richland, WA to discuss site audit for fire protection sys. Agenda encl.
AULUCK, R. Licensing Branch 2 83/02/16. SCHMENCER, A. Licensing Branch 2. 3pp. 17302.304. 24X Fiche: 50-397, 83/02/16, 8302250020.

G. Adjudicatory correspondence

8302240307 Memorandum & order denying Coalition for Safe Power 820222 petition to intervene & request for hearing & dismissing proceeding. Coalition failed to particularize or support contention.
HARBOUR, J., BRIGHT, O. D., GROSBMAN, H. Atomic Safety and Licensing Board Panel. 83/02/22. Coalition for Safe Power. 7pp. 17274.011. 24X Fiche: 50-397, 83/02/22, 8302240307.

H. General correspondence

8302080024 Appeals denial of FOIA request for SECY-82-377 & SECY-82-377A, "Hearing Requests on Extension of Const Completion Dates for WPPSS 1 & 2" & "Minor Revs to SECY-82-377," respectively.
NEWMAN, K. A. Debevoise & Liberman 82/11/09. CHILK, B. J. Office of the Secretary of the Commission 2pp 17106.161. 24X
Fiche: 50-397, 82/11/09, 8302080024

8302080018 Responds to appeal re denial of FOIA request for SECY-82-377 & SECY-82-377A Appeal denied Documents withheld (ref FOIA Exemption 5).
CHILK, B. J. Office of the Secretary of the Commission 83/01/12
NEWMAN, K. A. Debevoise & Liberman 2pp 17106.159. 24X
Fiche: 50-397, 83/01/12, 8302080018

I. Financial information

8302160215 Forwards Annual Financial Rept 1982.
BOUCHEY, O. D. Washington Public Power Supply System. 83/02/09
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17167.244. 24X Fiche: 50-000, 83/02/09, 8302160215

--8302160239 Annual Financial Rept 1982.
CAIN, B. H. Washington Public Power Supply System 83/02/09 50pp 17167.245. 24X Fiche: 50-000, 83/02/09, 8302160215.

J. Insurance & indemnity information

8302100218 Forwards Endorsement 6 to NELA Policy NF-270.
ASHBURN, D. J. Marsh & McLennan, Inc. M & H Nuclear Consultants, Inc. Div. 83/02/03. BALZMAN, J. Office of State Programs, Director 2pp. 17112.361. 24X Fiche: 50-397, 83/02/03, 8302100218

8302150200 Requests interpretation of regulations re geographical boundaries for indemnity location described in Indemnity Agreement B-94.
BOUCHEY, O. D. Washington Public Power Supply System 83/02/10
DINITI, I. Office of State Programs, Director 1p 17147.157. 24X
Fiche: 50-397, 83/02/10, 8302150200

K. Inspection reports, IE Bulletins & correspondence

8301180175 Forwards IE Insp Rept 50-397/82-27 on 821101-30 & notice of violation.
STERNBERG, D. H. Division of Resident Reactor Project & Engineering Programs 83/01/04. MATLOCK, R. O. Washington Public Power Supply System 2pp 16831.283. 24X Fiche: 50-397, 83/01/04, 8301180175

--8301180179 Notice of violation from insp on 821101-30.
DODDS, R. T. Division of Resident Reactor Project & Engineering Programs 83/01/04 2pp 16831.285. 24X Fiche: 50-397, 83/01/04, 8301180175

--8301180184 IE Insp Rept 50-397/82-27 on 821101-30 Noncompliance noted completed weld joint SLC-045-13 15 misaligned & pipe support strut and brackets did not have pipe curvature sufficient to result in flare bevel configuration.
TOTH, A. D., FEIL, R. A., DODDS, R. T. Division of Resident Reactor Project & Engineering Programs. 83/01/03 19pp. 16831.287. 24X
Fiche: 50-397, 83/01/04, 8301180175

8302090401 Forwards Rev O to "Visual Exam Acceptance Criteria for Reverification Insp of Welded Structures."
BOUCHEY, O. D. Washington Public Power Supply System 83/01/17
SCHMENCER, A. Licensing Branch 2 1p. 17067.109. 24X
Fiche: 50-397, 83/01/17, 8302090401

--8302090404 Rev O to, "Visual Exam Acceptance Criteria for Reverification Insp of Welded Structures."
CYOELMAN, A. I. Burns & Roe Co. QVI-09 R00 82/05/12. 9pp. 17067.110. 24X Fiche: 50-397, 83/01/17, 8302090401

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/26. Consolidated Edison Co. of New York, Inc 118pp 17023.160. 24X Fiche: 50-000, 83/01/26, 8212060358

8302150489 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration." Only Westinghouse penetrations used at facility.
MATLOCK, R. O. Washington Public Power Supply System. 83/01/27
ENDELKEN, R. H. Region 5, Office of Director 2pp. 17156.313. 24X
Fiche: 50-397, 83/01/27, 8302150489

DOCKETED ITEMS

29

8302230369 Forwards IE Insp Rept 50-397/82-27 on 821201-30 No noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/01/27 MATLOCK, R G Washington Public Power Supply System 2pp 17246 273 24X Fiche 50-397, 83/01/27, 8302230369

--8302230372 IE Insp Rept 50-397/82-29 on 821201-30 No noncompliance noted Major areas inspected reverification program activities, safety-related pipe supports & restraints & preoperational testing preparations & training
TOTH, A D, FEIL, R A, DODDS, R T Division of Resident, Reactor Project & Engineering Programs 83/01/25 17pp 17246 273 24X Fiche 50-397, 83/01/27, 8302230369

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230220 Forwards IE Insp Rept 50-397/82-25 on 821018-22 No noncompliance noted.
STERNBERG, D M. Division of Resident, Reactor Project & Engineering Programs 83/02/10 MATLOCK, R G. Washington Public Power Supply System 2pp 17245 139 24X Fiche 50-397, 83/02/10, 8302230220

--8302230226 IE Insp Rept 50-397/82-25 on 821018-22 No noncompliance noted Major areas inspected potentially reportable 10CFR50.55(e) items & action on followup items
D'ARDELLO, A. J., DODDS, R T Division of Resident, Reactor Project & Engineering Programs 83/02/09 5pp 17245 141 24X Fiche 50-397, 83/02/10, 8302230220

8302180409 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/82-27
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/02/11 MATLOCK, R G Washington Public Power Supply System 1p. 17214 267. 24X Fiche 50-397, 83/02/11, 8302180409.

--8302180423 Responds to NRC 830104 ltr re violations noted in IE Insp Rept 50-397/82-27 Corrective actions re-evaluation program instituted to review reverification QC Insp records. Support will be reinspected by 830311
MATLOCK, R G Washington Public Power Supply System. 83/02/02 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs. 5pp 17214 268 24X Fiche 50-397, 83/02/11, 8302180409

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp. 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 111pp 17347:098 24X Fiche 50-000, 83/02/24, 8212060365.

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24. Consolidated Edison Co. of New York, Inc 112pp. 17361:148 24X Fiche 50-000, 83/02/24, 8212060366.

R Periodic operating reports & related correspondence

8302040376 Forwards thirteenth progress rept re review of completed safety-related work for Oct - Dec 1982
MATLOCK, R G Washington Public Power Supply System 83/01/27. ENGELKEN, R H. Region 5, Office of Director 16pp 17018:286. 24X Fiche: 50-397, 83/01/27, 8302040376.

B Reportable occurrences, LERs & related correspondence

8302070231 Final deficiency rept for Condition 73 re concrete & grout work Initially reported on 801117 All grout types & installations found unsuitable in process of being replaced. Grout placement consolidated to one contractor.
MATLOCK, R G. Washington Public Power Supply System. 83/01/21 ENGELKEN, R H. Region 5, Office of Director 2pp. 17031:298. 24X Fiche 50-397, 83/01/21, 8302070231

8302070242 Final deficiency repts for Conditions 10, 58, 62, 83, 98 & 155 re unacceptable installation of concrete anchors & anchor bolts, out-of-caliber torque wrenches & welding on baseplates
Tech Specs revised & retorquing program expected by 830601.
MATLOCK, R G. Washington Public Power Supply System 83/01/28 ENGELKEN, R H Region 5, Office of Director. 9pp 17031 287 24X Fiche 50-397, 83/01/28, 8302070242

8302070283 Final & interim deficiency repts re Conditions 22, 29, 37, 43, 49, 59, 53-54, 60, 64, 82 & 102 concerning electrical separation. Next rept re Conditions 37, 49, 54, 60, 64 & 82 will be provided by 830418
MATLOCK, R G Washington Public Power Supply System 83/01/28 ENGELKEN, R H Region 5, Office of Director 17pp. 17029 180. 24X Fiche 50-397, 83/01/28, 8302070283.

8302230205 Forwards interim deficiency repts re installation of unqualified NAMCO EA740 limit switches in Class IE applications & nonconformance to design in nameplate voltage for 125-volt dc motor operator Next repts by 830426.
MATLOCK, R G Washington Public Power Supply System 83/02/02 ENGELKEN, R H Region 5, Office of Director. 1p 17243 208 24X Fiche: 50-397, 83/02/02, 8302230205.

--8302230209 Interim deficiency rept re installation of unqualified NAMCO EA740 limit switches 80T-P08-V/2A & 2B in Class IE applications. Switches replaced w/qualified Class IE limit switches. Quarterly repts will be submitted.
* Washington Public Power Supply System. 83/02/02. Region 5, Office of Director 1p 17243:209 24X Fiche 50-397, 83/02/02, 8302230205

--8302230213 Interim deficiency rept re nonconformance to design in nameplate voltage of 125-volt dc motor operator for valve RC1C-V-69 Motor operator will be replaced Review of valves conducted to ascertain if similar conditions exist.
* Washington Public Power Supply System. 83/02/02 Region 5, Office of Director. 2pp. 17243:210. 24X Fiche 50-397, 83/02/02, 8302230205

T. Hearing transcripts on non-antitrust matters

8302020006 Transcript of 830126 prehearing conference in Richland, WA. Pp 1-165
* Atomic Safety and Licensing Board Panel. 83/01/26 17pp. 16992 061 24X Fiche 50-397, 83/01/26, 8302020006.

8302020007 Transcript of 830127 prehearing conference in Richland, WA. Pp 166-284
* Atomic Safety and Licensing Board Panel. 83/01/27. 119pp. 16991:299. 24X Fiche 50-397, 83/01/27, 8302020007

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D. O. Division of Licensing. 83/01/31. Consolidated Edison Co. of New York, Inc. 14pp. 17347 177 24X Fiche: 50-000, 83/01/31, 8301310203

DOCKET 50-400 SHEARDN HARRIS NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8302250499 Forwards request for addl info in support of seismic & dynamic qualification review of qualification program outlined in FSAR & onsite audits.
KNIGHTON, O. H. Operating Reactors Branch 3. 83/02/02. UTLEY, E E. Carolina Power & Light Co. 27pp 17303 105 24X Fiche 50-400, 83/02/02, 8302250499

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 30X for Model D/2 & D/3 steam generators & at 70X for Model D/4 & D/5 steam generators.
NOVAK, T. M. Assistant Director for Licensing 83/02/03. Atomic Safety and Licensing Board Panel. 6pp 17143 293. 24X Fiche 50-000, 83/02/03, 8302100512.

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utilis Generating C SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators.
CHESTNUT, S. H. Licensing Branch 1 82/03/15 YOUNGBLOOD, B. J. Licensing Branch 1 46pp. 17143:298. 24X Fiche: 50-000, 83/02/03, 8302100512.

DOCKETED ITEMS

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290, 247 24X
Fiche: 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Hestinghouse designed NSSB re resolution of TH1 Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp, 17290, 212 24X Fiche 50-000, 83/02/08, 8302090080

D. NRC Draft/Final Environmental Statements, supp's & correspondence

8302070271 Forwards three tables re filter sludge activity calculations (normal & design) & feed streams to vol reduction sys (Unit 2 operation), per P Madambi request for use in preparation of DES
ZIMMERMAN, S R Carolina Power & Light Co 83/02/02 DENTON, H R, Office of Nuclear Reactor Regulation, Director 5pp 17035 056
24X Fiche 50-400, 83/02/02, 8302070271

8302150255 Forwards source term evaluation for vol reduction sys, requested by NRC for use in DES, NRC based decontamination factors on extremely conservative assumptions, inconsistent w/Topical Rept AECC-1
ZIMMERMAN, S R Carolina Power & Light Co. 83/02/11, DENTON, H R, Office of Nuclear Reactor Regulation, Director. 6pp 17148:347
24X Fiche: 50-400, 83/02/11, 8302150255

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche: 50-000, 83/02/01, 8301210340

G. Adjudicatory correspondence

8302020321 Answer to applicant response to motion re DCRDR info & proposed new contentions DCRDR not specific enough to formulate contentions in number of areas
EDDLEMAN, W Eddleman, W 83/01/26, Atomic Safety and Licensing Board Panel 6pp, 16994 008 24X Fiche: 50-400, 83/01/26, 8302020321

--8302020334 Responds to ASLB 830111 Memorandum & Order, Item V. L. No offense intended by cited language Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/01/26 KELLEY, BRIGHT, CARPENTER Atomic Safety and Licensing Board Panel 2pp 16994, 014 24X
Fiche 50-400, 83/01/26, 8302020334

8302010063 Response opposing W Eddleman 830108 motion to admit add'l contentions Proposed contentions premature & should be deferred Relevant documents unavailable Certificate of Svc encl.
BARTH, C A Hearing Branch 1, 83/01/28 Atomic Safety and Licensing Board Panel. 7pp, 16974 056 24X Fiche 50-400, 83/01/28, 8302010063

8302010572 Response opposing P Letchin proposed contentions based on Util Amend 5 to Environ Rept Contentions fail specificity requirement Pleading so vague that other parties not put on notice, Certificate of Svc encl.
BARTH, C A Hearing Branch 1, 83/01/31 Atomic Safety and Licensing Board Panel. 5pp 16977 088 24X Fiche: 50-400, 83/01/31, 8302010572

8302070490 Interrogatories & request for production of documents (first set) Certificate of Svc encl Related correspondence.
TRONBRIDGE, O F, Carolina Power & Light Co TRONBRIDGE, O F Shaw, Pittman, Potts & Trowbridge. 83/01/31 Eddleman, W 174pp 17039, 039 24X Fiche: 50-400, 83/01/31, 8302070490

8302070514 Regrets failure to agree on extensions of time re Eddleman 830115 discovery on Contention 15, Since util would not agree to equal extension for Eddleman, extending time to answer discovery would be hardship Certificate of Svc encl.
EDDLEMAN, W Eddleman, W 83/01/31 BAXTER, T, Shaw, Pittman, Potts & Trowbridge BAXTER, T Carolina Power & Light Co 2pp 17039:001 24X Fiche: 50-400, 83/01/31, 8302070514.

8302030180 Motion for extension of time to respond to W Eddleman initial interrogatories & request for production of documents re Eddleman Contention 15 Time should be extended to 14 days after ASLB order Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/02/01 Atomic Safety and Licensing Board Panel. 7pp 17004 222 24X Fiche 50-400, 83/02/01, 8302030180

8302070590 Response to applicant 820121 motion for dismissal of Contention IVB Human factors design evaluation rept, submitted as final detailed control room design review rept, inadequate per NUREG-0700, Section 5.2 W/Certificate of Svc
WILSON, R Wilson, R 83/02/02 Atomic Safety and Licensing Board Panel 4pp 17035 032 24X Fiche 50-400, 83/02/02, 8302070590

8302080008 Request for admission of fact that plants can be brought to cold shutdown even if heat removal capability of main condenser unavailable
BARTH, C A Hearing Branch 1 83/02/04 Conservation Council of North Carolina 1p 17058, 299 24X Fiche 50-400, 83/02/04, 8302080008

--8302080011 Interrogatories directed to Conservation Council of NC Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/02/04, Conservation Council of North Carolina 11pp 17058 300 24X Fiche 50-400, 83/02/04, 8302080008

8302090241 Answer to util 830201 motion for extension of time Util fails to show info sought is privileged, irrelevant, unduly burdensome or otherwise improper to produce
EDDLEMAN, W Eddleman, W 83/02/04 Atomic Safety and Licensing Board Panel 4pp, 17070 251 24X Fiche 50-400, 83/02/04, 8302090241

--8302090251 Motion to compel discovery from applicants. Applicants have apparently not answered 830115 interrogatories & fail to show interrogatories irrelevant, privileged or unduly burdensome Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/02/04 Atomic Safety and Licensing Board Panel 2pp 17070 255 24X Fiche 50-400, 83/02/04, 8302090241.

8302160363 Memorandum & order re 830224 prehearing conference in Raleigh, NC Due dates for responding to all pending interrogatories suspended until further ASLB order Listed subjs added to conference agenda
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/10 3pp 17169 195 24X Fiche 50-400, 83/02/10, 8302160363

8302160351 Revision, amended & add'l contentions based on W Eddleman Contention 15 & environ rept Amend 5 Certificate of Svc encl
EDDLEMAN, W Eddleman, W, 83/02/11 Atomic Safety and Licensing Board Panel 22pp 17164 289 24X Fiche 50-400, 83/02/11, 8302160351.

8302230568 Forwards proposed discovery schedule in response to ASLB memorandum memorializing 830121 conference call Four separate hearings should be held Certificate of Svc encl.
Related correspondence
PAYNE, M T Edelstein & Payne, PAYNE, M T Chapel Hill Anti-Nuclear Group Effort PAYNE, M T Conservation Council of North Carolina 83/02/16 KELLEY, J L, BRIGHT, O O, CARPENTER, J H Atomic Safety and Licensing Board Panel 5pp 17236 241, 24X
Fiche 50-400, 83/02/16, 8302230568.

--8302230579 Motion for extension to respond to applicant first set of interrogatories & request for production of documents, until 15 days after formal ruling on proposed discovery schedule W/Certificate of Svc
READ, D F, Chapel Hill Anti-Nuclear Group Effort EDDLEMAN, W Eddleman, W, RUNKLE, J D Conservation Council of North Carolina 83/02/16, Atomic Safety and Licensing Board Panel 3pp 17236 246, 24X Fiche 50-400, 83/02/16, 8302230568

8302230417 Response opposing proposed Wilson Contention V re detailed control room design rept Contention fails to express specific safety concern which could be litigated Certificate of Svc encl
O'NEILL, J H, Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/02/17 Atomic Safety and Licensing Board Panel 6pp 17246 114 24X Fiche 50-400, 83/02/17, 8302230417.

8302230496 Proposed schedule for remainder of licensing proceeding re intervenor contentions on environ, safety & emergency preparedness Certificate of Svc encl.
BAXTER, T A Carolina Power & Light Co, BAXTER, T A Shaw, Pittman, Potts & Trowbridge. 83/02/17 7pp 17246 182 24X
Fiche 50-400, 83/02/17, 8302230496

DOCKETED ITEMS

293

8302230589 Forwards corrected Pp 5,18,19 & 22 to util 830121 list of admitted contentions
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Carolina Power & Light Co 83/02/18 KELLEY, J L, BRIGHT, G O.
CARPENTER, J H Atomic Safety and Licensing Board Panel. 2pp
17255 217 24X Fiche 50-400, 83/02/18, 8302230589

--8302230594 Corrected Pp 5,18,19 & 22 to 830121 list of admitted contentions Svc list encl
* Carolina Power & Light Co 83/02/18 Atomic Safety and Licensing Board Panel 5pp 17255 219 24X Fiche 50-400, 83/02/18, 8302230589

G Inspection reports, IE Bulletins & correspondence

8302150703 Forwards IE Insp Repts 50-400/82-37 & 50-401/82-37 on 821214-17 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs. 83/01/07.
UTLEY, E E Carolina Power & Light Co 2pp 17151:001 24X
Fiche 50-400, 83/01/07, 8302150703

--8302150711 IE Insp Repts 50-400/82-37 & 50-401/82-37 on 821214-17 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, structural concrete & licensee identified item
HARRIS, J R, CONLON, T E. Division of Engineering & Radiological Safety Programs 83/01/05 5pp. 17151 003 24X
Fiche 50-400, 83/01/07, 8302150703

8312060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8312060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8312060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8312060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc. 110pp. 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8312060365 IE Info Notice 83-05, "Obtaining Approval For Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365.

8312060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/02/24 Consolidated Edison Co of New York, Inc. 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302010442 Forwards Quarterly Seismic Monitoring Rept for Oct - Dec 1982.
ZIMMERMAN, S. R. Carolina Power & Light Co 83/01/28 DENTON, H R, Office of Nuclear Reactor Regulation, Director. 1p 16981:077 24X
Fiche 50-400, 83/01/28, 8302010442

--8302010445 Quarterly Seismic Monitoring Rept for Oct - Dec 1982.
* Carolina Power & Light Co 83/01/28 1p. 16981:078. 24X
Fiche 50-400, 83/01/28, 8302010442

S Reportable occurrences, LERs & related correspondence

8302010272 Interim deficiency & Part 21 repts re seismic qualification test failure of starting air check Valves for emergency diesel engine generator sets Initially reported on 821223
Valves returned to manufacturer. Final rept by 831219
PARSONS, R M. Carolina Power & Light Co. 83/01/21 O'REILLY, J. P. Region 2, Office of Director 3pp. 16973 159. 24X
Fiche: 50-400, 83/01/21, 8302010272.

8302010361 Interim deficiency rept re deficiencies in bolted structural steel connections Initially reported on 821229 Reinsp of turbine bldg & evaluations of other deficiencies continue
Next rept expected by 830415
PARSONS, R. M. Carolina Power & Light Co. 83/01/21 O'REILLY, J. P. Region 2, Office of Director 1p 16973 327 24X
Fiche 50-400, 83/01/21, 8302010361

8302010580 Second interim deficiency & Part 21 repts re defective governor drive coupling purchase order Initially reported on 820909 Isoprene governor drive coupling will be replaced per Transamerica DeLaval instructions Final rept by 831219
PARSONS, R. M. Carolina Power & Light Co 83/01/21. O'REILLY, J. P. Region 2, Office of Director 4pp 16977-071 24X
Fiche 50-400, 83/01/21, 8302010580

8302010590 Fourth interim deficiency rept re threaded studs w/ insufficient threaded engagement into embedded strip plates
Initially reported on 81110 Extension until 830225 requested for submittal of final rept
PARSONS, R. M. Carolina Power & Light Co 83/01/21. O'REILLY, J. P. Region 2, Office of Director 4pp 16978-098 24X
Fiche 50-400, 83/01/21, 8302010590

8302030304 Second interim rept re 480-volt switchgear design deficiency of secondary disconnects Initially reported on 821102 Newly designed disconnects to replace originals Final rept will be submitted by 830429 Also reported per Part 21
PARSONS, R. M. Carolina Power & Light Co 83/01/28. O'REILLY, J. P. Region 2, Office of Director 4pp 17001-264 24X
Fiche 50-400, 83/01/28, 8302030304

8302150177 Interim deficiency rept re auxiliary relay cabinets. Initially reported on 821101 Extension requested for final rept to allow for evaluation of vendor seismic analysis of structural integrity of cabinets Final rept by 830429
PARSONS, R. M. Carolina Power & Light Co 83/02/04. O'REILLY, J. P. Region 2, Office of Director. 1p 17147-221 24X
Fiche 50-400, 83/02/04, 8302150177

8302170248 Interim deficiency rept re defective weld & unidentified bolting matl in boric acid transfer pumps Initially reported on 830113 Evaluation in progress Next rept will be submitted by 830516 Also reported per Part 21
PARSONS, R. M. Carolina Power & Light Co 83/02/08 O'REILLY, J. P. Region 2, Office of Director 1p 17181-362. 24X
Fiche 50-400, 83/02/08, 8302170248

8302280173 Interim deficiency rept re emergency diesel generator engine anchor bolts & nuts, item 114 Initially reported on 830117 Bolts & nuts type & grade discrepancies still under evaluation Next rept by 830415 Also reportable per Part 21
PARSONS, R. M. Carolina Power & Light Co 83/02/17. O'REILLY, J. P. Region 2, Office of Director. 1p 17305 318 24X
Fiche 50-400, 83/02/17, 8302280173

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses, Svc list encl
EISENHUT, D O Division of Licensing. 83/01/31 Consolidated Edison Co of New York, Inc 14pp. 17347.177. 24X
Fiche: 50-000, 83/01/31, 8301310203

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302230499 Forwards request for addl info in support of seismic & dynamic qualification review of qualification program outlined in FSAR & onsite audits
KNIGHTON, O H Operating Reactors Branch 3 83/02/02. UTLEY, E. E. Carolina Power & Light Co. 27pp 17303.105 24X
Fiche: 50-400, 83/02/02, 8302230499

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T. M. Assistant Director for Licensing. 83/02/03 Atomic Safety and Licensing Board Panel 6pp. 17143.293. 24X
Fiche: 50-000, 83/02/03, 8302100512.

--8302100522 Summary of 820219 meeting w/ ORNL, ANL, TX Utils Operating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S H. Licensing Branch 1 82/03/15 YOUNGBLOOD, S. J. Licensing Branch 1 46pp. 17143:298 24X Fiche. 50-000, 83/02/03, 8302100512

DOCKETED ITEMS

8302080293 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc 1st encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080293

8302090080 Generic Ltr 83-10C to all applicants w/Hastingshouse designed NSSB re resolution of TMI Action Item II.K 3 G, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D G Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

D NRC Draft/Final Environmental Statements, suppl's & correspondence

8302070271 Forwards three tables re filter sludge activity calculations (normal & design) & feed streams to vol reduction sys (Unit 2 operation), per P Kadambi request for use in preparation of DEB
ZIMMERMAN, B R Carolina Power & Light Co 83/02/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 17035 056
24X Fiche 50-400, 83/02/02, 8302070271.

8302150255 Forwards source term evaluation for vol reduction sys, requested by NRC for use in DEB NRC based decontamination factors on extremely conservative assumptions, inconsistent w/Topical Rept AECG-1
ZIMMERMAN, B R Carolina Power & Light Co 83/02/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 17148 347
24X Fiche: 50-400, 83/02/11, 8302150255.

F. Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability," Svc 1st encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302020321 Answer to applicant response to motion re DCRDR info & proposed new contentions. DCRDR not specific enough to formulate contentions in number of areas
EDDLEMAN, W Eddleman, W 83/01/26 Atomic Safety and Licensing Board Panel 6pp 16974 008 24X Fiche 50-400, 83/01/26, 8302020321

--8302020334 Responds to ASLB 830111 Memorandum & Order, Item V.L No offense intended by cited language Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/01/26 KELLEY, BRIGHT, CARPENTER
Atomic Safety and Licensing Board Panel 2pp 16974 014 24X
Fiche: 50-400, 83/01/26, 8302020334

8302010063 Response opposing W Eddleman 830108 motion to admit addl contentions Proposed contentions premature & should be deferred Relevant documents unavailable Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/01/28 Atomic Safety and Licensing Board Panel 7pp 16974 056 24X Fiche 50-400, 83/01/28, 8302010063

8302010572 Response opposing P Lotchin proposed contentions based on util Amend 5 to Environ Rept. Contentions fail specificity requirement Pleading so vague that other parties not put on notice Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/01/31 Atomic Safety and Licensing Board Panel 3pp 16977 088 24X Fiche 50-400, 83/01/31, 8302010572

8302070490 Interrogatories & request for production of documents (first set). Certificate of Svc encl Related correspondence
TROWBRIDGE, G F Carolina Power & Light Co. TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/01/31 Eddleman, W 174pp, 17039 039 24X Fiche 50-400, 83/01/31, 8302070490

8302070514 Regrets failure to agree on extensions of time re Eddleman 830113 discovery on Contention 15 Since util would not agree to equal extension for Eddleman, extending time to answer discovery would be hardship. Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/01/31 BAXTER, T Shaw, Pittman, Potts & Trowbridge BAXTER, T Carolina Power & Light Co 2pp 17039 001 24X Fiche 50-400, 83/01/31, 8302070514

8302030180 Motion for extension of time to respond to W Eddleman initial interrogatories & request for production of documents re Eddleman Contention 15 Time should be extended to 14 days after ASLB order Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/02/01 Atomic Safety and Licensing Board Panel 7pp 17004 222 24X Fiche 50-400, 83/02/01, 8302030180

8302070590 Response to applicant 820121 motion for dismissal of Contention IVB Human factors design evaluation rept, submitted as final detailed control room design review rept, inadequate per NUREG-0700, Section 5.2 W/Certificate of Svc
WILSON, R Wilson, R 83/02/02 Atomic Safety and Licensing Board Panel 4pp 17035 032 24X Fiche 50-400, 83/02/02, 8302070590

8302080008 Request for admission of fact that plants can be brought to cold shutdown even if heat removal capability of main condenser unavailable
BARTH, C A Hearing Branch 1 83/02/04 Conservation Council of North Carolina 1p 17058 299 24X Fiche 50-400, 83/02/04, 8302080008

--8302080011 Interrogatories directed to Conservation Council of NC Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/02/04 Conservation Council of North Carolina 11pp 17058 300 24X Fiche 50-400, 83/02/04, 8302080011

8302090241 Answer to util 830201 motion for extension of time Util fails to show info sought is privileged, irrelevant, unduly burdensome or otherwise improper to produce
EDDLEMAN, W Eddleman, W 83/02/04 Atomic Safety and Licensing Board Panel 4pp 17070 251 24X Fiche 50-400, 83/02/04, 8302090241

--8302090251 Motion to compel discovery from applicants Applicants have apparently not answered 830115 interrogatories & fail to show interrogatories irrelevant, privileged or unduly burdensome Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/02/04 Atomic Safety and Licensing Board Panel 2pp 17070 255 24X Fiche 50-400, 83/02/04, 8302090251

8302160363 Memorandum & order re 830224 prehearing conference in Raleigh, NC Due dates for responding to all pending interrogatories suspended until further ASLB order Listed subjs added to conference agenda
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/10 3pp 17169 193 24X Fiche 50-400, 83/02/10, 8302160363

8302160351 Revised, amended & addl contentions based on W Eddleman Contention 15 & environ rept Amend 5 Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/02/11 Atomic Safety and Licensing Board Panel 22pp 17164 289 24X Fiche 50-400, 83/02/11, 8302160351

8302230568 Forwards proposed discovery schedule in response to ASLB memorandum memorializing 830121 conference call Four separate hearings should be held Certificate of Svc encl
Related correspondence
PAYNE, M T, Edelstein & Payne PAYNE, M T Chapel Hill Anti-Nuclear Group Effort PAYNE, M T Conservation Council of North Carolina 83/02/16 KELLEY, J L, BRIGHT, G O, CARPENTER, J H Atomic Safety and Licensing Board Panel 5pp 17256 241 24X
Fiche 50-400, 83/02/16, 8302230568

--8302230579 Motion for extension to respond to applicant first set of interrogatories & request for production of documents, until 15 days after formal ruling on proposed discovery schedule W/Certificate of Svc
READ, D F Chapel Hill Anti-Nuclear Group Effort EDDLEMAN, W Eddleman, W RUNKLE, J D Conservation Council of North Carolina 83/02/16 Atomic Safety and Licensing Board Panel 3pp 17256 246 24X Fiche 50-400, 83/02/16, 8302230579

8302230417 Response opposing proposed Wilson Contention V re detailed control room design rept Contention fails to express specific safety concern which could be litigated Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/02/17 Atomic Safety and Licensing Board Panel 4pp 17246 114 24X Fiche 50-400, 83/02/17, 8302230417

8302230496 Proposed schedule for remainder of licensing proceeding re intervenor contentions on environ, safety & emergency preparedness Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co, BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/02/17 7pp 17246 182 24X
Fiche: 50-400, 83/02/17, 8302230496

DOCKETED ITEMS

2

8302230589 Forwards corrected Pp 5, 18, 19 & 22 to util 830121 list of admitted contentions
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge BAXTER, T. A.
Carolina Power & Light Co 83/02/18 KELLEY, J. L., BRIGHT, Q. O.
CARPENTER, J. H. Atomic Safety and Licensing Board Panel 2pp
17255 217 24X Fiche 50-400, 83/02/18, 8302230589

--8302230596 Corrected Pp 5, 18, 19 & 22 to 830121 list of admitted contentions Svc list encl
* Carolina Power & Light Co 83/02/18 Atomic Safety and Licensing Board Panel 5pp 17255 217 24X Fiche 50-400, 83/02/18, 8302230596

G Inspection Reports, IE Bulletins & correspondence

8302150703 Forwards IE Insp Repts 50-400/82-37 & 50-401/82-37 on 821214-17 No noncompliance noted
VERRELLI, D. Division of Project & Resident Programs 83/01/07
UTLEY, E. E. Carolina Power & Light Co 2pp 17151 001 24X
Fiche 50-400, 83/01/07, 8302150703

--8302150711 IE Insp Repts 50-400/82-37 & 50-401/82-37 on 821214-17. No noncompliance noted Major areas inspected license action on previous enforcement matters, structural concrete & licensee identified item
HARRIS, J. R., CONLON, T. E. Division of Engineering & Radiological Safety Programs 83/01/05 5pp 17151 003 24X
Fiche 50-400, 83/01/07, 8302150703

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/01/26 Consolidated Edison Co. of New York, Inc 11pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358.

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001. 24X Fiche 50-000, 83/01/28, 8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191. 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365.

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302010442 Forwards Quarterly Seismic Monitoring Rept for Oct - Dec 1982
ZIMMERMAN, S. R. Carolina Power & Light Co 83/01/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p 16981, 077. 24X
Fiche 50-400, 83/01/28, 8302010442

--8302010445 Quarterly Seismic Monitoring Rept for Oct - Dec 1982.
* Carolina Power & Light Co 83/01/28. 1p 16981, 078 24X
Fiche 50-400, 83/01/28, 8302010442

S Reportable occurrences, LERs & related correspondence

8302010272 Interim deficiency & Part 21 repts re seismic qualification test failure of starting air check valves for emergency diesel engine generator sets Initially reported on 821223
Valves returned to manufacturer. Final rept by 831219
PARSONS, R. M. Carolina Power & Light Co. 83/01/21 O'REILLY, J. P. Region 2, Office of Director 3pp 16973, 159 24X
Fiche 50-400, 83/01/21, 8302010272

8302010361 Interim deficiency rept re deficiencies in bolted structural steel connections Initially reported on 821229. Reins of turbine bldg & evaluations of other deficiencies continue
Next rept expected by 830415
PARSONS, R. M. Carolina Power & Light Co 83/01/21 O'REILLY, J. P. Region 2, Office of Director 1p 16973 327 24X
Fiche 50-400, 83/01/21, 8302010361

8302010580 Second interim deficiency & Part 21 repts re defective governor drive coupling purchase order Initially reported on 820909 Isoprene governor drive coupling will be replaced per Transamerica DeLaval instructions Final rept by 831219
PARSONS, R. M. Carolina Power & Light Co 83/01/21 O'REILLY, J. P. Region 2, Office of Director. 4pp 16977: 071 24X
Fiche 50-400, 83/01/21, 8302010580

8302010590 Fourth interim deficiency rept re threaded studs w/ insufficient threaded engagement into embedded strip plates. Initially reported on 811110. Extension until 830225 requested for submittal of final rept
PARSONS, R. M. Carolina Power & Light Co 83/01/21 O'REILLY, J. P. Region 2, Office of Director 4pp 16978 098 24X
Fiche 50-400, 83/01/21, 8302010590.

8302030304 Second interim rept re 480-volt switchgear design deficiency of secondary disconnects Initially reported on 821102 Newly designed disconnects to replace originals Final rept will be submitted by 830429 Also reported per Part 21
PARSONS, R. M. Carolina Power & Light Co 83/01/28, O'REILLY, J. P. Region 2, Office of Director. 4pp 17001 264. 24X
Fiche 50-400, 83/01/28, 8302030304

8302150177 Interim deficiency rept re auxiliary relay cabinets. Initially reported on 821101 Extension requested for final rept to allow for evaluation of vendor seismic analysis of structural integrity of cabinets. Final rept by 830429
PARSONS, R. M. Carolina Power & Light Co 83/02/04, O'REILLY, J. P. Region 2, Office of Director. 1p 17147, 221. 24X
Fiche 50-400, 83/02/04, 8302150177.

8302170248 Interim deficiency rept re defective weld & unidentified bolting matl in boric acid transfer pumps Initially reported on 830113. Evaluation in progress. Next rept will be submitted by 830516 Also reported per Part 21.
PARSONS, R. M. Carolina Power & Light Co 83/02/08 O'REILLY, J. P. Region 2, Office of Director. 1p 17181 362 24X
Fiche 50-400, 83/02/08, 8302170248

8302280173 Interim deficiency rept re emergency diesel generator engine anchor bolts & nuts. Item 114 Initially reported on 830117. Bolts & nuts type & grade discrepancies still under evaluation. Next rept by 830415 Also reportable per Part 21.
PARSONS, R. M. Carolina Power & Light Co. 83/02/17 O'REILLY, J. P. Region 2, Office of Director 1p. 17305: 318 24X
Fiche 50-400, 83/02/17, 8302280173

V. Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D. O. Division of Licensing. 83/01/31 Consolidated Edison Co. of New York, Inc. 14pp. 17347: 177. 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-402 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A Application/construction stage documents & correspondence

8302100512 Board Notification 83-11, forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50X for Model D/2 & D/3 steam generators, & at 70X for Model D/4 & D/5 steam generators.
NOVAK, T. M. Assistant Director for Licensing. 83/02/03, Atomic Safety and Licensing Board Panel 6pp 17143: 273 24X
Fiche 50-000, 83/02/03, 8302100512.

--8302100522 Summary of 820219 meeting w/ ORNL, ANL, TX Utils Generating SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators.
CHESTNUT, S. H. Licensing Branch 1. 82/03/15 YOUNGBLOOD, B. J. Licensing Branch 1 46pp 17143, 298 24X Fiche 50-000, 83/02/03, 8302100512

8302090080 Generic Ltr 83-10C to all applicants w/ Westinghouse design NSSB re resolution of TMI Action Item II K 3 S. "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D. O. Division of Licensing 83/02/08 Baltimore Gas & Electric Co. 30pp. 17290, 212 24X Fiche 50-000, 83/02/08, 8302090080.

DOCKETED ITEMS

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

A Application/construction stage documents & correspondence

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X Fiche 50-000, 83/02/03, 8302100512

--8302100922 Summary of 830219 meeting w/ORNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators CHESTNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100922

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps." EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co. 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEV, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEV, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

DOCKET 50-406 TUSKEGEE INST. RESEARCH REACTOR

P Operating license stage documents & correspondence

8302020187 Advises that joint request may be filed for authorization to dismantle & dispose of AON-201 reactor components & to terminate License R-122 Add'l actions to be taken listed THOMAS, G D Standardization & Special Projects Branch 83/01/28 CLAYTON, W F Tuskegee Inst 3pp 16999 242 24X Fiche 50-406, 83/01/28, 8302020187

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl I, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221-226 24X Fiche 50-000, 83/02/01, 8301210340

8302230131 Forwards changed page to training & qualification plan Page withheld (ref 10CFR73 211). LINDER, F Dairyland Power Cooperative 83/02/04 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17243 311 24X Fiche 50-409, 83/02/04, 8302230131

8302250262 Application for amend to License DPR-45 adding contingency plans to Section 6 B 1.6(i), responsibilities & Section 6 B 2 B(f), audits of Tech Specs LINDER, F Dairyland Power Cooperative 83/02/18 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17292-125 24X Fiche 50-409, 83/02/18, 8302250262

--8302250269 Proposed Tech Specs adding contingency plans to Section 6 B 1 6(i), responsibilities & Section 6 B 2 B(f), Tech Spec audits * Dairyland Power Cooperative 83/02/18 2pp 17292 127 24X Fiche 50-409, 83/02/18, 8302250262

8302280269 Forwards response to NRC telcon request for addl info on rewrite of Section 8 of fire protection rule 10CFR50 48 Key lock switches in individual junction boxes located in electrical penetration room will be provided LINDER, F Dairyland Power Cooperative 83/02/23 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 17312 264 24X Fiche 50-409, 83/02/23, 8302280269

P Operating license stage documents & correspondence

8302010627 Forwards final evaluation of SEP Topic III-4 B, "Turbine Missiles." Turbine missile risk for LACBWR safety-related sys acceptable provided listed conditions met Exam of factual correctness of SER requested CRUTCHFIELD, D Operating Reactors Branch 5 83/01/27 LINDER, F Dairyland Power Cooperative 11pp 16980 281 24X Fiche 50-409, 83/01/27, 8302010627

8302100210 Forwards evaluation of SEP Topic III.2, "Wind & Tornado Loadings." Evaluation identifies structures & portions of structures which cannot withstand postulated tornado loads. Topic may be changed if facility design changes CRUTCHFIELD, D Operating Reactors Branch 5 83/01/27 LINDER, F Dairyland Power Cooperative 11pp 17109 359 24X Fiche 50-409, 83/01/27, 8302100210

--8308190201 "Wind & Tornado Loadings, LaCrosse Nuclear Generating Station," technical evaluation rept BARRETT, D J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-408 82/08/14 PERBINKO, D NRC - No Detailed Affiliation Given 67pp 17110 004 24X Fiche 50-409, 83/01/27, 8302100210

8302070564 Forwards evaluation of SEP Topic II-1 A, "Exclusion Area Authority & Control." Util has authority to determine all activities within exclusion area per 10CFR100 NRC should be advised of changes in occupancy. CRUTCHFIELD, D Operating Reactors Branch 5 83/01/31 LINDER, F Dairyland Power Cooperative 8pp 17034 233 24X Fiche 50-409, 83/01/31, 8302070564

8302070453 Advises that Rev 1 to GA program, dtd 800828, acceptable CRUTCHFIELD, D Operating Reactors Branch 5 83/02/02 LINDER, F Dairyland Power Cooperative 2pp 17036 272 24X Fiche 50-409, 83/02/02, 8302070453

8302140937 Application for amend to License DPR-45, changing plant controlling annual tests to refueling shutdown tests LINDER, F Dairyland Power Cooperative 83/02/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17140 185 24X Fiche 50-409, 83/02/03, 8302140937

--8302140061 Proposed Tech Specs changing plant controlling annual tests to refueling shutdown tests * Dairyland Power Cooperative 83/02/03 2pp 17140 187 24X Fiche 50-409, 83/02/03, 8302140061

8302170319 Discusses review of NRC draft safety evaluation for SEP Topics III-6, "Seismic Design Considerations," & III-11, "Component Integrity." Safety consequences of mod to facility minimal Supporting documentation encl LINDER, F Dairyland Power Cooperative, 83/02/07 CRUTCHFIELD, D Operating Reactors Branch 5 58pp 17185 159 24X Fiche 50-409, 83/02/07, 8302170319

--8302170321 Rev 3 to "Safety-Related Electrical Equipment Anchorages for LACBWR." Related info encl. RUMPF, R E, STRNAD, T Nuclear Energy Service, Inc 81A0001 R03 83/01/04 208pp 17185-217 24X Fiche 50-409, 83/02/07, 8302170319

--8302170323 Rev 0 to "Seismic & Stress Analysis of LACBWR Manual Depressurization Sys." STRNAD, T Nuclear Energy Service, Inc 81A0052 R00 82/11/19 83pp 17186 065 24X Fiche 50-409, 83/02/07, 8302170319

--8302170325 Rev 1 to "Seismic & Structural Analysis of LACBWR Stack Using NRC Site-Specific Ground Response Spectra." HOBSTETLER, M, RUMPF, R, CAQ, N Nuclear Energy Service, Inc 81A0046 R01 82/09/27 143pp 17186 147 24X Fiche 50-409, 83/02/07, 8302170319

--8302170326 Addendum 1 to "Seismic & Stress Analysis of LACBWR HPCB Discharge Line Piping Sys"
DBLIQADO, A., HUSAIN, I., YOLE, A.H. Nuclear Energy Service, Inc
81A0091 ADD 01 82/06/30 13pp 17186 310 24X
Fiche 50-409, 83/02/07, 8302170319

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D.O. Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080304 Generic Ltr 83-11 to all operating reactor licensees re licensee qualification for performing safety analysis in support of licensing actions Ability to use code must be demonstrated by vendor or licensee Svc list encl
EISENHUT, D.O. Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, 8302080304

8302230393 Submits corrected as-built conditions, per 821213 BER re SEP Topic III-3 A, "Effect of High Water Level on Structures"
No assessment of Genoa 2 & 3 stacks performed for flood design
LINDER, F. Dairyland Power Cooperative 83/02/14 EISENHUT, D.O. Division of Licensing 2pp 17246 341 24X Fiche 50-409, 83/02/14, 8302230393

8302240024 Forwards reply to NRC requests for review summary of differences between current guidelines for new reactor const & original const stds identified by NRC SEP
LINDER, F. Dairyland Power Cooperative 83/02/16 CRUTCHFIELD, D. Operating Reactors Branch 5 43pp 17274 291 24X
Fiche 50-409, 83/02/16, 8302240024

8302250262 Application for amend to License DPR-45 adding contingency plans to Section 6.5.1.6(i), responsibilities & Section 6.5.2.8(f), audits of Tech Specs
LINDER, F. Dairyland Power Cooperative 83/02/18 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 17292 125 24X
Fiche 50-409, 83/02/18, 8302250262

--8302250269 Proposed Tech Specs adding contingency plans to Section 6.5.1.6(i), responsibilities & Section 6.5.2.8(f), Tech Spec audits
* Dairyland Power Cooperative 83/02/18 2pp 17292 127 24X
Fiche 50-409, 83/02/18, 8302250262

0 Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR.
FELTON, J.M. Division of Rules and Records 82/12/30 HIATT, S.L. Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L. Region 3, Office of Director 82/07/08
KEPPLER, J.O. Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302040067 Forwards IE Insp Rept 50-409/82-20 on 821101-1231 & notice of violation
STREETER, J.F. Division of Project & Resident Programs 83/01/20.
LINDER, F.W. Dairyland Power Cooperative 2pp 17020 315 24X
Fiche 50-409, 83/01/20, 8302040067

--8302040073 Notice of violation from insp on 821101-1231
STREETER, J.F. Division of Project & Resident Programs 83/01/20, 2pp. 17020 317 24X Fiche 50-409, 83/01/20, 8302040067

--8302040088 IE Insp Rept 50-409/82-20 on 821101-1231 Noncompliance noted failure to conduct proper shift turnovers & failure to properly document testing maint
BRANCH, M.W., REYES, L. Division of Project & Resident Programs 83/01/20 2pp 17020 319 24X Fiche 50-409, 83/01/20, 8302040067.

8302040046 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" No Ruster-Ramo electrical penetrations used at facility, No further action required
LINDER, F. Dairyland Power Cooperative 83/01/24 KEPPLER, J.O. Region 3, Office of Director 2pp 17021 099 24X
Fiche 50-409, 83/01/24, 8302040046

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302010456 Ack receipt of 830103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/82-18
NORELIUS, C.E. Division of Project & Resident Programs 83/01/26 LINDER, F.W. Dairyland Power Cooperative 1p 16980 360 24X
Fiche 50-409, 83/01/26, 8302010456

--8302010462 Responds to NRC 821202 ltr re violations noted in IE Insp Rept 50-409/82-18 Corrective actions procedures will be revised to include specific criteria re monthly test for emergency diesel generator
LINDER, F. Dairyland Power Cooperative 83/01/03 SPESBARD, R.L. Division of Project & Resident Programs 2pp 16980 361 24X
Fiche 50-409, 83/01/26, 8302010456

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advances of 830207 open forum in Chicago, IL re recent rev to 10CFR50.94 & 50.95 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESBARD, R.L. Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303.

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 038 24X Fiche 50-000, 83/02/24, 8212060365.

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

V Operator Examinations

8302070568 Responds to Generic Ltr 83-01 re operator licensing exam site visit Proposed schedule only for Category 5 submitted
LINDER, F. Dairyland Power Cooperative 83/01/28, EISENHUT, D.O. Division of Licensing 1p 17034 170 24X Fiche 50-409, 83/01/28, 8302070568

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D.O. Division of Licensing 83/01/31, Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302020022 Forwards DL application, consisting of acceptance review FSAR (filed in PDR Category K), Environ Rept (Category C), Physical Security & Emergency Plans (withheld), Failure Mode & Effects Analysis & proprietary & nonproprietary Assessment Repts.
MANGAN, C.V. Niagara Mohawk Power Corp 83/01/25, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 24X
Fiche 50-410, 83/01/25, 8302020022

--8302020034 Application for DL, consisting of acceptance review FSAR, Environ Rept, Physical Security & Emergency Plans (withheld), Failure Modes & Effects Analysis & proprietary & nonproprietary Design Assessment Repts
* Niagara Mohawk Power Corp 83/01/21 30pp 24X
Fiche 50-410, 83/01/25, 8302020022.

DOCKETED ITEMS

--8302020064 "Failure Modes & Effects Analysis, Nine Mile Point Nuclear Station, Unit 2," Books 1 & 2
 * Niagara Mohawk Power Corp 83/01/25 1,200pp 24X
 Fiche: 50-410, 83/01/25, 8302020062

8302020058 Forwards request for addl info re 820921 ltr on revetment - ditch sys. per 830121 discussion Response requested within 2 wks.
 SCHWENGER, A Licensing Branch 2 83/01/27 RHODE, O K. Niagara Mohawk Power Corp 3pp 1699B 350 24X Fiche 50-410, 83/01/27, 8302020058

8302140209 Notification of 830222-24 caseload forecast panel site visit in Scriba, NY to discuss const progress & to obtain info for assessing projected fuel load data Agenda encl
 HAUGHEY, M F Licensing Branch 2 83/02/04 SCHWENGER, A Licensing Branch 2 6pp 17143 328 24X Fiche 50-410, 83/02/04, 8302140209

8302170016 Forwards list of info to be reviewed at NRC caseload Forecast panel 830222-24 site visit re status of const
 SCHWENGER, A Licensing Branch 2 83/02/04 RHODE, O K Niagara Mohawk Power Corp 5pp 17176 346 24X Fiche 50-410, 83/02/04, 8302170016

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRS re review of C-E Owners Group emergency procedures guideline program Bvc list encl
 EISENHUT, D O. Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc. 11pp 17290 247 24X
 Fiche: 50-000, 83/02/08, 8302080295.

8302080301 Generic Ltr 83-05 to DWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Bvc list encl.
 EISENHUT, D O. Division of Licensing 83/02/08 Commonwealth Edison Co. 6pp 17234 245 24X Fiche: 50-000, 83/02/08, 8302080301

8302250412 Forwards responses to NRC 830127 ltr re const of revetment ditch sys at facility. One oversize figure encl Aperture card is available in PDR
 MANGAN, C V Niagara Mohawk Power Corp 83/02/18 SCHWENGER, A Licensing Branch 2 7pp 17296 189 24X Fiche: 50-410, 83/02/18, 8302250412

C Utility Environmental Report (ER), amends & correspondence

8302020022 Forwards acceptance review copy of Environ Rept for Nine Mile Point Nuclear Station, Unit 2
 MANGAN, C V. Niagara Mohawk Power Corp 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p 24X
 Fiche: 50-410, 83/01/25, 8302020022

--8302020036 Acceptance review copy of Environ Rept - OL stage for Nine Mile Point Nuclear Station, Unit 2
 * Niagara Mohawk Power Corp 83/01/25 950pp 24X
 Fiche: 50-410, 83/01/25, 8302020022

F. Security, medical, emergency & fire protection plans

8302020022 Forwards OL application, consisting of acceptance review FSAR (filed in PDR Category K), Environ Rept (Category C), Physical Security & Emergency Plans (withheld), Failure Mode & Effects Analysis & proprietary & nonproprietary Assessment Repts
 MANGAN, C V. Niagara Mohawk Power Corp 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p 24X
 Fiche: 50-410, 83/01/25, 8302020022.

--8302020031 Forwards acceptance review copy of Physical Security Plan Plan withheld (ref 10CFR2 790)
 MANGAN, C V. Niagara Mohawk Power Corp 83/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 24X
 Fiche 50-410, 83/01/25, 8302020022.

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability," Bvc list encl
 EISENHUT, D O. Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221, 226 24X
 Fiche: 50-000, 83/02/01, 8301210340.

8302160408 Releases public version of revised site emergency plan.
 FELTON, J M Division of Rules and Records. 83/02/07 Document Management Branch. 1p 17174 031 24X Fiche: 50-410, 83/02/07, 8302160408

--8302160410 Public version of Rev 10 to site emergency plan, consisting of App 13B to FSAR
 * Niagara Mohawk Power Corp 82/12/31 515pp 17174 039 24X
 Fiche 50-410, 83/02/07, 8302160408

K Utility Final Safety Analysis Report (FSAR) & amends

8302020022 Forwards acceptance review copy of FSAR for Nine Mile Point Nuclear Station, Unit 2
 MANGAN, C V. Niagara Mohawk Power Corp 83/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 24X
 Fiche 50-410, 83/01/25, 8302020022

--8302020038 Acceptance review copy of FSAR for Nine Mile Point Nuclear Station, Unit 2
 * Niagara Mohawk Power Corp 83/01/25 22,028pp 24X
 Fiche 50-410, 83/01/25, 8302020022

8302020069 Acceptance review copy of Chapter 1 to Nine Mile Point Unit 2 FSAR, "Introduction & General Description of Plant"
 * Niagara Mohawk Power Corp 83/01/25 700pp 24X
 Fiche: 50-410, 83/01/25, 8302020069

8302020076 Acceptance review copy of Chapter 2 to Nine Mile Point Unit 2 FSAR, "Site Characteristics"
 * Niagara Mohawk Power Corp 83/01/25 800pp 24X
 Fiche 50-410, 83/01/25, 8302020076

8302020085 Acceptance review copy of App 2A to Nine Mile Point Unit 2 FSAR, "Hazardous Materials Data Collection"
 * Niagara Mohawk Power Corp 83/01/25 11pp 24X
 Fiche 50-410, 83/01/25, 8302020085

8302020091 Acceptance review copy of App 2B to Nine Mile Point Unit 2 FSAR, "Onsite & Syracuse Natl Weather Svc Station Meteorological Summaries"
 * Niagara Mohawk Power Corp 83/01/25 500pp 24X
 Fiche 50-410, 83/01/25, 8302020091

8302020098 Acceptance review copy of App 2C to Nine Mile Point Unit 2 FSAR, "Visible Plume Model Description"
 * Niagara Mohawk Power Corp 83/01/25 16pp 24X
 Fiche 50-410, 83/01/25, 8302020098

8302020101 Acceptance review copy of App 2D to Nine Mile Point Unit 2 FSAR, "Salt Drift Model Description"
 * Niagara Mohawk Power Corp 83/01/25 14pp 24X
 Fiche 50-410, 83/01/25, 8302020101

8302020103 Acceptance review copy of App 2E to Nine Mile Point Unit 2 FSAR, "Description of Relative Humidity Augmentation Model"
 * Niagara Mohawk Power Corp 83/01/25 3pp 24X
 Fiche 50-410, 83/01/25, 8302020103

8302020107 Acceptance review copy of App 2F to Nine Mile Point Unit 2 FSAR, "Conservative & Realistic Short-Term Diffusion Estimates for Hypothetical Releases From Unit 2 Main Stack, Combined Radwaste & Reactor Bldg Vent & Main Steam"
 * Niagara Mohawk Power Corp 83/01/25 50pp 24X
 Fiche 50-410, 83/01/25, 8302020107

8302020110 Acceptance review copy of App 2G to Nine Mile Point Unit 2 FSAR, "Long-Term (Routine) Diffusion Estimates for Main Stack & Combined Radwaste & Reactor Bldg Vent"
 * Niagara Mohawk Power Corp 83/01/25 12pp 24X
 Fiche 50-410, 83/01/25, 8302020110

8302020111 Acceptance review copy of App 2H to Nine Mile Point Unit 2 FSAR, "Excavation Maps"
 * Niagara Mohawk Power Corp 83/01/25 300pp 24X
 Fiche 50-410, 83/01/25, 8302020111

8302020112 Acceptance review copy of App 2I to Nine Mile Point Unit 2 FSAR, "Demeter Structural Zone W/Discussion on Origin & Extent."
 * Niagara Mohawk Power Corp 83/01/25 600pp 24X
 Fiche 50-410, 83/01/25, 8302020112

8302020114 Acceptance review copy of App 2J to Nine Mile Point Unit 2 FSAR, "Test Procedures"
 * Niagara Mohawk Power Corp 83/01/25 15pp 24X
 Fiche 50-410, 83/01/25, 8302020114

8302020117 Acceptance review copy of App 2K to Nine Mile Point Unit 2 FSAR, "Boring Logs"
 * Niagara Mohawk Power Corp 83/01/25 300pp 24X
 Fiche: 50-410, 83/01/25, 8302020117

DOCKETED ITEMS

8302020120 Acceptance review copy of App 2L to Nine Mile Point Unit 2
FSAR, "Population Distribution"
* Niagara Mohawk Power Corp 83/01/25 50pp 24X
Fiche 50-410, 83/01/25, 8302020120

8302020124 Acceptance review copy of Chapter 3 to Nine Mile Point Unit 2
FSAR, "Design of Structures, Components, Equipment & Sys."
* Niagara Mohawk Power Corp 83/01/25 2,200pp 24X
Fiche 50-410, 83/01/25, 8302020124

8302020128 Acceptance review copy of App 3A to Nine Mile Point Unit 2
FSAR, "Computer Programs for Dynamic & Static Analysis of Category 1 Structures, Equipment & Components"
* Niagara Mohawk Power Corp 83/01/25 135pp 24X
Fiche 50-410, 83/01/25, 8302020128

8302020129 Acceptance review copy of App 3B to Nine Mile Point Unit 2
FSAR, "Pressure Analysis for Subcompartments Outside Containment"
* Niagara Mohawk Power Corp 83/01/25 75pp 24X
Fiche 50-410, 83/01/25, 8302020129

8302020133 Acceptance review copy of App 3C to Nine Mile Point Unit 2
FSAR, "Failure Mode Analysis for Pipe Breaks & Cracks"
* Niagara Mohawk Power Corp 83/01/25 8pp 24X
Fiche 50-410, 83/01/25, 8302020133

8302020135 Acceptance review copy of App 3D to Nine Mile Point Unit 2
FSAR, "Method of Panel Frequency Analysis"
* Niagara Mohawk Power Corp 83/01/25 6pp 24X
Fiche 50-410, 83/01/25, 8302020135

8302020138 Acceptance review copy of Chapter 4 to Nine Mile Point Unit 2
FSAR, "Reactor"
* Niagara Mohawk Power Corp 83/01/25 200pp 24X
Fiche 50-410, 83/01/25, 8302020138

8302020140 Acceptance review copy of Chapter 5 to Nine Mile Point Unit 2
FSAR, "RCS & Connected Sys"
* Niagara Mohawk Power Corp 83/01/25 400pp 24X
Fiche 50-410, 83/01/25, 8302020140

8302020143 Acceptance review copy of App 5A to Nine Mile Point Unit 2
FSAR, "Compliance W/10CFR50, App G & App H"
* Niagara Mohawk Power Corp 83/01/25 15pp 24X
Fiche 50-410, 83/01/25, 8302020143

8302020144 Acceptance review copy of Chapter 6 to Nine Mile Point Unit 2
FSAR, "ESFs"
* Niagara Mohawk Power Corp 83/01/25 3,500pp 24X
Fiche 50-410, 83/01/25, 8302020144

8302020149 Acceptance review copy of App 6A to Nine Mile Point Unit 2
FSAR, "Design Assessment Rept for Hydrodynamic Loads"
* Niagara Mohawk Power Corp 83/01/25 400pp 24X
Fiche 50-410, 83/01/25, 8302020149

8302020157 Acceptance review copy of App 6B to Nine Mile Point Unit 2
FSAR, "THREED Subcompartment Analytical Model"
* Niagara Mohawk Power Corp 83/01/25 13pp 24X
Fiche 50-410, 83/01/25, 8302020157

8302020167 Acceptance review copy of Chapter 7 to Nine Mile Point Unit 2
FSAR, "Instrumentation & Controls"
* Niagara Mohawk Power Corp 83/01/25 700pp 24X
Fiche 50-410, 83/01/25, 8302020167

8302020170 Acceptance review copy of Chapter 8 to Nine Mile Point Unit 2
FSAR, "Electric Power"
* Niagara Mohawk Power Corp 83/01/25 1,100pp 24X
Fiche 50-410, 83/01/25, 8302020170

8302020172 Acceptance review copy of Chapter 9 to Nine Mile Point Unit 2
FSAR, "Auxiliary Sys"
* Niagara Mohawk Power Corp 83/01/25 5,400pp 24X
Fiche 50-410, 83/01/25, 8302020172

8302020175 Acceptance review copy of App 9A to Nine Mile Point Unit 2
FSAR, "Fire Protection Program Evaluation Rept (FPPER)"
* Niagara Mohawk Power Corp 83/01/25 400pp 24X
Fiche 50-410, 83/01/25, 8302020175

8302020178 Acceptance review copy of Chapter 10 to Nine Mile Point Unit 2
FSAR, "Steam & Power Conversion Sys"
* Niagara Mohawk Power Corp 83/01/25 1,500pp 24X
Fiche 50-410, 83/01/25, 8302020178

8302020180 Acceptance review copy of Chapter 11 to Nine Mile Point Unit 2
FSAR, "Radwaste Mgt."
* Niagara Mohawk Power Corp 83/01/25 400pp 24X
Fiche 50-410, 83/01/25, 8302020180

8302020183 Acceptance review copy of App 11A to Nine Mile Point Unit 2
FSAR, "Radiological Doses"
* Niagara Mohawk Power Corp 83/01/25 28pp 24X
Fiche 50-410, 83/01/25, 8302020183

8302020186 Acceptance review copy of Chapter 12 to Nine Mile Point Unit 2
FSAR, "Radiation Protection"
* Niagara Mohawk Power Corp 83/01/25 700pp 24X
Fiche 50-410, 83/01/25, 8302020186

8302020189 Acceptance review copy of Chapter 13 to Nine Mile Point Unit 2
FSAR, "Conduct of Operations"
* Niagara Mohawk Power Corp 83/01/25 200pp 24X
Fiche 50-410, 83/01/25, 8302020189

8302020192 Acceptance review copy of App 13A to Nine Mile Point Unit 2
FSAR, "Typical Resumes"
* Niagara Mohawk Power Corp 83/01/25 200pp 24X
Fiche 50-410, 83/01/25, 8302020192

8302020195 Acceptance review copy of App 13B to Nine Mile Point Unit 2
FSAR, "Site Emergency Plan" Plan withheld
* Niagara Mohawk Power Corp 83/01/25 1p 24X
Fiche 50-410, 83/01/25, 8302020195

8302020197 Acceptance review copy of Chapter 14 to Nine Mile Point Unit 2
FSAR, "Initial Test Program"
* Niagara Mohawk Power Corp 83/01/25 450pp 24X
Fiche 50-410, 83/01/25, 8302020197

8302020200 Acceptance review copy of Chapter 15 to Nine Mile Point Unit 2
FSAR, "Accident Analysis"
* Niagara Mohawk Power Corp 83/01/25 300pp 24X
Fiche 50-410, 83/01/25, 8302020200

8302020203 Acceptance review copy of App 15A to Nine Mile Point Unit 2
FSAR, "Plant Nuclear Safety Operational Analysis (NSOA)"
* Niagara Mohawk Power Corp 83/01/25 100pp 24X
Fiche 50-410, 83/01/25, 8302020203

8302020209 Acceptance review copy of Chapter 16 to Nine Mile Point Unit 2
FSAR, "Tech Specs"
* Niagara Mohawk Power Corp 83/01/25 200pp 24X
Fiche 50-410, 83/01/25, 8302020209

8302020211 Acceptance review copy of Chapter 17 to Nine Mile Point Unit 2
FSAR, "QA"
* Niagara Mohawk Power Corp 83/01/25 50pp 24X
Fiche 50-410, 83/01/25, 8302020211

M Antitrust correspondence

8302180346 Forwards "Info for Antitrust Review of DL Application, Nine Mile Point Nuclear Station, Unit 2," per Reg Guide 9.3. Info supplied to submitted to Atty General for antitrust review re license application per 10CFR50, App L
MANGAN, C V Niagara Mohawk Power Corp 83/02/14, DENTON, H. R Office of Nuclear Reactor Regulation, Director 1p 17210.225, 2
Fiche 50-410, 83/02/14, 8302180346

--8302180348 "Info for Antitrust Review of DL Application, Nine Mile Point Nuclear Station, Unit 2"
* Niagara Mohawk Power Corp 83/02/14 36pp 17210.226 24X
Fiche 50-410, 83/02/14, 8302180346

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26, Consolidated Edison Co. of N York, Inc 118pp 17023.160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque HOBC, HIBC, H2BC & H3BC Gearheads," Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28, Consolidated Edison Co. of N York, Inc. 109pp 17144.001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28, Consolidated Edison Co. of N York, Inc 110pp 17074.095 24X Fiche 50-000, 83/01/28, 8212060361

DOCKETED ITEMS

8302090380 Responds to IE Bulletin 80-16 re misapplication of Rosemount transmitters Model 1151 transmitters w/A or D amplifier boards will be replaced w/equivalent transmitter Bulletin not applicable to Model 1152 transmitters
MANNING, S. F. Niagara Mohawk Power Corp 83/01/31 STAROSTECKI, R
Division of Project & Resident Programs 1p 17071 089 24X
Fiche: 50-410, 83/01/31, 8302090380

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp 17347 191 24X Fiche: 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 111pp 17347 058 24X Fiche: 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc. 112pp 17361 148 24X Fiche: 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302090160 Final deficiency rept re ITT Grinnell issue of planner w/o prior approval. Initially reported on 821101 ITT Grinnell committed to route all Category I planners through QC prior to field issuance
MANNING, S. F. Niagara Mohawk Power Corp 83/01/31 STAROSTECKI, R.
Division of Project & Resident Programs 2pp. 17069 360 24X
Fiche: 50-410, 83/01/31, 8302090160

8302090346 Final deficiency rept re enhancement of ITT Grinnell weld radiographs. Initially reported on 821108 Site radiographs isolated to B10430-0715 Welds reradiographed & found acceptable except for one weld
MANNING, S. F. Niagara Mohawk Power Corp. 83/01/31 STAROSTECKI, R.
Division of Project & Resident Programs 3pp. 17070 348 24X
Fiche: 50-410, 83/01/31, 8302090346

8302230331 Final deficiency rept re hydrogen recombiners. Initially reported on 821119 ITT Barton pressure transmitters replaced & disconnect switch eliminated from circuit. Also reported per Part 21
MANNING, C. V. Niagara Mohawk Power Corp 83/02/11 STAROSTECKI, R.
Division of Project & Resident Programs 2pp 17248 130 24X
Fiche: 50-410, 83/02/11, 8302230331

8302230662 Interim deficiency rept re weld radiograph for recirculation piping spool piece. Initially reported on 830113. GE requested to respond to problem. Final rept to be submitted by 830313.
MANNING, C. V. Niagara Mohawk Power Corp 83/02/14 STAROSTECKI, R.
Division of Project & Resident Programs 2pp. 17253 047 24X
Fiche: 50-410, 83/02/14, 8302230662

8302250438 Final deficiency rept re error in QHDSH computer program. Initially reported on 821008 Program revised to correct error
MANNING, C. V. Niagara Mohawk Power Corp. 83/02/15 STAROSTECKI, R.
Region 1, Office of Director. 3pp. 17294 013 24X
Fiche: 50-410, 83/02/15, 8302250438

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D. O. Division of Licensing. 83/01/31 Consolidated Edison Co. of New York, Inc. 14pp. 17347 177 24X
Fiche: 50-000, 83/01/31, 8301310203

8302140074 Responds to Generic Ltr 83-01 re planning for operator licensing.
LEMPDES, T. E. Niagara Mohawk Power Corp. 83/01/31 EISENHUT, D. O.
Division of Licensing. 2pp. 17142 115 24X Fiche: 50-220, 83/01/31, 8302140074

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8302040403 Notifies that NRC caseload forecast panel will visit plant on 830126-28 to obtain info re status of const activities
Agenda encl
KNIGHTON, O. W. Licensing Branch 3 83/01/18 WOOLLEVER, E. J.
Duquesne Light Co 5pp 17042 312 24X Fiche: 50-412, 83/01/18, 8302040403

8302030016 Daily highlight memo Util has submitted FSAR & environ rept for review FSAR acceptance review to be performed by E040, environ rept by NRC General info section of OL application received 821222
LAZO, L. Licensing Branch 3 83/01/26 DENTON, H. R., CASE, E. O., CARTER, J. Office of Nuclear Reactor Regulation, Director. 1p 17041 093 24X Fiche: 50-412, 83/01/26, 8302030016

8302170403 Notification of 830209 meeting w/util in Bethesda, MD to discuss review plan for control room
LAZO, L. Licensing Branch 3 83/02/03 KNIGHTON, O. W. Licensing Branch 3 3pp. 17195 255 24X Fiche: 50-412, 83/02/03, 8302170403

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl.
EISENHUT, D. O. Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc. 11pp 17290 247 24X
Fiche: 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSB re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D. O. Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche: 50-000, 83/02/08, 8302090080

8302170554 Summary of 821115 meeting w/util in Bethesda, MD re initial FSAR submittal
LAZO, L. Licensing Branch 3 DOOLITTLE, E. L. Licensing Branch 1 83/02/08 Licensing Branch 3 4pp. 17197 147 24X
Fiche: 50-412, 83/02/08, 8302170554

F. Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl
EISENHUT, D. O. Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc. 11pp 17221 226 24X
Fiche: 50-000, 83/02/01, 8301210340

G. Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc. 118pp 17023 160 24X Fiche: 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 109pp. 17144 001 24X Fiche: 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc. 110pp 17074 095 24X Fiche: 50-000, 83/01/28, 8212060361

8302100329 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetration assemblies not used at facility nor planned for installation
WOOLLEVER, E. J. Duquesne Light Co 83/01/28 HAYNES, R. C. Region 1, Office of Director. 2pp. 17110 093 24X Fiche: 50-412, 83/01/28, 8302100329

8302140199 Notification 83-09 of 830215 meeting w/licensee in Shippingport, PA to discuss SALP.
TRIPP, L. E. Division of Project & Resident Programs. 83/02/03 Region 1, Office of Director. 1p. 17143 326 24X
Fiche: 50-412, 83/02/03, 8302140199

DOCKETED ITEMS

201

B302150626 Forwards addl info in response to IE Bulletin 71-111 adopt methods used by Unit 1 for detecting potential flow blockage or degradation due to clams or shell debris
WOOLEVER, E J Duquesne Light Co 83/02/07 JORDAN, E L
17151 326 24X Fiche 50-412.83/02/09.8302150626

B302250336 Forwards IE Insp Rept 50-412/83-02 on B30103-31, noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs
WOOLEVER, E J Duquesne Light Co 2pp 17291 058 24X
Fiche 50-412.83/02/09.8302250336

--B302250343 IE Insp Rept 50-412/83-02 on B30103-31 No violation noted Major areas inspected electrical cable, tray connections, installation of spare penetration covers repairs to piping, site tours & control of contaminants on steels
WALTON, O, GRANT, J, TRIPP, L Division of Project & Resident Programs 83/02/09 11pp 17291 060 24X Fiche 50-412.83/02/09.8302250343

B302280478 Forwards IE Insp Rept 50-412/83-01 on B30103-07 & 08, violation
MARTIN, T T Division of Engineering & Technical Programs
WOOLEVER, E J Duquesne Light Co 2pp 17309 057 24X
Fiche 50-412.83/02/10.8302280478

--B302280482 Notice of Violation from insp on B30103-07
Division of Engineering & Technical Programs 83/02/10 1p
17309 089 24X Fiche 50-412.83/02/10.8302280482

--B302280488 IE Insp Rept 50-412/83-01 on B30103-07 Noncompliance re use of stainless steel weld procedure for welding on Inconel
GRAY, E H Division of Engineering & Technical Programs
Region 1, Office of Director 83/02/08 5pp 17309 070 24X
Fiche 50-412.83/02/10.8302280488

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Unit Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000.83/02/18.830212060363

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposal of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000.83/02/24.830212060365

B212060366 IE Info Notice 83-06, "Nonsidentical Replacement Parts Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000.83/02/24.830212060366

S Reportable occurrences, LERs & related correspondence

B302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by B30218
EMPEY, D C, Rockwell International Corp 82/12/17 COLLINS, J
Region 4, Office of Director App 17006 128 24X
Fiche 50-000.82/12/17.8302030495

B302250385 Interim Significant Deficiency Rept 83-01 re Westinghouse gate valve position indication Initially reported on B30112 Westinghouse conducting plant-specific review Results of review will be submitted by B30403
WOOLEVER, E J Duquesne Light Co 83/02/11 HAYNES, R C Region 1
Office of Director App 17297 219 24X Fiche 50-412.83/02/11.8302250385

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NES vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000.83/01/31.8301310203

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

DOCKETED ITEMS

D NRC Draft/Final Environmental Statements, suppl's & correspondence

8302230390 Informs that FES reviewed Document adequate in describing environ impact of plant
MOORE, S N Environmental Protection Agency 83/02/17 JABBOUR, K N
Division of Licensing 1p 17247 047 24X Fiche 50-413, 83/02/17,
8302230390

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8302010056 Forwards preliminary draft SER for power sys Comments,
including schedules for completion of further analyses or
other work associated w/resolution of open items, requested
within 2 wks of ltr receipt
NOVAK, T M Assistant Director for Licensing 83/01/24 TUCKER, H B
Duke Power Co 62pp 16990 240 24X Fiche 50-413, 83/01/24,
8302010056

8302100507 Disavows any knowledge of differing technical opinions on
part of reviewers involved in SER
MIRAGLIA, F J Assistant Director for Safety Assessment 83/02/07
NOVAK, T M Assistant Director for Licensing 1p 17143 262 24X
Fiche 50-413, 83/02/07, 8302100507

8302280007 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA
NUCLEAR STATION, UNITS 1 AND 2 Docket Nos 50-413 And 50-414
(Duke Power Company, et al)
* Office of Nuclear Reactor Regulation, Director NUREG-0954
83/02/28 556pp Available at NRC \$12 00 17318 001 24X
Fiche 50-413, 83/02/28, 8302280007

F Security, medical, emergency & fire protection plans

8302070351 Forwards Rev 2 to safeguards contingency plan changing
position titles Rev withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 83/01/25 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 17029 217 24X
Fiche 50-413, 83/01/25, 8302070351

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302180399 Forwards "Sys Description for Radio Controlled Prompt Alert
& Notification Sys for Catawba Nuclear Station," in response
to NRC 810723 request for schedule for installation of
public notification sys
TUCKER, H B Duke Power Co 83/02/10 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch
4 NENTON, F Federal Emergency Management Agency 2pp 17214 311
24X Fiche 50-413, 83/02/10, 8302180399

--8302180402 'Sys Description for Radio Controlled Prompt Alert &
Notification Sys for Catawba Nuclear Station' W/two
oversize maps Aperture cards are available in PDR
* Duke Power Co EL40101Y 83/02/10 24pp 17214 313 24X
Fiche 50-413, 83/02/10, 8302180399

8302280037 Forwards plans for complying w/guidance for emergency
response facilities per NUREG-0696 Plans part of more
extensive overall emergency planning under implementation
since Sept 1979
TUCKER, H B Duke Power Co 83/02/15 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch
4 6pp 17307 176 24X Fiche 50-413, 83/02/15, 8302280037

8302280199 Forwards sys description for proposed upgrade to
meteorological sys including Class A model Upgrade will
be completed by fuel load
TUCKER, H B Duke Power Co 83/02/21, DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch
4 8pp 17312 163 24X Fiche 50-413, 83/02/21, 8302280199

G Adjudicatory correspondence

8302010070 Forwards P 2 of NRC responses to Palmetto Alliance third set
of interrogatories & requests to produce, inadvertently
omitted from original answer
JOHNSON, G E Hearing Branch 4 83/01/28 GUILD, R Palmetto
Alliance 1p 16974 087 24X Fiche 50-413, 83/01/28, 8302010070

--8302010074 P 2 of NRC responses to third set of interrogatories &
requests to produce, inadvertently omitted from original
answer
* NRC - No Detailed Affiliation Given. 83/01/28 Palmetto
Alliance 1p 16974 088, 24X Fiche 50-413, 83/01/28, 8302010070

8302010610 Motion to compel discovery from util re util 821231
inadequate responses to interrogatories & requests to
produce on Contentions 6, 7 & 44 Suppl's & renews 821002 &
1103 motions W/Certificate of Svc Related correspondence
GUILD, R Palmetto Alliance GUILD, R Guild, R 83/01/28
Atomic Safety and Licensing Board Panel 28pp 16980 223 24X
Fiche 50-413, 83/01/28, 8302010610

8302070561 Memorandum & order denying Palmetto Alliance & Carolina
Environ Study Group 821220 joint motion for reconsideration,
or alternatively, for certification Adopts applicant proposed
schedule as revised
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/02
Palmetto Alliance 13pp 17034 241 24X Fiche 50-413, 83/02/02,
8302070561

8302070548 Forwards ASLB 830202 memorandum & order denying motion for
reconsideration of rulings rejecting contentions based on
DES as untimely Order may be relevant to pending review of
ALAB-687 W/o encl
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/03
MALECH, M O Office of the General Counsel 1p 17034 111 24X
Fiche 50-413, 83/02/03, 8302070548

8302100267 Advises that NRC will not file reply brief to applicant &
Palmetto Alliance initial briefs file per Commission 821223
order determining to review ALAB-687 sua sponte NRC position
fully presented in initial brief
JOHNSON, G E Hearing Branch 4 83/02/09 CHILK, S J Office of the
Secretary of the Commission 1p 17110 123 24X
Fiche 50-413, 83/02/09, 8302100267

8302140145 Memorandum & order ruling on util motions to compel
discovery of Palmetto Alliance
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/09
Duke Power Co 14pp 17140 089 24X Fiche 50-413, 83/02/09,
8302140145

8302150485 Requests that listed documents be sent to LPDR in Rock Hill,
SC for insp & copying Documents responsive to portions of
Palmetto Alliance first set of interrogatories & requests to
produce W/o encl
JOHNSON, G E Hearing Branch 4 83/02/10 SQUEDER, J Public
Document Branch 2pp 17156 299 24X Fiche 50-413, 83/02/10,
8302150485

8302160399 Amicus curiae brief on whether law requires ASLB to give
controlling weight to good cause factor in determining
admission of late-filed contention & on what constitutes
good cause for late filing Certificate of Svc encl
COWAN, B Z Atomic Industrial Forum 83/02/11 Commissioners
13pp 17169 204 24X Fiche 50-413, 83/02/11, 8302160399

8302170305 Amicus curiae brief re controlling weight of good-cause
factor when late-filed contention submitted based solely on
prior unavailability of licensing document Certificate of Svc encl
RASKIN, D B Florida Power & Light Co RASKIN, D B Houston Lighting
& Power Co RASKIN, D B Iowa Electric Light & Power Co 83/02/11
Commissioners, 19pp, 17177 029 24X Fiche 50-413, 83/02/11,
8302170305

8302170228 Advises of decision not to file reply brief to Palmetto
Alliance & NRC briefs filed per ALAB-687 Alliance request
for oral argument opposed Alliance brief provides no
meaningful argument & is of no value in appellate review
MCGARRY, J M Debevoise & Liberman MCGARRY, J M Duke Power Co
83/02/14 CHILK, S J Office of the Secretary of the Commission
2pp 17187 105 24X Fiche 50-413, 83/02/14, 8302170228

8302170307 Motion to file amicus curiae brief out of time Extension
needed due to blizzard
JORDAN, W S Union of Concerned Scientists JORDAN, W S Harmon &
Weiss 83/02/14 Commissioners 2pp 17177 008 24X
Fiche 50-413, 83/02/14, 8302170307

--8302170312 Amicus curiae brief in response to Commission questions re
circumstances under which institutional unavailability of
info justifies admission of late-filed contentions
Certificate of Svc encl
WEISS, E R, JORDAN, W S Union of Concerned Scientists WEISS, E R
Harmon & Weiss 83/02/14 Commissioners 19pp 17177 010
24X Fiche 50-413, 83/02/14, 8302170307

8302180328 Supplemental response to interrogatories & production
requests on Contentions 6 & 7 Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 83/02/17 Prairie Alliance
37pp 17213 305 24X Fiche 50-413, 83/02/17, 8302180328

8302240276 Forwards SER W/o encl 83/02/23 KELLEY, J L, FOSTER, R F,
JOHNSON, G E Hearing Branch 4 83/02/23 CALLIHAN, D Atomic Safety and Licensing Board Panel 1p
17274 187 24X Fiche 50-413, 83/02/23, 8302240276

DOCKETED ITEMS

K Utility Final Safety Analysis Report (FSAR) & amends

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FSAR
TUCKER, H B Duke Power Co 83/02/22 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 2pp 17269 001 24X Fiche 50-413, 83/02/22, 8302240208

--8302240210 Rev 7 to FSAR W/134 oversize P&IDs Aperture cards are
available in PDR
* Duke Power Co 83/02/22 866pp 17269 003 24X
Fiche 50-413, 83/02/22, 8302240208

M Antitrust correspondence

8302040180 Confirms telcons & ack receipt of counsel 830106 ltr to
util requesting transmission svcs for Carrasan Power Co
VOGLER, B H Hearing Branch 2 83/02/03 WENNER, A Van Ness,
Feldman, Sutcliffe, Curtis & Levenberg 1p 17021 330 24X
Fiche 50-413, 83/02/03, 8302040180

Q Inspection reports, IE Bulletins & correspondence

8302150636 Forwards IE Insp Repts 50-413/82-32 & 50-414/82-30 on
821126-1225 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/07
TUCKER, H B Duke Power Co 2pp 17154 126 24X
Fiche 50-413, 83/01/07, 8302150636

--8302150645 IE Insp Repts 50-413/82-32 & 50-414/82-30 on 821126-1225 No
noncompliance noted Major areas inspected review of
nonconforming items, followup of licensee & NRC identified
items & followup of IE bulletins & circulars
VANODORN, P K, BRYANT, J C Division of Project & Resident
Programs 83/01/07 3pp 17154 128 24X Fiche 50-413, 83/01/07,
8302150636

8302150130 Forwards IE Insp Repts 50-413/82-31 & 50-414/82-29 on
821228-30 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/24
TUCKER, H B Duke Power Co 2pp 17148 002 24X
Fiche 50-413, 83/01/24, 8302150130

--8302150140 IE Insp Repts 50-413/82-31 & 50-414/82-29 on 821228-30 No
noncompliance noted Major areas inspected IE Bulletin 79-02
& licensee identified items
LENAHAN, J J, CONLON, T E Division of Project & Resident Programs
83/01/19 7pp 17148 004 24X Fiche 50-413, 83/01/24, 8302150130

8302150219 Responds to IE Bulletin 82-04 re Bunker-Ramo electrical
penetrations No subj equipment installed or planned to be
installed at plants
TUCKER, H B Duke Power Co 83/01/24 O'REILLY, J P Region 2,
Office of Director 1p 17150 034 24X Fiche 50-413, 83/01/24,
8302150219

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150259 Ack receipt of IE Insp Repts 50-413/82-32 & 50-414/82-30
No proprietary info
TUCKER, H B Duke Power Co 83/02/04 O'REILLY, J P Region 2,
Office of Director 1p 17148 333 24X Fiche 50-413, 83/02/04,
8302150259

8212060363 IE Info Notice 83-04, "Failure of Elms Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058, 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302030467 Part 21 rept re defective ASME III-3 butterfly valves
supplied to Facility Defect consists of mathematical error
in seismic rept resulting in undersized actuator mounting
plate Inadequate mounting plates will be replaced
RICAPITO, R, LIDDLE, A H General Signal Corp 83/01/07
Director's Office, Office of Inspection and Enforcement 4pp
17006 157 24X Fiche 50-413, 83/01/07, 8302030467

8302030432 Significant Deficiency Rept SD 413-414/82-27 re cracked cel
containers in Transamerica Delaval diesel generator
batteries Initially reported on 821230 Sample of damaged
cells returned to manufacturer Final rept by 830601
TUCKER, H B Duke Power Co 83/01/26 O'REILLY, J P Region 2,
Office of Director 3pp 17005 141 24X Fiche 50-413, 83/01/26,
8302030432

8302280170 Significant Deficiency Rept SD 413-414/83-01 re undersized
valve electric operator mounting plates Initially reported
on 830112 Vendor will provide qualified 3/4-inch actuator
support plates Also reportable per Part 21
TUCKER, H B Duke Power Co 83/02/11 O'REILLY, J P Region 2,
Office of Director 2pp 17306 032 24X Fiche 50-413, 83/02/11,
8302280170

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for CLS, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302240068 Responds to Generic Ltr 83-01 Operator licensing exam
schedules listed
TUCKER, H B Duke Power Co 83/02/21 EISENHUT, D O Division of
Licensing 2pp 17281 041 24X Fiche 50-000, 83/02/21, 8302240068

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302010639 Advises that target fuel load date for Unit 1 is May 1984
TUCKER, H B Duke Power Co 83/01/26 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 2pp 16980 064 24X Fiche 50-413, 83/01/26, 8302010639

8302080174 Clarifies util plans for training for mitigating core
damage & for cold license certification program per TH1
Action Item 11 B 4
TUCKER, H B Duke Power Co 83/01/31 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch
4 4pp 17058 340 24X Fiche 50-413, 83/01/31, 8302080174

8302100512 Board Notification 83-11 forwards info indicating onset of
increased turbulence & acceleration of tube wear occurring
at feed flow rates of 50% for Model D/2 & D/3 steam
generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic
Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utilte Generating
SC Electric & Oas Co, Westinghouse, TVA & representatives of
Swedish nuclear power plant & Krsko in Bethesda, MD re
accelerated tube wear on Model D steam generators
CHESTNUT, B H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03,
8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

DOCKETED ITEMS

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSB re resolution of TH1 Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20 will be forwarded in Apr 1983
ELLIOTT, J L Duke Power Co 83/02/18 BIRKEL, R Office of Nuclear Reactor Regulation, Director 2pp 17296 215 24X Fiche 50-000, 83/02/18, 8302250391

--8302250400 Rev QA to Nuclear Guide 1 61, "Damping Values for Seismic Design of Nuclear Power Plants"
* Duke Power Co 83/01/06 7pp 17296 217 24X Fiche 50-000, 83/02/18, 8302250391

--8302250406 Rev 19 to Nuclear Guide 1 84, "Design & Fabrication Code Case Acceptability, ASME Section III, Div 1"
WYKE, T F Duke Power Co 83/01/06 12pp 17296 224 24X Fiche 50-000, 83/02/18, 8302250391

--8302250411 Rev 19 to Nuclear Guide 1 85, "Matls Code Case Acceptability, ASME Section III, Div 1"
WYKE, T F Duke Power Co 83/01/06 11pp 17296 237 24X Fiche 50-000, 83/02/18, 8302250391

--8302250417 Rev 1A to Nuclear Guide 1 111, "Methods for Estimating Atmospheric Transport & Dispersion of Gaseous Effluents in Routine Releases from Light-Water-Cooled Reactors"
EQMONDS, R F Duke Power Co 83/01/06 49pp 17296 248 24X Fiche 50-000, 83/02/18, 8302250391

--8302250424 Rev 1A to Nuclear Guide 1 143, "Design Guidance for Radwaste Mgt Sys, Structures & Components Installed in Light-Water-Cooled Nuclear Power Plants"
MILLER, R E Duke Power Co 83/01/06 14pp 17296 297 24X Fiche 50-000, 83/02/18, 8302250391

--8302250436 Rev 1 to Nuclear Guide 1 147, "Inservice Insp Code Case Acceptability, ASME Section XI, Div 1"
DALTON, D H Duke Power Co 83/01/06 7pp 17296 311 24X Fiche 50-000, 83/02/18, 8302250391

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FBAR
TUCKER, H B Duke Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17269 001 24X Fiche 50-413, 83/02/22, 8302240208

D NRC Draft/Final Environmental Statements, supplis & correspondence

8302230390 Informs that FES reviewed Document adequate in describing environ impact of plant
MOORE, S N Environmental Protection Agency 83/02/17 JABBOUR, K N Division of Licensing 1p 17247 047 24X Fiche 50-413, 83/02/17, 8302230390

E NRC Safety Evaluation Report (SER), supplis & correspondence

8302010056 Forwards preliminary draft SER for power sys Comments, including schedules for completion of further analyses or other work associated w/resolution of open items, requested within 2 wks of ltr receipt
NOVAK, T M Assistant Director for Licensing 83/01/24, TUCKER, H B Duke Power Co, 62pp, 16990 240 24X Fiche 50-413, 83/01/24, 8302010056

8302100507 Disavows any knowledge of differing technical opinions on part of reviewers involved in SER
MIRAGLIA, F J Assistant Director for Safety Assessment 83/02/07 NOVAK, T M Assistant Director for Licensing 1p 17143 262 24X Fiche 50-413, 83/02/07, 8302100507

LATED TO THE OPERATION OF CATAWBA
Nos 50-413 And 50-414

irector NUREG-0954
DO 17318 001 24X

ction plans

ingency plan changing
21)
YTON, H R Office of
17029 217 24X

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co or New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302180399 Forwards "Sys Description for Radio Controlled Prompt Alert & Notification Sys for Catawba Nuclear Station," in response to NRC 810723 request for schedule for installation of public notification sys
TUCKER, H B Duke Power Co 83/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 NEWTON, F Federal Emergency Management Agency 2pp 17214 311 24X Fiche 50-413, 83/02/10, 8302180399

--8302180402 "Sys Description for Radio Controlled Prompt Alert & Notification Sys for Catawba Nuclear Station" w/two oversize maps Aperture cards are available in PDR
* Duke Power Co EL40101Y 83/02/10 24pp 17214 313 24X Fiche 50-413, 83/02/10, 8302180399

8302280037 Forwards plans for complying w/guidance for emergency response facilities per NUREG-0696 Plans part of more extensive overall emergency planning under implementation since Sept 1979
TUCKER, H B Duke Power Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 6pp 17307 176 24X Fiche 50-413, 83/02/15, 8302280037

8302280199 Forwards sys description for proposed upgrade to meteorological sys including Class A model Upgrade will be completed by fuel load
TUCKER, H B Duke Power Co 83/02/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 8pp 17312 163 24X Fiche 50-413, 83/02/21, 8302280199

G Adjudicatory correspondence

8302010070 Forwards P 2 of NRC responses to Palmetto Alliance third set of interrogatories & requests to produce, inadvertently omitted from original answer
JOHNSON, G Hearing Branch 4 83/01/28 GUILD, R Palmetto Alliance 1p 16974 087 24X Fiche 50-413, 83/01/28, 8302010070

--8302010074 P 2 of NRC responses to third set of interrogatories & requests to produce, inadvertently omitted from original answer
* NRC - No Detailed Affiliation Given 83/01/28 Palmetto Alliance 1p 16974 088 24X Fiche 50-413, 83/01/28, 8302010070

8302010610 Motion to compel discovery from util re util 821231 inadequate responses to interrogatories & requests to produce on Contentions 6, 7 & 44 Supplis & renewals 821002 & 1103 motions w/Certificate of Svc Related correspondence
GUILD, R Palmetto Alliance GUILD, R Guild, R 83/01/28 Atomic Safety and Licensing Board Panel 28pp 16980 223 24X Fiche 50-413, 83/01/28, 8302010610

8302070561 Memorandum & order denying Palmetto Alliance & Carolina Environ Study Group 821220 joint motion for reconsideration, or alternatively, for certification Adopts applicant proposed schedule as revised
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/02 Palmetto Alliance 13pp 17034 241 24X Fiche 50-413, 83/02/02, 8302070561

8302070548 Forwards A5L8 830202 memorandum & order denying motion for reconsideration of rulings rejecting contentions based on DES as untimely Order may be relevant to pending review of ALAB-687 w/o encl
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/03 MALACHUK, M O Office of the General Counsel 1p 17034 111 24X Fiche 50-413, 83/02/03, 8302070548

8302100267 Advises that NRC will not file reply brief to applicant & Palmetto Alliance initial briefs file per Commission 821223 order determining to review ALAB-687 sua sponte NRC position fully presented in initial brief
JOHNSON, G E Hearing Branch 4 83/02/09 CHILK, S J Office of the Secretary of the Commission 1p 17110 123 24X Fiche 50-413, 83/02/09, 8302100267

8302140145 Memorandum & order ruling on util motions to compel discovery of Palmetto Alliance
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/09 Duke Power Co 14pp 17140 087 24X Fiche 50-413, 83/02/09, 8302140145

DOCKETED ITEMS

8302150495 Requests that listed documents be sent to LPDR in Rock Hill, SC for insp & copying Documents responsive to portions of Palmetto Alliance first set of interrogatories & requests to produce W/o encl
JOHNSON, G E Hearing Branch 4 83/02/10 SQUEDER, J Public Document Branch 2pp 17156 299 24X Fiche 50-413, 83/02/10, 8302150495

8302160359 Amicus curiae brief on whether law requires ASLB to give controlling weight to good cause factor in determining admission of late-filed contention & on what constitutes good cause for late filing Certificate of Svc encl
COHAN, B Z Atomic Industrial Forum 83/02/11 Commissioners 19pp 17169 204 24X Fiche 50-413, 83/02/11, 8302160359

8302170305 Amicus curiae brief re controlling weight of good-cause factor when late-filed contention submitted based solely on prior unavailability of licensing document Certificate of Svc encl
RASKIN, D B Florida Power & Light Co RASKIN, D B Houston Lighting & Power Co RASKIN, D B Iowa Electric Light & Power Co 83/02/11 Commissioners 19pp 17177 029 24X Fiche 50-413, 83/02/11, 8302170305

8302170228 Advises of decision not to file reply brief to Palmetto Alliance & NRC briefs filed per ALAB-687 Alliance request for oral argument opposed Alliance brief provides no meaningful argument & is of no value in appellate review
MCGARRY, J M Debevoise & Liberman MCGARRY, J M Duke Power Co 83/02/14 CHILK, S J Office of the Secretary of the Commission 2pp 17187 105 24X Fiche 50-413, 83/02/14, 8302170228

8302170307 Motion to file amicus curiae brief out of time Extension needed due to blizzard
JORDAN, W S Union of Concerned Scientists JORDAN, W S Harman & Weiss 83/02/14 Commissioners 2pp 17177.00B 24X Fiche 50-413, 83/02/14, 8302170307

--8302170312 Amicus curiae brief in response to Commission questions re circumstances under which institutional unavailability of info justifies admission of late-filed contentions Certificate of Svc encl
WEISS, E R JORDAN, W S Union of Concerned Scientists WEISS, E R Harman & Weiss 83/02/14 Commissioners 19pp 17177 010 24X Fiche 50-413, 83/02/14, 8302170307

8302180328 Supplemental response to interrogatories & production requests on Contentions 6 & 7 Certificate of Svc encl
JOHNSON, G E Hearing Branch 4 83/02/17 Prairie Alliance 37pp 17213 305 24X Fiche 50-413, 83/02/17, 8302180328

8302240276 Forwards SER W/o encl
JOHNSON, G E Hearing Branch 4 83/02/23 KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 1p 17274 187 24X Fiche 50-413, 83/02/23, 8302240276

K Utility Final Safety Analysis Report (FSAR) & amends

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FSAR
TUCKER, H B Duke Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 4 2pp 17269 001 24X Fiche 50-413, 83/02/22, 8302240208

--8302240210 Rev 7 to FSAR W/134 oversize P&IDs Aperture cards are available in PDR
4 Duke Power Co 83/02/22 866pp 17269 003 24X Fiche 50-413, 83/02/22, 8302240208

G Inspection reports, IE Bulletins & correspondence

8302150636 Forwards IE Insp Repts 50-413/82-32 & 50-414/82-30 on 821126-1225 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/07 TUCKER, H B Duke Power Co 2pp 17154 126 24X Fiche 50-413, 83/01/07, 8302150636

--8302150645 IE Insp Repts 50-413/82-32 & 50-414/82-30 on 821126-1225 No noncompliance noted Major areas inspected review of nonconforming items, followup of licenses & NRC identified items & followup of IE bulletins & circulars
VANDORRN, P K, BRYANT, J C Division of Project & Resident Programs 83/01/07 5pp 17154 128 24X Fiche 50-413, 83/01/07, 8302150636

8302150130 Forwards IE Insp Repts 50-413/82-31 & 50-414/82-29 on 821228-30 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/01/24 TUCKER, H B Duke Power Co 2pp 17148 002 24X Fiche 50-413, 83/01/24, 8302150130

--8302150140 IE Insp Repts 50-413/82-31 & 50-414/82-29 on 821228-30 No noncompliance noted Major areas inspected IE Bulletin 79-02 & licensees identified items
LENAHAN, J J, CONLON, T E Division of Project & Resident Programs 83/01/19 7pp 17148 004 24X Fiche 50-413, 83/01/24, 8302150130

8302150219 Responds to IE Bulletin 82-04 re Dunter-Ramo electrical penetrations No sub equipment installed or planned to be installed at plants
TUCKER, H B Duke Power Co 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 17150 034 24X Fiche 50-413, 83/01/24, 8302150219

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of NY, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of NY, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060358

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of NY, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060358

8302150259 Act receipt of IE Insp Repts 50-413/82-32 & 50-414/82-30 No proprietary info
TUCKER, H B Duke Power Co 83/02/04 O'REILLY, J P, Region 2, Office of Director 1p 17148 333 24X Fiche 50-413, 83/02/04, 8302150259

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of NY, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060358

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of NY, Inc 113pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060358

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of NY, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060358

S Reportable occurrences, LERs & related correspondence

8302030467 Part 21 rept re defective ASME III-3 butterfly valves supplied to facility Defect consists of mathematical error in seismic rept resulting in undersized actuator mounting plate Inadequate mounting plates will be replaced
RICAPITO, R, LIDDLE, A H General Signal Corp 83/01/07 Director's Office, Office of Inspection and Enforcement, App 17006 197 24X Fiche 50-413, 83/01/07, 8302030467

8302030432 Significant Deficiency Rept BD 413-414/82-27 re cracked c containers in Transamerica Delaval diesel generator batteries Initially reported on 821230 Sample of damaged cells returned to manufacturer Final rept by 830601
TUCKER, H B Duke Power Co 83/01/26 O'REILLY, J P Region 2, Office of Director 3pp 17005 141 24X Fiche 50-413, 83/01/26, 8302030432

8302070353 Interim Deficiency Rept BD 414/82-25 re incomplete penetration on Class 3 butt welds Initially reported on 821122 Caused by Welder 600 Failing to maintain level of quality Welder 600 welds radiographed Full rept by 831001
TUCKER, H B Duke Power Co 83/01/28 O'REILLY, J P, Region 2, Office of Director 2pp 17029 212 24X Fiche 50-414, 83/01/28, 8302070353

8302280170 Significant Deficiency Rept BD 413-414/83-01 re undersized valve electric operator mounting plates Initially reported on 830112 Vendor will provide qualified 3/4-inch actuator support plates Also reportable per Part 21
TUCKER, H B Duke Power Co 83/02/11 O'REILLY, J P, Region 2, Office of Director 2pp 17306 032 24X Fiche 50-413, 83/02/11, 8302280170

DOCKETED ITEMS

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, B301310203

B302240068 Responds to Generic Ltr 83-01 Operator licensing exam schedules listed
TUCKER, H B Duke Power Co 83/02/21 EISENHUT, D O Division of Licensing 2pp 17281 041 24X Fiche 50-000, 83/02/21, B302240068

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B302170482 Board Notification 83-1 forwards BNL draft rept, "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach"
EISENHUT, D O Division of Licensing FIN A-3397 83/02/01
FALLADINO, N J Commissioners 134pp 17203 309 24X
Fiche 50-000, 83/02/01, B302170482

B302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
BAGCHI, Q Equipment Qualification Branch 83/02/02 WOODMAN, V S Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000, 83/02/02, B302170011

--B311170512 Trip rept of 810728-30 site visit to Port Gibson, MS re review of seismic & dynamic qualification methods, procedures & results for selected mechanical & electrical equipment & of field installation to verify equipment modeling
CHAND, T V Equipment Qualification Branch 81/10/22
ROBERTO, Z R Equipment Qualification Branch 57pp 17206 330 24X Fiche 50-000, 83/02/02, B302170011

E NRC Safety Evaluation Report (SER), supplis & correspondence

B302160295 Forwards "Nuclear Environ Qualification Final Rept of Hydrogen Ignitor Assemblies for Grand Gulf Nuclear Station Unit 1," Vol 1 License condition referenced on P 22-5 of SER Suppl 3 removed NUREG-0588 evaluation worksheet encl
DALE, L F Mississippi Power & Light Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17164 331 24X Fiche 50-416, 83/02/14, B302160295

F. Security, medical, emergency & fire protection plans

B302150347 Ack receipt of B30106 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-76
LEWIS, R C Division of Project & Resident Programs 83/01/25
STAMPLEY, N L Mississippi Power & Light Co 1p 17148 152 24X
Fiche 50-416, 83/01/25, B302150347

--B302150351 Responds to NRC 821207 ltr re violations noted in IE Insp Rept 50-416/82-76 Corrective actions equipment clearances independently verified, plant quality insp deviation/mod form generated & security post-instructions revised
MCGAUGHY, J P Mississippi Power & Light Co 83/01/06
O'REILLY, J P Region 2, Office of Director 3pp 17148 153 24X
Fiche 50-416, 83/01/25, B302150347

--B302150357 Notice of violation from insp on 821018-1115
* Division of Project & Resident Programs 82/12/07 2pp.
17148 158 24X Fiche 50-416, 83/01/25, B302150347.

--B302150426 IE Insp Rept 50-416/82-76 on 821018-1115 Noncompliance noted failure to follow Administrative Procedures 01-B-06-1, Rev 6; "Protective Tagging Sys," & 12-B-01-B, Rev 8; "Plant Quality Insp," & Emergency Plan Procedure 10-B-01-16, Rev 1
WAGNER, A O, SCOTT, D E, CANTRELL, F S Division of Project & Resident Programs. 82/12/06 8pp 17148 160 24X
Fiche 50-416, 83/01/25, B302150347

B302150274 Ack receipt of B30105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-69
VERRELLI, D M Division of Project & Resident Programs 83/01/26
STAMPLEY, N L Mississippi Power & Light Co 1p 17148 271 24X
Fiche 50-416, 83/01/26, B302150274.

--B302150284 Responds to NRC 821126 ltr re violations noted in IE Insp Rept 50-416/82-69 Corrective actions fire rated hatch cover installed & sealed, open fire doors closed & signs will be posted for fire door placement
MCGAUGHY, J P Mississippi Power & Light Co 83/01/05
O'REILLY, J P Region 2, Office of Director 4pp 17148 272 24X
Fiche 50-416, 83/01/26, B302150274

--B302150272 Forwards IE Insp Rept 50-416/82-69 on 821101-04 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 82/11/26
STAMPLEY, N L Mississippi Power & Light Co 2pp 17148 276 24X
Fiche 50-416, 83/01/26, B302150274

--B302150277 Notice of violation from insp on 821101-04
* Division of Project & Resident Programs 82/11/26 2pp
17148 278 24X Fiche 50-416, 83/01/26, B302150274

--B302150303 IE Insp Rept 50-416/82-69 on 821101-04 Noncompliance noted failure to implement Tech Spec requirements for fire rated assemblies & barriers & failure to establish & implement procedures for fire protection program
MILLER, W H, CONLON, T E Division of Engineering & Radiological Safety Programs 82/11/23 8pp 17148 280 24X
Fiche 50-416, 83/01/26, B302150274

B302010508 Responds to NRC 821122 comments on 820922 Physical Security Plan, Rev 5 Addl justification addressing NRC concern w/ Section 6 & 2 2 will be provided by B30228 Clarification of Section 3 & 5 will be included in Rev 7
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16978 080 24X Fiche 50-416, 83/01/28, B302010508

B301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340

P Operating license stage documents & correspondence

B302010528 Informs that detailed review in progress addressing listed issues to support util position of initiating containment sprays at same time as hydrogen igniter sys when reactor core level reaches top of active fuel, per NRC request
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16977 244 24X Fiche 50-416, 83/01/28, B302010528

B302030103 Advises that NRC review of certain applications for license amendments revealed outstanding balance due Remittance requested
MILLER, W O License Fee Management Branch 83/01/28 MCGAUGHY, J P Mississippi Power & Light Co 1p 17028 336 24X
Fiche 50-416, 83/01/28, B302030103

B302030181 Requests approval by B30218 of proposed rev to FSAR Subsection 1B 1.4, in response to NUREG-0737, Item 1 A 2 1, "Upgrading Reactor Operator & Senior Reactor Operator Training & Qualifications"
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17004 229 24X Fiche 50-416, 83/01/28, B302030181

B302040426 Requests provisions of proposed OL Condition Item 2 C(42)1 be extended to include reinstallation of vibration monitoring equipment Responses to request for addl info re protective sleeves for local power range monitors encl
DALE, L F Mississippi Power & Light Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17017 328 24X Fiche 50-416, 83/02/02, B302040426

B302160139 Forwards Amend 6 to License NPF-13, safety evaluation & notice of issuance & availability Amend changes license conditions re schedule for submitting info on proposed mods to automatic depressurization sys logic
SCIMENCER, A Licensing Branch 2 83/02/07 MCGAUGHY, J P Mississippi Power & Light Co 2pp 17174 017 24X
Fiche 50-416, 83/02/07, B302160139

--B302160144 Amend 6 to License NPF-13, changing license conditions re schedule for submitting info on proposed mods to automatic depressurization sys logic & Tech Spec exception for Phase 1 operation
EISENHUT, D O Division of Licensing 83/02/07 3pp 17174 019 24X Fiche 50-416, 83/02/07, B302160139

--B302160146 Safety evaluation supporting Amend 6 to License NPF-13
* Office of Nuclear Reactor Regulation, Director 83/02/07 4pp
17174 022 24X Fiche 50-416, 83/02/07, B302160139

DOCKETED ITEMS

307

--B302160150 Notice of issuance & availability of Amend 6 to License
HPF-13
SCHWENCER, A Licensing Branch 2 83/02/07 3pp 17174 026 24X
Fiche 50-416, 83/02/07, B302160139

B302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

B302080301 Generic Ltr 83-05 to BWR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re SER of
"Emergency Procedure Guidelines, Rev 2," NEDO-24934, June
1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, B302080301

B302080304 Generic Ltr 83-11 to all operating reactor licensees re
licensee qualification for performing safety analysis in
support of licensing actions Ability to use code must be
demonstrated by vendor or licensee Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 9pp 17234 234 24X
Fiche 50-000, 83/02/08, B302080304

B302160295 Forwards "Nuclear Environ Qualification Final Rept of
Hydrogen Ignitor Assemblies for Grand Gulf Nuclear Station
Unit 1," Vol 1 License condition referenced on P 22-5 of
SER Suppl 3 removed NUREG-0588 evaluation worksheet encl
DALE, L F Mississippi Power & Light Co 83/02/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 17164 331
24X Fiche 50-416, 83/02/14, B302160275

--B302160300 "Nuclear Environ Qualification Final Rept of Hydrogen
Ignitor Assemblies for Grand Gulf Nuclear Station Unit 1,"
Vol 1 Ignitor Assemblies fully qualified per IEEE 323-1974
GREENWOOD, D D, HATMAKER, D F, YOH, J R Corporate Consulting &
Development Co, Ltd A-516-82 Vol 1 82/11/12 569pp 17164 335
24X Fiche 50-416, 83/02/14, B302160295

G Inspection reports, IE Bulletins & correspondence

B302150347 Ack receipt of B30106 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-416/82-76
LEWIS, R C Division of Project & Resident Programs 83/01/25
STAMPLEY, N L Mississippi Power & Light Co 1p 17148 152 24X
Fiche 50-416, 83/01/25, B302150347

--B302150351 Responds to NRC 821207 ltr re violations noted in IE Insp
Rept 50-416/82-76 Corrective actions equipment clearances
independently verified, plant quality insp deviation/mod form
generated & security post-instructions revised
MCQUAGHY, J P Mississippi Power & Light Co 83/01/06
O'REILLY, J P Region 2, Office of Director 3pp 17148 153 24X
Fiche 50-416, 83/01/25, B302150347

--B302150354 Forwards IE Insp Rept 50-416/82-76 on 821018-1115 & notice
of violation
LEWIS, R C Division of Project & Resident Programs 82/12/07
STAMPLEY, N L Mississippi Power & Light Co 2pp 17148 156 24X
Fiche 50-416, 83/01/25, B302150347

--B302150357 Notice of violation from insp on 821018-1115
* Division of Project & Resident Programs 82/12/07 2pp
17148 158 24X Fiche 50-416, 83/01/25, B302150347

--B302150426 IE Insp Rept 50-416/82-76 on 821018-1115 Noncompliance
noted failure to follow Administrative Procedures 01-8-06-1,
Rev 6, "Protective Tagging Sys," & 12-S-01-8, Rev B, "Plant
Quality Insp," & Emergency Plan Procedure 10-S-01-16, Rev 1
WAGNER, A G, SCOTT, D E, CANTRELL, F S Division of Project &
Resident Programs 82/12/06 8pp 17148 160 24X
Fiche 50-416, 83/01/25, B302150347

B302160358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B302150274 Ack receipt of B30105 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-416/82-69
VERRELLI, D M Division of Project & Resident Programs 83/01/26
STAMPLEY, N L Mississippi Power & Light Co 1p 17148 271 24X
Fiche 50-416, 83/01/26, B302150274

--B302150286 Responds to NRC 821126 ltr re violations noted in IE Insp
Rept 50-416/82-69 Corrective actions fire rated hatch cover
installed & sealed, open fire doors closed & signs will be
posted for fire door placement
MCQUAGHY, J P Mississippi Power & Light Co 83/01/05
O'REILLY, J P Region 2, Office of Director 4pp 17148 272 24X
Fiche 50-416, 83/01/26, B302150274

--B302150292 Forwards IE Insp Rept 50-416/82-69 on 821101-04 & notice
of violation
VERRELLI, D M Division of Project & Resident Programs 82/11/26
STAMPLEY, N L Mississippi Power & Light Co 2pp 17148 276 24X
Fiche 50-416, 83/01/26, B302150274

--B302150297 Notice of violation from insp on 821101-04
* Division of Project & Resident Programs 82/11/26 2pp
17148 278 24X Fiche 50-416, 83/01/26, B302150274

--B302150303 IE Insp Rept 50-416/82-69 on 821101-04 Noncompliance
noted failure to implement Tech Spec requirements for fire
rated assemblies & barriers & failure to establish &
implement procedures for fire protection program
MILLER, W H, CONLON, T E Division of Engineering & Radiological
Safety Programs 82/11/23 8pp 17148 280 24X
Fiche 50-416, 83/01/26, B302150274

B302160360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B302160361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

B302030554 Forwards responses to NRC informal questions re IE
Bulletin 80-11, "Masonry Walls " All load combinations in
design criteria, including OBE, SSE & tornado
depressurization, addressed
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 52pp 17006 232
24X Fiche 50-416, 83/01/28, B302030554

B302160363 IE Info Notice 83-04, "Failure of Elma Power Supply Units, "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B302160365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 059 24X Fiche 50-000, 83/02/24, B212060365

B302160366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

R Periodic operating reports & related correspondence

B302230232 Forwards monthly operating rept for Jan 1983
MCQUAGHY, J P Mississippi Power & Light Co 83/02/15 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
17245 129 24X Fiche 50-416, 83/02/15, B302230232

--B302230235 Monthly operating rept for Jan 1983
RICHARDSON, J D Mississippi Power & Light Co 83/02/11 6pp
17245 129 24X Fiche 50-416, 83/02/15, B302230232

S Reportable occurrences, LERs & related correspondence

B302150148 Final deficiency rept re corroded terminal boards on
Rosemount pressure, flow & level transmitters in safety-
related applications initially reported on 820421 Maint
work orders issued to restore transmitters to design specs
MCQUAGHY, J P Mississippi Power & Light Co 82/02/02
O'REILLY, J P Region 2, Office of Director 4pp 17147 254 24X
Fiche 50-416, 82/02/02, B302150148

DOCKETED ITEMS

8212140330 Part 21 rept re problem w/Brown Boveri Electric, Inc low voltage circuit breakers w/solid state trip devices Units from San Onofre 2 & 3 failed due to long-term degradation of filter capacitor C205 Suspect trip units should be tested DUVAL, D D Brown Boveri Corp (subs Brown Boveri & Co, Ltd) 82/12/10 STELLD, V Director's Office, Office of Inspection and Enforcement 2pp 17023 284 24X Fiche 50-416, 82/12/10, 8212140330

8302010495 Interim deficiency rept re Nelson stud failures on embedded plates Initially reported on 821221 Lab testing of plates in progress Deficiency reported per 10CFR21 for Unit 1 & 10CFR50 33(e) for Unit 2 Final rept expected by 830315 MCGAUGHY, J P Mississippi Power & Light Co 83/01/20 O'REILLY, J P Region 2, Office of Director 4pp 16981.331. 24X Fiche 50-416, 83/01/20, 8302010495

8302010172 Forwards LER 83-004/01T-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 16974 015 24X Fiche 50-416, 83/01/24, 8302010172

--8302010182 LER 83-004/01T-0 on 830110 discovered that control room floor penetration open since 821213 Caused by performance of planned maint work Incident noticed while implementing corrective actions to LER 82-132/01T-0 BYRD, R Mississippi Power & Light Co 83/01/24. Region 2, Office of Director 2pp 16974 016 24X Fiche 50-416, 83/01/24, 8302010172

8302010194 Forwards LER 82-178/99X-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 16974 007. 24X Fiche 50-416, 83/01/24, 8302010194

--8302010200 LER 82-178/99X-0 on 821218, fire barriers found open on control room floor Caused by need to reroute cable through floor Fire watch established FREEMAN, M S Mississippi Power & Light Co 83/01/24. Region 2, Office of Director 1p 16974 008 24X Fiche 50-416, 83/01/24, 8302010194

8302010470 Suppl to 820809 final Part 21 rept for potentially reportable deficiency re relay failure in Div 1 standby diesel generator Magnecraft W89LCPX-12 relay will be replaced since sufficient contacts not available for mod MCGAUGHY, J P Mississippi Power & Light Co 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 16982 044 24X Fiche 50-416, 83/01/24, 8302010470

8302010171 Forwards final LER 82-180/03L-0 MCGAUGHY, J P Mississippi Power & Light Co. 83/01/25 O'REILLY, J P Region 2, Office of Director 1p 16974 018 24X Fiche 50-416, 83/01/25, 8302010171

--8302010181 Final LER 82-180/03L-0 on 821227, isolation valve for hose station in control room replaced due to leaking which pressurized hose Addl hose run to supply backup fire protection Leaking valve replaced by returned to svc FREEMAN, M S Mississippi Power & Light Co 83/01/25 Region 2, Office of Director 1p 16974 019 24X Fiche 50-416, 83/01/25, 8302010171

8302010425 Forwards LER 82-177/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/25 O'REILLY, J P Region 2, Office of Director 1p 16974 255 24X Fiche 50-416, 83/01/25, 8302010425

--8302010427 LER 82-177/03L-0 on 821227, while attempting to start control room air conditioner B, common supply breaker for fan compressor tripped as soon as shut Caused by failed trip unit Unit replaced SPARKS, O L Mississippi Power & Light Co. 83/01/25 Region 2, Office of Director 1p 16974.256 24X Fiche 50-416, 83/01/25, 8302010425

8302010252 Forwards LER 82-181/03L-0. MCGAUGHY, J P Mississippi Power & Light Co. 83/01/27 O'REILLY, J P Region 2, Office of Director 1p. 16974 052 24X Fiche 50-416, 83/01/27, 8302010252

--8302010261 LER 82-181/03L-0 on 821228, two fire rated doors in control bldg blocked open to perform control room pressure test Continuous fire watch established Doors closed & fire watch disbanded upon test completion. FREEMAN, M S Mississippi Power & Light Co 83/01/27 Region 2, Office of Director 1p. 16974.053 24X Fiche 50-416, 83/01/27, 8302010252

8302030100 Forwards LER 82-179/03L-0. MCGAUGHY, J P Mississippi Power & Light Co. 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 17002 088 24X Fiche 50-416, 83/01/27, 8302030100

--8302030106 LER 82-179/03L-0 on 821229, smoke detectors covered during planned maint to prevent false alarms &/or damage Hourly fire watch established Detectors uncovered & returned to svc BAILEY, J P Mississippi Power & Light Co 83/01/28 Region 2, Office of Director 3pp 17002 089 24X Fiche 50-416, 83/01/27, 8302030100

8302030110 Forwards LER 83-002/01T-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 17004 288 24X Fiche 50-416, 83/01/27, 8302030110

--8302030113 LER 83-002/01T-0 on 830114, heat detectors in control room standby fresh air sys not functionally tested Caused by lack of proper procedure Surveillance Review Committee will write proper procedure FREEMAN, M S Mississippi Power & Light Co 83/01/28 Region 2, Office of Director 2pp 17004 289 24X Fiche 50-416, 83/01/27, 8302030110

8302030356 Forwards LER 82-182/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17005 354 24X Fiche 50-416, 83/01/28, 8302030356

--8302030359 LER 82-182/03L-0 on 821229 & 31, two fire doors blocked open to perform maint Open fire doors contrary to Tech Spec 3 7 7 Limiting condition of operation & fire watches established Maint completed & doors closed on 830103 FREEMAN, M S Mississippi Power & Light Co 83/01/28 Region 2, Office of Director 1p 17005 355 24X Fiche 50-416, 83/01/28, 8302030356

8302030363 Forwards LER 82-186/99X-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17005 348 24X Fiche 50-416, 83/01/28, 8302030363

--8302030367 LER 82-186/99X-0 on 821223, two fire doors in control bldg blocked open to perform planned maint in control room Open fire doors contrary to Tech Spec 3 7 7 Limiting condition of operation & fire watches established MCGAUGHY, J P Mississippi Power & Light Co 83/01/28 Region 2, Office of Director 1p 17005 349 24X Fiche 50-416, 83/01/28, 8302030363

8302030387 Forwards LER 82-184/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17005 343 24X Fiche 50-416, 83/01/28, 8302030387

--8302030393 LER 82-184/03L-0 on 821229, smoke detection Zone 2-14 (RHR C & LPCS pump rooms) alarmed w/no smoke or fumes present & would not reset Caused by spurious actuation Zone restored to operation on 830112 BYRD, R Mississippi Power & Light Co 83/01/28 Region 2, Office of Director 1p 17005 344 24X Fiche 50-416, 83/01/28, 8302030387

8302030562 Forwards LER 82-189/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 17008 091 24X Fiche 50-416, 83/01/28, 8302030562

--8302030569 LER 82-189/03L-0 on 821229, smoke detection Zone 2-17 (east corridor of auxiliary bldg, elevation 103 ft) alarmed & would not reset No fumes or smoke present Caused by spurious actuation Zone returned to operation on 830112 BAILEY, J P Mississippi Power & Light Co 83/01/28 Region 2, Office of Director 1p 17008 092 24X Fiche 50-416, 83/01/28, 8302030562

8302030300 Forwards LER 83-009/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 83/01/31 O'REILLY, J P Region 2, Office of Director 1p 17001 262 24X Fiche 50-416, 83/01/31, 8302030300

--8302030307 LER 83-009/03L-0 on 830101, shutdown cooling loop A declared inoperable Caused by need to replace discharge check valve for RHR jockey pump Control rod drive pump started to provide alternate DHR FREEMAN, M S Mississippi Power & Light Co 83/01/31 Region 2, Office of Director 1p 17001 263 24X Fiche 50-416, 83/01/31, 8302030300

8302070466 Fifth interim deficiency rept re sheered bolts on diesel generator rear crankcase cover Initially reported on 820322 Final rept will be submitted by 830601 Also reportable per 10CFR21 for Unit 1. MCGAUGHY, J P Mississippi Power & Light Co 83/01/31 O'REILLY, J P Region 2, Office of Director 2pp 17036 361 24X Fiche 50-416, 83/01/31, 8302070466

DOCKETED ITEMS

30

8302140030 Forwards LER 83-008/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/03
O'REILLY, J P Region 2, Office of Director 1p 17141 171 24X
Fiche 50-416, 83/02/03, 8302140030

--8302140032 LER 83-008/99X-0 on 830104, one door in control bldg (0C409)
& one door in auxiliary bldg (1A203) blocked open for
planned maint activities Hourly fire watch established
FREEMAN, M S Mississippi Power & Light Co 83/02/03 Region 2,
Office of Director 1p 17141 172 24X Fiche 50-416, 83/02/03,
8302140030

8302140053 Forwards LER 82-183/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/03
O'REILLY, J P Region 2, Office of Director 1p 17142 123 24X
Fiche 50-416, 83/02/03, 8302140053

--8302140060 LER 82-183/99X-0 on 821222, smoke detection zone covering
auxiliary bldg corridor area alarmed & would not reset No
smoke or fumes present Zone found functionally operable &
alarms reset
FREEMAN, M S Mississippi Power & Light Co 83/02/03 Region 2,
Office of Director 1p 17142 124 24X Fiche 50-416, 83/02/03,
8302140053

8302140058 Forwards LER 83-007/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/03
O'REILLY, J P Region 2, Office of Director 1p 17142 126 24X
Fiche 50-416, 83/02/03, 8302140058

--8302140064 LER 83-007/03L-0 on 830107, fire door 0C520 temporarily
blocked open to facilitate planned maint area Doors closed
on 830112 at completion of work
BAILEY, J P Mississippi Power & Light Co 83/02/03 Region 2,
Office of Director 1p 17142 127 24X Fiche 50-416, 83/02/03,
8302140058

8302140063 Forwards LER 83-011/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/03
O'REILLY, J P Region 2, Office of Director 1p 17142 130 24X
Fiche 50-416, 83/02/03, 8302140063

--8302140067 LER 83-011/99X-0 on 830103-24, certain fire rated barriers in
control bldg & auxiliary bldg opened to perform planned
maint Caused by cable routing Barriers to be restored by
Apr 1983
BYRD, R Mississippi Power & Light Co 83/02/03 Region 2,
Office of Director 3pp 17142 131 24X Fiche 50-416, 83/02/03,
8302140063

8302140014 Forwards LER 83-017/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/04
O'REILLY, J P Region 2, Office of Director 1p 17141 175 24X
Fiche 50-416, 83/02/04, 8302140014

--8302140019 LER 83-017/03L-0 on 830107, while in cold shutdown, fire
detection zone 2-2 auxiliary bldg corridor alarm activated
w/no smoke or flames present & would not reset Caused by
dirty detector Detector cleaned & satisfactorily tested
BYRD, R Mississippi Power & Light Co 83/02/04 Region 2,
Office of Director 1p 17141 176 24X Fiche 50-416, 83/02/04,
8302140014

8302140031 Forwards LER 83-015/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/04
O'REILLY, J P Region 2, Office of Director 1p 17141 167 24X
Fiche 50-416, 83/02/04, 8302140031

--8302140039 LER 83-015/03L-0 on 830105, shutdown cooling loop B removed
from svc for planned maint Caused by need to replace
feedwater check valve 01821F0328 carbon steel disk
w/stainless steel disk
BYRD, R Mississippi Power & Light Co 83/02/04 Region 2,
Office of Director 1p 17141 170 24X Fiche 50-416, 83/02/04,
8302140031

8302140089 Forwards LER 83-018/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/04
O'REILLY, J P Region 2, Office of Director 1p 17140 162 24X
Fiche 50-416, 83/02/04, 8302140089

--8302140093 LER 83-018/99X-0 on 830105, diesel generator 11 unloaded &
secured following trip on high bearing temp & indication of
increased crankcase pressure Caused by loose sensor on rear
main bearing allowing air to vent off pneumatic logic sys.
FREEMAN, M S Mississippi Power & Light Co 83/02/04 Region 2,
Office of Director 2pp 17140 163 24X Fiche 50-416, 83/02/04,
8302140089

8302140100 Forwards LER 83-012/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/04 Region 2,
Office of Director 1p 17142 170 24X Fiche 50-416, 83/02/04,
8302140100

--8302140102 LER 83-012/03L-0 on 830106, fire door 0C505 in control bldg
blocked open due to broken hinge Fire watch established &
hinge repaired
FREEMAN, M S Mississippi Power & Light Co 83/02/04 Region 2,
Office of Director 1p 17142 171 24X Fiche 50-416, 83/02/04,
8302140100

8302140194 Forwards LER 83-014/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/04
O'REILLY, J P Region 2, Office of Director 1p 17140 061 24X
Fiche 50-416, 83/02/04, 8302140194

--8302140204 LER 83-014/03L-0 on 830107, during cold shutdown, supervisory
sys alarms for several fire doors found in continuous alarm
& would not reset Caused by problems w/limit switches,
latches & magnets Fire watch established Doors reworked
FREEMAN, M S Mississippi Power & Light Co 83/02/04 Region 2,
Office of Director 2pp 17140 062 24X Fiche 50-416, 83/02/04,
8302140194

8302150099 Forwards LER 83-010/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/07
O'REILLY, J P Region 2, Office of Director 1p 17146 322 24X
Fiche 50-416, 83/02/07, 8302150099

--8302150106 LER 83-010/99X-0 on 830105, during insp of correction of
fire protection deficiencies on redundant raceways/cables,
similar deficiencies noted in auxiliary, turbine & control
bldgs Caused by incomplete const Maint work initiated
BYRD, R Mississippi Power & Light Co 83/02/07 Region 2,
Office of Director 2pp 17146 323 24X Fiche 50-416, 83/02/07,
8302150099

8302150083 Forwards LER 83-006/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/08
O'REILLY, J P Region 2, Office of Director 1p 17146 152 24X
Fiche 50-416, 83/02/08, 8302150083

--8302150094 LER 83-006/03L-0 on 830112, fire doors 0C714 & 0C710
temporarily blocked open to facilitate planned maint Fire
watch posted & doors closed at completion of work
BAILEY, J P Mississippi Power & Light Co 83/02/08 Region 2,
Office of Director 1p 17146 153 24X Fiche 50-416, 83/02/08,
8302150083

8302150110 Forwards LER 82-187/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/08
O'REILLY, J P Region 2, Office of Director 1p 17146 142 24X
Fiche 50-416, 83/02/08, 8302150110

--8302150115 LER 82-187/99X-0 on 821229, smoke detection zone covering
auxiliary bldg corridors at 166-ft elevation alarmed & would
not reset Caused by accumulation of dust in detector,
Detector cleaned, functionally tested & returned to svc
FREEMAN, M S Mississippi Power & Light Co 83/02/08 Region 2,
Office of Director 1p 17146 143 24X Fiche 50-416, 83/02/08,
8302150110

8302150635 Forwards LER 83-005/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/09
O'REILLY, J P Region 2, Office of Director 1p 17151 302 24X
Fiche 50-416, 83/02/09, 8302150635

--8302150641 LER 83-005/03L-0 on 830111, fire door 0R106 blocked opened
allow transport of resin Fire watch established per Tech
Specs Door closed when job completed on 830112
BAILEY, J P Mississippi Power & Light Co 83/02/09 Region 2,
Office of Director 1p 17151 303 24X Fiche 50-416, 83/02/09,
8302150635

8302170121 Forwards LER 83-019/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/11
O'REILLY, J P Region 2, Office of Director 1p 17181 394 24X
Fiche 50-416, 83/02/11, 8302170121

--8302170127 LER 83-019/03L-0 on 830112 & 20, one smoke detector in Zone
1-15 & eight detectors in Zone 2-18 covered during planned
maint functions to prevent false alarms or damage to unit
Detectors uncovered after maint completed
FREEMAN, M S Mississippi Power & Light Co 83/02/11 Region 2,
Office of Director 1p 17181 395 24X Fiche 50-416, 83/02/11,
8302170121

8302170308 Forwards updated LER 82-044/03X-1,
MCGAUGHY, J P Mississippi Power & Light Co 83/02/11
O'REILLY, J P Region 2, Office of Director 1p 17177 001 24X
Fiche 50-416, 83/02/11, 8302170308

DOCKETED ITEMS

--B302170311 Updated LER B2-044/03X-1 on B20813, while venting nuclear boiler instruments, several ECCS initiations occurred. Caused by procedural inadequacy Plant Procedure 07-S-13-23 written & approved
ROHRER, M V Mississippi Power & Light Co 83/02/09 Region 2,
Office of Director 2pp 17177 002 24X Fiche 50-416, 83/02/11,
8302170308

B302170318 Forwards LER B3-023/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/11
O'REILLY, J P Region 2, Office of Director 1p 17184 159 24X
Fiche 50-416, 83/02/11, 8302170318

--B302170320 LER B3-023/03L-0 on B30113 & 28, fire rated doors in control bldg OCT10, OCT14 & OCT09 blocked open to route hoses being used in planned maint activities. Doors restored on B30113 & 29
BYRD, R Mississippi Power & Light Co 83/02/11 Region 2,
Office of Director 1p 17184 160 24X Fiche 50-416, 83/02/11,
8302170318

B302170322 Forwards LER B3-024/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/11
O'REILLY, J P Region 2, Office of Director 1p 17184 001 24X
Fiche 50-416, 83/02/11, 8302170322

--B302170324 LER B3-024/03L-0 on B30114, several smoke detector zones in auxiliary bldg & control bldg would not reset. Cause attributed to spurious action. One detector replaced & remaining detectors cleaned
FREEMAN, M S Mississippi Power & Light Co 83/02/11 Region 2,
Office of Director 2pp 17184 002 24X Fiche 50-416, 83/02/11,
8302170322

B302170346 Forwards updated LER B2-059/01X-1
MCGAUGHY, J P Mississippi Power & Light Co 83/02/11
O'REILLY, J P Region 2, Office of Director 2pp 17189 143 24X
Fiche 50-416, 83/02/11, 8302170346

--B302170354 Updated LER B2-059/01X-1 on B20909, while performing RHR high to low pressure interface valve leakage test, setpoints for RHR injection valve differential pressure switches found greater than Tech Specs. Caused by misinterpretation
FLOYD, J M Mississippi Power & Light Co 83/02/09 Region 2,
Office of Director 2pp 17185 145 24X Fiche 50-416, 83/02/11,
8302170346

B302170358 Forwards LER B3-022/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/11
O'REILLY, J P Region 2, Office of Director 1p 17184 174 24X
Fiche 50-416, 83/02/11, 8302170358

--B302170362 LER B3-022/03L-0 on B30112 & 13, alarm received for two fire rated doors in auxiliary bldg & temporary door in control room. Caused by unadjusted limit switch & faulty door strike. Alarms cleared & doors restored
BYRD, R Mississippi Power & Light Co 83/02/11 Region 2,
Office of Director 1p 17184 175 24X Fiche 50-416, 83/02/11,
8302170358

B302220358 Forwards LER B3-020/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/14
O'REILLY, J P Region 2, Office of Director 1p 17232 010 24X
Fiche 50-416, 83/02/14, 8302220358

--B302220361 LER B3-020/03L-0 on B30115, during shutdown, lube oil heater on diesel generator 12 failed, resulting in diesel generator 12 & Div 2 ECCB being declared inoperable. Caused by overheating & shorting to ground. Heater replaced
FREEMAN, M S Mississippi Power & Light Co 83/02/14 Region 2,
Office of Director 1p 17232 011 24X Fiche 50-416, 83/02/14,
8302220358

B302220369 Forwards LER B3-013/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/15
O'REILLY, J P Region 2, Office of Director 1p 17232 340 24X
Fiche 50-416, 83/02/15, 8302220369

--B302220377 LER B3-013/99X-0 on B30119, while in cold shutdown, three doors in auxiliary bldg blocked open to support plant testing. Fire watches established. Testing completed & doors closed on B30127
SHINGLETON, E B Mississippi Power & Light Co 83/01/15 Region 2,
Office of Director 1p 17232 341 24X Fiche 50-416, 83/02/15,
8302220369

B302280235 Forwards updated LER B2-047/03X-1
MCGAUGHY, J P Mississippi Power & Light Co 83/02/18
O'REILLY, J P Region 2, Office of Director 2pp 17304 344 24X
Fiche 50-416, 83/02/18, 8302280235

--B302280243 Updated LER B2-047/03X-1 on B20830, reactor vessel flange & head flange temps not verified according to Tech Specs. Caused by personnel error & procedural inadequacy. Procedure revised to record temps as required
ROHRER, M V Mississippi Power & Light Co 83/02/18 Region 2,
Office of Director 2pp 17304 346 24X Fiche 50-416, 83/02/18,
8302280235

B302280283 Forwards LER B3-028/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/18
O'REILLY, J P Region 2, Office of Director 1p 17313 021 24X
Fiche 50-416, 83/02/18, 8302280283

--B302280289 LER B3-028/03L-0 on B30120, shutdown cooling loop A (RHR A) declared inoperable to install accelerometers on standby svc water loop. Loop declared operable on B30123
BYRD, R Mississippi Power & Light Co 83/02/18 Region 2,
Office of Director 1p 17313 022 24X Fiche 50-416, 83/02/18,
8302280283

B302280294 Forwards LER B3-031/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/18
O'REILLY, J P Region 2, Office of Director 1p 17312 355 24X
Fiche 50-416, 83/02/18, 8302280294

--B302280301 LER B3-031/99X-0 on B30113, fire rated door OCT04 blocked open to route temporary discharge hose from hot machine shop sump to turbine bldg floor drain sys. Hourly fire watches established. Design change requested
SHINGLETON, E B Mississippi Power & Light Co 83/02/18 Region 2,
Office of Director 1p 17312 356 24X Fiche 50-416, 83/02/18,
8302280294

B302280071 Forwards updated LER B2-145/03X-1
MCGAUGHY, J P Mississippi Power & Light Co 83/02/22
O'REILLY, J P Region 2, Office of Director 2pp 17307 135 24X
Fiche 50-416, 83/02/22, 8302280071

--B302280079 Updated LER B2-145/03X-1 on B21127, meteorological monitoring sys removed from svc to perform work required by Design Change Package B2-457. Caused by planned maint outage. Change package completed & sys restored
Mississippi Power & Light Co 83/02/22 Region 2, Office of Director 1p 17307 137 24X Fiche 50-416, 83/02/22, 8302280071

B302280225 Forwards LER B3-030/99X-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/22
O'REILLY, J P Region 2, Office of Director 1p 17304 355 24X
Fiche 50-416, 83/02/22, 8302280225

--B302280228 LER B3-030/99X-0 on B30109, Halon control panel 01113P917 trouble alarm annunciated w/no fire or smoke present & would not reset. Caused by loose detector mounting. Loose screws tightened. Fire watch established
SHINGLETON, E B Mississippi Power & Light Co 83/02/22 Region 2,
Office of Director 1p 17304 356 24X Fiche 50-416, 83/02/22,
8302280225

B302280230 Forwards LER B3-037/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/22
O'REILLY, J P Region 2, Office of Director 1p 17304 350 24X
Fiche 50-416, 83/02/22, 8302280230

--B302280234 LER B3-037/03L-0 on B30123, one air start receiver for diesel generator 12 found pressurized to less than min Tech Spec requirement. Caused by stuck valve on inlet to air dryer for electric driven air compressor
SHINGLETON, E B Mississippi Power & Light Co 83/02/22 Region 2,
Office of Director 1p 17304 351 24X Fiche 50-416, 83/02/22,
8302280230

B302280458 Forwards LER B3-036/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/22
O'REILLY, J P Region 2, Office of Director 1p 17309 217 24X
Fiche 50-416, 83/02/22, 8302280458

--B302280464 LER B3-036/03L-0 on B30124, heater element in steam generator for humidifier section of control room air conditioning sys. A train found arcing. Caused by mineral deposits from makeup water. Generator cylinders replaced
SHINGLETON, E B Mississippi Power & Light Co 83/02/22 Region 2,
Office of Director 2pp 17309 218 24X Fiche 50-416,
83/02/22, 8302280458

B302280424 Forwards LER B3-025/03L-0
MCGAUGHY, J P Mississippi Power & Light Co 83/02/23
O'REILLY, J P Region 2, Office of Director 1p 17307 325 24X
Fiche 50-416, 83/02/23, 8302280424

DOCKETED ITEMS

311

--8302280429 LER 83-025/03L-0 on 830124, auxiliary bldg equipment hatch on elevation 166 ft removed. Caused by deliberate personnel action to allow transport of neutron source into containment. Equipment hatch replaced.
FREEMAN, M S , SHINGLETON, B Mississippi Power & Light Co
83/02/23 Region 2, Office of Director 1p 17307 326 24X
Fiche 50-416, 83/02/23, 8302280424

8302280434 Forwards LER 83-035/01T-0
MCQUAGHY, J P Mississippi Power & Light Co 83/02/23
O'REILLY, J P Region 2, Office of Director 1p 17309 206 24X
Fiche 50-416, 83/02/23, 8302280434

--8302280440 LER 83-035/01T-0 on 830209, performance of previous refueling interlock surveillance procedure found to violate Tech Specs since reactor mode switch placed in startup/hot standby position. Cause not stated. Procedure changed.
FREEMAN, M S , SHINGLETON, B Mississippi Power & Light Co
83/02/23 Region 2, Office of Director 2pp 17309 207 24X
Fiche 50-416, 83/02/23, 8302280434

8302280448 Forwards LER 83-016/03L-0
MCQUAGHY, J P Mississippi Power & Light Co 83/02/23
O'REILLY, J P Region 2, Office of Director 1p 17309 212 24X
Fiche 50-416, 83/02/23, 8302280448

--8302280454 LER 83-016/03L-0 on 830124, during cold shutdown, supervision sys for fire-rate door OC517 alarmed & would not reset w/ door closed. Door declared inoperable. Cause unknown. Sys declared operational 1 wk later & door restored.
BYRD, R , SHINGLETON, B Mississippi Power & Light Co 83/02/23
Region 3, Office of Director 1p 17309 213 24X
Fiche 50-416, 83/02/23, 8302280448

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302010528 Informs that detailed review in progress addressing listed issues to support util position of initiating containment sprays at same time as hydrogen igniter sys when reactor core level reaches top of active fuel, per NRC request.
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16977 244
24X Fiche 50-416, 83/01/28, 8302010528

8302170482 Board Notification 83-1 forwards BNL draft rept, "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach".
EISENHUT, D O Division of Licensing FIN A-3397 83/02/01
PALLADINO, N J Commissioners 13pp 17203 309 24X
Fiche 50-000, 83/02/01, 8302170482

8302040426 Requests provisions of proposed OL Condition Item 2 C(42): be extended to include reinstallation of vibration monitoring equipment. Responses to request or add info re protective sleeves for local power range monitors encl.
DALE, L F Mississippi Power & Light Co 83/02/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 17017 328
24X Fiche 50-416, 83/02/02, 8302040426

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BNR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982. Guidelines acceptable. Svc list encl.
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

F Security, medical, emergency & fire protection plans

8302010508 Responds to NRC 821122 comments on 820922 Physical Security Plan, Rev 5. Addl justification addressing NRC concern w/ Section 6.6.2.2 will be provided by 830228 Clarification of Section 3.6.5 will be included in Rev 7.
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16978 080
24X Fiche 50-416, 83/01/28, 8302010508

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl.
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030554 Forwards responses to NRC informal questions re IE Bulletin 80-11, "Masonry Walls." All load combinations in design criteria, including OBE, SSE & tornado depressurization, addressed.
DALE, L F Mississippi Power & Light Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 52pp 17006 232
24X Fiche 50-416, 83/01/28, 8302030554

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302010495 Interim deficiency rept re Nelson stud failures on embedded plates. Initially reported on 821221 Lab testing of plates in progress. Deficiency reported per 10CFR21 for Unit 1 & 10CFR50.55(e) for Unit 2. Final rept expected by 830315.
MCQUAGHY, J P Mississippi Power & Light Co 83/01/20
O'REILLY, J P Region 2, Office of Director 4pp 16981 331 24X
Fiche 50-416, 83/01/20, 8302010495

8302070466 Fifth interim deficiency rept re sheared bolts on diesel generator rear crankcase cover. Initially reported on 820322. Final rept will be submitted by 830601. Also reportable per 10CFR21 for Unit 1.
MCQUAGHY, J P Mississippi Power & Light Co 83/01/31
O'REILLY, J P Region 2, Office of Director 2pp 17036 361 24X
Fiche 50-416, 83/01/31, 8302070466

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKETED ITEMS

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8302090545 Forwards requests for addl info needed to complete acceptance review of DL application. Info provided sufficient for docketing application & initiation of safety & environ reviews
EISENHUT, D G Division of Licensing 83/01/31 COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 58pp
17132 001 24X Fiche 50-423, 83/01/31, 8302090545

8302030186 Forwards DL application, consisting of general info, design basis response to Reg Guide 1.97, Failure mode & effects analysis, FSAR (PDR Category K), environ rept (Category C) & fire protection evaluation & emergency plan (Category F)
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/02/02
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17075 001 24X Fiche 50-423, 83/02/02, 8302030186

--8302030204 Application for DL, consisting of general info, Design Basis Response to Reg Guide 1.97, Failure Mode & Effects Analysis, FSAR, Environ Rept, Fire Protection Evaluation & Emergency Plan
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 106pp 17075 003 24X
Fiche 50-423, 83/02/02, 8302030186

--8302030230 "Design Basis Response to Reg Guide 1.97, Rev 2"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 46pp 17075 107 24X
Fiche 50-423, 83/02/02, 8302030186

--8302030237 "Failure Modes & Effects Analysis (FMEA)"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 916pp 17075 137 24X
Fiche 50-423, 83/02/02, 8302030186

8302100513 Submits daily highlight for 830202 DL application acceptance review completed. License review schedule will be issued following docketing. Projected fuel load date estimated to be 851101
DODLITTLE, E L Licensing Branch 1 83/02/02 DENTON, H R, CASE, E,
CARTER, J Office of Nuclear Reactor Regulation, Director 1p
17143 357 24X Fiche 50-423, 83/02/02, 8302100513

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Hestinghouse designed NSSS re resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D G Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302200148 Certifies distribution of 830131 application for DL to federal, state & local officials
COUNCIL, W G, SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) SEARS, C F Northeast Utilities 83/02/11
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17233 291 24X Fiche 50-423, 83/02/11, 8302200148

C Utility Environmental Report (ER), amends & correspondence

8302030186 Forwards environ rept for Millstone Unit 3
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/02, DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17075 001 24X Fiche 50-423, 83/02/02, 8302030186

--8302030248 Environ rept - DL stage for Millstone Unit 3 Seven oversize drawings encl Aperture cards available in PDR
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 1,411pp 17079 121 24X
Fiche 50-423, 83/02/02, 8302030186

F Security, medical, emergency & fire protection plans

8302010081 Releases public version of revised title pages to Emergency Plans
FELTON, J M Division of Rules and Records 83/01/26 Document
Management Branch 1p 16990 233 24X Fiche 50-000, 83/01/26, 8302010081

--8302010084 Forwards public version of revised title pages to Millstone & Haddam Neck Nuclear Power Plant Emergency Plans, including correction to site plan Figure 7-1c re lines of communication between emergency response ctrs
ST PIERRE, M Northeast Utilities 83/01/13 BAILEY, J NRC - No
Detailed Affiliation Given 1p 16990 234 24X
Fiche 50-000, 83/01/26, 8302010081

--8302010091 Public version of revised title page to Millstone Nuclear Plant Emergency Plan
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/01/13 1p 16990 235 24X Fiche 50-000, 83/01/26, 8302010081

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302030186 Forwards fire protection evaluation rept & emergency plan
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17075 001 24X Fiche 50-423, 83/02/02, 8302030186

--8302030254 "Fire Protection Evaluation Rept"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 275pp 17077 353 24X
Fiche 50-423, 83/02/02, 8302030186

--8302030258 Public version of draft emergency plan
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 213pp 17078 268 24X
Fiche 50-423, 83/02/02, 8302030186

K Utility Final Safety Analysis Report (FSAR) & amends

8302030186 Forwards FSAR for Millstone Unit 3
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17075 001 24X Fiche 50-423, 83/02/02, 8302030186

--8302030243 FSAR for Millstone Unit 3 Three oversize drawings & maps encl Aperture cards available in PDR
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 13pp 17083 092 24X
Fiche 50-423, 83/02/02, 8302030186

8302030308 Chapter 1 to Millstone Unit 3 FSAR, "Introduction & General Description of Plant"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 335pp 17083 105 24X
Fiche 50-423, 83/02/02, 8302030305

8302030310 Chapter 2 to Millstone Unit 3 FSAR, "Site Characteristics"
Forty-five oversize drawings encl Aperture cards available in PDR
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 1,009pp 17084 080 24X
Fiche 50-423, 83/02/02, 8302030310

8302030317 App 2 5A to Millstone Unit 3 FSAR, "Age of Till at Millstone Point, CT"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 1,009pp 17087 014 24X
Fiche 50-423, 83/02/02, 8302030317

8302030322 App 2 5B to Millstone Unit 3 FSAR, "Petrographic Repts Final Grade"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 10pp 17087 014 24X
Fiche 50-423, 83/02/02, 8302030322

8302030328 App 2 5C to Millstone Unit 3 FSAR, "Mineralogical Analysis of Millstone Fault Gouge Samples"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 83/02/02 6pp 17087 025 24X
Fiche 50-423, 83/02/02, 8302030328

8302030330 App 2 5D to Millstone Unit 3 FSAR, "Potassium-Argon Age Determination"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) *
Northeast Utilities 82/06/07 12pp 17087 032 24X
Fiche 50-423, 83/02/02, 8302030330

DOCKETED ITEMS

8302030334 App 2 SE to Millstone Unit 3 FSAR, "Separation of Less Than 2 Micron Fraction & Clay Analysis of Samples B.C.D (ESF Bldg) & P-1 & P-2 (Pumphouse) "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Dartmouth College 83/02/02 7pp
 17087 045 24x Fiche 50-423,83/02/02,8302030334

8302030336 App 2 FE to Millstone Unit 3 FSAR, "Dynamic Soil Testing on Beach Sands "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Geotechnical Engineers, Inc 79/09/05
 62pp 17087 053 24x Fiche 50-423,83/02/02,8302030336

8302030338 App 2 50 to Millstone Unit 3 FSAR, "Consolidated Undrained Tests on Beach Sands "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 76/07/31 9pp 17087 109 24x
 Fiche 50-423,83/02/02,8302030338

8302030341 App 2 5H to Millstone Unit 3 FSAR, "Seismic Velocity Measurements "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Weston Geophysical Corp 72/04/30 8pp
 17087 119 24x Fiche 50-423,83/02/02,8302030341

8302030343 App 2 5I to Millstone Unit 3 FSAR, "Direct Shear Tests on Natural Rock Joints "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Stone & Webster Engineering Corp 83/02/02
 40pp 17087 129 24x Fiche 50-423,83/02/02,8302030343

8302030347 App 2 5J to Millstone Unit 3 FSAR, "Boring Logs " Oversize drawings encl One hundred six oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 82/04/24 46pp 17087 168 24x
 Fiche 50-423,83/02/02,8302030347

8302030349 App 2 5K to Millstone Unit 3 FSAR, "Seismic Survey " Eight oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Weston Geophysical Corp 72/04/30 25pp
 17087 214 24x Fiche 50-423,83/02/02,8302030349

8302030352 App 2 5L to Millstone Unit 3 FSAR, "Seismic & Bathymetric Survey " Thirteen oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Weston Geophysical Corp 72/06/30 14pp
 17087 223 24x Fiche 50-423,83/02/02,8302030352

8302030355 App 2 5M to Millstone Unit 3 FSAR, "Lab Test Program for Proposed Addl Structural Backfill Sources "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities * Stone & Webster Engineering Corp 74/06/30
 21pp 17087 237 24x Fiche 50-423,83/02/02,8302030355

8302030358 Chapter 3 to Millstone Unit 3 FSAR, "Design of Structures, Components, Equipment & Sys " Two oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 1,076pp 17087 289 24x
 Fiche 50-423,83/02/02,8302030358

8302030360 App 3A to Millstone Unit 3 FSAR, "Computer Programs for Dynamic & Static Analysis of Seismic Category I Structures, Equipment & Components "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 110pp 17090 285 24x
 Fiche 50-423,83/02/02,8302030360

8302030362 App 3B to Millstone Unit 3 FSAR, "Environ Design Conditions "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 168pp 17091 035 24x
 Fiche 50-423,83/02/02,8302030362

8302030364 Chapter 4 to Millstone Unit 3 FSAR, "Reactor "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 229pp 17091 203 24x
 Fiche 50-423,83/02/02,8302030364

8302030366 Chapter 5 to Millstone Unit 3 FSAR, "RCB & Connected Sys " Six oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 215pp 17092 072 24x
 Fiche 50-423,83/02/02,8302030366

8302030368 Chapter 6 to Millstone Unit 3 FSAR, "EBFs " Thirteen oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 384pp 17092 287 24x
 Fiche 50-423,83/02/02,8302030368

8302030369 Chapter 7 to Millstone Unit 3 FSAR, "Instrumentation & Controls "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 268pp 17093 311 24x
 Fiche 50-423,83/02/02,8302030369

8302030370 Chapter 8 to Millstone Unit 3 FSAR, "Electric Power " Five oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 109pp 17094 219 24x
 Fiche 50-423,83/02/02,8302030370

8302030371 Chapter 9 to Millstone Unit 3 FSAR, "Auxiliary Sys " Seventy-three oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 415pp 17094 328 24x
 Fiche 50-423,83/02/02,8302030371

8302030372 Chapter 10 to Millstone Unit 3 FSAR, "Steam & Power Conversion Sys " Thirty-four oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 116pp 17096 023 24x
 Fiche 50-423,83/02/02,8302030372

8302030373 Chapter 11 to Millstone Unit 3 FSAR, "Radwaste Mgt " Eight oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 133pp 17096 139 24x
 Fiche 50-423,83/02/02,8302030373

8302030374 App 11A to Millstone Unit 3 FSAR, "Summary of Annual Radiation Doses, Dose Calculation Models & Assumptions & Cost-Benefit Analysis "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 43pp 17096 272 24x
 Fiche 50-423,83/02/02,8302030374

8302030380 Chapter 12 to Millstone Unit 3 FSAR, "Radiation Protection Four oversize drawings encl Aperture cards available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 84pp 17096 319 24x
 Fiche 50-423,83/02/02,8302030380

8302030381 Chapter 13 to Millstone Unit 3 FSAR, "Conduct of Operations "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 186pp 17097 043 24x
 Fiche 50-423,83/02/02,8302030381

8302030382 Chapter 14 to Millstone Unit 3 FSAR, "Initial Test Program One oversize drawing encl Aperture card available in PDR
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 181pp 17097 229 24x
 Fiche 50-423,83/02/02,8302030382

8302030383 Chapter 15 to Millstone Unit 3 FSAR, "Accident Analyses. "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 402pp 17098 050 24x
 Fiche 50-423,83/02/02,8302030383

8302030386 Chapter 16 to Millstone Unit 3 FSAR, "Tech Specs "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 5pp 17099 092 24x
 Fiche 50-423,83/02/02,8302030386

8302030390 Chapter 17 to Millstone Unit 3 FSAR, "QA "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 7pp 17099 095 24x
 Fiche 50-423,83/02/02,8302030390

8302030394 Chapter 18 to Millstone Unit 3 FSAR, "Human Factors Engineering "
 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 83/02/02 3pp 17099 099 24x
 Fiche 50-423,83/02/02,8302030394

DOCKETED ITEMS

M Antitrust correspondence

8302040153 Notifies that antitrust info. received w/utal 821029 ltr for review as part of application for OL will appear for simultaneous publication in FR, Public Power Weekly, Electric Light & Power & Rural Electric Magazine YOUNGBLOOD, B J Licensing Branch 1 83/01/24 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 17043 114 24X Fiche 50-423, 83/01/24, 8302040153

--8302040157 Notice of receipt of antitrust info re application for OL YOUNGBLOOD, B J Licensing Branch 1 83/01/24 6pp 17043 118 24X Fiche 50-423, 83/01/24, 8302040153

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/24 Consolidated Edison Co of New York, Inc 188pp 17023 160 24X Fiche 50-000, 83/01/24, 8212060358

8302010651 Forwards SALP Repts for Sept 1981 - Aug 1982 Performance exhibits high level of mgt attention & involvement Ample resources appear to be effectively used HAYNES, R C Region 1, Office of Director 83/01/27 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 16979 045 24X Fiche 50-000, 83/01/27, 8302010651

--8302010672 SALP rept on 821007 Geologic excavation & mapping by licensee accomplished Const deficiencies thoroughly analysed & promptly reported * Region 1, Office of Director 82/10/07 20pp 16979 107 24X Fiche 50-000, 83/01/27, 8302010651

--8302010679 Notifies of 821103 meeting to provide forum for candid discussions re util performance STAROSTECKI, R Division of Project & Resident Programs 82/10/27 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16979 160 24X Fiche 50-000, 83/01/27, 8302010651

--8302010682 Provides comments on 821103 meeting to ensure mutual understanding of detailed performance evaluation of util. COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/23 HAYNES, R C Region 1, Office of Director 5pp 16979 162 24X Fiche 50-000, 83/01/27, 8302010651

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H20C & H38C Gearheads " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302180193 Forwards IE Insp Rept 50-423/82-15 on 821206-830107 No noncompliance noted. STAROSTECKI, R Division of Project & Resident Programs 83/02/04 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17215 328 24X Fiche 50-423, 83/02/04, 8302180193

--8302180200 IE Insp Rept 50-423/82-15 on 821206-830107 No noncompliance noted. Major areas inspected installation of steam generator supports & heating & ventilation filters in auxiliary bldg & followup of previous insp findings MATTHEW, J C, ELBASSET, T Division of Project & Resident Programs 83/01/26 8pp 17215 330 24X Fiche 50-423, 83/02/04, 8302180193

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302280097 Responds to Generic Ltr 83-01 re requests for site visits for licensing/certification exams from Apr 1983 - Dec 1985 Estimated exam dates tentative COUNCIL, W O Connecticut Yankee Atomic Power Co SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/02/18 EISENHUT, D O Division of Licensing 5pp 17307 129 24X Fiche 50-000, 83/02/18, 8302280097

DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302040250 Documents verbal commitment to make simulators available for control room task analysis BECKHAM, J T Georgia Power Co 83/01/20 STOLZ, J Operating Reactors Branch 4 1p 17020 047 24X Fiche 50-000, 83/01/20, 8302040250

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302170044 Forwards addl info requested during 830104 meeting re mailing of FSAR, submittal of security plan, proposed fee structure & issuance of rev to STS & radiological effluent Tech Spec ADENSAH, C O Licensing Branch 4 83/02/08 DUTTON, D Georgia Power Co 3pp 17191 059 24X Fiche 50-424, 83/02/08, 8302170044

C Utility Environmental Report (ER), amends & correspondence

8302030261 Discusses preparation of environ rept - OL stage Certain sections of environ rept will be deleted to eliminate duplication of info between FSAR & environ rept WARREN, D H Southern Co Services, Inc 83/01/26 MILLER, M Division of Licensing 2pp 17008 084 24X Fiche 50-424, 83/01/26, 8302030261

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

G Inspection reports, IE Bulletins & correspondence

8302150575 Forwards IE Insp Repts 50-424/82-26 & 50-425/82-26 on 821026-29 & notice of deviation DANCE, H C Division of Project & Resident Programs 82/11/18 KELLY, R J Georgia Power Co 2pp 17156 130 24X Fiche 50-424, 82/11/18, 8302150575

DOCKETED ITEMS

--8302150581 Notice of deviation from insp on 821026-29
 * Division of Project & Resident Programs 82/11/18 1p
 17156 132 24X Fiche 50-424,82/11/18,8302150575

--8302150591 IE Insp Repts 50-424/82-26 & 50-425/82-26 on 821026-29
 Noncompliance noted failure to perform separate tensile test
 cycles for each splicing crew.
 HARRIS, J R , CONLON, T E Division of Engineering & Radiological
 Safety Programs 82/11/12 5pp 17156 133 24X
 Fiche 50-424,82/11/18,8302150575

8302150714 Responds to NRC ltr re deviation noted in IE Insp Repts
 50-424/82-26 & 50-425/82-26 Corrective actions Field
 Procedure CD-T-06 re rebar & cadweld QC revised to formally
 incorporate test sample frequency changes
 FOSTER, D O Georgia Power Co FOSTER, D O Southern Co Services,
 Inc 83/01/07 DANCE, H C Region 2, Office of Director 2pp
 17151 361 24X Fiche 50-424,83/01/07,8302150714

8302150493 Ack receipt of 821207 ltr informing NRC of steps taken to
 correct violations noted in IE Insp Repts 50-424/82-26 &
 50-425/82-26
 LEWIS, R C Division of Project & Resident Programs 83/01/25
 KELLY, R J Georgia Power Co 1p 17156 319 24X
 Fiche 50-424,83/01/25,8302150493

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/26 Consolidated Edison Co of New
 York, Inc 118pp 17023 160 24X Fiche 50-000,83/01/26,8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
 Gearheads " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Caliber of Liquid Level Instruments "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/01/28 Consolidated Edison Co of New
 York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/18 Consolidated Edison Co of New
 York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
 Very Low Level Radwaste - 10CFR20.302 " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

S Reportable occurrences, LERs & related correspondence

8302010212 Interim Deficiency Rept re piston skirt cracking in Delaval
 diesel generators Initially reported on 821223 Reportability
 still under evaluation Next rept will be submitted by
 830228
 FOSTER, D O Georgia Power Co 83/01/24 O'REILLY, J P Region 2,
 Office of Director 1p 16974 036 24X Fiche 50-424,83/01/24,
 8302010212

8302010239 Interim Deficiency Rept re unverified computer code used in
 main feedwater pipe supports Initially reported on 821222,
 Reportability still under evaluation Next rept will be
 submitted by 830228
 FOSTER, D O Georgia Power Co 83/01/24 O'REILLY, J P Region 2,
 Office of Director, 1p 16974 049 24X Fiche:50-424,83/01/24,
 8302010239

8302010647 Interim Deficiency Rept re Reliance Electric Co cable
 termination Initially reported on 821223 Results of
 evaluation will be provided by 830506
 FOSTER, D O Cincinnati Gas & Electric Co FOSTER, D O Southern Co
 Services, Inc 83/01/24 O'REILLY, J P Region 2, Office of
 Director 1p 16980 048 24X Fiche 50-424,83/01/24,8302010647

8302280136 Potential deficiency rept re use of cadwelds as end
 anchorages Initially reported on 830113 Engineering
 evaluation & completion schedule not yet determined Interim
 rept will be submitted by 830331
 FOSTER, D O Georgia Power Co 83/02/17 O'REILLY, J P Region 2,
 Office of Director 1p 17306 087 24X Fiche 50-424,83/02/17,
 8302280136

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
 for OL, NSS vendors, reactor vendors & AE re certificates
 & revised format for reactor operator & senior reactor
 operator licenses Svc list encl
 EISENHUT, D O Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche 50-000,83/01/31,8301310203

DOCKET 50-429 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302040250 Documents verbal commitment to make simulators available
 for control room task analysis
 BECKHAM, J T Georgia Power Co 83/01/20 STOLZ, J. Operating
 Reactors Branch 4 1p 17020 047 24X Fiche 50-000,83/01/20,
 8302040250

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
 applicants for OL & holders of CP for C-E PWRs re review of
 C-E Owners Group emergency procedures guideline program Svc
 list encl
 EISENHUT, D O Division of Licensing 83/02/08 Consolidated
 Edison Co of New York, Inc 11pp 17290 247 24X
 Fiche 50-000,83/02/08,8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Hastingshouse designs
 NSS re resolution of TMI Action Item I/K 3 5, "Automatic
 Trip of Reactor Coolant Pumps "
 EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas &
 Electric Co 30pp 17290 212 24X Fiche 50-000,83/02/08,
 8302090080

8302170044 Forwards addl info requested during 830104 meeting re
 mailing of FSAR, submittal of security plan, proposed fee
 structure & issuance of rev to STS & radiological effluent
 Tech Specs
 ADENSAH, E O Licensing Branch 4 83/02/08 DUTTON, D Georgia
 Power Co 3pp 17191 059 24X Fiche 50-424,83/02/08,8302170044

C Utility Environmental Report (ER), amends & correspondence

8302030261 Discusses preparation of environ rept - OL stage Certain
 sections of environ rept will be deleted to eliminate
 duplication of info between FSAR & environ rept
 WARREN, D H Southern Co Services, Inc 83/01/26 MILLER, M
 Division of Licensing 2pp 17008 084 24X Fiche 50-424,83/01/26
 8302030261

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
 applicants for OL & holders of CPs re regional workshop
 concerning Suppl 1, NUREG-0737, "Requirements for Emergency
 Response Capability " Svc list encl
 EISENHUT, D O Division of Licensing 83/02/01 Consolidated
 Edison Co of New York, Inc 11pp 17221 226 24X
 Fiche: 50-000,83/02/01,8301210340

Q Inspection reports, IE Bulletins & correspondence

8302150575 Forwards IE insp Repts 50-424/82-26 & 50-425/82-26 on
 821026-29 & notice of deviation
 DANCE, H C Division of Project & Resident Programs. 82/11/18
 KELLY, R J Georgia Power Co 2pp 17156 130 24X
 Fiche 50-424,82/11/18,8302150575

--8302150581 Notice of deviation from insp on 821026-29
 * Division of Project & Resident Programs. 82/11/18 1p
 17156 132 24X Fiche 50-424,82/11/18,8302150575

--8302150591 IE Insp Repts 50-424/82-26 & 50-425/82-26 on 821026-29
 Noncompliance noted failure to perform separate tensile test
 cycles for each splicing crew.
 HARRIS, J R , CONLON, T E Division of Engineering & Radiological
 Safety Programs 82/11/12 5pp 17156 133 24X
 Fiche 50-424,82/11/18,8302150575

DOCKETED ITEMS

8302150714 Responds to NRC ltr re deviation noted in IE Insp Repts 50-424/82-26 & 50-425/82-26 Corrective actions Field Procedure CD-T-06 re rebar & cadweld QC revised to formally incorporate test sample frequency changes
FOSTER, D D Georgia Power Co FOSTER, D D Southern Co Services, Inc 83/01/07 DANCE, H C Region 2, Office of Director 2pp 17151 361 24X Fiche 50-424, 83/01/07, 8302150714

8302150493 Ack receipt of 821207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-26 & 50-425/82-26
LEWIS, R C Division of Project & Resident Programs 83/01/25
KELLY, R J Georgia Power Co 1p 17156 319 24X
Fiche 50-424, 83/01/25, 8302150493

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302010212 Interim Deficiency Rept re piston skirt cracking in Delaval diesel generators Initially reported on 821223 Reportability still under evaluation Next rept will be submitted by 830228
FOSTER, D D Georgia Power Co 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 16974 036 24X Fiche 50-424, 83/01/24, 8302010212

8302010239 Interim Deficiency Rept re unverified computer code used in main feedwater pipe supports Initially reported on 821222 Reportability still under evaluation Next rept will be submitted by 830228
FOSTER, D D Georgia Power Co 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 16974 049 24X Fiche 50-424, 83/01/24, 8302010239

8302010647 Interim Deficiency Rept re Reliance Electric Co cable termination Initially reported on 821223 Results of evaluation will be provided by 830306
FOSTER, D D Cincinnati Gas & Electric Co FOSTER, D D Southern Co Services, Inc 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 16980 048 24X Fiche 50-424, 83/01/24, 8302010647

8302280136 Potential deficiency rept re use of cadwelds as end anchorages Initially reported on 830113 Engineering evaluation & completion schedule not yet determined Interim rept will be submitted by 830331
FOSTER, D D Georgia Power Co 83/02/17 O'REILLY, J P Region 2, Office of Director 1p 17306 087 24X Fiche 50-424, 83/02/17, 8302280136

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D D Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-434 SURRY POWER STATION, UNIT 3

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

DOCKET 50-435 SURRY POWER STATION, UNIT 4

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for CL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D D Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D D Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKETED ITEMS

3

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302010450 Requests extension of const completion dates until 840501 for Unit 1 & 870901 for Unit 2 Factors contributing to const delay listed
MILLS, L M Tennessee Valley Authority 83/01/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16981 312
24X Fiche 50-438, 83/01/26, 8302010450

8302030599 Forwards revised NRC review schedule for facilities Rev necessitated by delay in const Review schedule delayed approx 9 months DES will be issued after review resumed
NOVAH, T M Assistant Director for Licensing 83/02/01 PARRIS, H G
Tennessee Valley Authority 3pp 17013 336 24X
Fiche 50-438, 83/02/01, 8302030599

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090092 Generic Ltr 83-10E to all applicants w/B&W designed NSSB re resolution of TMI Action Item II K 3.9, "Automatic Trip of Reactor Coolant Pumps " Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consumers Power
Co 25pp 17298 316 24X Fiche 50-000, 83/02/08, 8302090092

8302250102 Notification of 830223 meeting w/B&W regulatory response group in Bethesda, MD to discuss small break LOCA procedures & maint of proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302250102

C Utility Environmental Report (ER), amends & correspondence

8302160183 Forwards response to 820713 ltr on Question 100 1 re summary of differences in environ effect discussed in environ rpt & environ hearings
MILLS, L M Tennessee Valley Authority 83/02/10 ADENAM, C
Licensing Branch 4 8pp 17163 015 24X Fiche 50-438, 83/02/10, 8302160183

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Inspection reports, IE Bulletins & correspondence

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150474 Ack receipt of 820913 & 830110 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts
80-438/82-18 & 80-439/82-18
VERRELLI, D M Division of Project & Resident Programs 83/01/31
PARRIS, H G Tennessee Valley Authority 1p 17157 075 24X
Fiche 50-438, 83/01/31, 8302150474

--8302150484 Responds to NRC 820726 ltr re violations noted in IE Insp Repts 50-438/82-18 & 50-439/82-18 Corrective actions lesson plan drafts for training program completed & reviewed within unit for content
MILLS, L M Tennessee Valley Authority 83/01/10 O'REILLY, J P
Region 2, Office of Director 2pp 17157 076 24X
Fiche 50-438, 83/01/31, 8302150474

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302150444 Revised final deficiency rept re overpressurization of makeup & purification piping & valves Initially reported on 820828 Valves will be visually examined for signs of distress & deficient valves replaced
MILLS, L M Tennessee Valley Authority 82/02/03 O'REILLY, J P
Region 2, Office of Director 2pp 17158 192 24X
Fiche 50-438, 82/02/03, 8302150444

8302010648 Fourth interim deficiency rept re engineering change review & handling Initially reported on 811215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution Bellefonte sampling under evaluation
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 16980 049 24X
Fiche 50-000, 83/01/19, 8302010648

8302010265 Final deficiency rept re deficient welds on cable tray supports Initially reported on 820908 Support mods scheduled for completion by 830707 Surveillance program revised to include preweld insp
MILLS, L M Tennessee Valley Authority 83/01/21 O'REILLY, J P
Region 2, Office of Director 2pp 16973 358 24X
Fiche 50-438, 83/01/21, 8302010265

8302010300 First interim deficiency rept re relief valves violating ASME Code Section III, Div 1, Section ND-3677 2 Initially reported on 821223 Condition could damage seal area coolers Condition under evaluation Next rept expected by 830705
MILLS, L M Tennessee Valley Authority 83/01/21 O'REILLY, J P
Region 2, Office of Director 2pp 16973 090 24X
Fiche 50-438, 83/01/21, 8302010300

8302010419 First interim deficiency rept re potential deterioration of isoprene gaskets on standby diesel generator Initially reported on 821217 Transamerica Delaval, Inc changed matl for drive element to neoprene Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16974 260 24X
Fiche 50-000, 83/01/24, 8302010419

8302010659 Second interim deficiency rept re pipe supports Initially reported on 811215 Support design load drawings, having "O" in thermal movement column, revised to remove erroneous info. Next rept expected by 830715
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16980 058 24X
Fiche 50-438, 83/01/24, 8302010659

8302010664 Third interim deficiency rept re failed valve control unit Initially reported on 820727 Control unit replaced Next rept expected by 830727 Deficiency also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16980 061 24X
Fiche 50-438, 83/01/24, 8302010664

DOCKETED ITEMS

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 info on Yellow Creek or Hartsville deferred until final decision re projects Next rept expected by 830531 MILLS, L M Tennessee Valley Authority 83/01/26 O'REILLY, J P Region 2, Office of Director 3pp 16974 037 24X Fiche 50-000, 83/01/26, 8302010215

8302010631 Revised Final Deficiency Rept re solid state ac voltage relays Initially reported on 810102 Delivery date of modified relays will be 830708 Corrective actions will be completed by 830817 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 16980 025 24X Fiche 50-438, 83/01/27, 8302010631

8302030542 Second interim deficiency rept re lack of environ qualification of equipment in auxiliary bldg Initially reported on 820422 Engineering Change Notice 1579 initiated Next rept by 830518 MILLS, L M Tennessee Valley Authority 83/01/27 O'REILLY, J P Region 2, Office of Director 2pp 17006 287 24X Fiche 50-438, 83/01/27, 8302030542

8302030490 First interim deficiency rept re backflow not considered for ERCH booster pump shutoff Initially reported on 821230 Pipe design drawings revised, Next rept by 830506 MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17007 305 24X Fiche 50-438, 83/01/28, 8302030490

8302030529 First interim deficiency rept re power for emergency air cleanup units after loss of offsite power Engineering Change Notice 1690 initiated to correct control logic Next rept expected by 831021 MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17007 161 24X Fiche 50-438, 83/01/28, 8302030529

8302030558 Third interim deficiency rept re design problems w/steam generators Initially reported on 820830 B&W to install external auxiliary feedwater header at top of steam generators Also reported per Part 21 Next rept by 831024 MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17006 230 24X Fiche 50-438, 83/01/28, 8302030558

8302140001 Fourth interim deficiency rept re nonconforming weldolets on Natl Valve & Mfg Co spool pieces Initially reported on 820224 Calculations performed per ASME & ANSI B31.1 piping codes Next rept due by 830606 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/02/03 O'REILLY, J P Region 2, Office of Director 2pp 17142 164 24X Fiche 50-438, 83/02/03, 8302140001

8302140018 Final deficiency rept re weld defects on 24 mitered joints on 12 header supports used on reactor bldg cooler coils Initially reported on 820621 Supports returned to manufacturer Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/02/03 O'REILLY, J P Region 2, Office of Director 2pp 17141 192 24X Fiche 50-438, 83/02/03, 8302140018

8302150271 Fourth interim deficiency rept re errors in NERC program distributed by AAA Technology Initially reported on 820409 WERC users manual made controlled computer program document Next rept due by 830422 MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P Region 2, Office of Director 3pp 17148 320 24X Fiche 50-000, 83/02/07, 8302150271

8302150572 Eighth interim deficiency rept re seismic qualification of B&W equipment in TVA panels Initially reported on 801124. Affected equipment being requalified by Bailey Meter Co through B&W Next rept due by 830909 MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P Region 2, Office of Director 2pp 17156 143 24X Fiche 50-438, 83/02/07, 8302150572

8302150583 Sixth Interim Deficiency Rept 50-438/81-61 re reactor coolant impeller-to-shaft mismatch Initially reported on 810917 Pump #P1A2 shaft & impeller returned to vendor for remanishing Next rept to be submitted by 830819 MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P Region 2, Office of Director 2pp 17156 122 24X Fiche 50-438, 83/02/07, 8302150583

8302150192 Addl supplemental info to interim deficiency rept re unacceptable replacement for component cooling water pump shaft Initially reported on 820301 Corrective actions delayed until 830419 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/02/08 O'REILLY, J P Region 2, Office of Director 1p 17147 161 24X Fiche 50-438, 83/02/08, 8302150192

8302150376 First interim deficiency rept re defective sequencer control cards from Consolidated Control Corp Initially reported on 830112 Failed cards returned to vendor for insp Next rept will be provided by 840206 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/02/08 O'REILLY, J P Region 2, Office of Director 2pp 17158 103 24X Fiche 50-438, 83/02/08, 8302150376

8302150473 First interim deficiency rept re GE electric motors supplied by Ingersoll Rand exceeding rated load Initially reported on 830110 Calibr oscillograph measurement will be sent to supplier Next rept will be submitted by 830725 MILLS, L M Tennessee Valley Authority 83/02/08 O'REILLY, J P Region 2, Office of Director 2pp 17158 105 24X Fiche 50-438, 83/02/08, 8302150473

8302170207 Third interim deficiency rept re failure of Basics Inflow, Inc butterfly valve seats Initially reported on 820511 Addl deficiencies discovered during investigation Next rept will be submitted by 830531 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/02/08 O'REILLY, J P Region 2, Office of Director 2pp 17179 084 24X Fiche 50-438, 83/02/08, 8302170207

8302170215 Supplemental final deficiency rept re mislocation of flow characteristic indicators Initially reported on 810109 Unit 1 corrective action will be completed by 830331 Use of 3/4-inch 3,000-lb threadolets approved MILLS, L M Tennessee Valley Authority 83/02/09 O'REILLY, J P Region 2, Office of Director 1p 17179 082 24X Fiche 50-438, 83/02/09, 8302170215

8302170342 Forwards list of deficiencies determined to have no adverse impact on safe operations of plants & were removed from 10CFR50.55(a) status MILLS, L M Tennessee Valley Authority 83/02/10 O'REILLY, J P Region 2, Office of Director 2pp 17184 108 24X Fiche 50-438, 83/02/10, 8302170342

8302220245 Supplemental final deficiency rept re makeup & purification letdown cooler supports Initially reported on 800226 Completion date for corrective actions revised to 830601 MILLS, L M Tennessee Valley Authority 83/02/14 O'REILLY, J P Region 2, Office of Director 1p 17230 131 24X Fiche 50-438, 83/02/14, 8302220245

8302230296 Final deficiency rept re inadequate installation of miscellaneous structural steel Initially reported on 821008 Extensive craft training program implemented & personnel retrained in following GC procedures & design documents MILLS, L M Tennessee Valley Authority 83/02/15 O'REILLY, J P Region 2, Office of Director 3pp 17244 300 24X Fiche 50-438, 83/02/15, 8302230296

8302230219 Interim deficiency rept re unqualified auxiliary bldg fuel handling zone ventilation fans Initially reported on 810506 Review of manufacturers seismic qualification rept on coils & coil support mods in progress Next rept by 830805 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17245 146 24X Fiche 50-438, 83/02/16, 8302230219

8302230234 Fifth interim deficiency rept re analysis for loss of feedwater event Initially reported on 810316 Preliminary review of B&W rept indicates FSAR analysis conservative Next rept expected by 830624 Also reported under Part 21 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17245 126 24X Fiche 50-438, 83/02/16, 8302230234

8302230330 Second interim deficiency rept re undersigned snubber on main feedwater piping in valve Room 8 Initially reported on 821013 Util documenting completed analysis & reviewing rigorous analysis problems Next rept expected by 830527 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17247 360 24X Fiche 50-438, 83/02/16, 8302230330

8302230645 First interim deficiency rept re improperly qualified nozzle loads Initially reported on 830224 Piping analysis packages reviewed to ensure nozzle qualifications performed according to mfg specs Next rept expected by 830427 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17255 215 24X Fiche 50-438, 83/02/16, 8302230645

8302280178 Final deficiency rept re grease in reactor bldg cooling fans Initially reported on 810128 Caused by hardened grease in bearings. Fan motors cleaned & bearings relubricated Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/02/17 O'REILLY, J P Region 2, Office of Director 2pp 17305 266 24X Fiche 50-438, 83/02/17, 8302280178

DOCKETED ITEMS

3

8302280335 First interim deficiency rept re makeup & purification
letdown cooler inlet/outlet piping reversal Initially
reported on 830124 Letdown coolers being inverted requiring
rev of design activities Next rept expected by 831214
MILLS, L M Tennessee Valley Authority 83/02/18 O'REILLY, J P
Region 2, Office of Director 2pp 17313 042 24X
Fiche 50-438, 83/02/18, 8302280335

8302280499 First interim deficiency rept re tube leaks in component
cooling water HXs Initially reported on 830124 Cause of
leaks under investigation by B&W Next rept expected by
830603
MILLS, L M Tennessee Valley Authority 83/02/18 O'REILLY, J P
Region 2, Office of Director 3pp 17309 062 24X
Fiche 50-438, 83/02/18, 8302280499

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
for OL, NSS vendors, reactor vendors & AE re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302010450 Requests extension of const completion dates until 840501
for Unit 1 & 870501 for Unit 2 Factors contributing to const
delay listed
MILLS, L M Tennessee Valley Authority 83/01/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 16981 312
24X Fiche 50-438, 83/01/26, 8302010450

8302030599 Forwards revised NRC review schedule for facilities Rev
necessitated by delay in const Review schedule delayed
approx 9 months DES will be issued after review resumed
NOVAR, T M Assistant Director for Licensing 83/02/01 PARRIS, H O
Tennessee Valley Authority 3pp 17013 336 24X
Fiche 50-438, 83/02/01, 8302030599

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PHRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090092 Generic Ltr 83-10E to all applicants w/B&W designed NSSB
re resolution of TMI Action Item II K 3 B, "Automatic Trip
of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consumers Power
Co 25pp 17298 316 24X Fiche 50-000, 83/02/08, 8302090092

8302250102 Notification of 830223 meeting w/B&W regulatory response
group in Bethesda, MD to discuss small break LOCA procedures
& maint of proper steam generator water level
VAN ULJET, J Operating Reactors Branch 4 83/02/17 STOLZ, J
Operating Reactors Branch 4 3pp 17303 098 24X
Fiche 50-000, 83/02/17, 8302250102

C Utility Environmental Report (ER), amends & correspondence

8302160183 Forwards response to 820713 ltr on Question 100 i re
summary of differences in environ effect discussed in
environ rept & environ hearings
MILLS, L M Tennessee Valley Authority 83/02/10 ADENSAM, E
Licensing Branch 4 8pp 17163 015 24X Fiche 50-438, 83/02/10,
8302160183

F. Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche: 50-000, 83/02/01, 8301210340

G Inspection reports, IE Bulletins & correspondence

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary
Containment Electrical Penetration Assemblies" & NRC
821203 ltr Bunker-Ramo Co electrical penetration assemblies
not in use at facilities,
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H32C
Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302150474 Ack receipt of 820913 & 830110 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-438/82-18 & 50-439/82-18
VERRELLI, D M Division of Project & Resident Programs 83/01/31
PARRIS, H O Tennessee Valley Authority 1p 17157 075 24X
Fiche 50-438, 83/01/31, 8302150474

--8302150484 Responds to NRC 820726 ltr re violations noted in IE Insp
Repts 50-438/82-18 & 50-439/82-18 Corrective actions lesson
plan drafts for training program completed & reviewed
within unit for content.
MILLS, L M Tennessee Valley Authority 83/01/10 O'REILLY, J P
Region 2, Office of Director 2pp 17157 076 24X
Fiche 50-438, 83/01/31, 8302150474

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

G Reportable occurrences, LERs & related correspondence

8302010648 Fourth interim deficiency rept re engineering change review
& handling, initially reported on 811215 Watts Bar Deficiency
2 not applicable Deficiencies 3 & 4 require addl sampling
before resolution Bellefonte sampling under evaluation.
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 16980 049 24X
Fiche 50-000, 83/01/19, 8302010648

8302010265 Final deficiency rept re deficient welds on cable tray
supports Initially reported on 820908 Support made scheduled
for completion by 830707 Surveillance program revised to
include preweld insp
MILLS, L M Tennessee Valley Authority 83/01/21 O'REILLY, J P
Region 2, Office of Director 2pp 16973 358 24X
Fiche 50-438, 83/01/21, 8302010265

8302010300 First interim deficiency rept re relief valves violating
ASME Code Section III, Div 1, Section ND-3677.2 Initially
reported on 821223 Condition could damage seal area coolers.
Condition under evaluation Next rept expected by 830705
MILLS, L M Tennessee Valley Authority 83/01/21 O'REILLY, J P
Region 2, Office of Director 2pp 16973 090 24X
Fiche 50-438, 83/01/21, 8302010300

DOCKETED ITEMS

8302010419 First interim deficiency rept re potential deterioration of isoprene gaskets on standby diesel generator Initially reported on 821217 Transamerica Delaval, Inc changed matl for drive element to neoprene Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 16974 260 24X Fiche 50-000, 83/01/24, 8302010419

8302010500 Second interim deficiency rept re linear indications in NAVCO spool pieces Initially reported on 820924 Evaluation in progress Next rept by 830518 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 16977 032 24X Fiche 50-439, 83/01/24, 8302010500

8302010659 Second interim deficiency rept re pipe supports Initially reported on 811215 Support design load drawings, having "0" in thermal movement column, revised to remove erroneous info Next rept expected by 830715 MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 16980 098 24X Fiche 50-438, 83/01/24, 8302010659

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 Info on Yellow Creek or Hartsville deferred until final decision re projects Next rept expected by 830531 MILLS, L M Tennessee Valley Authority 83/01/26 O'REILLY, J P Region 2, Office of Director 3pp 16974 037 24X Fiche 50-000, 83/01/26, 8302010215

8302010631 Revised Final Deficiency Rept re solid state ac voltage relays Initially reported on 810102 Delivery date of modified relays will be 830708 Corrective actions will be completed by 830817 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/01/27 O'REILLY, J P Region 2, Office of Director 1p 16980 025 24X Fiche 50-438, 83/01/27, 8302010631

8302030542 Second interim deficiency rept re lack of environ qualification of equipment in auxiliary bldg Initially reported on 820422 Engineering Change Notice 1579 initiated Next rept by 830518 MILLS, L M Tennessee Valley Authority 83/01/27 O'REILLY, J P Region 2, Office of Director 2pp 17006 287 24X Fiche 50-438, 83/01/27, 8302030542

8302030490 First interim deficiency rept re backflow not considered for ERGW booster pump shutoff Initially reported on 821230 Pipe design drawings revised Next rept by 830506 MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17007 305 24X Fiche 50-438, 83/01/28, 8302030490

8302030529 First interim deficiency rept re power for emergency air cleanup units after loss of offsite power Engineering Change Notice 1690 initiated to correct control logic Next rept expected by 831021 MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17007 161 24X Fiche 50-438, 83/01/28, 8302030529

8302030558 Third interim deficiency rept re design problems w/steam generators Initially reported on 820830 B&W to install external auxiliary feedwater header at top of steam generators Also reported per Part 21 Next rept by 831024 MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17006 230 24X Fiche 50-438, 83/01/28, 8302030558

8302140094 Final deficiency rept re corrosion of Transamerica Delaval diesel generator control panel Initially reported on 810320 Replacement voltage regulation panel will be reinstalled by 830817 & Procedure BNP-GCP-1 3 initiated MILLS, L M Tennessee Valley Authority 83/02/03 O'REILLY, J P Region 2, Office of Director 2pp 17141 210 24X Fiche 50-439, 83/02/03, 8302140094

8302150271 Fourth interim deficiency rept re errors in HERCO program distributed by AAA Technology Initially reported on 820409 HERCO users manual made controlled computer program document Next rept due by 830422 MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P Region 2, Office of Director 3pp 17148 320 24X Fiche 50-000, 83/02/07, 8302150271

8302150572 Eighth interim deficiency rept re seismic qualification of B&W equipment in TVA panels Initially reported on 801124 Affected equipment being requalified by Bailey Meter Co through B&W Next rept due by 830909 MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P Region 2, Office of Director 2pp 17156 143 24X Fiche 50-438, 83/02/07, 8302150572

8302170207 Third interim deficiency rept re failure of Basics Inflow, Inc butterfly valve seats Initially reported on 820511 Addl deficiencies discovered during investigation Next rept will be submitted by 830531 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 83/02/08 O'REILLY, J P Region 2, Office of Director 2pp 17179 084 24X Fiche 50-438, 83/02/08, 8302170207

8302170215 Supplemental final deficiency rept re mislocation of flow characteristic indicators Initially reported on 810109 Unit 1 corrective action will be completed by 830331 Use of 3/4-inch 3,000-lb threaded bolts approved MILLS, L M Tennessee Valley Authority 83/02/09 O'REILLY, J P Region 2, Office of Director, 1p 17179 082 24X Fiche 50-438, 83/02/09, 8302170215

8302170342 Forwards list of deficiencies determined to have no adverse impact on safe operations of plants & were removed from 10CFR50.55(e) status MILLS, L M Tennessee Valley Authority 83/02/10 O'REILLY, J P Region 2, Office of Director 2pp 17184 108 24X Fiche 50-438, 83/02/10, 8302170342

8302230296 Final deficiency rept re inadequate installation of miscellaneous structural steel Initially reported on 821008 Extensive craft training program implemented & personnel retrained in following QC procedures & design documents MILLS, L M Tennessee Valley Authority 83/02/15 O'REILLY, J P Region 2, Office of Director 3pp 17244 300 24X Fiche 50-438, 83/02/15, 8302230296

8302230219 Interim deficiency rept re unqualified auxiliary bldg fuel handling zone ventilation fans Initially reported on 810506 Review of manufacturers seismic qualification rept on coils & coil support mods in progress Next rept by 830805 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17245 146 24X Fiche 50-438, 83/02/16, 8302230219

8302230234 Fifth interim deficiency rept re analysis for loss of feedwater event Initially reported on 810316 Preliminary review of B&W rept indicates FBAR analysis conservative Next rept expected by 830624 Also reported under Part 21 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17245 126 24X Fiche 50-438, 83/02/16, 8302230234

8302230330 Second interim deficiency rept re underdesigned snubber on main feedwater piping in valve Room B Initially reported on 821013 Util documenting completed analysis & revising rigorous analysis problems Next rept expected by 830527 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17247 360 24X Fiche 50-438, 83/02/16, 8302230330

8302230645 First interim deficiency rept re improperly qualified nozzle loads Initially reported on 830224 Piping analysis packages reviewed to ensure nozzle qualifications performed according to mfg specs Next rept expected by 830427 MILLS, L M Tennessee Valley Authority 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 17255 215 24X Fiche 50-438, 83/02/16, 8302230645

8302280178 Final deficiency rept re grease in reactor bldg cooling fans Initially reported on 810128 Caused by hardened grease in bearings Fan motors cleaned & bearings relubricated. Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/02/17 O'REILLY, J P Region 2, Office of Director 2pp 17305 266 24X Fiche 50-438, 83/02/17, 8302280178

8302280335 First interim deficiency rept re makeup & purification letdown cooler inlet/outlet piping reversal Initially reported on 830124 Letdown coolers being inverted requiring rev of design activities Next rept expected by 831214 MILLS, L M Tennessee Valley Authority 83/02/18 O'REILLY, J P Region 2, Office of Director 2pp 17313 042 24X Fiche 50-438, 83/02/18, 8302280335

8302280499 First interim deficiency rept re tube leaks in component cooling water HXs Initially reported on 830124 Cause of leaks under investigation by B&W Next rept expected by 830603 MILLS, L M Tennessee Valley Authority 83/02/18 O'REILLY, J P Region 2, Office of Director 3pp 17309 062 24X Fiche 50-438, 83/02/18, 8302280499

V Operator Examinations

8301310203 Generic Ltr 83-04 to all power reactor licensees, applicants for DLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302070146 Addl response to FOIA request for five categories of documents Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) Info re Item 4 available in PDR No documents re Item 5 located
FELTON, J H Division of Rules and Records 82/12/02 HIATT, S
Ohio Citizens for Responsible Energy 4pp 17045 325 24X
Fiche 50-000, 82/12/02, 8302070146

8302170482 Board Notification 83-1 forwards BNL draft rept, "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach"
EISENHUT, D O Division of Licensing FIN A-3397 83/02/01
PALADINO, N J Commissioners 134pp 17203 309 24X
Fiche 50-000, 83/02/01, 8302170482

8302240112 Forwards request for addl info re plant-specific application of BWR Owners Group safety/relief valve operability test results per TMI Action Plan Item II D 1 Response requested within 7 days of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/02/04 EDELMAN, M R
Cleveland Electric Illuminating Co 4pp 17268 299 24X
Fiche 50-440, 83/02/04, 8302240112

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re BER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Ouidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302240319 Summary of 830203 meeting w/applicant in Bethesda, MD re seismic/dynamic equipment qualification, pump & valve qualification & environ equipment qualification List of participants encl
STEFANO, J J Licensing Branch 1 83/02/09 Licensing Branch 1
5pp 17284 341 24X Fiche 50-440, 83/02/09, 8302240319

8302240123 Requests updated description of QA program for design & const indicating revs relative to program reviewed & accepted by NRC & documented in PSAR
YOUNGBLOOD, B J Licensing Branch 1 83/02/10 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 17268 270 24X
Fiche 50-440, 83/02/10, 8302240123

8302230719 Informs of intent to submit updated description of corporate nuclear QA program used for design & const of plants in response to 830210 ltr Info will be incorporated into FBAR Chapter 17.1
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/17
YOUNGBLOOD, B J Licensing Branch 1 1p 17248 342 24X
Fiche 50-440, 83/02/17, 8302230719

8302280259 Forwards Rev 1 to NEDE-24326-1-P, "OE Environ Qualification Program" Rev withheld (ref 10CFR2 790)
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/22
YOUNGBLOOD, B J Licensing Branch 1 6pp 17310 356 24X
Fiche 50-440, 83/02/22, 8302280259

E NRC Safety Evaluation Report (SER), suppl & correspondence

8302040400 Forwards draft FBAR changes re SER mods to standby liquid control sys, scram discharge sys & new redundant reactivity control sys Changes will be incorporated into next FBAR amend
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/26
YOUNGBLOOD, B J Licensing Branch 1 78pp 17018 078 24X
Fiche 50-440, 83/01/26, 8302040400

8302070325 Forwards update of program to resolve concerns raised by J Humphrey, w/results of completed action plans, per BER
Outstanding Issue B on Mark III containment sys issues
Schedule for completion of unresolved items noted
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/26
YOUNGBLOOD, B J Licensing Branch 1 81pp 17030 233 24X
Fiche 50-440, 83/01/26, 8302070325

8302040038 Forwards draft FBAR pages for App 3A & 3B Change provides description of safety relief valve & LOCA-related hydrodynamic load definition for Mark III containment re
BER Outstanding Issue 9, "Pool Dynamic Loads"
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 75pp 17021 001 24X
Fiche 50-440, 83/01/31, 8302040038

8302070301 Forwards response to BER Confirmatory Issue 21 re suppression pool temp limits Response addresses plant-specific info & assumptions used in analyses to meet NUREG-0783 requirements & criteria
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 16pp 17029 097 24X
Fiche 50-440, 83/01/31, 8302070301

8302070313 Forwards addl info re BER Outstanding Issue 12 on manual initiation of ESF sys, per 821104 request Design provisions consistent w/IEEE-279 guidelines & meet 10CFR50 requirements
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 8pp 17029 133 24X
Fiche 50-440, 83/01/31, 8302070313

8302100274 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0887 802
83/01/31 60pp 17135 286 24X Fiche 50-440, 83/01/31, 8302100274.

8302190509 Documents commitment to provide fire protection features for portable communication sys fixed repeaters, per BER
Confirmatory Issue 37 Repeaters separated & Halon fire suppression sys provided
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/08
YOUNGBLOOD, B J Licensing Branch 1 1p 17156 333 24X
Fiche 50-440, 83/02/08, 8302190509

8302280208 Responds to 830105 ltr re BER Confirmatory Issue 14 on overheating of gadolinia fuel pellets GE rept verified that fuel melting not expected to occur during normal steady-state operation or during whole core anticipated transient
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/18
YOUNGBLOOD, B J Licensing Branch 1 1p 17312 161 24X
Fiche 50-440, 83/02/18, 8302280208

F Security, medical, emergency & fire protection plans

8302070196 Advises of delay in submittal of revised emergency plan, due to extensive NRC-required revs & need for consistency w/offsite plans Revised emergency plan will be submitted by 830301
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 1p 17031 307 24X
Fiche 50-440, 83/01/31, 8302070196

8302100340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8302100340

8302190509 Documents commitment to provide fire protection features for portable communication sys fixed repeaters, per BER
Confirmatory Issue 37 Repeaters separated & Halon fire suppression sys provided.
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/08
YOUNGBLOOD, B J Licensing Branch 1 1p 17156 333 24X
Fiche 50-440, 83/02/08, 8302190509

8302160192 Forwards final SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982
KEPLER, J G Region 3, Office of Director, 83/02/10 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 17162 183 24X
Fiche 50-440, 83/02/10, 8302160192

--8302160201 SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982 Licensee rating in containment & other safety-related structures improved based on ability to identify & promptly correct deficiencies QA program adequate
* Region 3, Office of Director 83/02/10. 21pp 17162 185 24X
Fiche 50-440, 83/02/10, 8302160192

DOCKETED ITEMS

--8302160209 Comments on 830114 meeting re Oct 1981 - Sept 1982 SALP evaluation Health physics program strengthened substantially since insp Strong mgt attention paid to staffing & experience levels
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/21
KEPPLER, J Q Region 3, Office of Director 4pp 17162 206 24X
Fiche 50-440, 83/02/10, 8302160192

8302280206 Submits info re emergency operations facility (EOF) per J Stefano 830215 telcon request EOF located approx 0.4 miles from Facility
EDELMAN, M R Commonwealth Edison Co 83/02/17 YOUNGBLOOD, B J
Licensing Branch 1 1p 17312 162 24X Fiche 50-440, 83/02/17, 8302280206

G Adjudicatory correspondence

8302010472 Memorandum & Order denying until 830106 motion for reconsideration of ASLB 821222 Memorandum & Order on summary disposition of Issue 3 Claim of surprise w/o merit
BLOCH, P B, KLINE, J R, BRIGHT, D O Atomic Safety and Licensing Board Panel 83/01/28
Cleveland Electric Illuminating Co 13pp
16982 046 24X Fiche 50-440, 83/01/28, 8302010472

8302070601 Requests to make limited appearance statement at OL hearings.
RANDALL, B Affiliation Unknown 83/01/29 NRC - No Detailed
Affiliation Given 1p 17034 280 24X Fiche 50-440, 83/01/29, 8302070601

8302080220 Requests to make limited appearance statement at OL hearings
OLBRIQ, R Affiliation Unknown 83/01/30 Docketing & Services
Branch 1p 17037 268 24X Fiche 50-440, 83/01/30, 8302080220

8302070555 Third set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw, Pittman, Potts & Trowbridge 83/01/31 Ohio Citizens for Responsible Energy 19pp 17034 125 24X Fiche 50-440, 83/01/31, 8302070555

8302080234 Ninth set of interrogatories Certificate of Svc encl Related correspondence.
HIATT, B L Ohio Citizens for Responsible Energy 83/01/31
Cleveland Electric Illuminating Co 14pp 17037 191 24X
Fiche 50-440, 83/01/31, 8302080234

8302080269 Ninth set of interrogatories Certificate of Svc encl Related correspondence
HIATT, B L Ohio Citizens for Responsible Energy 83/01/31
Office of the Executive Legal Director 9pp 17036 348 24X
Fiche 50-440, 83/01/31, 8302080269

8302080166 Requests to make limited appearance statement at OL hearings
TINIAHO, J C Sierra Club 83/02/02 Docketing & Services
Branch 1p 17037 221 24X Fiche 50-440, 83/02/02, 8302080166

8302040252 Answers to 820913 sixth set of interrogatories & ASLB 821223 questions Certificate of Svc encl
CUTCHIN, J H Hearing Branch 4 83/02/03 Ohio Citizens for Responsible Energy 65pp 17019 319 24X Fiche 50-440, 83/02/03, 8302040252

8302080217 Requests to make limited appearance statement at OL hearings
PINZORE, C R Affiliation Unknown 83/02/03 Docketing & Services
Branch 1p 17037 274 24X Fiche 50-440, 83/02/03, 8302080217

8302140009 Response in opposition to NRC 830114 motion for summary disposition of Issue 9 NRC failed to meet burden of proof Issue of environ qualification within ASLB jurisdiction Certificate of Svc encl
HIATT, B L Ohio Citizens for Responsible Energy 83/02/07 9pp
17141 100 24X Fiche 50-440, 83/02/07, 8302140009

--8302140016 Supplemental response to second set of interrogatories & request for production of documents Certificate of Svc encl
HIATT, B L Ohio Citizens for Responsible Energy 83/02/07
Cleveland Electric Illuminating Co 51pp 17141 109 24X
Fiche 50-440, 83/02/07, 8302140009

8302140025 Requests to make limited appearance statement at OL hearing
RICHMOND, S O International Brotherhood of Electrical Workers
83/02/07 Docketing & Services Branch 1p 17141 179 24X
Fiche 50-440, 83/02/07, 8302140025

8302170233 Requests to make limited appearance statement at OL hearings
HOFFMAN, M V Affiliation Unknown 83/02/07 NRC - No Detailed
Affiliation Given 1p 17187 101 24X Fiche 50-440, 83/02/07, 8302170233

8302100202 Answer supporting NRC 830114 motion for summary disposition of Issue 9 re radiation-induced degradation of polymers (ARC final rule on environ qualification of electrical equipment compliance schedules remove issue as matter of controversy)
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/02/08 Atomic Safety and Licensing Board Panel 4pp 17112 311 24X Fiche 50-440, 83/02/08, 8302100202

--8302100209 Affidavit of S Kasturi supporting NRC motion for summary disposition of Issue 9 No reasonable basis exists to believe radiation dose rate effects on polymers will induce failures in safety-related equipment Prof qualifications encl
KASTURI, S Cleveland Electric Illuminating Co KASTURI, S EOS Nuclear, Inc 83/02/04 33pp 17112 315 24X
Fiche 50-440, 83/02/08, 8302100202

--8302100213 Affidavit of DR Green supporting NRC motion for summary disposition of Issue 9 Surveillance & maint program includes features that enable identification of equipment degradation Certificate of Svc encl
GREEN, D R Cleveland Electric Illuminating Co 83/02/04 10pp
17112 351 24X Fiche 50-440, 83/02/08, 8302100202

8302250144 Advises of deadline extension until 830222 to respond to Citizens for Responsible Energy ninth set of interrogatories
YOUNGBLOOD, B J Licensing Branch 1 83/02/08 BEHLINGER, C H & Co Performance Branch LIAH, B D Materials Engineering Branch 1p 17299 355 24X Fiche 50-440, 83/02/08, 8302250144

8302170264 Requests to make limited appearance statement at OL hearing
DONAHUE, M United Assoc of Journeyman & Apprentices of Plumbers & Pipe Fitters Industry 83/02/10 Docketing & Services Branch 1p 17178 228 24X Fiche 50-440, 83/02/10, 8302170264

8302090249 Requests to make limited appearance statement at OL hearings
PALUMBO, R Affiliation Unknown 83/02/11 Docketing & Services
Branch 1p 17070 238 24X Fiche 50-440, 83/02/11, 8302090249

8302170296 Requests to make limited appearance statement at OL hearing
MORGAN, M J United Assoc of Journeyman & Apprentices of Plumbers & Pipe Fitters Industry 83/02/11 Office of the Secretary of the Commission 1p 17178 207 24X Fiche 50-440, 83/02/11, 8302170296

8302160353 Requests to make limited appearance statement at OL hearings
GLADDING, H Affiliation Unknown 83/02/12 NRC - No Detailed
Affiliation Given 1p 17167 308 24X Fiche 50-440, 83/02/12, 8302160353

8302170214 Requests to make limited appearance statement at OL hearing per 10CFR2 715
SMITH, L E United Assoc of Journeyman & Apprentices of Plumbers & Pipe Fitters Industry 83/02/12 Office of the Secretary of the Commission 1p 17179 083 24X Fiche 50-440, 83/02/12, 8302170214

8302170206 Confirms 830214 telcon & provides info re obtaining interrogatories on Issues 13-15 Copy of interrogatories will be hand delivered Postal Svc deserves blame for nondelivery w/svc list
SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/02/14 HIATT, B L Ohio Citizens for Responsible Energy 2pp 17179 087 24X
Fiche 50-440, 83/02/14, 8302170206

8302180438 Requests to make limited appearance statement at OL hearings
GRUNTNER, C United Assoc of Journeyman & Apprentices of Plumbers & Pipe Fitters Industry 83/02/15 Docketing & Services Branch 1p 17215 019 24X Fiche 50-440, 83/02/15, 8302180438

8302230429 Requests to make limited appearance statement at OL hearings
MCINTYRE, S Affiliation Unknown 83/02/15 NRC - No Detailed
Affiliation Given 1p 17246 199 24X Fiche 50-440, 83/02/15, 8302230429

8302180479 Advises that NRC will voluntarily answer OH Citizens for Responsible Energy 830131 interrogatories re Issues 13, 14 & 15
CUTCHIN, J H Hearing Branch 4 83/02/17 BLOCH, P B, BRIGHT, D O, KLINE, J R Atomic Safety and Licensing Board Panel 1p 17210 350
Fiche 50-440, 83/02/17, 8302180479

DOCKETED ITEMS

3

8302230436 Requests to make limited appearance statement at DL hearings
BATTAGLIA, F Affiliation Unknown 83/02/17 Docketing & Services Branch 1p 17245 255 24X Fiche 50-440, 83/02/17, 8302230436

8302230580 Motion to strike refs to "synergistic effects" in OH Citizens for Responsible Energy 830207 response to NRC motion for summary disposition of Issue 9 re radiation induced degradation of polymers Certificate of Svc encl
SILBERO, J E Cleveland Electric Illuminating Co 81LBERO, J E Shaw, Pittman, Potts & Trowbridge 83/02/18 Atomic Safety and Licensing Board Panel 6pp 17257 095 24X Fiche 50-440, 83/02/18, 8302230580

8302250270 Requests to make limited appearance statement at DL hearing
SULLIVAN, J F, HOULEHAN, F M Intl Assoc of Heat & Frost Insulators & Asbestos Workers 83/02/18 Docketing & Services Branch 1p 17292 113 24X Fiche 50-440, 83/02/18, 8302250270

8302250244 Requests to make limited appearance statement at DL hearings
OENQVESE, J Affiliation Unknown 83/02/20 NRC - No Detailed Affiliation Given 1p, 17292 328 24X Fiche 50-440, 83/02/20, 8302250244

8302280160 Answer supporting NRC 830208 motion for deadline by which OH Citizens for Responsible Energy must specify scenario to be litigated under Issue B Concur in NRC arguments Certificate of Svc encl
SILBERO, J E Cleveland Electric Illuminating Co 81LBERO, J E Shaw, Pittman, Potts & Trowbridge 83/02/23 Atomic Safety and Licensing Board Panel 4pp 17306 039 24X Fiche 50-440, 83/02/23, 8302280160

8302280266 Forwards amend to FSAR filed w/NRC re standby liquid control sys Amend referenced in util 820813 ltr to NRC included in applicant 820820 answer to Sunflower Alliance second set of interrogatories w/o encl Related correspondence
SILBERO, J E Shaw, Pittman, Potts & Trowbridge 81LBERO, J E Cleveland Electric Illuminating Co 83/02/23 HIATT, B Ohio Citizens for Responsible Energy 2pp 17312 267 24X Fiche 50-440, 83/02/23, 8302280266

H General correspondence

8302040105 Responds to 821214 ltr commenting on potential propane leak from Lake Underground Storage Facility to Morton Salt Mine & effects on safe operation of nuclear plants Accidents at Morton Mine would have no ill effects on nuclear plants
YOUNGBLOOD, B J Licensing Branch 1 83/01/27 BIMBER, R Affiliation Unknown 2pp 17043 174 24X Fiche 50-440, 83/01/27, 8302040105

8302040456 Forwards R Bimber 821214 ltr re potential propane leak from Lake Underground Storage Facility to Morton Salt Mine & effects on nuclear plants Util requested to address any inconsistencies claimed FSAR will be updated or corrected
YOUNGBLOOD, B J Licensing Branch 1 83/01/31 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17042 237 24X Fiche 50-440, 83/01/31, 8302040456

K Utility Final Safety Analysis Report (FSAR) & amends

8212020091 Forwards Amend 10 to FSAR
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16274 176 24X Fiche 50-440, 82/11/23, 8212020091

--8212020098 Amend 10 to FSAR w/629 oversize drawings. Aperture cards are available in PDR
* Cleveland Electric Illuminating Co 82/11/29 420pp 16274. 179 24X Fiche 50-440, 82/11/23, 8212020091

8302170338 Forwards Amend 11 to FSAR Amend incorporates previously submitted responses to Environ Qualification Branch questions
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17184 181. 24X Fiche 50-440, 83/02/15, 8302170338

--8302170340 Amend 11 to FSAR.
* Cleveland Electric Illuminating Co 83/02/15 275pp 17184 184 24X Fiche. 50-440, 83/02/15, 8302170338.

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040071 Control complex bldg high strength bolting operation insp i testing checkoff sheet
CRAY, B PBI Industries. 77/08/08 1p 17045 149 24X Fiche 50-000, 82/12/30, 8302040039

--8302040076 Forwards util 800825 memo discussing allegation re improper sandblasting of containment liner plate Investigation underway LK Constcoct Co, Inc nonconformance rept encl
WILLIAMS, C Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/04 NORELIOUS, C Region 3, Chicago, Office of the Director 4pp 17045 150 24X Fiche 50-000, 82/12/30, 8302040039

--8302040101 Discusses allegations received by TV reporter re reactor biological shield & weld crack coverup Biological shield problems reported under 10CFR50.35(e) Cracked weld on 399-ft elevation could not be located Matters closed
WEIL, C H Region 3, Chicago, Office of the Director (81/03/01) 82/01/28 Region 3, Chicago, Office of the Director (81/03/01) 3pp 17045 211 24X Fiche: 50-000, 82/12/30, 8302040039.

--8302040107 Advises of 811202 telcon w/E Cory, reporter for HEWB-TV in Cleveland, re allegations concerning reactor biological shield & weld crack coverup
HARABITO, R J Office of Public Affairs 81/12/03 WARNICK, R Enforcement & Investigation Staff 1p 17045 214 24X Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance dat for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director. 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039.

--8302040168 Forwards CH Weil 820208 memo re allegation concerning Pullman Power Products mechanical subcontractor at facilities Allegor refused to provide NRC further info Assistance request form encl
WARNICK, R F Region 3, Office of Director. 82/02/09 NORELIOUS, C E Division of Engineering 3pp. 17045 271 24X Fiche 50-000, 82/12/30, 8302040039

--8302040178 Discusses allegation re Pullman Power Products welding activities, matl storage & maint, nonconformance repts, NDEs & piping Allegor refused to provide NRC further info
WEIL, C H Region 3, Office of Director 82/02/08 Region 3, Office of Director 3pp 17045 274 24X Fiche 50-000, 82/12/30, 8302040039

--8302040186 Discusses allegation re installation of diesel generator stator & rotor w/o approved procedures Field mod of procedure acceptable Case closed
WEIL, C H Region 3, Office of Director. 82/03/17 Region 3, Office of Director 2pp 17045 277 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPEBBARD, R L Division of Project & Resident Programs. 2pp 17045 279. 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche: 50-000, 82/12/30, 8302040039

--8302040355 Advises that insp of allegations re Pullman Power Products at facilities conducted per Region 3, Div of Engineering & Technical Program 820209 request IE Insp Repts 50-440/82-03 & 50-441/82-03 issued. Insp evaluation encl
WEIL, C H Region 3, Office of Director 82/07/08 Region 3, Office of Director. 3pp 17045 274 24X Fiche. 50-000, 82/12/30, 8302040039

DOCKETED ITEMS

- B302040373 Forwards DD Wilt B20514 ltr for response, addressing potential damage to piping between cooling tower & turbine condenser at facility investigation unwarranted
FOSTER, J E Region 3, Office of the Director 82/07/21
NORELIUS, C E Division of Engineering 1p 17045 299 24X
Fiche 50-000, 82/12/30, B302040039
- B302040378 Evaluation of B21011-12 insp (IE Insp Repts 50-440/B2-12 & 50-441/B2-11)
YIN, I Region 3, Office of the Director 82/10/13 3pp 17045 301
24X Fiche 50-000, 82/12/30, B302040039
- B302040381 Responds to B20514 ltr expressing concern re piping between cooling towers & turbine condensers at facility Piping is not safety-related & does not come under NRC jurisdiction or insp program
KEPPLER, J O Region 3, Office of the Director 82/08/20 WILT, D D Wegman, Hessler & Vandenburg 1p 17045 304 24X
Fiche 50-000, 82/12/30, B302040039
- B302040386 Forwards MR Naidu B20624 memo to CE Norelius re flammable matl used in Class IE switchgear Plan & schedule for action required by B20924
DAVIS, A B Division of Project & Resident Programs 82/08/25
Division of Engineering 1p 17045 305 24X
Fiche 50-000, 82/12/30, B302040039
- B302040389 Evaluation of B21012-13 insp (IE Insp Repts 50-440/B2-13 & 50-441/B2-12)
DEBTHANN, M J Region 3, Office of the Director 82/10/14 2pp 17045 310 24X Fiche 50-000, 82/12/30, B302040039
- B302040389 Forwards JO Keppler 790524 response to ltr to Senator Hetzenbaum re shoddy workmanship at facilities Matter closed per 790522 discussion Personal info deleted
NORELIUS, C E Region 3, Chicago, Office of the Director 79/05/30 WARD, W J Office of Inspection & Enforcement, Office of the Director 1p 17045 312 24X Fiche 50-000, 82/12/30, B302040039
- B302040395 Discusses allegations re electrical work at facilities Unresolved items re conduit reaming documented in IE Insp Repts 50-440/B2-16 & 50-441/B2-15 No basis found for full investigation Personal info deleted Related info encl
FOSTER, J E Region 3, Chicago, Office of the Director (81/03/01) 81/01/28 Region 3, Chicago, Office of the Director (81/03/01) 7pp 17045 320 24X Fiche 50-000, 82/12/30, B302040039
- B302040396 Forwards allegation ltr received by licensee from former electrical inspector at facilities Individual has not contacted NRC W/o encl
WILLIAMS, C C Region 3, Chicago, Office of the Director 80/06/23 NORELIUS, C E Region 3, Chicago, Office of the Director 1p 17045 327 24X Fiche 50-000, 82/12/30, B302040039
- B302040405 Forwards IE Insp Repts 50-440/B2-27 & 50-441/B2-27, per 801222 & 23 telcons Personal info deleted W/o encl
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01) 81/01/28 Affiliation Unknown 1p 17045 342 24X
Fiche 50-000, 82/12/30, B302040039
- B302040408 Forwards IE Insp Repts 50-440/B2-27 & 50-441/B2-27 re allegation concerning defective weld & C Well transcribed notes No further action planned & matter considered closed Personal info deleted W/o encl
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01) 81/01/28 Region 3, Chicago, Office of the Director (81/03/01) 1p 17045 343 24X Fiche 50-000, 82/12/30, B302040039
- B302040414 Forwards RN Gardner B11005 memo to CC Williams re allegation concerning reactor vessel inner steel No basis found for investigation No further action planned & matter considered closed Personal info deleted
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01) 81/10/15 Region 3, Chicago, Office of the Director (81/03/01) 1p 17045 347 24X Fiche 50-000, 82/12/30, B302040039
- B302040421 Informs of allegation re reactor vessel inner steel Stainless steel welded to cover defective paint/coating Steel tensile strength ruined during welding process Personal info deleted
GARDNER, R M Region 3, Chicago, Office of the Director (81/03/01) 81/10/05 WILLIAMS, C C Engineering Inspection Branch 1p 17045 348 24X Fiche 50-000, 82/12/30, B302040039
- B302040428 Discusses allegation re foundation work at facilities Due to insufficient info, no further action planned & matter considered closed Personal info deleted
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01) 81/12/17 Region 3, Chicago, Office of the Director (81/03/01) 2pp 17045 349 24X Fiche 50-000, 82/12/30, B302040039
- B302040431 Discusses alleged threat against life of QC inspector employed by LK Comstock Co Individual life not threatened No further action planned & matter considered closed Personal info deleted Related info encl
WEIL, C H Region 3, Chicago, Office of the Director (81/03/01) 81/12/31 Region 3, Chicago, Office of the Director (81/03/01) 6pp 17045 351 24X Fiche 50-000, 82/12/30, B302040039
- B302040435 Discusses allegations from former employee of Gilbert Assoc re pipe stress calculations & concrete in svc water bldg Mgt meeting held w/ licensee on 811215 re planned improvements Case closed Personal info deleted
FOSTER, J E Region 3, Office of the Director 82/02/02 Region 3, Office of the Director 2pp 17045 357 24X Fiche 50-000, 82/12/30, B302040039
- B302040440 Discusses allegation re possession of false AWS certificate by former QC inspector Matter closed for listed reasons Personal info deleted
WEIL, C H Region 3, Office of the Director 82/03/13 Region 3, Office of the Director 2pp 17045 359 24X Fiche 50-000, 82/12/30, B302040039
- B302040375 Expresses concern re potential defect in piping between cooling tower & turbine condenser at facility
WILT, D D Wegman, Hessler & Vandenburg 82/05/14 KEPPLER, J O Region 3, Office of the Director 1p 17045 300 24X
Fiche 50-000, 82/12/30, B302040375
- B302040040 Forwards IE Insp Repts 50-440/B2-17 & 50-441/B2-16 on 821101-1231 No noncompliance noted
KNOP, R C Division of Project & Resident Programs 83/01/20 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17020 344 24X Fiche 50-440, 83/01/20, B302040040
- B302040045 IE Insp Repts 50-440/B2-17 & 50-441/B2-16 on 821101-1231 No noncompliance noted Major areas inspected safety-related const activities, including followup on previous insp findings & participation in SARP Board & licensee meetings
OLDNER, M L, KONKLIN, J E Division of Project & Resident Programs 83/01/19 3pp 17020 346 24X Fiche 50-440, 83/01/20, B302040040
- B212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358
- B302080167 Responds to IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Bunker-Ramo electrical penetration assemblies not utilized at facilities
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/27 KEPPLER, J F Region 3, Office of the Director 1p 17057 222 24X
Fiche 50-440, 83/01/27, B302080167
- B212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360
- B212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 093 24X Fiche 50-000, 83/01/28, B212060361
- B302030303 Advises of B30207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, B302030303
- B302040365 Ack receipt fo B21027 & 1110 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/B1-19 & 50-441/B1-19 Response did not meet format of 10CFR2.201
KEPPLER, J O Region 3, Office of the Director 83/01/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17019 015 24X
Fiche 50-440, 83/01/28, B302040365
- B302040366 Responds to NRC B20927 ltr re violations noted in IE Insp Repts 50-440/B1-19 & 50-441/B1-19 Corrective actions memo issued reiterating correct procedure for routing & review of vendor drawings & LK Comstock Procedure 4.3.3 revised
DAVIDSON, D R Cleveland Electric Illuminating Co 82/10/27 KEPPLER, J O Region 3, Office of the Director 17pp 17019 017 24X
Fiche 50-440, 83/01/28, B302040366

DOCKETED ITEMS

--8302040368 Corrects info in Paragraph V B 2(b) of 821027 response to NRC 820927 ltr re violations noted in IE Insp Repts 50-440/81-19 & 50-441/81-19 LK Comstock Procedure 4 3 3 evaluated No procedure rev necessary
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/10
KEPPLER, J Q Region 3, Office of Director 2pp 17019 034 24X
Fiche 50-440, 83/01/28, 8302040365

8302150363 Forwards IE Insp Repts 50-440/82-15 & 50-441/82-14 on 821101-04 No noncompliance noted
NORELIUS, C E Division of Engineering 83/01/28 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 17157 257 24X
Fiche 50-440, 83/01/28, 8302150363

--8302150367 IE Insp Repts 50-440/82-15 & 50-441/82-14 on 821101-04 No noncompliance noted Major areas inspected licensee 821027 response to noncompliance noted in IE Insp Repts 50-440/81-19 & 50-441/81-19 re cable pulling procedures
NAIDU, K R, WILLIAMS, C C Division of Engineering 83/01/13
8pp 17197 259 24X Fiche 50-440, 83/01/28, 8302150363

8302070261 Ack receipt of NRC 830126 ltr on info re recent deficiencies in quality IE Info Notice 83-01 will be acted upon promptly Significant deficiencies identified will be reported per 10CFR50.55
GINV, R M Cleveland Electric Illuminating Co 83/02/01 YOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
17031 355 24X Fiche 50-440, 83/02/01, 8302070261

8302180204 Forwards IE Insp Repts 50-440/83-01 & 50-441/83-01 on 830111-14 & notice of violation
KNOPF, R C Division of Project & Resident Programs 83/02/03
EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17215 342
24X Fiche 50-440, 83/02/03, 8302180204

--8302180208 Notice of violation from insp on 830111-14
KNOPF, R C Division of Project & Resident Programs 83/02/03 1p
17215 344 24X Fiche 50-440, 83/02/03, 8302180204

--8302180213 IE Insp Repts 50-440/83-01 & 50-441/83-01 on 830111-14 Noncompliance noted failure to take timely corrective action re procedure rev
PELKE, P R, KONKLIN, J E Division of Project & Resident Programs 83/02/02 4pp 17215 345 24X Fiche 50-440, 83/02/03, 8302180204

8302160192 Forwards final SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982
KEPPLER, J Q Region 3, Office of Director 83/02/10 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 17162 183 24X
Fiche 50-440, 83/02/10, 8302160192

--8302160201 SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982 Licensee rating in containment & other safety-related structures improved based on ability to identify & promptly correct deficiencies QA program adequate
* Region 3, Office of Director 83/02/10 21pp 17162 185 24X
Fiche 50-440, 83/02/10, 8302160192

--8302160209 Comments on 830114 meeting re Oct 1981 - Sept 1982 SALP evaluation. Health physics program strengthened substantially since Insp. Strong mgt attention paid to staffing & experience levels
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/21
KEPPLER, J Q Region 3, Office of Director 4pp 17162 206 24X
Fiche 50-440, 83/02/10, 8302160192

8302180424 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/81-19 & 50-441/81-19
NORELIUS, C E Division of Project & Resident Programs 83/02/14
EDELMAN, M R Cleveland Electric Illuminating Co 1p 17215 189
24X Fiche 50-440, 83/02/14, 8302180424

--8302180434 Responds to NRC 820927 ltr re violations noted in IE Insp Repts 50-440/81-19 & 50-441/81-19 Corrective actions: penetration insp records reviewed & motor control ctr. unit substitution & switchgear requalification programs complete
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/21
KEPPLER, J Q Region 3, Office of Director 2pp 17215 190 24X
Fiche 50-440, 83/02/14, 8302180424

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units", Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302", Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts", Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8302280509 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/81-16 & 50-441/81-16
SPESSARD, R L Division of Engineering 83/02/24 EDELMAN, M R
Cleveland Electric Illuminating Co 1p 17309 075 24X
Fiche 50-440, 83/02/24, 8302280509

--8302280513 Responds to NRC 820105 ltr re violations noted in IE Insp Repts 50-440/81-16 & 50-441/81-16 Corrective actions remain as identified in 820128 ltr Completion scheduled for 830630
DAVIDSON, D R Cleveland Electric Illuminating Co 82/09/29
NORELIUS, C E Division of Engineering 1p 17309 076 24X
Fiche 50-440, 83/02/24, 8302280509

B Reportable occurrences, LERs & related correspondence

8302040061 Interim Deficiency Rept RDC 64(83) re bracket welds for main steam & recirculation sys pipe whip restraints Initially reported on 821228 Linear indications caused by mfg error. Corrective action will be evaluated Next rept by 830415
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/26
KEPPLER, J Q Region 3, Office of Director 2pp 17020 331 24X
Fiche 50-440, 83/01/26, 8302040061

8302080323 Clarifies 830114 final rept on suppression pool floor plate welding deficiencies Top 1/4-inch of weld matl removed from all suspect welds in suppression pool floor
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/01
KEPPLER, J Q Region 3, Office of Director 2pp 17056 310 24X
Fiche 50-440, 83/02/01, 8302080323

8302180216 Final deficiency rept re Drillco corebore type bits Initially reported on 830104 Addl testing determined that 3/4-inch & 1-inch Drillco-installed bolts acceptable issue not reportable per 10CFR50.55(e)
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/03
KEPPLER, J Q Region 3, Office of Director 2pp 17150 032 24X
Fiche 50-440, 83/02/03, 8302180216

U Congressional/Executive Correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR.
FELTON, J H Division of Rules and Records 82/12/30 HIATT, B L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--7910230415 Forwards constituent ltr re concern over shoddy work practices at nuclear reactor const site
METZENBAUM, H M Senate 79/04/16 Commissioners 5pp
17045 315 24X Fiche 50-000, 82/12/30, 8302040039

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicant for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302280306 Responds to Generic Ltr 83-01 re operator license exams. Schedule of license exams through 1985 submitted
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/22
EISENHUT, D O Division of Licensing 2pp 17312 361 24X
Fiche 50-440, 83/02/22, 8302280306

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302170482 Board Notification 83-1 forwards BNL draft rept, "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach"
EISENHUT, D O Division of Licensing FIN A-3397 83/02/01
PALLADINO, N J Commissioners 194pp 17203 309 24X
Fiche 50-000, 83/02/01, 8302170482

DOCKETED ITEMS

8302240112 Forwards request for addl info re plant-specific application of BWR Owners Group safety/relief valve operability test results per TMI Action Plan Item II D 1 Response requested within 7 days of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/02/04 EDELMAN, M R
Cleveland Electric Illuminating Co 4pp 17268 299 24X
Fiche 50-440, 83/02/04, 8302240112

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program BvC list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable. BvC list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302240319 Summary of 830203 meeting w/applicant in Bethesda, MD re seismic/dynamic equipment qualification, pump & valve qualification & environ equipment qualification List of participants encl
STEFANO, J J Licensing Branch 1 83/02/09 Licensing Branch 1
5pp 17284 341 24X Fiche 50-440, 83/02/09, 8302240319

8302240123 Requests updated description of QA program for design & const indicating revs relative to program reviewed & accepted by NRC & documented in FSAR
YOUNGBLOOD, B J Licensing Branch 1 83/02/10 EDELMAN, M R
Cleveland Electric Illuminating Co 3pp 17268 270 24X
Fiche 50-440, 83/02/10, 8302240123

8302230719 Informs of intent to submit updated description of corporate nuclear QA program used for design & const of plants, in response to 830210 ltr info will be incorporated into FSAR Chapter 17
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/17
YOUNGBLOOD, B J Licensing Branch 1 1p 17248 362 24X
Fiche 50-440, 83/02/17, 8302230719

8302280299 Forwards Rev 1 to NEDE-24326-1-P, "OE Environ Qualification Program" Rev withheld (ref 10CFR2790)
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/22
YOUNGBLOOD, B J Licensing Branch 1 6pp 17310 396 24X
Fiche 50-440, 83/02/22, 8302280299

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302040400 Forwards draft FSAR changes re SER mods to standby liquid control sys, scram discharge sys & new redundant reactivity control sys Changes will be incorporated into next FSAR amend.
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/26
YOUNGBLOOD, B J Licensing Branch 1 78pp 17018 078 24X
Fiche 50-440, 83/01/26, 8302040400

8302070325 Forwards update of program to resolve concerns raised by J Humphrey, w/results of completed action plans, per SER Outstanding Issue 8 on Mark III containment sys issues Schedule for completion of unresolved items noted
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/26
YOUNGBLOOD, B J Licensing Branch 1 81pp 17030 233 24X
Fiche 50-440, 83/01/26, 8302070325

8302040038 Forwards draft FSAR pages for App 3A & 3B Change provides description of safety relief valve & LOCA-related hydrodynamic load definition for Mark III containment re SER Outstanding Issue 9, "Pool Dynamic Loads"
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 75pp 17021:001 24X
Fiche 50-440, 83/01/31, 8302040038

8302070301 Forwards response to SER Confirmatory Issue 21 re suppression pool temp limits Response addresses plant-specific info & assumptions used in analyses to meet NUREG-0783 requirements & criteria
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 16pp 17029 097 24X
Fiche 50-440, 83/01/31, 8302070301

8302070313 Forwards addl info re SER Outstanding Issue 12 on manual initiation of EBF sys, per 821104 request Design provisions consistent w/IEEE-279 guidelines & meet 10CFR50 requirements
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 8pp 17029 133 24X
Fiche 50-440, 83/01/31, 8302070313

8302100276 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0687 S02
83/01/31 60pp 17135 286 24X Fiche 50-440, 83/01/31, 8302100276

8302150509 Documents commitment to provide fire protection features for portable communication sys fixed repeaters, per SER Confirmatory Issue 37 Repeater separated & Halon fire suppression sys provided
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/08
YOUNGBLOOD, B J Licensing Branch 1 1p 17156 333 24X
Fiche 50-440, 83/02/08, 8302150509

8302280208 Responds to 830105 ltr re SER Confirmatory Issue 14 on overheating of gadolinia fuel pellets GE rept verified that fuel melting not expected to occur during normal steady-state operation or during whole core anticipated transient
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/18
YOUNGBLOOD, B J Licensing Branch 1 1p 17312 161 24X
Fiche 50-440, 83/02/18, 8302280208

F Security, medical, emergency & fire protection plans

8302070196 Advises of delay in submittal of revised emergency plan, due to extensive NRC-required revs & need for consistency w/offsite plans Revised emergency plan will be submitted by 830301
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/31
YOUNGBLOOD, B J Licensing Branch 1 1p 17031 307 24X
Fiche 50-440, 83/01/31, 8302070196

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" BvC list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302150509 Documents commitment to provide fire protection features for portable communication sys fixed repeaters, per SER Confirmatory Issue 37 Repeater separated & Halon fire suppression sys provided
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/08
YOUNGBLOOD, B J Licensing Branch 1 1p 17156 333 24X
Fiche 50-440, 83/02/08, 8302150509

8302160192 Forwards final SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982
KEPPLER, J G Region 3, Office of Director 83/02/10 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 17162 183 24X
Fiche 50-440, 83/02/10, 8302160192

--8302160201 SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982 Licensee rating in containment & other safety-related structures improved based on ability to identify & promptly correct deficiencies QA program adequate
* Region 3, Office of Director 83/02/10 21pp 17162 185 24X
Fiche 50-440, 83/02/10, 8302160192

--8302160209 Comments on 830114 meeting re Oct 1981 - Sept 1982 SALP evaluation Health physics program strengthened substantially since insp Strong mgt attention paid to staffing & experience levels
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/21
KEPPLER, J G Region 3, Office of Director 4pp 17162 206 24X
Fiche 50-440, 83/02/10, 8302160192

8302280206 Submits info re emergency operations facility (EOF) per J Stefano 830215 telcon request EOF located approx 0.4 miles from facility
EDELMAN, M R Commonwealth Edison Co 83/02/17 YOUNGBLOOD, B J
Licensing Branch 1 1p 17312 162 24X Fiche 50-440, 83/02/17, 8302280206

G Adjudicatory correspondence

8302010472 Memorandum & Order denying util 830106 motion for reconsideration of ASLB 821222 Memorandum & Order on summary disposition of Issue 3 Claim of surprise w/o merit
BLOCH, P B, KLINE, J R, BRIGHT, O O Atomic Safety and Licensing Board Panel 83/01/28 Cleveland Electric Illuminating Co 13pp
16982 046 24X Fiche 50-440, 83/01/28, 8302010472

8302070601 Requests to make limited appearance statement at OL hearings
RANDALL, S Affiliation Unknown 83/01/29 NRC - No Detailed
Affiliation Given 1p 17034 280 24X Fiche 50-440, 83/01/29, 8302070601

DOCKETED ITEMS

8302080220 Requests to make limited appearance statement at OL hearings
OLRIG, R Affiliation Unknown 83/01/30 Docketing & Services Branch 1p 17057 268 24X Fiche 50-440, 83/01/30, 8302080220

8302070555 Third set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
SHIGER, M A Cleveland Electric Illuminating Co SHIGER, M A Shaw, Pittman, Potts & Trowbridge 83/01/31 Ohio Citizens for Responsible Energy 19pp 17034 125 24X Fiche 50-440, 83/01/31, 8302070555

8302080234 Ninth set of interrogatories Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/01/31 Cleveland Electric Illuminating Co 14pp 17057 191 24X Fiche 50-440, 83/01/31, 8302080234

8302080269 Ninth set of interrogatories Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/01/31 Office of the Executive Legal Director 9pp 17056 348 24X Fiche 50-440, 83/01/31, 8302080269

8302080166 Requests to make limited appearance statement at OL hearings
TINIANOW, J C Sierra Club 83/02/02 Docketing & Services Branch 1p 17057 221 24X Fiche 50-440, 83/02/02, 8302080166

8302040252 Answers to 830913 sixth set of interrogatories & ASLB 821223 questions Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 83/02/03 Ohio Citizens for Responsible Energy 65pp 17019 319 24X Fiche 50-440, 83/02/03, 8302040252

8302080217 Requests to make limited appearance statement at OL hearings
PINZOME, C R Affiliation Unknown 83/02/03 Docketing & Services Branch 1p 17057 274, 24X Fiche 50-440, 83/02/03, 8302080217

8302140009 Response in opposition to NRC 830114 motion for summary disposition of issue 9 NRC failed to meet burden of proof Issue of environ qualification within ASLB jurisdiction Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/02/07 9pp 17141 100 24X Fiche 50-440, 83/02/07, 8302140009

--8302140016 Supplemental response to second set of interrogatories & request for production of documents Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy, 83/02/07, Cleveland Electric Illuminating Co 5pp 17141, 109 24X Fiche 50-440, 83/02/07, 8302140009

8302140025 Requests to make limited appearance statement at OL hearing
RICHMOND, S O International Brotherhood of Electrical Workers 83/02/07 Docketing & Services Branch 1p 17141, 179 24X Fiche 50-440, 83/02/07, 8302140025

8302170233 Requests to make limited appearance statement at OL hearings
HOFFMAN, M V Affiliation Unknown 83/02/07 NRC - No Detailed Affiliation Given 1p 17187 101 24X Fiche 50-440, 83/02/07, 8302170233

8302100202 Answer supporting NRC 830114 motion for summary disposition of issue 9 re radiation-induced degradation of polymers NRC final rule on environ qualification of electrical equipment compliance schedules remove issue as matter of controversy
BILBERG, J E Cleveland Electric Illuminating Co, BILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/02/08 Atomic Safety and Licensing Board Panel, 4pp 17112 311 24X Fiche 50-440, 83/02/08, 8302100202

--8302100209 Affidavit of S Kasturi supporting NRC motion for summary disposition of Issue 9 No reasonable basis exists to believe radiation dose rate effects on polymers will induce failures in safety-related equipment Prof qualifications encl
KASTURI, S Cleveland Electric Illuminating Co, KASTURI, S EDS Nuclear, Inc 83/02/04 33pp 17112, 315 24X Fiche 50-440, 83/02/08, 8302100202

--8302100213 Affidavit of DR Green supporting NRC motion for summary disposition of Issue 9, Surveillance & maint program includes features that enable identification of equipment degradation Certificate of Svc encl
GREEN, D R Cleveland Electric Illuminating Co, 83/02/04 10pp 17112 351, 24X Fiche 50-440, 83/02/08, 8302100202

8302250144 Advises of deadline extension until 830222 to respond to Citizens for Responsible Energy ninth set of interrogatories
YOUNGBLOOD, B J Licensing Branch 1 83/02/08 BERLINGER, C H Performance Branch LIAW, B D Materials Engineering Branch 1p 17299 355 24X Fiche 50-440, 83/02/08, 8302250144

8302170264 Requests to make limited appearance statement at OL hearings
DONAHUE, M United Assoc of Journeyman & Apprentices of Plumbing Pipe Fitters Industry 83/02/10 Docketing & Services Branch 1p 17178 228 24X Fiche 50-440, 83/02/10, 8302170264

8302090249 Requests to make limited appearance statement at OL hearings
PALUMBRO, R Affiliation Unknown 83/02/11 Docketing & Services Branch 1p 17070 258 24X Fiche 50-440, 83/02/11, 8302090249

8302170296 Requests to make limited appearance statement at OL hearing
MORAN, M J United Assoc of Journeyman & Apprentices of Plumbing Pipe Fitters Industry 83/02/11 Office of the Secretary of Commission 1p 17178 207 24X Fiche 50-440, 83/02/11, 8302170296

8302160353 Requests to make limited appearance statement at OL hearings
GLADDINO, H Affiliation Unknown 83/02/12 NRC - No Detailed Affiliation Given 1p 17167 308 24X Fiche 50-440, 83/02/12, 8302160353

8302170214 Requests to make limited appearance statement at OL rev hearing, per 10CFR2 715
SMITH, L E United Assoc of Journeyman & Apprentices of Plumbing Pipe Fitters Industry 83/02/12 Office of the Secretary of Commission 1p 17179 083 24X Fiche 50-440, 83/02/12, 8302170214

8302170206 Confirms 830214 telcon & provides info re obtaining interrogatories on issues 13-15 Copy of interrogatories will be hand delivered Postal Svc deserves blame for nondelivery W/svc list
BILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/02/14 HIA Ohio Citizens for Responsible Energy 2pp 17179 087 24X Fiche 50-440, 83/02/14, 8302170206

8302180438 Requests to make limited appearance statement at OL hearings
GRUNTNER, C United Assoc of Journeyman & Apprentices of Plumbing Pipe Fitters Industry 83/02/15 Docketing & Services Branch 1p 17215 019 24X Fiche 50-440, 83/02/15, 8302180438

8302230429 Requests to make limited appearance statement at OL hearings
MCINTYRE, S Affiliation Unknown 83/02/15 NRC - No Detailed Affiliation Given 1p 17246 159 24X Fiche 50-440, 83/02/15, 8302230429

8302180479 Advises that NRC will voluntarily answer OH Citizens for Responsible Energy 830131 interrogatories re issues 13, 14 & 15.
CUTCHIN, J M Hearing Branch 4 83/02/17 BLOCH, P D, BRIGHT, O KLINE, J R Atomic Safety and Licensing Board Panel 1p 17210 24X Fiche 50-440, 83/02/17, 8302180479

8302230436 Requests to make limited appearance statement at OL hearings
BATTAGLIA, F Affiliation Unknown 83/02/17 Docketing & Services Branch 1p 17245 255 24X Fiche 50-440, 83/02/17, 8302230436

8302230580 Motion to strike refs to "synergistic effects" in OH Citizens for Responsible Energy 830207 response to NRC motion for summary disposition of issue 9 re radiation induced degradation of polymers Certificate of Svc encl
BILBERG, J E Cleveland Electric Illuminating Co, BILBERG, J E, Shaw, Pittman, Potts & Trowbridge 83/02/18 Atomic Safety & Licensing Board Panel, 6pp 17257 095 24X Fiche 50-440, 83/02/18, 8302230580

8302250270 Requests to make limited appearance statement at OL hearing
BULLIVANT, J F, HOULEHAN, F M Intl Assoc of Heat & Frost Insul & Asbestos Workers 83/02/18 Docketing & Services Branch, 17292 113 24X Fiche 50-440, 83/02/18, 8302250270

8302250244 Requests to make limited appearance statement at OL hearings
GENOVESE, J Affiliation Unknown 83/02/20 NRC - No Detailed Affiliation Given 1p 17292 328, 24X Fiche 50-440, 83/02/20, 8302250244

DOCKETED ITEMS

8302280160 Answer supporting NRC 830208 motion for deadline by which OH Citizens for Responsible Energy must specify scenario to be litigated under Issue B Concur in NRC arguments Certificate of Svc encl
SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Trowbridge 83/02/23 Atomic Safety and Licensing Board Panel App 17306 039 24X Fiche 50-440, 83/02/23, 8302280160

8302280266 Forwards amend to FSAR filed w/NRC re standby liquid control sys Amend referenced in util 820813 ltr to NRC included in applicant 820820 answer to Sunflower Alliance second set of interrogatories W/o encl Related correspondence
SILBERO, J E Shaw, Pittman, Potts & Trowbridge SILBERO, J E Cleveland Electric Illuminating Co 83/02/23 HIATT, S Ohio Citizens for Responsible Energy 2pp 17312 267 24X Fiche 50-440, 83/02/23, 8302280266

H General correspondence

8302040105 Responds to 821214 ltr commenting on potential propane leak from Lake Underground Storage Facility to Morton Salt Mine & effects on safe operation of nuclear plants Accidents at Morton Mine would have no ill effects on nuclear plants
YOUNGBLOOD, B J Licensing Branch 1 83/01/27 BIMBER, R Affiliation Unknown 2pp 17043 174 24X Fiche 50-440, 83/01/27, 8302040105

8302040456 Forwards R Bimber 821214 ltr re potential propane leak from Lake Underground Storage Facility to Morton Salt Mine & effects on nuclear plants Util requested to address any inconsistencies claimed FSAR will be updated or corrected
YOUNGBLOOD, B J Licensing Branch 1 83/01/31 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17042 237 24X Fiche 50-440, 83/01/31, 8302040456

K Utility Final Safety Analysis Report (FSAR) & amends

8212020091 Forwards Amend 10 to FSAR
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16274 176 24X Fiche 50-440, 82/11/23, 8212020091

--8212020098 Amend 10 to FSAR W/629 oversize drawings Aperture lids are available in PDR
* Cleveland Electric Illuminating Co 82/11/29 420pp 16274 179 24X Fiche 50-440, 82/11/29, 8212020091

8302170338 Forwards Amend 11 to FSAR Amend incorporates previously submitted responses to Environ Qualification Branch questions
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17184 181 24X Fiche 50-440, 83/02/15, 8302170338

--8302170340 Amend 11 to FSAR
* Cleveland Electric Illuminating Co 83/02/15 275pp 17184 184 24X Fiche 50-440, 83/02/15, 8302170338

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040071 Control complex bldg high strength bolting operation insp & testing checkoff sheet
CRAY, B FBI Industries 77/08/08 1p 17045 149 24X Fiche 50-000, 82/12/30, 8302040039

--8302040076 Forwards util 800825 memo discussing allegation re improper sandblasting of containment liner plate Investigation underway LK Constock Co, Inc nonconformance rept encl
WILLIAMS, C Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/04, NORELIUS, C Region 3, Chicago, Office of the Director, App 17045 150 24X Fiche 50-000, 82/12/30, 8302040039

--8302040101 Discusses allegations received by TV reporter re reactor biological shield & weld crack coverage Biological shield problems reported under 10CFR50.55(a) Cracked weld on 599-ft elevation could not be located Matters closed
WEIL, C H Region 3, Chicago, Office of the Director (81/03/01) 82/01/28 Region 3, Chicago, Office of the Director (81/03/01) 3pp 17045 211 24X Fiche 50-000, 82/12/30, 8302040039

--8302040107 Advises of 811202 telcon w/E Cory, reporter for HEBS-TV in Cleveland, re allegations concerning reactor biological shield & weld crack coverage
MARABITO, R J Office of Public Affairs 81/12/03 WARNICK, R Enforcement & Investigation Staff 1p 17045 214 24X Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPPLER, J G Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040168 Forwards CH Weil 820208 memo re allegation concerning Pullman Power Products, mechanical subcontractor at Facilities Allegor refused to provide NRC further info Assistance request form encl
WARNICK, R F Region 3, Office of Director 82/02/09 NORELIUS, C E Division of Engineering 3pp 17045 271 24X Fiche 50-000, 82/12/30, 8302040039

--8302040178 Discusses allegation re Pullman Power Products welding activities, matl storage & maint, nonconformance repts, NDEs & piping Allegor refused to provide NRC further info
WEIL, C H Region 3, Office of Director 82/02/08 Region 3, Office of Director 3pp 17045 274 24X Fiche 50-000, 82/12/30, 8302040039

--8302040186 Discusses allegation re installation of diesel generator stator & rotor w/o approved procedures Field mod of procedure acceptable Case closed
WEIL, C H Region 3, Office of Director 82/03/17 Region 3, Office of Director 2pp 17045 277 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
BUCHARSKI, L Region 3, Office of Director 82/07/08 KEPPLER, J G Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

--8302040355 Advises that insp of allegations re Pullman Power Products at facilities conducted per Region 3, Div of Engineering & Technical Program 820209 request IE Insp Repts 50-440/82-03 & 50-441/82-03 issued Insp evaluation encl
WEIL, C H Region 3, Office of Director, 82/07/08, Region 3, Office of Director 5pp 17045 294 24X Fiche 50-000, 82/12/30, 8302040039

--8302040378 Evaluation of 821011-12 insp (IE Insp Repts 50-440/82-12 & 50-441/82-11)
VIN, I Region 3, Office of Director 82/10/13 3pp 17045 301 24X Fiche 50-000, 82/12/30, 8302040039

--8302040386 Forwards KR Naidu 820624 memo to CE Norelius re flammable matl used in Class IE switchgear Plan & schedule for action required by 820924
DAVIS, A B Division of Project & Resident Programs 82/08/25 Division of Engineering 1p 17045 303 24X Fiche 50-000, 82/12/30, 8302040039

--8302040388 Evaluation of 821012-13 insp (IE Insp Repts 50-440/82-13 & 50-441/82-12)
GESTMANN, M J Region 3, Office of Director 82/10/14 2pp 17045 310 24X Fiche 50-000, 82/12/30, 8302040039

--8302040389 Forwards JO Keppler 790924 response to ltr to Senator Metzenbaum re shoddy workmanship at facilities, Matter closed per 790822 discussion Personal info deleted
NORELIUS, C E Region 3, Chicago, Office of the Director 79/05/30 WARD, W J Office of Inspection & Enforcement, Office of the Director 1p 17045 312 24X Fiche 50-000, 82/12/30, 8302040039

--8302040395 Discusses allegations re electrical work at facilities Unresolved items re conduit reaming documented in IE Insp Repts 50-440/80-16 & 50-441/80-15, No basis found for full investigation Personal info deleted Related info encl
FOSTER, J E Region 3, Chicago, Office of the Director (81/03/01) 81/01/28 Region 3, Chicago, Office of the Director (81/03/01) 7pp 17045 320 24X Fiche 50-000, 82/12/30, 8302040039

DOCKETED ITEMS

--8302040396 Forwards allegation ltr received by licensee from former electrical inspector at facilities Individual has not contacted NRC w/o encl
WILLIAMS, C C Region 3, Chicago, Office of the Director
80/06/23 NORELIOUS, C E Region 3, Chicago, Office of the Director
ip 17045 327 24X Fiche 50-000, 82/12/30, 8302040039

--8302040405 Forwards IE Insp Repts 50-440/80-27 & 50-441/80-27, per 801222 & 23 telcons Personal info deleted w/o encl
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01)
81/01/28 Affiliation Unknown ip 17045 342 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040408 Forwards IE Insp Repts 50-440/80-27 & 50-441/80-27 re allegation concerning defective weld & C Well transcribed notes No further action planned & matter considered closed
Personal info deleted w/o encl
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01)
81/01/28 Region 3, Chicago, Office of the Director (81/03/01)
ip 17045 343 24X Fiche 50-000, 82/12/30, 8302040039

--8302040414 Forwards RN Gardner B11005 memo to CC Williams re allegation concerning reactor vessel inner steel No basis found for investigation No further action planned & matter considered closed Personal info deleted
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01)
81/10/15 Region 3, Chicago, Office of the Director (81/03/01)
ip 17045 347 24X Fiche 50-000, 82/12/30, 8302040039

--8302040421 Informs of allegation re reactor vessel inner steel Stainless steel welded to cover defective paint/coating Steel tensile strength ruined during welding process Personal info deleted
GARDNER, R N Region 3, Chicago, Office of the Director (81/03/01)
81/10/05 WILLIAMS, C C Engineering Inspection Branch ip
17045 348 24X Fiche 50-000, 82/12/30, 8302040039

--8302040428 Discusses allegation re foundation work at facilities Due to insufficient info, no further action planned & matter considered closed Personal info deleted
PHILLIP, O A Region 3, Chicago, Office of the Director (81/03/01)
81/12/17 Region 3, Chicago, Office of the Director (81/03/01)
2pp 17045 349 24X Fiche 50-000, 82/12/30, 8302040039

--8302040431 Discusses alleged threat against life of QC inspector employed by LK Comstock Co Individual life not threatened No further action planned & matter considered closed Personal info deleted Related info encl
WEIL, C H Region 3, Chicago, Office of the Director (81/03/01)
81/12/31 Region 3, Chicago, Office of the Director (81/03/01)
6pp 17045 351 24X Fiche 50-000, 82/12/30, 8302040039

--8302040435 Discusses allegations from former employee of Oilbert Assoc re pipe stress calculations & concrete in svc water bldg Mgt meeting held w/licenses on 811215 re planned improvements Case closed Personal info deleted
FOSTER, J E Region 3, Office of Director 82/02/02 Region 3, Office of Director 2pp 17045 357 24X Fiche 50-000, 82/12/30, 8302040039

--8302040440 Discusses allegation re possession of false AWS certificate by former QC inspector Matter closed for listed reasons Personal info deleted
WEIL, C H Region 3, Office of Director 82/03/13 Region 3, Office of Director 2pp 17045 359 24X Fiche 50-000, 82/12/30, 8302040039

8302040040 Forwards IE Insp Repts 50-440/82-17 & 50-441/82-16 on 821101-1231 No noncompliance noted
KNOP, R C Division of Project & Resident Programs 83/01/20
EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17020 344
24X Fiche 50-440, 83/01/20, 8302040040

--8302040045 IE Insp Repts 50-440/82-17 & 50-441/82-16 on 821101-1231 No noncompliance noted Major areas inspected safety-related const activities, including followup on previous insp findings & participation in BALP Board & licensee meetings
GILDER, M L, KONKLIN, J E Division of Project & Resident Programs 83/01/19 3pp 17020 346 24X Fiche 50-440, 83/01/20, 8302040040

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302080167 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Bunker-Ramo electrical penetration assemblies not utilized at facilities
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/27
KEPPLER, J F Region 3, Office of Director, ip 17057 222 24X
Fiche 50-440, 83/01/27, 8302080167

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev taken to correct violations noted in IE Insp Repts
10CFR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPEER, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302040365 Ack receipt fo 821027 & 1110 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts
50-440/81-19 & 50-441/81-19 Response did not meet format of 10CFR2 201
KEPPLER, J O Region 3, Office of Director 83/01/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17019 015 24X
Fiche 50-440, 83/01/28, 8302040365

--8302040366 Responds to NRC 820927 ltr re violations noted in IE Insp Repts 50-440/81-19 & 50-441/81-19 Corrective actions memo issued reiterating correct procedure for routing & review of vendor drawings & LK Comstock Procedure 4 3.3 revised
DAVIDSON, D R Cleveland Electric Illuminating Co 82/10/27
KEPPLER, J O Region 3, Office of Director 17pp 17019 017 24X
Fiche 50-440, 83/01/28, 8302040366

--8302040368 Corrects info in Paragraph V B 2(b) of 821027 response to NRC 820927 ltr re violations noted in IE Insp Repts
50-440/81-19 & 50-441/81-19 LK Comstock Procedure 4 3 3 evaluated No procedure rev necessary
DAVIDSON, D R Cleveland Electric Illuminating Co 82/11/10, 17pp 17019 034 24X
KEPPLER, J O Region 3, Office of Director 2pp 17019 034 24X
Fiche 50-440, 83/01/28, 8302040368

8302150363 Forwards IE Insp Repts 50-440/82-15 & 50-441/82-14 on 821101-04 No noncompliance noted
NORELIOUS, C E Division of Engineering 83/01/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17157 257 24X
Fiche 50-440, 83/01/28, 8302150363

--8302150367 IE Insp Repts 50-440/82-15 & 50-441/82-14 on 821101-04 No noncompliance noted Major areas inspected licensee 821027 response to noncompliance noted in IE Insp Repts
50-440/81-19 & 50-441/81-19 re cable pulling procedures
NAIDU, K R, WILLIAMS, C C Division of Engineering 83/01/13
8pp 17157 259 24X Fiche 50-440, 83/01/28, 8302150367

8302070261 Ack receipt of NRC 830126 ltr on info re recent deficiencies in quality IE Info Notice 83-01 will be acted upon promptly Significant deficiencies identified will be reported per 10CFR50 55e
QIN, R M Cleveland Electric Illuminating Co 83/02/01 YOUNG, R C Region 3's Office, Office of Inspection and Enforcement ip.
17031 355 24X Fiche 50-440, 83/02/01, 8302070261

8302180204 Forwards IE Insp Repts 50-440/83-01 & 50-441/83-01 on 830111-14 & notice of violation
KNOP, R C Division of Project & Resident Programs 83/02/03
EDELMAN, M R Cleveland Electric Illuminating Co 2pp, 17215 342, 24X Fiche 50-440, 83/02/03, 8302180204

--8302180208 Notice of violation from Insp on 830111-14
KNOP, R C Division of Project & Resident Programs 83/02/03 1p
17215 344 24X Fiche 50-440, 83/02/03, 8302180208

--8302180213 IE Insp Repts 50-440/83-01 & 50-441/83-01 on 830111-14 Noncompliance noted failure to take timely corrective action re procedure rev
PELKE, P R, KONKLIN, J E Division of Project & Resident Programs, 83/02/02, 4pp 17215 345 24X Fiche 50-440, 83/02/03, 8302180204

8302160192 Forwards final BALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sept 1982
KEPPLER, J O Region 3, Office of Director 83/02/10, EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17162 183 24X
Fiche 50-440, 83/02/10, 8302160192

--8302160201 SALP Repts 50-440/83-04 & 50-441/83-04 for Oct 1981 - Sep 1982 Licensee rating in containment & other safety-related structures improved based on ability to identify & promptly correct deficiencies GA program adequate.
* Region 3, Office of Director 83/02/10 21pp 17162 185 2
Fiche 50-440, 83/02/10, 8302160192

DOCKETED ITEMS

--8302160209 Comments on 830114 meeting re Oct 1981 - Sept 1982 SALP evaluation Health physics program strengthened substantially since insp Strong mgt attention paid to staffing & experience levels
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/21
KEPPLER, J O Region 3, Office of Director 4pp 17162 206 24X
Fiche 50-440, 83/02/10, 8302160192

8302180424 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/81-19 & 50-441/81-19
NORELIUS, C E Division of Project & Resident Programs 83/02/14
EDELMAN, M R Cleveland Electric Illuminating Co 1p 17215 189
24X Fiche 50-440, 83/02/14, 8302180424

--8302180434 Responds to NRC 820927 ltr re violations noted in IE Insp Repts 50-440/81-19 & 50-441/81-19 Corrective actions penetration insp records reviewed & motor control ctr unit substation & switchgear reverification programs complete
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/21
KEPPLER, J O Region 3, Office of Director 2pp 17215 190 24X
Fiche 50-440, 83/02/14, 8302180424

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 11pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 12pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8302280509 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/81-16 & 50-441/81-16
SPESSARD, R L Division of Engineering 83/02/27 EDELMAN, M R Cleveland Electric Illuminating Co 1p 17309 075 24X
Fiche 50-440, 83/02/24, 8302280509

--8302280513 Responds to NRC 820105 ltr re violations noted in IE Insp Repts 50-440/81-16 & 50-441/81-16 Corrective actions remain as identified in 820128 ltr Completion scheduled for 830630.
DAVIDSON, D R Cleveland Electric Illuminating Co 82/09/29
NORELIUS, C E Division of Engineering 1p 17309 076 24X
Fiche 50-440, 83/02/24, 8302280509

S. Reportable Occurrences, LERs & related correspondence

8302040061 Interim Deficiency Rept RDC 64(83) re bracket welds for main steam & recirculation sys pipe whip restraints Initially reported on 821228 Linear indications caused by mfg error Corrective action will be evaluated Next rept by 830415
EDELMAN, M R Cleveland Electric Illuminating Co 83/01/26
KEPPLER, J O Region 3, Office of Director 2pp 17020 331 24X
Fiche 50-440, 83/01/26, 8302040061

8302150216 Final deficiency rept re Drillco corebore type bits Initially reported on 830104 Addl testing determined that 3/4-inch & 1-inch Drillco-installed bolts acceptable Issue not reportable per 10CFR50 55(e)
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/03
KEPPLER, J O Region 3, Office of Director 2pp 17150 032 24X
Fiche 50-440, 83/02/03, 8302150216

U Congressional/Executive Correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

7910230415 Forwards constituent ltr re concern over shoddy work practices at nuclear reactor const site
METZENBAUM, H M Senate 79/04/16 Commissioners 5pp 17045 315 24X Fiche 50-000, 82/12/30, 8302040039

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302280306 Responds to Generic Ltr 83-01 re operator license exams Schedule of license exams through 1985 submitted
EDELMAN, M R Cleveland Electric Illuminating Co 83/02/22
EISENHUT, D G Division of Licensing 2pp 17312 361 24X
Fiche 50-440, 83/02/22, 8302280306

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302020500 Forwards info on operability qualification & demonstration of purge & vent valves to help prepare for Seismic Qualification Review Team site audits
KNIGHTON, G W Licensing Branch 3 83/01/24 TALLMAN, W C Public Service Co. of New Hampshire 9pp 16999 279 24X
Fiche 50-443, 83/01/24, 8302020500

8302010406 Forwards response re single failure assumptions for Condition II events, supplementing 820312 response Response will be included in Amend 49 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/01/28 KNIGHTON, G W Licensing Branch 3 4pp 16974 264 24X Fiche 50-443, 83/01/28, 8302010406

8302010433 Forwards responses to Requests for Addl Info 440 89 & 440 127 re locked rotor/shaft break event Item discussed in 830110-12 meetings & will be included in Amend Application 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/01/28 KNIGHTON, G W Licensing Branch 3 15pp 16981 035 24X Fiche 50-443, 83/01/28, 8302010433

8302010646 Forwards open item responses to Auxiliary Sys Branch & Containment Sys Branch re RCP5 leakage detection, NUREG-0737, Items II E 4 2, "Containment Isolation Dependability," & II F 1 2, "Containment Water Level " DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/01/28 KNIGHTON, G W Licensing Branch 3 4pp 16980 042 24X Fiche 50-443, 83/01/28, 8302010646

8302020152 Responds to open item re SRP 9 5 B concerning design of emergency diesel generator exhaust piping Flanged joints on diesel exhaust sys will be visually inspected for leakage & commitments included in OL application, Amend 48
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/01/31 KNIGHTON, G W Licensing Branch 3 2pp 16993 360 24X Fiche 50-443, 83/01/31, 8302020152

8302020275 Forwards married-up FSAR Table 3 9(B)-23, resulting from review of test requirements for safety class valves Changes will be incorporated in Amend 48 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/01/31 KNIGHTON, G W Licensing Branch 3 35pp 16994 024 24X Fiche 50-443, 83/01/31, 8302020275

8302020281 Forwards revs to FSAR Sections 12 5 1 & 13 1 2 2 & Figures 12 5-1 & 13 1-5, in response to 821014 memo re safety review open items
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/01/31 KNIGHTON, G W Licensing Branch 3 4pp 16993 320 24X Fiche 50-443, 83/01/31, 8302020281

8302040092 Forwards revised FSAR Pp 3 9(B)-9 & 3 9(B)-10 re steady state & operating transient vibration, in response to Mechanical Engineering Branch open items
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/02/01 KNIGHTON, G W Licensing Branch 3 4pp 17021 249 24X Fiche 50-443, 83/02/01, 8302040092

8302040107 Forwards responses to Power Sys Branch open items discussed at 830110-12 & 15 meetings Responses will be included in Amend 49 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co. of New Hampshire 83/02/01 KNIGHTON, G W Licensing Branch 3 12pp 17020 303 24X Fiche 50-443, 83/02/01, 8302040107

DOCKETED ITEMS

8302040372 Responds to open item re containment spray chemistry, per discussion at 830110-12 & 26 meetings. Operability of gravity feed sys will be demonstrated during preoperational testing of ECCS
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/01 KNIGHTON, G W Licensing
Branch 3 2pp 17018 279 24X Fiche 50-443, 83/02/01, 8302040372

8302040066 Forwards marked-up FSAR pages re responses to open items of SRP Sections 12.3.4 & 12.5.2. Encl will be included in Amend 48 to DL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing
Branch 3 6pp 17020 147 24X Fiche 50-443, 83/02/02, 8302040066

8302040338 Forwards revised FSAR Section 6.2.2.2 re inert cover gas on sodium hydroxide tank. FSAR rev will be included in DL application, Amend 48
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing
Branch 3 3pp 17018 239 24X Fiche 50-443, 83/02/02, 8302040338

8302040425 Forwards revised response to Request for Addl Info 440.133. Response reflects discussions w/Reactor Sys Branch at 830110-12 meeting & will be included in Amend 48 to DL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/02 KNIGHTON, G W Division of
Licensing 18pp 17017 310 24X Fiche 50-443, 83/02/02, 8302040425

8302080186 Forwards response to Hydrologic & Geotechnical Engineering Branch Request for Addl Info RAI 240.42 W/three oversize drawings, including one proprietary Nonproprietary aperture cards in PDR, proprietary cards in Central Files
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/03 KNIGHTON, G W Licensing
Branch 3 506pp 17053 057 24X Fiche 50-443, 83/02/03, 8302080186

8302080215 Forwards revised FSAR Section 3.9(B).3.4 re snubber installation / operability verification. In response to Mechanical Engineering Branch open item Revs will be included in Amend 49 to DL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/03 KNIGHTON, G W Licensing
Branch 3 9pp 17059 040 24X Fiche 50-443, 83/02/03, 8302080215

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSS re resolution of TMI Action Item II K.3.5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302150407 Notices that loose parts monitoring sys that complies w/Reg Guide 1.133 has been purchased from Technology for Energy Corp. Detailed info required by Reg Guide 1.133, Positions C.1.C.2, C.3.C.4, C.5 & C.6 to be provided 830701
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/09 KNIGHTON, G W Licensing
Branch 3 2pp 17137 244 24X Fiche 50-443, 83/02/09, 8302150407

8302150451 Forwards revised FSAR pages for Sections 9.1.2 & 9.1.3 re spent fuel pool cooling subsys. Pages will be incorporated in DL application, Amend 48
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/09 KNIGHTON, G W Licensing
Branch 3 17pp 17159 175 24X Fiche 50-443, 83/02/09, 8302150451

8302160263 Forwards "Criticality Analysis of Seabrook Spent Fuel," in response to Auxiliary Branch request for addl info. Rept to be incorporated in DL application, Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/10 KNIGHTON, G W Licensing
Branch 3 17pp 17170 237 24X Fiche 50-443, 83/02/10, 8302160263

8302170369 Forwards revised FSAR Table 13.2-3 indicating that training program for mitigating core damage follows INPO guidelines. In response to NRC 830210 request. Revised table will be included in Amend 49 to DL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/10 KNIGHTON, G W Licensing
Branch 3 3pp 17187 130 24X Fiche 50-443, 83/02/10, 8302170369

8302250105 Summary of 821230, 830110-12, 18, 19, 25 & 26 meetings w/applicant re open items in review of electrical power sys, fire protection program & mechanical sys associated w/emergency diesel generator. Revised memo encl
WHEELER, L Licensing Branch 3 83/02/10 Licensing Branch 3
8pp 17303 077 24X Fiche 50-443, 83/02/10, 8302250105

8302160166 Responds to open item re potential for unmonitored discharge of steam generator blowdown demineralizer regenerant solution. Samples will be analyzed for radioactive contaminants prior to discharging waste holdup sump
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/14 KNIGHTON, G W Licensing
Branch 3 3pp 17162 069 24X Fiche 50-443, 83/02/14, 8302160166

8302160274 Forwards revised response to open item re preheating of diesel engine combustion air in low ambient air temp & no load conditions. Revised response addresses qualification of diesel air preheating sys & corrects typographical errors
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/14 KNIGHTON, G W Licensing
Branch 3 4pp 17170 234 24X Fiche 50-443, 83/02/14, 8302160274

8302160326 Forwards revised responses to 640 series request for addl info re procedures & tests
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/14 KNIGHTON, G W Licensing
Branch 3 12pp 17166 216 24X Fiche 50-443, 83/02/14, 8302160326

8302220166 Forwards responses to Containment Sys Branch Open Item SR & 2 B, per TMI Action Items II E.4.2 & II F.1.2. Responses will be incorporated in DL application, Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 8pp 17233 154 24X Fiche 50-443, 83/02/17, 8302220166

8302220327 Forwards revised pages of previously submitted responses requests for addl info in response to Instrumentation & Control Sys Branch open items. Supplementary info re Requests for Addl Info 420.21 & 420.29 also encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 18pp 17230 096 24X Fiche 50-443, 83/02/17, 8302220327

8302220331 Forwards response to open item re NUREG-0737, Item II F.2, "Detection of Inadequate Core Cooling." Commitment to utilize reactor coolant inventory monitor, saturation monitor & core exit thermocouples encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 4pp 17230 087 24X Fiche 50-443, 83/02/17, 8302220331

8302220388 Forwards revised FSAR Pages 1.8-17 & 5.2-24 through 5.2-3 in response to open item re detection of leakage from RCPB. FSAR pages will be incorporated in Amend 49 to DL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 13pp 17232 016 24X Fiche 50-443, 83/02/17, 8302220388

8302250172 Amend 48 to application for DLs, incorporating responses / revised responses to NRC request for addl info, responses to NRC licensing review open items & miscellaneous & minor editorial revs
JOHNSON, W P Yankee Atomic Electric Co JOHNSON, W P Public
Service Co of New Hampshire 83/02/18 KNIGHTON, G W Licensing
Branch 3 2pp 17294 011 24X Fiche 50-443, 83/02/18, 8302250172

8302250441 Forwards info re low temp overpressure protection in response to Request for Addl Info 440.132. Response will be incorporated in DL application, Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/23 KNIGHTON, G W Licensing
Branch 3 9pp 17296 352 24X Fiche 50-443, 83/02/23, 8302250441

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8302040210 Forwards response to open item re reactor vessel closure studs. Response discussed in 830110-12 meetings w/Matlis Engineering Branch & will be included in Amend 49 to DL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/01 KNIGHTON, G W Licensing
Branch 3 3pp 17023 326 24X Fiche 50-443, 83/02/01, 8302040210

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHART, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 1pp 1721 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302040036 Submits commitment re inadvertent operation of fire protection sys discussed at 830110-12 & 25 meetings w/Power Sys Branch Spray shield will be provided to protect pump motor from spray impingement Pump/motor will be elevated
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing Branch 3 3pp 17020 350 24X Fiche 50-443, 83/02/02, 8302040036

8302250105 Summary of 821230, 830110-12, 18, 19, 25 & 26 meetings w/applicant re open items in review of electrical power sys, fire protection program & mechanical sys associated w/emergency diesel generator Revised memo encl
WHEELER, L Licensing Branch 3 83/02/10 Licensing Branch 3 8pp 17303 077 24X Fiche 50-443, 83/02/10, 8302250105

G Adjudicatory correspondence

8302010521 Response to 821111 interrogatories & request for production of documents Certificate of Svc encl Related correspondence
CURRAN, D, JORDAN, W S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss 83/01/28 Office of the Executive Legal Director 19pp 16977 273 24X Fiche 50-443, 83/01/28, 8302010521

8302010589 Forwards motion to compel New England Coalition on Nuclear Pollution answers Related correspondence
GAD, R K Ropes & Gray GAD, R K Public Service Co of New Hampshire 83/01/28 Public Document Branch 1p 16978 144 24X Fiche 50-443, 83/01/28, 8302010589

--8302010594 Motion to compel New England Coalition on Nuclear Pollution answers to util 821207 interrogatories Coalition seeks shelter from obligation behind shield of unpreparedness w/Certificate of Svc Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/01/28 Atomic Safety and Licensing Board Panel 22pp 16978 145 24X
Fiche 50-443, 83/01/28, 8302010594

8302010529 Answers to 830107 third set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/01/29 New Hampshire, State of 10pp 16977 246 24X Fiche 50-443, 83/01/29, 8302010529

8302010533 Answers to 830107 second set of interrogatories & requests for documents on Contentions I D, I D 4, I F, I L & I U & motion for protective order Certificate of Svc encl Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/01/29 New England Coalition on Nuclear Pollution 18pp 16977 223 24X Fiche 50-443, 83/01/29, 8302010533

8302010547 Answers to 830107 third set of interrogatories & requests for documents on Contentions I A, I B 1, I B 2 & I C Certificate of Svc encl Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/01/29 New England Coalition on Nuclear Pollution 23pp 16982 335 24X Fiche 50-443, 83/01/29, 8302010547

8302020253 Memorandum & Order denying State of NH 830107 objection to ASLB ruling on motion for extension of discovery NH failed to meet burden of proving motion should be granted
HOYT, H F Atomic Safety and Licensing Board Panel 83/01/31 New Hampshire, State of 12pp 16994 282 24X Fiche 50-443, 83/01/31, 8302020253

102070159 Summarizes conversations re timing of New England Coalition on Nuclear Pollution responses to NRC interrogatories & request for production of documents NRC summary disposition of Coalition contentions due 830228
ESSY, R P Hearing Branch 3 83/02/04 CURRAN, D Harmon & Weiss 17032:344 24X Fiche 50-443, 83/02/04, 8302070159

8302080014 Motion to compel Coastal Chamber of Commerce of NH answers to NRC 821110 discovery requests or alternatively, to dismiss contentions on accident classification, onsite protective measures & radioactive monitoring w/Certificate of Svc
LESSY, R P, PERLIS, R O, PATTERSON, W F Hearing Branch 3 83/02/04 Atomic Safety and Licensing Board Panel 9pp 17058 255 24X
Fiche 50-443, 83/02/04, 8302080014

8302080039 Answer & objection to 830117 interrogatories & request for production of documents to NRC 1/2 util interrogatories untimely Subj of interrogatories does not relate to admitted contentions Certificate of Svc encl
LESSY, R P Hearing Branch 3 83/02/04 Hampton Beach Area Chamber of Commerce, Hampton, NH 9pp 17058 163 24X
Fiche 50-443, 83/02/04, 8302080039

8302080185 Response in opposition to applicant motion to compel answers to interrogatories & motion for issuance of protective order Supplemental answers to specific interrogatories currently being prepared w/svc list Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/02/04 Atomic Safety and Licensing Board Panel 8pp 17057 246 24X Fiche 50-443, 83/02/04, 8302080185

8302080238 Forwards objection to util motion to compel interrogatories & motion for issuance of protective order w/o encl Related correspondence
BACKUS, R A Backus, Shea & Meyer BACKUS, R A Seacoast Anti-Pollution League 83/02/04 Docketing & Services Branch 1p 17057 186 24X Fiche 50-443, 83/02/04, 8302080238

8302080264 First set of interrogatories & requests for documents re Contentions III 1, III 2, III 3, III 12 & III 13 Related correspondence
CURRAN, D, BISHOP, L L New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss 83/02/04 Public Service Co of New Hampshire 18pp 17056 357 24X Fiche 50-443, 83/02/04, 8302080264

8302100220 First motion for summary disposition of New England Coalition on Nuclear Pollution Contentions I D 4 & I L Intervenor do not intend to litigate contentions Certificate of Svc encl Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/02/07 Atomic Safety and Licensing Board Panel 10pp 17114 053 24X Fiche 50-443, 83/02/07, 8302100220

8302100228 Fourth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I I Regulatory basis for contention no longer exists Certificate of Svc encl Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/02/07 Atomic Safety and Licensing Board Panel 7pp 17115 045 24X Fiche 50-443, 83/02/07, 8302100228

8302100235 Third motion for summary disposition of New England Coalition on Nuclear Pollution Contention I F Interrogatories show contention withdrawn & w/o basis w/Certificate of Svc Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/02/07 Atomic Safety and Licensing Board Panel 8pp 17115 055 24X Fiche 50-443, 83/02/07, 8302100235

8302100243 Second motion for summary disposition of New England Coalition on Nuclear Pollution Contention I N Interrogatories show contention withdrawn Certificate of Svc encl
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/02/07 Atomic Safety and Licensing Board Panel 5pp 17114 103 24X Fiche 50-443, 83/02/07, 8302100243

8302140139 Forwards request to participate as interested municipality CA Canney should be placed on svc list Eight specific areas of concern listed
CANNEY, C A Portsmouth, NH 83/02/07 HOYT, H F Atomic Safety and Licensing Board Panel 1p 17140 051 24X Fiche 50-443, 83/02/07, 8302140139

--8302140141 Request to participate as interested municipality pursuant to 10CFR2.715(c) Certificate of Svc encl
CANNEY, C A Portsmouth, NH 83/02/07 Atomic Safety and Licensing Board Panel 2pp 17140 052 24X Fiche 50-443, 83/02/07, 8302140139

8302160207 Ninth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I B 1 Facility RHR relies on sys which are safety-grade & environmentally qualified Certificate of Svc encl Related correspondence
DIGNAM, T O, GAD, R K Public Service Co of New Hampshire DIGNAM, T O Ropes & Gray 83/02/09 Atomic Safety and Licensing Board Panel 3pp 17163 041 24X Fiche 50-443, 83/02/09, 8302160207

DOCKETED ITEMS

- B302160216 Affidavit of PL Anderson, supporting ninth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I B 1
ANDERSON, P L Yankee Atomic Electric Co 83/02/28 1p
17163 046 24X Fiche 50-443, 83/02/09, B302160207
- B302160323 Sixteenth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I M Evidentiary hearings unnecessary Certificate of Svc encl Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/09 Atomic Safety and Licensing Board Panel 5pp 17166 196 24X Fiche 50-443, 83/02/09, B302160323
- B302160341 Affidavit of EA Sawyer supporting summary disposition of New England Coalition on Nuclear Pollution Contention I M Facility meets requirements of ODC 3
SAWYER, E A Yankee Atomic Electric Co 83/02/28 1p 17166 201
24X Fiche 50-443, 83/02/09, B302160323
- B302160329 Eleventh motion for summary disposition of New England Coalition on Nuclear Pollution Contention I C Equipment to ensure pumphouse function is classified safety-related Certificate of Svc encl Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/09 Atomic Safety and Licensing Board Panel 5pp 17164 205 24X Fiche 50-443, 83/02/09, B302160329
- B302160368 Affidavit of PL Anderson on New England Coalition on Nuclear Pollution Contention I C
ANDERSON, P L Yankee Atomic Electric Co 83/02/09 1p
17164 210 24X Fiche 50-443, 83/02/09, B302160329
- B302160346 Answer in opposition to applicant motion to compel answers to B21208 interrogatories & motion for protective order Contentions to which interrogatories relate did not originate w/NH W/Certificate of Svc Related correspondence
KINDER, E T New Hampshire, State of 83/02/09 Atomic Safety and Licensing Board Panel 12pp 17169 223 24X Fiche 50-443, 83/02/09, B302160346
- B302160352 Suppl to answers to third set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence
QAD, R K Public Service Co of New Hampshire QAD, R K Ropes & Gray 83/02/09 New Hampshire, State of 5pp 17167 303 24X Fiche 50-443, 83/02/09, B302160352
- B302170201 Motion for leave to file brief in support of motion for summary disposition Brief would be filed in 3 wks if motion granted
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/02/11 Atomic Safety and Licensing Board Panel 1p 17179 091 24X Fiche 50-443, 83/02/11, B302170201
- B302170284 Motion for summary disposition of contention Suppl III & For ASLR to stay continuation of all OL proceedings until FES conforms w/interim policy statement Statement of matl facts encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/02/11 Atomic Safety and Licensing Board Panel 10pp 17178 190 24X Fiche 50-443, 83/02/11, B302170284
- B302170289 Affidavit of RL Kaufmann supporting Seacoast Anti-Pollution League motion for summary disposition of contention Suppl III Svc list encl
KAUFMANN, R L New Hampshire, Univ of, 83/02/11 3pp
17178 200 24X Fiche 50-443, 83/02/11, B302170284
- B302180093 Sixth motion for summary disposition of Contention NH-13 on compliance w/NUREG-0737 re personnel qualifications & training No genuine issue of matl fact exists Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17216 212 24X Fiche 50-443, 83/02/11, B302180093
- B302180106 Affidavit of QS Thomas supporting sixth motion for summary disposition of Contention NH-13 Certificate of Svc encl
THOMAS, Q S Power Authority of the State of New York 83/02/11 4pp 17216 215 24X Fiche 50-443, 83/02/11, B302180093
- B302180136 Fifth motion for summary disposition of Contentions NH-9 & CCNH-7 re radioactivity monitoring sys & programs meeting requirements of ODC 63 & 64 Statement of matl facts as to which there is no dispute encl Related correspondence
DIGNAN, T G, QAD, R K Power Authority of the State of New York
DIGNAN, T G Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 4pp 17216 166 24X Fiche 50-443, 83/02/11, B302180136
- B302180142 Affidavit of JA MacDonald supporting sixth motion for summary disposition of Contentions NH-9 & CCNH-7 Certificate of Svc encl
MACDONALD, J A Yankee Atomic Electric Co 83/02/11 4pp
17216 170 24X Fiche 50-443, 83/02/11, B302180136
- B302180310 Motion for summary disposition of Contention BAPL Suppl 3 No genuine issue of matl fact exists & until entitled to favorable decision Certificate of Svc encl Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 7pp 17211 221 24X Fiche 50-443, 83/02/11, B302180310
- B302180355 Twelfth motion for summary disposition of Contention NECNP I D 1 re compliance w/ODC 1 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire DIGNAN, T G, QAD, R K Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17209 192 24X Fiche 50-443, 83/02/11, B302180355
- B302180357 Affidavit of JJ Lance supporting twelfth motion for summary disposition of Contention NECNP I D 1 No contention issue warrants hearings Certificate of Svc encl
LANCE, J J Public Service Co of New Hampshire LANCE, J J Yankee Atomic Electric Co 83/02/10 3pp 17209 195 24X Fiche 50-443, 83/02/11, B302180355
- B302180360 Thirteenth motion for summary disposition of Contention NECNP I D 2 re compliance w/ODC 21 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire DIGNAN, T G, QAD, R K Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17209 198 24X Fiche 50-443, 83/02/11, B302180360
- B302180361 Affidavit of WN Fadden supporting thirteenth motion for summary disposition of Contention NECNP I D 2 No contention issue warrants hearings Certificate of Svc encl
FADDEN, W N Public Service Co of New Hampshire FADDEN, W N Yankee Atomic Electric Co 83/02/10 3pp 17209 201 24X Fiche 50-443, 83/02/11, B302180360
- B302180421 Eighth motion for summary disposition of Contention NECNP I A 2 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17214 339 24X Fiche 50-443, 83/02/11, B302180421
- B302180428 Affidavit of JM O'Connor supporting eighth motion for summary disposition of Contention NECNP I A 2 Certificate of Svc encl
O'CONNOR, J M Yankee Atomic Electric Co 83/02/11 4pp
17214 342 24X Fiche 50-443, 83/02/11, B302180421
- B302180487 Fourteenth motion for summary disposition of Contention NECNP I D 3 re compliance w/ODC 30 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire DIGNAN, T G, QAD, R K Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17210 346 24X Fiche 50-443, 83/02/11, B302180487
- B302180493 Affidavit of WN Fadden supporting fourteenth motion for summary disposition of Contention NECNP I D 3 No contention issue warrants hearings Certificate of Svc encl
FADDEN, W N Public Service Co of New Hampshire FADDEN, W N Yankee Atomic Electric Co 83/02/10 3pp 17210 349 24X Fiche 50-443, 83/02/11, B302180487
- B302180295 Twenty-first motion for summary disposition of NECNP Contentions III 12 & III 13 No genuine issue of matl fact exists & until entitled to favorable decision Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 3pp 17210 171 24X Fiche 50-443, 83/02/14, B302180295
- B302180302 Affidavit of JA MacDonald supporting 21st motion for summary disposition of NECNP Contentions III 12 & III 13 Evacuation time estimates calculated for 2.5 & 10-mile radii areas Certificate of Svc encl
MACDONALD, J A Public Service Co. of New Hampshire 83/02/11 5pp 17210 174 24X Fiche 50-443, 83/02/14, B302180295
- B302180308 Eighteenth motion for summary disposition of Contentions NECNP II B 1, 3, 4 & 5. No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
DIGNAN, T G, QAD, R K Public Service Co. of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 3pp 17210 102 24X Fiche 50-443, 83/02/14, B302180308

DOCKETED ITEMS

--8302180314 Affidavit of VL Killpack supporting motion for summary disposition of Contentions NECNP II B 1,3,4 & S Certificate of Svc encl
KILLPACK, V L Public Service Co of New Hampshire 83/02/14
3pp 17210 105 24X Fiche 50-443,83/02/14,8302180308

8302180322 Seventeenth motion for summary disposition of Contention
NECNP I U No genuine issue of matl fact exists & applicant
entitled to favorable decision Certificate of Svc encl
Related correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/14 Atomic Safety and Licensing
Board Panel 3pp 17210 097 24X Fiche 50-443,83/02/14,8302180322

8302180373 Motion to extend time until 830215 to file motions for
summary disposition East coast blizzard made necessary
reproduction svcs impossible Certificate of Svc encl Related
correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/14 Atomic Safety and Licensing
Board Panel 4pp 17210 179 24X Fiche 50-443,83/02/14,8302180375

8302180400 Seventh motion for summary disposition of Contentions NH-21
& CCNHH-S re onsite protective measures Related
correspondence
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/14 Atomic Safety and Licensing
Board Panel 3pp 17208 199 24X Fiche 50-443,83/02/14,8302180400

--8302180404 Affidavit of JA MacDonald supporting motion for summary
disposition of Contentions NH-21 & CCNHH-S Applicants fully
addressed all regulatory requirements re onsite protective
measurements Certificate of Svc encl
MACDONALD, J A Public Service Co of New Hampshire 83/02/11
338pp 17208 202 24X Fiche 50-443,83/02/14,8302180400

8302180465 Twentieth motion for summary disposition of Contention
NECNP III 2 No genuine issue of matl fact exists & util
entitled to favorable decision
DIGNAN, T G, QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/14 Atomic Safety and Licensing
Board Panel 3pp 17214 001 24X Fiche 50-443,83/02/14,8302180465

--8302180475 Affidavit of JA MacDonald supporting twentieth motion for
summary disposition of Contention NECNP III 2 Radiological
emergency plan adequate Certificate of Svc encl
MACDONALD, J A Yankee Atomic Electric Co 83/02/11 5pp
17214 004 24X Fiche 50-443,83/02/14,8302180465

8302250036 Motion for summary disposition of portion of NH Contention
13(a) - (d) re operations personnel qualifications &
training No genuine issue of matl fact exists & dismissal
warranted
PATTERSON, W F Hearing Branch 3 LESSY, R P Hearings Division
83/02/14 Atomic Safety and Licensing Board Panel 16pp
17294 017 24X Fiche 50-443,83/02/14,8302250036

--8302250042 Affidavit of JT Higgins Requirements of NUREG-0737, Item
I A 1.1, "Shift Technical Advisor," relates only to shift
technical advisor position & not to other operations
personnel positions Prof qualifications encl
WIGGINS, J T Division of Project & Resident Programs 83/02/14
4pp 17294 033 24X Fiche 50-443,83/02/14,8302250036

--8302250047 Affidavit of HQ Kennedy Util committed to implement
Westinghouse Owners Group guidelines on program of emergency
operating procedures & operator training in response to
NUREG-0737, Item 1 C 1 Prof qualifications encl
KENNEDY, H O Procedures & Test Review Branch 83/02/09 3pp
17294 037 24X Fiche 50-443,83/02/14,8302250036

--8302250055 Affidavit of JJ Buzy Util committed to implement INPD
training program re recognition & mitigation of consequences
of core damage, in response to NUREG-0737, Item II B 4,
"Training for Mitigating Core Damage" Program acceptable
BUZY, J J Licensee Qualifications Branch 83/02/09 62pp
17294 040 24X Fiche 50-443,83/02/14,8302250036

8302170098 Advises that NRC takes no position on util motions to compel
answers to interrogatories by State of NH, Seacoast Anti-
Pollution League & New England Coalition on Nuclear
Pollution & to League objection to util motion
PATTERSON, W F Hearing Branch 3 83/02/16, HOYT, H, LUEBKE, E A
HARBOUR, J Atomic Safety and Licensing Board Panel 2pp
17181-360 24X Fiche 50-443,83/02/16,8302170098

8302170279 Memorandum & order re motions on interrogatories to & from
Hampton Beach Area Chamber of Commerce Hampton directed to
answer NRC 821110 & Util 821208 interrogatories & requests
for production NRC need not answer Hampton 830117 filing
HOYT, H F Atomic Safety and Licensing Board Panel 83/02/16
Hampton Beach Area Chamber of Commerce, Hampton, NH 4pp
17178 203 24X Fiche 50-443,83/02/16,8302170279

8302220366 Motion for 2-day extension to file motions to compel util
answers to interrogatories & answer opposing util motion to
compel Delay due to historic blizzard
CURRAN, D, BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and Licensing
Appeal Panel 1p 17232 342 24X Fiche 50-443,83/02/16,8302220366

--8302220382 Motion to compel util answers to New England Coalition on
Nuclear Pollution second set of interrogatories on
Contentions I D 1, I D 4, I F, I L 1 & I B Util refuses to
provide access to draft reactor vessel exam plan
CURRAN, D, BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and
Licensing Appeal Panel 2pp 17232 343 24X
Fiche 50-443,83/02/16,8302220366

--8302220392 Motion to compel util answers to New England Coalition on
Nuclear Pollution third set of interrogatories on
Contentions I A 2, I B 1, I B 2 & I C
CURRAN, D, BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and
Licensing Appeal Panel 2pp 17232 345 24X
Fiche 50-443,83/02/16,8302220366

--8302220399 Answer opposing util motion to compel & motion for
protective order Certificate of Svc encl
CURRAN, D, BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and
Licensing Appeal Panel 19pp 17232 347 24X
Fiche 50-443,83/02/16,8302220366

8302220018 Response to City of Portsmouth, NH 830207 request to
participate as interested municipality NRC has no objection
if City admitted sub; to same conditions as listed towns &
if City takes proceeding as is Certificate of Svc encl
PATTERSON, W F Hearing Branch 3 83/02/18 Atomic Safety and
Licensing Board Panel 4pp 17233 101 24X Fiche 50-443,83/02/18,
8302220018

8302280181 Order scheduling 830317 prehearing conference in Boston, MA
re motions for summary disposition, contentions & emergency
plans
HOYT, H F Atomic Safety and Licensing Board Panel 83/02/24 2pp
17305 264 24X Fiche 50-443,83/02/24,8302280181

K Utility Final Safety Analysis Report (FSAR) & amends

8302230359 Amend 4B to FSAR
* Public Service Co of New Hampshire 83/01/31 1574pp
17264 09B 24X Fiche 50-443,83/01/31,8302230359

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000,83/01/26,8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8302170366 Responds to Mechanical Engineering Branch Open Item
SRP 10 2 3 re turbine insp frequency Turbine maint program
will be adopted & turbine insp will be performed prior to
power escalation
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/11 KNIGHTON, Q W Licensing
Branch 3 2pp 17187 115 24X Fiche 50-443,83/02/11,8302170366

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

DOCKETED ITEMS

33

B212060356 IE Info Notice 83-06, "Nonidentical Replacement Parts"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/02/24 Consolidated Edison Co of New
 York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060356

R Periodic operating reports & related correspondence

B302040356 Forwards const status rept for period ending 821231
 DEVINCENTIS, J Public Service Co of New Hampshire 83/01/31
 HARTFIELD, R A Management Information Branch 6pp 17019 054 24X
 Fiche 50-443, 83/01/31, B302040356

S Reportable occurrences, LERs & related correspondence

B302030275 Interim deficiency rept re sheared pinion keys in Limitorque
 Model SB-0-25 motor operators initially reported on 820805
 Westinghouse & Limitorque continuing investigation to
 identify operators & corrective action Next rept by 830501
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/26 STAROSTECKI, R Division of
 Project & Resident Programs 2pp 17008 082 24X
 Fiche 50-443, 83/01/26, B302030275

B302030455 Final deficiency rept re partition-type nonmasonry
 walls not designed to initial project seismic criteria
 Initially reported on 821223 Design of walls revised & walls
 will be structurally modified
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/26 STAROSTECKI, R Region 1,
 Office of Director 3pp 17006 194 24X Fiche 50-443, 83/01/26,
 B302030455

B302030563 Interim deficiency rept re power surges in solid state
 protection sys Initially reported on 820805 Test procedure
 changes per Westinghouse 820806 ltr will be used until
 Westinghouse completes review Next rept provided by 830701
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/26 STAROSTECKI, R Division of
 Project & Resident Programs 2pp 17008 118 24X
 Fiche 50-443, 83/01/26, B302030563

B302230449 Interim deficiency rept re Westinghouse-mfg gate valve
 position indicators Initially reported on 830110 Detailed
 analysis & corrective actions will be provided by 830430
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/11 STAROSTECKI, R Division of
 Project & Resident Programs 2pp 17256 341 24X
 Fiche 50-443, 83/02/11, B302230449

B302250033 Interim Deficiency Rept SRN-473 re electrical cable tray
 support bolts Initially reported on 810727 Final rept
 expected by 840131 following review of United Engineers &
 Constructors test results due 831206
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/18 STAROSTECKI, R Division of
 Project & Resident Programs 2pp 17294 113 24X
 Fiche 50-443, 83/02/18, B302250033

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants
 for OLS, NRS vendors, reactor vendors & AE re certificates
 & revised format for reactor operator & senior reactor
 operator licenses Svc list encl
 EISENHUT, D Q Division of Licensing 83/01/31 Consolidated
 Edison Co of New York, Inc 14pp 17347 177 24X
 Fiche 50-000, 83/01/31, B301310203

X Onsite Storage of Low Level Waste

B302150134 Responds to B30104 inquiry re possible long-term storage of
 low level radwaste at plant NRC should not take deliberate
 action that would hinder establishment of addl disposal
 capacity by states but should permit util flexibility
 BRENNEMAN, F N Region 1, Office of Director 83/02/03
 EISENBERG, R H New Hampshire, State of 2pp 17147 282 24X
 Fiche 50-443, 83/02/03, B302150134

--B302150143 Requests comments on possibility of long-term storage of
 low level radwaste at plant
 EISENBERG, R H New Hampshire, State of 83/01/04,
 BRENNEMAN, F N Region 1, Office of Director 2pp 17147 287
 24X Fiche 50-443, 83/02/03, B302150143

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B302020500 Forwards info on operability qualification & demonstration
 of purge & vent valves to help prepare for Seismic
 Qualification Review Team site audits
 KNIGHTON, G W Licensing Branch 3 83/01/24 TALLMAN, W C Public
 Service Co of New Hampshire 9pp 16999 279 24X
 Fiche 50-443, 83/01/24, B302020500

B302010406 Forwards response re single failure assumptions for
 Condition II events, supplementing 820312 response Response
 will be included in Amend 49 to OL application
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/28 KNIGHTON, G W Licensing
 Branch 3 4pp 16974 264 24X Fiche 50-443, 83/01/28, B302010406

B302010435 Forwards responses to Requests for Addl Info 440 B9 &
 440 127 re locked rotor/shaft break event Item discussed in
 B30110-12 meetings & will be included in Amend Application
 49
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/28 KNIGHTON, G W Licensing
 Branch 3 13pp 16981 035 24X Fiche 50-443, 83/01/28, B302010435

B302010646 Forwards open item responses to Auxiliary Sys Branch &
 Containment Sys Branch re RCPB leakage detection,
 NUREG-0737, Items II E 4.2, "Containment Isolation
 Dependability," & II F 1.2, "Containment Water Level"
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/28 KNIGHTON, G W Licensing
 Branch 3 6pp 16980 042 24X Fiche 50-443, 83/01/28, B302010646

B302020152 Responds to open item re SRP 9.5.8 concerning design
 of emergency diesel generator exhaust piping Flanged joints
 on diesel exhaust sys will be visually inspected for leakage
 & commitments included in OL application/Amend 48
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/31 KNIGHTON, G W Licensing
 Branch 3 2pp 16993 360 24X Fiche 50-443, 83/01/31, B302020152

B302020273 Forwards marked-up FSAR Table 3.9(B)-23, resulting from
 review or test requirements for safety class valves Changes
 will be incorporated in Amend 48 to OL application
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/31 KNIGHTON, G W Licensing
 Branch 3 56pp 16994 024 24X Fiche 50-443, 83/01/31, B302020273

B302020281 Forwards revs to FSAR Sections 12.5.1 & 13.1.2.2 & Figures
 12.5-1 & 13.1-5, in response to 821014 memo re safety review
 open items
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/01/31 KNIGHTON, G W Licensing
 Branch 3 6pp 16993 320 24X Fiche 50-443, 83/01/31, B302020281

B302040092 Forwards revised FSAR Pp 3.9(B)-9 & 3.9(B)-10 re steady
 state & operating transient vibration, in response to
 Mechanical Engineering Branch open items
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/01 KNIGHTON, G W Licensing
 Branch 3 4pp 17021 249 24X Fiche 50-443, 83/02/01, B302040092

B302040109 Forwards responses to Power Sys Branch open items discussed
 at B30110-12 & 15 meetings Responses will be included in
 Amend 49 to OL application
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/01 KNIGHTON, G W Licensing
 Branch 3 12pp 17020 303 24X Fiche 50-443, 83/02/01, B302040109

B302040372 Responds to open item re containment spray chemistry, per
 discussion at B30110-12 & 26 meetings Operability of
 gravity feed sys will be demonstrated during preoperational
 testing of ECCS
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/01 KNIGHTON, G W Licensing
 Branch 3 2pp 17018 279 24X Fiche 50-443, 83/02/01, B302040372

B302040066 Forwards marked-up FSAR pages re responses to open items of
 SRP Sections 12.3.4 & 12.5.2 Encl will be included in Amend
 48 to OL application
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing
 Branch 3 6pp 17020 147 24X Fiche 50-443, 83/02/02, B302040066

B302040338 Forwards revised FSAR Section 6.2.2.2 re inert cover gas
 on sodium hydroxide tank FSAR rev will be included in OL
 application/Amend 48
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing
 Branch 3 3pp 17018 237 24X Fiche 50-443, 83/02/02, B302040338

DOCKETED ITEMS

8302040425 Forwards revised response to Request for Addl Info 440 133
Response reflects discussions w/Reactor Sys Branch at
830110-12 meeting & will be included in Amend 48 to OL
application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing
Branch 3 18pp 17017 310 24X Fiche 50-443, 83/02/02, 8302040425

8302080186 Forwards response to Hydrologic & Geotechnical Engineering
Branch Request for Addl Info RAI 240 42 w/three oversize
drawings, including one proprietary Nonproprietary aperture
cards in PDR, proprietary cards in Central Files.
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/03 KNIGHTON, G W Licensing
Branch 3 306pp 17053 057 24X Fiche 50-443, 83/02/03, 8302080186

8302080215 Forwards revised FSAR Section 3 9(B) 3 4 re snubber
installation & operability verification, in response to
Mechanical Engineering Branch open item Revs will be
included in Amend 49 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/03 KNIGHTON, G W Licensing
Branch 3 5pp 17058 040 24X Fiche 50-443, 83/02/03, 8302080215

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PHWRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D G Division of Licensing, 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Nestinghouse designed
NSSS re resolution of TMI Action Item I K 3 5, "Automatic
Trip of Reactor Coolant Pumps"
EISENHUT, D G Division of Licensing 83/02/08 Baltimore Gas &
Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08,
8302090080

8302150407 Notifies that loose parts monitoring sys that complies
w/Reg Guide 1 133 has been purchased from Technology for
Energy Corp Detailed info required by Reg Guide 1 133,
Positions C 1, C 2, C 3, C 4, C 5 & C 6 to be provided 830701.
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/09 KNIGHTON, G W Licensing
Branch 3 2pp 17157 244 24X Fiche 50-443, 83/02/09, 8302150407

8302150451 Forwards revised FSAR pages for Sections 9 1 2 & 9.1 3 re
spent fuel pool cooling subsys Pages will be incorporated in
OL application, Amend 48
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/09 KNIGHTON, G W Licensing
Branch 3 17pp 17158 175 24X Fiche 50-443, 83/02/09, 8302150451

8302160263 Forwards "Criticality Analysis of Seabrook Spent Fuel," in
response to Auxiliary Branch request for addl info Rept to
be incorporated in OL application Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/10 KNIGHTON, G W Licensing
Branch 3 17pp 17170 239 24X Fiche 50-443, 83/02/10, 8302160263

8302170369 Forwards revised FSAR Table 13 2-3 indicating that training
program for mitigating core damage follows INPO guidelines,
in response to NRC 830210 request Revised table will be
included in Amend 49 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/10 KNIGHTON, G W Licensing
Branch 3 3pp 17187 130 24X Fiche 50-443, 83/02/10, 8302170369

8302250105 Summary of 821230, 830110-12, 18, 19, 25 & 26 meetings
w/applicant re open items in review of electrical power sys,
fire protection program & mechanical sys associated
w/emergency diesel generator Revised memo encl
WHEELER, L Licensing Branch 3 83/02/10 Licensing Branch 3
Bpp 17303 077 24X Fiche 50-443, 83/02/10, 8302250105

8302160166 Responds to open item re potential for unmonitored discharge
of steam generator blowdown demineralizer regenerant
solution Samples will be analyzed for radioactive
contaminants prior to discharging waste holdup sump
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire, 83/02/14 KNIGHTON, G W Licensing
Branch 3 3pp 17162-069 24X Fiche 50-443, 83/02/14, 8302160166

8302160274 Forwards revised response to open item re preheating of
diesel engine combustion air in low ambient air temp & no
load conditions Revised response addresses qualification of
diesel air preheating sys & corrects typographical errors.
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/14 KNIGHTON, G W Licensing
Branch 3 4pp 17170 234 24X Fiche 50-443, 83/02/14, 8302160274.

8302160326 Forwards revised responses to 640 series request for addl
info re procedures & tests
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/14 KNIGHTON, G W Licensing
Branch 3 12pp 17166 216 24X Fiche 50-443, 83/02/14, 8302160326

8302220166 Forwards responses to Containment Sys Branch Open Item SRP
A 2 8, per TMI Action Items II E 4 2 & II F 1 2 Responses
will be incorporated in OL application, Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 8pp 17233 154 24X Fiche 50-443, 83/02/17, 8302220166

8302220327 Forwards revised pages of previously submitted responses to
requests for addl info in response to Instrumentation &
Control Sys Branch open items Supplementary info re
Requests for Addl Info 420 21 & 420 29 also encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 18pp 17230 096 24X Fiche 50-443, 83/02/17, 8302220327

8302220331 Forwards response to open item re NUREG-0737, Item II F 2,
"Detection of Inadequate Core Cooling" Commitment to
utilize reactor coolant inventory monitor, saturation monitor
& core exit thermocouples encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 4pp 17230 087 24X Fiche 50-443, 83/02/17, 8302220331.

8302220388 Forwards revised FSAR Pages 1 8-17 & 5 2-24 through 5 2-31
in response to open item re detection of leakage from RCPB
FSAR pages will be incorporated in Amend 49 to OL
application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/17 KNIGHTON, G W Licensing
Branch 3 13pp 17232 016 24X Fiche 50-443, 83/02/17, 8302220388

8302250172 Amend 48 to application for OLs, incorporating responses/
revised responses to NRC request for addl info, responses to
NRC licensing review open items & miscellaneous & minor
editorial revs
JOHNSON, W P Yankee Atomic Electric Co JOHNSON, W P. Public
Service Co of New Hampshire 83/02/18 KNIGHTON, G W Licensing
Branch 3 2pp 17294 011 24X Fiche 50-443, 83/02/18, 8302250172

8302250441 Forwards info re low temp overpressure protection in
response to Request for Addl Info 440 132 Response will be
incorporated in OL application, Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/23 KNIGHTON, G W Licensing
Branch 3 5pp 17296 352 24X Fiche 50-443, 83/02/23, 8302250441

E NRC Safety Evaluation Report (SER), supply & correspondence

8302040210 Forwards response to open item re reactor vessel closure
study Response discussed in 830110-12 meetings w/Matls
Engineering Branch & will be included in Amend 49 to OL
application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/01 KNIGHTON, G W Licensing
Branch 3 3pp 17023 328 24X Fiche 50-443, 83/02/01, 8302040210

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302040036 Submits commitment re inadvertent operation of fire
protection sys discussed at 830110-12 & 25 meetings w/Power
Sys Branch Spray shield will be provided to protect pump
motor from spray impingement Pump/motor will be elevated
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/02 KNIGHTON, G W Licensing
Branch 3 3pp 17020 330 24X Fiche 50-443, 83/02/02, 8302040036

8302250105 Summary of 821230, 830110-12, 18, 19, 25 & 26 meetings
w/applicant re open items in review of electrical power sys,
fire protection program & mechanical sys associated
w/emergency diesel generator, Revised memo encl
WHEELER, L Licensing Branch 3, 83/02/10 Licensing Branch 3,
Bpp 17303 077 24X Fiche 50-443, 83/02/10, 8302250105

DOCKETED ITEMS

G Adjudicatory correspondence

8302010521 Response to 821111 interrogatories & request for production of documents Certificate of Svc encl Related correspondence
CURRAN, D , JORDAN, W B New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/01/28 Office of the Executive
Legal Director 19pp 16977 273 24X Fiche 50-443, 83/01/28,
8302010521

8302010589 Forwards motion to compel New England Coalition on Nuclear
Pollution answers Related correspondence
GAD, R K Ropes & Gray GAD, R K Public Service Co of New
Hampshire 83/01/28 Public Document Branch 1p 16978 144
24X Fiche 50-443, 83/01/28, 8302010589

--8302010594 Motion to compel New England Coalition on Nuclear Pollution
answers to util 821207 interrogatories Coalition seeks
shelter from obligation behind shield of unpreparedness
W/Certificate of Svc Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/01/28 Atomic Safety and
Licensing Board Panel 22pp 16978 145 24X
Fiche 50-443, 83/01/28, 8302010589

8302010529 Answers to 830107 third set of interrogatories & request for
production of documents Certificate of Svc encl Related
correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/01/29 New Hampshire, State of
10pp 16977 246 24X Fiche 50-443, 83/01/29, 8302010529

8302010533 Answers to 830107 second set of interrogatories & requests
for documents on Contentions I D 1, I D 4, I F 1, I L 1, I L 11 B
& motion for protective order Certificate of Svc encl
Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/01/29 New England Coalition on
Nuclear Pollution 18pp 16977 223 24X Fiche 50-443, 83/01/29,
8302010533

8302010547 Answers to 830107 third set of interrogatories & requests
for documents on Contentions I A 2, I B 1, I D 2 & I C
Certificate of Svc encl Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/01/29 New England Coalition on
Nuclear Pollution 23pp 16982 335 24X Fiche 50-443, 83/01/29,
8302010547

8302020253 Memorandum & Order denying State of NH 830107 objection to
ASLR ruling on motion for extension of discovery NH failed
to meet burden of proving motion should be granted
HOYT, H F Atomic Safety and Licensing Board Panel 83/01/31 New
Hampshire, State of 12pp 16994 282 24X Fiche 50-443, 83/01/31,
8302020253

8302070139 Summarizes conversations re timing of New England Coalition
on Nuclear Pollution responses to NRC interrogatories &
request for production of documents NRC summary disposition
motions on Coalition contentions due 830228
LESSY, R P Hearing Branch 3 83/02/04 CURRAN, D Harmon & Weiss
2pp 17032 344 24X Fiche 50-443, 83/02/04, 8302070139

8302080014 Motion to compel Coastal Chamber of Commerce of NH answers
to NRC 821110 discovery requests or alternatively, to dismiss
contentions on accident classification, onsite protective
measures & radioactive monitoring W/Certificate of Svc
LESSY, R P , PERLIS, R G , PATTERSON, W F Hearing Branch 3 83/02/04
Atomic Safety and Licensing Board Panel 9pp 17058 255 24X
Fiche 50-443, 83/02/04, 8302080014

8302080039 Answer & objection to 830117 interrogatories & request for
production of documents to NRC & util Interrogatories
ultimately Subj of interrogatories does not relate to admitted
contentions Certificate of Svc encl
LESSY, R P Hearing Branch 3 83/02/04 Hampton Beach Area
Chamber of Commerce, Hampton, NH 9pp 17058 163 24X
Fiche 50-443, 83/02/04, 8302080039

8302080185 Response in opposition to applicant motion to compel answers
to interrogatories & motion for issuance of protective
order Supplemental answers to specific interrogatories
currently being prepared W/svc list Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/02/04 Atomic Safety and Licensing Board Panel
8pp 17057 246 24X Fiche 50-443, 83/02/04, 8302080185

8302080238 Forwards objection to util motion to compel interrogatories
& motion for issuance of protective order W/s encl Related
correspondence
BACKUS, R A Backus, Shea & Meyer BACKUS, R A Seacoast
Anti-Pollution League 83/02/04 Docketing & Services Branch.
1p 17057 184 24X Fiche 50-443, 83/02/04, 8302080238

8302080264 First set of interrogatories & requests for documents
Contentions III 1, III 2, III 3, III 12 & III 13 Related
correspondence
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/04 Public Service Co of
Hampshire 18pp 17056 357 24X Fiche 50-443, 83/02/04, 8302080264

8302100220 First motion for summary disposition of New England
Coalition for Nuclear Pollution Contentions I D 4 & I L
Intervenor do not intend to litigate contentions
Certificate of Svc encl Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/07 Atomic Safety and Licensing
Board Panel 10pp 17114 053 24X Fiche 50-443, 83/02/07,
8302100220

8302100228 Fourth motion for summary disposition of New England
Coalition on Nuclear Pollution Contention I.I Regulatory
basis for contention no longer exists Certificate of Svc
encl Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/07 Atomic Safety and Licensing
Board Panel 7pp 17115 045 24X Fiche 50-443, 83/02/07, 8302100228

8302100235 Third motion for summary disposition of New England
Coalition on Nuclear Pollution Contention I F
Interrogatories show contention withdrawn & W/o basis W/
Certificate of Svc Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/07 Atomic Safety and Licensing
Board Panel 8pp 17115 055 24X Fiche 50-443, 83/02/07, 8302100235

8302100243 Second motion for summary disposition of New England
Coalition on Nuclear Pollution Contention I.N
Interrogatories show contention withdrawn Certificate of
Svc encl
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/07 Atomic Safety and Licensing
Board Panel 5pp 17114 103 24X Fiche 50-443, 83/02/07, 8302100243

8302140139 Forwards request to participate as interested municipa
CA Canney should be placed on svc list Eight specific areas
of concern listed
CANNEY, C A Portsmouth, NH 83/02/07 HOYT, H F Atomic Safe
Licensing Board Panel 1p 17140 051 24X Fiche 50-443, 83/02/07,
8302140139

--8302140141 Request to participate as interested municipality pl
to 10CFR2.715(c) Certificate of Svc encl
CANNEY, C A Portsmouth, NH 83/02/07 Atomic Safety and
Licensing Board Panel 2pp 17140 052 24X Fiche 50-443,
83/02/07, 8302140139

8302160207 Ninth motion for summary disposition of New England
Coalition on Nuclear Pollution Contention I B 1 Facility
RHR relies on sys which are safety-grade & environmentally
qualified Certificate of Svc encl Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/09 Atomic Safety and Licensing
Board Panel 5pp 17163 041 24X Fiche 50-443, 83/02/09, 8302160207

--8302160216 Affidavit of PL Anderson supporting ninth motion for
disposition of New England Coalition on Nuclear Pollution
Contention I B 1
ANDERSON, P L Yankee Atomic Electric Co 83/02/28 1p
17163 046 24X Fiche 50-443, 83/02/09, 8302160207

8302160323 Sixteenth motion for summary disposition of New England
Coalition on Nuclear Pollution Contention I.M Evidentiary
hearings unnecessary Certificate of Svc encl Related
correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/09 Atomic Safety and Licensing
Board Panel 5pp 17165 196 24X Fiche 50-443, 83/02/09, 8302160323

--8302160341 Affidavit of EA Sawyer supporting summary dispositio
New England Coalition on Nuclear Pollution Contention I.M
Facility meets requirements of QDC 3.
SAWYER, E A Yankee Atomic Electric Co 83/02/28 1p 1716
24X Fiche 50-443, 83/02/09, 8302160323

8302160329 Eleventh motion for summary disposition of New England
Coalition on Nuclear Pollution Contention I C Equipment to
ensure pumphouse function is classified safety-related
Certificate of Svc encl Related correspondence
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/02/09 Atomic Safety and Licensing
Board Panel 5pp 17164 205 24X Fiche 50-443, 83/02/09, 8302160329

--8302160368 Affidavit of PL Anderson on New England Coalition on
Pollution Contention I C
ANDERSON, P L Yankee Atomic Electric Co 83/02/09 1p
17164 210 24X Fiche 50-443, 83/02/09, 8302160329

DOCKETED ITEMS

8302160346 Answer in opposition to applicant motion to compel answers to 831208 interrogatories & motion for protective order. Contentions to which interrogatories relate did not originate w/NH W/Certificate of Svc Related correspondence KINDER, E. T. New Hampshire, State of 83/02/09 Atomic Safety and Licensing Board Panel 12pp 17169 223 24X Fiche 50-443, 83/02/09, 8302160346

8302160352 Suppl to answers to third set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence QAD, R. K. Public Service Co. of New Hampshire QAD, R. K. Ropes & Gray, 83/02/09 New Hampshire, State of 5pp 17167 303 24X Fiche 50-443, 83/02/09, 8302160352

8302170201 Motion for leave to file brief in support of motion for summary disposition Brief would be filed in 3 wks if motion granted BACKUS, R. A. Seacoast Anti-Pollution League BACKUS, R. A. Backus, Shea & Meyer 83/02/11 Atomic Safety and Licensing Board Panel 1p. 17179 081 24X Fiche 50-443, 83/02/11, 8302170201

8302170284 Motion for summary disposition of contention Suppl III & for ASLR to stay continuation of all CL proceedings until FEB conforms w/interim policy statement Statement of matl facts encl BACKUS, R. A. Seacoast Anti-Pollution League BACKUS, R. A. Backus, Shea & Meyer 83/02/11 Atomic Safety and Licensing Board Panel 10pp 17178 190 24X Fiche 50-443, 83/02/11, 8302170284

--8302170289 Affidavit of RL Kaufmann supporting Seacoast Anti-Pollution League motion for summary disposition of contention Suppl III Svc list encl KAUFMANN, R. L. New Hampshire, Univ. of. 83/02/11 3pp 17178 200 24X Fiche 50-443, 83/02/11, 8302170289

8302180093 Sixth motion for summary disposition of Contention NH-13 on compliance w/NUREG-0737 re personnel qualifications & training No genuine issue of matl fact exists Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17216 212 24X Fiche 50-443, 83/02/11, 8302180093

--8302180106 Affidavit of OS Thomas supporting sixth motion for summary disposition of Contention NH-13 Certificate of Svc encl THOMAS, O. S. Power Authority of the State of New York, 83/02/11 4pp 17216 215 24X Fiche 50-443, 83/02/11, 8302180093

8302180136 Fifth motion for summary disposition of Contentions NH-9 & CCNHN-7 re radioactivity monitoring sys & programs meeting requirements of ODC 63 & 64 Statement of matl facts as to which there is no dispute encl Related correspondence DIGNAN, T. O., QAD, R. K. Power Authority of the State of New York DIGNAN, T. O. Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 4pp 17216 166 24X Fiche 50-443, 83/02/11, 8302180136

--8302180142 Affidavit of JA MacDonald supporting sixth motion for summary disposition of Contentions NH-9 & CCNHN-7 Certificate of Svc encl MACDONALD, J. A. Yankee Atomic Electric Co. 83/02/11 4pp 17216 170 24X Fiche 50-443, 83/02/11, 8302180136

8302180310 Motion for summary disposition of Contention BAPL Suppl 3 No genuine issue of matl fact exists & util entitled to favorable decision Certificate of Svc encl Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 7pp 17211 221 24X Fiche 50-443, 83/02/11, 8302180310

8302180355 Twelfth motion for summary disposition of Contention NECNP I D 1 re compliance w/ODC 1 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence DIGNAN, T. O. Public Service Co. of New Hampshire DIGNAN, T. O., QAD, R. K. Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp. 17209 192 24X Fiche 50-443, 83/02/11, 8302180355

--8302180357 Affidavit of JJ Lance supporting twelfth motion for summary disposition of Contention NECNP I D 1 No contention issue warrants hearings Certificate of Svc encl LANCE, J. J. Public Service Co. of New Hampshire LANCE, J. J. Yankee Atomic Electric Co. 83/02/10 3pp 17209 195 24X Fiche 50-443, 83/02/11, 8302180355

8302180360 Thirteenth motion for summary disposition of Contention NECNP I D 2 re compliance w/ODC 21 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence DIGNAN, T. O. Public Service Co. of New Hampshire DIGNAN, T. O., QAD, R. K. Ropes & Gray, 83/02/11 Atomic Safety and Licensing Board Panel 3pp. 17209 198 24X Fiche 50-443, 83/02/11, 8302180360

--8302180361 Affidavit of WN Fadden supporting thirteenth motion for summary disposition of Contention NECNP I D 2 No contention issue warrants hearings Certificate of Svc encl FADDEN, W. N. Public Service Co. of New Hampshire FADDEN, W. N. Yankee Atomic Electric Co. 83/02/10 3pp 17209 201 24X Fiche 50-443, 83/02/11, 8302180360

8302180421 Eighth motion for summary disposition of Contention NECNP I A 2 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17214 339 24X Fiche 50-443, 83/02/11, 8302180421

--8302180428 Affidavit of JM O'Connor supporting eighth motion for summary disposition of Contention NECNP I A 2 Certificate of Svc encl O'CONNOR, J. M. Yankee Atomic Electric Co. 83/02/11 4pp 17214 342 24X Fiche 50-443, 83/02/11, 8302180421

8302180487 Fourteenth motion for summary disposition of Contention NECNP I D 3 re compliance w/ODC 30 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence DIGNAN, T. O. Public Service Co. of New Hampshire DIGNAN, T. O., QAD, R. K. Ropes & Gray 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17210 346 24X Fiche 50-443, 83/02/11, 8302180487

--8302180493 Affidavit of WN Fadden supporting fourteenth motion for summary disposition of Contention NECNP I D 3 No contention issue warrants hearings Certificate of Svc encl FADDEN, W. N. Public Service Co. of New Hampshire FADDEN, W. N. Yankee Atomic Electric Co. 83/02/10 3pp 17210 349 24X Fiche 50-443, 83/02/11, 8302180487

8302180295 Twenty-first motion for summary disposition of NECNP Contentions III 12 & III 13 No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 3pp 17210 171 24X Fiche 50-443, 83/02/14, 8302180295

--8302180302 Affidavit of JA McDonald supporting 21st motion for summary disposition of NECNP Contentions III 12 & III 13 Evacuation time estimates calculated for 2.5 & 10-mile radii areas Certificate of Svc encl MCDONALD, J. A. Public Service Co. of New Hampshire 83/02/11 5pp 17210 174 24X Fiche 50-443, 83/02/14, 8302180295

8302180308 Eighteenth motion for summary disposition of Contentions NECNP II B 1, 3, 4 & 5 No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 3pp 17210 102 24X Fiche 50-443, 83/02/14, 8302180308

--8302180314 Affidavit of VL Killpack supporting motion for summary disposition of Contentions NECNP II B 1, 3, 4 & 5 Certificate of Svc encl KILLPACK, V. L. Public Service Co. of New Hampshire 83/02/14 3pp 17210 105 24X Fiche 50-443, 83/02/14, 8302180308

8302180322 Seventeenth motion for summary disposition of Contention NECNP I U No genuine issue of matl fact exists & applicant entitled to favorable decision Certificate of Svc encl Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 5pp 17210 097 24X Fiche 50-443, 83/02/14, 8302180322

8302180375 Motion to extend time until 830215 to file motions for summary disposition East coast blizzard made necessary reproduction svcs impossible Certificate of Svc encl Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 4pp 17210 179 24X Fiche 50-443, 83/02/14, 8302180375

8302180400 Seventh motion for summary disposition of Contentions NH-21 & CCNHN-5 re onsite protective measures Related correspondence DIGNAN, T. O., QAD, R. K. Public Service Co. of New Hampshire DIGNAN, T. O. Ropes & Gray 83/02/14 Atomic Safety and Licensing Board Panel 3pp 17208 199 24X Fiche 50-443, 83/02/14, 8302180400

--8302180406 Affidavit of JA MacDonald supporting motion for summary disposition of Contentions NH-21 & CCNHN-3 Applicants fully addressed all regulatory requirements re onsite protective measurements Certificate of Svc encl MACDONALD, J. A. Public Service Co. of New Hampshire, 83/02/11 33pp 17208 202 24X Fiche 50-443, 83/02/14, 8302180400

DOCKETED ITEMS

3:

8302180465 Twentieth motion for summary disposition of Contention
NECNP III.2 No genuine issue of matl fact exists & util
entitled to favorable decision
DIGNAM, T O , GAD, R K Public Service Co of New Hampshire
DIGNAM, T O Ropes & Oray 83/02/14 Atomic Safety and Licensing
Board Panel 3pp 17214 001 24X Fiche 50-443, 83/02/14, 8302180465

--8302180475 Affidavit of JA MacDonald supporting twentieth motion for
summary disposition of Contention NECNP III.2 Radiological
emergency plan adequate Certificate of Svc encl
MACDONALD, J A Yankee Atomic Electric Co 83/02/11 5pp
17214 004 24X Fiche 50-443, 83/02/14, 8302180465

8302250036 Motion for summary disposition of portion of NH Contention
13(a) - (d) re operations personnel qualifications &
training No genuine issue of matl fact exists & dismissal
warranted
PATTERSON, W F Hearing Branch 3 LESSY, R P Hearings Division
83/02/14 Atomic Safety and Licensing Board Panel 16pp
17294 017 24X Fiche 50-443, 83/02/14, 8302250036

--8302250042 Affidavit of JT Higgins Requirements of NUREG-0737, Item
I A 1.1, "Shift Technical Advisor," relates only to shift
technical advisor position & not to other operations
personnel positions Prof qualifications encl
HIGGINS, J T Division of Project & Resident Programs 83/02/14
App 17294 033 24X Fiche 50-443, 83/02/14, 8302250036

--8302250047 Affidavit of HQ Kennedy Util committed to implement
Westinghouse Owners Group guidelines on program of emergency
operating procedures & operator training, in response to
NUREG-0737, Item I C 1 Prof qualifications encl
KENNEDY, H O Procedures & Test Review Branch 83/02/09 3pp
17294 037 24X Fiche 50-443, 83/02/14, 8302250036

--8302250055 Affidavit of JJ Buzy Util committed to implement INPD
training program re recognition & mitigation of consequences
of core damage, in response to NUREG-0737, Item II B 4,
"Training for Mitigating Core Damage " Program acceptable
BUZY, J J Licensee Qualifications Branch 83/02/09 62pp
17294 040 24X Fiche 50-443, 83/02/14, 8302250036

8302170098 Advises that NRC takes no position on util motions to compel
answers to interrogatories by State of N.H. Seacoast Anti-
Pollution League & New England Coalition on Nuclear
Pollution & to League objection to util motion
PATTERSON, W F Hearing Branch 3 83/02/16 HOYT, H , LUEBKE, E A ,
HARBOR, J Atomic Safety and Licensing Board Panel 2pp
17181 360 24X Fiche 50-443, 83/02/16, 8302170098

8302170279 Memorandum & order re motions on interrogatories to & from
Hampton Beach Area Chamber of Commerce Hampton directed to
answer NRC 821110 & util 821208 interrogatories & requests
for production NRC need not answer Hampton 830117 filing
HOYT, H F Atomic Safety and Licensing Board Panel 83/02/16
Hampton Beach Area Chamber of Commerce, Hampton, NH 4pp
17178 203 24X Fiche 50-443, 83/02/16, 8302170279

8302270366 Motion for 2-day extension to file motions to compel util
answers to interrogatories & answer opposing util motion to
compel Delay due to historic blizzard
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and Licensing
Appeal Panel 1p 17232 342 24X Fiche 50-443, 83/02/16, 8302270366

--8302220382 Motion to compel util answers to New England Coalition on
Nuclear Pollution second set of interrogatories on
Contentions I D 1, I D 4, I F, I, I, I L & II B Util refuses to
provide access to draft reactor vessel exam plan
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and
Licensing Appeal Panel 2pp 17232 343, 24X
Fiche 50-443, 83/02/16, 8302220382

--8302220392 Motion to compel util answers to New England Coalition on
Nuclear Pollution third set of interrogatories on
Contentions I A 2, I B 1, I B 2 & I C
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/02/16 Atomic Safety and
Licensing Appeal Panel 2pp 17232 345 24X
Fiche 50-443, 83/02/16, 8302220382

--8302220399 Answer opposing util motion to compel & motion for
protective order Certificate of Svc encl,
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss, 83/02/16 Atomic Safety and
Licensing Appeal Panel 19pp 17232 347 24X
Fiche 50-443, 83/02/16, 8302220382

8302220018 Response to City of Portsmouth, NH 830207 request to
participate as interested municipality NRC has no objection
if City admitted subj to same conditions as listed towns &
if City takes proceeding as is Certificate of Svc encl
PATTERSON, W F Hearing Branch 3 83/02/18 Atomic Safety and
Licensing Board Panel 4pp 17233 101 24X Fiche 50-443, 83/02/18,
8302220018

8302280181 Order scheduling 830317 prehearing conference in Boston, MA
re motions for summary disposition, contentions & emergency
plans
HOYT, H F Atomic Safety and Licensing Board Panel 83/02/24 2pp
17305 264 24X Fiche 50-443, 83/02/24, 8302280181

K Utility Final Safety Analysis Report (FSAR) & amends

8302230359 Amend 4B to FSAR
* Public Service Co of New Hampshire 83/01/31 1574pp
17264 098 24X Fiche 50-443, 83/01/31, 8302230359.

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiterque HOBC, HIBC, H2BC & H3BC
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments, "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302170366 Responds to Mechanical Engineering Branch Open Item
BRP 10 2 3 re turbine insp frequency Turbine maint program
will be adopted & turbine insp will be performed prior to
power escalation
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/02/11 KNIGHTON, O W Licensing
Branch 3 2pp 17187 115 24X Fiche 50-443, 83/02/11, 8302170366

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 038 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts. "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

R Periodic operating reports & related correspondence

8302040356 Forwards const status rept for period ending 821231
DEVINCENTIS, J Public Service Co of New Hampshire 83/01/31
HARTFIELD, R A Management Information Branch 4pp 17019 054 24
Fiche 50-443, 83/01/31, 8302040356

B Reportable occurrences, LERs & related correspondence

8302030275 Interim deficiency rept re sheared pinion keys in Limitorque
Model SB O-25 motor operators Initially reported on 820803
Westinghouse & Limitorque continuing investigation to
identify operators & corrective action Next rept by 830501
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
Service Co of New Hampshire 83/01/26 STAROSTECKI, R, Division c
Project & Resident Programs 2pp 17008 082 24X
Fiche 50-443, 83/01/26, 8302030275

DOCKETED ITEMS

8302030455 Final deficiency rept re partition-type nonmasonry walls not designed to initial project seismic criteria Initially reported on 821223 Design of walls revised & walls will be structurally modified
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/01/26 STAROSTECKI, R Region 1, Office of Director 3pp 17006 194 24X Fiche 50-443, 83/01/26, 8302030455

8302030563 Interim deficiency rept re power surges in solid state protection sys Initially reported on 820805 Test procedure changes per Westinghouse 820806 ltr will be used until Westinghouse completes review Next rept provided by 830701
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/01/26 STAROSTECKI, R Division of Project & Resident Programs 2pp 17008 118 24X Fiche 50-443, 83/01/26, 8302030563

8302230449 Interim deficiency rept re Westinghouse-mfg gate valve position indicators Initially reported on 830110 Detailed analysis & corrective actions will be provided by 830430
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/11 STAROSTECKI, R Division of Project & Resident Programs 2pp 17256 361 24X Fiche 50-443, 83/02/11, 8302230449

8302250033 Interim Deficiency Rept 88N-473 re electrical cable tray support bolts Initially reported on 810727 Final rept expected by 840131 following review of United Engineers & Constructors test results due 831206
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/18 STAROSTECKI, R Division of Project & Resident Programs 2pp 17294 113 24X Fiche 50-443, 83/02/18, 8302250033

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347:177 24X Fiche 50-000, 83/01/31, 8301310203

X Onsite Storage of Low Level Waste

8302150134 Responds to 830104 inquiry re possible long-term storage of low level radwaste at plant NRC should not take deliberate action that would hinder establishment of addl disposal capacity by states but should permit util flexibility
BRENNEMAN, F N Region 1, Office of Director 83/02/03 EISENOREIN, R H New Hampshire, State of 2pp 17147:282 24X Fiche 50-443, 83/02/03, 8302150134

--8302150143 Requests comments on possibility of long-term storage of low level radwaste at plant
EISENOREIN, R H New Hampshire, State of 83/01/04 BRENNEMAN, F N Region 1, Office of Director 2pp 17147 287 24X Fiche 50-443, 83/02/03, 8302150134

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 1

A. Application/construction stage documents & correspondence

8302080113 Board Notification 82-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake W/o encl.
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic Safety and Licensing Board Panel 18pp 17105 335 24X Fiche 50-000, 82/12/30, 8302080113

8302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment Repts also available in PDR
BAOCHI, G Equipment Qualification Branch 83/02/02 NOQMAN, V B Equipment Qualification Branch 3pp 17203 188 24X Fiche 50-000, 83/02/02, 8302170011

--8212070376 Forwards evaluation of 820809-13 site audit of safety-related electric & mechanical equipment Specific concerns should be resolved satisfactorily as package instead of providing piece meal submittal
NOQMAN, V B Equipment Qualification Branch 82/11/24 YOUNGBLOOD, B J Licensing Branch 1 65pp 17207 195 24X Fiche 50-000, 83/02/02, 8302170011

8302080158 Advises that recheck & changes made to demonstrated radiation values resolve radiation level comment for environ qualification audit
SCHMIDT, H C Texas Utilities Services, Inc 83/02/03 YOUNGBLOOD, B J Licensing Branch 1 1p 17059 063 24X Fiche 50-445, 83/02/03, 8302080158

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

--8210290111 Summary of 820929-30 meeting w/independent design review group of Model D2/D3 steam generator owners & ANL re review of Westinghouse program for correcting damaging tube vibration
KANE, W F Licensing Branch 1 82/10/06 YOUNGBLOOD, B J Licensing Branch 1 5pp 17143 348 24X Fiche 50-000, 83/02/03, 8302100512

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302170339 Forwards documentation for May House, Somervell County, TX Inclusion in Register of Natl Historic Places recommended W/o encl
HERRINGTON, L Texas, State of 83/02/09 ROGERB, J Interior, Dept of, National Park Service 2pp 17184 151 24X Fiche 50-445, 83/02/09, 8302170339

8302230460 Forwards description of proposed Amend 38 to FSAR
MARSHALL, J S Texas Utilities Services, Inc 83/02/14 BURWELL, S B Office of Nuclear Reactor Regulation, Director 7pp 17246 049 24X Fiche 50-445, 83/02/14, 8302230460

8302250161 Notification of 830228 meeting w/util in Bethesda, MD to discuss const & preoperational testing schedule
BURWELL, S B Licensing Branch 1 83/02/16 YOUNGBLOOD, B J Licensing Branch 1 3pp 17298 339 24X Fiche 50-445, 83/02/16, 8302250161

8302280256 Forwards info re eligibility of May House for inclusion in Natl Register of Historic Places, per NRC 820525 request info sent to TX State Historic Preservation officer on 830121
SCHMIDT, H C Texas Utilities Services, Inc 83/02/22 YOUNGBLOOD, B J Licensing Branch 1 22pp 17312 236 24X Fiche 50-445, 83/02/22, 8302280256

--8302280262 "Natl Register Evaluation of May House"
BINGOLETON, K Environmental Consultants, Inc 81/09/03 3pp 17312 252 24X Fiche 50-445, 83/02/22, 8302280256

--8302280267 Requests info to initiate determination of eligibility request to keeper of Natl Register re May House, per 36CFR63 Appropriate measures should be taken to protect resources during eligibility process
YOUNGBLOOD, B J Licensing Branch 1 82/05/25 GARY, R J Texas Utilities Generating Co 2pp 17312 261 24X Fiche 50-445, 83/02/22, 8302280256

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302230177 Forwards response to Action Item I C 5 addressing SER, Suppl 1, NUREG-0797 re feedback of operating experience to plant staff Info will be incorporated into future FSAR amend
SCHMIDT, H C Texas Utilities Services, Inc 83/02/18 YOUNGBLOOD, B J Licensing Branch 1 2pp 17248 093 24X Fiche 50-445, 83/02/18, 8302230177

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

DOCKETED ITEMS

8302170368 Forwards Rev 2 to safeguards contingency plan Rev withheld (ref 10CFR73.21)
GARY, R J Texas Utilities Generating Co 83/02/14 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 17183 338
24X Fiche 50-445, 83/02/14, 8302170368

G Adjudicatory correspondence

8302020240 Request for show cause order for applicants to show cause why Orinell & NPSI design criteria used for pipe supports/hangers should not be provided if util does not have documents. NRC regulations violated Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/01/28
Commissioners 10pp 16994 251 24X Fiche 50-445, 83/01/28, 8302020240

8302020331 Forwards 830119 newspaper article re faulty steam generators Problem significant & should be included in proceedings Related correspondence
ELLIS, J Citizens Association for Sound Energy 83/01/28.
MILLER, M E, MCCOLLUM, K A, COLE, R F Atomic Safety and Licensing Board Panel 3pp 16993 350 24X Fiche 50-445, 83/01/28, 8302020331

8302020265 Order admitting NRC Exhibits 10, 11 & 12 into evidence
MILLER, M E Atomic Safety and Licensing Board Panel 83/01/31
Office of the Executive Legal Director 1p 16994 113 24X
Fiche 50-445, 83/01/31, 8302020265

8302070549 Comments on issue of confidentiality of nuclear witnesses at plant Informants privilege should protect applicant employees who are most vulnerable to reprisal Svc list encl
GARDE, B P Government Accountability Project 83/02/01
ROSENTHAL, A S, JOHNSON, W R, MOORE, T S Atomic Safety and Licensing Appeal Panel 10pp 17034 146 24X Fiche 50-445, 83/02/01, 8302070549

8302070578 Response in opposition to Citizens Assoc for Sound Energy
830118 motion for ASLB order directing NRC & applicants to provide potentially significant documents Prima Facie case not presented W/Certificate of Svc
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S
Debevoise & Liberman 83/02/02 Atomic Safety and Licensing Board Panel 86pp 17034 297 24X Fiche 50-445, 83/02/02, 8302070578

8302080171 Forwards affidavit of RL Messerly re shoddy const practices
ELLIS, J Citizens Association for Sound Energy 83/02/03
Docketing & Services Branch 1p 17058 346 24X
Fiche 50-445, 83/02/03, 8302080171

--8302080173 Affidavit of RL Messerly re shoddy const practices
MESSERLY, R L Citizens Association for Sound Energy
MESSERLY, R L Brown & Root Corp (subs of Halliburton Corp)
83/02/03 8pp 17058 347 24X Fiche 50-445, 83/02/03, 8302080173

8302080189 Suppl to 830124 motion for protective orders for R Combs, L Smith & FR Harrell Witnesses interrogated by applicants w/o legal representation Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/02/03 Atomic
Safety and Licensing Board Panel 4pp 17059 001 24X
Fiche 50-445, 83/02/03, 8302080189

8302080038 Response opposing Citizens Assoc for Sound Energy 830118 motion for ASLB order requiring NRC & util to provide documents Motion is for discovery, which ASLB ordered to be informally discussed w/parties. Certificate of Svc encl
MIZUNO, O S Hearing Branch 1 83/02/04 Atomic Safety and Licensing Board Panel 17pp 17058 172 24X Fiche 50-445, 83/02/04, 8302080038

8302080251 Order striking Govt Accountability Project 830201 filing reviewing issues on appeal Project is not party to proceeding. Filing entirely inappropriate. Proper procedure would have been to file motion to file amicus curiae brief.
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/04
Government Accountability Project 3pp 17057 103 24X
Fiche 50-445, 83/02/04, 8302080251

8302090443 Forwards NRC 830131 ltr issuing BALP rept, including BALP board rept & util comments Rept covers Oct 1981 - Sept 1982
ROTHSCHILD, M U Hearing Branch 1 83/02/08 MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 22pp 17066 264 24X Fiche 50-445, 83/02/08, 8302090443

8302100238 Answer opposing Citizens Assoc for Sound Energy motion & suppl for protective orders ASLB should direct Assoc to cease directing or encouraging concealment of potential nonconforming conditions by applicant employees
REYNOLDS, N S Texas Utilities Generating Co 83/02/08 Atomic
Safety and Licensing Board Panel 27pp 17115 063 24X
Fiche 50-445, 83/02/08, 8302100238

--8302100242 Affidavit of A Vega re RK Combs concerns Investigation of concerns conducted Combs refused to provide component identifications or physically to identify items of concern on advice from Citizens Assoc for Sound Energy
VEGA, A Texas Utilities Generating Co 83/02/04 10pp 17115 090 24X Fiche 50-445, 83/02/08, 8302100238

--8302100246 Affidavit of A Vega re L Smith allegations Investigation of concerns conducted re weld data card for Field Weld 1 on Line MB-2-RB-19 Entire history not on weld card but could be found through ref listed card Certificate of Svc encl
VEGA, A Texas Utilities Generating Co 83/02/07 6pp 17115 100 24X Fiche 50-445, 83/02/08, 8302100238

8302150476 Response opposing Citizens Assoc for Sound Energy 830124 motion for protective orders for R Combs, L Smith & F Ray ASLB lacks jurisdiction to apply Section 210 remedies to employees discriminated against W/Certificate of Svc.
MIZUNO, O S Hearing Branch 1 83/02/14 Atomic Safety and Licensing Board Panel 22pp 17157 090 24X Fiche 50-445, 83/02/14, 8302150476

8302220415 Order requesting info by 830303 from applicants & NRC, to provide current best projections of completion dates of Unit 1
MILLER, M E Atomic Safety and Licensing Board Panel 83/02/17.
Texas Utilities Generating Co 2pp 17232 134 24X
Fiche 50-445, 83/02/17, 8302220415

8302230505 Forwards License 81M-1912, issued to util on 830214 Related documents encl
ROTHSCHILD, M U Hearing Branch 1 83/02/18, MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 14pp 17245 168 24X Fiche 50-445, 83/02/18, 8302230505.

8302240016 Forwards 1E Insp Repts 50-445/82-26 & 50-446/82-14 re Walsh & Doyle allegations on pipe support engineering program
ROTHSCHILD, M U Hearing Branch 1 83/02/22, MILLER, M E, COLE, R., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 41pp 17271 265 24X Fiche 50-445, 83/02/22, 8302240016

8302250279 Decision ALAB-714, dismissing NRC appeal of ASLB 820930 order directing disclosure of Informants Appeal dismissed for want of genuine controversy. Grant of petition for directed certification withdrawn. Johnson dissenting opinion encl
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/24.
33pp 17291 302 24X Fiche 50-445, 83/02/24, 8302250279

8302280398 Forwards provisional proposed findings of fact, transcript corrections & exhibit list on all controverted matters except Walsh/Doyle allegations
ROTHSCHILD, M U, MIZUNO, O S Hearing Branch 1 83/02/24
MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 17310 029 24X Fiche 50-445, 83/02/24, 8302280398

--8302280403 Provisional proposed findings of fact.
ROTHSCHILD, M U, MIZUNO, O S Hearing Branch 1 83/02/24. 218pp.
17310 030 24X Fiche 50-445, 83/02/24, 8302280398

--8302280407 Transcript corrections for 811202-03, 820607-11, 0726-30 & 0913-17 OL hearings Certificate of Svc encl
ROTHSCHILD, M U, MIZUNO, O S Hearing Branch 1 83/02/24. 7pp
17310 248 24X Fiche 50-445, 83/02/24, 8302280398

8302280265 Application for stay of effectiveness of ASLB 830224 Decision ALAR-714 NRC likely to prevail on merits. Irreparable injury will result & no other parties will be harmed Certificate of Svc encl
CUNNINGHAM, O H Office of the Executive Legal Director TURK, S E.
Hearing Branch 1 83/02/25 Atomic Safety and Licensing Appeal Panel 13pp 17312 269 24X Fiche 50-445, 83/02/25, 8302280265.

J Insurance & indemnity information

8302100216 Forwards Endorsement & to NELIA Policy NF-274.
GARY, R J Texas Utilities Generating Co 83/01/26 SALTZMAN, J. D.
Office of State Programs, Director 2pp 17114 063 24X
Fiche 50-445, 83/01/26, 8302100216

K. Utility Final Safety Analysis Report (FSAR) & amends

8302170175 Forwards Amend 38 to FSAR Affidavit encl
CLEMENIS, B. R. Texas Utilities Generating Co. 83/02/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17183 080
24X Fiche 50-445, 83/02/14, 8302170175

--8302170179 Amend 38 to FSAR
Texas Utilities Generating Co 83/02/14. 238pp. 17183 082.
24X Fiche 50-445, 83/02/14, 8302170175

DOCKETED ITEMS

M Antitrust correspondence

8302150371 Confirms telcon w/OS Powers & 830209 notification of destruction of util exhibits
VOGLER, B H Antitrust Division 83/02/10 KNOTTS, J B Debevoise & Liberman 1p 17157 227 24X Fiche 50-445, 83/02/10, 8302150371

Q Inspection reports, IE Bulletins & correspondence

8302030326 Forwards IE Insp Rept 50-445/82-31 on 821201-31 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/01/18 GARY, R J Texas Utilities Generating Co 2pp 17001 278 24X Fiche 50-445, 83/01/18, 8302030326

--8302030331 IE Insp Rept 50-445/82-31 on 821201-31 No noncompliance noted. Major areas inspected preoperational test procedure review, plant tours, initial startup procedure review, preoperational test performance & plant status
KELLEY, D L, WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 83/01/14 8pp 17001 280 24X Fiche 50-445, 83/01/18, 8302030326

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302090403 Responds to Rev 1, Suppl 1 to IE Bulletin 82-01
Radiographing of all welds has been completed Welds acceptable
GARY, R J Texas Utilities Generating Co 83/01/31 COLLINS, J T Region 4, Office of Director 1p 17071 085 24X Fiche 50-445, 83/01/31, 8302090403

8302170353 Responds to 821227 ltr commenting on SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982
COLLINS, J T Region 4, Office of Director 83/01/31 GARY, R J Texas Utilities Generating Co 3pp 17185 099 24X Fiche 50-445, 83/01/31, 8302170353

--8302170357 Comments on observations made in NRC SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982 Util recognizes need for improvement in performing insps of vendor supplied welds
GARY, R J Texas Utilities Generating Co 82/12/27 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 2pp 17185 102 24X Fiche 50-445, 83/01/31, 8302170353

--8302170359 Forwards SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982
MADSEN, G L Region 4, Office of Director 82/12/03 GARY, R J Texas Utilities Generating Co 2pp 17185 104 24X Fiche 50-445, 83/01/31, 8302170353

--8302170364 SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982
WESTERMAN, T F, MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/11/24 15pp 17185 106 24X Fiche 50-445, 83/01/31, 8302170353

8302070413 Ack receipt of 830111 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/82-11 & 50-446/82-10
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/02 GARY, R J Texas Utilities Generating Co 1p 17029 299 24X Fiche 50-445, 83/02/02, 8302070413

8302070419 Responds to NRC 821213 ltr re violations noted in IE Insp Repts 50-445/82-11 & 50-446/82-10 Corrective actions subj alleged tenure verified & QA Procedure CP-QAP-2 1, "Personnel Training & Qualification," revised
GARY, R J Texas Utilities Generating Co 83/01/11 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 3pp 17029 300 24X Fiche 50-445, 83/02/02, 8302070413

8302090443 Forwards NRC 830131 ltr issuing SALP rept, including SALP board rept & util comments Rept covers Oct 1981 - Sept 1982
ROTHSCHILD, M U Hearing Branch 1 83/02/08 MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 22pp 17066 264 24X Fiche 50-445, 83/02/08, 8302090443

8302160322 Informs that IE Insp Rept 50-445/82-28 has been canceled No insp rept will be issued for rept number
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/08 GARY, R J Texas Utilities Generating Co 1p 17170 222 24X Fiche 50-445, 83/02/08, 8302160322

8302230526 IE Insp Repts 50-445/82-17 & 50-446/82-08 have been canceled
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/15 GARY, R J Texas Utilities Generating Co 1p 17237 279 24X Fiche 50-445, 83/02/15, 8302230526

8302250159 Submits daily highlight for 830215 IE Insp Repts 50-445/82-26 & 50-446/82-14 will be signed & issued
BURNELL, S B Licensing Branch 1 83/02/15 DENTON, H R, CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 17298 342 24X Fiche 50-445, 83/02/15, 8302250159

8302250237 Forwards IE Insp Repts 50-445/82-26 & 50-446/82-14 on 821013-1202 & 830118 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/15 GARY, R J Texas Utilities Generating Co 2pp 17295 156 24X Fiche 50-445, 83/02/15, 8302250237

--8302250243 IE Insp Repts 50-445/82-26 & 50-446/82-14 on 821013-1202 & 830118 No noncompliance noted Major areas inspected pipe support engineering program in response to concerns expressed at ASLB hearing
TAPIA, J I, TAYLOR, R G Division of Resident, Reactor Project & Engineering Programs RAJAN, J R N Mechanical Engineering Branch 83/02/09 59pp 17295 158 24X Fiche 50-445, 83/02/15, 8302250237

8302230538 Advises of program instituted to send copy of insp repts of vendors used at facilities Repts will be forwarded w/o transmittal ltr through resident inspector, w/distribution ticket to flag significant problems
COLLINS, J T Region 4, Office of Director 83/02/16 GARY, R J Texas Utilities Generating Co 3pp 17256 351 24X Fiche 50-445, 83/02/16, 8302230538

8302230630 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/82-30
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/17 GARY, R J Texas Utilities Generating Co 1p 17254 195 24X Fiche 50-445, 83/02/17, 8302230630

--8302230648 Responds to NRC 830112 ltr re violations noted in IE Insp Rept 50-445/82-30 Corrective actions program established to recheck all certified pipe support packages for calculation errors by 830801
GARY, R J Texas Utilities Generating Co 83/02/10 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 3pp 17254 196 24X Fiche 50-445, 83/02/17, 8302230630

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302240016 Forwards IE Insp Repts 50-445/82-26 & 50-446/82-14 re Walsh & Doyle allegations on pipe support engineering program
ROTHSCHILD, M U Hearing Branch 1 83/02/22 MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 61pp 17271 265 24X Fiche 50-445, 83/02/22, 8302240016

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

8302280295 Interim deficiency rept re Borg-Warner check valve malfunction [initially reported on 830120] Caused by broken tack weld securing stud connecting valve disc to operating arm Valves will be repaired by 830601
GARY, R J Texas Utilities Generating Co 83/02/15 MADSEN, O L Region 4, Office of Director 2pp 17312 358 24X
Fiche 50-445, 83/02/15, 8302280295

T Hearing transcripts on non-antitrust matters

8302280398 Forwards provisional proposed findings of fact, transcript corrections & exhibit list on all controverted matters except Walsh/Doyle allegations
ROTHSCHILD, M U, MIZUNO, G S Hearing Branch 1 83/02/24
MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 17310 029 24X Fiche 50-445, 83/02/24, 8302280398

--8302280407 Transcript corrections for 811202-03, 820607-11, 0726-30 & 0913-17 OL hearings Certificate of Svc encl
ROTHSCHILD, M U, MIZUNO, G S Hearing Branch 1 83/02/24 7pp
17310 248 24X Fiche 50-445, 83/02/24, 8302280398

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302230402 Lists projected requests for site visits by NRC to conduct operator licensing or instructor certification exams through 831231 per Generic Ltr 83-01
SCHMIDT, H C Texas Utilities Services, Inc 83/02/18
EISENHUT, D O Division of Licensing 2pp 17248 082 24X
Fiche 50-445, 83/02/18, 8302230402

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA, UNIT 2

A Application/construction stage documents & correspondence

8302080113 Board Notification 82-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1086 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic
Safety and Licensing Board Panel 18pp 17105 335 24X
Fiche 50-000, 82/12/30, 8302080113

8302080158 Advises that recheck & changes made to demonstrated radiation values resolve radiation level comment for environ qualification audit
SCHMIDT, H C Texas Utilities Services, Inc 83/02/03
YOUNGBLOOD, B J Licensing Branch 1 1p 17059 063 24X
Fiche 50-445, 83/02/03, 8302080158

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic
Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORN, ANL, TX Utils Generating Co, BC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSS re resolution of TH1 Action Item I K 3 D, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302170339 Forwards documentation for May House, Somervell County, TX Inclusion in Register of Natl Historic Places recommended W/o encl
HERRINGTON, L Texas, State of 83/02/09, ROGERS, J Interior, Dept of, National Park Service 2pp 17184 151 24X
Fiche 50-445, 83/02/09, 8302170339

8302230460 Forwards description of proposed Amend 38 to F8AR MARSHALL, J S Texas Utilities Services, Inc 83/02/14
BURNELL, S B Office of Nuclear Reactor Regulation, Director 7pp
17246 049 24X Fiche 50-445, 83/02/14, 8302230460

8302250161 Notification of 830228 meeting w/util in Bethesda, MD to discuss const & preoperational testing schedule
BURNELL, S B Licensing Branch 1 83/02/16 YOUNGBLOOD, B J Licensing Branch 1 3pp 17298 337 24X Fiche 50-445, 83/02/16, 8302250161

8302280256 Forwards info re eligibility of May House for inclusion in Natl Register of Historic Places, per NRC 820525 request info sent to TX State Historic Preservation officer on 830121
SCHMIDT, H C Texas Utilities Services, Inc 83/02/22
YOUNGBLOOD, B J Licensing Branch 1 22pp 17312 236 24X
Fiche 50-445, 83/02/22, 8302280256

--8302280267 Requests info to initiate determination of eligibility request to keeper of Natl Register re May House, per 36CFR63
Appropriate measures should be taken to protect resources during eligibility process
YOUNGBLOOD, B J Licensing Branch 1 82/03/25 GARY, R J Texas Utilities Generating Co 2pp 17312 261 24X
Fiche 50-445, 83/02/22, 8302280256

E NRC Safety Evaluation Report (SER), suppis & correspondence

8302230177 Forwards response to Action Item I C 5 addressing SER, Suppl 1, NUREG-0797 re feedback of operating experience to plant staff info will be incorporated into future FSAR amend
SCHMIDT, H C Texas Utilities Services, Inc 83/02/18
YOUNGBLOOD, B J Licensing Branch 1 2pp 17245 093 24X
Fiche 50-445, 83/02/18, 8302230177

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302170368 Forwards Rev 2 to safeguards contingency plan Rev withheld (ref 10CFR73 21)
GARY, R J Texas Utilities Generating Co 83/02/14 DENYON, H Office of Nuclear Reactor Regulation, Director 2pp 17183 338
24X Fiche 50-445, 83/02/14, 8302170368

G Adjudicatory correspondence

8302020240 Request for show cause order for applicants to show cause why Orinell & NPS1 design criteria used for pipe supports/hangers should not be provided IF util does not have documents, NRC regulations violated Certificate of Svc encl
ELIJS, J Citizens Association for Sound Energy 83/01/28
Commissioners 10pp 16994 251 24X Fiche 50-445, 83/01/28, 8302020240

8302020331 Forwards 830119 newspaper article re faulty steam generators Problem significant & should be included in proceedings Related correspondence
ELIJS, J Citizens Association for Sound Energy 83/01/28
MILLER, M E, MCCOLLUM, K A, COLE, R F Atomic Safety and Licensing Board Panel 3pp 16993 330 24X Fiche 50-445, 83/01/28, 8302020331

8302020265 Order admitting NRC Exhibits 10, 11 & 12 into evidence
MILLER, M E Atomic Safety and Licensing Board Panel 83/01/31
Office of the Executive Legal Director 1p 16994 113 24X
Fiche 50-445, 83/01/31, 8302020265

8302070349 Comments on issue of confidentiality of nuclear witnesses plant informants privilege should protect applicant employees who are most vulnerable to reprisal Svc list encl
GARDE, B P Government Accountability Project 83/02/01
ROSENTHAL, A S, JOHNSON, W R, MOORE, T S Atomic Safety and Licensing Board Panel 10pp 17034 146 24X Fiche 50-445, 83/02/01, 8302070349

8302070378 Response in opposition to Citizens Assoc for Sound Energy 830118 motion for ASLB order directing NRC & applicants to provide potentially significant documents Prima facie case not presented W/Certificate of Svc
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/02/02 Atomic Safety and Licensing Board Panel 8pp 17034 297 24X Fiche 50-445, 83/02/02, 8302070378

8302080171 Forwards affidavit of RL Messerly re shoddy const practices
ELLIS, J Citizens Association for Sound Energy 83/02/03
Docketing & Services Branch 1p 17058 346 24X
Fiche 50-445, 83/02/03, 8302080171

--8307080173 Affidavit of RL Messerly re shoddy const practices
MESSERLY, R L Citizens Association for Sound Energy
MESSERLY, R L Brown & Root Corp (subs of Halliburton Corp)
83/02/03 8pp 17058 347 24X Fiche 50-445, 83/02/03, 8302080171

8302080189 Suppl to 830124 motion for protective orders for R Combs,
L Smith & FR Harrell Witnesses interrogated by applicants
w/o legal representation Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/02/03 Atomic
Safety and Licensing Board Panel 6pp 17059 001 24X
Fiche 50-445, 83/02/03, 8302080189

8302080035 Response opposing Citizens Assoc for Sound Energy 830118
motion for ASLB order requiring NRC & util to provide
documents Motion is for discovery, which ASLB ordered to be
informally discussed w/particles Certificate of Svc encl
MIZUNO, O S Hearing Branch 1 83/02/04 Atomic Safety and
Licensing Board Panel 19pp 17058 172 24X Fiche 50-445, 83/02/04,
8307080035

8302080251 Order striking Govt Accountability Project 830201 filing
reviewing issues on appeal Project is not party to
proceeding Filing entirely inappropriate Proper procedure
would have been to file motion to file amicus curiae brief
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/04
Government Accountability Project 3pp 17057 103 24X
Fiche 50-445, 83/02/04, 8302080251

8302090443 Forwards NRC 830131 ltr issuing SALP rept, including SALP
board rept & util comments Rept covers Oct 1981 - Sept 1982
ROTHSCHILD, M U Hearing Branch 1 83/02/08 MILLER, M E, COLE, R,
MCCOLLUM, K A Atomic Safety and Licensing Board Panel 22pp
17066 264 24X Fiche 50-445, 83/02/08, 8302090443

8302100238 Answer opposing Citizens Assoc for Sound Energy motion &
suppl for protective orders ASLB should direct Assoc to
cease directing or encouraging concealment of potential
nonconforming conditions by applicant employees
REYNOLDS, N S Texas Utilities Generating Co 83/02/08 Atomic
Safety and Licensing Board Panel 27pp 17115 063 24X
Fiche 50-445, 83/02/08, 8302100238

--8302100242 Affidavit of A Vega re RK Combs concerns investigation
of concerns conducted, Combs refused to provide component
identifications or physically to identify items of concern
on advice from Citizens Assoc for Sound Energy
VEGA, A Texas Utilities Generating Co 83/02/04 10pp
17115 090 24X Fiche 50-445, 83/02/08, 8302100238

--8302100246 Affidavit of A Vega re L Smith allegations investigation of
concerns conducted re weld data card for Field Weld 1 on
Line MS-2-RB-19 Entire history not on weld card but could be
found through ref listed card Certificate of Svc encl
VEGA, A Texas Utilities Generating Co 83/02/07 6pp
17115 100 24X Fiche 50-445, 83/02/08, 8302100238

8302150476 Response opposing Citizens Assoc for Sound Energy 830124
motion for protective orders for R Combs, L Smith & F Ray
ASLB lacks jurisdiction to apply Section 210 remedies to
employees discriminated against w/Certificate of Svc
MIZUNO, O S Hearing Branch 1 83/02/14 Atomic Safety and
Licensing Board Panel 22pp 17157 090 24X Fiche 50-445, 83/02/14,
8302150476

8302220415 Order requesting info by 830303, from applicants & NRC, to
provide current best projections of completion dates of
Unit 1
MILLER, M E Atomic Safety and Licensing Board Panel 83/02/17
Texas Utilities Generating Co 2pp 17232 134 24X
Fiche 50-445, 83/02/17, 8302220415

8302230505 Forwards License SNM-1912, issued to util on 830214 Related
documents encl
ROTHSCHILD, M U Hearing Branch 1 83/02/18 MILLER, M E, COLE, R,
MCCOLLUM, K A Atomic Safety and Licensing Board Panel 14pp
17245 168 24X Fiche 50-445, 83/02/18, 8302230505

8302240016 Forwards IE Insp Repts 50-445/82-26 & 50-446/82-14 re Walsh
& Doyle allegations on pipe support engineering program
ROTHSCHILD, M U Hearing Branch 1 83/02/22 MILLER, M E, COLE, R,
MCCOLLUM, K A Atomic Safety and Licensing Board Panel 61pp
17271, 265 24X Fiche 50-445, 83/02/22, 8302240016

8302250279 Decision ALAB-714, dismissing NRC appeal of ASLB 820930 order
directing disclosure of informants Appeal dismissed for want
of genuine controversy Grant of petition for directed
certification withdrawn Johnson dissenting opinion encl
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/24
33pp 17291 302 24X Fiche 50-445, 83/02/24, 8302250279

8302280398 Forwards provisional proposed findings of fact, transcript
corrections & exhibit list on all controverted matters
except Walsh/Doyle allegations
ROTHSCHILD, M U, MIZUNO, O S Hearing Branch 1 83/02/24
MILLER, M E, COLE, R, MCCOLLUM, K A Atomic Safety and Licensing
Board Panel 1p 17310 029 24X Fiche 50-445, 83/02/24, 8302280398

--8302280403 Provisional proposed findings of fact
ROTHSCHILD, M U, MIZUNO, O S Hearing Branch 1 83/02/24 218pp
17310 030 24X Fiche 50-445, 83/02/24, 8302280398

8302280265 Application for stay of effectiveness of ASLB 830224
Decision ALAB-714 NRC likely to prevail on merits,
irreparable injury will result & no other parties will be
harmed Certificate of Svc encl
CUNNINGHAM, O H Office of the Executive Legal Director TURK, S E
Hearing Branch 1 83/02/25 Atomic Safety and Licensing Appeal
Panel 13pp 17312 267 24X Fiche 50-445, 83/02/25, 8302280265

J Insurance & indemnity information

8302100216 Forwards Endorsement & to NELIA Policy NF-274
GARY, R J Texas Utilities Generating Co 83/01/26 BALTZMAN, J D
Office of State Programs, Director 2pp 17114 063 24X
Fiche 50-445, 83/01/26, 8302100216

K Utility Final Safety Analysis Report (FSAR) & amends

8302170175 Forwards Amend 38 to FSAR Affidavit encl
CLEMENTS, B R Texas Utilities Generating Co 83/02/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17183 080
24X Fiche 50-445, 83/02/14, 8302170175

--8302170179 Amend 38 to FSAR
* Texas Utilities Generating Co 83/02/14 238pp 17183 082
24X Fiche 50-445, 83/02/14, 8302170175

M Antitrust correspondence

8302150371 Confirms telcon w/OS Powers & 830209 notification of
destruction of util exhibits
VOGLER, B H Antitrust Division 83/02/10 KNOTT, J B Debevoise &
Liberman 1p 17157 227 24X Fiche 50-445, 83/02/10, 8302150371

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302090403 Responds to Rev 1, Suppl 1 to IE Bulletin 82-01
Reradiographing of all welds has been completed Welds
acceptable

GARY, R J Texas Utilities Generating Co 83/01/31 COLLINS, J T
Region 4, Office of Director 1p 17071, 085 24X
Fiche 50-445, 83/01/31, 8302090403

8302170353 Responds to 821227 ltr commenting on SALP Repts 50-445/82-24
& 50-446/82-12 for Oct 1981 - Sept 1982
COLLINS, J T Region 4, Office of Director 83/01/31 GARY, R J
Texas Utilities Generating Co 3pp 17185, 099 24X
Fiche 50-445, 83/01/31, 8302170353

DOCKETED ITEMS

3

--8302170357 Comments on observations made in NRC SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982 Util recognizes need for improvement in performing insps of vendor supplied welds
GARY, R J Texas Utilities Generating Co 82/12/27 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 2pp 17185 102 24X Fiche 50-445, 83/01/31, 8302170353

--8302170359 Forwards SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982
MADSEN, G L Region 4, Office of Director 82/12/03 GARY, R J Texas Utilities Generating Co 2pp 17185 104 24X Fiche 50-445, 83/01/31, 8302170353

--8302170364 SALP Repts 50-445/82-24 & 50-446/82-12 for Oct 1981 - Sept 1982
WESTERMAN, T F, MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/11/24 15pp 17185 106 24X Fiche 50-445, 83/01/31, 8302170353

8302070413 Ack receipt of 830111 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/82-11 & 50-446/82-10
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/02 GARY, R J Texas Utilities Generating Co 1p 17029 299 24X Fiche 50-445, 83/02/02, 8302070413

--8302070419 Responds to NRC 821213 ltr re violations noted in IE Insp Repts 50-445/82-11 & 50-446/82-10 Corrective actions subj alleged tenure verified & QA Procedure CP-QAP-2 I, "Personnel Training & Qualification," revised
GARY, R J Texas Utilities Generating Co 83/01/11 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 3pp 17029 300 24X Fiche 50-445, 83/02/02, 8302070413

8302090443 Forwards NRC 830131 ltr issuing SALP rept, including SALP board rept & util comments Rept covers Oct 1981 - Sept 1982
ROTHSCHILD, M U Hearing Branch 1 83/02/08 MILLER, M E Atomic Safety and Licensing Board Panel 22pp 17066 264 24X Fiche 50-445, 83/02/08, 8302090443

8302230526 IE Insp Repts 50-445/82-17 & 50-446/82-08 have been canceled
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/15 GARY, R J Texas Utilities Generating Co 1p 17297 275 24X Fiche 50-445, 83/02/15, 8302230526

8302250159 Submits daily highlight for 830215 IE Insp Repts 50-445/82-26 & 50-446/82-14 will be signed & issued
BURWELL, S B Licensing Branch 1 83/02/15 DENTON, H R., CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 17298 342 24X Fiche 50-445, 83/02/15, 8302250159

8302250237 Forwards IE Insp Repts 50-445/82-26 & 50-446/82-14 on 821013-1202 & 830118 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/15 GARY, R J Texas Utilities Generating Co 2pp 17295 156 24X Fiche 50-445, 83/02/15, 8302250237

--8302250243 IE Insp Repts 50-445/82-26 & 50-445/82-14 on 821013-1202 & 830118 No noncompliance noted Major areas inspected, pipe support engineering program in response to concerns expressed at ASLB hearing
TAPIA, J I, TAYLOR, R G Division of Resident, Reactor Project & Engineering Programs RAJAN, J R N Mechanical Engineering Branch 83/02/09 59pp 17295 158 24X Fiche 50-445, 83/02/15, 8302250237

8302230558 Advises of program instituted to send copy of insp repts of vendors used at facilities Repts will be forwarded w/o transmittal ltr through resident inspector, w/distribution ticket to flag significant problems
COLLINS, J T Region 4, Office of Director 83/02/16 GARY, R J Texas Utilities Generating Co 3pp 17256 351 24X Fiche 50-445, 83/02/16, 8302230558

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302240016 Forwards IE Insp Repts 50-445/82-26 & 50-446/82-14 re Walsh & Doyle allegations on pipe support engineering program
ROTHSCHILD, M U, Hearing Branch 1 83/02/22 MILLER, M E Atomic Safety and Licensing Board Panel 61pp 17271 265, 24X Fiche 50-445, 83/02/22, 8302240016

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347, 098, 24X Fiche, 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

Reportable occurrences, LERs & related correspondence

8302280295 Interim deficiency rept re Borg-Warner check valve malfunction Initially reported on 830120 Caused by broken tack weld securing stud connecting valve disc to operating arm Valves will be repaired by 830601
GARY, R J Texas Utilities Generating Co 83/02/15 MADSEN, G L Region 4, Office of Director 2pp 17312 358 24X Fiche 50-445, 83/02/15, 8302280295

Hearing transcripts on non-antitrust matters

8302280398 Forwards provisional proposed findings of fact, transcript corrections & exhibit list on all controverted matters except Walsh/Doyle allegations
ROTHSCHILD, M U Hearing Branch 1 83/02/24 MILLER, M E Atomic Safety and Licensing Board Panel 1p 17310 029 24X Fiche 50-445, 83/02/24, 8302280398

--8302280407 Transcript corrections for 811202-03, 820607-11, 0726-30 & 0913-17 GL hearings Certificate of Svc encl.
ROTHSCHILD, M U, HIZUNO, G S Hearing Branch 1 83/02/24, 7pp, 17310 248 24X Fiche, 50-445, 83/02/24, 8302280398

Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302230402 Lists projected requests for site visits by NRC to conduct operator licensing or instructor certification exams through 831231 per Generic Ltr 83-01
SCHMIDT, H C Texas Utilities Services, Inc 83/02/18 EISENHUT, D O Division of Licensing 2pp 17248 082 24X Fiche 50-445, 83/02/18, 8302230402

DOCKET 87N-50-447 OESSAR-238

Application/construction stage documents & correspondence

8302010709 Notification of 830125 meeting w/OE in Bethesda, MD to discuss fuels-related issues in OESSAR-II, BWR/6 nuclear island design & OESTR-LCCA, model for prediction of fuel rod thermal performance
TOKAR, M Core Performance Branch 83/01/18 BERLINGER, C H Core Performance Branch 2pp 16989 279 24X Fiche 50-447, 83/01/18, 8302010709

8302010644 Forwards final draft responses to Instrumentation & Control Sys Branch questions contained in Commission B21005 request for addl info
SHERNOOD, G O General Electric Co 83/01/28 EISENHUT, D O Division of Licensing 148pp 16979 237, 24X Fiche 50-447, 83/01/28, 8302010644

8302020023 Forwards remaining final draft responses to Instrumentation & Control Sys Branch questions per B21005 request. Responses reflect results of info exchange meetings w/NRC
SHERNOOD, G O General Electric Co 83/01/31 EISENHUT, D O Division of Licensing 25pp 17005, 081 24X Fiche, 50-447, 83/01/31, 8302020023

8302080411 Forwards request for addl info re seismic & dynamic qualification of mechanical & electrical equipment described in OESSAR-II "BWR/6 Nuclear Island Design " Responses requested by 830211
THOMAS, C O Standardization & Special Projects Branch, 83/01/31 SHERNOOD, G O General Electric Co 7pp 17074 333 24X Fiche 50-447, 83/01/31, 8302080411

8302070377 Forwards revised final draft responses to NRC 820825, 1005 & 1115 info requests & Mechanical Engineering Branch draft BER meetings
SHERNOOD, G O General Electric Co 83/02/02 EISENHUT, D O Division of Licensing 88pp 17029 003, 24X Fiche: 50-447, 83/02/02, 8302070377

DOCKETED ITEMS

8302100205 Forwards draft responses to NRC 830131 request for addl info re OESSAR-II
SHERWOOD, G O General Electric Co 83/02/09 EISENHUT, D O
Division of Licensing 23pp 17112 288 24X Fiche 50-447, 83/02/09,
8302100205

8302170335 Forwards info re OE response to OESSAR II Question 490 OI,
re fuel rod cladding & deformation per M Tokar request at
830125 & 26 meetings
CHARNEY, J S General Electric Co 83/02/09 BERLINGER, C H Core
Performance Branch 4pp 17184 104 24X Fiche 50-447, 83/02/09,
8302170335

8302220152 Forwards assessment of Unresolved Safety Issue Task A-46 &
final draft responses to selected questions of 820825, 1115
& 1231 Commission info requests
SHERWOOD, G O General Electric Co 83/02/17 EISENHUT, D O
Division of Licensing 48pp 17233 207 24X Fiche 50-447, 83/02/17,
8302220152

E NRC Safety Evaluation Report (SER), suppl & correspondence

8302070377 Forwards revised final draft responses to NRC 820825, 1005
& 1115 info requests & Mechanical Engineering Branch draft
SER meetings
SHERWOOD, G O General Electric Co 83/02/02 EISENHUT, D O
Division of Licensing 88pp 17029 003 24X Fiche 50-447, 83/02/02,
8302070377

8302280484 Commits to review each human engineering discrepancy in Apps
A & B of OESSAR II SER identified during 821211-13 control
room design audit at Black Fox simulator
SHERWOOD, G O General Electric Co 83/02/22 EISENHUT, D O
Division of Licensing 2pp 17309 235 24X Fiche 50-447, 83/02/22,
8302280484

DOCKET STN-50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170011 Forwards audit repts on seismic & dynamic qualification of
safety-related equipment Repts also available in PDR
BAQCCHI, G Equipment Qualification Branch 83/02/02 NOONAN, V S
Equipment Qualification Branch 3pp 17205 188 24X
Fiche 50-000, 83/02/02, 8302170011

--8302170025 Trip rept of 820913-17 visit to facility to review seismic &
dynamic qualification methods, procedures & results for
safety-related mechanical & electrical equipment & observe
field installation of equipment
LFE, A Equipment Qualification Branch 82/12/20 NOONAN, V
Equipment Qualification Branch 66pp 17205 191 24X
Fiche 50-000, 83/02/02, 8302170011

8302100162 Summary of seismic qualification review team 820913-17
site visits w/BNL re site audit
OLSHAN, L N Licensing Branch 1 83/02/03 Licensing Branch 1
67pp 17134 197, 24X Fiche 50-454, 83/02/03, 8302100162

8302100512 Board Notification 83-11 forwards info indicating onset of
increased turbulence & acceleration of tube wear occurring
at feed flow rates of 50% for Model D/2 & D/3 steam
generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic
Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co,
SC Electric & Gas Co, Westinghouse, TVA & representatives of
Swedish nuclear power plant & Kresko in Bethesda, MD re
accelerated tube wear on Model D steam generators
CHESTNUT, S M Licensing Branch 1 82/03/13 YOUNGBLOOD, B J
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03,
8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-E PHRs re review of
C-E Owners Group emergency procedures guideline program Svc
list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed
NBS re resolution of TMI Action Item II K 3 5, "Automatic
Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas &
Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08,
8302090080

8302160165 Requests approval of interim power restriction option to
enable plant startup in event that steam generator mods to
prevent tube vibration cannot be completed prior to fuel
load
TRAMM, T R Commonwealth Edison Co 83/02/09 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 17162 064 24X
Fiche 50-000, 83/02/09, 8302160165

8302180379 Submits info re prevention of steam generator water hammer
Check valves removed to assure effectiveness of controlled
closure check valves upstream Addl check valve will be
installed in discharge piping to minimize backleakage
TRAMM, T R Commonwealth Edison Co 83/02/15 DENTON, H R Office
of Nuclear Reactor Regulation, Director 3pp 17209 317 24X
Fiche 50-000, 83/02/15, 8302180379

8302240330 Notifies that NRC position on reactor trip breaker testing
issue unchanged Houston 830202 ltr to Westinghouse
forwarded
YOUNGBLOOD, B J Licensing Branch 1 83/02/16 DELGEORGE, L O
Commonwealth Edison Co 2pp 17284 337 24X Fiche 50-000, 83/02/16,
8302240330

C Utility Environmental Report (ER), amends & correspondence

8302080152 Forwards Amend 4 to environ rept - OL stage, consisting of
revs to annual average X/Q at site boundary, agricultural
soils, historic archaeological, architectural, scenic, cultural
& natural features & authorizations for const & operation
SWARTZ, E D Commonwealth Edison Co 83/01/26 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 17059 026 24X
Fiche 50-454, 83/01/26, 8302080152

--8302080154 Amend 4 to environ rept - OL stage Oversize drawing encl
* Commonwealth Edison Co 83/01/31 31pp 17059 028 24X
Fiche 50-454, 83/01/26, 8302080152

E NRC Safety Evaluation Report (SER), suppl & correspondence

8302170481 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BYRON
STATION, UNITS 1 AND 2 Docket Nos STN 50-454 And STN 50-455
(Commonwealth Edison Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0876 802
83/01/31 30pp Available at NRC \$4 75 17197 264 24X
Fiche 50-454, 83/01/31, 8302170481

8302100203 Forwards SER, Suppl 2 (NUREG-0876, Suppl 2) w/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/02/02 DELGEORGE, L O
Commonwealth Edison Co 2pp 17134 124 24X Fiche 50-454, 83/02/02,
8302100203

8302240119 Requests addl info to close out SER issue re verification of
seismic analysis of river screenhouse
YOUNGBLOOD, B J Licensing Branch 1 83/02/07 DELGEORGE, L O
Commonwealth Edison Co 3pp 17268 273 24X Fiche 50-454, 83/02/07,
8302240119

8302170149 Forwards addl info re instrumentation for detection of
inadequate core cooling info closes out SER Outstanding
Item 9
TRAMM, T R Commonwealth Edison Co 83/02/08 DENTON, H R Office
of Nuclear Reactor Regulation, Director 21pp 17180 151 24X
Fiche 50-000, 83/02/08, 8302170149

8302240103 Forwards NUREG-0876, Suppl 2 to SER re operation of
facilities Copies placed in PDR & Rockford IL Public
Library w/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/02/15 DELGEORGE, L O
Commonwealth Edison Co 3pp 17268 303 24X Fiche 50-454, 83/02/15,
8302240103

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document
Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27,
8302040033

--8302040037 Forwards public version of revised Emergency Plan
Implementing Procedures ED-29 re meteorological maint
programs & ED-25 re computer codes for access to ODCS
programs
PAJOWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC
- No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

DOCKETED ITEMS

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to QDCS programs Revised index encl
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp
17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders or CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

830100176 Advises that changes in Rev 7 to security plan consistent w/10CFR50.55(p) Encl to util 821008 ltr withheld per 10CFR73.21
YOUNGBLOOD, B J Licensing Branch 1 83/02/02 DELGEORGE, L O
Commonwealth Edison Co 3pp 17134 188 24X Fiche 50-454, 83/02/02, 830100176

8302080316 Responds to 821207 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-111B guidelines valid
KEPPLER, J O Region 3, Office of Director 83/02/04 REED, C
Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8301250545 Forwards IE Safeguards Insp Rept 50-454/83-05 on 830124-25 MILLER, J R Region 3, Office of Director 83/02/09 REED, C
Commonwealth Edison Co 2pp 17156 211 24X Fiche 50-454, 83/02/09, 8301250545

--8301250557 IE Safeguards Insp Rept 50-454/83-05 on 830124-25 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization-mgt, personnel & response Details withheld (ref 10CFR73.21)
BELANGER, J L, KNICELEY, J R, CREED, J R Region 3, Office of Director 83/02/07 2pp 17156 213 24X Fiche 50-454, 83/02/09, 8301250545

8301280102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8301280102

--8301280126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X
Fiche 50-000, 83/02/15, 8301280102

--8301280156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager"
NELLIS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8301280102

8302280349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302280349

--8302280361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities lists of locations encl
SWARTZ, E D Commonwealth Edison Co 83/01/28 KEPPLER, J O Region 3, Office of Director 4pp 17291 074 24X
Fiche 50-000, 83/02/18, 8302280349

G Adjudicatory correspondence

8302020257 Notice of appearance in proceeding Certificate of Svc encl
THOMAS, D C League of Women Voters of Rockford, IL 83/01/24 3pp 16994 264 24X Fiche 50-454, 83/01/24, 8302020257

8302030533 Forwards Suppl 2 to SER W/o encl
GOLDBERG, S C Hearing Branch 4 83/02/02 SMITH, I, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 17007 124 24X Fiche 50-454, 83/02/02, 8302030533

8302100255 Forwards IE insp repts re IE 1982 investigation of Hayward-Tyler Pump Co
GOLDBERG, S C Hearing Branch 4 83/02/03 CHAVEZ, D DeKalb Area Alliance for Responsible Energy CHAVEZ, D Mississippi Alliance the Environment (SAFE) 276pp 17114 128 24X
Fiche 50-454, 83/02/03, 8302100255

8302090229 Notice of appearance in proceeding Certificate of Svc encl
HASWELL, A DeKalb Area Alliance for Responsible Energy HASWELL, A Smississippi Alliance for the Environment (SAFE) HASWELL, A Haswell, H 83/02/04 3pp 17069 349 24X Fiche 50-454, 83/02/04, 8302090229

8302160223 Forwards 830210 affidavit of KA Ainger re potential for bubble collapse water hammer in feedwater bypass line Temp sensors will be installed in bypass sys piping Check valve upstream of auxiliary nozzle removed from plant design
COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Commonwealth Edison Co 83/02/10 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17163 023 24X
Fiche 50-454, 83/02/10, 8302160223

--8302160227 Affidavit of KA Ainger re changes to plant design to mitigate potential for RRSKO-type bubble collapse water hammer in feedwater bypass line Westinghouse ltr, bypass drawing & notice of appearance by V O Copeland encl
AINGER, K A Commonwealth Edison Co 83/02/10 7pp 17163 027 24X Fiche 50-454, 83/02/10, 8302160223

8302220344 Requests to make limited appearance statement at hearing
BLAND, T J Audubon Society 83/02/14 NRC - No Detailed Affiliation Given 1p 17228 001 24X Fiche 50-454, 83/02/14, 8302220344

8302230423 Requests to make limited appearance statement at OL hearings
SCHRADER, D Affiliation Unknown 83/02/16 Docketing & Service Branch 1p 17246 122 24X Fiche 50-454, 83/02/16, 8302230423

8302230446 Forwards util 830215 ltr re DAAWE/SAFE Contention 9a concerning potential for bubble collapse water hammer in feedwater bypass line Encl ltr explains changes to feedwater bypass sys & auxiliary feedwater sys
COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Commonwealth Edison Co 83/02/16 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17246 075 24X
Fiche 50-454, 83/02/16, 8302230446

8302230540 Notice of appearance in proceeding Certificate of Svc encl
HERRIN, M O Commonwealth Edison Co HERRIN, M O Isham, Lincoln & Beale 83/02/18 3pp 17257 073 24X Fiche 50-454, 83/02/18, 8302230540

8302280185 Notice of appearance in proceeding Certificate of Svc encl
THOMAS, D C League of Women Voters of Rockford, IL 83/02/18 17306 043 24X Fiche 50-454, 83/02/18, 8302280185

X Utility Final Safety Analysis Report (FSAR) & amends

8302280204 Forwards Amend 41 to FSAR, consisting of new & revised responses to NRC questions
TRAMM, T R Commonwealth Edison Co 83/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17311 344 24X
Fiche 50-000, 83/02/23, 8302280204

--8302280212 Amend 41 to FSAR
Commonwealth Edison Co 83/02/28 170pp 17311 348 24X
Fiche 50-000, 83/02/23, 8302280204

O Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HATT, B L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPPLER, J O Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

DOCKETED ITEMS

- 8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESARD, R L Division of Project & Resident Programs 2pp. 17045 279 24X Fiche 50-000, 82/12/30, 8302040039
- 8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
BUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039
- 8302040402 Forwards draft SALP rept for 1982 Comments requested by 830126
OLSHAN, L N, STEVENS, J A Licensing Branch 1 83/01/24
EISENHUT, D O Division of Licensing MATTSO, R J Division of Systems Integration (post 811005) VOLLMER, R H Division of Engineering 3pp 17042 317 24X Fiche 50-000, 83/01/24, 8302040402
- 8212060358 IE Info Notice 83-01, "Ray Moller, Inc " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8302150404 Forwards IE Insp Repts 50-454/82-27 & 50-455/82-21 on 821101-1231 & notice of violation
KNOP, R C Division of Project & Resident Programs 83/01/26
REED, C Commonwealth Edison Co 2pp 17158 086, 24X Fiche 50-454, 83/01/26, 8302150404
- 8302150406 Notice of violation from insp on 821101-1231
KNOP, R C Division of Project & Resident Programs 83/01/26 3pp 17158 088 24X Fiche 50-454, 83/01/26, 8302150404
- 8302150408 IE Insp Repts 50-454/82-27 & 50-455/82-21 on 821101-1231
Noncompliance noted failure to include specs for structural bolted connections in drawings, instructions or procedures
FORNEY, W, CONNAUGHTON, K, HAYES, D W Division of Project & Resident Programs 83/01/19 9pp 17158 091 24X Fiche 50-454, 83/01/26, 8302150404
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360
- 8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp. 17074 095 24X Fiche 50-000, 83/01/28, 8212060361
- 8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co. 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303
- 8302150689 Forwards IE Insp Repts 50-454/83-01 & 50-455/83-01 on 830112-14 No noncompliance noted
LITTLE, W B Division of Engineering 83/01/28 REED, C Commonwealth Edison Co 2pp 17151 351 24X Fiche 50-454, 83/01/28, 8302150689
- 8302150724 IE Insp Repts 50-454/83-01 & 50-455/83-01 on 830112-14 No noncompliance noted Major areas inspected preservice insp procedures, work activities, NDE personnel certifications & data & previous insp findings
WARD, K D, DANIELSON, D H Division of Engineering 83/01/25 4pp. 17151 353 24X Fiche 50-454, 83/01/28, 8302150689
- 8302100100 Forwards NRR input to SALP rept for Oct-Dec 1982, per TN sampling request Personnel solicited for input listed. Appropriate comments from various NRR div directors incorporated into rept.
OLSHAN, L N, STEVENS, J A Licensing Branch 1 83/02/02
EISENHUT, D O Division of Licensing 3pp. 17134 353 24X Fiche 50-000, 83/02/02, 8302100100
- 8302100255 Forwards IE insp repts re IE 1982 investigation of Hayward-Tyler Pump Co
GOLDBERG, S C Hearing Branch 4. 83/02/03 CHAVEZ, D DeKalb Area
Alliance for Responsible Energy CHAVEZ, D Mississippi Alliance for the Environment (SAFE) 276pp. 17114 128 24X Fiche 50-454, 83/02/03, 8302100255
- 8302180365 Forwards IE Insp Repts 50-454/82-25 & 50-455/82-19 on 821202-830114 No noncompliance noted
NORELIUS, C E Division of Project & Resident Programs 83/02/07
REED, C Commonwealth Edison Co 2pp 17209 216 24X Fiche 50-454, 83/02/07, 8302180365
- 8302180383 IE Insp Repts 50-454/82-25 & 50-455/82-19 on 821202-830114 No noncompliance noted Major areas inspected receipt insp records for tendons, tendon accessories & masonry blocks
HAYES, D W Division of Project & Resident Programs 83/02/07 21pp 17209 218 24X Fiche 50-454, 83/02/07, 8302180365
- 8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin B1-03, "Flow Blockage of Cooling Water to Safety-Related Systems Components by Asiatic Clams & Mussels "
SWARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17156 215 24X Fiche 50-000, 83/02/08, 8302150528
- 8302150545 Forwards IE Safeguards Insp Rept 50-454/83-05 on 830124-25
MILLER, J R Region 3, Office of Director 83/02/09 REED, C, Commonwealth Edison Co 2pp 17156 211 24X Fiche 50-454, 83/02/09, 8302150545
- 8302150557 IE Safeguards Insp Rept 50-454/83-05 on 830124-25 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization-mgt, personnel & response Details withheld (ref 10CFR73.21)
BELANDER, J L, KNICELEY, J R, CREED, J R Region 3, Office of Director 83/02/07 2pp 17156 213 24X Fiche 50-454, 83/02/09, 8302150545
- 8302280368 Forwards IE Insp Repts 50-454/82-26 & 50-455/82-20 on 821227-29 & 830125-28 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/02/10 REED, C Commonwealth Edison Co 2pp 17311 001 24X Fiche 50-454, 83/02/10, 8302280368
- 8302280375 IE Insp Repts 50-454/82-26 & 50-455/82-20 on 821227-29 & 830125-28 No noncompliance noted Major areas inspected followup on allegations re piping support installation & QC insp deficiencies
YIN, I T, DANIELSON, D H Region 3, Office of Director 83/02/10 11pp 17311 003 24X Fiche 50-454, 83/02/10, 8302280368
- 8302280542 Forwards IE Insp Repts 50-454/83-02 & 50-455/83-02 on 830103-07 & 10 No noncompliance noted
LITTLE, W B Division of Engineering 83/02/10, REED, C Commonwealth Edison Co 2pp 17309 052 24X Fiche 50-454, 83/02/10, 8302280542
- 8302280550 IE Insp Repts 50-454/83-02 & 50-455/83-02 on 830103-07 & 10 No noncompliance noted Major areas inspected review of procedures, work activities & records for reinsp of structural steel bolting in containment & auxiliary bldg.
KEATINGE, D E, DANIELSON, D H Region 3, Office of Director 83/02/10 3pp 17309 054 24X Fiche 50-454, 83/02/10, 8302280542
- 8302280485 Forwards IE Insp Repts 50-454/82-28 & 50-455/82-22 on 821201-29 & 830114 No noncompliance noted
LITTLE, W B Division of Engineering 83/02/11, REED, C Commonwealth Edison Co 2pp 17322 217, 24X Fiche 50-454, 83/02/11, 8302280485
- 8302280489 IE Insp Repts 50-454/82-28 & 50-455/82-22 on 821201-29 & 830114 No noncompliance noted Major areas inspected, followup on allegations/concerns re const deficiencies, concerning uniformity of concrete & quantity of water.
NORTON, J F, WILLIAMS, C C Region 3, Office of Director 83/02/11 17pp 17322 219 24X Fiche 50-454, 83/02/11, 8302280485
- 8302180458 Ack receipt of 830207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-24 & 50-455/82-18.
NORELIUS, C E Division of Project & Resident Programs 83/02/15, REED, C Commonwealth Edison Co 1p 17215 168 24X Fiche 50-454, 83/02/15, 8302180458
- 8302180463 Responds to NRC 830103 ltr re violations noted in IE Insp Repts 50-454/82-24 & 50-455/82-18 Corrective actions, temp monitoring devices ordered & will be installed in warehouses to verify proper temp band maintained.
FARRAR, D L Commonwealth Edison Co 83/02/09, KEPPLER, J O Region 3, Office of Director 3pp 17215 169, 24X Fiche 50-454, 83/02/15, 8302180458
- 8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc. 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

DOCKETED ITEMS

8212040255 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 058 24X Fiche 50-000,83/02/24,8212040365

8212040366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212040366

8302280296 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-18 & 50-455/82-13 Confirms 830223 telcon that specific ref to testing of first batch of concrete will be deleted
SPESARD, R L Division of Engineering 83/02/25 REED, C Commonwealth Edison Co 1p 17311 076 24X Fiche 50-454,83/02/25,8302280296

--8302280303 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-454/82-18 & 50-455/82-13 Corrective actions FEAR will be reviewed & revised re conflicts w/structural design drawings & specs
FARRAR, D L Commonwealth Edison Co 83/02/10 KEPPLER, J G Region 3, Office of Director 3pp 17311 077 24X Fiche 50-454,83/02/25,8302280296

G Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000,82/12/17,8302030495

8302230542 Part 21 rept re 170 wire tendon post-tensioning sys Problem lies w/poor const techniques not nonconforming threads Nonconforming threads not responsible for failures exhibited at job sites QA procedure encl
MATYKIEWICZ, C INRYCO, Inc (subs of Inland Steel Co) 83/01/27 Region 3, Office of Director 11pp 17257 014 24X Fiche 50-000,83/01/27,8302230542

--8302230555 Rev O to "Anchorage Measurement control" * INRYCO, Inc (subs of Inland Steel Co) 83/01/19 16pp 17257 025 24X Fiche 50-000,83/01/27,8302230542

8302040370 Deficiency Rept 82-11 re accuracy of Barton electronic instrument transmitters being installed at facilities Initially reported on 821221 Corrective action based on recommendation from Barton Instruments
TRAMM, T R Commonwealth Edison Co 83/01/28 KEPPLER, J G Region 3, Office of Director 2pp 17018 313 24X Fiche 50-000,83/01/28,8302040370

8302150419 Interim deficiency rept re installation of HVAC sys components Initially reported on 830125 Procedures revised, design tolerances clarified & safety-related HVAC field installations reinspected
TRAMM, T R Commonwealth Edison Co 83/02/07 KEPPLER, J G Region 3, Office of Director 2pp 17148 150 24X Fiche 50-454,83/02/07,8302150419

8302280450 Interim deficiency rept re resolution of mechanical snubber bracket interference Initially reported on 830110 Lists of snubbers to be inspected compiled Insp criteria not finalized Next rept will be provided within 60 days
TRAMM, T R Commonwealth Edison Co 83/02/16 KEPPLER, J G Region 3, Office of Director 1p 17308 011 24X Fiche 50-000,83/02/16,8302280450

H Hearing transcripts on non-antitrust matters

8302160176 Forwards testimony of I Alterman, R Rothman, A Serkis, MA Lamastra, EF Branagan, JJ Hayes, RF Skelton, LO Hulman & ML Wohl, per ASLB 810907 order, in preparation of 830301 hearing
OOLBERG, B C Hearing Branch 4 83/02/15 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17161 044 24X Fiche 50-454,83/02/15,8302160176

--8302160182 Testimony of I Alterman on Rockford League of Women Voters Contention 106 re seismic capability of geologic faults
ALTERMAN, I Geosciences Branch 83/02/15 16pp 17161 044 24X Fiche 50-454,83/02/15,8302160176

--8302160188 Testimony of R Rothman on Rockford League of Women Voters Contention 106 re seismic capability of geologic faults
ROTHMAN, R Geosciences Branch 83/02/15 15pp 17161 062 24X Fiche 50-454,83/02/15,8302160176

--8302160194 Testimony of A Serkis on Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 9A re implications of 1981 KRSKO water hammer event on facility
SERKIS, A Generic Issues Branch 83/02/15 8pp 17161 077 24X Fiche 50-454,83/02/15,8302160176

--8302160203 Testimony of MA Lamastra, EF Branagan, JJ Hayes & RF Skelton on Rockford League of Women Voters Contentions 42, 111 & 112 re ALARA & radiation monitoring onsite
LAMAISTRA, M A, BRANAGAN, E F Radiological Assessment Branch HAYES, J J Effluent Treatment Systems Branch 83/02/15 70pp 17161 085 24X Fiche 50-454,83/02/15,8302160176

--8302160212 Testimony of LO Hulman, ML Wohl, S Newberry & EF Branagan on Rockford League of Women Voters Contentions 8 & 62 & on Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 2A re risk & accidents
HULMAN, L O, WOHL, M L Accident Evaluation Branch NEWBERRY, S Reliability & Risk Assessment Branch 83/02/15 40pp 17161 111 24X Fiche 50-454,83/02/15,8302160176

8302170292 Forwards testimony of S Levine & L Conway
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co 83/02/15 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17177 063 24X Fiche 50-454,83/02/15,8302170292

--8302170298 Testimony of S Levine re contentions on Class 9 accident Plant design provides substantial protection against severe or Class 9 accidents
LEVINE, S Commonwealth Edison Co LEVINE, S NUS Corp 83/02/15 35pp 17177 065 24X Fiche 50-454,83/02/15,8302170292

--8302170302 Testimony of L Conway re contentions claiming reduction occupational exposure not considered in design Steam generators embody very best design feature to reduce occupational radiation exposure
CONWAY, L Commonwealth Edison Co CONWAY, L Westinghouse Electric Corp 83/02/15 12pp 17177 100 24X Fiche 50-454,83/02/15,8302170292

8302220291 Forwards testimony on seismic, occupational exposure & water hammer contentions & unexecuted stipulation re final language & order of contentions Certificate of Svc encl
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/02/15 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 22pp 17228 016 24X Fiche 50-454,83/02/15,8302220291

--8302220298 Testimony of AK Yonk re Rockford League of Women Voters Contention 106 on strain gauge tests Last movement of faults over 200,000 yrs ago Faults are not capable under 10CFR100, App A criteria Prof qualifications encl
YONK, A K Commonwealth Edison Co YONK, A K Sargent & Lundy, Inc 83/02/15 13pp 17228 038 24X Fiche 50-454,83/02/15,8302220291

--8302220304 Testimony of AK Singh re Rockford League of Women Voters Contention 106 on ground acceleration values for design Ground acceleration values & OBE std appropriate for plant Prof qualifications encl
SINGH, A K Commonwealth Edison Co SINGH, A K Sargent & Lundy, Inc 83/02/15 11pp 17228 054 24X Fiche 50-454,83/02/15,8302220291

--8302220310 Testimony of R Pleniewicz re util actions taken to minimize occurrence of KRSKO-type water hammer event, per Westinghouse recommendations (Contention 9a) Util plans to change check valve arrangement
PLENIEWICZ, R Commonwealth Edison Co 83/02/15 8pp 17228 061 24X Fiche 50-454,83/02/15,8302220291

--8302220317 Testimony of RW Carlson re Contention 9a on water hammer event If util follows Westinghouse recommendations to prevent KRSKO-type water hammer event, likelihood of occurrence of event reduced to acceptable level
CARLSON, R W Commonwealth Edison Co CARLSON, R W Westinghouse Electric Corp 83/02/15 21pp 17228 074 24X Fiche 50-454,83/02/15,8302220291

--8302220321 Testimony of JL Roulo on Contention 42 re sabotage No increased risk of sabotage results from use of contractor employees, including transient workers
ROULO, J L Commonwealth Edison Co 83/02/15 26pp 17228 077 24X Fiche 50-454,83/02/15,8302220291

DOCKETED ITEMS

- B302220325 Testimony of QP Lahti re Contentions 42, 111 & 112 on plant design for reducing occupational radiation exposure. Each design principle which can reduce radiation exposure used appropriately.
LAHTI, Q P Commonwealth Edison Co LAHTI, Q P Sargent & Lundy, Inc 83/02/15 34pp 17228 123 24X Fiche 50-454, 83/02/15, B302220291
- B302220328 Testimony of JI Fabrikant on Contentions 42, 111 & 112 re radiation exposure. Natl committee for radiation protection recommendations on dose limit for exposure to pregnant women provides protection against teratogenic effects.
FABRIKANT, J I Commonwealth Edison Co 83/02/15 100pp 17228 157 24X Fiche 50-454, 83/02/15, B302220291
- B302220332 Testimony of F Rescek re Contentions 42, 111 & 112 Discusses util corporate ALARA, dosimetry program, recordkeeping procedures & training program.
RESCEK, F Commonwealth Edison Co 83/02/15 493pp 17228 257 24X Fiche 50-454, 83/02/15, B302220291
- B302220336 Testimony of JR Van Laere re Contentions 43, 111 & 112 Discusses ALARA program, health physics dept staff & in-plant monitoring program.
VAN LAERE, J Commonwealth Edison Co 83/02/15 55pp 17230 030 24X Fiche 50-454, 83/02/15, B302220291
- B302180387 Errata to L Conway B30215 testimony
GALLO, J, CONWAY, L Commonwealth Edison Co GALLO, J Isham, Lincoln & Beale 83/02/16 3pp 17209 337 24X Fiche 50-454, 83/02/16, B302180387
- B302230545 Forwards K Morgan affidavit & Certificate of Svc inadvertently omitted from testimony. Related correspondence.
JOHNSON, B League of Women Voters of Rockford, IL 83/02/17
MARGOLIES, M B, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 17256 274 24X Fiche 50-454, 83/02/17, B302230545
- B302230553 K Morgan affidavit & Certificate of Svc. inadvertently omitted from testimony.
MORGAN, K Z League of Women Voters of Rockford, IL 83/02/17 2pp 17256 275 24X Fiche 50-454, 83/02/17, B302230545
- B302220023 Forwards Page 2 of A Serkiz testimony, LQ Hulman prof qualifications & Table 2 to MA Lamstra testimony, omitted from NRC B30215 testimony.
GOLDBERG, B C Hearing Branch 4 83/02/18 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 17233 255 24X Fiche 50-454, 83/02/18, B302220023
- B302220027 Page 2 of A Serkiz testimony, LQ Hulman prof qualifications & Table 2 to MA Lamstra testimony, omitted from NRC B30215 testimony.
SERKIZ, A, HULMAN, L Q, LAMASTRA, M A NRC - No Detailed Affiliation Given 83/02/18 7pp 17233 256 24X Fiche 50-454, 83/02/18, B302220023
- B302230455 Forwards L Conway corrected testimony addressing Contentions 42, 111 & 112 re occupational radiation exposure concerning Westinghouse steam generators. Related correspondence.
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co 83/02/21 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17246 056 24X Fiche 50-454, 83/02/21, B302230455
- B302230461 Corrected testimony of L Conway, addressing Contentions 42, 111 & 112 re occupational exposure reduction.
CONWAY, L Westinghouse Electric Corp 83/02/21 13pp 17246 058 24X Fiche 50-454, 83/02/21, B302230455
- B302230544 Testimony of HH Woodard on Contention 106 re seismic-related site problems discovered subsequent to issuance of CP Certificate of Svc. encl. Related correspondence.
WOODARD, H H League of Women Voters of Rockford, IL WOODARD, H H Beloit College 83/02/22 Atomic Safety and Licensing Board Panel 10pp 17256 264 24X Fiche 50-454, 83/02/22, B302230544
- B302240059 Forwards L Frank, J Rajan, C McCracken, L Marsh, M Phillips & J Spraul testimony on listed contentions.
GOLDBERG, B C Hearing Branch 4 83/02/22 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17273 013 24X Fiche 50-454, 83/02/22, B302240059
- B302240064 Testimony of JR Rajan re flow-induced tube vibrations in Model D steam generators. If corrective mods unavailable before Unit 1 OL received, util would have to justify interim operation. Prof qualifications encl.
RAJAN, J R Mechanical Engineering Branch 83/02/22 9pp 17273 015 24X Fiche 50-454, 83/02/22, B302240059
- B302240070 Testimony of LB Marsh, L Frank & JR Rajan re steam generator tube degradation. Concurrent steam generator tube rupture & other DBA events beyond current design bases. Prof qualifications encl.
MARSH, L B Reactor Systems Branch FRANK, L Materials Engineering Branch RAJAN, J R Mechanical Engineering Branch 83/02/22 13pp 17273 024 24X Fiche 50-454, 83/02/22, B302240059
- B302240074 Testimony of L Frank re steam generator tube degradation. Discusses insp of tubes & measures taken to ensure tube integrity & minimize potential for degradation. Prof qualifications encl.
FRANK, L Materials Engineering Branch 83/02/22 13pp 17273 037 24X Fiche 50-454, 83/02/22, B302240059
- B302240078 Testimony of CE McCracken on primary & secondary water chemistry control & corrosion re steam generator tube integrity. Numerous changes in design & procedures incorporated. Prof qualifications encl.
MCCRACKEN, C Chemical Engineering Branch 83/02/22 10pp 17273 050 24X Fiche 50-454, 83/02/22, B302240059
- B302240083 Testimony of M Phillips on emergency planning issues. Util onsite emergency plan complies w/NRC emergency planning requirements w/some exceptions.
PHILLIPS, M Division of Emergency Preparedness & Operational Support 83/02/22 24pp 17273 060 24X Fiche 50-454, 83/02/22, B302240059
- B302240088 Testimony of JG Spraul re adequacy of util QA program. Util organization provides QA dept w/sufficient independence from cost & schedule, authority to carry out QA operations & access to mgt Prof qualifications encl.
SPRAUL, J G Quality Assurance 83/02/22 13pp 17273 084 24X Fiche 50-454, 83/02/22, B302240059
- B302240092 Testimony of WL Forney, DW Hayes, JE Konklin, CC Williams & IT Yin re QA program during const & preoperational testing. Util implemented acceptable const QA program & has ability & willingness to implement acceptable operating QA program.
FORNEY, W L Region 3, Office of Director HAYES, D W, KONKLIN, J E Division of Project & Resident Programs 83/02/22 167pp 17273 097 24X Fiche 50-454, 83/02/22, B302240059
- V Operator Examinations

- B3021310203 Generic Ltr B3-06 to all power reactor licensees, applicants for GLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B3021310203
- DOCKET STN-50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence

- B302170011 Forwards audit repts on seismic & dynamic qualification of safety-related equipment. Repts also available in PDR.
BAGCHI, G Equipment Qualification Branch 83/02/02 NOONAN, V & Equipment Qualification Branch 3pp 17205 188 24X Fiche 50-000, 83/02/02, B302170011
- B302170025 Trip repts of B20913-17 visit to facility to review seismic & dynamic qualification methods, procedures & results for safety-related mechanical & electrical equipment & observe field installation of equipment.
LEE, A Equipment Qualification Branch 82/12/20 NOONAN, V Equipment Qualification Branch 65pp 17205 191 24X Fiche 50-000, 83/02/02, B302170011
- B302100512 Board Notification B3-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators.
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X Fiche 50-000, 83/02/03, B302100512
- B302100522 Summary of B20219 meeting w/DRNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators.
CHESTNUT, B H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, B302100512

DOCKETED ITEMS

351

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Hestinghouse designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302160165 Requests approval of interim power restriction option to enable plant startup in event that steam generator mods to prevent tube vibration cannot be completed prior to fuel load
TRAH, T R Commonwealth Edison Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17162 064 24X
Fiche 50-000, 83/02/09, 8302160165

8302180379 Submits info re prevention of steam generator water hammer Check valves removed to assure effectiveness of controlled closure check valves upstream Addl check valve will be installed in discharge piping to minimize backleakage
TRAH, T R Commonwealth Edison Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17209 317 24X
Fiche 50-000, 83/02/15, 8302180379

8302240330 Notifies that NRC position on reactor trip breaker testing issue unchanged Houston 830202 ltr to Westinghouse forwarded
YOUNGBLOOD, B J Licensing Branch 1 83/02/16 DELGEORGE, L O Commonwealth Edison Co 2pp 17284 337 24X Fiche 50-000, 83/02/16, 8302240330

C Utility Environmental Report (ER), amends & correspondence

8302080152 Forwards Amend 4 to environ rept - OL stage, consisting of revs to annual average X/G at site boundary, agricultural soils, historic archaeological, architectural, scenic, cultural & natural features & authorizations for const & operation
SMARTZ, E D Commonwealth Edison Co 83/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17059 026 24X
Fiche 50-454, 83/01/26, 8302080152

--8302080154 Amend 4 to environ rept - OL stage Oversize drawing encl
Commonwealth Edison Co 83/01/31 31pp 17059 028 24X
Fiche 50-454, 83/01/26, 8302080152

E NRC Safety Evaluation Report (SER), suppis & correspondence

8302170481 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BYRON STATION, UNITS 1 AND 2 Docket Nos STN 50-454 And STN 50-455 (Commonwealth Edison Company)
Office of Nuclear Reactor Regulation, Director NUREG-0874 802 83/01/31 30pp Available at NRC 44 75 17197 264 24X
Fiche 50-454, 83/01/31, 8302170481

8302100203 Forwards SER, Suppl 2 (NUREG-0876, Suppl 2) w/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/02/02 DELGEORGE, L O Commonwealth Edison Co 2pp 17134 124 24X Fiche 50-454, 83/02/02, 8302100203

8302240119 Requests addl info to close out SER issue re verification of seismic analysis of river screenhouse
YOUNGBLOOD, B J Licensing Branch 1 83/02/07 DELGEORGE, L O Commonwealth Edison Co 3pp 17268 273 24X Fiche 50-454, 83/02/07, 8302240119

8302170149 Forwards addl info re instrumentation for detection of inadequate core cooling Info closes out SER Outstanding Item 9
TRAH, T R Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp 17180 151 24X
Fiche 50-000, 83/02/08, 8302170149

8302240103 Forwards NUREG-0876, Suppl 2 to SER re operation of facilities Copies placed in PDR & Rockford IL Public Library w/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/02/15 DELGEORGE, L O Commonwealth Edison Co 3pp 17268 303 24X Fiche 50-454, 83/02/15, 8302240103

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs
PAJGWSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC
No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs Revised index encl
LITERSKI, L A Commonwealth Edison Co 83/01/04 11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

830210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 830210340

8302100176 Advises that changes in Rev 7 to security plan consistent w/10CFR50.55(p) Encl to util 821008 ltr withheld per 10CFR73.21
YOUNGBLOOD, B J Licensing Branch 1 83/02/02 DELGEORGE, L O Commonwealth Edison Co 3pp 17134 188 24X Fiche 50-454, 83/02/02, 8302100176

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-111B guidelines valid
KEPPLER, J O Region 3, Office of Director 83/02/04 REED, C Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director Jpp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X
Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EDF-2, "Technical Support Manager"
HELLIS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities Lists of locations encl
SMARTZ, E D Commonwealth Edison Co 83/01/28 KEPPLER, J O Region 3, Office of Director 4pp 17291 074 24X
Fiche 50-000, 83/02/18, 8302250349

DOCKETED ITEMS

G Adjudicatory correspondence

8302020257 Notice of appearance in proceeding Certificate of Svc encl
THOMAS, D C League of Women Voters of Rockford, IL 83/01/24 3pp
14994 264 24X Fiche 50-454, 83/01/24, 8302020257

8302030533 Forwards Suppl 2 to SER W/O encl
GOLDBERG, S C Hearing Branch 4 83/02/02 SMITH, I, CALLIHAN, A D,
COLE, R F Atomic Safety and Licensing Board Panel 1p 17007 160
24X Fiche 50-454, 83/02/02, 8302030533

8302100255 Forwards IE insp repts re IE 1982 investigation of
Hayward-Tyler Pump Co
GOLDBERG, S C Hearing Branch 4 83/02/03 CHAVEZ, D DeKalb Area
Alliance for Responsible Energy CHAVEZ, D Mississippi Alliance for
the Environment (SAFE) 27pp 17114 128 24X
Fiche 50-454, 83/02/03, 8302100255

8302090229 Notice of appearance in proceeding Certificate of Svc encl
HASELL, A DeKalb Area Alliance for Responsible Energy HASELL, A
Mississippi Alliance for the Environment (SAFE) HASELL, A
Haseull, H 83/02/04 3pp 17069 349 24X Fiche 50-454, 83/02/04,
8302090229

8302160223 Forwards 830210 affidavit of KA Ainger re potential for
bubble collapse water hammer in feedwater bypass line Temp
sensors will be installed in bypass sys piping Check valve
upstream of auxiliary nozzle removed from plant design
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth
Edison Co 83/02/10 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic
Safety and Licensing Board Panel 2pp 17163 023 24X
Fiche 50-454, 83/02/10, 8302160223

--8302160227 Affidavit of KA Ainger re changes to plant design to
mitigate potential for KRSKO-type bubble collapse
water hammer in feedwater bypass line Westinghouse ltr,
bypass drawing & notice of appearance by VO Copeland encl
AINGER, K A Commonwealth Edison Co 83/02/10 7pp 17163 025
24X Fiche 50-454, 83/02/10, 8302160223

830220344 Requests to make limited appearance statement at hearings
BLAND, T J Audubon Society 83/02/14 NRC - No Detailed
Affiliation Given 1p 17228 001 24X Fiche 50-454, 83/02/14,
830220344

8302230423 Requests to make limited appearance statement at OL
hearings
SCHRAEDER, D Affiliation Unknown 83/02/16 Docketing & Services
Branch, 1p 17246 122 24X Fiche 50-454, 83/02/16, 8302230423

8302230446 Forwards util 830215 ltr re DAARE/SAFE Contention 9a
concerning potential for bubble collapse water hammer in
feedwater bypass line Encl ltr explains changes to feedwater
bypass sys & auxiliary feedwater sys
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth
Edison Co 83/02/16 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic
Safety and Licensing Board Panel 2pp 17246 075 24X
Fiche 50-454, 83/02/16, 8302230446

8302230540 Notice of appearance in proceeding Certificate of Svc encl
HERRIN, M G Commonwealth Edison Co HERRIN, M G Isham, Lincoln &
Beale 83/02/18 3pp 17257 073 24X Fiche 50-454, 83/02/18,
8302230540

8302280185 Notice of appearance in proceeding Certificate of Svc encl
THOMAS, D C League of Women Voters of Rockford, IL 83/02/18 3pp
17306 043 24X Fiche 50-454, 83/02/18, 8302280185,

K Utility Final Safety Analysis Report (FSAR) & amends

8302280204 Forwards Amend 41 to FSAR, consisting of new & revised
responses to NRC questions
TRAMM, T R Commonwealth Edison Co 83/02/23 BENTON, H R Office
of Nuclear Reactor Regulation, Director 4pp 17311 344 24X
Fiche 50-000, 83/02/23, 8302280204

--8302280212 Amend 41 to FSAR
* Commonwealth Edison Co 83/02/28 170pp 17311.348 24X
Fiche 50-000, 83/02/23, 8302280204

Inspection reports, IE Bulletins & correspondence

2040039 Addl response to FOIA request for 12 categories of documents
at facilities. Personal info deleted from documents re util/
instructor employee allegations concerning QA deficiency
rewards App A documents. Document 31 available in PDR
TOWN, J M Division of Rules and Records 82/12/30 HATT, S L
o Citizens for Responsible Energy 3pp 17045:144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data
for 1976-83
HIND, J A Division of Emergency Preparedness & Operational
Support 82/02/03 KEPLER, J G Region 3, Office of Director
23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for
1976-81, per JJ Harrison request Total insp hours for each
facility added
HIND, J A Division of Emergency Preparedness & Operational
Support 82/06/08 SPENCER, R L Division of Project & Resident
Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants,
consisting of total numbers of noncompliance items, repts
issued, insp hours, severity levels, points & hours per rept &
item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPLER, J G Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8302040402 Forwards draft SALP rept for 1982 Comments requested by
830126
OLSHAN, L N, STEVENS, J A Licensing Branch 1 83/01/24
EISENHUT, D G Division of Licensing MATTHEW, R J Division of
Systems Integration (post 811005) VOLLMER, R H Division of
Engineering 3pp 17042 317 24X Fiche 50-000, 83/01/24, 8302040402

8212040358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 18pp 17023 160 24X Fiche 50-000, 83/01/26, 8212040358

8302150404 Forwards IE Insp Repts 50-454/82-27 & 50-455/82-21 on
821101-1231 & notice of violation
KNOP, R C Division of Project & Resident Programs 83/01/26
REED, C Commonwealth Edison Co 2pp 17158 086 24X
Fiche 50-454, 83/01/26, 8302150404

--8302150406 Notice of violation from insp on 821101-1231
KNOP, R C Division of Project & Resident Programs 83/01/26
3pp 17158 088 24X Fiche 50-454, 83/01/26, 8302150404

--8302150408 IE Insp Repts 50-454/82-27 & 50-455/82-21 on 821101-1231
Noncompliance noted failure to include specs for structural
bolted connections in drawings, instructions or procedures
FORNEY, W, CONNAUGHTON, K, HAYES, D W Division of Project &
Resident Programs 83/01/19 9pp 17158 091 24X
Fiche 50-454, 83/01/26, 8302150404

8212040360 IE Info Notice 83-02, "Limitorque H08C, H10C, H28C & H30C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212040360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to
10CFR50.54 & 50.55 IE will conduct formal presentation
followed by question & answer session Requests that
participation be limited to three people
SPENCER, R L Division of Engineering 83/01/28 Commonwealth
Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302150689 Forwards IE Insp Repts 50-454/83-01 & 50-455/83-01 on
830112-14 No noncompliance noted
LITTLE, W S Division of Engineering 83/01/28 REED, C
Commonwealth Edison Co 2pp 17151 351 24X Fiche 50-454, 83/01/28,
8302150689

--8302150724 IE Insp Repts 50-454/83-01 & 50-455/83-01 on 830112-14. No
noncompliance noted Major areas inspected preservice insp
procedures, work activities, NDE personnel certifications &
data & previous insp findings
WARD, K D, DANIELSON, D H Division of Engineering 83/01/25
4pp 17151 353 24X Fiche 50-454, 83/01/28, 8302150689

8302100100 Forwards NRR input to SALP rept for Oct-Dec 1982, per
TN Tarnling request Personnel solicited for input listed
Appropriate comments from various NRR div directors
incorporated into rept
OLSHAN, L N, STEVENS, J A Licensing Branch 1 83/02/02
EISENHUT, D G Division of Licensing 3pp 17134 355 24X
Fiche 50-000, 83/02/02, 8302100100

DOCKETED ITEMS

35

8302100255 Forwards IE Insp Repts re IE 1982 investigation of Hayward-Tyler Pump Co
GOLDBERG, S C Hearing Branch 4 83/02/03 CHAVEZ, D DeKalb Area
Alliance for Responsible Energy 276pp 17114 128 24X
Fiche 50-454, 83/02/03, 8302100255

8302180365 Forwards IE Insp Repts 50-454/82-25 & 50-455/82-19 on 821202-630114 No noncompliance noted
NGRELIUS, C E Division of Project & Resident Programs 83/02/07
REED, C Commonwealth Edison Co 2pp 17209 216 24X
Fiche 50-454, 83/02/07, 8302180365

--8302180383 IE Insp Repts 50-454/82-25 & 50-455/82-19 on 821202-830114 No noncompliance noted Major areas inspected receipt insp records for tendons, tendon accessories & masonry blocks
HAYES, D W Division of Project & Resident Programs 83/02/07
21pp 17209 216 24X Fiche 50-454, 83/02/07, 8302180383

8302190528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels"
SWARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000, 83/02/08, 8302190528

8302280368 Forwards IE Insp Repts 50-454/82-26 & 50-455/82-20 on 821227-29 & 830125-28 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/02/10 REED, C Commonwealth Edison Co 2pp 17311 001 24X Fiche 50-454, 83/02/10, 8302280368

--8302280375 IE Insp Repts 50-454/82-26 & 50-455/82-20 on 821227-29 & 830125-28 No noncompliance noted Major areas inspected followup on allegations re piping support installation & GC insp deficiencies
YIN, I T, DANIELSON, D H Region 3, Office of Director 83/02/10
11pp 17311 003 24X Fiche 50-454, 83/02/10, 8302280375

8302280542 Forwards IE Insp Repts 50-454/83-02 & 50-455/83-02 on 830103-07 & 10 No noncompliance noted
LITTLE, W S Division of Engineering 83/02/10 REED, C Commonwealth Edison Co 2pp 17309 052 24X Fiche 50-454, 83/02/10, 8302280542

--8302280550 IE Insp Repts 50-454/83-02 & 50-455/83-02 on 830103-07 & 10 No noncompliance noted Major areas inspected review of procedures, work activities & records for reinsp of structural steel bolting in containment & auxiliary bldg
KEATING, D E, DANIELSON, D H Region 3, Office of Director 83/02/10
5pp 17309 054 24X Fiche 50-454, 83/02/10, 8302280550

8302280485 Forwards IE Insp Repts 50-454/82-28 & 50-455/82-22 on 821201-29 & 830114 No noncompliance noted
LITTLE, W S Division of Engineering 83/02/11 REED, C Commonwealth Edison Co 2pp 17322 217 24X Fiche 50-454, 83/02/11, 8302280485

--8302280489 IE Insp Repts 50-454/82-28 & 50-455/82-22 on 821201-29 & 830114 No noncompliance noted Major areas inspected followup on allegations/concerns re const deficiencies, concerning uniformity of concrete & quantity of water
NORTON, J F, WILLIAMS, C C Region 3, Office of Director 83/02/11
17pp 17322 219 24X Fiche 50-454, 83/02/11, 8302280489

8302180458 Ack receipt of 830209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-24 & 50-455/82-18
NGRELIUS, C E Division of Project & Resident Programs 83/02/15
REED, C Commonwealth Edison Co 1p 17215 168 24X
Fiche 50-454, 83/02/15, 8302180458

--8302180463 Responds to NRC 830103 ltr re violations noted in IE Insp Repts 50-454/82-24 & 50-455/82-18 Corrective actions temp monitoring devices ordered & will be installed in warehouses to verify proper temp band maintained
FARRAR, D L Commonwealth Edison Co 83/02/09 KEPLER, J O Region 3, Office of Director 5pp 17215 169 24X
Fiche 50-454, 83/02/15, 8302180463

8212040363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212040363

8212040365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212040365

8212040366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212040366

8302280294 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-18 & 50-455/82-13 Confirms 830223 telcon that specific ref to testing of first batch of concrete will be deleted
SPESSARD, R L Division of Engineering 83/02/25 REED, C Commonwealth Edison Co 1p 17311 076 24X Fiche 50-454, 83/02/25, 8302280294

--8302280303 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-454/82-18 & 50-455/82-13 Corrective actions FSAR will be reviewed & revised re conflicts w/structural design drawings & specs
FARRAR, D L Commonwealth Edison Co 83/02/10 KEPLER, J O Region 3, Office of Director 3pp 17311 077 24X
Fiche 50-454, 83/02/25, 8302280303

B Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218.
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

8302230542 Part 21 rept re 170 wire tendon post-tensioning sys Problem lies w/poor const techniques not nonconforming threads Nonconforming threads not responsible for failures exhibited at job sites GA procedure encl
WAIKUS, D W, MATYKIEWICZ, C INRYCO, Inc (subs of Inland Steel Co) 83/01/27 Region 3, Office of Director 11pp 17257:014 24X Fiche 50-000, 83/01/27, 8302230542

8302040370 Deficiency Rept 82-11 re accuracy of Barton electronic instrument transmitters being installed at facilities Initially reported on 821221 Corrective action based on recommendation from Barton Instruments
TRAMM, T R Commonwealth Edison Co 83/01/28 KEPLER, J O Region 3, Office of Director 2pp 17018 313 24X Fiche 50-000, 83/01/28, 8302040370

8302150419 Interim deficiency rept re installation of HVAC sys components Initially reported on 830125 Procedures revised; design tolerances clarified & safety-related HVAC field installations reinspected
TRAMM, T R Commonwealth Edison Co 83/02/07 KEPLER, J O Region 3, Office of Director 2pp 17148 130 24X Fiche 50-454, 83/02/07, 8302150419

8302280450 Interim deficiency rept re resolution of mechanical snubber bracket interference Initially reported on 830110 Lists of snubbers to be inspected compiled Insp criteria not finalized Next rept will be provided within 60 days
TRAMM, T R Commonwealth Edison Co 83/02/16 KEPLER, J O Region 3, Office of Director 1p 17308:011 24X Fiche 50-000, 83/02/16, 8302280450

T Hearing transcripts on non-antitrust matters

8302160176 Forwards testimony of I Alterman, R Rothman, A Berkiz, MA Lamstra, EF Branagan, JJ Hayes, RF Skelton, LO Hulman & ML Wohl, per ASLB 810709 order, in preparation of 830301 hearing.
GOLDBERG, S C Hearing Branch 4 83/02/15 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17161 044 24X Fiche 50-454, 83/02/15, 8302160176

--8302160182 Testimony of I Alterman on Rockford League of Women Voters Contention 106 re seismic capability of geologic faults.
ALTERMAN, I Geosciences Branch 83/02/15 16pp 17161 046 24X
Fiche 50-454, 83/02/15, 8302160182

--8302160188 Testimony of R Rothman on Rockford League of Women Voters Contention 106 re seismic capability of geologic faults.
ROTHMAN, R Geosciences Branch 83/02/15 15pp 17161 062 24X
Fiche 50-454, 83/02/15, 8302160188

--8302160194 Testimony of A Berkiz on Dekalb Area Alliance for Responsible Energy/Birmingham Alliance for Environ Contention 9A re implications of 1981 KRBRQ water hammer event on facility.
BERKIZ, A Generic Issues Branch 83/02/15 8pp 17161 077 24X
Fiche 50-454, 83/02/15, 8302160194

DOCKETED ITEMS

- B302160203 Testimony of MA Lamastra, EF Branagan, JJ Hayes & RF Skelton on Rockford League of Women Voters Contentions 42, 111 & 112 re ALARA & radiation monitoring onsite
LAMAISTRA, M A, BRANAGAN, E F Radiological Assessment Branch
HAYES, J J Effluent Treatment Systems Branch 83/02/15 70pp
17161 085 24X Fiche 50-454, 83/02/15, 8302160176
- B302160212 Testimony of LO Hulman, ML Wohl, S Newberry & EF Branagan on Rockford League of Women Voters Contentions 8 & 42 & on Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 2A re risk & accidents
HULMAN, L O, WOHL, M L Accident Evaluation Branch NEWBERRY, S
Reliability & Risk Assessment Branch 83/02/15 40pp 17161 155
24X Fiche 50-454, 83/02/15, 8302160176
- 8302170292 Forwards testimony of S Levine & L Conway
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co
83/02/15 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and
Licensing Board Panel 2pp 17177 063 24X Fiche 50-454, 83/02/15, 8302170292
- B302170298 Testimony of S Levine re contentions on Class 9 accidents
Plant design provides substantial protection against severe
or Class 9 accidents
LEVINE, S Commonwealth Edison Co LEVINE, S NUS Corp 83/02/15
35pp 17177 065 24X Fiche 50-454, 83/02/15, 8302170292
- B302170302 Testimony of L Conway re contentions claiming reduction of
occupational exposure not considered in design Steam
generators embody very best design feature to reduce
occupational radiation exposure
CONWAY, L Commonwealth Edison Co CONWAY, L Westinghouse
Electric Corp 83/02/15 12pp 17177 100 24X
Fiche 50-454, 83/02/15, 8302170292
- 8302220291 Forwards testimony on seismic, occupational exposure & water
hammer contentions & unexecuted stipulation re final
language & order of contentions Certificate of Svc encl
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth
Edison Co 83/02/15 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic
Safety and Licensing Board Panel 22pp 17228 016 24X
Fiche 50-454, 83/02/15, 8302220291
- B302220298 Testimony of AK Yonk re Rockford League of Women Voters
Contention 106 on strain gauge tests last movement of faults
over 200,000 yrs ago Faults are not capable under 10CFR100,
App A criteria Prof qualifications encl
YONK, A K Commonwealth Edison Co YONK, A K Sargent & Lundy,
Inc 83/02/15 13pp 17228 038 24X Fiche 50-454, 83/02/15,
8302220291
- B302220304 Testimony of AK Singh re Rockford League of Women Voters
Contention 106 on ground acceleration values for design
Ground acceleration values & GBE std appropriate for plant
Prof qualifications encl
SINGH, A K Commonwealth Edison Co SINGH, A K Sargent & Lundy,
Inc 83/02/15 11pp 17228 054 24X Fiche 50-454, 83/02/15,
8302220291
- B302220310 Testimony of R Pleniewicz re util actions taken to minimize
occurrence of KRSKO-type water hammer event, per Westinghouse
recommendations (Contention 9a) Util plans to change check
valve arrangement
PLENIEWICZ, R Commonwealth Edison Co 83/02/15 8pp 17228 065
24X Fiche 50-454, 83/02/15, 8302220291
- B302220317 Testimony of RW Carlson re Contention 9a on water hammer
event If util follows Westinghouse recommendations to
prevent KRSKO-type water hammer event, likelihood of
occurrence of event reduced to acceptable level.
CARLSON, R W Commonwealth Edison Co CARLSON, R W Westinghouse
Electric Corp 83/02/15 21pp 17228 074 24X
Fiche 50-454, 83/02/15, 8302220291
- B302220321 Testimony of JL Roulo on Contention 42 re sabotage No
increased risk of sabotage results from use of contractor
employees, including transient workers
ROULO, J L Commonwealth Edison Co 83/02/15 26pp 17228 097
24X Fiche 50-454, 83/02/15, 8302220291
- B302220325 Testimony of OP Lahti re Contentions 42, 111 & 112 on plant
design for reducing occupational radiation exposure Each
design principle which can reduce radiation exposure used
appropriately
LAHTI, O P Commonwealth Edison Co LAHTI, O P Sargent & Lundy,
Inc 83/02/15 34pp 17228 123 24X Fiche 50-454, 83/02/15,
8302220291
- 8302220328 Testimony of JI Fabrikant on Contentions 42, 111 & 112 re
radiation exposure, Natl committee for radiation protection
recommendations on dose limit for exposure to pregnant
women provides protection against teratogenic effects
FABRIKANT, J I Commonwealth Edison Co 83/02/15 100pp
17228 157 24X Fiche 50-454, 83/02/15, 8302220291
- B302220332 Testimony of F Rescek re Contentions 42, 111 & 112 Discusses
util corporate ALARA dosimetry program, recordkeeping
procedures & training program
RESECK, F Commonwealth Edison Co 83/02/15 493pp 17228 257
24X Fiche 50-454, 83/02/15, 8302220291
- B302220336 Testimony of JR Van Laere re Contentions 43, 111 & 112
Discusses ALARA program, health physics dept staff & in-plant
monitoring program
VAN LAERE, J Commonwealth Edison Co 83/02/15 55pp 17230 030
24X Fiche 50-454, 83/02/15, 8302220291
- 8302180387 Errata to L Conway 830215 testimony
GALLO, J, CONWAY, L Commonwealth Edison Co GALLO, J Isham,
Lincoln & Beale 83/02/16 3pp 17209 337 24X
Fiche 50-454, 83/02/16, 8302180387
- 8302230345 Forwards K Morgan affidavit & Certificate of Svc
inadvertently omitted from testimony Related correspondence
JOHNSON, B League of Women Voters of Rockford, IL 83/02/17
MARQUILIER, M B, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing
Board Panel 1p 17256 274 24X Fiche 50-454, 83/02/17, 8302230345
- B302230353 K Morgan affidavit & Certificate of Svc, inadvertently
omitted from testimony
MORGAN, K Z League of Women Voters of Rockford, IL 83/02/17
2pp 17256 275 24X Fiche 50-454, 83/02/17, 8302230345
- 8302220023 Forwards Page 2 of A Serkiz testimony, LO Hulman prof
qualifications & Table 2 to MA Lamastra testimony, omitted
from NRC 830215 testimony
GOLDBERG, S C Hearing Branch 4 83/02/18 SMITH, I W, COLE, R F,
CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p
17233 295 24X Fiche 50-454, 83/02/18, 8302220023
- B302220027 Page 2 of A Serkiz testimony, LO Hulman prof qualifications &
Table 2 to MA Lamastra testimony, omitted from NRC 830215
testimony
SERKIZ, A, HULMAN, L O, LAMAISTRA, M A NRC - No Detailed
Affiliation Given 83/02/18 7pp 17233 296 24X
Fiche 50-454, 83/02/18, 8302220023
- 8302230455 Forwards L Conway corrected testimony addressing Contentions
42, 111 & 112 re occupational radiation exposure concerning
Westinghouse steam generators Related correspondence
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co
83/02/21 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and
Licensing Board Panel 2pp 17246 056 24X Fiche 50-454, 83/02/21,
8302230455
- B302230461 Corrected testimony of L Conway, addressing Contentions
42, 111 & 112 re occupational exposure reduction
CONWAY, L Westinghouse Electric Corp 83/02/21 13pp
17246 058 24X Fiche 50-454, 83/02/21, 8302230455
- 8302230544 Testimony of HH Woodard on Contention 106 re seismic-related
site problems discovered subsequent to issuance of CP
Certificate of Svc encl Related correspondence
WOODARD, H H League of Women Voters of Rockford, IL WOODARD, H H
Detroit College 83/02/22 Atomic Safety and Licensing Board
Panel 10pp 17256 264 24X Fiche 50-454, 83/02/22, 8302230544
- 8302240059 Forwards L Frank, J Rajan, C McCracken, L Marsh, M Phillips &
J Spraul testimony on listed contentions
GOLDBERG, S C Hearing Branch 4 83/02/22 SMITH, I W, COLE, R F,
CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp
17273 013 24X Fiche 50-454, 83/02/22, 8302240059
- B302240064 Testimony of JR Rajan re flow-induced tube vibrations in
Model D steam generators If corrective mods unavailable
before Unit 1 DL received, util would have to justify interim
operation Prof qualifications encl
RAJAN, J R Mechanical Engineering Branch 83/02/22 9pp
17273 015 24X Fiche 50-454, 83/02/22, 8302240059
- B302240070 Testimony of LB Marsh, L Frank & JR Rajan re steam generator
tube degradation Concurrent steam generator tube rupture &
other DBA events beyond current design bases Prof
qualifications encl
MARSH, L B Reactor Systems Branch FRANK, L Materials
Engineering Branch RAJAN, J R Mechanical Engineering Branch
83/02/22 13pp 17273 024 24X Fiche 50-454, 83/02/22, 8302240059
- B302240074 Testimony of L Frank re steam generator tube degradation
Discusses insp of tubes & measures taken to ensure tube
integrity & minimize potential for degradation Prof
qualifications encl
FRANK, L Materials Engineering Branch, 83/02/22 13pp
17273 037 24X Fiche 50-454, 83/02/22, 8302240059

--8302240078 Testimony of CE McCracken on primary & secondary water chemistry control & corrosion re steam generator tube integrity. Numerous changes in design & procedures incorporated. Prof qualifications encl.
MCCRACKEN, C Chemical Engineering Branch 83/02/22 10pp
17273 050 24X Fiche 50-454, 83/02/22, 8302240059

--8302240083 Testimony of M Phillips on emergency planning issues. Util onsite emergency plan complies w/IRC emergency planning requirements w/some exceptions.
PHILLIPS, M Division of Emergency Preparedness & Operational Support 83/02/22 24pp 17273 060 24X Fiche 50-454, 83/02/22, 8302240059

--8302240088 Testimony of JG Spraul re adequacy of util QA program. Util organization provides QA dept w/sufficient independence from cost & schedule, authority to carry out QA operations & access to mgt Prof qualifications encl.
SPRAUL, J G Quality Assurance 83/02/22 13pp 17273 084 24X Fiche 50-454, 83/02/22, 8302240059

--8302240092 Testimony of WL Forney, DW Hayes, JE Konklin, CC Williams & IT Yin re QA program during const & preoperational testing. Util implemented acceptable const QA program & has ability & willingness to implement acceptable operating QA program.
FORNEY, W L Region 3, Office of Director HAYES, D W, KONKLIN, J E Division of Project & Resident Programs 83/02/22 167pp 17273 097 24X Fiche 50-454, 83/02/22, 8302240059

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl.
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-456 DRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8302040459 Forwards request for addl info re Section 2.5 of FSAR through Amend 40 Response requested by 830301.
YOUNGBLOOD, B J Licensing Branch 1 83/02/01 DELGEORGE, L O
Commonwealth Edison Co 4pp 17042 342 24X Fiche 50-456, 83/02/01, 8302040459

8302100208 Forwards comments on util response to NRC B10507 request for addl info re geotechnical engineering. Response to questions re vol of later seepage from essential svc pond unacceptable. Response due by 830311.
YOUNGBLOOD, B J Licensing Branch 1 83/02/01 DELGEORGE, L O
Commonwealth Edison Co 12pp 17134 112 24X Fiche 50-456, 83/02/01, 8302100208

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators.
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/DRNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators.
CHESTNUT, B H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-07 to all operating reactor licensees, applicants for DL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl.
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302160165 Requests approval of interim power restriction option to enable plant startup in event that steam generator mods to prevent tube vibration cannot be completed prior to fuel load.
TRAHM, T R Commonwealth Edison Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17162 064 24X
Fiche 50-000, 83/02/09, 8302160165

8302180379 Submits info re prevention of steam generator water hammer. Check valves removed to assure effectiveness of controlled closure check valves upstream. Addl check valve will be installed in discharge piping to minimize backleakage.
TRAHM, T R Commonwealth Edison Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17209 317 24X
Fiche 50-000, 83/02/15, 8302180379

8302240330 Notifies that NRC position on reactor trip breaker testing issue unchanged. Houston 830202 ltr to Westinghouse forwarded.
YOUNGBLOOD, B J Licensing Branch 1 83/02/16 DELGEORGE, L O
Commonwealth Edison Co 2pp 17284 337 24X Fiche 50-000, 83/02/16, 8302240330

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8302170149 Forwards addl info re instrumentation for detection of inadequate core cooling. Info closes out SER Outstanding Item 9.
TRAHM, T R Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp 17180 151 24X
Fiche 50-000, 83/02/08, 8302170149

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan implementing procedures.
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs.
PAJONSKI, J E Commonwealth Edison Co 83/01/07 DENTON, H R NRC - No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs. Revised index encl.
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080316 Responds to 821209 ltr re incident response plan & 820717 training session. No new requirements requested for emergency response facility. Minor changes suggested as result of meeting exercise NUREG-0696 & SECY-82-1118 guidelines valid.
KEPPLER, J O Region 3, Office of Director 83/02/04 REED, C
Commonwealth Edison Co 4pp 17056 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820717 meeting requests to modify emergency response facilities. Requests contradictory to NRC directive for simplification.
REED, C Commonwealth Edison Co 82/12/09 KEPPLER, J O Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302220364 Forwards response to Questions 372 21 & 372 22 re meteorological data tape, in response to NRC 830301 request for addl info concerning FSAR.
SHARTZ, E D Commonwealth Edison Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17232 006 24X
Fiche 50-456, 83/02/14, 8302220364

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure.
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure EOP-2, "Technical Support Manager".
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC - No Detailed Affiliation Given 1p 17223 219 24X
Fiche 50-000, 83/02/15, 8302180102

DOCKETED ITEMS

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan implementing Procedure EOF-2, "Technical Support Manager" NELLIS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220 24X Fiche 50-000, 83/02/15, 8302180102

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp 17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities Lists of locations encl SWARTZ, E D Commonwealth Edison Co 83/01/28 KEPLER, J O Region 3, Office of Director 4pp 17291 074 24X Fiche 50-000, 83/02/18, 8302250349

K Utility Final Safety Analysis Report (FSAR) & amends

8302280204 Forwards Amend 41 to FSAR, consisting of new & revised responses to NRC questions TRAHM, Y R Commonwealth Edison Co 83/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17311 344 24X Fiche 50-000, 83/02/23, 8302280204

--8302280212 Amend 41 to FSAR # Commonwealth Edison Co 83/02/28 170pp 17311 348 24X Fiche 50-000, 83/02/23, 8302280204

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR FELTON, J M Division of Rules and Records 82/12/30 HIATT, B L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80 HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item BUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

8302010479 Forwards IE Insp Repts 50-456/82-07 & 50-457/82-07 on 821215-17 & notice of violation KNOP, R C Division of Project & Resident Programs 83/01/19 REED, C Commonwealth Edison Co 2pp 16977 036 24X Fiche 50-456, 83/01/19, 8302010479

--8302010486 Notice of violation from insp on 821215-17 KNOP, R C Division of Project & Resident Programs 83/01/19 4pp 16977 038 24X Fiche 50-456, 83/01/19, 8302010479

--8302010494 IE Insp Repts 50-456/82-07 & 50-457/82-07 on 821215-17 Noncompliance noted inadequate program to control temp & humidity in storage, failure to maintain cleanliness in matl storage & failure to prevent entrance of animals HIND, J H, HAYES, D W, Division of Project & Resident Programs 83/01/18 7pp 16977 042 24X Fiche 50-456, 83/01/19, 8302010479

8302040402 Forwards draft BALP rept for 1982 Comments requested by 830126 OLSHAN, L N, STEVENS, J A Licensing Branch 1 83/01/24 EISENHUT, D G, Division of Licensing MATTHEW, R J Division of Systems Integration (post 811005), VOLLMER, R H, Division of Engineering 3pp 17042 317 24X Fiche 50-000, 83/01/24, 8302040402

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.94 & 50.95 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302040320 EN-83-005 on 830202 notice of violation & proposed imposition of civil penalties in amount of \$100,000 to be issued Action based on failure to implement adequate QA program for installation of safety-related equipment KLINGLER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/01/28 1p 17019 060 24X Fiche 50-456, 83/01/28, 8302040320

8302040290 Forwards corrected pages to IE Insp Repts 50-456/82-07 & 50-457/82-07 & to transmittal ltr KNOP, R C Division of Project & Resident Programs 83/02/01 REED, C Commonwealth Edison Co 1p 17017 359 24X Fiche 50-456, 83/02/01, 8302040290

--8302040295 Corrected P 2 to ltr transmitting IE Insp Repts 50-456/82-07 & 50-457/82-07 KNOP, R C Division of Project & Resident Programs 83/01/19 Commonwealth Edison Co 1p 17017 360 24X Fiche 50-456, 83/02/01, 8302040290

--8302040299 Corrected cover page to IE Insp Repts 50-456/82-07 & 50-457/82-07 HIND, J M, HAYNES, D W Division of Project & Resident Programs 83/01/18 1p 17017 361 24X Fiche 50-456, 83/02/01, 8302040290

8302040334 Discusses IE insp on 820419-0720 & forwards notice of violation & notice of proposed imposition of civil penalty KEPLER, J O Region 3, Office of Director 83/02/02 O'CONNOR, J J Commonwealth Edison Co 4pp 17019 069 24X Fiche 50-456, 83/02/02, 8302040334

--8302040336 Notice of violation & notice of proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted failure to perform audit prior to 800630-0709 re mechanical equipment erection & insp activities of Phillips, Oelshou KEPLER, J O Region 3, Office of Director 83/02/02 10pp 17019 069 24X Fiche 50-456, 83/02/02, 8302040334

8302100100 Forwards NRR input to BALP rept for Oct-Dec 1982, per TN Tanbling request Personnel solicited for input listed Appropriate comments from various NRR div directors incorporated into rept OLSHAN, L N, STEVENS, J A Licensing Branch 1 83/02/02 EISENHUT, D G Division of Licensing 3pp 17134 355 24X Fiche 50-000, 83/02/02, 8302100100

8302150528 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (e) of IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels " SWARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17156 215 24X Fiche 50-000, 83/02/08, 8302150528

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 038 24X Fiche 50-000, 83/02/24, 8212060365

DOCKETED ITEMS

357

8212040366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212040366

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp. high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

8302230542 Part 21 rept re 170 wire tendon post-tensioning sys Problem lies w/poor const techniques not nonconforming threads Nonconforming threads not responsible for failures exhibited at job sites GA procedure encl
WAITKUS, D H, HATYKIEWICZ, C INRYCO, Inc (subs of Inland Steel Co.) 83/01/27 Region 3, Office of Director 11pp 17257 014 24X Fiche 50-000, 83/01/27, 8302230542

8302040370 Deficiency Rept 82-11 re accuracy of Barton electronic recombination transmitters being installed at facilities Initially reported on 821221 Corrective action based on recommendation from Barton Instruments
TRAHM, T R Commonwealth Edison Co 83/01/28 KEPLER, J Q Region 3, Office of Director 2pp 17018 313 24X Fiche 50-000, 83/01/28, 8302040370

8302150183 Final Deficiency Rept 82-02A re fusible links in American Warning & Ventilating, Inc curtain-type fire dampers Initially reported on 820624 All curtain-type fire dampers will be reworked prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/02/03 KEPLER, J Q Region 3, Office of Director 2pp 17147 229 24X Fiche 50-456, 83/02/03, 8302150183

8302280450 Interim deficiency rept re resolution of mechanical snubber bracket interference Initially reported on 830110 Lists of snubbers to be inspected compiled Insp criteria not finalized Next rept will be provided within 60 days
TRAHM, T R Commonwealth Edison Co 83/02/16 KEPLER, J Q Region 3, Office of Director 1p 17308 011 24X Fiche 50-000, 83/02/16, 8302280450

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

8302040459 Forwards request for addl info re Section 2.5 of FBR through Amend 40 Response requested by 830301
YOUNGBLOOD, B J Licensing Branch 1 83/02/01 DELGEOERGE, L O Commonwealth Edison Co 4pp 17042 342 24X Fiche 50-456, 83/02/01, 8302040459

8302100208 Forwards comments on util response to NRC 810507 request for addl info re geotechnical engineering Response to questions re vol of water seepage from essential svc pond unacceptable Response due by 830311
YOUNGBLOOD, B J Licensing Branch 1 83/02/01 DELGEOERGE, L O Commonwealth Edison Co 12pp 17134 112 24X Fiche 50-456, 83/02/01, 8302100208

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NDVAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302160165 Requests approval of interim power restriction option to enable plant startup in event that steam generator mods to prevent tube vibration cannot be completed prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17162 064 24X
Fiche 50-000, 83/02/09, 8302160165

8302180379 Submits info re prevention of steam generator water hammer. Check valves removed to assure effectiveness of controlled closure check valves upstream Addl check valve will be installed in discharge piping to minimize backleakage
TRAHM, T R Commonwealth Edison Co 83/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17209 317 24X
Fiche 50-000, 83/02/15, 8302180379

8302240330 Notifies that NRC position on reactor trip breaker testing issue unchanged Houston 830202 ltr to Westinghouse forwarded
YOUNGBLOOD, B J Licensing Branch 1 83/02/16 DELGEOERGE, L O Commonwealth Edison Co 2pp 17284 337 24X Fiche 50-000, 83/02/16, 8302240330

E NRC Safety Evaluation Report (SER): supp's & correspondence

8302170149 Forwards addl info re instrumentation for detection of inadequate core cooling info closes out SER Outstanding item 9
TRAHM, T R Commonwealth Edison Co 83/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp 17180 151 24X
Fiche 50-000, 83/02/08, 8302170149

F Security, medical, emergency & fire protection plans

8302040033 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/01/27, Document Management Branch 1p 17043 230 24X Fiche 50-000, 83/01/27, 8302040033

--8302040037 Forwards public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs
PAJOWSKI, J E Commonwealth Edison Co 83/01/07, DENTON, H R NRC - No Detailed Affiliation Given 1p 17043 231 24X
Fiche 50-000, 83/01/27, 8302040033

--8302040048 Public version of revised Emergency Plan Implementing Procedures ED-29 re meteorological maint programs & ED-25 re computer codes for access to ODCS programs. Revised index encl
LITERSKI, L A Commonwealth Edison Co 83/01/06 11pp 17043 232 24X Fiche 50-000, 83/01/27, 8302040033

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl. NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01, Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302080316 Responds to 821209 ltr re incident response plan & 820917 training session No new requirements requested for emergency response facility Minor changes suggested as result of meeting exercise NUREG-0696 & BECY-82-111B guidelines valid
KEPLER, J Q Region 3, Office of Director 83/02/04 REED, C, Commonwealth Edison Co 4pp 17036 290 24X Fiche 50-000, 83/02/04, 8302080316

--8302080322 Objects to 820917 meeting requests to modify emergency response facilities Requests contradictory to NRC directive for simplification
REED, C Commonwealth Edison Co 82/12/09 KEPLER, J Q Region 3, Office of Director 3pp 17056 294 24X Fiche 50-000, 83/02/04, 8302080316

8302220364 Forwards response to Questions 372.21 & 372.22 re meteorological data tape. In response to NRC 830301 request for addl info concerning FBR
SHARTZ, E D Commonwealth Edison Co 83/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17232 006 24X
Fiche 50-456, 83/02/14, 8302220364

DOCKETED ITEMS

8302180102 Releases public version of revised corporate command ctr generating station emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document
Management Branch 1p 17223 218 24X Fiche 50-000, 83/02/15, 8302180102

--8302180126 Forwards public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure
ECF-2, "Technical Support Manager"
MOORE, R D Commonwealth Edison Co 83/01/03 DENTON, H R NRC -
No Detailed Affiliation Given 1p 17223 219 24X
Fiche 50-000, 83/02/15, 8302180102

--8302180156 Public version of Rev 2 to Corporate Command Ctr Generating Station Emergency Plan Implementing Procedure ECF-2,
"Technical Support Manager"
NELLS, C A Commonwealth Edison Co 83/02/02 68pp 17223 220
24X Fiche: 50-000, 83/02/15, 8302180102

8302250349 Advises that R Lickus will contact util for site visits to review proposed emergency notification sys & health physics network locations at technical support ctrs & emergency operating facilities, per util 830128 request.
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/18 REED, C Commonwealth Edison Co 2pp
17291 072 24X Fiche 50-000, 83/02/18, 8302250349

--8302250361 Requests approval & acquisition of necessary equipment to activate proposed locations for emergency notification sys & health physics network phones within technical support ctrs & emergency operating facilities. Lists of locations encl
SWARTZ, E D Commonwealth Edison Co 83/01/28 KEPLER, J O
Region 3, Office of Director 4pp 17291 074 24X
Fiche: 50-000, 83/02/18, 8302250349

K Utility Final Safety Analysis Report (FSAR) & amends

8302280204 Forwards Amend 41 to FSAR, consisting of new & revised responses to NRC questions
TRAHM, T R Commonwealth Edison Co 83/02/23 DENTON, H R Office
of Nuclear Reactor Regulation, Director 4pp 17311 344 24X
Fiche 50-000, 83/02/23, 8302280204

--8302280212 Amend 41 to FSAR
+ Commonwealth Edison Co 83/02/28 170pp 17311 348 24X
Fiche 50-000, 83/02/23, 8302280204

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities. Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records, 82/12/30 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director
23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESBARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
BUCHARSKI, L Region 3, Office of Director 82/07/08
KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche: 50-000, 82/12/30, 8302040039

1302010479 Forwards IE Insp Repts 50-456/82-07 & 50-457/82-07 on 821215-17 & notice of violation
KNOP, R C Division of Project & Resident Programs 83/01/19
REED, C Commonwealth Edison Co 2pp 16977 036 24X
Fiche: 50-456, 83/01/19, 8302010479

--8302010486 Notice of violation from insp on 821215-17
KNOP, R C Division of Project & Resident Programs 83/01/19
4pp 16977 038 24X Fiche: 50-456, 83/01/19, 8302010479

--8302010494 IE Insp Repts 50-456/82-07 & 50-457/82-07 on 821215-17
Noncompliance noted inadequate program to control temp & humidity in storage, failure to maintain cleanliness in matl storage & failure to prevent entrance of animals
HINDS, J M, HAYES, D W Division of Project & Resident Programs
83/01/18 7pp 16977 042 24X Fiche 50-456, 83/01/19, 8302010479

8302040402 Forwards draft SALP rept for 1982 Comments requested by
830126
OLSHAN, L N Licensing Branch 1 83/01/24 EISENHUT, D G Division
of Licensing 3pp 17042 317 24X Fiche 50-000, 83/01/24, 8302040402

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H10C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session. Requests that participation be limited to three people
SPESBARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302040320 EN-83-005 on 830202, notice of violation & proposed imposition of civil penalties in amount of \$100,000 to be issued Action based on failure to implement adequate QA program for installation of safety-related equipment
KLINGLER, G, AYLWARD, J Director's Office, Office of Inspection and Enforcement 83/01/28 1p 17019 060 24X Fiche 50-456, 83/01/28, 8302040320

8302040290 Forwards corrected pages to IE Insp Repts 50-456/82-07 & 50-457/82-07 & to transmittal ltr
KNOP, R C Division of Project & Resident Programs 83/02/01
REED, C Commonwealth Edison Co 1p 17017 339 24X
Fiche 50-456, 83/02/01, 8302040290

--8302040295 Corrected P 2 to ltr transmitting IE Insp Repts 50-456/82-07 & 50-457/82-07
KNOP, R C Division of Project & Resident Programs 83/01/19
Commonwealth Edison Co 1p 17017 360 24X Fiche 50-456, 83/02/01, 8302040290

--8302040299 Corrected cover page to IE Insp Repts 50-456/82-07 & 50-457/82-07
HINDS, J M, HAYNES, D W Division of Project & Resident Programs
83/01/18 1p 17017 361 24X Fiche 50-456, 83/02/01, 8302040290

8302040334 Discusses IE insp on 820419-0720 & forwards notice of violation & notice of proposed imposition of civil penalty
KEPLER, J O Region 3, Office of Director 83/02/02 O'CONNOR, J J
Commonwealth Edison Co 4pp 17019 065 24X Fiche 50-456, 83/02/02, 8302040334

--8302040336 Notice of violation & notice of proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted failure to perform audit prior to 800630-0709 re mechanical equipment erection & insp activities of Phillips, Oetshaw
KEPLER, J O Region 3, Office of Director 83/02/02 10pp
17019 069 24X Fiche 50-456, 83/02/02, 8302040334

8302100100 Forwards NRR input to SALP rept for Oct-Dec 1982, per TN Tambling request Personnel solicited for input listed. Appropriate comments from various NRR div directors incorporated into rept
OLSHAN, L N Licensing Branch 1 83/02/02 EISENHUT, D G Division
of Licensing 3pp 17134 355 24X Fiche 50-000, 83/02/02, 8302100100

8302150328 Requests delay until 830328 to respond to NRC request for supplemental info re Refs (a), (b), (c) & (d) of IE Bulletin B1-03, "Flow Blockage of Cooling Water to Safety-Related Sys Components by Asiatic Clams & Mussels"
SWARTZ, E D Commonwealth Edison Co 83/02/08 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 17156 215 24X
Fiche 50-000, 83/02/08, 8302150328

DOCKETED ITEMS

35

8212040363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212040363

8212040365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Redwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212040365

8212040366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212040366

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

8302230542 Part 21 rept re 170 wire tendon post-tensioning sys Problem lies w/poor const techniques not nonconforming threads Nonconforming threads not responsible for failures exhibited at job sites QA procedure encl
HAITKUS, D W INRYCO, Inc (subs of Inland Steel Co.) 83/01/27 Region 3, Office of Director 11pp 17257 014 24X Fiche 50-000, 83/01/27, 8302230542

8302040370 Deficiency Rept 82-11 re accuracy of Barton electronic instrument transmitters being installed at facilities Initially reported on 821221 Corrective action based on recommendation from Barton Instruments
TRAHM, T R Commonwealth Edison Co 83/01/28 KEPPLER, J O Region 3, Office of Director 2pp 17018 313 24X Fiche 50-000, 83/01/28, 8302040370

8302150183 Final Deficiency Rept 82-02A re fusible links in American Warning & Ventilating, Inc curtain-type fire dampers Initially reported on 820624 All curtain-type fire dampers will be reworked prior to fuel load
TRAHM, T R Commonwealth Edison Co 83/02/03 KEPPLER, J O Region 3, Office of Director 2pp 17147 225 24X Fiche 50-458, 83/02/03, 8302150183

8302280450 Interim deficiency rept re resolution of mechanical snubber bracket interference Initially reported on 830110 Lists of snubbers to be inspected compiled Insp criteria not finalized Next rept will be provided within 60 days
TRAHM, T R Commonwealth Edison Co 83/02/16 KEPPLER, J O Region 3, Office of Director 1p 17308 011 24X Fiche 50-000, 83/02/16, 8302280450

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, HSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-458 RIVER DEMO STATION, UNIT 1

A Application/construction stage documents & correspondence

8302040547 Informs that instrument tubing & supports programs described in util 830103 submittal, acceptable provided fabricated supports accord w/App B QA program
SCHWENCER, A Licensing Branch 2 83/02/01 CAHILL, W J Gulf States Utilities Co 3pp 17050 254 24X Fiche 50-458, 83/02/01, 8302040547

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

F Security, medical, emergency & fire protection plans

8302040268 Notification of 830203 meeting w/util & S&W in Bethesda, MD to discuss emergency preparedness topics
WEINKAM, E J Licensing Branch 2 83/01/28 SCHWENCER, A Licensing Branch 2 3pp 17042 348 24X Fiche 50-458, 83/01/28, 8302040268

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302170038 Summary of 830203 meeting w/applicant & S&W in Bethesda, MD re emergency planning & onsite emergency preparedness program
WEINKAM, E J Licensing Branch 2 83/02/08 Licensing Branch 2 3pp 17191 044 24X Fiche 50-458, 83/02/08, 8302170038

O Adjudicatory correspondence

8302250058 Notice of appearance in proceeding Certificate of Svc encl
REPKA, D A Hearing Branch 3 83/02/24 3pp 17293 341 24X Fiche 50-458, 83/02/24, 8302250058

Q Inspection reports, IE Bulletins & correspondence

8212040358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212040358

8212040360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212040360

8212040361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212040361

8302070547 Discusses E Transcillits concerns re generic equipment qualification problems Special insp recommended
PHILLIPS, M S Division of Vendor & Technical Programs 83/02/02 JOHNSON, E H Enforcement Staff 4pp 17034 107 24X Fiche 50-458, 83/02/02, 8302070547

8302230317 Submits addl info in response to NRC 821210 ltr re util 811209 final response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Aquatic clam) & Mytilus Sp (Mussel) "
BOOKER, J E Gulf States Utilities Co 83/02/14 SEYFRIT, K V Region 4, Office of Director 3pp 17248 314 24X Fiche 50-458, 83/02/14, 8302230317

8302230546 Advises of program instituted to send copy of insp repts of vendors used at facilities Repts will be forwarded w/o transmittal ltr through resident inspector, w/distribution ticket to flag significant problems
COLLINS, J T Region 4, Office of Director 83/02/16 CAHILL, W J Gulf States Utilities Co 3pp 17256 277 24X Fiche 50-458, 83/02/16, 8302230546

8302230704 Ack receipt of 830114 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/82-13
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/17 CAHILL, W J Gulf States Utilities Co 1p 17259 290 24X Fiche: 50-458, 83/02/17, 8302230704

--8302230709 Responds to NRC 821216 ltr re violations noted in IE Insp Rept 50-458/82-13 Corrective actions Weld Treatment Sheet W3-03 revised to specify travel speed of 1 4 inches per minute at welding current of 100 amperes & 14 volts
CAHILL, W J Gulf States Utilities Co 83/01/14 COLLINS, J T Region 4, Office of Director 4pp 17259 291 24X Fiche 50-458, 83/02/17, 8302230704

8212040363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212040363

DOCKETED ITEMS

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 11pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302010602 Interim Deficiency Rept DR-89 re malfunction of primary knife-type disconnect mfg by RTE Delta Corp Initially reported on 821222 Addl info provided in manufacturer 820421 ltr Investigation continuing Next rept expected by 830317
BOOKER, J. E. Gulf States Utilities Co 83/01/24 COLLINS, J. T
Region 4, Office of Director 1p 16978 137 24X
Fiche 50-458, 83/01/24, 8302010602

8302030412 Interim deficiency rept re improperly installed spring nuts in GE supplied power generation control complex termination cabinets Testing to determine significance of problem incomplete Interim or final status rept provided by 830321
BOOKER, J. E. Gulf States Utilities Co 83/01/24 COLLINS, J. T
Region 4, Office of Director 1p 17005 148 24X
Fiche 50-458, 83/01/24, 8302030412

8302030379 Final Deficiency Rept DR-88 re Spec 228 310 documentation requirements Initially reported on 821222 Integral attachment matrix examined & found in compliance w/ASME requirements Condition not reportable per 10CFR50.55e
BOOKER, J. E. Gulf States Utilities Co 83/01/25 COLLINS, J. T
Region 4, Office of Director 1p 17005 347 24X
Fiche 50-458, 83/01/25, 8302030379

8302070424 Final Deficiency Rept DR-77 re violation of requirements for min spacing between drilled-in anchors & adjacent embedment plates Initially reported on 821109 Condition determined not reportable per 10CFR50.55(e)
BOOKER, J. E. Gulf States Utilities Co 83/01/27 COLLINS, J. T
Region 4, Office of Director 1p 17029 298 24X
Fiche 50-458, 83/01/27, 8302070424

8302070433 Final Deficiency Rept DR-65 re cracked, spalled & chipped concrete around main steam & other penetrations through drywell wall to steam tunnel Initially reported on 820806 Condition determined not reportable per 10CFR50.55(e)
BOOKER, J. E. Gulf States Utilities Co 83/01/27 COLLINS, J. T
Region 4, Office of Director 1p 17029 289 24X
Fiche 50-458, 83/01/27, 8302070433

8302070458 Interim Deficiency Rept DR-74 re incorrect installation of 1/4-inch drilled-in-expansion-type anchor bolts seismically support control room emergency lighting battery units Initially reported on 820830 Next rept by 830328
BOOKER, J. E. Gulf States Utilities Co 83/01/28 COLLINS, J. T
Region 4, Office of Director 1p 17036 278 24X
Fiche 50-458, 83/01/28, 8302070458

8302090400 Final Deficiency Rept DR-90 re installation of undersized vertical connection plates of structural steel beam located in drywell area Initially reported on 821228 Corrective action initiated Condition not reportable per 10CFR50.55(e)
BOOKER, J. E. Gulf States Utilities Co 83/01/28 COLLINS, J. T
Region 4, Office of Director 1p 17067 108 24X
Fiche 50-458, 83/01/28, 8302090400

8302160237 Interim deficiency rept re installation of nonseismic pipe supports over Category I components in control bldg. Initially reported on 820615 Util currently evaluating info by S&W Final rept expected by 830831
BOOKER, J. E. Gulf States Utilities Co 83/02/03 COLLINS, J. T
Region 4, Office of Director 1p 17170 120 24X
Fiche 50-458, 83/02/03, 8302160237

8302160251 Interim Deficiency Rept DR-84 re linear indication found in root of fillet weld for lug on one safety relief valve quencher Initially reported on 821206 Investigation continuing Next rept expected by 830331
BOOKER, J. E. Gulf States Utilities Co 83/02/04 COLLINS, J. T
Region 4, Office of Director 1p 17170 256 24X
Fiche 50-458, 83/02/04, 8302160251

8302200237 Interim deficiency rept re misapplication of Bethlehem Steel load indicating washer in structural steel slip connection in containment Initially reported on 830111 Investigation incomplete Next rept to be submitted on 830412
BOOKER, J. E. Gulf States Utilities Co 83/02/10 COLLINS, J. T
Region 4, Office of Director 1p 17230 135 24X
Fiche 50-458, 83/02/10, 8302200237

8302230181 Interim Deficiency Rept DR-93 re Atlas Industrial Mfg Co interconnecting piping between reactor water cleanup HX Investigation not completed Interim or final status rept expected by 830330
BOOKER, J. E. Gulf States Utilities Co 83/02/14 COLLINS, J. T
Region 4, Office of Director 1p 17245 155 24X
Fiche 50-458, 83/02/14, 8302230181

8302230325 Interim Deficiency Rept DR-92 re supplier & subsupplier ASME III documentation for Category I stainless steel thermowells Initially reported on 830114 Investigation not completed Next rept expected by 830418
BOOKER, J. E. Gulf States Utilities Co 83/02/14 COLLINS, J. T
Region 4, Office of Director 1p 17248 137 24X
Fiche 50-458, 83/02/14, 8302230325

8302230218 Interim Deficiency Rept DR-23 re HPCS diesel generator radiant heat loss value used in sizing of HPCS room cooling design Initially reported on 820212 Util awaiting addl info from GE to complete evaluation Final rept by 830429
BOOKER, J. E. Gulf States Utilities Co 83/02/15 COLLINS, J. T
Region 4, Office of Director 1p 17245 148 24X
Fiche 50-458, 83/02/15, 8302230218

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D. G. Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

830280295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/08 Consolidated Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 830280295

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/01 Consolidated Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302280069 Notice of appearance in proceeding Certificate of Svc encl
REPKA, D. A. Hearing Branch 3 83/02/24 3pp 17293 341 24X
Fiche 50-458, 83/02/24, 8302280069

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorgue H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302070547 Discusses E Transcaltiti concerns re generic equipment qualification problems Special insp recommended
PHILLIPS, H. S. Division of Vendor & Technical Programs 83/02/02
JOHNSON, E. H. Enforcement Staff 4pp 17034 107 24X
Fiche 50-458, 83/02/02, 8302070547

DOCKETED ITEMS

361

B302230317 Submits addl info in response to NRC B21210 ltr re util
B11207 final response to IF Bulletin 01-03, "Flow Blockage
of Cooling Water to Safety Sys Components by Corbicula Sp
(Asiatic clam) & Mytilus Sp (Mussel) "
BODGER, J C Gulf States Utilities Co 03/02/14 BEVFRIT, K V
Region 4, Office of Director 3pp 17248 314 24X
Fiche 50-458, B3/02/14, B302230317

B302230546 Advises of program instituted to send copy of insp repts
of vendors used at facilities Repts will be forwarded w/o
transmittal ltr through resident inspector, w/distribution
ticket to flag significant problems
COLLINS, J T Region 4, Office of Director 03/02/16 CAHILL, W J
Gulf States Utilities Co 3pp 17296 277 24X
Fiche 50-458, B3/02/16, B302230546

B212060363 IE Info Notice B3-04, "Failure of Elma Power Supply Units "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 03/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, B3/02/18, B212060363

B212060365 IE Info Notice B3-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 03/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 098 24X Fiche 50-000, B3/02/24, B212060365

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 03/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 140 24X Fiche 50-000, B3/02/24, B212060366

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants
for OLs, NSS vendors, reactor vendors & AC re certificates
& revised format for reactor operator & senior reactor
operator licenses Svc list encl
EISENHUT, D G Division of Licensing 03/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, B3/01/31, B301310203

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B302080211 Responds to NRC B21227 ltr re cooperation in control room
crew task analysis Util participated w/General Physics Corp
& Biotechnology, Inc in performing data collection phase &
preliminary analyses of four scenarios on simulator
BOUCHEY, O D Washington Public Power Supply System 03/02/03
ADENSAK, M E Licensing Branch 4 1p 17038 054 24X
Fiche 50-460, B3/02/03, B302080211

B302080295 Generic Ltr B3-09 to all operating reactor licensees,
applicants for OL & holders of CP for C-C PWRs re review of
C-E Owners Group emergency procedures guideline program Bvc
list encl
EISENHUT, D G Division of Licensing 07/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, B3/02/08, B302080295

B302080301 Generic Ltr B3-05 to BWR licensees of operating reactors
(except LACBWR), applicants for OL & holders of CP re SER of
"Emergency Procedure Guidelines, Rev 2," NEDQ-24934, June
1982 Guidelines acceptable Bvc list encl
EISENHUT, D G Division of Licensing 03/02/08 Commonwealth
Edison Co 6pp 17234 248 24X Fiche 50-000, B3/02/08, B302080301

B302250102 Notification of B30223 meeting w/B&W regulatory response
group in Bethesda, MD to discuss small break LOCA procedures
& maint of proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 03/02/17 BTOLZ, J
Operating Reactors Branch 4 3pp 17303 078 24X
Fiche 50-000, B3/02/17, B302250102

C Utility Environmental Report (ER), amends & correspondence

B302010548 Forwards response to B20716 request for addl info re Environ
Rept - OL stage acceptance review
BOUCHEY, O D Washington Public Power Supply System 03/01/25
Office of Nuclear Reactor Regulation, Director 8pp 16982 325
24X Fiche 50-460, B3/01/25, B302010548

F Security, medical, emergency & fire protection plans

B301210340 Generic Ltr B3-04 to all licensees of operating reactors,
applicants for OL & holders of CPs re regional workshop
concerning Suppl 1, NUREG-0737, "Requirements for Emergency
Response Capability " Svc list encl
EISENHUT, D G Division of Licensing 03/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, B3/02/01, B301210340

O Adjudicatory correspondence

B302070488 Forwards, per ASLB request at B30126-27 prehearing
conference, util B20430 ltr to NRC discussing util Board of
Directors decision to suspend plant const for 2 - 5 yrs
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington
Public Power Supply System 03/02/03 GROSSMAN, H, BRIGHT, O D,
HARBOUR, J Atomic Safety and Licensing Board Panel 1p 17039 213
24X Fiche 50-460, B3/02/03, B302070488

B302090021 Position on issuance of order to prevent public disclosure
of identity of members through whom organization seeks to
obtain standing NRC does not object if other parties
consent Certificate of Svc encl
WAGNER, M E, YOUNG, M A Hearing Branch 4 03/02/07 9pp,
17070 005 24X Fiche 50-460, B3/02/07, B302090021

B302090238 Memorandum opposing issuance of protective order to protect
disclosure of individuals upon which Coalition for Safe
Power is attempting to base standing No factual basis shown
to support Coalition request w/Certificate of Svc
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debevoise & Liberman 03/02/07 Atomic Safety and Licensing Board
Panel 23pp 17070 153 24X Fiche 50-460, B3/02/07, B302090238

B302160362 Views on need for & proposed wording of protective order for
membership info required to establish petitioner standing No
further info needed to establish Coalition for Safe Power
standing Certificate of Svc encl
BELL, N Coalition for Safe Power 03/02/07 10pp 17169 185 24X
Fiche 50-460, B3/02/07, B302160362

B302160354 Amended Contention 2, per ASLB B30126 order Util decision to
defer const for 2 to 5 yrs & subsequent cessation of const
dilatory Certificate of Svc encl
BELL, N Coalition for Safe Power 03/02/11 Atomic Safety and
Licensing Board Panel 6pp 17167 318 24X Fiche 50-460, B3/02/11,
B302160354

B302160356 Views on five-factor test to establish standing, Test
unnecessary because reliance not placed on Caldwell
affidavit Caldwell affidavit cured potential defect in
petition in timely manner Certificate of Svc encl
BELL, N Coalition for Safe Power 03/02/11 Atomic Safety and
Licensing Board Panel 11pp 17167 330 24X Fiche 50-460, B3/02/11,
B302160356

B302220350 Motion for leave to suppl B30207 memorandum opposing
issuance of protective order, w/encl QC Sorensen affidavit
Cross distortions of truth by petitioner must be revealed
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S
Debevoise & Liberman 03/02/17 Atomic Safety and Licensing Board
Panel 3pp 17233 007 24X Fiche 50-460, B3/02/17, B302220350

--B302220352 Affidavit of QC Sorensen re contact w/member of petitioner
Coalition for Safe Power Describes telcon w/T Dana re
allegations Portions of transcript & Certificate of Svc
encl
SORENSEN, O C Washington Public Power Supply System 03/02/15
10pp 17233 010 24X Fiche 50-460, B3/02/17, B302220350

B302240299 Memorandum & order following B30126 first prehearing
conference Coalition for Safe Power has standing to
intervene Coalition granted 15 days after conference to
modify contentions due to util recent application for mod
HARBOUR, J, BRIGHT, O D, GROSSMAN, H Atomic Safety and Licensing
Board Panel 03/02/22 8pp, 17273 290 24X Fiche 50-460, B3/02/22,
B302240299

B302240281 Position opposing Coalition for Safe Power amended petition
to intervene Coalition fails to show balancing of five
factors governing late-filed petitions Certificate of Svc
encl
WAGNER, M E, YOUNG, M A Hearing Branch 4 03/02/23 Atomic
Safety and Licensing Board Panel 12pp 17273 273 24X
Fiche 50-460, B3/02/23, B302240281

B302240291 Response to Coalition for Safe Power Amended Contention 2 re
decision to defer const of plant Admission not opposed if
hearing otherwise ordered Certificate of svc encl
YOUNG, M A, WAGNER, M E Hearing Branch 4 03/02/23 Atomic
Safety and Licensing Board Panel 4pp, 17273 286 24X
Fiche 50-460, B3/02/23, B302240291

DOCKETED ITEMS

8302250248 Response opposing Coalition for Safe Power 830211 petition to intervene Five-factor test governing late intervention not satisfied Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debovoise & Liberman 83/02/23 Atomic Safety and Licensing Board Panel 29pp 17292 286 24X Fiche 50-460, 83/02/23, 8302250248

8302250298 Resubmits until 820430 ltr w/attachments, submitted on 830203 Caption of 830203 ltr incorrectly referred to DL proceeding instead of CP proceeding
HARTMANN, S L Debovoise & Liberman HARTMANN, S L Washington Public Power Supply System 83/02/24 GROSSMAN, H, BRIGHT, G D, HARBOUR, J Atomic Safety and Licensing Board Panel 12pp 17291 243 24X Fiche 50-460, 83/02/24, 8302250298

H General correspondence

8302080024 Appeals denial of FOIA request for SECY-82-377 & SECY-82-377A, "Hearing Requests on Extension of Const Completion Dates for WPPSS 1 & 2" & "Minor Revs to SECY-82-377," respectively
NEWMAN, K A Debovoise & Liberman 82/11/09 CHILK, S J Office of the Secretary of the Commission 2pp 17106 161 24X Fiche 50-460, 82/11/09, 8302080024

8302080018 Responds to appeal re denial of FOIA request for SECY-82-377 & SECY-83-377A Appeal denied Documents withheld (ref FOIA Exemption 5)
CHILK, S J Office of the Secretary of the Commission 83/01/12 NEWMAN, K A Debovoise & Liberman 2pp 17106 159 24X Fiche 50-460, 83/01/12, 8302080018

I Financial information

8302160215 Forwards Annual Financial Rept 1982
BOUCHEY, G D Washington Public Power Supply System 83/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17167 244 24X Fiche 50-000, 83/02/09, 8302160215

--8302160239 Annual Financial Rept 1982
CAIN, S H Washington Public Power Supply System 83/02/09 50pp 17167 245 24X Fiche 50-000, 83/02/09, 8302160215

J Insurance & indemnity information

8302100218 Forwards Endorsement & to HELIA Policy NF-270
ASHBURN, D J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 83/02/03 SALTZMAN, J Office of State Programs, Director 2pp 17112 361 24X Fiche 50-397, 83/02/03, 8302100218

Q Inspection reports, IE Bulletins & correspondence

8302150231 Responds to IE Bulletin 82-04 re deficiencies in primary containment electrical penetration assemblies Bulletin not applicable to project where electrical penetrations supplied by Westinghouse No Bunker-Ramo penetrations installed
RODT, R W Washington Public Power Supply System 83/01/17 ENDELKEN, R H Region 5, Office of Director 2pp 17149 273 24X Fiche 50-460, 83/01/17, 8302150231

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302180203 PWS-V-83-004 on 830206, police arrested former utility contract employee possessing explosive mats, components & diagrams of site general svcs bldg No specific threat against site identified
SCHWAN, C A, SCHUSTER, M D Region 5, Office of Director 83/02/10 1p 17215 359 24X Fiche 50-460, 83/02/10, 8302180203

T Hearing transcripts on non-antitrust matters

8302020006 Transcript of 830126 prehearing conference in Richland, WA Pp 1-165
Atomic Safety and Licensing Board Panel 83/01/26 171pp 16992 061 24X Fiche 50-397, 83/01/26, 8302020006

8302020007 Transcript of 830127 prehearing conference in Richland, WA Pp 166-264
Atomic Safety and Licensing Board Panel 83/01/27 119pp 16991 299 24X Fiche 50-397, 83/01/27, 8302020007

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for DLs, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8302080113 Board Notification 82-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic Safety and Licensing Board Panel 18pp 17105 335 24X Fiche 50-000, 82/12/30, 8302080113

8302170482 Board Notification 83-1 forwards BNL draft rept. "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach"
EISENHUT, D G Division of Licensing FIN A-3397 83/02/01 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 134pp 17203 309 24X Fiche 50-000, 83/02/01, 8302170482

8302150125 Forwards responses to J Humphrey concerns consisting of Action Plans 7, 9, 10, 11, 12, 13, 16, 17, 20, 23, 24, 27, 30, 34, 35, 36 & 37
WULLER, G E Illinois Power Co 83/02/04 SCHWENGER, A Licensing Branch 2 46pp 17147 317 24X Fiche 50-461, 83/02/04, 8302150125

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for DL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302180444 Forwards revised recovery plan for procurement of spare & replacement parts
HALL, D P Illinois Power Co 83/02/09 KEPPLER, J G Region 3, Office of Director 13pp 17214 292 24X Fiche 50-461, 83/02/09, 8302180444

8302180449 Forwards Rev 1 to "IL Power Co Recovery Plan Training"
HALL, D P Illinois Power Co 83/02/10 KEPPLER, J G Region 3, Office of Director 1p 17215 141 24X Fiche 50-461, 83/02/10, 8302180449

--8302180452 Rev 1 to "IL Power Co Recovery Plan Training"
HALL, D P Illinois Power Co 83/02/03 15pp 17215 142 24X Fiche 50-461, 83/02/03, 8302180449

DOCKETED ITEMS

8302230453 Discusses concern that HPCB diesel generators startup testing requirements too stringent. Similarly designed sys clearly demonstrates reliability. Late Mar 1983 meeting w/NRC requested to discuss matter further.
MULLER, G E Illinois Power Co 83/02/15 SCHWENCER, A Licensing Branch 2 1p 17246 048 24X Fiche 50-461, 83/02/15, 8302230453

E NRC Safety Evaluation Report (SER), suppls & correspondence

8302080179 Forwards Brand Industrial Svcs, Inc design drawing/testing matrix providing penetration seal matl & corresponding fire test rept & ANI approved file number into closes SER.
Confirmatory Issue 39
MULLER, G E Illinois Power Co 83/02/03 SCHWENCER, A Licensing Branch 2 4pp 17098 321 24X Fiche 50-461, 83/02/03, 8302080179

8302180015 Notification of 830216 meeting w/utl in Bethesda, MD to discuss status of open confirmatory SER issues.
ABELSON, H Licensing Branch 2 83/02/11 SCHWENCER, A Licensing Branch 2 4pp 17223 117 24X Fiche 50-461, 83/02/11, 8302180015

G Adjudicatory correspondence

8302020256 Request for production of documents Certificate of Svc encl Related correspondence
PLANT, R L, FOY, J Prairie Alliance 83/01/28 Illinois Power Co 3pp 16994 267 24X Fiche 50-461, 83/01/28, 8302020256

8302070545 Motion for protective order that discovery not be had re Prairie Alliance 830128 request for production of documents on Contention VI Motion for summary disposition shows no remaining issue of fact on contention VI/Certificate of Svc.
FOX, C D Illinois Power Co FOX, C D Boyland Power Cooperative, Inc FOX, C D Western Illinois Power Cooperative, Inc 83/02/02 Commissioners 8pp 17034 225 24X Fiche 50-461, 83/02/02, 8302070545

8302080248 Answer opposing applicant motion for summary disposition of Prairie Alliance Contention VI Motion fails to resolve & address all issues of fact raised in contention. All relevant documents not available to Alliance Certificate of Svc encl.
PLANT, R L, FOY, J Prairie Alliance 83/02/03 Atomic Safety and Licensing Board Panel 10pp 17056 322 24X Fiche 50-461, 83/02/03, 8302080248

8302170259 Answer opposing applicant motion that discovery not be had re Prairie Alliance 830128 request for documents. No good cause shown why discovery should not be had. Supporting statements irrelevant. Certificate of Svc encl.
FOY, J Prairie Alliance 83/02/11 Atomic Safety and Licensing Board Panel 3pp 17187 094 24X Fiche 50-461, 83/02/11, 8302170259

8302180364 Answer supporting applicant 830117 motion for summary disposition of Prairie Alliance Contention VI re GE withdrawal from nuclear hardware market. No genuine issue of fact exists.
PATTERSON, W F Hearing Branch 3 83/02/14 Atomic Safety and Licensing Board Panel 7pp 17209 204 24X Fiche 50-461, 83/02/14, 8302180364

--8302180366 Affidavit of H Abelson Affiant has no independent info contrary to GE statements re GE intentions to remain in nuclear business, to continue to furnish support to util & to make svcs available in future. Certificate of Svc encl.
ABELSON, H Licensing Branch 2 83/02/08 5pp 17209 211 24X Fiche 50-461, 83/02/14, 8302180366

8302220037 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.
GUTIERREZ, J M Hearing Branch 3 83/02/18 3pp 17233 267 24X Fiche 50-461, 83/02/18, 8302220037

J Insurance & indemnity information

8301270285 Forwards Endorsement 16 to NELIA Policy NF-261.
TURNER, C L Illinois Power Co 83/01/07 SALTZMAN, J Antitrust & Economic Analysis Branch (Utility Finance) 2pp 16734 098 24X Fiche 50-461, 83/01/07, 8301270285

K Utility Final Safety Analysis Report (FSAR) & amends

8302030112 Files FSAR Amend 22, consisting of update to Section 3.11, "Environ Qualification of Electrical Equipment".
KOCH, L J Illinois Power Co 83/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17002 260 24X Fiche 50-461, 83/01/31, 8302030112

--8302030114 FSAR Amend 22
+ Illinois Power Co 83/01/31 448pp 17002 261 24X Fiche 50-461, 83/01/31, 8302030112

G Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities. Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency.
Forwards App A documents Document 31 available in PDR.
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80.
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPPLER, J O Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request. Total insp hours for each facility added.
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item.
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

8302010612 Forwards IE Insp Rept 90-461/82-20 on 821103-10 & notice of violation.
KIND, R C Division of Project & Resident Programs 83/01/18 GERSTNER, W C Illinois Power Co 2pp 16980 256 24X Fiche 50-461, 83/01/18, 8302010612

--8302010616 Notice of violation from insp on 821103-10
* Division of Project & Resident Programs 83/01/18 1p 16980 258 24X Fiche 50-461, 83/01/18, 8302010612

--8302010622 IE Insp Rept 90-461/82-20 on 821103-10 Noncompliance notice failure to control AE activities in areas of piping bellows expansion joints.
YIN, I T, KEY, W J, LOVE, R S Division of Project & Resident Programs 83/01/11 14pp 16980 259 24X Fiche 50-461, 83/01/11, 8302010612

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302080319 Forwards Rev 0 to "IL Power Co Recovery Plan, Corrective Action Program," per util 821115 ltr.
HALL, D P Illinois Power Co 83/01/26 KEPPLER, J O Region 3, Office of Director 1p 17056 173 24X Fiche 50-461, 83/01/26, 8302080315

--8302080318 Rev 0 to "IL Power Co Recovery Plan, Corrective Action Program".
SHIRDLDS, C A, HALL, D P Illinois Power Co 83/01/26 108pp 17056 174 24X Fiche 50-461, 83/01/26, 8302080315

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/26, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/26, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev 0 JOCR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session. Requests that participation be limited to three people.
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, 8302030303

8302150486 Ack receipt of 830128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-461/82-18.
SPESSARD, R L Division of Engineering 83/02/08 GERSTNER, W C Illinois Power Co 1p 17156 301 24X Fiche 50-461, 83/02/08, 8302150486

DOCKETED ITEMS

--B302150512 Responds to NRC B21123 ltr re violations noted in IE Insp Rept 50-461/82-18 Corrective actions QA manual revised, evaluation plan re inspector qualification developed & inspector exams investigated
HALL, D P Illinois Power Co 83/01/28 NORELIUS, C E Division of Engineering 11pp 17156 302 24X Fiche 50-461, 83/02/08, 8302150486

B302250326 Forwards Change 1 of overinsp program, incorporating schedule date changes to overinsp milestone event list List of effective pages & record of corrections encl
HALL, D P Illinois Power Co 83/02/15 KEPLER, J O Region 3, Office of Director 6pp 17291 148 24X Fiche 50-461, 83/02/15, 8302250326

B212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

S Reportable occurrences, LERs & related correspondence

B302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by B30218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, B302030495

B302150032 Interim deficiency rept re inconsistencies in certifications for HVAC mats installed by Zack Co Initially reported on B11002, Vendor QA manual revised, centralized documentation ctr established & procurement documentation reviewed
HALL, D P Illinois Power Co 83/02/03 KEPLER, J O Region 3, Office of Director 4pp 17148 036 24X Fiche 50-461, 83/02/03, B302150032

B302180127 Interim deficiency rept re possible min wall violations for safety-related piping Initially reported on B21007 Evaluation for corrective action continuing Final rept will be provided by B30613
HALL, D P Illinois Power Co 83/02/10 KEPLER, J O Region 3, Office of Director 4pp 17216 178 24X Fiche 50-461, 83/02/10, B302180127

B302280508 Deficiency Rept 83-02 re counterboring of safety-related pipe Initially reported on B30113, Investigation still in progress No further weld fit-up or matl identification insps will be performed until procedures & instructions revised
HALL, D P Illinois Power Co 83/02/16 KEPLER, J O Region 3, Office of Director 4pp 17309 071 24X Fiche 50-461, 83/02/16, B302280508

B280302 Final Deficiency Rept 83-03 re certification of startup test personnel, Initially reported on B30114 Review determined vent not reportable under 10CFR50.55e Problems noted which require corrective action to prevent recurrence
HALL, D P Illinois Power Co 83/02/18 KEPLER, J O Region 3, Office of Director 6pp 17311 070 24X Fiche 50-461, 83/02/18, B302280302

B280309 Interim Deficiency Rept 83-01 re qualification of calibr svcs suppliers Initially reported on B30113, Investigation plan determined need to include QA requirements in procedure documents for calibr tasks by svcs suppliers
HALL, D P Illinois Power Co 83/02/18 KEPLER, J O Region 3, Office of Director 4pp 17308 072 24X Fiche 50-461, 83/02/18, B302280309

B280556 Interim Deficiency Rept 82-12 re binding of sway strut/ snubber piping component supports Initially reported on B21021 Investigation process not complete Scope of potential deficiency not defined & no action taken
HALL, D P Illinois Power Co 83/02/18 KEPLER, J O Region 3, Office of Director 4pp 17309 029 24X Fiche 50-461, 83/02/18, B302280556

V Operator Examinations

B301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for QLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B301310203

B302230151 Discusses best estimate schedule re licensed operator exams Util re-evaluating Jan 1984 fuel load data which should be complete by June 1983 Upon completion of re-evaluation, list of desired exam dates will be provided
WULLER, O E Illinois Power Co 83/02/14 SCHWENCER, A Licensing Branch 2 2pp 17243 234 24X Fiche 50-461, 83/02/14, B302230151

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

B302080113 Board Notification 82-122A forwards USGS B2111B ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic Safety & Licensing Board Panel 18pp 17103 335 24X Fiche 50-000, 82/12/30, B302080113

B302170482 Board Notification 83-1 forwards BNL draft rept, "Identification of Seismically Risk-Sensitive Sys & Components in Nuclear Power Plants - General Methodological Approach " EISENHUT, D O Division of Licensing FIN A-3397 83/02/01 PALLADINO, N J, QILINSKY, V, AHEARNE, J F Commissioners 124pp 17203 309 24X Fiche 50-000, 83/02/01, B302170482

B302180449 Forwards Rev 1 to "IL Power Co Recovery Plan Training " HALL, D P Illinois Power Co 83/02/10 KEPLER, J O Region 3, Office of Director 1p 17215 141 24X Fiche 50-461, 83/02/10, B302180449

--B302180452 Rev 1 to "IL Power Co Recovery Plan Training " HALL, D P Illinois Power Co 83/02/03 15pp 17215 142 24X Fiche 50-461, 83/02/10, B302180449

J Insurance & indemnity information

B301270285 Forwards Endorsement 16 to NELIA Policy NF-261 TURNER, C L Illinois Power Co 83/01/07 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 2pp 14934 098 24X Fiche 50-461, 83/01/07, B301270285

Q Inspection reports, IE Bulletins & correspondence

B302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/ contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, B302040039

--B302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/03 KEPLER, J O Region 3, Office of Director 23pp 17043 219 24X Fiche 50-000, 82/12/30, B302040039

--B302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, B302040039

--B302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & then
SUGHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, B302040039

B212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

DOCKETED ITEMS

3

8212060360 IE Info Notice 83-02, "Limitorque H0BC,H1BC,H2BC & H3BC Gearheads " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
EISENHUT,D G Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000,83/01/28,8302030303

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp,high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY,D C Rockwell International Corp 82/12/17 COLLINS,J Region 4, Office of Director 4pp 17006 128, 24X Fiche 50-000,82/12/17,8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees,applicants for OLs,NBS vendors,reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT,D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000,83/01/31,8301310203

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR),applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines,Rev 2," NEDO-24934,June 1982 Guidelines acceptable Svc list encl
EISENHUT,D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000,83/02/08,8302080301,

H General correspondence

8302170069 Confirms 830207 telcon re closing of LPDR for Allens Creek Util has canceled const plans
SQUER,J L Division of Rules and Records 83/02/09, KROESCHE,B Sealy, TX 1p 17191 075 24X Fiche 50-466,83/02/09,8302170069

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller,Inc " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp, 17023 160 24X Fiche:50-000,83/01/26,8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC,H1BC,H2BC & H3BC Gearheads " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360.

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR),applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines,Rev 2," NEDO-24934,June 1982 Guidelines acceptable Svc list encl
EISENHUT,D G Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000,83/02/08,8302080301

H General correspondence

8302170069 Confirms 830207 telcon re closing of LPDR for Allens Creek Util has canceled const plans
SQUER,J L Division of Rules and Records 83/02/09, KROESCHE,B Sealy, TX 1p 17191 075 24X Fiche 50-466,83/02/09,8302170069

DOCKET STN-50-470 CESSAR SYSTEM B0

A Application/construction stage documents & correspondence

8302010451 Advises that administrative slippage in CESSAR-F schedule unwarranted & counterproductive CESSAR-F final design approval should be issued by Mar 1983
SCHERER,A E Combustion Engineering, Inc 83/01/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 16981 316, 24X Fiche 50-470,83/01/27,8302010451

8302160439 Forwards request for addl info re steam line & feedwater line break analysis & CESEC code Schedule for response requested within 7 days of receipt of ltr
THOMAS,C D Standardization & Special Projects Branch 83/02/07
SCHERER,A E Combustion Engineering, Inc 19pp 17172 226 24X Fiche 50-470,83/02/07,8302160439

E NRC Safety Evaluation Report (SER), supplis & correspondence

8302080424 Forwards request for addl info re 820330 submittal on core protection calculations,to complete review of CESSAR Sys B0 SER,NUREG-0852,Section 4 4 5 Schedule for responses requested within 7 days of ltr receipt
THOMAS,C D Standardization & Special Projects Branch 83/01/31
SCHERER,A E Combustion Engineering, Inc 6pp 17074 312 24X Fiche 50-470,83/01/31,8302080424

8302220011 Discusses C-E request for appeals meeting to resolve SER confirmatory item on containment sprays Accident Evaluation Branch finds that use of spray sys w/hydrazine acceptable w/periodic post-accident sampling of iodine C-E disagrees
MEYER,Q C Standardization & Special Projects Branch 83/02/15
MIRAGLIA,F J Assistant Director for Safety Assessment 2pp 17233 304 24X Fiche 50-470,83/02/15,8302220011

8302240290 Requests CESSAR-F SER,Section 5 4 3, "Shutdown Cooling Sys, be changed to reflect commitment to perform boron mixing testing on first Sys B0 reactor
SCHERER,A E Combustion Engineering, Inc 83/02/18 EISENHUT,D G Division of Licensing 1p 17274 076 24X Fiche 50-470,83/02/18,8302240290

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8302040245 Forwards info modifying FSAR re hot standby conditions Info concerns use of redundant safety-grade equipment to maintain extended hot standby conditions from outside control room Info will be incorporated into future FSAR amend
PETRICK,N A Standardized Nuclear Unit Power Plant System 83/02/02 DENTON,H R, Office of Nuclear Reactor Regulation, Director 2pp 17019 317 24X Fiche 50-000,83/02/02,8302040245

8302090308 Forwards addl info re NUREG-0737,Item II B 3, "Post-Accident Sampling " Info resolves License Condition 20 for Callaway & License Condition B 17 for Wolf Creek & supplis info in FSAR Section 18 2 3
PETRICK,N A Standardized Nuclear Unit Power Plant System 83/02/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 17069 335 24X Fiche 50-000,83/02/04,8302090308

DOCKETED ITEMS

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302250117 Notification of 830222 meeting w/utills in Bethesda, MD to discuss matters re equipment qualification review
EDISON, O E, HOLMICH, J J Licensing Branch 1 83/02/09
YOUNGBLOOD, B J Licensing Branch 1 4pp 17302 191 24X
Fiche 50-000, 83/02/09, 8302250117

8302250145 Requests identification of organization & reviewer responsible for review of Section 6 of Tech Specs re administrative controls
NOVAK, T M Assistant Director for Licensing 83/02/15
THOMPSON, H L Division of Human Factors Safety 1p 17299 354
24X Fiche 50-000, 83/02/15, 8302250145

8302240353 Notifies that NRC position on reactor trip breaker testing issue unchanged Houston 830202 ltr to Westinghouse
Forwarded
YOUNGBLOOD, B J Licensing Branch 1 83/02/16 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 3pp 17289 217 24X Fiche 50-000, 83/02/16, 8302240353

--8302100261 Discusses 830126 meeting re appeal for testing of reactor trip breakers Appeal denied
HOUSTON, R W Assistant Director for Reactor Safety 83/02/02
RAHE, E P Westinghouse Electric Corp 2pp 17289 220 24X
Fiche 50-000, 83/02/16, 8302240353

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302040363 Forwards addl info to support resolution or identification of proposed actions required to resolve SER Confirmatory Issues 15, 17, 18, 19 & 23
PETRICK, N A Standardized Nuclear Unit Power Plant System
83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17018 275 24X Fiche 50-000, 83/02/02, 8302040363

8302040374 Forwards analysis of postulated steam line break event which concludes that consequences of event bounded by previous accident analyses described in FSAR Rept satisfies SER Confirmatory Issues 13 & B 14
PETRICK, N A Standardized Nuclear Unit Power Plant System
83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 17018 302 24X Fiche 50-000, 83/02/02, 8302040374

F Security, medical, emergency & fire protection plans

8302080126 Releases public version of detailed applicant description of emergency classification scheme
FELTON, J M Division of Rules and Records 83/01/27 Document Management Branch 1p 17105 034 24X Fiche 50-482, 83/01/27, 8302080126

--8302080130 Forwards public version of detailed description of emergency classification scheme in response to NRC 821206 request
Encl info will be incorporated into Rev 10 of FSAR
KOESTER, G L Kansas Gas & Electric Co 83/01/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 33pp 17105 035
24X Fiche 50-482, 83/01/27, 8302080126

ID1210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Inspection reports, IE Bulletins & correspondence

8302070356 Forwards IE Insp Rept 50-482/82-21 on 821116-1215 No noncompliance noted
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/13 KOESTER, G L Kansas Gas & Electric Co 2pp 17099 200 24X Fiche 50-482, 83/01/13, 8302070356

--8302070359 IE Insp Rept 50-482/82-21 on 821116-1215 No noncompliance noted Major areas inspected general plant tours, followup of previously identified insp findings & observations of installation activities for safety-related piping sys
VANDEL, T E, JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 83/01/10 6pp 17029 202 21X
Fiche 50-482, 83/01/13, 8302070356

8302190562 Ack receipt of 821223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/82-17
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/01/18 KOESTER, G L Kansas Gas & Electric Co 1p 17157 009 24X Fiche 50-482, 83/01/18, 8302190562

--8302150573 Responds to NRC 821124 ltr re violations noted in IE Insp Rept 50-482/82-17 Corrective actions Nonconformance Rept 15N 6817 P, re Hanger AE04-H001/242, written 821021 & interim change to Procedure 45 approved
KOESTER, G L Kansas Gas & Electric Co 82/12/23 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 3pp 17157 010 24X Fiche 50-482, 83/01/18, 8302150562

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302070538 Ack receipt of 830119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/82-22
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/03 KOESTER, G L Kansas Gas & Electric Co 1p 17038 333 24X Fiche 50-482, 83/02/03, 8302070538

--8302070545 Responds to NRC 821220 ltr re violations noted in IE Insp Rept 50-482/82-22 Corrective actions Operations
Administrative Procedure ADM 02-100, reviewed & revised
KOESTER, G L Kansas Gas & Electric Co 83/01/19 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 17038 334 24X Fiche 50-482, 83/02/03, 8302070538

8302230690 Informs of new program to enable more timely notification of insp results by Vendor Program Branch Repts will be forwarded through NRC resident inspector, w/encl distribution ticket info in vendor repts should be used in assessments
COLLINS, J T Region 4, Office of Director 83/02/16 KOESTER, G L Kansas Gas & Electric Co 3pp 17248 325 24X
Fiche 50-482, 83/02/16, 8302230690

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8302250198 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" All Bunker Ramo furnished penetration assemblies inspected & reworked to correct deficiencies
SEIKEN, S J Standardized Nuclear Unit Power Plant System 83/02/23
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 17292 359 24X Fiche 50-000, 83/02/23, 8302250190

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

DOCKETED ITEMS

36

S Reportable occurrences, IFRs & related correspondence

8302090374 Interim deficiency rept re compromised Level II welding inspector exam. Initially reported on 830212 Unaccepted welds rejected for minor deviations. Evaluation for each of 17 inspectors expected by 830425
KOSTER, O L Kansas Gas & Electric Co 83/01/31 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17071 097 24X Fiche 50-482, 83/01/31, 8302090374

8302160245 Interim deficiency rept re loose stud/nut combinations in diesel generators. Initially reported on 830614 Rework plan for insp & retorquing of stud/nut combinations finalized. Status of insp expected by 830606
KOSTER, O L Kansas Gas & Electric Co 83/02/04 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17170 297 24X Fiche 50-482, 83/02/04, 8302160245

8302230504 Interim deficiency rept re restricted movement of nonstationary pipe supports. Initially reported on 831014 Evaluation of supports by AF incomplete. Status of evaluation will be provided by 830425
KOSTER, O L Kansas Gas & Electric Co 83/02/16 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17246 197 24X Fiche 50-482, 83/02/16, 8302230504

8302280511 Interim deficiency rept re discrepancies in barated refueling water storage sys. Initially reported on 830120 Actions initiated to correct discrepancies & determine if similar problems exist. Next rept by 830425
KOSTER, O L Kansas Gas & Electric Co 83/02/17 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17309 077 24X Fiche 50-482, 83/02/17, 8302280511

8302280387 PKO-IV-83-008 on 830222, stop work order imposed on turnover of safety-related sys & components from contractor to startup organization. Procedure reviews & tests must be completed
JOHNSEN, W D, SCHUM, W B Region 4, Office of Director 83/02/23 1p 17309 325 24X Fiche 50-482, 83/02/23, 8302280387

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, P&S vendors, reactor vendors & AF re certificates & revised format for reactor operator & senior reactor operator licenses. Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302280423 Responds to Generic Ltr 83-01 requesting project schedule requirements for conducting operator licensing exams. Initial exams tentatively scheduled during wks of 840716-20 & 0917-21 Oath of Affirmation encl
KOSTER, O L Kansas Gas & Electric Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17309 167 24X Fiche 50-482, 83/02/25, 8302280423

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302080113 Board Notification 83-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1986 Charleston-type earthquake. W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic Safety and Licensing Board Panel 18pp 17105 335 24X Fiche 50-000, 82/12/30, 8302080113

8302040245 Forwards info modifying FSAR re hot standby conditions. Info concerns use of redundant safety-grade equipment to maintain extended hot standby conditions from outside control room. Info will be incorporated into future FSAR amend
PETRICK, N A Standardized Nuclear Unit Power Plant System, 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17019 317 24X Fiche 50-000, 83/02/02, 8302040245

8302090308 Forwards addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling." Info resolves License Condition 20 for Callaway & License Condition B 17 for Wolf Creek & suppls info in FSAR Section 18.2.3
PETRICK, N A Standardized Nuclear Unit Power Plant System, 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17069 335 24X Fiche 50-000, 83/02/04, 8302090308

8302080275 Generic Ltr 83-09 to all operating reactor licensees, applicants for CL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program. Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080275

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NS&S re resolution of TH1 Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302250117 Notification of 830222 meeting w/utills in Bethesda, MD to discuss matters re equipment qualification review
EDLICH, G E, HOLNICH, J J Licensing Branch 1 83/02/09 YOUNGBLOOD, B J Licensing Branch 1 4pp 17302 191 24X Fiche 50-000, 83/02/09, 8302250117

8302250145 Requests identification of organization & reviewer responsible for review of Section 6 of Tech Specs re administrative controls
NOVAK, T M Assistant Director for Licensing 83/02/15 THOMPSON, H L Division of Human Factors Safety 1p 17299 354 24X Fiche 50-000, 83/02/15, 8302250145

8302240353 Notifies that NRC position on reactor trip breaker testing issue unchanged. Houston 830202 ltr to Westinghouse forwarded
YOUNGBLOOD, B J Licensing Branch 1 83/02/16 SCHNELL, D F Union Electric Co KOSTER, O L Kansas Gas & Electric Co 3pp 17289 217 24X Fiche 50-000, 83/02/16, 8302240353

--8302100261 Discusses 830126 meeting re appeal for testing of reactor trip breakers. Appeal denied
HOUSTON, R W Assistant Director for Reactor Safety 83/02/02 RAHE, E P Westinghouse Electric Corp 2pp 17289 220 24X Fiche 50-000, 83/02/16, 8302240353

E NRC Safety Evaluation Report (SER), suppls & correspondence

8302040363 Forwards addl info to support resolution or identification of proposed actions required to resolve SER Confirmatory Issues 15, 17, 19, 19 & 23
PETRICK, N A Standardized Nuclear Unit Power Plant System, 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17018 275 24X Fiche 50-000, 83/02/02, 8302040363

8302040374 Forwards analysis of postulated steam line break event which concludes that consequences of event bounded by previous accident analyses described in FSAR Rept satisfies SER Confirmatory Issues 13 & 14
PETRICK, N A Standardized Nuclear Unit Power Plant System, 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 17018 302 24X Fiche 50-000, 83/02/02, 8302040374

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for CL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302020259 Notice of ASLAP constitution AS Rosenthal, Chairman & OJ J Edles & RL Gotschy, members
SHOFMAKER, C J Atomic Safety and Licensing Appeal Panel 83/01/31 1p 16994 167 24X Fiche 50-483, 83/01/31, 8302020259

8302080243 Answer opposing util 830121 motion to change schedule for litigation of emergency planning contentions. Util using delaying tactics to circumvent not solve issues
Certificate of Svc encl
REED, J O Reed, J O 83/02/01 Atomic Safety and Licensing Board Panel 3pp 17057 166 24X Fiche 50-483, 83/02/01, 8302080243

8302070537 Memorandum & order granting applicant motion to change schedule for filing motions for summary disposition & testimony & for hearing. Revised schedule listed
BRIGHAM, G O, KLINE, J R, GLEASON, J P Atomic Safety and Licensing Board Panel 83/02/03 Union Electric Co 2pp 17038 331 24X Fiche 50-483, 83/02/03, 8302070537

DOCKETED ITEMS

8302070573 Exceptions to ASLAs B21213 partial initial decision re insp of embedded plates Certificate of Svc encl
CHACKES, K M Joint Intervenor-Calloway CHACKES, K M Chackes & Hoare 83/02/03 Atomic Safety and Licensing Appeal Panel 8pp 17034 284 24X Fiche 50-483, 83/02/03, 8302070573

8302160297 Confirms 830101 & 07 telcons re objection to applicant B30121 proposed change of schedule Change unjustified Ruling on Contentions 16 - 20 omitted from B21207 memorandum & order requested
REED, J G Reed, J G 83/02/09 GLEASON, J P, BRIGHT, G D, KLINE, J R Atomic Safety and Licensing Board Panel 1p 17170 091 24X Fiche 50-483, 83/02/09, 8302160297

8302180267 Views on applicability of 10CFR20 stds to emergency planning activities No legal requirement exists that Part 20 must be used to control post-accident re-entry & recovery Certificate of Svc encl
PERLIS, R Q Hearing Branch 3 83/02/14 6pp 17212 064 24X Fiche 50-483, 83/02/14, 8302180267

8302230607 Answer opposing NRC 830214 views on 10CFR20 stds for protection against radiation Safety stds that apply to routine plant operations should apply to extraordinary operations Certificate of Svc encl
REED, J G Reed, J G 83/02/18 Atomic Safety and Licensing Board Panel 3pp 17254 055 24X Fiche 50-483, 83/02/18, 8302230607

J Insurance & indemnity information

8302040270 Forwards Endorsement 12 to NELA Policy NF-264
NADEL, M Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc Div 83/01/31 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 17020 035 24X Fiche 50-483, 83/01/31, 8302040270

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1974-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J G Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1974-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J G Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

8302040047 Forwards IE Insp Rept 50-483/82-19 on B21101-1231 & notice of violation
KNOP, R C Division of Project & Resident Programs 83/01/20 SCHNELL, D F Union Electric Co 2pp 17020 333 24X Fiche 50-483, 83/01/20, 8302040047

--8302040051 Notice of violation from insp on B21101-1231
KNOP, R C Division of Project & Resident Programs 83/01/20 2pp 17020 335 24X Fiche 50-483, 83/01/20, 8302040047

--8302040055 IE Insp Rept 50-483/82-19 on B21101-1231 Noncompliance noted inadequate insp of surface mounted plate & failure to maintain min separation between redundant Class 1F flexible conduits at feedwater flow control valves
NEISLER, J H, KONKLIN, J E Region 3, Office of Director 83/01/19 7pp 17020 337 24X Fiche 50-483, 83/01/20, 8302040047

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limit torque H0BC, H1BC, H2BC & H3HC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev & 10CFR50 54 & 50 55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17038 187 24X Fiche 50-000, 83/01/28, 8302030303

8302150456 Ack receipt of 830126 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-07
SPESARD, R L Division of Engineering 83/02/08 SCHNELL, D F Union Electric Co 1p 17158 108 24X Fiche 50-483, 83/02/08, 8302150456

--8302150466 Responds to NRC 820917 ltr re violations noted in IE Insp Rept 50-483/82-07 Completion date of 830131 cannot be met due to delays in obtaining rebar locating equipment & time devoted to training
SCHNELL, D F Union Electric Co 83/01/26 NURELIUS, C E Division of Engineering 1p 17158 109 24X Fiche 50-483, 83/02/08, 8302150456

8302250198 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " All Bunker Remo furnished penetration assemblies inspected & reworked to correct deficiencies
SEIKEL, S J Standardized Nuclear Unit Power Plant System 11/10/79 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 17292 359 24X Fiche 50-000, 83/02/08, 8302250198

S Reportable occurrences, IERs & related correspondence

8302040344 Interim deficiency rept re battery charger output chubw failure Initially reported on 830105 Caused by short circuit between choke input lead & coil Final rept expected by 830215 Also reportable per Part 21
SCHNELL, D F Union Electric Co 83/01/26 KEPLER, J G Region 3, Office of Director 1p 17018 251 24X Fiche 50-483, 83/01/26, 8302040344

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, HSS vendors, reactor vendors & AF re certificates & revised format for reactor operator & senior reactor operator licensees Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limit torque H0BC, H1BC, H2BC & H3HC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

DOCKETED ITEMS

DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302090080 Generic Ltr 83-10C to all applicants w/Hestinghouse designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1974-80

HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director 23pp 17045 219 24X Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added

HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item

SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IC will conduct formal presentation followed by question & answer session Requests that participation be limited to three people

SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 18/ 24X Fiche 50-000, 83/01/28, 8302030303

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

B Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

B Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director App 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 8TH-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSS re resolution of TMI Action Item IF K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

8302250391 Forwards Amend 19 to Duke Power nuclear guides Amend 20 will be forwarded in Apr 1983 ELLIOTT, J L Duke Power Co 83/02/18 DIRKEL, R Office of Nuclear Reactor Regulation, Director App 17296 215 24X Fiche 50-000, 83/02/18, 8302250391

--8302250400 Rev DA to Nuclear Guide 1 61, "Damping Values for Seismic Design of Nuclear Power Plants" + Duke Power Co 83/01/06 7pp 17296 217 24X Fiche 50-000, 83/02/18, 8302250391

--8302250424 Rev 1A to Nuclear Guide 1 143, "Design Guidance For Radwaste Mgt Sys, Structures & Components Installed in Light-Water-Cooled Nuclear Power Plants" MILLER, R E Duke Power Co 83/01/06 14pp 17296 297 24X Fiche 50-000, 83/02/18, 8302250391

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

Q Inspection reports, IE Bulletins & correspondence

8302150108 Forwards response to 821210 request for addl info on IE Bulletin B1-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (Mussel)" Monitoring program for clams to be established DALL, L C Duke Power Co 83/01/17 O'REILLY, J P Region 2, Office of Director App 17146 356 24X Fiche 50-491, 83/01/17, 8302150108

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director App 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 8TH-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

Q Inspection reports, IE Bulletins & correspondence

8302150108 Forwards response to 821210 request for addl info on IE Bulletin B1-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (Mussel)" Monitoring program for clams to be established DALL, L C Duke Power Co 83/01/17 O'REILLY, J P Region 2, Office of Director App 17146 356 24X Fiche 50-491, 83/01/17, 8302150108

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director App 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSS re resolution of IMI Action Item 11 K 3 D, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Louisiana Power & Light Co 22pp 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

Q Inspection reports, IE Bulletins & correspondence

8302150108 Forwards response to 821210 request for addl info on IE Bulletin BI-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (Mussel)" Monitoring program for clams to be established
DALL, L C Duke Power Co 83/01/17 O'REILLY, J P Region 2, Office of Director 2pp 17146 356 24X Fiche 50-491, 83/01/17, 8302150108

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

S Reportable occurrences, LFRs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

Q Inspection reports, IE Bulletins & correspondence

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

Q Inspection reports, IE Bulletins & correspondence

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8302070516 Forwards "Review of Quadrex Rept," transition phase-final rept Rept contains Bechtel technical response to & rationale for disposition of each Quadrex issue Bechtel 820826 ltr encl
DPREA, O W Houston Lighting & Power Co 82/08/26 COLLINS, J T Region 4, Office of Director 3pp 17037 080 24X
Fiche 50-458, 82/08/26, 8302070516

--8302070525 "Review of Quadrex Rept," transition phase-final rept Related responses encl
* Houston Lighting & Power Co EN-619 82/08/26 554pp
17037 083 24X Fiche 50-498, 82/08/26, 8302070516

8302080113 Board Notification 82-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1886 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic
Safety and Licensing Board Panel 18pp 17105 335 24X
Fiche 50-000, 82/12/30, 8302080113

DOCKETED ITEMS

8302140163 Advises that NRC in-progress audit discussed in 821029 ltr should be rescheduled for mid-Apr 1983 to support timely review or control room design results
GOLDBERG, J H Houston Lighting & Power Co 83/01/31 NOVAK, T M Assistant Director for Licensing 2pp 17141 200 24X
Fiche 50-498, 83/01/31, 8302140163

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORN, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Xrsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070364 Act receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/01 OPREA, Q W Houston Lighting & Power Co 1p 17030 012 24X Fiche 50-498, 83/02/01, 8302070364

--8302070366 Responds to NRC 821213 ltr re violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16 Corrective actions two addl UL listed 3 h fire dampers installed in HVAC ducts
Disputes violation re improper storage of QA records
OPREA, Q W Houston Lighting & Power Co 83/01/10 COLLINS, J T Region 4, Office of Director 7pp 17030 013 24X
Fiche 50-498, 83/02/01, 8302070364

8302170524 Notification of 830217 & 18 meetings w/util in Bay City, TX to discuss status of emergency planning, including emergency response facilities & appropriate rules, regulations & guidance
SCHIERLING, H Licensing Branch 3 83/02/01 KNIGHTON, Q W Licensing Branch 3 4pp 17197 111 24X Fiche 50-498, 83/02/01, 8302170524

G Adjudicatory correspondence

8302030263 Forwards IE Insp Repts 50-498/82-12 & 50-499/82-12 of util activities re resolution of findings in "Design Review of Brown & Root Engineering Work for South TX Project (Quadrex Rept)"
GUTIERREZ, J M Hearing Branch 3 83/01/17 BECHHOEFER, C, HILL, E E, LAMB, J C Atomic Safety and Licensing Board Panel 466pp 17000 001 24X Fiche 50-498, 83/01/17, 8302030263

8302150515 Forwards "Special Insp Rept of Quadrex Corp Rept on Design Review of Brown & Root Engineering Work for South TX Project, Units 1 & 2" W/o encl
GUTIERREZ, J M Hearing Branch 1 83/02/10 BECHHOEFER, C, HILL, E E, LAMB, J C Atomic Safety and Licensing Board Panel 1p 17156 242 24X Fiche 50-498, 83/02/10, 8302150515

8302270033 Notice of RO Perlis appearance in proceeding & JM Gutierrez withdrawal of appearance in proceeding Certificate of Svc encl
PERLIS, R O, GUTIERREZ, J M Hearing Branch 3 83/02/18 4pp 17233 263 24X Fiche 50-498, 83/02/18, 8302270033

G Inspection reports, IE Bulletins & correspondence

8302030263 Forwards IE Insp Repts 50-498/82-12 & 50-499/82-12 of util activities re resolution of findings in "Design Review of Brown & Root Engineering Work for South TX Project (Quadrex Rept)"
GUTIERREZ, J M Hearing Branch 3 83/01/17 BECHHOEFER, C, HILL, E E, LAMB, J C Atomic Safety and Licensing Board Panel 466pp 17000 001 24X Fiche 50-498, 83/01/17, 8302030263

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302010558 Responds to IE Bulletin 82-04 No Bunker-Ramo electrical penetration assemblies installed or planned for installation at facilities Affidavit encl
OPREA, Q W Houston Lighting & Power Co 83/01/26 COLLINS, J T Region 4, Office of Director 3pp 16977 104 24X
Fiche 50-498, 83/01/26, 8302010558

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H20C & H30C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302170221 SPECIAL INSPECTION REPORT OF QUADREX CORPORATION REPORT ON DESIGN REVIEW OF BROWN & ROOT ENGINEERING WORK FOR SOUTH TEXAS PROJECT, UNITS 1 AND 2 Docket Nos 50-498 And 50-499 (Houston Lighting And Power Company)
OBERLO, C R Division of Resident, Reactor Project & Engineering Programs NUREG-0948 83/01/31 466pp Available at NRC 111 Ch 17188 213 24X Fiche 50-498, 83/01/31, 8302170221

8302070364 Act receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/01 OPREA, Q W Houston Lighting & Power Co 1p 17030 012 24X Fiche 50-498, 83/02/01, 8302070364

--8302070366 Responds to NRC 821213 ltr re violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16 Corrective actions two addl UL listed 3 h fire dampers installed in HVAC ducts
Disputes violation re improper storage of QA records
OPREA, Q W Houston Lighting & Power Co 83/01/10 COLLINS, J T Region 4, Office of Director 7pp 17030 013 24X
Fiche 50-498, 83/02/01, 8302070364

8302230409 Forwards IE Insp Repts 50-498/82-18 & 50-499/82-18 on 821201-31 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/02 OPREA, Q W Houston Lighting & Power Co 13pp 17245 340 24X Fiche 50-498, 83/02/02, 8302230409

--8302230416 IE Insp Repts 50-498/82-18 & 50-499/82-18 on 821201-31 No noncompliance noted Major areas inspected welding activities, storage & maint, site tours, structural concrete, transition activities & safety-related fasteners
HILL, E E, BOARDMAN, J R, TOMLINSON, D P Division of Resident, Reactor Project & Engineering Programs 83/01/26 13pp 17245 342 24X Fiche 50-498, 83/02/02, 8302230409

8302230581 Notifies that program instituted to provide insp repts of vendors used at facilities Program assures notification of insp results Sample ticket used to flag significant problems encl Ack of receipt of rpt on encl ticket requested
COLLINS, J T Region 4, Office of Director 83/02/16 OPREA, Q W Houston Lighting & Power Co 3pp 17256 254 24X
Fiche 50-498, 83/02/16, 8302230581

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

DOCKETED ITEMS

373

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

B Reportable occurrences, LERs & related correspondence

8302070607 Deficiency rept re two cases of insulator flashover experienced at 345 kV substation since Apr 1980 Insulators mfg by Lapp Insulator Co Cause unknown Incidents not reportable per 10CFR21 or 10CFR30 55(e)
OPREA, O W Houston Lighting & Power Co 83/01/24 COLLINS, J T
Region 4, Office of Director 2pp 17034 274 24X
Fiche 50-498, 83/01/24, 8302070607

8302030384 Second interim deficiency rept re essential cooling water strainer backwash discharge line Initially reported on 820723 Util evaluating Bechtel corrective actions Next rept will be submitted by 830913
OPREA, O W Houston Lighting & Power Co 83/01/27 COLLINS, J T
Region 4, Office of Director 2pp 17005 206 24X
Fiche 50-498, 83/01/27, 8302030384

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co. of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8302070516 Forwards "Review of Quadrex Rept," transition phase-final rept Rept contains Bechtel technical response to & rationale for disposition of each Quadrex issue Bechtel 820826 ltr encl
OPREA, O W Houston Lighting & Power Co 82/08/26 COLLINS, J T
Region 4, Office of Director 3pp 17037 080 24X
Fiche 50-498, 82/08/26, 8302070516

--8302070525 "Review of Quadrex Rept," transition phase-final rept Related responses encl
* Houston Lighting & Power Co CN-617 82/08/26 554pp
17037 083 24X Fiche 50-498, 82/08/26, 8302070516

8302080113 Board Notification 82-122A forwards USGS 821118 ltr clarifying previous recommendations re recurrence of 1986 Charleston-type earthquake W/o encl
NOVAK, T M Assistant Director for Licensing 82/12/30 Atomic
Safety and Licensing Board Panel 18pp 17105 335 24X
Fiche 50-000, 82/12/30, 8302080113

8302140163 Advises that NRC in-progress audit discussed in 821029 ltr should be rescheduled for mid-Apr 1983 to support timely review of control room design results
GOLDBERG, J H Houston Lighting & Power Co 83/01/31 NOVAK, T M
Assistant Director for Licensing 2pp 17141 200 24X
Fiche 50-498, 83/01/31, 8302140163

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic
Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820217 meeting w/ORNL, ANL, TX Utilte Generating Co, SC Electric & Oas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHERNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co. of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co. of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302070364 Ack receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 83/02/01 OPREA, O W Houston Lighting & Power Co 1p
17030 012 24X Fiche 50-498, 83/02/01, 8302070364

--8302070366 Responds to NRC 821213 ltr re violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16 Corrective actions two addl UL listed 3 h fire dampers installed in HVAC ducts Disputes violation re improper storage of QA records
OPREA, O W Houston Lighting & Power Co 83/01/10 COLLINS, J T
Region 4, Office of Director 7pp 17030 013 24X
Fiche 50-498, 83/02/01, 8302070364

8302170524 Notification of 830217 & 18 meetings w/util in Bay City, TX to discuss status of emergency planning, including emergency response facilities & appropriate rules, regulations & guidance
SCHIERLING, M Licensing Branch 3 83/02/01 KNIGHTON, O W
Licensing Branch 3 4pp 17197 111 24X Fiche 50-498, 83/02/01, 8302170524

G Adjudicatory correspondence

8302030263 Forwards IE Insp Repts 50-498/82-12 & 50-499/82-12 of util activities re resolution of findings in "Design Review of Brown & Root Engineering Work for South TX Project (Quadrex Rept)"
GUTIERREZ, J M Hearing Branch 3 83/01/17 BECHHOEFER, C
HILL, E E, LAMB, J C Atomic Safety and Licensing Board Panel 466pp 17000 001 24X Fiche 50-498, 83/01/17, 8302030263

8302150515 Forwards "Special Insp Rept of Quadrex Corp Rept on Design Review of Brown & Root Engineering Work for South TX Project, Units 1 & 2 " W/o encl
GUTIERREZ, J M Hearing Branch 1 83/02/10 BECHHOEFER, C
HILL, E E, LAMB, J C Atomic Safety and Licensing Board Panel 1p
17156 242 24X Fiche 50-498, 83/02/10, 8302150515

8302220033 Notice of RO Perlis appearance in proceeding & JM Gutierrez withdrawal of appearance in proceeding Certificate of Svc encl
PERLIS, R O, GUTIERREZ, J M Hearing Branch 3 83/02/18 4pp
17233 263 24X Fiche 50-498, 83/02/18, 8302220033

Q Inspection reports, IE Bulletins & correspondence

8302030263 Forwards IE Insp Repts 50-498/82-12 & 50-499/82-12 of util activities re resolution of findings in "Design Review of Brown & Root Engineering Work for South TX Project (Quadrex Rept)"
GUTIERREZ, J M Hearing Branch 3 83/01/17 BECHHOEFER, C Atomic
Safety and Licensing Board Panel 466pp 17000 001 24X
Fiche 50-498, 83/01/17, 8302030263

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8302010558 Responds to IE Bulletin 82-04 No Bunker-Rambo electrical penetration assemblies installed or planned for installation at facilities Affidavit encl
OPREA, O W Houston Lighting & Power Co 83/01/26 COLLINS, J T
Region 4, Office of Director 3pp 16777 104 24X
Fiche 50-498, 83/01/26, 8302010558

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

DOCKETED ITEMS

8302170221 SPECIAL INSPECTION REPORT OF QUADREX CORPORATION REPORT ON DESIGN REVIEW OF BROWN & ROOT ENGINEERING WORK FOR SOUTH TEXAS PROJECT, UNITS 1 AND 2 Docket Nos 50-498 And 50-499 (Houston Lighting And Power Company)
OPREA, C R Division of Resident, Reactor Project & Engineering Programs NUREG-0948 83/01/31 46pp Available at NRC 411 00 17188 213 24X Fiche 50-498, 83/01/31, 8302170221

8302070364 Ack receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/01 OPREA, G W Houston Lighting & Power Co 1p 17030 012 24X Fiche 50-498, 83/02/01, 8302070364

--8302070366 Responds to NRC 821213 ltr re violations noted in IE Insp Repts 50-498/82-16 & 50-499/82-16 Corrective actions two add'l UL listed 3 h fire dampers installed in HVAC ducts Disputes violation re improper storage of QA records
OPREA, G W Houston Lighting & Power Co 83/01/10 COLLINS, J T Region 4, Office of Director 7pp 17030 013 24X Fiche 50-498 83/02/01, 8302070364

8302230409 Forwards IE Insp Repts 50-498/82-18 & 50-499/82-18 on 821201-31 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/02 OPREA, G W Houston Lighting & Power Co 2pp 17245 340 24X Fiche 50-498, 83/02/02, 8302230409

--8302230416 IE Insp Repts 50-498/82-18 & 50-499/82-18 on 821201-31 No noncompliance noted Major areas inspected welding activities, storage & maint, site tours, structural concrete, transition activities & safety-related fasteners
HILL, W M, BOARDMAN, J R, TOMLINSON, D P Division of Resident, Reactor Project & Engineering Programs 83/01/26 13pp 17245 342 24X Fiche 50-498, 83/02/02, 8302230409

8302230581 Notifies that program instituted to provide insp repts of vendors used at facilities Program assures notification of insp results Sample ticket used to flag significant problems encl Ack of receipt of rept on encl ticket requested
COLLINS, J T Region 4, Office of Director 83/02/16 OPREA, G W Houston Lighting & Power Co 3pp 17256 254 24X Fiche 50-498, 83/02/16, 8302230581

B Reportable occurrences, LERS & related correspondence

8302070607 Deficiency rept re two cases of insulator flashover experienced at 345 kV substation since Apr 1980 Insulators mfg by Lapp Insulator Co Cause unknown Incidents not reportable per 10CFR21 or 10CFR50 55(e)
OPREA, G W Houston Lighting & Power Co 83/01/24 COLLINS, J T Region 4, Office of Director 2pp 17034 274 24X Fiche 50-498, 83/01/24, 8302070607

8302030384 Second interim deficiency rept re essential cooling water strainer backwash discharge line Initially reported on 820723 Util evaluating Bechtel corrective actions Next rept will be submitted by 830513
OPREA, G W Houston Lighting & Power Co 83/01/27 COLLINS, J T Region 4, Office of Director 2pp 17005 206 24X Fiche 50-498, 83/01/27, 8302030384

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8302040039 Add'l response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J G Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040332

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

G Inspection reports, IE Bulletins & correspondence

8302040039 Add'l response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08 KEPLER, J G Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, 8302040039

DOCKET STN-50-506 KOSHKONONG NUCLEAR PLANT, UNIT 3

G Inspection reports, IE Bulletins & correspondence

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8302030282 Forwards Branch Technical Position MTEB-5-5 re fracture toughness testing requirements for ASME Code Class 2 & Class 3 components, per B Albert request
TRAPP, O E Washington Public Power Supply System 83/01/13 WHEELER, D Licensing Branch 3 3pp 17001 256 24X Fiche 50-508, 83/01/13, 8302030282

8302030094 Submits NRC questions for discussion at 830208 meeting re geoscience section of FSAR
KNIGHTON, G W Licensing Branch 3 83/01/21 COOK, K W Washington Public Power Supply System 3pp 17023 361 24X Fiche 50-508, 83/01/21, 8302030094

8302010416 Forwards suppl info on conformance to SRP, NUREG-0800
BOUCHEY, G D Washington Public Power Supply System 83/01/27 KNIGHTON, G W Licensing Branch 3 7pp 16974 167 24X Fiche 50-508, 83/01/27, 8302010416

8302100126 Notification of 830208 meeting w/util, USGS, Woodward-Clyde & Ebasco Svcs in Bethesda, MD for presentation on site geology & seismology
VIETTI, A Licensing Branch 3 83/01/28 KNIGHTON, G W Licensing Branch 3 3pp 17134 320 24X Fiche 50-508, 83/01/28, 8302100126

8302070276 Forwards responses to NRC 820820 questions generated during acceptance review of util 820820 CL application Changes to FSAR will be included in subsequent amend
BOUCHEY, G D Washington Public Power Supply System 83/02/03 KNIGHTON, G W Licensing Branch 3 99pp 17031 017 24X Fiche 50-508, 83/02/03, 8302070276

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSS re resolution of TMI Action Item 11 K 3 5, "Automatic Trip of Reactor Coolant Pumps" Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp 17314 232 24X Fiche 50-000, 83/02/08, 8302090065

C Utility Environmental Report (ER), amends & correspondence

8302020003 Forwards info re Environ Rept - CL stage, in response to NRC 821206 ltr
BOUCHEY, G D Washington Public Power Supply System 83/01/26 KNIGHTON, G W Licensing Branch 3 6pp 17005 072 24X Fiche 50-508, 83/01/26, 8302020003

8302020068 Forwards response to Environ Engineering Branch request for add'l info resulting from review of Environ Rept - CL stage
BOUCHEY, G D Washington Public Power Supply System 83/01/26 KNIGHTON, G W Licensing Branch 3 97pp 16991 001 24X Fiche 50-508, 83/01/26, 8302020068

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co or New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

I Financial information

8302160215 Forwards Annual Financial Rept 1982
BOUCHEY, G D Washington Public Power Supply System 83/02/09
BENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17167 244 24X Fiche 50-000, 83/02/09, 8302160215

--8302160239 Annual Financial Rept 1982
CAIN, S H Washington Public Power Supply System 83/02/09 50pp
17167 245 24X Fiche 50-000, 83/02/09, 8302160215

J Insurance & indemnity information

8302100218 Forwards Endorsement & to NELA Policy NF-270
ASHBURN, D J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc
Div 83/02/03 SALTZMAN, J Office of State Programs, Director
2pp 17112 361 24X Fiche 50-397, 83/02/03, 8302100218

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8312060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230252 Forwards IE Insp Rept 50-508/83-01 on 830101-17 No
noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 83/01/28 LEDDICK, R S Washington Public Power Supply
System 1p 17244 281 24X Fiche 50-508, 83/01/28, 8302230252

--8302230257 IE Insp Rept 50-508/83-01 on 830101-17 No noncompliance
noted Major areas inspected const activities, including exam
of welding for safety-related piping restraints & supports &
installation of core internals
ALBERT, W G, DODDS, R T Division of Resident, Reactor Project &
Engineering Programs 83/01/28 4pp 17244 282 24X
Fiche 50-508, 83/01/28, 8302230252

8302070253 Ack receipt of 830117 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-508/82-20
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 83/01/31 LEDDICK, R S Washington Public Power Supply
System 1p 17031 332 24X Fiche 50-508, 83/01/31, 8302070253

--8302070255 Responds to NRC 820202 ltr re violations noted in IE Insp
Rept 50-508/82-20 Corrective actions Ebasco site support
engineering considered in compliance w/procedural
requirements of E-76 & ANSI N45.2 II
LEDDICK, R S Washington Public Power Supply System 83/01/17
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 4pp 17031 333 24X Fiche 50-508, 83/01/31, 8302070253

8302230273 Forwards IE Insp Rept 50-508/83-02 on 830117-21 & notice
of violation
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 83/02/03 LEDDICK, R S Washington Public Power Supply
System 2pp 17242 332 24X Fiche 50-508, 83/02/03, 8302230273

--8302230274 Notice of violation from insp on 830117-21
DODDS, R T Division of Resident, Reactor Project & Engineering
Programs 83/02/03 2pp 17242 334 24X Fiche 50-508, 83/02/03,
8302230273

--8302230278 IE Insp Rept 50-508/83-02 on 830117-21 Noncompliance noted
failure to observe hold point during valve installation
HAIST, D P, WAGNER, W J, DODDS, R T Division of Resident, Reactor
Project & Engineering Programs 83/02/03 10pp 17242 337 24X
Fiche 50-508, 83/02/03, 8302230273

8302230582 Ack receipt of 830203 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-508/82-19
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 83/02/17 LEDDICK, R S Washington Public Power Supply
System 1p 17256 111 24X Fiche 50-508, 83/02/17, 8302230582

--8302230595 Responds to NRC 821115 ltr re violations noted in IE Insp
Rept 50-508/82-19 Corrective actions weld procedure
qualification test performed Addl training provided
LEDDICK, R S Washington Public Power Supply System 83/02/03
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 3pp 17256 112 24X Fiche 50-508, 83/02/17, 8302230582

8312060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts"
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

9 Reportable occurrences, LERs & related correspondence

8302070248 Clarifies 821229 interim deficiency rept re failure to meet
AWS min weld size requirements in response to NRC 830104
telcon Nine welds received satisfactory preheat in
accordance w/requirements of AWS D1.1
LEDDICK, R S Washington Public Power Supply System 83/01/28
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 3pp 17031 313 24X Fiche 50-508, 83/01/28, 8302070248

8302080177 Suppl to interim deficiency rept re structural welds
failing to meet AWS weld size requirements NDE will not be
required Welds will meet AWS D1.1 requirements upon
completion of fillet weld qualification
LEDDICK, R S Washington Public Power Supply System 83/01/28
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 4pp 17059 333 24X Fiche 50-508, 83/01/28, 8302080177

8302180215 Final deficiency rept re failed diffuser retaining cap
screws to Sys 80 reactor coolant pumps Cap screw matl heat
treatment will be changed to prevent hydrogen embrittlement/
stress corrosion cracking Not reportable per 10CFR50.55(a)
LEDDICK, R S Washington Public Power Supply System 83/02/08
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 3pp 17215 310 24X Fiche 50-508, 83/02/08, 8302180215

8302230148 Forwards Final Deficiency Rept D/N 46 re diffuser retaining
cap screws on reactor coolant pumps
LEDDICK, R S Washington Public Power Supply System 83/02/16
NRC - No Detailed Appellation Given 1p 17243 224 24X
Fiche 50-508, 83/02/16, 8302230148

--8302230154 Final Deficiency Rept D/N 46 re diffuser retaining cap
screws on reactor coolant pumps Initially reported on
821105 Cap screw matl heat treatment changed to matl not
susceptible to hydrogen corrosion cracking
LEDDICK, R S Washington Public Power Supply System 83/02/08
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 3pp 17243 225 24X Fiche 50-508, 83/02/16, 8302230148

8302230238 Forwards final deficiency rept provided to Region V re
compressible matl-embedded containment penetrations
(D/N 44)
LEDDICK, R S Washington Public Power Supply System 83/02/16
NRC - No Detailed Appellation Given 1p 17243 003 24X
Fiche 50-508, 83/02/16, 8302230238

--8302230246 Final Deficiency Rept D/N 44 re compressible matl - embedded
containment penetrations Initially reported on 820921 Load
case test results confirm subj deficiency not reportable per
10CFR50.55(e)
LEDDICK, R S Washington Public Power Supply System 83/02/11
STERNBERG, D M Division of Resident, Reactor Project & Engineering
Programs 4pp 17243, 004 24X Fiche 50-508, 83/02/16, 8302230238

DOCKETED ITEMS

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, B301310203

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 3A Application/construction stage documents & correspondence

B302090065 Generic Ltr B3-10A to all applicants w/C-E designed NSSS re resolution of TMI Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps " Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp 17314 232 24X Fiche 50-000, 83/02/08, B302090065

I Financial information

B302160215 Forwards Annual Financial Rept 1982
BOUCHEY, G D Washington Public Power Supply System 83/02/09
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17167 244 24X Fiche 50-000, 83/02/09, B302160215

--B302160239 Annual Financial Rept 1982
CAIN, S H Washington Public Power Supply System 83/02/09 50pp
17167 245 24X Fiche 50-000, 83/02/09, B302160215

J Insurance & indemnity information

B302100218 Forwards Endorsement & to NELIA Policy NF-270.
ASHBURN, D J Marsh & McLennan, Inc, H & M Nuclear Consultants, Inc
Div 83/02/03 SALTZMAN, J Office of State Programs, Director
2pp 17112 361 24X Fiche 50-397, 83/02/03, B302100218

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4I Financial information

B302160215 Forwards Annual Financial Rept 1982
BOUCHEY, G D Washington Public Power Supply System 83/02/09
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17167 244 24X Fiche 50-000, 83/02/09, B302160215

--B302160239 Annual Financial Rept 1982
CAIN, S H Washington Public Power Supply System 83/02/09 50pp
17167 245 24X Fiche 50-000, 83/02/09, B302160215

J Insurance & indemnity information

B302100218 Forwards Endorsement & to NELIA Policy NF-270
ASHBURN, D J Marsh & McLennan, Inc, H & M Nuclear Consultants, Inc
Div 83/02/03 SALTZMAN, J Office of State Programs, Director
2pp 17112 361 24X Fiche 50-397, 83/02/03, B302100218

Q Inspection reports, IE Bulletins & correspondence

B302150231 Responds to IE Bulletin B2-04 re deficiencies in primary containment electrical penetration assemblies Bulletin not applicable to project where electrical penetrations supplied by Westinghouse, No Bunker-Ramo penetrations installed
ROOT, R H Washington Public Power Supply System 83/01/17
EHOELKEN, R H Region 8, Office of Director 2pp 17149 273 24X
Fiche 50-460, 83/01/17, B302150231

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1A Application/construction stage documents & correspondence

B302080295 Generic Ltr B3-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

F Security, medical, emergency & fire protection plans

B301210340 Generic Ltr B3-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, B301210340

G Adjudicatory correspondence

B302160365 Response to ASLB B30118 memorandum & order Meteorological tower will be salvaged & disposed of Exploratory trench will be left State of OR requirements for bank sloping & grass seeding will be met Certificate of Svc encl
HASTINGS, W Portland General Electric Co 83/02/04 4pp
17164 327 24X Fiche 50-514, 83/02/04, B302160365

B302280186 Memorandum & order granting w/o prejudice, applicant B21112 request to withdraw applications for CPs
SMITH, I W Atomic Safety and Licensing Board Panel 83/02/24
Portland General Electric Co 1p 17306 046 24X
Fiche 50-514, 83/02/24, B302280186

Q Inspection reports, IE Bulletins & correspondence

B212060358 IE Info Notice B3-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice B3-02, "Limitorque H08C, H18C, H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice B3-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

B212060363 IE Info Notice B3-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice B3-05, "Obtaining Approval for Disposing of Very Low Level Radiowaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, B301310203

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2A Application/construction stage documents & correspondence

B302080295 Generic Ltr B3-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, B302080295

B302090092 Generic Ltr B3-10E to all applicants w/B&W designed NSSS re resolution of TMI Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps " Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consumers Power Co 29pp 17298 316 24X Fiche 50-000, 83/02/08, B302090092

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

B301210340 Generic Ltr B3-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability." Svc list encl
EISENHUT, D O Division of Licensing B3/02/01 Consolidated
Edison Co of New York, Inc 1pp 17221 226 24X
Fiche 50-000, B3/02/01, B301210340

G Adjudicatory correspondence

B302160365 Response to ASLB B30118 memorandum & order Meteorological tower will be salvaged & disposed of Exploratory trench will be left State of OR requirements for bank sloping & grass seeding will be met Certificate or Svc encl
HASTINGS, W Portland General Electric Co B3/02/04 4pp
17164 327 24X Fiche 50-514, B3/02/04, B302160365

B302280186 Memorandum & order granting w/o prejudice, applicant B21112 request to withdraw applications for CPs
SMITH, I W Atomic Safety and Licensing Board Panel B3/02/24
Portland General Electric Co 1p 17306 046 24X
Fiche 50-514, B3/02/24, B302280186

G Inspection reports, IE Bulletins & correspondence

B212060358 IE Info Notice B3-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, B3/01/26, B212060358

B212060360 IE Info Notice B3-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, B3/01/28, B212060360

B212060361 IE Info Notice B3-03, "Calibr of Liquid Level Instruments." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, B3/01/28, B212060361

B212060363 IE Info Notice B3-04, "Failure of Elma Power Supply Units." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/02/18 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, B3/02/18, B212060363

B212060365 IE Info Notice B3-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/02/24 Consolidated Edison Co of New
York, Inc 111pp 17347 058 24X Fiche 50-000, B3/02/24, B212060365

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/02/24 Consolidated Edison Co of New
York, Inc 112pp 17361 148 24X Fiche 50-000, B3/02/24, B212060366

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing B3/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, B3/01/31, B301310203

DOCKET 50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

B302080301 Generic Ltr B3-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing B3/02/08 Commonwealth
Edison Co 4pp 17234 245 24X Fiche 50-000, B3/02/08, B302080301

B302220489 Requests util provide good cause why Commission should grant extension to CPs as requested in util B30121 ltr Response by B30228 requested
SCHWENGER, A Licensing Branch 2 B3/02/17, MILLS, L M Tennessee
Valley Authority 4pp 17237 343 24X Fiche 50-000, B3/02/17, B302220489

G Inspection reports, IE Bulletins & correspondence

B302150610 Responds to IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC B21203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority B3/01/24 O'REILLY, J P
Region 2, Office of Director 1p 17153 309 24X
Fiche 50-000, B3/01/24, B302150610

B212060358 IE Info Notice B3-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, B3/01/26, B212060358

B212060360 IE Info Notice B3-02, "Limiterque H0BC, H1BC, H2BC & H3BC Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, B3/01/28, B212060360

B212060361 IE Info Notice B3-03, "Calibr of Liquid Level Instruments." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, B3/01/28, B212060361

S Reportable occurrences, LERs & related correspondence

B302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by B30218
EMPEY, D C Rockwell International Corp B2/12/17 COLLINS, J
Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, B2/12/17, B302030495

B302010648 Fourth interim deficiency rept re engineering change revision handling Initially reported on B11215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution Bellefonte sampling under evaluation
MILLS, L M Tennessee Valley Authority B3/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 16980 049 24X
Fiche 50-000, B3/01/19, B302010648

B302010417 First interim deficiency rept re residual stress on diesel generator engine piston skirt castings Initially reported on B21219 Removal of piston skirt for insp deferred until restart of design & const Also reportable per Part 21
MILLS, L M Tennessee Valley Authority B3/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16974 174 24X
Fiche 50-518, B3/01/24, B302010417

B302010419 First interim deficiency rept re potential deterioration of neoprene gaskets on standby diesel generator Initially reported on B21217 Transamerica Delaval, Inc changed matl for drive element to neoprene Also reportable per Part 21
MILLS, L M Tennessee Valley Authority B3/01/24 O'REILLY, J P
Region 2, Office of Director 2pp 16974 260 24X
Fiche 50-000, B3/01/24, B302010419

B302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on B20816 Info on Yellow Creek or Hartsville deferred until final decision re projects Next rept expected by B30531
MILLS, L M Tennessee Valley Authority B3/01/24 O'REILLY, J P
Region 2, Office of Director 3pp 16974 037 24X
Fiche 50-000, B3/01/24, B302010215

B302070380 Final deficiency rept re ITT Grinnell failure to use proper testing methods Initially reported on B10304 Spool pieces re-examined per ASME Section III, 1974 Edition, Hinder Addenda 1979 code Condition no longer reportable per 10CFR50.55(a)
MILLS, L M Tennessee Valley Authority B3/01/31 O'REILLY, J P
Region 2, Office of Director 1p 17030 037 24X
Fiche 50-518, B3/01/31, B302070380

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing B3/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, B3/01/31, B301310203

DOCKETED ITEMS

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

0 Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co. of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

8302220489 Requests util provide good cause why Commission should grant extension to CPs as requested in util 830121 ltr Response by 830228 requested
SCHWENGER, A Licensing Branch 2 83/02/17 MILLS, L M Tennessee Valley Authority 4pp 17237 343 24X Fiche 50-000, 83/02/17, 8302220489

0 Inspection reports, IE Bulletins & correspondence

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC B21203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 1p 17153 309 24X Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

8302010648 Fourth interim deficiency rept re engineering change review & handling Initially reported on 811215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution Bellefonte sampling under evaluation
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P Region 2, Office of Director 2pp 16980 049 24X Fiche 50-000, 83/01/19, 8302010648

8302010417 First interim deficiency rept re residual stress on diesel generator engine piston skirt castings Initially reported on 821215 Removal of piston skirt for insp deferred until restart of design & const Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 16974 174 24X Fiche 50-518, 83/01/24, 8302010417

8302010419 First interim deficiency rept re potential deterioration of isoprene gaskets on standby diesel generator Initially reported on 821217 Transamerica Delaval, Inc changed matl for drive element to neoprene Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/01/24 O'REILLY, J P Region 2, Office of Director 2pp 16974 260 24X Fiche 50-000, 83/01/24, 8302010419

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 Info on Yellow Creek or Hartsville deferred until final decision re projects Next rept expected by 830331
MILLS, L M Tennessee Valley Authority 83/01/26 O'REILLY, J P Region 2, Office of Director 3pp 16974 037 24X Fiche 50-000, 83/01/26, 8302010215

8302070380 Final deficiency rept re ITT Grinnell failure to use proper testing methods Initially reported on 810304 Spool pieces re-examined per ASME Section III, 1974 Edition, Winter Addenda 1975 code Condition no longer reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/01/31 O'REILLY, J P Region 2, Office of Director 1p 17030 037 24X Fiche 50-518, 83/01/31, 8302070380

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A Application/construction stage documents & correspondence

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

0 Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

DOCKETED ITEMS

379

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

B Reportable occurrences, IIRs & related correspondence

8302030495 Part 21 rep't re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310207 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50 000, 83/01/31, 8301310207

DOCKET 50-522 SAGIT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8302080294 Generic Ltr 83-04 to all operating reactor licensees, applicants for OLS & holders of CP for C-E PWRS re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50 000, 83/02/08, 8302080294

C Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OLS & holders of CP re regional workshop concerning Suppl 1, NUREG-0747, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50 000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302010584 Notice of appeal & exceptions to ASLB 830118 Memorandum & Order Memorandum & Order fails to recognize Yakima Indian Nation sovereignty & treaty rights are supreme law of land Affidavit of Svc encl
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 83/01/24 Commissioners 6pp 16977 011 24X
Fiche 50 522, 83/01/24, 8302010584

8302030182 New contentions based on new info in GER suppl Certificate of Svc encl
WAPATO, B T Columbia River Inter-Tribal Fish Commission 83/01/31 Atomic Safety and Licensing Board Panel 6pp 17002 034 24X
Fiche 50-522, 83/01/31, 8302030182

8302020263 Memorandum & Order ALAB 712, dismissing Confederated Tribes & Bands of Yakima Indian Nation appeal of ASLB rejection of part or all of four Yakima contentions Appeal unauthorized by Commission Rules of Practice
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/01 Yakima Indian Nation 2pp 16994 114 24X Fiche 50-522, 83/02/01, 8302020263

8302080182 Motion for order suspending health & safety prehearing schedule, pending adoption of final regional power plan & further order of ASLB Suspension would be in best interest of all concerned W/Certificate of Svc
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 83/02/04 Atomic Safety and Licensing Board Panel 15pp 17059 000 24X Fiche 50-522, 83/02/04, 8302080182

8302160302 Motion to suspend health & safety prehearing schedule pending adoption of final regional energy plan or until conclusion of evidentiary hearings on "need for power " Applicant appears ready to absorb facility costs
WAPATO, B T Columbia River Inter-Tribal Fish Commission HOVIS, J B Yakima Indian Nation, HOVIS, J B Hovis, Cockrill, Weaver & Bjur 83/02/10 Atomic Safety and Licensing Board Panel 8pp 17170 083 24X Fiche 50 522, 83/02/10, 8302160302

8302240305 Certifies svc of intervenor motion to suspend safety & health schedule on 830210
LOTHROP, R C Affiliation Unknown 83/02/10 4pp 17273 357 24X
Fiche 50-522, 83/02/10, 8302240305

8302230643 Memorandum & order suspending ASLB 830118 prehearing schedule beginning w/Event 3 Arrangement in util counsel
830209 ltr to be pursued
WOLF, J F Atomic Safety and Licensing Board Panel 83/02/18 3pp 17295 182 24X Fiche 50-522, 83/02/18, 8302230643

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H0BC, H1BC, H2BC & H3BC Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

U Congressional/Executive Correspondence

830220474 Responds to 830110 request for explanation of proposed ACRB technical meeting to discuss project ACRB & NRC required to review pending application
MALSCH, H G Office of the General Counsel 83/01/24 MARKEY, E J House of Rep, Interior & Insular Affairs 1p 17235 362 24X
Fiche 50-522, 83/01/24, 830220474

--830220476 Questions why vital resources of ACRB will be wasted on technical meeting for proposed project in light of financial & planning disaster associated w/const
MARKEY, E J House of Rep, Interior & Insular Affairs 83/01/10 PALLADINO, N Commissioners 1p 17235 363 24X
Fiche 50-522, 83/01/24, 830220474

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NBS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 50-522 SAGIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OLS & holders of CP for C-E PWRS re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D G Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302010585 Notice of appeal & exceptions to ASLB 830118 Memorandum & Order Memorandum & Order fails to recognize Yakima Indian Nation sovereignty & treaty rights which are supreme law of land Affidavit of Svc encl
HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 83/01/26 Commissioners 6pp 16977 011 24X
Fiche 50-522, 83/01/26, 8302010585

8302030182 New contentions based on new info in SER suppl Certificate of Svc encl
WAPATO, S T Columbia River Inter-Tribal Fish Commission 83/01/31 Atomic Safety and Licensing Board Panel 6pp 17002 034 24X
Fiche 50-522, 83/01/31, 8302030182

8302020263 Memorandum & Order ALAB-712, dismissing Confederated Tribes & Bands of Yakima Indian Nation appeal of ASLB rejection of part or all of four Yakima contentions Appeal unauthorized by Commission Rules of Practice
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/01 Yakima Indian Nation 2pp 16994 114 24X Fiche 50-522, 83/02/01, 8302020263

8302080182 Motion for order suspending health & safety prehearing schedule, pending adoption of final regional power plan & further order of ASLB Suspension would be in best interest of all concerned w/Certificate of Svc
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams 83/02/04 Atomic Safety and Licensing Board Panel 15pp 17059 008 24X Fiche 50-522, 83/02/04, 8302080182

8302160302 Motion to suspend health & safety prehearing schedule pending adoption of final regional energy plan or until conclusion of evidentiary hearings on "need for power" Applicant appears ready to absorb facility costs
WAPATO, S T Columbia River Inter-Tribal Fish Commission HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 83/02/10 Atomic Safety and Licensing Board Panel 8pp 17170 083 24X Fiche 50-522, 83/02/10, 8302160302

8302240305 Certifies svc of intervenor motion to suspend safety & health schedule on 830210
LOTHROP, R C Affiliation Unknown 83/02/10 4pp 17273 357 24X
Fiche: 50-522, 83/02/10, 8302240305

8302230643 Memorandum & order suspending ASLB 830118 prehearing schedule beginning w/Event 3 Arrangement in util counsel
830209 Ltr to be pursued
WOLF, J F Atomic Safety and Licensing Board Panel 83/02/18 3pp 17255:182 24X Fiche: 50-522, 83/02/18, 8302230643

a Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche: 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C Gearheads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche: 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347:191 24X Fiche: 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

U Congressional/Executive Correspondence

8302220474 Responds to 830110 request for explanation of proposed ACRS technical meeting to discuss project ACRS & NRC required to review pending application
MALSEN, M G Office of the General Counsel 83/01/24 MARKEY, E J House of Rep, Interior & Insular Affairs 1p 17235 362 24X
Fiche 50-522, 83/01/24, 8302220474

--8302220476 Questions why vital resources of ACRS will be wasted on technical meeting for proposed project in light of financial & planning disaster associated w/const
MARKEY, E J House of Rep, Interior & Insular Affairs 83/01/18 PALLADINO, N Commissioners 1p 17235 363 24X
Fiche 50-522, 83/01/24, 8302220474

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSB vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET 8TH-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302100131 Notification of revised time for 830215-17 meetings w/util & consultants at site & in Phoenix, AZ to conduct seismic qualification review team audit of plants
LICHTHA, E A Licensing Branch 3 83/01/17 KNIGHTON, G W Licensing Branch 3 3pp 17134 317 24X Fiche 50-528, 83/01/17, 8302100131

8302020115 Forwards 820326 request for addl info re rapid depressurization & DHR for CESSAR plant Justification for safe operation of plant, if responses to encl question will not be provided 1 month prior to load, requested
NOVAK, T M Assistant Director for Licensing 83/01/19 VAN BRUNT, E E Arizona Public Service Co 4pp 16998 282 24X
Fiche 50-528, 83/01/19, 8302020115

8302030002 Requests that Amend 10 to FSAR, changing GA Class for pressurizer relief piping from relief valves & control room panels in Tables 3 2-1 be re-evaluated Appropriate rev to FSAR Table 3 2-1 should be submitted
KNIGHTON, G W Licensing Branch 3 83/01/19 VAN BRUNT, E E Arizona Public Service Co 2pp 17028 361 24X
Fiche 50-528, 83/01/19, 8302030002

8302020490 Submits update on organizational arrangement for technical support of operations for plant Organizational structure now meets ERP criteria
NOVAK, T M Assistant Director for Licensing 83/01/24 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 2pp 16996 344 24X Fiche 50-528, 83/01/24, 8302020490

8302100198 Advises that 23 items of equipment identified for which seismic qualification review team will conduct site audit on 830215-17 Completed qualification summary of equipment form should be submitted for each item
KNIGHTON, G W Licensing Branch 3 83/01/25 VAN BRUNT, E E Arizona Public Service Co 4pp 17134 126 24X
Fiche 50-528, 83/01/25, 8302100198

8302010493 Forwards revised description of test, "Total Loss of Flow Trip From 80% Power w/Natural Circulation Verification," for review, to determine if NRC 821117 concerns satisfied
VAN BRUNT, E E Arizona Public Service Co 83/01/27 KNIGHTON, G W Licensing Branch 3 7pp 16981 324 24X Fiche 50-528, 83/01/27, 8302010493

#

DOCKETED ITEMS

8302160483 Forwards notice of finding of no significant antitrust changes & of time for filing requests for re-evaluation & "Palo Verde Nuclear Generating Station Units 1 & 2 Significant Change Analysis" TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 VAN BRUNT, E E Arizona Public Service Co 1p 17175 228 24X Fiche 50-528, 83/02/03, 8302160483

--8302160484 Notice of finding of no significant antitrust changes & of time for filing requests for re-evaluation TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 3pp 17175 229 24X Fiche 50-528, 83/02/03, 8302160483

--8302160489 "Palo Verde Nuclear Generating Station Units 1 & 2 Significant Change Analysis" NICHOLSON, P Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 4pp 17175 232 24X Fiche 50-528, 83/02/03, 8302160483

G Inspection reports, IE Bulletins & correspondence

8302010387 Forwards IE Insp Rept 50-528/82-33 on 821122-1217 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/29 ANDOGNINI, G C Arizona Public Service Co 2pp 16973 264 24X Fiche 50-528, 82/12/29, 8302010387

--8302010390 IE Insp Rept 50-528/82-33 on 821122-1217 No noncompliance noted Major areas inspected facility design changes preoperational test procedure review, piping verification program, facility tours & independent effort FIORELLI, G, JOHNSTON, G, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/12/27 5pp 16973 266 24X Fiche 50-528, 82/12/29, 8302010387

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limiterque H08C, H18C, H28C & H38C Gearheads " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8302230267 Forwards IE Insp Rept 50-528/83-01 on 830104-07 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/01/28 ANDOGNINI, G C Arizona Public Service Co 2pp 17243 357 24X Fiche 50-528, 83/01/28, 8302230267

--8302230268 IE Insp Rept 50-528/83-01 on 830104-07 No noncompliance noted Major areas inspected preoperational test records & operational staff testing & independent insp effort JOHNSON, P H, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 83/01/28 4pp 17243 359 24X Fiche 50-528, 83/01/28, 8302230267

8302230305 Forwards IE Insp Rept 50-528/82-38 on 821220-830121 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/01/31 ANDOGNINI, G C Arizona Public Service Co 2pp 17242 357 24X Fiche 50-528, 83/01/31, 8302230305

--8302230311 IE Insp Rept 50-528/82-28 on 821220-830121 No noncompliance noted Major areas inspected startup testing, containment integrated leak rate test, startup QA/QC, fuel receipt preparations & TMI items II E 1-2 & II E 1-1 FIORELLI, G, JOHNSTON, G, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 83/01/28 6pp 17242 359 24X Fiche 50-528, 83/01/31, 8302230305

r Supply Units "

gineering
dison Co of New
02/18, 8212060363

or Disposing of

gineering
dison Co of New
83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218 EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director App 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

8302070221 Interim deficiency rept re preoperational testing failure of ESF actuation sys dc power supply ground detectors Final rept will be not be submitted until 830325 due to extensive evaluation VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17031 324 24X Fiche 50-528, 83/01/26, 8302070221

8302070254 Interim deficiency rept re Pullman-Kellogg pipe lining failure in essential cooling water sys investigation continuing Final rept will be submitted by 830405 VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17031 337 24X Fiche 50-528, 83/01/26, 8302070254

8302070259 Final Deficiency Rept DER 82-54 re main steam valves w/internal corrosion from outdoor exposure while removed for sys hydrotest Const work plan procedures revised to address mat'l handling & storage VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 17031 351 24X Fiche 50-528, 83/01/26, 8302070259

8302070387 Informs that final submittal for Deficiency Rept DER 82-39 re C-E valve limit switches (Class IE) will not be finalized until 830325 Delay due to extensive investigation & evaluation required VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17035 044 24X Fiche 50-528, 83/01/26, 8302070387

8302150186 Deficiency Rept DER 82-56 re condensate storage tank design scaled-down w/o new calculations for seismic response Initially reported on 821015 Time extension required due to extensive investigation Next rept expected by 830323 VAN BRUNT, E E Arizona Public Service Co 83/01/27 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17147 223 24X Fiche 50-528, 83/01/27, 8302150186

8302150625 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response Initially reported on 821026 Extension from 830210 to 830324 for submittal of final rept requested VAN BRUNT, E E Arizona Public Service Co 83/01/27 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17151 304 24X Fiche 50-528, 83/01/27, 8302150625

8302070483 Final Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially reported on 810529 All accessible embedded fasteners hardness tested & results documented Bechtel conducted followup verification review on 821008 VAN BRUNT, E E Arizona Public Service Co 83/01/28 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 17036 071 24X Fiche 50-528, 83/01/28, 8302070483

--8302070493 Rev 0 to "Engineering Evaluation of Nonconforming ASIM A354 Grade B8 Studs & Bolts," deficiency evaluation rept SHIOBAKA, D R, SCHECHTER, K M, PETERS, R P Bechtel Corp 81-14 R00 82/09/30 173pp 17036 079 24X Fiche 50-528, 83/01/28, 8302070483

8302230425 Interim Deficiency Rept DER 82-85 re failure of Harlin relay, to operate in relay panels during prerequisite testing due to supplier error using dc coils in ac circuits Initially reported on 830107 Final rept will be submitted by 830307 VAN BRUNT, E E Arizona Public Service Co 83/02/07 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 17246 168 24X Fiche 50-528, 83/02/07, 8302230425

8302230533 Interim Deficiency Rept DER 82-84 re Class IE load ctrs internal damage by space heaters Initially reported on 830107 Bechtel corresponding w/IYE-Gould to disposition condition Next rept by 830419 VAN BRUNT, E E Arizona Public Service Co 83/02/07 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 17256 307 24X Fiche 50-528, 83/02/07, 8302230533

DOCKETED ITEMS

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

8302250299 Forwards proposed schedule for operator licensing exam requirements from present through Dec 1985, per Generic Ltr 83 01
ANDRONINI, G C Arizona Public Service Co 83/02/17 EISENHUT, D O
Division of Licensing 2pp 17291 257 24X Fiche 50-528, 83/02/17, 8302250299

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302100131 Notification of revised time for 830215-17 meetings w/util & consultants at site & in Phoenix, AZ to conduct seismic qualification review team audit of plants
LICITRA, E A Licensing Branch 3 83/01/17 KNIGHTON, G W
Licensing Branch 3 3pp 17134 317 24X Fiche 50-528, 83/01/17, 8302100131

8302020115 Forwards 820326 request for addl info re rapid depressurization & DHR for CESSAR plant Justification for safe operation of plant, if responses to encl question will not be provided 1 month prior to load, requested
NOVAK, T M Assistant Director for Licensing 83/01/19 VAN BRUNT, E E Arizona Public Service Co 4pp 16998 282 24X
Fiche 50-528, 83/01/19, 8302020115

8302030002 Requests that Amend 10 to FSAR, changing QA Class for pressurizer relief piping from relief valves & control room panels in Tables 3 2-1 be re-evaluated Appropriate rev to FSAR Table 3 2-1 should be submitted
KNIGHTON, G W Licensing Branch 3 83/01/19 VAN BRUNT, E E Arizona Public Service Co 2pp 17028 361 24X
Fiche 50-528, 83/01/19, 8302030002

8302020490 Submits update on organizational arrangement for technical support of operations for plant Organizational structure now meets SRP criteria
NOVAK, T M Assistant Director for Licensing 83/01/24 FRALEY, R I ACRS - Advisory Committee on Reactor Safeguards 2pp 16996 344 24X Fiche 50-528, 83/01/24, 8302020490

8302100198 Advises that 23 items of equipment identified for which seismic qualification review team will conduct site audit on 830215-17 Completed qualification summary of equipment form should be submitted for each item
KNIGHTON, G W Licensing Branch 3 83/01/25 VAN BRUNT, E E Arizona Public Service Co 4pp 17134 126 24X
Fiche 50-528, 83/01/25, 8302100198

8302010493 Forwards revised description of test, "Total Loss of Flow Trip From 80% Power W/Natural Circulation Verification," for review to determine if NRC 821117 concerns satisfied
VAN BRUNT, E E Arizona Public Service Co 83/01/27 KNIGHTON, G W Licensing Branch 3 7pp 16981 324 24X Fiche 50-528, 83/01/27, 8302010493

8302070523 Forwards info on seismic qualification of equipment supplementing util 830121 submittal info addresses specific items 6, 7 & 8 re resistor input card, indicator 1151 & control element drive mechanism reed switch position
MAURIN, L V Louisiana Power & Light Co 83/02/01 NOVAK, T M Assistant Director for Licensing 11pp 17035 257 24X
Fiche 50-000, 83/02/01, 8302070523

--8302070531 "AZ Nuclear Power Project 150-Inch Reed Switch Position Transmitter & Litton Electrical Connector Seismic Qualification Test (Sine Sweep Testing)" Age considerations for seismic design & surveillance in mild environs encl
HASLINGER, K H Combustion Engineering, Inc TR-ESE-442 81/10/79 99pp 17035 268 24X Fiche 50-000, 83/02/01, 8302070523

8302080210 Advises that rev to FSAR Table 3 2-1 responding to 830119 ltr will be submitted by 830315
VAN BRUNT, E E Arizona Public Service Co 83/02/03 KNIGHTON, G W Licensing Branch 3 1p 17058 055 24X Fiche 50-528, 83/02/03, 8302080210

8302100221 Forwards proposed FSAR changes revising details for new spent fuel storage rack cell blocking device New design blocking device will be placed onto spent fuel racks in same manner as spring type blocking devices
VAN BRUNT, E E Arizona Public Service Co 83/02/03 KNIGHTON, G W Licensing Branch 3 5pp 17114 030 24X Fiche 50-528, 83/02/03, 8302100221

8302170419 Requests info re qualification program for safety-related pumps & valves info should include schedule for completion & confirmation that program complete prior to fuel load
Response will complete PVQRT audit review
KNIGHTON, G W Licensing Branch 3 83/02/03 VAN BRUNT, E E Arizona Public Service Co 4pp 17195 237 24X
Fiche 50-528, 83/02/03, 8302170419

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRS re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302280443 Notifies that completed qualification summary of equipment form for selected equipment items for audit by Seismic Qualification Review Team submitted on 830201 Response to NRC 830125 ltr complete
VAN BRUNT, E E Arizona Public Service Co 83/02/24 KNIGHTON, G W Licensing Branch 3 1p 17309 200 24X Fiche 50-528, 83/02/24, 8302280443

8302280492 Forwards revised responses to NRC Questions 210 1 & 440 3 inter sys LOCA surveillance requirements NRC concerns not applicable to plants Proposed amended FSAR pages provide justification for including operating limits in Tech Specs
VAN BRUNT, E E Arizona Public Service Co 83/02/24 KNIGHTON, G W Licensing Branch 3 16pp 17309 095 24X Fiche 50-528, 83/02/24, 8302280492

E NRC Safety Evaluation Report (SER), supp's & correspondence

8302080362 Forwards "Environ Qualification Rept Per Requirements of NUREG-0888," an response to request for info per NUREG-0857, SER, Section 3 11 Rept supports 830314 qualification program audit
VAN BRUNT, E E Arizona Public Service Co 83/02/07 KNIGHTON, G W Licensing Branch 3 2pp 17051 181 24X Fiche 50-528, 83/02/07, 8302080362

--8302080367 "Environ Qualification Rept Per Requirements of NUREG-0857" * Arizona Public Service Co 83/02/07 594pp 17051 183 24X
Fiche 50-528, 83/02/07, 8302080362

8302230326 Forwards "ESF Load Sequencer Software Verification & Validation Rept," as required by SER Section 8 4 & (NUREG-0857)
VAN BRUNT, E E Arizona Public Service Co 83/02/15 KNIGHTON, G W Licensing Branch 3 3pp 17248 163 24X Fiche 50-528, 83/02/15, 8302230326

--8302230328 "ESF Load Sequencer Software Verification & Validation Rept" * Simpac Associates, Inc 82/09/09 103pp 17248 166 24X
Fiche 50-528, 83/02/15, 8302230326

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302170494 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/02/15 Document Management Branch 1p 17201 251 24X Fiche 50-528, 83/02/15, 8302170494

--8302170498 Forwards public version of Rev 1 to Emergency Plan implementing Procedure EPIP-14B re dose assessment Receipt form encl
* Arizona Public Service Co 83/01/28 NRC - No Detailed Affiliation Given 1p 17201 252 24X Fiche 50-528, 83/02/15, 8302170494

DOCKETED ITEMS

--8302170903 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-148 re dose assessment Revised index encl
LUCIA, S Arizona Public Service Co 82/12/30 582pp 17201 25J
24X Fiche 50-528,83/02/15,8302170494

G Adjudicatory correspondence

8302070595 Motion for ruling on Contentions I,II,IV(A),IV(C),V & VI re salt deposition,for declaration that NEPA analysis inadequate & for continuance of proceeding Certificate of Svc encl
BERLIN, K West Valley Agricultural Protection Council, Inc 83/02/02 Atomic Safety and Licensing Board Panel 32pp
17035 170 24X Fiche 50-529,83/02/02,8302070595

8302170267 Notice of change of address of counsel Certificate of Svc encl
BERNABEI, L Hourihan, P BERNABEI, L Government Accountability Project 83/02/14 3pp 17178 221 24X Fiche 50-528,83/02/14, 8302170267

8302180394 Answer opposing West Valley Agricultural Protection Council, Inc motion for ruling on contentions,for declaration that NEPA analysis inadequate & for continuance of proceeding No basis/need to admit contentions shown W/Certificate of Svc
BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A Snell & Wilmer 83/02/14 Atomic Safety and Licensing Board Panel 36pp
17210-185 24X Fiche 50-528,83/02/14,8302180394

8302160355 Decision ALAB-713,affirming ASLB 821230 Initial Decision LBP-82-117A re availability of adequate supply of condenser cooling water
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/15 4pp 17164 285 24X Fiche 50-528,83/02/15,8302160355

8302180279 Response opposing West Valley Agricultural Protection Council, Inc 830202 motion for ruling on contentions,for declaration that NEPA analysis inadequate & for continuance of proceeding Certificate of Svc encl
DEWEY, L S Hearing Branch 3 83/02/17 Atomic Safety and Licensing Board Panel 12pp 17211 265 24X Fiche 50-529,83/02/17, 8302180279

8302230350 Reaffirms West Valley Agricultural Protection Council intent to discuss outstanding issues from petition to intervene & need for continuance of DL proceedings Certificate of Svc encl
BERLIN, K Berlack, Israel & Liberman BERLIN, K West Valley Agricultural Protection Council, Inc 83/02/17 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 4pp 17247 354 24X Fiche 50-528,83/02/17,8302230350

H Antitrust correspondence

8302080079 Forwards for publication in FR,notice of finding of no significant antitrust changes & time for filing of request for re-evaluation
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 COMBS, T Docketing & Services Branch 2pp
17106 143 24X Fiche 50-528,83/02/03,8302080079

--8302080083 Notice of finding of no significant antitrust changes & time for filing of requests for re-evaluation
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 83/01/28 3pp 17106 147 24X Fiche 50-528,83/02/03, 8302080079

8302160483 Forwards notice of finding of no significant antitrust changes & of time for filing requests for re-evaluation & "Palo Verde Nuclear Generating Station Units 1 & 2 Significant Change Analysis"
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 VAN BRUNT, E E Arizona Public Service Co 1p
17175 228 24X Fiche 50-528,83/02/03,8302160483

--8302160484 Notice of finding of no significant antitrust changes & of time for filing requests for re-evaluation
TOALSTON, A L Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 3pp 17175 227 24X Fiche 50-528,83/02/03, 8302160483

--8302160488 "Palo Verde Nuclear Generating Station Units 1 & 2 Significant Change Analysis"
NICHOLSON, P. Antitrust & Economic analysis Branch (Utility Finance) 83/02/03 4pp 17175 232 24X Fiche 50-528,83/02/03, 8302160483

I Inspection reports, IE Bulletins / correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000,83/01/26,8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C,H18C,H28C & H38C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

J Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp,high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000,82/12/17,8302030495

8302070221 Interim deficiency rept re preoperational testing failure of ESF actuation sys dc power supply ground detectors Final rept will be not be submitted until 830325 due to extensive evaluation
VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident,Reactor Project & Engineering Programs 2pp
17031 324 24X Fiche 50-528,83/01/26,8302070221

8302070249 Final Deficiency Rept DER 82-71 re Henry Pratt motor operated butterfly valves loose bolt holding yoke to valve body in containment purge sys Yoke will be retorqued
Situation determined not reportable per 10CFR50 55(a)
VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident,Reactor Project & Engineering Programs 4pp
17031 326 24X Fiche 50-529,83/01/26,8302070249

8302070387 Informs that final submittal for Deficiency Rept DER 82-39 re C-E valve limit switches (Class IE) will not be finalized until 830325 Delay due to extensive investigation & evaluation required
VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D M Division of Resident,Reactor Project & Engineering Programs 2pp
17035 044 24X Fiche 50-528,83/01/26,8302070387

8302150186 Deficiency Rept DER 82-56 re condensate storage tank design scaled-down w/o new calculations for seismic response
Initially reported on 821015 Time extension required due to extensive investigation Next rept expected by 830323
VAN BRUNT, E E Arizona Public Service Co 83/01/27 STERNBERG, D M Division of Resident,Reactor Project & Engineering Programs 2pp
17147 223 24X Fiche 50-528,83/01/27,8302150186

8302150625 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response Initially reported on 821026 Extension from 830210 to 830324 for submittal of final rept requested
VAN BRUNT, E E Arizona Public Service Co 83/01/27 STERNBERG, D M Division of Resident,Reactor Project & Engineering Programs 2pp
17151 304 24X Fiche 50-528,83/01/27,8302150625

DOCKETED ITEMS

38

830207048J Final Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially reported on 810529 All accessible embedded fasteners hardness tested & results documented Bechtel conducted followup verification review on 821008 VAN BRUNT, E E Arizona Public Service Co 83/01/28 STERNBERG, D M Division or Resident, Reactor Project & Engineering Programs Bpp 17036 071 24X Fiche 50-528, 83/01/28, 830207048J

830223036I Final Deficiency Rept DER 82-43 re Comsip main control panels w/improperly crimped termination lugs Initially reported on 820813 Connectors not meeting visual criteria will be repaired Also reported per Part 21 VAN BRUNT, E E Arizona Public Service Co 83/02/07 STERNBERG, D M Division or Resident, Reactor Project & Engineering Programs 3pp 17248 092 24X Fiche 50-528, 83/02/07, 830223036I

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl EISENHUT, D G Division or Licensing 83/01/31 Consolidated Edison Co or New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302250299 Forwards proposed schedule for operator licensing exam requirements from present through Dec 1985, per Generic Ltr 83 01 ANDOGNINI, G C Arizona Public Service Co 83/02/17 EISENHUT, D G Division of Licensing 2pp 17291 257 24X Fiche 50-528, 83/02/17, 8302250299

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

830210013I Notification of revised time for 830215-17 meetings w/util & consultants at site & in Phoenix, AZ to conduct seismic qualification review team audit of plants LICITRA, E A Licensing Branch 3 83/01/17 KNIGHTON, O W Licensing Branch 3 3pp 17134 317 24X Fiche 50-528, 83/01/17, 830210013I

8302020115 Forwards 820326 request for addl info re rapid depressurization & DHR for CESSAR plant Justification for safe operation of plant, i.e. responses to encl question will not be provided 1 month prior to load, requested NOVAK, T M Assistant Director for Licensing 83/01/19 VAN BRUNT, E E Arizona Public Service Co 4pp 16998 282 24X Fiche 50-528, 83/01/19, 8302020115

8302030002 Requests that Amend 10 to FSAR, changing QA Class for pressurizer relief piping from relief valves & control room panels in Tables 3 2-1 be re-evaluated Appropriate rev to FSAR Table 3 2-1 should be submitted KNIGHTON, O W Licensing Branch 3 83/01/19 VAN BRUNT, E E Arizona Public Service Co 2pp 17028 361 24X Fiche 50-528, 83/01/19, 8302030002

8302020490 Submits update on organizational arrangement for technical support of operations for plant Organizational structure now meets SRP criteria NOVAK, T M Assistant Director for Licensing 83/01/24 FRALEY, R I ACRS - Advisory Committee on Reactor Safeguards 2pp 16996 344 24X Fiche 50-528, 83/01/24, 8302020490

830210019B Advises that 23 items of equipment identified for which seismic qualification review team will conduct site audit on 830215-17 Completed qualification summary of equipment form should be submitted for each item KNIGHTON, O W Licensing Branch 3 83/01/25 VAN BRUNT, E E Arizona Public Service Co 4pp 17134 126 24X Fiche 50-528, 83/01/25, 830210019B

8302010493 Forwards revised description of test, "Total Loss of Flow Trip From 80% Power W/Natural Circulation Verification," for review, to determine if NRC 82117 concerns satisfied VAN BRUNT, E E Arizona Public Service Co 83/01/27 KNIGHTON, O W Licensing Branch 3 7pp 16981 324 24X Fiche 50-528, 83/01/27, 8302010493

8302070523 Forwards info on seismic qualification of equipment supplementing util 830121 submittal Info addresses specific items 6, 7 & 8 re resistor input card, Indicator 1151 & control element drive mechanism reed switch position MAURIN, L V Louisiana Power & Light Co 83/02/01 NOVAK, T M Assistant Director for Licensing 11pp 17035 297 24X Fiche 50-000, 83/02/01, 8302070523

--830207053I 'AZ Nuclear Power Project 150-Inch Reed Switch Position Transmitter & Litton Electrical Connector Seismic Qualification Test (Sine Sweep Testing)' Age considerations for seismic design & surveillance in mild environs encl HASLINGER, K H Combustion Engineering, Inc TR-E8E-442 81/10/97 App 17036 001 24X Fiche 50-000, 83/02/01, 8302070523

8302080210 Advises that rev to FSAR Table 3 2-1 responding to 830119 ltr will be submitted by 830315 VAN BRUNT, E E Arizona Public Service Co 83/02/03 KNIGHTON, O W Licensing Branch 3 1p 17058 055 24X Fiche 50-528, 83/02/03, 8302080210

8302100221 Forwards proposed FSAR changes revising details for new spent fuel storage rack cell blocking device New design blocking device will be placed onto spent fuel racks in same manner as spring type blocking devices VAN BRUNT, E E Arizona Public Service Co 83/02/03 KNIGHTON, O W Licensing Branch 3 3pp 17114 030 24X Fiche 50-528, 83/02/03, 8302100221

8302170419 Requests info re qualification program for safety-related pumps & valves Info should include schedule for completion & confirmation that program complete prior to fuel load Response will complete PVORT audit review KNIGHTON, O W Licensing Branch 3 83/02/03 VAN BRUNT, E E Arizona Public Service Co 4pp 17195 237 24X Fiche 50-528, 83/02/03, 8302170419

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl EISENHUT, D G Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302280443 Notifies that completed qualification summary of equipment form for selected equipment items for audit by Seismic Qualification Review Team submitted on 830201 Response to NRC 830125 ltr complete VAN BRUNT, E E Arizona Public Service Co 83/02/24 KNIGHTON, O W Licensing Branch 3 1p 17309 200 24X Fiche 50-528, 83/02/24, 8302280443

8302280492 Forwards revised responses to NRC Questions 210 I & 440 3 re inter sys LQSA surveillance requirements NRC concerns not applicable to plants Proposed amended FSAR pages provide justification for including operating limits in Tech Specs VAN BRUNT, E E Arizona Public Service Co 83/02/24 KNIGHTON, O W Licensing Branch 3 16pp 17309 095 24X Fiche 50-528, 83/02/24, 8302280492

E NRC Safety Evaluation Report (SER), supplis & correspondence

8302080362 Forwards "Environ Qualification Rept Per Requirements of NUREG-0588," in response to request for info per NUREG-0857, SER, Section 3 11 Rept supports 830314 qualification program audit VAN BRUNT, E E Arizona Public Service Co 83/02/07 KNIGHTON, O W Licensing Branch 3 2pp 17051 181 24X Fiche 50-528, 83/02/07, 8302080362

--8302080367 "Environ Qualification Rept Per Requirements of NUREG-0588" * Arizona Public Service Co 83/02/07 594pp 17051 183 24X Fiche 50-528, 83/02/07, 8302080362

8302230326 Forwards "ESF Load Sequencer Software Verification & Validation Rept," as required by SER Section 8 4 & (NUREG-0857), VAN BRUNT, E E Arizona Public Service Co 83/02/15 KNIGHTON, O W Licensing Branch 3 3pp 17248 163 24X Fiche 50-528, 83/02/15, 8302230326

--8302230328 "ESF Load Sequencer Software Verification & Validation Rept" * Impact Associates, Inc 82/09/09 103pp 17248 166 24X Fiche 50-528, 83/02/15, 8302230326

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl EISENHUT, D G Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

DOCKETED ITEMS

8302170494 Releases public version of revised emergency plan implementing procedure
FELTM, J M Division of Rules and Records 83/02/15 Document
Management Branch 1p 17201 251 24X Fiche 50-528, 83/02/15, 8302170494

--8302170498 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B re dose assessment Receipt form encl
* Arizona Public Service Co 83/01/28 NRC - No Detailed Affiliation Given 1p 17201 252 24X Fiche 50-528, 83/02/15, 8302170494

--8302170503 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B re dose assessment Revised index encl
LUCIA, S Arizona Public Service Co 82/12/30 582pp 17201 253 24X Fiche 50-528, 83/02/15, 8302170494

0 Adjudicatory correspondence

8302070595 Motion for ruling on Contentions I, II, IV(A), IV(C), V & VI re salt deposition, for declaration that NEPA analysis inadequate & for continuance of proceeding Certificate of Svc encl
BERLIN, K West Valley Agricultural Protection Council, Inc 83/02/02 Atomic Safety and Licensing Board Panel 32pp 17035 170 24X Fiche 50-528, 83/02/02, 8302070595

8302170267 Notice of change of address of counsel Certificate of Svc encl
BERNABEI, L Maurihan, P BERNABEI, L Government Accountability Project 83/02/14 3pp 17178 221 24X Fiche 50-528, 83/02/14, 8302170267

8302180394 Answer opposing West Valley Agricultural Protection Council, Inc motion for ruling on contentions, for declaration that NEPA analysis inadequate & for continuance of proceeding No basis/need to admit contentions shown W/Certificate of Svc
BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A Snell & Wilner 83/02/14 Atomic Safety and Licensing Board Panel 36pp 17210 185 24X Fiche 50-528, 83/02/14, 8302180394

8302160355 Decision ALAB-713, affirming ASLB 821230 Initial Decision LDP-82-117A re availability of adequate supply of condenser cooling water
SHOMAKER, C J Atomic Safety and Licensing Appeal Panel 83/02/15 4pp 17144 265 24X Fiche 50-528, 83/02/15, 8302160355

8302180279 Response opposing West Valley Agricultural Protection Council, Inc 830202 motion for ruling on contentions, for declaration that NEPA analysis inadequate & for continuance of proceeding Certificate of Svc encl
DEWEY, L S Hearing Branch 3 83/02/17 Atomic Safety and Licensing Board Panel 12pp 17211 265 24X Fiche 50-528, 83/02/17, 8302180279

8302230350 Reaffirms West Valley Agricultural Protection Council intent to discuss outstanding issues from petition to intervene & need for continuance of OL proceedings Certificate of Svc encl
BERLIN, K Berlack, Israel & Liberman BERLIN, K West Valley Agricultural Protection Council, Inc 83/02/17 LAZO, R M, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 4pp 17247 354 24X Fiche 50-528, 83/02/17, 8302230350

Q Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H30C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

S Reportable occurrences, IFRs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

8302070221 Interim deficiency rept re preoperational testing failure of ESF actuation sys dc power supply ground detectors Final rept will be not be submitted until 830325 due to extensive evaluation
VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D II Division of Resident, Reactor Project & Engineering Programs 2pp 17031 324 24X Fiche 50-528, 83/01/26, 8302070221

8302070297 Informs that final submittal for Deficiency Rept DER 82-37 re C-E valve limit switches (Class IE) will not be finalized until 830325 Delay due to extensive investigation & evaluation required
VAN BRUNT, E E Arizona Public Service Co 83/01/26 STERNBERG, D II Division of Resident, Reactor Project & Engineering Programs 2pp 17035 044 24X Fiche 50-528, 83/01/26, 8302070297

8302150186 Deficiency Rept DER 82-56 re condensate storage tank design scaled-down w/o new calculations for seismic response Initially reported on 821015 Time extension required due to extensive investigation Next rept expected by 830323
VAN BRUNT, E E Arizona Public Service Co 83/01/27 STERNBERG, D II Division of Resident, Reactor Project & Engineering Programs 2pp 17147 223 24X Fiche 50-528, 83/01/27, 8302150186

8302150625 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response Initially reported on 821026 Extension from 830210 to 830324 for submittal of final rept requested
VAN BRUNT, E E Arizona Public Service Co 83/01/27 STERNBERG, D II Division of Resident, Reactor Project & Engineering Programs 2pp 17151 304 24X Fiche 50-528, 83/01/27, 8302150625

8302070483 Final Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially reported on 810527 All accessible embedded fasteners hardness tested & results documented Hechtel conducted followup verification review on 821008
VAN BRUNT, E E Arizona Public Service Co 83/01/28 STERNBERG, D II Division of Resident, Reactor Project & Engineering Programs 8pp 17036 071 24X Fiche 50-528, 83/01/28, 8302070483

--8302070493 Rev 0 to "Engineering Evaluation of Nonconforming ASTM A194 Grade 30 Studs & Bolts," deficiency evaluation rept
SHOBAKA, D R, SCHECHTER, K M, PETERS, R P Bechtel Corp 81-14 R00 82/09/30 173pp 17036 079 24X Fiche 50-528, 83/01/28, 8302070483

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301310203

8302250299 Forwards proposed schedule for operator licensing exam requirements from present through Dec 1985, per Generic Ltr 83-01
ANDONINI, G C Arizona Public Service Co 83/02/17 EISENHUT, D G Division of Licensing 2pp 17291 257 24X Fiche 50-528, 83/02/17, 8302250299

DOCKETED ITEMS

38

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

B302010437 Forwards "Thermal Margin Beyond Design Base (TMDBB) Sodium-Concrete Penetration Margins Assessment for CRBR Plant," for review

LONGENECKER, J. Energy Dept of, Clinch River Breeder Reactor Plant
82/10/20 CHECK, P S Clinch River Breeder Reactor Program Office
1p 16981 079 24x Fiche 50-537, 82/10/20, B302010437

--B302010439 "Thermal Margin Beyond Design Base (TMDBB) Sodium-Concrete Penetration Margins Assessment for CRBR Plant"
BALL, T W, CROSS, J F, KOSKURBA, D P Energy, Dept of, Clinch River Breeder Reactor Plant 82/08/31 55pp 16981 080 24x
Fiche 50-537, 82/10/20, B302010437

B302040123 FOIA request for documents sent w/wood blocks from site
WEISS, E R Harmon & Weiss 82/10/29 FELTON, J Division of Rules and Records 1p 17042 753 24x Fiche 50-537, 82/10/29, B302040123

B302010124 Notification of contract execution, Mod 2 to "Casework-CRRR" Contractor SBA Subcontractor Engineering & Economics Research, Inc
FLEENOR, C Technical Assistance Contracts Branch FIN B-8601
82/12/21 CHECK, P S Clinch River Breeder Reactor Program Office
MORRIS, B NRC - No Detailed Affiliation Given 1p 16989 357 24x
Fiche 50-537, 82/12/21, B302010124

--B302010133 Mod 2, providing incremental funding in support of Task Order 3, to "Casework-CRRR"
BERGDOHL, T E Small Business Administration OUPA, J N Engineering & Economics Research, Inc OUSTAVE, R P Division of Contracts FIN B-8601 82/12/21 3pp 16989 358 24x
Fiche 50-537, 82/12/21, B302010124

B302040129 Responds to FOIA request for documents sent w/wood blocks from site Notes to Commissioner Ahearne not located Ahearne under impression that notes not agency records Forwards documents listed in app Documents also available in PDR
FELTON, J Division of Rules and Records 82/12/27 WEISS, E R Harmon & Weiss 2pp 17042 354 24x Fiche 50-537, 82/12/27, B302040129

--B302040133 Forwards copy of wood sections from first tree cut at site
BREWINGTON, P Energy, Dept of 82/09/21 PALLADINO, N, OILINSKY, V, ROBERTS, T Commissioners 8pp 17042 356 24x
Fiche 50-537, 82/12/27, B302040129

B302070592 Forwards "Comparison of CRBR DBA W/Those for LWRs & Liquid-Metal-Coated Fast Reactors"
SAFFEL, B F EG&G, Inc FIN A-6472 83/01/10 SOLECKI, J E Energy, Dept of, Idaho Operations Office 1p 17035 074 24x
Fiche 50-537, 83/01/10, B302070592

--B302070598 "Comparison of CRBR DBA W/Those for LWRs & Liquid-Metal-Coated Fast Reactors," interim report
HAWESON, E EG&G, Inc FIN A-6472 EG&G-NTAP-6152 DRFT
83/01/31 ALLEN, C A Office of Nuclear Reactor Regulation, Director 89pp 17035 075 24x Fiche 50-537, 83/01/10, B302070592

B302240222 Final response to FOIA request for three categories of documents re CRBR from Jan 1981 to present Forwards agenda for B30216 discussion meeting Document also available in PDR
FELTON, J M Division of Rules and Records 83/01/20 WEISS, E R Harmon & Weiss 2pp 17287 340 24x Fiche 50-537, 83/01/20, B302240222

--B302240230 Agenda for B30216 meeting w/DOE in Washington, DC to discuss DOE reorganization nuclear licensing regulation, nuclear waste legislation, NRC/DOE safety relationships, NRC safety goal, LDP & CRBR program / Meese & Wilson ltrs
* NRC - No Detailed Affiliation Given 82/02/16 NRC - No Detailed Affiliation Given 1p 17287 361 24x
Fiche 50-537, 83/01/20, B302240222

B302030220 Notification of B30209 meeting w/applicants & DOE in Bethesda, MD to discuss PRA Phase II
STARK, R M Clinch River Breeder Reactor Program Office 83/01/28
GRACE, J N Clinch River Breeder Reactor Program Office 3pp
17013 355 24x Fiche 50-537, 83/01/28, B302030220

B302070417 Forwards addl info re ex-vessel storage tank cooling
Appropriate info on encl charts re structural temp limitations, decay power level & alternate heat removal paths will be included in Section 9.1 of future PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/02 GRACE, J N Clinch River Breeder Reactor Program Office
11pp 17029 241 24x Fiche 50-537, 83/02/02, B302070417

B302070420 Forwards two pages inadvertently omitted from B21214 transmittal or addl info re control & protection sys interaction Revised PSAR pages will be incorporated in future PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/02 GRACE, J N Clinch River Breeder Reactor Program Office
3pp 17029 303 24x Fiche 50-537, 83/02/02, B302070420

B302080001 Responds to NRC B21227 issuance of principal design criteria info will be incorporated into PSAR in Feb 1983
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/02 GRACE, J N Clinch River Breeder Reactor Program Office
1p 17058 318 24x Fiche 50-537, 83/02/02, B302080001

B302100183 Notification of B30209 meeting w/DOE, TVA & Project Mgt Corp in Bethesda, MD to review open items
STARK, R M Clinch River Breeder Reactor Program Office 83/02/03
GRACE, J N Clinch River Breeder Reactor Program Office 3pp
17134 183 24x Fiche 50-537, 83/02/03, B302100183

B302160105 Notification of contract execution "CRBR Subcommittee & Associated Working Group," awarded to SI Abdel-Khalik
LITTLE, M Administrative Contracts Branch FIN B-1557 83/02/03
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards
BOEHMERT, P NRC - No Detailed Affiliation Given 1p 17160 257
24x Fiche 50-537, 83/02/03, B302160105

--B302160110 Contract "CRBR Subcommittee & Associated Working Group," awarded to SI Abdel-Khalik
ABDEL-KHALIK, S Abdel-Khalik, S J REDELLO, J E Division of Contracts FIN B-1557 83/02/03 4pp 17160 258 24x
Fiche 50-537, 83/02/03, B302160105

B302070440 Forwards requested info re fuel, blanket & removable radial shield assembly precautions to preclude assembly blockages
Info will be included in next PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/04 GRACE, J N Clinch River Breeder Reactor Program Office
3pp 17029 278 24x Fiche 50-537, 83/02/04, B302070440

B302070451 Forwards addl info re sodium spills analyzed in PSAR Chapters 6 & 15 Info will be added to future PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/04 GRACE, J N Clinch River Breeder Reactor Program Office
13pp 17036 259 24x Fiche 50-537, 83/02/04, B302070451

B302070477 Forwards amended PSAR P 5.5-12, providing addl info re mitigation or water hammer in steam generator sys Page will be incorporated in next PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/04 GRACE, J N Clinch River Breeder Reactor Program Office
2pp 17036 062 24x Fiche 50-537, 83/02/04, B302070477

B302070245 Notification of contract execution, Mod 4 to "Technical Assistance in Support of NRC License Review of CRBR Plant by Analyzing Reactor Shutdown Sys" Contractor NUS Corp
SILVIS, R M Technical Assistance Contracts Branch FIN B-1116-7
83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director
SINISGALLI, A NRC - No Detailed Affiliation Given 1p 17117 361 24x Fiche 50-537, 83/02/04, B302070245

--B302070254 Mod 4, deobligating funds, to "Technical Assistance in Support of NRC License Review of CRBR Plant by Analyzing Reactor Shutdown Sys"
EHMUNDSON, L R NUS Corp OUSTAVE, R P Division of Contracts FIN B-1116-7 83/02/04 1p 17117 362 24x Fiche 50-537, 83/02/04, B302070245

B302090326 Forwards new & revised responses re NRC structural - seismic audit findings on cell linear analysis discussed at B21221 open items meeting
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/04 GRACE, J N Clinch River Breeder Reactor Program Office
30pp 17070 282 24x Fiche 50-537, 83/02/04, B302090326

B302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PNRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D G Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24x
Fiche 50-000, 83/02/08, B302080295

B302090325 Application for amend to application for CP consisting of Amend 79 to PSAR Amend includes rev to Section 1.4, "Identification of Project Participants" & Section 5.0, "Heat Transport & Connected Sys"
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/08 CHECK, P S Clinch River Breeder Reactor Program Office
4pp 17068 001 24x Fiche 50-537, 83/02/08, B302090325

DOCKETED ITEMS

0302150343 Documents agreements reached at 830209 meeting Confirmatory program action plans listed Low temp design info will be forwarded under separate cover
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/10 GRACE, J N Clinch River Breeder Reactor Program Office
2pp 17157 228 24X Fiche 50-537, 83/02/10, 8302150343

0302150457 Forwards amended PSAR Chapter 4 & 5 re gas entrainment in primary heat transport sys Info will be included in next PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/11 GRACE, J N Clinch River Breeder Reactor Program Office
11pp 17158 136 24X Fiche 50-537, 83/02/11, 8302150457

0302150576 Forwards amended PSAR Pp 5 6-8 & 13, clarifying auxiliary feedwater sys valve description Pages will be included in next amend to PSAR
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/14 GRACE, J N Clinch River Breeder Reactor Program Office
3pp 17156 127 24X Fiche 50-537, 83/02/14, 8302150576

0302150588 Forwards marked-up PSAR page providing addl info on nitrogen gas svcs Info will be incorporated into Chapter 9 of PSAR in future amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/14 GRACE, J N Clinch River Breeder Reactor Program Office
2pp 17156 111 24X Fiche 50-537, 83/02/14, 8302150588

0302150601 Responds to Siting Analysis Branch request for addl info re PSAR concerning potential highway accidents w/ resulting toxic plumes that could impact facility Info will be included in future amend of Chapter 2 2 of PSAR
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/14 GRACE, J N Clinch River Breeder Reactor Program Office
4pp 17155 360 24X Fiche 50-537, 83/02/14, 8302150601

0302230347 Forwards "Sodium Slug Energy Absorption Capability of Modified CRBR Closure Head," Westinghouse CRBR engineering study rept
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/14 GRACE, J N Clinch River Breeder Reactor Program Office
2pp 17248 002 24X Fiche 50-537, 83/02/14, 8302230347

-8302230351 "Sodium Slug Energy Absorption Capability of Modified CRBR Closure Head," Westinghouse CRBR engineering study rept
PENNEL, W E, DEWALD, W W Westinghouse Electric Corp
ES-LRD-83-3029 83/02/10 6pp 17248 004 24X
Fiche 50-537, 83/02/14, 8302230347

0302160153 Forwards addl info on CRBR instrumentation & controls discussed in 830201 telcon w/NRC 2 revised responses to NRC Questions CS421 15, 19 & 46 Revised pages will be included in next PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/15 GRACE, J N Clinch River Breeder Reactor Program Office
45pp 17162 221 24X Fiche 50-537, 83/02/15, 8302160153

0302160170 Forwards revised PSAR Section 3 1, incorporating final principal design criteria Info will be included in next PSAR rev
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/15 GRACE, J N Clinch River Breeder Reactor Program Office
83pp 17162 094 24X Fiche 50-537, 83/02/15, 8302160170

0302170180 Forwards revised response to Mechanical Engineering Branch Question 26 & amended PSAR Section 3 9 (Question 70) re low temp components, providing addl info requested at 830209 meeting
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/15 GRACE, J N Clinch River Breeder Reactor Program Office
11pp 17163, 064 24X Fiche 50-537, 83/02/15, 8302170180

0302250290 Forwards amended PSAR Page 10 4-7 re consequences of flooding due to failures in circulating water sys Pages respond to MRC questions & will be included in next PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/23 GRACE, J N Clinch River Breeder Reactor Program Office
3pp 17291 291 24X Fiche 50-537, 83/02/23, 8302250290

0302250292 Forwards edited PSAR pages re secondary control rod sys capability Info will be included in future PSAR amend
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/23 GRACE, J N Clinch River Breeder Reactor Program Office
8pp 17291 279 24X Fiche 50-537, 83/02/23, 8302250292

0302250314 Forwards revised responses to Mechanical Engineering Branch Items 26 & 70 re low temp components Info to be included in next amend to PSAR,
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/24 GRACE, J N Clinch River Breeder Reactor Program Office
0pp 17291 017 24X Fiche 50-537, 83/02/24, 8302250314

B Utility Preliminary Safety Analysis Report, amends

8302090325 Application for amend to application for CP consisting of Amend 75 to PSAR Amend includes rev to Section 1 4, "Identification of Project Participants" & Section 5 0, "Heat Transport & Connected Sys"
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/08 CHFCV, P S Clinch River Breeder Reactor Program Office
4pp 17068 001 24X Fiche 50-537 83/02/08, 8302090325

--8302070334 Amend 75 to PSAR
* Tennessee Valley Authority 83/02/28 635pp 17068 009 24X
Fiche 50-537 83/02/08, 8302090325

8302180324 Forwards corrected pages to page replacement guide of Amend 75 to PSAR
RANOD, J Burns & Roe Co 83/02/10 SHUTTLEWORTH, P Clinch River Breeder Reactor Program Office 1p 17213 342 24X
Fiche 50-537, 83/02, 10, 8302180324

--8302180333 Corrected pages to page replacement guide of Amend 75 to PSAR
* Tennessee Valley Authority 83/02/28 2pp 17213 343 24X
Fiche 50-537, 83/02/10, 8302180324

8302230201 Forwards affidavit confirming distribution of Amend 75 to PSAR to designated local public officials & govt agency representatives
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
83/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17245 113 24X Fiche 50 537, 83/02/17, 8302230201

F Security, medical, emergency & fire protection plans

8302120340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for PL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHAUT, D G Division of licensing 83/02/01 Consolidated
Editor Co or New York, Inc 1pp 17221 226 24X
Fiche 50-000, 83/02/01, 8302120340

G Adjudicatory correspondence

8302070155 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
JONES, B W Region 2, Office of Director 83/02/01 3pp
17032 341 24X Fiche 50 537, 83/02/01, 8302070155

8302240013 Notice of SE Turk appearance in & DT Swanson withdrawal from proceeding Certificate of Svc encl
TURK, S F, EVANSON, D T Hearing Branch 1 83/02/22 4pp
17272 359 24X Fiche 50-537, 83/02/22, 8302240013

H Advisory Committee on Reactor Safeguards reports & correspondence

8302080465 Summary of ACRS CRBR Working Group on Sys Integration & Instrumentation Control 826920 meeting in Washington, DC re proposed configuration of plant protection & instrument control sys
* ACRS - Advisory Committee on Reactor Safeguards 82/09/17
ACRS - Advisory Committee on Reactor Safeguards 31pp 17072 036
24X Fiche 50-537, 82/09/17, 8302080465

8302080461 Summary of ACRS CRBR Working Group 821026 meeting in Washington, DC re review of thermal hydraulic aspects of plant design
* ACRS - Advisory Committee on Reactor Safeguards 82/10/28
ACRS - Advisory Committee on Reactor Safeguards 6pp 17108 071
24X Fiche 50-537, 82/10/28, 8302080461

8302080102 Summary of ACRS CRBR Subcommittee 821119 meeting w/NDE in Washington, DC re review of hypothetical core disruptive accident energetics issue
* ACRS - Advisory Committee on Reactor Safeguards 82/12/06
ACRS - Advisory Committee on Reactor Safeguards 34pp 17106 016
24X Fiche 50-537, 82/12/06, 8302080102

I Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

DOCKETED ITEMS

8212060360 IE Info Notice 83-02, "Limitorque H08C,H18C,H28C & H38C Gearheads Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 109pp 17144 001 24X Fiche 50-000,83/01/28,8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New York, Inc 110pp 17074 095 24X Fiche 50-000,83/01/28,8212060361

8302100315 Submits inservice insp commitments to be included in future FSAR amend,per NRC request Prior to sodium fill,complete ultrasonic exam will be conducted on all large diameter pipe welds
LOISENECKER,J Energy,Dept of, Clinch River Breeder Reactor Plant 83/01/28 CRACE,J N Clinch River Breeder Reactor Program Office 1p 17116 378 24X Fiche 50-537,83/01/28,8302100315

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New York, Inc 110pp 17347 191 24X Fiche 50-000,83/02/18,8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 111pp 17347 098 24X Fiche 50-000,83/02/24,8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New York, Inc 112pp 17361 148 24X Fiche 50-000,83/02/24,8212060366

T Hearing transcripts on non-antitrust matters

8302020250 Order correcting transcripts
MILLER,M E Atomic Safety and Licensing Board Panel 83/01/31 31pp 16994 294 24X Fiche 50-537,83/01/31,8302020250

8302030190 Applicant corrections to 821116-19 transcripts, inadvertently omitted from 830124 list of transcript corrections
Certificate of Svc encl
EDGAR,G L Project Management Corp 83/02/02 9pp 17002 094 24X Fiche 50-537,83/02/02,8302030190

8302070059 Transcript of ACRS Subcommittee on CRBR & Thermal Hydraulics Working Group 830203 joint meeting in Washington,DC re plant thermal hydraulic design issues & emergency power sys
Pp 1-313 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/03 462pp 17032 359 24X Fiche 50-537,83/02/03,8302070059

8302080184 Transcript of ACRS CRBR Subcommittee & Thermal Hydraulics Working Group 830204 joint meeting in Washington,DC
Pp 344-646 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/04 517pp 17054 203 24X Fiche 50-537 83/02/04,8302080184

8302280100 Transcript of ACRS Subcommittee on CRBR Working Group on Sys Integration & Instrumentation Control 830224 meeting in Washington,DC Pp 1-261 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/24 393pp 17306 102 24X Fiche 50-537,83/02/24,8302280100

U Congressional/Executive Correspondence

8302030015 FOIA request for NRC correspondence w/White House & Congress re CRBR since Jan 1981
WEISS,E R Harmon & Weiss 82/10/27 FELTON,J Division of Rules and Records 2pp 17022 293 24X Fiche 50-537,82/10/27,8302030015

8302030017 Responds to FOIA request for NRC correspondence w/White House & Congress re CRBR since Jan 1981 Forwards documents listed in app
FELTON,J M Division of Rules and Records 82/12/29 WEISS,E R Harmon & Weiss 3pp 17022 295 24X Fiche 50-537,82/12/29,8302030017

--8208050174 Responds to 820714 ltr re CRBR Suppl to 1977 FES will be circulated for public comment for 45-day period beginning 820730 Final suppl to FES will be issued in Oct & will address comments received
DIRCKS,W J Office of the Executive Director for Operations 82/07/28 BOUQUARD,M L House of Rep, Science & Technology 9pp 17022 315 24X Fiche 50-537,82/12/29,8302030017

--8302030024 Notifies of opposition to DOE request for CRBR site preparation before environ impact hearing
MITCHELL,G J Senate 82/08/02 PALLADINO,N Commissioners 2pp 17022 305 24X Fiche 50-537,82/12/29,8302030017

--8302030029 Urges denial of DOE 820701 request for CRBR site preparation before issuance of CP or LWA
UDALL,M, COUGHLIN,L, HOLPE,H House of Rep 82/07/30 PALLADINO,N, OILINSKY,V, ROBERTS,T F Commissioners 4pp 17022 307 24X Fiche 50-537,82/12/29,8302030017

--8302030034 Act receipt of 820723 ltr forwarding SA Knapp request for DOE exemption from regulations enabling site preparation activities
KAMMERER,C Office of Congressional Affairs 82/07/29 BYRD,R C Senate 1p 17022 311 24X Fiche 50-537,82/12/29,8302030017

--8302030037 Forwards 4E Knapp 820720 & E Stanley 820720 ltrs re DOE request for early site preparation for consideration in rept
BYRD,R C Senate 82/07/23 KAMMERER,C Office of Congressional Affairs 1p 17022 312 24X Fiche 50-537,82/12/29,8302030017

--8302030038 Urges approval of DOE request to begin CRBR site preparation
KNAPP,W E, KNAPP,S A Affiliation Unknown 82/07/20 PALLADINO,N Commissioners 1p 17022 313 24X Fiche 50-537,82/12/29,8302030017

--8302030041 Urges approval of DOE request to begin CRBR site preparation
STALEY,E Affiliation Unknown 82/07/20 PALLADINO,N Commissioners 1p 17022 314 24X Fiche 50-537,82/12/29,8302030017

--8302030072 Urges rejection of DOE licensing exemption request for CRBR
Approval would damage credibility & set bad precedence
VENTO,B F House of Rep 82/07/28 PALLADINO,N Commissioners 1p 17022 318 24X Fiche 50-537,82/12/29,8302030017

--8302030079 Discusses 820708 meeting re necessity of recirculating EIS for CRBR CEQ regulations suggest supplementing EIS after 5 yrs when appropriate
HELL,A A President of US & Executive Offices 82/07/13 PALLADINO,N Commissioners 1p 17022 323 24X Fiche 50-537,82/12/29,8302030017

--8302030086 Urges approval of DOE request for early site preparation for const of CRBR if criteria of 10CFR50 12 met
BAKER,H H Senate 82/02/26 PALLADINO,N Commissioners 1p 17022 336 24X Fiche 50-537,82/12/29,8302030017

--8302030097 Expresses support for approval of DOE request for early site preparation for CRBR const if criteria of 10CFR50 12 met
SIMPSON,A K Senate 82/02/25 PALLADINO,N J Commissioners 2pp 17022 337 24X Fiche 50-537,82/12/29,8302030017

--8302030104 Advises of support of DOE request for early site preparation for CRBR so R&D results can be expedited
KEYWORTH,O A President of US & Executive Offices 82/02/24 PALLADINO,N J Commissioners 1p 17022 339 24X Fiche 50-537,82/12/29,8302030017

--8302030109 Urges approval of DOE request for early site preparation for CRBR Facility vital to R&D program re CMFBR Omnibus Budget Reconciliation Act of 1981 re Fusion R&D encl
FUGUA,D, ROE,R, BOUQUARD,M House of Rep, Science & Technology 82/02/11 PALLADINO,N J Commissioners 7pp 17022 340 24X Fiche 50-537,82/12/29,8302030017

--8302030123 Act receipt of 820119 ltr on behalf of IN Sassafraus Audubon Soc re DOE request for exemption for CRBR Commission 811224 order establishing proceeding for reviewing request encl
W/o encl
KAMMERER,C Office of Congressional Affairs 82/02/11 HAMILTON,L House of Rep 1p 17023 005 24X Fiche 50-537,82/12/29,8302030017

--8302030125 Forwards IN Sassafraus Audubon Soc 820115 ltr opposing DOE request for early site preparation for CRBR
HAMILTON,L H House of Rep 82/01/19 NRC - No Detailed Affiliation Given 2pp 17023 006 24X Fiche 50-537,82/12/29,8302030017

--8302030133 Opposes DOE request for site preparation w/o CP or LWA
FREY,D S Sassafraus Audubon Society 82/01/11 CHILK,S J Office of the Secretary of the Commission 1p 17023 008 24X Fiche 50-537,82/12/29,8302030017

DOCKETED ITEMS

--8302030136 Opposes DOE request for early site preparation w/o CP or LNA Proposed licensing changes would thwart public input
DECKARD, J House of Rep 82/01/22 CHILK, S J Office of the
Secretary of the Commission 1p 17023 009 24X
Fiche 50-546, 83/02/24, 8302030136

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OL, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOVAK, T M Assistant Director for Licensing 83/02/03 Atomic
Safety and Licensing Board Panel 6pp 17143 293 24X
Fiche 50-000, 83/02/03, 8302100512

--8302100522 Summary of 820219 meeting w/ORNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S M Licensing Branch 1 82/03/15 YOUNGBLOOD, B J
Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-07 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSS re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302230075 Submits daily highlight for 830216 Senior reactor inspector called to Washington, DC by Ofc of Congressional Affairs to brief Congress on allegations of electrical deficiencies
Project manager should be informed
O'CONNOR, P M Licensing Branch 1 83/02/16 DENTON, H R, CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 17302 339 24X Fiche 50-546, 83/02/16, 8302230075

8302280121 Forwards Amend 22 to OL application, consisting of responses to NRC questions, FSAR (filed in PDR Category K), security plan & fire protection rept (Category F), environ rept (Category C) & Central Files version of emergency plan
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W
Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280133 Amend 22 to OL application, consisting of responses to NRC questions, FSAR, security plan, fire protection rept, environ rept & emergency plan
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W
Wabash Valley Power Association, Inc 83/02/24 21pp 17375 004 24X Fiche 50-546, 83/02/24, 8302280121

--8302280158 "Byron/Braidwood - Responses to NRC Questions"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1,500pp 17398 090 24X
Fiche 50-546, 83/02/24, 8302280121

C Utility Environmental Report (ER), amends & correspondence

8302280121 Forwards environ rept
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280149 Environ rept for Marble Hill Nuclear Generating Station, Units 1 & 2
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1,000pp 17405 131 24X
Fiche 50-546, 83/02/24, 8302280121

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

8302250206 Confirms 830322 meeting at Region III ofc in Glen Ellyn, IL to discuss plans for emergency response Facilities Meeting notice & list of attendees encl
KEPPLER, J O Region 3, Office of Director 83/02/18 SHIELDS, S W
Public Service Co of Indiana, Inc 2pp 17293 109 24X
Fiche 50-546, 83/02/18, 8302250206

8302280121 Forwards security plan & fire protection rept Security plan withheld (ref 10CFR2 790)
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280143 Fire protection rept
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1,000pp 17402 253 24X
Fiche 50-546, 83/02/24, 8302280121

K Utility Final Safety Analysis Report (FSAR) & amends

8302280121 Forwards FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280137 FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2
W/133 oversize drawings Aperture cards are available in PDR
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1p 17375 027 24X
Fiche 50-546, 83/02/24, 8302280121

8302280161 Chapter 1 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Introduction & General Description of Plant"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 185pp 17375 038 24X
Fiche 50-546, 83/02/24, 8302280161

8302280167 Chapter 2 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Site Characteristics"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 720pp 17375 223 24X
Fiche 50-546, 83/02/24, 8302280167

8302280171 Chapter 3 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Design of Structures, Components, Equipment & Sys"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 913pp 17382 212 24X
Fiche 50-546, 83/02/24, 8302280171

8302280285 Chapter 4 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Reactor"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 267pp 17385 045 24X
Fiche 50-546, 83/02/24, 8302280285

8302280291 Chapter 5 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "RCS"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 206pp 17385 312 24X
Fiche 50-546, 83/02/24, 8302280291

8302280293 Chapter 6 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "ESFs"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 474pp 17386 158 24X
Fiche 50-546, 83/02/24, 8302280293

DOCKETED ITEMS

3

8302280298 Chapter 7 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Instrumentation & Controls"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 367pp 17387 272 24X
Fiche 50-546, 83/02/24, 8302280298

8302280299 Chapter 8 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Electric Power"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 50pp 17388 281 24X
Fiche 50-546, 83/02/24, 8302280299

8302280305 Chapter 9 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Auxiliary Sys"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 379pp 17389 026 24X
Fiche 50-546, 83/02/24, 8302280305

8302280307 Chapter 10 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Steam & Power Conversion Sys"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 114pp 17391 020 24X
Fiche 50-546, 83/02/24, 8302280307

8302280308 Chapter 11 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Radwaste Mgt"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 300pp 17391 134 24X
Fiche 50-546, 83/02/24, 8302280308

8302280314 Chapter 12 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Radiation Protection"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 297pp 17392 074 24X
Fiche 50-546, 83/02/24, 8302280314

8302280317 Chapter 13 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Conduct of Operation"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 100pp 17393 011 24X
Fiche 50-546, 83/02/24, 8302280317

8302280319 Chapter 14 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Initial Test Program"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 137pp 17393 111 24X
Fiche 50-546, 83/02/24, 8302280319

8302280322 Chapter 15 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Accident Analyses"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 365pp 17393 248 24X
Fiche 50-546, 83/02/24, 8302280322

8302280324 Chapter 16 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Tech Specs"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 356pp 17395 006 24X
Fiche 50-546, 83/02/24, 8302280324

8302280326 Chapter 17 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "QA"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 64pp 17396 002 24X
Fiche 50-546, 83/02/24, 8302280326

8302280328 App A to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Application of NRC Reg Guides"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 205pp 17396 066 24X
Fiche 50-546, 83/02/24, 8302280328

8302280330 App B to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Const Matl Stds & QC Procedures"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 63pp 17396 271 24X
Fiche 50-546, 83/02/24, 8302280330

8302280331 App C to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Turbine Missile Study"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 47pp 17396 333 24X
Fiche 50-546, 83/02/24, 8302280331

8302280332 App D to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Computer Programs"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 75pp 17397 023 24X
Fiche 50-546, 83/02/24, 8302280332

8302280334 App E to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Requirement Resulting From TMI-2 Accident"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 89pp 17397 172 24X
Fiche 50-546, 83/02/24, 8302280334

M Antitrust Correspondence

8302280172 Forwards "Info for Antitrust Review of DL Application, Marble Hill Nuclear Generating Station Units 1 & 2" Amend 22 to DL application submitted under separate cover
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17305 274 24X
Fiche 50-546, 83/02/24, 8302280172

--8302280177 "Info for Antitrust Review of DL Application, Marble Hill Nuclear Generating Station Units 1 & 2"
* Public Service Co of Indiana, Inc 83/02/28 43p 17305 275 24X
Fiche 50-546, 83/02/24, 8302280172

0 Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J O Region 3, Office of Director, 23pp 17045 219 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/08 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040332 Forwards 1981 comparison data for operating & const plants consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SCHARSKA, L Region 3, Office of Director 82/07/08 KEPLER, J O Region 3, Office of Director 13pp 17045 281 24X
Fiche 50-000, 82/12/30, 8302040039

8212060358 IE Info Notice 83-01, "Ray Miller, Inc" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/26 Consolidated Edison Co of New York, Inc 18pp 17023 160 24X
Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H00C, H10C, H20C & H30C Gearheads" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X
Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X
Fiche 50-000, 83/01/28, 8212060361

8302030303 Advises of 830207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X
Fiche 50-000, 83/01/28, 8302030303

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X
Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 038 24X
Fiche 50-000, 83/02/24, 8212060365

DOCKETED ITEMS

8212060356 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060356

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LDCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, 8302030495

8302040164 Part 21 rept re deficiency in Class IE low voltage switchgear Arc welds not added to connect rear vertical corner channel w/rear horizontal channel in rear bus section of switchgear encl
DUVAL, D D Brown Boveri Corp (subs Brown Boveri & Co, Ltd) 82/12/22 STELLO, V Director's Office, Office of Inspection and Enforcement 2pp 17020 296 24X Fiche 50-546, 82/12/22, 8302040164

8302040351 Deficiency rept re three welds on containment polar cranes, between end tie beam flange & bottom plate, bolted to saddle beam w/visible cracks Initially reported on 821007 Welds excavated & magnetic particle tested
SHIELDS, S W Public Service Co of Indiana, Inc 83/01/26
KEPPLER, J O Region 3, Office of Director 2pp 17019 052 24X Fiche 50-546, 83/01/26, 8302040351

8302040080 PND-III-83-010 on 830121, allegation received from fired electrical worker re deficiencies in mkt traceability of electrical hangers & in control of work instructions (travelers) in field installation of hangers stopped
KONWILIN, J, VNGP, R, NORELIOUS, C Region 3, Office of Director 83/01/31 1p 17020 193 24X Fiche 50-546, 83/01/31, 8302040080

8302180242 Final deficiency rept re disposition of contractor nonconformance rept approved w/o design subcontractor review of affected equipment Initially reported on 820811
Corrective action documented in acceptable manner
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/07
KEPPLER, J O Region 3, Office of Director 2pp 17215 278 24X Fiche 50-546, 83/02/07, 8302180242

8302160164 Final deficiency rept re incorrectly fabricated structural steel Initially reported on 830610 All pre- & post-installed deficiencies corrected by Neuberger-Marble Hill
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/08
KEPPLER, J O Region 3, Office of Director 2pp 17162 066 24X Fiche 50-546, 83/02/08, 8302160164

8302160213 Interim deficiency rept re use of AE design drawings w/o consideration of possible design changes Initially reported on 820622 Sargent & Lundy reviewing drawings to determine design changes to previously installed steel
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/08
KEPPLER, J O Region 3, Office of Director 2pp 17163 037 24X Fiche 50-546, 83/02/08, 8302160213

V Operator Examinations

8301030333 Generic Ltr 83-06 to all power reactor licensees, applicants for GLS, NRS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, 8301030333

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302100512 Board Notification 83-11 forwards info indicating onset of increased turbulence & acceleration of tube wear occurring at feed flow rates of 50% for Model D/2 & D/3 steam generators & at 70% for Model D/4 & D/5 steam generators
NOWAK, T M Assistant Director for Licensing 83/02/03 Atomic Safety and Licensing Board Panel 6pp 17143 293 24X Fiche 50-000, 83/02/03, 8302100512

8302100522 Summary of 820217 meeting w/ORNL, ANL, TX Utils Generating Co, SC Electric & Gas Co, Westinghouse, TVA & representatives of Swedish nuclear power plant & Krsko in Bethesda, MD re accelerated tube wear on Model D steam generators
CHESTNUT, S H Licensing Branch 1 82/03/15 YOUNGBLOOD, B J Licensing Branch 1 46pp 17143 298 24X Fiche 50-000, 83/02/03, 8302100512

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for DL & holders of CP for C-E PWRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated Edison Co of New York, Inc 11pp 17290 247 24X Fiche 50-000, 83/02/08, 8302080295

8302090080 Generic Ltr 83-10C to all applicants w/Westinghouse designed NSSS re resolution of IMF Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
EISENHUT, D O Division of Licensing 83/02/08 Baltimore Gas & Electric Co 30pp 17290 212 24X Fiche 50-000, 83/02/08, 8302090080

8302230075 Submits daily highlight for 830216 Senior reactor inspector called to Washington, DC by Ofc of Congressional Affairs to brief Congress on allegations of electrical deficiencies
Project manager should be informed
D'CONOR, P W Licensing Branch 1 83/02/16 DENTON, H R, CASE, E, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 17302 339 24X Fiche 50-546, 83/02/16, 8302230075

8302280121 Forwards Amend 22 to DL application, consisting of responses to NRC questions, FSAR (filed in PDR Category K), security plan & fire protection rept (Category F), environ rept (Category C) & Central Files version of emergency plan
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X Fiche 50-546, 83/02/24, 8302280121

--8302280133 Amend 22 to DL application, consisting of responses to NRC questions, FSAR, security plan, fire protection rept, environ rept & emergency plan
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/02/24 21pp 17375 006 24X Fiche 50-546, 83/02/24, 8302280121

--8302280158 Byron/Braidwood - Responses to NRC Questions "
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1,503pp 17398 090 24X Fiche 50-546, 83/02/24, 8302280121

C Utility Environmental Report (ER), amends & correspondence

8302280121 Forwards environ rept
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X Fiche 50-546, 83/02/24, 8302280121

--8302280149 Environ rept for Marble Hill Nuclear Generating Station, Units 1 & 2
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1,000pp 17405 131 24X Fiche 50-546, 83/02/24, 8302280121

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for DL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability" Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated Edison Co of New York, Inc 11pp 17221 226 24X Fiche 50-000, 83/02/01, 8301210340

8302250206 Confirms 830322 meeting at Region III ofc in Glen Ellyn, IL to discuss plans for emergency response facilities Meeting notice & list of attendees encl
KEPPLER, J O Region 3, Office of Director 83/02/18 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 17293 109 24X Fiche 50-546, 83/02/18, 8302250206

8302280121 Forwards security plan & fire protection rept Security plan withheld (ref 10CFR2 790)
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X Fiche 50-546, 83/02/24, 8302280121

--8302280143 Fire protection rept
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1,000pp 17402 293 24X Fiche 50-546, 83/02/24, 8302280121

* Utility Final Safety Analysis Report (FSAR) & amends

8302280121 Forwards FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280137 FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2
W133 oversize drawings Aperture cards are available in PDR
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1p 17375 027 24X
Fiche 50-546, 83/02/24, 8302280137

8302280161 Chapter 1 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Introduction & General Description of Plant"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 185pp 17375 038 24X
Fiche 50-546, 83/02/24, 8302280161

8302280167 Chapter 2 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Site Characteristics"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 720pp 17375 223 24X
Fiche 50-546, 83/02/24, 8302280167

8302280171 Chapter 3 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Design of Structures, Components, Equipment & Sys"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 913pp 17382 212 24X
Fiche 50-546, 83/02/24, 8302280171

8302280285 Chapter 4 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Reactor"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 267pp 17385 045 24X
Fiche 50-546, 83/02/24, 8302280285

8302280291 Chapter 5 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "RCS"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 206pp 17385 312 24X
Fiche 50-546, 83/02/24, 8302280291

8302280293 Chapter 6 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "EGS"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 474pp 17386 158 24X
Fiche 50-546, 83/02/24, 8302280293

8302280298 Chapter 7 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Instrumentation & Controls"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 369pp 17387 272 24X
Fiche 50-546, 83/02/24, 8302280298

8302280299 Chapter 8 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Electric Power"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 50pp 17388 281 24X
Fiche 50-546, 83/02/24, 8302280299

8302280305 Chapter 9 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Auxiliary Sys"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 379pp 17389 026 24X
Fiche 50-546, 83/02/24, 8302280305

8302280307 Chapter 10 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Steam & Power Conversion Sys"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 114pp 17391 020 24X
Fiche 50-546, 83/02/24, 8302280307

8302280308 Chapter 11 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Radioactive Mgt"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 300pp 17391 134 24X
Fiche 50-546, 83/02/24, 8302280308

8302280314 Chapter 12 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Radiation Protection"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 297pp 17392 074 24X
Fiche 50-546, 83/02/24, 8302280314

8302280317 Chapter 13 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Conduct of Operation"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 100pp 17393 011 24X
Fiche 50-546, 83/02/24, 8302280317

8302280319 Chapter 14 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Initial Test Program"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 137pp 17393 111 24X
Fiche 50-546, 83/02/24, 8302280319

8302280322 Chapter 15 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Accident Analyses"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 365pp 17393 248 24X
Fiche 50-546, 83/02/24, 8302280322

8302280324 Chapter 16 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Tech Specs"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 356pp 17395 006 24X
Fiche 50-546, 83/02/24, 8302280324

8302280326 Chapter 17 to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "QA"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 64pp 17396 002 24X
Fiche 50-546, 83/02/24, 8302280326

8302280328 App A to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Application of NRC Reg Guides"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 205pp 17396 066 24X
Fiche 50-546, 83/02/24, 8302280328

8302280330 App B to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Const Matl Stds & QC Procedures"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 63pp 17396 271 24X
Fiche 50-546, 83/02/24, 8302280330

8302280331 App C to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Turbine Missile Study"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 47pp 17396 333 24X
Fiche 50-546, 83/02/24, 8302280331

8302280332 App D to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Computer Programs"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 79pp 17397 023 24X
Fiche 50-546, 83/02/24, 8302280332

8302280334 App E to Marble Hill Nuclear Generating Station, Units 1 & 2, FSAR, "Requirement Resulting From TMI-2 Accident"
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 85pp 17397 172 24X
Fiche 50-546, 83/02/24, 8302280334

M Antitrust correspondence

8302280172 Forwards "Info for Antitrust Review of DL Application, Marble Hill Nuclear Generating Station Units 1 & 2" Amend 22 to DL application submitted under separate cover
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17305 274 24X
Fiche 50-546, 83/02/24, 8302280172

--8302280177 "Info for Antitrust Review of DL Application, Marble Hill Nuclear Generating Station Units 1 & 2"
* Public Service Co of Indiana, Inc 83/02/28 43p 17305 275 24X
Fiche 50-546, 83/02/24, 8302280172

Q Inspection reports, IE Bulletins & correspondence

8302040039 Addl response to FOIA request for 12 categories of documents re facilities Personal info deleted from documents re util/contractor employee allegations concerning QA deficiency.
Forwards App A documents Document 31 available in PDR
FELTON, J M Division of Rules and Records 82/12/30 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17045 144 24X
Fiche 50-000, 82/12/30, 8302040039

--8302040111 Forwards graphics summarizing const site noncompliance data for 1976-80
HIND, J A Division of Emergency Preparedness & Operational Support 82/02/05 KEPLER, J G Region 3, Office of Director 23pp 17045 219 24X
Fiche 50-000, 82/12/30, 8302040039

DOCKETED ITEMS

--B302040197 Forwards updated noncompliance history for const sites for 1976-81, per JJ Harrison request Total insp hours for each facility added
HIND, J A Division of Emergency Preparedness & Operational Support 82/06/09 SPESSARD, R L Division of Project & Resident Programs 2pp 17045 279 24X Fiche 50-000, 82/12/30, B302040039

--B302040332 Forwards 1981 comparison data for operating & const plants, consisting of total numbers of noncompliance items, repts issued, insp hours, severity levels, points & hours per rept & item
SUCHARSKI, L Region 3, Office of Director 82/07/08
KEPPLER, J G Region 3, Office of Director 13pp 17045 281 24X Fiche 50-000, 82/12/30, B302040039

B212060338 IE Info Notice B3-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060338

B212060360 IE Info Notice B3-02, "Litorque H08C, H10C, H20C & H30C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice B3-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

B302030303 Advises of B30207 open forum in Chicago, IL re recent rev to 10CFR50.54 & 50.55 IE will conduct formal presentation followed by question & answer session Requests that participation be limited to three people
SPESSARD, R L Division of Engineering 83/01/28 Commonwealth Edison Co 2pp 17008 187 24X Fiche 50-000, 83/01/28, B302030303

B212060363 IE Info Notice B3-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/02/18 Consolidated Edison Co of New York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, B212060363

B212060365 IE Info Notice B3-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, B212060365

B212060366 IE Info Notice B3-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/02/24 Consolidated Edison Co of New York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, B212060366

B Reportable occurrences, LERs & related correspondence

B302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by B30218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, B302030495

B302040164 Part 21 rept re deficiency in Class IE low voltage switchgear Arc welds not added to connect rear vertical corner channel w/rear horizontal channel in rear bus section of switchgear encl
BUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd.) 82/12/22 STELLO, V Director's Office, Office of Inspection and Enforcement 2pp 17020 296 24X Fiche 50-546, 82/12/22, B302040164

102040351 Deficiency rept re three welds on containment polar crane, between end tie beam flange & bottom plate, bolted to saddle beam w/visible cracks Initially reported on 821007 Welds excavated & magnetic particle tested
SHIELDS, S W Public Service Co of Indiana, Inc 83/01/26
KEPPLER, J G Region 3, Office of Director 2pp 17019 092 24X Fiche 50-546, 83/01/26, B302040351

102040080 PND-III-B3-010 on B30121, allegation received from fired electrical worker re deficiencies in mat'l traceability of electrical hangers & in control of work instructions (travelers) in field Installation of hangers stopped
KONKLIN, J, KNOP, R, NORELIUS, C Region 3, Office of Director 83/01/31 1p 17020 153 24X Fiche 50-546, 83/01/31, B302040080

B302180242 Final deficiency rept re disposition of contractor nonconformance rept approved w/o design subcontractor review of affected equipment Initially reported on B20811
Corrective action documented in acceptable manner
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/07
KEPPLER, J G Region 3, Office of Director 2pp 17215 278 24X Fiche 50-546, 83/02/07, B302180242

B302160164 Final deficiency rept re incorrectly fabricated structural steel Initially reported on B20610 All pre- & post-installed deficiencies corrected by Newberg-Marble Hill
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/08
KEPPLER, J G Region 3, Office of Director 2pp 17162 066 24X Fiche 50-546, 83/02/08, B302160164

B302160213 Interim deficiency rept re use of AE design drawings w/o consideration of possible design changes Initially reported on B20622 Sargent & Lundy reviewing drawings to determine design changes to previously installed steel
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/08
KEPPLER, J G Region 3, Office of Director 2pp 17163 037 24X Fiche 50-546, 83/02/08, B302160213

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B301310203

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B302230137 Forwards "TVA Cancellation of Phipps Bend Nuclear Plant," per util B21026 ltr Withdrawal of CPR-162 & CPR-163 requested
MILLS, L M Tennessee Valley Authority 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17243 279 24X Fiche 50-553, 83/02/16, B302230137

--B302230138 "TVA Cancellation of Phipps Bend Nuclear Plant " * Tennessee Valley Authority 83/02/28 13pp 17243 280 24X Fiche 50-553, 83/02/16, B302230137

Q Inspection reports, IE Bulletins & correspondence

B212060358 IE Info Notice B3-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/26 Consolidated Edison Co of New York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, B212060358

B212060360 IE Info Notice B3-02, "Litorque H08C, H10C, H20C & H30C Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co of New York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, B212060360

B212060361 IE Info Notice B3-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/01/28 Consolidated Edison Co of New York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, B212060361

S Reportable occurrences, LERs & related correspondence

B302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by B30218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J Region 4, Office of Director 4pp 17006 128 24X Fiche 50-000, 82/12/17, B302030495

V Operator Examinations

B301310203 Generic Ltr B3-06 to all power reactor licensees, applicants for DLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated Edison Co of New York, Inc 14pp 17347 177 24X Fiche 50-000, 83/01/31, B301310203

DOCKETED ITEMS

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302230137 Forwards TVA Cancellation of Phipps Bend Nuclear Plant " per util 821026 ltr Withdrawal of CPR-162 & CPR-163 requested
MILLS, L M Tennessee Valley Authority 83/02/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 17243 279 24X
Fiche 50-553, 83/02/16, 8302230137

-8302230138 "TVA Cancellation of Phipps Bend Nuclear Plant " * Tennessee Valley Authority 83/02/28 13pp 17243 280 24X
Fiche 50-553, 83/02/16, 8302230137

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 107pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

S Reportable occurrences, LERs & related correspondence

8302030495 Part 21 rept re determination that post-LOCA hydrogen recombiner is likely to malfunction following exposure to elevated temp, high humidity environ Replacement part identification will be provided to operators by 830218
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J
Region 4, Office of Director 4pp 17006 128 24X
Fiche 50-000, 82/12/17, 8302030495

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for OLs, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 11pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

G Adjudicatory correspondence

8302160262 Motion for extension until 830223 to respond to util 830123 motion for termination of proceeding & withdrawal of application W/Certificate of Svc
SINGER, R K, DRAKE, S J Oklahoma, State of 83/02/07 Atomic
Safety and Licensing Board Panel 5pp 17169 239 24X
Fiche 50-556, 83/02/07, 8302160262

8302220409 Order granting State of OK 830207 motion for extension until 830228 to respond to applicant 830123 motion for termination or proceeding & withdrawal of application Good cause shown
NOLFE, S J Atomic Safety and Licensing Board Panel 83/02/17
Oklahoma, State of 2pp 17232 132 24X Fiche 50-556, 83/02/17, 8302220409

G Inspection reports, IE Bulletins & correspondence

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17347 098 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co of New
York, Inc 11pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

8302080295 Generic Ltr 83-09 to all operating reactor licensees, applicants for OL & holders of CP for C-E PHRs re review of C-E Owners Group emergency procedures guideline program Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Consolidated
Edison Co of New York, Inc 11pp 17290 247 24X
Fiche 50-000, 83/02/08, 8302080295

8302080301 Generic Ltr 83-05 to BWR licensees of operating reactors (except LACBWR), applicants for OL & holders of CP re SER of "Emergency Procedure Guidelines, Rev 2," NEDO-24934, June 1982 Guidelines acceptable Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Commonwealth
Edison Co 6pp 17234 245 24X Fiche 50-000, 83/02/08, 8302080301

F Security, medical, emergency & fire protection plans

8301210340 Generic Ltr 83-04 to all licensees of operating reactors, applicants for OL & holders of CPs re regional workshop concerning Suppl 1, NUREG-0737, "Requirements for Emergency Response Capability " Svc list encl
EISENHUT, D O Division of Licensing 83/02/01 Consolidated
Edison Co of New York, Inc 11pp 17221 226 24X
Fiche 50-000, 83/02/01, 8301210340

DOCKETED ITEMS

1 Adjudicatory correspondence

8302160262 Motion for extension until 830223 to respond to until 830123 motion for termination of proceeding & withdrawal of application W/Certificate of Evc
SINGER, R K, DRAKE, S J Oklahoma, State of. 83/02/07 Atomic
Safety and Licensing Board Panel 5pp 17169 239 24X
Fiche 50-556, 83/02/07, 8302160262

8302220409 Order granting State of OK 830207 motion for extension until 830228 to respond to applicant 830123 motion for termination of proceeding & withdrawal of application Good cause shown
WOLFE, S J Atomic Safety and Licensing Board Panel 83/02/17
Oklahoma, State of 2pp 17232 132 24X Fiche 50-556, 83/02/17, 8302220409

2 Inspection reports, IE Bulletins & correspondence

8312060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8312060360 IE Info Notice 83-02, "Limitorque HOBC, H1BC, H2BC & H3BC Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8312060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 093 24X Fiche 50-000, 83/01/28, 8212060361

8312060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8312060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20.302" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8312060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSB re resolution of TMI Action Item II.K 3.5, "Automatic Trip of Reactor Coolant Pumps." Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Louisiana Power & Light Co 28pp, 17314, 232 24X Fiche 50-000, 83/02/08, 8302090065

8302220489 Requests until provide good cause why Commission should grant extension to CPs as requested in util 830121 ltr Response by 830228 requested
SCHWENGER, A Licensing Branch 2, 83/02/17 MILLS, L. M. Tennessee Valley Authority, 4pp 17237, 343 24X Fiche 50-000, 83/02/17, 8302220489

G Inspection reports, IE Bulletins & correspondence

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority, 83/01/24, O'REILLY, J. P. Region 2, Office of Director, 1p, 17153, 309 24X
Fiche 50-000, 83/01/24, 8302150610

8312060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp, 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque HOBC, H1BC, H2BC & H3BC Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 093 24X Fiche 50-000, 83/01/28, 8212060361

B Reportable occurrences, LERs & related correspondence

8302010648 Fourth interim deficiency rept re engineering change review & handling initially reported on 811215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution Bellefonte sampling under evaluation.
MILLS, L M Tennessee Valley Authority, 83/01/19 O'REILLY, J. P. Region 2, Office of Director 2pp 16980, 049, 24X
Fiche 50-000, 83/01/19, 8302010648

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review initially reported on 820816 Info on Yellow Creek or Hartsville deferred until final decision re projects. Next rept expected by 830531
MILLS, L M Tennessee Valley Authority, 83/01/26 O'REILLY, J. P. Region 2, Office of Director 3pp 16974 037, 24X
Fiche 50-000, 83/01/26, 8302010215

8302030351 Second revised final deficiency rept re welds on component cooling water HX mfg by Joseph Oat Corp initially reported on 810306 Defects removed by grinding. Also reported per Part 21.
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J. P. Region 2, Office of Director 2pp 17006, 285, 24X
Fiche 50-566, 83/01/28, 8302030351

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NSS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D O Division of Licensing 83/01/31, Consolidated
Edison Co of New York, Inc, 14pp 17347, 177, 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8302090065 Generic Ltr 83-10A to all applicants w/C-E designed NSSB re resolution of TMI Action Item II.K 3.5, "Automatic Trip of Reactor Coolant Pumps." Svc list encl
EISENHUT, D O Division of Licensing 83/02/08 Louisiana Power & Light Co, 28pp, 17314, 232 24X Fiche 50-000, 83/02/08, 8302090065

8302220489 Requests until provide good cause why Commission should grant extension to CPs as requested in util 830121 ltr Response by 830228 requested
SCHWENGER, A Licensing Branch 2, 83/02/17, MILLS, L. M. Tennessee Valley Authority 4pp 17237, 343, 24X Fiche 50-000, 83/02/17, 8302220489

G. Inspection reports, IE Bulletins & correspondence

8302150610 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" & NRC 821203 ltr Bunker-Ramo Co electrical penetration assemblies not in use at facilities
MILLS, L M Tennessee Valley Authority, 83/01/24, O'REILLY, J. P. Region 2, Office of Director, 1p, 17153, 309, 24X
Fiche 50-000, 83/01/24, 8302150610

8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023, 160, 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Limitorque HOBC, H1BC, H2BC & H3BC Gearheads." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/01/28 Consolidated Edison Co. of New
York, Inc, 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

DOCKETED ITEMS

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

S Reportable occurrences, LERs & related correspondence

8302010648 Fourth interim deficiency rept re engineering change review & handling Initially reported on 811215 Watts Bar Deficiency 2 not applicable Deficiencies 3 & 4 require addl sampling before resolution Bellefonte sampling under evaluation
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P
Region 2, Office of Director 2pp 16980 049 24X
Fiche 50-000, 83/01/19, 8302010648

8302010215 Second interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 820816 Info on Yellow Creek or Hartsville deferred until final decision re projects Next rept expected by 830531
MILLS, L M Tennessee Valley Authority 83/01/26 O'REILLY, J P
Region 2, Office of Director 3pp 16974 037 24X
Fiche 50-000, 83/01/26, 8302010215

8302030551 Second revised final deficiency rept re welds on component cooling water HX mfg by Joseph Dat Corp Initially reported on 810306 Defects removed by grinding Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 2pp 17006 285 24X
Fiche 50-566, 83/01/28, 8302030551

V Operator Examinations

8301310203 Generic Ltr 83-06 to all power reactor licensees, applicants for CLS, NRS vendors, reactor vendors & AE re certificates & revised format for reactor operator & senior reactor operator licenses Svc list encl
EISENHUT, D G Division of Licensing 83/01/31 Consolidated
Edison Co of New York, Inc 14pp 17347 177 24X
Fiche 50-000, 83/01/31, 8301310203

DOCKET STN-50-599 CARROLL FACILITY I

G Adjudicatory correspondence

8302070542 Submits quarterly status rept on proceeding per ASLB request Projected inservice date revised for Unit 1 from 1999 to 2000 & for Unit 2 from 2000 to 2001 Related correspondence
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth
Edison Co 83/02/01 WOLF, J F, HOLTON, R L, BRIGHT, O G Atomic
Safety and Licensing Board Panel 2pp 17038 360 24X
Fiche 50-599, 83/02/01, 8302070542

DOCKET STN-50-600 CARROLL FACILITY II

G Adjudicatory correspondence

8302070542 Submits quarterly status rept on proceeding per ASLB request Projected inservice date revised for Unit 1 from 1999 to 2000 & for Unit 2 from 2000 to 2001 Related correspondence
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth
Edison Co 83/02/01 WOLF, J F, HOLTON, R L, BRIGHT, O G Atomic
Safety and Licensing Board Panel 2pp 17038 360 24X
Fiche 50-599, 83/02/01, 8302070542

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP, CANOGA PARK, CA

8302080051 Confirms 820812 discussion re problems of complying w/ requirements of SNM control & accounting plan for SEFOR decladding & interim plan Program initiated to install slave manipulators in glove boxes
REHMEY, M E Rockwell International Corp 82/08/13 EVANS, L J
Fuel Facility Safeguards Licensing Branch 3pp 17106, 260

8302080399 Provides info re emergency shipment of nuclear matl of moderate strategic significance Exception granted re advance notice requirement
BCHAUBERT, V J Rockwell International Corp 82/11/11 ENGELKEN, R
Region 5, Office of Director 2pp 17105 358

DOCKET 70-0027 BABCOCK & WILCOX CO, LYNCHBURG, VA

8302040559 Application for amend of License SNM-42 re reassignment nuclear safety & licensing responsibilities
KELLY, J W Babcock & Wilcox Co 82/07/20 PAGE, R G Uranium
Licensing Branch 17pp 17042 217

8302040604 Application for amend to License SNM-42, correcting typographical errors in 820720 amend request
KELLY, J W Babcock & Wilcox Co 82/09/10 PAGE, R G Uranium
Licensing Branch 4pp 17042 042

8302040589 Application for amend of License SNM-42 re existing 72-receipt verification requirement for clad research reactor fuel plates
KELLY, J W Babcock & Wilcox Co 82/09/14 EVANS, L J Fuel
Facility Safeguards Licensing Branch 2pp 17042 205

8302080389 Submits stack environ releases in total quantities & concentration for 1979-1981
OLSEN, A F Babcock & Wilcox Co 82/10/01 SHUM, E Y B Uranium
Fuel Licensing Branch 1p 17105 362

8302070022 Requests amend to license for extension of time limit for completion of matl measurements required in Paragraph 25 of instructions for Form DOE/NRC-741
KELLY, J W Babcock & Wilcox Co 82/10/21 EVANS, L J Fuel
Facility Safeguards Licensing Branch 2pp 17062 361

8302030433 Forwards IE Safeguards Insp Rept 70-0027/83-01 on 830103 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/02/01 ECKERT, J P Babcock & Wilcox Co 2pp 17005 205

--8302030437 IE Safeguards Insp Rept 70-0027/83-01 on 830103-06 No noncompliance noted Major areas inspected review of unresolved item (81-20-02), site orientation & security plan Details withheld (ref 10CFR73 21)
TOBIN, W J, MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/01/31 1p 17005 205

DOCKET 70-0033 TEXAS INSTRUMENTS, INC, ATTLBORO, MA

8302220070 Requests assistance in making confirmatory survey to verify facility & equipment decontaminated to acceptable levels
PAGE, R G Uranium Fuel Licensing Branch 83/02/07 MARTIN, T T
Division of Engineering & Technical Programs 1p 17234 052

DOCKET 70-0036 COMBUSTION ENGINEERING, INC, WINDSOR, CT

8302080021 Requests 14-day delay until 830114 to comply w/ 10CFR70 (4)(i) through (iv) requirements for physical inventory Addl time required due to holiday shutdown Scheduled administrative amend fee encl
ESKRIDGE, H E Combustion Engineering, Inc 82/12/14 EVANS, L
Fuel Facility Safeguards Licensing Branch 1p 17108 012

DOCKET 70-0113 PENNSYLVANIA STATE UNIV, UNIVERSITY PARK, PA

8302180235 Forwards IE Safeguards Insp Repts 50-005/83-01 & 70-0113/83-01 on 830110-14 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/07
Pennsylvania State Univ 2pp 17212 085 24X
Fiche 50-005, 83/02/07, 8302180235

--8302180241 IE Safeguards Insp Repts 50-005/83-01 & 70-0113/83-01 on 830110-14 No noncompliance noted Major areas inspected nuclear matl control & accounting, physical inventory & verification & records & repts
ZIBULSKY, H Region 1, Office of Director GDDY, A T Region
Office of Director 83/02/04 8pp 17212 087 24X
Fiche 50-005, 83/02/07, 8302180235

DOCKET 70-0124 TELEDYNE ISOTOPE, INC, WESTWOOD, NJ

8302180393 Forwards IE Insp Rept 70-0124/83-01 on 830105-07 & not of violation
MARTIN, T T Division of Engineering & Technical Programs 83/02/07
SCHURF, D F Teledyne Isotopes 2pp 17210 021

--8302180369 Notice of violation from insp on 830105-07
* Division of Engineering & Technical Programs. 83/02/04, 17210 023

DOCKETED ITEMS

--B302180371 IE Insp Rept 70-0124/B2-01 on B30105-07 Noncompliance noted failure to conduct monthly air velocity measurements on hoods
ROTH, J., QDDY, A T Division of Engineering & Technical Programs
83/01/31 8pp 17210 024

DOCKET 70-0135 BARCOCK & WILCOX CO., APOLLO, PA

B302070031 Informs of personnel change WL Coleman, manager of PA operations of nuclear power generation div. effective B21001
AUSTIN, M A Babcock & Wilcox Co 82/10/08 HAYNES, R C Region 1
Office of Director 1p 17062 360

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

B302070191 Forwards revised pages to physical safeguards plans Pages withheld (ref 10CFR73 21)
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/03/22 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 17062 335

B302080091 Forwards Amend 1 to physical safeguards plan w/drawings re lack of storage space Safeguards info withheld
(ref 10CFR73 21)
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/04/16 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 17106 104

B302070127 Forwards Rev 6 to physical safeguards plan, including Amends 1 & 11 to plan No fees applicable to mods Rev withheld
(ref 10CFR2 790)
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/07/12 EVANS, L J Division of Safeguards 1p 17065 359

B302080087 Forwards Rev 2 to B20301 interim security measures Encl withheld (ref 10CFR73 21)
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/07/26 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 17106 136

B302040579 Application for amend of License SNM-124 Encl describing amend withheld (ref 10CFR2 790)
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/09/13 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 17042 216

B302070038 Forwards rept on airborne radioactivity concentrations released from plant stacks in Sept 1982 per Condition 61, Amend 6 & Condition 67, Amend 9 of License SNM-124
HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/10/15 O'REILLY, J P 2P Region 2, Office of Director 2pp 17062 354

--B302070046 "Daily Summary of Stack Monitoring," for Sept 1982
* Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/10/15
4pp 17062 356

B302090061 Forwards Nov 1982 Rev 44 to Jul 1982 fundamental nuclear matl control plan, Section 7 Upgrading mods, per 10CFR70 32 Rev withheld (ref 10CFR2 790)
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/12/06 EVANS, L J Fuel Facility Safeguards Licensing Branch
1p 17119 255

B302080377 Forwards Rev 45 to fundamental nuclear matl control plan Plan withheld (ref 10CFR73 21)
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
82/12/29 RENTSCHLER, R R Fuel Facility Safeguards Licensing Branch 1p 17107 145

B302040017 Application to amend License SNM-124 per attachment conditions Attachment withheld (ref 10CFR73 21)
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/01/04 RENTSCHLER, R R Fuel Facility Safeguards Licensing Branch 1pp 17043 296

B302150352 Forwards IE Safeguards Insp Rept 70-0143/B2-51 on B21220-22 No noncompliance noted
STOHR, J P Division of Engineering & Radiological Safety Programs
83/01/07 HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 17157 221

--B302150356 IE Safeguards Insp Rept 70-0143/B2-51 on B21220-22 No noncompliance noted Major areas inspected radwaste mgmt & followup on previous inspector items
KAHLE, J B, BARR, K P Division of Engineering & Radiological Safety Programs 83/01/07 4pp 17157 223

B302040015 Confirms telcon w/EE Gergely re relocation of environ air sampler currently located at end of Meadowbrook Lane per License Condition 62 New location approx 50 meters northeast of present site
HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/01/10 MONTGOMERY, D Region 2, Office of Director 1pp 17043 297

B302070036 Forwards response to NRC ltr re violations noted in IE Insp Rept 70-0143/B2-48 Corrective actions personnel will be re-instructed on requirement to keep fire doors operable at all times
HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/01/10 O'BRIEN, A F Division of Engineering & Radiological Safety Programs 2pp 17059 350

B302070638 Responds to NRC ltr re violations noted in IE Insp Rept 70-0143/B2-45 Corrective actions Pall filters & sample bottles placed on correct storage racks
HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/01/10 CLSHINSKI, J A Division of Engineering & Radiological Safety Programs 3pp 17059 352

B302080345 Application for amend of License SNM-124 Encl withheld (ref 10CFR2 790)
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/01/13 RENTSCHLER, R R Fuel Facility Safeguards Licensing Branch 1p 17107 213

B302280126 Addl response to FOIA request for seven categories of info re facility Documents listed in app completely withheld (ref FOIA Exemptions 1, 3 & 4) Access to portions of documents provided through NMSS protective order
FELTON, J M Division of Rules and Records 83/01/19 WEISS, E R Harmon & Weiss 4pp 17314 274

B302150315 Ack receipt of IE Insp Rept 70-0143/B2-52 No proprietary info
HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/01/20 STOHR, J P Division of Emergency Preparedness & Materials Safety 1p 17148 220

B302030216 Advises that NFB request to extend effective date of Condition 66, limiting routine airborne radioactive releases until Apr 1983, will have no significant impact on public health & safety Ventilation sys upgrade incomplete
NIXON, W A Uranium Fuel Licensing Branch 83/01/26 Uranium Fuel Licensing Branch 1p 17013 350

B302020498 Unofficial transcript of Commission B30127 discussion/possible vote in Washington, DC re procedure for hearing on NFB-Erwin license amend Pp 1-95
* Commissioners 83/01/27 9pp 16995 106

B302150033 Ack receipt of B30110 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/B2-45
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/02/01 HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 17147 130

--B302150057 Forwards IE Insp Rept 70-0143/B2-45 on B21115-19 & notice of violation
CLSHINSKI, J A Division of Engineering & Radiological Safety Programs 82/12/09 HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 17147 134

--B302150061 Notice of violation from insp on B21115-19
* Division of Engineering & Radiological Safety Programs
82/12/09 1p 17147 136

--B302150069 IE Insp Rept 70-0143/B2-45 on B21115-19 Noncompliance noted failure to follow posted safety limits at two in-storage racks in Bldg 302-3
CORVELL, G P, MCALPINE, E J Division of Engineering & Radiological Safety Programs 82/11/29 4pp 17147 137

B302100084 Staff requirements memo re B30127 discussion/possible vote in Washington, DC on procedures for hearing on NFB-Erwin
CHILKS, J Office of the Secretary of the Commission 83/02/02
HALSCH, M Q Office of the General Counsel 1p 17135 104

B302150034 Ack receipt of IE Insp Rept 70-0143/B2-51 No proprietary info
HANSEN, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/02/03 O'BRIEN, A F Division of Engineering & Radiological Safety Programs 1p 17146 001

B302170565 Transcript of B30209 Commission affirmation/discussion & vote in Washington, DC re revised order on NFB-Erwin hearing Pp 1-5
* Commissioners 83/02/09 5pp 17197 174

DOCKETED ITEMS

8302140023 Order resolving pending matters & establishing schedule & format in preparation for 830325 oral session Participants may provide written responses to other party questions Areas on which parties should focus listed
CHILLY, S J Office of the Secretary of the Commission 83/02/10 7pp 17141 182

8302150379 Forwards IE Safeguards Insp Rept 70-0143/83-02 on 830109-14 No noncompliance noted
STCHIR, J P Division of Emergency Preparedness & Materials Safety 83/02/10 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 17148 171

--8302150403 IE Safeguards Insp Rept 70-0143/83-02 on 830109-14 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 10CFR2 790)
CLAY, E L, MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/02/10 1p 17148 173

8302180517 Staff requirements memo re affirmation/discussion & vote in Washington, DC on revised order for NRC-Erwin hearing
CHILK, S J Office of the Secretary of the Commission 83/02/10 HALSCH, M G Office of the General Counsel 1p 17221 268

8302160347 Forwards corrected title page & attachments to NRDC objection to ex parte communication & request for remedial action Original sent out under incorrect heading
WEISS, E R Harmon & Weiss WEISS, E R Natural Resources Defense Council 83/02/15 PALLADINO, M J, GILINSKY, V, AHEARNE, J Commissioners 1p 17167 307

--8302160349 Corrected title page & attachments to NRDC objection to ex parte communication & request for remedial action Certificate of Svc encl
Natural Resources Defense Council 83/02/15 Commissioners 8pp 17167 310

DOCKET 70-0146 SPENCER CHEMICAL CO, KANSAS CITY, MO

8302240241 Addl response to FOIA request for documents re Spencer Chemical Co Forwards documents listed in App A
FELTON, J M Division of Rules and Records 83/01/14 BARNES, C Affiliation Unknown 2pp 17288 127

--8302240244 Application to amend License SNM-154, authorizing changes to fully enriched plant & addition of equipment limited to handling enrichments up to 10% U-235
ROBERTSON, N C, LANDRUM, L H Spencer Chemical Co 5B/05/14 PRICE, H L Atomic Energy Commission 4pp 17288 129

--8302240246 Forwards application for SNM license, authorizing handling of U-235 in processing U hexafluoride to dioxide or scrap to purified nitrate or oxide
BRQW, J R Spencer Chemical Co 57/09/15 PRICE, H L Atomic Energy Commission 1p 17288 133

--8302240253 Application for SNM license, authorizing handling of U-235 in processing U hexafluoride to dioxide or scrap to purified nitrate or oxide
Spencer Chemical Co 57/09/15 27pp 17288 134

DOCKET 70-0212 IOWA, UNIV OF, IOWA CITY, IA

8302280521 Confirms 830224 telcon re NRC 830301 site visit to begin acceptance appraisal required prior to cooperative agreement between NRC & Univ Hygienic Lab Meeting agenda encl
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/24 HAUGLER, H J Iowa, Univ of 2pp 17309 048

DOCKET 70-0223 CALIFORNIA, UNIV OF, LOS ANGELES, CA

8302270050 Addl response to FOIA request for documents re UCLA lab & research reactors Forwards documents listed on Apps A & B App B documents partially withheld commercial & financial info (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 82/12/30 HIRSCH, D CBS News, CBS, Inc 3pp 17240 329

--8302220063 Safeguards Insp Rept 80 111-16 on 710114 No noncompliance noted Major areas inspected audit of records, repts & source documents, review of written matl controls & accounting procedures & physical inventory of SNM
RIZZOLO, V N Atomic Energy Commission 71/01/25 7pp 17241 002

--8302220067 IE Safeguards Insp Repts 50-142/75-03 & 70-0223/75-01 on 750520 No noncompliance noted Major areas inspected review of records, repts, source documents & procedures & physical inventory of SNM
KOBORI, Y, RIZZOLO, V N Region 5, San Francisco, Office of the Director 75/06/18 7pp 17241 009

--8302220130 IE Safeguards Insp Rept 50-142/80-01 & 70-0223/80-01 on 800211-12 No noncompliance noted Major areas inspected compliance w/applicable sections of regulations
HAYADA, G Region 5, San Francisco, Safeguards Branch 80/02/25 3pp 17241 072

--8302220135 Forwards IE Safeguards Insp Repts 50-142/80-01 & 70-0223/80-01 on 800211 12
NORDERHAUS, L R Region 5, San Francisco, Safeguards Branch 80/02/26 BROWN, H V California, Univ of, Los Angeles 2pp 17241 070

DOCKET 70-0250 BOEING CO, SEATTLE, WA

8302170139 IE Insp Findings & Licensee Ack dtg 821110 of License SNM-255 Insp findings no violations observed
Region 5, Office of Director 82/11/10 1p 17180 214

DOCKET 70-0364 BARCOCK & WILCOX CO, APOLLO, PA

8302070031 Informs of personnel change WL Coleman, manager of PA operations of nuclear power generation div, effective 821001
AUSTIN, M A Babcock & Wilcox Co 82/10/08 HAYNES, R C Region 1, Office of Director 1p 17062 360

8302090189 Forwards Amend 18 to License SNM-414, revising Spec I-1 re SNM byproduct & source matl limitations & Spec I-2 re authorized activities
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/21 AUSTIN, M A Babcock & Wilcox Co 2pp 17132 079

--8302090195 Amend 18 to License SNM-414, revising Spec I-1 re SNM byproduct & source matl limitations & Spec I-2 re authorized activities
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/21 9pp 17132 081

--8302090200 Safety evaluation supporting issuance of Amend 18 to License SNM-414
BURKHARDT, W, ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/01/20 1p 17132 090

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC, UNCASVILLE, CT

8302040616 Forwards list of interim measures licensee will provide until final upgrade physical protection plan const/matl installation is completed List withheld (ref 10CFR2 790)
GUSTAFSON, R B United Nuclear Corp 82/04/06 EVANS, L J Fuel Facility Safeguards Licensing Branch 1p 17042 041

8302040143 Revises products physical protection plan to show Federal Spec FF-P-110F as std for combination locks in lieu of UL-768 No commercially available combination padlocks meet UL-768 specs Plan page withheld
GUSTAFSON, R B United Nuclear Corp 82/04/07 EVANS, L J Fuel Facility Safeguards Licensing Branch 1p 17043 124

8302070012 Forwards status rept for June 1982 re progress of const items listed in schedule of Chapter 13 of physical protection plan for SNM Encl withheld
GUSTAFSON, R B United Nuclear Corp 82/07/13 EVANS, L J Fuel Facility Safeguards Licensing Branch 1p 17045 350

8302080125 Forwards status rept for Jul 1982 re progress of const item listed in physical protection plan, Chapter 13 schedule Rept withheld
GUSTAFSON, R B United Nuclear Corp 82/08/03 EVANS, L J Fuel Facility Safeguards Licensing Branch 1p 17105 068

8302070137 Forwards Aug 1982 status rept re progress of const items listed in physical protection plan for SNM, Chapter 13 schedule Rept withheld (ref 10CFR23 21)
GUSTAFSON, R B United Nuclear Corp 82/09/09 EVANS, L J Fuel Facility Safeguards Licensing Branch 1p 17065 358

DOCKETED ITEMS

B302080074 Requests 3-wk extension to complete receiver measurements within 30 days or receipt of fuel feed matl Extension requested for two shipments extending due dates to B30128 & B30203 Delay due to matl & equipment problems
COLLIPPY, T J United Nuclear Corp 83/01/12 SMITH, C N Fuel Facility Safeguards Licensing Branch 3pp 17106 151

B302030528 Forwards IE Insp Rept 70-0371/82-14 on B21110-12 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/01/21 AMY, O O United Nuclear Corp 2pp 17007 163

--B302030531 Notice of violation from insp on B21110-12
* Division of Engineering & Technical Programs 83/01/21 2pp 17037 165

--B302030537 IE Insp Rept 70-0371/82-14 on B21110-12 Noncompliance noted ventilation flow in wrong direction, fuel vault & trailers containing SNM not properly posted & differential pressure across filters not measured
CLEMONS, P, KINNEY, W, SHAIKAWY, M Division of Engineering & Technical Programs 83/01/19 7pp 17007 167

B302040447 Submits rationale for using "&/or" phase in drafting environ sampling for nonradioactive matls Position stated in NRC B30114 ltr should be reconsidered Hearing may be only path open under current requests
KIRK, W F United Nuclear Corp 83/01/21 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 7pp 17042 331

B302010334 Forwards IE Safeguards Insp Rept 70-0371/82-16 on B21214-16 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/01/24 AMY, O O United Nuclear Corp 2pp 16973 018

--B302010336 IE Safeguards Insp Rept 70-0371/82-16 on B21214-16 No noncompliance noted Major areas inspected security plan & implementing procedures
SMITH, Q C, GODY, A T Division of Engineering & Technical Programs 83/01/18 2pp 16973 020

B302180258 Forwards IE Safeguards Insp Rept 70-0371/82-15 on B21213-17 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/02 AMY, O O United Nuclear Corp 2pp 17215 239

--B302180264 IE Safeguards Insp Rept 70-0371/82-15 on B21213-17 No noncompliance noted Major areas inspected measurement control program & shipper-receiver verification
ZIBULSKY, H, GODY, A T Region 1, Office of Director 83/01/31 3pp 17215 241

B302220482 Advises of issuance of Amend 19 to License SNM-368, authorizing fabrication of new fuel parts New Page 10 O-7d of Part 1 dtd B20127 should be added to Annex D of license
PAGE, R O Uranium Fuel Licensing Branch 83/02/09 KIRK, W F United Nuclear Corp 1p 17234 358

--B302220484 Safety evaluation recommending approval of amend application authorizing fabrication of new fuel parts
BIDINGER, O H, CRQW, N T Uranium Fuel Licensing Branch 83/02/09 2pp 17234 359

DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC

B302090534 Forwards radiological emergency plan for matls licenses at NBS, in response to NRC order to prepare radiological contingency plan for License SNM-362 implementing procedures will be prepared upon receipt of NRC approval
PEVEY, L E Commerce, Dept of, National Bureau of Standards 82/09/03 PAGE, R O Uranium Fuel Licensing Branch 1p 17108 302

--B302090538 Radiological emergency plan for matls licenses at NBS
* Commerce, Dept of, National Bureau of Standards 82/09/03 8pp 17108 303

B302010624 Ack receipt of B30111 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0398/82-05
MARTIN, T T Division of Engineering & Technical Programs 83/01/26 PEVEY, L E Commerce, Dept of, National Bureau of Standards 1p 16980 279

--B302010633 Responds to NRC B21229 ltr re violation noted in IE Insp Rept 70-0398/82-05 Corrective actions principal operator of compactor individually instructed on compactor operating instructions on B21206 & entire staff counseled on B21203
PEVEY, L E Commerce, Dept of, National Bureau of Standards 83/01/11 MARTIN, T T Division of Engineering & Technical Programs 1p 16980 280

B302250231 Forwards IE Safeguards Insp Rept 70-0398/83-01 on B30110-21 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/10 PEVEY, L E Commerce, Dept of, National Bureau of Standards 2pp 17295 217

--B302250239 IE Safeguards Insp Rept 70-0398/83-01 on B30110-21 No noncompliance noted Major areas inspected Facility organization & operation, physical inventory, records & repts & ngt or nuclear matls control sys
BELLA, R A T A, WOLTER, F F, GODY, A T Region 1, Office of Director 83/02/09 4pp 17295 219

DOCKET 70-0470 NATIONAL AERONAUTICS & SPACE ADMIN, GREENBELT, MD

B302070236 IE Insp Findings & Licensee Ack dtd B30126 of Licenses 19-05748-02, 19 05748-03 & SNM-761 Insp findings no noncompliance noted
FRIEDMAN, L F Region 1, Office of Director 83/01/26 1p 17031 001

DOCKET 70-0687 UNION CARBIDE CORP, TUCEDG, NY

B302010552 Ack receipt of B30107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0687/82-07
MARTIN, T T Division of Engineering & Technical Programs 83/01/26 MCCOY, J M Union Carbide Corp 1p 16982 333

--B302010559 Responds to NRC B21206 ltr re violations noted in IE Insp Rept 70-0687/82-07 Corrective actions polyethylene bag replaced by rigid secondary container & proper signs posted in new waste storage facility area
MCCOY, J M Union Carbide Corp 83/01/07 MARTIN, T T Division of Engineering & Technical Programs 1p 16982 334

DOCKET 70-0734 QA TECHNOLOGIES, INC, SAN DIEGO, CA

B302080930 Confirms conversation re inability to submit License SNM-644 renewal questions by B21001 Meeting planned for B21001 & 04 to discuss new plan for ltr submittal
MOWRY, W R QA Technologies, Inc /General Atomic Co 82/09/24 CRCW, H T Office of Nuclear Material Safety & Safeguards, Director 1p 17108 011

B302250315 Forwards IE Insp Rept 70-0734/83-02 on B30110-14 & notice of violation
BROCK, H C Division of Radiological Safety & Safeguards Program 83/02/10 PARKER, J W QA Technologies, Inc /General Atomic Co 2pp 17291 038

--B302250316 Notice of violation from insp on B30110-14
THOMAS, R D Region 5, Office of Director 83/02/10 1p 17291 040

--B302250317 IE Insp Rept 70-0734/83-02 on B30110-14 Noncompliance noted alarm detectors monitoring SNM storage areas deactivated for 45 minutes
BROCK, H C, THOMAS, R D, BROCK, H C Division of Radiological Safety & Safeguards Program 83/02/10 11pp 17291 041

DOCKET 70-0754 GENERAL ELECTRIC CO, PLASANTON, CA

B302040528 Repts on decontamination & survey effort at Advanced Fuels Lab, starting at point where glove boxes & associated equipment removed from lab area
CUNNINGHAM, R E General Electric Co 82/12/16 General Electric Co 102pp 17050 257

B302080034 Forwards request for revalidation of existing route for shipment of irradiated reactor fuel, previously approved per 10CFR73 Encl withheld (ref 10CFR2 790)
KIRKLAND, M H General Electric Co 82/11/30 HILLMAN, C R Office of Nuclear Material Safety & Safeguards, Director 3pp 17106 360

B302080104 Forwards request for revalidation of existing route for shipment of irradiated reactor fuel, previously approved per 10CFR73 Request withheld (ref 10CFR2 790)
KIRKLAND, M H General Electric Co 82/12/10 HILLMAN, C R Office of Nuclear Material Safety & Safeguards, Director 1p 17106 015

B302080076 "Effluent Monitoring Rept, Jul-Dec 1982"
BEST, R E General Electric Co 83/01/17 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 1p 17106 150

DOCKETED ITEMS

8302160364 Response to NRC 830117 response to ASLB 821112 & 19 memoranda & orders requesting views on OE 821105 & 23 procedural requests Also replies to OE 830127 response to NRC response Certificate of Svc encl
TURK, J Affiliation Unknown 83/02/02 Atomic Safety and Licensing Board Panel 7pp 17169 178 24X Fiche 50-070.83/02/02, 8302160364

8302240010 Notice of SE Turk appearance in & DT Buranson withdrawal from proceeding Certificate of Svc encl
TURK, S E, SMANBDN, D T Hearing Branch 1 83/02/22 4pp 17272 335 24X Fiche 50-070.83/02/22.8302240010

DOCKET 70-0820 UNITED NUCLEAR CORP, WOOD RIVER JCT, RI

8302080383 Forwards response to NRC 820412 comments on "Detailed Soil Decontamination Plan" Site Characterization Survey will be forwarded
GREGO, R J United Nuclear Corp 82/08/31 CROW, W T Uranium Fuel Licensing Branch 6pp 17108 004

8302090129 Confirms verbal agreement re painting steelwork & underside of steel roof decking w/primer paint on 821129
HELQESON, K A United Nuclear Corp 82/11/23 CROW, W T NRC - No Detailed Affiliation Given 1p 17119 325

8302040024 Requests verification survey of Section I areas of Wood River Junction, RI facility
GREGO, R J United Nuclear Corp 83/01/13 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 2pp 17043, 275

DOCKET 70-1062 TODD SHIPYARDS CORP, GALVESTON, TX

8302230503 Forwards IE Insp Rept 70-1062/83-01 substantiating licensee survey results & indicating that facility may be released for unrestricted use
CAIN, C L Division of Resident, Reactor Project & Engineering Programs 83/02/11 CROW, W T Uranium Fuel Licensing Branch 1p 17246 177

--8302230509 IE Insp Rept 70-1062/83-01 in 830118 No noncompliance noted Major areas inspected confirmatory radiation survey
CAIN, C L Division of Resident, Reactor Project & Engineering Programs EVERETT, R J Region 4, Office of Director 83/01/26 4pp 17246 178

DOCKET 70-1100 COMBUSTION ENGINEERING, INC, WINDSOR, CT

8302070054 Responds to request for addl info supporting 820514 license renewal application Resolution of NRC comments & sample insurance audit encl
LICHTENBERGER Combustion Engineering, Inc 82/10/04 PAGE, R Q Uranium Fuel Licensing Branch 4pp 17062 350

8302180157 Effluent releases rept for Jul-Dec 1982.
SHEERAN, R E Combustion Engineering, Inc 83/02/08 Region 1, Office of Director 1p 17216 224

8302220146 Ack receipt of 830124 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1100/82-11
MARTIN, T T Division of Engineering & Technical Programs 83/02/08 LICHTENBERGER Combustion Engineering, Inc 2pp 17233, 287

--8302220153 Responds to NRC 821229 ltr re violation noted in IE Insp Rept 70-1100/82-11 Corrective actions incoming
Model CE-250-2 shipping containers monitored on external surfaces of package for radioactive contamination
PLANAM, F J Combustion Engineering, Inc 83/01/24 MARTIN, T T Division of Engineering & Technical Programs 2pp 17233, 287

DOCKET 70-1113 GENERAL ELECTRIC CO, WILMINGTON, NC

8302080101 Identifies corrective actions re receipt of eight shipping containers containing SNM SNM identified booked into accountability ledgers & entered into computerized tracking sys Requests approval of actions
VAUGHAN, C M General Electric Co 82/07/15, EVANS, L J Fuel Facility Safeguards Licensing Branch 3pp 17106, 091

8302080033 Forwards comments & action item responses re license conditions for 1-yr renewal of License SNM-1097, per meeting in Wilmington, DE Other issues re 810527 license renewal application not addressed
VAUGHAN, C M General Electric Co 82/09/24 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 4pp 17106 356

8302040586 Application for amend of License SNM-1097, to construct U process mgt facilities
VAUGHAN, C M General Electric Co 82/12/14 EVANS, L J Office of Nuclear Material Safety & Safeguards, Director 9pp 17042, 207

8302150425 Forwards IE Safeguards Insp Rept 70-1113/83-01 on 830103- No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/01/19 LONG, J A General Electric Co 2pp 17155-213.

--8302150429 IE Safeguards Insp Rept 70-1113/83-01 on 830103-07 No noncompliance noted Major areas inspected external exposure control, radiological surveys, respiratory protection training & labeling of radiological areas
HOBBS, C M, BARR, K P Division of Engineering & Radiological Safety Programs 83/01/18 6pp 17155 215

8302150030 Ack receipt of IE Insp Rept 70-1113/83-01 on 830103-07 No proprietary info
VAUGHAN, C M General Electric Co 83/01/25 STOHR, J P Division of Emergency Preparedness & Materials Safety 1p 17146 002

8302080471 Forwards revised License SNM-1097, changing expiration date to 840131, adding environ monitoring license conditions & incorporating previous license amendments
PAGE, R Q Uranium Fuel Licensing Branch 83/02/01, VAUGHAN, C M General Electric Co 18pp 17071-328

--8302080474 Revised License SNM-1097 for OE, changing expiration date to 840131, adding environ monitoring license conditions & incorporating previous license amendments.
PAGE, R Q Office of Nuclear Material Safety & Safeguards, Director 83/02/01, 7pp 17071, 346

--8302080476 Guidelines for decontamination of facilities & equipment prior to release for unrestricted use or termination of licenses for byproduct, source or SNM
* Office of Nuclear Material Safety & Safeguards, Director 82/07/31 5pp 17071 353

--8302080477 Safety evaluation supporting renewal of License SNM-1097 for 1-yr period.
BIDINGER, G H, SHUM, E Y, CROW, W T Uranium Fuel Licensing Branch 82/12/30 8pp 17071 358

8302080270 PHO-11-83-006, on 830202, Tri-State truck driver reported truck carrying U hexafluoride fired on GE placed truck & cargo in isolation Three deep dents found in cylinders.
No evidence of penetration FBI informed
CORVELL, G P, MCALPINE, E J Region 2, Office of Director 83/02/01 2pp 17056 346

8302220075 Informs that submittal of environ info to cover const of additions to existing process bldg unnecessary introduction of SNM into new additions not authorized
PAGE, R Q Uranium Fuel Licensing Branch 83/02/09 VAUGHAN, C M General Electric Co 1p 17234 173

--8302220079 Safety evaluation recommending const of additions to existing process bldg
BIDINGER, G H Advanced Fuel & Spent Fuel Licensing Branch 83/02/09 1p, 17234 174

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP, PITTSBURGH, PA

8302070553 Forwards "Effluent Semiannual Monitoring Rept for Jul-Dec 1982"
WOODSUM, H C Westinghouse Electric Corp. 83/01/28 Region 1, Office of Director, 1p 17035 210

--8302070560 "Effluent Semiannual Monitoring Rept for Jul-Dec 1982"
WOODSUM, H C Westinghouse Electric Corp 83/01/28 1p, 17035, 211

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

8301250293 Discusses evaluation re adjustment of air sampling vols d to rotometer flow calibr, per IE Insp Rept 70-1151/82-18 Implementation of mod to obtain true air flow reading expected in Jan 1983
SANDERS, C F Westinghouse Electric Corp 82/11/11 OIBSON, A F, Region 2, Office of Director, 1p 16896 360

DOCKETED ITEMS

DOCKET 70-1193 KERR-MCCEE NUCLEAR CORP., OKLAHOMA CITY, OK

8302180168 Forwards IE Safeguards Insp Rept 70-1193/83-01 on 830117-21 & notice of violation Notice of violation withheld (ref 10CFR73.21)
MILLER, J. R. Region 3, Office of Director 83/02/11 SHELLEY, W. J.
Kerr-McCee Nuclear Corp 2pp 17216 102

--8302180173 IE Safeguards Insp Rept 70-1193/83-01 on 830117-21
Noncompliance noted failure to maintain perimeter fence properly Details withheld (ref 10CFR73.21)
CHRISTOFFER, O., CREED, J. R. Region 3, Office of Director
83/02/09 1p 17216 104

DOCKET 70-1201 BABCOCK & WILCOX CO., LYNCHBURG, VA

8302070168 Advises that no fee received re licensee 820719 request for extension of time to complete physical inventory Fee due
WEISS, D. License Fee Management Branch 82/08/11 FORD, J. T.
Babcock & Wilcox Co. 1p 17065 353

--8302070178 Requests 14-day extension of time to complete physical inventory Extension necessary due to sample turnaround problems w/Apollo Lab
FORD, J. T. Babcock & Wilcox Co 82/07/19 EVANS, L. J. Fuel Facility Safeguards Licensing Branch. 2pp. 17065 351

8302080381 Forwards water quality data from Buchanan & Cartersville stations for Oct 1979 - Sept 1980
FORD, J. T. Babcock & Wilcox Co. 82/08/27 PAOER, O. Uranium Fuel Licensing Branch. 20pp. 17107 083

8302040494 Application for amend to License SNM-116B, revising Pp 4-2, 4-6, 7-1 & B-1 of radiological contingency plan
Organization chart encl
FORD, J. T. Babcock & Wilcox Co 82/09/24 PAOER, O. Uranium Fuel Licensing Branch 4pp. 17044 357

8302080379 Forwards info re revs to license conditions, fundamental nuclear matl control plan & page-date index. Encl withheld (ref 10CFR2.790)
FORD, J. T. Babcock & Wilcox Co 82/11/24 EVANS, L. J. Fuel Facility Safeguards Licensing Branch 1p 17107 103

8302090050 Forwards response to 820831 questions, revised Pp 5 & 6 & 7 of fundamental nuclear matl control plan & revised Pp 1, 2 & 3 of page-date index Encl withheld (ref 10CFR2.790(d))
FORD, J. T. Babcock & Wilcox Co 82/11/24 EVANS, L. J. Fuel Facility Safeguards Licensing Branch 1p 17121 362.

8302160393 Forwards "Effluent Monitoring Rept, Jul-Dec 1982"
SPEIGHT, C. W. Babcock & Wilcox Co 83/01/24 Director's Office, Office of Inspection and Enforcement 1p 17164 271

--8302160397 "Effluent Monitoring Rept, Jul-Dec 1982"
SPEIGHT, C. W. Babcock & Wilcox Co 83/01/24 1p 17164 272

8302150409 Forwards IE Safeguards Insp Rept 70-1201/83-01 on 830117-21
No noncompliance noted
STOHR, J. P. Division of Emergency Preparedness & Materials Safety
83/02/09 ALTO, R. A. Babcock & Wilcox Co 2pp. 17148 168

--8302150411 IE Safeguards Insp Rept 70-1201/83-01 on 830117-21
No noncompliance noted Major areas inspected physical inventory observation, shipping & receiving & records & repts Details withheld (ref 10CFR2.790)
LANFORD, J. B., RICHARDS, B. L., MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety 83/02/09. 1p 17148 170.

DOCKET 70-1257 EXXON NUCLEAR CO., INC., RICHLAND, WA

8302040120 Forwards draft copies of Rev 12 to Fundamental Nuclear Matls Control Plan, XN-12, "Nuclear Matls Safeguards Procedures Description for Fuel Fabrication Plants." for review Plan withheld (ref 10CFR2.790).
SCHEIDT, R. A. Exxon Nuclear Co., Inc (subs of Exxon Corp.)
82/05/06. SMITH, C. M. Fuel Facility Safeguards Licensing Branch 1p. 17043 169

8302040545 Rev 6 to application for renewal of License SNM-1227
Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 82/05/31. 39pp 17059 299.

8302040538 Application for amend of License SNM-1227, to add facilities addition to U dioxide bldg Contaminated maint shop & scrap recovery operation to be relocated into new addition
MALODY, C. W. Exxon Nuclear Co., Inc (subs of Exxon Corp.)
82/06/02 CROW, H. T. Uranium Fuel Licensing Branch 11pp 17059 338

8302040533 Application for amend of License SNM-1227, to provide for single hypalon-lined lagoon as contingency for storage of chemical process liquid wastes if existing storage capacity exceeded
MALODY, C. W. Exxon Nuclear Co., Inc (subs of Exxon Corp.)
82/07/27 CROW, H. T. Uranium Fuel Licensing Branch 4pp 17050 359

8302040463 Forwards "Groundwater Quality & Flow Characteristics in Vicinity of Exxon Nuclear Co, Inc Fuel Fabrication Facility Richland, WA," per License Condition 19 of License SNM-1227
MALODY, C. W. Exxon Nuclear Co., Inc (subs of Exxon Corp.)
82/10/12 CUNNINGHAM, R. E. Division of Fuel Cycle & Material Enrichment 1p 17050 188

--8302040466 "Groundwater Quality & Flow Characteristics in Vicinity of Exxon Nuclear Co, Inc Fuel Fabrication Facility, Richland, WA"
VEENSTRA, R. C. J-U-B Engineers, Inc XN-JUB-82-86 02/10/12 57pp 17050 189

8302180166 Forwards IE Insp Rept 70-1257/82-07 on 821204-10 & notice of violation
SPENCER, G. B. Division of Radiological Safety & Safeguards Program
83/01/19 MALODY, C. W. Exxon Nuclear Co., Inc (subs of Exxon Corp.) 2pp 17216 124

--8302180170 Notice of violation from insp on 821204-10
THOMAS, R. D. Division of Radiological Safety & Safeguards Program
83/01/19 1p 17216 126

--8302180172 IE Insp Rept 70-1257/82-07 on 821204-10 Noncompliance noted container in shipment of nuclear waste showed visible cracks in bottom
BROCK, B. L., THOMAS, R. D., BROOK, H. C. Division of Radiological Safety & Safeguards Program 83/01/19 10pp 17216 127

8302230297 Ack receipt of 830203 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1257/82-07
BROCK, H. C. Division of Radiological Safety & Safeguards Program
83/02/18 MALODY, C. W. Exxon Nuclear Co., Inc (subs of Exxon Corp.) 1p 17243 008

--8302230300 Responds to NRC 830119 ltr re violation noted in IE Insp Rept 70-1257/82-07 Corrective actions inside surfaces of weld seams of metal buried boxes inspected before waste was put into boxes
MALODY, C. W. Exxon Nuclear Co., Inc (subs of Exxon Corp.)
83/02/03 THOMAS, R. D. Division of Radiological Safety & Safeguards Program 3pp 17243 009

DOCKET 70-1362 HAHNEMANN MEDICAL COLLEGE & HOSP., PHILADELPHIA, PA

8302230262 Ack receipt of 821115 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-02959/82-01 & 70-1362/82-01
MARTIN, T. T. Division of Engineering & Technical Programs
82/11/15 MILLS, L. C. Hahnemann Medical College & Hosp Philadelphia PA 1p 17244 275

--8302230272 Responds to NRC 821022 ltr re violations noted in IE Insp Repts 30-02959/82-01 & 70-1362/82-01 Corrective actions to avoid missing quarterly linearity checks on dose calibrator, calendars kept of test due dates
DAY, J. Hahnemann Medical College & Hosp Philadelphia PA
82/11/15 MARTIN, T. T. Division of Engineering & Technical Programs 4pp. 17244 276

--8302230284 Approves response & corrective actions to NRC 821022 ltr re violations noted in IE Insp Repts 30-02959/82-01 & 70-1362/82-01
MILLS, L. C. Hahnemann Medical College & Hosp Philadelphia PA
82/11/19 MARTIN, T. T. Division of Engineering & Technical Programs 1p. 17244 280

DOCKET 70-1418 NICHIOAN, UNIV OF, ANN ARBOR, MI

8302190126 IE Insp Findings & Licensee Ack dtd 830124-20 of License 21-00215-04, 21-00215-05, SNM-1377, SNM-1329, SNM-1835 & SNM-1398 Insp findings, no violations observed
MULLAUER, J. R. Region 3, Office of Director 83/01/28 1p 17148 001

DOCKETED ITEMS

40

DOCKET 70-1621 DUQUESNE LIGHT CO , PITTSBURGH, PA

8302020005 Forwards Endorsement 4 to NELIA Certificate N-58 & MAELU Certificate M-58
BARNETT, J E Conover & Associates, Inc Insurance 83/01/26
DINITZ, I Assistant Director for State & License Relations 3pp
17005 078

8302020046 Forwards Endorsements 61 & 53 to NELIA Policy NF-226 & MAELU Policy MF-87, respectively
BARNETT, J E Conover & Associates, Inc Insurance 83/01/26
DINITZ, I Antitrust & Economic analysis Branch (Utility Finance)
3pp 17004 336

DOCKET 70-1719 YOUNGSTOWN HOSP ASSOCIATION, YOUNGSTOWN, OH

8302250426 Discusses IE insp of Licenses SNM-1498 & 34-01026-01 on 830208 & forwards notice of violation
BRENIAWSKI, D J Region 3, Office of Director 83/02/22
WISSUCHEK, C Youngstown Hosp Association Youngstown, OH 2pp
17297 032

--8302250433 Notice of violation from insp on 830208 Noncompliance noted
Cs-137 sources used as implants not tested for contamination
& leakage 800125-820518 & from 820518 to present, exceeding
6-month requirement
BRENIAWSKI, D J Region 3, Office of Director 83/02/22 3pp
17297 034

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO , JOPLIN, MO

8302080133 Requests approval of check call frequency schedules for two
forthcoming shipments of strategic quantities of SNM
RUTENKROGER, F Tri-State Motor Transit Co (subs of Georgia Pacific
Corp) 82/08/13 HILLMAN, C HRC - No Detailed Affiliation Given
1p 17103 278

DOCKET 70-1856 MICHIGAN, UNIV OF, ANN ARBOR, MI

8302150126 IE Insp Findings & Licensee Ack dtd 830124-28 of Licenses
21-00215-04, 21-00215-05, SNM-1377, SNM-1529, SNM-1835 &
SUD-1378 Insp findings no violations observed
MULLAUER, J R Region 3, Office of Director 83/01/28 1p
17148 001

DOCKET 70-1866 MACMURRAY COLLEGE, JACKSONVILLE, IL

8212210286 Discusses IE insp of License 12-11030-04 on 821129. No
noncompliance noted Major areas inspected selective exam of
procedures & representative records, observations,
independent measurements & interviews w/personnel
WIEDEMAN, D O Division of Project & Resident Programs 82/12/15
MITCHELL, E J MacMurray College 1p 16497 044

DOCKET 70-1936 TEXAS A&M UNIV , COLLEGE STATION, TX

8302230501 Forwards IE Safeguards Insp Repts 50-128/83-02 &
70-1936/83-02 on 830103-07 No noncompliance noted
MADSEN, O L Division of Resident, Reactor Project & Engineering
Programs 83/02/17 BERG, R R Texas A&M Univ , College Station,
TX 2pp 17257 243 24X Fiche 50-128, 83/02/17, 8302230501

--8302230517 IE Safeguards Insp Repts 50-128/83-02 & 70-1936/83-02 on
830103-07 No noncompliance noted Major areas inspected
nuclear matl control & accountability measurement & controls
& shipping & receiving Details withheld (ref 10CFR2 790)
CALDWELL, R A , KELLY, J A Division of Resident, Reactor Project &
Engineering Programs 83/02/14 1p 17257 243 24X
Fiche 50-128, 83/02/17, 8302230501

DOCKET 70-2199 VETERANS ADMIN MEDICAL CENTER, WASHINGTON, DC

8302230717 Discusses IE insp of Licenses SNM-1605, 08-00942-04 &
08-00942-05 on 830105 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/02/07
GAUVAZZI, A Vet Admin Hosp Wash, D C 2pp. 17257 301

--8302230721 Notice of violation from insp on 830105 Noncompliance noted
failure to perform required surveys & to determine
occupational dose for certain individuals
* Division of Engineering & Technical Programs 83/02/07 2pp
17257 303

DOCKET 70-2467 GOOD SAMARITAN HOSP , POTTSVILLE, PA

8302010436 Recommends that License SNM-1714 be retired per 821229
request Notification must be given within 7 days of
receipt of ltr if action inconsistent w/hosp intent
KINNEMAN, J D Region 1, Office of Director 83/01/25 KOVAL, B
Good Samaritan Hosp , Pottsville, PA 1p 16981 032

--8302010448 Requests termination of License SNM-1714 No nuclear
pacemakers implanted since 790507 & none anticipated
KOVAL, B O Good Samaritan Hosp , Pottsville, PA 82/12/29
KINNEMAN, J D Region 1, Office of Director 2pp 16981 033

DOCKET 70-2479 TRANSNUCLEAR, INC , FALLS CHURCH, VA

8302080037 Requests extension of route approval for Import Licenses
ISNM-1699/ISNM-81017 from 821231 to 831231
HANNETT, B A Transnuclear, Inc 82/10/28 HILLMAN, C Division of
Safeguards 1p 17106 362

8302280040 Requests extension of approval of route from Norfolk, VA to
Allen, SC through 831231
HANNETT, B A Transnuclear, Inc 83/01/18 HILLMAN, C Division of
Safeguards 2pp 17314 298

8302280049 Requests extension of approval of route from Newport News, VA
to Allen, SC through 831231
HANNETT, B A Transnuclear, Inc 83/01/18 HILLMAN, C Division of
Safeguards 2pp 17314 295

8302280095 Requests extension of approval of route from Oakland, CA to
ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 83/01/18 HILLMAN, C Division of
Safeguards 2pp 17314 282

DOCKET 70-2677 GOOD SAMARITAN HOSP , DOWNERS GROVE, IL

8302160217 Discusses IE insp of Licenses 12-17325-01 & SNM-1761 on
830131 No noncompliance noted Major areas inspected,
procedures, observations, measurements & personnel interviews
re radiation safety
WIEDEMAN, D O Region 3, Office of Director 83/02/11 MOORE, P
Good Samaritan Hosp Downers Grove, IL 1p 17163 032

DOCKET 70-2864 MICHIGAN, UNIV OF, ANN ARBOR, MI

8302150126 IE Insp Findings & Licensee Ack dtd 830124-28 of Licenses
21-00215-04, 21-00215-05, SNM-1377, SNM-1529, SNM-1835 &
SUD-1378 Insp Findings no violations observed
MULLAUER, J R Region 3, Office of Director 83/01/28 1p
17148 001

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO , DALLAS, TX

8302080352 Change 2 to application for SNM license, adding Tex-La
Electric Cooperative of TX, Inc as owner & changing beginning
date of license to 830101
GARY, R J Texas Utilities Generating Co 82/08/11 KETZLACH, M
Division of Fuel Cycle & Material Safety 3pp 17107 199

8302040137 Informs that symbol "YGL" assigned as reporting
identification symbol for activities under License SNM-1912
BERNINGTON, O M Material Transfer Safeguards Licensing Branch
82/12/28 GARY, R J Texas Utilities Generating Co 3pp
17043 125

8302230103 Unexecuted Indemnity Agreement I-96, establishing amount
& delineating extent of coverage
SALTZMAN, J Assistant Director for State & License Relations
83/02/14 13pp 17303 085

8302230505 Forwards License SNM-1912, issued to util on 830214 Related
documents encl
ROTHSCHILD, M U Hearing Branch 1. 83/02/18 MILLER, M E , COLE, R ,
MCCLLON, K A Atomic Safety and Licensing Board Panel 14pp,
17245 168 24X Fiche 50-449, 83/02/18, 8302230505

DOCKETED ITEMS

DOCKET 70-2937 PENNSYLVANIA POWER & LIGHT, ALLENTOWN, PA

B302070634 Forwards Endorsements 1B & 5 to NELIA & MAELU Policies NF-262 & MF-107, respectively
CURTIS, N W Pennsylvania Power & Light Co 83/01/17 PAQER, R O
Uranium Fuel Licensing Branch 3pp 17059 359

DOCKET 70-2945 UNION ELECTRIC CO, ST LOUIS, MO

B302080393 Documents B20810 & 11 telcons re addl info supplied in support of B10626 SNM license application.
SCHINELL, D F Union Electric Co 82/08/11 DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 5pp 17107 354

DOCKET 70-2946 LOUISIANA POWER & LIGHT CO, NEW ORLEANS, LA

B302040029 Forwards responses to questions asked in B30103 telcon between B Serini & B Wilkins re SNM license application.
Middle South Svcs conducts training to qualify sufficient number of fuel inspectors
MAURIN, L V Louisiana Power & Light Co 83/01/07 Office of
Nuclear Material Safety & Safeguards, Director 8pp 17043 267

B302230055 Forwards License SNM-1913 for receipt, possession, insp & storage of U-235 isotope in fuel assemblies & two Pu/Be neutron sources Evaluation of license application dtd B30209 also encl
PAQER, R O Uranium Fuel Licensing Branch 83/02/10 Louisiana Power & Light Co 2pp 17241 326

--B302230041 License SNM-1913 for LA Power & Light Co, authorizing receipt, possession, insp & storage of U-enriched in U-235, contained in fuel assemblies & receipt, possession & use of two Pu/Be neutron sources
PAQER, R O Uranium Fuel Licensing Branch 83/02/09 4pp 17241 328

--B302230048 SER for 810727 application for matls license authorizing receipt, possession, insp & storage of enriched U fuel assemblies & two Pu/Be neutron sources Recommends approval of roval of application & addition of several conditions
SERINI, B L Uranium Fuel Licensing Branch 83/02/09 15pp 17241 332

DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO, PHOENIX, AZ

B302040534 Forwards request for amend of application for SNM license, adding participating util W/o encl
ANDOGNINI, O C Arizona Public Service Co 83/01/11 Office of
Nuclear Material Safety & Safeguards, Director 1p 17042, 234

B302030037 Forwards revised SNM License SNM-1887, authorizing possession of U-235 in fuel assemblies, ex-core detectors & Pu-Be sources
PAQER, R O Uranium Fuel Licensing Branch 83/01/27 ANDOGNINI, O C
Arizona Public Service Co 2pp 17023 331

--B302030045 Revised SNM License SNM-1887, authorizing possession of U-235 in fuel assemblies, ex-core & in-core detectors & Pu-Be sources
PAQER, R O Uranium Fuel Licensing Branch 83/01/26 4pp 17023 333

--B302030050 Safety evaluation supporting issuance of revised License SNM-1887, in response to util 810817 application for SNM license to authorize possession of fuel assemblies, ex-core & in-core detectors & Pu-Be sources
KETZLACH, N, CROW, W T Uranium Fuel Licensing Branch 83/01/27 14pp 17023 337

DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

B302080005 Forwards Rev 2 to "New Fuel Storage Physical Security Plan" Rev withheld (ref 10CFR73 21)
BOUCHEY, O D Washington Public Power Supply System 82/07/16
Office of Nuclear Material Safety & Safeguards, Director 1p 17108 015

DOCKET 70-2957 FLORIDA POWER & LIGHT CO, MIAMI, FL

B302080339 Application for license to allow receipt of first shipment of unirradiated reactor fuel on B20809
UHRIG, R E Florida Power & Light Co 82/03/19 CUNNINGHAM, R E
Assistant Director for Fuel Cycle Safety & Licensing 54pp 17107 214

DOCKET 70-2960 KANSAS GAS & ELECTRIC CO, WICHITA, KS

B302080398 Forwards addl info re Wolf Creek Generating Station interim security plan for protection of SNM Info withheld
(ref 10CFR73 21)
KOESTER, O L Kansas Gas & Electric Co 82/12/22 EVANS, L J Fuel
Facility Safeguards Licensing Branch 1p 17105 360

B302040019 Forwards revised response to Question 8 re interim security plan for protection of SNM Statement acknowledging that outdated responses destroyed requested Response withheld
(ref 10CFR73 21)
KOESTER, O L Kansas Gas & Electric Co 83/01/17 EVANS, L J Fuel
Facility Safeguards Licensing Branch 1pp 17043 278

B302040035 Requests current review schedule be maintained in response to B21202 ltr requesting addl info re SNM license application for receipt, possession & storage of fresh fuel assemblies, fission chambers & fission counter
KOESTER, O L Kansas Gas & Electric Co 83/01/21 DAVIS, J O
Office of Nuclear Material Safety & Safeguards, Director 45pp 17043 179

DOCKET 70-2964 CONSUMERS POWER CO, JACKSON, MI

B302040112 Forwards security plan for protection of SNM of low strategic significance Plan will be implemented prior to first arrival of fuel at site & will be replaced by permanent plan Plan withheld (ref 10CFR73 21)
COOK, J W Consumers Power Co 82/06/22 DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 2pp 17043 170

B302040512 Informs that security measures identified in B20622 ltr re security plan for fuel no longer apply to fission chamber assemblies
COOK, J W Consumers Power Co 82/08/12 DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 2pp 17044 353

B302220043 Forwards License SNM-1913, issued on B30210 & related matls License does not relate to any issues being adjudicated & no ASLB action required
TURK, S E Hearing Branch 1 83/02/18 WOLFE, S J, JORDAN, W H,
FOREMAN, H Atomic Safety & Licensing Board Panel 22pp 17233 175 24X Fiche 50-392, 83/02/18, B302220043

DOCKET 70-2965 CONSUMERS POWER CO, JACKSON, MI

B302040112 Forwards security plan for protection of SNM of low strategic significance Plan will be implemented prior to first arrival of fuel at site & will be replaced by permanent plan Plan withheld (ref 10CFR73 21)
COOK, J W Consumers Power Co 82/06/22 DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 2pp 17043 170

B302040512 Informs that security measures identified in B20622 ltr re security plan for fuel no longer apply to fission chamber assemblies
COOK, J W Consumers Power Co 82/08/12 DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 2pp 17044 353

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO, CLEVELAND, OH

B302040597 Application for amend of SNM license, so that physical security plan would be effective, not interim security plan
DAVIDSON, D R Cleveland Electric Illuminating Co 82/09/30
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 6pp 17042 199

DOCKET 70-2973 COMMONWEALTH EDISON CO, CHICAGO, IL

B302080349 Application for amend of License SNM-1860, to receive, possess & store unirradiated fuel assemblies Authorization needed by B30301
TRAMM, T R Commonwealth Edison Co 82/10/06, DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 9pp 17107 204

DOCKETED ITEMS

40

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0345 CAROLINA POWER & LIGHT CO

B302090236 Forwards GA program approval for Radioactive Matl Package 0345, Rev 2
MACDONALD, C E Transportation Branch 83/01/19 UTLEY, E E
Carolina Power & Light Co 1p 17121 353

--B302090242 GA program approval for Radioactive Matl Package 0345, Rev 2
MACDONALD, C E Transportation Branch 83/01/19 1p 17121 354

DOCKET 71-0476 TEXAS, STATE OF

B302090134 Forwards GA program approval for Radioactive Matl Package 0476, Rev 0
MACDONALD, C E Transportation Branch 83/01/19 BLAKE, C L
Midwest Insp Services, Inc 1p 17121 348

--B302090144 GA program approval for Radioactive Matl Package 0476, Rev 0
MACDONALD, C E Transportation Branch 83/01/19 1p 17121 349

DOCKET 71-0491 MID-CON INSPECTION SERVICES, INC

B302040010 Forwards GA program for shipping packages per 10CFR71.51
OLSEN, C R Mid-Con Inspection Services, Inc 83/01/05 Material
Control Licensing Branch 1p 17043 299

--B302040013 GA program for Part 71 requirements
* Mid-Con Inspection Services, Inc 82/10/15 4pp 17043 300

B302080084 Forwards GA program for shipping packages
OLSEN, C R Mid-Con Inspection Services, Inc 83/01/05 Region 4,
Office of Director 1p 17106 137

--B302080086 GA program
* Mid-Con Inspection Services, Inc 82/10/15 4pp 17106 138

B302100474 Forwards GA program approval for Radioactive Matl Package 0491, Rev 0
MACDONALD, C E Transportation Branch 83/02/01 OLSEN, C R
Mid-Con Inspection Services, Inc 1p 17143 273

--B302100481 GA program approval for Radioactive Matl Package 0491, Rev 0
MACDONALD, C E Transportation Branch 83/02/01 1p 17143 274

DOCKET 71-5450 MODEL RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP

B302280564 Requests registration as user of Models RCC-1, RCC-2, RCC-3 or RCC-4
BROWN, C D Exxon Nuclear Co, Inc (subs of Exxon Corp)
83/01/31 MACDONALD, C E Transportation Branch 1p 17322 165

DOCKET 71-5805 MODEL CNS-3-55, CHEM-NUCLEAR SYSTEMS, INC

B302280236 Advises that 801126 application for renewal of Certificate of Compliance 5805 for Model CNS 3-55 packaging considered satisfactory for timely renewal Rev 7 to Certificate of Compliance 5805 will not expire until final determination
MACDONALD, C E Transportation Branch 83/02/22 MARSH, C A
Chem-Nuclear Systems, Inc 2pp 17322 213

DOCKET 71-5814 MODEL NRBK-41, -42 & -43, ENERGY, DEPT OF

B302030147 Advises that request to amend Certificate of Compliance 5814 needed to include general license condition in certificate
MACDONALD, C E Transportation Branch 83/01/26 HENRY, L Q New York State Univ of, Buffalo 1p 17023 312

DOCKET 71-5926 MODEL GE-100, GENERAL ELECTRIC CO

B302040012 Advises that DM Riddle has replaced HO Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-5957 MODEL BMI-1, BATTELLE COLUMBUS LABORATORY

B302090083 Notification of registration as user of Model BMI in response to 821201 request.
MACDONALD, C E Transportation Branch 83/01/21 FIEDLER, P B
General Public Utilities - GPU Service Corp 1p 17119 296

DOCKET 71-6144 MODEL B-2, U S ECOLOGY

B302090136 Notification of registration as user of Models B-2 & GE-1400 in response to 821212 request Approved GA program required for registration under 10CFR71.12(b) W/o encl
MACDONALD, C E Transportation Branch 83/01/25 AYRES, J M AWC, Inc 1p 17119 362

DOCKET 71-6272 MODEL 6272, U S ECOLOGY

B302040021 Responds to 830105 request for addl info to support application for revised contents for Model 6272 & 6400 packaging Info will be sent by 830215.
MOSE, R M Energy, Dept of 83/01/19 MACDONALD, C E
Transportation Branch 1pp 17043 277

DOCKET 71-6346 MODEL FSV-1, GENERAL ATOMIC CO

B302030122 Requests registration as user of Model FSV-1
MUSOLF, D Northern States Power Co 83/01/05 MACDONALD, C E
Transportation Branch 1p 17028 330

B302090141 Notification of registration as user of Model FSV-1 in response to 830105 request
MACDONALD, C E Transportation Branch 83/01/25 MUSOLF, D
Northern States Power Co 1p 17119 361

B302030224 Notification of correction of 821105 registration as user Correct model is Model FSV-1
MACDONALD, C E Transportation Branch 83/01/26 COONEY, J J
Philadelphia Electric Co 1p 17023 310

B302020063 Informs that schedule for providing addl info to 801009 application for amend to Model FSV-1 package not received Denial will be issued unless schedule received within 20 days
MACDONALD, C E Transportation Branch 83/01/27 MONRY, W R GA Technologies, Inc /General Atomic Co 1p 17241 202.

DOCKET 71-6347 MODEL FSV-3, GENERAL ATOMIC CO

B302030224 Notification of correction of 821105 registration as user Correct model is Model FSV-1
MACDONALD, C E Transportation Branch 83/01/26 COONEY, J J
Philadelphia Electric Co 1p 17023 310

DOCKET 71-6386 MODEL 235R001, ENERGY, DEPT OF

B302080402 Forwards Rev 7 to Certificate of Compliance 6386 for Model 235R001
MACDONALD, C E Transportation Branch 83/01/21 ENGEL, W P
Energy, Dept of. 1p 17100 001.

--B302080404 Certificate of Compliance 6386, Rev 7 for Model 235R001 Approval record encl
MACDONALD, C E Transportation Branch 83/01/21 5pp 17100 002

DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP

B302040021 Responds to 830105 request for addl info to support application for revised contents for Model 6272 & 6400 packaging Info will be sent by 830215.
MOSE, R M Energy, Dept of 83/01/19 MACDONALD, C E
Transportation Branch 1pp 17043 277

B302220088 Forwards Rev 12 to Certificate of Compliance 6400 for Model 6400
MACDONALD, C E Transportation Branch 83/02/10 NARDI, A J
Westinghouse Electric Corp 3pp 17234 175

--B302220090 Certificate of Compliance 6400, Rev 12, for Model 6400 Approval record encl.
MACDONALD, C E Transportation Branch 83/02/10 7pp 17234 178

DOCKETED ITEMS

DOCKET 71-6441 MODEL D20 POWER UNIT, ENERGY, DEPT OF

8302220101 Forwards Rev 2 to Certificate of Compliance 6441 for Model D20
MACDONALD, C E Transportation Branch 83/02/10 ENGEL, W P
Energy, Dept of Ip 17234 190

--8302220103 Certificate of Compliance 6441, Rev 2, for Model D20 Approval
record encl
MACDONALD, C E Transportation Branch 83/02/10 4pp 17234 191

DOCKET 71-6550 MODEL 6-QS-1, ENERGY, DEPT OF

8302040008 Notifies that 1 Ci radium beryllium source will be shipped
on or about 830401, using NRC package approved for use by
LLL
PEVEY, L E Commerce, Dept of, National Bureau of Standards
83/01/19 Office of Nuclear Material Safety & Safeguards, Director
Ip. 17043 306

DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

8302280568 Requests registration as user of Models HN-100, Series 2 & 3
& HN-200
HIS, F J Rochester Gas & Electric Corp 83/02/10 MACDONALD, C E
Transportation Branch. Ip 17322 166

DOCKET 71-6642 MODEL 4 5 TON CF, ENERGY, DEPT OF

8302180537 Forwards Rev 2 to Certificate of Compliance 6642 for
Model 4 5-ton Cf
MACDONALD, C E Transportation Branch 83/02/09 PRICHARD, R P
Energy, Dept of 2pp 17221 240

--8302180538 Certificate of Compliance 6642, Rev 2, for Model 4 5-ton Cf
Approval record encl.
MACDONALD, C E Transportation Branch 83/02/09 4pp 17221 242

DOCKET 71-6679 MODEL 6679, U S ECOLOGY

8302080437 Forwards Rev 5 to Certificate of Compliance 6679 for
Model 6679
MACDONALD, C E Transportation Branch 83/01/24 SCOVILLE, J J US
Ecology, Inc (Formerly Nuclear Engineering) 3pp 17071 111

--8302080439 Certificate of Compliance 6679, Rev 5 for Model 6679
Approval record encl
MACDONALD, C E Transportation Branch 83/01/24 7pp 17071 114

DOCKET 71-6697 MODEL: GE-8900, GENERAL ELECTRIC CO

8302040012 Advises that DH Riddle has replaced HD Richardson as
radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation
Branch Ip 17043 298

DOCKET 71-6698 MODEL: NFS-4, NUCLEAR FUEL SERVICES, INC

8302040106 Requests approval on behalf of Comm Ed, of route for planned
irradiated fuel shipment from BMI to Zion Proposed route
described
DANESE, F L Nuclear Assurance Corp. 82/09/14 Division of
Safeguards 2pp. 17043 172

8302080009 Requests approval of proposed route for planned irradiated
fuel shipment from facility to BMI
DANESE, F L Nuclear Assurance Corp. 82/09/14. Division of
Safeguards 2pp 17108, 013

8302080004 Notifies of planned spent fuel shipment from facility to
BMI per 10CFR73 72. Schedule withheld
DANESE, F L Nuclear Assurance Corp 82/12/01. Region 3, Office
of Director Ip. 17108 016

8302170304 Responds to 830128 ltr requesting further analysis by NRC
of dry shipment of spent fuel & withdrawal of casks from
svc Based on corrections to errors in calculation &
assumptions, more detailed consideration by NRC unwarranted
ODEGAARDEN, R H Transportation Branch 83/02/03 RESNIKOFF, M
Council on Economic Priorities. Ip 17197 087

DOCKET 71-6717 MODEL 6717-B, GAMMA INDUSTRIES

8302040501 Requests registration as user of Gamma Industries Type B
Overpack Model 6717-B
BADIALI, J Eastern Testing & Inspection, Inc 82/12/31
MACDONALD, C E Transportation Branch Ip 17046 297

8302070015 Requests registration as user of Model 6717-B
ROLLINS, M V Southwestern Laboratories 83/01/03 MACDONALD, C E
Transportation Branch Ip 17046 349

8302030042 Requests registration as user of Models 6717, C-1 &
SPEC 2-T
HEAD, T O Monroe X-Ray Co, Inc 83/01/06 MACDONALD, C E
Transportation Branch Ip 17026 342

8302030048 Requests registration as user of Models 6717, C-1 &
SPEC 2-T
HEAD, K Y H&H X-Ray Services, Inc 83/01/06 MACDONALD, C E
Transportation Branch Ip 17028 335

8302040012 Advises that DH Riddle has replaced HD Richardson as
radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation
Branch Ip 17043 298

8302090094 Notification of registration as user of Model 6717-D in
response to 821210 request
MACDONALD, C E Transportation Branch 83/01/21 GORNEB, J W
Dayton Power & Light Co Ip 17119 300

8302030154 Notification of registration as user of Models 6717-D,
C-1 & SPEC 2-T, in response to 830106 request
MACDONALD, C E Transportation Branch 83/01/26 HEAD, K Y H&H
X-Ray Services, Inc Ip 17023 311

8302090123 Notification of registration as user of Model 6717-B in
response to 821231 request Approved GA program necessary
for registration under 10CFR71 12(b) W/o encl
MACDONALD, C E Transportation Branch 83/01/28 BADIALI, J
Eastern Testing & Inspection, Inc Ip 17119 324

DOCKET 71-6771 MODEL SN-1, METROPOLITAN EDISON CO

8302080447 Forwards Rev 4 to Certificate of Compliance 6771 for
Model SN-1
MACDONALD, C E Transportation Branch 83/01/12 HAHN, R E General
Public Utilities - CPU Service Corp Ip 17107 347

--8302080449 Certificate of Compliance 6771, Rev 4 for Model SN-1
Approval record encl
MACDONALD, C E Transportation Branch 83/01/12 3pp 17107 346

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

8302090113 Notification of registration as user of Model IF-300 in
response to 821130 request
MACDONALD, C E Transportation Branch 83/01/21 PILANT, J H
Nebraska Public Power District Ip 17119 321

8302170504 Responds to 830128 ltr requesting further analysis by NRC
of dry shipment of spent fuel & withdrawal of casks from
svc Based on corrections to errors in calculation &
assumptions, more detailed consideration by NRC unwarranted
ODEGAARDEN, R H Transportation Branch 83/02/03 RESNIKOFF, M
Council on Economic Priorities Ip 17197 087

8302280140 Forwards request for addl info re 821021 application for
amend to Model IF-300 packaging for shipment of BWR fuel
assemblies Response within 30 days of date of ltr requested
advising when addl info will be provided
MACDONALD, C E Transportation Branch 83/02/22 DAWSON, D M
General Electric Co 2pp 17322 204

DOCKET 71-9006 MODEL 500-SU, AUTOMATION INDUSTRIES, INC

8302090131 Notification of registration as user of Models 650 & 500-SU
in response to 821203 request
MACDONALD, C E Transportation Branch 83/01/21 CASH, A Yuba Heat
Transfer Corp Ip 17121 360

DOCKETED ITEMS

407

DOCKET 71-9007 MODEL 520, AUTOMATION INDUSTRIES, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

8302090102 Notification of registration as user of Models NLI-1/2, TN-B & TN-BL in response to 821221 request
MACDONALD, C E Transportation Branch 83/01/21 STEWART, W L Virginia Electric & Power Co 1p 17119 301

8302170504 Responds to 830128 ltr requesting further analysis by NRC of dry shipment of spent fuel & withdrawal of casks from svc Based on corrections to errors in calculation & assumptions, more detailed consideration by NRC unwarranted
OBERGARDEN, R H Transportation Branch 83/02/03 RESNIKOFF, M Council on Economic Priorities 1p 17197 087

DOCKET 71-9015 MODEL TN-B, -BL, NO USERS

8302090102 Notification of registration as user of Models NLI-1/2, TN-B & TN-BL in response to 821221 request
MACDONALD, C E Transportation Branch 83/01/21 STEWART, W L Virginia Electric & Power Co 1p 17119 301

DOCKET 71-9021 MODEL 730, TECHNICAL OPERATIONS, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9027 MODEL 741 & 741E, TECHNICAL OPERATIONS, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

8302040473 Requests registration as user of Models 660, 650 & B20 LOWERY, G K Progressive Fabricators, Inc 83/01/14 MACDONALD, C E Transportation Branch 1pp 17050 115

8302090120 Notification of registration as user of Model 650 in response to 821214 request
MACDONALD, C E Transportation Branch 83/01/21 FOX, C E Intermountain Testing Co 1p 17119 323

8302090131 Notification of registration as user of Models 650 & S00-SU in response to 821203 request
MACDONALD, C E Transportation Branch 83/01/21 CASH, A Yuba Heat Transfer Corp 1p 17121 360

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

8302040473 Requests registration as user of Models 660, 650 & B20 LOWERY, G K Progressive Fabricators, Inc 83/01/14 MACDONALD, C E Transportation Branch 1pp 17050 115

8302040481 Responds to 821124 ltr re package registration per 10CFR71 12(b) Approved QA program required prior to registration. "QA Programs for Industrial Radiography Licensees" not encl
MACDONALD, C E Transportation Branch 83/01/21 SMITH, R Kokomo Tube Co 1p 17059 349

8302280564 Requests registration as user of Model 660 DOHRMAN, K F Panhandle Eastern Pipeline Co 83/01/26 MACDONALD, C E Transportation Branch 1p 17322 162

DOCKET 71-9036 MODEL C-1, SOURCE PRODUCTION & EQUIPMENT CO

8302030042 Requests registration as user of Models 6717, C-1 & SPEC 2-T
HEAD, T G Monroe X-Ray Co, Inc 83/01/06 MACDONALD, C E Transportation Branch 1p 17026 342

8302030048 Requests registration as user of Models 6717, C-1 & SPEC 2-T
HEAD, K Y H&H X-Ray Services, Inc 83/01/06 MACDONALD, C E Transportation Branch 1p 17028 335

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

8302030154 Notification of registration as user of Models 6717-B, C-1 & SPEC 2-T in response to 830106 request
MACDONALD, C E Transportation Branch 83/01/26 HEAD, K Y H&H X-Ray Services, Inc 1p 17023 311

DOCKET 71-9037 MODEL 713, TECHNICAL OPERATIONS, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8302030602 Requests registration as user of Model CNS1 1-13 STEIN, S S Advanced Medical Systems, Inc 83/01/21 MACDONALD, C E Transportation Branch 1p 17013 340

8302090136 Notification of registration as user of Models B-2 & GE-1600 in response to 821212 request Approved QA program required for registration under 10CFR71 12(b) W/o encl
MACDONALD, C E Transportation Branch 83/01/25 AYRES, J M AWC, Inc 1p 17119 362

8302020132 Forwards request for addl info re 830117 application for amend to Model GE-1600 packaging Response schedule requested within 30 days
MACDONALD, C E Transportation Branch 83/01/26 CUNNINGHAM, G E General Electric Co 3pp 16998 271

8302240031 Forwards Rev 11 to Certificate of Compliance 9044 for Model GE-1600
MACDONALD, C E Transportation Branch 83/02/10 CUNNINGHAM, G E General Electric Co 3pp 17288 003

--8302240035 Certificate of Compliance 9044, Rev 11, for Model GE-1600
MACDONALD, C E Transportation Branch 83/02/10 3pp 17288 006

8302280132 Notification of registration as user of Model GE-1600 in response to 830121 request
MACDONALD, C E Transportation Branch 83/02/22 STEIN, S S Advanced Medical Systems, Inc 1p 17322 203

DOCKET 71-9053 MODEL 683, TECHNICAL OPERATIONS, INC

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9056 MODEL SPEC 2-T, SOURCE PRODUCTION & EQUIPMENT CO

8302030042 Requests registration as user of Models 6717, C-1 & SPEC 2-T
HEAD, T G Monroe X-Ray Co, Inc 83/01/06 MACDONALD, C E Transportation Branch 1p 17026 342

8302030048 Requests registration as user of Models 6717, C-1 & SPEC 2-T
HEAD, K Y H&H X-Ray Services, Inc 83/01/06 MACDONALD, C E Transportation Branch 1p 17028 335

DOCKETED ITEMS

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
 RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

8302030154 Notification of registration as user of Models 6717-B, C-1 & SPEC 2-T, in response to 830106 request
 MACDONALD, C E Transportation Branch 83/01/26 HEAD, K V H&H X-Ray Services, Inc 1p 17023 311

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

8302280958 Requests registration as user of Models HN-100, Series 2 & 3 & HN-200
 MIS, F J Rochester Gas & Electric Corp 83/02/10 MACDONALD, C E Transportation Branch 1p 17322 166

DOCKET 71-9081 MODEL CNSI 1-13C, CHEM-NUCLEAR SYSTEMS, INC

8302030117 Requests registration as user of Model CNS-1600
 FIEDLER, P B General Public Utilities - GPU Service Corp 82/12/22 MACDONALD, C E Transportation Branch 1p 17023 395.

8302090147 Notification of registration as user of Model CNS 1-13C in response to 821222 request
 MACDONALD, C E Transportation Branch 83/01/25 FIEDLER, P B General Public Utilities - GPU Service Corp 1p 17119 360

DOCKET 71-9094 MODEL CNS 14-195-H, CHEM-NUCLEAR SYSTEMS, INC

8302030604 Requests registration as user of Model CNSI-14-195H
 PARKYN, J D Dairyland Power Cooperative 83/01/06 MACDONALD, C E Transportation Branch 1p 17013 341

8302280120 Notification of registration as user of Model CNS-14-195H in response to 830106 request
 MACDONALD, C E Transportation Branch 83/02/22 PARKYN, J D Dairyland Power Cooperative 1p 17314 268

DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC

8302090107 Notification of registration as user of Model CNS 21-300 in response to 821207 request
 MACDONALD, C E Transportation Branch 83/01/21 SKEDIRA, C Neutron Products, Inc 1p 17119 320

DOCKET 71-9107 MODEL 771, TECHNICAL OPERATIONS, INC

8302070284 Application for renewal of Certificate of Compliance 9107 for Model 771 Type B Package SAR supporting application
 encl
 MUNKO, J J Technical Operations, Inc 82/12/30 MACDONALD, C E Transportation Branch 1p 17062 160

--8302070287 'SAR Tech/Ops Model 771 Type B(U) Package "
 " Technical Operations, Inc 81/04/30 83pp 17062 161.

8302220094 Forwards Rev 1 to Certificate of Compliance 9107 for Model 771
 MACDONALD, C E Transportation Branch 83/02/10 MUNKO, J J Technical Operations, Inc 2pp 17234 185

--8302220097 Certificate of Compliance 9107, Rev 1, for Model 771
 Approval record encl
 MACDONALD, C E Transportation Branch 83/02/10 3pp 17234 187

DOCKET 71-9110 MODEL MX-1C-100, MAGNAFLUX CORP

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
 RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
 RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9127 MODEL 100, 100A, 200, 200A, GAMMA INDUSTRIES

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
 RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9128 MODEL C-B, GAMMA INDUSTRIES

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
 RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9132 MODEL T-3, ENERGY, DEPT OF

8302240028 Requests addl info within 30 days to complete review of 820819 application requesting amend to Model T-3 packaging
 Info should be submitted in form of revised pages
 MACDONALD, C E Transportation Branch 83/02/15 HANSEN, L J Nuclear Packaging, Inc 2pp 17268 361

DOCKET 71-9135 MODEL CENTURY B & SA, GEN UNIV B & SA, GAMMA IND.

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
 RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9137 MODEL 820, TECHNICAL OPERATIONS, INC

8302040473 Requests registration as user of Models 660, 650 & 820.
 LOWERY, O K Progressive Fabricators, Inc 83/01/14 MACDONALD, C E Transportation Branch 1pp 17050 115

DOCKET 71-9138 MODEL 78-D-145B, NAVY, DEPT OF

8302020061 Advises that 791204 application for approval of Cs-137, 30-Ci gamma source shipping container will be denied unless schedule for submitting addl info requested on 800423, provided within 20 days
 MACDONALD, C E Transportation Branch 83/01/27 Navy, Dept. of 1p 16798 349

DOCKET 71-9139 MODEL 589, GENERAL ELECTRIC CO

8302280113 Notification of registration as user of Model 589 in response to 830124 request
 MACDONALD, C E Transportation Branch 83/02/22 Chem-Nuclear Systems, Inc 1p 17314 271

DOCKET 71-9148 MODEL 770, TECHNICAL OPERATIONS, INC

8302030119 Requests registration as user of Model 770
 CUNNINGHAM, G E General Electric Co 83/01/06 MACDONALD, C E Transportation Branch 1p 17028 331

8302090130 Notification of registration as user of Model 770 in response to 830106 request
 MACDONALD, C E Transportation Branch 83/01/25 CUNNINGHAM, G E General Electric Co 1p 17121 361

8302220108 Advises that Model 770 authorized by Certificate of Compliance 9148 meets requirements for Type B(U) packages, per 810324 request
 MACDONALD, C E Transportation Branch 83/02/10 RAWL, R R Transportation, Dept of 1p 17234 195

DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT. OF

8302040487 Comments on agenda forwarded w/821130 ltr for 830113 meeting in Silver Spring, MD to discuss scope & content of revised application re Certificate of Compliance 9150 Agenda is satisfactory basis for discussions
 CAUDLE, R E Energy, Dept of 83/01/12 MACDONALD, C E Transportation Branch 2pp 17046 159

DOCKETED ITEMS

--8302040507 Discusses DOE request to delete operational control which requires PAT-2 packages to be stowed in aft-most location aboard aircraft Meeting held on 821006 in Albuquerque, NM to discuss application Resolutions listed
CHAPPELL, C R Transportation Branch 82/10/15 Transportation Branch Bpp 17046 212

DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

8302080442 Forwards Rev 1 to Certificate of Compliance 9151 for Models HN-100, Series 3 & CNS 14-170, Series III
MACDONALD, C E Transportation Branch 83/01/12 SILLYMAN, D Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp 17071 101

--8302080445 Certificate of Compliance 9151, Rev 1 for Models HN-100, Series 3 & CNS 14-170, Series III Approval record encl
MACDONALD, C E Transportation Branch 83/01/12 4pp 17071 103

8302070639 Application for amend to Certificate of Compliance 9151, modifying Paragraph 8(i) re seal security.
MALLORY, C W Hittman Corp 83/01/13 MACDONALD, C Transportation Branch 1p 17059 355

8302030406 Requests registration as user of Model CNS 14-170 Series 3
DIMMICK, D Hittman Nuclear & Development Corp (subs Hittman Corp) 83/01/19 MACDONALD, C E Transportation Branch 1p 17013 342

8302030600 Requests registration as user of Model HN-100 Series 3.
O'DONNELL, D M Yankee Atomic Electric Co 83/01/20 MACDONALD, C E Transportation Branch 1p 17013 339

8302280568 Requests registration as user of Models HN-100, Series 2 & 3 & HN-200
HIS, F J Rochester Gas & Electric Corp 83/02/10 MACDONALD, C E Transportation Branch 1p 17322 166

8302280124 Notification of registration as user of Model HN-100, Series 3 in response to 830120 request
MACDONALD, C E Transportation Branch 83/02/22 O'DONNELL, D M Yankee Atomic Electric Co 1p 17314 263

8302280127 Notification of registration as user of Model HN-100, Series 3 in response to 830119 request
MACDONALD, C E Transportation Branch 83/02/22 DIMMICK, D Hittman Nuclear & Development Corp (subs Hittman Corp) 1p. 17314.267

8302280210 Notification of registration as user of Model HN-100, Series 3 in response to 830123 request
MACDONALD, C E Transportation Branch 83/02/22, STEWART, W L Virginia Electric & Power Co 1p 17322 167

DOCKET 71-9156 MODEL IR-50, INDUSTRIAL NUCLEAR CO

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298.

DOCKET 71-9157 MODEL IR-100, INDUSTRIAL NUCLEAR CO

8302040012 Advises that DH Riddle has replaced HD Richardson as radiation safety officer
RICHARDSON, H Gamma Corp 83/01/14 MACDONALD, C E Transportation Branch 1p 17043 298

DOCKET 71-9158 MODEL GPU 80, GENERAL PUBLIC UTILITIES

8302090181 Advises that 820126 application for approval of Model GPU-80 will be denied unless commitment to provide addl info received within 20 days
MACDONALD, C E Transportation Branch 83/01/24 RIDIHALOH, J Ridihaigh, Eggers & Associates 1p 17132 096

DOCKET 71-9167 MODEL 3206B, 3227B & 3218, AMERSHAM CORP

8302040430 Forwards Rev 1 to "SAR, Keg Design Containers, Type B Package " Locations of responses to 821029 questions indicated
BAOBY, L A Amersham Corp 83/01/17 MACDONALD, C Transportation Branch 4pp 17045 001.

--8302040454 Rev 1 to, "SAR, Keg Design Containers, Type B Package "
* Amersham Corp 83/01/17 139pp. 17045:005

DOCKET 71-9168 MODEL CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC

8302220112 Forwards request for info re 820930 application for amend to Certificate of Compliance 9168 for Model CNS 8-120B.
MACDONALD, C E Transportation Branch. 83/02/10 MARSH, C A Chem-Nuclear Systems, Inc 4pp 17234 196

DOCKET 71-9853 MODEL ORNL DOT SPEC 6M SPECIAL FORM PACKAGE, ENERGY.

8302080048 Forwards Certificate of Compliance 9853 & "SAR for Packaging-ORNL DOT Spec 6M - Special Form Package."
PRICHARD R P Energy, Dept of 83/01/03, MACDONALD, C, E. Transportation Branch 1p 17106 269

--8302080053 Certificate of Compliance 9855, Rev O, for Model DOT-6M Typ Special Form
TRAVIS, W H Energy, Dept of 82/05/05, 4pp 17106 270

--8302080058 "SAR for Packaging ORNL DOT Spec 6M - Special Form Packaging."
SCHAICH, R W Oak Ridge National Laboratory. ORNL/TM-8340 82/07/31 82pp 17106 274

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO.

8302080080 Forwards cover sheets to be inserted in 821008 application to amend Licenses DPR-32 & DPR-37, replacing safeguards contingency plan sections of physical security plan
STEWART, W L Virginia Electric & Power Co. 83/01/03 CUNNINGHAM, E E Division of Fuel Cycle & Material Safety. 3pp. 17106.142 24X Fiche: 50-280, 83/01/03, 8302080080

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

8302030616 Unofficial transcript of Commission 830127 meeting in Washington, DC re discussion of Regulatory Reform Task Force legislative proposals Pp 1-115 Supporting documentation encl.
* Commissioners 83/01/27 188pp 17012 237

8302080481 Transcript of 830128 public meeting in Washington, DC re Regulatory Reform Task Force legislative proposals Pp 1-71
* Commissioners 83/01/28, 75pp 17071 194,

8302100118 Staff requirements memo re SECY-82-490A, Commission review of Director's Decision DD-82-12 on emergency planning deficiencies Commission approved proposed order noting that review unnecessary
CHILK, B J Office of the Secretary of the Commission M830127C 83/02/02. Correspondence & Records Branch 1p 17134 324

8302140175 Transcript of 830128 public meeting in Washington, DC re U mill tailings regulations Pp 1-68 Supporting documentation encl.
* Commissioners 83/01/28 75pp 17145 232

8302140213 Staff requirements memo re 830128 briefing on schedule for action on U mill tailings regulations Commission will review mill tailing regulations within 90 days of issuance of proposed EPA stds
CHILK, B J Office of the Secretary of the Commission M830128A 83/02/07 DIRCKS, W J Office of the Executive Director for Operations 1p 17145 334

8302160013 Transcript of Commission 830208 meeting in Washington, DC re regionalization Pp 1-95 Viewgraphs & supporting documentation encl.
* Commissioners. 83/02/08 124pp 17171 282

8302160404 Suggests closeout of Multi-Plant Action D-67 re pressurized thermal shock to reactor pressure vessels. Action Item D-72 should be developed instead
LAINAB, G C Assistant Director for Operating Reactors 83/02/03 EIBENHUT, D G Division of Licensing 2pp. 17173 192

--8302160406 Staff requirements memo re 821209 discussion/possible vote in Washington, DC on pressurized thermal shock actions.
CHILK, B J Office of the Secretary of the Commission M821209A 83/01/05. Office of the Executive Director for Operations 2pp 17173 193

8302160407 Transcript of 830204 briefing in Washington, DC on SEP, Phase II results Pp 1-98 Viewgraphs encl.
* Commissioners 83/02/04, 138pp. 17173:054

8302220028 Staff requirements memo informing of Commission 830204 public meeting in Washington, DC re SEP Phase 2 results No action taken
CHILK, B J Office of the Secretary of the Commission 83/02/09. Office of the Secretary of the Commission 1p 17233 293

8302220132 Transcript of Commission 830209 public meeting in Washington, DC re discussion/possible vote on regulatory reform task force - legislative proposals Pp 1-84
* Commissioners 83/02/09 86pp 17227:100,

--8302220144 Forwards revised analysis of new authority granted to NRC by licensing reform bill. Rev clarifies provisions in bill re fees & burden of proof for site permit & design approval
MARBCH, M O. Office of the General Counsel 83/02/08, PALLADINO, N J., GILINSKY, V., AHEARNE, J Commissioners 13pp 17227 187,

--8302220149 Discusses new authority granted to NRC by licensing reform bill Unclear whether provisions re fees & burden of proof in renewals in Sections 193 & 194 could be accomplished administratively
AHEARNE, J Commissioners 83/02/08 Office of the General Counsel 1p 17227 200

--8302220154 Forwards documents necessary for next Commission meeting on licensing legislation, including draft bill, comparative draft bill, ltr to Vice-President Bush, analysis of bill & ltr to OMB
TOURTELLOTT, J Regulatory Reform Task Force 83/02/04 PALLADINO, N J., GILINSKY, V., AHEARNE, J Commissioners 88pp 17227 201

8302220461 Transcript of 830210 joint meeting w/ACRS in Washington, DC re severe accident policy Pp 1-78 Supporting documentation encl.
* Commissioners 83/02/10 Bpp 17241 077

--8302170132 Forwards marked-up copy of "Proposed Commission Policy Statement on Severe Accidents & Related Views on Nuclear Reactor Regulation"
DIRCKS, W J Office of the Executive Director for Operations 83/02/07 PALLADINO, N J., GILINSKY, V., AHEARNE, J F Commissioners 34pp 17427 302

--8302220520 Expresses strong industry support of policy statement on severe accidents proposed under SECY-82-18 Program represents interests of industry participants re severe accidents in regulatory process
REED, C Commonwealth Edison Co. 83/02/01 PALLADINO, N J Commissioners 2pp 17241 199

8302280052 Transcript of 830217 briefing in Washington, DC re shift manning requirements at nuclear power plants Pp 1-86 Viewgraphs encl.
* Commissioners 83/02/17 108pp 17319 207

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8302080088 Summary of ACRS Subcommittee on Reliability & Probabilistic Assessment 820802 meeting in Washington, DC re draft action plan for implementation of proposed safety goals & accident policy Viewgraphs encl.
* ACRS - Advisory Committee on Reactor Safeguards 82/08/12 ACRS - Advisory Committee on Reactor Safeguards 31pp 17104 109

8302080096 Summary of ACRS Procedures Subcommittee 821103 meeting in Washington, DC re scope & content of ACRS reviews & ACRS working relationship w/NRC field ofcs
* ACRS - Advisory Committee on Reactor Safeguards 82/11/26 ACRS - Advisory Committee on Reactor Safeguards 45pp 17104 096

8302080117 Summary of ACRS Subcommittee on Human Factors 820907 meeting in Washington, DC re draft version of integrated human factors program plan
* ACRS - Advisory Committee on Reactor Safeguards 82/11/30 ACRS - Advisory Committee on Reactor Safeguards 27pp 17105 308

8302080128 Summary of ACRS Subcommittee on Reactor Operations 820825 meeting in Washington, DC re NRC enforcement policy, IE performance appraisal team & SALP programs, ideas for improving operational safety & regionalization effort
* ACRS - Advisory Committee on Reactor Safeguards 82/11/05 ACRS - Advisory Committee on Reactor Safeguards 31pp 17103 305

8302080131 Summary of ACRS Subcommittee on ATWS 821022 meeting in Washington, DC re proposed schedule & plans of ATWS Task Force on resolution of ATWS
* ACRS - Advisory Committee on Reactor Safeguards 82/11/23 ACRS - Advisory Committee on Reactor Safeguards 21pp 17103 279

NONDOCKETED ITEMS

8302080363 Summary of ACRS Subcommittee on Reactor Operations 820929 meeting in Washington, DC re low temp overpressurization & suppression pool or containment sump water contamination adverse effects on cooling pumps
* ACRS - Advisory Committee on Reactor Safeguards 20183
82/12/15 ACRS - Advisory Committee on Reactor Safeguards 16pp
17107 123 24X Fiche 80-000, 82/12/15, 8302080363

8302080370 Summary of ACRS Metal Components Working Group 820930 meeting in Washington, DC re NRC position on pressurized thermal shock
* ACRS - Advisory Committee on Reactor Safeguards 82/11/23
ACRS - Advisory Committee on Reactor Safeguards 33pp 17107 166

8302080414 Summary of ACRS ECCS Subcommittee 821202-03 meeting in San Jose, CA re GE development of best estimate model for licensing
CATTON, I ACRS - Advisory Committee on Reactor Safeguards
82/12/06 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 1p 17074 332

8302080416 Summary of ACRS Advanced Code Review Group 821214-15 meeting in Bethesda, MD re void fractions, flow blockage & clad ballooning
CATTON, I ACRS - Advisory Committee on Reactor Safeguards
83/01/11 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 3pp 17074 329

8302080444 Delineates proposal for training human factor engineers for safe design & operation of nuclear power plants
BALVENDY, O ACRS - Advisory Committee on Reactor Safeguards
82/11/22 FISCHER, D ACRS - Advisory Committee on Reactor Safeguards 3pp 17107 351

8302080463 Summary of ACRS Subcommittee on Extreme External Phenomena 821021-22 meetings in Santa Monica, CA re flooding, severe winds & seismic issues associated w/SEP plants
* ACRS - Advisory Committee on Reactor Safeguards 20183
83/01/07 ACRS - Advisory Committee on Reactor Safeguards 32pp
17108 039

8302080467 Comments on ACRS ECCS Subcommittee 821202-03 meeting in San Jose, CA General concept proposed by GE for licensing based on LOCA-binding energy calculations w/adds very appealing
SCHROCK, V E ACRS - Advisory Committee on Reactor Safeguards
SCHROCK, V E California, Univ of, Berkeley 82/12/17 PLESBETT, M
ACRS - Advisory Committee on Reactor Safeguards 1p 17072 035

8302080469 Comments on ACRS ECCS Subcommittee 821202-03 meeting in San Jose, CA re current evaluation models used to comply w/App K requirements
ZUDANS, Z ACRS - Advisory Committee on Reactor Safeguards
ZUDANS, Z Franklin Institute/Franklin Research Center 82/12/09
BOEHNERT, P A ACRS - Advisory Committee on Reactor Safeguards 2pp
17072 032

8302080470 Summary of ACRS ECCS Subcommittee 821202-03 meetings w/GE in San Jose, CA re rev to GE ECCS evaluation model codes (SAFER/GESTER) & to hear presentations on pros & cons of use of electrical vs nuclear heater rods for LOCA tests
* ACRS - Advisory Committee on Reactor Safeguards 020183
82/12/09 ACRS - Advisory Committee on Reactor Safeguards 28pp
17072 004

8302080472 Comments on ACRS ECCS Subcommittee 821202-03 meeting in San Jose, CA Work presented at meeting shows high level of technical competence
TIEN, C ACRS - Advisory Committee on Reactor Safeguards. TIEN, C
California, Univ of, Berkeley 82/12/08 BOEHNERT, P ACRS -
Advisory Committee on Reactor Safeguards. 2pp 17071 326

8302080475 Comments on ACRS ECCS Subcommittee 821202-03 meeting GE efforts re rev of App K commendable Major improvements in technology should be factored into licensing process & safety design & procedures
THEOFANOUS, T O ACRS - Advisory Committee on Reactor Safeguards
THEOFANOUS, T O Purdue Univ 82/12/07 BOEHNERT, P ACRS -
Advisory Committee on Reactor Safeguards 2pp 17071 321

83090007 Recommends ACRS consider & discuss w/NRC reliability analysis to be used in safety evaluation Analysis should be conservative & not based on averages
IPINSKI, W C ACRS - Advisory Committee on Reactor Safeguards
IPINSKI, W C Argonne National Laboratory 83/01/11, MAJOR, R
RS - Advisory Committee on Reactor Safeguards 1p 17119 180

83090009 Criticizes NRC responses to ACRS fire protection questions RS Fire Protection Subcommittee should review issue of rifying continued plant compliance w/fire protection requirements
IPINSKI, W C ACRS - Advisory Committee on Reactor Safeguards
IPINSKI, W C Argonne National Laboratory 82/12/21 BENDER, M
RS - Advisory Committee on Reactor Safeguards 2pp 17119 178

8302090012 Summary of ACRS Advanced Reactors Subcommittee 821208 meeting re status of NRC LMFBR research program for annual rept to Congress on FY84 - 85 budget
* ACRS - Advisory Committee on Reactor Safeguards 82/12/10
ACRS - Advisory Committee on Reactor Safeguards 7pp 17119 169

8302090016 Summary of ACRS Class 9 Accidents Subcommittee 820806 meeting in Washington, DC re NRC rev to severe accident research plan (SARP), (NUREG-0900) & SARP relation to BECY-82-1A
* ACRS - Advisory Committee on Reactor Safeguards 82/10/08
ACRS - Advisory Committee on Reactor Safeguards. 10pp 17119 159

8302090070 Summary of ACRS Subcommittee on AC/DC Power Sys Reliability 820928 meeting in Washington, DC re review of status of improved requirements for dc power sys, station blackout & diesel generator & battery testing practices
* ACRS - Advisory Committee on Reactor Safeguards 82/10/29
ACRS - Advisory Committee on Reactor Safeguards 34pp 17119 256

8302090079 Summary of ACRS Joint Committees on Safety Philosophy, Technology & Criteria & Class 9 Accidents 820908 meeting in Washington, DC re severe accidents policy statement, safety goals & implementation
* ACRS - Advisory Committee on Reactor Safeguards 20183
82/10/23 ACRS - Advisory Committee on Reactor Safeguards 3pp.
17119 291

8302090312 Transcript of ACRS Subcommittee on Regulatory Policy & Procedures 830207 meeting in Washington, DC Pp 1-177
* ACRS - Advisory Committee on Reactor Safeguards 83/02/07
179pp 17067 185

8302100222 Transcript of ACRS Subcommittee on Regulatory Policy & Procedures 830208 meeting in Washington, DC Pp 178-235 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/08 90pp
17113 300

8302100253 Transcript of ACRS Subcommittee on ECCS 830208 meeting in Washington, DC Pp 1-242 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/08
297pp 17113 001

8302100106 Transcript of ACRS Subcommittee on Reliability & FRA 830209 meeting in Washington, DC Pp 1-139 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/09
206pp 17141 223

8302140178 Summary of ACRS Subcommittee on Extreme External Phenomena 820811 meeting w/NRR & RES in Washington, DC re ACRS recommendations on evaluation of seismic design margins for earthquakes more severe than SSE
* ACRS - Advisory Committee on Reactor Safeguards 020183
82/08/12 ACRS - Advisory Committee on Reactor Safeguards 12pp
17144 113

8302150344 Transcript of 274th ACRS general meeting on 830210 in Washington, DC Pp 1-123 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/10
164pp. 17157 282

8302160282 Transcript of 274th ACRS general meeting on 830211 in Washington, DC Pp 124-474 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/02/11
543pp 17167 341.

8302240211 Transcript of ACRS Subcommittees on Class 9 Accidents & Reactor Radiological Effects 830222 meeting in Washington, DC Pp 1-352 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards. 83/02/22
530pp 17278 324.

COMMISSION NRC COMMISSIONERS

8302020094 Weekly info rept for wk ending 830121
RCHM, T A Office of the Executive Director for Operations
83/01/27 40pp 16998 296

8302030193 Responds to 821213 ltr re impact of NRC requirements on U milling companies
KAHMERER, C. Office of Congressional Affairs 83/01/24 GARN, J
Senate 7pp 16999-235

--8302020198 Requests info re changes & amends to U milling company license, resulting in excessive costs
GARN, J Senate 82/12/13 PALLADINO, N J. Commissioners. 1p
16999 241

NONDOCKETED ITEMS

8302070047 Responds to 821013 memo re re-exam of U mill tailings regulations Div of Fuel Cycle & Matl Safety assigned lead responsibility for task Working group appointed to review regulations & consider change options
DIRCKS, W J Office of the Executive Director for Operations
82/12/20 PALLADINO, N Commissioners 6pp 17065 300

8302080464 Weekly info rept for wk ending 830128
REHM, T A Office of the Executive Director for Operations
83/02/02 40pp 17107 302

8302090178 Responds to 830105 ltr to Chairman Palladino re operator requalification exams & nuclear plant drills Importance of balancing exams designed to assure operator effectiveness against potential impacts on operators recognized
DIRCKS, W J Office of the Executive Director for Operations
83/01/28 BOSCHWITZ, R Senate 5pp 17132 098

--8302090183 Expresses concerns re stricter operator requalification exams & nuclear plant drills Tougher exam procedures could overtax operators which in turn could hurt plant safety in final analysis
BOSCHWITZ, R Senate 83/01/05 PALLADINO, N J Commissioners 1p 17132 102

8302170081 Responds to Questions 5 - 7 in 830114 ltr re Commission authority to issue temporary DLs Projected significant licensing delay is zero
PALLADINO, N J Commissioners 83/02/03 OTTINGER, R L House of Rep 10pp 17234 220

--8302170086 Requests info re continued need for temporary Commission authority to issue DLs prior to conduct or completion of required hearing
OTTINGER, R L House of Rep 83/01/14 PALLADINO, N J Commissioners 2pp 17234 228

8302170383 Weekly info rept for wk ending 830204
REHM, T A Office of the Executive Director for Operations
83/02/10 50pp 17195 295

8302220446 Requests approval to reprogram portion of FY83 available funds to compensate for 1982 pay raises & to increase efforts in QA & use of cost benefit analysis Proposed program forwarded & also serves as first quarter base rept
PALLADINO, N J Commissioners 83/02/03 DEVILL, T House of Rep, Appropriations 7pp 17236 324

8302220458 Forwards rept of nondisclosure of safeguards info for quarter ending 821231
PALLADINO, N J Commissioners 83/02/07 O'NEILL, T P House of Rep, Speaker of the House 1p 17236 319

--8302220469 Forwards rept of nondisclosure of safeguards info for quarter ending 821231.
PALLADINO, N J Commissioners 83/02/07 BUSH, O H W. Senate, President of the Senate 6pp 17236 314

8302220466 Forwards NUREG-0090, Vol 5, Number 3, "Rept to Congress on ADS, Jul-Sept 1982"
PALLADINO, N J Commissioners 83/02/03 O'NEILL, T P House of Rep, Speaker of the House 1p 17234 307

--8302220469 Forwards NUREG-0090, Vol 5, Number 3, "Rept to Congress on ADS, Jul-Sept 1982"
PALLADINO, N J Commissioners 83/02/03 BUSH, O H W. Senate, President of the Senate 1p 17234 308

8302220594 Weekly info rept for wk ending 830211
REHM, T A Office of the Executive Director for Operations
83/02/17 41pp 17239 273

8302230088 Expresses concern re Raychem-Fiamtrol issue & requests being informed of Commission actions to resolve matter
PANETTA, L E House of Rep. 82/11/19 PALLADINO, N Commissioners 2pp. 17299 328.

8302240057 Forwards fourteenth joint status rept on emergency preparedness & second quarterly rept for period ending 821231
AHEARNE, J F Commissioners GIUFFRIDA, L O Federal Emergency Management Agency 83/01/25 SIMPSON, A K Senate, Environment & Public Works 1p 17287 278

--8302240065 "NRC/FEHA Joint Quarterly Rept to Congress on Emergency Preparedness, Oct-Dec 1982," discussing efforts to upgrade issues
* Commissioners * Federal Emergency Management Agency.
83/01/25 58pp 17287 279

8302240233 Forwards response to 821217 list of questions re studies on safeguards at licensed nuclear power reactors NUREG-0525, -0703 & -0459 encl in response to request for studies, memos or repts relevant to stated topic (w/o encls)
PALLADINO, N J Commissioners 83/02/07 MARKEY, E J House of Rep, Interior & Insular Affairs 25pp 17288 161

--8302240239 Requests reply to questions re risk to commercial nuclear power plants from deliberate acts of sabotage Studies, memos & repts on topic also requested
MARKEY, E J House of Rep, Interior & Insular Affairs 82/12/17 PALLADINO, N J Commissioners 2pp 17288 186

8302240367 Trip rept of 820725-29 visit to Korea re technical assistance on LNR safety Assignment of full-time technical representative in Korea proposed
OILIKSVY, V Commissioners 82/10/21 Commissioners 7pp 17289 340

8302240402 Responds to 821210 ltr expressing concerns re program of independent design reviews performed by applicants for DLs
PALLADINO, N J Commissioners 83/02/08 REYNOLDS, H S Debevoise Liberman 2pp 17289 354

--8302240405 Expresses concern w/independent design verification progr (IDVP) reviews performed by applicants for DLs NRC urged to refrain from imposing IDVP on DL applicants as if IDVP were binding legal requirement
REYNOLDS, H S Debevoise & Liberman 82/10/10 PALLADINO, N J Commissioners 3pp 17288 356

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8302010001 Notification of contract execution, Mod 5 to "Fire Protection Program Review & Evaluation" Contractor Gage-Babcock & Assoc, Inc
FIELD, J Technical Assistance Contracts Branch FIN B-6804
NRC-03-B1-103 83/01/11 VOLLMER, R H Division of Engineering
NOLAN, F NRC - No Detailed Affiliation Given 1p 16995 041

--8302010002 Mod 5, modifying Article I re scope of work, to "Fire Protection Program Review & Evaluation"
COHEN, B Gage-Babcock Associates, Inc GUSTAVE, R P Division of Contracts FIN B-6804 NRC-03-B1-103 83/01/11 2pp 16995 042

8302010005 Notification of contract execution "Sys Analysis & Program Support Svcs," awarded to SBA & Logical Technical Svcs Corp
BORSEY, M, MILES, E B Administrative Contracts Branch FIN B-8803
NRC-33-B3-453 82/12/30 BASSETT, H S, VINEYARD, P W Division of Data Automation & Management Information 1p 16995 009

--8302010009 Contract "Sys Analysis & Program Support Svcs," awarded SBA & Logical Technical Svcs Corp
RDOERS, A A Small Business Administration GREENLEE, C A Logic, Technical Service Corp HATTIA, M J Division of Contracts FIN B-8803 NRC-33-B3-453 82/12/30 21pp 16995 010

8302010023 Notification of contract execution, Mod 7 to "Card-Entry Access Control Sys" Contractor Racial Vikonics, Inc
OILBENHORN, A J Administrative Contracts Branch NRC-10-B2-399
83/01/25 SPRINGER, H L Office of Administration FINGER, R NRC
No Detailed Affiliation Given 1p 16990 359

--8302010028 Mod 7, correcting period of performance to 840119, to "Card-Entry Access Control Sys"
* Racial Vikonics, Inc * IAGAN, T F Division of Contracts
NRC-10-B2-399 83/01/25 1p 16990 360

8302010033 Notification of contract execution "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling," awarded to Water, Waste & Land, Inc
EDGEMER, H F Technical Assistance Contracts Branch FIN B-7361-3
NRC-02-B3-030 83/01/21 DAVIS, J, SIEFKEN, D Office of Nuclear Material Safety & Safeguards, Director 1p 16995 079

--8302010039 Contract "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling," awarded to Water, Waste & Land, Inc
* Water, Waste & Land, Inc * MORTON, K Division of Contracts
FIN B-7361-3 NRC-02-B3-030 83/01/21 15pp 16995 080

8302010109 Notification of contract execution, Mod 3 to "MCLAMS Mod" Contractor NUBAC, Inc
FIELD, J Technical Assistance Contracts Branch NRC-02-B2-034
83/01/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MESSINGER, M NRC - No Detailed Affiliation Given 1p 16990 104

NONDOCKETED ITEMS

--8302010115 Mod 3, changing mailing address for invoice submission, to "MCLAMS Mod 3", awarded to NUSAC, Inc. HAGAN, T F Division of Contracts NRC-02-82-034 83/01/03 1p 16990 105

8302020018 Corrected notification of contract execution "Lab-Studies Dynamic Response of Prototypical Piping Sys," awarded to ANCO Engineers, Inc & EPRI BAISEBEN, L Technical Assistance Contracts Branch FIN B-8907 NRC-04-82-025 83/01/21 FOREHAND, W Office of Nuclear Regulatory Research, Director O'BRIEN, J NRC - No Detailed Affiliation Given 1p 16998 357

8302020020 Corrected notification of contract execution, Mod 2 to "Seismic Investigation of Epicentral Region About 800727 Sharpburg, KY Earthquake" Contractor Univ of KY WOLLETT, S Technical Assistance Contracts Branch FIN B-7477 NRC-04-81-189 83/01/27 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p 16998 356

8302020032 Corrected notification of contract execution, Mod 10 to "Utilization of BNR & PWR Simulator Activities" Contractor TVA WOLLETT, S Technical Assistance Contracts Branch NRC-05-76-357 83/01/27 BLAHA, J Program Support Branch FOX, E NRC - No Detailed Affiliation Given 1p 16998 355

8302020050 Notification of grant execution, Mod 2 to "Process of Droplet Disposition in Two Phase Gas Liquid Flow Analysis of Mechanism & Modeling" Grantee Univ of Houston MCDEHNOTT, D Technical Assistance Contracts Branch FIN O-1026 NRC-0-04-81-027 83/01/26 BATSON, W Office of Nuclear Regulatory Research, Director ZUBER, N NRC - No Detailed Affiliation Given 1p 16998 353

--8302020056 Mod 2, providing addl funds, to "Process of Droplet Disposition in Two Phase Gas Liquid Flow Analysis of Mechanism & Modeling" MORTON, K V Technical Assistance Contracts Branch FIN O-1026 NRC-0-04-81-027 83/01/26 1p 16998 354

8302020084 Notification of contract execution, Mod 4 to "Availability of Medical Treatment to Minimize Early Fatalities Post-Severe Reactor Accidents" Contractor SBA Subcontractor Andrus Research Corp FLEENOR, C Technical Assistance Contracts Branch NRC-03-82-128 83/01/19 MATTHEW, R Division of Systems Integration (post 811005) CHU, A NRC - No Detailed Affiliation Given 1p 16998 358

--8302020090 Mod 4, incorporating revised indirect rates, to "Availability of Medical Treatment to Minimize Early Fatalities Post-Severe Reactor Accidents" * Small Business Administration * Andrus Research Corp GUSTAVE, R P Division of Contracts NRC-03-82-128 83/01/19 2pp 16998 359

8302020087 Notification of grant execution, Mod 1 to "Thermal-Hydraulic Transients Behavior of Coolant in Simulated Reactor Loop" Grantee Univ of MD MCDEHNOTT, D Technical Assistance Contracts Branch FIN O-1043 NRC-0-04-82-013 83/01/28 BATSON, W Office of Nuclear Regulatory Research, Director YOUNG, M NRC - No Detailed Affiliation Given 1p 16998 336

--8302020093 Mod 1, providing addl funds, to "Thermal-Hydraulic Transients Behavior of Coolant in Simulated Reactor Loop" MEDINA, V Maryland, Univ of MORTON, K V Technical Assistance Contracts Branch FIN O-1043 NRC-0-04-82-013 83/01/28 1p 16998 337

8302020097 Notification of contract execution "State Legislative Reporting Svcs," awarded to Public Affairs Info, Inc BAZIN, J P Division of Contracts FIN B-1592 NRC-06-83-266 83/01/13 KERR, O W Office of State Programs, Director LANDAU, M, NRC - No Detailed Affiliation Given 1p 16998 200

--8302020100 Contract "State Legislative Reporting Svcs," awarded to Public Affairs Info, Inc ALLENDER, O W Public Affairs Information, Inc. MATTIA, M J Division of Contracts FIN B-1592 NRC-06-83-266 83/01/13 70pp 16998 201

8302020118 Notification of contract execution, Mod 4 to "MCLAMS Mod 4" Contractor NUSAC, Inc FIELDS, J Technical Assistance Contracts Branch NRC-02-82-034 83/01/11 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MESSINGER, M, NRC - No Detailed Affiliation Given 1p 16998 279

--8302020123 Mod 4, modifying statement of work, to "MCLAMS Mod 4" PEVENSTEIN, J E NUSAC, Inc GUSTAVE, R P Division of Contracts NRC-02-82-034 83/01/11 2pp 16998 280

8302020148 Notification of contract execution "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to Univ of VA TOWNSEND, B L Administrative Contracts Branch FIN B-8985 NRC-04-83-010 83/01/25 BASSETT, O E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 16999 262

--8302020155 Contract "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to Univ of VA REYNOLDS, A B Virginia, Univ of REBELLO, J E Division of Contracts FIN B-8985 NRC-04-83-010 83/01/25 4pp 16999 263

8302020232 Notification of contract execution "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to UCLA TOWNSEND, B L Administrative Contracts Branch FIN B-8990 NRC-04-83-015 83/01/25 BASSETT, O E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 16999 193

--8302020236 Contract "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to UCLA KASTENBERG, H E California, Univ of, Los Angeles REBELLO, J E Division of Contracts FIN B-8990 NRC-04-83-015 83/01/25 4pp 16999 194

8302020242 Notification of contract execution "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to NC State Univ TOWNSEND, B L Administrative Contracts Branch FIN B-8984 NRC-04-83-009 83/01/25 BASSETT, O E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 16999 182

--8302020245 Contract "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to NC State Univ ZUMWALT, L R North Carolina State Univ REBELLO, J E Division of Contracts FIN B-8984 NRC-04-83-009 83/01/25 4pp 16999 183

8302020270 Notification of contract execution "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to S Levy, Inc TOWNSEND, B L Administrative Contracts Branch FIN B-8989 NRC-04-83-104 83/01/25 BASSETT, O E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 16999 111

--8302020273 Contract "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions,'" awarded to S Levy, Inc LEVY, S S Levy, Inc REBELLO, J E Division of Contracts FIN B-8989 NRC-04-83-104 83/01/25 4pp 16999 112

8302020409 Notification of grant execution, Mod 3 to "Geological Studies of Faults & Terraces of Central & Western KY" Grantee Univ of KY Research Foundation MCDEHNOTT, D Technical Assistance Contracts Branch FIN O-1020 NRC-0-04-81-018 83/01/26 BATSON, W Office of Nuclear Regulatory Research, Director WASTLER, S NRC - No Detailed Affiliation Given 1p 16999 343

--8302020417 Mod 3, providing addl funds, to "Geological Studies of Faults & Terraces of Central & Western KY" * Kentucky, Univ of MORTON, K V Technical Assistance Contracts Branch FIN O-1020 NRC-0-04-81-018 83/01/26 1p 16999 344

8302020423 Notification of contract execution, Mod 5 to "Analysis of Atmospheric Diffusion Through Application of Lidar Technology" Contractor: SRI Int'l WOLLETT, S Technical Assistance Contracts Branch FIN B-6793 NRC-04-81-211 83/01/20 BATSON, W, KORNASIEWICZ, R Office of Nuclear Regulatory Research, Director 1p 16999 318

NONDOCKETED ITEMS

--8302020429 Mod 5, exercising option for Phase III, to "Analysis of Atmospheric Diffusion Through Application of Lidar Technology"
 FLOYD, S SR International GUSTAVE, R P Division of Contracts
 FIN B-6793 NRC-04-B1-211 83/01/20 2pp 17005 126

8302030019 Notification of contract execution "Licensing Technical Assistance," awarded to Science Applications, Inc
 EDDEWORTH, P Technical Assistance Contracts Branch FIN B-7339-3
 NRC-02-B3-035 83/01/21 DAVIS, J Office of Nuclear Material
 Safety & Safeguards, Director LOYSEN, P NRC - No Detailed Affiliation
 Affiliation Given 1p 17041 059

--8302030022 Contract "Licensing Technical Assistance," awarded to Science Applications, Inc
 FINDLEY, D E Science Applications, Inc MORTON, K V Division of
 Contracts FIN B-7339-3 NRC-02-B3-035 83/01/21 33pp
 17041:060

8302030206 Notification of contract execution, Mod 3 to "Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events" Contractor Science Applications, Inc
 FLYNN, M Technical Assistance Contracts Branch FIN B-8622
 NRC-03-B2-131 82/12/21 EISENHUT, D G Division of Licensing
 SILVER, H NRC - No Detailed Affiliation Given 1p 17013 351

--8302030211 Mod 3, initiating addl work, extending period of performance to 830509 & recognizing revised fringe benefit rate, to "Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events"
 FINDLEY, D E Science Applications, Inc GUSTAVE, R P Division of
 Contracts FIN B-8622 NRC-03-B2-131 82/12/21 3pp
 17013 352

8302040127 Notification of contract execution, Mod 1 to "Audiovisual Consultant Svcs" Contractor N Hall
 PERLMAN, J Administrative Contracts Branch FIN B-8181
 NRC-17-B3-398 83/01/25 CHILK, S J Office of the Secretary of the
 Commission 1p 17043 165

--8302040134 Mod 1, adding FIN Number to accounting data, to "Audiovisual Consultant Svcs"
 HALL, M Hall, N SMITH, P A Division of Contracts FIN B-8181
 NRC-17-B3-398 83/01/25 1p 17043 166

8302040159 Notification of contract execution, Mod 4 to "Multidimensional Effects in LWR Thermal Hydraulics" Contractor Rensselaer Polytechnic Inst.
 HOLLETT, B Technical Assistance Contracts Branch FIN B-7272
 NRC-04-B0-236 83/01/17 BATSON, W Office of Nuclear Regulatory
 Research, Director HSU, Y Y NRC - No Detailed Affiliation Given
 1p 17043 111

--8302040167 Mod 4, extending contract until 830531, to "Multidimensional Effects in LWR Thermal Hydraulics"
 LOUDICE, J M Rensselaer Polytechnic Inst. GUSTAVE, R P
 Technical Assistance Contracts Branch FIN B-7272 83/01/17
 2pp, 17043, 112

8302040298 Notification of contract execution, Mod 7 to "Disease Incidence Rates From Occupational Exposure to Hazardous Substances" Contractor BMI
 HOLLETT, B Technical Assistance Contracts Branch FIN B-10660
 NRC-01-B0-016 83/01/19 FOREHAND, W Office of Nuclear Regulatory
 Research, Director ROECKLEIN, A NRC - No Detailed Affiliation
 Given 1p 17042 310

--8302040304 Mod 7, extending completion date until 821230, to "Disease Incidence Rates From Occupational Exposure to Hazardous Substances"
 LUTZ, F J Battelle Memorial Institute, Columbus Laboratories
 GUSTAVE, R P Division of Contracts FIN B-10660 NRC-01-B0-016
 83/01/19 1p 17042 311

8302040452 Notification of contract execution, Mod 4 to "Technical Assistance to Support IE Personnel in Investigations of Incidents" Contractor Parameter, Inc
 HOLLETT, B Technical Assistance Contracts Branch FIN B-1302
 NRC-05-B2-249 83/01/20, BLAHA, J Director's Office, Office of
 Inspection and Enforcement LAUDAN, W NRC - No Detailed Affiliation
 Given 1p 17042, 346

--8302040458 Mod 4, providing addl funding, to "Technical Assistance to Support IE Personnel in Investigations of Incidents"
 LOFY, R A Parameter, Inc GUSTAVE, R P Division of Contracts
 FIN B-1302, NRC-05-B2-249 83/01/20 1p 17042 347

8302040460 Notification of contract execution, Mod 2 to "Study of Earthquake Hazards in NY State & Adjacent Areas"
 Contractor Columbia Univ
 WOLLETT, S Technical Assistance Contracts Branch FIN B-7243
 NRC-04-B1-179 83/01/17 BATSON, W Office of Nuclear Regulatory
 Research, Director MURPHY, A NRC - No Detailed Affiliation Given
 1p 17042 340

--8302040462 Mod 2, changing principal investigator, to "Study of Earthquake Hazards in NY State & Adjacent Areas"
 LEWIS, J P Columbia Univ GUSTAVE, R P Division of Contracts
 FIN B-7243 NRC-04-B1-179 83/01/17 1p 17042 341

8302040464 Notification of contract execution "Multiple Award Task Order Contract for ADP Development," awarded to Rehab Group, Inc
 MILFG, E Administrative Contracts Branch FIN B-8166
 NRC-33-B3-452 83/01/28 BASSETT, M Division of Data Automation &
 Management Information HARVES, J NRC - No Detailed Affiliation
 Given 1p 17042 266

--8302040465 Contract "Multiple Award Task Order Contract for ADP Development," awarded to Rehab Group Inc
 GUIO, R S Rehab Group, Inc MATTIA, M J Division of Contracts
 FIN B-8166 NRC-33-B3-452 83/01/28 28pp 17042 267

8302040480 Notification of contract execution, Mod 3 to "Implementation of Executive Development Program" Contractor Project Assoc, Inc
 MCLEAREN, T Administrative Contracts Branch NRC-10-79-368
 83/01/31 SPRINGER, M Office of Administration GOLDMAN, P J NRC
 - No Detailed Affiliation Given 1p 17045 361

--8302040485 Mod 3, deobligating funds to "Implementation of Executive Development Program"
 CONVEPANO, E M Project Associates HAGAN, T F Division of
 Contracts NRC-10-79-368 83/01/31 1p 17045 362

8302040488 Notification of contract execution, Mod 9 to "Publication Distribution Svcs" Contractor Computer Data Sys, Inc
 PAGE, M Administrative Contracts Branch NRC-10-B0-362 83/01/28
 DORIE, W M Office of Administration SCOTT, S Document Management
 Branch 1p 17059 346

--8302040491 Mod 9, extending period of performance to 830207, to "Publication Distribution Svcs"
 * Computer Data Systems, Inc SMITH, P A Division of Contracts
 NRC-10-B0-362 83/01/28 2pp 17059 347

8302070139 Notification of contract execution, Mod 7 to "Safeguards for High Level Waste Repositories" Contractor Science Applications, Inc
 SILVIS, R M Technical Assistance Contracts Branch FIN B-6376-9
 NRC-02-79-035 83/01/31 DAVIS, J Office of Nuclear Material
 Safety & Safeguards, Director GARDES, G NRC - No Detailed
 Affiliation Given 1p 17065 356

--8302070151 Mod 7, deobligating funds, to "Safeguards for High Level Waste Repositories"
 McDONALD, R J Science Applications, Inc GUSTAVE, R P Technical
 Assistance Contracts Branch FIN B-6376-9 NRC-02-79-035
 83/01/31 1p 17065 357

8302070629 Notification of contract execution, Mod 5 to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbelt" Contractor FL State Univ
 SILVIS, R M Technical Assistance Contracts Branch FIN B-10538
 NRC-01-78-004 83/01/27 MINQUE, R P Office of Nuclear Regulatory
 Research, Director O'DONNELL, E NRC - No Detailed Affiliation
 Given 1p 17059 362

--8302070632 Mod 5, deobligating remaining funds, to "Characterization & Classification of Geologic Faults & Fractures in Appalachian Foldbelt"
 JOHNSON, R M Florida State Univ GUSTAVE, R P Division of
 Contracts FIN B-10538 NRC-01-78-004 83/01/27 1p
 17059 363

8302070633 Notification of contract execution, Mod 6 to "Trench Design & Const Techniques" Contractor US Army Corps of Engineers,
 US Army Waterways Experiment Station
 FLEENOR, C Technical Assistance Contracts Branch NRC-02-B1-034
 83/01/10 DAVIS, J Office of Nuclear Material Safety &
 Safeguards, Director PENNIFILL, R NRC - No Detailed Affiliation
 Given 1p 17059 356

--8302070637 Mod 6, extending period of performance to 830115, revising billing instructions & incorporating updated NRC Manual Chapter 3202, to "Trench Design & Const Techniques"
 MARCUSON, W F Army, Dept of, Corps of Engineers NRC-02-B1-034
 83/01/10 2pp 17059 357

NONDOCKETED ITEMS

8302080060 Notification of contract execution, Mod 1 to "NRC Issuances & Indexes " Contractor Data Composition Svcs, Inc
PAGE, M Administrative Contracts Branch NRC-10-82-368 83/01/31
BESAH, W J Division of Technical Information & Document Control
SAVOLAINEN, A NRC - No Detailed Affiliation Given 1p 17104 257

--8302080064 Mod 1, decreasing funding for termination, to "NRC Issuances & Indexes "
HALEY, K T Data Composition Services, Inc SMITH, P A Division of Contracts NRC-10-82-368 83/01/31 2pp 17104 258

8302080067 Notification of contract execution, Mod 2 to "Study Entitled, 'Exam of Agreement State Program "' Contractor, Natl Governors Assoc
PAGE, M Administrative Contracts Branch FIN B-1667
NRC-06-81-293 83/01/27 KERR, O W Office of State Programs.
Director LUBENAU, J NRC - No Detailed Affiliation Given 1p 17106 255

--8302080070 Mod 2, extending period of performance & final rept delivery date until 830131, to "Study Entitled, 'Exam of Agreement State Program "'
FARBER, S O National Governors' Association SMITH, P A Division of Contracts FIN B-1667 NRC-06-81-293 83/01/27 1p 17106 256

8302080129 Notification of contract execution "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LHR Specific Accident Conditions, "' awarded to Rowe Assoc
TOWNSEND, B L Administrative Contracts Branch FIN B-8968
NRC-04-83-007 83/01/25 BASSETT, O E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 17103 300

--8302080134 Contract "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept Entitled 'Radionuclide Release Under LHR Specific Accident Conditions, "' awarded to Rowe Assoc
ROWE, D S Rowe Associates REDELLO, J E Division of Contracts FIN B-8968 NRC-04-83-007 83/01/25 4pp 17103 301

8302080429 Notification of contract execution "1974 & 80 Editions of ASME Boiler & Pressure Vessel Codes," awarded to ASME
HAGAN, Y H Administrative Contracts Branch NRC-10-83-313 83/01/25
BESAH, W Division of Technical Information & Document Control
DEVINE, R NRC - No Detailed Affiliation Given 1p 17074 259

--8302080433 Contract "1974, 77 & 80 Editions of ASME Boiler & Pressure Vessel Codes," awarded to ASME
AGUILERA, M F American Society of Mechanical Engineers
MATTIA, M J Division of Contracts NRC-10-83-313 83/01/25 52pp 17074 260

8302090024 Notification of contract execution, Mod 2 to "Intrinsic Germanium Gamma-Ray Detector " Contractor Princeton Gamma-Tech, Inc
PERLMAN, J Division of Contracts NRC-28-82-716 83/01/26
MCQUEEN, J D Division of Emergency Preparedness & Operational Support KOTTAH, J Region I, Office of Director 1p 17119 152

--8302090030 Mod 2, changing delivery date to 821230 & decreasing funding, to "Intrinsic Germanium Gamma-Ray Detector "
FISCHBERG, A Princeton Gamma-Tech, Inc MATTIA, M J Division of Contracts NRC-28-82-716 83/01/26 1p 17119 153

8302090263 Notification of contract execution, Mod 2 to "Geotechnical Engineering of Operator Reactor Plants " Contractor US Army Corps of Engineers
BILVIS, R M Technical Assistance Contracts Branch FIN B-6882
NRC-03-81-121 83/02/04 DENTON, H R Office of Nuclear Reactor Regulation, Director LEAR, O NRC - No Detailed Affiliation Given 1p 17117 342

--8302090270 Mod 2, deobligating funds, to "Geotechnical Engineering Reviews of Operator Reactor Plants "
KAVANAUGH, P F Army, Dept. of, Corps of Engineers OUSTAVE, R P Division of Contracts FIN B-6882 NRC-03-81-121 83/02/04 1p. 17117 343

8302090500 Notification of contract execution, Mod 1 to "Fire Protection Program Review & Evaluation " Contractor Schirmer Engineering Corp
FIELDS, J A Technical Assistance Contracts Branch
NRC-03-82-093-02 82/12/15 VOLLMER, R H Division of Engineering FERGUSON, R NRC - No Detailed Affiliation Given 1p 17108 337

8302090504 Mod 1, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Fire Protection Program Review & Evaluation "
OSMAN, R Schirmer Engineering Corp HAGAN, T F Division of Contracts NRC-03-82-093-02 82/12/15 1p 17108 338

8302090507 Notification of contract execution, Mod 1 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation "
Contractor Simons Li & Assoc, Inc
FIELDS, J A Technical Assistance Contracts Branch
NRC-02-79-031-06 82/12/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director OLLEN, D NRC - No Detailed Affiliation Given 1p 17108 335

--8302090510 Mod 1, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation "
SIMONS, D J Simons, Li & Associates, Inc HAGAN, T F Division of Contracts NRC-02-79-031-06 82/12/03 1p 17108 336

8302100011 Notification of grant execution, Mod 3 to "Structural Geology in Vicinity of Shawneetown Fault Zone, Southeastern IL " Grantee Univ of IL at Champaign
MCBERKOTT, D Technical Assistance Contracts Branch FIN Q-1018
NRC-0-04-81-016 83/01/28 BATSON, W Office of Nuclear Regulatory Research, Director WASTLER, S NRC - No Detailed Affiliation Given 1p 17135 173

--8302100013 Mod 3, providing addl funds, to "Structural Geology in Vicinity of Shawneetown Fault Zone, Southeastern IL "
BAZZAUI, C B Illinois, Univ of, Urbana-Champaign MORTON, K V Technical Assistance Contracts Branch FIN Q-1018
NRC-0-04-81-016 83/01/28 1p 17135 174

8302100017 Notification of contract execution, Mod 2 to "Tornado Windspeed Document " Contractor, Univ of Chicago
WOLLETT, S Technical Assistance Contracts Branch, FIN B-8108
NRC-04-82-004 83/01/20 BATSON, W Office of Nuclear Regulatory Research, Director ABBEY, R NRC - No Detailed Affiliation Given 1p 17135 171

--8302100021 Ltr Contract NRC-04-82-004, Mod 2 to "Tornado Windspeed Document," providing incremental funding Accepted by DB Sigal on 830120
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-8108
NRC-04-82-004 83/01/14 SIGAL, D S Chicago, Univ of 1p 17135 172

8302100026 Notification of contract execution, Mod 2 to "Fuel Cycle Project Review " Contractor Science Applications, Inc
WOLLETT, S Technical Assistance Contracts Branch FIN B-6694
NRC-04-80-178 83/01/24 FOREHAND, W Office of Nuclear Regulatory Research, Director ENG, C NRC - No Detailed Affiliation Given 1p 17135 165

--8302100029 Mod 2, extending completion date until 830215 on Task Order 5, to "Fuel Cycle Project Review "
BRAINARD, M F Science Applications, Inc GUSTAVE, R P Division of Contracts FIN B-6694 NRC-04-80-178 83/01/24 1p 17135 166

8302100033 Notification of contract execution, Mod 9 to "Development of Thermal Hydraulic Stability Methods for BWRs " Contractor Rensselaer Polytechnic Inst
SILVER, R M Technical Assistance Contracts Branch FIN B-7230.
NRC-03-78-128, 83/01/28 BATSON, W Office of Nuclear Regulatory Research, Director ZUBER, N NRC - No Detailed Affiliation Given 1p. 17135 163

--8302100038 Ltr Contract NRC-03-78-128, Mod 9, increasing funds to "Development of Thermal Hydraulic Stability Methods for BWRs " Accepted by JM LoGiudice on 830128
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-7230
NRC-02-78-128 82/12/17, SCAMMELL, R E Rensselaer Polytechnic Inst 1p 17135 164

8302100053 Notification of contract execution, Mod 2 to "Licensing Assistance/Geotechnical & Hydrological Evaluations "
Contractor Harding-Lawson Assoc
FIELDS, J A Technical Assistance Contracts Branch
NRC-02-80-033-05 83/01/04 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 17135 128

--8302100057 Mod 2, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Geotechnical & Hydrological Evaluations "
BEROHAN, K H Harding-Lawson Associates, HAGAN, T F Division of Contracts NRC-02-80-033-05 83/01/04 1p 17135 129

8302100074 Notification of contract execution, Mod 3 to "Licensing Assistance/Geotechnical & Hydrological Evaluations "
Contractor: Barr Engineering Co
FIELDS, J A Technical Assistance Contracts Branch
NRC-02-80-033-03 83/01/04 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 17135 123

NONDOCKETED ITEMS

417

--B302100081 Mod 3, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Geotechnical & Hydrological Evaluations " DICKSON, J D Barr Engineering Co HAGAN, T F Division of Contracts, NRC-02-80-033-03 83/01/04 1p 17135 124

B302100091 Notification of contract execution, Mod 9 to "Review of Tailings Mgt " Contractor CO State Univ
FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-082 83/01/04 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director FLEMING, T NRC - No Detailed Affiliation Given 1p 17135 065

--B302100078 Mod 9, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Review of Tailings Mgt " BROWN, J F Colorado State Univ HAGAN, T F Division of Contracts NRC-02-80-082 83/01/04 1p 17135-066

B302100106 Notification of contract execution, Mod 3 to "Licensing Assistance/Geotechnical & Hydrological Evaluations, " Contractor Intl Engineering Co
FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-033-04 83/01/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 17134 353

--B302100114 Mod 3, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Geotechnical & Hydrological Evaluations " CHRISTENSEN, R International Engineering Co HAGAN, T F Division of Contracts NRC-02-80-033-04 83/01/03 1p 17134, 354

B302100121 Notification of contract execution, Mod 1 to "Development of Matl Accounting Data Storage Analysis Sys " Contractor NUBAC, Inc.
FIELDS, J A Technical Assistance Contracts Branch NRC-02-82-033 83/01/04, DAVIS, J Office of Nuclear Material Safety & Safeguards, Director HESSINGER, M NRC - No Detailed Affiliation Given 1p 17134 325

--B302100128 Mod 1, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Development of Matl Accounting Data Storage Analysis Sys " * NUBAC, Inc HAGAN, T F Division of Contracts NRC-02-82-033 83/01/04 1p 17134 326

B302100136 Notification of contract execution, Mod 8 to "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities " Contractor NUBAC, Inc
FIELDS, J A Technical Assistance Contracts Branch, NRC-02-81-028 83/01/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director HESSINGER, M NRC - No Detailed Affiliation Given 1p 17134 285,

--B302100142 Mod 8, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities, " * NUBAC, Inc, HAGAN, T F Division of Contracts NRC-02-81-028 83/01/03 1p 17134-286,

B302100250 Notification of contract execution, Mod 2 to "Microfiche Verification & Retrofit " Contractor Labat-Anderson, Inc.
PAOE, M Administrative Contracts Branch, NRC-10-82-425 83/02/03 BEBAW, W J Division of Technical Information & Document Control BODCZLAG, J, SCOTT, S Document Management Branch 1p 17134, 110

--B302100252 Mod 2, increasing funding, to "Microfiche Verification & Retrofit " * Labat-Anderson, Inc, SMITH, P A Division of Contracts, NRC-10-82-425 83/02/03 1p 17134 111,

B302100485 Notification of contract execution, Mod 2 to "Licensing Assistance/Geotechnical & Hydrological Evaluation " Contractor Converse Ward Davis Dixon, Inc
FIELDS, J A Technical Assistance Contracts Branch, NRC-02-80-033-07 82/12/21 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P. NRC - No Detailed Affiliation Given 1p 17143: 271

--B302100489 Mod 2, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Geotechnical & Hydrological Evaluation " LESKY, A G Converse, Davis & Associates, HAGAN, T F, Division of Contracts, NRC-02-80-033-07 82/12/21 1p 17143-272

B302100499 Notification of contract execution, Mod 1 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " Contractor Energy Resources Co, Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-02-79-031-07 83/01/04, DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GILLEN, D NRC - No Detailed Affiliation Given 1p 17143 263

--B302100501 Mod 1, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " GATES, H Energy Resources Co, Inc HAGAN, T F Division of Contracts NRC-02-79-031-07 83/01/04 1p 17143 264

B302150728 Notification of contract execution, Mod 4 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " Contractor Geotechnical Engineers, Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-02-79-031-01 83/01/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director ROSSDACH, L NRC - No Detailed Affiliation Given 1p 17160 107

--B302150736 Mod 4, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation, " CASTRO, O. Geotechnical Engineers, Inc HAGAN, T F Technical Assistance Contracts Branch NRC-02-79-031-01 83/01/03 1p 17160 108

B302150761 Notification of contract execution, Task Order 28 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " Contractor Parameter, Inc.
WOLLETT, S Technical Assistance Contracts Branch FIN B-1302 NRC-03-82-249 83/02/07 BLAHA, J Director's Office, Office of Inspection and Enforcement LAUDAN, W NRC - No Detailed Affiliation Given 1p. 17158 238

B302160006 Notification of contract execution, Mod 1 to "Fire Protection Program Review & Evaluation " Contractor FFE Group
FIELDS, J A Technical Assistance Contracts Branch NRC-03-82-093-03 83/01/04 VOLLMER, R H Division of Engineering FERQUEBN, R NRC - No Detailed Affiliation Given 1p 17170 356

--B302160009 Mod 1, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Fire Protection Program Review & Evaluation " BERG, K E FFE Group, The HAGAN, T F Division of Contracts NRC-03-82-093-03 83/01/04 1p 17170 357

B302160029 Notification of grant execution, Mod 1 to "Publication of BBSA " * Orante Seismological Soc of America
MCBERNITT, D Technical Assistance Contracts Branch FIN G-1048 NRC-0-04-82 006 83/02/04 BATSON, W. Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p. 17170 358

--B302160037 Mod 1, providing addl funds & extending period of performance to B30631, to "Publication of BBSA " NEWMAN, B. Seismological Society of America MORTON, K V Division of Contracts, FIN G-1048 NRC-0-04-82-006 83/02/04 1p 17170 359

B302160485 Notification of contract execution, Mod 5 to "Support of Continuing Activities of US Natl Committee for Rock Mechanics " Contractor US Bureau of Mines
FLEENOR, C. Technical Assistance Contracts Branch FIN B-6932-3 NRC-02-80-038, 83/01/10 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director SEAMANS, T NRC - No Detailed Affiliation Given, 1p 17173 226,

--B302160491 Mod 5, increasing funding for FY83, to "Support of Continuing Activities of US Natl Committee for Rock Mechanics " * Interior, Dept. of, Bureau of Mines GUSTAVE, R. P. Division of Contracts FIN B-6932-3 NRC-02-80-038, 83/01/10, 1p 17173, 227

B302160497 Notification of contract execution, Mod 2 to "Hydrological Engineering (Coastal) Case Review 1, " Contractor, US Dept of Army.
FIELDS, J A. Division of Contracts NRC-03-81-110 83/01/04 VOLLMER, R H Division of Engineering LEAR, O. NRC - No Detailed Affiliation Given, 1p 17176-328

--B302160502 Mod 2, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Hydrological Engineering (Coastal) Case Review 1, " BISHOP, T E Army, Dept. of HAGAN, T F Division of Contracts NRC-03-81-110 83/01/04, 1p 17176 329

NONDOCKETED ITEMS

- 8302160507 Notification of contract execution, Mod 1 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " Contractor Weston Designers Consultants
FIELDER, J. A. Technical Assistance Contracts Branch
NRC-02-79-031-08 83/01/03 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director ROSSBACH, L. NRC - No Detailed Affiliation Given 1p 17176 321
- 8302160509 Mod 1, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance Tailings Mgt Program Technical Evaluation " THOMPSON, A. F. Roy F. Weston, Inc. HAGAN, T. F. Division of Contracts NRC-02-79-031-08 83/01/03 1p 17176 322
- 8302170384 Notification of contract execution, Mod 9 to "Word Processing Svcs " Contractor Automated Correspondence Sys., Inc.
SMITH, P. A. Division of Contracts NRC-10-80-702 83/02/07 SPRINGER, M. L. Office of Administration JOHANSEN, J. NRC - No Detailed Affiliation Given 1p 17195 293
- 8302170389 Mod 9, increasing funds initially obligated, to "Word Processing Svcs " * Automated Correspondence Systems, Inc. SMITH, P. A. Division of Contracts NRC-10-80-702 83/02/07 1p 17195 294
- 8302170390 Notification of contract execution, Mod 15 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co. Inc.
PAGE, H. Administrative Contracts Branch FIN B-1311 NRC-17-80-448 83/02/04 CHILK, S. J., SULLIVAN, P. Office of the Secretary of the Commission MCNAMARA, A. Atomic Safety and Licensing Board Panel 1p 17195 289
- 8302170394 Mod 15, extending period of performance to 830315 & increasing funds, to "Stenographic Reporting Svcs " SHARP, I. H. Alderson Reporting SMITH, P. A. Division of Contracts FIN B-1311 NRC-17-80-448 83/02/04 1p 17195 290
- 8302170421 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to GA Dept of Natural Resources
MCDEHOTT, D. Technical Assistance Contracts Branch. FIN B-8404 NRC-29-83-625 83/02/09 LOY, T. N. Region 2, Office of Director MONTGOMERY, D. M. NRC - No Detailed Affiliation Given. 1p 17195 222
- 8302170424 Contract "Radiation Monitoring Program Requirements," awarded to GA Dept of Natural Resources
LEDBETTER, J. L. Georgia, State of MORTON, K. V. Division of Contracts FIN B-8404 NRC-29-83-625 83/02/09 14pp 17195 223
- 8302170425 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of MA
MCDEHOTT, D. Technical Assistance Contracts Branch FIN B-8350 NRC-28-83-606 83/02/09 MCSCHAR, J. Region 1, Office of Director COSTELLO, F. NRC - No Detailed Affiliation Given 1p 17205 154
- 8302170429 Contract "Radiation Monitoring Program Requirements," awarded to State of MA
FRECKETTE, A. L. Massachusetts, Commonwealth of, MORTON, K. V. Division of Contracts FIN B-8350 NRC-28-83-606 83/02/09 15pp 17205 155
- 8302170484 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of AR
MCDEHOTT, D. Technical Assistance Contracts Branch FIN B-8500 NRC-31-83-667 83/02/09 MEYERS, D. M. Region 4, Office of Director NICHOLAS, J. B. NRC - No Detailed Affiliation Given 1p 17203 194
- 8302170489 Contract "Radiation Monitoring Program Requirements," awarded to State of AR
SALTZMAN, B. N. Arkansas, State of MORTON, K. V. Technical Assistance Contracts Branch FIN B-8500 NRC-31-83-667 83/02/09 18pp. 17203 195
- 8302170536 Notification of grant execution, Mod 2 to "Variance Propagation in Fault Trees " Grantee MIT.
MCDEHOTT, D. Technical Assistance Contracts Branch FIN Q-1033 NRC-0-04-82-002 83/02/08 BATSON, W. Office of Nuclear Regulatory Research, Director. JOHNSON, J. NRC - No Detailed Affiliation Given 1p 17197 126
- 8302170540 Mod 2, extending period of performance to 830131, to "Variance Propagation in Fault Trees " DICKSON, H. R. Massachusetts Institute of Technology. MORTON, K. V. Technical Assistance Contracts Branch FIN Q-1033 NRC-0-04-82-002 83/02/08 1p 17197 127
- 8302170545 Notification of grant execution, Mod 2 to "Natural Connection Heat Transfer in Spent Breeder Fuel Shipping Configurations " Contractor Howard Univ.
MCDEHOTT, D. Technical Assistance Contracts Branch FIN Q-1015 NRC-0-04-81-007 83/02/09 BATSON, W. Office of Nuclear Regulatory Research, Director LARKINS, J. NRC - No Detailed Affiliation Given 1p 17197 132.
- 8302170549 Mod 2, extending grant period to 830228, to "Natural Connection Heat Transfer in Spent Breeder Fuel Shipping Configurations " * Howard Univ. MORTON, K. V. Technical Assistance Contracts Branch FIN Q-1015 NRC-0-04-81-007 83/02/09 1p 17197 133
- 8302170566 Notification of contract execution, Mod 4 to "Geophysical-Geological Studies of Possible Extensions of New Madrid Fault Zone " Contractor Purdue Research Foundation
WOLLETT, S. Technical Assistance Contracts Branch FIN B-8077, NRC-04-81-195 83/02/10 BATSON, W. Office of Nuclear Regulatory Research, Director WASTLER, S. NRC - No Detailed Affiliation Given 1p 17197 183
- 8302170571 Mod 4, increasing funding for FY83 thru 840929, to "Geophysical-Geological Studies of Possible Extensions of New Madrid Fault Zone " * Purdue Research Foundation GUSTAVE, R. P. Technical Assistance Contracts Branch FIN B-8077 NRC-04-81-195 83/02/10 1p. 17197 184
- 8302180474 Notification of contract execution, Mod 3 to "Performance of Engineered Barriers in Geologic Repository " Contractor Golder Assoc. Inc.
FIELDER, J. A. Technical Assistance Contracts Branch NRC-02-81-027 83/01/03 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director PITTIGLIO, L. NRC - No Detailed Affiliation Given 1p 17221 321
- 8302180478 Mod 3, changing address for submission of invoices & incorporating B20429 revised Manual Chapter 3202, to "Performance of Engineered Barriers in Geologic Repository " NEBT, S. J. Golder Associates HAGAN, T. F. Division of Contracts, NRC-02-81-027 83/01/03 1p 17221 322
- 8302180501 Notification of contract execution "Consultant Svcs of R. Budnitz to Review SEP Integrated Plant Safety Assessment Repts," awarded to Future Resources Assoc.
FIELDER, J. A. Technical Assistance Contracts Branch FIN B-8636 NRC-03-83-099 83/02/10 EISENHUT, D. Division of Licensing GRIMES, G. NRC - No Detailed Affiliation Given 1p 17221 309
- 8302180519 Contract "Consultant Svcs of R. Budnitz to Review SEP Integrated Plant Safety Assessment Repts," awarded to Future Resources Assoc.
BUDNITZ, R. J. Future Resources Associates, Inc. MORTON, K. V. Division of Contracts FIN B-8636 NRC-03-83-099 83/02/10 11pp 17221 310
- 8302180512 Notification of contract execution, Mod 1 to "Subscription to Energy Daily," Contractor Energy Daily
PERLMAN, J. Administrative Contracts Branch. NRC-10-82-394 83/02/07 BEGAW, H. J. Division of Technical Information & Document Control CONYNGHAM, M. NRC - No Detailed Affiliation Given 1p 17221 265
- 8302180513 Mod 1, extending period of contract to 840131, to "Subscription to Energy Daily " THOMAS, B. Energy Daily, Inc. SMITH, P. A. Administrative Contracts Branch. NRC-10-82-394 83/02/07 2pp 17221 266
- 8302180515 Notification of contract execution, Mod 2 to "Micrographic Svcs of Source Drawing Documents for Agency " Contractor Microtech Industries, Inc.
PERLMAN, J. Administrative Contracts Branch NRC-10-82-360 83/01/28 DORIE, W. Office of Administration SCOTT, S., SKOCZLAS, J. Document Management Branch 1p 17221 263
- 8302180516 Mod 2, increasing funding through Mar 1984, to "Micrographic Svcs of Source Drawing Documents for Agency " * Microtech Industries, Inc. SMITH, P. A. Administrative Contracts Branch NRC-10-82-360 83/01/28 1p 17221 264
- 8302180523 Notification of contract execution, Mod 7 to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Operations." Contractor RE Williams & Assoc.
FIELDER, J. A. Technical Assistance Contracts Branch. NRC-02-81-039 82/12/15 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director GARCIA, P. NRC - No Detailed Affiliation Given 1p 17221 256

NONDOCKETED ITEMS

419

--8302180525 Mod 7, revising address for submission of invoices & incorporating revised Manual Chapter 3202, to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Operations " WILLIAMS, R E R E Williams & Associates, Inc HAGAN, T F Division of Contracts NRC-02-81-039 82/12/15 1p 17221 257

8302220020 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to NC Dept of Human Resources MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8406 NRC-29-83-627 83/02/08 LOY, T N Region 2, Office of Director MCINTOMERY, D M NRC - No Detailed Affiliation Given 1p 17227 354

--8302220025 Contract "Radiation Monitoring Program Requirements," awarded to NC Dept of Human Resources WILKERSON, I D North Carolina, State of MORTON, K V Division of Contracts FIN B-8406 NRC-29-83-627 83/02/08 8pp 17227 355

8302220036 Notification of contract execution, "Radiation Monitoring Program Requirements," awarded to MO Div of Health MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8434. NRC-30-83-643 83/02/09 PAPPAS, H Region 3, Office of Director GETHMAN, M J NRC - No Detailed Affiliation Given 1p 17227 336

--8302220042 Contract, "Radiation Monitoring Program Requirements," awarded to MO Div of Health * Missouri, State of MORTON, K V Division of Contracts. FIN B-8434 NRC-30-83-643 83/02/09 7pp 17227 337

8302220068 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to SC Dept of Health & Environ Control, MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8403 NRC-29-83-624 83/02/09 LOY, T N Region 2, Office of Director MCINTOMERY, D M NRC - No Detailed Affiliation Given 1p 17234 260

--8302220074 Contract "Radiation Monitoring Program Requirements," awarded to SC Dept of Health & Environ Control DANTZLER, M U South Carolina, State of MORTON, K V Division of Contracts FIN B-8403 NRC-29-83-624, 83/02/09 15pp, 17234 201

8302220440 Notification of contract execution, Mod B to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Recovery Operations " Contractor Williams-Robinette & Assoc FIELDS, J A Technical Assistance Contracts Branch FIN B-7301-3 NRC-02-81-039 83/01/27 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director QARCIA, P NRC - No Detailed Affiliation Given 1p 17236 331

--8302220445 Mod B, correcting accounting & appropriation data for Mod A under FIN B-7301-3 & FIN B-7383-3, to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Recovery Operations " * Williams-Robinette & Associates, Inc GUSTAVE, R P Division of Contracts FIN B-7301-3 NRC-02-81-039, 83/01/27 1p 17236 332.

8302220449 Notification of contract execution, Mod 7 to "Geotechnical Engineering Case Review," Contractor US Army Corps of Engineers. FIELDS, J A Technical Assistance Contracts Branch, NRC-03-79-167, 83/01/27 VOLLMER, R H Division of Engineering LEAR, Q NRC - No Detailed Affiliation Given, 1p 17236 322

--8302220453 Mod 7, extending period of performance to 830930 & changing estimated completion dates for Subtasks 4 & 5 to 830930, to "Geotechnical Engineering Case Review " KAVANAUGH, P F, Army, Dept of, Corps of Engineers, GUSTAVE, R P, Division of Contracts NRC-03-79-167, 83/01/27 1p 17236 323.

8302220457 Notification of contract execution, Mod 3 to "Analysis of Safeguards Needs for Transport of High Level Waste," Contractor, BM1. FIELDS, J A Technical Assistance Contracts Branch NRC-02-81-030 83/01/04, DAVIS, J, Office of Nuclear Material Safety & Safeguards, Director SAWYER, C, NRC - No Detailed Affiliation Given 1p 17236 320.

--8302220459 Mod 3, changing address for submission of invoices & incorporating 820429 Manual Chapter 3202, to "Analysis of Safeguards Needs for Transport of High Level Waste " LUKW, F J Battelle Memorial Institute, Columbus Laboratories. HAGAN, T F, Division of Contracts NRC-02-81-030, 83/01/04, 1p 17236 321

8302240051 Corrected notification of contract execution, Mod 8 to "Development & Implementation of Flow Analysis Sys Based on Synthetic Aperture Ultrasonic Imaging Technique " Contractor SHRI WOLLETT, S Technical Assistance Contracts Branch FIN B-5605 NRC-04-77-145 83/02/17 FOREHAND, W Office of Nuclear Regulatory Research, Director MUSCARA, J NRC - No Detailed Affiliation Given 1p 17268 319

8302240061 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) " Contractor Waterford CT Public Library LITTLE, M Administrative Contracts Branch NRC-10-82-379 83/02/17 FELTON, J M Division of Rules and Records SQUER, J NRC - No Detailed Affiliation Given 1p 17268 315

--8302240075 Mod 1, extending period of performance to 840301 & increasing funds, to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Waterford, CT REBELLO, J E Division of Contracts NRC-10-82-379 83/02/17 1p 17268 316

8302240071 Notification of contract execution, Mod 7 to "Newspaper Clipping Svc " Contractor Press Intelligence, Inc MCLEAREN, T Administrative Contracts Branch NRC-10-81-357 83/02/17 SPRINGER, M Office of Administration CONYNGHAM, M NRC - No Detailed Affiliation Given 1p 17268 313

--8302240079 Mod 7, deobligating unliquidated balance of funds remaining in contract, to "Newspaper Clipping Svc " JONES, J M Press Intelligence, Inc HAGAN, T F Administrative Contracts Branch NRC-10-81-357 83/02/17 1p 17268 314

8302240087 Notification of contract execution "Employee Grievance," awarded to H Fishgold HOYLE, A Administrative Contracts Branch NRC-10-83-339 83/02/15 BIRD, P E Division of Organization and Personnel JACKSON, J NRC - No Detailed Affiliation Given 1p 17268 306

--8302240091 Contract "Employee Grievance," awarded to H Fishgold FISHGOLD, H Fishgold, H REBELLO, J E Division of Contracts NRC-10-83-339 83/02/15 6pp 17268 307

8302240110 Notification of contract execution, Mod 6 to "Rental/Purchase Three Data General ECLIPSE C-330 Mini-Computers " Contractor Centennial Sys, Inc MCLEAREN, T Administrative Contracts Branch NRC-10-77-108 83/02/17 SPRINGER, M Office of Administration WINNINGHAM, J B NRC - No Detailed Affiliation Given 1p 17268 276

--8302240122 Mod 6, deobligating unliquidated balance of funds remaining under contract, to "Rental/Purchase Three Data General ECLIPSE C-330 Mini-Computers " MEISSNER, W C Centennial Systems, Inc HAGAN, T F Administrative Contracts Branch NRC-10-77-108 83/02/17 1p 17268 277

8302240178 Notification of contract execution, "Radiation Monitoring Program Requirements," awarded to State of NH MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8364 NRC-28-83-611 83/02/14 MCSCHAR, J Region 1, Office of Director COSTELLO, F NRC - No Detailed Affiliation Given 1p 17288 258

--8302240185 Contract "Radiation Monitoring Program Requirements," awarded to State of NH WALLACE, W T, New Hampshire, State of MORTON, K V Division of Contracts FIN B-8364 NRC-28-83-611 83/02/14 10pp 17288 259

8302240234 Notification of contract execution, Mod 5 to "Environ Monitoring Program W/State of NJ " Contractor State of NJ WOLLETT, S Research Contracts Branch, FIN B-5108 NRC-05-80-270 83/02/10, COBB, L I Director's Office, Office of Inspection and Enforcement COHEN, L K NRC - No Detailed Affiliation Given 1p, 17288 001.

--8302240240 Mod 5, decreasing funding, to "Environ Monitoring Program W/State of NJ " FISHER, E J New Jersey, State of GUSTAVE, R P Division of Contracts FIN B-5108 NRC-05-80-270 83/02/10 1p 17288 002

8302240269 Notification of contract execution, "Radiation Monitoring Program Requirements," awarded to State of DE MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8352 NRC-28-83-602 83/02/14 MCSCHAR, J Region 1, Office of Director COSTELLO, F NRC - No Detailed Affiliation Given 1p 17288 078.

--8302240275 Contract "Radiation Monitoring Program Requirements," awarded to State of DE WILSON, J E Delaware, State of MORTON, K V Division of Contracts FIN B-8352, NRC-28-83-602 83/02/14 12pp 17288 079

NONDOCKETED ITEMS

B302240391 Notification of contract execution, Mod 4 to "Performance of Engineered Barriers in Geologic Repository " Contractor Golder Associates, Inc. FIELD, J A Technical Assistance Contracts Branch FIN D-6986-3 NRC-02-B1-027 83/01/31 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director PITTIOLIO, L NRC - No Detailed Affiliation Given 1p 17289 282

--B302240395 Mod 4, increasing funding & scope of work to "Performance of Engineered Barriers in Geologic Repository " PENTZ, D L Golder Associates GUSTAVE, R P Division of Contracts FIN B-6986-3 NRC-02-B1-027 83/01/31 4pp 17289 283

B302250074 Notification of grant execution "Conference Entitled 'Anticipated & Abnormal Plant Transients in LWRs,' " awarded to ANS MCBERMOTT, D Technical Assistance Contracts Branch FIN Q-1045 NRC-0-04-B3 001 83/02/14 BATSON, W Office of Nuclear Regulatory Research, Director SULLIVAN, L NRC - No Detailed Affiliation Given 1p 17302 340

--B302250079 Grant "Conference Entitled 'Anticipated & Abnormal Plant Transients in LWRs,' " awarded to ANS MAJUMDAR, D American Nuclear Society MORTON, K V Division of Contracts FIN Q-1045 NRC-0-04-B3-001 83/02/14 2pp 17302 341

B302280242 Notification of contract execution, Mod 2 to "ADP Sys Support " Contractor SBA/Technassociates, Inc. GILDENHORN, A J Administrative Contracts Branch NRC-25-B2-319 83/02/01 BARRY, L Office of Resource Management, Director GELLMAN, C NRC - No Detailed Affiliation Given 1p 17322 208

--B302280252 Mod 2, adding new labor category & changing fee withholding provisions to "ADP Sys Support " DEWIKSTON, S F Small Business Administration OFFORD, J C Technassociates, Inc HAGAN, T F Administrative Contracts Branch NRC-25-B2-315 83/02/01 4pp 17322 209

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

B302010049 FOIA request for Special Review Panel rept & any other matls pertaining to NRC procedures for dealing w/differing prof opinions GRAHAM, J W Northwestern Univ 82/11/03 Division of Rules and Records 1p 16990 001

B302010054 Partial response to FOIA request for Special Review Panel rept re NRC procedures for differing prof opinions Similar requests under FOIA-79-475 & FOIA-79-531 available in PDR Forwards documents re NRC Manual Chapter 4125 FELTON, J M Division of Rules and Records 82/12/06 GRAHAM, J W Northwestern Univ. 1p 16990 002

--B302010057 Summary of 820910 meeting w/Special Review Panel to review functioning of agency procedures for resolution of differing prof opinions BINGER, K Affiliation Unknown 82/09/22 Affiliation Unknown 2pp 16990 003

--B302010061 Forwards marked-up Manual Chapter 4125 describing NRC policy & procedures for resolution of differing prof opinions Policy assures that all employees have opportunity to express differing prof opinions DIRCKS, W J Office of the Executive Director for Operations 80/10/03 NRC - No Detailed Affiliation Given 18pp. 16990 005

B302010065 Addl response to FOIA request for all documents considered by Commission in promulgating final rule on environ qualification & SECY-82-207. Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/12/06 CURRAN, D Harmon & Weiss 5pp 16990 023

--B112100049 SECY-81-6038 Recommends Commission approval for publication of notice of proposed rulemaking, "Environ Qualification of Electric Equipment for Nuclear Power Plants." DIRCKS, W J Office of the Executive Director for Operations. 81/11/16 15pp 16990 030

environ qualification of
ety Areas of cold
tatus &
or for Operations

--B211150056 Requests concise plant-by-plant status rept on environ qualification of electrical equipment for full compliance w/Commission Order CLI-80-21, Table form preferred GILINSKY, V Commissioners CLI-80-21 82/10/19 DIRCKS, W J Office of the Executive Director for Operations 1p 16990 044

--B302010071 Advises of amend to item d of staff requirements memo re equipment qualification of electrical equipment CHILK, S J Office of the Secretary of the Commission 81/11/24 Office of the Secretary of the Commission. 1p 16990 047.

--B302010082 Discusses history & lack of clarity in requirements for environ qualification of electrical equipment Rulemaking should be canceled until staff reviews existing programs ABBOTT, E Commissioners IE0-79-018 82/07/29 GARNER, D , LIAM, B D, ZECH, Q NRC - No Detailed Affiliation Given 7pp 16990 057

B302020338 Final response to FOIA request for documents re SEP Forwards SECY-77-545 Document available in PDR FELTON, J M Division of Rules and Records 82/12/27 GALLO, J Isham, Lincoln & Beals 1p 16999 152

--B302020339 SECY-77-545 Weekly info rept for wk ending 771014 REIM, T A Office of the Executive Director for Operations 77/10/18 25pp 16999 153

B210130458 PNL-4475 "Recommended Program for Development of Maint Guidelines for Nuclear Power Plants " BADALAMENTE, R , ASHTON, W B , CHOCKIE, A D Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2360 PNL-4475 82/09/30 NRC - No Detailed Affiliation Given 223pp 16996 029

--B212880528 "NRC Integrated Human Factors Program Plan " * Division of Human Factors Safety 82/11/30 64pp 16996 251

B302020382 Addl response to FOIA request for SECY-75-588, 588A, 588B, SECY-R-74-64, SECY-81-600A & SECY-81-622A Forwards SECY-R-74-64 & SECY-75-588 & 588B SECY-81-622A withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/12/03 CONNOR, L Doc-Search Associates 2pp 17011 176

--B302020385 SECY-R-74-064 Recommends approval of publication of notice in FR requesting comments on five alternative approaches to proprietary info in Commission licensing proceedings MUNTZINO, L M Atomic Energy Commission 73/11/01 26pp 17011 179

--B302020388 SECY-75-588B Recommends final rule changing Commission regulations in 10CFR2 790 re evaluation, protection & disclosure of proprietary info SHAPAR, H K Office of the Executive Legal Director 76/02/16 89pp 17011 205

--B302020391 SECY-75-588 Recommends final rule changing Commission regulations in 10CFR2 790 re evaluation, protection & disclosure of proprietary info SHAPAR, H K Office of the Executive Legal Director 75/10/08 114pp 17011 294

B302020390 FOIA request for documents pertaining to infiltration & surveillance of US nuclear weapons freeze movement by 20 listed groups. OLESH, S Affiliation Unknown 82/10/28 Division of Rules and Records 2pp 17009 088

B302020392 Responds to FOIA request for documents pertaining to infiltration & surveillance of US nuclear weapons freeze movement by 20 listed groups No documents located FELTON, J M Division of Rules and Records 82/12/02 OLESH, S Affiliation Unknown 1p 17009 090

B302020396 FOIA request for two categories of records which have been or will be provided per 8 Separ FOIA Request 82-569 McMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 82/12/29 FELTON, J M, Division of Rules and Records. 2pp 17009 085

B302020401 Responds to FOIA request for two categories of records per 8 Separ FOIA Request 82-569. Relevant records filed in FOIA Folder 82-A-19C (82-308) in PDR FELTON, J M, Division of Rules and Records 82/12/30 McMURRAY, C M, Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 1p. 17009 087

NONDOCKETED ITEMS

42

8302020406 Responds to appeal re denial of FOIA request for documents pertaining to environ qualification of electrical equipment. Appeal denied WM Shields 820503 memo withheld (ref FOIA Exemption 5)
CHILK, S J Office of the Secretary of the Commission 82/12/08
CURRAN, D Harmon & Weiss 2pp 17008 197

8302020435 FOIA request for seven categories of documents. Documents needed to prepare proposed questions on NRC 821014 direct testimony & DOE 821013 testimony for Commission by 821109
WEISS, E R. Natural Resources Defense Council 82/10/22 FELTON, J
Division of Rules and Records 2pp 17008 330

8302020461 Partial response to FOIA request for seven categories of documents Releasability of documents under review
FELTON, J. M. Division of Rules and Records 82/12/02 WEISS, E R
Harmon & Weiss 2pp 17008 332

8302020477 Partial response to FOIA request for SAND 81-1549 (NUREG/CR-2239), SAND 82-1110 (NUREG/CR-2723), NUREG-0773 & NUREG/CR-2326 & all documents re CRAC Code Forwards draft NUREG-0773 NUREG/CR-2239 available in PDR
FELTON, J M. Division of Rules and Records 82/12/02, ELLIOTT, C W
Thomas & Hair 1p 17008 334

--8302020483 NUREG-0773 DRAFT
REACTOR ACCIDENT SOURCE TERMS, DESIGN AND SITING
PERSPECTIVES
* NRC - No Detailed Affiliation Given 82/03/31 107pp
17008 336

8302040082 IE Insp Rept 30-11671/81-01 on 811103-04 No noncompliance noted Major areas inspected licensee actions re possession, disposal, operating & handling procedures assuring safe operation of radiography equipment, per IE Bulletin 80-22
QIBBONS, D R., SRENIANSKI, D J. Region 3, Chicago, Office of the Director (81/03/01) IE8-80-22 81/11/10 22pp 17045 155

--8302040091 Forwards IE Insp Rept 30-06182/81-01 on 811103-04 of activities under License 37-08042-01 No noncompliance noted Statistical data & draft ltr to licensee encl
WIEDEMAN, D Materials Radiation Protection Section 1 81/12/02
KINNEHAN, J Materials Radiological Protection Section. 5pp
17045 177.

--8302040095 IE Insp Rept 30-06182/81-01 on 811103-04. No noncompliance noted Major areas inspected licensee audits, training, radiation protection procedures, equipment & facilities, shipping incidents & inventory of byproduct matl
QIBBONS, D R., WIEDEMAN, D G. Materials Radiation Protection Section 1 81/11/30 24pp 17045 182

--8302040162 IE Insp Rept 30-04041/81-01 on 811102-04 Noncompliance noted: failure to utilize/possess Automation Industries Model 200-520-008 pigtail/drive cable assemblies or similar quick disconnect type assemblies per IE Bulletin 80-22.
QIBBONS, D R., WIEDEMAN, D G. Region 3, Chicago, Office of the Director (81/03/01). IE8-80-22 81/12/18 23pp 17045 248

8302040104 FOIA request that SECY-82-326 & SECY-82-315 be made available in PDR.
DOVE, K. L. Dove, K. L. 82/11/30 FELTON, J. Division of Rules and Records. 1p. 17061 081.

8302040108 Addl response to FOIA request for SECY-82-326 & SECY-82-315 Forwards SECY-82-326. Document also available in PDR
FELTON, J M. Division of Rules and Records 82/12/27 DOVE, K. L.
Dove, K. L. 1p 17061 082.

--8207010085 SECY-82-326
Requests approval of proposed rulemaking, policy statement & draft FR notice re backfitting
TOURTELLOTTIE, J Regulatory Reform Task Force 82/08/02. 20pp.
17061 083.

8302040114 FOIA request for four categories of records & info re contempt of court order or decree to which NRC is party.
AMBASH, J. W. Foley, Hoag & Elliot 82/12/10 FELTON, J M. Division of Rules and Records. 2pp 17043 335.

8302040118 Responds to FOIA request for four categories of records & info re contempt of court order or decree to which NRC is party NRC has no records subj to request. Info confirms 821228 telcon w/L Robinson
FELTON, J. M. Division of Rules and Records 82/12/29 QOLDBSTEIN, R
Foley, Hoag & Elliot. 1p. 17043 337.

8302040146 Submits comments on 771019 memo re policy concerning use of cameras during licensing hearings Counsel would be discomfoted by artificial lights & witnesses might tailor presentations
YORE, J R Atomic Safety and Licensing Board Panel 77/10/25
FOUCHARD, J J Office of Public Affairs 1p 17043 341

--8302040169 Forwards rev to proposed draft policy statement re camera coverage, incorporating comments on 771212 draft statement Presence of representative from OFC of Public Affairs during coverage recommended
YORE, J R Atomic Safety and Licensing Board Panel 77/12/13
FOUCHARD, J J. Office of Public Affairs ROSENTHAL, A Atomic Safety and Licensing Board Panel NELSON, J Office of the General Counsel 2pp 17043 346

--8302040173 Concurs w/JR Yore 771025 memo requesting that personal views be forwarded w/submittal to Commission re policy concerning camera coverage of adjudicatory hearings
ROSENTHAL, A S Atomic Safety and Licensing Board Panel 77/10/26
FOUCHARD, J. J. Office of Public Affairs 1p 17043 348

8302040467 Final response to FOIA request for SECY-82-39A, SECY-82-197, SECY-82-197A & SECY-82-197B SECY-82-197 withheld (ref FOIA Exemption 5)
FELTON, J M. Division of Rules and Records 82/12/27 GRABER, L
Affiliation Unknown 1p 17042 264

8302040470 FOIA request for documents re valve & basket problems on IF-300 casks & basket on two rail casks owned by Nuclear Assurance Corp
MILLAR, F Environmental Policy Institute 82/12/10 Division of Rules and Records 1p 17042 244

8302040478 Responds to FOIA request for documents re IF-300 cask valve & basket problems & basket on two rail casks owned by Nuclear Assurance Corp Forwards Documents 2 c & 2 f of app. Other documents listed available in PDR
FELTON, J M. Division of Rules and Records 82/12/27 MILLAR, F
Environmental Policy Institute 2pp 17042 245

--8302040482 "Presentation to NRC on IF-300 BWR Fuel Basket Problem "
* General Electric Co 82/10/07 6pp 17042 247

--8302040483 "Discussion Questions on 821021 Application GE Model IF-300 Packaging."
* NRC - No Detailed Affiliation Given 82/12/28 2pp
17042 253

8302040492 FOIA request for statement of work under Contract NRC-04-83-001
STEGER, W A Consad Research Corp NRC-04-83-001 83/01/04
Division of Contracts 1p 17042 258.

8302040496 Responds to FOIA request for statement of work under Contract NRC-04-83-001 awarded to Maxima Corp W/o encl statement of work.
FELTON, J M. Division of Rules and Records NRC-04-83-001
83/01/12 STEGER, W A Consad Research Corp 1p 17042 257

8302040532 FOIA request for info re specific license issued to AccuRay to supply general license holders w/Model 510 nucleonic thickness gauge
BTEPHAN, M B Consolidated Aluminum Corp 82/12/17 FELTON, J M
Division of Rules and Records 1p. 17042 255

8302040552 Responds to FOIA request for info re specific license issued to AccuRay to supply general license holders w/Model 510 nucleonic thickness gauge No documents available subj to request
FELTON, J M. Division of Rules and Records 83/01/13 BRAW, A
Consolidated Aluminum Corp. 1p. 17042 256

8302070001 FOIA request for specific category of mailing labels for mailing complimentary copies of Nuclear Plant Safety Magazine
AGNIHOTRI, N K Equipment Qualification Engineering Services, Inc. 83/01/14. FELTON, J. M. Division of Rules and Records. 2pp.
17062 346

8302070002 FOIA request for specific category of mailing labels
AGNIHOTRI, N K Equipment Qualification Engineering Services, Inc 83/01/14. FELTON, J M. Division of Rules and Records. 1p
17062 348

8302070003 Responds to FOIA request for several categories of labels. Labels TC, AP & IC do not exist. W/o encl
FELTON, J M. Division of Rules and Records 83/01/27
AGNIHOTRI, N K Equipment Qualification Engineering Services, Inc 1p 17062 349

NONDOCKETED ITEMS

- 8302070005 Addl response to FOIA request for Special Review Panel rept & matl re procedures for dealing w/differing prof opinions
No documents available subj to request
FELTON, J M Division of Rules and Records 83/01/13 GRAHAM, J W
Northwestern Univ 1p 17062 344
- 8302070006 FOIA request for SECY-82-207D, SECY-82-203 & SECY-82-203A
PEDRO, J NUS Corp CD-LIS-8803 82/12/21 Division of Rules and Records 1p 17062 342
- 8302070008 Responds to FOIA request for SECY-82-203, SECY-82-203A & SECY-82-207D Documents available in PDR
FELTON, J M Division of Rules and Records 83/01/13 PEDRO, J NUS Corp 1p 17062 343
- 8302070010 FOIA request for names & addresses of members of NRC Medical Review Committee
SAVINI, R J LXI, Inc 83/01/18 Division of Rules and Records 1p 17062 340
- 8302070013 Responds to FOIA request for names & addresses of members of NRC Medical Review Committee
FELTON, J M Division of Rules and Records 83/01/28 SAVINI, R J LXI, Inc 1p 17062 341
- 8302070025 Addl response to FOIA request for documents re packaging & transporting of spent nuclear fuel away from reactor sites by util Forwards Documents 1-27 Documents 28-31 withheld (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 82/11/23 RAPKIN, A Illinois, State of 3pp 17062 013
- 8302070042 Forwards 10CFR73.37 & NUREG-0561 for physical protection of shipments of irradiated reactor fuel per 791212 telcon
HILLMAN, C Physical Security Licensing Branch 79/12/12 OWEN, L NRC - No Detailed Affiliation Given 1p 17062 024
- 8302070098 Forwards two bypass routes for Springfield, IL Alternate 1 recommended bypass for shipments using US-36 from MD enroute to Battelle or Morris, KS W/o encl
MITCHELL, H M NRC - No Detailed Affiliation Given 80/08/28 HILLMAN, C NRC - No Detailed Affiliation Given 1p 17062 054
- 8302070070 FOIA request for 22 categories of documents
SHOLLY, B C Union of Concerned Scientists 82/11/02 FELTON, J M Division of Rules and Records 4pp 17063 001
- 8302070076 Partial response to FOIA request for 22 categories of documents Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App B documents completely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, B Union of Concerned Scientists 6pp 17063 005
- 8108170251 Requests assistance re second quarter CY81 AQ rept to Congress Ofcs asked to review listed items & provide alternate selections or suggest deletions
CROOK, J L Director's Office 81/07/06 MARTORE, J Office of Nuclear Reactor Regulation, Director O'CONNELL, R L, GRAHAM, R M Office of Nuclear Material Safety & Safeguards, Director 11p 17064 157
- 8202160093 Forwards R Blond & M Taylor 820125 briefing notes re technical relationships between source term & emergency planning; & implementation NUREG-0771 will be revised to include addl requirements for review of ESF effectiveness
BLOND, R M Reactor Risk Branch 82/01/28 SCODDINS, R M Administration & Resources Control Staff 5pp 17064 303
- 8302070085 "Status of Support Work for Reactor Siting Criteria Rulemaking" & draft "Concept Paper - Study to Evaluate & Review Economic Component of CRAC Model"
* NRC - No Detailed Affiliation Given 82/12/21 25pp 17063 011
- 8302070090 SAI-013-79-585LJ
"Nuclear Sys Components - Review of Typical Design & Operating Characteristics of Components Used in Nuclear Power Plant Sys"
LOBNER, P, GOLDMAN, L, KUHN, T. Science Applications, Inc 79/03/21 331pp 17063 036
- 8302070123 Documents 801113 telcon w/L Norrholm re potential sabotage at Facility Ramifications re sodium chloride contamination of hydrazine addition tank & subsequent contamination of auxiliary feedwater sys discussed
RESNER, M E Office of Inspector & Auditor 80/11/23, Office of Inspector & Auditor. 2pp, 17064 010. 24X Fiche 50-000, 82/12/21, 8302070076
- 8302070129 Documents 801114 telcon w/J Camera of FBI re potential sabotage at Facility Union problems & acts of vandalism existed prior to 800910 Incident
RESNER, M E Office of Inspector & Auditor 80/11/25 Office of Inspector & Auditor 1p 17064 012 24X Fiche 50-000, 82/12/21, 8302070076
- 8302070148 Responds to Commissioner Ahearn requests during B10529 briefing on SECY-81-240, draft NUREG-0771 & 0772 re accident source term assumptions Comments will be sought from outside NRC Detailed analysis encl.
DIRCKS, W J Office of the Executive Director for Operations 81/06/29 CHILK, B J Office of the Secretary of the Commission 11pp 17064 145 24X Fiche 50-000, 82/12/21, 8302070076
- 8302070157 "Improving Socioeconomic Impact Assessments of Nuclear Power Plant Accidents," draft
TAHIL, J J, BERZIO, K, CROWN, F J Battelle Memorial Institute, Pacific Northwest Laboratory 81/11/30 NRC - No Detailed Affiliation Given 139pp 17064 161
- 8302070161 Draft input comments for EDO-11387 (REB-94) on EPRI ltrs to FEMA & Chairman Palladino
SILBERBERG, M NRC - No Detailed Affiliation Given 82/01/18 3pp 17064 300
- 8302070181 Forwards comments on ORNL draft interim source term rept Source term estimates considered high for listed reasons Importance of primary sys retention & effects of delayed containment failure on source reduction underestimated
SHERRY, R Fuel Behavior Branch 82/03/11 PASEDA, W Division of Accident Evaluation 1pp 17064 316
- 8302070186 Forwards draft Chapters 1, 2, 6 & app of NUREG/CR-2629, "Interim Source Term Assumptions for Emergency Planning & Equipment Qualification," for review in 820318 meeting in Bethesda, MD
CHESTER, R O Oak Ridge National Laboratory 82/03/11 THADANI, M C NRC - No Detailed Affiliation Given 79pp 17064 327
- 8302070205 "NRC Physical Research on Radiological Source Term"
KELBER, C N Division of Accident Evaluation 82/06/30 23pp 17065 044
- 8302070211 Rept entitled "NRC Activities in Regulation of Radiation," presented at AIF 821003-06 Conference on Radiation Issues for Nuclear Industry in New Orleans, LA
MINOQUE, R B Office of Nuclear Regulatory Research, Director. 82/10/03 20pp 17065 067
- 8302070218 PNS-I-82-010 on 820816, manual isolation stop valve to air start motors for 2C diesel generator found in shut position Possibly caused by deliberate tampering Operability checks of all rotating ECCB equipment conducted
TRIPP, L Region 1, Office of Director 82/08/17 2pp 17065 087 24X Fiche 50-000, 82/12/21, 8302070076
- 8302070228 PNS-I-82-009 on 820809, miscellaneous ac 115-volt distribution panel 12 lost power supply (station essential controls inverter 12) due to tripped position of inverter breaker Probably caused by sabotage Surveillances initiated.
MARTIN, T Region 1, Office of Director 82/08/16, 1p 17065 089, 24X Fiche 50-000, 82/12/21, 8302070076
- 8302070236 PNS-I-82-003 on 820428, at 100% power, one operating steam generator feedwater pump tripped due to misaligned isolation & vent valves Caused by sabotage Valves aligned Labor union contract negotiations in progress
TRIPP, L E Region 1, Office of Director 82/04/29 1p 17065 090 24X Fiche 50-000, 82/12/21, 8302070076
- 8302070240 SAN76-0534
"Influence of Plume Rise on Consequences of Radioactive Matl Releases"
RUEB, A J, WAYLAND, J R, RITCHIE, L T Sandia Laboratories UC-78 77/01/31 NRC - No Detailed Affiliation Given 26pp 17065 091
- 8302070244 Test description of nuclear power plant siting Pp 5-9
* Sandia Laboratories 82/12/21 6pp 17063 130
- 8302070146 Addl response to FOIA request for five categories of documents Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) Info re item 4 available in PDR No documents re item 5 located
FELTON, J M Division of Rules and Records 82/12/02 HIATT, B Ohio Citizens for Responsible Energy 4pp 17065 325 24X Fiche 50-000, 82/12/02, 8302070146

NONDOCKETED ITEMS

42

- 8302070156 Informs that no legal basis exists to prevent removal of beep tones from telephone sys in NRC Operations Ctr, in response to 810507 memo Proposed amend to Manual Chapter 0270 will provide adequate notice to personnel
RAAGAN, H B Operations & Administrative Division 81/06/04
KERR, V B Telecommunications Branch 2pp 17065 341
- 8302080018 Responds to appeal re denial of FOIA request for BECY-82-377 & BECY-83-377A Appeal denied Documents withheld (ref FOIA Exemption 5)
CHILK, B J Office of the Secretary of the Commission 83/01/12
NEKMAN, K A Debevoise & Liberman 2pp 17106 159
- 8302080028 FOIA request for BECY-82-489 re licensing of tritium - illuminated gun sights
BASS, E J GOVAN, E L Covington & Burling 82/12/17 NORRY, P.
Office of Administration. 3pp 17105 239
- 8302080032 Responds to FOIA request for BECY-82-489 Document completely withheld, predecisional info in ongoing policy deliberation (ref FOIA Exemption 5)
ROTHSCHILD, T Office of the Secretary of the Commission 83/01/12
Covington & Burling 2pp 17105 230
- 8302080038 FOIA request for "background calculations of very low probability events" referred to by R Bernero on 821101 when speaking of Sandia Rept, "Technical Guidance for Siting Criteria Development" Related info encl
GROSSMAN, K Island Closures News Service. 82/11/26. NRC - No Detailed Affiliation Given 3pp 17105 234.
- 8302080044 Responds to FOIA request for "background calculations of very low probability events" referred to by R Bernero on 821101. Forwards NUREG/CR-2239 "Technical Guidance for Siting Criteria Development" w/o encl
FELTON, J M Division of Rules and Records 83/01/13 GROSSMAN, K
Island Closures News Service 1p 17105 238.
- 8302080047 FOIA request for names & addresses of all persons in State of MI issued registration certificates for certain in-vitro clinical or lab testing under general license in 10CFR31.11
KRONZEK, A L. FOI Services 82/12/06 FELTON, J M, LAVING, D
Division of Rules and Records 1p 17100 007
- 8302080052 Responds to FOIA request for names & addresses of all persons in State of MI issued registration certificates for certain in-vitro clinical or lab testing under general license in 10CFR31.11. Forwards documents
FELTON, J M Division of Rules and Records 82/12/29 KRONZEK, A L
FOI Services 1p. 17100 008.
- 8302080056 "Registration Certificate-In-Vitro Testing W/Byproduct Matl Under General License 10CFR31.11." for State of MI
* NRC - No Detailed Affiliation Given. 82/12/29 1.349pp.
17100-009
- 8302080115 Forwards Matls Engineering Branch proposed Tech Specs re steam generator tubing surveillance, per 750707 memo.
Proposed Tech Specs developed on basis of comments on Reg Guide 1.83, Rev 1
MACCARY, R R Division of Technical Review (NRR-1975 only).
75/08/05 COLLIER, K.R. Division of Reactor Licensing (NRR-1975 only). 2pp. 17105-096.
- 8302080118 Proposed Tech Specs 4.4.5 & 3.12 re steam generator surveillance & secondary water monitoring requirements.
Spec for low & intermediate tensile strength carbon steel plates for pressure vessels encl
* Division of Technical Review (NRR-1975 only) 75/07/30 27pp
17105 098
- 8302080121 Forwards Matls Engineering Branch status rept re Generic Safety Item II, C.A.3, "Corrosion of Steam Generator Tubing in PHRS." Recommends continuation of generic safety item until end of 1976
ALMETER, F.M. Division of Technical Review (NRR-1975 only)
75/09/04 PAWLICKI, B.S. Division of Technical Review (NRR-1975 only). 14pp 17105-125
- 8302080122 Summary of 751121 meeting w/utls & Westinghouse re new type of imperfection discovered in recent addy current insps of dent steam generator tubes Investigation re listed unreviewed safety questions recommended.
KINTNER, L.L. Division of Reactor Licensing (NRR-1975 only)
75/11/24. KNIEL, K. Division of Reactor Licensing (NRR-1975 only) 4pp. 17105.139. 24X Fiche 50-000.82/12/17.8302080100
- 8302080135 "Update of Operations W/Westinghouse Steam Generators," presented at ANS 23rd annual meeting on 770612-16 in New York, NY
MALINOWSKI, D.D., FLETCHER, W.D. Westinghouse Electric Corp
77/06/12 17pp. 17105.157
- 8302080139 Trip rept of 770929 visit to Westinghouse in Pittsburgh, PA re generic programs concerning steam generator tube integrity Draft ltr from VP Knight to T Anderson & BNL
790814 memo encl
STUART, R J, GAMBLE, R M Engineering Branch (Pre 791030)
77/10/14 SHAD, L C Engineering Branch (Pre 791030) 12pp
17105 174
- 8302080141 Summary of 820302 meeting w/Westinghouse in Bethesda, MD re steam generator tube degradation & rupture accident mgt List of attendees & agenda encl Proprietary info withheld (ref 10CFR2.790)
WICHMAN, K R Operating Reactors Assessment Branch 82/03/02
Operating Reactors Assessment Branch 4pp 17105-186
- 8302080143 "Environ Assisted Cracking in LWR Sys," monthly progress rept for May 1982 Billing charges under "Financial Summary" deleted
SHACK, W J Argonne National Laboratory FIN A-2212 82/06/28
MUSCARA, J Materials Engineering Branch 19pp 17105 190
- 8302080147 IAEA-SM-218/26 DRAFT
Draft paper entitled "PHR Steam Generator Tubing Corrosion Problems," presented at IAEA 771010-14 Symposium on Application on Reliability Technology to Nuclear Power Plants in Vienna, Austria
* Affiliation Unknown 77/10/10 22pp 17105 209
- 8302080150 Excerpts of "US Experience in Steam Generator Degradation & BWR/PHR Pipe Cracking"
SHAD, L C BYROSNIDER, J R, BURNS, J J NRC - No Detailed Affiliation Given 82/12/17 3pp 17105 231
- 8302080395 FOIA request for 86 gummed labels to be attached to distribution codes for resident inspectors
FEIBELMAN, H M Robinson Group 83/01/13 CARR, J C Division of Rules and Records 1p 17107 043
- 8302080397 Respond to FOIA request for 86 gummed labels to be attached to distribution lists for resident inspectors
Labels encl w/o encl
FELTON, J M Division of Rules and Records 83/01/31
FEIBELMAN, H M Robinson Group 1p 17107 044
- 8302090005 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 App A documents available in PDR App B Documents 1-7 & 11-18 partially withheld (ref FOIA Exemptions & 7)
FELTON, J M Division of Rules and Records 83/01/04 DEVINE, T
Government Accountability Project 5pp 17124 001.
- 8302090107 Notifies that E Davis of Ope of Special Council of Merit Sys Protection has been contacted re recent ltr submitted to Special Council on behalf of T Applegate by Govt Accountability Project of Inst for Policy Studies
CUMMINGS, J J Office of Inspector & Auditor 83/12/10 AHEARNE, J,
GILINBY, V, HENDRIE, J Commissioners. 1p 17118 028
- 8302090460 Addl response to FOIA request for documents re IE Insp Rept 50-358/81-13 Forwards App A documents App B documents partially & completely withheld (ref FOIA Exemptions 3, 5, 6 & 7)
FELTON, J M Division of Rules and Records 83/01/10 DEVINE, T
Government Accountability Project 6pp 17123 214
- 8302100007 FOIA request for statement of work from RFP RS-RES-82-02P & name & telephone number of representative
FINK, M A Andrus Research Corp NRC-04-83-001 83/01/04
Division of Contracts 1p 17134 150
- 8302100010 Responds to FOIA request for statement of work from RFP RS-RES-82-022 & name & telephone number of technical representative Forwards statement of work Name & number of representative submitted
FELTON, J M Division of Rules and Records 83/01/11 FINK, M A
Andrus Research Corp 1p 17134 151
- 8302100012 Statement of work for NRC-04-83-001, "Review of Application of Strategic Analysis to Matl Accounting"
* NRC - No Detailed Affiliation Given NRC-04-83-001
RS-RES-82-002 83/01/11 3pp. 17134.152
- 8302100019 Addl response to FOIA request for documents re NRC policy concerning press releases covering enforcement & licensing activities & media coverage of NRC hearings Forwards documents Review of remaining documents in progress.
FELTON, J M Division of Rules and Records 83/01/11. HARTMAN, B
Debevoise & Liberman. 2pp. 17134.139

NONDOCKETED ITEMS

- B10720033 Forwards Region 2 memo re timing of press releases on enforcement actions
THOMPSON, D Enforcement & Investigation Staff (Pre B20201)
B1/06/19 FOUCHARD, J J Office of Public Affairs 1p
17134 146
- B302100023 Responds to 770921 memo re NRC policy on use of cameras in adjudicatory hearings Application of Alternative 3 for trial period recommended
ENELHARDT, T F Deputy Executive Legal Director 77/10/03
FOUCHARD, J J Office of Public Affairs 1p 17134 145
- B302100062 Recommends that news releases re proposed CPs be delayed 1 day allowing licensee to receive advance copy Delay of 7-10 days recommended for mafi licensees
O'REILLY, J P Region 2, Atlanta, Office of the Director
(B1/03/01) B1/06/16 THOMPSON, D Director's Office, Office of Inspection and Enforcement 1p 17134 147.
- B302100067 Recommends that policy statement on camera coverage be expanded to provide estimate of number of meetings affected
Some ASLB proposed revs unnecessary & ambiguous
KENNEKE, A Office of Policy Evaluations 77/12/16 FOUCHARD, J
Office of Public Affairs 2pp 17134 148
- B302150729 Responds to FOIA request for documents released under FOIA Request B2-397 to B0 Sawicki & FOIA Request B2-305 to R Hubbard & documents re differences in design or const & HHS liaison during emergency Forwards App A documents w/o encls
FELTON, J M Division of Rules and Records B3/01/17, HIATT, S
Ohio Citizens for Responsible Energy 2pp 17140 109
- B302150730 Addl response to FOIA request for SECY-B2-207C & SECY-B2-207D Forwards SECY-B2-207D.
FELTON, J M Division of Rules and Records B3/01/17.
AGNIHOTRI, N K Affiliation Unknown 1p 17160 112
- B302160457 Addl response to FOIA request for documents re EE Kent allegations concerning facilities. Forwards documents listed in Apps A & B. Documents partially withheld (ref FOIA Exemptions 5, 6 & 7) Tapes available in PDR
FELTON, J M Division of Rules and Records B3/01/12 CARPENTER, T
Grange County Alliance for Survival App 17175 194
- B302180024 FOIA request for records re proposed rev of license fee schedules.
KNOWLES, N J Shaw, Pittman, Potts & Trowbridge B2/12/15 Office of Administration 2pp 17222 001
- B302180031 Partial response to FOIA request for records re proposed rev of license fee schedules Forwards documents listed in App A Documents also available in PDR.
FELTON, J M Division of Rules and Records B3/01/11 KNOWLES, N J
Shaw, Pittman, Potts & Trowbridge 7pp 17222 003
- B109220921 States that impact of proposed license fee schedule revs would be too great to be effective if licensee questions insp bill, list of insps could be provided Not necessary to be able to trace manhours to specific repts.
STELLO, V Director's Office, Office of Inspection and Enforcement
B1/09/05 DONOGHUE, D J Office of Administration 1p
17222 084
- B112040003 Recommends change to proposed license fee rule rev re periodic billing & payment of fees Bills should be batched & sent quarterly rather than monthly
BERKOW, H N Management Analysis Branch B1/11/10 MILLER, W D
License Fee Management Branch 2pp 17222 177.
- B112170293 Forwards list of allocation of resources expended for license fee review in FYB1, in response to B11105 request
BASSETT, H B Office of Management and Program Analysis B1/11/09
DONOGHUE, D J Office of Administration 2pp 17222 145
- B202160169 Responds to Commission question in B11104 memo re IE recoverable resources in license fee proposal Revised tables of FYB2 budget for IE staffing & dollar analysis re license fee recovery & for distribution of direct insp encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B1/11/20 DONOGHUE, D J Office of Administration
5pp 17222 184.
- B203030578 Forwards response to Donoghue B20108 memo re manhour estimates applicable to FYB1 & FYB2 insp efforts Correlation of IE license groupings w/fee categories difficult, because former based on risk, latter on license type
DORNELL, L J Office of Administration B2/02/05 MILLER, W D
License Fee Management Branch 3pp 17222 246.
- B211040395 Comments on FR notice package for proposed revised fee schedule Policy that application fees not refundable should be made clear
BERKOW, H N Management Analysis Branch B2/10/21 MILLER, W
License Fee Management Branch 2pp 17223 046
- B211040458 Forwards draft FR notice re license fee schedule revs Comments requested by B21021
NORRY, P O Office of Administration B2/10/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 60pp
17222 342
- B211150690 Comments on proposed FR notice re license fee schedule revs
FERRI, R T Regional Coordination Staff B2/10/26 MILLER, W D
License Fee Management Branch 1p 17223 050
- B211180459 Forwards proposed rev to 10CFR170 re license fees, for FR publication Sixty-day comment period should be provided
W/o encl
MILLER, W D License Fee Management Branch B2/10/29 FELTON, J M
Division of Rules and Records 63pp 17223 051
- B302180035 Forwards completed FYB0 budget & current average estimated manpower & financial requirements to process custom plant forms in response to Congressional Udall/Vento questions
CHO, J Atomic Safety and Licensing Board Panel B1/04/13
CLARK, J Office of Management and Program Analysis 3pp
17222 010
- B302180039 Resubmits B10326 response to Udall/Vento questions to conform w/new B10409 forms & definitions.
BROHN, R S Program Support Branch B1/04/15 CLARK, J W Office of Management and Program Analysis 4pp 17222 013.
- B302180041 Submits response to Udall/Vento B10316 questions re FYB0 resources Narrative to ASLB response to Vento questions & ACRS response encl
THOMPSON, H L Planning & Program Analysis Staff B1/04/15
CLARK, J Office of Management and Program Analysis 14pp
17222 017
- B302180044 Forwards response to Udall/Vento questions re FYB0 resources Activities used in collecting data listed
BIDDLE, D Director's Office, Office of Inspection and Enforcement, B1/04/22 CLARK, J Office of Management and Program Analysis
5pp 17222 031
- B302180047 Requests info re percentage of pay raise increases adopted & percentage of yearly inflationary increases provided to program ofcs for budget development Info required for proposed revised fee schedule requested by Commission
DONOGHUE, D J Office of Administration B1/07/10, BARRY, L W
Office of the Controller 1p 17222 036
- B302180059 Submits info re pay increases & inflationary data per B10710 memo
TRINER, E O Division of Budget B1/07/14 DONOGHUE, D J Office of Administration 2pp 17222 037
- B302180062 Requests range of costs for processing new licenses, approvals, amends & renewals for certain fee categories Info needed by B10717 for use in proposed revised fee schedule requested by Commission
DONOGHUE, D J Office of Administration B1/07/14 DAVIS, J
Office of Nuclear Material Safety & Safeguards, Director 2pp
17222 039
- B302180067 Requests range of manpower expended on insps covered by certain 10CFR170 32 fee categories Info required for proposed revised fee schedule requested by Commission
DONOGHUE, D J Office of Administration B1/07/15 STELO, V
Director's Office, Office of Inspection and Enforcement 3pp
17222 041
- B302180071 Submits info re pay raises for 1977 & 1978 to suppl B10714 memo
TRINER, E O Division of Budget B1/07/17 DONOGHUE, D J Office of Administration 2pp 17222 044
- B302180075 Informs of proposed rev to license fee schedule to provide full cost recovery of licensing expenses from applicants Comments on proposed format requested
BROWN, R S Program Support Branch B1/07/17 BURNETT, R F
Division of Safeguards CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director MARTIN, J B, Division of Waste Management 2pp 17222 046

NONDOCKETED ITEMS

425

- B302180081 "Range of Manhours by Fee Category for Completed Licensing Actions, FY78-81" WEISS, D Office of Nuclear Material Safety & Safeguards, Director 81/07/16 8pp 17222 050
- B302180084 Requests addl info re Section K-1 of NUREG-0748, "Operating Reactors Licensing Action Summary," dtd June 1981 High & low range for each fee class required MILLER, W O License Fee Management Branch 81/07/20 BERKOW, H Management Analysis Branch 15pp 17222 058
- B302180086 Forwards revs to current license fee categories BROHN, R S Program Support Branch 81/07/20 MILLER, W O License Fee Management Branch 1p 17222 073
- B302180088 Submits mods for proposed approach to rev of license fees Category I, H should be broken down into only two types of license applications for ISFBI ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 81/07/17 CARTER, T F Division of Fuel Cycle & Material Safety 2pp 17222 074
- B302180092 Discusses mod of license fee categories Separating out amend fees for R&D scale & production scale activities appropriate LINEMAN, J J Uranium Recovery Licensing Branch 81/07/17 EVANS, J Program Support Branch 1p 17222 076
- B302180095 Forwards range of manhours & technical assistance contract dollars, ore buying stations & ion exchange facilities, per 810714 request BROHN, R S Program Support Branch 81/07/24 MILLER, W O License Fee Management Branch 5pp 17222 077
- B302180110 Submits chart of insp manhour ranges, in response to 810717 request, Min/max ranges based on history, planned insp & judgement DONNELLY, L J Resource Management Branch 81/08/07 MILLER, W O License Fee Management Branch 2pp 17222 085
- B302180113 Approves proposal to revise manpower sys if method of billing for certain insps modified DONOGHUE, D J Office of Administration 81/08/26 STELLO, V Director's Office, Office of Inspection and Enforcement 1p 17222 087
- B302180117 Submits manpower info to be used in developing operator licensing program for license fees based on 810911 meeting HOLLOWAY, C J License Fee Management Branch 81/09/21 COLLINS, P Division of Licensing 8pp 17222 088
- B302180121 Forwards draft notice of proposed rulemaking to amend 10CFR170 re license fee schedule, for comment by 810928 DONOGHUE, D J Office of Administration 81/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director DAVIS, J Office of Nuclear Material Safety & Safeguards, Director STELLO, V Director's Office, Office of Inspection and Enforcement 51pp 17222 096
- B302180125 Forwards comments on 810922 draft notice of proposed rulemaking amending 10CFR170 re license fee schedule Rule presents administrative burden due to reporting & tracking sys Total review time for similar actions likely to vary THOMPSON, H L Planning & Program Analysis Staff 81/09/28 DONOGHUE, D J Office of Administration 3pp 17222 146
- B302180131 Comments on 810922 draft notice of proposed rulemaking to amend 10CFR170 license fee schedule Proposed procedure not appropriate for certain matls licenses BROHN, R S Program Support Branch 81/09/28 DONOGHUE, D J Office of Administration 1p 17222 149
- B302180135 Comments on draft notice for proposed rulemaking to amend 10CFR170 license fee schedule Traveling time of inspectors not considered Manhours cannot be identified for each insp rept however activities can be broken down STELLO, V Director's Office, Office of Inspection and Enforcement 81/09/28 DONOGHUE, D J Office of Administration 1p 17222 150
- B302180141 Comments on notice of proposed rulemaking re 10CFR170 on license fee schedule Only Commission should be allowed to raise fees Viewgraphs of changes discussed in SECY-81-613 encl BARRY, L W Office of the Controller 81/09/28 DONOGHUE, D J Office of Administration 10pp 17222 151
- B302180148 Requests info re allocation of time expended in FY81 workload for proposed revised license fee schedules. DONOGHUE, D J Office of Administration 81/11/05 REHM, T A Office of the Executive Director for Operations 1p 17222 161
- B302180162 Requests allocation of time spent in FY81 for proposed revised license fee schedule DONOGHUE, D J Office of Administration 81/11/05 BASSETT, H S Office of Management and Program Analysis 1p 17222 162
- B302180167 Requests allocation of time spent in FY81 & explanation of basis of time distribution for proposed revised license fee schedule DONOGHUE, D J Office of Administration 81/11/05 CHILK, S Office of the Secretary of the Commission 1p 17222 163
- B302180177 Requests time allocated in FY81 & explanation of basis for time distribution for proposed revised license fee schedule DONOGHUE, D J Office of Administration 81/11/05 SHAPER, H Office of the Executive Legal Director 1p 17222 164
- B302180179 Submits allocation of time spent in FY81 per 811105 request Workload data maintained by each div & monitored by Program Support Branch ENGELHARDT, T F Office of the Executive Legal Director 81/11/09 DONOGHUE, D J Office of Administration 2pp 17222 167
- B302180181 Submits manpower & program support costs for CP & OL reviews HOLLOWAY, C J License Fee Management Branch 81/11/10 License Fee Management Branch 2pp 17222 169
- B302180187 Responds to Commission 811105 question re recoverable resources contained in license fee proposal FY82 budget data shows that 30% of total budget recoverable Budget encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 81/11/10 DONOGHUE, D J Office of Administration 5pp 17222 171
- B302180189 Submits allocation of time spent in FY81 Info based on estimates using papers & correspondence as guides REHM, T A Office of the Executive Director for Operations 81/11/10 MILLER, W O License Fee Management Branch 1p 17222 176
- B302180196 Requests review of IE prof rate for FY81 provided by Ofc of Controller MILLER, W O License Fee Management Branch 81/11/12 DONNELLY, L J Resource Management Branch 1p 17222 179
- B302180201 Notifies that meaningful review of prof staff yr rate cannot be performed due to lack of adequate documents & unknown objectives DONNELLY, L J Resource Management Branch 81/11/12 MILLER, W O License Fee Management Branch 2pp 17222 180
- B302180207 Confirms that 9.56 prof direct yrs of effort expended on ASLAB activities during FY81 HOLLOWAY, C J License Fee Management Branch 81/11/18 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 1p 17222 182
- B302180212 Advises that 32 full-time equivalents of prof effort expended in FY81, per 811112 telcon HOLLOWAY, C J License Fee Management Branch 81/11/18 FITT, C J Atomic Safety and Licensing Board Panel 1p 17222 183
- B302180216 Notifies that 29 prof direct staff yrs expended on activities during FY81, per 811110 telcon HOLLOWAY, C J License Fee Management Branch, 81/11/18 NEWSON, A ACRS - Advisory Committee on Reactor Safeguards 1p 17222 184
- B302180221 Confirms that 22 full-time staff members in Div of Rules & Records during FY81 MILLER, W O License Fee Management Branch 81/11/19 COOPER, L Office of Administration 1p 17222 185
- B302180262 Discusses development of cost range data for facility amends based on printout of all TAC numbers from 751207-810808 HOLLOWAY, C J License Fee Management Branch 81/11/25 MILLER, W O License Fee Management Branch 1p 17222 191
- B302180271 Discusses exclusion of costs for certain svc & ofcs from license fees in FY81 budget Ofc of Small & Disadvantaged Business Utilization & Ofc of Analysis & Evaluation of Operational Data excluded MILLER, W O License Fee Management Branch, 81/12/08 DONOGHUE, D J Office of Administration, 4pp 17222 195

NONDOCKETED ITEMS

- B302180274 Discusses exclusion of svcs & costs of certain ofcs from license fees for FY77 budget Ofcs of Policy Evaluation, Inspector & Auditor, Congressional Affairs, Public Affairs & Planning & Analysis excluded
MILLER, W O License Fee Management Branch 77/03/04
DONOGHUE, D J Office of Administration App 17222 197
- B302180278 Submits FY82 resources for matl licensing No overhead resources outside branches included
EVANS, J Program Support Branch 81/12/11 MILLER, B License Fee Management Branch 1p 17222 203
- B302180286 Requests rept of prof direct staff yrs expended in listed functions & account of all other staff yrs to help determine whether actual cost method in assessing fees would hurt small licensees
DONOGHUE, D J Office of Administration 82/01/04 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 3pp 17222 204
- B302180288 Requests submittal of range of manpower expended for insp of small matl programs to assist in proposed rev to fee schedule
DONOGHUE, D J Office of Administration 82/01/08 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 12pp 17222 207
- B302180293 Requests submittal of range of prof hours expended for applications, new licenses, amends & renewals of small matl programs
MILLER, W O License Fee Management Branch 82/01/08 BROWN, R Program Support Branch 11pp 17222 220
- B302180297 Forwards charts showing allocation of FY82 prof direct & all other staff yrs for Matl Licensing Branch & Matl Certification & Procedures Branch.
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 82/01/26 DONOGHUE, D J Office of Administration 15pp 17222 231
- B302180301 Responds to 820126 memo re proposed license fee rev Prof staff hours required to process application for license amend 12 times greater than hours required for new license
DONOGHUE, D J Office of Administration 82/02/10, DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 10pp 17222 249
- B302180304 Responds to 820205 memo re routine insp effort Verification required that numbers provided interpreted as intended Estimated number of routine & nonroutine insps conducted in each fee category also required
MILLER, W O License Fee Management Branch 82/02/12 DONNELLY, L Office of Administration 8pp 17222:259
- B302180307 Forwards info in response to 820212 request re safety & environ staff hours.
DONNELLY, L J Office of Administration, 82/03/01 MILLER, W O License Fee Management Branch 3pp 17222 267
- B302180311 Notifies that Matl Licensing Branch proposed fee schedule will not be completed until 820430 due to lack of adequate data, Matl Licensing Branch portion should remain unchanged if Commission unable to delay current fee schedule rev
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 82/03/11 DONOGHUE, D J Office of Administration 1p 17222 270
- B302180315 Forwards schedule of average prof time for matl licenses derived from 1981-82 data
CUNNINGHAM, R E, Division of Fuel Cycle & Material Safety 82/03/26 DONOGHUE, D J Office of Administration 7pp 17222 271.
- B302180318 Forwards chart illustrating FY81 resources included & excluded from fees Fee vs nonfee work charts also encl
BROWN, R S Program Support Branch 82/03/31 MILLER, W O License Fee Management Branch, 5pp 17222 278
- B302180323 Forwards FY82 activities w/estimated resources that are included & excluded from proposed license fee schedules.
BLAHA, J L Program Support Branch, 82/03/31 MILLER, W O License Fee Management Branch, 2pp 17222 283
- B302180326 Forwards FY81 actual expenditures included & excluded from recovery under proposed new fee rules.
BERKMAN, H N Management Analysis Branch, 82/04/01 MILLER, W O License Fee Management Branch, 3pp, 17222:285.
- B302180331 Confirms discussion & changes to proposed fee schedule per 820416 meeting Changes based on RE Cunningham 820326 memo
MILLER, W O License Fee Management Branch, 82/04/23 SINGER, B Procedures & Certification Branch 2pp, 17222:288
- B302180335 Notifies that one action item re license fees remains Data re actual cost method for radioisotope license economic impact on small entities recently received
NORRY, P O Office of Administration 82/04/23 DIRCKS, W J Office of the Executive Director for Operations 1p 17222 290
- B302180340 Requests review of matl license categories by 820506 for proposed license fee rev
MILLER, W O License Fee Management Branch 82/04/28 DONNELLY, L J Regional Coordination Staff 7pp 17222 297.
- B302180341 Requests staff hour requirements for new medical license approvals, renewals & amends by 820512
MILLER, W O License Fee Management Branch, 82/05/11 SINGER, B Procedures & Certification Branch 3pp 17222 305
- B302180345 Forwards consolidated regional estimate of inspector time chargeable to fees under proposed fee guidelines
MATHEWS, O M Regional Coordination Staff 82/05/14 MILLER, W O License Fee Management Branch 7pp 17222,308
- B302180347 Forward summary of applications received in FY81 Proposed fee categories specify program codes encompassed for categories
MILLER, W O License Fee Management Branch 82/05/18 SINGER, B Procedures & Certification Branch 9pp 17222 315
- B302180350 Submits statement to support estimates embodied in computation of proposed insp fees
DONNELLY, L J Regional Coordination Staff 82/06/02 MILLER, W O License Fee Management Branch 1p 17222 324
- B302180368 Concurs w/821018 memo re FR notice of license fee schedules
BARRY, L W Office of Resource Management, Director 82/10/20 NORRY, P O Office of Administration 1p 17223 040
- B302180370 Concurs w/821018 memo re draft FR notice of proposed rev of license fee schedules
ROSENTHAL, A B Atomic Safety and Licensing Appeal Panel, 82/10/20 NORRY, P O Office of Administration 1p 17223 041.
- B302180372 Submits review of proposed rev of license fee schedules Addition of users of byproduct matl on Page 30 Line 9 enlarges number & class of licensees affected by proposal
FELTON, J M Division of Rules and Records 82/10/21 NORRY, P O Office of Administration 2pp 17223 042
- B302180373 Reviews proposed rev of license fee schedules per 821018 request Billing costs of investigations would be unfair & would sometimes negatively impact investigative process
FITZGERALD, J A Office of Investigation 82/10/21 NORRY, P O Office of Administration 2pp 17223 044
- B302180380 Comments on FR notice on license fees Changes semantic Section on topical repts re treatment of repts filed after 780323 which are still active on effective date of proposed rule unclear
BROWN, R S Program Support Branch 82/10/26 NORRY, P S Office of Administration 1p 17223 049
- B302180385 Forwards corrections to 821122 FR notice of proposed rulemaking Notice of proposed rev to 10CFR170, license fees, dtd 821122 encl
MILLER, W O License Fee Management Branch 82/11/24 PHILIPS, J Division of Rules and Records 3pp 17223 063
- B302180404 Forwards proposed notice of rulemaking 10CFR170 re amending fee policy All comments accommodated except NRR suggestion that cost of svc provided to DOE & DOD be recovered w/o stated encl
DONOGHUE, D J Office of Administration 81/10/05, DIRCKS, W J Office of the Executive Director for Operations 2pp 17223:072
- B302180164 Forwards "Hydrostatic/Pneumatic Test Rept RR-28,"
RITTER, B J Cincinnati Gas & Electric Co 79/09/28 Kaiser Industries Corp 3pp 17218 084
- B302220030 Addl response to FOIA request for documents re UCLA lab & research reactors Forwards documents listed on Apps A & B. App B documents partially withheld commercial & financial info (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 82/12/30 HIRSH, D. CBS News, CBS, Inc 3pp 17240 329
- B302220054 SECY-79-1870
Provides marked-up status rept on impact of safeguards upgrade rule on 22 nonpower reactor licensees, review of safeguards measures & status of re-evaluation on 100 rem/h at 3-ft self-protection exemption criterion
DIRCKS, W J Office of Nuclear Material Safety & Safeguards, Director 79/12/19 17pp 17240 336

NONDOCKETED ITEMS

--8302220058 SECY-79-1878

Requests approval to defer manpower reactor licensees from implementing upgrade rule & repts on evaluation of 100 rem/h at 3-ft exemption criterion Immediate publication of upgrade rule requested
 HINGOUE, R B Office of Standards Development, Director
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 DIRCKS, W J Office of Nuclear Material Safety & Safeguards, Director 79/07/13 12pp 17240 353

8302240199 FOIA request for license Applications for Nuclear Radiopharmacy in Northern VA or DC area
 BUSCH, J E Pharmatopes, Inc 83/01/04 FELTON, J M Division of Rules and Records 1p 17288 300

8302240207 Responds to FOIA request for license applications for license for Nuclear Radiopharmacy in Northern VA or DC area
 No pending action or license for Nuclear Radiopharmacy pending at present time
 FELTON, J M Division of Rules and Records 83/01/21 BUSCH, J E Pharmatopes, Inc 1p 17288 301

8302240217 FOIA request for documents re Baystate Medical Ctr
 ROSENBAUM, P J Affiliation Unknown 83/01/10 Division of Rules and Records 1p 17284 079

8302240223 Responds to FOIA request for documents re Baystate Medical Ctr Forwards App A documents
 FELTON, J M Division of Rules and Records 83/01/20
 ROSENBAUM, P J Affiliation Unknown 2pp 17284 080

--7902020122 AJ Stark is licensed to dispense drugs in practice of medicine in MA w/encl resume & copy of certification by American Board of Radiology in Therapeutic Radiology
 QIFFORD, H C Baystate Medical Center Springfield, MA 95873/95879
 79/01/08 VACCA, P C Radioisotopes Licensing Branch (Pre 790501) App 17284 300

--7904250165 Application for renewal of Matl/Byproduct License 20-01412-03 to authorize use of Co-60 for installation in Teletherapy Unit Theratron 780 Supporting info encl
 QIFFORD, H C Baystate Medical Center Springfield, MA 99286
 79/03/25 20pp 17284 082

--7905290339 Application for renewal of Matl/Byproduct License 20-01412-05 authorizing use of Cs-137 & Co-60 in sealed source for calibr of survey meters Safety procedures encl
 QIFFORD, H C Baystate Medical Center Springfield, MA 99661
 79/04/26 108pp 17284 168

--7908220573 Submits radiation survey following installation of new Co-60 source in Theratron 780 unit in accordance w/Condition 18 to License 20-01412-03 All conditions fulfilled. Certificates of Insp & disposal encl
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 00686
 79/07/18 Licensing Management Branch. 19pp 17284.117.

--7911210270 Submits addl info requested by NRC 791015 telcon re application to amend Matl/Byproduct License 20-01412-03
 Calibr rept encl.
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 00686
 79/10/23 ST MARY, F A Licensing Management Branch 24pp 17284 136

--8004250184 Submits addl info requested by NRC 790501 ltr re application to renew Matl/Byproduct License 20-01412-03 Includes info re matl for medical use, location of calibr lab, duties of director, radiation safety & waste disposal
 QIFFORD, H C Baystate Medical Center Springfield, MA 99661
 80/03/04 VACCA, P Licensing Management Branch App 17284.287

--8010090441 Submits addl info requested by NRC 800805 ltr re application to renew Matl/Byproduct License 20-01412-05. Info requested contained in 790426 & 800304 ltrs Radiation safety committee will use criteria of Reg Guide 10.8 for approval of users
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 99661.
 80/08/22 LAMABTRA, M. A. Licensing Management Branch. App 17284.291.

--8302240235 Forwards info re surveys, tests & interlock checks completed to satisfy conditions of License 20-01412-03
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA. 74/03/25
 BABBIN, N Atomic Energy Commission, Directorate of Licensing. 15pp 17284.102.

--8302240250 Requests exemption from requirement for 2-yr calibr of dosimetry sys per 10CFR30 Related info encl.
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 11267
 82/04/15 ST MARY, F A Licensing Management Branch. 5pp 17284 161.

--8302240255 Application to amend Matl/Byproduct Licenses 20-01412-03 & 20-01412-04 to include exemption from calibr requirement of 10CFR35.22 & 35.23
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 82/06/22
 VACCA, P Licensing Management Branch 2pp 17284 166

--8302240270 Discusses responsibilities of Director of Medical Physics
 Radiation Safety
 QIFFORD, H C Baystate Medical Center Springfield, MA 1879
 80/08/22 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 3pp 17284 295

--8302240277 Application for amend to Matl/Byproduct Licenses 20-01412- & 20-01412-06, changing Condition 12 re use of licensed matl
 BRAHMAVAR, S M, GRUGAN, R A, PARK, W C Baystate Medical Center Springfield, MA 95879 78/08/01 WADE, L Division of Fuel Cycle & Material Safety 2pp 17284 298

--8302240288 Submits info re dosimetry sys per 811008 request Capintec-122 & Victoreen-570R electrometers utilized at hosg
 BRAHMAVAR, S M Baystate Medical Center Springfield, MA 08744
 81/10/13 ST MARY, F Licensing Management Branch 2pp 17284 304

--8302240293 Submits info re radiation survey following installation of Co-60 source in Eldorado-6 unit per Conditions 18, 19 & 20 to License 20-01412-06 Certificates of measurement, disposal & Insp encl
 BRAHMAVAR, S M, PARK, W C, GRUGAN, R A Baystate Medical Center Springfield, MA 08744 81/08/03 VACCA, P. Licensing Management Branch 31pp 17284 306

8302240355 FOIA request for list of businesses, colleges & individuals, in Worcester, MA area possessing permits to keep radioactive matls
 QIRQUARD, D Affiliation Unknown 83/01/14 Division of Rules and Records 1p 17288 304

8302240357 Responds to FOIA request for list of businesses, colleges & individuals in Worcester, MA area possessing permits to keep radioactive matls Forwards computer printout listing required info
 FELTON, J M Division of Rules and Records 83/01/21 QIRQUARD, D Affiliation Unknown 1p 17288 305

--8302240358 List of active NRC licenses in Worcester, MA
 KREIBERG, D Health & Human Services, Dept of, 83/01/17 App 17288 306

8302240363 FOIA request for info re funding of various citizen organizations listed
 DAVIS, G A National Alliance of Senior Citizens 83/01/10
 Office of Administration 3pp 17288 310

8302240365 Responds to FOIA request for info re funding of various citizens organizations listed Subj organizations never received funds from NRC Action on request completed
 FELTON, J M Division of Rules and Records 83/01/21 DAVIS, G. A National Alliance of Senior Citizens 1p 17288 313

8302280126 Addl response to FOIA request for seven categories of info re facility Documents listed in app completely withheld (ref FOIA Exemptions 1,3 & 4) Access to portions of documents provided through N88 protective order
 FELTON, J M Division of Rules and Records 83/01/19 WEISS, E R Harmon & Weiss App

8302280135 Responds to FOIA request for documents re NRC shutdown plan mentioned in Weekly Info Rept for wk ending 810831 & SECY-BI-600 & 600A Forwards Manual Chapter 1302, "Shutdown Plan, Contingency Plan for Periods of Lapsed Appropriations"
 FELTON, J M Division of Rules and Records 83/01/25 CONNDR, L Doc-Search Associates. 1p 17322.169

--8302280139 Manual Chapter 1302, "Shutdown Plan, Contingency Plan for Period of Lapsed Appropriations"
 * NRC - No Detailed Affiliation Given 82/12/21. 32pp 17322 171

GEN T&C 18 GENERIC TECHNICAL ISSUES

8302080370 Summary of ACRS Metal Components Working Group 820930 meeting in Washington, DC re NRC position on pressurized thermal shock
 * ACRB - Advisory Committee on Reactor Safeguards 82/11/23.
 ACRB - Advisory Committee on Reactor Safeguards 33pp 17107.166

NONDOCKETED ITEMS

8302160404 Suggests closeout of Multi-Plant Action B-67 re pressurized thermal shock to reactor pressure vessels Action Item B-72 should be developed instead
LAINAS, O C Assistant Director for Operating Reactors 83/02/03
EISENHUT, D G Division of Licensing 2pp 17173 192

--8302160406 Staff requirements memo re B21209 discussion/possible vote in Washington, DC on pressurized thermal shock actions
CHILK, S J Office of the Secretary of the Commission H821209A
83/01/05 Office of the Executive Director for Operations 2pp
17173 193

I&E INSPECTION AND ENFORCEMENT

8212060358 IE Info Notice 83-01, "Ray Miller, Inc " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
York, Inc 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358

8212060360 IE Info Notice 83-02, "Litorque H08C, H18C, H28C & H38C
Gearheads " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360

8212060361 IE Info Notice 83-03, "Calibr of Liquid Level Instruments " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361

8212060363 IE Info Notice 83-04, "Failures of Elma Power Supply Units " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363

8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of Very Low Level Radwaste - 10CFR20 302 " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365

8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366

8212210113 PNO-I-82-080 on 821214, truck w/density gauge containing 9 mCi Cs-137 source & possibly 40 mCi Am-241-Ba source stolen in Monroeville, PA Gauge not hazardous to public unless sources removed from laced device
JOHANESE, J. GLENN, J. Region 1, Office of Director 82/12/14 1p
16491 041

8302010471 PNS-V-83-003 on 830126, security guard accidentally discharged newly issued revolver & caused superficial wounds to right leg Guard treated & held overnight at hosp for observation
MORTENSEN, W P Region 5, Office of Director 83/01/27 1p
16481 302

8302040080 PNO-III-83-010 on 830121, allegation received from fired electrical worker re deficiencies in mail traceability of electrical hangers & in control of work instructions (travelers) in field installation of hangers stopped
KOHMANN, J. Region 3, Office of Director 83/01/31 1p 17020 153

8302070076 Partial response to FOIA request for 22 categories of documents Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App B documents completely withheld (ref FOIA Exemption 9)
FELTON, J M Division of Rules and Records 82/12/21 EHOLLY, S
Union of Concerned Scientists App 17063 005

8302070232 PNO-V-83-006 on 830114, improper shipment of low level waste received from Teledyne Isotopes, Westwood, NJ State of WA banned company from use of burial site & suspended burial permit, effective 830117
THOMAS, R D Region 5, Office of Director 83/02/02 1p
17031 297

8302070371 PNO-IV-83-004, on 830129, LA Nuclear Energy Div fourth quarter film badge rept for Dresser Atlas employee indicated whole body exposure of 372 rems Value not true No medical indications that individual received indicated exposure
MEYER, R S, DODD, R J Region 4, Office of Director 83/02/02 2pp,
17029 358

8302140043 PNO-III-83-007 on 830204, unidentified caller telephoned in bomb threat Identified device found near temporary bldg but contained no explosives Proper authorities notified & threat considered hoax
MCQUIRE, D R Region 2, Office of Director 83/02/07 2pp
17142 139

8302180309 PNO-III-83-014 on 830211, higher than anticipated gaseous effluent release occurred while collecting sample from gas space from Unit 1 Second unplanned release from Unit 2 occurred while collecting coolant sample
HUETER, L J Region 3, Office of Director 83/02/11 1p
17211 228

8302230249 EN-83-011 on 830218, notice of violation & civil penalties issued in amount of \$600,000 based on violations re Tech Spec surveillance requirements for several safety sys & components & failure to correct identified problems
BARBER, O Director's Office, Office of Inspection and Enforcement 83/02/18 1p 17244 310

8302290384 PNO-IV-83-005A on 830217, licensee reported that package containing 10 mCi Cs-137 sealed source located at Northwest Orient Airlines terminal in Houston, TX Shipment will be sent from Houston to Scotland.
EVERETT, R J Region 4, Office of Director 83/02/18 1p
17297 218

8302280456 PNO-V-83-009 on 830213, Mo-99/Tc-99m generator containing 880 mCi radioactive matl, possibly lost on delivery from Nuclear Pharmacy, Inc Supplier indicated generator delivered to Naval Regional Medical Ctr
THOMAS, R D Region 5, Office of Director 83/02/23 1p
17309 214

8302280325 PNO-I-83-009 on 830221, three gauges stolen from car parked outside Holiday Inn in King of Prussia, PA Gauges contained Cs-137 & Am-241/Ba No hazard to public unless sources removed from shielded, locked device
FRIEDMAN, L. GLENN, J. Region 1, Office of Director 83/02/22 1p
17309 050

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

830110451 Forwards fuel cycle & matls LER summary for Nov-Dec 1982
BRIGHAM, O D Division of Vendor & Technical Programs 83/01/07,
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
MICHELSON, C Director's Office 3pp 16743 029

8302010456 Requests that listed actions re control of field changes at all const sites be initiated W/o memo describing problem
COLLINS, J T Region 4, Office of Director 83/01/26, DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p,
16980 057.

8302070016 Forwards completed Forms T-820-A for NRC Federal Advisory Committee for use in preparation of annual rept of President for CY82
HOYLE, J C Office of the Secretary of the Commission. 83/01/28
MARTINSON, R L National Archives & Records Service (DO NOT USE)
38pp 17108 165

8302090153 Act receipt of 821103 ltr re 821007 presentation to NRC & INPO Issues of operator integrity & abnormal operating procedures discussed
THOMPSON, H L Division of Human Factors Safety, 83/01/24,
SHEEHY, E J Affiliation Unknown 5pp 17121 355

8302150364 Requests waiver of present per diem rate for visit to designated high-rate geographical area
HUBBARD, O T Division of Vendor & Technical Programs 83/02/07
COLLINS, J T Region 4, Office of Director 1p 17157 267

8302150538 Forwards projected vendor insp schedule through 830423, in order to assist in planning & coordinating insp of nonlicensee organizations
COLLINS, J T Region 4, Office of Director 83/02/07 HAYNES, R C
Region 1, Office of Director O'REILLY, J P Region 2, Office of Director, KEPLER, J O Region 3, Office of Director 2pp
17156 361

8302150752 Comments on revised Insp Procedure 94300 for performing regional evaluation of near-term OL facilities Third part independent design verification repts should be included in summary
EISENHUT, D O Division of Licensing 83/02/03 TAYLOR, J M
Division of Reactor Programs (Pre 830103). 1pp 17159 076

NONDOCKETED ITEMS

8302220031 Forwards Dec 1982 ltr rept in response to 820818 request for addl info re review of Windsor site reactor prototype Ltr submits changes to proposed locations & location where addl soil tests performed W/o encl
THOMAS, C Q Standardization & Special Projects Branch 83/02/10
LEAR, G Structural Engineering Branch 1p 17233 294

8302220324 Advises that operating areas of Fish & Wildlife Svc, Ecological Svc Field Ofc in TX have been realigned Map depicting relative boundaries of each ofc & list of counties encl
YOUNG, J A Interior, Dept of, Fish & Wildlife Service 83/02/07
NRC - No Detailed Affiliation Given 5pp 17230 114

8302230115 Forwards fuel cycle & matis LER summary for Jan 1983
BROWN, O D Division of Vendor & Technical Programs 83/02/16
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
MICHELSON, C Director's Office 3pp 17243, 214

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8302010525 Forwards technical justification for relationship of scram time fraction to scram discharge vol pipe break probability as used in NEDD-22209; "Analysis of Scram Discharge Vol Sys Piping Integrity"
BENTON, T J BWR Owners Group BWROG-8303 83/01/28 ECCLESTON, K
NRC - No Detailed Affiliation Given 16pp. 16977 257

8302020477 Partial response to FOIA request for SAND BI-1549 (NUREG/CR-2239), SAND 82-1110 (NUREG/CR-2723), NUREG-0773 & NUREG/CR-2326 & all documents re CRAC Code Forwards draft NUREG-0773 NUREG/CR-2239 available in PDR
FELTON, J M Division of Rules and Records 82/12/02 ELLIOTT, C W
Thomas & Hair 1p 17008 334

--8302020483 NUREG-0773 DRFT
REACTOR ACCIDENT SOURCE TERMS DESIGN AND SITING
PERSPECTIVES
* NRC - No Detailed Affiliation Given 82/03/31 107pp
17008 336

8302030208 NUREG/CR-2861
IMAGE ANALYSIS FOR FACILITY SITING A COMPARISON OF LOW AND HIGH-ALTITUDE IMAGE INTERPRETABILITY FOR LAND USE/LAND COVER MAPPING
BORELLA, H M EQ&O, Inc ESTES, J E, EZRA, C E California, Univ of, Santa Barbara FIN A-1251-2 8-744-R 82/11/30 Division of Health, Siting & Environment 76pp Available at NRC \$5 00
17013 221

8302030239 NUREG-0748 V02 N11
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of November 30, 1982 (Orange Book)
* Management Information Branch 82/12/31 292pp 17022 001

8302030252 NUREG/CR-2706
TRAINING COURSE NO 2 THE IMPLEMENTATION OF FEMWASTE (ORNL-5601) COMPUTER PROGRAM
YEH, O T Oak Ridge National Laboratory FIN A-9095 ORNL/TM-8328 82/11/30 Division of Waste Management 136pp Available at NRC \$7.50 17023, 018

8302030259 NUREG/CR-3090
EVALUATION OF WATER HAMMER POTENTIAL IN PREHEAT STEAM GENERATORS
BEXTON, D E, KABAHAHA, M, UFFER, R A Quadrex Corp FIN A-6451 82/12/31 Division of Safety Technology 42pp Available at NRC \$4 75 17013 179

8302040468 NUREG/CR-2966
BUCKLING INVESTIGATION OF RING-STIFFENED CYLINDRICAL SHELLS UNDER UNSYMMETRICAL AXIAL LOADS
BAKER, W, BENNETT, J, BARCOCK, C Los Alamos Scientific Laboratory FIN A-7222 LA-9536-HS 82/12/31 Division of Engineering Technology 82pp 17044 001.

8302040472 NUREG-0942 DRFT
CONDUCTING NEED-FOR-POWER REVIEW FOR NUCLEAR POWER PLANTS Guidelines To States.
NASH, A D Office of State Programs, Director 82/12/31 107pp
17044 084

8302040479 NUREG/CR-3097
BENCHMARK PROBLEMS FOR REPOSITORY SITING MODELS
ROSB, B., MERCER, J. W., THOMAS, S. D Geotrans, Inc FIN 8-6985 82/12/31 Division of Waste Management 151pp 17044 191

8302040502 NUREG/CR-2997 V01
APPLICATIONS OF ENERGY RELEASE RATE TECHNIQUES TO PART-THROUGH CRACK IN PLATES AND CYLINDERS
BASS, B R, BRYSON, J W Oak Ridge National Laboratory FIN B-0119 ORNL/TM-8527/V1 82/12/31 Division of Engineering Technology 17pp 17046 220

8302040508 NUREG/CR-2238 V19
ADVANCED REACTOR SAFETY RESEARCH QUARTERLY REPORT, JULY - SEPTEMBER 1981
* Sandia Laboratories FIN A-1016 SAND81-1529 82/12/31
Office of Nuclear Regulatory Research, Director 257pp 17041 142

8302040521 NUREG/CR-2988
AN APPROACH TO MODELING SUPERVISORY CONTROL OF A NUCLEAR POWER PLANT
BARDON, S., FEHRER, C., MURALIDHARAN, R Bolt, Beranck & Neuman, Inc FIN B-0438 ORNL/SUB/81-705 82/12/31 Office of Nuclear Regulatory Research, Director 158pp 17046 001

8302070042 Forwards 10CFR73.37 & NUREG-0561 for physical protection of shipments of irradiated reactor fuel per 791212 telcon
HILLMAN, C Physical Security Licensing Branch 79/12/12 OWEN, L
NRC - No Detailed Affiliation Given 1p 17062 024

8302070076 Partial response to FOIA request for 22 categories of documents Forwards documents listed in App A Documents 12, 13, 16, 18, 19, 27 & 28 available in PDR App D documents completely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 82/12/21 SHOLLY, S
Union of Concerned Scientists 6pp 17063 005

--8302070148 Responds to Commissioner Ahearn requests during B10529 briefing on SECY-BI-240, draft NUREG-0771 & 0772 re accident source term assumptions Comments will be sought from outside NRC Detailed analysis encl
DIRCKS, W J Office of the Executive Director for Operations B1/06/22 CHILK, S J Office of the Secretary of the Commission 11pp 17064 145 24X Fiche 50-000, 82/12/21, 8302070076

--8302070186 Forwards draft Chapters 1, 2, 6 & app of NUREG/CR-2629, "Interim Source Term Assumptions for Emergency Planning & Equipment Qualification," for review in 820318 meeting in Bethesda, MD
CHESTER, R O Oak Ridge National Laboratory 82/03/11 THADANI, H C NRC - No Detailed Affiliation Given 79pp
17064 327

8302080044 Responds to FOIA request for "background calculations of very low probability events" referred to by R Bernero on 821101 Forwards NUREG/CR-2239 "Technical Guidance For Siting Criteria Development" W/o encl
FELTON, J M Division of Rules and Records 83/01/13 GROSSMAN, K
Island Closeup News Service 1p 17105 238

8302080088 Summary of ACRS Subcommittee on Reliability & Probabilistic Assessment 820802 meeting in Washington, DC re draft action plan for implementation of proposed safety goals & accident policy Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/08/12
ACRS - Advisory Committee on Reactor Safeguards 31pp 17106 106

8302090016 Summary of ACRS Class 9 Accidents Subcommittee 820806 meeting in Washington, DC re NRC rev to severe accident research plan (SARP), (NUREG-0900) & SARP relation to SECY-82-1A
* ACRS - Advisory Committee on Reactor Safeguards 82/10/08
ACRS - Advisory Committee on Reactor Safeguards 10pp 17119 159

8302090079 Summary of ACRS Joint Committees on Safety Philosophy, Technology & Criteria & Class 9 Accidents 820908 meeting in Washington, DC re severe accidents policy statement, safety goals & implementation
* ACRS - Advisory Committee on Reactor Safeguards 20183 82/10/23 ACRS - Advisory Committee on Reactor Safeguards 5pp
17119 291

8302100263 NUREG/BR-0025 V09 N1
INFORMATION REPT ON STATE LEGISLATION
* Office of State Programs, Director 83/01/31 12pp 17133 171

8302100265 NUREG-0040 V06 N04
LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT Quarterly Report, October 1982 - December 1982
* Region 4, Office of Director 83/01/31, 269pp 17133 187

8302100271 NUREG/BR-0058
REGULATORY ANALYSIS GUIDELINES OF THE U S NUCLEAR REGULATORY COMMISSION
* Office of the Executive Director for Operations 83/01/31, 30
17143 232

NONDOCKETED ITEMS

- 3302100273 NUREG/CR-2806
A KINETIC MODEL FOR THE CHLORINATION OF POWER PLANT COOLING
WATERS
JOHNSON, J D , GUALLS, R G North Carolina, Univ of FIN B-624B
83/01/31 Division of Health, Siting & Environment 68pp
17135 194
- 3302100279 NUREG-0540 V04 N09
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE September 1-
30, 1982
* Division of Technical Information & Document Control 83/01/31
520pp 17136 015
- 3302100281 NUREG/CR-2300 V02
PRA PROCEDURES GUIDE A Guide To The Performance Of
Probabilistic Risk Assessments For Nuclear Power Plants
ICKMAN, J W American Nuclear Society * Institute of Electrical &
Electronic Engineers FIN G-1004 83/01/31 Office of Nuclear
Regulatory Research, Director 447pp 17138 324
- 3302100284 NUREG/CR-2300 V01
PRA PROCEDURES GUIDE A Guide To The Performance Of
Probabilistic Risk Assessments For Nuclear Power Plants
HICKMAN, J W American Nuclear Society * Institute of Electrical &
Electronic Engineers FIN G-1004 83/01/31 Office of Nuclear
Regulatory Research, Director 487pp 17137 197
- 3302100286 NUREG/CR-2847
COGAP A NUCLEAR POWER PLANT CONTAINMENT HYDROGEN CONTROL
SYSTEM EVALUATION CODE
GIDD, R J Los Alamos Scientific Laboratory FIN A-7105
LA-9459-MS 83/01/31 Division of Systems Integration (post
811005) 31pp 17135 346
- 3302140091 Comments on draft Rev 0 to NUREG-0933, "Prioritization of
Generic Safety Issues " Recommends that prioritization
methodology be revised to achieve consistency
SHERWOOD, G O General Electric Co 47FR57595 001 83/02/04
Docketing & Services Branch 5pp 17141 096
- 3302150027 Comments on proposed rule 10CFR50 & NUREG-0906, "Guidance
for Implementation of 10CFR50 34(g) " NUREG vague on what
info in SAR required to be evaluated against SRP
WOLFEVER, E J Duquesne Light Co 47FR47019 010 83/02/02
Docketing & Services Branch 2pp 17148 055
- 3302150718 NUREG/CR-2848
MECHANISTIC DRY-PRESSURE-CONTAINMENT LOCA ANALYSIS
GIDD, R J, LAMM, D , KESTEL, A Los Alamos Scientific Laboratory
FIN A-7105 LA-9460-MS 83/01/31 Division of Systems
Integration (post 811005) 53pp 17140 117
- 3302150723 NUREG-0580 V11 N12
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of
December 31, 1982 (Blue Book)
* Management Information Branch 83/01/31 65pp 17140 174
- 3302170022 NUREG-0748 V02 N12
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of
December 31, 1982 (Orange Book)
* Management Information Branch 83/01/31 292pp 17191 120
- 3302170024 NUREG-0090 V05 N03
REPORT TO CONGRESS ON ABNORMAL OCCURRENCES July - September
1982
* Director's Office 83/01/31 40pp Available at NRC \$4 50
17192 052
- 3302170028 NUREG-0485 V04 N12
SYSTEMATIC EVALUATION PROGRAM Status Summary Report Data As
Of December 31, 1982. (Buff Book)
* Office of Resource Management, Director 83/01/31 59pp
17192 089
- 3302170029 NUREG-0900
NUCLEAR PLANT SEVERE ACCIDENT RESEARCH PLAN
LARKINS, J T , CUNNINGHAM, M Office of Nuclear Regulatory Research,
Director 83/01/31 84pp 17192 149
- 3302170033 NUREG/CR-2000 V01N12
LICENSEE EVENT REPORT (LER) COMPILATION For Month Of
December 1982.
* Oak Ridge National Laboratory FIN B-1583, DRNL/NBIC-200
83/01/31 Director's Office 112pp 17192 282
- 3302170042 NUREG-0540 V04 N10
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE October 1 -
1982
* Division of Technical Information & Document Control 83/01/31,
pp 17193 034
- 8302170107 NUREG-0020 V06 N09
LICENSED OPERATING REACTORS Status Summary Report Data As Of
August 31, 1982 (Grey Book)
* Management Information Branch 83/01/31 366pp 17194 180
- 8302170198 NUREG/CR-2666
PWR SEVERE ACCIDENT DELINEATION AND ASSESSMENT
AHMAD, A , CATTON, I , CUESTA-GONZALEZ California, Univ of, Los
Angeles FIN B-6835 UCLA-ENG-8284 83/01/31 Division of
Systems Integration (post 811005) 276pp Available at NRC \$8 00
17187 137
- 8302170205 NUREG/CR-3008
AUDITORY PERCEPTION IN LOOSE-PARTS MONITORING
HOWARD, J H Catholic Univ FIN B-8253 83/01/31 Division of
Facility Operations 50pp Available at NRC \$4 75 17188 161
- 8302170208 NUREG/CR-2801
PIPING RELIABILITY MODE VALIDATION AND POTENTIAL USE FOR
LICENSING REGULATION DEVELOPMENT
WOOD, H H , CHOU, C K Lawrence Livermore Laboratory FIN A-0363-1
UCRL-53040 83/01/31 Division of Engineering Technology 63pp
Available at NRC \$5 00 17188 096
- 8302170213 NUREG/CR-2015 V03
SEISMIC SAFETY MARGINS RESEARCH PROGRAM, PHASE I FINAL
REPORT-DEVELOPMENT OF SEISMIC INPUT (PROJECT II)
BERNREUTER, D L , CHUNG, D H , MORTGAT, C P Lawrence Livermore
Laboratory FIN A-0130 UCRL-53021 83/01/31 Division of
Engineering Technology 142pp Available at NRC, \$6 00
17190 149
- 8302170251 NUREG/CR-3080
NETWORK LOCATION TESTING AND VELOCITY VARIATIONS IN
CENTRAL VIRGINIA
SHOLD, M B , BOLLINGER, G A Virginia Polytechnic Institute FIN
B-6249 83/01/31 Division of Health, Siting & Environment
80pp Available at NRC \$9 00 17196 011
- 8302170431 Forwards "NRC Reliability Program Plan, Task 2
Recommendations" & "NRC Reliability Program, Task 1 Survey
Results " Research conducted at Rome Air Development Ctr in
response to NUREG-0660, Task II C 4, reliability engineering
THADANI, A C Reliability & Risk Assessment Branch FIN B-8014
83/02/10 DENTON, H R Office of Nuclear Reactor Regulation,
Director SPEIS, T Division of Safety Technology EISENHUT, D O
Division of Licensing 8pp 17204 093
- 8302170435 RAC-TR-82-E01
"NRC Reliability Program Plan, Task 2 Recommendations," final
rept
LAUFFENBURGER, ANDERSON, R T , HENRY, C D IIT Research Inst
NRC-03-81-138 82/12/31 NRC - No Detailed Affiliation Given
11pp 17204 101
- 8302170438 "NRC Reliability Program Plan, Task 1 Survey Results,"
interim rept
HARESKY, J J , ANDERSON, R T , HENRY, C D IIT Research Inst,
NRC-03-81-138 82/10/31 NRC - No Detailed Affiliation Given
1p 17204 230
- 8302170469 NUREG/CR-1120 V10
SEISMIC SAFETY MARGINS RESEARCH PROGRAM Progress Report No
14
BOHN, M P , BERNREUTER, D L , CHUANQ, T V Lawrence Livermore
Laboratory FIN A-0126 83/01/31 Division of Engineering
Technology 42pp Available at NRC \$5 00 17197 185
- 8302170483 NUREG-0959
USER'S GUIDE FOR 10 CFR 61 IMPACT ANALYSIS CODES
WIDMAYER, D A Division of Waste Management 83/01/31 72pp
Available at NRC \$6 00 17198 073
- 8302170487 NUREG/CP-0041 V01
PROCEEDINGS OF THE TENTH WATER REACTOR SAFETY RESEARCH
INFORMATION MEETING
SZAWLEWICZ, S A Szawlewicz, S A 83/01/31 Office of Nuclear
Regulatory Research, Director 443pp Available at NRC \$11 00
17198 209
- 8302170491 NUREG/CP-0041 V05
PROCEEDINGS OF THE TENTH WATER REACTOR SAFETY RESEARCH
INFORMATION MEETING
SZAWLEWICZ, S A Szawlewicz, S A 83/01/31 Office of Nuclear
Regulatory Research, Director 399pp Available at NRC \$9 50,
17199 292
- 8302170496 NUREG/CP-0041 V06
PROCEEDINGS OF THE TENTH WATER REACTOR SAFETY RESEARCH
INFORMATION MEETING
SZAWLEWICZ, S A Szawlewicz, S A 83/01/31 Office of Nuclear
Regulatory Research, Director, 280pp Available at NRC \$8 00
17200 331

NONDOCKETED ITEMS

431

8302180031 Partial response to FOIA request for records re proposed rev of license fee schedules Forwards documents listed in App A Documents also available in PDR
FELTON, J M Division of Rules and Records 83/01/11 KNOXLES, N J
Shaw, Pittman, Potts & Trowbridge 7pp 17222 003

--8302180084 Requests addl info re Section K-1 of NUREQ-0748, "Operating Reactors Licensing Action Summary," 8td June 1981 High & Low range for each fee class required
MILLER, W D License Fee Management Branch 81/07/20 BERKOW, H
Management Analysis Branch 19pp 17222 058

8302220014 NUREQ-0750 V15 102
INDEXES TO NUCLEAR REGULATORY COMMISSION ISSUANCES
January - June 1982
* Commissioners 82/06/30 128pp 17239 145

8302220426 NUREQ/CR-2907 V01
RADIOACTIVE MATERIALS RELEASED FROM NUCLEAR POWER PLANTS - 1980
TICHER, J, BENKOVITZ, C Brookhaven National Laboratory FIN
8-2243 BNL-NUREG-51581 83/01/31 Division of Data Automation &
Management Information 219pp Available at NRC \$7 00
17240 114

8302220431 NUREQ/CR-3086
INVESTIGATION OF THE CONSERVATISM ASSOCIATED WITH DIFFERENT COMBINATIONS BETWEEN PRIMARY AND SECONDARY PIPING RESPONSES
WANG, Y K, SUBUDHI, M, BEZIER, P Brookhaven National Laboratory
FIN 8-3358 BNL-NUREG-51627 87/01/31 Division of Engineering
84pp Available at NRC \$5 00 17237 231

8302220435 NUREQ/CR-2805 V02
LWR PRESSURE VESSEL SURVEILLANCE DOSIMETRY IMPROVEMENT
PROGRAM Quarterly Progress Report April 1982 - June 1982
GUTHRIE, O L, MCCLROY, W N Hanford Engineering Development
Laboratory FIN 8-3988-7 HEDL-TMC 82-19, 83/01/31 Division of
Engineering Technology 50pp Available at NRC \$4 75 17237 177

8302220438 NUREQ-0940 V01 N04
ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESOLVED Quarterly
Progress Report October - December 1982
* Director's Office, Office of Inspection and Enforcement
83/01/31 132pp Available at NRC \$6 50 17237 025

8302220441 NUREQ/CP-0041 V02
PROCEEDINGS OF THE TENTH WATER REACTOR SAFETY RESEARCH
INFORMATION MEETING
SZAWLEWICZ, S A Szawlewicz, S A 83/01/31 Office of Nuclear
Regulatory Research, Director 504pp Available at NRC \$11 00
17238, 001

8302220442 NUREQ/CP-0041 V03
PROCEEDINGS OF THE TENTH WATER REACTOR SAFETY RESEARCH
INFORMATION MEETING
SZAWLEWICZ, S A Szawlewicz, S A 83/01/31 Office of Nuclear
Regulatory Research, Director 312pp Available at NRC \$8 50
17234 001

8302220443 NUREQ/CP-0041 V04
PROCEEDINGS OF THE TENTH WATER REACTOR SAFETY RESEARCH
INFORMATION MEETING
SZAWLEWICZ, S A Szawlewicz, S A 83/01/31 Office of Nuclear
Regulatory Research, Director 326pp Available at NRC \$8 50
17235 001

8302220466 Forwards NUREQ-0090, Vol 5, Number 3, "Rept to Congress on
AQs, Jul-Sept 1982."
PALLADINO, N J Commissioners 83/02/03 O'NEILL, T P House of
Rep., Speaker of the House 1p 17234 307

--8302220469 Forwards NUREQ-0090, Vol 5, Number 3, "Rept to Congress on
AQs, Jul-Sept 1982."
PALLADINO, N J Commissioners 83/02/03 BUSH, G H W Senate,
President of the Senate 1p 17234 308

8302230025 NUREQ/CR-3079
EARTHQUAKE HAZARD STUDIES IN NEW YORK STATE AND ADJACENT
AREAS Final Report, April 1976 - June 1982
KUFKA, A L Columbia Univ FIN 8-6096 83/01/31 Division of
Health, Siting & Environment, 70pp Available at NRC \$5 00
17241 225

8302230043 NUREQ-0737 601
CLARIFICATION OF THE ACTION PLAN REQUIREMENTS REQUIREMENTS
FOR EMERGENCY RESPONSE CAPABILITY
* Division of Licensing 83/01/31 28pp Available at NRC
\$4 50 17301 324,

8302250016 NUREQ/CR-3106
COMPARISON OF FIVE-MINUTE RADON DAUGHTER MEASUREMENTS WITH
LONG-TERM RADON AND RADON DAUGHTER CONCENTRATIONS
YOUNG, J A, JACKSON, P O, THOMAS, V H Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2370 PNL-4591 83/01/31
Division of Health, Siting & Environment 23pp Available at NRC
\$4 50 17299 316

8302250053 NUREQ/CR-2675 V03
RELEVANCE OF BIOTIC PATHWAYS TO REGULATION OF NUCLEAR WASTE
DISPOSALS Topical Report On Preference Eastern Humid
Low-Level Sites
MCKENZIE, D H, CADMELL, L L, EBERHARDT, L E Battelle Memorial
Institute, Pacific Northwest Laboratory FIN 8-2377 PNL-4241
83/01/31 Division of Health, Siting & Environment 34pp
Available at NRC \$4 75 17300 250

8302250071 NUREQ-0851
MONITORING FOR EVALUATION OF DOSES FROM FINITE NOBLE GAS
CLOUDS
PASCIAK, W J, FAIROBENT, L A, WANDLER, M E Division of Systems
Integration (post 811003) 83/01/31 249pp Available at NRC
\$7 50 17300 001

8302250094 NUREQ/CR-2856
A REVIEW OF FUGITIVE DUST CONTROL FOR URANIUM MILL
TAILINGS
LI, C T, ELIORE, M R, HARTLEY, J H Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2370 PNL-4360 83/01/31
Division of Health, Siting & Environment 58pp Available at NRC
\$5 00 17300 309

8302250112 NUREQ-0943
THREADED FASTENER EXPERIENCE IN NUCLEAR POWER PLANTS
KOD, W M Division of Licensing 83/01/31 30pp Available at NRC
\$4 50 17299 284

8302250113 NUREQ-0953
FY 1984/85 BUDGET ESTIMATES
* Office of Resource Management, Director 83/01/31 92pp
17302 099

8302250115 NUREQ-0965
NRC INVENTORY OF DAMS
LEAR, G E, THOMPSON, O D NRC - No Detailed Affiliation Given
83/01/31, 58pp Available at NRC \$5 50 17302 001

8302250122 NUREQ/CR-2983
SELECTED HYDROLOGIC AND GEOCHEMICAL ISSUES IN SITE
CHARACTERIZATION FOR NUCLEAR WASTE DISPOSAL Flood Basalts
At the Hanford Reservation
ABRAHAM, C L, DELANY, J H, LONG, J C S Lawrence Berkeley Laboratory
FIN 8-3107 LBL-15029 83/01/31 Division of Waste Management
180pp Available at NRC \$6 50 17301 004

8302250129 NUREQ/CR-2755
PACKING MATERIAL TESTING REQUIRED TO DEMONSTRATE COMPLIANCE
WITH 1000-YEAR RADIOACTIVE CONTAINMENT Semiannual Report On
Waste Package Verification Tests
BIDA, O, EASTWOOD, D Brookhaven National Laboratory FIN A-3167
BNL-NUREG-51544 83/01/31 Division of Waste Management 38pp
Available at NRC \$4 50 17299 246

8302250135 NUREQ/CR-2805 V01
LWR PRESSURE VESSEL SURVEILLANCE DOSIMETRY IMPROVEMENT
PROGRAM Quarterly Progress Report January 1982 - March 1982
GUTHRIE, O L, MCCLROY, W N Hanford Engineering Development
Laboratory FIN 8-3988-1 HEDL-TMC 82-18 83/01/31 Division of
Engineering Technology 136pp 17301 186

8302250140 NUREQ-0580 V12 N01
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of
January 31, 1983 (Blue Book)
* Management Information Branch 83/02/28 68pp 17299 175

8302250146 NUREQ/CR-2804
THE APPLICATION OF FISHERIES MANAGEMENT TECHNIQUES TO
ASSESSING IMPACTS Final Report
MCKENZIE, D H, SIMMONS, M A, SKALSKI, J R Battelle Memorial
Institute, Pacific Northwest Laboratory FIN 8-2160-B 83/01/31
Division of Engineering 58pp Available at NRC \$4 75
17299 073

8302250151 NUREQ/CR-3076
COMPUTER PREDICTION OF SUBSURFACE RADIOACTIVE TRANSPORT -
AN ADAPTIVE NUMERICAL METHOD
NEUMAN, S P Arizona Univ of FIN 8-5753 83/01/31 Waste
Management Branch 43pp Available at NRC \$4 75 17299 130

8302280004 NUREQ-0936 V01 N04
NRC REGULATORY AGENDA Quarterly Report September -
December 1982
* Division of Rules and Records 83/01/31 210pp 17313 113

NONDOCKETED ITEMS

- 8302280036 NUREG/CR-2879
FEASIBILITY FOR QUANTITATIVE ASSESSMENT OF AVAILABLE
MARGINS INHERENT IN FLOOD PROTECTION OF NUCLEAR POWER
PLANTS
BORGMAN, L. E. Army, Dept. of Army Engineer Waterways Experiment
Station FIN 8-7003 83/01/31 Division of Health, Siting &
Environment 163pp Available at NRC \$6 50 17320 136
- 8302280013 NUREG/CR-3109
EXTENDED BURNUP CALCULATIONS FOR OPERATING REACTOR RELOAD
REVIEWS
WILSON, W. B., ENGLAND, T. R., LABAUVE, R. J. Los Alamos Scientific
Laboratory FIN A-7264 LA-9563-MS 83/02/28 Division of
Systems Integration (post 811009) 96pp Available at NRC \$5 50
17314 136
- 8302280020 NUREG/CR-2805 V03
LWR PRESSURE VESSEL SURVEILLANCE DOSIMETRY IMPROVEMENT
PROGRAM 1982 ANNUAL REPORT (October 1, 1981 - September 30,
1982)
MCCLROY, W. H. Hanford Engineering Development Laboratory KAM, F. B. K
Oak Ridge National Laboratory GRUNDL, J. A. Commerce, Dept. of,
National Bureau of Standards FIN 5-5988-7 HEDL-THE 82-20
83/01/31 Division of Engineering Technology 173pp 17313 323
- 8302280024 NUREG-0871 V02 N01
SUMMARY INFORMATION REPORT October 1 - December 31, 1982
(Brown Book)
* Management Information Branch 83/02/28 52pp 17303 270
- 8302280044 NUREG/BR-0059
SMALL BUSINESS INNOVATION RESEARCH PROGRAM Program
Solicitation FY 1983
* Office of Nuclear Regulatory Research, Director 83/02/28 44pp
17303 323
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

- 8212060358 IE Info Notice 83-01, "Ray Miller, Inc." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/26 Consolidated Edison Co. of New
York, Inc. 118pp 17023 160 24X Fiche 50-000, 83/01/26, 8212060358
- 8212060360 IE Info Notice 83-02, "Limitorque H08C, H18C, H28C & H38C
Overheads" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc. 109pp 17144 001 24X Fiche 50-000, 83/01/28, 8212060360
- 8212060361 IE Info Notice 83-03, "Caliber of Liquid Level Instruments" Svc
list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/01/28 Consolidated Edison Co. of New
York, Inc. 110pp 17074 095 24X Fiche 50-000, 83/01/28, 8212060361
- 8212060363 IE Info Notice 83-04, "Failure of Elma Power Supply Units" Svc
list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/18 Consolidated Edison Co. of New
York, Inc. 110pp 17347 191 24X Fiche 50-000, 83/02/18, 8212060363
- 8212060365 IE Info Notice 83-05, "Obtaining Approval for Disposing of
Very Low Level Radwaste - 10CFR20 302" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc. 111pp 17347 058 24X Fiche 50-000, 83/02/24, 8212060365
- 8212060366 IE Info Notice 83-06, "Nonidentical Replacement Parts" Svc
list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/02/24 Consolidated Edison Co. of New
York, Inc. 112pp 17361 148 24X Fiche 50-000, 83/02/24, 8212060366
- 8302040030 Forwards project & budget proposal for NRC work "Equipment
Qualification Research Program"
MILAKS, B. Energy, Dept. of Idaho Operations Office FIN A-6322
83/01/21, ARLOTT, O. A. Division of Engineering Technology 1p
17043 243
- 8302040031 Project & budget proposal for NRC work "Equipment
Qualification Research Program"
HUNTER, J. A. EG&G, Inc. FIN A-6322 83/01/05 CAMPBELL,
RICHARDSON Office of Nuclear Regulatory Research, Director 23pp
17043 244
- 8302080034 Forwards request for OMB review & supporting statement re
reporting requirements of IE Bulletin 83-01, "Stress
Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless
Steel Recirculation Sys Piping at BWR Plants"
NORRY, P. O. Office of Administration IEB-83-01 83/02/04
SCURRY, N. Office of Management & Budget 1p 17071 155.
- 8302080351 Responds to approval request for info collection re
abandoned well-logging sources Request approved through
831031 under OMB Number 3150-0095, per Paperwork Reduction
Act
SCURRY, N. Office of Management & Budget OMB 3150-0095 83/01/27
SCOTT, S. Document Management Branch 2p 17071 168
- 8302100459 Forwards request for OMB review & supporting statement re
reporting & recordkeeping requirements of NRC Form 136,
"Security Termination Statement"
NORRY, P. O. Office of Administration 83/02/08 SCURRY, N. Office
of Management & Budget 1p 17143 275
- 8302100466 Forwards request for OMB review & supporting statement re
reporting & recordkeeping requirements of NRC Form 277,
"Request for Visit or Access Approval"
NORRY, P. O. Office of Administration 83/02/08 SCURRY, N. Office
of Management & Budget 3pp 17143 283
- 8302170005 Responds to approval request for info collection re proposed
rule 10CFR90.54(i) concerning fitness for duty Request
approved through 850430 under OMB Number 3150-0011, per
Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0011 82/12/27
SCOTT, S. Document Management Branch 2pp 17196 007
- 8302170007 Responds to approval request for info collection re NRC
Form 212 concerning qualification investigations (prof)
Request approved through 851231 under OMB Number 3150-0033,
per Paperwork Reduction Act
SCURRY, N. Office of Management & Budget OMB 3150-0033 82/12/27
SCOTT, S. Document Management Branch 2pp 17196 009
- 8302240057 Forwards fourteenth joint status rept on emergency
preparedness & second quarterly rept for period ending
821231
AHEARNE, J. F. Commissioners GIUFFRITA, L. D. Federal Emergency
Management Agency 83/01/25 SIMPSON, A. K. Senate, Environment &
Public Works 1p 17287 278
- 8302240065 'NRC/FEMA Joint Quarterly Rept to Congress on Emergency
Preparedness, Oct-Dec 1982,' discussing efforts to upgrade
issues
* Commissioners 4 Federal Emergency Management Agency
83/01/25 58pp 17287 279
- PR PROPOSED RULE

- 8301170225 Advises recipients of comments on proposed rule 10CFR2 re
authority to issue notices of violation to nonlicensees &
delegation of authority to regional administrators that
Comment 7 miscoded & will not be used again
* Docketing & Services Branch 47FR51402 83/01/13 Docketing &
Services Branch 1p 16810 261
- 8301240253 Responds to 821227 inquiry re RJ Cerny ltr on Commission
proposed schedule of revised fees Fee for renewal of
medical license designed to cover Commission cost of
renewing license
DIRCKS, W. J. Office of the Executive Director for Operations
47FR52454 83/01/13 VANDER JAOT, G. House of Rep 2pp
17112 215
- 8302100471 Requests response to encl R Cerny 821221 comment on proposed
rule 10CFR170 re intent of NRC to raise fees for
applications, renewals & amends to nuclear medicine licenses
VANDER JAOT, G. House of Rep 82/12/27 KAMMERER, C. Office of
Congressional Affairs 1p 17112 217.
- 8302100473 Comments on proposed rule 10CFR170 re NRC intent to raise
fees for applications, renewals & amends to nuclear medicine
licenses Opposes rule & requests return to more rational sys
of revenue generation for NRC
CERNY, R. J. Memorial Hosp. of Mason County, Ludington, MI
82/12/21 Docketing & Services Branch 1p 17112 218
- 8302100227 Advises recipients of comments on proposed rule 10CFR90,
"Personnel (U) Unescorted Access to Protected Areas/Fitness
for Duty," that Comment 72 miscoded Number will not be used
again
* Office of the Secretary of the Commission 47FR33980 072
83/02/04 Office of the Secretary of the Commission 1p
17114 127.
- 8302100233 Package of two comments on proposed rule 10CFR170 re
schedule of fees for insps & reviews of applications,
renewals & amends Opposes rule
REMLEY, M. E. Rockwell International Corp SHEAGREN, C. McDonough
District Hosp. Macomb, IL 47FR52454 83/01/27 Docketing &
Services Branch 13pp 17115 052

NONDOCKETED ITEMS

8302100269 Comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention periods for security records Personnel, security & confidential info should be excluded
THORPE, J R General Public Utilities - GPU Service Corp 47FR52452 017 83/01/21 CHILK, S J Office of the Secretary of the Commission 2pp 17110 121

8302100275 Package of two comments opposing proposed rule 10CFR170 re proposed rev of industrial radiography licensee fee schedules
KOVACS, B Foster Wheeler Corp * Harper-Grace Hosps Detroit, MI 47FR52454 83/01/19 Docketing & Services Branch 2pp 17110 111

8302100277 Package of four comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention period for security records
BOOKER, J E Gulf States Utilities Co 47FR52452 83/01/24 Docketing & Services Branch 6pp 17110 113

8302100283 Package of three comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention period for security records
KNUTH, D F Kerr-McOee Chemical Corp (subs of Kerr-McOee Corp) 47FR52452 83/01/21 CHILK, S J Office of the Secretary of the Commission 8pp 17110 181

8302100285 Package of two comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention periods for security records
COUNSILL, W O Northeast Utilities 47FR52452 83/01/31 CHILK, S J Office of the Secretary of the Commission 5pp 17110 176

8302100287 Package of three comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention periods for security records
THOMAS, O S Public Service Co of New Hampshire 47FR52452 83/01/27 CHILK, S J Office of the Secretary of the Commission 9pp 17110 167

8302100291 Package of seven comments re proposed rule 10CFR170 concerning rev of license fee schedules Opposes proposed rule
DELEGORGE, L O Commonwealth Edison Co MITTLER, L Public Service Electric & Gas Co of New Jersey OIESLER, C W Wisconsin Public Service Corp 47FR52454 83/01/21 CHILK, S J Office of the Secretary of the Commission 14pp 17112 067

8302100300 Comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention periods for security records Release of many records could constitute unwarranted intrusion into employees privacy
UHRIG, R E Florida Power & Light Co L-83-20 83/01/17 Docketing & Services Branch 2pp 17116 194

8302100308 Advises recipients of comments on proposed rule 10CFR170 re rev of license fee schedules that Comment 122 was mis-coded Number 122 will not be used again
* Docketing & Services Branch 47FR52454 83/02/08 Docketing & Services Branch 1p 17112 055

8302100319 Forwards 821222 ltr protesting fee increase in proposed rule 10CFR170 re license fee schedule
DIXON, A J Senate 47FR52454 019 83/01/14 NRC - No Detailed Affiliation Given 1p 17116 323

--8302100320 Urges re-evaluation of proposed rule 10CFR170 re license fee schedules Opposes increases
MUSSEBAUM, B Victory Memorial Hosp , Waukegan, IL 47FR52454 019 82/12/22 Docketing & Services Branch 2pp 17116 324

8302100321 Forwards comments on proposed rule 10CFR170 re license fee increases Response requested
DIXON, A J Senate 47FR52454 013 83/01/14 NRC - No Detailed Affiliation Given 1p 17112 081

--8302100324 Comments on proposed rule 10CFR170 re license fee change Opposes rule
PICKUS, M Grant Hosp of Chicago Chicago, IL 47FR52454 013 82/12/22 Docketing & Services Branch 1p 17112 082

8302100322 Comments on protest to proposed rule 10CFR170 re license fee increases Final rule will consider submitted comments
KAMMERER, C Office of Congressional Affairs 47FR52454 83/01/24 PROXHIRE, W Senate 2pp 17117 058

--8302100325 Forwards protest for response re proposed rule 10CFR170 concerning license fee schedules
PROXHIRE, W Senate 47FR52454 83/01/19 PATTON, L Office of Congressional Affairs 1p 17117: 060.

--8302100326 Comments on proposed rule 10CFR170 re license fee sched Opposes rule
MCWINSKI, D M Langlade County Memorial Hosp Antigo, WI 47FR52454 83/01/05 Docketing & Services Branch 2pp 17117 051

8302100323 Responds to 830104 inquiry re proposed rule 10CFR170 concerning schedule or revised fees for facilities & matls applications, renewals, amends & licenses
KAMMERER, C Office of Congressional Affairs 47FR52454 039 83/01/17 LAUXE, T House of Rep 2pp 17110 085

--8302100327 Comments on proposed rule 10CFR170 re proposed fee sche for nuclear medicine licenses announced in 821122 FR
Proposed increase excessive in light of rising health care Requests current status & alternatives under consideration
TAUAF, T Congress (Joint & Rotating Committees, etc) 47FR524 039 83/01/04 PALLADINO, N J Commissioners 1p 17110 087

8302100328 Forwards revised 830121 ltr correcting typographical errors in comments on proposed rules 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention periods for security records
WIESEMANN, R A Westinghouse Electric Corp NS-RAW-83-447 83/01/27 CHILK, S J Office of the Secretary of the Commission 1p 17110 088

--8302100336 Revised comments on proposed rules 10CFR19.21.30.40.50.71.73 & 110 re authority for copying of records & retention periods for security records
RAHE, E P Westinghouse Electric Corp 47FR52452 020 83/01/21 CHILK, S J Office of the Secretary of the Commission 5pp 17110 089

8302100337 Comments on proposed rule 10CFR20 re testing of personnel dosimetry processors, intermediate working draft, Aug 1982
TARAS, D H Army, Dept of Headquarters Materiel Development & Readiness Command 45FR16023 076 83/01/21 Docketing & Serv: Branch 5pp 17116 351

8302100338 Package of nine comments on proposed rule 10CFR170 re rev license fee schedule Opposes rule
MCDOVERN, J H Union Carbide Corp WISENBURG, M R Houston Light & Power Co DUNN, D W Iowa Hosp Association 47FR52454 83/01/24 Docketing & Services Branch 20pp 17111 116

8302100343 Requests extension of time until 830208 to file comments on proposed rule 10CFR170 re proposed rev to license fee schedule
SZALAY, R Atomic Industrial Forum 47FR52454 83/01/14 Docketing & Services Branch 1p 17112 061

8302100344 Responds to 821222 inquiry re AP Compton 821213 comments proposed rule 10CFR170 concerning schedule of revised fees for facilities & matls applications, amends & licenses
DIRKS, W J Office of the Executive Director for Operations 47FR52454 003 83/01/13 BOREN, D Senate 2pp 17112 056

--8302100346 Requests response to AP Compton 821213 ltr re proposed 10CFR170 concerning license fee schedules
BOREN, D L Senate 47FR52454 003 82/12/22 Office of Congressional Affairs 2pp 17112 058

8302100347 Comments on proposed rule 10CFR170 re proposed rev to license fee schedule Horrified at prospects of 300-600% increase Lambasts govt bureaucracy for attitude toward health care profession
HEUNIER, J St Alphonsus Hosp Port Washington, WI 47FR52454 01 83/01/10 Docketing & Services Branch 1p 17112 021

8302100348 Responds to 830106 inquiry re H Bruyn 821229 comments on proposed rule 10CFR170 re revised fees for facilities & matls applications, renewals, amend & licenses Notice of proposed rulemaking published in 821122 FR encl W/o encl
KAMMERER, C Office of Congressional Affairs 47FR52454 047 83/01/17 KASTEN, R H Senate 1p 17112.018

--8302100351 Requests response to encl H Bruyn 821229 ltr re proposed rule 10CFR170 concerning fee increases for license applications & amends
KASTEN, R H Senate 47FR52454 83/01/06 KRAMER, C Office of Congressional Affairs 2pp 17112 019

8302100354 Comments on behalf of listed utils & C-E on proposed rule 10CFR19.21.30.40.50.70.71.73 & 110 re authority for copying of records & retention period for security records Opposes rules
SHEA, K H Lowenstein, Newman, Reis, Axelrad & Toll 47FR52452 010 83/01/21 CHILK, S J Office of the Secretary of the Commission 3pp 17116 256.

NONDOCKETED ITEMS

02100356 Package of four comments re proposed rule 10CFR170 concerning license fee schedules
HERLINGER, D R Mercy Hosp & Medical Center Chicago, IL BENTSEN, L
Senate SCHERER, A E Combustion Engineering, Inc 47FR52454
83/01/31 Docketing & Services Branch 8pp 17112 043

02100340 Responds to 830107 inquiry re WJ Rogers 821223 comments on proposed rule 10CFR170 concerning schedule of revised fees for facilities & matls applications, renewals, amends & licenses
KAMMERER, C Office of Congressional Affairs 47FR52454 83/01/17
GRASSLEY, C E Senate 2pp 17110 097

8302100365 Requests response to encl WJ Rogers 821223 comments on proposed rule 10CFR170 re proposed increases for nuclear medicine licenses
GRASSLEY, C E Senate 47FR52454 83/01/07 KAMMERER, C C
Office of Congressional Affairs 2pp 17110 099

02100362 Package of ten comments opposing proposed rule 10CFR170 re proposed rev of license fee schedules
CONNER, T B Conner & Hetterbahn CLARK, J R Nuclear Fuel Services, Inc (subs of Getty Oil Co) TOWNSEND, T Maytag Co 47FR52454
83/01/20 Docketing & Services Branch 48pp 17116 204

02100353 Forwards notice of proposed rulemaking in response to 830114 inquiry from PF Opp re proposed rule 10CFR170 on proposed fees for nuclear medicine licenses
KAMMERER, C Office of Congressional Affairs 47FR52454 012
83/01/28 DIXON, A J Senate 2pp 17110 106

8302100371 Forwards PF Opp 821222 comments on proposed rule 10CFR170 re nuclear medicine licenses, for review
DIXON, A J Senate 47FR52454 012 83/01/14 NRC - No Detailed
Affiliation Given 1p 17110 108

8302100377 Comments on proposed rule 10CFR170 re proposed fees for nuclear medicine licenses Opposes rule
OPP, P F Community Memorial Hosp Monmouth, IL 47FR52454 012
82/12/22 Docketing & Services Branch 1p 17110 109

02100368 Responds to inquiry re H Bruyn 821230 comments on proposed rule 10CFR170 concerning schedule of revised fees for facilities & matls applications, renewals, amends & licenses
KAMMERER, C Office of Congressional Affairs 47FR52454 082
83/01/19 PROXMIER, W Senate 1p 17116 197

8302100372 Requests response to encl H Bruyn 821230 ltr re proposed rule 10CFR170 concerning fee increases for license applications & amends
PROXMIER, W Senate 47FR52454 082 83/01/03 Office of
Congressional Affairs 2pp 17116 198

02100370 Comments on proposed schedule of revised fees in response to protest forwarded in 830125 ltr Protest will be considered in final rule
KAMMERER, C Office of Congressional Affairs 47FR52454 125
83/02/01 BENTSEN, L Senate 2pp 17116 189

8302100376 Forwards petition from constituent re proposed schedule of revised fees Response requested
BENTSEN, L Senate 83/01/25 KAMMERER, C C Office of
Congressional Affairs 3pp 17116 191

02100375 Comments on proposed rule 10CFR170 re rev of license fee schedules Supports concept of payment by identifiable recipients of special benefits for cost associated w/ benefits Recommends several changes to rule
HANCOCK, J A Florida Power Corp 47FR52454 104 83/01/19
CHILK, S J Office of the Secretary of the Commission 2pp
17110 080

02100378 Requests response to encl J Meunier 830110 ltr re proposed increase in fees for nuclear medicine licenses
PROXMIER, W Senate 47FR52454 089 83/01/28 Office of
Congressional Affairs 1p 17110 083

02100379 Forwards constituent 821221 ltr to be submitted as public comment on proposed rule 10CFR170 re license fee schedules
EMERSON, B House of Rep 83/01/12 Office of the Secretary of
the Commission 2pp 17112 261

02100382 Responds to 830111 inquiry re AP Compton comment on proposed rule 10CFR170 concerning schedule of revised fees for facilities & matls applications, renewals, amends & licenses
Insp conducted as part of NRC statutory obligations
KAMMERER, C Office of Congressional Affairs 47FR52454 003
83/01/17 NICKLES, D Senate 2pp 17111 326

--8302100386 Requests response to encl AP Compton 821213 ltr re proposed rule 10CFR170 concerning licensing fees & effect on medical industry
NICKLES, D Senate 47FR52454 003 83/01/11 Office of
Congressional Affairs 2pp 17111 328

8302100393 Comments on behalf of utils on proposed rule 10CFR170 re rev of license fee schedules Opposes rule
HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 47FR52454 081
83/01/18 Docketing & Services Branch 11pp 17112 271

--8108200457 Comments on proposed use of insp manhours for license fee purposes to recover more of costs for performing insp
Rev to proposal suggested Range of insp manpower expended
per licensee for insp conducted during FY81 encl
STELLO, V, Director's Office, Office of Inspection and Enforcement
47FR52454 81/07/27 DOMOGHUE, D J Office of Administration
2pp 17112 285

--8302100392 Comments on proposed rev of license fee schedules per 821018 request Billing costs of investigations would in some instances be unfair
FITZGERALD, J A Director's Office, Office of Inspection and Enforcement 82/10/21 MARRY, P G Office of Administration
2pp 17112 282

--8302100400 Comments on FR notice re rev to license fees
SNIEZEK, J H Director's Office, Office of Inspection and Enforcement 82/10/21 MARRY, P G Office of Administration 1p
17112 284

8302100384 Comments on proposed rules 10CFR19, 21, 30, 40, 50, 70, 71, 73 & 110 re authorization for NRC representatives to make & remove copies of licensee record documents Opposes rules
KOVACS, B Foster Wheeler Corp 47FR52454 007 83/01/14
Docketing & Services Branch 1p 17116 362

8302100395 Responds to 830117 inquiry re LG Perry ltr commenting on proposed schedule of revised fees for facilities & matls applications, renewals, amends & licenses Notice of proposed rulemaking published in 821122 FR encl w/o encl
KAMMERER, C Office of Congressional Affairs 47FR52454 176
83/01/28 LUGAR, R O Senate 2pp 17117 001

--8302100389 Requests response to encl LG Perry 821221 ltr re proposed NRC fees for nuclear medicine licenses
LUGAR, R O Senate 83/01/17 KAMMERER, C, Office of
Congressional Affairs 2pp 17117 003

8302100390 Forwards Vernon County, WI comments on proposed rule 10CFR170 re revised fees for facilities & matls applications, renewals, amends & licenses Opposes rule as written & suggests alternative fee schedule
GUNDERSON, B House of Rep 47FR52454 127 83/01/28 HOYLE, J C
Office of the Secretary of the Commission 5pp 17116 339

8302100393 Responds to 830125 inquiry re proposed rule 10CFR170 concerning revised fees Policy of charging fees explained
KAMMERER, C Office of Congressional Affairs 47FR52454 83/01/28
MICHEL, R H House of Rep 2pp 17117 010

--8302100398 Requests cost identification formula explaining license fee increase per proposed rule 10CFR170
MICHEL, R H House of Rep 47FR52454 83/01/25 KAMMERER, C C
Office of Congressional Affairs 1p 17117 012

8302100394 Forwards, for response, H Bruyn 821230 ltr opposing proposed rule 10CFR170 re proposed licensee fee increases
PROXMIER, W Senate 47FR52454 082 83/01/19 NRC - No Detailed
Affiliation Given 2pp 17117 007

8302100396 Comments on proposed rule 10CFR70 re amend to regulations governing matl control & accounting requirements for low enriched U Approves amend.
SCHLAPPER, G A Texas A&M Univ, College Station, TX 47FR55951 003
83/01/10 Docketing & Services Branch 1p 17111 283

8302100397 Comments on proposed rule 10CFR170 re revs of license fee schedule Opposes rule
PELLIZZA, M S Uranium Resources, Inc 47FR52454 117, 83/01/21,
Docketing & Services Branch 2pp 17117 189

8302100399 Responds to 830106 inquiry re L Macek comment on proposed rule 10CFR170 concerning schedule of revised fees for facilities & matls applications, renewals, amends & licenses
Written comments under review
KAMMERER, C, Office of Congressional Affairs 47FR52454 054
83/01/17 DIXON, A J Senate 2pp 17117 013,

NONDOCKETED ITEMS

4

--B302100403 Requests response to encl LJ Macet B21230 ltr re proposed rule 10CFR170 concerning fees for nuclear medicine licenses
DIXON, A J Senate 47FR52454 054 83/01/06 NRC - No Detailed Affiliation Given 2pp 17117 015

B302100402 Responds to B30114 inquiry from constituent M Pickus re proposed rule 10CFR170 on proposed rev of license fee schedule
constituent comments will be considered in NRC deliberations
KAHMERER, C Office of Congressional Affairs 47FR52454 013 83/01/28 DIXON, A J Senate 2pp 17117 018

--B302100411 Forwards constituent M Pickus B21222 ltr commenting on proposed rule 10CFR170 re proposed rev of license fee schedule
Response requested
DIXON, A J Senate 47FR52454 013 83/01/14 NRC - No Detailed Affiliation Given 2pp 17117 020

B302100404 Comments on proposed rule 10CFR170 re rev of license fee schedules
Policy position re nonroutine insps supported
WEIR, J O , BHQDP, J D American College of Nuclear Physicians
WEIR, J O Society of Nuclear Medicine 47FR52454 089 83/01/18 Docketing & Services Branch 2pp 17112 193

B302100410 Supports & adopts JB Hamlin B30118 comments on proposed rule 10CFR170 re proposed rev of license fee schedule
KAPLAN, D B Sacramento Municipal Utility District 47FR52454 128 83/01/31 Docketing & Services Branch 1p 17112 102

B302100420 Responds to B30105 ltr transmitting constituent AP Compton B21213 comments on proposed rule 10CFR170 re proposed schedule of revised fees for facilities & matl applications, amends & licenses
DICKER, W J Office of the Executive Director for Operations 47FR52454 83/01/13 JONES, J R House of Rep 2pp 17112 103

--B302100425 Requests response to constituent AP Compton B21213 comments on proposed rule 10CFR170 re proposed schedule of revised fees for facilities & matl applications, amends & licenses
JONES, J R House of Rep 47FR52454 83/01/05 KAHMERER, C Office of Congressional Affairs 2pp 17112 105

B302100422 Replaces Comment 10, dtd B30105, re proposed rules 10CFR30.40 & 70 concerning specifying licensee responsibility for nuclear matls & procedures for termination of specific licenses
DELOEDROG, L O Commonwealth Edison Co 47FR47400 83/01/17 Docketing & Services Branch 2pp 17112 202

B302100423 Comments on proposed rule 10CFR70 re amended matl control & accounting requirements for SNM of low strategic significance, Supports rule
LUMB, R F NUBAC, Inc 47FR55951 004 83/01/26 Docketing & Services Branch 2pp 17117 255

B302100431 Responds to B30112 inquiry re comments on proposed rule 10CFR170 concerning revised fees Policy of charging fees & addl comments explained
KAHMERER, C Office of Congressional Affairs 47FR52454 83/01/17 JEPSON, R C Senate 2pp 17117 151

--B302100435 Forwards comments re proposed rule 10CFR170 concerning license fee schedules Views & findings requested
JEPSON, R W Senate 47FR52454 83/01/10 Office of Congressional Affairs 2pp 17117 153

B302100432 Comments on proposed rules 10CFR2 & 55, "Hearing on Denial of Reactor Operator License " Opposes rule
BANDY, W A Professional Reactor Operator Society 47FR53028 009 83/01/20 Office of the Secretary of the Commission 6pp 17117 170

B302100434 Comments on proposed rule 10CFR20 re testing of personnel dosimetry processors. Agrees w/rev requiring NRC licensee to utilize personnel dosimetry processors accredited by NBB, Natl Voluntary Lab Accreditation Program
SHEALY, H O Conference of Radiation Control Program Directors, Inc 47FR20493 079 83/01/27 PALLADINO, N J Commissioners 2pp 17112 265

B302100439 Comments on proposed rules 10CFR2 & 55 re hearings on denial of operator licenses Opposes any changes in existing appeal process
HUGOLF, D Northern States Power Co 47FR53028 010 83/01/25 Docketing & Services Branch 1p 17117 196

B302100441 Comments on protest to proposed rule 10CFR170 re fee increase for applications, renewals, amends & insps. Final rule will consider protests
KAHMERER, C Commissioners, 47FR52454 114 83/01/24 EMERSON, B House of Rep 2pp 17112 267

--B302100462 Forwards B21221 ltr from constituent for response re proposed rule 10CFR170 on fee increase for applications, renewals, amends & insps
EMERSON, B House of Rep 47FR52454 83/01/12 KAHMERER, C Office of Public Affairs 2pp 17112 269

B302100442 Comments on proposed rule 10CFR50 re incorporation by ref of Summer 1982 addenda of ASME Code to 10CFR50 Objects to certification of Level III personnel Test does not verify ability to perform tasks
GAMBLE, O C Conam Inspection 47FR57054 001 83/01/25 Docketing & Services Branch 1p 17117 195

B302100443 Clarifies B30119 comments on proposed rule 10CFR170 re license fees Costs associated w/resident insp program should be shared among licensees & public Program should not be included as insp for which fees will be assessed
GIESLER, C W Wisconsin Public Service Corp 47FR52454 120 83/01/24 Docketing & Services Branch 1p 17117 042

B302100445 Responds to B30114 ltr re constituent S Nussbaum B21222 ltr commenting on proposed rule 10CFR170 concerning revising fees for applications, renewals, amends & licenses Proposed fees necessary to recover costs involved in review process
KAHMERER, C Office of Congressional Affairs 47FR52454 83/01/28 DIXON, A J Senate 2pp 17117 037

--B302100453 Forwards, for response, constituent S Nussbaum B21222 ltr commenting on proposed rule 10CFR170 revising fees for applications, renewals, amends & licenses
DIXON, A J Senate 47FR52454 83/01/14 NRC - No Detailed Affiliation Given 1p 17117 039

--B302100458 Comments on proposed rule 10CFR170 re revised fees for applications, renewals, amends & licenses Opposes rule
NUSSBAUM, S Victory Memorial Hosp , Waukegan, IL 47FR52454 82/12/22 Docketing & Services Branch 2pp 17117 040

B302100448 Responds to B30117 inquiry re constituent ltr commenting on proposed rule 10CFR170 re proposed schedule of revised fees for applications & licenses Revised fees intended to recover costs of issuing, renewing or amending NRC license
KAHMERER, C Office of Congressional Affairs 47FR52454 83/01/28 LUOAR, R O Senate 2pp 17117 043

--B302100449 Requests comments on encl constituent RW Hahn B30103 comments on proposed rule 10CFR170 re increases in fees for nuclear medicine licenses
LUOAR, R O Senate 47FR52454 83/01/17 KAHMERER, C Office of Congressional Affairs 2pp 17117 045

B302100450 Package of 11 comments on proposed rule 10CFR170 re proposed rev to license fee schedule
SHEA, K H Lowenstein, Newman, Reis, Axelrad & Toll THOMSEN, F T Perkins, Cole, Stone, Olsen & Williams HAWES, P S Affiliation Unknown 47FR52424 83/01/18 CHILK, S J Docketing & Services Branch 47pp 17117 104

B302100451 Package of two comments on proposed rule 10CFR170 re fee increases for applications, renewals & amends Addl info needed for clarification of increases
MICHEL, R H House of Rep CORDANI, R A Babcock & Wilcox Co 47FR52454 83/01/28 KAHMERER, C Office of Congressional Affairs 3pp 17117 025

B302100455 Forwards comment protesting proposed rule 10CFR170 re increase in license application fee schedule Response requested
DIXON, A J Senate 47FR52454 012 83/01/14 NRC - No Detailed Affiliation Given 1p 17117 197

--B302100457 Comments on proposed rule 10CFR170 re fee increase for applications & amends Opposes rule
OPP, P F Community Hosp of Ottawa, IL 47FR52454 012 82/12/1 Docketing & Services Branch 2pp 17117 198

B302100460 Comments on proposed rules 10CFR19.21, 30, 40, 50, 70, 71, 73 & 110 re copying of records & retention periods for security records Opposes rule
KIND, R E Square D Co , Electromagnetic Industries 47FR52454 01 83/01/20 Docketing & Services Branch 3pp 17112 251

B302100464 Package of ten comments opposing proposed rule 10CFR170 re proposed rev of license fee schedule
BCHREINER, K V St Francis Hosp Evanston, IL THOMAS, E L Air Transport Association CATCHPOLE, O J Ogle Petroleum, Inc 47FR52454 83/01/17 Docketing & Services Branch 22pp 17112 224

NONDOCKETED ITEMS

8302100465 Requests comments on two protests to proposed rule 10CFR170 re fee increases for applications, renewals, amends & insps
LUGAR, R G Senate 47FR52454 83/01/17 KAMMERER, C Office of Public Affairs 3pp 17112 248

8302100467 Ack receipt of 821203 ltr re potential economic impact of proposed rule 10CFR20 on stds for protection against radiation ALARA & implementation costs discussed
MILLS, W A Health Effects Branch 45FR18023 075 83/01/12
BURDINE, J A Society of Nuclear Medicine 3pp 17112 220

--8302100470 Preliminary comments re rev to proposed rule 10CFR20 on stds against radiation Concern associated w/economic impact of changes expressed
BURDINE, J A Society of Nuclear Medicine 45FR18023 82/12/03 Docketing & Services Branch 1p 17112 223

8302100472 Ack receipt of 821123 comments re rev of 10CFR20 on stds for protection against radiation Comments will be incorporated into rev
MILLS, W A Health Effects Branch 45FR18023 074 83/01/25
SINCLAIR, W K National Council on Radiation Protection & Measurements 2pp 17112 246

8302140105 Package of two comments on proposed rule 10CFR170 re rev of license fee schedules
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 47FR52454 83/02/07 Docketing & Services Branch 6pp 17141 090

8302140107 Comments on proposed rule 10CFR170 re rev of license fee schedules Proposed regulations will have severe adverse impacts on existing & future licensing activities.
SZALAY, R Atomic Industrial Forum 47FR52454 132 83/02/08 Docketing & Services Branch 3pp 17142 098

8302140111 Comments on proposed rule 10CFR170 re rev of license fee schedules Retention of present fee ceilings recommended
KEARNEY, J J Edison Electric Institute 47FR52454 131 83/02/08 Docketing & Services Branch 17pp 17142 081

8302140125 Comments on proposed rule 10CFR60 re technical criteria for disposal of high level radwaste in geologic repositories Opposes rule
MUNTZING, L M American Nuclear Society 46FR35280 093 83/01/24
PALLADINO, N J Commissioners 14pp 17140 112

8302140128 Comments on proposed rules 10CFR19.21, 30, 40, 50, 70, 71, 73 & 110 re authority to copy licensee records Opposes rules
CHUR, Y L Vet Admin Hosp Iowa City, IA 47FR52452 023 83/02/07 Docketing & Services Branch 1p 17141 222

8302140206 Comments on proposed rule 10CFR70 re amended matl control & accounting requirements for SNM of low strategic significance Supports rule
NIBSON, R Exxon Nuclear Co, Inc (subs of Exxon Corp) 47FR55951 005 83/02/04 Docketing & Services Branch 2pp 17140 059

8302150027 Comments on proposed rule 10CFR50 & NUREG-0906, "Guidance for Implementation of 10CFR50 34(g)" NUREG vague on what info in SAR required to be evaluated against SRP
WODLEVER, E J Duquesne Light Co 47FR47019 010 83/02/02 Docketing & Services Branch 2pp 17148 055

8302200022 Discusses proposed revs to STS & preparation of final rule change to 10CFR50 36 Procedures for processing change revised for issuance of Rev 1 to OFC Ltr 38 Replacement for STS section leader recommended
MIRAGLIA, F J Assistant Director for Safety Assessment 83/02/08
EISENHUT, D O Division of Licensing 2pp 17227 352

8302250021 Comments on proposed rule 10CFR170 re rev of licensee fee schedules Changes should not be effective earlier than 840101, to provide adequate time for licensees to estimate & adjust increases
D'OTOLE, J D Consolidated Edison Co of New York, Inc 47FR52454 134 83/02/08 CHILK, S J Office of the Secretary of the Commission 1p 17291 001

8302250022 Package of two comments opposing proposed rule 10CFR170 re rev of license fee schedules
PATRISON, R S Rio Algom Ltd HARRINGTON, W D Boston Edison Co 47FR52454 83/02/18 Docketing & Services Branch 3pp 17291 053

8302250023 Comments on proposed rules 10CFR19.21, 30, 40, 50, 70, 71, 73 & 110 re authority to copy licensee records Opposes rule.
TAYLOR, J H Babcock & Wilcox Co 47FR52452 024 83/02/10 Docketing & Services Branch 2pp 17291 093

8302250028 Responds to 830128 inquiry re J Meunier comments opposing proposed rule 10CFR170 re increase in fees for nuclear medicine licenses
KAMMERER, C Office of Congressional Affairs 47FR52454 059 83/02/02 PROXMIER, B Senate 3pp 17291 110

--8302250031 Forwards J Meunier 821122 comments opposing proposed rule 10CFR170 re increase in fees for nuclear medicine licenses
MEUNIER, J Senate 47FR52454 83/01/10 Docketing & Services Branch 1p 17291 113

8302250031 Forwards RW Hann 830103 comments opposing proposed rule 10CFR170 re increase in fees for nuclear medicine licenses
QUAYLE, D Senate 47FR52454 135 83/02/08 KAMMERER, C Office of Congressional Affairs 2pp 17297 283

8302250033 Forwards revised comments on proposed rule 10CFR170 re rev of license fee schedules
HARTON, J P Cofar, Beauchamp, Hawes & Brown 47FR52454 078 83/02/08 HOYLE, J C Office of the Secretary of the Commission 1p 17291 078

--8302250037 Comments on proposed rule 10CFR170 re rev of license fee schedules Opposes rule
HARROLD, T J Cofar, Beauchamp, Hawes & Brown 47FR52454 078, 83/02/08 HOYLE, J C Office of the Secretary of the Commission 6pp 17291 079

8302250036 Package of three ltrs supporting proposed rule 10CFR70 re amended matl control & accounting requirements for SNM
LICHTENBERGER Combustion Engineering, Inc VAUGHAN, C M General Electric Co SDRENSON, R J Institute of Nuclear Materials Management 47FR55951 83/02/15 Docketing & Services Branch 9pp 17291 116

8302250039 Responds to 830203 inquiry re constituent J Murray comments on proposed rules 10CFR30, 32, 70 & 150 re smelted alloys containing residual contamination of certain radioactive matl
KAMMERER, C Office of Congressional Affairs 45FR70874 3684 83/02/09 EAULETON, T F Senate 2pp 17291 085

--8302250032 Forwards J Murray comments opposing use of radioactive metal in consumer products
EAULETON, T F Senate 45FR70874 83/02/03 Office of Congressional Affairs 2pp 17291 087

8302250033 Comments on proposed rule 10CFR170 re rev of license fee schedules Opposes rule
VANDEWALLE, D J Consumers Power Co 47FR52454 136 83/02/09 Docketing & Services Branch 2pp 17291 172

8302250035 Comments on proposed rule 10CFR70 re amended matl control & accounting requirements for SNM of low strategic significance Supports rule
NARDI, A J Westinghouse Electric Corp 47FR55951 009 83/02/14 Docketing & Services Branch 2pp 17291 146

8302250036 Responds to 830127 ltr advising of support for requiring licensees to use natl voluntary lab accreditation program personnel dosimetry svcs
HINSOUE, R B Office of Nuclear Regulatory Research, Director, 45FR20493 079 83/02/15 SHEALY, H O Conference of Radiation Control Program Directors, Inc 1p 17291 174

--8302250038 Recommends all states adopt regulations requiring licensees to use natl voluntary lab accreditation program personnel dosimetry svcs
SHEALY, H O Conference of Radiation Control Program Directors, Inc 45FR20493 079 83/01/27 PALLADINO, N Commissioners 2pp 17291 175

PRM PETITION FOR RULEMAKING

8302070047 Responds to 821013 memo re re-exam of U mill tailings regulations Div of Fuel Cycle & Matl Safety assigned lead responsibility for task Working group appointed to review regulations & consider change options
DIRCKS, W J Office of the Executive Director for Operations 82/12/20 PALLADINO, N Commissioners 6pp 17065 300

8302100256 Comments on UCS petition for rulemaking PRM-50-35 re emergency planning Hearings should not be closed & no final determination made until provision made for implementation & exercise of plan.
PEVEAR, R C New Hampshire, State of 47FR51889 067, 83/01/15 Docketing & Services Branch 1p 17110 189

NONDOCKETED ITEMS

437

8302100264 Comments on behalf of LILCO on UCS petition for rulemaking PRM-50-35 re emergency planning Opposes rule
CHRISTMAN, J N Hunton & Williams 47FR51889 068 83/01/17
Docketing & Services Branch 7pp 17110 124

8302100272 Comments on UCS petition for rulemaking PRM-50-35 re amend of 10CFR50.47 concerning public litigation rights in offsite emergency plans Rulemaking should be denied since provisions already exist for adjudicatory hearings
FAY, C W Wisconsin Electric Power Co 47FR51889 069 83/01/18
Docketing & Services Branch 2pp 17110 119

8302100294 Package of two comments opposing UCS petition for rulemaking PRM-50-35 re amend of rule on emergency planning
SHOTWELL, J A Massachusetts, Commonwealth of, MCLAUGHLIN, D.
Federal Emergency Management Agency 47FR51889 83/01/27
Docketing & Services Branch 16pp 17117 089

8302100305 Package of two comments opposing UCS petition for rulemaking PRM-50-35 re litigation of emergency planning issues
REYNOLDS, N B Debevoise & Liberman PATTERSON, J D Middle South
Services, Inc 47FR51889 83/01/19 Docketing & Services Branch
11pp 17111 331

8302100306 Package of two comments supporting UCS petition for rulemaking PRM-50-35 re emergency planning issues
SEELY, B Concerned Citizens of Rhode Island DRAKE, M Affiliation
Unknown, 47FR51889 83/01/19 Docketing & Services Branch 2pp
17116 326

8302100339 Comments on petition for rulemaking PRM-50-34 re App E concerning frequency of local participation in full-scale exercises to be compatible w/state participation Supports petition
TIERNAN, J A Baltimore Gas & Electric Co 47FR50918 010 83/01/13
Docketing & Services Branch 1p 17116 320

8302100341 Requests 1 wk extension for filing comments on UCS petition for rulemaking PRM-50-35 re emergency planning
CURRAN, D, Harmon & Weiss 47FR51889 83/01/17 STUCKY, B
Docketing & Services Branch 1p 17112 062

8302100349 Package of two comments supporting UCS petition for rulemaking PRM-50-35 re amend of rule on emergency planning.
CLEWETT, J Critical Mass Energy Project WEISS, E R, CURRAN, D
Union of Concerned Scientists 47FR51889 83/01/25 Office of
the Secretary of the Commission 21pp 17112 022

8302100353 Comments on behalf of FL Power & Light & IA Electric Light & Power Co on petitions for rulemaking PRM-50-32, PRM-50-32A & PRM-50-32B re electromagnetic pulse Petitions should be rejected because no basis presented for requested relief
BAUSER, M A Lowenstein, Neuman, Reis, Axelsrad & Toll 47FR27371 022
83/01/21 Docketing & Services Branch 4pp 17116 259

8302100355 Forwards comments on behalf of Kerr-McOee re Union Carbide petition for rulemaking PRM-40-24 on radon flux std
MONTAGNE, C H Covington & Burling 47FR33889 005 83/02/02
Docketing & Services Branch 1p 17109 001

8302100358 Comments on Union Carbide petition for rulemaking PRM-40-24 re radon flux std Supports petition
SHELLEY, W J Kerr-McOee Corp 47FR53889 83/01/27 Docketing
& Services Branch 352pp 17109 003

8302100357 Package of two comments supporting UCS petition for rulemaking PRM-50-35 re emergency planning participation
SKIBNIEWSKY, B Affiliation Unknown HOLY, J Public Interest
Research Group, New York 47FR51889 83/01/20 CHILK, S J Office
of the Secretary of the Commission 4pp. 17116 252

8302100361 Notice of receipt of petitions for rulemaking PRM-50-32A & PRM-50-32B from MI Lewis & Mapleton intervenors re issue of electromagnetic pulse
HOYLE, J C Office of the Secretary of the Commission 47FR53030
82/11/17 5pp 17110 101

8302100366 Comments on petitions for rulemaking PRM-50-32A & PRM-50-32B re electromagnetic pulse Electromagnetic pulse (EMP) shielding impractical because auxiliary power supply tied to electric grid upon which EMP would pour in.
TERMINI, R P Affiliation Unknown 47FR53030 001. 83/01/13
Office of the Secretary of the Commission 1p. 17116 196

8302100373 Comments on petitions for rulemaking PRM-50-32A & PRM-50-32B re electromagnetic pulse Petitions should be rejected since electromagnetic pulse phenomenon is not understood well enough to determine affect on control sys of power plant
BRADBURY, R B Stone & Webster Engineering Corp 47FR33030 003
83/01/24 Docketing & Services Branch 2pp. 17110 095

8302100380 Package of five comments opposing UCS petition for rulemaking PRM-50-35 re emergency planning proceedings
SCHUKAI, R J Union Electric Co CRANE, P A Pacific Gas & Electric
Co MILLS, L M Tennessee Valley Authority 47FR51889 83/01/20
CHILK, S J Docketing & Services Branch 11pp 17117 047

8302100387 Comments on UCS petition for rulemaking PRM-50-35 re emergency planning proceedings Supports rule.
SIDEROTHAN, D P New England Coalition on Nuclear Pollution
47FR51889 052 83/01/17 Docketing & Services Branch 1p
17117 009

8302100401 Comments on petition for rulemaking PRM-40-24 re U mill tailings regulations Supports petition & forwards supportive affidavit
BOGGS, L A American Mining Congress 47FR53889 003 83/01/31
CHILK, S J Office of the Secretary of the Commission 10pp
17111 284

8302100408 Affidavit of L Hamilton re health effects of radon releases from U mining & milling Contends that Rn-222 releases have negligible health effects
HAMILTON, L D Commissioners 47FR53889 003 83/01/31 22pp
17111 299

8302100406 Package of two comments on UCS petition for rulemaking PRM-50-35 re emergency preparedness & planning Petition should be denied
HELFRICH, R E Yankee Atomic Electric Co COWAN, B Z Atomic
Industrial Forum 47FR51889 83/01/18 Docketing & Services
Branch 4pp 17117 191

8302100413 Comments on petition for rulemaking PRM-34-3 concerning storage of radiation exposure devices Supports petition
KOVACS, B Foster Wheeler Corp 47FR52722 002 83/01/12
Docketing & Services Branch 1p 17117 017

8302100419 Comments on Union Carbide petition for rulemaking PRM-40-24 re lower criteria for long-term stabilization of U mill tailings Opposes petition
PARSONS, C Affiliation Unknown 47FR53889 001 83/01/24 NRC -
No Detailed Affiliation Given 1p 17112 066

8302100426 Forwards correction to 830110 comments re State of SC petition for rulemaking PRM-50-34 Name of AL Power & Light Co corrected to AL Power Co
ZAHLER, R E Shaw, Pittman, Potts & Trowbridge, ZAHLER, R E Alabama
Power Co 47FR50918 83/01/20 Docketing & Services Branch 1p
17112 088

8302100428 Comments on petition for rulemaking PRM-34-3 re safe storage of radiographic exposure devices Suggests rev of petition.
BRADBURY, R B Stone & Webster Engineering Corp 47FR52722 003
83/01/24 Docketing & Services Branch 1p 17117 260

8302100433 Comments on petition for rulemaking PRM-50-32, 32A & 32B re electromagnetic pulse radiation at nuclear power plants.
Opposes petition
HIATT, S L Affiliation Unknown 47FR27371 023 83/01/22
Docketing & Services Branch 4pp 17117 155

8302100440 Package of three comments on Union Carbide petition for rulemaking PRM-40-24 re Criteria 1, 5, & 10 of App A to 10CFR40 concerning operation of U mills & tailings Requests extension of comment period
YEAGER, B B Sierra Club PERRY, W Wyoming, State of BERICK, D M
Environmental Policy Institute 47FR53889. 83/01/31 Docketing &
Services Branch 8pp 17117 159

8302100446 Comments on petition for rulemaking PRM-34-3 re radiation surveys of radiographic exposure devices Storage survey method Proposed rewrite should be revised as submitted
LANIER, N P Mettels, Inc 47FR52722 004 83/01/26 Docketing &
Services Branch 2pp 17117 005

8302100452 Comments on petition for rulemaking PRM-40-24 re U mill tailings regulations Amend self-serving & w/o merit
YOUNG, R Sierra Club 47FR53889 006. 83/01/30 Office of the
Secretary of the Commission 1p 17117 204.

8302100454 Comments on petition for rulemaking PRM-40-24 re U mill tailings & disposal Opposes petition
WELLS, P L, NELSON, T L Environmental Defense Fund 47FR53889 004
83/01/28 Docketing & Services Branch 4pp. 17117 200

8302100456 Package of two comments supporting UCS petition for rulemaking PRM-50-35 re emergency planning
FRISCO, D C Coalition for Nuclear Power Plant Postponement
QUIRO, C Pollution & Environmental Problems, Inc. 47FR51889
83/01/17 Docketing & Services Branch. 9pp 17117 028

NONDOCKETED ITEMS

8302100463 Comments on petitions for rulemaking PRM-50-32A & 32B re DL requirement to provide design features to protect against effects of electromagnetic pulse Opposes petition
CURTIS, N W Pennsylvania Power & Light Co 47FR53030 005
83/01/24 Docketing & Services Branch 1p 17112 219

8302140085 Comments on petitions for rulemaking PRM-50-32, PRM-50-32A & PRM-50-32B re electromagnetic pulse Opposes petition
EDWARDS, D W Yankee Atomic Electric Co 47FR27371 024 83/01/28
Docketing & Services Branch 2pp 17142 104

8302140211 Comments on petition for rulemaking PRM-50-35 re implementation of evacuation plans Supports petition
CAMPBELL, S E Smississippi Alliance for the Environment (SAFE)
47FR51889 078 83/02/01 Office of the Secretary of the Commission 1p 17140 064

8302250163 Forwards D Tolbert 820423 comments on petition for rulemaking PRM-35-2, "Guide for Preparation of Applications for Licenses in Medical Teletherapy Programs," (Task TM 408-4)
VACCA, P C Division of Fuel Cycle & Material Safety 47FR4311 019
83/02/09 STUCKY, S W Docketing & Services Branch 1p 17293 344

8302250369 Requests 45-day extension to comment period on Union Carbide Corp petition for rulemaking PRM-40-24 re revs of NRC 801003 U mill licensing regulations
SHUEY, C Southwest Research and Information Center 47FR53889
83/01/31 Docketing & Services Branch 2pp 17291 114

8302250373 Rulemaking 40-24, "Union Carbide Corp. Petition for Rulemaking, Extension of Comment Period " Comment period extended to 830502
CHILK, S J Office of the Secretary of the Commission 47FR53889
83/02/17 2pp 17297 212

PROJ PROJECTS - PREDOCKET LICENSING

8302020247 Exceptions to ASLB 830119 Memorandum & Order granting Util mention to withdraw application for CP Certificate of Svc encl
ADRAGNA, J K Northern California Power Agency, California, State of, ISSUANCES A 83/01/31 Commissioners 8pp 16994 330

8302030256 Discusses Westinghouse proposed modular approach to constructing SAR documents in conjunction w/Westinghouse Advanced PWR licensing control document Modular approach believed to be efficient licensing process
RAHE, E P Westinghouse Electric Corp. NS-EPR-2712 83/01/31
EISENHUT, D G Division of Licensing 2pp 17001 248

8302030339 Forwards schedule developed by Westinghouse to implement submittal of extensive PRA of Westinghouse Advanced PWR (WAPWR) Nonproprietary slides presented at 821222 initial meeting re WAPWR PRA encl
RAHE, E P Westinghouse Electric Corp NS-EPR-2711 83/01/31
EISENHUT, D G Division of Licensing 17pp. 17006 110

8302030507 Informs that proprietary info contained in QNS, Topical SAR for Castor Type ISFSI, " submitted in May 1982, has been destroyed per LLL procedures
SCHWARTZ, M W Lawrence Livermore Laboratory. 21822 83/01/11
ROBERTS, J P Division of Fuel Cycle & Material Safety 1p 17013 335

8302040131 Presents overview of Westinghouse Advanced PWR Project Westinghouse intends to submit preliminary design info during current prebidding phase
MEYER, O C Standardization & Special Projects Branch 83/01/26
Standardization & Special Projects Branch 33pp 17043 128

8302040439 Forwards revised page to Section 06 2, "Control of Design," of GA plan
RICE, H K Ridihalgh, Eggers & Associates 21802 83/01/03
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p 17042 321

--8302040443 Revised page to Section 06 2, "Control of Design," of GA plan
ADAMS, J E Ridihalgh, Eggers & Associates. 21802 82/10/18
2pp 17042 322

8302090176 Responds to 830105 ltr. Revised P 1 of Section 0642, "Control of Design," of App A of GA plan for design & fabrication of REA 2023 dry storage casks for spent fuel will be reviewed
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch. 83/01/20
RICE, H K Ridihalgh, Eggers & Associates, 1p. 17132-104

8302170414 Notification of 830209 meeting w/Gesellschaft Fuer Nuklear Svc in Silver Spring, MD to discuss topical repts for Castor IE & Castor V Dry Cask ISFSI
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/02/09
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 17195 241

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8302010459 Part 21 rept re defect in radiation monitor supplied to encl list of facilities initially reported on 830124 Customers notified of condition Corrective action will be determined by field tests during wk ending 830131
DEAN, R A QA Technologies, Inc /General Atomic Co 83/01/27
DEVUNO, R C Director's Office, Office of Inspection and Enforcement 10pp 16981 001

8302030080 Part 21 rept re possible defect in hydrogen ignitors, Model 6042 Since original design & qualification, manufacturer changed sealing procedure from brazing to hot rolled compression fit Plugs to be replaced
CAKE, M P Morrison-Knudsen Co, Inc 83/01/28 O'REILLY, J P Region 2, Office of Director 2pp 17002 092

8302070204 Advises that insp of Farr Co not warranted unless safety significant deficiency identified Vendor identified, retested & replaced all affected filters Item closed
POTAPOVS, U Division of Vendor & Technical Programs AITS
H06000481 83/02/01 BAER, R L Engineering & Technical Support Branch 1p 17031 309

8302070294 Informs that review of applicable util potential conceptual design requirement & associated documentation indicates that safety hazard did not exist as filters tested upon field installation Facility insp not warranted
POTAPOVS, U Division of Vendor & Technical Programs AITS
F02500123 83/02/01 LEWIS, R C Division of Project & Resident Programs 1p 17029 095

8302070489 Potential Part 21 rept re defect on Rockbestos triaxial cable RSS-4-108 Initially reported on 830121 Test data indicates cables will meet LOCA requirements of IEEE 383-1974
MASSEY, W F, UNDERWOOD, R H Westinghouse Electric Corp 83/01/28
Region 4, Office of Director 11pp 17039 028

8302070603 Advises that 1/4-inch thick strut fittings, mfg by B-Line Sys, Inc, not defective based on Vendor Program Branch contact w/manufacture & review of 10CFR21 rept Action Item Tracking Sys H07003385 closed out
POTAPOVS, U Division of Vendor & Technical Programs 83/02/01
MILLS, W R Events Analysis Branch 1p 17034 279.

8302090385 Part 21 rept re post-LOCA hydrogen recombiner component determined likely to fail following exposure to elevated temp, high humidity environ Timer will be replaced w/sealed timer List of affected plants encl
EMPEY, D C Rockwell International Corp 82/12/17 COLLINS, J
Region 4, Office of Director 4pp 17047 128

QA999 QUALITY ASSURANCE INSPECTIONS

8302010455 Ack receipt of 830104 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900365/82-01
POTAPOVS, U Division of Vendor & Technical Programs 83/01/26.
HEARS, L N Van Huffel Tube Corp 1p 16981 028

--8302010460 Responds to NRC 821208 ltr re nonconformance noted in QA Program Insp Rept 99900365/82-01 Corrective actions illegible Argon gas flow meter removed from svc & replaced w/new unit Welder qualification test records revised.
HEARS, L N Van Huffel Tube Corp 83/01/04 POTAPOVS, U Division of Vendor & Technical Programs 3pp 16981 027

8302010509 Forwards QA Program Insp Rept 99900792/82-01 on 821018-22 & notice of nonconformance
POTAPOVS, U Division of Vendor & Technical Programs. 83/01/10
HARRINGTON, O W Greenville Metal Manufacturing, Inc 2pp 16978-068

--8302010518 Notice of nonconformance from insp on 821018-22
* Division of Vendor & Technical Programs 83/01/10 1p 16978 070.

NONDOCKETED ITEMS

4

--8302010527 QA Program Insp Rept 99900792/B2-01 on 821018-22
Noncompliance noted no documented evidence that subvender,
National Insp & Consultants, performed ultrasonic exam of
welds w/induced shear wave 40 to 75 degrees
KELLEY, W D , BARNES, I Division of Vendor & Technical Programs
83/01/04 9pp 16978 071

8302030337 Confirms QA program 830418-22 insp at Richmond, VA plant per
830125 telcon
POTAPQVS, U Division of Vendor & Technical Programs 83/01/31
LOUTHAN, F O Richmond Engineering Co , Inc ip 17006 127

8302030377 Confirms QA Program insp on 830207-11 at East Farmington, NY
plant per 830131 telcon NRC inspector will be WD Kelley &
insp will relate to implementation of QA program
POTAPQVS, U Division of Resident, Reactor Project & Engineering
Programs 83/01/31 PATTARINI, D M Target Rock Corp ip
17005 350

8302030415 Ack receipt of 820920, 1007 & 1129 ltrs informing NRC of
steps taken to correct nonconformance noted in QA Program
Insp Rept 99900116/B2-01
POTAPQVS, U Division of Vendor & Technical Programs 83/01/31
GROLLE, O L Bunker Ramo-Eltra Corp ip 17008 189

--8302030423 Forwards FC Casillas 821129 response to NRC 820908 ltr re
nonconformance noted in QA Program Insp Rept 99900116/B2-01
GROLLE, O L Bunker Ramo-Eltra Corp 82/11/29 POTAPQVS, U
Division of Vendor & Technical Programs ip 17008 190

--8302030431 Responds to NRC 820908 ltr re nonconformance noted in QA
Program Insp Rept 99900116/B2-01 Corrective actions
Chatsworth facility closed, electrical penetration assemblies
no longer mfg & customer svc provided by ANCO Engineers, Inc
CABILLAS, F C Bunker Ramo-Eltra Corp. 82/11/29 Region 4,
Office of Director. 3pp 17008 191

--8302030435 Confirms 821104 meeting w/NRC in Arlington, TX to discuss QA
Program Insp Rept 99900116/B2-01 Response to notice of
violation extended past 821029
GROLLE, O L Bunker Ramo-Eltra Corp. 82/10/28 POTAPQVS, U
Division of Vendor & Technical Programs ip 17008 194

--8302030444 Proposes to file written statement by 821029 in response to
NRC 820908 notice of violation re QA Program Insp Rept
99900116/B2-01
GROLLE, O L Bunker Ramo-Eltra Corp. 82/10/07 POTAPQVS, U
Division of Vendor & Technical Programs ip 17008 195

--8302030452 Proposes to file application by 821029 for withholding info
in NRC 820908 ltr & associated QA Program Insp Rept
99900116/B2-01
GROLLE, O L Bunker Ramo-Eltra Corp. 82/09/20 POTAPQVS, U
Division of Vendor & Technical Programs ip 17008 196

8302030471 Ack receipt of 830117 ltr informing NRC of steps taken to
correct deviation noted in QA Program Insp Rept
99900364/B2-01 Corrective actions appropriate &
satisfactorily resolve item.
POTAPQVS, U Division of Vendor & Technical Programs. 83/01/31,
KRIDBLE, A M Midland-Ross Corp ip 17006 149

--8302030478 Responds to NRC 830107 & 11 ltrs re deviation noted in QA
Program Insp Rept 99900364/B2-01 Corrective actions signs
re commercial grade items posted
KRIDBLE, A M Midland-Ross Corp. 83/01/17. POTAPQVS, U Division
of Vendor & Technical Programs 2pp 17006 150

8302030479 Ack receipt of 830117 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900266/B2-02.
POTAPQVS, U Division of Vendor & Technical Programs 83/01/31
EMPEY, D Rockwell International Corp ip 17006 145

--8302030489 Responds to NRC 821217 ltr re nonconformance noted in QA
Program Insp Rept 99900266/B2-02. Corrective actions meetings
held w/quality engineer staff to stress importance of
properly reviewing purchase orders.
EMPEY, D, C Rockwell International Corp. 83E80487. 83/01/17.
POTAPQVS, U Division of Vendor & Technical Programs. 3pp.
17006:146.

8302030480 Forwards QA Program Insp Rept 99900791/B2-01 on 820907-10
& notice of violation & notice of nonconformance,
POTAPQVS, U. Division of Vendor & Technical Programs 82/11/18
CANUP, J D. Bahnsen Co., Inc. (subs of Hillmen Coal & Coke Co)
2pp 17008:133

--8302030485 Notice of violation from insp on 820907-10
* Region 4, Office of Director 82/11/18 2pp 17008 135

--8302030492 Notice of nonconformance from insp on 820907-10
* Region 4, Office of Director 82/11/18 ip 17008 137

--8302030507 QA Program Insp Rept 99900791/B2-01 on 820907-10
Noncompliance noted failure to provide procedures for
evaluating deviations & QA program did not provide control
necessary to assure proper processing, insp & testing
SUTTON, J W , BARNES, I Division of Resident, Reactor Project &
Engineering Programs 82/11/08 9pp 17008 138

8302030483 Forwards QA Program Insp Rept 99900116/B2-01 on 820503-07
& notice of violation
POTAPQVS, U Division of Vendor & Technical Programs 82/09/08
NELLOTTE, A Bunker Ramo-Eltra Corp 2pp 17007 321

--8302030488 Notice of violation from insp on 820503-07
* Division of Vendor & Technical Programs 82/09/08 2pp
17007 323

--8302030504 QA Program Insp Rept 99900116/B2-01 on 820503-07
Noncompliance noted failure to evaluate deviations
identified in electrical penetration assemblies & to include
number & location of all components in Part 21 rept
AQEE, J R , PHILLIPS, H S Division of Vendor & Technical Programs
82/07/14 22pp 17007 325

8302030509 Confirms 830207-11 insp of QA program, per 830121 telcon
POTAPQVS, U Division of Vendor & Technical Programs 83/01/31
KOHES, J M Bechtel Corp ip 17007 174

8302030538 Ack receipt of 821008 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900396/B2-01
POTAPQVS, U Division of Vendor & Technical Programs 83/01/31
SESHAQIRI, M L CLOW Corp ip 17006 303

--8302030544 Responds to NRC 821118 ltr re nonconformance noted in QA
Program Insp Rept 99900396/B2-01 Corrective actions monthly
log or calendar listing all gauges to be calibr maintained
KELLEY, H CLOW Corp 83/01/20 POTAPQVS, U Division of Vendor
Technical Programs ip 17006 304

--8302030548 Ack receipt of 821008 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900396/B2-01 Addl info re instrument measuring &
preventive measures needed
POTAPQVS, U Division of Vendor & Technical Programs 82/11/18
SESHAQIRI, M L CLOW Corp ip 17006 305

--8302030556 Responds to NRC 820816 ltr re nonconformance noted in QA
Program Insp Rept 99900396/B2-01 Corrective actions
measuring equipment calibr on 820719 & documented
SESHAQIRI, M L CLOW Corp 82/10/08 SUTTON, J W Region 4,
Office of Director ip 17006 306

8302070257 Forwards QA Program Insp Rept 99900736/B2-01 on 821115-19
& notice of nonconformance
POTAPQVS, U Division of Vendor & Technical Programs 83/01/18
TAKEUCHI, J D NPS Industries, Inc 2pp 17031 340

--8302070260 Notice of nonconformance from insp on 821115-19
* Division of Vendor & Technical Programs 83/01/18 2pp
17031 342

--8302070265 QA Program Insp Rept 99900736/B2-01 on 821115-19
Noncompliance noted QA release form for Shipment 4 missing,
F number not recorded on performance qualification records &
inspector failed to sign data sheet
COKHAY, J T , BARNES, I Division of Vendor & Technical Programs
83/01/17 7pp 17031 344

8302070263 Forwards QA Program Insp Rept 99900235/B2-01 on 821115-18
No noncompliance noted
POTAPQVS, U Division of Vendor & Technical Programs 83/01/18
FRISCD, L J Raychem Corp 2pp 17031:356

--8302070266 QA Program Insp Rept 99900235/B2-01 on 821115-18 No
noncompliance noted Major areas inspected, ascertain whether
appropriate records had been maintained which would allow
verification of potentially defective electrical cable
ROBERTS, H W , VILLALVA, I , BARNES, I Division of Vendor &
Technical Programs 83/01/13 4pp 17031 358

8302070280 Advises that IE 821115-18 insp finding re Borg-Warner supp
of valves for inside containment svc w/unqualified motor
operators isolated case
SUTTON, J W Division of Vendor & Technical Programs VITS 82-285
83/02/01 BARNES, I Division of Vendor & Technical Programs ip
17031 149

NONDOCKETED ITEMS

8302070286 Informs that util failed to provide clarification re self-cleaning filter deficiencies identified in QA Program Insp Rept 99900752/81-01 ERCW sys modified to compensate for excessive pressure drop across filters Items closed
 POTAPOVS,U Division of Vendor & Technical Programs AITS
 FOZ200316 83/02/01 LEWIS,R C Division of Project & Resident Programs Ip 17029 179

8302070302 Forwards QA Program Insp Rept 99900005/82-02 on 821116-18 & notice of nonconformance
 POTAPOVS,U Division of Vendor & Technical Programs 83/01/18
 JACOBI,W M Westinghouse Electric Corp 2pp 17029 113

8302070304 Notice of nonconformance from insp on 821116-18
 * Division of Vendor & Technical Programs 83/01/18 2pp
 17029 115

8302070307 GA Program Insp Rept 99900005/82-02 on 821116-18
 Noncompliance noted no evidence of submittal & approval by purchaser of procedures for outside & inside surface finish process, chemical composition testing & tensile testing.
 MCNEILL,W M , BARNES,I Division of Vendor & Technical Programs
 83/01/13 7pp 17029 117

8302070320 Forwards QA Program Insp Rept 99900289/82-03 on 821115-18 & notice of nonconformance
 POTAPOVS,U Division of Vendor & Technical Programs 83/01/18
 TESTHUIDE,R R Borg-Warner Corp 2pp 17029 143

8302070322 Notice of nonconformance from insp on 821115-18
 * Division of Vendor & Technical Programs. 83/01/18 Ip
 17029 145

8302070327 GA Program Insp Rept 99900289/82-03 on 821115-18
 Noncompliance noted source control drawings for six 4-inch gate valves completed & sent to procurement & QC w/o being checked by design engineering manager
 SUTTON,J W , BARNES,I Division of Vendor & Technical Programs
 83/01/12 11pp 17029 146

8302070476 Confirms 830228-0304 GA program insp at plant, per 830125 telcon Insp relates to short circuit bracing of vertical lift metal-clad switchgear & QA program implementation
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/02
 GREENE,R General Electric Co Ip 17034 064

8302070588 Confirms QA program insp to be conducted on 830214-18, per 830126 telcon Insp will relate to review of QA records pertaining to fabrication of Indian Point Unit 3 steam generators
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/01
 SLEMBER,R J Westinghouse Electric Corp Ip 17034 264

8302070597 Suppls 821218 response to NRC ltr re nonconformance noted in QA Program Insp Rept 99900346/82-01 Corrective actions QA manual chief inspector functions deleted & authority & responsibility statement clarified
 FRANCOIS,E I Velan Valve Co 83/01/24 POTAPOVS,U Division of Vendor & Technical Programs Ip 17034 281

8302090327 Summary of 821129 mgt meeting at Engineering Analysis & Test Co, in Santa Monica, CA re NRC equipment qualification program
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
 Region 4, Office of Director 3pp 17071 003

8302090328 Forwards QA Program Insp Rept 99900021/82-01 on 821116-18 & notice of nonconformance
 COLLINS,J T Region 4, Office of Director 83/01/19 HOWARD,R E
 Pullman - Swindell Associates, Inc 3pp. 17067 132

8302090343 Notice of nonconformance from insp on 821116-18
 * Region 4, Office of Director 83/01/19 4pp 17067 135

8302090353 GA Program Insp Rept 99900021/82-01 on 821116-18
 Noncompliance noted welder, welding procedure & matl identities not documented on assembly weld history rept & area around temporary welds not marked
 NORMAN,D E , BARNES,I Division of Vendor & Technical Programs
 83/01/06 12pp 17067 139

8302090342 Forwards QA Program Insp Rept 99900023/82-01 on 821129-1202 & notices of violation & deviation
 POTAPOVS,U Division of Vendor & Technical Programs 83/01/20
 MOERKE,N M Southwest Fabricating & Welding Co, (subs of IU International Corp) 3pp 17067 163

8302090347 Notice of violation from insp on 821129-1202
 * Division of Vendor & Technical Programs. 83/01/20 Ip
 17067 166

8302090355 Notice of nonconformance from insp on 821129-1202
 * Division of Vendor & Technical Programs 83/01/20 2pp
 17067 167

8302090367 GA Program Insp Rept 99900023/82-01 on 821129-1202
 Noncompliance noted current copy of 10CFR21 not posted & 1/8-inch Inconel electrodes found mixed w/1/8-inch type E-9018 electrodes
 HAMILTON,J W , BARNES,I Division of Vendor & Technical Programs
 83/01/19 10pp 17067 169

8302090359 Advises that NRC will proceed w/Insp of Sandvik Special Metals, Inc QA program for mfg of zirconium tubing for use by power reactor licensees based on authority to conduct appropriate insp of QA program
 LIEBERMAN,J Regional Operations & Enforcement Division 83/02/03
 WHITE,E B United Nuclear Corp 2pp 17070 346

8302090360 Forwards QA Program Insp Rept 99900798/82-01 on 821115-19 & notices of nonconformance & violation
 POTAPOVS,U Division of Vendor & Technical Programs 83/01/20
 HERD,R Thermo Electron Corp 2pp 17070 331

8302090365 Notice of violation from insp on 821115-19
 * Division of Vendor & Technical Programs 83/01/20 Ip
 17070 333.

8302090371 Notice of nonconformance from insp on 821115-19
 * Division of Vendor & Technical Programs 83/01/20 2pp.
 17070 334

8302090379 GA Program Insp Rept 99900798/82-01 on 821115-19
 Noncompliance noted instructions not prepared for design review & engineering responsibilities & timer circuitry not deleted in Drawing 10889-805
 PARKER,L B , BARNES,I Division of Vendor & Technical Programs
 83/01/17 10pp 17070 336

8302090375 Ack receipt of 830125 ltr re questions concerning proposed QA program insp Director & Chief Counsel of Regional Operations & Enforcement Div will contact legal representative
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
 LINDBERG,J A Sandvik Special Metals Corp Ip 17071 095.

8302090381 Responds to NRC 830125 ltr re proposed QA program insp Clarification of wording & statutes or regulations governing proposed insp requested
 LINDBERG,J A Sandvik Special Metals Corp 83/01/25 POTAPOVS,U
 Division of Vendor & Technical Programs Ip 17071 096

8302090387 Ack receipt of 830120 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900401/82-04 Confirms 820202 telcon Instructions on field action request procedure will be documented by memo
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
 ETHERIDGE,M R Combustion Engineering, Inc Ip 17067 017

8302090391 Responds to NRC 821221 ltr re nonconformance noted in QA Program Insp Rept 99900401/82-04 Corrective actions engineer will be formally instructed to review requirements of field action request per Design Procedure (GADD) 5.7
 ETHERIDGE,M R Combustion Engineering, Inc. 83/01/20
 POTAPOVS,U Division of Vendor & Technical Programs 3pp
 17067 018

8302090392 Forwards QA Insp Rept 99900021/82-01 on 821116-18 at Pullman Power Products Corp in Williamsport, PA re furnishing of piping stools to Vogtle Units 1 & 2 w/unacceptable welds Item of nonconformance closed W/o encl
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
 LEWIS,R C Division of Project & Resident Programs Ip. 17067 022

8302090398 Forwards QA Insp Rept 99900798/82-01 on 821115-19 including potential defect in Eberline PIC-6A portable survey instrument Subj closed W/o encl
 POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
 SPENCER,G S Division of Resident, Reactor Project & Engineering Programs Ip 17067 107

8302090406 Forwards Midland-Ross Corp response to notice of violation re QA Program Insp Rept 99900364/82-01 & NRC ack of response Correspondence should be sent to ASLB for info W/o encl
 COLLINS,J T Region 4, Office of Director. 83/02/04 EISENHUT,D O
 Division of Licensing Ip 17066 143

NONDOCKETED ITEMS

B302090409 Forwards GA Program Insp Rept 99900021/82-01 on 821116-18 re absence of gaps in socket welded control rod drive piping No violations noted W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
BAER,R L Director's Office, Office of Inspection and Enforcement
2pp 17071 072

B302090419 Forwards GA Program Insp Rept 99900021/82-01 on 821116-18 No violations identified Stock problem re mislabeled Socketlet fabricated w/Heat Code 495AN resolved W/o encl
POTAPOVS,U Division of Vendor & Technical Programs AITS
H07003320 83/02/04 BAER,R L Division of Engineering & Quality Assurance (Pre 830103) 1p 17066 246

B302090425 Summary of 821130 mgt meeting w/Rockwell Intl,Energy Sys Groupin Canoga Park,CA re equipment qualification program
POTAPOVS,U Division of Vendor & Technical Programs 83/02/04
Division of Vendor & Technical Programs 4pp 17066 288

B302090442 Advises that Section E 2 of encl GA Program Insp Rept 99900403/82-02 re fuel pool cooling & cleanup HX relief valve settings at Grand Gulf considered closed W/o encl
POTAPOVS,U Division of Vendor & Technical Programs VITS 82-191
83/02/04 LEWIS,R C Division of Project & Resident Programs 1p 17066 254

B302090465 Discusses Vendor Program Branch insp on 821129-1202 at Southwest Fabricating & Welding Co Items F02700232 & F02700260 in GA Program Insp Rept 9900025/82-01 re main steam piping,closed,W/o stated encl
POTAPOVS,U Division of Vendor & Technical Programs AITS
F02700232 83/02/04 LEWIS,R C Division of Project & Resident Programs 1p 17066 292

B302150239 Summary of 821005 meeting w/Wyle Labs in Huntsville,AL re NRC equipment qualification program
PHILLIPS,H B Division of Vendor & Technical Programs 83/02/07
Division of Vendor & Technical Programs 2pp 17149 280

B302150310 Confirms plans for 830328-0401 GA program insp
POTAPOVS,U Division of Vendor & Technical Programs 83/02/07
MILLER,T D Westinghouse Electric Corp 1p 17148 221

B302150324 Ack receipt of 830126 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900784/82-01
POTAPOVS,U Division of Vendor & Technical Programs 83/02/07
CHRISTOFFERSON Chicago Bridge & Iron Co 1p 17148 175

--B302150328 Responds to NRC 830104 ltr re nonconformance noted in GA Program Insp Rept 99900784/82-01 Corrective actions nonconformance control list & shop checklist control list will be revised
BONINA,R A Chicago Bridge & Iron Co 83/01/26 Division of Vendor & Technical Programs 1p 17148 176

--B302150333 Ack receipt of 820916 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900784/82-01 Addl info requested re sys changes for repair welding
POTAPOVS,U Division of Vendor & Technical Programs 83/01/04
CHRISTOFFERSON Chicago Bridge & Iron Co 1p 17148 177

--B302150337 Responds to NRC 820819 ltr re nonconformance noted in GA Program Insp Rept 99900784/82-01 Corrective actions: nonconformance control list signed to show completion of disposition.
CHRISTOFFERSON, BONINA,R A Chicago Bridge & Iron Co 82/09/16, Division of Vendor & Technical Programs, 4pp 17148 178

B302150389 Confirms 830201 telcon re 830307-12 insp of implementation of GA program
POTAPOVS,U Division of Vendor & Technical Programs, 83/02/07.
HAGSTROM,R W General Electric Co 1p. 17158 151.

B302150417 Confirms 830214-17 insp at Buffalo,NY re implementation of GA program for equipment qualification testing of Class IE equipment per 830202 telcon
POTAPOVS,U Division of Vendor & Technical Programs, 83/02/07
BURDURE,R L Conax Corp 1p 17157 166

B302150452 Notifies that GA program described in Topical Rept OIBSAR-17-A implemented satisfactorily Conclusion valid for 3 yrs Program subj to periodic insps Acceptability does not imply that specific product/svc is of acceptable quality
COLLINS,J.T. Region 4, Office of Director 83/02/07 DERIENZO,P P Gibbs & Hill, Inc. (subs of Dravo Corp) 2pp 17157 147

B302150464 Ack receipt of 830124 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 99900262/82-01
POTAPOVS,U Division of Vendor & Technical Programs 83/02/07
BEAUMONT,N Control Components, International (subs of Babcock & Wilcox) 1p 17157 072

--B302150460 Responds to NRC 830104 ltr re nonconformances noted in Program Insp Rept 99900262/82-01 Corrective actions design calculations reviewed & signed off by reviewer, personnel trained & design control procedures revised
BEAUMONT,N Control Components, International (subs of Babcock & Wilcox) 83/01/24 POTAPOVS,U Division of Vendor & Technical Programs 2pp 17157 073

B302150519 Ack receipt of 820930 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900768/82-01
POTAPOVS,U Division of Vendor & Technical Programs 83/02/07
KOH,B Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp 17156 334

--B302150530 Responds to NRC 820806 ltr re nonconformance noted in GA Program Insp Rept 99900768/82-01 Corrective actions procedure written for evaluating deviations Request for withdrawal of violations re recordkeeping encl
KOH,B Hittman Nuclear & Development Corp (subs Hittman Corp) 82/09/30 POTAPOVS,U Division of Vendor & Technical Programs 2pp 17156 336

--B302150540 Request for reconsideration of 820806 notice of violation screening tests of Flextron Urethane 66-11 foam for Feb-June 1981 GA Program Insp Rept 99900768/82-01 Pp 4 & 5 should be excised & deleted
FEINSTEIN,H Hittman Nuclear & Development Corp (subs Hittman Corp) 82/09/30 NRC - No Detailed Affiliation Given 4pp 17156 338

--B302150546 Affidavit of B Koh supporting reasons for not retaining records of Flextron foam
KOH,B Hittman Nuclear & Development Corp (subs Hittman Corp) 82/09/30 3pp. 17156 354

--B302150556 Affidavit of CW Mallory re screening tests of Flextron
MALLORY,C W Hittman Nuclear & Development Corp (subs Hittman Corp) 82/09/30 2pp 17156 357

--B302150561 Confirms agreement that written application must be filed by 820916 in support of 820825 request to delete certain info from docket prior to placement in PDR
FEINSTEIN,H W Hittman Nuclear & Development Corp (subs Hittman Corp) 82/08/26 POTAPOVS,U Division of Vendor & Technical Programs 1p 17156 359

--B302150569 Confirms request & I Barnes concurrence for extension of to respond to 820806 ltr until 820920 Extension for disclosure exemption request will be filed if need for request determined
FEINSTEIN,H W Hittman Nuclear & Development Corp (subs Hittman Corp) 82/08/12 POTAPOVS,U Division of Vendor & Technical Programs 1p 17156 360

B302150925 Confirms 830202 telcon re delay of Mt Vernon,GH plant GA Program Insp Rept 99900373/83-01 until 830214-1B Rept will cover GA program implementation,Agastat relays,control panels & high voltage cubicles
POTAPOVS,U Division of Vendor & Technical Programs 83/02/07
DEKKER,H A Cooper Energy Services 1p 17156 223

B302150931 Recommends issuance of encl ltr confirming that Gibbs & Hill, Inc satisfactorily implemented GA program W/o encl
HARRELL,P H Division of Vendor & Technical Programs 83/02/02
COLLINS,J T Region 4, Office of Director 2pp 17156 217

B302160157 Forwards GA Program Insp Rept 99900255/82-02 on 821213-15 Pacific Scientific Co 820913 potential Part 21 rept concerning damaged mechanical shock arrestors Resident Inspector at Beaver Valley aware of Part 21 rept W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/02/08
BAER,R L Division of Emergency Preparedness (Pre 830103) 1p 17162 316

B302160290 Forwards GA Program Insp Rept 99900280/82-01 on 821206-09 & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 83/01/28
FISHER,T.R Westinghouse Electric Corp. 2pp 17170 099

--B302160294 Notice of nonconformance from insp on 821206-09
* Division of Vendor & Technical Programs 83/01/28 2pp 17170 101

NONDOCKETED ITEMS

--8302160298 QA Program Insp Rept 99900280/B2-01 on 821206-09
Nonconformance noted error correction tags not attached to
five completed pressure transmitters identified as scrap
matl & locked panel not provided for scrap disposal
SUTTON, J W , BARNES, I Region 4, Office of Director 83/01/26
8pp 17170 103

8302160309 Forwards QA Program Insp Rept 99900255/B2-02 on 821213-15
No noncompliance noted
POTAPQVS, U Division of Vendor & Technical Programs 83/01/28
HADUAGV, P A Pacific Scientific 2pp 17166 202

--8302160315 QA Program Insp Rept 99900255/B2-02 on 821213-15 No
noncompliance noted Major areas inspected QA program
implementation re mfg process control & heat treatment
OLLER, R E , BARNES, I Region 4, Office of Director 83/01/26
12pp 17166 204

8302160325 Forwards QA Program Insp Rept 99900524/B2-03 on 821129-1203
& notice of nonconformance
POTAPQVS, U Division of Vendor & Technical Programs 83/01/28
DIRIENZO, P P Gibbs & Hill, Inc (subs of Dravo Corp) 2pp
17166 240

--8302160327 Notice of nonconformance from insp on 821129-1203
* Division of Vendor & Technical Programs 83/01/28 1p
17166 242

--8302160331 QA Program Insp Rept 99900524/B2-03 on 821129-1203
Noncompliance noted previous issues of drawings not marked
superseded & project procedures did not provide provisions
for distribution of drawings & revs
HARRELL, P H , HALE, C J Region 4, Office of Director 83/01/27
22pp 17166 243

8302160333 Forwards QA Program Insp Rept 99900522/B2-03 on 821129-1202
& notice of nonconformance
POTAPQVS, U Division of Vendor & Technical Programs. 83/01/28
STATTON, C D Bechtel Corp 2pp 17164 311

--8302160334 Notice of nonconformance from insp on 821129-1202
* Division of Vendor & Technical Programs 83/01/28 1p
17164 313

--8302160339 QA Program Insp Rept 99900522/B2-03 on 821129-1202
Noncompliance noted procedure implementation did not provide
for appropriate product QA, insp or qualification of clamps
& stock assemblies
COSTELLO, J R , HALE, C J Region 4, Office of Director 83/01/27
13pp 17164 314

8302220239 Confirms QA program insp at Portland, OR plant on 830228-0303
per 830208 telcon
POTAPQVS, U Division of Vendor & Technical Programs 83/02/15
PATTY, D F Bingham-Willamette Co 1p 17230 134

8302220323 Confirms 830209 telcon discussing review of Figure 306/307
enablers at facility on 830303-04
POTAPQVS, U Division of Vendor & Technical Programs 83/02/15
SEWELL, D M ITT Grinnell (subs of IIT) 1p 17230 145

8302230191 Ack receipt of 821215 & 830126 ltrs informing NRC of steps
taken to correct nonconformances noted in QA Program Insp
Rept 99900369/B2-01
POTAPQVS, U Division of Vendor & Technical Programs 83/02/16
EHRHARD, E R Automatic Switch Co 1p 17245 121

--8302230194 Responds to NRC 821115 ltr re nonconformances noted in QA
Program Insp Rept 99900369/B2-01 Corrective actions: mfg
control procedure revised incorporating computer controlled
Bill of Matl procedures currently implemented
NAUMANN, H R Automatic Switch Co 83/01/26 POTAPQVS, U
Division of Vendor & Technical Programs 2pp 17245 122

--8302230199 Ack receipt of 821215 ltr informing NRC of steps taken to
correct nonconformances noted in QA Program Insp Rept
99900369/B2-01 Addl info required within 25 days
POTAPQVS, U Division of Vendor & Technical Programs 83/01/07
EHRHARD, E R Automatic Switch Co 1p 17245 124

--8302230204 Responds to NRC 821115 ltr re nonconformances noted in QA
Program Insp Rept 99900369/B2-01 Corrective actions
initiated Addl documentation to be prepared within 60
days.
NAUMANN, H R Automatic Switch Co. 82/12/15 POTAPQVS, U
Division of Vendor & Technical Programs 1p 17245 125

REG00 REGULATORY GUIDES

8302140097 Forwards 820825 comments on draft Reg Guide IC 126-5,
"Instrument Sensing Lines," since ltr not reflected in NRC
discussion of public comments on reg guide
CAHN, A L Bechtel Corp 83/01/31 Docketing & Services Branch
1p 17142 101

--8302140101 Comments on draft Reg Guide IC 126-5, "Instrument Sensing
Lines " Recommends that final reg guide be issued w/o
Regulatory Positions C3 & C4 & classifications for
instrument sensing lines in ISA 67 02 be endorsed
CAHN, A L Bechtel Corp 82/09/25 Docketing & Services Branch
2pp 17142 102

8302180045 Reg Guide 7 10, Tasks TP 019-4 & TP 020-4, "Establishing QA
Programs for Packaging Used in Transport of Radioactive
Matl "
* Office of Nuclear Regulatory Research, Director 83/01/31 20pp
17223 194

--8302180049 Value/impact statement for Reg Guide 7 10, Tasks TP 019-4
& TP 020-4 Reg guide should be prepared & issued
* Office of Nuclear Regulatory Research, Director 83/01/31
2pp 17223 215.

8302250334 Ack receipt of 830128 ltr forwarding HJ Swan comments on
Reg Guide 10 B re revised training & experience criteria for
physicians
KAMMERER, C Office of Congressional Affairs 47FR3228 83/02/09
WAXMAN, H A House of Rep 1p 17291 089

--8302250338 Requests review of new policy re revised training &
experience criteria for physicians
WAXMAN, H A House of Rep 83/01/28 PALLADINO, N Commissioners
3pp 17291 090

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8302030032 "Investigation of Accident-Induced Flow & Matl Transport in
Nuclear Facilities," monthly progress rept for Dec 1982.
MARTIN, R A , GREGORY, W S Los Alamos Scientific Laboratory FIN
A-7029 83/01/31 BERNSTEIN, B Transportation & Materials Risk
Branch 6pp 17028 342

8302070124 "BWR/4 Loss of Feedwater Transient Analysis," informal
rept
LU, M S Battelle Memorial Institute, Pacific Northwest Laboratory
LEVINE, M M , SHIER, W O Brookhaven National Laboratory FIN A-3350
BNL-NUREG-32396 82/07/31 HODGES, M W Reactor Systems Branch,
36pp 17065 136

8302080119 "Non-NRC Performance Assessment Activities," yearly status
rept
* Sandia Laboratories FIN A-1165 82/07/31 Division of Waste
Management. 42pp 17105 264

8302080124 "Investigation of Ventilation Component Response to Large
Pressure Pulses," progress rept for Dec 1982
* Los Alamos Scientific Laboratory FIN A-7028 83/01/26
Office of Nuclear Regulatory Research, Director 6pp 17105 252.

8302080482 "Generation of BWR Point Kinetics Reactivity Functions,"
informal rept
DIAMOND, D J Brookhaven National Laboratory FIN A-3350
BNL-NUREG-32412 82/09/30 HODGES, M W Reactor Systems Branch
26pp 17071 170.

8302150739 "Evaluation of Thermal-Hydraulic Objectives of LOFT
Experiment L2-6," experiment planning rept
HARVEED, E A , BEHLING, S R , TOLMAN, E L EQ&O, Inc FIN A-6048
EQO-LOFT-6093 82/10/31 MCPHERSON, G D NRC - No Detailed
Affiliation Given 47pp. 17160 054

8302150741 "Monthly Rept Representing Research Portion of Water Reactor
Research Dept & Thermal Fuels Behavior Program "
DEARIEN, J A EQ&O, Inc EQO-WRR-6129 82/11/30 NRC - No
Detailed Affiliation Given 162pp 17159 250

8302150745 "Use of In-Situ Procedures for Seismic Equipment
Qualification in Currently Operating Plants," informal rept
BADIK, S , DIXON, B. W. EQ&O, Inc FIN A-6474 EQO-EA-6140
82/12/31, NRC - No Detailed Affiliation Given. 82pp. 17159 118.

NONDOCKETED ITEMS

8302150748 "Signal Isolation Device & Stored Program Digital Computer Problems Experienced by US Commercial Nuclear Power Plants," informal rept
ROHRDANZ, R R EQ&O, Inc FIN A-6370 EQO-EE-6052 82/09/28
BOEHM, D W Office of Nuclear Regulatory Research, Director 41pp 17159 077

8302150758 "Post-Test Analysis of LOFT Anticipated Transient Experiments L6-1, L6-2, L6-3 & L6-5"
OLLIKKALA, H, BEHLING, S R EQ&O, Inc FIN A-6048 EQO-LOFT-6159
83/01/31 MCPHERSON, O D Office of Nuclear Regulatory Research, Director 48pp 17158 239

8302160002 "Density Profile & Mass Flow Rate Calculation Procedures," internal technical rept
LASSAHN, O D, GOODRICH, L D, HANSON, D J EQ&O, Inc LO-87-80-152
81/03/04 NRC - No Detailed Affiliation Given 72pp 17171 001

8302160003 "BCDAP Replication of MARCH Hydrogen Calculations," technical rept
CHAMBERS, R EQ&O, Inc FIN A-6354 EQO-NTAP-6148 82/12/31
LARKINS, J T NRC - No Detailed Affiliation Given 43pp 17170 298

8302160005 "RELAP5 Pretest Analysis of Test B-PL-3"
SHAW, R A EQ&O, Inc FIN A-6038 EQO-BEHI-6134 82/12/31
LANDRY, R R Office of Nuclear Regulatory Research, Director 25pp 17172 016

8302160008 "1983 First Quarter Interim Rept on Two Phase Instrumentation Evaluation,"
ENSLERT, S B, EQ&O, Inc FIN A-6376 EQO-ID-6141 82/12/31
KONDIG, N N Instrumentation & Control Branch 31pp 17170 267

8302160025 "Rock Mass Sealing - Shaft or Borehole Plug-Rock Mechanical Interaction"
JEFFREY, R O Arizona, Univ. of NRC-04-78-271 80/12/31 Office
of Nuclear Regulatory Research, Director 154pp 17171 073

8302160097 "Nuclear Power Plant Anticipatory Measurement Recommendations," quarterly progress rept
LASSAHN, O D EQ&O, Inc FIN A-6380, EQO-ID-6142 82/12/31
KONDIG, N N Instrumentation & Control Branch 60pp 17160 264

8302160398 "RELAP5 Ref Calculation for LOFT Experiment L6-7/L9-2," experiment ref calculation rept
CONDIE, K G EQ&O, Inc FIN A-6048 EQO-LOFT-6014, 83/01/31
MCPHERSON, O D Division of Reactor Safety Research 55pp 17173 325

8302160401 "Fuel Behavior Experiment Requirements for LOFT Test L2-4"
BROUGHTON, J M, MACDONALD, P E, HAGMAN, D L EQ&O, Inc FIN A-6362
EQO-TFBP-6077 82/10/31 MCPHERSON, O D Division of Reactor
Safety Research 49pp 17173 275

8302160402 "TRAC-BD1 (Version 12) Assessment Using SSTF BWR/4 Data," technical rept
KULLBERG, C M EQ&O, Inc FIN A-6047 EQO-NTAP-6146, 82/12/31
ODAR, F Office of Nuclear Regulatory Research, Director 79pp 17173 196

8302170009 "Comparison of Mass Flow Calculations Using Drag-Disc Turbine Transducer (DTT) Data From Transient Flow Calibr Facility," internal technical rept
MEACHUM, T R EQ&O, Inc, LO-87-80-145, 80/11/04, NRC - No
Detailed Affiliation Given, 65pp 17190:312.

8302220467 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nuclear Station, Units 1, 2 & 3," informal rept
UDY, A C EQ&O, Inc FIN A-6429 TAC 12741, 83/01/31 EMAMI, H
Division of Systems Integration (post B11005), 15pp, 17239 358

8302240011 "Thermal Stability of Low Level Waste Forms," draft rept
PICIULO, P L, CHAN, S Brookhaven National Laboratory FIN A-3159
BNL-NUREQ-32337, 82/12/31, PERSON, L, Office of Nuclear Material
Safety & Safeguards, Director 49pp 17288-033

8302240360 "Draft Staff Technical Positions Subtask 1 2: Post-Emplacement Monitoring," draft interim rept
FAMNO, S V Brookhaven National Laboratory FIN A-3168,
BNL-NUREQ-32380 82/12/31, WICK, E A High Level Waste Licensing
Management Branch 119pp 17290 008

8302240361 "Two Phase Flow Through Porous Beds - Preliminary Investigation," informal rept.
TUTU, N K, OINBERG, T Brookhaven National Laboratory, FIN A-3024,
BNL-NUREQ-32394 82/12/31 CURTIS, R T, Severs Accident Assessment
Branch 32pp, 17289, 308

8302250039 "Momentum Integral Network Method for Thermal-Hydraulic Transient Analysis," for presentation at 1983 ANS annual meeting in Detroit, MI
VAN TUYLE, G J Brookhaven National Laboratory BNL-NUREQ-32444
83/02/23 NRC - No Detailed Affiliation Given 6pp 17298 236

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8302020463 Transcript of second Ad Hoc Committee on Review of Nuclear Reactor Licensing Reform Proposals 830126 meeting in Washington, DC Pp 1-177
* Commissioners 83/01/26 179pp 16995 205

8302080088 Summary of ACRS Subcommittee on Reliability & Probabilistic Assessment 820802 meeting in Washington, DC re draft action plan for implementation of proposed safety goals & accident policy Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/08/12
ACRS - Advisory Committee on Reactor Safeguards 31pp 17106 105

8302100334 Notification of CROR Meeting 32 on 830217 in Bethesda, MD to review proposed final rule 10CFR50.73 re LER sys Attendance should be limited to senior staff
STELLO, V Committee to Review Generic Requirements, 83/02/08
EISENHUT, D O Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p 17112 108

--8302100340 Forwards proposed final rule 10CFR50.73 re LER sys & req for OMB review & supporting statement CROR meeting on 830216 for expedited review requested Final rule 10CFR50.72 should also be discussed in 830216 meeting
MICHELSON, C Director's Office 83/02/07 STELLO, V Regional Operations & Generic Requirements 65pp 17112 110

8302100352 Notification of CROR Meeting 31 on 830209 in Bethesda, MD to review two proposed IE bulletins Attendance should be limited to senior staff
STELLO, V Committee to Review Generic Requirements 1EB-83-01
83/02/08 EISENHUT, D O Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 17111 245

--8302100359 Forwards proposed IE bulletin, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" Final CROR briefing on 830209 requested
DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 83/02/03 STELLO, V Regional Operations & Generic Requirements 10pp 17111 247

--8302100381 Forwards proposed IE Bulletin 83-01, "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants" & OMB clearance package Major differences between IE Bulletins 82-03 & 83-01 discussed
DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 1EB-83-01, 83/02/03 STELLO, V, Regional Operations & Generic Requirements 24pp 17111 257

8302160180 Summary of CROR Meeting 30 on 830126 re ATWS rulemaking & potential problem concerning Ray Miller, Inc fraudulent products sold to nuclear industry companies List of attendees & P Barancowsky briefing on ATWS rulemaking encl
STELLO, V Committee to Review Generic Requirements 83/02/08 DIRCKS, W J Office of the Executive Director for Operations 17pp 17161-196

8302170393 Forwards monthly activities rept for 830101-0204 & open items from previous meetings
SCHWINK, W Committee to Review Generic Requirements 83/02/04
Committee to Review Generic Requirements 1p 17195 281

--8302170397 "CROR monthly rept for 830101-0204,"
* Committee to Review Generic Requirements, 83/02/04, App, 17195 282

8302220465 Notices of agenda mod for CROR Meeting 32 on 830217 Proposed amend to 10CFR50.72 re immediate notification requirements encl for review prior to meeting
STELLO, V, Regional Operations & Generic Requirements, 83/02/15
EISENHUT, D O Division of Licensing JORDAN, E L Director's Office, Office of Inspection and Enforcement, CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 44pp 17239, 314

NONDOCKETED ITEMS

8302230480 Forwards proprietary "Util Design Review Panel Evaluation Rept D2/D3 Steam Generator Design Mod " Mod to D2/D3 steam generator preheater section can be installed & steam generator can operate safely Rept withheld (ref 10CFR2 790) BLACKLEY, S K Design Review Panel 83/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 4pp

8302230632 Forwards proprietary & nonproprietary "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod" & Westinghouse 830114 application for withholding proprietary info Proprietary rept withheld (ref 10CFR2 790) BLACKLEY, S K Design Review Panel 83/01/19 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 2pp 17249 081

--8302230640 Submits application for withholding proprietary "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod," per 10CFR2 790 Affidavit encl WIESEMANN, R A Westinghouse Electric Corp CAW-83-2 83/01/14 EISENHUT, D O Division of Licensing 8pp 17249 082

--8302230650 Nonproprietary "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod " * Design Review Panel 83/01/31 190pp 17249 071

SECY POSITION PAPERS BEFORE THE COMMISSION

8301240226 SECY-83-016
Recommends publication of proposed & final regulations implementing legislation which authorizes NRC to issue temporary OL & requested OL amends involving no significant hazards consideration before conducting hearing Rev encl DIRCKS, W J Office of the Executive Director for Operations 83/01/13 136pp 16914 292

8302010065 Addl response to FOIA request for all documents considered by Commission in promulgating final rule on environ qualification & SECY-82-207 Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/12/06 CURRAN, D Harmon & Weiss 3pp 16990 023

--8112100049 SECY-81-603B
Recommends Commission approval for publication of notice of proposed rulemaking, "Environ Qualification of Electric Equipment for Nuclear Power Plants " DIRCKS, W J Office of the Executive Director for Operations 81/11/16 15pp 16990 030

--8209200462 SECY-82-207D
Suppl's SECY-82-207C final rule on environ qualification of electric equipment important to safety Areas of cold shutdown, replacement parts, Reg Guide 1.89 status & deadline supplemented DIRCKS, W J Office of the Executive Director for Operations 82/08/26 4pp 16990.053

8302020338 Final response to FOIA request for documents re SEP Forwards SECY-77-545 Document available in PDR FELTON, J M Division of Rules and Records 82/12/27 GALLO, J Isham, Lincoln & Seale 1p 16999 152

--8302020339 SECY-77-545
Weekly info rept for wk ending 771014 REHM, T A Office of the Executive Director for Operations 77/10/18 25pp 16999 153

8302020382 Addl response to FOIA request for SECY-75-58B, 58BA, 58BB, SECY-R-74-64, SECY-81-600A & SECY-81-622A Forwards SECY-R-74-64, SECY-75-58B & 58BB SECY-81-622A withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/12/03 CONNOR, L Doc-Search Associates 2pp 17011 176

--8302020391 SECY-75-58B
Recommends final rule changing Commission regulations in 10CFR2 790 re evaluation, protection & disclosure of proprietary info SHAPAR, H K Office of the Executive Legal Director 75/10/08 114pp 17011 294.

--8302020388 SECY-75-58BB
Recommends final rule changing Commission regulations in 10CFR2 790 re evaluation, protection & disclosure of proprietary info SHAPAR, H K Office of the Executive Legal Director. 76/02/16 89pp 17011 205

--8302020385 SECY-R-74-064
Recommends approval of publication of notice in FR requesting comments on five alternative approaches to proprietary info in Commission licensing proceedings HUNTZING, L M Atomic Energy Commission 73/11/01 26pp 17011 179

8302040108 Addl response to FOIA request for SECY-82-326 & SECY-82-315 Forwards SECY-82-326 Document also available in PDR FELTON, J M Division of Rules and Records 82/12/27 DOVE, K L Dove, K L 1p 17061 082

--8209010085 SECY-82-326
Requests approval of proposed rulemaking, policy statement & draft FR notice re backfitting TOURTELLI, J Regulatory Reform Task Force 82/08/02 20pp 17061 093

8302170075 SECY-83-052
Requests Commission approval of final rulemaking re licensed operator staffing at plants & of draft policy statement on shift crew qualifications DIRCKS, W J Office of the Executive Director for Operations 83/02/03 67pp 17319 315

8302220050 Addl response to FOIA request for documents re UCLA lab & research reactors Forwards documents listed on Apps A & B App B documents partially withheld commercial & financial info (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 82/12/30 HIRSCH, D. CBS News, CBS, Inc 3pp 17240 329

--8302220058 SECY-79-187B
Requests approval to defer manpower reactor licensees from implementing upgrade rule & repts on evaluation of 100 rem/h at 3-ft exemption criterion Immediate publication of upgrade rule requested HINDOUE, R B Office of Standards Development, Director DENTON, H R Office of Nuclear Reactor Regulation, Director DIRCKS, W J Office of Nuclear Material Safety & Safeguards, Director 79/07/13, 12pp 17240 353

--8302220054 SECY-79-187C
Provides maried-up status rept on impact of safeguards upgrade rule on 22 nonpower reactor licensees, review of safeguards measures & status of re-evaluation on 100 rem/h at 3-ft self-protection exemption criterion DIRCKS, W J Office of Nuclear Material Safety & Safeguards, Director 79/12/19 17pp 17240 356

STATE PROG STATE PROGRAMS

8301310191 Forwards response to technical comments & recommendation for AR Radiation Control Program, as result of 820830-0903 review Great improvements made in program WILSON, E F Arkansas, State of 83/01/12 COLLINS, J T Region 4, Office of Director 43pp 17241 203

8302040472 NUREG-0942 DRAFT
CONDUCTING NEED-FOR-POWER REVIEW FOR NUCLEAR POWER PLANTS Guidelines To States NASH, A D Office of State Programs, Director 82/12/31, 107pp, 17044 084

8302070371 PNO-IV-83-004 on 830129, LA Nuclear Energy Div fourth quarter film badge rept for Dresser Atlas employee indicated whole body exposure of 372 rads Value not true No medical indications that individual received indicated exposure HEVER, R S, DQDA, R J Region 4, Office of Director 83/02/02, 2pp 17028 358

8302070445 Forwards IE Followup Performance Appraisal Rept 99990004/82-07 on 821118-19 for NRC/State of CO Environ Monitoring Contract NRC-05-80-267 for Jan-Oct 1982 Recommends that contract be renewed for 3 yrs BROWN, O D Division of Vendor & Technical Programs NRC-05-80-267 83/01/31, COLLINS, J T Region 4, Office of Director, 1p 17036 289.

--8302070450 IE Followup Performance Appraisal Rept 99990004/82-07 on 821118-19 for NRC/State of CO Environ Monitoring Contract NRC-05-80-267 for Jan-Oct 1982 Overall performance re sample collection & analyses acceptable, NICHOLAS, J D., MURRAY, B Region 4, Office of Director 83/01/27 11pp 17036 290

NONDOCKETED ITEMS

44

8302070558 Confirms discussions re review & evaluation of radiation control program for regulation of agreement matls adequate to protect public health & safety. Technical comments & recommendations for program encl
COLLINS, J T Region 4, Office of Director 83/02/01 LOMMEN, A K
North Dakota, State of 5pp 17035 228

8302080052 Responds to FOIA request for names & addresses of all persons in State of MI issued registration certificates for certain in-vitro clinical or lab testing under general license in 10CFR31.11 Forwards documents
FELTON, J M Division of Rules and Records 82/12/29 KRONZEK, A L
FOI Services 1p 17100 008

--8302080056 "Registration Certificate-In-Vitro Testing W/Byproduct Matl Under General License 10CFR31.11," for State of MI
* NRC - No Detailed Affiliation Given 82/12/29 1,349pp
17100 009

8302080067 Notification of contract execution, Mod 2 to "Study Entitled, 'Exam of Agreement State Program'" Contractor, Natl Governors Assoc
PAQUER, M Administrative Contracts Branch FIN B-1667
NRC-06-81-293 83/01/27. KERR, O W. Office of State Programs, Director LUBENAU, J, NRC - No Detailed Affiliation Given 1p
17106 255

--8302080070 Mod 2, extending period of performance & final rept delivery date until 830131, to "Study Entitled, 'Exam of Agreement State Program'"
FARBER, S O National Governors' Association SMITH, P A. Division of Contracts FIN B-1667. NRC-06-81-293 83/01/27. 1p
17106 256

8302100263 NUREG/BR-0025 V09 N1
INFORMATION REPT ON STATE LEGISLATION
* Office of State Programs, Director 83/01/31. 12pp. 17133 176

8302130756 Forwards notice of availability of "Natl Governors Assoc Exam of Agreement State Program," for FR publication
KERR, O W Office of State Programs, Director 8A/JOL 83/01/31
COHRS, T R Correspondence & Records Branch. 1p 17158 287

--8302130759 Forwards advance copy of "Natl Governors Assoc Exam of Agreement State Program"
LUBENAU, J O. Office of State Programs, Director 83/02/01 FU, F
Public Document Branch 1p 17158 288.

--8302130760 "Natl Governors Assoc Exam of Agreement State Program"
* National Governors' Association. 83/01/31 147pp. 17158 289

8302170421 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to QA Dept of Natural Resources
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8404
NRC-29-83-625. 83/02/09 LOY, T N Region 2, Office of Director
MONTGOMERY, D M NRC - No Detailed Affiliation Given 1p
17195 222.

--8302170424 Contract: "Radiation Monitoring Program Requirements," awarded to QA Dept of Natural Resources.
LEDBETTER, J. L. Georgia, State of MORTON, K V Division of Contracts. FIN B-8404 NRC-29-83-625 83/02/09 14pp
17195:223

8302170425 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of MA
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8350
NRC-28-83-606. 83/02/09. MCSGAR, J Region 1, Office of Director
COSTELLO, F NRC - No Detailed Affiliation Given 1p. 17205.154

--8302170429 Contract. "Radiation Monitoring Program Requirements," awarded to State of MA.
FRECKETTE, A L Massachusetts, Commonwealth of. MORTON, K V Division of Contracts FIN B-8350. NRC-28-83-606 83/02/09. 15pp. 17205:155

8302170484 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of AR
MCDERMOTT, D Technical Assistance Contracts Branch. FIN B-8300
NRC-31-83-667. 83/02/09. MEYER, D M Region 4, Office of Director.
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 17203.194

--8302170489 Contract: "Radiation Monitoring Program Requirements," awarded to State of AR
SALTZMAN, B. N Arkansas, State of MORTON, K V Technical Assistance Contracts Branch FIN B-8300. NRC-31-83-667 83/02/09 18pp. 17203 195

8302220020 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to NC Dept of Human Resources
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8406
NRC-29-83-627 83/02/08 LOY, T N Region 2, Office of Director
MONTGOMERY, D M NRC - No Detailed Affiliation Given 1p
17227 354

--8302220025 Contract "Radiation Monitoring Program Requirements," awarded to NC Dept of Human Resources
WILKERSON, I O North Carolina, State of MORTON, K V Division of Contracts FIN B-8406 NRC-29-83-627 83/02/08 8pp
17227 355

8302220036 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to MD Div of Health
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8454
NRC-30-83-643 83/02/09 PAPPAS, H Region 3, Office of Director
GEBMANN, M J NRC - No Detailed Affiliation Given 1p 17227 336

--8302220042 Contract "Radiation Monitoring Program Requirements," awarded to MD Div of Health
* Missouri, State of MORTON, K V Division of Contracts FIN B-8454 NRC-30-83-643 83/02/09 9pp 17227 337.

8302220068 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to SC Dept of Health & Environ Control
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8403
NRC-29-83-624 83/02/09 LOY, T N Region 2, Office of Director
MONTGOMERY, D M NRC - No Detailed Affiliation Given 1p
17234 200

--8302220074 Contract "Radiation Monitoring Program Requirements," awarded to SC Dept of Health & Environ Control
DANTZLER, M U South Carolina, State of MORTON, K V. Division of Contracts FIN B-8403 NRC-29-83-624 83/02/09 15pp
17234 201

8302220407 Forwards "Rept & Staff Evaluation of NE Radiation Control Program for Period 810822-821110"
COLLINS, J T Region 4, Office of Director 83/02/15 SIMMONS, E
Nebraska, State of. 1p 17232 070

--8302220410 Forwards "Rept & Staff Evaluation of NE Radiation Control Program for Period 810822-821110" & technical comments
Significant problems identified in two Category I indicators Review & response requested
COLLINS, J T. Region 4, Office of Director 83/01/18 SMITH, H D
Nebraska, State of 5pp 17232 071

--8302220414 "Rept & Staff Evaluation of NE Radiation Control Program for Period 810822-821110"
* Region 4, Office of Director 83/01/18 55pp 17232 075

8302240178 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of NH
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8364
NRC-28-83-611 83/02/14 MCSGAR, J Region 1, Office of Director
COSTELLO, F NRC - No Detailed Affiliation Given 1p 17288 258

--8302240185 Contract "Radiation Monitoring Program Requirements," awarded to State of NH
WALLACE, W T New Hampshire, State of MORTON, K V. Division of Contracts FIN B-8364 NRC-28-83-611 83/02/14 10pp
17288-259

8302240234 Notification of contract execution, Mod 5 to "Environ Monitoring Program W/State of NJ" Contractor State of NJ
WOLLETT, B Research Contracts Branch FIN B-5108 NRC-05-80-270
83/02/10 COBBS, L I Director's Office, Office of Inspection and Enforcement COHEN, L K NRC - No Detailed Affiliation Given 1p
17288 001

--8302240240 Mod 3, decreasing funding, to "Environ Monitoring Program W/State of NJ"
FISHER, E J New Jersey, State of. GUSTAVE, R P. Division of Contracts FIN B-5108 NRC-05-80-270 83/02/10 1p 17288 002

8302240269 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of DE
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8352
NRC-28-83-602 83/02/14 MCSGAR, J Region 1, Office of Director
COSTELLO, F. NRC - No Detailed Affiliation Given. 1p. 17288:078

--8302240275 Contract "Radiation Monitoring Program Requirements," awarded to State of DE
WILSON, J E Delaware, State of. MORTON, K V Division of Contracts FIN B-8352 NRC-28-83-602 83/02/14 12pp
17288.079

NONDOCKETED ITEMS

8302240323 Forwards State of SC 830106 & State of NV 830111 comments on "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste " SCHEIDER, K N Office of State Programs, Director 83/01/26
JOHNSON, T Division of Waste Management 1p 17290 181

--8302240327 Comments on "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste," in response to NRC 821213 ltr SHEALY, H G South Carolina, State of 83/01/06 NUSSBAUMER, D Office of State Programs, Director 2pp 17290 182

--8302240338 Comments on "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste " VADEN, J Nevada, State of 83/01/11 NUSSBAUMER, D Office of State Programs, Director 1p 17290 184

8302250067 Forwards branch technical positions re Part 61 per telcon w/o encl LOHAUS, P Low Level Waste Licensing Branch 83/01/31 SCHNEIDER, K Office of State Programs, Director 2pp 17302 357

8302250077 Requests assistance in obtaining repts re low level waste disposal from States of CA, IL, NH, NM, PA, TN & VA HANKINS, E F Low Level Waste Licensing Branch 83/02/08
BALOMON, S N Office of State Programs, Director 1p 17302 338

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

7910120435 Notifies that NRC is reviewing NEDD-24708, "Addl Info Required for NRC Staff Generic Rept on BWR Reactors " Encl requests for addl info required by 791001
ROBB, D F TMI-2 Bulletin & Orders Task Force 79/09/28
KEENAN, T D General Electric Operating Plant Owners Group 5pp 17023 155

8301260116 Forwards proprietary OESTR presentation made during NRC-GE 830125 meeting Presentation info withheld (ref 10CFR2 790)
CHARLNEY, J S General Electric Co JSC-006-83 83/01/25
BERLINGER, C Core Performance Branch 1p 16911 330

8301280357 Summary of 830119 meeting w/Westinghouse, Bechtel & utils in Bethesda, MD re reactor coolant pump seal performance
EDISON, O E Licensing Branch 1 83/01/21 YOUNGBLOOD, B J Licensing Branch 1 74pp 17012 183

8302010144 Discusses review of Topical Rept WCAP-9500, "Ref Core Rept 17x17 Optimized Fuel Assembly " Rept acceptable
THOMAS, C D Standardization & Special Projects Branch 83/01/24
RAHE, E P Westinghouse Electric Corp 6pp 16990 09B

8302010360 Discusses review of Topical Repts WCAP-9401/9402, "Verification Testing & Analysis of 17x17 Optimized Fuel Assembly " Repts acceptable
THOMAS, C D Standardization & Special Projects Branch 83/01/24
RAHE, E. P. Westinghouse Electric Corp 6pp 16989 331

8302010421 Requests guidance as to whether Stock Equipment Co should continue w/review of topical rept update in light of unknown costs associated w/NRC review of rept
WILLIAMS, P C Stock Equipment Co 83/01/27 THOMAS, C D Standardization & Special Projects Branch 2pp 16974 258

8302010525 Forwards technical justification for relationship of scram time fraction to scram discharge vol pipe break probability as used in NEDD-22207, "Analysis of Scram Discharge Vol Sys Piping Integrity " DENTON, T J BWR Owners Group BHR00-8303 83/01/28 ECCLESTON, K NRC - No Detailed Affiliation Given 16pp 16977 257

8302020062 Confirms 830112 selection of high priority safety & licensing issues, w/emphasis on rev of App R, DHR & high strength bolting Possible items for discussion at 820209 meeting suggested
NICKELL, R E Electric Power Research Institute 83/01/27 THOMAS, C D Standardization & Special Projects Branch 2pp 17004 339

8302020277 Forwards proprietary version of Rev 3 to Topical Rept EDR-1(P)-A, "Ederer Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes," for review & approval
CLARK, G W Ederer, Inc 83/01/24 THOMAS, C Standardization & Special Projects Branch 1p 96096, 001

8302020327 Summarizes 821105 meeting re design basis of Westinghouse cold overpressure mitigation sys & provides info on App G guidelines requested by NRC
RAHE, E P Westinghouse Electric Corp NS-EPR-2703 83/01/06
SHERON, B W NRC - No Detailed Affiliation Given 2pp 16993 353

8302030256 Discusses Westinghouse proposed modular approach to constructing SAR documents in conjunction w/Westinghouse Advanced PNR licensing control document Modular approach believed to be efficient licensing process
RAHE, E P Westinghouse Electric Corp NS-EPR-2712 83/01/31
EISENHUT, D O Division of Licensing 2pp 17001 248

8302030339 Forwards schedule developed by Westinghouse to implement submittal of extensive PRA of Westinghouse Advanced PWR (WAPWR) Nonproprietary slides presented at 821222 initial meeting re WAPWR PRA encl
RAHE, E P Westinghouse Electric Corp NS-EPR-2711 83/01/31
EISENHUT, D O Division of Licensing 17pp 17006 110

8302040032 Speech entitled "Structural Re-Evaluation of Mark I Containment for Hydrodynamic Loads," to be presented at 830822-26 conference in Chicago, IL
WICHMAN, K NRC - No Detailed Affiliation Given SUBRAMONIAN, N Franklin Institute/Franklin Research Center GONZALEZ, A A Puerto Rico, Univ of 83/02/01 10pp 17044 342

8302040125 Notification of 830202 meeting w/OE & BWR Owners Group in Bethesda, MD to discuss BWR Owners Group submittal, "Analysis of Scram Discharge Vol Sys Piping Integrity " ECCLESTON, K T Operating Reactors Branch 2 83/01/21
VABBALLO, D B Operating Reactors Branch 2 2pp 17043 167

8302040131 Presents overview of Westinghouse Advanced PWR Project Westinghouse intends to submit preliminary design info during current pretendering phase
MEYER, O C Standardization & Special Projects Branch 83/01/26
Standardization & Special Projects Branch 33pp 17043 128

8302080112 Notification of 830209 meeting w/utils & Westinghouse in Bethesda, MD to discuss Westinghouse conceptual design for adopting Westinghouse reactor vessel level instrumentation sys to non-Westinghouse PWRs per TMI Item II F 2
SHEA, J J Operating Reactors Branch 5 83/02/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17105 356

8302080146 Forwards Endorsements 58 & 122 to MAELU Policy MF-59 & NELIA Policy NF-34, respectively Endorsements provide name change from GA Co to GA Technologies & show Valley Pines Assoc as subsidiary
ASHBURN, D J Marsh & McLennan, Inc, M & M Nuclear Consultants, Inc, Div 83/02/01 SALTZMAN, J Assistant Director for State & Licensee Relations 4pp 17057 217

8302080332 Forwards revised organization chart Upon acceptance by NRC, changes will be incorporated into next amend of GIBBAR-17A
KEDDIS, N N Gibbs & Hill, Inc (subs of Dravo Corp.) 83/02/02
HAASS, W P Quality Assurance Branch 1p 17055 360

8302080422 Summary of 830112 meeting w/EPRI in Bethesda, MD re review of licensing issues to be considered in LWR standardization program
MORAN, D H Standardization & Special Projects Branch 83/01/21
Standardization & Special Projects Branch 4pp 17074 323

8302080478 Forwards generic categorization of BWR transients based on frequency of occurrence as required by Reg Guide 1 70, Rev 2 Review & comments requested Working level meeting requested for late June 1976
HUOHEB, E A General Electric Co 76/05/28 DEYOUNG, R C Assistant Director for Light Water Reactors 45pp 17071 276,

8302090176 Responds to 830105 ltr Revised P 1 of Section 0662, "Control of Design," of App A of GA plan for design & fabrication of REA 2023 dry storage casks for spent fuel will be reviewed
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/01/20
RICE, M K. Ridihalgh, Eggers & Associates 1p 17132 104

8302090292 Forwards proprietary WCAP-10271, "Evaluation of Surveillance Frequencies & Out of Svc Times for Reactor Protection Instrumentation Sys " Rept withheld (ref 10CFR2 790) Application for withholding encl
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co 00-86 83/02/03
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17067 007.

--8302090297 Application for withholding proprietary WCAP-10271, "Evaluation of Surveillance Frequencies & Out of Svc Times for Reactor Protection Instrumentation Sys " Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp CAH-83-7 83/02/03
DENTON, H R Office of Nuclear Reactor Regulation, Director, App. 17067 009

NONDOCKETED ITEMS

4

8302090389 Forwards summary of 830112 meeting w/NRC re matls program
Unclear or unresponsive areas concerning needs of reactor
vessel integrity remain issues of special interest
HUBBON, C J Babcock & Wilcox Operating Plants Owners Group
ESB-040 83/01/20 ELLIOT, B J NRC - No Detailed Affiliation
Given 80pp 17067 023

8302090390 Forwards proprietary & nonproprietary versions of Rev 2 to
"Mobile Cement Solidification Sys." Encl rev includes
response to NRC 820623 request for addl info & EQ&O 821129
recommendations Proprietary version withheld Affidavit encl
STAEHR, J P Chem-Nuclear Systems, Inc WPD-5036-3 83/01/31
HILLER, J R Standardization & Special Projects Branch 4pp
17066 301

--8302090394 CNSI-2 R02
Nonproprietary version of Rev 2 to "Mobile Cement
Solidification Sys."
* Chem-Nuclear Systems, Inc 4313-01354-01P 83/01/31 54pp
17066 306

8302090414 Comments on EQO-EA-6109, "Identification & Ranking of
Nuclear Plant Structures, Sys & Components & Graded QA
Guidelines - Draft." Implementation of proposed approach
would have little or no positive effects on plant safety
D'ARDEENNE, W H General Electric Co MFN-022-83 83/02/01
HAASS, W P Quality Assurance Branch 2pp 17071 022

8302090423 Forwards proprietary & nonproprietary apps to WCAP-10170 &
"Functional Requirements for Technical Support Complex" &
"Design Basis Document Plant Safety Status Display"
Application for withholding (ref 10CFR2 790) encl
RAHE, E P Westinghouse Electric Corp NS-EPR-2704 83/01/26
PAULSON, W A Operating Reactors Branch 5 2pp 17066 001

--8302090424 Application for withholding proprietary apps to WCAP-10170,
Rev 1 to ESD-CR&CD-94, "Functional Requirements for
Technical Support Complex" & Rev 1 to ESD-CR&CD-105, "Design
Basis Document Plant Safety Status Display"
WIESEMANN, R A Westinghouse Electric Corp AW-83-9 83/01/26
PAULSON, W A Operating Reactors Branch 9 7pp 17066 003

--8302090426 WCAP-10170 APP
Nonproprietary version of apps to WCAP-1917 "Functional
Requirements for Technical Support Complex"
* Westinghouse Electric Corp 83/01/11 22pp 17066 010

--8302090427 ESD-CR&CD-94 R01
Nonproprietary Rev 1 to "Functional Requirements for
Technical Support Complex"
SCHAEFER, W F, LITTLE, J L Westinghouse Electric Corp
SA&I-ESI-079 81/07/14 26pp 17066 032

--8302090429 ESD-CR&CD-105 R01
Nonproprietary Rev 1 to "Design Basis Document Plant Safety
Status Display"
SCHAEFER, W F, LITTLE, J L Westinghouse Electric Corp
SA&I-ESI-078 81/07/10 41pp 17066 058

8302090475 Forwards proprietary & nonproprietary Addendum 3 to
"Improved Analytical Models Used in Westinghouse Fuel Rod
Design Computations/Application for BWR Fuel Analysis" &
application for withholding proprietary rept per 10CFR2 790
RAHE, E P Westinghouse Electric Corp NS-EPR-2715 83/02/03
THOMAS, C D Standardization & Special Projects Branch, 2pp
17066 103

--8302090484 Submits application for withholding proprietary Addendum 3
to "Improved Analytical Models Used in Westinghouse Fuel
Rod Design Computations/Application for BWR Fuel Analysis,"
per 10CFR2 790 Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp AW-83-10 83/02/03
THOMAS, C D Standardization & Special Projects Branch 9PP.
17066 103

--8302090490 WCAP-8785 ADD 03
Nonproprietary Addendum 3 to "Improved Analytical Models
in Westinghouse Fuel Rod Design Computations/Application for
BWR Fuel Analysis"
EWING, J H, SMITH, W L, KAISER, R S Westinghouse Electric Corp
0299L 6 83/01/31, 20pp 17066 114

8302090477 ANCR-NUREG-1335 V03
"RELAP4/MOD5 Computer Program for Transient Thermal-
Hydraulic Analysis of Nuclear Reactors & Related Sys User
Manual, Vol III Checkout Applications"
* Idaho National Engineering Laboratory, 76/09/30 NRC - No
Detailed Affiliation Given 273pp 17121 001

8302090489 DPST-NUREG-77-2
"User Guide to Input for WRAP - Water Reactor Analysis
Package"
GREGORY, M V Energy, Dept of 77/06/30 NRC - No Detailed
Affiliation Given 362pp 17120 001

8302090929 Forwards Request 1 for addl info on proposed barrier fuel
rev of NEDE-24011-P-A-4, "OE Std Application for Reactor
Fuel" Schedule for submittals requested
THOMAS, C D Standardization & Special Projects Branch 83/02/01
BHCARDOD, D G General Electric Co 3pp 17143 289

8302090932 Forwards Request 1 for addl info on WCAP-10021,
"Westinghouse Wet Annular Burnable Absorber Evaluation
Rept." Schedule for submittal requested
THOMAS, C D Standardization & Special Projects Branch 83/02/01
RAHE, E P Westinghouse Electric Corp 5pp 17108 311

8302180301 Forwards proprietary corrected P 2-17 of "Generic Safety
Evaluation for Low-Low Set Logic & Lowered MSIV Water
Level Trip." Page withheld
PFEFFERLEN, H C General Electric Co MFN-027-83 83/02/08
VASSALLO, D B Operating Reactors Branch 2 1p 17156 298

8302150664 Forwards Endorsements 24, 69, 70, 19 & 53 to NELIA Policies
NF-24B, NF-182 & MAELU Policies MF-101 & MF-61, respectively
Endorsements 1-3 for Certificates M-69, N-69, M-22, N-22, M-23,
N-23, M-24 & N-24 also encl
LAWSON, L T Duke Power Co 83/02/10 SALTZMAN, J Antitrust &
Economic analysis Branch (Utility Finance) 120pp 17153 314

8302160152 Informs that BAW-10154, "Small Break LOCA ECCS Evaluation
Model," does not contain proprietary info per B21101 ltr
Restrictions on distribution withdrawn
TAYLOR, J H Babcock & Wilcox Co 83/02/10 BERGOREN, J B
Standardization & Special Projects Branch 1p 17162 214

8302160305 Forwards addl documentation for high pressure version
(HP-BASIC) of emergency response guidelines, for review
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co 00-85 83/02/09
EISENHUT, D G Division of Licensing 1p 17163 060

--8302160314 Emergency Action Guideline ECA-4, "Response to Multiple
Steam Generator Depressurization"
* Westinghouse Electric Corp 82/11/01 63pp 17163 061

--8302160316 Emergency Response Guideline ECA-5, "Loss of Emergency
Coolant Recirculation"
* Westinghouse Electric Corp 82/11/01 33pp 17163 120

--8302160320 Emergency Response Guideline ES-2 3, "Safety Injection
Termination Following Excessive RCS Cooledown"
* Westinghouse Electric Corp 82/11/01 26pp 17163 153

8302170164 Forwards "Series 600 Actuator Dynamic Analysis Using
STARDYNE Computer Code W/Mode/Frequency Capability" &
ASME B1-DET-32 "Dynamic Evaluation of Nuclear MSIV
Actuator"
WEISZ, D A Gulf & Western Industries, Inc 83/02/08 THOMAS, C D
Standardization & Special Projects Branch 13pp 17180 293

--8302170168 ER-81-28
"Series 600 Actuator Dynamic Analysis Using STARDYNE
Computer Code W/Mode/Frequency Capability"
PATBALIDES, N M, WEISZ, D A Gulf & Western Industries, Inc
81/07/27, 28pp, 17180 268

--8302170174 B1-DET-32
Paper entitled "Dynamic Evaluation of Nuclear MSIV
Actuator," presented at B10920-23 design engineering
technical conference in Hartford, CT
PATTEN, A J Gulf & Western Industries, Inc. PATTEN, A J, America
Society of Mechanical Engineers 81/09/20 8pp 17180 296

8302180243 Forwards proprietary "Stability Evaluation of BWR Cores
Sensitivity Analyses" Affidavit to support withholding of
rept from public disclosure encl Rept withheld
(ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc, (subs of Exxon Corp)
JCC 030 83 83/02/15 THOMAS, C D Standardization & Special
Projects Branch 4pp 17210 221

8302180336 Forwards proprietary Rev 2 to "RDEX2 Fuel Rod Thermal-
Mechanical Response Evaluation Model," containing minor
model refinements per NRC review of initial rept Rept
withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC 028 83 83/02/16 THOMAS, C D Standardization & Special
Projects Branch 1p 17210 220

NONDOCKETED ITEMS

8302220142 Comments on Science Applications, Inc final draft, "Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events," per Generic Ltr 82-32 & 821213 request Rept conclusions supported
TAYLOR, J H Babcock & Wilcox Co OL-82-32 83/02/10
EISENHUT, D G Division of Licensing 7pp 17233 109

8302220281 Notices of organizational changes within engineering svcs segment of util power generation div Changes have no impact on QA program commitments in BAW-10096A, Rev 4
TAYLOR, J H Babcock & Wilcox Co 83/02/09 HAAAS, W P Quality Assurance Branch 1p 17230 144

8302220379 Forwards "Review Plan for Upgrading Licensed Power of PWR Plant," describing vendor position re methodology & evaluations required to support upgrading application & proposing basis for performing evaluations
RAHE, E P Westinghouse Electric Corp NS-EPR-2179 83/02/11
THOMAS, C O Standardization & Special Projects Branch 1p 17232 302

--8302220384 WCAP-10263
"Review Plan for Upgrading Licensed Power of PWR Power Plant"
MCFETRIDGE, R H, MARCHASS, R T, FAAS, R H Westinghouse Electric Corp 83/02/11 34pp 17232 304

8302220150 Forwards tape containing collapsed cross-sections for 9x9 equilibrium reload core (one dimensional) for stability audit calculation input, per LA Nielsen 820208 ltr Listing of cross-sections encl W/o tape
NIELSEN, L A Exxon Nuclear Co, Inc (subs of Exxon Corp.) 83/02/16 SCHWENK, G A Core Performance Branch 4pp 17243 230

8302220155 Forwards tape containing collapsed 2-dimensional cross-sections for 9x9 equilibrium reload core, per 820208 ltr. Listing of cross-sections on tape encl W/o tape
NIELSEN, L A Exxon Nuclear Co, Inc (subs of Exxon Corp.). 83/02/16 SCHWENK, G A Core Performance Branch 14pp 17243 239

8302220221 Requests completion of review of NEDE-22-148-P "Extended Burnup Evaluation Methodology," by June 1983 rather than Aug 1983 to assure that fuel thermal-mechanical design analysis for new fuel calculated w/approved methods
CHARNEY, J S General Electric Co JSC-015-83 83/02/16
BERLINGER, C H Core Performance Branch 1p 17243 158

8302220327 Forwards proprietary "Response to NRC Request Number 3 for Add'l Info re Rept XN-NF-79-6(P), Rev 1," in response to NRC 820210 request Response withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp.) JCC 034 B3 83/02/18 THOMAS, C O Standardization & Special Projects Branch 1p 17248 001

8302220407 Requests completion of review of application of thermal-mechanical design model & approval of amend to NEDE-24011-P-A by 830501
CHARNEY, J S General Electric Co JSC-013-83 83/02/15
BERLINGER, C H Core Performance Branch 1p 17248 154

8302220480 Forwards proprietary "Util Design Review Panel Evaluation Rept D2/D3 Steam Generator Design Mod." Mod to D2/D3 steam generator preheater section can be installed & steam generator can operate safely Rept withheld (ref 10CFR2 790)
BLACKLEY, S K Design Review Panel 83/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 4pp

8302220566 Forwards proprietary & nonproprietary "Associated Technologies, Inc Vol Reduction & Bitumen Solidification Sys." Proprietary version withheld
DAY, J E Associated Technologies, Inc CH-045-002 83/02/15
THOMAS, C O Standardization & Special Projects Branch 4pp 17263 224

--8302220574 ATI-VR-001-NP
Nonproprietary "Associated Technologies, Inc Vol Reduction & Bitumen Solidification Sys."
* Associated Technologies, Inc 81/01/31 200pp, 17263 231

8302220632 Forwards proprietary & nonproprietary "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod." & Westinghouse 830114 application for withholding proprietary info Proprietary rept withheld (ref 10CFR2 790).
BLACKLEY, S K Design Review Panel 83/01/19 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 2pp 17249 081

82230640 Submits application for withholding proprietary "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod." per 10CFR2 790 Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp CAW-83-2 83/01/14
EISENHUT, D O Division of Licensing 8pp 17249 082

--8302220650 Nonproprietary "Util Design Review Panel Evaluation Rept D2/D3 Steam Generator Design Mod."
* Design Review Panel. 83/01/31 190pp 17249 091

8302220680 Forwards add'l documentation on SAFER evaluation model, NEDE-23785-1-P, qualification & application results All OE documentation commitments completed Documentation withheld (ref 10CFR2 790)
PFEFFERLE, H C General Electric Co MFN-034-83 83/02/16
SHERON, B Reactor Systems Branch 5pp 17263 221

8302220298 Forwards proprietary responses to questions from Reactor Fuels Section of Core Performance Branch re OE proposed barrier fuel amend to NEDE-24011-P-A-4 Responses withheld (ref 10CFR2 790)
CHARNEY, J S General Electric Co MFN 037-83 83/02/22
THOMAS, C O Standardization & Special Projects Branch 1p 17273 001

8302220312 Forwards proprietary preheat steam generator D2/D3 design mod evaluation package addendum 830114 suppl Nonproprietary version forthcoming Encl withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2713 83/02/02
EISENHUT, D O NRC - No Detailed Affiliation Given 3pp 17273 002

--8302220316 Submits application for withholding proprietary preheat steam generator D2/D3 design mod evaluation package addendum 830114 suppl from public disclosure
WIESEMANN, R A Westinghouse Electric Corp, AW-83-3 83/01/14
EISENHUT, D O NRC - No Detailed Affiliation Given 8pp 17273 005

8302220053 NUREG/CR-2675 V03
RELEVANCE OF BIOTIC PATHWAYS TO REGULATION OF NUCLEAR WASTE DISPOSALS Topical Report On Reference Eastern Humid Low-Level Sites
MCKENZIE, D. H., CADWELL, L. L., EBERHARDT, L. E Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2377 PNL-4241 83/01/31 Division of Health, Siting & Environment 34pp Available at NRC \$4 75 17300 220

8302220149 Summary of 830121 meeting w/Westinghouse re reactor coolant pump seal performance (generic)
EDISON, G E Licensing Branch 1 83/02/04 Licensing Branch 1 3pp 17298, 353

8302220130 Approves 821111 application & 821029 affidavit requesting withholding of topical rept "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste in Accordance w/10CFR61 Regulations," per 10CFR2 790
HAWKINS, E Low Level Waste Licensing Branch 83/01/26 TUIE, P T Waste Management Group, Inc 3pp 17314 264

8302220151 Forwards revised topical rept evaluation of CNSI-2 [4313-01354-01], "Mobile Cement Solidification Sys."
RANDOLPH, P D EOKO, Inc 83/02/17 LEE, J. Y Effluent Treatment Systems Branch 3pp 17305 324

--8302220164 Topical rept evaluation of CNSI-2 [4313-01354-01], "Mobile Cement Solidification Sys." Rept acceptable
* EOKO, Inc 83/02/17 34pp 17305 327

8302220546 Forwards nonproprietary Vols 1 & 2, "Westinghouse Preheat Steam Generator D2/D3 Design Mod Evaluation Package"
RAHE, E P Westinghouse Electric Corp NS-EPR-2714 83/02/02
EISENHUT, D O Division of Licensing 2pp 17315, 001

--8302220594 Vols 1 & 2, "Westinghouse Preheat Steam Generator D2/D3 Design Mod Evaluation Package"
* Westinghouse Electric Corp 82/12/31 1,082pp 17315 002

WASTE 1407 NUCLEAR WASTE MANAGEMENT

8302010043 Designates K Hamill as NRC representative on technical panel at Grand Junction & Rifle Site 830207-09 scoping meetings
HAWKINS, E F Low Level Waste Licensing Branch, 83/01/24
MORLEY, J A Energy, Dept of 1p 16990 308,

8302020375 Forwards hydrogeology & waste package info transmitted to DOE-RL by HJ Miller on 821123 Review of package determined info not cleared for release Info restricted to internal use only, One oversize drawing encl
OLSON, O L Energy, Dept of 82/12/23 WRIGHT, R. J. High Level Waste Technical Development Branch, 805pp 17009 091,

--8302020376 "Basalt Operating Procedure Drilling"
LEDDERWOOD, R. K. Energy, Dept of 82/06/30 10pp 17010 237

NONDOCKETED ITEMS

- 8302020377 "Basalt Operating Procedure General Hydrologic Field Testing Procedures"
JACKSON, R L, LEONHART, L S Energy, Dept of 82/06/30 49pp
17010 284
- 8302020378 SD-BWI-TI-073
"Analysis of Two-Well Tracer Tests W/Pulse Input"
GELHAR, L W Rockwell International Corp 82/04/28 67pp
17010 312
- 8302020380 RSD-BWI-OP-035
"Deep Borehole Stratigraphic Correlation Charts & Structure Cross Sections," supporting Document BWIP data package
One oversize drawing encl
CROSS, R W Rockwell International Corp 82/01/15 167pp
17011 009
- 8302090482 Forwards "Rn-222 Rept for Nov 1982"
CAIN, J Cotter Corp 00044 83/01/12 HAZLE, A J Colorado, State of 2pp 17131 359
- 8302090487 "Rn-222 Rept for Nov 1982"
* Cotter Corp 00044 83/01/12 1p 17131 361
- 8302090492 Forwards "Breathing Zone Rept for Airborne Particulates, 1982"
CAIN, J Cotter Corp 00043 83/01/12 HAZLE, A J Colorado, State of 2pp 17131 354
- 8302090495 "Breathing Zone Rept for Airborne Particulates, 1982"
* Cotter Corp 00043 83/01/12 3pp 17131 356
- 8302170023 Forwards "Water Quality Rept for Nov 1982" Corrections to Sept 1982 water quality rept listed
CAIN, J Cotter Corp 00061 83/01/25 HAZLE, A J Colorado, State of 2pp 17191 026
- 8302170026 "Water Quality Rept for Nov 1982"
* Cotter Corp 00061 83/01/21 4pp 17191 028
- 8302170031 Forwards "Water Quality Rept for Dec 1982" Change to Nov 1982 water quality rept noted
CAIN, J Cotter Corp 00066 83/02/01 HAZLE, A J Colorado, State of 2pp 17191 035
- 8302170035 "Water Quality Rept for Dec 1982"
* Cotter Corp 00066 83/02/01 4pp 17191 037
- 8302170039 Forwards "Breathing Zone Summary Rept for CY83"
CAIN, J Cotter Corp 00068 83/02/01 HAZLE, A J Colorado, State of 2pp 17191 047
- 8302170043 "Breathing Zone Summary Rept for CY83"
* Cotter Corp 00068 83/02/01 2pp 17191 049
- 8302180522 Forwards "General Air Survey Summary for Third Quarter 1982"
CAIN, J Cotter Corp 20872 82/11/16 HAZLE, A J Colorado, State of 2pp 17221 258
- 8302180524 "General Air Survey Summary for Third Quarter 1982"
* Cotter Corp 20872 82/11/16 3pp 17221 260
- 8302220194 Forwards "General Air Survey Summary for First Three Quarters of 1982"
CAIN, J Cotter Corp 20854 82/11/11 HAZLE, A J Colorado, State of 2pp 17234 037
- 8302220203 "General Air Survey Summary for First Three Quarters of 1982"
* Cotter Corp 20854 82/11/08 3pp 17234 039
- 8302240027 Comments on "Evaluation of Occupational & Environ Exposure to Radon & Radon Daughters in US" Rept confirms assumption that radiation-induced lung cancer is stochastic process w/no threshold
QUONOLLI, O N Low Level Waste Licensing Branch 83/02/07
FOULKE, J Health Effects Branch 2pp 17284 354
- 8302240037 Notifies that branch has no comments on EIS re disposal of submarine reactor plants
FEHRINGER, D J High Level Waste Licensing Management Branch 83/01/28
REHFELDT, W R High Level Waste Licensing Management Branch 1p 17268 356
- 8302240042 Forwards info re EQLO low level waste data base
WIDMAYER, D A Low Level Waste Licensing Branch 83/01/24
QOLDBERG, F ADP Systems Development Branch 4pp 17268 352
- 8302240317 Seventh status rept for Edgemont, SD offsite cleanup action program as of 821231 Radiological surveys encl
FLORY, C Low Level Waste Licensing Branch 83/02/01 HAWKINS, E
Low Level Waste Licensing Branch 6pp 17284 346
- 8302240323 Forwards State of SC 830106 & State of NV 830111 comments on "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste"
SCHEIDER, K H Office of State Programs, Director 83/01/26
JOHNSON, T Division of Waste Management 1p 17290 181
- 8302240327 Comments on "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste," in response to NRC 821213 ltr
SHEAN, W H South Carolina, State of 83/01/06 NUSSBAUMER, D
Office of State Programs, Director 2pp 17290 182
- 8302240338 Comments on "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste"
VADEN, J Nevada, State of 83/01/11 NUSSBAUMER, D Office of State Programs, Director 1p 17290 184
- 8302240342 Trip rept of 821101-04 visit to Matls Research Soc 1982 annual meeting in Boston, MA
HICK, E A High Level Waste Licensing Management Branch 83/02/01
COCK, F R High Level Waste Licensing Management Branch 11pp 17290 138
- 8302240347 Summary of Nov 1982 annual meeting of Matls Research Soc & review of BNL high level waste research program
COCK, F R High Level Waste Licensing Management Branch 83/01/28
BELL, M J High Level Waste Licensing Management Branch 3pp 17288 314
- 8302240349 Proceedings of Sixth Intl Symposium on Scientific Basis for Nuclear Waste Mgt on 821101-04
BROOKINGS, D G New Mexico, Univ of 82/11/01 30pp 17288 317
- 8302240351 Summary of 830118 meeting of EPA Science Advisory Board in Crystal City, VA re description of High Level Radwaste Disposal Subcommittee purpose & membership
FEHRINGER, D J High Level Waste Licensing Management Branch 83/01/28
KNAPP, M R High Level Waste Licensing Management Branch 4pp 17290 001
- 8302240352 Forwards branch technical position on waste form
JOHNSON, T C Low Level Waste Licensing Branch 83/02/14
BROWNING, R E Division of Waste Management 13pp 17289 347
- 8302240354 Comments on JGC-TR-001-P which describes drum mixer process for solidification of certain reactor wastes Rept has insufficient info on waste properties to make judgement on ability of process to satisfy requirements
LOHAUS, P Low Level Waste Licensing Branch 83/01/26 GAMMILL, W P
Effluent Treatment Systems Branch 1p 17289 360
- 8302240356 Forwards BNL-NURE0-30247, "Characterization of Radioactive Large Quantity Waste Package of Union Carbide Corp" & NURE0/CR-2102, "Evaluation of Trench Subsistence & Stabilization at Sheffield Low Level Radwaste" w/o encl
WIDMAYER, D A Low Level Waste Licensing Branch 83/01/25
GUERRERO, P Environmental Protection Agency 1p 17290 135
- 8302240383 Forwards environ assessment for remedial actions at Spook Site in Converse County, WY, incorporating responses to comments received on draft circulated in Sept 1982 w/o assessment details
MORLEY, J A Energy, Dept of 83/01/31 SCARAND, R NRC - Nn
Detailed Affiliation Given 2pp 17289 300
- 8302240385 Forwards schedule for UMRAP environ assessments Areas re licensing of inactive sites for further discussion listed
LECHEL, D Jacobs Engineering Group, Inc 83/01/14 HAMILL, K NRC
- No Detailed Affiliation Given 2pp 17289 298
- 8302240386 Forwards listing of several computer inputs in response to 830124 telcon re implementation of GENDVM Program ran unsuccessfully four times Assistance requested to make effective use of GENDVM in performance assessments
WEBER, M F High Level Waste Licensing Management Branch 83/01/28
CRANNELL, R Sandia Laboratories 4pp 17289 294
- 8302240388 Advises of affirmative vote on proposed bylaw changes dtd 830117
BELL, M J High Level Waste Licensing Management Branch 83/02/15
SEEFELDT, W B Argonne National Laboratory 1p 17289 290

NONDOCKETED ITEMS

8302240374 Forwards abstract or paper to be presented at American Inst of Chemical Engineers 831031-1104 meeting in Washington, DC
BELL, M J High Level Waste Licensing Management Branch 83/02/16
CRANDALL, J L E I du Pont de Nemours & Co, Inc 2pp 17289 287

8302250091 Advises that draft environ assessment for DOE proposed remedial action at inactive Mexican Hat U Mill Tailings Site will be forwarded by Ford, Bacon & Davis Comment should be provided to listed individuals
MORLEY, J A Energy, Dept of 83/01/31 HAWKINS, E Division of Waste Management 1p 17298 290

8302250067 Forwards branch technical positions re Part 61 per telcon W/o encl
LOHAUS, P Low Level Waste Licensing Branch 83/01/31 SCHNEIDER, K Office of State Programs, Director 2pp 17302 357

8302250071 Forwards "Results of Test Program for Solidification of Contaminated Waste Lubricating Oils," for review & comments by 830318 W/o encl
JOHNSON, T C Low Level Waste Licensing Branch 83/02/03
ORELLA, A W Director's Office, Office of Inspection and Enforcement
GAMMILL, W Effluent Treatment Systems Branch 1p 17302 356

8302250077 Requests assistance in obtaining repts re low level waste disposal from States of CA, IL, NH, NM, PA, TN & VA
HAWKINS, E F Low Level Waste Licensing Branch 83/02/08
SALOMON, S N Office of State Programs, Director 1p 17302 338

8302250122 NUREG/CR-2983
SELECTED HYDROLOGIC AND GEOCHEMICAL ISSUES IN SITE CHARACTERIZATION FOR NUCLEAR WASTE DISPOSAL Flood Basalts At The Hanford Reservation
ARIHAN, C L, DELANY, J M, LONG, J C S Laurence Berkeley Laboratory
FIN B-3109 LBL-15029 83/01/31 Division of Waste Management 180pp Available at NRC 46 50 17301 006

8302280130 Approves 82111 application & 821029 affidavit requesting withholding or topical rept "RADMAN, Computer Code to Classify & Document Packaged Low Level Waste in Accordance W/10CFR61 Regulations," per 10CFR2 790
HAWKINS, E Low Level Waste Licensing Branch 83/01/26 TUIITE, P T Waste Management Group, Inc 3pp 17314 264

8302280144 Ack receipt of topical rept "Results of Test Program for Solidification of Contamination Waste Lubricating Oils," transmitted by 821213 ltr Tentative schedule for review encl
LOHAUS, P H Low Level Waste Licensing Branch 83/01/27
IRVING, B A Viken Industries, Inc 2pp 17322 206

8302280190 Declines, on behalf of JB Martin, invitation to prepare article on nuclear waste mgt for book entitled, "Natural Resource Conservation"
BELL, M J High Level Waste Licensing Management Branch 83/02/04
OWEN, D S Wisconsin, Univ of, Eau Claire 1p 17322 168

EXPORT, EXPORT AND IMPORT LICENSES

8302010685 License for Mitsui & Co, Inc to export 19 71 U-235, contained in 943 3 g U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MBK/PHC 83/01/24 2pp 16989 349

702010687 License for C Itoh & Co to export 20 pieces Zircaloy tubing to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards WE-15-(4) 83/01/25 1p 16989 348

010688 License for Westinghouse to export one fission chamber, del WL-6376A, to The Netherlands
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE-10502 83/01/25 1p 16989 344

2010693 License for Aldrich Chemical Co to export 40 kg deuterium ride to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 31/82 83/01/27 1p 16989 347

2010694 Amend 4 to Missho-Iwai American Corp export license, extending expiration date to 831001
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HMM-0184 83/01/24 1p 16989 346

10695 Amend 2 to Edlow Intl Co export license, authorizing resale of sealed light sources
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/21 1p 16989 345

8302010696 Amend 1 to GE export license, extending expiration date to 860701
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-004-B3 83/01/24 1p 16989 343

8302020160 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/21 GRIFFIN, J A Energy, Dept of 1p 16999 247

8302020164 Forwards application for export license for minor nuclear export Ltr of assurance required
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/26 GRIFFIN, J A Energy, Dept of 1p 16999 245

--8302020169 Application for license to export 15 g U dioxide powder to Spain
WILSON, B D General Electric Co BDW-83-006 83/01/17 1p 16999 246

8302020313 Forwards application for license to export 6,834 kg U, as enriched U hexafluoride, to Japan
HATTORI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) 83/01/18 Assistant Director for Export/Import & International Safeguards 1p 16998 360

--8302020320 Application for license to export 6,834 kg U, as enriched U hexafluoride, to Japan
HATTORI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) MBK-H2-R6 (B) 83/01/18 1p 16998 361

8302020337 Forwards application for license to export 21,294 kg U, as enriched U hexafluoride, to Japan
HATTORI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) 83/01/18 Assistant Director for Export/Import & International Safeguards 1p 16998 358

--8302020340 Application for license to export 21,294 kg U, as enriched U hexafluoride, to Japan
HATTORI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co, Ltd) MBK-H2-R6 (A) 83/01/18 1p 16998 359

8302020344 Submits addl info per 830112 application for amend to export license Addl company requested purchase of licensed matl, bringing amend request total of 40,000 Ci tritium Immediate issuance of amend requested
SHAW, A Edlow International Co 83/01/20 HEMBRY, A Assistant Director for Export/Import & International Safeguards 1p 16999 116

--8302020359 Submits addl info per 830112 application for amend to export license Saunders-Roe normally receives bulk tritium from GRNL in package not acceptable to new United Kingdom transportation regulations
SHAW, A Edlow International Co 83/01/17 HEMBRY, E Assistant Director for Export/Import & International Safeguards 1p 16999 117

--8302020358 Submits application to amend export license, permitting resale of 20,000 Ci tritium in bulk form to Saunders-Roe for production of sealed light sources
SHAW, A Edlow International Co 83/01/12 HEMBRY, E Assistant Director for Export/Import & International Safeguards, 1p 16999 118

8302020362 Forwards application for license to export 20 pieces of Zircaloy fuel tube to Japan
YUKOTO, H C Itoh & Co (America), Inc 83/01/20 HEMBRY, E O NRC - No Detailed Affiliation Given 1p 17012 181

--8302020364 Application for license to export 20 pieces of Zircaloy fuel tube to Japan
YUKOTO, H C Itoh & Co (America), Inc WE-15-(4) 83/01/20 1p 17012 182

8302020366 Forwards application for export license for minor nuclear export Ltr of assurance required
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/25 GRIFFIN, J A Energy, Dept of 1p 17012 179

--8302020368 Application for license to export fully clad, irradiated fuel, including RISD 12 test segments to Denmark & HALDEN 22 test segments to Norway
WILSON, B D General Electric Co BDW-005-B3 83/01/06 1p 17012 180

NONDOCKETED ITEMS

8302020369 Application for license to export 3 units Type WL-23744 BF3 proportional counters to Switzerland
POCHAL, W F Westinghouse Electric Corp ZE 83/01/21 1p
16999 362

8302020370 Application for license to export 0.002 g Ca-252 to India
BENSON, E Isotope Products Laboratories W/O 10274 83/01/21 1p
16999 361

8302020371 Application for license to export 16 pieces fuel tube machinery for nuclear power reactor to Japan
* C Itoh & Co (America), Inc WC-15(04-2) 83/01/26 1p
16999 360

8302020372 Forwards application for amend to export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/24 GRIFFIN, J A Energy, Dept of 1p
16999 358

--8302020373 Requests amend to export license, adding intermediate consignee & 1,300 kg natural enrichment U as U dioxide powder
WILSON, B D General Electric Co BWH-001-83 83/01/06
WRIGHT, D L Assistant Director for Export/Import & International Safeguards 1p 16999 359

8302020508 Informs that License XSNM-1986 may be issued No mat'l changed circumstances since issuance of License XSNM-1987
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/18 Assistant Director for Export/Import & International Safeguards 1p 16999 278

8302020510 Advises of no objection to request for amend to export license, allowing resale of 40,000 Ci bulk tritium to United Kingdom, provided re-export not authorized & resales limited to 100,000 Ci
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/24 Assistant Director for Export/Import & International Safeguards 1p 16999 277

8302030007 Advises of issuance of license to export 20 Zircaloy tubing pieces, as test samples, to Japan w/o normal 15-day waiting period Proposed export meets Atomic Energy Act requirements
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/25 Assistant Director for Export/Import & International Safeguards 1p 17028 360

8302030071 Forwards application for export license for minor nuclear export Ltr of assurance required
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/25 GRIFFIN, J A Energy, Dept of 1p
17013 359

8302030083 Requests Executive Branch position re Transnuclear, Inc application to amend export license application, increasing quantity of mat'l from 10.8 kg U-235, contained in 54 135 kg U, to 12.956 kg U-235, contained in 64 742 kg U
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/24 STQIBER, C R State, Dept of 1p 17028 340

--8302030087 Requests amend to export license application, increasing quantity of mat'l from 10.8 kg U-235, contained in 54 135 kg U, to 12.956 kg U-235, contained in 64 742 kg U
HANNETT, B A Transnuclear, Inc 83/01/18 MOORE, N Assistant Director for Export/Import & International Safeguards 1p
17028 341

8302030111 Submits application to amend import license, increasing quantity from 150 kg U, containing 5.3 kg U-235 enriched to 3.5%, to 25,225 kg U, containing 980 kg U-235 enriched to 3.6% max & extending expiration date to 901231
HERSCH, H M Westinghouse Electric Corp MMH-225 83/01/17
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 17029 356

8302070158 Advises of forthcoming spent fuel shipments from AECL Facility at Chalk River to DOE Savannah River Plant
Schedule & port of entry info withheld (ref 10CFR2 790)
DANESE, F L Nuclear Assurance Corp 21775 82/09/29 GDDY, A Region 1, Office of Director 1p 17065 354

8302070184 Informs that spent fuel shipments from Chalk River, Canada to DOE Savannah River Facility, identified in 820929 ltr, suspended due to State of NY action
DANESE, F L Nuclear Assurance Corp 21518 82/10/12 GDDY, A Region 1, Office of Director 1p 17062 336

8302070308 Forwards IE Safeguards Insp Rept 110-02838/83-01 on 830113 No noncompliance noted
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 83/01/31 MCNDEN, T Mitsui & Co (U S A), Inc (Subs Mitsui & Co, Ltd) 2pp 17029 125

--8302070311 IE Safeguards Insp Rept 110-02838/83-01 on 830113 No noncompliance noted Major areas inspected verification of shipping drum identification & tamper seal numbers to packing lists & exam of shipping container
WEIDF, A, NELSON, G, PANG, F Division of Radiological Safety Safeguards Program 83/01/28 3pp 17029 127

8302080074 Confirms 830703 telcon cancelling Shipments 9, 10 & 11 on 820831 schedule
DANESE, F L Nuclear Assurance Corp 21522 83/01/10 GDDY, A Region 1, Office of Director 1p 17104 102

8302080443 Requests Executive Branch position re Transnuclear, Inc application for license to export 23.3 kg U-235, enriched to 93.3%, to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/25 STQIBER, C R State, Dept of, Bureau of Oc & Internatl Environ & Scientific Affairs 1p 17108 110

--8302080446 Forwards application for license to export 23.3 kg U-2 enriched to 93.3%, to France
HANNETT, B A Transnuclear, Inc TNP-430 83/01/17 MOORE, N Office of International Programs, Director 1p 17108 111

--8302080448 Application for license to export 23.3 kg U-235, enriched 93.3%, to France End use statement encl
HANNETT, B A Transnuclear, Inc TNP-430 83/01/18 5pp
17108 112

8302090177 Forwards applications for export licenses for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/01/28 GRIFFIN, J A Energy, Dept of 1p
17132 103

8302090180 License for Westinghouse to export one proportional counter Model WL-23773, to Belgium
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE 20603 83/01/31 1p 17132 077

8302090198 License for Westinghouse to export four compensated ionization chambers, Model WL-23196, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE 60260 83/01/31 1p 17132 078

8302090201 Ltr of assurance re Transnuclear, Inc 830114 application export 24 kg U-235, contained in 600 kg U, to France
MARCHEL, J European Communities, Commission of TN-429 83/01/ GRIFIN, J A Energy, Dept of 1p 17132 077

8302090202 License for Westinghouse to export one penetration conversion unit for electrical feedthrough, Model E-404, to Switzerland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE 10499 83/01/31 1p 17132 076

8302090208 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/03 GRIFFIN, J A Energy, Dept of 1p
17132 067

8302090212 Requests Executive Branch position re DOE request for ai to application for license to export Pu W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/03 STQIBER, C R State, Dept of, Bureau of D & Internatl Environ & Scientific Affairs 1p 17132 064

8302090216 Amend 1 to DOE/Rockwell Hanford Operations export license extending expiration date to 850601 & increasing quantity to 13.1 kg U-235, contained in 445 kg U, for export to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BR-1593 83/02/03 1p 17132 063

8302090220 Amend 4 to OA Technologies, Inc export license, changing of license & increasing amount to 399 g U-235, for export to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-954 83/01/14 1p 17132 062

8302090231 License for GE to export 1,202 kg U-235, contained in 40,920 kg U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BWH-02-093 83/02/03 1p 17131 362

NONDOCKETED ITEMS

- 8302090235 License for Liquid Carbonic Corp to export 10,000 liters (1 656 kg) deuterium to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards G O 7046 83/02/01 1p 17119 181
- 8302090267 Executive Branch position re Edlow Intl Co application to export 961,632 kg natural U in form of U ore concentrate or U hexafluoride to EURATOM member states License should be granted
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 00410 83/01/27 SHEA, J R Office of International Programs, Director 3pp 17117 339
- 8302090273 Ltr of assurance re export of 1,202 kg U-235, contained in 40,920 kg U to Japan
SHIRAKAWA, T Japan, Govt of, 83/01/21 GRIFFIN, J A Energy, Dept of 1p 17117 338
- 8302090277 Questions whether Indonesia radioisotope plant could be designed to use low enriched U instead of highly enriched U
DARDIS, J O State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 83/01/27 MOWRY, W R GA Technologies, Inc /General Atomic Co 3pp 17121 350
- 8302090470 Informs that License XSNM-1994 may be issued No matl changed circumstances since issuance of License XSNM-1987
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/02/03 Assistant Director for Export/Import & International Safeguards 1p 17121 274
- 8302090526 Application for amend to application for license to export Pu & U to Switzerland DOE/Switzerland carbide fuel development agreement encl
CEJA, S N Energy, Dept of 83/01/24 MOORE, N Office of International Programs, Director 19pp 17108 316
- 8302160129 Application for license to export 97,050 lb Zircaloy trex to West Germany
AERNI, B L Teledyne Wah Chang Albany 2625 (JFM) 83/01/28 1p 17160 249
- 8302160141 Application to amend export license, increasing quantity of U-235 from 471 25 kg U-235, contained in 14,800 kg U to 928 25 kg U-235, contained in 28,600 kg U & from 0 033 kg, contained in 1 kg U to 0 066 kg, contained in 2 0 kg U
HAYNETT, B A Transnuclear, Inc RDU 39A 83/01/26 MOORE, N Office of International Programs, Director 2pp 17160 247
- 8302200508 Requests Executive Branch position re Pechiney Ugine Kuhlmann Development, Inc application for license to export 30 kg U enriched to 19 75% U-235 to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 STOLBER, C R State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 1p 17234 347
- 8302200515 Forwards application for export license for minor nuclear export ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 GRIFFIN, J A Energy, Dept of 1p 17234 346
- 8302200523 Clarifies 821110 application to amend export license, increasing quantities of U-235, U-233, Th-232 & Pu-237
MOWRY, W R GA Technologies, Inc /General Atomic Co IEL-4041 83/02/07 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 2pp 17235 357
- 8302200528 Amends 810904 ltr of assurance re export of low enriched U to Indonesia, increasing quantity to 12 956 kg U-235, contained in 64 742 kg U
MARCHEL, J European Communities, Commission of 83/02/03, GRIFFIN, J A Energy, Dept of 1p 17234 357
- 8302200533 Amends 820211 ltr of assurance, increasing quantity to 928 25 kg U-235, contained in 28,600 kg U & 1 kg U as sample
MARCHEL, J European Communities, Commission of 83/01/31 GRIFFIN, J A Energy, Dept of 1p 17234 352
- 8302200540 Informs that approx 1,300,000 lb U-308 shipped to United Kingdom for conversion & subsequent return to USA for enrichment will be enriched within European Community for use in West Germany
MARCHEL, J European Communities, Commission of AGN/464 83/02/03 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 17234 351
- 8302200545 Advises of issuance of Amend 1 to Reuter-Stokes export license w/o customary 15-day waiting period, due to urgency of export
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/10 Assistant Director for Export/Import & International Safeguards 1p 17234 350
- 8302240001 Forwards application for blanket license to import 5 million kg U, containing 250,000 kg U-235, from various countries
EINBUUND, B R New York Nuclear Corp 83/02/04 MOORE, R N Assistant Director for Export/Import & International Safeguards 1p 17287 337
- 8302240002 Application for license to import 5 million kg U, containing 250,000 kg U-235, from various countries
EINBUUND, B R New York Nuclear Corp 83/02/04 1p 17287 338
- 8302240140 Ltr of assurance to OE 830106 application for license to export low enriched U & Pu to Denmark
MARCHEL, J European Communities, Commission of 83/02/07 GRIFFIN, J A Energy, Dept of 1p 17268 254
- 8302240147 Informs that License XSNM-2002 may be issued No matl changed circumstances since issuance of License XSNM-1982
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/20 Assistant Director for Export/Import & International Safeguards 1p 17288 276
- 8302240152 Informs that License XSNM-2001 may be issued No matl changed circumstances since issuance of License XSNM-1982
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/20 Assistant Director for Export/Import & International Safeguards 1p 17288 275
- 8302240158 Informs that License XSNM-1995 may be issued No matl changed circumstances since issuance of License XSNM-1994
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/02/07 Assistant Director for Export/Import & International Safeguards 1p 17288 274
- 8302240161 Ltr of assurance re export of 1,016 kg U-235, contained in 33,079 kg U to Japan
SHIRAKAWA, T Japan, Govt of, 83/02/01 GRIFFIN, J A Energy, Dept of 1p 17288 273
- 8302240165 Submits application to amend export license, extending expiration date to 850301
WIDMAN, J C KMS Fusion, Inc (Subs of KMS Industries, Inc) RSO-232-JCN 83/02/02 Assistant Director for Export/Import & International Safeguards 1p 17288 269
- 8302240224 License for Transnuclear, Inc to export 269.34 kg U-235 & 0 0335 kg U-235 sample, enriched to 3 33% U, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards RDU-428 83/02/09, 2pp 17288 199
- 8302240229 License for Exxon Nuclear Co, Inc to export 995 kg U-235, enriched to 3 4% U, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 2pp 17288 188
- 8302240343 Submits application to amend export license, increasing quantities to 623,939 073 kg U, containing 22,141 170 kg U-235
SHAW, A Edlow International Co 83/02/02 Assistant Director for Export/Import & International Safeguards 2pp 17290 136
- 8302240346 Application for license to export 30 kg U metal, contained in 5 985 kg U, to France
COURCIER, P Pechiney Ugine Kuhlmann Development, Inc PHC/LAC-1038 83/02/03 3pp 17290 005
- 8302240348 License for Transnuclear, Inc to export 24 kg U-235, contained in 600 kg U, to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TNP-429, 83/02/07 2pp 17289 361
- 8302240373 Forwards application for license to export 1.1 Ci Cf-252, contained in sealed neutron radiation source, to Japan
YAMANA, K Nissso-Iwai American Corp MPD-0298 83/02/01 HENBY, E Assistant Director for Export/Import & International Safeguards 1p 17289 304
- 8302240375 Application for license to export 1.1 Ci Cf-252, contained in sealed neutron radiation source, to Japan
YAMANA, K Nissso-Iwai American Corp GBM-1466 83/02/01 1p 17289 307
- 8302240376 License for OE to export four Zircaloy heater fuel rods & one annulus test section & fittings to Taiwan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-111-B2 83/02/07 1p 17289 305

NONDOCKETED ITEMS

8302240377 Informs that License XSNM-1996 may be issued No matl changed circumstances since issuance of License XSNM-1995
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/02/07 Assistant Director for Export/Import & International Safeguards 1p 17289 304

8302240378 License for Transnuclear, Inc to export 4 582 kg U-235, contained in 4 911 kg U, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82-069/01 83/02/09 2pp 17289 302

8302240387 License for Transnuclear, Inc to export 2,647 kg U-235, contained in 79,000 kg U & 0 17 kg U-235, contained in 5 kg U, to The Netherlands
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 2pp 17289 291

--8302240390 Informs that License XSNM-1998 may be issued No matl changed circumstances since issuance of License XSNM-1893
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/18 Assistant Director for Export/Import & International Safeguards 1p 17289 293

8302240393 License for Westinghouse to export three proportional counters, Model WL-23744, to Switzerland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/11 1p 17288 360

8302240396 License for C Itah & Co (America), Inc to export 16 pieces Zircaloy tubing to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards WE-18(04-2) 83/02/10 1p 17288 361

8302240398 Amend 1 to KMS Fusion, Inc export license, extending expiration date to 850301
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards KMSF-0480-AL 83/02/09 1p 17288 359

8302240403 Executive Branch position re OE application to export Zircaloy rods to be used as fuel cladding matl for lab research & fuel performance testing, to Taiwan License should be granted End use statement encl
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 83/02/02 SHEA, J R Office of International Programs, Director 3pp 17288 347

8302250152 License for Mitsui & Co (USA), Inc to export 3,215 kg U-235, contained in 147,900 kg U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MBK-K1 83/02/09 2pp 17298 351

8302250157 Forwards application for license to export 1,000 kg natural thorium to Canada
ZIELINSKI, A M General Electric Co 83/02/03 HEMBY, E Assistant Director for Export/Import & International Safeguards 1p 17298 343

--8302250160 Application for license to export 1,000 kg natural thorium to Canada
ZIELINSKI, A M General Electric Co SMD-191 83/02/02 1p 17298 344

8302250492 Application for license to export two compensated ionization chambers, Model 8074, to Japan End use statement encl
POCHAL, W F Westinghouse Electric Corp ZE 60261 83/02/01 9pp 17303 156

8302250495 Amend 1 to Reuter-Stokes, Inc export license, increasing quantity of in-core neutron detectors for flux mapping from 20 to 60
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards W-8824, 83/02/10 1p 17303 145

8302250504 Executive Branch position re Mitsui & Co application to export 3,215 kg U-235, contained in 147,900 kg U, to Japan License should be granted
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ Scientific Affairs 83/02/03 SHEA, J R Office of International Programs, Director 2pp 17303 101

8302280001 Ltr of assurance re Transnuclear, Inc 830118 application export highly enriched U to France
MARCHEL, J European Communities, Commission of 83/02/03 GRIFFIN, J A Energy, Dept of 1p 17314 308

8302280002 Forwards application for license to export specifically designed components for nuclear fuel assemblies to Spain
HERSCH, M M Westinghouse Electric Corp MMH-330 83/01/31 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 17314 306

--8302280003 Application for license to export specifically designed components for nuclear fuel assemblies to Spain
HERSCH, M M Westinghouse Electric Corp MMH-330 83/01/29 17314 307

8302280030 Forwards application for license to export 682 kg U-235, contained in 19,754 kg U, to Japan
SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-08 83/01/26 Assistant Director for Export/Import International Safeguards 3pp 17314 297

--8302280032 Application for license to export 682 kg U-235, contained in 19,754 kg U, to Japan
Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-08 83/01/26 2pp 17314 302

8302280053 Requests extension of approval of route from Portland, OR ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 21948 83/01/18 HILLMAN, C Division of Safeguards 2pp 17314 293

8302280099 Requests extension of approval of route from Norfolk, VA Aiken, SC through 831231
HANNETT, B A Transnuclear, Inc 21949 83/01/18 HILLMAN, C Office of Nuclear Material Safety & Safeguards, Director 2pp 17314 304

8302280108 Requests extension of approval of route from Oakland, CA ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 21951 83/01/18 HILLMAN, C Division of Safeguards 2pp 17314 272

8302280116 Requests extension of approval of route from Newport News, VA to Aiken, SC through 831231
HANNETT, B A Transnuclear, Inc 21950 83/01/18 HILLMAN, C Division of Safeguards 2pp 17314 269

8302280548 Requests extension of approval of route from Portland, OR ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 21944 83/01/18 HILLMAN, C Division of Safeguards 2pp 17322 215

8302250498 Submits application to amend export license to include 40 addl in-core neutron detectors for flux mapping
SKARUPA, J D Reuter-Stokes, Inc A-9512 83/02/09 WRIGHT, D - No Detailed Affiliation Given 1p 17303 137

8302250500 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/10 GRIFFIN, J A Energy, Dept of 1p 17303 104

8302250502 Requests Executive Branch position re Westinghouse application for license to export components for nuclear fuel fabrication to Spain
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/10 STODER, C R State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 1p 17303 103

NONDOCKETED ITEMS

- 8302090235 License for Liquid Carbonic Corp to export 10,000 liters (1,656 kg) deuterium to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards G O 7046 83/02/01 1p 17119 181
- 8302090267 Executive Branch position re Edlow Intl Co application to export 961,632 kg natural U in form of U ore concentrate or U hexafluoride to EURATOM member states License should be granted
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 00410 83/01/27 SHEA, J R Office of International Programs, Director 3pp 17117 339
- 8302090273 Ltr of assurance re export of 1,202 kg U-235, contained in 40,920 kg U to Japan
SHIRAKAWA, T Japan, Govt of, 83/01/21 GRIFFIN, J A Energy, Dept of 1p 17117 338
- 8302090277 Questions whether Indonesia radioisotope plant could be designed to use low enriched U instead of highly enriched U
DARIDIS, J G State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 83/01/27 KERNY, W R QA Technologies, Inc /General Atomic Co 3pp 17121 350
- 8302090470 Informs that License XSNM-1974 may be issued No matl changed circumstances since issuance of License XSNM-1987
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/02/03 Assistant Director for Export/Import & International Safeguards 1p 17121 274
- 8302090526 Application for amend to application for license to export Pu & U to Switzerland DOE/Switzerland carbide fuel development agreement encl
CEJA, S N Energy, Dept of 83/01/24 MOORE, N Office of International Programs, Director 1pp 17108 316
- 8302160129 Application for license to export 97,050 lb Zircaloy tres to West Germany
ACERNI, B L Teledyne Wah Chang Albany 2625 (JFM) 83/01/28 1p 17160 249
- 8302160141 Application to amend export license, increasing quantity of U-235 from 471 25 kg U-235, contained in 14,500 kg U to 928 25 kg U-235, contained in 28,600 kg U & from 0 033 kg, contained in 1 kg U to 0 065 kg, contained in 2 0 kg U
HANNETT, B A Transnuclear, Inc RBU 39A 83/01/26 MOORE, N Office of International Programs, Director 2pp 17160, 247
- 8302200508 Requests Executive Branch position re Pechiney Ughine Kuhlmann Development, Inc application for license to export 30 kg U, enriched to 19 75% U-235, to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 STOBER, C R State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 1p 17234 347
- 8302200515 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 GRIFFIN, J A Energy, Dept of 1p 17234 346
- 8302200523 Clarifies 82110 application to amend export license, increasing quantities of U-235, U-233, Th-232 & Pu-239
MORRY, W R QA Technologies, Inc /General Atomic Co IEL-4041 83/02/07 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 2pp 17235 357
- 8302200528 Amends 810904 ltr of assurance re export of low enriched U to Indonesia, increasing quantity to 12 956 kg U-235, contained in 64 742 kg U
MARCHAL, J European Communities, Commission of 83/02/03 GRIFFIN, J A Energy, Dept of 1p 17234 357
- 8302200533 Amends 820211 ltr of assurance, increasing quantity to 928 25 kg U-235, contained in 28,600 kg U & 1 kg U as sample
MARCHAL, J European Communities, Commission of 83/01/31 GRIFFIN, J A Energy, Dept of 1p 17234 352
- 8302200540 Informs that approx 1,300,000 lb U-308 shipped to United Kingdom for conversion & subsequent return to USA for enrichment, will be enriched within European Community for use in West Germany
MARCHAL, J European Communities, Commission of AGN/464 83/02/03 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 17234 356
- 8302200545 Advises of issuance of Amend 1 to Reuter-Stokes export license w/o customary 15-day waiting period, due to urgency of export
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/10 Assistant Director for Export/Import & International Safeguards 1p 17234 350
- 8302240001 Forwards application for blanket license to import 5 million kg U, containing 250,000 kg U-235, from various countries
EINBUND, D R New York Nuclear Corp 83/02/04 MOORE, R N Assistant Director for Export/Import & International Safeguards 1p 17287 337
- 8302240002 Application for license to import 5 million kg U, containing 250,000 kg U-235, from various countries
EINBUND, D R New York Nuclear Corp 83/02/04 1p 17287 338
- 8302240140 Ltr of assurance re OE 830106 application for license to export low enriched U & Pu to Denmark
MARCHAL, J European Communities, Commission of 83/02/07 GRIFFIN, J A Energy, Dept of 1p 17268 254
- 8302240147 Informs that License XSNM-2002 may be issued No matl changed circumstances since issuance of License XSNM-1982
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/20 Assistant Director for Export/Import & International Safeguards 1p 17288 276
- 8302240152 Informs that License XSNM-2001 may be issued No matl changed circumstances since issuance of License XSNM-1982
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/20 Assistant Director for Export/Import & International Safeguards 1p 17288 275
- 8302240158 Informs that License XSNM-1995 may be issued No matl changed circumstances since issuance of License XSNM-1994
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/02/07 Assistant Director for Export/Import & International Safeguards 1p 17288 274
- 8302240161 Ltr of assurance re export of 1,016 kg U-235, contained in 33,079 kg U to Japan
SHIRAKAWA, T Japan, Govt of, 83/02/01 GRIFFIN, J A Energy, Dept of 1p 17288 273
- 8302240165 Submits application to amend export license, extending expiration date to 850301
WIDMAN, J C KMS Fusion, Inc (Subs of KMS Industries, Inc) RSD-232-JCW 83/02/02 Assistant Director for Export/Import & International Safeguards 1p 17288 269
- 8302240224 License for Transnuclear, Inc to export 269 34 kg U-235 & 0 0335 kg U-235 sample, enriched to 3 35% U to West Germany.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards RBU-428 83/02/09 2pp 17288 199
- 8302240229 License for Exxon Nuclear Co, Inc to export 995 kg U-235, enriched to 3.4% U to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 2pp 17288 188
- 8302240313 Submits application to amend export license, increasing quantities to 623,939 073 kg U, containing 22,141 170 kg U-235.
BHAN, A Edlow International Co 83/02/02 Assistant Director for Export/Import & International Safeguards 2pp 17290 136
- 8302240346 Application for license to export 30 kg U metal, contained in 5 985 kg U to France
COURCIER, P Pechiney Ughine Kuhlmann Development, Inc PHC/LAC-1338 83/02/03 3pp 17290 005
- 8302240348 License for Transnuclear, Inc to export 24 kg U-235, contained in 600 kg U to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TNP-429 83/02/07 2pp 17289 361
- 8302240373 Forwards application for license to export 1 1 Ci Cf-252, contained in sealed neutron radiation source, to Japan.
YAMANA, K Nissho-Iwai American Corp MPD-0298 83/02/01 JEM/J, S Assistant Director for Export/Import & International Safeguards 1p 17289 306
- 8302240375 Application for license to export 1 1 Ci Cf-252, contained in sealed neutron radiation source, to Japan
YAMANA, K Nissho-Iwai American Corp QBM-1466 83/02/01 1p 17289 307
- 8302240376 License for OE to export four Zircaloy heater fuel rods & one annulus test section & fittings to Taiwan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-111-82 83/02/07 1p 17289 305

8302240377 Informs that License XSNM-1996 may be issued No matl changed circumstances since issuance of License XSNM-1995
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/02/07 Assistant Director for Export/Import & International Safeguards 1p 17289 304

8302240378 License for Transnuclear, Inc to export 4 582 kg U-235, contained in 4 911 kg U, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82-069/01 83/02/09 2pp 17289 302

8302240387 License for Transnuclear, Inc to export 2,647 kg U-235, contained in 79,000 kg U & 0 17 kg U-235, contained in 9 kg U, to The Netherlands
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/09 2pp 17289 291

--8302240390 Informs that License XSNM-1998 may be issued No matl changed circumstances since issuance of License XSNM-1893
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/01/18 Assistant Director for Export/Import & International Safeguards 1p 17289 293

8302240393 License for Westinghouse to export three proportional counters, Model HL-23744, to Switzerland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/11 1p 17288 340

8302240396 License for C Itoh & Co (America), Inc to export 16 pieces Zircaloy tubing to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards WE-15(04-2) 83/02/10 1p 17288 361

8302240398 Amend 1 to KMS Fusion, Inc export license, extending expiration date to 850301
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards KMSF-0480-AL 83/02/09 1p 17288 359

8302240403 Executive Branch position re OE application to export Zircaloy rods to be used as fuel cladding matl for lab research & fuel performance testing, to Taiwan License should be granted End use statement encl
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 83/02/02 SHEA, J R Office of International Programs, Director 3pp 17288 347

8302250152 License for Mitsui & Co (USA), Inc to export 3,215 kg U-235, contained in 147,900 kg U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MBK-K1 83/02/09 2pp 17298 351

8302250157 Forwards application for license to export 1,000 kg natural thorium to Canada
ZIELINSKI, A M General Electric Co 83/02/03 HEMBY, E Assistant Director for Export/Import & International Safeguards 1p 17298 343

--8302250160 Application for license to export 1,000 kg natural thorium to Canada
ZIELINSKI, A M General Electric Co BMB-191 83/02/02 1p 17298 344

8302250492 Application for license to export two compensated ionization chambers, Model 8074, to Japan End use statement encl
POCHAL, W F Westinghouse Electric Corp ZE 60261. 83/02/01 9pp 17303 156

8302250495 Amend 1 to Reuter-Stokes, Inc export license, increasing quantity of in-core neutron detectors for flux mapping from 20 to 60
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards W-8824 83/02/10 1p 17303 145

8302250504 Executive Branch position re Mitsui & Co application to export 3,215 kg U-235, contained in 147,990 kg U, to Japan
License should be granted
DEVINE, J B State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 83/02/03 SHEA, J R Office of International Programs, Director 2pp 17303 101

8302280001 Ltr of assurance re Transnuclear, Inc 830118 application to export highly enriched U, to France
MARCHAL, J European Communities, Commission of 83/02/03 GRIFFIN, J A Energy, Dept of 1p 17314 308

8302280002 Forwards application for license to export specifically designed components for nuclear fuel assemblies to Spain
HERSCH, M M Westinghouse Electric Corp MMH-330 83/01/31 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 17314 306

--8302280003 Application for license to export specifically designed components for nuclear fuel assemblies to Spain
HERSCH, M M Westinghouse Electric Corp MMH-330 83/01/29 1p 17314 307

8302280030 Forwards application for license to export 682 kg U-235, contained in 19,734 kg U, to Japan
SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-09 83/01/26 Assistant Director for Export/Import & International Safeguards 3pp 17314 299

--8302280032 Application for license to export 682 kg U-235, contained in 19,734 kg U, to Japan
* Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-08 83/01/26 2pp 17314 302

8302280053 Requests extension of approval of route from Portland, OR to ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 21948 83/01/18 HILLMAN, C Division of Safeguards 2pp 17314 293

8302280099 Requests extension of approval of route from Norfolk, VA to Aiken, SC through 831231
HANNETT, B A Transnuclear, Inc 21947 83/01/18 HILLMAN, C Office of Nuclear Material Safety & Safeguards, Director 2pp 17314 304

8302280108 Requests extension of approval of route from Oakland, CA to ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 21951 83/01/18 HILLMAN, C Division of Safeguards 2pp 17314 272

8302280116 Requests extension of approval of route from Newport News, VA to Aiken, SC through 831231
HANNETT, B A Transnuclear, Inc 21950 83/01/18 HILLMAN, C Division of Safeguards 2pp 17314 269

8302280548 Requests extension of approval of route from Portland, OR to ID Falls, ID through 831231
HANNETT, B A Transnuclear, Inc 21944 83/01/18 HILLMAN, C Division of Safeguards 2pp 17322 215

8302250498 Submits application to amend export license to include 40 addl in-core neutron detectors for flux mapping
SKARUPA, J D Reuter-Stokes, Inc A-9512 83/02/09 WRIGHT, D NRC - No Detailed Affiliation Given 1p 17303 137

8302250500 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/10 GRIFFIN, J A Energy, Dept of 1p 17303 104

8302250502 Requests Executive Branch position re Westinghouse application for license to export components for nuclear fuel fabrication to Spain
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/02/10 STODER, C R State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 1p 17303 103

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|----------------|------------------|------------------|----------------|------------------|------------------|
| ABBOTT, E | 8302010082* | FOIA | ANDERSON, R | 8302010377* | 50-373 Q | AXELSON, H L | 8302250364* | 50-10 |
| ABDEL-KHALIK, S | 8302160110* | 50-837 A | ANDERSON, R L | 8209240433* | 50-269 P | BABCOCK, C. | 8302040468 | NUREQ |
| ABEL, S L | 8302280385* | 50-285 S | ANDERSON, R T | 8302170435* | NUREQ | BACHMANN, R G | 8302080201 | 50-155 |
| ABELSON, H | 8302180015 | 50-461 E | ANDERSON, R T | 8302170438* | NUREQ | BACHMANN, R G | 8302280279 | 50-170 |
| ABELSON, H | 8302180366* | 50-461 Q | ANDERSON, S W | 8302250396* | 50-247 Q | BACHMANN, R G | 8302280282* | 50-170 |
| ACKERMAN, H C | 8302010069 | 40-8743 | ANDERSON, S W | 8302250396* | 50-247 Q | BACI, P E | 8302180083* | 50-358 |
| ACKERMAN, U C | 8302010077 | 40-299 | ANDERSON, S W | 8302250396* | 50-247 Q | BACKUS, R A | 8302080185 | 50-443 |
| ACKERMAN, U C | 8302070554 | 40-8584 | ANDOGNINI, O C | 8302040554 | 70-2949 | BACKUS, R A | 8302080185 | 50-443 |
| ADAMS, J E | 8302040443* | PROJ | ANDOGNINI, O C | 8302250299 | 50-828 V | BACKUS, R A | 8302080238 | 50-443 |
| ADAMS, J W | 8302250049 | 50-320 P | ANDREWS, D L | 8302150721* | 50-321 Q | BACKUS, R A | 8302080238 | 50-443 |
| ADENSAH, E O | 8302030053 | 50-327 P | APICELLA, F | 8302170910 | 50-331 P | BACKUS, R A | 8302170201 | 50-443 |
| ADENSAH, E O | 8302160034 | 50-395 P | APICELLA, F L | 8302040442 | 50-331 F | BACKUS, R A | 8302170201 | 50-443 |
| ADENSAH, E O | 8302160041* | 50-395 P | APICELLA, F L | 8302100137 | 50-331 F | BACKUS, R A | 8302170284 | 50-443 |
| ADENSAH, E O | 8302160051* | 50-395 P | APPEL, R R | 8302020386 | 40-8728 | BACKUS, R A | 8302170284 | 50-443 |
| ADENSAH, E O | 8302170044 | 50-424 A | APPEL, R R | 8302020389* | 40-8728 | BADALAMANTE, R | 8210130458* | FOIA |
| ADENSAH, E O | 8302170398 | 50-395 P | ARCHITZEL, R | 8302100289 | 50-318 S | BADIALI, J. | 8302040501 | 71-6717 |
| ADENSAH, E O | 8302170397* | 50-395 P | ARCHITZEL, R E | 8302150373* | 50-317 Q | BABBY, L A | 8302040450 | 71-9167 |
| ADENSAH, E O | 8302240136 | 50-328 P | ARNAHAN, C L | 8302250122 | NUREQ | BACCHI, G | 8302170011 | 50-322 |
| ADENSAH, E O | 8302240153* | 50-328 P | ARNOLD, R C | 8302010376 | 50-320 P | BACCHI, G | 8302170218* | 50-322 |
| ADRAGNA, J M | 8302020247 | PROJ | ARNOLD, R C | 8302010399* | 50-320 P | BAGGART, M | 8302150621 | 50-219 |
| AGNI, B L | 8302160129 | XPORTLIC | ARNOLD, R C | 8302040416 | 50-320 P | BAILEY, J P | 8302030106* | 50-416 |
| AGARWAL, R | 8209080533* | 50-206 P | ARNOLD, R C | 8302080300 | 50-289 P | BAILEY, J P | 8302030569* | 50-416 |
| AGEC, J R | 8302030504 | 0A999 | ARNOLD, R C | 8302240039 | 50-289 P | BAILEY, J P | 8302140064* | 50-416 |
| AGNIHOTRI, N K | 8302070001 | FOIA | ARRINGTON, T T | 8302230536 | 50-322 T | BAILEY, J P | 8302150094* | 50-416 |
| AGNIHOTRI, N K | 8302070002 | FOIA | ARRINGTON, T T | 8302230536 | 50-322 T | BAILEY, J P | 8302150641* | 50-416 |
| AGUILENA, H F | 8302080433* | CONTRACT | ASH, R F | 8302070473 | 50-317 P | BAILEY, R J | 8302230549* | 50-286 |
| AHEARNE, J | 8302090118* | 50-358 Q | ASHBURN, D J | 8302080146 | TOPREP | BAIR, O O | 8302010569* | 50-344 |
| AHEARNE, J | 8302140174* | 50-249 P | ASHBURN, D J | 8302100218 | 50-397 J | BATSDEN, L | 8302020018 | CONTRACT |
| AHEARNE, J | 8302220149* | 10CFR | ASTON, W B | 8210130458* | FOIA | BAKER, C E | 8302020381 | 40-8675 |
| AHEARNE, J F | 8302090261* | 50-313 P | ATEFI, B | 8302020136* | 50-29 P | BAKER, C E | 8302090607 | 40-8681 |
| AHEARNE, J F | 8302240057 | COMMISSION | ATEFI, B | 8302070269* | 50-213 P | BAKER, H H | 8302030086* | 50-537 |
| AHMAD, A | 8302170198 | NUREQ | AULUCK, R | 8302100137 | 50-397 A | BAKER, W | 8302040468 | NUREQ |
| AHRENS, P F | 8302250257* | 50-309 Q | AULUCK, R | 8302140189 | 50-397 A | DALL, T W | 8302010439* | 50-537 |
| ALINGER, K A | 8302160227* | 50-454 Q | AULUCK, R | 8302250020 | 50-397 F | DALLENTINE, J | 8302030289 | 50-293 |
| ALBERT, W O | 8302230257* | 50-508 Q | AULUCK, R | 8302250091 | 50-397 A | DALLWEG, T | 8302040329 | 50-329 |
| ALBRIGHT, R H | 8302150694* | 50-324 Q | AULUCK, R | 8302250062 | 50-397 A | DARBER, O | 8302040358 | 50-364 |
| ALDEN, W H | 8302180336* | 50-277 R | AUSTIN, O | 8302170163* | 50-295 R | DARBER, O | 8302150587 | 50-237 |
| ALEXICH, M P | 8302010663 | 50-315 F | AUSTIN, M A | 8302070031 | 70-135 | DARBER, O | 8302170080 | 50-219 |
| ALEXICH, M P | 8302040256 | 50-315 J | AUTIO, H A | 8302230124 | 50-29 S | DARBER, O | 8302230249 | 50-324 |
| ALEXICH, M P | 8302080278 | 50-315 F | AHALT, C | 8302250399* | 50-247 Q | DARLETTA, R E | 8302240359 | 27-47 |
| ALEXICH, M P | 8302100313 | 50-315 P | AHALT, C | 8302250399* | 50-247 Q | DARNES, I | 8302010527* | 0A999 |
| ALGER, D M | 8302230401 | 50-186 R | AXELRAD, J | 8302040320 | 50-456 Q | DARNES, I | 8302030507* | 0A999 |
| ALLENDER, O W | 8302020100* | CONTRACT | AXELRAD, J | 8302040358 | 50-364 Q | DARNES, I | 8302070265* | 0A999 |
| ALMEYER, F M | 8302080121* | FOIA | AXELRAD, J | 8302150587 | 50-237 Q | DARNES, I | 8302070266* | 0A999 |
| ALTERMAN, I | 8302160182* | 50-454 T | AXELRAD, J | 8302170080 | 50-219 Q | DARNES, I | 8302070307* | 0A999 |
| AMBASH, J H | 8302040114 | FOIA | AXELRAD, J | 8302230211 | 40-8698 | DARNES, I | 8302070327* | 0A999 |
| AMICO, P | 8302020136* | 50-29 P | AXELRAD, J | 8302230215 | 40-8681 | DARNES, I | 8302090353* | 0A999 |
| AMICO, P | 8302070269* | 50-213 P | AXELRAD, J | 8302230249 | 50-324 Q | DARNES, I | 8302090369* | 0A999 |
| ANANDAPPA, A | 8302160159* | 50-227 S | AXELRAD, J | 8302230376 | 50-298 Q | DARNES, I | 8302090377* | 0A999 |
| ANDERSON, C | 8302180225* | 50-387 Q | AXELRAD, J A | 8302190680 | 50-302 Q | DARNES, I | 8302160298* | 0A999 |
| ANDERSON, C J | 8302030511* | 50-324 Q | AXELRAD, J A | 8302170407 | 50-302 Q | DARNES, I | 8302160315* | 0A999 |
| ANDERSON, J | 8302100374 | 50-155 H | AXELRAD, J A | 8302220007 | 50-247 Q | DARNES, R H | 8302040398* | 50-289 |
| ANDERSON, P | 8302180427 | 50-266 Q | AXELSON, H L | 8302040212* | 50-263 Q | DARNETT, J E | 8302020005 | 70-1621 |
| ANDERSON, P L | 8302160216* | 50-443 Q | AXELSON, H L | 8302040303* | 50-305 Q | DARNETT, J E | 8302020046 | 70-1621 |
| ANDERSON, P L | 8302160369* | 50-443 Q | AXELSON, H L | 8302250283* | 50-255 Q | DARON, B | 8302040521 | NUREQ |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|-----------------|------------------|------------------|
| BARR, K | 8302030428* | 50-277 Q | BAKTER, T A | 8302250310 | 50-289 Q | BERNREUTER, D L | 8302170469 | NUREQ |
| BARR, K | 8302030502* | 50-320 Q | DAY, J H | 8302230523 | 50-142 Q | BERNREUTER, D L | 8302170213 | NUREQ |
| BARR, K | 8302150039 | 50-160 S | DAYNARD, P Y | 8302010220 | 50-302 S | BERRY, Z E | 8302010130* | 50-250 S |
| BARR, K | 8302230128* | 50-320 Q | DAYNARD, P Y | 8302150067* | 50-302 Q | BERRY, Z E | 8302150070* | 50-250 S |
| BARR, K | 8302250355* | 50-320 Q | DAYNARD, P Y | 8302170166 | 50-302 F | BERRY, Z E | 8302280351* | 50-250 S |
| BARR, K P | 8302150356* | 70-143 | DAYNARD, P Y | 8302180327 | 50-302 R | BERZCO, K | 8302070157* | FOIA |
| BARR, K P | 8302150429* | 70-1113 | DAYNARD, P Y | 8302220215 | 50-302 P | BESS, J | 8302070486* | 50-382 Q |
| BARR, K P | 8302150458* | 50-250 Q | DAYNARD, P Y | 8302220360 | 50-302 P | BETTENHAUSEN, L | 8302150130* | 50-289 Q |
| BARR, K P | 8302150837* | 50-324 Q | DAYNARD, P Y | 8302230208 | 50-302 P | DEVAN, R | 8302100088 | 50-254 Q |
| BARR, K P | 8302150999* | 50-280 Q | DAYNE, J P | 8302010332 | 50-333 P | DEVAN, R B | 8302170262* | 50-159 P |
| BARR, K P | 8302150674* | 50-324 Q | DAYNE, J P | 8302010443 | 50-333 Q | DEVERLY, K | 8302080359* | 50-249 S |
| BARR, K P | 8302150710* | 50-259 Q | DAYNE, J P | 8302030323 | 50-286 P | DEZLER, P | 8302220431 | NUREQ |
| BARRETT, D J | 8208170201* | 50-409 P | DAYNE, J P | 8302030424 | 50-286 F | DIBB, H E | 8302150428* | 50-335 Q |
| BARRETT, L H | 8302080107 | 50-320 R | DAYNE, J P | 8302030441 | 50-333 P | DIDA, G | 8302250112* | NUREQ |
| BARRETT, L H | 8302170100 | 50-320 R | DAYNE, J P | 8302080159 | 50-333 P | DIDINGER, O H | 8302080477* | 70-1113 |
| BARRETT, L H | 8302220012 | 50-320 R | DAYNE, J P | 8302080218 | 50-286 P | DIDINGER, O H | 8302220079* | 70-1113 |
| BARRETT, L H | 8302220030 | 50-320 F | DAYNE, J P | 8302140105 | PR | DIDINGER, O H | 8302220484* | 70-371 |
| BARRETT, M | 8302170378 | 50-341 H | DAYNE, J P | 8302150159 | 50-333 P | IDLE, D | 8302180044* | FOIA |
| BARRY, L W | 8302180141* | FOIA | DAYNE, J P | 8302150163* | 50-333 P | IELAWSKI, A P | 8302070542 | 50-599 Q |
| BARRY, L W | 8302180368* | FOIA | DAYNE, J P | 8302150349 | 50-247 P | IELAWSKI, A P | 8302070542 | 50-599 Q |
| BARTH, C A | 8302010063 | 50-400 Q | DAYNE, J P | 8302150421 | 50-286 P | IELAWSKI, A P | 8302220291 | 50-454 T |
| BARTH, C A | 8302010572 | 50-400 Q | DAYNE, J P | 8302180108 | 50-286 P | IELAWSKI, A P | 8302220291 | 50-454 T |
| BARTH, C A | 8302080008 | 50-400 Q | DAYNE, J P | 8302230282 | 50-286 P | INZ, R D | 8302230221* | 50-219 S |
| BARTH, C A | 8302080011* | 50-400 Q | DAYNE, J P | 8302230445 | 50-286 F | ISCHOFF, C A | 8302180394 | 50-928 Q |
| BARTOLOZZI, A R | 8302250210* | 40-86 | DAYNE, J P | 8302230482 | 50-286 P | ISCHOFF, C A | 8302180394 | 50-928 Q |
| BARTOLOZZI, A R | 8302250214* | 40-86 | DAYNE, J P | 8302240029 | 50-333 P | ISHOP, L | 8302080264 | 50-443 Q |
| BASKIN, K P | 8302010546 | 50-361 P | DAYNE, J P | 8302240032* | 50-333 P | ISHOP, L L | 8302080264 | 50-443 Q |
| BASKIN, K P | 8302020004 | 50-361 P | GAZIN, J P | 8302020097 | CONTRACT | ISHOP, L L | 8302220366 | 50-443 Q |
| BASKIN, K P | 8302070273 | 50-361 P | GAZZANO, C B | 8302100013* | CONTRACT | ISHOP, L L | 8302220366 | 50-443 Q |
| BASKIN, K P | 8302080164 | 50-361 P | KEALE, K E | 8302180099* | 50-395 F | ISHOP, L L | 8302220382* | 50-443 Q |
| BASKIN, K P | 8302090010 | 50-361 P | BEAUMONT, N | 8302150480* | QA999 | ISHOP, L L | 8302220382* | 50-443 Q |
| BASKIN, K P | 8302100480 | 50-361 P | BECKHAM, J T | 8302010538* | 50-321 Q | ISHOP, L L | 8302220392* | 50-443 Q |
| BASKIN, K P | 8302140079 | 50-361 P | BECKHAM, J T | 8302040250 | 50-321 P | ISHOP, L L | 8302220392* | 50-443 Q |
| BASKIN, K P | 8302150053 | 50-361 P | BECKHAM, J T | 8302150042 | 50-321 Q | ISHOP, L L | 8302220397* | 50-443 Q |
| BASKIN, K P | 8302150227 | 50-206 P | BEGLEY, J A | 8302280404* | 50-295 P | ISHOP, L L | 8302220397* | 50-443 Q |
| BASKIN, K P | 8302150332 | 50-206 P | DEGOR, R | 8302250082* | 50-315 F | ISHOP, T E | 8302160502* | CONTRACT |
| BASKIN, K P | 8302160249 | 50-361 P | DEHLING, S R | 8302150739 | RES | ISHOP, T W | 8302070337 | 50-275 Q |
| BASKIN, K P | 8302160371 | 50-206 F | DEHLING, S R | 8302150758 | RES | ISHOP, T W | 8302150366 | 50-206 Q |
| BASKIN, K P | 8302180291 | 50-361 P | BEHRENS, P | 8302040397* | 50-245 S | ISHOP, T W | 8302230255 | 50-361 Q |
| BASKIN, K P | 8302180418 | 50-206 P | BEILMAN, T P | 8302150439* | 50-316 S | ISHOP, T W | 8302230379 | 50-275 Q |
| BASKIN, K P | 8302180454 | 50-361 F | DELANGER, J L | 8302150557* | 50-454 Q | ISHOP, T W | 8302230395 | 50-361 Q |
| BASKIN, K P | 8302280280 | 50-361 P | DELANGER, J L | 8302180457* | 50-373 Q | ISHOP, T W | 8302230396 | 50-361 Q |
| BASS, B R | 8302040502 | NUREQ | DELLIS, O A | 8302150416* | 50-241 Q | ISHOP, T W | 8302230657 | 50-275 Q |
| BASS, E | 8302080028 | FOIA | DELL, M J | 8302240388 | WASTE HOT | BLACK, H | 8302070036* | 50-206 F |
| BASS, O | 8302170348* | 50-239 S | DELL, M J | 8302240394 | WASTE HOT | BLACKLEY, S K | 8302230480 | REVIEW ORF |
| BASSETT, H S | 8112170273* | FOIA | DELL, M J | 8302280190 | WASTE HOT | BLACKLEY, S K | 8302230632 | REVIEW ORF |
| BASSO, L F | 8302010205* | 50-317 S | DELL, N | 8302160302 | 50-522 Q | BLAHA, J L | 8302180323* | FOIA |
| BASSO, L F | 8302010354* | 50-317 S | DELL, N | 8302160334 | 50-440 Q | BLAKE, J J | 8302150024* | 50-259 Q |
| BASSO, L F | 8302070415* | 50-317 S | DELL, N | 8302160336 | 50-440 Q | BLAKE, J J | 8302150072* | 50-324 Q |
| BASSO, L F | 8302070418* | 50-317 S | DELL, N | 8302160362 | 50-440 Q | BLAKE, J J | 8302150171* | 50-269 Q |
| BASSO, L F | 8302070427* | 50-318 S | BELLIS, R | 8302180070* | 50-358 A | BLAKE, J J | 8302150342* | 50-259 Q |
| BASSO, L F | 8302230722* | 50-318 S | DEMIS, P | 8302150022* | 50-261 Q | BLAKE, J J | 8302150388* | 50-389 Q |
| BASSO, L F | 8302250199* | 50-317 S | DEMIS, P | 8302150128* | 50-261 Q | BLAND, T J | 8302220344 | 50-454 Q |
| BATEMAN, W | 8302030177* | 50-322 Q | DEMIS, P | 8302150445* | 50-324 Q | BLOCH, P B | 8302010472 | 50-440 Q |
| BATEMAN, W H | 8302230608* | 50-354 Q | DEMIS, P R | 8302150461* | 50-124 Q | BLOCH, P B | 8302070506 | 50-266 Q |
| DATES, J D | 8302090100* | 50-358 Q | DENARQYA, V | 8302090037 | 50-289 P | BLOND, R M | 8302160093* | FOIA |
| BATTAGLIA, F | 8302230436 | 50-440 Q | DENKOWITZ, C | 8302220426 | NUREQ | BLOUGH, A R | 8302100298* | 50-277 Q |
| BAUER, T L | 8302070256 | 50-192 P | DENNETT, J | 8302040468 | NUREQ | BLOUGH, A R | 8302100414* | 50-277 Q |
| BAUER, T L | 8302100367 | 50-192 P | DENNINGTON, G M | 8302040137 | 70-2932 | BLUM, J M | 8302240064 | 50-3 Q |
| BAUER, T L | 8302100417 | 50-192 P | DENSON, E | 8302020370 | XPORTRIC | BOARDMAN, J R | 8302230416* | 50-498 Q |
| BAUNACK, W | 8302030447 | 50-247 S | DENTEN, L | 8302100356 | PR | BODINE, J C | 8302180298* | 50-244 S |
| BAUNACK, W | 8302070291* | 50-333 Q | DENTEN, L | 8302100376* | PR | BODINE, J C | 8302180337* | 50-244 S |
| BAUNACK, W | 8302100436* | 50-333 Q | DERO, A E | 8302160009* | CONTRACT | BODINE, J C | 8302230370* | 50-244 S |
| BAUSER, M A | 8302100353 | PRM | DERODOLL, T E | 8302010133* | 50-537 A | BODINE, J C | 8302230586* | 50-244 S |
| BAKTER, T A | 8302010507 | 50-289 Q | DERGER, C L | 8302230515* | 50-346 S | BODINE, J C | 8302230674* | 50-244 S |
| BAKTER, T A | 8302010507 | 50-289 Q | BERGER, H | 8302080268 | 50-251 Q | BODINE, J C | 8302230723* | 50-244 S |
| BAKTER, T A | 8302030180 | 50-400 Q | BERGER, J D | 8302280094 | 40-86 | BODART, D | 8302180332* | 50-302 R |
| BAKTER, T A | 8302030180 | 50-400 Q | BERGERON, P A | 8302250167* | 50-271 P | BODOS, L A | 8302100401 | PRM |
| BAKTER, T A | 8302080178 | 50-289 Q | BERGHOFF, J C | 8302040005* | 40-2061 | BONH, M P | 8302170469 | NUREQ |
| BAKTER, T A | 8302080178 | 50-289 Q | BERGHOFF, J C | 8302040005* | 40-2061 | BOLLINGER, G A | 8302170251 | NUREQ |
| BAKTER, T A | 8302160317 | 50-289 Q | BERGMAN, K H | 8302100057* | CONTRACT | BONAN, B L | 8302160171* | 50-313 F |
| BAKTER, T A | 8302160317 | 50-289 Q | BERICK, D H | 8302100440 | PRM | BONINA, R A | 8302180328* | QA999 |
| BAKTER, T A | 8302170219 | 50-289 Q | BERKOW, H N | 8112040003* | FOIA | BONINA, R A | 8302150337* | QA999 |
| BAKTER, T A | 8302170219 | 50-289 Q | BERKOW, H N | 8211040375* | FOIA | BODK, H E | 8302010458 | 50-375 Q |
| BAKTER, T A | 8302220347 | 50-289 T | BERKOW, H N | 8302180326* | FOIA | BODK, H E | 8302010465* | 50-375 Q |
| BAKTER, T A | 8302220347 | 50-289 T | BERLIN, K | 8302070595 | 50-529 Q | BODK, H E | 8302010476* | 50-375 Q |
| BAKTER, T A | 8302220387* | 50-289 T | BERLIN, K | 8302230350 | 50-528 Q | BODK, H E | 8302040436 | 27-48 |
| BAKTER, T A | 8302220387* | 50-289 T | BERLIN, K | 8302230350 | 50-528 Q | BODK, H E | 8302040448* | 27-48 |
| BAKTER, T A | 8302230496 | 50-400 Q | BERNABEI, L | 8302070522 | 50-358 Q | BODK, H E | 8302070279 | 50-187 Q |
| BAKTER, T A | 8302230496 | 50-400 Q | BERNABEI, L | 8302070522 | 50-358 Q | BODK, H E | 8302150112 | 50-206 Q |
| BAKTER, T A | 8302230589 | 50-400 Q | BERNABEI, L | 8302170267 | 50-528 Q | BODK, H E | 8302180172* | 70-1257 |
| BAKTER, T A | 8302230589 | 50-400 Q | BERNABEI, L | 8302170267 | 50-528 Q | BODK, H E | 8302180209 | 50-113 Q |
| BAKTER, T A | 8302230589 | 50-400 Q | BERNABEI, L | 8302170294 | 50-358 Q | BODK, H E | 8302230144 | 50-326 Q |
| BAKTER, T A | 8302230589 | 50-400 Q | BERNABEI, L | 8302040347* | 50-305 S | BODK, H E | 8302230251 | 50-312 Q |
| BAKTER, T A | 8302230589 | 50-400 Q | BERNABEI, L | 8302150151* | 50-305 S | BODK, H E | 8302230256* | 50-312 Q |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|----------------|------------------|------------------|----------------|------------------|------------------|----------------|------------------|------------------|
| BOOK, H E | 8302230297 | 70-1257 | BOUCHON, M | 8302070499* | 50-29 P | BROWN, J F | 8302100098* | CONTRACT |
| BOOK, H E | 8302230323 | 50-344 Q | BOUGUARD, M | 8302030109* | 50-337 U | BROWN, J F | 8302100190* | 40-8102 |
| BOOK, H E | 8302230324* | 50-344 Q | BOUMAKER, N J | 8302100283 | PR | BROWN, J R | 8302240246* | 70-146 |
| BOOK, H E | 8302230365 | 50-206 Q | BOUMAN, F C | 8302190500* | 50-358 H | BROWN, R A | 8301250612 | 40-3149 |
| BOOK, H E | 8302230378* | 50-206 Q | BOWMAN, H E | 8302070606* | 50-318 S | BROWN, R S | 8302180039* | FOIA |
| BOOK, H E | 8302250315 | 70-734 | BOYD, D C | 8302010382* | 50-255 Q | BROWN, R S | 8302180075* | FOIA |
| BOOK, H E | 8302250317* | 70-734 | BOYD, D C | 8302190534* | 50-155 Q | BROWN, R S | 8302180086* | FOIA |
| BOOKER, J E | 8302010602 | 50-458 S | BOYD, R | 8302030502* | 50-320 Q | BROWN, R S | 8302180095* | FOIA |
| BOOKER, J E | 8302030377 | 50-458 S | BOYER, V S | 8302170330* | 50-277 P | BROWN, R S | 8302180131* | FOIA |
| BOOKER, J E | 8302030412 | 50-458 S | BRADBURY, R D | 8302100291 | PR | BROWN, R S | 8302180138* | FOIA |
| BOOKER, J E | 8302070424 | 50-458 S | BRADBURY, R D | 8302100373 | PRM | BROWN, R S | 8302180380* | FOIA |
| BOOKER, J E | 8302070433 | 50-458 S | BRADBURY, R S | 8302100428 | PRM | BROWNINO, R E | 8302250088 | 50-320 |
| BOOKER, J E | 8302160351 | 50-458 S | BRADLEY, E J | 8302180036 | 50-352 K | BROWNLEE, V L | 8302150101* | 50-302 |
| BOOKER, J E | 8302090400 | 50-458 S | BRADLEY, E J | 8302170329 | 50-277 P | BROWNLEE, V L | 8302150233* | 50-321 |
| BOOKER, J E | 8302100277 | PR | BRADLEY, J | 8302180403* | 50-329 T | BROWNLEE, V L | 8302150488* | 50-321 |
| BOOKER, J E | 8302100380 | PRM | BRADLEY, J | 8302180403* | 50-329 T | BROWNLEE, V L | 8302150659* | 50-321 |
| BOOKER, J E | 8302160237 | 50-458 S | BRAMMAVAR, S H | 7908220373* | FOIA | BRUCE, M B | 8302140122* | 50-244 |
| BOOKER, J E | 8302160251 | 50-458 S | BRAMMAVAR, S H | 7911210270* | FOIA | BRUNNER, E J | 8302180095* | 50-277 |
| BOOKER, J E | 8302220237 | 50-458 S | BRAMMAVAR, S H | 8010090441* | FOIA | RYAN, J C | 8302150645* | 50-413 |
| BOOKER, J E | 8302230181 | 50-458 S | BRAMMAVAR, S H | 8302240235* | FOIA | RYAN, J H | 8302040502 | NUREQ |
| BOOKER, J E | 8302230218 | 50-458 S | BRAMMAVAR, S H | 8302240250* | FOIA | BUCKLEY, B | 8302170405 | 50-275 |
| BOOKER, J E | 8302230317 | 50-458 Q | BRAMMAVAR, S H | 8302240255* | FOIA | BUCKLEY, B C | 8302230172* | 50-312 |
| BOOKER, J E | 8302230325 | 50-458 S | BRAMMAVAR, S H | 8302240277* | FOIA | BUD, W H | 8302150104* | PR |
| BORDENICK, B H | 8302070152 | 50-322 Q | BRAMMAVAR, S H | 8302240288* | FOIA | BUDNITZ, R J | 8302170310* | 50-247 |
| BORDENICK, B H | 8302160369 | 50-322 Q | BRAMMAVAR, S H | 8302240293* | FOIA | BUDNITZ, R J | 8302180319* | CONTRACT |
| BORDENICK, B H | 8302170097* | 50-322 Q | BRANARD, H F | 8302100029* | CONTRACT | BUFFER, J L | 8302280268* | 50-302 |
| BORDINE, T C | 8302010259 | 50-155 S | BRANAGAN, E F | 8302160203* | 50-454 T | BURCH, D | 8302230293* | 50-333 |
| BORDINE, T C | 8302010484 | 50-155 P | BRANAGAN, E F | 8302160212* | 50-454 T | BURDINE, J A | 8302100404 | PR |
| BORDINE, T C | 8302010636 | 50-155 P | BRANCH, H W | 8302040088* | 50-409 Q | BURDINE, J A | 8302100470* | PR |
| BORDINE, T C | 8302010654 | 50-155 P | BRANDENBURG, B | 8302010530 | 50-247 T | BURDINE, J F | 8302230666* | 50-275 |
| BORDINE, T C | 8302040078 | 50-155 P | BRANDENBURG, B | 8302020254 | 50-247 Q | BURGESS, F J | 8302160244* | 50-271 |
| BORDINE, T C | 8302040238 | 50-155 S | BRANDENBURG, B | 8302020345 | 50-247 Q | BURGESS, B L | 8302040330* | 50-329 |
| BORDINE, T C | 8302140003 | 50-155 F | BRANDENBURG, B | 8302030164 | 50-247 Q | BURGESS, B L | 8302250393* | 50-329 |
| BORDINE, T C | 8302230206 | 50-155 P | BRANDENBURG, B | 8302030175* | 50-247 Q | BURKHARDT, W | 8302090200* | 70-364 |
| BORDINO, T C | 8302010660 | 50-155 F | BRANDENBURG, B | 8302070559 | 50-247 Q | BURNETT, P T | 8302150370* | 50-338 |
| BORRELLA, H M | 8302030208 | NUREQ | BRANDENBURG, B | 8302070224 | 50-247 T | BURNETT, R F | 8302070027* | 50-206 |
| BORRELLA, H M | 8302100346* | PR | BRANDENBURG, B | 8302160271 | 50-247 Q | BURNETT, R F | 8302070108* | 50-206 |
| BORGAN, L E | 8302280006 | NUREQ | BRANDENBURG, B | 8302160278 | 50-247 Q | BURNETT, R F | 8302070128* | 50-206 |
| BORGAN, E A | 8302010223 | 50-358 S | BRANDENBURG, B | 8302160367 | 50-247 Q | BURNS, J B | 8302080180* | FOIA |
| BORGAN, E A | 8302010535 | 50-358 C | BRANDENBURG, B | 8302160372 | 50-247 Q | BURSTEIN, B | 8302010595 | 50-266 |
| BORGAN, E A | 8302010545 | 50-358 K | BRANDENBURG, B | 8302160384 | 50-247 Q | BURSTEIN, S | 8302010603 | 50-266 |
| BORGAN, E A | 8302010638 | 50-358 S | BRANDENBURG, B | 8302160399 | 50-247 Q | BURSTEIN, S | 8302030366 | 50-266 |
| BORGAN, E A | 8302040083 | 50-358 A | BRANDENBURG, B | 8302170260 | 50-247 T | BURWELL, B B | 8302250159 | 50-445 |
| BORGAN, E A | 8302040423 | 50-358 S | BRANDENBURG, B | 8302170277 | 50-247 T | BURWELL, S B | 8302250161 | 50-445 |
| BORGAN, E A | 8302040432 | 50-358 Q | BRANNIN, J P | 8302010467* | 50-335 S | BURWELL, S B | 8302250243* | 50-445 |
| BORGAN, E A | 8302080291 | 50-358 B | BRANNIN, J P | 8302170160* | 50-335 S | BUSCH, J E | 8302240199 | FOIA |
| BORGAN, E A | 8302080299 | 50-358 B | BRENNEMAN, F H | 8302150134 | 50-443 X | BUSCH, S L | 8302080019* | 50-206 |
| BORGAN, E A | 8302080323 | 50-358 S | BRENNER, L | 8302070495 | 50-322 Q | BUSS, R | 8302150048* | 50-254 |
| BORGAN, E A | 8302140006 | 50-358 C | BRENNER, L | 8302160397 | 50-352 Q | BUTCHER, R C | 8302150139 | 50-259 |
| BORGAN, E A | 8302150358 | 50-358 A | BRENNER, L | 8302160358 | 50-322 Q | BUTCHER, R C | 8302230192 | 50-260 |
| BORGAN, E A | 8302150377 | 50-358 S | BRENNER, L | 8302160361 | 50-352 Q | BUTLER, S D | 8302150320* | 50-327 |
| BORGAN, E A | 8302150529 | 50-358 S | BRENNER, L | 8302230635 | 50-352 Q | BUTLER, S D | 8302150482* | 50-327 |
| BORGAN, E A | 8302170037 | 50-358 K | BRENNER, L | 8302100480 | PR | BUTLER, S D | 8302150678* | 50-327 |
| BORGAN, E A | 8302180253 | 50-358 B | BRENNER, L | 8302040133* | 50-537 A | BUZZY, J J | 8302250055* | 50-443 |
| BORGAN, E A | 8302180270 | 50-358 B | BREY, H L | 8302070382 | 50-267 P | BYRD, R | 8302010192* | 50-416 |
| BORGAN, E A | 8302180356* | 50-358 A | BREY, H L | 8302070355 | 50-267 P | BYRD, R | 8302030393* | 50-416 |
| BORGAN, E A | 8302180444 | 50-358 B | BREY, H L | 8302150618 | 50-267 P | BYRD, R | 8302140019* | 50-416 |
| BORGAN, E A | 8302180470 | 50-358 B | BRIDEN, D W | 8302080380* | 50-346 F | BYRD, R | 8302140039* | 50-416 |
| BORGAN, E A | 8302280435 | 50-358 B | BRIDEN, D W | 8302180073* | 50-346 F | BYRD, R | 8302140067* | 50-416 |
| BORST, F J | 8302230641 | 50-267 R | BRIDEN, D W | 8302230418* | 50-213 Q | BYRD, R | 8302150106* | 50-416 |
| BORST, F J | 8302250232 | 50-267 P | BRIDEN, P H | 8302070370* | 50-244 Q | BYRD, R | 8302170320* | 50-416 |
| BORCHOWITZ, R | 8302090183* | COMMISSION | BRIGHT, O O | 8302010472 | 50-440 Q | BYRD, R | 8302170362* | 50-416 |
| BOUCHEY, O D | 8302010416 | 50-508 A | BRIGHT, O O | 8302070537 | 50-483 Q | BYRD, R | 8302280289* | 50-416 |
| BOUCHEY, O D | 8302010548 | 50-460 C | BRIGHT, O O | 8302240299 | 50-460 Q | BYRD, R | 8302280454* | 50-416 |
| BOUCHEY, O D | 8302020003 | 50-508 C | BRIGHT, O O | 8302240307 | 50-397 Q | BYRD, R C | 8302030373* | 50-537 |
| BOUCHEY, O D | 8302020033 | 50-397 A | BROBST, O E | 8302230616* | 50-317 S | BYRON, P H | 8302180104* | 50-341 |
| BOUCHEY, O D | 8302020048 | 50-508 C | BROCK, B L | 8302180172* | 70-1257 | CACCIAPOUTI, R | 8302250167* | 50-271 |
| BOUCHEY, O D | 8302030046 | 50-397 F | BROCK, B L | 8302220067* | 50-142 Q | CADWELL, L L | 8302250053 | NUREQ |
| BOUCHEY, O D | 8302070276 | 50-508 A | BROCK, B L | 8302230317* | 70-734 | CAONETTA, J P | 8302010491 | 50-245 |
| BOUCHEY, O D | 8302080005 | 70-2950 | BROCK, B L | 8302230387* | 50-247 Q | CAONETTA, J P | 8302010491 | 50-245 |
| BOUCHEY, O D | 8302080021 | 50-460 A | BROCK, B L | 8302010386 | 50-344 P | CAONETTA, J P | 8302010565 | 50-213 |
| BOUCHEY, O D | 8302090366 | 50-397 A | BROCK, B L | 8302010398 | 50-344 S | CAONETTA, J P | 8302030202* | 50-245 |
| BOUCHEY, O D | 8302090388 | 50-397 A | BROCK, B L | 8302030084 | 50-286 Q | CAONETTA, J P | 8302030202* | 50-245 |
| BOUCHEY, O D | 8302090401 | 50-397 G | BROCK, B L | 8302040349* | WASTE MOT | CAONETTA, J P | 8302030250* | 50-245 |
| BOUCHEY, O D | 8302100338 | PR | BROCK, B L | 8302150323* | 50-155 P | CAONETTA, J P | 8302030250* | 50-245 |
| BOUCHEY, O D | 8302150189 | 50-397 A | BROUGHTON, J H | 8302010401 | REB | CAONETTA, J P | 8302180184* | 50-245 |
| BOUCHEY, O D | 8302150200 | 50-397 J | BROWN, B | 8302150048* | 50-254 R | CAONETTA, J P | 8302230709* | 50-458 |
| BOUCHEY, O D | 8302150597 | 50-397 A | BROWN, C O | 8302280564 | 71-3450 | CAHILL, W J | 8302140017 | REGOD |
| BOUCHEY, O D | 8302150637 | 50-397 A | BROWN, O D | 8301110451 | MISC | CAHN, A L | 8302140017 | REGOD |
| BOUCHEY, O D | 8302160215 | 50-397 I | BROWN, O D | 8302070443 | State Prog | CAHN, A L | 8302140017 | REGOD |
| BOUCHEY, O D | 8302170391 | 50-397 A | BROWN, O D | 8302230115 | MISC | CAIN, C L | 8302230503 | 70-1062 |
| BOUCHEY, O D | 8302230285 | 50-397 A | BROWN, H | 8302240318* | 50-322 Q | CAIN, C L | 8302230509* | 70-1062 |
| BOUCHEY, O D | 8302230374 | 50-397 A | BROWN, H | 8302240318* | 50-322 Q | CAIN, J | 8302090482 | WASTE I |
| BOUCHEY, O D | 8302230386 | 50-397 F | BROWN, H H | 8302240321* | 50-322 Q | CAIN, J | 8302090492 | WASTE I |
| BOUCHEY, O D | 8302230521 | 50-397 A | BROWN, H H | 8302240321* | 50-322 Q | CAIN, J | 8302170023 | WASTE I |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|-------------------|------------------|------------------|
| CAIN, J | 8302170031 | WASTE MGT | CARTWRIGHT, W R | 8302280486 | 50-339 S | CHILK, S J | 8302180517 | 70-143 |
| CAIN, J | 8302170039 | WASTE MGT | CARTWRIGHT, W R | 8302280491* | 50-339 S | CHILK, S J | 8302220028 | 10CFR |
| CAIN, J | 8302180522 | WASTE MGT | CARUSO, R | 8302170929 | 50-322 A | CHILK, S J | 8302220340 | 50-289 Q |
| CAIN, J | 8302220194 | WASTE MGT | CARUSO, R | 8302240023 | 50-322 A | CHILK, S J | 8302220343 | 50-329 Q |
| CAIN, S H | 8302160239* | 50-377 I | CARUSO, R | 8302250037 | 50-322 A | CHILK, S J | 8302230585 | 50-289 Q |
| CAKE, M P | 8302030080 | PT21 | CARVER, A M | 8302150568* | 50-328 S | CHILK, S J | 8302230617 | 50-358 Q |
| CALDWELL, R A | 8302070180* | 50-131 Q | CARVER, A M | 8302170146* | 50-327 S | CHILK, S J | 8302230660 | 50-289 Q |
| CALDWELL, R A | 8302150582* | 50-128 Q | CARVER, A M | 8302240266* | 50-327 S | CHILK, S J | 8302250373 | PRM |
| CALDWELL, R A | 8302230517* | 50-128 Q | CASADA, M L | 8302020139* | 50-29 P | CHILK, S J | 8302280193 | 50-277 Q |
| CALLAN, L J | 8302070475* | 50-313 Q | CASTILLAS, F C | 8302030431* | GA999 | CHIN, P | 8302090605* | 50-293 R |
| CAMP, M J | 8302080326* | 50-313 S | CASTLE, L W | 8302180230* | 50-316 S | CHIN, P | 8302090609* | 50-293 R |
| CAMPBELL, J | 8302040311* | 50-267 F | CASTRO, G | 8302100173* | 40-3453 | CHIN, P | 8302090617* | 50-293 R |
| CAMPBELL, R D | 8302160189 | 50-329 A | CASTRO, G | 8302150736* | CONTRACT | CHRISHOLM, R J | 8302220375* | 50-289 T |
| CAMPBELL, R D | 8302170309 | 50-329 A | CATCHPOLE, D J | 8302010017 | 40-8745 | CHITKARA, K K | 8302280229 | 50-358 V |
| CAMPBELL, S E | 8302140211 | PRM | CATCHPOLE, D J | 8302090497 | 40-8693 | CHOU, J | 8302180035* | FOIA |
| CANNEY, C A | 8302140139 | 50-443 Q | CATCHPOLE, D J | 8302090583 | 40-8745 | CHOCKIE, A D | 8302103045* | FOIA |
| CANNEY, C A | 8302140141* | 50-443 Q | CATCHPOLE, D J | 8302100464 | PR | CHOI, H | 8302070267* | 50-213 P |
| CANTER, H L | 8302230271* | 50-312 Q | CATCHPOLE, D J | 8302160412 | 40-8745 | CHOU, C K | 8302170208 | NUREG |
| CANTRELL, F S | 8302070581 | 50-296 Q | CATTON, I | 8302080414 | ACRS | CHRISTOFFERSON, N | 8302280341* | 50-254 Q |
| CANTRELL, F S | 8302150426* | 50-416 Q | CATTON, I | 8302080416 | ACRS | CHRISTEL, B | 830210152* | 50-237 S |
| CANTRELL, F S | 8302230192 | 50-260 S | CATTON, I | 8302080479 | 50-382 Q | CHRISTENSEN, R | 8302100114* | CONTRACT |
| CANTRELL, F S | 8302010185* | 50-293 S | CATTON, I | 8302170198 | NUREG | CHRISTMAN, J N | 8302100264 | PRM |
| CANTRELL, F S | 8302080287* | 50-304 S | CATTON, I | 8302220116* | 50-142 Q | CHRISTMAN, J N | 8302220344 | 50-280 P |
| CAO, N | 8302170325* | 50-409 P | CATTON, I | 8302220119* | 50-142 F | CHRISTOFFER, O | 8302180173* | 70-1193 |
| CAPHTON, D L | 8302180236* | 50-247 Q | CAUDLE, R E | 8302040487 | 71-9150 | CHRISTOFFERSON | 8302150337* | GA999 |
| CAPODANNO, O R | 8302220359* | 50-289 T | CAUSEY, J C | 8302160248 | 50-321 P | CHU, R Y L | 8302140128 | PR |
| CAPODANNO, O R | 8302220375* | 50-289 T | CAUSEY, J C | 8302180287 | 50-321 P | CHUANG, T V | 8302170469 | NUREG |
| CARBON, M W | 8302180078* | 50-358 Q | CAVANAUGH, W | 8302150011 | 50-368 P | CHUNG, D H | 8302170213 | NUREG |
| CAREY, J J | 8302080296 | 50-334 P | CAVANAUGH, W | 8302180393 | 50-368 Q | CHUNG, J W | 8302280446* | 50-387 Q |
| CAREY, J J | 8302080302 | 50-334 P | CAVANAUGH, W | 8302230403 | 50-313 P | CHURCHILL, B W | 8302020278 | 50-382 Q |
| CAREY, J J | 8302150335 | 50-334 P | CAVANAUGH, W | 8302230499 | 50-313 H | CHURCHILL, B W | 8302020278 | 50-382 Q |
| CAREY, J J | 8302160267 | 50-334 F | CEJA, S N | 8302090526 | XPORTLIC | CHURCHILL, B W | 8302020341 | 50-382 Q |
| CAREY, J J | 8302170186 | 50-334 P | CERNE, A | 8302030197* | 50-322 Q | CHURCHILL, B W | 8302020341 | 50-382 Q |
| CAREY, J J | 8302170193* | 50-334 P | CERNY, R J | 8302100473* | PR | CHURCHILL, B W | 8302250430 | 50-382 Q |
| CAREY, J J | 8302170380 | 50-334 P | CHACKES, K M | 8302070573 | 50-483 Q | CHURCHILL, B W | 8302250430 | 50-382 Q |
| CAREY, J J | 8302170381* | 50-334 P | CHACKES, K M | 8302070573 | 50-483 Q | CILLIS, M | 8302230324* | 50-344 Q |
| CAREY, J J | 8302180440 | 50-334 Q | CHAFFEE, A | 8302230263* | 50-361 Q | CLARDY, L S | 8302080313* | 50-331 Q |
| CAREY, J J | 8302220322 | 50-334 P | CHALK, W S | 8302030458 | 50-139 R | CLARK, C W | 8302020277 | TOPREP |
| CAREY, J J | 8302220370 | 50-334 P | CHAMBERS, O | 8302280184* | 50-260 S | CLARK, D | 8302170505 | 50-259 Q |
| CAREY, J J | 8302240315* | 50-334 F | CHAMBERS, O T | 8302030577* | 50-259 S | CLARK, J R | 8302100283 | PR |
| CAREY, J J | 8302250185 | 50-334 Q | CHAMBERS, R | 8302160003 | RES | CLARK, J R | 8302100362 | PR |
| CARLSON, J D | 8302070339* | 50-275 Q | CHAM, S | 8302240011 | RES | CLARK, L | 8302180070* | 50-358 A |
| CARLSON, R W | 8302220317* | 50-454 T | CHANDLER, J C | 8302140044 | 50-316 P | CLARK, L A | 8302090035* | 50-358 Q |
| CARLSON, R W | 8302220317* | 50-454 T | CHANDLER, J C | 8302180243 | TOPREP | CLARK, P R | 8302030365* | 50-363 Q |
| CARLTON, R F | 8302180211* | 50-358 A | CHANDLER, J C | 8302180336 | TOPREP | CLARK, P R | 8302180504 | 50-219 P |
| CARNAHAN, C L | 8302250122 | NUREG | CHANDLER, J C | 8302230327 | TOPREP | CLARK, R A | 8302010013 | 50-335 P |
| CARR, A V | 8302240062 | 50-269 P | CHANDLER, L J | 8302020291 | 50-361 Q | CLARK, R A | 8302010030 | 50-285 P |
| CARTEAUX, P | 8302080266* | 50-315 S | CHANDLER, L J | 8302020326 | 50-361 Q | CLARK, R A | 8302010046 | 50-313 P |
| CARTEAUX, P | 8302090329* | 50-316 S | CHANDLER, L J | 8302020335* | 50-361 Q | CLARK, R A | 8302010050 | 50-313 P |
| CARTEAUX, P | 8302080335* | 50-316 S | CHANDLER, L J | 8302280263 | 50-275 Q | CLARK, R A | 8302010062 | 50-285 P |
| CARTEAUX, P | 8302080337* | 50-316 S | CHANG, T Y | 8110230003* | 50-322 A | CLARK, R A | 8302010085 | 50-309 P |
| CARTEAUX, P | 8302080341* | 50-316 S | CHANG, T Y | 8111170512* | 50-322 A | CLARK, R A | 8302010090 | 50-316 P |
| CARTEAUX, P | 8302160285* | 50-316 S | CHAPLIN, S D | 8302230699* | 50-320 S | CLARK, R A | 8302020182 | 50-335 P |
| CARTEAUX, P | 8302160340* | 50-315 S | CHAPLIN, S D | 8302250211* | 50-320 S | CLARK, R A | 8302020205 | 50-317 Q |
| CARTEAUX, P | 8302160342* | 50-315 S | CHAPPELL, C R | 8302040307* | 71-9150 | CLARK, R A | 8302020219* | 50-317 Q |
| CARTEAUX, P | 8302280352* | 50-316 S | CHARNLEY, J E | 8302010350* | 50-321 Q | CLARK, R A | 8302020223 | 50-266 P |
| CARTER, R E | 8302280286* | 50-170 Q | CHARNLEY, J S | 8301260116 | TOPREP | CLARK, R A | 8302020243 | 50-309 S |
| CARTWRIGHT, W R | 8302010176 | 50-339 S | CHARNLEY, J S | 8302170335 | 50-447 A | CLARK, R A | 8302070121 | 50-285 P |
| CARTWRIGHT, W R | 8302010187* | 50-339 S | CHARNLEY, J S | 8302230221 | TOPREP | CLARK, R A | 8302080354 | 50-317 P |
| CARTWRIGHT, W R | 8302010207 | 50-339 S | CHARNLEY, J S | 8302230407 | TOPREP | CLARK, R A | 8302100006 | 50-313 P |
| CARTWRIGHT, W R | 8302010214* | 50-339 S | CHARNLEY, J S | 8302240298 | TOPREP | CLARK, R A | 8302100082 | 50-285 P |
| CARTWRIGHT, W R | 8302010237 | 50-339 S | CHAUDHARY, S K | 8302230273* | 50-352 Q | CLARK, R A | 8302100109* | 50-318 P |
| CARTWRIGHT, W R | 8302010245* | 50-339 S | CHEN, P Y | 8103140808* | 50-322 A | CLARK, R A | 8302100127* | 50-317 P |
| CARTWRIGHT, W R | 8302070309 | 50-339 S | CHEN, H P | 8302230243* | 50-445 Q | CLARK, R A | 8302100141* | 50-338 P |
| CARTWRIGHT, W R | 8302070314* | 50-339 S | CHESTER, R D | 8302070186* | FOIA | CLARK, R A | 8302100150* | 50-338 P |
| CARTWRIGHT, W R | 8302070340 | 50-339 S | CHESTNUT, S H | 8302100322* | 50-445 A | CLARK, R A | 8302100171 | 50-344 F |
| CARTWRIGHT, W R | 8302070342* | 50-339 S | CHILDERS, B D | 8302100291 | PR | CLARK, R A | 8302100193 | 50-285 P |
| CARTWRIGHT, W R | 8302070372 | 50-338 S | CHILK, S J | 8302100336 | 50-289 Q | CLARK, R A | 8302100197 | 50-282 F |
| CARTWRIGHT, W R | 8302070376* | 50-338 S | CHILK, S J | 8302010071* | FOIA | CLARK, R A | 8302100260 | 50-309 P |
| CARTWRIGHT, W R | 8302140024 | 50-339 S | CHILK, S J | 8302010499 | 50-341 Q | CLARK, R A | 8302100492 | 50-309 P |
| CARTWRIGHT, W R | 8302140027* | 50-339 S | CHILK, S J | 8302010503 | 50-329 Q | CLARK, R A | 8302100496 | 50-309 P |
| CARTWRIGHT, W R | 8302140036 | 50-339 S | CHILK, S J | 8302010510 | 50-289 Q | CLARK, R A | 8302160082* | 50-282 P |
| CARTWRIGHT, W R | 8302140047* | 50-339 S | CHILK, S J | 8302020406 | FOIA | CLARK, R A | 8302160061* | 50-282 P |
| CARTWRIGHT, W R | 8302140081 | 50-339 S | CHILK, S J | 8302070527 | 50-247 Q | CLARK, R A | 8302160519 | 50-368 P |
| CARTWRIGHT, W R | 8302140088 | 50-339 S | CHILK, S J | 8302070544 | 50-289 Q | CLARK, R A | 8302160522 | 50-313 P |
| CARTWRIGHT, W R | 8302140092 | 50-338 S | CHILK, S J | 8302070550 | 50-289 Q | CLARK, R A | 8302170013 | 50-266 P |
| CARTWRIGHT, W R | 8302140095* | 50-339 S | CHILK, S J | 8302080018 | 50-397 H | CLARK, R A | 8302170063 | 50-368 S |
| CARTWRIGHT, W R | 8302140096* | 50-339 S | CHILK, S J | 8302070247 | 50-329 Q | CLARK, R A | 8302170273 | 50-344 F |
| CARTWRIGHT, W R | 8302140098* | 50-338 S | CHILK, S J | 8302090253 | 50-289 Q | CLARK, R A | 8302170274 | 50-344 F |
| CARTWRIGHT, W R | 8302170152 | 50-339 S | CHILK, S J | 8302090260 | 50-392 Q | CLARK, R A | 8302170439 | 50-285 P |
| CARTWRIGHT, W R | 8302170158* | 50-339 S | CHILK, S J | 8302100084 | 70-143 | CLARK, R A | 8302220044 | 50-266 P |
| CARTWRIGHT, W R | 8302170190 | 50-338 S | CHILK, S J | 8302100118 | 10CFR | CLARK, R A | 8302220047 | 50-309 P |
| CARTWRIGHT, W R | 8302170200* | 50-338 S | CHILK, S J | 8302140023 | 70-143 | CLARK, R A | 8302230019 | 50-336 P |
| CARTWRIGHT, W R | 8302170220 | 50-339 S | CHILK, S J | 8302140213 | 10CFR | CLARK, R A | 8302240129 | 50-344 P |
| CARTWRIGHT, W R | 8302170226* | 50-339 S | CHILK, S J | 8302160406* | GEN TEC 16 | CLARK, R A | 8302240404 | 50-313 P |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|----------------|------------------|------------------|---------------|------------------|------------------|
| CLAY, E L | 8302150403* | 70-143 | COLLINS, J T | 8302220410* | State Prog | COBNEY, M J | 8302220106 | 50-278 |
| CLAYTON, F L | 8302010095 | 50-348 S | COLLINS, J T | 8302230120 | 50-382 Q | COBNEY, M J | 8302220114* | 50-278 |
| CLAYTON, F L | 8302010916 | 50-348 S | COLLINS, J T | 8302230340 | 50-285 Q | COBNEY, M J | 8302220121 | 50-278 |
| CLAYTON, F L | 8302010539 | 50-348 Q | COLLINS, J T | 8302230538 | 50-313 Q | COBNEY, M J | 8302220126* | 50-278 |
| CLAYTON, F L | 8302030344 | 50-348 P | COLLINS, J T | 8302230546 | 50-498 Q | COBNEY, M J | 8302220401 | 50-278 |
| CLAYTON, F L | 8302070613 | 50-348 S | COLLINS, J T | 8302230558 | 50-449 Q | COBNEY, M J | 8302230146 | 50-27 |
| CLAYTON, F L | 8302080012 | 50-344 Q | COLLINS, J T | 8302230565 | 50-382 Q | COOPER, J H | 8302070317* | 50-338 |
| CLAYTON, F L | 8302080017* | 50-344 Q | COLLINS, J T | 8302230573 | 50-298 Q | COOPER, W E | 8302030496 | 50-278 |
| CLAYTON, F L | 8302090329 | 50-348 P | COLLINS, J T | 8302230581 | 50-498 Q | COOPER, W E | 8302090152 | 50-278 |
| CLAYTON, F L | 8302090467* | 50-348 F | COLLINS, J T | 8302230591 | 50-285 Q | COOPER, W E | 8302090182 | 50-278 |
| CLAYTON, F L | 8302100245 | 50-348 P | COLLINS, J T | 8302230684 | 50-267 Q | COOPER, W E | 8302180252 | 50-278 |
| CLAYTON, F L | 8302100338 | PR | COLLINS, J T | 8302230690 | 50-482 Q | COOPER, W E | 8302180277 | 50-278 |
| CLAYTON, F L | 8302150009 | 50-344 Q | COLLINS, J T | 8302230696 | 50-267 Q | COOPER, W E | 8302220368 | 50-27 |
| CLAYTON, F L | 8302180247 | 50-348 P | COLLINS, S J | 8302270357* | 50-29 | COOPER, W E | 8302240280 | 50-27 |
| CLAYTON, F L | 8302220127 | 50-348 R | COLLINS, T J | 8302070018 | 40-7455 | COPELAND, V O | 8302160223 | 50-45 |
| CLAYTON, F L | 8302220174 | 50-348 S | COLLINS, T R | 8302150320* | 50-327 Q | COPELAND, V O | 8302160223 | 50-45 |
| CLAYTON, F L | 8302220363 | 50-348 S | COLLINS, T R | 8302150710* | 50-259 Q | COPELAND, V O | 8302230446 | 50-45 |
| CLAYTON, F L | 8302220408 | 50-344 R | COLLOPY, T J | 8302080074 | 70-371 | COPELAND, V O | 8302230446 | 50-45 |
| CLAYTON, F L | 83022303197 | 50-344 P | COLQUHOUN, R | 8302170376* | 50-312 R | CORBIT, C D | 8302170061* | 50-28 |
| CLAYTON, F L | 8302230397 | 50-348 P | COLQUHOUN, R W | 8302040276* | 50-312 S | CORDANI, R A | 8302100451 | PR |
| CLAYTON, F L | 8302230708 | 50-344 S | COLQUHOUN, R W | 8302230613* | 50-312 S | CORNICAN, A | 8302220419* | 50-24 |
| CLAYTON, F L | 8302280038 | 50-344 S | COMDIE, K O | 8302160397 | RES | CORVELL, O P | 8302080270 | 70-11 |
| CLAYTON, D J | 8302150001 | 50-267 S | CONLON, T E | 8302150084* | 50-370 Q | CORVELL, O P | 8302150069* | 70-14 |
| CLEMENTS, B R | 8302170175 | 50-445 K | CONLON, T E | 8302150140* | 50-413 Q | COSTELLO, J R | 8302160339* | QA999 |
| CLEMENTS | 8302150559* | 50-245 Q | CONLON, T E | 8302150303* | 50-416 Q | COSTA, R J | 8302100338 | PR |
| CLEMENTS, P | 8302030537* | 70-371 | CONLON, T E | 8302150496* | 50-390 Q | COTTON, O D | 8302220337* | 50-36 |
| CLEWETT, J | 8302100349 | PRM | CONLON, T E | 8302150591* | 50-424 Q | COTTON, O D | 8302220339* | 50-36 |
| CLINE, W E | 8302150645* | 50-369 Q | CONLON, T E | 8302150711* | 50-400 Q | COTTON, O D | 8302220284* | 50-36 |
| COCKRELL, R O | 8302150075* | 50-111 Q | CONNAUGHTON, K | 8302150408* | 50-454 Q | COUGHLIN, L | 8302030029* | 50-53 |
| COCKRELL, R O | 8302150082* | 50-111 Q | CONNER, T B | 8302010924 | 50-352 Q | COUNCIL, W O | 8302190078 | 50-21 |
| CODDINGTON, C T | 8302280091 | 50-387 P | CONNER, T B | 8302010924 | 50-352 Q | COUNCIL, W O | 8302190078 | 50-21 |
| COEN, R W | 8302160226* | 50-237 S | CONNER, T B | 8302070510 | 50-352 Q | COUNCIL, W O | 8302010301 | 50-21 |
| COGAN, N J | 8302180236* | 50-247 Q | CONNER, T B | 8302070510 | 50-352 Q | COUNCIL, W O | 8302010301 | 50-21 |
| COHALAN, P F | 8302240313 | 50-322 Q | CONNER, T B | 8302100362 | PR | COUNCIL, W O | 8302010301 | 50-21 |
| COHEN, I | 8302250333* | 50-272 Q | CONNER, T B | 8302230488 | 50-352 Q | COUNCIL, W O | 8302010301 | 50-21 |
| COHEN, L A | 8302240320 | 50-247 T | CONNER, T B | 8302230488 | 50-352 Q | COUNCIL, W O | 8302010491 | 50-24 |
| COHN, B | 8302010002* | CONTRACT | CONRAN, J H | 8302100262* | 50-322 Q | COUNCIL, W O | 8302010491 | 50-24 |
| COLARULLI, P F | 8302010530 | 50-247 T | CONSTABLE, O L | 8302030390* | 50-382 Q | COUNCIL, W O | 8302010565 | 50-21 |
| COLARULLI, P F | 8302010530 | 50-247 T | CONTE, R | 8302030429* | 50-289 Q | COUNCIL, W O | 8302010682* | 50-21 |
| COLARULLI, P F | 8302020254 | 50-247 Q | CONTE, R | 8302070335* | 50-289 Q | COUNCIL, W O | 8302010682* | 50-21 |
| COLARULLI, P F | 8302020254 | 50-247 Q | CONTE, R | 8302250288* | 50-289 Q | COUNCIL, W O | 8302030043* | 50-21 |
| COLARULLI, P F | 8302020254 | 50-247 Q | CONVERSE, E M | 8302040485* | CONTRACT | COUNCIL, W O | 8302030043* | 50-21 |
| COLARULLI, P F | 8302020345 | 50-247 Q | CONVERSE, R | 8302180304* | 50-333 S | COUNCIL, W O | 8302030043* | 50-21 |
| COLARULLI, P F | 8302030164 | 50-247 Q | CONVERSE, R J | 8302080239 | 50-333 R | COUNCIL, W O | 8302030186 | 50-42 |
| COLARULLI, P F | 8302030164 | 50-247 Q | CONWAY, J T | 8302070265* | QA999 | COUNCIL, W O | 8302030186 | 50-42 |
| COLARULLI, P F | 8302030175* | 50-247 Q | CONWAY, L | 8302170302* | 50-454 T | COUNCIL, W O | 8302030202* | 50-24 |
| COLARULLI, P F | 8302030175* | 50-247 Q | CONWAY, L | 8302170302* | 50-454 T | COUNCIL, W O | 8302030202* | 50-24 |
| COLARULLI, P F | 8302070559 | 50-247 Q | CONWAY, L | 8302180387 | 50-454 T | COUNCIL, W O | 8302030250* | 50-24 |
| COLARULLI, P F | 8302070559 | 50-247 Q | CONWAY, L | 8302230461* | 50-454 T | COUNCIL, W O | 8302030250* | 50-24 |
| COLARULLI, P F | 8302090224 | 50-247 T | COOK, D. | 8302160158* | 50-265 S | COUNCIL, W O | 8302040278 | 50-21 |
| COLARULLI, P F | 8302090224 | 50-247 T | COOK, F R | 8302240347 | HASTE MGT | COUNCIL, W O | 8302040283 | 50-21 |
| COLARULLI, P F | 8302160278 | 50-247 Q | COOK, J | 8302080242* | 50-333 R | COUNCIL, W O | 8302070198 | 50-21 |
| COLARULLI, P F | 8302160270 | 50-247 Q | COOK, J W | 8302020451* | 50-329 F | COUNCIL, W O | 8302070384 | 50-21 |
| COLARULLI, P F | 8302160372 | 50-247 Q | COOK, J W | 8302030399 | 50-329 A | COUNCIL, W O | 8302070432 | 50-21 |
| COLARULLI, P F | 8302160372 | 50-247 Q | COOK, J W | 8302040093 | 50-329 E | COUNCIL, W O | 8302070566 | 50-21 |
| COLARULLI, P F | 8302160372 | 50-247 Q | COOK, J W | 8302040093 | 50-329 E | COUNCIL, W O | 8302070566 | 50-21 |
| COLARULLI, P F | 8302160385 | 50-247 Q | COOK, J W | 8302040112 | 70-2944 | COUNCIL, W O | 8302070566 | 50-21 |
| COLARULLI, P F | 8302160385 | 50-247 Q | COOK, J W | 8302040307 | 50-329 S | COUNCIL, W O | 8302070566 | 50-21 |
| COLARULLI, P F | 8302160399 | 50-247 Q | COOK, J W | 8302040328 | 50-329 S | COUNCIL, W O | 8302080202 | 50-21 |
| COLARULLI, P F | 8302160399 | 50-247 Q | COOK, J W | 8302040329 | 50-329 S | COUNCIL, W O | 8302090304 | 50-2 |
| COLARULLI, P F | 8302170860 | 50-247 T | COOK, J W | 8302040512 | 70-2944 | COUNCIL, W O | 8302100234 | 50-2 |
| COLARULLI, P F | 8302170260 | 50-247 T | COOK, J W | 8302080205 | 50-329 S | COUNCIL, W O | 8302100285 | PR |
| COLARULLI, P F | 8302170277 | 50-247 T | COOK, J W | 8302080216 | 50-329 Q | COUNCIL, W O | 8302140105 | PR |
| COLARULLI, P F | 8302170277 | 50-247 T | COOK, J W | 8302080305 | 50-329 S | COUNCIL, W O | 8302140105 | PR |
| COLARULLI, P F | 8302170283 | 50-247 T | COOK, J W | 8302180456 | 50-329 S | COUNCIL, W O | 8302140105 | PR |
| COLARULLI, P F | 8302170283 | 50-247 T | COOK, J W | 8302180500 | 50-329 S | COUNCIL, W O | 8302150498 | 50-2 |
| COLEMAN, J H | 8302160348 | 50-338 Q | COOK, J W | 8302180502 | 50-329 A | COUNCIL, W O | 8302150498 | 50-2 |
| COLEMAN, J H | 8302160348 | 50-338 Q | COOK, J W | 8302230241 | 50-329 E | COUNCIL, W O | 8302150444 | 50-2 |
| COLEY, J L | 8302180024* | 50-289 Q | COOK, J W | 8302230405 | 50-329 A | COUNCIL, W O | 8302160224 | 50-2 |
| COLLIER, J W | 8302010937* | 50-287 P | COOK, J W | 8302230492 | 50-329 A | COUNCIL, W O | 8302160224 | 50-2 |
| COLLINS, D J | 8302100437* | 50-387 Q | COOK, J W | 8302230508 | 50-329 A | COUNCIL, W O | 8302160224 | 50-2 |
| COLLINS, D J | 8302180239* | 50-317 Q | COOK, J W | 8302240262 | 50-329 A | COUNCIL, W O | 8302180184* | 50-2 |
| COLLINS, D J | 8302180289* | 50-309 Q | COOK, J W | 8302240267* | 50-329 A | COUNCIL, W O | 8302180184* | 50-2 |
| COLLINS, J T | 8302010231 | 50-313 Q | COOK, J W | 8302280169 | 50-329 A | COUNCIL, W O | 8302180429 | 50-3 |
| COLLINS, J T | 8302010656 | MISC | COOK, R J | 8302040310* | 50-329 Q | COUNCIL, W O | 8302220148 | 50-4 |
| COLLINS, J T | 8302030329 | 50-298 Q | COOK, R J | 8302250393* | 50-329 Q | COUNCIL, W O | 8302220148 | 50-4 |
| COLLINS, J T | 8302070343 | 50-368 Q | COOKE, O C | 8302010605* | 50-335 P | COUNCIL, W O | 8302220148 | 50-4 |
| COLLINS, J T | 8302070559 | State Prog | COONEY, M J | 8302180334 | 50-277 R | COUNCIL, W O | 8302220155 | 50-2 |
| COLLINS, J T | 8302090339 | QA999 | COONEY, M J | 8302030400 | 50-277 S | COUNCIL, W O | 8302220155 | 50-2 |
| COLLINS, J T | 8302090406 | QA999 | COONEY, M J | 8302030408* | 50-277 S | COUNCIL, W O | 8302220349 | 50-3 |
| COLLINS, J T | 8302150098 | 50-267 P | COONEY, M J | 8302070521 | 50-278 S | COUNCIL, W O | 8302220349 | 50-3 |
| COLLINS, J T | 8302180107 | 50-298 Q | COONEY, M J | 8302090318 | 50-277 S | COUNCIL, W O | 8302220427 | 50-2 |
| COLLINS, J T | 8302180452 | QA999 | COONEY, M J | 8302090339 | 50-277 S | COUNCIL, W O | 8302220427 | 50-2 |
| COLLINS, J T | 8302190338 | MISC | COONEY, M J | 8302090349* | 50-277 S | COUNCIL, W O | 8302230532* | 50-2 |
| COLLINS, J T | 8302170393 | 50-445 Q | COONEY, M J | 8302090393 | 50-278 S | COUNCIL, W O | 8302230532* | 50-2 |
| COLLINS, J T | 8302220407 | State Prog | COONEY, M J | 8302150693 | 50-277 S | COUNCIL, W O | 8302240326 | 50-2 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---------------|------------------|------------------|-----------------|------------------|------------------|----------------|------------------|------------------|
| COUNCIL, H Q | 8302240331 | 50-213 P | CROUSE, R P | 8302280396* | 50-346 Q | CURRAN, D | 8302220382* | 50-443 Q |
| COUNCIL, H Q | 8302240331 | 50-213 P | CROUSE, R P | 8302280405* | 50-346 Q | CURRAN, D | 8302220392* | 50-443 Q |
| COUNCIL, H Q | 8302240331 | 50-213 P | CROUSE, R P | 8302280408* | 50-346 Q | CURRAN, D | 8302220392* | 50-443 Q |
| COUNCIL, H Q | 8302280097 | 50-213 V | CROW, W T | 8302030050* | 70-2949 | CURRAN, D | 8302220399* | 50-443 Q |
| COUNCIL, H Q | 8302280097 | 50-213 V | CROW, W T | 8302080477* | 70-1113 | CURRAN, D | 8302220399* | 50-443 Q |
| COUNCIL, H Q | 8302280097 | 50-213 V | CROW, W T | 8302220484* | 70-371 | CURTIS, D J | 8302220526* | 50-323 H |
| COUNCIL, H Q | 8302280226 | 50-213 P | CROWLEY, B R | 8302010593 | 50-325 S | CURTIS, N W | 8302030403 | 50-387 P |
| COUNCIL, H Q | 8302280431 | 50-336 P | CROWLEY, B R | 8302010684 | 50-325 S | CURTIS, N W | 8302070247 | 50-387 P |
| COUNCIL, H Q | 8302280431 | 50-336 P | CROWN, F J | 8302070197* | FOIA | CURTIS, N W | 8302070634 | 70-2937 |
| COUNCIL, H Q | 8302280440 | 50-245 P | CROYLE, R H | 8302040431 | 40-17 | CURTIS, N W | 8302090309 | 50-387 P |
| COUNCIL, H Q | 8302280490 | 50-245 P | CRUTCHFIELD, D | 8302280195* | 50-255 P | CURTIS, N W | 8302090314* | 50-387 P |
| COURTIER, P | 8302240346 | XPORTLIC | CRUTCHFIELD, D | 8212030242 | 50-219 P | CURTIS, N W | 8302100277 | PR |
| COVER, L E | 8302170469 | NUREG | CRUTCHFIELD, D | 8302010627 | 50-409 P | CURTIS, N W | 8302100463 | PRM |
| COWAN, B Z | 8302100406 | PRM | CRUTCHFIELD, D | 8302010632 | 50-153 P | CURTIS, N W | 8302150198 | 50-387 P |
| COWAN, B Z | 8302160359 | 50-413 Q | CRUTCHFIELD, D | 8302010713 | 50-29 F | CURTIS, N W | 8302150207* | 50-387 P |
| COWGILL, C | 8302030197* | 50-322 Q | CRUTCHFIELD, D | 8302040300 | 50-213 P | CURTIS, N W | 8302150616 | 50-388 A |
| COWGILL, C | 8302230142* | 50-219 Q | CRUTCHFIELD, D | 8302040326 | 50-213 P | CURTIS, N W | 8302180131 | 50-388 S |
| COX, H T | 8302150683* | 50-261 S | CRUTCHFIELD, D | 8302040331* | 50-213 P | CURTIS, N W | 8302180191 | 50-388 S |
| COX, H T | 8302280222* | 50-261 S | CRUTCHFIELD, D | 8302040240* | 50-213 P | CURTIS, N W | 8302180245 | 50-387 S |
| COY, S A | 8302280059* | 50-269 F | CRUTCHFIELD, D | 8302040251* | 50-255 P | CURTIS, N W | 8302180251 | 50-387 F |
| COYLE, L | 8302280524* | 50-249 S | CRUTCHFIELD, D | 8302040257* | 50-255 P | CURTIS, N W | 8302230291 | 50-388 S |
| CRABTREE, R A | 8302080298 | 50-309 I | CRUTCHFIELD, D | 8302040517 | 50-245 F | CUTCHIN, J M | 8302020284 | 50-387 Q |
| CRAGIN, J Q | 8302090165 | 50-273 P | CRUTCHFIELD, D | 8302070453 | 50-409 P | CUTCHIN, J M | 8302040252 | 50-440 Q |
| CRAGIN, J Q | 8302180252 | 50-273 P | CRUTCHFIELD, D | 8302070485 | 50-29 P | CUTCHIN, J M | 8302090458 | 50-289 Q |
| CRAGIN, J Q | 8302240368 | 50-275 P | CRUTCHFIELD, D | 8302070564 | 50-409 P | CUTCHIN, J M | 8302170083 | 50-289 T |
| CRANDELL, H E | 8302070282* | 50-187 Q | CRUTCHFIELD, D | 8302080015 | 50-206 P | CUTCHIN, J M | 8302180321 | 50-289 Q |
| CRANE, C J | 8209020218* | 50-220 P | CRUTCHFIELD, D | 8302080197 | 50-29 P | CUTCHIN, J M | 8302180479 | 50-440 Q |
| CRANE, C J | 8209040228* | 50-220 P | CRUTCHFIELD, D | 8302080191 | 50-237 F | CUTCHIN, J M | 8302280251 | 50-289 Q |
| CRANE, P A | 8302010431 | 50-273 P | CRUTCHFIELD, D | 8302090174 | 50-245 F | CVGELMAN, A I | 8302090404* | 50-397 Q |
| CRANE, P A | 8302020002 | 50-275 P | CRUTCHFIELD, D | 8302100210 | 50-409 P | CZECH, L B | 8302230477* | 50-247 T |
| CRANE, P A | 8302020028 | 50-323 J | CRUTCHFIELD, D | 8302150319 | 50-155 P | D'ANGELO, A J | 8302230226* | 50-397 Q |
| CRANE, P A | 8302030605* | 50-275 F | CRUTCHFIELD, D | 8302150620 | 50-244 P | D'ARDENNE, W H | 8302090414 | TOPRE |
| CRANE, P A | 8302040369 | 50-275 R | CRUTCHFIELD, D | 8302150629* | 50-244 P | DALE, L C | 8302150108 | 50-491 Q |
| CRANE, P A | 8302080176 | 50-275 Q | CRUTCHFIELD, D | 8302150633* | 50-244 P | DALE, L F | 8302010308 | 50-416 F |
| CRANE, P A | 8302090014 | 50-275 F | CRUTCHFIELD, D | 8302160125 | 50-245 F | DALE, L F | 8302010528 | 50-416 P |
| CRANE, P A | 8302090357 | 50-275 F | CRUTCHFIELD, D | 8302160197 | 50-245 P | DALE, L F | 8302030181 | 50-416 P |
| CRANE, P A | 8302090376 | 50-275 F | CRUTCHFIELD, D | 8302160231 | 50-219 P | DALE, L F | 8302030551 | 50-416 Q |
| CRANE, P A | 8302090428 | 50-275 F | CRUTCHFIELD, D | 8302160261 | 50-244 P | DALE, L F | 8302040420 | 50-416 F |
| CRANE, P A | 8302100380 | PRM | CRUTCHFIELD, D | 8302160296 | 50-29 P | DALE, L F | 8302160295 | 50-416 P |
| CRANE, P A | 8302140034 | 50-133 F | CRUTCHFIELD, D | 8302160374 | 50-219 P | DALTON, D W | 8302250436* | 50-269 F |
| CRANE, P A | 8302140087 | 50-275 P | CRUTCHFIELD, D | 8302180446 | 50-206 P | DALTROFF, S L | 8302040404* | 50-277 P |
| CRANE, P A | 8302170331 | 50-275 P | CRUTCHFIELD, D | 8302230415 | 50-255 F | DALTROFF, S L | 8302140026 | 50-277 Q |
| CRANE, P A | 8302170363 | 50-275 P | CRUTCHFIELD, D | 8302230497 | 50-245 F | DALTROFF, S L | 8302140086 | 50-277 P |
| CRANE, P A | 8302230134 | 50-275 F | CRUTCHFIELD, D | 8302280143 | 50-245 P | DALTROFF, S L | 8302280469* | 50-277 Q |
| CRANE, P A | 8302230398 | 50-275 F | CRUTCHFIELD, D | 8302280182 | 50-235 P | DANCE, H C | 8302150428* | 50-333 Q |
| CRANE, P A | 8302230420 | 50-275 P | CRUTCHFIELD, D | 8302280191* | 50-255 P | DANCE, H C | 8302150074 | 50-370 Q |
| CRANE, P A | 8302230493 | 50-275 R | CRUTCHFIELD, D | 8302280232 | 50-219 P | DANCE, H C | 8302150090 | 50-389 Q |
| CRANE, P A | 8302280054 | 50-275 P | CRUTCHFIELD, D | 8302280406 | 50-244 P | DANCE, H C | 8302150130 | 50-413 Q |
| CRAWFORD, A B | 8302080139* | 50-29 Q | CRUTCHFIELD, D | 8302280453 | 50-244 P | DANCE, H C | 8302150165 | 50-269 Q |
| CRAY, B | 8302040071* | 50-440 Q | CUESTA-GONZALEZ | 8302170198 | NUREG | DANCE, H C | 8302170221 | 50-321 Q |
| CRAY, H A | 8302250173* | 50-373 S | CULVER, B K | 8302180111* | 50-358 A | DANCE, H C | 8302180258 | 50-389 Q |
| CREED, J | 8302180412 | 50-156 S | CUMMINGS, J J | 8302070136* | 50-272 Q | DANCE, H C | 8302150308 | 50-389 Q |
| CREED, J R | 8302040339* | 50-341 S | CUMMINGS, J J | 8302090107* | FOIA | DANCE, H C | 8302150360* | 50-370 Q |
| CREED, J R | 8302140075 | 50-373 S | CUMMINGS, J J | 8302090148* | 50-358 Q | DANCE, H C | 8302150422 | 50-335 Q |
| CREED, J R | 8302150557* | 50-454 S | CUMMINGS, J J | 8302090157* | 50-358 Q | DANCE, H C | 8302150427 | 50-321 Q |
| CREED, J R | 8302180173* | 70-1193 | CUMMINGS, J J | 8302090485* | 50-358 Q | DANCE, H C | 8302150430 | 50-250 Q |
| CREED, J R | 8302180451* | 50-10 Q | CUMMINGS, J J | 8302090489* | 50-358 Q | DANCE, H C | 8302150440* | 50-250 Q |
| CREED, J R | 8302180457* | 50-373 Q | CUMMINGS, J J | 8302090491* | 50-358 Q | DANCE, H C | 8302150495* | 50-321 Q |
| CREWS, J L | 8302070256* | 50-206 Q | CUMMINGS, J J | 8302090496* | 50-358 Q | DANCE, H C | 8302150375 | 50-424 Q |
| CRLENJAK, R V | 8302150488* | 50-321 Q | CUMMINGS, J J | 8302090501* | 50-358 Q | DANCE, H C | 8302150378 | 50-280 Q |
| CROCKER, H W | 8302100303* | 50-309 Q | CUMMINGS, J J | 8302090508* | 50-358 Q | DANCE, H C | 8302150589* | 50-280 Q |
| CROCKER, H W | 8302230333* | 50-272 Q | CUMMINGS, J J | 8302090520* | 50-358 Q | DANCE, H C | 8302150611 | 50-321 Q |
| CROOK, J L | 8108170251* | FOIA | CUMMINGS, J J | 8302090546* | 50-358 Q | DANCE, H C | 8302150636 | 50-413 Q |
| CROSS, R H | 8302020380* | WASTE HOT | CUMMINGS, J E | 8302030590* | 50-382 Q | DANCE, H C | 8302150646* | 50-321 Q |
| CROSSMAN, H A | 8302030590* | 50-382 Q | CUMMINGS, J E | 8302070475* | 50-313 Q | DANCE, H C | 8302150661 | 50-369 Q |
| CROSSMAN, H A | 8302070486* | 50-382 Q | CUMMINGS, J E | 8302230168 | 50-368 B | DANCE, H C | 8302150669 | 50-369 Q |
| CROSSMAN, H A | 8302230416* | 50-498 Q | CUNNINGHAM, A L | 8302150459* | 50-321 Q | DANCE, H C | 8302150696 | 50-335 Q |
| CROUSE, R P | 8302180134 | 50-346 Q | CUNNINGHAM, Q E | 8302030119 | 71-9148 | DANCE, H C | 8302150712 | 50-395 Q |
| CROUSE, R P | 8302030176 | 50-346 P | CUNNINGHAM, Q E | 8302040528 | 70-754 | DANCE, H C | 8302150715 | 50-389 Q |
| CROUSE, R P | 8302030388 | 50-346 P | CUNNINGHAM, Q H | 8302150494 | 50-358 H | DANCE, H C | 8302150716 | 50-321 Q |
| CROUSE, R P | 8302030395* | 50-346 P | CUNNINGHAM, Q H | 8302280265 | 50-445 Q | DANCE, H C | 8302170300 | 50-369 Q |
| CROUSE, R P | 8302040063 | 50-346 P | CUNNINGHAM, R E | 8302170029 | NUREG | DANESE, F L | 8302040106 | 71-6698 |
| CROUSE, R P | 8302040272 | 50-346 P | CUNNINGHAM, R E | 8302080076 | 70-754 | DANESE, F L | 8302040476 | 50-280 F |
| CROUSE, R P | 8302070250 | 50-346 P | CUNNINGHAM, R E | 8302180311* | FOIA | DANESE, F L | 8302070188 | XPORTLIC |
| CROUSE, R P | 8302070369 | 50-346 P | CUNNINGHAM, R E | 8302180315* | FOIA | DANESE, F L | 8302070184 | XPORTLIC |
| CROUSE, R P | 8302070478 | 50-346 P | CUNNINGHAM, R O | 8302280188 | 50-5 R | DANESE, F L | 8302080004 | 71-6698 |
| CROUSE, R P | 8302070569 | 50-346 P | CURRAN, D | 8302010521 | 50-443 Q | DANESE, F L | 8302080009 | 71-6698 |
| CROUSE, R P | 8302080198 | 50-346 P | CURRAN, D | 8302080244 | 50-443 Q | DANESE, F L | 8302080094 | XPORTLIC |
| CROUSE, R P | 8302080209 | 50-346 P | CURRAN, D | 8302080264 | 50-443 Q | DANIELSON, D | 8302040367 | 50-282 S |
| CROUSE, R P | 8302080223 | 50-346 P | CURRAN, D | 8302100341 | PRM | DANIELSON, D | 8302150594 | 50-237 S |
| CROUSE, R P | 8302080228 | 50-346 P | CURRAN, D | 8302100349 | PRM | DANIELSON, D H | 8302040352* | 50-341 Q |
| CROUSE, R P | 8302100362 | PR | CURRAN, D | 8302220346 | 50-443 Q | DANIELSON, D H | 8302150322* | 50-263 Q |
| CROUSE, R P | 8302160172 | 50-346 P | CURRAN, D | 8302220366 | 50-443 Q | DANIELSON, D H | 8302150724* | 50-454 Q |
| CROUSE, R P | 8302230290 | 50-346 P | CURRAN, D | 8302220382* | 50-443 Q | DANIELSON, D H | 8302280375* | 50-454 Q |
| CROUSE, R P | 8302280336 | 50-346 P | CURRAN, D | | | DANIELSON, D H | 8302280550* | 50-454 Q |

PERSONAL AUTHOR INDEX

46

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|----------------|------------------|------------------|
| DANIELSON, S K | 8302040486 | 50-341 D | DEVINCENITIS, J | 8302040092 | 50-443 A | DIEDERICH, O J | 8302230390 | 50-373 |
| DANTZLER, M U | 8302220074* | CONTRACT | DEVINCENITIS, J | 8302040092 | 50-443 A | DIEDERICH, O J | 8302230395 | 50-373 |
| DARDIS, J O | 8302390277 | XPORTLIC | DEVINCENITIS, J | 8302040109 | 50-443 A | DIEDERICH, O J | 8302280374 | 50-373 |
| DARNTZEL, R W | 8302160045 | 50-73 S | DEVINCENITIS, J | 8302040109 | 50-443 A | DIEDERICH, O J | 8302280497 | 50-373 |
| DAVIDOFF, D B | 8302230477* | 50-247 T | DEVINCENITIS, J | 8302040210 | 50-443 E | DIEDERICH, O L | 8302230209 | 50-373 |
| DAVIDSON, D R | 83020403091 | 50-440 K | DEVINCENITIS, J | 8302040210 | 50-443 E | DIETCH, R | 8302220334 | 50-361 |
| DAVIDSON, D R | 8302040366* | 50-440 Q | DEVINCENITIS, J | 8302040338 | 50-443 A | DIETCH, R | 8302220337* | 50-361 |
| DAVIDSON, D R | 8302040368* | 50-440 Q | DEVINCENITIS, J | 8302040338 | 50-443 A | DIETCH, R | 8302220339* | 50-361 |
| DAVIDSON, D R | 8302040597 | 70-2768 | DEVINCENITIS, J | 8302040356 | 50-443 R | DIETCH, R | 8302280284* | 50-361 |
| DAVIDSON, D R | 8302280513* | 50-440 Q | DEVINCENITIS, J | 8302040372 | 50-443 A | DIETZ, C R | 8301170409 | 50-324 |
| DAVIS, A B | 8302040386* | 50-440 Q | DEVINCENITIS, J | 8302040372 | 50-443 A | DIETZ, C R | 8302010080 | 50-324 |
| DAVIS, F Y | 8302140020 | 50-266 Q | DEVINCENITIS, J | 8302040425 | 50-443 A | DIETZ, C R | 8302010087 | 50-324 |
| DAVIS, B T | 8302240363 | FOIA | DEVINCENITIS, J | 8302040425 | 50-443 A | DIETZ, C R | 8302010234 | 50-325 |
| DAVIS, J O | 8302180277* | FOIA | DEVINCENITIS, J | 8302080186 | 50-443 A | DIETZ, C R | 8302010267 | 50-324 |
| DAVIS, M V | 8302140122* | 50-244 Q | DEVINCENITIS, J | 8302080186 | 50-443 A | DIETZ, C R | 8302010281 | 50-324 |
| DAY, J | 8302220272* | 70-1362 | DEVINCENITIS, J | 8302080215 | 50-443 A | DIETZ, C R | 8302010363 | 50-325 |
| DAY, J E | 8302220366 | TOPREP | DEVINCENITIS, J | 8302080215 | 50-443 A | DIETZ, C R | 8302010371 | 50-324 |
| DE AGAZIO, A | 8302170410 | 50-346 P | DEVINCENITIS, J | 8302150407 | 50-443 A | DIETZ, C R | 8302010454 | 50-324 |
| DEAN, R A | 8302010439 | PT21 | DEVINCENITIS, J | 8302150407 | 50-443 A | DIETZ, C R | 8302010563 | 50-324 |
| DEARLEN, J A | 8302150741 | RES | DEVINCENITIS, J | 8302150451 | 50-443 A | DIETZ, C R | 8302010601 | 50-325 |
| DEBBAGE, A Q | 8302150277* | 50-389 Q | DEVINCENITIS, J | 8302150451 | 50-443 A | DIETZ, C R | 8302030626 | 50-324 |
| DEBBAGE, A Q | 8302150607* | 50-389 Q | DEVINCENITIS, J | 8302160166 | 50-443 A | DIETZ, C R | 8302030187 | 50-325 |
| DEBB, B T | 8302150599* | 50-280 Q | DEVINCENITIS, J | 8302160166 | 50-443 A | DIETZ, C R | 8302030385 | 50-325 |
| DECKARD, J | 8302030136* | 50-537 U | DEVINCENITIS, J | 8302160263 | 50-443 A | DIETZ, C R | 8302030401 | 50-325 |
| DECKER, M | 8302070370* | 50-244 Q | DEVINCENITIS, J | 8302160263 | 50-443 A | DIETZ, C R | 8302030410 | 50-324 |
| DEEO, F H | 8302070224* | 50-333 J | DEVINCENITIS, J | 8302160274 | 50-443 A | DIETZ, C R | 8302030414 | 50-324 |
| DEEO, F H | 8302150036 | 50-333 J | DEVINCENITIS, J | 8302160274 | 50-443 A | DIETZ, C R | 8302030503 | 50-324 |
| DEEO, F H | 8302150586 | 50-286 J | DEVINCENITIS, J | 8302160326 | 50-443 A | DIETZ, C R | 8302140010 | 50-324 |
| DELANY, J M | 8302250122 | NUREG | DEVINCENITIS, J | 8302160326 | 50-443 A | DIETZ, C R | 8302140042 | 50-324 |
| DELGEORGE, L O | 8302040302* | 50-10 Q | DEVINCENITIS, J | 8302170366 | 50-443 Q | DIETZ, C R | 8302140134 | 50-325 |
| DELGEORGE, L O | 8302100287 | PR | DEVINCENITIS, J | 8302170366 | 50-443 Q | DIETZ, C R | 8302150023 | 50-324 |
| DELGEORGE, L O | 8302100291 | PR | DEVINCENITIS, J | 8302170369 | 50-443 A | DIETZ, C R | 8302150119 | 50-324 |
| DELGEORGE, L O | 8302100380 | PRM | DEVINCENITIS, J | 8302170369 | 50-443 A | DIETZ, C R | 8302150172 | 50-324 |
| DELGEORGE, L O | 8302100422 | PR | DEVINCENITIS, J | 8302220166 | 50-443 A | DIETZ, C R | 8302150330* | 50-324 |
| DELGEORGE, L O | 8302150516* | 50-249 Q | DEVINCENITIS, J | 8302220166 | 50-443 A | DIETZ, C R | 8302150318 | 50-324 |
| DELGEORGE, L O | 8302170297* | 50-373 Q | DEVINCENITIS, J | 8302220327 | 50-443 A | DIETZ, C R | 8302150642 | 50-324 |
| DELLA RATTI, A | 8302250237* | 70-398 | DEVINCENITIS, J | 8302220327 | 50-443 A | DIETZ, C R | 8302170074 | 50-324 |
| DELLA ROCCA, M | 8302280168 | 50-247 T | DEVINCENITIS, J | 8302220331 | 50-443 A | DIETZ, C R | 8302170093 | 50-324 |
| DELLA ROCCA, M | 8302280168 | 50-247 T | DEVINCENITIS, J | 8302220331 | 50-443 A | DIETZ, C R | 8302170172 | 50-325 |
| DENISON, E | 8302180488 | 50-275 R | DEVINCENITIS, J | 8302220388 | 50-443 A | DIETZ, C R | 8302170177 | 50-325 |
| DENISON, E | 8302240278 | 50-275 P | DEVINCENITIS, J | 8302220388 | 50-443 A | DIETZ, C R | 8302170178 | 50-324 |
| DENISON, E | 8302240282* | 50-275 P | DEVINCENITIS, J | 8302230449 | 50-443 S | DIETZ, C R | 8302230166 | 50-324 |
| DENISON, E | 8302240286* | 50-275 P | DEVINCENITIS, J | 8302230449 | 50-443 S | DIETZ, C R | 8302240245 | 50-325 |
| DENISON, E | 8302240292* | 50-275 P | DEVINCENITIS, J | 8302250033 | 50-443 S | DIETZ, C R | 8302280066 | 50-324 |
| DENISON, E T | 8302090187* | 50-275 P | DEVINCENITIS, J | 8302250033 | 50-443 S | DIETZ, C R | 8302280219 | 50-324 |
| DENNINGTON, S F | 8302280252* | CONTRACT | DEVINCENITIS, J | 8302250441 | 50-443 A | DIETZ, C R | 8302280250 | 50-325 |
| DENTON, H R | 8302010040 | 50-373 H | DEVINCENITIS, J | 8302250441 | 50-443 A | DIETZ, C R | 8302280502 | 50-324 |
| DENTON, H R | 8302010044* | 50-373 H | DEVINE, J B | 8302090267 | XPORTLIC | DIOGB, R H | 8302030097 | 50-373 |
| DENTON, H R | 8302080110 | 50-341 Q | DEVINE, J B | 8302240403 | XPORTLIC | DIOGB, R H | 8302080366 | 50-293 |
| DENTON, H R | 8302080114* | 50-341 Q | DEVINE, J B | 8302250804 | XPORTLIC | DIOGB, R H | 8302100122 | 50-334 |
| DENTON, H R | 8302180014 | 50-373 Q | DEVINE, T | 8302070522 | 50-358 Q | DIOGB, R H | 8302100166 | 50-247 |
| DENTON, H R | 8302180020* | 50-373 Q | DEVINE, T | 8302090013* | 50-358 A | DIOGB, R H | 8302160086 | 50-327 |
| DENTON, H R | 8302180023* | 50-373 Q | DEVINE, T | 8302090023* | 50-358 A | DIOGB, R H | 8302170027 | 50-275 |
| DENTON, H R | 8302180052* | 50-373 Q | DEVINE, T | 8302090035* | 50-358 Q | DIOGB, R H | 8302170032 | 50-267 |
| DENTON, H R | 8302180058* | 50-373 Q | DEVINE, T | 8302170294 | 50-358 Q | DIOGB, R H | 8302170382 | 50-298 |
| DENTON, H R | 8302220058* | FOIA | DEVINE, T | 8302180070* | 50-358 A | DIOGB, R H | 8302220498 | 50-301 |
| DENTON, H R | 8302220514 | 50-309 Q | DEWALD, W H | 8302230351* | 50-537 A | DIGNAN, T O | 8302010529 | 50-443 |
| DENTON, H R | 8302220517* | 50-309 Q | DEWEY, L S | 8302180279 | 50-529 Q | DIGNAN, T O | 8302010529 | 50-443 |
| DENTON, H R | 8302220517* | 50-309 Q | DEWITT, R B | 8302010640* | 50-155 P | DIGNAN, T O | 8302010533 | 50-443 |
| DENTON, H R | 8302220525 | 50-323 H | DEWITT, R B | 8302240267* | 50-329 A | DIGNAN, T O | 8302010533 | 50-443 |
| DENTON, T J | 8302010525 | TOPREP | DEYOUNG, R C | 8302160169* | FOIA | DIGNAN, T O | 8302010547 | 50-443 |
| DESANDES, K D | 8302280415* | 50-336 S | DEYOUNG, R C | 8302100359* | REVIEW GRP | DIGNAN, T O | 8302010547 | 50-443 |
| DETUILLD, D | 8302280500* | 50-390 Q | DEYOUNG, R C | 8302100381* | REVIEW GRP | DIGNAN, T O | 8302010594* | 50-443 |
| DEVINCENITIS, J | 8302010406 | 50-443 A | DEYOUNG, R C | 8302180187* | FOIA | DIGNAN, T O | 8302010594* | 50-443 |
| DEVINCENITIS, J | 8302010406 | 50-443 A | DIAMOND, D J | 8302080482 | RES | DIGNAN, T O | 8302100220 | 50-443 |
| DEVINCENITIS, J | 8302010438 | 50-443 A | DICK, O F | 8302070426 | 50-29 P | DIGNAN, T O | 8302100220 | 50-443 |
| DEVINCENITIS, J | 8302010438 | 50-443 A | DICKERSON, M W | 8302030475* | 50-267 Q | DIGNAN, T O | 8302100228 | 50-443 |
| DEVINCENITIS, J | 8302010646 | 50-443 A | DICKERSON, M W | 8302230673* | 50-267 Q | DIGNAN, T O | 8302100228 | 50-443 |
| DEVINCENITIS, J | 8302010646 | 50-443 A | DICKHONER, W H | 8302010575 | 50-358 A | DIGNAN, T O | 8302100235 | 50-443 |
| DEVINCENITIS, J | 8302020152 | 50-443 A | DICKHONER, W H | 8302080169 | 50-358 A | DIGNAN, T O | 8302100235 | 50-443 |
| DEVINCENITIS, J | 8302020152 | 50-443 A | DICKSON, J D | 8302100081* | CONTRACT | DIGNAN, T O | 8302100243 | 50-443 |
| DEVINCENITIS, J | 8302020275 | 50-443 A | DICKSON, W R | 8302170540* | CONTRACT | DIGNAN, T O | 8302100243 | 50-443 |
| DEVINCENITIS, J | 8302020275 | 50-443 A | DIEDERICH, O J | 8302010122 | 50-373 S | DIGNAN, T O | 8302100207 | 50-443 |
| DEVINCENITIS, J | 8302020281 | 50-443 A | DIEDERICH, O J | 8302010373 | 50-373 S | DIGNAN, T O | 8302160207 | 50-443 |
| DEVINCENITIS, J | 8302020281 | 50-443 A | DIEDERICH, O J | 8302040176 | 50-373 S | DIGNAN, T O | 8302160323 | 50-443 |
| DEVINCENITIS, J | 8302030275 | 50-443 S | DIEDERICH, O J | 8302040260 | 50-373 S | DIGNAN, T O | 8302160323 | 50-443 |
| DEVINCENITIS, J | 8302030275 | 50-443 S | DIEDERICH, O J | 8302040261 | 50-373 S | DIGNAN, T O | 8302160329 | 50-443 |
| DEVINCENITIS, J | 8302030455 | 50-443 S | DIEDERICH, O J | 8302040333 | 50-373 S | DIGNAN, T O | 8302180093 | 50-443 |
| DEVINCENITIS, J | 8302030455 | 50-443 S | DIEDERICH, O J | 8302080289 | 50-373 S | DIGNAN, T O | 8302180093 | 50-443 |
| DEVINCENITIS, J | 8302030563 | 50-443 S | DIEDERICH, O J | 8302180453 | 50-373 S | DIGNAN, T O | 8302180093 | 50-443 |
| DEVINCENITIS, J | 8302040036 | 50-443 F | DIEDERICH, O J | 8302180467* | 50-373 S | DIGNAN, T O | 8302180136 | 50-443 |
| DEVINCENITIS, J | 8302040036 | 50-443 F | DIEDERICH, O J | 8302250168 | 50-373 S | DIGNAN, T O | 8302180136 | 50-443 |
| DEVINCENITIS, J | 8302040066 | 50-443 A | DIEDERICH, O J | 8302250220 | 50-373 S | DIGNAN, T O | 8302180295 | 50-443 |
| DEVINCENITIS, J | 8302040066 | 50-443 A | DIEDERICH, O J | 8302250286 | 50-373 S | DIGNAN, T O | 8302180295 | 50-443 |
| DEVINCENITIS, J | 8302040066 | 50-443 A | DIEDERICH, O J | 8302250307 | 50-373 S | DIGNAN, T O | 8302180308 | 50-443 |

PERSONAL AUTHOR INDEX

| AUTHOR | | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | | ACCESSION NUMBER | SUBJECT CATEGORY |
|-------------|--|------------------|------------------|----------------|--|------------------|------------------|-----------------|--|------------------|------------------|
| DIGNAN, T O | | 8302180308 | 50-443 Q | DODDS, R T | | 8302230240* | 50-344 Q | EDELMAN, H R | | 8302080167 | 50-440 Q |
| DIGNAN, T O | | 8302180310 | 50-443 Q | DODDS, R T | | 8302230257* | 50-508 Q | EDELMAN, H R | | 8302080323 | 50-440 S |
| DIGNAN, T O | | 8302180310 | 50-443 Q | DODDS, R T | | 8302230274* | 50-508 Q | EDELMAN, H R | | 8302150216 | 50-440 S |
| DIGNAN, T O | | 8302180322 | 50-443 Q | DODDS, R T | | 8302230278* | 50-508 Q | EDELMAN, H R | | 8302150509 | 50-440 E |
| DIGNAN, T O | | 8302180322 | 50-443 Q | DODDS, R T | | 8302230372* | 50-397 Q | EDELMAN, H R | | 8302160209* | 50-440 Q |
| DIGNAN, T O | | 8302180355 | 50-443 Q | DOERFLEIN, L | | 8302100436* | 50-333 Q | EDELMAN, H R | | 8302170338 | 50-440 K |
| DIGNAN, T O | | 8302180355 | 50-443 Q | DOERFLEIN, L T | | 83022030456* | 50-333 Q | EDELMAN, H R | | 8302180434* | 50-440 Q |
| DIGNAN, T O | | 8302180360 | 50-443 Q | DOHRMAN, K F | | 8302280566 | 71-9033 | EDELMAN, H R | | 8302230719 | 50-440 A |
| DIGNAN, T O | | 8302180360 | 50-443 Q | DONAHUE, M | | 8302170264 | 50-440 Q | EDELMAN, H R | | 8302280206 | 50-440 F |
| DIGNAN, T O | | 8302180375 | 50-443 Q | DONNELLY, L J | | 8203030578* | FOIA | EDELMAN, H R | | 8302280208 | 50-440 E |
| DIGNAN, T O | | 8302180375 | 50-443 Q | DONNELLY, L J | | 8302180110* | FOIA | EDELMAN, H R | | 8302280259 | 50-440 A |
| DIGNAN, T O | | 8302180400 | 50-443 Q | DONNELLY, L J | | 8302180201* | FOIA | EDELMAN, H R | | 8302280306 | 50-440 V |
| DIGNAN, T O | | 8302180400 | 50-443 Q | DONNELLY, L J | | 8302180307* | FOIA | EDGAR, G L | | 8302030190 | 50-537 T |
| DIGNAN, T O | | 8302180421 | 50-443 Q | DONNELLY, L J | | 8302180350* | FOIA | EDGEWORTH, P | | 8302010033 | CONTRACT |
| DIGNAN, T O | | 8302180421 | 50-443 Q | DONOGHUE, D J | | 8302180047* | FOIA | EDGEWORTH, P | | 8302030019 | CONTRACT |
| DIGNAN, T O | | 8302180465 | 50-443 Q | DONOGHUE, D J | | 8302180062* | FOIA | EDISON, Q E | | 8301280357 | TOPREP |
| DIGNAN, T O | | 8302180465 | 50-443 Q | DONOGHUE, D J | | 8302180067* | FOIA | EDISON, Q E | | 8302290117 | 50-482 A |
| DIGNAN, T O | | 8302180487 | 50-443 Q | DONOGHUE, D J | | 8302180113* | FOIA | EDISON, Q E | | 8302290149 | TOPREP |
| DIGNAN, T O | | 8302180487 | 50-443 Q | DONOGHUE, D J | | 8302180121* | FOIA | EDMONDS, R F | | 8302230417* | 50-269 P |
| DIANNI, D C | | 8302020231 | 50-282 P | DONOGHUE, D J | | 8302180148* | FOIA | EDMONSON, L R | | 8302090254* | 50-537 A |
| DIANNI, D C | | 8302100185 | 50-282 P | DONOGHUE, D J | | 8302180162* | FOIA | EDWARDS, D L | | 8302100008 | 40-3453 |
| DIANNI, D C | | 8302150731 | 50-282 P | DONOGHUE, D J | | 8302180167* | FOIA | EDWARDS, D N | | 8302140085 | PRM |
| DIANNI, D C | | 8302160043 | 50-282 P | DONOGHUE, D J | | 8302180177* | FOIA | EDWARDS, N | | 8302040511* | 50-269 F |
| DIANNI, D C | | 8302170293* | 50-155 P | DONOGHUE, D J | | 8302180286* | FOIA | EGLE, D M | | 8302230614 | 50-112 H |
| DIANNI, D C | | 8302240334 | 50-282 P | DONOGHUE, D J | | 8302180288* | FOIA | FICHI, E | | 8302230441* | 50-247 R |
| DIMEGLIO, F | | 8302010372* | 50-193 Q | DONOGHUE, D J | | 8302180301* | FOIA | EICHENHOLZ, H | | 8302230259* | 50-293 Q |
| DIMEGLIO, F | | 8302030606 | 71-9151 | DONOGHUE, D J | | 8302180404* | FOIA | EINBUND, D R | | 8302240001 | XPORTRIC |
| DIRCKS, W J | | 8112100049* | FOIA | DONOGHUE, D J | | 8302100513 | 50-423 A | EINBUND, D R | | 8302240002* | XPORTRIC |
| DIRCKS, W J | | 8208050174* | 50-937 U | DONOGHUE, D J | | 8302170534 | 50-412 A | EISENGREIN, R H | | 8302150143* | 50-443 X |
| DIRCKS, W J | | 8209200462* | FOIA | DORSEY, M | | 8302010005 | CONTRACT | EISENHUT, D O | | 8302150752 | HISC |
| DIRCKS, W J | | 8301240226 | SECY | DOUGHERTY, D | | 83022250049 | 50-320 P | EISENHUT, D O | | 8208060366 | 50-387 P |
| DIRCKS, W J | | 8301240253 | PR | DOVE, K L | | 8302040104 | FOIA | EISENHUT, D O | | 8301210340 | 50-3 F |
| DIRCKS, W J | | 8302010061* | FOIA | DRAKE, M | | 8302100306 | PRM | EISENHUT, D O | | 8301310203 | 50-3 V |
| DIRCKS, W J | | 8302070067 | COMMISSION | DRAKE, S J | | 8302160262 | 50-356 Q | EISENHUT, D O | | 8302010037 | 50-275 P |
| DIRCKS, W J | | 8302070148* | 50-280 P | DUCE, S W | | 8302150744 | 50-312 P | EISENHUT, D O | | 8302020226* | 50-266 P |
| DIRCKS, W J | | 8302090178 | COMMISSION | DUCK, J R | | 8302020009 | 50-327 J | EISENHUT, D O | | 8302030089 | 50-219 P |
| DIRCKS, W J | | 8302090252 | 50-313 P | DUCK, J R | | 8302070207 | 50-335 J | EISENHUT, D O | | 8302080127* | 50-206 P |
| DIRCKS, W J | | 8302100344 | PR | DUCK, J R | | 8302080275 | 50-335 J | EISENHUT, D O | | 8302080151 | 50-275 P |
| DIRCKS, W J | | 8302100420 | PR | DUOLEY, R F | | 8302080244 | 50-237 P | EISENHUT, D O | | 8302080194* | 50-237 F |
| DIRCKS, W J | | 8302140168 | 50-269 P | DUFFY, B | | 8302030340* | 50-336 S | EISENHUT, D O | | 8302080275 | 50-3 P |
| DIRCKS, W J | | 8302170095 | SECY | DUNCAN, E L | | 8302010551* | 50-382 Q | EISENHUT, D O | | 8302080301 | 50-10 P |
| DIRCKS, W J | | 8302170132* | 100FR | DUNCAN, E L | | 8302070532 | 50-382 Q | EISENHUT, D O | | 8302080304 | 50-3 P |
| DIRCKS, W J | | 8302220094* | FOIA | DUNN, D W | | 8302100338 | PR | EISENHUT, D O | | 8302080431 | 50-247 F |
| DIRCKS, W J | | 8302220058* | FOIA | DUPONT, R L | | 8302170287* | 50-247 T | EISENHUT, D O | | 8302080441 | 50-289 P |
| DIRCKS, W J | | 8302250219* | 40-86 | DUPONT, S O | | 8302280341* | 50-254 Q | EISENHUT, D O | | 8302090065 | 50-382 A |
| DIXON, A J | | 8302100319 | PR | DURR, J | | 8302030591* | 50-286 Q | EISENHUT, D O | | 8302090072 | 50-255 P |
| DIXON, A J | | 8302100321 | PR | DURR, J P | | 8302150420* | 50-352 Q | EISENHUT, D O | | 8302090080 | 50-323 A |
| DIXON, A J | | 8302100371* | PR | DURR, J P | | 8302230273* | 50-352 Q | EISENHUT, D O | | 8302090085 | 50-206 P |
| DIXON, A J | | 8302100403* | PR | DURR, J P | | 8302280488* | 50-412 Q | EISENHUT, D O | | 8302090092 | 50-329 A |
| DIXON, A J | | 8302100411* | PR | DUS, R | | 8302250401* | 50-373 S | EISENHUT, D O | | 8302090098 | 50-269 P |
| DIXON, A J | | 8302100453* | PR | DUVAL, D D | | 8212140330 | 50-315 S | EISENHUT, D O | | 8302090345 | 50-423 A |
| DIXON, A J | | 8302100455 | PR | DUVAL, D D | | 8302040164 | 50-546 S | EISENHUT, D O | | 8302100094 | 50-275 P |
| DIXON, B W | | 8302150745 | RES | EAGLE, J | | 8302040054* | 50-254 S | EISENHUT, D O | | 8302100101 | 50-238 P |
| DIXON, O W | | 8302010111 | 50-395 S | EAGLE, J | | 8302280321* | 50-254 S | EISENHUT, D O | | 8302100105* | 50-238 P |
| DIXON, O W | | 8302010139 | 50-395 S | EAGLETON, T F | | 8302250362* | PR | EISENHUT, D O | | 8302100110* | 50-238 P |
| DIXON, O W | | 8302010155 | 50-395 S | EAFEN, P | | 8302010325* | 50-277 Q | EISENHUT, D O | | 8302100200* | 50-282 F |
| DIXON, O W | | 8302010342 | 50-395 F | EAFEN, P K | | 8302100436* | 50-333 Q | EISENHUT, D O | | 8302150318 | 50-292 P |
| DIXON, O W | | 8302010374 | 50-395 S | EARLEY, A F | | 8302170263 | 50-322 Q | EISENHUT, D O | | 8302160050 | 50-387 P |
| DIXON, O W | | 8302010584 | 50-395 S | EARLEY, A F | | 8302170263 | 50-322 Q | EISENHUT, D O | | 8302160054* | 50-387 P |
| DIXON, O W | | 8302030392 | 50-395 Q | EARLEY, A F | | 8302230435 | 50-322 T | EISENHUT, D O | | 8302160144* | 50-416 P |
| DIXON, O W | | 8302040361 | 50-395 P | EARLEY, A F | | 8302230435 | 50-322 T | EISENHUT, D O | | 8302170019 | 50-155 P |
| DIXON, O W | | 8302070381 | 50-395 S | EASTWOOD, D | | 8302250129 | NUREG | EISENHUT, D O | | 8302170041 | 50-382 F |
| DIXON, O W | | 8302070394 | 50-395 P | EBERHARDT, L E | | 8302250053 | NUREG | EISENHUT, D O | | 8302170066 | 50-293 F |
| DIXON, O W | | 8302080237 | 50-395 J | EBNETER, S D | | 8302100436* | 50-333 Q | EISENHUT, D O | | 8302170119* | 50-302 F |
| DIXON, O W | | 8302100223 | 50-395 P | EBNETER, S D | | 8302230273* | 50-352 Q | EISENHUT, D O | | 8302170129* | 50-155 P |
| DIXON, O W | | 8302100317 | 50-395 F | ECCLESTON, K T | | 8203180248* | 50-155 P | EISENHUT, D O | | 8302170229* | 50-259 F |
| DIXON, O W | | 8302150132 | 50-395 R | ECCLESTON, K T | | 8302040125 | TOPREP | EISENHUT, D O | | 8302170482 | 50-322 A |
| DIXON, O W | | 8302150215 | 50-395 S | ECCLESTON, K T | | 8302170176* | 50-155 P | EISENHUT, D O | | 8302202024* | 50-10 P |
| DIXON, O W | | 8302150584 | 50-395 S | ECKHARDT, J H | | 8302230332 | 50-361 S | EISENHUT, D O | | 8302220495 | 50-289 Q |
| DIXON, O W | | 8302150613 | 50-395 S | ECKHARDT, J H | | 8302230406* | 50-361 Q | EISENHUT, D O | | 8302220522* | 50-3 Q |
| DIXON, O W | | 8302150639 | 50-395 Q | ECONOMOS, N | | 8302150171* | 50-269 Q | EISENHUT, D O | | 8302230005 | 50-275 P |
| DIXON, O W | | 8302150649 | 50-395 Q | EDDLEMAN, W | | 8302020321 | 50-400 Q | EISENHUT, D O | | 8302230009* | 50-307 F |
| DIXON, O W | | 8302150656 | 50-395 S | EDDLEMAN, W | | 8302020334* | 50-400 Q | EISENHUT, D O | | 8302230419* | 50-255 F |
| DIXON, O W | | 8302170241 | 50-395 S | EDDLEMAN, W | | 8302070514 | 50-400 Q | EISENHUT, D O | | 8302240003 | 50-389 A |
| DIXON, O W | | 8302180096* | 50-395 F | EDDLEMAN, W | | 8302090241 | 50-400 Q | EISENHUT, D O | | 8302240004* | 50-389 A |
| DIXON, O W | | 8302220244 | 50-395 P | EDDLEMAN, W | | 8302090251* | 50-400 Q | EISENHUT, D O | | 8302240143* | 50-328 P |
| DIXON, O W | | 8302230381 | 50-395 P | EDDLEMAN, W | | 8302160351 | 50-400 Q | EISENHUT, D O | | 8302240216 | 50-250 F |
| DIXON, O W | | 8302230432 | 50-395 P | EDDLEMAN, W | | 8302230579* | 50-400 Q | EISENHUT, D O | | 8302250027* | 50-327 Q |
| DIXON, O W | | 8302230437 | 50-395 R | EDELMAN, H R | | 8302040038 | 50-440 E | EISENHUT, D O | | 8302250193 | 50-358 S |
| DIXON, O W | | 8302280196 | 50-395 S | EDELMAN, H R | | 8302040061 | 50-440 E | ELLIS, J | | 8302020408 | 50-352 A |
| DIXON, O W | | 8302280479 | 50-395 V | EDELMAN, H R | | 8302040400 | 50-440 E | ELLIS, J | | 8302020408 | 50-352 A |
| DIXON, O W | | 8302280737 | 1A5 | EDELMAN, H R | | 8302070196 | 50-440 F | ELLIS, J | | 8302020408 | 50-352 A |
| DIXON, O W | | 8302180179* | 50-397 Q | EDELMAN, H R | | 8302070301 | 50-440 E | ELLIS, J | | 8302020408 | 50-352 A |
| DIXON, O W | | 8302180184* | 50-397 Q | EDELMAN, H R | | 8302070301 | 50-440 E | ELLIS, J | | 8302020408 | 50-352 A |
| DIXON, O W | | 8302230226* | 50-397 Q | EDELMAN, H R | | 8302070325 | 50-440 E | ELLIS, J | | 8302020408 | 50-352 A |

PERSONAL AUTHOR INDEX

46

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|----------------|------------------|------------------|--------------|------------------|------------------|
| ELLIS, J | 8302080189 | 50-445 Q | FEIL, R A | 8301180184* | 50-397 Q | FELTON, J H | 8302080100 | 50-250 |
| ELMORE, M R | 8302250049 | NUREG | FEIL, R A | 8302230372* | 50-397 Q | FELTON, J H | 8302080126 | 50-482 |
| ELROD, S A | 8302150428* | 50-335 Q | FEINBERG, J D | 8302080225 | 50-247 Q | FELTON, J H | 8302080137 | 50-344 |
| ELSASSEK, T | 8302160115 | 50-293 P | FEINBERG, J D | 8302230471 | 50-247 T | FELTON, J H | 8302080271 | 50-285 |
| FLSASSEK, T | 8302170408 | 50-293 Q | FEINBERG, J D | 8302280270 | 50-247 Q | FELTON, J H | 8302080365 | 50-254 |
| ELSASSEK, T | 8302180200* | 50-423 Q | FEINSTEIN, H | 8302150540* | QA999 | FELTON, J H | 8302080375 | 50-346 |
| ELSASSER, T | 8302230259* | 50-293 Q | FEINSTEIN, H H | 8302150561* | QA999 | FELTON, J H | 8302080382 | 50-289 |
| ELSASSER, T C | 8302230418* | 50-213 Q | FEINSTEIN, H H | 8302150569* | QA999 | FELTON, J H | 8302080397 | FOIA |
| EMERSON, B | 8302100379 | PR | FEITKNECHT, C | 8302010666 | 50-334 R | FELTON, J H | 8302080405 | 50-298 |
| EMERSON, B | 8302100462* | PR | FEITKNECHT, C | 8302280342 | 50-334 R | FELTON, J H | 8302080432 | 50-317 |
| EMPEY, D C | 8302030489* | QA999 | FELTON, J | 8302040129 | 50-537 A | FELTON, J H | 8302090005 | 50-358 |
| EMPEY, D C | 8302030493 | 50-269 S | FELTON, J H | 8302102050 | 50-269 F | FELTON, J H | 8302090019 | 50-289 |
| EMPEY, D C | 8302090385 | PT21 | FELTON, J H | 8302010016 | 50-348 F | FELTON, J H | 8302090049 | 50-315 |
| EMPEY, D C | 8302220346* | 50-352 S | FELTON, J H | 8302010026 | 50-348 F | FELTON, J H | 8302090068 | 50-280 |
| EMPEY, D C | 8302220353* | 50-352 S | FELTON, J H | 8302010054 | FOIA | FELTON, J H | 8302090091 | 50-298 |
| ENGELHARDT, T F | 8302100023* | FOIA | FELTON, J H | 8302010065 | FOIA | FELTON, J H | 8302090105 | 50-315 |
| ENGELHARDT, T F | 8302180179* | FOIA | FELTON, J H | 8302010081 | 50-213 F | FELTON, J H | 8302090445 | 50-289 |
| ENGELKEN, R H | 8212010524* | 50-362 Q | FELTON, J H | 8302010108 | 50-317 F | FELTON, J H | 8302090460 | 50-358 |
| ENGELKEN, R H | 8302220071* | 50-142 Q | FELTON, J H | 8302010112 | 50-289 T | FELTON, J H | 8302090462 | 50-348 |
| ENGELKEN, R H | 8302220076* | 50-142 Q | FELTON, J H | 8302020043 | 50-267 F | FELTON, J H | 8302090535 | 50-267 |
| ENGLAND, T R | 8302280013 | NUREG | FELTON, J H | 8302020336 | 50-321 F | FELTON, J H | 8302090590 | 50-293 |
| ENGLE, L | 8302170110* | 50-155 P | FELTON, J H | 8302020338 | FOIA | FELTON, J H | 8302100010 | FOIA |
| ENGLE, L B | 8302100134 | 50-308 P | FELTON, J H | 8302020343 | 50-244 P | FELTON, J H | 8302100019 | FOIA |
| ENGLE, L B | 8302170276* | 50-155 P | FELTON, J H | 8302020399 | 50-206 P | FELTON, J H | 8302100040 | 50-271 |
| ENGLERT, S B | 8302160008 | RES | FELTON, J H | 8302020382 | FOIA | FELTON, J H | 8302150729 | FOIA |
| ERIKSON, K T | 8302250405* | 50-247 Q | FELTON, J H | 8302020392 | FOIA | FELTON, J H | 8302150730 | FOIA |
| ERIKSON, K T | 8302250405* | 50-247 Q | FELTON, J H | 8302020401 | FOIA | FELTON, J H | 8302160408 | 50-410 |
| ERIKSON, K T | 8302250405* | 50-247 Q | FELTON, J H | 8302020405 | 50-387 F | FELTON, J H | 8302160457 | 50-206 |
| ERIKSON, K T | 8302250405* | 50-247 Q | FELTON, J H | 8302020413 | 50-352 A | FELTON, J H | 8302160474 | 50-334 |
| ERNST, P C | 8302080002 | 50-67 F | FELTON, J H | 8302020422 | 50-264 F | FELTON, J H | 8302170449 | 50-382 |
| ESKRIDGE, H E | 8302080021 | 70-36 | FELTON, J H | 8302020427 | 50-289 P | FELTON, J H | 8302170485 | 50-387 |
| ESTES, J E | 8302030208 | NUREG | FELTON, J H | 8302020433 | 50-341 F | FELTON, J H | 8302170494 | 50-328 |
| ETHERIDGE, M R | 8302090391* | QA999 | FELTON, J H | 8302020445 | 50-329 F | FELTON, J H | 8302170507 | 50-313 |
| EURY, L W | 8302010460 | 50-324 P | FELTON, J H | 8302020458 | 50-10 F | FELTON, J H | 8302170544 | 50-285 |
| EURY, L W | 8302100290 | 50-261 P | FELTON, J H | 8302020461 | FOIA | FELTON, J H | 8302180007 | 50-317 |
| EVANS, D H | 8302180398* | 50-329 T | FELTON, J H | 8302020477 | 50-352 A | FELTON, J H | 8302180018 | 50-289 |
| EVANS, D H | 8302180398* | 50-329 T | FELTON, J H | 8302020502 | 50-263 F | FELTON, J H | 8302180030 | 50-315 |
| EVANS, J | 8302180278* | FOIA | FELTON, J H | 8302030017 | 50-537 U | FELTON, J H | 8302180031 | FOIA |
| EVERETT, R J | 8302230509* | 70-1062 | FELTON, J H | 8302030025 | 50-263 F | FELTON, J H | 8302180046 | 50-317 |
| FVERETT, R J | 8302250384 | I&E | FELTON, J H | 8302030033 | 50-213 F | FELTON, J H | 8302180055 | 50-298 |
| EWING, J H | 8302090490* | TOPREP | FELTON, J H | 8302030044 | 50-312 F | FELTON, J H | 8302180064 | 50-346 |
| EZRA, C E | 8302030208 | NUREG | FELTON, J H | 8302030057 | 50-259 F | FELTON, J H | 8302180066 | 50-358 |
| FAAS, R H | 8302220384* | TOPREP | FELTON, J H | 8302030059 | 50-348 F | FELTON, J H | 8302180077 | 50-219 |
| FABRIKANT, J I | 8302230328* | 50-434 T | FELTON, J H | 8302030137 | 50-299 F | FELTON, J H | 8302180090 | 50-395 |
| FABRY, A | 8302280020 | NUREG | FELTON, J H | 8302030207 | 50-346 F | FELTON, J H | 8302180102 | 50-10 |
| FADDEN, W N | 8302180361* | 50-443 Q | FELTON, J H | 8302030226 | 50-295 F | FELTON, J H | 8302180372* | FOIA |
| FADDEN, W N | 8302180361* | 50-443 Q | FELTON, J H | 8302030233 | 50-245 F | FELTON, J H | 8302180494 | 50-10 |
| FADDEN, W N | 8302180493* | 50-443 Q | FELTON, J H | 8302030267 | 50-387 F | FELTON, J H | 8302180518 | 50-295 |
| FADDEN, W N | 8302180493* | 50-443 Q | FELTON, J H | 8302030603 | 50-275 F | FELTON, J H | 8302220032 | 50-369 |
| FAIROBENT, L A | 8302250091 | NUREG | FELTON, J H | 8302030614 | 50-280 F | FELTON, J H | 8302220050 | 50-142 |
| FAIRFIELE, M | 8302170188* | 50-155 P | FELTON, J H | 8302030622 | 50-295 F | FELTON, J H | 8302220052 | 50-269 |
| FAIRFIELE, M B | 8302170076* | 50-155 P | FELTON, J H | 8302030627 | 50-259 F | FELTON, J H | 8302220053 | 50-285 |
| FAIRFIELE, M B | 8302170115 | 50-302 F | FELTON, J H | 8302040018 | 50-3 F | FELTON, J H | 8302220061 | 50-298 |
| FAIRFIELE, M B | 8302170192* | 50-155 P | FELTON, J H | 8302040033 | 50-10 F | FELTON, J H | 8302220072 | 50-369 |
| FAIRFIELE, M B | 8302220480 | 50-302 P | FELTON, J H | 8302040039 | 50-440 Q | FELTON, J H | 8302220073 | 50-3 |
| FANNING, O | 8302180159* | 50-295 B | FELTON, J H | 8302040108 | FOIA | FELTON, J H | 8302220188 | 50-3 |
| FARBER, S O | 8302080070* | CONTRACT | FELTON, J H | 8302040118 | FOIA | FELTON, J H | 8302220207 | FOIA |
| FARRAR, D L | 8302170315* | 50-373 Q | FELTON, J H | 8302040139 | 50-329 Q | FELTON, J H | 8302220222 | 50-337 |
| FARRAR, D L | 8302180463* | 50-454 Q | FELTON, J H | 8302040177 | 50-289 F | FELTON, J H | 8302220223 | FOIA |
| FARRAR, D L | 8302280303* | 50-454 Q | FELTON, J H | 8302040205 | 50-254 F | FELTON, J H | 8302220241 | 70-146 |
| FARRELL, E V | 8302250195* | 50-318 S | FELTON, J H | 8302040467 | FOIA | FELTON, J H | 8302220306 | 50-334 |
| FARRELL, R E | 8302040360* | 50-263 Q | FELTON, J H | 8302040478 | FOIA | FELTON, J H | 8302220357 | FOIA |
| FASANO, A | 8302030502* | 50-320 Q | FELTON, J H | 8302040490 | 50-341 D | FELTON, J H | 8302220365 | FOIA |
| FASANO, A | 8302230128* | 50-320 Q | FELTON, J H | 8302040496 | FOIA | FELTON, J H | 8302220003 | 50-267 |
| FASANO, A | 8302250355* | 50-320 Q | FELTON, J H | 8302040497 | 50-269 F | FELTON, J H | 8302230021 | 50-387 |
| FAY, C W | 8302080320 | 50-266 Q | FELTON, J H | 8302040905 | 50-206 Q | FELTON, J H | 8302250041 | 50-317 |
| FAY, C W | 8302090408 | 50-301 P | FELTON, J H | 8302040952 | FOIA | FELTON, J H | 8302250073 | 50-315 |
| FAY, C W | 8302090421 | 50-266 F | FELTON, J H | 8302040600 | 50-29 F | FELTON, J H | 8302280126 | 70-143 |
| FAY, C W | 8302100272 | PRM | FELTON, J H | 8302070003 | FOIA | FELTON, J H | 8302280135 | FOIA |
| FAY, C W | 8302150410 | 50-266 P | FELTON, J H | 8302070005 | FOIA | FELTZ, D E | 8302010592 | 50-128 |
| FAY, C W | 8302170153 | 50-266 R | FELTON, J H | 8302070008 | FOIA | FELTZ, D E | 8302140131 | 50-128 |
| FAY, C W | 8302170153* | 50-266 R | FELTON, J H | 8302070013 | FOIA | FERRILL, W | 8302020136* | 50-29 |
| FAY, C W | 8302180195 | 50-266 B | FELTON, J H | 8302070025 | 50-206 F | FERRI, R T | 8211150690* | FOIA |
| FAY, C W | 8302180206* | 50-266 B | FELTON, J H | 8302070076 | 50-272 Q | FEY, F L | 8302030036* | 50-263 |
| FAY, C W | 8302230236 | 50-266 P | FELTON, J H | 8302070146 | 50-289 P | FIEDLER, P B | 8302010145 | 50-219 |
| FAY, C W | 8302280154 | 50-266 P | FELTON, J H | 8302070164 | 50-288 F | FIEDLER, P B | 8302030117 | 71-9081 |
| FAY, C W | 8302280156 | 50-266 P | FELTON, J H | 8302070278 | 50-206 Q | FIEDLER, P B | 8302040262 | 50-219 |
| FAY, C W | 8302280310 | 50-266 P | FELTON, J H | 8302070288 | 50-317 F | FIEDLER, P B | 8302040380 | 50-219 |
| FAY, C W | 8302280366 | 50-266 P | FELTON, J H | 8302070295 | 50-313 F | FIEDLER, P B | 8302070539 | 50-219 |
| FAY, C W | 8302280552* | 50-266 Q | FELTON, J H | 8302070625 | 50-315 F | FIEDLER, P B | 8302080027 | 50-219 |
| FEHRER, C | 8302040521 | NUREG | FELTON, J H | 8302070630 | 50-346 F | FIEDLER, P B | 8302080148 | 50-219 |
| FEHRINGER, D J | 8302240037 | WASTE MOT | FELTON, J H | 8302080007 | 50-285 F | FIEDLER, P B | 8302090334 | 50-219 |
| FEHRINGER, D J | 8302240351 | WASTE MOT | FELTON, J H | 8302080044 | FOIA | FIEDLER, P B | 8302150273* | 50-219 |
| FEIBELMAN, M M | 8302080395 | FOIA | FELTON, J H | 8302080052 | FOIA | FIEDLER, P B | 8302180082* | 50-219 |
| FEIERABEND, C D | 8302010581* | 50-282 Q | FELTON, J H | 8302080063 | 50-220 P | FIEDLER, P B | 8302180087* | 50-219 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|----------------|------------------|------------------|
| FIEDLER, P B | 8302180087* | 50-219 F | FORD, J T | 8302080379 | 70-1201 | GAD, R K | 8302100228 | 50-443 Q |
| FIEDLER, P B | 8302220314 | 50-219 F | FORD, J T | 8302080381 | 70-1201 | GAD, R K | 8302100228 | 50-443 Q |
| FIEDLER, P B | 8302220321 | 50-219 S | FORD, J T | 8302090050 | 70-1201 | GAD, R K | 8302100235 | 50-443 Q |
| FIEDLER, P B | 8302220324 | 50-219 P | FORNEY, W | 8302150408* | 50-454 Q | GAD, R K | 8302100235 | 50-443 Q |
| FIEDLER, P B. | 8302280213 | 50-219 Q | FORNEY, W L | 8302240092* | 50-454 T | GAD, R K | 8302100243 | 50-443 Q |
| FIELDS, H C | 8302010142* | 50-395 S | FORTUNA, R A | 8302070142* | 50-272 Q | GAD, R K | 8302100243 | 50-443 Q |
| FIELDS, H C | 8302010378* | 50-395 S | FOSTER, D O | 8302010212 | 50-424 S | GAD, R K | 8302160297 | 50-443 Q |
| FIELDS, H C | 8302150624* | 50-395 S | FOSTER, D O | 8302010239 | 50-424 S | GAD, R K | 8302160323 | 50-443 Q |
| FIELDS, J | 8302010001 | CONTRACT | FOSTER, D O | 8302010647 | 50-424 S | GAD, R K | 8302160323 | 50-443 Q |
| FIELDS, J | 8302010109 | CONTRACT | FOSTER, D O | 8302010647 | 50-424 S | GAD, R K | 8302160329 | 50-443 Q |
| FIELDS, J | 8302020118 | CONTRACT | FOSTER, D O | 8302150714 | 50-424 Q | GAD, R K | 8302160329 | 50-443 Q |
| FIELDS, J | 8302150728 | CONTRACT | FOSTER, D O | 8302150714 | 50-424 Q | GAD, R K | 8302160352 | 50-443 Q |
| FIELDS, J A | 8302090500 | CONTRACT | FOSTER, D O | 8302280136 | 50-424 S | GAD, R K | 8302160352 | 50-443 Q |
| FIELDS, J A | 8302090507 | CONTRACT | FOSTER, J E | 8302040373* | 50-440 Q | GAD, R K | 8302160393 | 50-443 Q |
| FIELDS, J A | 8302100093 | CONTRACT | FOSTER, J E | 8302040395* | 50-440 Q | GAD, R K | 8302160093 | 50-443 Q |
| FIELDS, J A | 8302100074 | CONTRACT | FOSTER, J E | 8302040435* | 50-440 Q | GAD, R K | 8302160136 | 50-443 Q |
| FIELDS, J A | 8302100091 | CONTRACT | FOSTER, J E | 8302180065* | 50-373 Q | GAD, R K | 8302160136 | 50-443 Q |
| FIELDS, J A | 8302100106 | CONTRACT | FOX, C D | 8302070565 | 50-461 Q | GAD, R K | 8302160295 | 50-443 Q |
| FIELDS, J A | 8302100121 | CONTRACT | FOX, C D | 8302070565 | 50-461 Q | GAD, R K | 8302160295 | 50-443 Q |
| FIELDS, J A | 8302100136 | CONTRACT | FOX, C D | 8302070565 | 50-461 Q | GAD, R K | 8302160308 | 50-443 Q |
| FIELDS, J A | 8302100165 | 40-3453 | FOY, J | 8302020256 | 50-461 Q | GAD, R K | 8302180308 | 50-443 Q |
| FIELDS, J A | 8302100182 | 40-8102 | FOY, J | 8302080248 | 50-461 Q | GAD, R K | 8302180310 | 50-443 Q |
| FIELDS, J A | 8302100485 | CONTRACT | FOY, J | 8302170259 | 50-461 Q | GAD, R K | 8302180310 | 50-443 Q |
| FIELDS, J A | 8302100499 | CONTRACT | FRAMM, R | 8302040304* | 50-272 S | GAD, R K | 8302180322 | 50-443 Q |
| FIELDS, J A | 8302160006 | CONTRACT | FRAMM, R | 8302010310* | 50-311 S | GAD, R K | 8302180322 | 50-443 Q |
| FIELDS, J A | 8302160497 | CONTRACT | FRAMM, R | 8302010344* | 50-272 S | GAD, R K | 8302180355 | 50-443 Q |
| FIELDS, J A | 8302160507 | CONTRACT | FRAMM, R | 8302070446* | 50-272 S | GAD, R K | 8302180395 | 50-443 Q |
| FIELDS, J A | 8302180474 | CONTRACT | FRAMM, R | 8302070461* | 50-311 S | GAD, R K | 8302180360 | 50-443 Q |
| FIELDS, J A | 8302180501 | CONTRACT | FRAMM, R | 8302150507* | 50-311 S | GAD, R K | 8302180360 | 50-443 Q |
| FIELDS, J A | 8302180523 | CONTRACT | FRAMM, P W | 8302070306* | 40-86 | GAD, R K | 8302180375 | 50-443 Q |
| FIELDS, J A | 8302220440 | CONTRACT | FRANCIS, E | 8302010078 | 40-299 | GAD, R K | 8302180375 | 50-443 Q |
| FIELDS, J A | 8302220449 | CONTRACT | FRANCIS, E | 8302170091 | 40-4492 | GAD, R K | 8302180400 | 50-443 Q |
| FIELDS, J A | 8302220457 | CONTRACT | FRANCIS, E J | 8302070597 | 0A999 | GAD, R K | 8302180400 | 50-443 Q |
| FIELDS, J A | 8302240391 | CONTRACT | FRANK, L | 8302240070* | 50-454 T | GAD, R K | 8302180421 | 50-443 Q |
| FIELDS, M | 8302170040* | 50-261 P | FRANK, L | 8302240074* | 50-454 T | GAD, R K | 8302180421 | 50-443 Q |
| FILBURN, T P | 8302030324* | 50-336 S | FRECKETTIE, A L | 8302170429* | CONTRACT | GAD, R K | 8302180465 | 50-443 Q |
| FILE, P A | 8302070203* | 50-318 S | FREDERICKSON, P | 8302150662* | 50-390 O | GAD, R K | 8302180465 | 50-443 Q |
| FINDLEY, D E | 8302030022* | CONTRACT | FREEMAN, H B | 8302010181* | 50-416 S | GAD, R K | 8302180487 | 50-443 Q |
| FINDLEY, D E | 8302030211* | CONTRACT | FREEMAN, H B | 8302010261* | 50-416 S | GAD, R K | 8302180487 | 50-443 Q |
| FINK, M A | 8302100007 | FOIA | FREEMAN, H B | 8302030113* | 50-416 S | GAD, R K | 8302250423 | 50-293 P |
| FINKEL, A | 8302030511* | 50-334 Q | FREEMAN, H B | 8302030307* | 50-416 S | GAD, T Q | 8302160207 | 50-443 Q |
| FINKEL, A E | 8302180225* | 50-387 Q | FREEMAN, H B | 8302030359* | 50-416 S | GALLAGHER, E J | 8302090310* | 50-329 A |
| FIORILLI, O | 8302010390* | 50-528 Q | FREEMAN, H B | 8302040032* | 50-416 S | GALLAGHER, J W | 8302030105 | 50-277 Q |
| FIORILLI, O | 8302180089* | 50-358 Q | FREEMAN, H B | 8302040060* | 50-416 S | GALLAGHER, J W | 8302040393 | 50-277 P |
| FIORILLI, O | 8302230311* | 50-528 Q | FREEMAN, H B | 8302140093* | 50-416 S | GALLAGHER, J W | 8302150654 | 50-277 P |
| FISCHBERG, A | 8302090030* | CONTRACT | FREEMAN, H B | 8302140102* | 50-416 S | GALLAGHER, R H | 8302180218* | 50-113 Q |
| FISCHER, D C | 8302080048 | 50-311 P | FREEMAN, H B | 8302140204* | 50-416 S | GALLEHER, O A | 8302250440* | 50-269 P |
| FISCHER, D L | 8302090006* | 50-297 P | FREEMAN, H B | 8302150115* | 50-416 S | GALL, J | 8302170292 | 50-454 T |
| FISHER, E J | 8302240240* | CONTRACT | FREEMAN, H B | 8302170127* | 50-416 S | GALL, J | 8302170292 | 50-454 T |
| FISHGOLD, H | 8302240091* | CONTRACT | FREEMAN, H B | 8302170324* | 50-416 S | GALL, J | 8302180387 | 50-454 T |
| FITZGERALD, J A | 8302070347* | 50-368 Q | FREEMAN, H B | 8302220361* | 50-416 S | GALL, J | 8302180387 | 50-454 T |
| FITZGERALD, J A | 8302090126* | 50-358 Q | FREEMAN, H B | 8302280429* | 50-416 S | GALL, J | 8302250455 | 50-454 T |
| FITZGERALD, J A | 8302100392* | PR | FREEMAN, H B | 8302280440* | 50-416 S | GALL, J | 8302250455 | 50-454 T |
| FITZGERALD, J A | 8302180373* | FOIA | FREEMAN, S | 8302010200* | 50-416 S | GALL, J | 8302250597 | 50-155 Q |
| FITZGERALD, M J | 8302070546* | 50-219 S | FREY, D B | 8302030133* | 50-537 U | GALL, J | 8302250597 | 50-155 Q |
| FLACK, E | 8302230211 | 40-8498 | FRIEDMAN, L | 8302280525 | 1A-E | GALL, J | 8302250610 | 50-155 Q |
| FLACK, E | 8302230213 | 40-8498 | FRIEDMAN, L F | 8302070336 | 70-470 | GALL, J | 8302250610 | 50-155 Q |
| FLEENOR, C | 8302010124 | 50-537 A | FRISCO, D C | 8302100456 | PRM | GALL, R | 8302030197* | 50-322 Q |
| FLEENOR, C | 8302020084 | CONTRACT | FRYE, J H | 8302010492 | 50-142 Q | GALL, R | 8302150495* | 50-309 Q |
| FLEENOR, C | 8302020096 | 50-320 F | FRYE, J H | 8302090227 | 50-142 Q | GALL, R | 8302250300* | 50-309 Q |
| FLEENOR, C | 8302070635 | CONTRACT | FRYE, J H | 8302090237 | 50-142 Q | GALL, R K | 8302070357* | 50-29 Q |
| FLEENOR, C | 8302160485 | CONTRACT | FRYE, J H | 8302160193 | 50-142 Q | GALL, R H | 8302180171* | 50-322 Q |
| FLEISCHMANN, R | 8302230202 | 50-278 S | FRYER, J | 8302090125* | 50-315 F | GAMBLE, D | 8302090008* | 50-358 A |
| FLEISHER, Z S | 8302280163 | 50-247 Q | FUHS, A | 8302040189* | 50-254 S | GAMBLE, D | 8302090524* | 50-358 Q |
| FLEISHER, Z S | 8302280277 | 50-247 Q | FULLEN, C | 8302150593* | 50-267 S | GAMBLE, D H | 8302090478* | 50-358 Q |
| FLEMING, F J | 8302100464 | PR | FULLER, C | 8302070579* | 50-267 S | GAMBLE, D H | 8302090527* | 50-358 Q |
| FLEMING, T E | 8302090051* | 40-8452 | FULLER, C | 8302070591* | 50-267 S | GAMBLE, D C | 8302100442 | PR |
| FLEMING, T E | 8302140203* | 40-8102 | FULLER, C | 8302070623* | 50-267 S | GAMBLE, R H | 8302080139* | FOIA |
| FLEMING, T E | 8302170303 | 40-8102 | FULLER, C | 8302150001* | 50-267 S | GARCIA, E H | 8302010476* | 50-375 Q |
| FLENNER, R A | 8302180156* | 50-10 F | FULLER, C | 8302150003* | 50-267 S | GARCIA, P J | 8302160315 | 40-6622 |
| FLETCHER, W D | 8302080135* | FOIA | FULLER, C | 8302170347* | 50-267 S | GARCIA, P J | 8302160518 | 40-3453 |
| FLIPP, T A | 8302030590* | 50-382 Q | FUGUA, D | 8302030109* | 50-537 U | GARDE, B | 8302040499 | 50-206 Q |
| FLORY, C | 8302240317 | WASTE MGT | FURR, B J | 8302150263 | 50-261 Q | GARDE, B | 8302240368 | 50-329 A |
| FLOYD, J H | 8302170354* | 50-416 S | GAD, R K | 8302010529 | 50-443 Q | GARDE, B P | 8302070549 | 50-445 Q |
| FLOYD, S | 8302020429* | CONTRACT | GAD, R K | 8302010529 | 50-443 Q | GARDNER, R H | 8302040421* | 50-410 Q |
| FLYNN, M | 8302020206 | CONTRACT | GAD, R K | 8302010533 | 50-443 Q | GARDNER, R N | 8302250393* | 50-329 Q |
| FOLEY, T. | 8302030447 | 50-247 S | GAD, R K | 8302010533 | 50-443 Q | GARLINO, R A | 8302020389* | 40-8728 |
| FOLEY, T. | 8302230394* | 50-247 Q | GAD, R K | 8302010547 | 50-443 Q | GARN, J | 8302020198* | CONMISSION |
| FOKEM, O J | 8302070236 | 50-192 P | GAD, R K | 8302010547 | 50-443 Q | GARNER, L W | 8302150345* | 50-324 Q |
| FOOTE, R C | 8302170395* | 50-320 P | GAD, R K | 8302010589 | 50-443 Q | GARRITY, J H | 8302010308 | 50-309 S |
| FORD, E J | 8302190320* | 50-327 Q | GAD, R K | 8302010589 | 50-443 Q | GARRITY, J H | 8302030469 | 50-309 P |
| FORD, E J | 8302190482* | 50-327 Q | GAD, R K | 8302010594* | 50-443 Q | GARRITY, J H | 8302070526* | 50-309 P |
| FORD, E J | 8302190678* | 50-327 Q | GAD, R K | 8302010594* | 50-443 Q | GARRITY, J H | 8302070535* | 50-309 P |
| FORD, J T | 8302040494 | 70-1201 | GAD, R K | 8302100220 | 50-443 Q | GARRITY, J H | 8302100421* | 50-309 Q |
| FORD, J T | 8302070178* | 70-1201 | GAD, R K | 8302100220 | 50-443 Q | GARRITY, J H | 8302220383 | 50-309 P |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|----------------|------------------|------------------|----------------|------------------|------------------|----------------|------------------|------------------|
| GARRITY, J H | 8302230459 | 50-309 P | GDDY, A T | 8302230549* | 50-286 Q | GREGG, R J | 8302080383 | 70-398 |
| GARRITY, J H | 8302230554 | 50-309 S | GDDY, A T | 8302230539* | 70-398 | GREGG, R J | 8302090489 | 70-398 |
| GARY, R J | 8302070419* | 50-445 G | GOLDBERG, J H | 8302140163 | 50-498 A | GREGG, R J | 8302090532 | 70-398 |
| GARY, R J | 8302080352 | 70-2932 | GOLDBERG, S C | 8302030533 | 50-454 G | GRIFFIN, R L | 8302090006* | 50-454 |
| GARY, R J | 8302090403 | 50-445 G | GOLDBERG, S C | 8302100255 | 50-454 G | GRIFFIN, A | 8302230578* | 50-454 |
| GARY, R J | 8302100216 | 50-445 J | GOLDBERG, S C | 8302160176 | 50-454 T | GRIFFIN, J M | 8302180469 | 50-454 |
| GARY, R J | 8302170357* | 50-445 Q | GOLDBERG, S C | 8302220023 | 50-454 T | GRIFFIN, J M | 8302220275 | 50-454 |
| GARY, R J | 8302170368 | 50-445 F | GOLDBERG, S C | 8302240059 | 50-454 T | GROESCH, Q L | 8302010543 | 50-454 |
| GARY, R J | 8302230648* | 50-445 Q | GOLDEN, M P | 8302240019 | 50-272 J | GROESCH, Q L | 8302080246 | 50-454 |
| GARY, R J | 8302280295 | 50-445 S | GOLDMAN, L | 8302070090* | FOIA | GROULE, Q L | 8302030423* | 50-454 |
| GATES, H | 8302100501* | CONTRACT | GONZALEZ, A A | 8302040032 | TOPREP | GROULE, Q L | 8302030435* | 50-454 |
| GATES, W G | 8302220168* | 50-285 R | GODDHOPE, A C | 8302180433 | 27-39 | GROULE, Q L | 8302030444* | 50-454 |
| GAZILLO, F | 8302170198 | 50-346 F | GODMAN, L S | 8302100291 | PR | GROULE, Q L | 8302030452* | 50-454 |
| GEDDES, B L | 8302180073* | 50-346 F | GODMAN, L D | 8302160002 | RES | GROUNACK, A | 8302180384* | 50-454 |
| GEIGER, H J | 8302030199 | 50-247 T | GOUAN, E L | 8302080028 | FOIA | GROUNACK, A | 8302010439* | 50-454 |
| GEIGER, H J | 8302030199 | 50-247 T | GRACIE, R L | 8302100236* | 50-213 P | GROSSMAN, H | 8302240299 | 50-454 |
| GLFAR, L H | 8302020378* | WASTE MGT | GRAESSER, K L | 8302010173 | 50-295 S | GROSSMAN, H | 8302240307 | 50-454 |
| GENOVESE, J | 8302250244 | 50-440 G | GRAESSER, K L | 8302040349 | 50-304 S | GROSSMAN, H | 8302080307 | 50-454 |
| GERDEMAN, F W | 8302230422 | 40-8698 | GRAESSER, K L | 8302080284 | 50-304 S | GROTHMANN, M | 8302170204* | 50-454 |
| GEST, R E | 8302080076 | 70-754 | GRAESSER, K L | 8302170139 | 50-295 R | GROTHMANN, M | 8302240278* | 50-454 |
| GIBBONS, D R | 8302010625 | 40-8626 | GRAESSER, K L | 8302180152 | 50-295 S | GRUGAN, R A | 8302240293* | 50-454 |
| GIBBONS, D R | 8302040082* | FOIA | GRAESSER, K L | 8302290187 | 50-295 S | GRUNDEL, J A | 8302280020 | 50-454 |
| GIBBONS, D R | 8302040095* | FOIA | GRAESSER, K L | 8302250193 | 50-304 S | GRUNSEICH, R W | 8302010546 | 50-454 |
| GIBBONS, D R | 8302040162* | FOIA | GRAESSER, K L | 8302280470 | 50-295 S | GRUNTHNER, C | 8302180438 | 50-454 |
| GIBBONS, T D | 8302150084* | 50-370 Q | GRAESSER, K L | 8302280473 | 50-295 S | GUCA, L T | 8302010512 | 50-454 |
| GIBBONS, T D | 8302150496* | 50-390 Q | GRAESSER, K L | 8302280529 | 50-295 S | GUCA, L T | 8302150431* | 50-454 |
| GIBSON, A F | 8302150059 | 50-160 S | GRAHAM, J W | 8302010049 | FOIA | GUCA, L T | 8302150443* | 50-454 |
| GIBSON, A F | 8302150181* | 50-327 Q | GRANT, J | 8302250343* | 50-412 Q | GUCA, L T | 8302150627* | 50-454 |
| GIDD, R J | 8302100286 | HUREG | GRANT, P | 8302250355* | 50-320 Q | GUCA, L T | 8302150640* | 50-454 |
| GIDD, R J | 8302150718 | HUREG | GRANT, W B | 8302280438* | 50-237 Q | GUCA, L T | 8302010702 | 50-454 |
| GIESLER, C W | 8302010343 | 50-305 S | GRASSLEY, C E | 8302100365* | PR | GUCA, L T | 8302180123 | 50-454 |
| GIESLER, C W | 8302020347 | 50-305 P | GRAVES, R H | 8301190084* | 50-213 F | GUCA, L T | 8302180275 | 50-454 |
| GIESLER, C W | 8302040340 | 50-305 S | GRAVES, R H | 8302150188 | 50-213 S | GUCA, L T | 8302180320 | 50-454 |
| GIESLER, C W | 8302040411* | 50-305 Q | GRAVES, R H | 8302280499 | 50-213 S | GUCA, L T | 8302290432 | 50-454 |
| GIESLER, C W | 8302080226 | 50-305 S | GRAY, E | 8302030429* | 50-289 Q | GUILD, R | 8302010610 | 50-454 |
| GIESLER, C W | 8302100285 | PR | GRAY, E H | 8302280488* | 50-412 Q | GUILD, R | 8302010610 | 50-454 |
| GIESLER, C W | 8302100291 | PR | GRIEN, D R | 8302100213* | 50-440 Q | GULDEMOND, W | 8302010377* | 50-454 |
| GIESLER, C W | 8302100443 | PR | GRIEN, H J | 8302280194 | 50-327 S | GUNDERSON, B | 8302100390 | 50-454 |
| GIESLER, C W | 8302150144 | 50-305 S | GRIEN, H J | 8302010141 | 50-296 S | GUPTA, J H | 8302010133* | 50-454 |
| GIESLER, C W | 8302160377 | 50-305 R | GRIEN, H J | 8302010217 | 50-299 S | GUSTAFSON, R B | 8302040143 | 50-454 |
| GIESLER, C W | 8302230466 | 50-305 P | GREEN, H J | 8302010270 | 50-296 S | GUSTAFSON, R B | 8302040616 | 70-398 |
| GIESLER, C W | 8302280166 | 50-305 P | GREEN, H J | 8302010368 | 50-327 S | GUSTAFSON, R B | 8302070012 | 70-398 |
| GIFFORD, H C | 7902020122* | FOIA | GREEN, H J | 8302030273 | 50-328 S | GUSTAFSON, R B | 8302070137 | 70-398 |
| GIFFORD, H C | 7904250165* | FOIA | GREEN, H J | 8302030426 | 50-327 S | GUSTAFSON, R B | 8302080125 | 70-398 |
| GIFFORD, H C | 7905290339* | FOIA | GREEN, H J | 8302030510 | 50-296 S | GUSTAFSON, R B | 8302040235* | 50-454 |
| GIFFORD, H C | 8004250184* | FOIA | GREEN, H J | 8302030567 | 50-299 S | GUSTAVE, R P | 8302010002* | CON |
| GIFFORD, H C | 8302240270* | FOIA | GREEN, H J | 8302140004 | 50-260 S | GUSTAVE, R P | 8302010133* | 50-454 |
| GILBERT, R A | 8302280087 | 50-237 P | GREEN, H J | 8302140017 | 50-296 S | GUSTAVE, R P | 8302020090* | CON |
| GILCHRIST, C W | 8302240229* | 50-170 Q | GREEN, H J | 8302140037 | 50-296 S | GUSTAVE, R P | 8302020123* | CON |
| GILDELMAN, A J | 8302010023 | CONTRACT | GREEN, H J | 8302140144 | 50-260 S | GUSTAVE, R P | 8302020429* | CON |
| GILDELMAN, A J | 8302280247* | CONTRACT | GREEN, H J | 8302180524 | 50-327 S | GUSTAVE, R P | 8302030211* | CON |
| GILDNER, M L | 8302040045* | 50-440 Q | GREEN, H J | 8302190544 | 50-328 S | GUSTAVE, R P | 8302040167* | CON |
| GILINSKY, V | 8211150056* | FOIA | GREEN, H J | 8302170141 | 50-297 S | GUSTAVE, R P | 8302040292* | 50-454 |
| GILINSKY, V | 8302240367 | COMMISSION | GREEN, H J | 8302170142 | 50-296 S | GUSTAVE, R P | 8302040304* | CON |
| GILLEN, D H | 8302090025 | 40-8681 | GREEN, H J | 8302170182 | 50-327 S | GUSTAVE, R P | 8302040458* | CON |
| GILLEN, D H | 8302160434 | 40-8681 | GREEN, H J | 8302170343 | 50-299 S | GUSTAVE, R P | 8302040462* | CON |
| GILLMAN, D | 8302230412 | 50-398 Q | GREEN, H J | 8302230108 | 50-327 S | GUSTAVE, R P | 8302070131* | CON |
| GINN, R M | 8302070261 | 50-440 Q | GREEN, H J | 8302230230 | 50-327 S | GUSTAVE, R P | 8302070632* | CON |
| GINSBERG, T | 8302240361 | RFS | GREEN, H J | 8302230591 | 50-328 S | GUSTAVE, R P | 8302090254* | 50-454 |
| GIRARD, E H | 8302150342* | 50-259 Q | GREEN, H J | 8302230567 | 50-260 S | GUSTAVE, R P | 8302090254* | 50-454 |
| GIRQUARD, D | 8302240355 | FOIA | GREEN, H J | 8302230609 | 50-299 S | GUSTAVE, R P | 8302100021* | CON |
| GIRTZ, W H | 8302010502* | 40-8798 | GREEN, H J | 8302230618 | 50-296 S | GUSTAVE, R P | 8302100029* | CON |
| GUFFRITA, L D | 8302240057 | COMMISSION | GREEN, H J | 8302240254 | 50-327 S | GUSTAVE, R P | 8302100038* | CON |
| GLADDING, H | 8302160353 | 50-440 Q | GREEN, H J | 8302240261 | 50-327 S | GUSTAVE, R P | 8302160491* | CON |
| GLASS, S H | 8302280384* | 50-247 T | GREEN, H J | 8302280150 | 50-327 S | GUSTAVE, R P | 8302170571* | CON |
| GLEASON, J | 8302010517 | 50-247 Q | GREEN, H J | 8302280159 | 50-327 S | GUSTAVE, R P | 8302220445* | CON |
| GLEASON, J P | 8302070496 | 50-247 Q | GREEN, H J | 8302280175 | 50-260 S | GUSTAVE, R P | 8302220453* | CON |
| GLEASON, J P | 8302070537 | 50-483 Q | GREEN, H J | 8302280338 | 50-296 S | GUSTAVE, R P | 8302240240* | CON |
| GLEASON, J P | 8302090234 | 50-247 Q | GREEN, H J | 8302280354 | 50-299 S | GUSTAVE, R P | 8302240375* | CON |
| GLEASON, J P | 8302090244 | 50-247 Q | GREEN, H J | 8302280437 | 50-327 S | GUTHRIE, Q L | 8302220435 | NUR |
| GLEASON, J P | 8302220393 | 50-247 Q | GREEN, H J | 8302280463 | 50-328 S | GUTHRIE, Q L | 8302250135 | NUR |
| GLEASON, J P | 8302280187 | 50-247 Q | GREEN, H J | 8302280472 | 50-299 S | GUTIERREZ, J H | 8302030263 | 50-454 |
| GLENN, J | 8212210113 | I&E | GREEN, H J | 8302080380* | 50-346 F | GUTIERREZ, J H | 8302150915 | 50-454 |
| GLENN, J | 8302280525 | I&E | GREENHAY, W R | 8302040390 | 50-289 F | GUTIERREZ, J H | 8302220029 | 50-454 |
| GLODIO, R | 8302080220 | 50-440 Q | GREENLEAF, E A | 8302010009* | CONTRACT | GUTIERREZ, J H | 8302220033 | 50-454 |
| GLOERSEN, H B | 8302250364* | 50-10 Q | GREENMAN, E | 8302030447 | 50-247 S | GUTIERREZ, J H | 8302220037 | 50-454 |
| GODDARD, R J | 8302240027 | WASTE MGT | GREENMAN, E O | 8302030197* | 50-322 Q | HACKNEY, C A | 8302170061* | 50-454 |
| GODDARD, R J | 8302180303 | 50-155 Q | GREENWOOD, D D | 8302160300* | 50-416 P | HAELBIG, R T | 8302100450 | PR |
| GODDARD, R J | 8302180367 | 50-155 Q | GREGG, L R | 8302010554* | 50-295 Q | HAQAN, T F | 8302010028* | CON |
| GODDARD, R J | 8302220029 | 50-309 Q | GREGG, L R | 8302040289* | 50-195 Q | HAQAN, T F | 8302010115* | CON |
| GODDY, A T | 8302010336* | 70-371 | GREGG, L R | 8302150012* | 50-315 Q | HAQAN, T F | 8302020102* | 50-454 |
| GODDY, A T | 8302070236* | 50-311 S | GREGG, L R | 8302150019* | 50-398 Q | HAQAN, T F | 8302040485* | CON |
| GODDY, A T | 8302180241* | 50-5 B | GREGG, L R | 8302180309 | 50-315 S | HAQAN, T F | 8302090504* | CON |
| GODDY, A T | 8302180264* | 70-371 | GREGG, L R | 8302280438* | 50-237 Q | HAQAN, T F | 8302090510* | CON |
| GODDY, A T | 8302180371* | 70-124 | GREGG, R J | 8302040024 | 70-820 | HAQAN, T F | 8302100557* | CON |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---------------|------------------|------------------|-----------------|------------------|------------------|----------------|------------------|------------------|
| HAGAN, T F | 8302100081* | CONTRACT | HANNON, J N | 8302170096* | 50-155 P | HAYNES, P C | 8302080298 | 50-317 Q |
| HAGAN, T F | 8302100098* | CONTRACT | HANSON, D J | 8302180002 | RES | HAYNES, P C | 8302180511 | 50-387 H |
| HAGAN, T F | 8302100114* | CONTRACT | HANSON, J E | 8302070598* | 50-537 A | HAYS, S | 8302030393 | 50-206 P |
| HAGAN, T F | 8302100126* | CONTRACT | HARBOUR, J | 830224027* | 50-460 G | HAZELTINE, J | 8302010292* | 50-373 P |
| HAGAN, T F | 8302100142* | CONTRACT | HARBOUR, J | 8302240307 | 50-397 G | HAZELTINE, J | 8302080204* | 50-373 P |
| HAGAN, T F | 8302100173 | 40-3453 | HARDIN, A K | 8302150461* | 50-124 Q | HEAD, G F | 8302280605* | 50-321 P |
| HAGAN, T F | 8302100190* | 40-8102 | HARDING, M R | 8302280283* | 50-328 S | HEAD, W Y | 8302030048 | 71-6717 |
| HAGAN, T F | 8302100489* | CONTRACT | HARDING, M R | 8302030437* | 50-327 S | HEAD, T G | 8302030092* | 71-6717 |
| HAGAN, T F | 8302100501* | CONTRACT | HARDING, M R | 8302150536* | 50-327 S | HEATHERLY, T L | 8302180355* | 50-390 Q |
| HAGAN, T F | 8302150736* | CONTRACT | HARDING, M R | 8302150568* | 50-328 S | HEATHERLY, T L | 8302180662* | 50-390 Q |
| HAGAN, T F | 8302160009* | CONTRACT | HARDING, M R | 8302170146* | 50-327 S | HEGNER, J D | 8302170283* | 50-155 P |
| HAGAN, T F | 8302160502* | CONTRACT | HARDING, M R | 8302230111* | 50-327 S | HEHL, C W | 8302010593 | 50-375 S |
| HAGAN, T F | 8302160509* | CONTRACT | HARDING, M R | 8302230233* | 50-327 S | HEHL, C W | 8302010684 | 50-325 S |
| HAGAN, T F | 8302180478* | CONTRACT | HARDING, M R | 8302230562* | 50-328 S | HEHL, C W | 8302180461* | 50-174 Q |
| HAGAN, T F | 8302180525* | CONTRACT | HARDING, M R | 8302240257* | 50-327 S | HEIDEL, C H | 8302010400* | 50-311 K |
| HAGAN, T F | 8302220459* | CONTRACT | HARDING, M R | 8302240266* | 50-327 S | HEIDER, L H | 8302010391 | 50-297 Q |
| HAGAN, T F | 8302240079* | CONTRACT | HARDING, M R | 8302280155* | 50-327 S | HEIDER, L H | 8302050313* | 50-297 F |
| HAGAN, T F | 8302240122* | CONTRACT | HARDING, M R | 8302280162* | 50-327 S | HEIDER, L H | 8302140114 | 50-271 P |
| HAGER, S B | 8302280282* | 50-269 P | HARDING, M R | 8302280200* | 50-327 S | HEIDER, L H | 8302150686* | 50-297 Q |
| HAGER, S B | 8302280440* | 50-269 P | HARDING, M R | 8302280469* | 50-327 S | HEIDER, L H | 8302250164 | 50-271 P |
| HAGEY, H | 8302080429 | CONTRACT | HARDING, M R | 8302280171* | 50-328 S | HEIDER, L H | 8302250242 | 50-271 P |
| HAGMAN, D L | 8302160401 | RES | HARDY, O | 8302160189 | 50-329 A | HEIDER, L H | 8302250403 | 50-271 P |
| HAIRSTON, W O | 8302010103* | 50-348 S | HARPER, T L | 8302090076* | 50-358 Q | HEIDER, L H | 8302280505* | 50-297 Q |
| HAIRSTON, W O | 8302030048* | 50-348 F | HARPER, T L | 8302180089* | 50-358 Q | HEINTZMAN, M | 8302250180* | 50-294 V |
| HAIRSTON, W O | 8302070614* | 50-348 S | HARRELL, P H | 8302150531 | Q4999 | HEINTNER, K L | 8302170181* | 50-155 P |
| HAIRSTON, W O | 8302070617* | 50-348 S | HARRELL, P H | 8302160331* | Q4999 | HEITNER, K L | 8302250142 | 50-309 S |
| HAIRSTON, W O | 8302070620* | 50-348 S | HARRINGTON, K H | 8302020137* | 50-297 P | HELDRAUP, P | 8302180381 | 50-217 F |
| HAIRSTON, W O | 8302220131* | 50-348 R | HARRINGTON, W D | 8302080160 | 50-293 P | HELFKICH, R C | 8302100106 | PRM |
| HAIRSTON, W O | 8302220177* | 50-348 S | HARRINGTON, W D | 8302080192 | 50-293 P | HELLER, J V | 8302090129 | 70-820 |
| HAIRSTON, W O | 8302220364* | 50-348 S | HARRINGTON, W D | 8302100342* | 50-293 Q | HELLER, J V | 8302010382* | 50-255 Q |
| HAIRSTON, W O | 8302220372* | 50-348 S | HARRINGTON, W D | 8302140090 | 50-293 Q | HENDRICKS, J R | 8302250440* | 50-269 P |
| HAIRSTON, W O | 8302220413* | 50-364 R | HARRINGTON, W D | 8302220170 | 50-293 F | HENRY, C D | 8302170435* | MUREO |
| HAIRSTON, W O | 83022203711* | 50-364 S | HARRINGTON, W D | 83022201190 | 50-293 P | HENRY, C D | 8302170438* | MUREO |
| HAIRSTON, W O | 8302280042* | 50-364 S | HARRINGTON, W D | 8302230064* | 50-293 Q | HENSLEY, K D | 8302040017 | 70-143 |
| HAIRSTON, W O | 8302280211 | 50-348 S | HARRINGTON, W D | 8302250058 | 50-293 P | HENSLEY, K D | 8302040579 | 70-143 |
| HAIST, D P | 8302230278* | 50-508 Q | HARRINGTON, W D | 8302250322 | PR | HENSELEY, K D | 8302080345 | 70-143 |
| HALAPATZ, J | 8302040531* | 50-387 P | HARRIS, J R | 8302150591* | 50-424 Q | HENSELEY, K D | 8302080377 | 70-143 |
| HALE, C J | 8302160331* | Q4999 | HARRIS, J R | 8302150711* | 50-400 Q | HENSELEY, K D | 8302090061 | 70-143 |
| HALE, C J | 8302160339* | Q4999 | HARRISON, F | 8302150650* | 50-324 R | HERRING, R F | 8302160338* | 50-315 Q |
| HALE, D P | 8302280508 | 50-461 S | HARRISON, J J | 8302010622* | 50-461 Q | HERRING, R F | 8302220373 | 50-315 F |
| HALEY, K T | 8302080064* | CONTRACT | HARROLD, T J | 8302250357* | PR | HERLINGER, J R | 8302100356 | PR |
| HALL, D P | 8302080315 | 50-461 Q | HARTFORD, K | 8302230302* | 50-333 S | HERNANDEZ, G | 8302230666* | 50-275 Q |
| HALL, D P | 8302080318* | 50-461 Q | HARTLEY, J N | 8302290094 | MUREO | HERR, R K | 8302070474* | 50-368 Q |
| HALL, D P | 8302150032 | 50-461 S | HARTMANN, S L | 8302250298 | 50-460 Q | HERRICK, P C | 8212200051* | 50-244 P |
| HALL, D P | 8302150512* | 50-461 Q | HARTMAN, S L | 8302250298 | 50-460 Q | HERRIN, M G | 8302230540 | 50-454 G |
| HALL, D P | 8302180127 | 50-461 S | HARTZMAN, R M | 8302160306 | 50-247 Q | HERRIN, M G | 8302230540 | 50-454 G |
| HALL, D P | 8302180444 | 50-461 A | HARTZMAN, R M | 8302160306 | 50-247 Q | HERRING, L | 8302170339 | 50-445 A |
| HALL, D P | 8302180449 | 50-461 A | HARTZMAN, R M | 8302160311* | 50-247 Q | HERSHKOWITZ, R | 8302230123* | 50-205 P |
| HALL, D P | 8302180452* | 50-461 A | HARTZMAN, R M | 8302160318* | 50-247 Q | HERSCH, M H | 8302030111 | XPORTLIC |
| HALL, D P | 8302220326 | 50-461 Q | HARVEY, E A | 8302150739 | RES | HERSCH, M H | 8302280002* | XPORTLIC |
| HALL, D P | 8302280302 | 50-461 S | HARWARD, J E | 8302170361 | 50-293 J | HERSCH, M H | 8302280003* | XPORTLIC |
| HALL, D P | 8302280309 | 50-461 S | HASLINGER, K H | 8302070531* | 50-382 A | HERSHOFF, L W | 8302020400 | 40-8180 |
| HALL, D P | 8302280536 | 50-461 S | HASSELL, D F | 8302080003 | 50-247 Q | HEVER, R S | 8302070371 | 12 E |
| HALL, D P | 8302040134* | CONTRACT | HASSELL, D F | 8302170079 | 50-247 Q | HIATT, S L | 8302230234 | 50-440 Q |
| HALL, S | 8302280410* | 50-247 G | HASSELL, D F | 8302280275 | 50-247 G | HIATT, S L | 8302080267 | 50-440 Q |
| HALL, S | 8302250410* | 50-247 Q | HASSELL, D F | 8302280377 | 50-247 T | HIATT, S L | 8302100433* | PRM |
| HALL, S | 8302250410* | 50-247 Q | HASTINGS, W | 8302140365 | 50-514 Q | HIATT, S L | 8302140039 | 50-410 Q |
| HALL, S | 8302250410* | 50-247 Q | HASWELL, A | 8302090229 | 50-454 Q | HIATT, S L | 8302140016* | 50-440 Q |
| HALL, S | 830220130* | 50-142 Q | HASWELL, A | 8302090229 | 50-454 Q | HICKEY, C R | 8302100107 | 50-320 R |
| HALL, S | 8302220067* | 50-142 Q | HASWELL, A | 8302090229 | 50-454 Q | HICKMAN, J N | 8302100201 | MUREO |
| HALL, S | 8302220067* | 50-142 Q | HATHAKER, D F | 8302160300* | 50-416 P | HIGGINS, J | 8302030197* | 50-322 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020313 | XPORTLIC | HIGGINS, J C | 8302180171* | 50-322 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020320* | XPORTLIC | HILL, A A | 8302030079 | 50-537 U |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020337 | XPORTLIC | HILL, C D | 8302150001 | 50-267 S |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | 50-247 Q |
| HALL, S | 8302220067* | 50-142 Q | HATTORI, H | 8302020340* | XPORTLIC | HILL, E E | 8302070506* | |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|------------------|------------------|------------------|--------------------|------------------|------------------|
| HIRSH, J. C. | 8302230477* | 50-247 S | HUKILL, H. D. | 8302030541 | 50-289 S | JOHANSEN, E. | 8302080227 | 50-244 |
| HINTZ, D. C. | 8302040277 | 50-305 V | HUKILL, H. D. | 8302070446 | 50-289 P | JOHANSEN, J. | 8302210113 | 1&E |
| HIRSCH, D. | 8302160184 | 50-142 G | HUKILL, H. D. | 8302070452* | 50-289 P | JOHANSEN, A. D. | 8302230386* | 50-275 |
| HIRSCH, D. | 8302180400 | 50-142 G | HUKILL, H. D. | 8302080175 | 50-289 F | JOHANSEN, B. | 8302230545 | 50-454 |
| HOBANG, H. K. | 8302010434* | 50-237 P | HUKILL, H. D. | 8302080195 | 50-289 P | JOHANSEN, B. D. | 8302040121 | 50-255 |
| HOCK, J. B. | 8302040371* | 50-275 R | HUKILL, H. D. | 8302080385* | 50-289 F | JOHANSEN, B. D. | 8302040135 | 50-255 |
| HOCK, J. B. | 8302040377* | 50-275 R | HUKILL, H. D. | 8302090170 | 50-289 S | JOHANSEN, B. D. | 8302070439 | 50-255 |
| HODGSON, A. P. | 8302030454 | 50-352 G | HUKILL, H. D. | 8302090341 | 50-289 P | JOHANSEN, B. D. | 8302080317 | 50-255 |
| HODGSON, A. P. | 8302030470 | 50-352 G | HUKILL, H. D. | 8302090351* | 50-289 P | JOHANSEN, B. D. | 8302160173 | 50-255 |
| HODGSON, A. P. | 8302080906 | 50-352 G | HUKILL, H. D. | 8302090402 | 50-289 P | JOHANSEN, B. D. | 8302160250 | 50-255 |
| HODGES, W. | 8302070101* | 50-259 P | HUKILL, H. D. | 8302090407 | 50-289 V | JOHANSEN, B. D. | 8302160255* | 50-255 |
| HOLLER, J. | 8302040321* | 50-265 S | HUKILL, H. D. | 8302090452* | 50-289 F | JOHANSEN, B. D. | 8302230380 | 50-255 |
| HOFFMAN, G. L. | 8302090577* | 40-6745 | HUKILL, H. D. | 8302100232 | 50-289 P | JOHANSEN, B. D. | 8302280365 | 50-255 |
| HOFFMAN, M. V. | 8302170233 | 50-440 G | HUKILL, H. D. | 8302100237* | 50-289 P | JOHANSEN, B. D. | 8302280386 | 50-255 |
| HOFMAYER, C. H. | 8302170034* | 50-322 A | HUKILL, H. D. | 8302150052 | 50-289 P | JOHANSEN, B. H. | 8302070264 | 50-213 |
| HOFMAYER, C. H. | 8302170060* | 50-322 A | HUKILL, H. D. | 8302150603* | 50-289 Q | JOHANSEN, C. E. | 8302070486* | 50-392 |
| HOLDER, E. | 8302140005* | 50-260 S | HUKILL, H. D. | 8302150634 | 50-289 Q | JOHANSEN, D. | 8302010325 | 50-277 |
| HOLDER, E. | 8302140150* | 50-260 S | HUKILL, H. D. | 8302150651 | 50-289 P | JOHANSEN, D. | 8302100289 | 50-318 |
| HOLLIER, E. | 8302280369* | 50-259 S | HUKILL, H. D. | 8302180182* | 50-289 Q | JOHANSEN, E. H. | 8302010258* | 50-313 |
| HOLLOWAY, C. J. | 8302180117* | FOIA | HUKILL, H. D. | 8302230156 | 50-289 R | JOHANSEN, E. H. | 8302010258* | 50-313 |
| HOLLOWAY, C. J. | 8302180181* | FOIA | HUKILL, H. D. | 8302230175 | 50-289 P | JOHANSEN, E. H. | 8302070470 | 40-8084 |
| HOLLOWAY, C. J. | 8302180207* | FOIA | HUKILL, H. D. | 8302160212* | 50-454 T | JOHANSEN, F. N. | 8302230380 | 50-373 |
| HOLLOWAY, C. J. | 8302180212* | FOIA | HUKILL, H. D. | 8302220027* | 50-454 T | JOHANSEN, F. N. | 8302080204* | 50-373 |
| HOLLOWAY, C. J. | 8302180216* | FOIA | HUKILL, H. D. | 8302070486* | 50-382 Q | JOHANSEN, G. D. | 8302010070 | 50-413 |
| HOLLOWAY, C. J. | 8302180262* | FOIA | HUKILL, H. D. | 8302070556* | 50-313 Q | JOHANSEN, G. D. | 8302100267 | 50-413 |
| HULM, J. S. | 8302010597* | 50-335 P | HUNNICUTT, D. M. | 8302250243* | 50-445 Q | JOHANSEN, G. E. | 8302150485 | 50-413 |
| HOLMES-RAY, P. | 8302150234* | 50-321 Q | HUNNICUTT, D. M. | 8302250320* | 50-358 Q | JOHANSEN, G. E. | 8302230380 | 50-413 |
| HOLMES-RAY, P. | 8302150408* | 50-321 Q | HUNTER, R. S. | 8302040031* | GRG | JOHANSEN, G. E. | 8302240276 | 50-413 |
| HOLMES-RAY, P. | 8302150659* | 50-321 Q | HUNTER, R. S. | 8302160312* | 50-315 Q | JOHANSEN, J. | 8302230259* | 50-293 |
| HOLNICH, J. J. | 8302250117 | 50-482 A | HUNTER, R. S. | 8302220231 | 50-315 F | JOHANSEN, J. D. | 8302100273 | NUREG |
| HULT, J. | 8302010604 | 50-247 G | HUNTER, R. S. | 8302250301 | 50-315 Q | JOHANSEN, J. J. | 8302170469 | NUREG |
| HULT, J. | 8302100357 | PRM | HUNTER, R. S. | 8302250311* | 50-315 Q | JOHANSEN, J. H. | 8302230268* | 50-528 |
| HULT, J. | 8302160366 | 50-247 G | HURFORD, W. J. | 8302090434 | 50-261 P | JOHANSEN, J. R. Q. | 8302150548 | 50-263 |
| HULT, J. | 8302240314 | 50-247 G | HURFORD, W. J. | 8302160161 | 50-261 P | JOHANSEN, R. O. | 8302150628 | 50-263 |
| HULT, J. | 8302250372 | 50-247 G | HURSH, J. B. | 8302010637* | 40-672 | JOHANSEN, R. H. | 8302070632* | CONTRACT |
| HULT, J. | 8302250379* | 50-247 G | HUSAIN, I. | 8302170326* | 50-409 P | JOHANSEN, T. C. | 8302240352 | WASTE MGT |
| HULT, J. | 8302250393* | 50-247 G | HUSEBY, D. E. | 8302090422* | 50-318 S | JOHANSEN, T. C. | 8302250071 | WASTE MGT |
| HONMA, G. | 8302170237* | 50-322 A | HYLKA, R. | 8302040331* | 50-237 S | JOHANSEN, T. L. | 8302170550 | 40-8584 |
| HONMA, G. | 8302170235* | 50-322 A | ICKMAN, J. N. | 8302100281 | NUREG | JOHANSEN, T. L. | 8302070358* | 50-482 |
| HOPFER, A. H. | 8302170306 | 50-247 P | IGNATONIS, A. | 8302150676* | 50-369 Q | JOHANSEN, W. D. | 8302070391* | 50-313 |
| HORTON, G. L. | 8302240341 | 40-299 | IRBY, B. J. | 8302030327* | 50-296 S | JOHANSEN, W. D. | 8302070431* | 50-313 |
| HOSBY, C. H. | 8302150429* | 70-1113 | IRBY, B. J. | 8302140040* | 50-296 S | JOHANSEN, W. D. | 8302070475* | 50-313 |
| HOSBY, C. H. | 8302150458* | 50-250 Q | IRBY, B. J. | 8302280340* | 50-296 S | JOHANSEN, W. D. | 8302070543* | 50-298 |
| HOSBY, C. H. | 8302150597* | 50-280 Q | IRWIN, D. P. | 8302070501 | 50-322 G | JOHANSEN, W. D. | 8302070556* | 50-313 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302070501 | 50-322 G | JOHANSEN, W. D. | 8302070600* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302140152 | 50-322 Q | JOHANSEN, W. D. | 8302160258 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302280247 | 50-322 Q | JOHANSEN, W. D. | 8302230168 | 50-368 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302280254* | 50-322 Q | JOHANSEN, W. D. | 8302230168 | 50-368 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302280260* | 50-322 Q | JOHANSEN, W. D. | 8302230346* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302080142* | 50-346 S | JOHANSEN, W. D. | 8302230478* | 50-267 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302220124* | 50-142 Q | JOHANSEN, W. D. | 8302280387 | 50-482 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302010622* | 50-461 Q | JOHANSEN, W. P. | 8302250172 | 50-443 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302040034 | 50-201 J | JOHANSEN, W. P. | 8302250172 | 50-443 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302040367 | 50-282 S | JOHANSEN, W. P. | 8302160376 | 50-255 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302040331* | 50-305 Q | JOHANSEN, W. P. | 8302010390* | 50-328 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302140075 | 50-373 S | JOHANSEN, W. P. | 8302230311* | 50-528 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302280474* | 50-373 S | JOHANSEN, W. P. | 8302070155 | 50-537 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302240320 | 50-247 T | JOHANSEN, W. P. | 8302030333 | 50-298 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302250420 | 50-247 S | JOHANSEN, W. P. | 8302150676 | 50-296 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150416* | 50-261 Q | JOHANSEN, W. P. | 8302150475 | 50-259 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302250046 | NUREG | JOHANSEN, W. P. | 8302170048 | 50-260 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302020377* | WASTE MGT | JOHANSEN, W. P. | 8302240079* | CONTRACT |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302280215 | 50-72 R | JOHANSEN, W. P. | 8302100425 | PR |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302020430* | 50-289 P | JOHANSEN, W. P. | 8302220572 | 40-8629 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302220475* | 50-135 P | JOHANSEN, W. P. | 8302220362* | 50-289 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302100093 | 50-310 P | JOHANSEN, W. P. | 8302220371* | 50-289 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302100113 | 50-317 P | JOHANSEN, W. P. | 8302220381* | 50-289 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302170169* | 50-155 P | JOHANSEN, W. P. | 8302090254 | 40-8102 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302240195 | 50-317 S | JOHANSEN, W. P. | 8302010568 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302280480* | 50-295 S | JOHANSEN, W. P. | 8302010619 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302010322* | 50-322 Q | JOHANSEN, W. P. | 8302010621* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302010608* | 27-39 | JOHANSEN, W. P. | 8302040026 | 40-8822 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150102* | 50-359 Q | JOHANSEN, W. P. | 8302080188 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150304* | 50-370 Q | JOHANSEN, W. P. | 8302080273* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150370* | 50-359 Q | JOHANSEN, W. P. | 8302070383 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150720* | 50-389 Q | JOHANSEN, W. P. | 8302100276 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302010298* | 50-313 Q | JOHANSEN, W. P. | 8302150095* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302070343* | 50-298 Q | JOHANSEN, W. P. | 8302150187 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302160025 | RES | JOHANSEN, W. P. | 8302150660 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150316* | 50-389 Q | JOHANSEN, W. P. | 8302150675 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150665* | 50-369 Q | JOHANSEN, W. P. | 8302220057* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302150721* | 50-321 Q | JOHANSEN, W. P. | 8302220164 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302010588* | 50-335 P | JOHANSEN, W. P. | 8302220221 | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302170087* | 50-289 T | JOHANSEN, W. P. | 8302230349* | 50-285 |
| HOSBY, C. H. | 8302170325* | 50-409 P | IRWIN, D. P. | 8302100433* | PR | JOHANSEN, W. P. | 8302230575 | 50-285 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|-----------------|------------------|------------------|
| JONES, W C | 8302230576 | 50-295 P | KANGA, B K | 8302230207 | 50-320 S | KENNEDY, J E | 8302030247* | 50-322 T |
| JONES, W C | 8302280378 | 50-295 S | KANGA, B K | 8302230277 | 50-320 P | KENNEDY, R F | 8302170309 | 50-329 A |
| JORDAN, E L | 8212040358 | 50-3 Q | KAPLAN, C | 8302230352 | 50-247 Q | KENNEDY, R F | 8302280176* | 50-329 A |
| JORDAN, E L | 8212040360 | 50-3 Q | KAPLAN, C | 8302230361* | 50-247 Q | KENNEDY, W E | 8302250053 | NUREG |
| JORDAN, E L | 8212040361 | 50-3 Q | KAPLAN, C | 8302230364* | 50-247 Q | KENNEDY, W E | 8302250047* | 50-443 Q |
| JORDAN, E L | 8212040363 | 50-3 Q | KAPLAN, C | 8302230572* | 50-217 Q | KENNEKE, A | 8302100067* | FOIA |
| JORDAN, E L | 8212040365 | 50-3 Q | KAPLAN, C | 8302240709 | 50-247 Q | KENNY, T J | 8302070348* | 50-286 Q |
| JORDAN, E L | 8212040366 | 50-3 Q | KAPLAN, D S | 8302100410 | PR | KENYON, B D | 8302030564* | 50-387 Q |
| JORDAN, M J | 8302080313* | 50-331 Q | KAPLAN, S A | 8302040353* | 50-304 S | KENYON, B D | 8302280547 | 50-387 R |
| JORDAN, W S | 8302010521 | 50-443 G | KARMAN, M | 8302180389 | 50-261 Q | KENYON, T J | 8302170051 | 50-390 A |
| JORDAN, W S | 8302010521 | 50-443 Q | KARR, B | 8302040288 | 50-368 S | KEPPLER, J O | 8302010617 | 50-329 Q |
| JORDAN, W S | 8302170307 | 50-413 Q | KASAHARA, H | 8302030259 | NUREG | KEPPLER, J O | 8302010620 | 50-395 Q |
| JORDAN, W S | 8302170307 | 50-413 Q | KASTEN, R W | 8302100351* | PR | KEPPLER, J O | 8302040247 | 50-358 A |
| JORDAN, W S | 8302170312* | 50-413 Q | KASTENBERG, W E | 8302170190 | NUREG | KEPPLER, J O | 8302040334 | 50-456 Q |
| JORDAN, W S | 8302170312* | 50-413 Q | KASTENBERG, W E | 8302020236* | CONTRACT | KEPPLER, J O | 8302040336* | 50-456 Q |
| JORGENSEN, D L | 8302010382* | 50-235 Q | KASTURI, S | 8302100209* | 50-440 Q | KLPPLER, J O | 8302010065 | 50-440 Q |
| JOHNSON, P V | 8302070285* | 50-206 T | KASTURI, S | 8302100209* | 50-440 Q | KLPPLER, J O | 8302040381* | 50-440 Q |
| JULIAN, C A | 8302150316 | 50-389 Q | KAUFMAN, R L | 8302170289* | 50-443 Q | KLPPLER, J O | 8302080307* | 50-329 A |
| JUNGE, M A | 8302010175* | 50-318 S | KAUSEL, E | 8302070499* | 50-29 P | KLPPLER, J O | 8302080316 | 50-10 F |
| JUNGE, M A | 8302010205* | 50-317 S | KAVANAUGH, P F | 8302090270* | CONTRACT | KLPPLER, J O | 8302090044* | 50-358 Q |
| JUNGE, M A | 8302010345* | 50-318 S | KAVANAUGH, P F | 8302220453* | CONTRACT | KLPPLER, J O | 8302090052* | 50-358 Q |
| JUNGE, M A | 8302010354* | 50-317 S | KAY, J A | 8302150045 | 50-29 P | KLPPLER, J O | 8302090060* | 50-358 Q |
| JUNGE, M A | 8302070427* | 50-318 S | KAY, J A | 8302250252 | 50-29 P | KLPPLER, J O | 8302090064* | 50-358 Q |
| JUNGE, M A | 8302090399* | 50-317 S | KAY, M A | 8302070170* | 50-288 F | KLPPLER, J O | 8302160192 | 50-440 Q |
| JUNGE, M A | 8302090422* | 50-318 S | KEARNEY, J J | 8302140111 | PR | KLPPLER, J O | 8302180091* | 50-358 Q |
| JUNGE, M A | 8302180269* | 50-317 S | KEATING, D E | 8302280550* | 50-454 Q | KLPPLER, J O | 8302180445 | 50-237 Q |
| JUNGE, M A | 8302230476* | 50-317 S | KEDDIS, N N | 8302080332 | TOPREP | KLPPLER, J O | 8302180459* | 50-237 Q |
| JUNGE, M A | 8302290404* | 50-318 S | KEIMIG, R | 8302070335* | 50-289 Q | KLPPLER, J O | 8302180491 | 50-237 Q |
| KAEPEL, J B | 8302150124* | 50-234 S | KEIMIG, R | 8302250288* | 50-289 Q | KLPPLER, J O | 8302180496* | 50-237 Q |
| KAHLE, J F | 8302150356* | 70-143 | KEIMIG, R R | 8302070218* | 50-311 S | KLPPLER, J O | 8302250206 | 50-546 F |
| KAISER, R S | 8302090490* | TOPREP | KEIMIG, R R | 8302070228* | 50-272 S | KLPPLER, J O | 8302280461 | 50-373 Q |
| KALIVIANAKIS, N | 8302010132 | 50-265 S | KEIMIG, R R | 8302070236* | 50-311 S | KERR, G W | 8302150756 | State Proc |
| KALIVIANAKIS, N | 8302010540 | 50-254 S | KEIMIG, R R | 8302250360* | 50-34 Q | KETZLACH, N | 8302030090* | 70-2949 |
| KALIVIANAKIS, N | 8302040050 | 50-254 S | KEISER, H N | 8302010151 | 50-387 S | KEY, W J | 8302010622* | 50-461 Q |
| KALIVIANAKIS, N | 8302040171 | 50-254 S | KEISER, H N | 8302010160 | 50-387 S | KEY, W J | 8302150532* | 50-263 Q |
| KALIVIANAKIS, N | 8302040304 | 50-265 S | KEISER, H N | 8302010324 | 50-387 S | KEYWORTH, O A | 8302030104* | 50-537 U |
| KALIVIANAKIS, N | 8302040394 | 50-265 S | KEISER, H N | 8302010351 | 50-387 S | KILLPACK, V L | 8302180314* | 50-443 Q |
| KALIVIANAKIS, N | 8302080292 | 50-254 S | KEISER, H N | 8302030074 | 50-387 S | KINDER, E T | 8302160346 | 50-443 Q |
| KALIVIANAKIS, N | 8302150044 | 50-254 R | KEISER, H N | 8302030223 | 50-387 S | KING, R E | 8302100460 | PR |
| KALIVIANAKIS, N | 8302150114 | 50-254 S | KEISER, H N | 8302030278 | 50-387 S | KINNEHAN, J | 8302010658* | 40-672 |
| KALIVIANAKIS, N | 8302150691 | 50-254 R | KEISER, H N | 8302030337 | 50-387 S | KINNEHAN, J D | 8302010436 | 70-2467 |
| KALIVIANAKIS, N | 8302160151 | 50-265 S | KEISER, H N | 8302030555 | 50-387 S | KINNEHAN, J D | 8302250204 | 40-86 |
| KALIVIANAKIS, N | 8302280316 | 50-254 S | KEISER, H N | 8302040110 | 50-387 S | KINNEY, W | 8302030537* | 70-371 |
| KALMAN, K L | 8302160127 | 40-8064 | KEISER, H N | 8302180273 | 50-387 S | KINNEY, W H | 8302250340* | 50-54 Q |
| KAM, F B K | 8302280020 | NUREG | KEISER, H N | 8302180317 | 50-387 S | KINTNER, L L | 8302080109* | 50-252 P |
| KAMMER, D S | 8302010614 | 50-259 P | KEISER, H N | 8302220165 | 50-387 S | KINTNER, L L | 8302080122* | 50-280 Q |
| KAMMER, D S | 8302100415 | 50-390 F | KEISER, H N | 8302220380 | 50-387 S | KIRK, W F | 8302040447 | 70-371 |
| KAMMER, D S | 8302150035 | 50-260 Q | KEISER, H N | 8302220398 | 50-387 S | KIRKLAND, M W | 8302080034 | 70-754 |
| KAMMER, D S | 8302150047 | 50-260 Q | KEISER, H N | 8302230133 | 50-387 S | KIRKLAND, M W | 8302080104 | 70-754 |
| KAMMER, D S | 8302150470* | 50-327 Q | KEISER, H N | 8302230269 | 50-387 S | KIRSCH, D | 8302230263* | 50-361 Q |
| KAMMERER, C | 8302020193 | COMMISSION | KEISER, H N | 8302230333 | 50-387 S | KIRSCH, D F | 8302070265* | 50-206 T |
| KAMMERER, C | 8302030034* | 50-537 U | KEISER, H N | 8302230417 | 50-387 S | KIRSCH, D F | 8302070339* | 50-275 Q |
| KAMMERER, C | 8302030123* | 50-537 U | KEISER, H N | 8302230528 | 50-387 S | KIRSCH, D F | 8302190373* | 50-206 Q |
| KAMMERER, C | 8302090498* | 50-358 Q | KEISER, H N | 8302230694 | 50-387 S | KIRSCH, D F | 8302230258* | 50-361 Q |
| KAMMERER, C | 8302100322 | PR | KEITH, H | 8302030205* | 50-333 S | KIRSCH, D F | 8302230332 | 50-361 S |
| KAMMERER, C | 8302100323 | PR | KEITH, H | 8302030402* | 50-333 S | KIRSCH, D F | 8302230388* | 50-275 Q |
| KAMMERER, C | 8302100348 | PR | KEITH, H | 8302230547* | 50-333 S | KIRSCH, D F | 8302230399* | 50-361 Q |
| KAMMERER, C | 8302100360 | PR | KEITH, H | 8302230691* | 50-333 S | KIRSCH, D F | 8302230404* | 50-361 Q |
| KAMMERER, C | 8302100363 | PR | KELDER, C N | 8302070205* | FOIA | KIRSCH, D F | 8302230406* | 50-361 Q |
| KAMMERER, C | 8302100368 | PR | KELLER, J H | 8302280370* | 50-247 T | KIRVEN, J | 8302070582 | 50-261 Q |
| KAMMERER, C | 8302100370 | PR | KELLEY, D L | 8302030331* | 50-445 Q | KISTER, H | 8302010247 | 50-309 S |
| KAMMERER, C | 8302100382 | PR | KELLEY, H | 8302030544* | 0A999 | KISTER, H | 8302010504 | 50-309 S |
| KAMMERER, C | 8302100385 | PR | KELLEY, J L | 8302070548 | 50-413 Q | KISTER, H | 8302070348* | 50-286 Q |
| KAMMERER, C | 8302100393 | PR | KELLEY, J L | 8302070561 | 50-413 Q | KISTER, H | 8302230394* | 50-247 Q |
| KAMMERER, C | 8302100399 | PR | KELLEY, J L | 8302070605 | 50-361 Q | KISTER, H B | 8302030215* | 50-220 Q |
| KAMMERER, C | 8302100402 | PR | KELLEY, J L | 8302140145 | 50-413 Q | KISTER, H B | 8302030456* | 50-333 Q |
| KAMMERER, C | 8302100431 | PR | KELLEY, J L | 8302160363 | 50-400 G | KISTER, H B | 8302030576* | 50-244 Q |
| KAMMERER, C | 8302100441 | PR | KELLEY, W D | 8302010527* | 0A999 | KLEIN, D E | 8302070256 | 50-192 P |
| KAMMERER, C | 8302100445 | PR | KEILY, J | 8302230536 | 50-322 T | KLEINBORGE, W P | 8302180388* | 50-389 Q |
| KAMMERER, C | 8302100448 | PR | KELLY, J A | 8302070180* | 50-131 Q | KLINE, J R | 8302010472 | 50-440 Q |
| KAMMERER, C | 8302290328 | PR | KELLY, J A | 8302150582* | 50-128 Q | KLINE, J R | 8302070506 | 50-266 Q |
| KAMMERER, C | 8302250334 | REQD | KELLY, J A | 8302230517* | 50-128 Q | KLINE, J R | 8302070537 | 50-463 Q |
| KAMMERER, C | 8302250359 | PR | KELLY, J F | 8302080286 | 50-358 Q | KI NOLAN, O | 8302040320 | 50-456 Q |
| KE, W F | 8210290111* | 50-445 A | KELLY, J W | 8302040559 | 70-27 | KING, L F | 8302090451 | 50-329 Q |
| KEA, B K | 8302010353* | 50-320 Q | KELLY, J W | 8302040589 | 70-27 | KNAPP, W E | 8302030038* | 50-537 U |
| KEA, B K | 8302020001 | 50-320 P | KELLY, J H | 8302040604 | 70-27 | KNICELEY, J R | 8302150557* | 50-454 Q |
| KEA, B K | 8302070326 | 50-320 R | KELLY, J W | 8302070022 | 70-27 | KNICELEY, J R | 8302180457* | 50-373 Q |
| KEA, B K | 8302080031 | 50-320 F | KELLY, W J | 8302180175* | 50-275 S | KNIIGHT, J P | 8302100189* | 50-282 P |
| KEA, B K | 8302170379 | 50-320 P | KEMPER, J S | 8302010401* | 50-352 Q | KNIIGHTON, O | 8302280496 | 50-361 P |
| KEA, B K | 8302180250 | 50-320 S | KEMPER, J S | 8302080156 | 50-352 A | KNIIGHTON, O W | 8302020493 | 50-275 P |
| K | 8302180261 | 50-320 P | KEMPER, J S | 8302220341 | 50-352 S | KNIIGHTON, O W | 8302020500 | 50-443 A |
| K | 8302180431 | 50-320 P | KEMPER, J S | 8302230474 | 50-352 Q | KNIIGHTON, O W | 8302030002 | 50-528 A |
| K | 8302230695 | 50-320 S | KEMPER, J S | 8302230725 | 50-352 S | KNIIGHTON, O W | 8302030094 | 50-508 A |
| K | 8302240260 | 50-320 P | KEMPER, J S | 8302280323 | 50-352 S | KNIIGHTON, O W | 8302030107 | 50-275 P |
| K | 8302240271 | 50-320 P | KENNEDY, D M | 8302160247 | 50-255 R | KNIIGHTON, O W | 8302040403 | 50-412 A |

PERSONAL AUTHOR INDEX

469

| ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---------------------|---------------------|--------|---------------------|---------------------|----------------|---------------------|---------------------|
| 8302070948 | 50-382 | A | 8302280013 | NUREG | LEDERWOOD, R K | 830220376* | WASTE MGT |
| 8302100198 | 50-328 | A | 8302070576 | 50-334 | LEE, A | 8106010266* | 50-322 |
| 8302170419 | 50-328 | A | 8302090368 | 50-334 | LEE, A | 8110190094* | 50-322 |
| 8302230499 | 50-400 | A | 8302160479* | 50-334 | LEE, A | 8302170025* | 50-322 |
| 8302040080 | 50-546 | S | 8302180443 | 50-334 | LEE, D R | 8302230174 | 50-267 |
| 8302010479 | 50-456 | Q | 8302070053* | 50-206 | LEE, D R | 8302250251 | 50-267 |
| 8302010486* | 50-456 | Q | 8302070117* | 50-206 | LEHNERT, R A | 8302170036* | 50-341 |
| 8302010612 | 50-461 | Q | 8302010314* | 50-309 | LEMPGES, T E | 8302010370* | 50-220 |
| 8302040040 | 50-440 | Q | 8302010389* | 50-317 | LEMPGES, T E | 8302140074 | 50-220 |
| 8302040047 | 50-483 | Q | 8302090203* | 50-318 | LEMPGES, T E | 8302140082 | 50-220 |
| 8302040031* | 50-483 | Q | 8302090321* | 50-317 | LEMPGES, T E | 8302230679* | 50-220 |
| 8302040270 | 50-456 | Q | 8302090377* | 50-318 | LENAHAN, J J | 8302150140* | 50-413 |
| 8302040275* | 50-456 | Q | 8302230306* | 50-317 | LENTINE, F Q | 8302090437 | 50-295 |
| 8302150404 | 50-454 | Q | 8302220325* | 50-454 | LENTINE, F Q | 8302090464* | 50-295 |
| 8302150406* | 50-454 | Q | 8302220325* | 50-454 | LENTINE, F Q | 8302180417 | 50-295 |
| 8302180094 | 50-341 | Q | 8302010066 | 50-259 | LENTINE, F Q | 8302230159 | 50-295 |
| 8302180101* | 50-341 | Q | 8302100097* | 50-318 | LENTINE, F Q | 8302280400 | 50-295 |
| 8302180204 | 50-440 | Q | 8302100119* | 50-317 | LEONHART, L S | 8302020377* | WASTE MGT |
| 8302180208* | 50-440 | Q | 8302100257 | 50-269 | LESKYB, A Q | 8302100489* | CONTRACT |
| 8302180024 | FOIA | | 8302160404 | OEN TEC IS | LESSOR, L | 8302090097* | 50-298 |
| 8302250297 | 50-219 | P | 8302160203* | 50-454 | LESSOR, L C | 8302230712 | 50-298 |
| 8302100283 | PR | | 8302220027* | 50-454 | LESSY, R P | 8302010067 | 27-39 |
| 8302220067* | 50-142 | Q | 8302150718 | NUREG | LESSY, R P | 8302070159 | 50-443 |
| 8302030112 | 50-461 | K | 8302180357* | 50-443 | LESSY, R P | 8302080014 | 50-443 |
| 8302020428* | 50-264 | F | 8302180357* | 50-443 | LESSY, R P | 8302080039 | 50-443 |
| 8302150718 | NUREG | | 8302150235 | 50-322 | LESSY, R P | 8302250036 | 50-443 |
| 8302040019 | 70-2760 | | 8302010404 | 50-341 | LESTER, B H | 8302040479 | NUREG |
| 8302040035 | 70-2760 | | 8302150316* | 50-389 | LESTYK, J A | 8302100362 | PR |
| 8302070545* | 50-482 | Q | 8302230153 | 50-354 | LETSCHKE, K | 8302280260* | 50-322 |
| 8302080130* | 50-482 | F | 8302230171 | 50-354 | LETSCHKE, K J | 8302020325 | 50-322 |
| 8302080398 | 70-2760 | | 8302220244* | 70-146 | LETSCHKE, K J | 8302020325 | 50-322 |
| 8302090374 | 50-482 | S | 8302040330* | 50-329 | LETSCHKE, K J | 8302140149 | 50-322 |
| 830215073* | 50-482 | Q | 8302080312* | 50-329 | LETSCHKE, K J | 8302140149 | 50-322 |
| 8302160245 | 50-482 | S | 8302250393* | 50-329 | LETSCHKE, K J | 8302140152* | 50-322 |
| 8302230504 | 50-482 | S | 8302220362* | 50-289 | LEVI, I | 8302030210 | 50-247 |
| 8302280423 | 50-482 | V | 8302220391* | 50-289 | LEVI, I | 8302030210 | 50-247 |
| 8302280511 | 50-482 | S | 8302100446 | PRM | LEVIN, A A | 8302100464 | PR |
| 8302150330* | QA999 | | 8302010258* | 50-313 | LEVINE, J J | 8302230235 | 50-247 |
| 8302150546* | QA999 | | 8302150411* | 70-1201 | LEVINE, J J | 8302230235 | 50-247 |
| 8302230374* | 50-247 | Q | 8302280474* | 50-373 | LEVINE, J M | 8302070299* | 50-313 |
| 8302040080 | 50-546 | S | 8302160375 | 50-322 | LEVINE, M H | 8302070124 | RES |
| 8302040045* | 50-440 | Q | 8302160375 | 50-322 | LEVINE, S | 8302170298* | 50-454 |
| 8302040055* | 50-483 | Q | 8302240300 | 50-322 | LEVINE, S | 8302170298* | 50-454 |
| 8302180104* | 50-341 | Q | 8302240300 | 50-322 | LEVINE, S H | 8302280192* | 50-5 |
| 8302180213* | 50-440 | Q | 8302280247 | 50-322 | LEVY, S | 8302020273* | CONTRACT |
| 8302240092* | 50-454 | T | 8302280254* | 50-322 | LEWIS, J P | 8302040462* | CONTRACT |
| 8302250112 | NUREG | | 8302170029 | NUREG | LEWIS, R C. | 8302150013 | 50-261 |
| 8302010439* | 50-537 | A | 8302180265 | 50-269 | LEWIS, R C. | 8302150017* | 50-261 |
| 8112220673* | 50-293 | P | 8302230427 | 50-282 | LEWIS, R C. | 8302150058 | 50-302 |
| 8302090594* | 50-293 | P | 8302230686* | 50-282 | LEWIS, R C. | 8302150071* | 50-302 |
| 8302100275 | PR | | 8302160002 | RES | LEWIS, R C. | 8302150079 | 50-261 |
| 8302100384 | PR | | 8302160097 | RES | LEWIS, R C. | 8302150085* | 50-302 |
| 8302100413 | PRM | | 8302020316 | 50-322 | LEWIS, R C. | 8302150109* | 50-261 |
| 8302010448* | 70-2467 | | 8302020318 | 50-322 | LEWIS, R C. | 8302150288 | 50-370 |
| 8302280390* | 50-247 | T | 8302140152* | 50-322 | LEWIS, R C. | 8302150296 | 50-327 |
| 8302010588* | 50-335 | P | 8302280260* | 50-322 | LEWIS, R C. | 8302150309 | 50-259 |
| 8302010340* | 50-315 | S | 8302280273 | 50-322 | LEWIS, R C. | 8302150311* | 50-327 |
| 8302080324* | 50-315 | S | 8302280273 | 50-322 | LEWIS, R C. | 8302150331* | 50-259 |
| 8302160279* | 50-316 | S | 8302040057 | 50-312 | LEWIS, R C. | 8302150347 | 50-416 |
| 8302250184* | 50-315 | S | 8302040237 | 50-312 | LEWIS, R C. | 8302150348 | 50-390 |
| 8302250241* | 50-316 | S | 8302040398* | 50-289 | LEWIS, R C. | 8302150354* | 50-416 |
| 8302280409* | 50-315 | S | 8302170435* | NUREG | LEWIS, R C. | 8302150359* | 50-390 |
| 8302280410* | 50-315 | S | 8302220345 | 50-247 | LEWIS, R C. | 8302150380 | 50-261 |
| 8302140078 | 50-275 | P | 8302150664 | TGPREP | LEWIS, R C. | 8302150382 | 50-389 |
| 8302180492 | 50-275 | R | 8302030268 | 50-272 | LEWIS, R C. | 8302150412 | 50-261 |
| 8302240358* | FOIA | | 8302030397* | 50-334 | LEWIS, R C. | 8302150423 | 50-321 |
| 8302180248 | 50-255 | S | 8302180190 | 50-334 | LEWIS, R C. | 8302150434 | 50-124 |
| 8302180376 | 50-255 | S | 8302280445 | 50-272 | LEWIS, R C. | 8302150435* | 50-321 |
| 8302030478* | QA999 | | 8302250289* | 50-334 | LEWIS, R C. | 8302150446* | 50-124 |
| 8302020142 | 50-206 | P | 8302030016 | 50-412 | LEWIS, R C. | 8302150463 | 50-327 |
| 8302020241 | 50-206 | P | 8302170403 | 50-412 | LEWIS, R C. | 8302150493 | 50-424 |
| 8302020337 | 50-206 | P | 8302170554 | 50-412 | LEWIS, R C. | 8302150499 | 50-261 |
| 8302090305 | 50-206 | P | 8302100219 | 50-309 | LEWIS, R C. | 8302150538* | 50-338 |
| 8302150184 | 50-206 | P | 8302250115 | NUREG | LEWIS, R C. | 8302150598 | 50-389 |
| 8302160394 | 50-206 | P | 8302240385 | WASTE MGT | LEWIS, R C. | 8302150609 | 50-302 |
| 8302220378 | 50-206 | F | 8302170424* | CONTRACT | LEWIS, R C. | 8302150619* | 50-269 |
| 8302280250 | 50-206 | P | 8302070248 | 50-308 | LEWIS, R C. | 8302150671 | 50-259 |
| 8302080047 | FOIA | | 8302070235* | 50-308 | LEWIS, R C. | 8302150692* | 50-302 |
| 8302150102* | 50-389 | Q | 8302080177 | 50-308 | LJ, C T | 8302250094 | NUREG |
| 8302150676* | 50-369 | Q | 8302180215 | 50-308 | LIBERATOR I, L | 8302240095* | 50-247 |
| 8302100450 | PR | | 8302230148 | 50-308 | LICHTENBERGER | 8302070034 | 70-1100 |
| 8302030560* | 50-387 | S | 8302230154* | 50-308 | LICHTENBERGER | 8302250336 | PR |
| 8302230025 | NUREG | | 8302230238 | 50-308 | LICITRA, E A | 8302100131 | 50-528 |
| 8302070090* | FOIA | | 8302230246* | 50-308 | LIDOLE, A H | 8302030467 | 50-413 |
| 8302160402 | RES | | 8302230595* | 50-308 | LIDEN, E A | 812210244 | 50-272 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|---------------|------------------|------------------|-----------------|------------------|------------------|
| MAURIN, L V | 8302160373 | 50-382 A | MCGAUGHY, J P | 8302140014 | 50-416 S | MCNEILL, C A | 8302230621* | 50-333 D |
| MAURIN, L V | 8302170456* | 50-382 F | MCGAUGHY, J P | 8302140030 | 50-416 S | MCNEILL, C A | 8302230661 | 50-333 S |
| MAURIN, L V | 8302220265 | 50-382 S | MCGAUGHY, J P | 8302140031 | 50-416 S | MCNEILL, C A | 8302230687 | 50-333 S |
| MAURIN, L V | 8302230301 | 50-382 S | MCGAUGHY, J P | 8302140053 | 50-416 S | MCNEILL, W M | 8302070307* | QA997 |
| MAURIN, L V | 8302230320 | 50-382 S | MCGAUGHY, J P | 8302140058 | 50-416 S | MCPHERSON, B R | 8302170148* | 50-276 S |
| MAURIN, L V | 8302230335 | 50-382 F | MCGAUGHY, J P | 8302140063 | 50-416 S | MEACHUM, T R | 8302170009 | RES |
| MAURIN, L V | 8302230345 | 50-382 S | MCGAUGHY, J P | 8302140089 | 50-416 S | MEARS, L N | 8302010460* | QA999 |
| MAURIN, L V | 8302230440 | 50-382 A | MCGAUGHY, J P | 8302140100 | 50-416 S | MEDFORD, H O | 8302020030 | 50-362 P |
| MAURIN, L V | 8302250291 | 50-382 F | MCGAUGHY, J P | 8302140196 | 50-416 S | MEDINA, V | 8302020093* | CONTRACT |
| MAURIN, L V | 8302280329 | 50-382 G | MCGAUGHY, J P | 8302150083 | 50-416 S | MEDLOCK, R L | 8302170012 | 40-8452 |
| MAURIN, L V | 8302280333 | 50-382 S | MCGAUGHY, J P | 8302150099 | 50-416 S | MEISSNER, W C | 8302240122* | CONTRACT |
| MAURIN, L V | 8302280402 | 50-382 A | MCGAUGHY, J P | 8302150110 | 50-416 S | MENDONCA, M M | 8302070339* | 50-273 Q |
| MAURIN, L V | 8302280535 | 50-382 S | MCGAUGHY, J P | 8302150148 | 50-416 S | MENDONCA, M M | 8302230386* | 50-275 Q |
| MCALPINE, E J | 8302080270 | 70-1113 | MCGAUGHY, J P | 8302150286* | 50-416 Q | MENDONCA, M M | 8302030346* | 50-361 Q |
| MCALPINE, E J | 8302190659* | 70-143 | MCGAUGHY, J P | 8302150351* | 50-416 Q | MERCER, J W | 8302040479 | NUREQ |
| MCALPINE, E J | 8302150403* | 70-143 | MCGAUGHY, J P | 8302150635 | 50-416 B | MESEBLY, R L | 8302080173* | 50-445 Q |
| MCALPINE, E J | 8302150411* | 70-1201 | MCGAUGHY, J P | 8302170121 | 50-416 B | MESSELY, R L | 8302080173* | 50-445 Q |
| MCBRIDE, L M | 8302220159* | 50-267 | MCGAUGHY, J P | 8302170308 | 50-416 S | METZENBAUM, H M | 7910230415* | 50-440 U |
| MCBRIDE, M H | 8302090543* | 50-267 R | MCGAUGHY, J P | 8302170318 | 50-416 S | MEUNIER, J | 8302100347 | PR |
| MCBRIDE, M H | 8302010322* | 50-322 Q | MCGAUGHY, J P | 8302170322 | 50-416 S | MEUNIER, J | 8302250331* | PR |
| MCBRIDE, M H | 8302100312* | 50-213 Q | MCGAUGHY, J P | 8302170346 | 50-416 S | MEYER, O C | 8302040131 | PROJ |
| MCCABE, E | 8302010325* | 50-277 Q | MCGAUGHY, J P | 8302170358 | 50-416 S | MEYER, O C | 8302020011 | 50-470 E |
| MCCABE, E C | 8302100292* | 50-387 Q | MCGAUGHY, J P | 8302220358 | 50-416 S | MEYER, O F | 8302250273* | 50-352 Q |
| MCCABE, E C | 8302100298* | 50-277 Q | MCGAUGHY, J P | 8302220369 | 50-416 S | MEYER, J N | 8302030346* | 50-247 T |
| MCCABE, E C | 8302100414* | 50-277 Q | MCGAUGHY, J P | 8302230322 | 50-416 R | MITCHELL, C J | 8302070127 | 70-143 |
| MCCABE, E C | 8302150393* | 50-317 Q | MCGAUGHY, J P | 8302280071 | 50-416 S | MICHEL, C J | 8302070191 | 70-143 |
| MCCABE, E C | 8302180171* | 50-322 Q | MCGAUGHY, J P | 8302280225 | 50-416 S | MICHEL, C J | 8302080087 | 70-143 |
| MCCANN, J F | 8302100292* | 50-387 Q | MCGAUGHY, J P | 8302280230 | 50-416 S | MICHEL, C J | 8302080091 | 70-143 |
| MCCLEUNG, C E | 8302020335* | 50-361 Q | MCGAUGHY, J P | 8302280235 | 50-416 S | MICHEL, R H | 8302100398* | PR |
| MCCLEUNG, C E | 8302020335* | 50-361 Q | MCGAUGHY, J P | 8302280283 | 50-416 S | MICHEL, R H | 8302100451 | PR |
| MCCORKLE, O W | 8302070049* | 50-206 F | MCGAUGHY, J P | 8302280294 | 50-416 S | MICHELSON, C | 8302100340* | REVIEW GRP |
| MCCORKLE, O W | 8302070112* | 50-206 F | MCGAUGHY, J P | 8302280424 | 50-416 S | MIDURA, H J | 8302010195 | 50-272 S |
| MCCORKLE, O W | 8302070134* | 50-206 F | MCGAUGHY, J P | 8302280431 | 50-416 S | MIDURA, H J | 8302010303 | 50-311 S |
| MCCORKLE, O W | 8302070192* | 50-334 S | MCGAUGHY, J P | 8302280448 | 50-416 S | MIDURA, H J | 8302010339 | 50-272 S |
| MCCRACKEN, C | 8302020430* | 50-289 P | MCGAUGHY, J P | 8302280458 | 50-416 S | MIDURA, H J | 8302070300 | 50-272 S |
| MCCRACKEN, C | 8302240078* | 50-454 T | MCGINTY, D H | 8302040437 | 50-186 F | MIDURA, H J | 8302070442 | 50-272 S |
| MCCRACKEN, C E | 8302010564* | 50-329 T | MCGINTY, D H | 8302040624 | 50-186 F | MIDURA, H J | 8302070457 | 50-311 S |
| MCCRACKEN, R A | 8302180476* | 50-331 F | MCGOVERN, J M | 8302010559* | 70-687 | MIDURA, H J | 8302190501 | 50-211 S |
| MCCRORY, S L | 8302070391* | 50-313 Q | MCGOVERN, J M | 8302100336 | PR | MIDURA, H J | 8302220133 | 50-311 R |
| MCCRORY, S L | 8302070543* | 50-278 Q | MCGOWAN, J W | 8302090471* | 50-348 F | MIDURA, H J | 8302220173 | 50-272 R |
| MCDERMOTT, D | 8302020050 | CONTRACT | MCGUIRE, D R | 8302030437* | 70-27 | MILAM, B B | 8302040520 | ORG |
| MCDERMOTT, D | 8302020087 | CONTRACT | MCGUIRE, D R | 8302140043 | 50-390 S | MILES, E | 8302040464 | CONTRACT |
| MCDERMOTT, D | 8302020409 | CONTRACT | MCGUIRE, D R | 8302150346* | 50-259 Q | MILES, E B | 8302010009 | CONTRACT |
| MCDERMOTT, D | 8302100011 | CONTRACT | MCGUIRE, D R | 8302150614* | 50-302 Q | MILLAR, F | 8302040470 | FOIA |
| MCDERMOTT, D | 8302160029 | CONTRACT | MCGUIRE, D R | 8302150700* | 50-302 Q | MILLER, C F | 8302170227* | 50-322 A |
| MCDERMOTT, D | 8302170421 | CONTRACT | MCGUIRE, D R | 8302150717* | 50-395 Q | MILLER, C F | 8302170235* | 50-322 A |
| MCDERMOTT, D | 8302170423 | CONTRACT | MCGUIRE, D R | 8302170304 | 50-369 Q | MILLER, D B | 8302250225 | 50-327 A |
| MCDERMOTT, D | 8302170484 | CONTRACT | MCGUIRE, D R | 8302250315 | 50-338 Q | MILLER, D B | 8302250230 | 50-329 A |
| MCDERMOTT, D | 8302170536 | CONTRACT | MCGUIRE, D R | 8302070133 | 50-338 Q | MILLER, D B | 8302250245 | 50-329 A |
| MCDERMOTT, D | 8302170545 | CONTRACT | MCGUIRE, D R | 8302280390* | 50-247 T | MILLER, D B | 8302280239 | 50-329 A |
| MCDERMOTT, D | 8302220020 | CONTRACT | MCINTOSH, J T | 8302040504* | 50-269 F | MILLER, D B | 8302280300 | 50-329 A |
| MCDERMOTT, D | 8302220036 | CONTRACT | MCINTOSH, J T | 8302220047* | 50-369 F | MILLER, D E | 8302150019* | 50-359 Q |
| MCDERMOTT, D | 8302220068 | CONTRACT | MCINTYRE, S | 8302230429 | 50-410 Q | MILLER, J | 8302180412 | 50-156 S |
| MCDERMOTT, D | 8302240178 | CONTRACT | MCKENZIE, D H | 8302250053 | NUREQ | MILLER, J R | 8302010534 | 50-255 Q |
| MCDERMOTT, D | 8302240269 | CONTRACT | MCKENZIE, D H | 8302250146 | NUREQ | MILLER, J R | 8302010544* | 50-255 Q |
| MCDERMOTT, D | 8302250074 | CONTRACT | MCKEOWN, L H | 8302230549* | 50-284 Q | MILLER, J R | 8302040281 | 50-155 Q |
| MCDONALD, D Q | 8302080395 | 50-250 P | MCKINNEY, C J | 8302010120* | 50-395 S | MILLER, J R | 8302040324 | 50-341 Q |
| MCDONALD, D Q | 8302090518 | 50-250 P | MCKINNEY, C J | 8302010165* | 50-395 S | MILLER, J R | 8302150345 | 50-154 Q |
| MCDONALD, D Q | 8302180302* | 50-443 Q | MCKINNEY, C J | 8302010591* | 50-395 S | MILLER, J R | 8302180168 | 70-1193 |
| MCDONALD, R J | 8302070131* | CONTRACT | MCKINNEY, C J | 8302070383* | 50-395 S | MILLER, J R | 8302180447 | 50-10 G |
| MCDONALD, R P | 8302030068* | 50-348 F | MCKINNEY, C J | 8302150223* | 50-395 S | MILLER, L K | 8302220138* | 50-311 R |
| MCELROY, W N | 8302220435 | NUREQ | MCKINNEY, C J | 8302150595* | 50-395 S | MILLER, L K | 8302220177* | 50-272 P |
| MCELROY, W N | 8302250135 | NUREQ | MCKINNEY, C J | 8302150666* | 50-395 S | MILLER, M E | 8302020290 | 50-537 T |
| MCELROY, W N | 8302280020 | NUREQ | MCKINNEY, C J | 8302170244* | 50-395 S | MILLER, M E | 8302020265 | 50-445 Q |
| MCFARLAND, C R | 8302190607* | 50-389 Q | MCKINNEY, C J | 8302280198* | 50-395 S | MILLER, M E | 8302220415 | 50-445 Q |
| MCFETRIDGE, R H | 8302220384* | TOPREP | MCKNIGHT, J | 8302020147 | 50-320 B | MILLER, M S | 8302080230 | 50-322 Q |
| MCGARRY, E D | 8302280020 | NUREQ | MCKNIGHT, J | 8302020171 | 50-320 B | MILLER, M S | 8302080230 | 50-322 Q |
| MCGARRY, J M | 8302170228 | 50-413 Q | MCKNIGHT, J | 8302020302 | 50-320 B | MILLER, P E | 8302250424* | 50-269 P |
| MCGARRY, J M | 8302170228 | 50-413 Q | MCLAUGHLIN, D | 8302100294 | PRM | MILLER, W H | 8302150303* | 50-416 Q |
| MCGAUGHY, J P | 8302010171 | 50-416 S | MCLAUGHLIN, D | 8302040480 | CONTRACT | MILLER, W O | 8211180459* | FOIA |
| MCGAUGHY, J P | 8302010172 | 50-416 S | MCLEAREN, T. | 8302240071 | CONTRACT | MILLER, W O | 8302030103 | 50-416 F |
| MCGAUGHY, J P | 8302010194 | 50-416 S | MCLEAREN, T. | 8302240110 | CONTRACT | MILLER, W O | 8302080168 | 50-315 F |
| MCGAUGHY, J P | 8302010252 | 50-416 S | MCLEAREN, T. | 8302160181 | 50-382 A | MILLER, W O | 8302090117 | 50-261 F |
| MCGAUGHY, J P | 8302010425 | 50-416 S | MCLENDON, O D | 8302020396 | FOIA | MILLER, W O | 8302100078 | 50-339 I |
| MCGAUGHY, J P | 8302010470 | 50-416 S | MCMURRAY, C H | 8302030200 | 50-333 S | MILLER, W O | 8302100083 | 50-267 I |
| MCGAUGHY, J P | 8302010495 | 50-416 S | MCNEILL, C A | 8302030396 | 50-333 S | MILLER, W O | 8302170004 | 50-315 I |
| MCGAUGHY, J P | 8302030100 | 50-416 S | MCNEILL, C A | 8302030413 | 50-333 S | MILLER, W O | 8302170128 | 50-263 I |
| MCGAUGHY, J P | 8302030110 | 50-416 S | MCNEILL, C A | 8302180300 | 50-333 S | MILLER, W O | 8302180084* | FOIA |
| MCGAUGHY, J P | 8302030300 | 50-416 S | MCNEILL, C A | 8302230224 | 50-333 S | MILLER, W O | 8302180196* | FOIA |
| MCGAUGHY, J P | 8302030356 | 50-416 S | MCNEILL, C A | 8302230288 | 50-333 S | MILLER, W O | 8302180221* | FOIA |
| MCGAUGHY, J P | 8302030363 | 50-416 S | MCNEILL, C A | 8302230295 | 50-333 S | MILLER, W O | 8302180271* | FOIA |
| MCGAUGHY, J P | 8302030367* | 50-416 S | MCNEILL, C A | 8302230298 | 50-333 S | MILLER, W O | 8302180273* | FOIA |
| MCGAUGHY, J P | 8302030387 | 50-416 S | MCNEILL, C A | 8302230469 | 50-333 S | MILLER, W O | 8302180293* | FOIA |
| MCGAUGHY, J P | 8302030562 | 50-416 S | MCNEILL, C A | 8302230537 | 50-333 S | MILLER, W O | 8302180304* | FOIA |
| MCGAUGHY, J P | 8302070466 | 50-416 S | MCNEILL, C A | 8302230577 | 50-333 S | MILLER, W O | 8302180331* | FOIA |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---------------|------------------|------------------|---------------|------------------|------------------|-----------------|------------------|------------------|
| MILLER, W O | 8302180340* | FOIA | MILLS, L H | 8302190655* | 50-327 | MOBLE, R D | 8302030351* | 50-397 |
| MILLER, W O | 8302180341* | FOIA | MILLS, L H | 8302190681* | 50-259 | MOJTA, K J | 8302100312* | 50-213 |
| MILLER, W O | 8302180347* | FOIA | MILLS, L H | 8302160183 | 50-438 | MONTANGE, C H | 8302100355 | PRM |
| MILLER, W O | 8302180385* | FOIA | MILLS, L H | 8302160253 | 50-390 | MONTGOMERY, B S | 8302090285 | 50-317 |
| MILLER, W O | 8302220034 | 50-368 | MILLS, L H | 8302170003 | 40-1341 | MONTGOMERY, D M | 8302150181* | 50-327 |
| MILLER, W O | 8302220502 | 50-244 | MILLS, L H | 8302170165 | 50-260 | MONTGOMERY, D M | 8302150459* | 50-321 |
| MILLER, W O | 8302250024 | 50-272 | MILLS, L H | 8302170207 | 50-438 | MONTGOMERY, J | 8302230693* | 50-267 |
| MILLIGAN, K H | 8302010359 | 50-322 | MILLS, L H | 8302170215 | 50-438 | MONTGOMERY, J L | 8302170061* | 50-285 |
| MILLIGAN, K H | 8302100427 | 50-322 | MILLS, L H | 8302170342 | 50-438 | MONTI, W A | 8302240320 | 50-247 |
| MILLIGAN, K H | 8302180202 | 50-322 | MILLS, L H | 8302170356 | 50-390 | MOORE, D E | 8302150346* | 50-259 |
| MILLIGAN, K H | 8302230200 | 50-322 | MILLS, L H | 8302220245 | 50-438 | MOORE, J E | 8302030539 | 50-247 |
| MILLS, L G | 8302230284* | 70-1362 | MILLS, L H | 8302230137 | 50-593 | MOORE, J E | 8302090449 | 50-247 |
| MILLS, L H | 8301180127 | 50-259 | MILLS, L H | 8302230143 | 50-259 | MOORE, J E | 8302090454 | 50-247 |
| MILLS, L H | 8302010215 | 50-390 | MILLS, L H | 8302230152 | 50-390 | MOORE, R D | 8302180126* | 50-10 |
| MILLS, L H | 8302010230 | 50-390 | MILLS, L H | 8302230160 | 50-390 | MOORE, R N | 8302020308 | XPORTL |
| MILLS, L H | 8302010233 | 50-390 | MILLS, L H | 8302230219 | 50-438 | MOORE, R N | 8302090470 | XPORTL |
| MILLS, L H | 8302010243 | 50-390 | MILLS, L H | 8302230234 | 50-438 | MOORE, R N | 8302240147 | XPORTL |
| MILLS, L H | 8302010254 | 50-390 | MILLS, L H | 8302230276 | 50-438 | MOORE, R N | 8302240152 | XPORTL |
| MILLS, L H | 8302010265 | 50-438 | MILLS, L H | 8302230330 | 50-438 | MOORE, R N | 8302240158 | XPORTL |
| MILLS, L H | 8302010293 | 50-390 | MILLS, L H | 8302230343 | 50-390 | MOORE, R N | 8302240377 | XPORTL |
| MILLS, L H | 8302010300 | 50-438 | MILLS, L H | 8302230344 | 50-259 | MOORE, R N | 8302240390* | XPORTL |
| MILLS, L H | 8302010417 | 50-518 | MILLS, L H | 8302230411 | 50-259 | MOORE, S N | 8302230309 | 50-413 |
| MILLS, L H | 8302010419 | 50-438 | MILLS, L H | 8302230514 | 50-390 | MORAN, D H | 8302080422 | TOPREP |
| MILLS, L H | 8302010450 | 50-438 | MILLS, L H | 8302230590 | 50-327 | MORBY, W C | 8302010159 | 50-361 |
| MILLS, L H | 8302010453 | 50-390 | MILLS, L H | 8302230643 | 50-438 | MORBY, W C | 8302010169* | 50-361 |
| MILLS, L H | 8302010461 | 50-390 | MILLS, L H | 8302230647 | 50-390 | MORGAN, C | 8302160271 | 50-247 |
| MILLS, L H | 8302010500 | 50-439 | MILLS, L H | 8302230682 | 50-259 | MORGAN, C | 8302160271 | 50-247 |
| MILLS, L H | 8302010583 | 50-259 | MILLS, L H | 8302280123 | 50-390 | MORGAN, C | 8302160324 | 50-247 |
| MILLS, L H | 8302010587 | 50-327 | MILLS, L H | 8302280142 | 50-390 | MORGAN, C | 8302160324 | 50-247 |
| MILLS, L H | 8302010598 | 50-390 | MILLS, L H | 8302280165 | 50-390 | MORGAN, C | 8302160384 | 50-247 |
| MILLS, L H | 8302010631 | 50-438 | MILLS, L H | 8302280178 | 50-438 | MORGAN, C | 8302160384 | 50-247 |
| MILLS, L H | 8302010648 | 50-390 | MILLS, L H | 8302280240 | 50-327 | MORGAN, K Z | 8302230553* | 50-454 |
| MILLS, L H | 8302010659 | 50-438 | MILLS, L H | 8302280335 | 50-438 | MORGAN, M J | 8302170296 | 50-440 |
| MILLS, L H | 8302010664 | 50-438 | MILLS, L H | 8302280495 | 50-390 | MORTARTY, J H | 8302250201 | 50-354 |
| MILLS, L H | 8302020119 | 40-1341 | MILLS, L H | 8302280499 | 50-438 | MORTIN, L | 8302070370* | 50-244 |
| MILLS, L H | 8302030062* | 50-259 | MILLS, W A | 8302100467 | PR | MORLEY, J A | 8302240383 | WASTE T |
| MILLS, L H | 8302030064 | 50-328 | MILLS, W A | 8302100472 | PR | MORLEY, J A | 8302250001 | WASTE T |
| MILLS, L H | 8302030459 | 50-390 | MINECK, D L | 8302040362 | 50-331 | MORRILL, P J | 8302070339* | 50-275 |
| MILLS, L H | 8302030470 | 50-438 | MINECK, D L | 8302080245 | 50-331 | MORRILL, P J | 8302230388* | 50-275 |
| MILLS, L H | 8302030478 | 50-390 | MINECK, D L | 8302080328 | 50-331 | MORTENSEN, W P | 8302010471 | 50-361 |
| MILLS, L H | 8302030514 | 50-390 | MINECK, D L | 8302220129 | 50-331 | MORTENSEN, W P | 8302220107* | 50-142 |
| MILLS, L H | 8302030527 | 50-438 | MINECK, D L | 8302230280 | 50-331 | MORTENSEN, W P | 8302220113* | 50-142 |
| MILLS, L H | 8302030542 | 50-438 | MINECK, D L | 8302230452 | 50-331 | MORTGAT, C P | 8302170213 | NUREQ |
| MILLS, L H | 8302030551 | 50-566 | MINER, S | 8302080116 | 50-312 | MORTON, K | 8302010039* | CONTRAC |
| MILLS, L H | 8302030558 | 50-438 | MINER, S | 8302170282* | 50-155 | MORTON, K V | 8302020056* | CONTRAC |
| MILLS, L H | 8302030628* | 50-259 | MINER, S | 8302250133 | 50-312 | MORTON, K V | 8302020093* | CONTRAC |
| MILLS, L H | 8302040041 | 50-327 | MINDOCK, J R | 8302160343 | 50-341 | MORTON, K V | 8302020417* | CONTRAC |
| MILLS, L H | 8302040056 | 50-327 | MINDOCK, J R | 8302220309 | 50-341 | MORTON, K V | 8302030022* | CONTRAC |
| MILLS, L H | 8302070321 | 50-327 | MINDOCK, J R | 8302220309 | 50-341 | MORTON, K V | 8302100013* | CONTRAC |
| MILLS, L H | 8302070339 | 50-390 | MINDOCK, J R | 8302070211* | FOIA | MORTON, K V | 8302160037* | CONTRAC |
| MILLS, L H | 8302070380 | 50-518 | MINDOCK, R B | 8302220058* | FOIA | MORTON, K V | 8302170424* | CONTRAC |
| MILLS, L H | 8302070585 | 50-390 | MINDOCK, R B | 8302250366 | PR | MORTON, K V | 8302170429* | CONTRAC |
| MILLS, L H | 8302090002 | 50-259 | MIRAOLIA, F J | 8302100507 | 50-413 | MORTON, K V | 8302170489* | CONTRAC |
| MILLS, L H | 8302100330 | 50-259 | MIRAOLIA, F J | 8302220022 | PR | MORTON, K V | 8302170540* | CONTRAC |
| MILLS, L H | 8302100380 | PRM | MIR, F J | 8302280568 | 71-6574 | MORTON, K V | 8302170549* | CONTRAC |
| MILLS, L H | 8302140001 | 50-438 | MIRAK, A L | 8302010140* | 50-265 | MORTON, K V | 8302180519* | CONTRAC |
| MILLS, L H | 8302140018 | 50-438 | MITCHELL, D O | 8302010158* | 50-387 | MORTON, K V | 8302220025* | CONTRAC |
| MILLS, L H | 8302140038 | 50-390 | MITCHELL, D O | 8302010168* | 50-387 | MORTON, K V | 8302220042* | CONTRAC |
| MILLS, L H | 8302140054 | 50-390 | MITCHELL, D O | 8302030297* | 50-387 | MORTON, K V | 8302220074* | CONTRAC |
| MILLS, L H | 8302140085 | 50-390 | MITCHELL, D O | 8302030361* | 50-387 | MORTON, K V | 8302240185* | CONTRAC |
| MILLS, L H | 8302140059 | 50-390 | MITCHELL, D O | 8302180282* | 50-387 | MORTON, K V | 8302240275* | CONTRAC |
| MILLS, L H | 8302140068 | 50-390 | MITCHELL, D O | 8302180325* | 50-387 | MORTON, K V | 8302250079* | CONTRAC |
| MILLS, L H | 8302140071 | 50-390 | MITCHELL, D O | 8302220172* | 50-387 | MOSE, R M | 8302040021 | 71-6272 |
| MILLS, L H | 8302140076 | 50-259 | MITCHELL, D O | 8302220386* | 50-387 | MOGLAK, T | 8302030502* | 50-320 |
| MILLS, L H | 8302140094 | 50-439 | MITCHELL, D O | 8302220404* | 50-387 | MOGLAK, T | 8302230128* | 50-320 |
| MILLS, L H | 8302140129 | 50-390 | MITCHELL, D O | 8302230139* | 50-387 | MOGLAK, T | 8302230355* | 50-320 |
| MILLS, L H | 8302140154 | 50-390 | MITCHELL, D O | 8302230292* | 50-387 | MOHRY, W R | 8302080030 | 70-734 |
| MILLS, L H | 8302150051 | 50-390 | MITCHELL, D O | 8302230338* | 50-387 | MOHRY, W R | 8302220523 | XPORTL |
| MILLS, L H | 8302150065 | 50-259 | MITCHELL, D O | 8302230437* | 50-387 | MOHRY, W R | 8302230523 | 50-163 |
| MILLS, L H | 8302150160 | 50-390 | MITCHELL, D O | 8302230697* | 50-387 | MOHRY, W R | 8302250271 | 50-89 |
| MILLS, L H | 8302150192 | 50-438 | MITCHELL, D O | 8302030024* | 50-537 | MROCKA, E J | 8302030073 | 50-245 |
| MILLS, L H | 8302150271 | 50-390 | MITCHELL, H M | 8302070089* | 50-206 | MROCKA, E J | 8302030093 | 50-245 |
| MILLS, L H | 8302150305* | 50-327 | MITCHELL, H M | 8302070098* | FOIA | MROCKA, E J | 8302030262* | 50-245 |
| MILLS, L H | 8302150317* | 50-259 | MITCHELL, H M | 8302220177* | 50-294 | MROCKA, E J | 8302030308 | 50-336 |
| MILLS, L H | 8302150326* | 50-259 | MITTL, R L | 8302030595 | 50-354 | MROCKA, E J | 8302030308 | 50-336 |
| MILLS, L H | 8302150353* | 50-390 | MITTL, R L | 8302090411 | 50-354 | MROCKA, E J | 8302030332 | 50-336 |
| MILLS, L H | 8302150372 | 50-327 | MITTL, R L | 8302160291 | PR | MROCKA, E J | 8302030332 | 50-336 |
| MILLS, L H | 8302150376 | 50-438 | MITTL, R L | 8302230531 | 50-354 | MROCKA, E J | 8302030582 | 50-245 |
| MILLS, L H | 8302150444 | 50-438 | MIZUNO, O S | 8302080053 | 50-445 | MROCKA, E J | 8302030582 | 50-245 |
| MILLS, L H | 8302150473 | 50-438 | MIZUNO, O S | 8302150476 | 50-445 | MROCKA, E J | 8302100444 | 50-245 |
| MILLS, L H | 8302150484* | 50-438 | MIZUNO, O S | 8302280398 | 50-445 | MROCKA, E J | 8302100444 | 50-245 |
| MILLS, L H | 8302150554 | 50-327 | MIZUNO, O S | 8302280403* | 50-445 | MROCKA, E J | 8302230385 | 50-245 |
| MILLS, L H | 8302150572 | 50-438 | MIZUNO, O S | 8302280407* | 50-445 | MROCKA, E J | 8302230385 | 50-245 |
| MILLS, L H | 8302150583 | 50-438 | ND, T | 8302250071 | NUREQ | MROCKA, E J | 8302280411 | 50-336 |
| MILLS, L H | 8302150610 | 50-259 | NODEEN, D J | 8302010403* | 50-344 | MROCKA, E J | 8302280411 | 50-336 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|------------------|------------------|------------------|----------------|------------------|------------------|----------------|------------------|------------------|
| MUELLER, T | 8302010022 | 40-8714 | NICKELL, R E | 8302020062 | TOPREP | NORRELIUS, C E | 8302280468* | 50-373 Q |
| MULCAHEY, E | 8302230299* | 50-333 S | NICKLES, D | 8302100386* | PR | NORRELIUS, C E | 8302280491 | 50-346 Q |
| MULLAUER, J R | 8302150126 | 40-8787 | NIELSEN, L A | 8302230150 | TOPREP | NORRELIUS, C E | 8302280498* | 50-346 Q |
| MULLIKIN, R P | 8302070486* | 50-382 Q | NIELSEN, L A | 8302230155 | TOPREP | NORMAN, D E | 8302090353* | QA979 |
| MUMAH, I | 8302170378 | 50-341 H | NILGON, R | 8302100464 | PR | NORRHOLM, L | 8302030581* | 50-29 Q |
| MUNRO, J J | 8302070284 | 71-9107 | NILSON, R | 8302140206 | PR | NORRHOLM, L J | 8302030525* | 50-318 Q |
| MUNTZING, L M | 8302020385* | FOIA | NIMITZ, R L | 8302010322* | 50-322 Q | NORRHOLM, L J | 8302280446* | 50-367 Q |
| MUNTZING, L M | 8302140125 | PR | NIMITZ, R L | 8302100437* | 50-387 Q | NORRELIUS, C E | 8302170070* | 50-261 R |
| MURALI DHARAN, R | 8302040521 | MUREG | NIX, H | 8302020346* | 50-321 F | NORRIS, J A | 8302080386 | 50-295 P |
| MURDOCK, R J | 8302010154* | 50-219 S | NIX, H C | 8302010393 | 50-321 S | NORRIS, J L | 8302020056* | CONTRACT |
| MURPHY, C E | 8302080042* | 50-315 F | NIX, H C | 8302010428 | 50-366 S | NORRY, P O | 8211040458* | FOIA |
| MURPHY, D E | 8302010227* | 50-299 S | NIX, H C | 8302020342* | 50-321 F | NORRY, P O | 8302080346 | ORG |
| MURPHY, J | 8302250425* | 50-247 Q | NIX, H C | 8302030288 | 50-321 S | NORRY, P O | 8302100459 | ORG |
| MURPHY, J | 8302250425* | 50-247 Q | NIX, H C | 8302030375 | 50-366 S | NORRY, P O | 8302100466 | ORG |
| MURPHY, L O | 8302080120 | 40-8027 | NIX, H C | 8302030449 | 50-366 S | NORRY, P O | 8302180335* | FOIA |
| MURPHY, M E | 8302070391* | 50-313 Q | NIX, H C | 8302030472 | 50-366 S | NORTON, J F | 8302280489* | 50-454 Q |
| MURPHY, M E | 8302070431* | 50-313 Q | NIX, H C | 8302030515 | 50-366 S | NORWITZ, P | 8302040521 | MUREG |
| MURPHY, M E | 8302230478* | 50-267 Q | NIX, H C | 8302070395 | 50-366 S | NOVAK, T M | 8302010056 | 50-413 E |
| MURPHY, W P | 8302160240 | 50-271 R | NIX, H C | 8302140027 | 50-366 S | NOVAK, T M | 8302020115 | 50-528 A |
| MURRAY, B | 8302070450* | State Prog | NIX, H C | 8302140028 | 50-366 S | NOVAK, T M | 8302020490 | 50-328 A |
| MURRAY, T D | 8302030214* | 50-346 F | NIX, H C | 8302140046 | 50-321 S | NOVAK, T M | 8302030090 | 50-382 A |
| MURRAY, T D | 8302070633* | 50-346 F | NIX, H C | 8302140103 | 50-366 S | NOVAK, T M | 8302030599 | 50-438 A |
| MURRAY, T D | 8302080136 | 50-346 S | NIX, H C | 8302140160 | 50-366 S | NOVAK, T M | 8302080113 | 50-327 A |
| MURRAY, T D | 8302150390 | 50-346 S | NIX, H C | 8302140169 | 50-321 S | NOVAK, T M | 8302100512 | 50-445 A |
| MURRAY, T D | 8302150393* | 50-346 S | NIX, H C | 8302150020 | 50-321 S | NOVAK, T M | 8302250023 | 50-329 Q |
| MURRAY, T D | 8302230510 | 50-346 S | NIX, H C | 8302150073 | 50-366 S | NOVAK, T M | 8302250134 | 50-358 A |
| MURRAY, T D | 8302230539 | 50-346 S | NIX, H C | 8302150091 | 50-366 S | NOVAK, T M | 8302250145 | 50-482 A |
| MURRAY, T D | 8302280419 | 50-346 S | NIX, H C | 8302150103 | 50-366 S | NOVAK, T M | 8302250486 | 50-389 A |
| MURRAY, T D | 8302280433 | 50-346 S | NIX, H C | 8302150121 | 50-366 S | NOVINSKI, D M | 8302100326* | PR |
| MUSELER, W J | 8302230536 | 50-322 T | NIX, H C | 8302150133 | 50-366 S | NUSSBAUM, S | 8302100320* | PR |
| MUSOLF, D | 8302030122 | 71-6346 | NIX, H C | 8302150182 | 50-321 S | NUSSBAUM, S | 8302100438* | PR |
| MUSOLF, D | 8302040513 | 50-263 P | NIX, H C | 8302150190 | 50-321 S | NUSSBAUM, S | 8302010599* | 50-335 P |
| MUSOLF, D | 8302070415 | 50-282 P | NIX, H C | 8302150201 | 50-321 S | NUSSBAUM, S | 8302010605* | 50-335 P |
| MUSOLF, D | 8302100439 | PR | NIX, H C | 8302150203 | 50-366 S | NYRIEL, B | 8302280536* | 50-295 S |
| MUSOLF, D | 8302150369 | 50-263 P | NIX, H C | 8302150241 | 50-366 S | O'BRIEN, J | 8302230271* | 50-312 Q |
| MUSOLF, D | 8302150491 | 50-263 P | NIX, H C | 8302150287 | 50-321 S | O'CONNOR, J M | 8302180428* | 50-443 Q |
| MUSOLF, D | 8302150491 | 50-263 P | NIX, H C | 8302180397 | 50-366 S | O'CONNOR, P W | 8302250075 | 50-346 A |
| MUSOLF, D | 8302150502 | 50-263 F | NIX, H C | 8302150481 | 50-366 S | O'CONNOR, W | 8302280437* | 50-346 S |
| MUSOLF, D | 8302180505 | 50-263 P | NIX, H C | 8302150506 | 50-366 S | O'DONNELL, D M | 8302030660 | 71-9151 |
| MUSOLF, D | 8302180139 | 50-263 P | NIX, H C | 8302150539 | 50-366 S | O'NEILL, B | 8302030428* | 50-277 Q |
| MUSOLF, D | 8302180143* | 50-263 P | NIX, H C | 8302150672 | 50-366 S | O'NEILL, B | 8302030502* | 50-320 Q |
| MUSOLF, D | 8302240294 | 50-263 P | NIX, H C | 8302160232 | 50-321 R | O'NEILL, B | 8302230128* | 50-320 Q |
| MUSOLF, D H | 8302080144 | 50-282 P | NIX, H C | 8302160243 | 50-321 R | O'NEILL, B | 8302250335* | 50-320 Q |
| MYERS, D O | 8302150345* | 50-324 Q | NIX, H C | 8302230210 | 50-366 S | O'NEILL, J | 8302140157 | 50-155 Q |
| MYERS, D O | 8302030049* | 50-312 F | NIX, H C | 8302230223 | 50-321 S | O'NEILL, J | 8302140161* | 50-155 Q |
| MYRLOT, C E | 8302240280 | 50-275 P | NIX, H C | 8302230231 | 50-366 S | O'NEILL, J | 8302280427* | 50-346 S |
| NADEL, M | 8302040270 | 50-483 J | NIX, H C | 8302230300 | 50-321 S | O'NEILL, J H | 8302230417 | 50-400 Q |
| NADAI, Y | 8302020306 | 50-219 F | NIX, H C | 8302230485 | 50-321 S | O'NEILL, J H | 8302230417 | 50-400 Q |
| NAIDU, K R | 8302150367* | 50-440 Q | NIX, H C | 8302230590 | 50-366 S | O'REILLY, J P | 8302020340* | 50-359 P |
| NAIDU, K R | 8302180065* | 50-373 Q | NIX, H C | 8302230700 | 50-366 S | O'REILLY, J P | 8302100062* | FOIA |
| NAPUDA, Q | 8302100436* | 50-333 Q | NIX, H C | 8302230702 | 50-366 S | O'REILLY, J P | 8302150028 | 50-261 Q |
| NARDACCI, O A | 8302100117* | 50-320 R | NIX, H C | 8302280131 | 50-366 S | O'REILLY, J P | 8302150477 | 50-324 Q |
| NARDI, A J | 8302250365 | PR | NIX, H C | 8302280146 | 50-366 S | O'REILLY, J P | 8302150520* | 50-324 Q |
| NARDOCI, P B | 8302140124* | 50-369 S | NIX, H C | 8302280207 | 50-321 S | O'REILLY, J P | 8302150523 | 50-338 Q |
| NARDOCI, P B | 8302230603* | 50-369 S | NIX, H C | 8302280272 | 50-321 S | O'REILLY, J P | 8302150608 | 50-269 Q |
| NARDOCI, P B | 8302280089* | 50-369 S | NIX, H C | 8302280343 | 50-321 S | O'TOOLE, J D | 8302010114 | 50-247 S |
| NARDOSKY, J J | 8302170438* | MUREG | NIXON, W A | 8302230216 | 70-143 | O'TOOLE, J D | 8302010446 | 50-247 S |
| NARROH, L | 8302250273* | 50-352 Q | NOONAN, V S | 8212070376* | 50-322 A | O'TOOLE, J D | 8302040020* | 50-3 F |
| NASH, A D | 8302040472 | MUREG | NOONAN, V S | 8302030247* | 50-322 T | O'TOOLE, J D | 8302070216 | 50-3 F |
| NASH, B. | 8302040191* | 50-289 F | NORDEHAUG, L R | 8302070078* | 50-206 F | O'TOOLE, J D | 8302100230 | 50-247 P |
| NAUMANN, H R | 8302230194* | QA979 | NORDEHAUG, L R | 8302070308 | XPORTLIC | O'TOOLE, J D | 8302100307 | 50-247 P |
| NAUMANN, H R | 8302230204* | QA979 | NORDEHAUG, L R | 8302070311* | XPORTLIC | O'TOOLE, J D | 8302150268 | 50-247 S |
| NEIGHBORS, J D | 8302170270* | 50-155 P | NORDEHAUG, L R | 8302190002 | 50-206 Q | O'TOOLE, J D | 8302150341 | 50-247 P |
| NETSLER, J H | 8302040035* | 50-483 Q | NORDEHAUG, L R | 8302150004 | 50-275 Q | O'TOOLE, J D | 8302150349 | 50-247 P |
| NELLIS, C A | 8302150657* | 50-373 F | NORDEHAUG, L R | 8302150690 | 50-228 Q | O'TOOLE, J D | 8302170316 | 50-3 P |
| NELLIS, C A | 8302180156* | 50-10 F | NORDEHAUG, L R | 8302220098* | 50-142 Q | O'TOOLE, J D | 8302230002 | 50-247 P |
| NELSON, C C | 8302220476* | 50-155 P | NORDEHAUG, L R | 8302220107* | 50-142 Q | O'TOOLE, J D | 8302230434 | 50-247 R |
| NELSON, O | 8302070311* | XPORTLIC | NORDEHAUG, L R | 8302220113* | 50-142 Q | O'TOOLE, J D | 8302230468 | 50-247 S |
| NIN, M A | 8302080385* | 50-289 F | NORDEHAUG, L R | 8302220122* | 50-142 Q | O'TOOLE, J D | 8302230498* | 50-247 Q |
| NIN, M A | 8302090022* | 50-289 F | NORDEHAUG, L R | 8302220124* | 50-142 Q | O'TOOLE, J D | 8302230659* | 50-247 Q |
| NIN, R L | 8302040331* | 50-305 Q | NORDEHAUG, L R | 8302220130* | 50-142 Q | O'TOOLE, J D | 8302250321 | PR |
| NIN, R L | 8302180420* | 50-305 Q | NORDEHAUG, L R | 8302220135* | 50-142 Q | O'TOOLE, J D | 8302280179 | 50-247 Q |
| NIN, T L | 8302100454 | PRH | NORDEHAUG, L R | 8302280421 | 50-133 Q | O'TOOLE, K J | 8302180260 | 50-289 S |
| NI, V | 8302020468 | 50-369 A | NORRELIUS, C | 8302040080 | 50-346 Q | OATES, J H | 8302020311* | 50-219 P |
| NI, V | 8302160219 | 50-389 A | NORRELIUS, C E | 8302010456 | 50-409 Q | OBORG, C R | 8302170221 | 50-498 Q |
| NI, V | 8302240127 | 50-389 F | NORRELIUS, C E | 8302040294 | 50-10 Q | OBLIGADO, A | 8302170326* | 50-409 P |
| NI, V | 8302250111 | 50-389 A | NORRELIUS, C E | 8302040389* | 50-440 Q | OBEGARDEN, R H | 8302170504 | 71-6698 |
| NI, S P | 8302250151 | MUREG | NORRELIUS, C E | 8302080274 | 50-243 Q | OESTMANN, M J | 8302040158* | 50-341 Q |
| NI, S P | 8302160212* | 50-454 T | NORRELIUS, C E | 8302150363 | 50-440 Q | OESTMANN, M J | 8302040388* | 50-440 Q |
| NI, K A | 8302080024 | 50-377 H | NORRELIUS, C E | 8302150503 | 50-249 Q | OESTMANN, M J | 8302150450* | 50-295 Q |
| NI, S | 8302160037* | CONTRACT | NORRELIUS, C E | 8302180065* | 50-373 Q | OFFORD, J C | 8302280292* | CONTRACT |
| NI, S | 8302030429* | 50-289 Q | NORRELIUS, C E | 8302180365 | 50-454 Q | OGLE, K M | 8302240044 | 40-8663 |
| NI, S | 8302070430* | State Prog | NORRELIUS, C E | 8302180424 | 50-440 Q | OLESH, B | 8302020390 | FOIA |
| NI, S | 8302130450* | 50-295 Q | NORRELIUS, C E | 8302180458 | 50-454 Q | OLLER, R E | 8302160315* | QA979 |
| NI, S | 8302160488* | 50-528 H | NORRELIUS, C E | 8302250306 | 50-315 Q | OLLIKKALA, H | 8302150758 | REG |

PERSONAL AUTHOR INDEX

47

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|-----------------|------------------|------------------|
| OLSEN, A F | 8302080399 | 70-27 | PARIS, O H | 83022230393 | 50-247 O | PELLIZZA, H S | 8302030031 | 40-8786 |
| OLSEN, C R | 8302040010 | 71-491 | PARK, W C | 8302240277* | FOIA | PELLIZZA, H S | 8302100397 | PR |
| OLSEN, C R | 8302080084 | 71-491 | PARK, W C | 8302240293* | FOIA | PELLIZZA, H S | 8302160411 | 40-8786 |
| OLSHAN, L R | 8302040402 | 50-454 Q | PARKER, L B | 8302090379* | QA999 | PELLE, P R | 8302180213* | 50-440 |
| OLSHAN, L R | 8302100100 | 50-454 Q | PARKER, M E | 8302150334* | 50-155 Q | PELLETIER, J P | 8302010192 | 50-271 |
| OLSHAN, L R | 8302100162 | 50-454 A | PARKINSON, T F | 8302150438* | 50-124 Q | PELLETIER, J P | 8302010199* | 50-271 |
| OLSHINSKI, J A | 8302150037* | 70-143 | PARKS, B M | 8302140035* | 50-335 S | PELLETIER, J P | 8302100270 | 50-271 |
| OLSON, O L | 8302020375 | WASTE MGT | PARKS, B M | 8302140119* | 50-335 S | PELLETIER, J P | 8302010297* | 50-271 |
| OPP, P F | 8302100377* | PR | PARKYN, J | 8302100464 | PR | PELLETIER, J P | 8302010312 | 50-271 |
| OPP, P F | 8302100437* | PR | PARKYN, J D | 8302030604 | 71-9094 | PELLETIER, J P | 8302010318* | 50-271 |
| OPREA, G W | 8302010358 | 50-498 Q | PARR, O D | 8302170114* | 50-155 P | PELLETIER, J P | 8302230593 | 50-271 |
| OPREA, G W | 8302030384 | 50-498 S | PARRISH, R A | 8302090095 | 50-358 Q | PELLETIER, J P | 8302230606* | 50-271 |
| OPREA, G W | 8302070366* | 50-498 Q | PARSONS, C | 8302100419 | PRH | PELLETIER, J P | 8302230382 | 50-271 |
| OPREA, G W | 8302070516 | 50-498 A | PARSONS, R H | 8302010272 | 50-400 S | PELLETIER, J P | 8302230387* | 50-271 |
| OPREA, G W | 8302070607 | 50-498 S | PARSONS, R H | 8302010361 | 50-400 S | PELOQUIN, R A | 8302230053 | NUREG |
| ORDERS, W | 8302150676* | 50-369 Q | PARSONS, R M | 8302010580 | 50-400 S | PENNELL, W E | 8302230351* | 50-537 |
| ORNSTEIN, H L | 8302280258* | 50-289 Q | PARSONS, R M | 8302010590 | 50-400 B | PENNINGTON, T W | 8302010277 | PR |
| OSMAN, R R | 8302070504* | CONTRACT | PARSONS, R M | 8302030304 | 50-400 B | PENNINGTON, T W | 8302100450 | PR |
| OTTINGER, R L | 8302020283 | 50-247 U | PARSONS, R M | 8302150177 | 50-400 B | PENTZ, D L | 8302240375* | CONTRACT |
| OTTINGER, R L | 8302170086* | COMMISSION | PARSONS, R M | 8302170248 | 50-400 B | PERCH, R L | 8302150734 | 50-387 |
| PADOVAN, K L | 8302170123* | 50-155 P | PARSONS, R M | 8302280173 | 50-400 B | PERCH, R L | 8302160121 | 50-387 |
| PAGE, M | 8302040488 | CONTRACT | PASCIAK, W J | 8302020501 | NUREG | PERCH, R L | 8302010019 | 50-387 |
| PAGE, M | 8302080060 | CONTRACT | PASTVA, M J | 8301170414* | 50-324 B | PERCH, R L | 8302250070 | 50-387 |
| PAGE, M | 8302080067 | CONTRACT | PASTVA, M J | 8302010083* | 50-324 S | PERLIS, R Q | 8302080014 | 50-443 |
| PAGE, M | 8302100250 | CONTRACT | PASTVA, M J | 8302010092* | 50-324 S | PERLIS, R Q | 8302180267 | 50-483 |
| PAGE, M | 8302170390 | CONTRACT | PASTVA, M J | 8302010240* | 50-325 B | PERLIS, R Q | 8302220033 | 50-498 |
| PAGE, R Q | 8302030039 | 70-2949 | PASTVA, M J | 8302010277* | 50-324 S | PETEMAN, J | 8302040127 | CONTRACT |
| PAGE, R Q | 8302030043* | 70-2949 | PASTVA, M J | 8302010287* | 50-324 S | PETEMAN, J | 8302090024 | CONTRACT |
| PAGE, R Q | 8302080471 | 70-1113 | PASTVA, M J | 8302010367* | 50-325 S | PETEMAN, J | 8302180512 | CONTRACT |
| PAGE, R Q | 8302080474* | 70-1113 | PASTVA, M J | 8302010375* | 50-324 B | PETEMAN, J | 8302180513 | CONTRACT |
| PAGE, R Q | 8302220070 | 70-33 | PASTVA, M J | 8302010457* | 50-324 B | PERNY, C D | 8302150700* | 50-302 |
| PAGE, R Q | 8302220075 | 70-1113 | PASTVA, M J | 8302010573* | 50-324 B | PERROW, C | 8302030184 | 50-247 |
| PAGE, R Q | 8302220482 | 70-371 | PASTVA, M J | 8302010619* | 50-325 B | PERROW, C | 8302030184 | 50-247 |
| PAGE, R Q | 8302230055 | 70-2946 | PASTVA, M J | 8302010634* | 50-324 B | PERROW, C | 8302030184 | 50-247 |
| PAGE, R Q | 8302230061* | 70-2946 | PASTVA, M J | 8302030420* | 50-324 B | PERRY, W | 8302100440 | PRH |
| PAGLIARD, J A | 8302040303* | 50-305 Q | PASTVA, M J | 8302030422* | 50-324 B | PEBCHER, J M | 8302040360* | 50-263 |
| PAGLIARD, J A | 8302250283* | 50-255 Q | PASTVA, M J | 8302030510* | 50-324 B | PETERS, J | 8302040335* | 50-373 |
| PAINTER, B | 8302190050 | 50-280 J | PASTVA, M J | 8302140049* | 50-324 B | PETERS, R P | 8302070493* | 50-528 |
| PAJOWSKI, J E | 8302040037* | 50-10 F | PASTVA, M J | 8302140142* | 50-325 B | PETERSON, D A | 8302160232* | 50-255 |
| PAJOWSKI, J E | 8302040048* | 50-10 F | PASTVA, M J | 8302150026* | 50-324 B | PETRICK, N A | 8302040245 | 50-482 |
| PALLADINO, N J | 8302170081 | COMMISSION | PASTVA, M J | 8302170084* | 50-324 S | PETRICK, N A | 8302040363 | 50-482 |
| PALLADINO, N J | 8302220446 | COMMISSION | PASTVA, M J | 8302170101* | 50-324 S | PETRICK, N A | 8302040374 | 50-482 |
| PALLADINO, N J | 8302220458 | COMMISSION | PASTVA, M J | 8302170183* | 50-325 S | PETRICK, N A | 8302090300 | 50-482 |
| PALLADINO, N J | 8302220463* | COMMISSION | PASTVA, M J | 8302170184* | 50-324 S | PETRONE, C | 8302030581* | 50-29 |
| PALLADINO, N J | 8302220466 | COMMISSION | PASTVA, M J | 8302230169* | 50-324 S | PETRONE, C | 8302280446* | 50-387 |
| PALLADINO, N J | 8302220469* | COMMISSION | PASTVA, M J | 8302240251* | 50-325 S | PETRONE, C D | 8302180171* | 50-322 |
| PALLADINO, N J | 8302230076 | 50-324 U | PASTVA, M J | 8302280074* | 50-325 S | PETTENGILL, H J | 8302040355* | 40-8452 |
| PALLADINO, N J | 8302240233 | COMMISSION | PASTVA, M J | 8302280257* | 50-325 S | PETTENGILL, H J | 8302090256 | 40-8102 |
| PALLADINO, N J | 8302240402 | COMMISSION | PASTVA, M J | 8302280507* | 50-324 S | PETTENGILL, H J | 8302140191* | 40-299 |
| PALMER, R A | 8302040202* | 50-316 S | PATE, R J | 8302230404* | 50-361 Q | PETTENGILL, H J | 8302140203* | 40-8102 |
| PALMER, R A | 8302080294* | 50-316 B | PATBALIDES, N M | 8302170168* | TOPREP | PETTENGILL, H J | 8302140208 | 40-2257 |
| PALMER, R A | 8302080298* | 50-316 B | PATTEN, A J | 8302170174* | TOPREP | PETTENGILL, H J | 8302160506* | 40-299 |
| PALMER, R A | 8302080331* | 50-316 B | PATTEN, A J | 8302170174* | TOPREP | PETTENGILL, H J | 8302160515 | 40-6622 |
| PALMER, R A | 8302160337* | 50-315 S | PATTERSON, J D | 8302100305 | PRH | PETTENGILL, H J | 8302160518 | 40-3453 |
| PALMER, R A | 8302180238* | 50-316 S | PATTERSON, J P | 8302040212* | 50-263 Q | PETTENGILL, H J | 8302170303 | 40-8102 |
| PALMER, R A | 8302180285* | 50-316 B | PATTERSON, W F | 8302080014 | 50-443 Q | PETTENGILL, H J | 8302180511* | 40-2257 |
| PALMER, R A | 8302230571* | 50-316 S | PATTERSON, W F | 8302170098 | 50-443 Q | PETTENGILL, H J | 8302220065 | 40-8084 |
| PALMER, R A | 8302280355* | 50-316 S | PATTERSON, W F | 8302180364 | 50-461 Q | PETTENGILL, H J | 8302220069 | 40-8084 |
| PALMER, R A | 8302280358* | 50-316 B | PATTERSON, W F | 8302220018 | 50-443 Q | PETTENGILL, H J | 8302220263 | 40-299 |
| PALMER, R A | 8302280389* | 50-315 S | PATTERSON, W F | 8302280036 | 50-443 Q | PETTENGILL, H J | 8302220487 | 40-8584 |
| PALMER, R A | 8302280416* | 50-315 S | PATTISON, R S | 8302250322 | PR | PETTY, J C | 8302030434* | 50-269 |
| PALMER, R A | 8302280541* | 50-316 S | PAUL, R A | 8302280438* | 50-237 Q | PETTY, J C | 8302030473* | 50-269 |
| PALUMBO, R | 8302090249 | 50-440 Q | PAULSON, N | 8302070429 | 50-206 P | PETTY, J C | 8302280418* | 50-269 |
| PANETTA, L E | 8302230088* | COMMISSION | PAULSON, N | 8302180233 | 50-206 P | PEVCAR, R C | 8302100256 | PRH |
| PANO, F | 8302070311* | XPORTLIC | PAULSON, W A | 8302010652 | 50-206 P | PEVENSTEIN, J E | 8302020123* | CONTRACT |
| PANNO, S V | 8302240360 | RES | PAULSON, W A | 8302070612 | 50-206 P | PEVEY, L E | 8302010633* | 70-398 |
| PAPAY, L T | 8302150120* | 50-206 Q | PAULSON, W A | 8302070615 | 50-206 P | PEVEY, L E | 8302040008 | 71-6550 |
| PAPAZOGLOU, I A | 8212290219* | 50-352 Q | PAULSON, W A | 8302230400 | 50-206 P | PEVEY, L E | 8302090534 | 70-398 |
| PAPERIELLO, C J | 8302010600 | 27-39 | PAVIS, G S | 8302070390* | 50-317 B | PEW, R | 8302040521 | NUREG |
| PAPERIELLO, C J | 8302040212* | 50-263 Q | PAVIS, G S | 8302070606* | 50-318 B | PFEFFERLEN, H C | 8302150301 | TOPREP |
| PAPERIELLO, C J | 8302040280 | 50-373 Q | PAVIS, G S | 8302230701* | 50-317 B | PFEFFERLEN, H C | 8302230680 | TOPREP |
| PAPERIELLO, C J | 8302040287 | 50-305 Q | PAVIS, G S | 8302230722* | 50-318 B | PHILLIPS, O A | 8302040405* | 50-440 |
| PAPERIELLO, C J | 8302040406 | 50-305 Q | PAVIS, G S | 8302250193* | 50-318 B | PHILLIPS, O A | 8302040408* | 50-440 |
| PAPERIELLO, C J | 8302190010 | 50-315 Q | PAXTON, H C | 8302070506 | 50-266 Q | PHILLIP, O A | 8302040414* | 50-440 |
| PAPERIELLO, C J | 8302190015 | 50-358 Q | PAYNE, M T | 8302230568 | 50-400 Q | PHILLIP, O A | 8302040428* | 50-440 |
| PAPERIELLO, C J | 8302150647 | 50-373 F | PAYNE, M T | 8302230568 | 50-400 Q | PHILLIPS, H B | 8302030504* | QA999 |
| PAPERIELLO, C J | 8302230125 | 50-10 P | PAYNE, M T | 8302230568 | 50-400 Q | PHILLIPS, H B | 8302070547 | 50-458 |
| PAPERIELLO, C J | 8302250278 | 50-255 Q | PAYNE, M T | 8302230568 | 50-400 Q | PHILLIPS, H B | 8302150239 | QA999 |
| PAPERIELLO, C J | 8302250349 | 50-237 F | PAYNE, M T | 8302230568 | 50-400 Q | PHILLIPS, H B | 8302240083* | 50-454 |
| PAPERIELLO, C J | 8302250358 | 50-10 Q | PAYNE, M T | 8302230579* | 50-400 Q | PHILLIPS, H B | 8302250364* | 50-10 |
| PAPERIELLO, C J | 8302280371 | 50-255 Q | PAYNE, M T | 8302230579* | 50-400 Q | PICCONI, R O | 8302030165 | 50-247 |
| PAPERIELLO, C J | 8302280426 | 50-237 Q | PEDEDO, J | 8302070006 | FOIA | PICCONI, R O | 8302030165 | 50-247 |
| PAPERIELLO, C J | 8302280430* | 50-237 Q | PEEBLES, T A | 8302280503* | 50-346 Q | PICULO, P L | 8302240011 | RES |
| PAPERIELLO, C J | 8302280521 | 70-212 | PEERY, W N | 8302150537* | 50-324 Q | PICULO, P L | 8302240359 | 27-47 |
| PARIS, O H | 8302090227 | 50-142 Q | PELLIZZA, H S | 8302030027 | 40-8786 | PICKUS, M | 8302100324* | PR |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---------------|------------------|------------------|---------------|------------------|------------------|---------------|------------------|------------------|
| PICOTT, D R | 8302020335* | 50-361 Q | POTAPQVS, U | 8302160325 | 0A999 | RAUSCH, T J | 8302250212 | 50-237 P |
| PICOTT, D R | 8302020335* | 50-361 Q | POTAPQVS, U | 8302160333 | 0A999 | RAUSCH, T J | 8302250273 | 50-254 Q |
| PILANT, J H | 8302010676 | 50-298 Q | POTAPQVS, U | 8302220329 | 0A999 | RAWSON, R J | 8302100258 | 50-322 Q |
| PILANT, J H | 8302080408* | 50-298 F | POTAPQVS, U | 8302220323 | 0A999 | RAWSON, R J | 8302170092 | 50-322 Q |
| PILANT, J H | 8302180061* | 50-298 F | POTAPQVS, U | 8302230191 | 0A999 | RAWSON, R J | 8302170099* | 50-322 Q |
| PILANT, J H | 8302180362 | 50-298 V | POTAPQVS, U | 8302230199* | 0A999 | RAISON, R J | 8302240009 | 50-322 Q |
| PILANT, J H | 8302230310* | 50-298 Q | POTTER, T E | 8302170268* | 50-247 T | RAY, H B | 8302010138 | 50-361 S |
| PILANT, J H | 8302230724* | 50-298 Q | POTTER, T E | 8302170268* | 50-247 T | RAY, H B | 8302010150* | 50-361 S |
| PILANT, J H | 8302250370 | 50-298 P | POTTER, T E | 8302170280* | 50-247 T | RAY, H B | 8302010159 | 50-361 S |
| PILANT, J H | 8302280046 | 50-298 K | POTTER, T E | 8302170280* | 50-247 T | RAY, H B | 8302010169* | 50-361 S |
| PINZONE, C R | 8302080217 | 50-440 Q | PULK, R H | 8302140012* | 50-324 S | RAY, H B | 8302010280 | 50-361 S |
| PITILE, Q L | 8302180451* | 50-10 Q | PULK, R H | 8302170268* | 50-324 S | RAY, H B | 8302010285* | 50-361 S |
| PITILE, Q L | 8302180457* | 50-373 Q | POWER, E J | 8302220124* | 50-142 Q | RAY, H B | 8302010327 | 50-361 S |
| PISELLO, D H | 8302030165 | 50-247 T | POYSER, R H | 8302090578 | 40-2259 | RAY, H B | 8302010346* | 50-361 S |
| PISELLO, D H | 8302030165 | 50-247 T | PRATT, W T | 8302030546* | 50-247 T | RAY, H B | 8302010394 | 50-361 S |
| PLANKI, F J | 8302220153* | 70-1100 | PRESNELL, O H | 8302010337* | 50-287 P | RAY, H B | 8302010405* | 50-361 S |
| PLANT, R J | 8302020256 | 50-461 Q | PRESNELL, O H | 8302150622* | 50-267 P | RAY, H B | 8302010412* | 50-361 S |
| PLANT, R L | 8302080246 | 50-461 Q | PRICHARD, R P | 8302080048 | 71-7855 | RAY, H B | 8302010450 | 50-361 S |
| PLAYTON, S J | 8302090597* | 40-8745 | PROXHIRE, W | 8302100325* | PR | RAY, H B | 8302010668 | 50-361 S |
| PLENIEWICZ, R | 8302220310* | 50-454 T | PROXHIRE, W | 8302100372* | PR | RAY, H B | 8302010674* | 50-361 S |
| PLIML, Q | 8302030139* | 50-295 F | PROXHIRE, H | 8302100378 | PR | RAY, H B | 8302010678 | 50-362 S |
| PLIML, Q | 8302030236* | 50-295 F | PROXHIRE, H | 8302100394 | PR | RAY, H B | 8302010681* | 50-362 S |
| PLIML, Q | 8302030648* | 50-295 F | PUGLIA, A | 8302090478* | 50-358 Q | RAY, H B | 8302150117 | 50-362 S |
| PLIML, Q | 8302180520* | 50-295 F | PUGLIA, A | 8302090527* | 50-358 Q | RAY, H B | 8302150155* | 50-362 S |
| PLIML, Q | 8302030511* | 50-334 Q | PULLANI, S | 8302280446* | 50-387 Q | RAY, H B | 8302150217 | 50-362 S |
| PLISKI, T J | 8302230364* | 50-10 Q | PULLANI, S V | 8302030325* | 50-310 Q | RAY, H B | 8302150229* | 50-362 S |
| PLUMLEE, O L | 8302030475* | 50-267 Q | PURVIS, J | 8302250439 | 27-47 | RAY, H B | 8302150245 | 50-361 S |
| PLUMLEE, O L | 8302230693* | 50-267 Q | PURVIS, J | 8302080183* | 50-344 F | RAY, H B | 8302150276 | 50-361 S |
| PLUMLEE, K | 8302010384* | 50-317 Q | PYRON, J H | 8302020311* | 50-219 P | RAY, H B | 8302150281* | 50-361 S |
| POCHAL, W F | 8302020369 | XPORTLIC | QUALLB, R O | 8302100273 | NUREG | RAY, H B | 8302150285* | 50-361 S |
| POCHAL, W F | 8302250492 | XPORTLIC | QUAYLE, D | 8302250351 | PR | RAY, H B | 8302150322 | 50-361 S |
| POCHAL, B E | 8302280168 | 50-247 T | QUICK, D R | 8302150320* | 50-327 Q | RAY, H B | 8302150327* | 50-361 S |
| POCHAL, B E | 8302280168 | 50-247 T | QUICK, D R | 8302150365* | 50-390 Q | RAY, H B | 8302150433 | 50-361 S |
| PODLK, R J | 8302010715 | 50-3 P | QUICK, D R | 8302150482* | 50-327 Q | RAY, H B | 8302150447* | 50-361 S |
| POLLOCK, D | 8302020353 | 50-206 P | QUICK, D R | 8302150678* | 50-327 Q | RAY, H B | 8302150853 | 50-361 S |
| POLLOCK, M B | 8302220374 | 50-322 A | QUIG, C | 8302100456 | PRM | RAY, H B | 8302150555 | 50-361 S |
| POLLOCK, M B | 8302280501* | 50-322 Q | QUIG, R S | 8302040465* | CONTRACT | RAY, H B | 8302150564* | 50-361 S |
| PORTER, M R | 8302010863* | 50-296 S | QUIGLEY, T H | 8302010073 | 40-8743 | RAY, H B | 8302150566* | 50-361 S |
| PORTER, M R | 8302140021* | 50-296 S | QUIGLEY, T H | 8302240052 | 40-8743 | RAY, H B | 8302150571 | 50-361 S |
| PORTER, P | 8302160366 | 50-247 G | QUINN, M D | 8302150193* | 50-213 S | RAY, H B | 8302150577* | 50-361 S |
| POTAPQVS, U | 8302010455 | 0A999 | RAEFORD, J K | 8302070062* | 50-206 F | RAY, H B | 8302150580* | 50-361 S |
| POTAPQVS, U | 8302010509 | 0A999 | RAEFORD, J K | 8302070064* | 50-206 F | RAY, H B | 8302180231 | 50-361 S |
| POTAPQVS, U | 8302030337 | 0A999 | RAEFORD, J K | 8302070066* | 50-206 F | RAY, H B | 8302180234* | 50-361 S |
| POTAPQVS, U | 8302030377 | 0A999 | RAEFORD, J K | 8302070072* | 50-206 F | RAY, H B | 8302180237 | 50-361 S |
| POTAPQVS, U | 8302030413 | 0A999 | RAOAN, H B | 8302070156* | FOIA | RAY, H B | 8302180239* | 50-361 S |
| POTAPQVS, U | 8302030471 | 0A999 | RAGLIN, K | 8302010377* | 50-373 Q | RAY, H B | 8302250213 | 50-361 S |
| POTAPQVS, U | 8302030479 | 0A999 | RAHE, E P | 8302020327 | TOPREP | RAY, H B | 8302250223 | 50-361 S |
| POTAPQVS, U | 8302030480 | 0A999 | RAHE, E P | 8302030256 | PRQJ | RAY, H B | 8302250224* | 50-361 S |
| POTAPQVS, U | 8302030483 | 0A999 | RAHE, E P | 8302030339 | PRQJ | RAY, H B | 8302250226* | 50-361 S |
| POTAPQVS, U | 8302030509 | 0A999 | RAHE, E P | 8302090423 | TOPREP | RAYMOND, H | 8302030177* | 50-322 Q |
| POTAPQVS, U | 8302030538 | 0A999 | RAHE, E P | 8302090475 | TOPREP | RAYNOR, J W | 8302010337* | 50-317 S |
| POTAPQVS, U | 8302030548* | 0A999 | RAHE, E P | 8302100287 | PR | RAYNOR, J W | 8302010389* | 50-317 S |
| POTAPQVS, U | 8302070204 | P T21 | RAHE, E P | 8302100336* | PR | RAYNOR, J W | 8302070390* | 50-317 S |
| POTAPQVS, U | 8302070257 | 0A999 | RAHE, E P | 8302100339 | PR | RAYNOR, J W | 8302090377* | 50-310 S |
| POTAPQVS, U | 8302070263 | 0A999 | RAHE, E P | 8302220379 | TOPREP | RAYNOR, J W | 8302090399* | 50-317 S |
| POTAPQVS, U | 8302070286 | 0A999 | RAHE, E P | 8302240312 | TOPREP | REAB, D F | 8302230579* | 50-400 Q |
| POTAPQVS, U | 8302070294 | P T21 | RAHE, E P | 8302280546* | TOPREP | REAVIS, J A | 8302180319* | 50-369 R |
| POTAPQVS, U | 8302070302 | 0A999 | RAJAN, J R | 8302170131* | 50-289 P | REAVIS, J A | 8302180377* | 50-249 R |
| POTAPQVS, U | 8302070320 | 0A999 | RAJAN, J R | 8302240064* | 50-454 T | REBELLO, J | 8302220003* | 50-390 A |
| POTAPQVS, U | 8302070476 | 0A999 | RAJAN, J R | 8302240070* | 50-454 T | REBELLO, J E | 8302020155* | CONTRACT |
| POTAPQVS, U | 8302070588 | 0A999 | RAJAN, J R H | 8302250243* | 50-445 Q | REBELLO, J E | 8302020236* | CONTRACT |
| POTAPQVS, U | 8302070603 | P T21 | RAMBEY, C | 8302280466* | 50-155 Q | REBELLO, J E | 8302020245* | CONTRACT |
| POTAPQVS, U | 8302090327 | 0A999 | RANDALL, S | 8302070601 | 50-440 Q | REBELLO, J E | 8302020273* | CONTRACT |
| POTAPQVS, U | 8302090342 | 0A999 | RANDAZZA, J B | 8302070505 | 50-309 Q | REBELLO, J E | 8302090123* | 40-8027 |
| POTAPQVS, U | 8302090360 | 0A999 | RANDAZZA, J B | 8302070596* | 50-309 Q | REBELLO, J E | 8302090134* | CONTRACT |
| POTAPQVS, U | 8302090375 | 0A999 | RANDAZZA, J B | 8302230304 | 50-309 P | REBELLO, J E | 8302160110* | 50-507 P |
| POTAPQVS, U | 8302090387 | 0A999 | RANDAZZA, J B | 8302230430 | 50-309 P | REBELLO, J E | 8302170310* | 50-247 P |
| POTAPQVS, U | 8302090392 | 0A999 | RANDAZZA, J B | 8302180324 | 50-537 P | REBELLO, J E | 8302220125* | 50-206 P |
| POTAPQVS, U | 8302090398 | 0A999 | RANDOLPH, P D | 8302280151 | TOPREP | REBELLO, J E | 8302240075* | CONTRACT |
| POTAPQVS, U | 8302090409 | 0A999 | RANGANATH, S | 8302170170* | 50-260 P | REBELLO, J E | 8302240091* | CONTRACT |
| POTAPQVS, U | 8302090419 | 0A999 | RARIS, O H | 8302090234 | 50-247 Q | REDELONSKI, T | 8302230418* | 50-213 Q |
| POTAPQVS, U | 8302090425 | 0A999 | RASKIN, D B | 8302170305 | 50-413 Q | REDANO, R T | 8302230478* | 50-267 Q |
| POTAPQVS, U | 8302090442 | 0A999 | RASKIN, D B | 8302170305 | 50-413 Q | REED, C | 8302010629* | 50-275 Q |
| POTAPQVS, U | 8302090465 | 0A999 | RASKIN, D B | 8302170305 | 50-413 Q | REED, C | 8302080322* | 50-10 Q |
| POTAPQVS, U | 8302150310 | 0A999 | RAUSCH, T J | 8302100294 | 50-254 P | REED, C | 8302220320* | 10CFR |
| POTAPQVS, U | 8302150324 | 0A999 | RAUSCH, T J | 8302010429 | 50-237 P | REED, J | 8302030214* | 50-346 Q |
| POTAPQVS, U | 8302150333* | 0A999 | RAUSCH, T J | 8302070215 | 50-237 P | REED, J Q | 8302080243 | 50-483 Q |
| POTAPQVS, U | 8302150389 | 0A999 | RAUSCH, T J | 8302070274 | 50-237 P | REED, J Q | 8302160297 | 50-483 Q |
| POTAPQVS, U | 8302150417 | 0A999 | RAUSCH, T J | 8302080277 | 50-237 Q | REED, J Q | 8302230607 | 50-483 Q |
| POTAPQVS, U | 8302150464 | 0A999 | RAUSCH, T J | 8302080303 | 50-245 P | REEDY, R F | 8302090306 | 50-275 Q |
| POTAPQVS, U | 8302150519 | 0A999 | RAUSCH, T J | 8302100214 | 50-237 P | REEDY, R F | 8302090311 | 50-275 Q |
| POTAPQVS, U | 8302150525 | 0A999 | RAUSCH, T J | 8302100224 | 50-237 P | REEDY, R F | 8302140041 | 50-275 Q |
| POTAPQVS, U | 8302160157 | 0A999 | RAUSCH, T J | 8302170345 | 50-237 P | REEDY, R F | 8302240014 | 50-275 Q |
| POTAPQVS, U | 8302160290 | 0A999 | RAUSCH, T J | 8302180296 | 50-237 P | REEDY, R F | 8302100103 | 50-348 Q |
| POTAPQVS, U | 8302160309 | 0A999 | RAUSCH, T J | 8302230187 | 50-237 P | REEDY, R F | 8302010950* | 50-321 Q |

PERSONAL AUTHOR INDEX

477

| ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---------------------|---------------------|-----------------|---------------------|---------------------|-----------------|---------------------|---------------------|
| 1302080082* | 50-334 P | RITTER, S J | 8302180138* | 50-358 A | ROTELLA, T S | 8302140109* | 50-335 S |
| 1302020094 | COMMISSION | RITTER, S J | 8302180164* | FOIA | ROTH, J | 8302180371* | 70-124 |
| 1302020339* | FOIA | RITTER, S J | 8302180189* | 50-358 A | ROTHMAN, R | 8302160188* | 50-454 T |
| 1302080464 | COMMISSION | RITTER, S J | 8302180194* | 50-358 A | ROTHSCHILD, M U | 8302090443 | 50-445 G |
| 1302170383 | COMMISSION | RIVENBARK, O | 8302020482 | 50-321 P | ROTHSCHILD, M U | 8302230505 | 50-445 G |
| 1302180189* | FOIA | RIVENBARK, O W | 8302040282 | 50-321 P | ROTHSCHILD, M U | 8302240016 | 50-445 G |
| 1302220594 | COMMISSION | RIVENBARK, O W | 8302080384 | 50-321 P | ROTHSCHILD, M U | 8302280398 | 50-445 G |
| 1302170104* | 50-322 A | RIVENBARK, O W | 8302100036 | 50-321 P | ROTHSCHILD, M U | 8302280403* | 50-445 G |
| 1302170109* | 50-322 A | RIZZOLO, V N | 8302220043* | 50-142 G | ROTHSCHILD, M U | 8302280407* | 50-445 G |
| 1302170195* | 50-322 A | RIZZOLO, V N | 8302220067* | 70-223 | ROTHSCHILD, T | 8302080032 | FOIA |
| 1302170197* | 50-322 A | RIZZOLO, V N | 8302220080* | 50-142 G | ROULO, J L | 8302220321* | 50-454 T |
| 1302280474* | 50-373 G | RIZZOLO, V N | 8302220082* | 50-142 G | ROUSE, L C | 8302090189 | 70-364 |
| 1302030232 | 50-322 G | RIZZOLO, V N | 8302220086* | 50-142 G | ROUSE, L C | 8302090195* | 70-364 |
| 1302150445 | 50-277 G | RIZZOLO, V N | 8302220091* | 50-142 G | ROUSE, L C | 8302090200* | 70-364 |
| 1302090051 | 70-25 | RIZZOLO, V N | 8302220095* | 50-142 G | ROUSE, L C | 8302090205 | 50-259 X |
| 1302100233 | PR | ROBERTS, H W | 8302070266* | 0A999 | ROUSE, L C | 8302090213* | 50-259 X |
| 1302240159 | 50-266 I | ROBERTS, J P | 8302090176 | PROJ | ROUSE, L C | 8302090222* | 50-259 X |
| 1302040110* | 50-397 A | ROBERTS, J P | 8302170414 | PROJ | ROUSE, L C | 8302180088* | FOIA |
| 1302040128* | 50-397 A | ROBERTSON, H C | 8302240244* | 70-146 | ROUSE, L C | 8302220035 | 50-259 X |
| 1302010079 | 50-322 G | ROBINSON, D | 8302040100* | 50-315 S | ROWE, C | 8302010658* | 40-672 |
| 1302030241 | 50-322 T | ROBINSON, D | 8302150006* | 50-315 S | ROWE, C | 8302030428* | 50-277 G |
| 1302140152* | 50-322 G | ROBINSON, D | 8302160272* | 50-316 S | ROWE, D S | 8302080134* | CONTRACT |
| 1302170099* | 50-322 G | ROBINSON, D | 8302280362* | 50-316 S | ROWLAND, G B | 8302250391 | 50-264 P |
| 1302250068 | 50-458 G | ROBINSON, D | 8302280364* | 50-316 S | ROWSONE, F H | 8302280255* | 50-289 G |
| 1302280247 | 50-322 G | ROCCA, J | 8302180329 | 50-206 J | ROZAK, S | 8302150450* | 50-295 G |
| 1302280254* | 50-322 G | RUDEN, J F | 8302250416* | 50-247 G | RUBLE, P | 8302090035* | 50-358 G |
| 1302280260* | 50-322 G | RODGERS, W A | 8302170268* | 50-247 T | RUFF, A B | 8302150607* | 50-389 G |
| 1302170387* | 50-261 P | RODGERS, W A | 8302170268* | 50-247 T | RUITER, G H | 8302160380* | 50-305 R |
| 1302180033 | 50-261 P | RODRIGUEZ, R J | 8302170373 | 50-312 R | RUMPF, R | 8302170325* | 50-409 P |
| 1302220332* | 50-454 T | ROE, R | 8302030109* | 50-537 U | RUMPF, R E | 8302170321* | 50-409 P |
| 1302070096* | 50-272 G | ROGERS, A A | 8302010009* | CONTRACT | RUNKLE, J D | 8302230579* | 50-400 G |
| 1302070103* | 50-272 G | ROGERS, A E | 8302010434* | 50-237 P | RUSHMORE, J W | 8302070187 | 50-220 J |
| 1302070110* | 50-272 G | ROGERS, D | 8302150504 | 50-128 P | RUSHMORE, J W | 8302070190 | 50-220 J |
| 1302070123* | 50-272 G | ROGERS, H R | 8302030429* | 50-327 S | RUSSELL, L B | 8302090372 | 50-318 S |
| 1302070129* | 50-272 G | ROGERS, H R | 8302150536* | 50-327 S | RUSSELL, L B | 8302010163 | 50-318 S |
| 1302250264 | 50-322 G | ROGERS, H R | 8302230566* | 50-328 S | RUSSELL, L B | 8302010180 | 50-318 S |
| 1302250264 | 50-322 G | ROGERS, H R | 8302280155* | 50-327 S | RUSSELL, L B | 8302010198 | 50-317 S |
| 1302010381* | 50-282 G | ROGERS, H R | 8302280162* | 50-327 S | RUSSELL, L B | 8302010330 | 50-317 S |
| 1302040088* | 50-409 G | ROGERS, H R | 8302280200* | 50-327 S | RUSSELL, L B | 8302010341 | 50-318 S |
| 1302180420* | 50-305 G | ROGERS, H R | 8302280471* | 50-328 S | RUSSELL, L B | 8302010348 | 50-317 S |
| 1302280503* | 50-346 G | ROGERS, P | 8302070363* | 50-313 S | RUSSELL, L B | 8302010349 | 50-318 S |
| 1302020155* | CONTRACT | ROGERS, P | 8302170068* | 50-313 S | RUSSELL, L B | 8302010383 | 50-317 S |
| 1302070488 | 50-460 G | ROGERS, P | 8302170136* | 50-368 S | RUSSELL, L B | 8302010595 | 50-318 S |
| 1302070488 | 50-460 G | ROGERS, P | 8302170237* | 50-368 S | RUSSELL, L B | 8302010566 | 50-318 S |
| 1302070578 | 50-445 G | ROGERS, P | 8302170377* | 50-368 S | RUSSELL, L B | 8302070292* | 50-317 F |
| 1302070578 | 50-445 G | ROGERS, P | 8302230473* | 50-368 S | RUSSELL, L B | 8302070379 | 50-317 S |
| 1302090238 | 50-460 G | ROGERS, P | 8302280455* | 50-313 S | RUSSELL, L B | 8302070405 | 50-317 S |
| 1302090238 | 50-460 G | ROGERS, R F | 8302150659* | 50-321 G | RUSSELL, L B | 8302070411 | 50-317 S |
| 1302100238 | 50-445 G | ROGERS, W G | 8302280503* | 50-346 G | RUSSELL, L B | 8302070421 | 50-318 S |
| 1302100305 | PRM | ROGERS, W H | 8302020346* | 50-321 F | RUSSELL, L B | 8302070593 | 50-318 S |
| 1302100362 | PR | ROGGE, J F | 8302150488* | 50-321 G | RUSSELL, L B | 8302080440* | 50-317 F |
| 1302220350 | 50-460 G | ROHRBAUGH, R | 8302150748 | RES | RUSSELL, L B | 8302090180 | 50-318 S |
| 1302220350 | 50-460 G | ROHRER, M V | 8302170311* | 50-416 S | RUSSELL, L B | 8302090316 | 50-317 S |
| 1302240405* | COMMISSION | ROHRER, M V | 8302280243* | 50-416 S | RUSSELL, L B | 8302090395 | 50-317 S |
| 1302250248 | 50-460 G | ROLLINS, M V | 8302070015 | 71-6717 | RUSSELL, L B | 8302090420 | 50-318 S |
| 1302250248 | 50-460 G | ROMAN, T H | 8302140084* | 50-220 R | RUSSELL, L B | 8302180257 | 50-317 S |
| 1302010553* | 50-254 S | ROOD, H | 8302170552 | 50-361 P | RUSSELL, L B | 8302230222 | 50-318 S |
| 1302030591* | 50-286 G | ROOD, H | 8302170555 | 50-361 P | RUSSELL, L B | 8302230227 | 50-317 S |
| 1302250273* | 50-352 G | ROOD, H | 8302170558 | 50-361 P | RUSSELL, L B | 8302230303 | 50-317 S |
| 1302010276* | 50-237 S | ROOD, H | 8302170561 | 50-362 P | RUSSELL, L B | 8302230463 | 50-317 S |
| 1302080356* | 50-249 S | ROOD, H | 8302180563 | 50-361 P | RUSSELL, L B | 8302230605 | 50-317 S |
| 1302160198* | 50-237 S | ROOD, H | 8302250147 | 50-361 P | RUSSELL, L B | 8302230698 | 50-317 S |
| 1302030197* | 50-322 G | ROONEY, V L | 8302290123* | 50-155 P | RUSSELL, L B | 8302230716 | 50-318 S |
| 1302100292* | 50-387 G | ROONEY, V L | 8302170202* | 50-155 P | RUSSELL, L B | 8302250188 | 50-318 S |
| 1302100291 | PR | ROONEY, V L | 8302240015 | 50-271 P | RUSSELL, L B | 8302250196 | 50-317 S |
| 1302030467 | 50-413 S | ROOT, L D | 8302150174 | 50-331 P | RUSSELL, L B | 8302250402 | 50-318 S |
| 1302010350* | 50-321 G | ROOT, L D | 8302150196 | 50-331 R | RUSSELL, M J | 8302170210* | 50-322 A |
| 1302230129* | 50-29 S | ROOT, L D | 8302150267 | 50-331 P | RUSSELL, W T | 8302020130 | 50-29 P |
| 1302040439 | PROJ | ROOT, L D | 8302150279 | 50-331 P | RUSSELL, A J | 8302070240* | FOIA |
| 1302190411* | 70-1201 | ROOT, L D | 8302160286* | 50-331 G | RUTENKROGER, E | 8302080099 | 50-267 F |
| 1302030197* | 50-322 G | ROOT, L D | 8302180471* | 50-331 F | RUTENKROGER, E | 8302080133 | 70-1739 |
| 1302030429* | 50-289 G | ROOT, R W | 8302150231 | 50-460 G | RUTLEDGE, C | 8302100073 | 40-8902 |
| 1302250273* | 50-352 G | ROBAND, R | 8302230376 | 50-298 G | RUTLEDGE, C | 8302160450 | 40-8502 |
| 1302040012 | 71-5726 | ROSENBAUM, P J | 8302240217 | FOIA | RUTLEDGE, C | 8302230276 | 40-8902 |
| 1302230235* | 50-416 R | ROSENBLATT, P L | 8302280168 | 50-247 T | RYAN, P J | 8302010433* | 50-275 P |
| 1302140025 | 50-440 G | ROSENBLATT, P L | 8302280168 | 50-247 T | RYBAK, B | 8302220330 | 50-237 P |
| 1302230548* | 50-346 S | ROSENTHAL, A B | 8302040173* | FOIA | RYBAK, B | 8302250179 | 50-254 P |
| 1302230530 | 50-170 G | ROSENTHAL, A B | 8302180370* | FOIA | RYBAK, B | 8302250255 | 50-254 P |
| 1302070240* | FOIA | ROSS, B | 8302040477 | NUREG | SADIK, S | 8302150745 | RES |
| 1302240055 | 40-8502 | ROSS, D F | 7910120435 | TOPREP | SADLOWSKI, R H | 8302180211* | 50-358 A |
| 1302180120* | 50-358 A | ROSS, F W | 8302160418 | 40-8745 | SAFFELL, B F | 8302070592 | 50-537 A |
| 1302180130* | 50-358 A | ROSS, M J | 8302090022* | 50-289 F | SALTZMAN, D N | 8302170489* | CONTRACT |
| 1302180137* | 50-358 A | ROSTOCZY, Z R | 8209150350* | 50-322 A | SALTZMAN, J | 8302160149 | 50-369 J |
| 1302180144* | 50-358 A | ROSTOCZY, Z R | 8302170231* | 50-322 A | SALTZMAN, J | 8302250103 | 70-2932 |
| 1302180151* | 50-358 A | ROTELLA, T S | 8302010320* | 50-335 S | SALVENDY, O | 8302080444 | ACRS |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|----------------|------------------|------------------|-----------------|------------------|------------------|
| SANDERS, C F | 83021230293 | 70-1151 | SCHWEINER, A | 83022401514 | 50-387 P | SHACKLETON, O C | 83020702854 | 50-2064 T |
| SANDY, M A | 8302100432 | PR | SCHWEINER, A | 83022401604 | 50-387 P | SHACKLETON, O C | 83021604604 | 50-2064 T |
| SARGENT, I H | 83020806269 | 50-344 P | SCHWIMM, W | 8302170393 | REVIEW ORP | SHAFER, W D | 83020603354 | 50-379 Q |
| SATHER, A | 83020402354 | 50-329 Q | SCINTO, J F | 83022400064 | 50-387 A | SHAFER, W D | 83020103304 | 50-379 Q |
| SAVAN, N K | 83021020469 | 50-289 Q | SCOTT, D E | 83021504264 | 50-416 Q | SHAFER, W D | 83021601604 | 50-379 Q |
| SAVINI, R J | 8302070010 | FOIA | SCOTT, D J | 8302010147 | 50-237 S | SHAFER, W D | 83020503934 | 50-379 Q |
| SAWYER, E A | 8302160434 | 50-443 Q | SCOTT, D J | 8302010269 | 50-237 S | SHAFER, W D | 8302280511 | 50-379 Q |
| SEAPAN, J | 8302030208 | NUREG | SCOTT, D J | 8302010376 | 50-237 S | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHAEFER, M F | 83020904274 | TOPREP | SCOTT, D J | 83020204704 | 50-10 F | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHAEFER, M F | 83020904294 | TOPREP | SCOTT, D J | 8302040058 | 50-237 S | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHALCH, R W | 83020800584 | 71-9855 | SCOTT, D J | 8302040387 | 50-237 S | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHAUBERT, V J | 8302080399 | 70-25 | SCOTT, D J | 8302080344 | 50-249 S | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHNECHTER, K H | 83020704934 | 50-528 S | SCOTT, D J | 8302080353 | 50-249 S | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHNEIDER, C | 83020402354 | 50-329 Q | SCOTT, D J | 8302010560 | 50-237 R | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHERER, A E | 8302010451 | 50-470 A | SCOTT, D J | 8302160154 | 50-237 S | SHAFER, W D | 83020103844 | 50-379 Q |
| SCHERER, A E | 8302100356 | PR | SCOTT, D J | 8302160190 | 50-237 S | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHERER, A E | 8302100362 | PR | SCOTT, D J | 8302160222 | 50-237 S | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHERER, A E | 8302240290 | 50-470 F | SCOTT, D J | 83021804984 | 50-10 F | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHERNER, J | 83021603394 | 50-206 P | SCOTT, D J | 83022301304 | 50-10 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHIERLING, H | 83020204764 | 50-275 P | SCOTT, D J | 83022301304 | 50-237 S | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHIERLING, H | 8302170400 | 50-275 P | SCOTT, D J | 8302280518 | 50-249 S | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHIERLING, H | 8302170524 | 50-498 F | SCOTT, D J | 8302240041 | 40-299 | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHLAPPER, O A | 8302100396 | PR | SCOTT, D J | 8302250007 | 27-48 | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHMIDT, H C | 8302080158 | 50-445 A | SCOTT, D J | 8302240297 | 50-170 G | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHMIDT, H C | 8302230177 | 50-445 E | SCOTT, D J | 8302280351 | ORG | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHMIDT, H C | 8302230402 | 50-445 V | SCOTT, D J | 8302170035 | ORG | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHMIDT, H C | 8302280256 | 50-445 A | SCOTT, D J | 8302170037 | ORG | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHMITT, M B | 83022200034 | 50-390 A | SCOTT, D J | 8302160224 | 50-213 F | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHNEBEL, A A | 83020905054 | 50-358 Q | SCOTT, D J | 8302160224 | 50-213 F | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHNEIDER, K N | 8302240323 | WASTE MGT | SCOTT, D J | 8302160224 | 50-213 F | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHNEIDER, R A | 8302040120 | 70-1257 | SEARS, C F | 8302180429 | 50-336 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHNELL, D F | 8302040344 | 50-483 S | SEARS, C F | 8302180429 | 50-336 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHNELL, D F | 8302080393 | 70-2943 | SEARS, C F | 8302220148 | 50-423 A | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHNELL, D F | 83021504664 | 50-483 Q | SEARS, C F | 8302220148 | 50-423 A | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHOTT, J R | 83021808334 | 50-358 A | SEARS, C F | 8302220349 | 50-336 S | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHRADER, D | 8302230423 | 50-454 Q | SEARS, C F | 8302220349 | 50-336 S | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHREINER, V | 8302100464 | PR | SEARS, C F | 8302220427 | 50-245 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROCK, C A | 83020802314 | 50-305 S | SEARS, C F | 8302220427 | 50-245 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROCK, V E | 8302080467 | ACRS | SEARS, C F | 8302280097 | 50-213 V | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROCK, V E | 8302080467 | ACRS | SEARS, C F | 8302280097 | 50-213 V | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, B A | 83020103814 | 50-237 S | SEARS, C F | 8302280226 | 50-213 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, B A | 83021306064 | 50-237 R | SEARS, C F | 8302280431 | 50-336 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C H | 83020102864 | 50-373 P | SEARS, C F | 8302280431 | 50-336 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C H | 8302040053 | 50-374 S | SEARS, C F | 8302280490 | 50-245 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C W | 83020370464 | 50-374 A | SEARS, C F | 8302280490 | 50-245 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C W | 8302080199 | 50-373 P | SEARS, J R | 83022803804 | 50-247 T | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C W | 8302170187 | 50-373 K | SEASONSWEIN, R | 83022503924 | 50-247 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C W | 8302230518 | 50-373 P | SEELY, S | 83021003064 | PRM | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHROEDER, C W | 8302280344 | 50-373 K | SEIDLE, W C | 8302070541 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUKAT, R J | 8302100580 | PRM | SEIDLE, W C | 8302010478 | 50-368 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHULTZ, S P | 83022501674 | 50-271 P | SEIDLE, W C | 8302010481 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUM, W S | 8302280387 | 50-482 S | SEIDLE, W C | 8302070172 | 50-131 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUMACHER, M C | 83020106084 | 27-39 | SEIDLE, W C | 8302070356 | 50-482 G | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUMACHER, M C | 83020401584 | 50-341 Q | SEIDLE, W C | 8302070374 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUMACHER, M C | 83021504504 | 50-295 Q | SEIDLE, W C | 8302070408 | 50-285 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUSTER, M D | 8302010471 | 50-361 S | SEIDLE, W C | 8302070425 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUSTER, M D | 83021507014 | 50-228 Q | SEIDLE, W C | 8302070438 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUSTER, M D | 8302180203 | 50-460 S | SEIDLE, W C | 8302070462 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUSTER, M D | 83022200824 | 50-142 Q | SEIDLE, W C | 8302070471 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUSTER, M D | 83022200954 | 50-142 Q | SEIDLE, W C | 8302070538 | 50-482 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHUYLER, J D | 8302080176 | 50-275 Q | SEIDLE, W C | 8302070551 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWAN, C A | 83021507014 | 50-228 Q | SEIDLE, W C | 8302070589 | 50-285 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWAN, C A | 8302180203 | 50-460 S | SEIDLE, W C | 8302080180 | 50-313 F | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWART, H W | 8302030607 | PRQJ | SEIDLE, W C | 8302150087 | 50-285 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83021602114 | 50-352 Q | SEIDLE, W C | 8302150562 | 50-482 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302010031 | 50-352 A | SEIDLE, W C | 8302170046 | 50-285 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302020058 | 50-410 A | SEIDLE, W C | 8302170333 | 50-368 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302040347 | 50-458 A | SEIDLE, W C | 83021705484 | 50-285 F | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302080406 | 50-387 P | SEIDLE, W C | 83022303424 | 50-285 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83020804094 | 50-387 P | SEIDLE, W C | 83022303464 | 50-285 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83020804174 | 50-387 P | SEIDLE, W C | 83022303584 | 50-313 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302160644 | 50-387 P | SEIDLE, W C | 8302250193 | 50-482 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83021601304 | 50-416 P | SEIDLE, W C | 8302010577 | 50-155 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302160159 | 50-416 P | SEIDLE, W C | 8302010577 | 50-155 Q | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302160491 | 50-352 E | SEIDLE, W C | 83022300664 | 70-2746 | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302170016 | 50-410 A | SEIDLE, W C | 83021601944 | 50-454 T | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302170039 | 50-387 F | SEIDLE, W C | 83022200274 | 50-454 T | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302170125 | 50-322 Q | SEIDLE, W C | 8302150744 | 50-312 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302180026 | 50-387 P | SEIDLE, W C | 83020305544 | 0A999 | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83021800294 | 50-387 P | SEIDLE, W C | 83021400834 | 50-275 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83021800374 | 50-387 P | SEIDLE, W C | 8302180112 | 50-275 R | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302220004 | 50-322 E | SEIDLE, W C | 83021602384 | 50-321 R | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302220005 | 50-354 A | SEIDLE, W C | 8302030259 | NUREG | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 83022200489 | 50-518 A | SEIDLE, W C | 83020203114 | 50-219 P | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302240146 | 50-387 P | SEIDLE, W C | 83020801434 | FOIA | SHAFER, W D | 83021003844 | 50-379 Q |
| SCHWENGER, A | 8302240146 | 50-387 P | SEIDLE, W C | 8302240146 | 50-387 P | SHAFER, W D | 83021003844 | 50-379 Q |

PERSONAL AUTHOR INDEX

479

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|--------------|------------------|------------------|-----------------|------------------|------------------|
| ANDERSON, C. J. | 8302020244 | 50-382 G | SMITH, J. C. | 8302010336 | 70-371 | ANDERSON, C. J. | 8302010424 | 50-416 S |
| ANDERSON, C. J. | 8302020257 | 50-481 G | SMITH, J. H. | 8302280186 | 50-514 Q | ANDERSON, C. J. | 8302010434 | 50-247 T |
| ANDERSON, C. J. | 8302020263 | 50-522 C | SMITH, J. J. | 8302170386 | 40-6622 | ANDERSON, C. J. | 8302010444 | 50-244 S |
| ANDERSON, C. J. | 8302030251 | 50-415 G | SMITH, J. E. | 8302102056 | 50-269 F | ANDERSON, C. J. | 8302010454 | 50-244 S |
| ANDERSON, C. J. | 8302030259 | 50-269 G | | 8302040506 | 50-269 F | ANDERSON, C. J. | 8302010464 | 70-1201 |
| ANDERSON, C. J. | 8302070261 | 50-155 G | SMITH, J. L. | 8301250435 | 50-322 K | ANDERSON, C. J. | 8302010474 | 70-1201 |
| ANDERSON, C. J. | 8302140051 | 50-382 G | SMITH, J. L. | 8302010542 | 50-322 E | ANDERSON, C. J. | 8302010484 | 50-373 S |
| ANDERSON, C. J. | 8302160354 | 50-528 G | SMITH, J. L. | 8302020027 | 50-322 A | ANDERSON, C. J. | 8302010494 | 50-373 S |
| ANDERSON, C. J. | 8302160360 | 50-382 G | SMITH, J. L. | 8302090364 | 50-322 A | ANDERSON, C. J. | 8302010504 | 70-1257 |
| ANDERSON, C. J. | 8302220397 | 50-269 G | SMITH, J. L. | 8302100201 | 50-322 F | ANDERSON, C. J. | 8302010514 | 50-331 Q |
| ANDERSON, C. J. | 8302220402 | 50-155 G | SMITH, J. L. | 8302160277 | 50-322 A | ANDERSON, C. J. | 8302030303 | 50-10 Q |
| ANDERSON, C. J. | 8302250274 | 50-415 G | SMITH, J. L. | 8302220394 | 50-322 E | ANDERSON, C. J. | 8302150456 | 50-483 Q |
| ANDERSON, C. J. | 8302250337 | 50-275 G | SMITH, J. L. | 8302250006 | 50-322 A | ANDERSON, C. J. | 8302150486 | 50-461 Q |
| ANDERSON, C. J. | 8302250360 | 50-275 G | SMITH, J. L. | 8302250236 | 50-322 A | ANDERSON, C. J. | 8302160503 | 50-331 Q |
| ANDERSON, C. J. | 8302250370 | 50-247 T | SMITH, J. L. | 8302250312 | 50-322 E | ANDERSON, C. J. | 8302160524 | 50-315 Q |
| ANDERSON, C. J. | 8302250377 | 50-217 T | SMITH, J. L. | 8302250342 | 50-322 E | ANDERSON, C. J. | 8302160524 | 50-341 Q |
| ANDERSON, C. J. | 8302250381 | 50-247 G | SMITH, J. L. | 8302250429 | 50-322 E | ANDERSON, C. J. | 8302170291 | 50-373 Q |
| ANDERSON, C. J. | 8302250393 | 50-247 G | SMITH, J. E. | 8302170214 | 40-440 G | ANDERSON, C. J. | 8302170314 | 50-373 Q |
| ANDERSON, C. J. | 8302170114 | 50-289 P | SMITH, J. J. | 8302040212 | 50-263 Q | ANDERSON, C. J. | 8302170324 | 50-454 Q |
| ANDERSON, C. J. | 8302100404 | PR | SMITH, J. P. | 8302040134 | CONTRACT | ANDERSON, C. J. | 8302170334 | 50-346 Q |
| ANDERSON, C. J. | 8302150037 | 40-8709 | SMITH, P. A. | 8302040191 | CONTRACT | ANDERSON, C. J. | 8302170344 | 50-440 Q |
| ANDERSON, C. J. | 8302150041 | 40-8709 | SMITH, P. A. | 8302080064 | CONTRACT | ANDERSON, C. J. | 8302170354 | 50-467 Q |
| ANDERSON, C. J. | 8302230193 | 40-8709 | SMITH, P. A. | 8302080070 | CONTRACT | ANDERSON, C. J. | 8302170364 | 40-8380 |
| ANDERSON, C. J. | 8302230208 | 40-8709 | SMITH, P. A. | 8302100252 | CONTRACT | ANDERSON, C. J. | 8302240049 | 40-8290 |
| ANDERSON, C. J. | 8302250174 | 50-327 A | SMITH, P. A. | 8302160098 | 50-289 T | ANDERSON, C. J. | 8302150379 | 40-8483 |
| ANDERSON, C. J. | 8302090551 | 50-293 H | SMITH, P. A. | 8302160104 | 50-289 T | ANDERSON, C. J. | 8302080293 | 50-358 C |
| ANDERSON, C. J. | 8302100294 | PRM | SMITH, P. A. | 8302170384 | CONTRACT | ANDERSON, C. J. | 8302240088 | 50-454 T |
| ANDERSON, C. J. | 8302210298 | 50-313 Q | SMITH, P. A. | 8302170387 | CONTRACT | ANDERSON, C. J. | 8302230348 | 50-382 F |
| ANDERSON, C. J. | 8302230369 | PRM | SMITH, P. A. | 8302170392 | 50-320 P | ANDERSON, C. J. | 8302230353 | 50-382 F |
| ANDERSON, C. J. | 8302170459 | NUREG | SMITH, P. A. | 8302170394 | CONTRACT | ANDERSON, C. J. | 8302230359 | 50-382 F |
| ANDERSON, C. J. | 8302080477 | 70-1113 | SMITH, P. A. | 8302170395 | 50-320 P | ANDERSON, C. J. | 8302230368 | 50-382 F |
| ANDERSON, C. J. | 8302170291 | NUREG | SMITH, P. A. | 8302180513 | CONTRACT | ANDERSON, C. J. | 8302180508 | 40-8799 |
| ANDERSON, C. J. | 8302100348 | PRM | SMITH, P. A. | 8302180516 | CONTRACT | ANDERSON, C. J. | 8302040082 | FOIA |
| ANDERSON, C. J. | 8302030194 | 50-247 T | SMITH, R. D. | 8302090033 | 40-8452 | ANDERSON, C. J. | 8302250426 | 70-1719 |
| ANDERSON, C. J. | 8302030194 | 50-247 T | SMITH, R. D. | 8302140184 | 40-299 | ANDERSON, C. J. | 8302250433 | 70-1719 |
| ANDERSON, C. J. | 8302160476 | 50-314 F | SMITH, R. D. | 8302140197 | 40-8102 | ANDERSON, C. J. | 8302010584 | 50-213 F |
| ANDERSON, C. J. | 8302220255 | 50-334 Q | SMITH, R. D. | 8302160504 | 40-299 | ANDERSON, C. J. | 8302090390 | TOPREP |
| ANDERSON, C. J. | 8302220257 | 50-334 P | SMITH, R. D. | 8302180510 | 40-2259 | ANDERSON, C. J. | 8302170400 | 50-395 P |
| ANDERSON, C. J. | 8302240397 | 27-39 | SMITH, R. H. | 8302100303 | 50-309 Q | ANDERSON, C. J. | 8302250197 | 50-304 S |
| ANDERSON, C. J. | 8302170296 | 50-155 P | SMITH, R. H. | 8302250333 | 50-272 Q | ANDERSON, C. J. | 8302260306 | 50-329 A |
| ANDERSON, C. J. | 8302070161 | FOIA | SMITH, W. O. | 8302010333 | 50-315 S | ANDERSON, C. J. | 8302030041 | 50-537 U |
| ANDERSON, C. J. | 8302100202 | 50-440 G | SMITH, W. O. | 8302020079 | 50-315 S | ANDERSON, C. J. | 8302150717 | 50-395 Q |
| ANDERSON, C. J. | 8302100203 | 50-410 G | SMITH, W. O. | 8302040096 | 50-315 S | ANDERSON, C. J. | 8302150346 | 50-259 Q |
| ANDERSON, C. J. | 8302170206 | 50-440 G | SMITH, W. O. | 8302040195 | 50-316 S | ANDERSON, C. J. | 8302180412 | 50-156 S |
| ANDERSON, C. J. | 8302230350 | 50-440 G | SMITH, W. O. | 8302050236 | 50-315 S | ANDERSON, C. J. | 8302030220 | 50-537 A |
| ANDERSON, C. J. | 8302230380 | 50-440 G | SMITH, W. O. | 8302050263 | 50-315 S | ANDERSON, C. J. | 8302100183 | 50-537 A |
| ANDERSON, C. J. | 8302280160 | 50-440 G | SMITH, W. O. | 8302050289 | 50-316 S | ANDERSON, C. J. | 8302010319 | 50-261 S |
| ANDERSON, C. J. | 8302280160 | 50-440 G | SMITH, W. O. | 8302080311 | 50-315 S | ANDERSON, C. J. | 8302150014 | 50-261 Q |
| ANDERSON, C. J. | 8302280266 | 50-440 G | SMITH, W. O. | 8302080321 | 50-315 S | ANDERSON, C. J. | 8302150031 | 50-261 Q |
| ANDERSON, C. J. | 8302280746 | 50-440 G | SMITH, W. O. | 8302080327 | 50-316 S | ANDERSON, C. J. | 8302150093 | 50-261 Q |
| ANDERSON, C. J. | 8302250122 | NUREG | SMITH, W. O. | 8302150005 | 50-315 S | ANDERSON, C. J. | 8302150017 | 50-261 P |
| ANDERSON, C. J. | 8302070139 | CONTRACT | SMITH, W. O. | 8302150415 | 50-316 S | ANDERSON, C. J. | 8302150677 | 50-261 S |
| ANDERSON, C. J. | 8302070627 | CONTRACT | SMITH, W. O. | 8302160268 | 50-316 S | ANDERSON, C. J. | 8302170065 | 50-261 R |
| ANDERSON, C. J. | 8302090245 | 50-537 A | SMITH, W. O. | 8302160535 | 50-315 S | ANDERSON, C. J. | 8302280217 | 50-261 S |
| ANDERSON, C. J. | 8302090263 | CONTRACT | SMITH, W. O. | 8302180226 | 50-316 S | ANDERSON, C. J. | 8302140424 | 50-272 G |
| ANDERSON, C. J. | 8302100033 | CONTRACT | SMITH, W. O. | 8302180276 | 50-316 S | ANDERSON, C. J. | 8302103316 | 50-277 Q |
| ANDERSON, C. J. | 8302180246 | 40-8792 | SMITH, W. O. | 8302230357 | 50-316 S | ANDERSON, C. J. | 8302010347 | 50-320 Q |
| ANDERSON, C. J. | 8302250053 | NUREG | SMITH, W. O. | 8302250181 | 50-316 S | ANDERSON, C. J. | 8302103355 | 50-320 Q |
| ANDERSON, C. J. | 8302250144 | NUREG | SMITH, W. O. | 8302250230 | 50-316 S | ANDERSON, C. J. | 8302103369 | 50-193 Q |
| ANDERSON, C. J. | 8302090137 | 50-350 G | SMITH, W. O. | 8302280349 | 50-316 S | ANDERSON, C. J. | 8302010388 | 50-317 Q |
| ANDERSON, C. J. | 8302010235 | 50-329 Q | SMITH, W. O. | 8302280357 | 50-316 S | ANDERSON, C. J. | 8302010397 | 50-352 Q |
| ANDERSON, C. J. | 8302090510 | CONTRACT | SMITH, W. O. | 8302280382 | 50-315 S | ANDERSON, C. J. | 8302010679 | 50-213 Q |
| ANDERSON, C. J. | 8302030094 | 50-537 U | SMITH, W. O. | 8302280394 | 50-315 S | ANDERSON, C. J. | 8302030191 | 50-322 Q |
| ANDERSON, C. J. | 8302290347 | 50-271 F | SMITH, W. O. | 8302280401 | 50-315 S | ANDERSON, C. J. | 8302030209 | 50-220 Q |
| ANDERSON, C. J. | 8302090493 | 50-358 Q | SMITH, W. O. | 8302280413 | 50-315 S | ANDERSON, C. J. | 8302030389 | 50-334 Q |
| ANDERSON, C. J. | 8302090502 | 50-358 Q | SMITH, W. O. | 8302280422 | 50-316 S | ANDERSON, C. J. | 8302030436 | 50-333 Q |
| ANDERSON, C. J. | 8302090512 | 50-358 Q | SMITH, W. O. | 8302280534 | 50-316 S | ANDERSON, C. J. | 8302030487 | 50-320 Q |
| ANDERSON, C. J. | 8302010057 | FOIA | SMITH, W. O. | 8302090490 | TOPREP | ANDERSON, C. J. | 8302030559 | 50-387 Q |
| ANDERSON, C. J. | 8302160367 | 50-556 G | SMITH, W. O. | 8302230158 | 50-289 R | ANDERSON, C. J. | 8302030568 | 50-244 Q |
| ANDERSON, C. J. | 8302220301 | 50-454 T | SMITH, W. O. | 8302040303 | 50-305 Q | ANDERSON, C. J. | 8302070231 | 50-289 Q |
| ANDERSON, C. J. | 8302220301 | 50-454 T | SMITH, W. O. | 8302250364 | 50-10 Q | ANDERSON, C. J. | 8302070341 | 50-286 Q |
| ANDERSON, C. J. | 8302170210 | 50-322 A | SMITH, W. O. | 8302100400 | PR | ANDERSON, C. J. | 8302070344 | 50-334 Q |
| ANDERSON, C. J. | 8302170223 | 50-322 A | SMITH, W. O. | 8302250424 | 50-269 P | ANDERSON, C. J. | 8302070319 | 50-309 F |
| ANDERSON, C. J. | 8302280262 | 50-445 A | SMITH, W. O. | 8302170112 | 40-8584 | ANDERSON, C. J. | 8302070562 | 50-309 Q |
| ANDERSON, C. J. | 8302020054 | 50-213 J | SMITH, W. O. | 8302030040 | 40-8584 | ANDERSON, C. J. | 8302070562 | 50-309 Q |
| ANDERSON, C. J. | 8302250146 | NUREG | SMITH, W. O. | 8302220047 | 40-8584 | ANDERSON, C. J. | 8302070586 | 50-309 Q |
| ANDERSON, C. J. | 8302250498 | XPORILLIC | SMITH, W. O. | 8302160526 | 40-8681 | ANDERSON, C. J. | 8302080267 | 50-317 Q |
| ANDERSON, C. J. | 8302160203 | 50-454 T | SMITH, W. O. | 8302180511 | 40-2259 | ANDERSON, C. J. | 8302100288 | 50-387 Q |
| ANDERSON, C. J. | 8302100357 | PRM | SMITH, W. O. | 8302230049 | 40-6622 | ANDERSON, C. J. | 8302100295 | 50-277 Q |
| ANDERSON, C. J. | 8302150704 | 50-335 Q | SMITH, W. O. | 8302230064 | 40-6622 | ANDERSON, C. J. | 8302100405 | 50-277 Q |
| ANDERSON, C. J. | 8302030629 | 50-259 F | SMITH, W. O. | 8302030035 | 40-8783 | ANDERSON, C. J. | 8302100407 | 50-354 Q |
| ANDERSON, C. J. | 8302070609 | 50-273 R | SMITH, W. O. | 8302180398 | 50-329 T | ANDERSON, C. J. | 8302100416 | 50-309 Q |
| ANDERSON, C. J. | 8302080318 | 50-461 Q | SMITH, W. O. | 8302250352 | 50-460 Q | ANDERSON, C. J. | 8302150266 | 50-219 Q |
| ANDERSON, C. J. | 8302150101 | 50-302 Q | SMITH, W. O. | 8302250353 | PR | ANDERSON, C. J. | 8302150386 | 50-317 Q |
| ANDERSON, C. J. | 8302070185 | 40-8786 | SMITH, W. O. | 8302170069 | 50-466 H | ANDERSON, C. J. | 8302150483 | 50-309 Q |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|----------------|------------------|------------------|--------------|------------------|------------------|-----------------|------------------|------------------|
| STAROSTECKI, R | 8302190590 | 50-289 Q | STEWART, N L | 8302250265 | 50-283 P | SUMMERS, R | 8302280445 | 50-272 S |
| STAROSTECKI, R | 8302160270 | 50-289 Q | STEWART, N L | 8302250428 | 50-280 P | SUMNER, H L | 8302010430 | 50-366 S |
| STAROSTECKI, R | 8302180165 | 50-322 Q | STEWART, N L | 8302280080 | 50-280 P | SUMNER, H L | 8302030274 | 50-321 S |
| STAROSTECKI, R | 8302180193 | 50-423 Q | STEWART, N L | 8302280202 | 50-280 P | SUMNER, H L | 8302030460 | 50-366 S |
| STAROSTECKI, R | 8302230122 | 50-320 Q | STOHR, J P | 8302303033 | 70-27 | SUMNER, H L | 8302030523 | 50-366 S |
| STAROSTECKI, R | 8302230135 | 50-219 Q | STOHR, J P | 8302150033 | 70-143 | SUMNER, H L | 8302140015 | 50-366 S |
| STAROSTECKI, R | 8302230254 | 50-273 Q | STOHR, J P | 8302150352 | 70-143 | SUMNER, H L | 8302140050 | 50-321 S |
| STAROSTECKI, R | 8302230377 | 50-247 Q | STOHR, J P | 8302150399 | 70-143 | SUMNER, H L | 8302150191 | 50-321 S |
| STAROSTECKI, R | 8302230410 | 50-213 Q | STOHR, J P | 8302150409 | 70-1201 | SUMNER, H L | 8302150682 | 50-366 S |
| STAROSTECKI, R | 8302230413 | 50-271 S | STOHR, J P | 8302150425 | 70-1113 | SUMNER, H L | 8302230563 | 50-366 S |
| STAROSTECKI, R | 8302230467 | 50-247 Q | STOLZ, J | 8302010313 | 50-312 F | SUMNER, H L | 8302280223 | 50-321 S |
| STAROSTECKI, R | 8302230593 | 50-354 Q | STOLZ, J | 8302240164 | 50-297 F | SUMNER, H L | 8302280345 | 50-321 S |
| STAROSTECKI, R | 8302230632 | 50-247 Q | STOLZ, J F | 8302010046 | 50-313 P | SUTTON, J W | 8302030050 | QA999 |
| STAROSTECKI, R | 8302230681 | 50-289 Q | STOLZ, J F | 8302010050 | 50-313 P | SUTTON, J W | 8302070280 | QA999 |
| STAROSTECKI, R | 8302230682 | 50-334 Q | STOLZ, J F | 8302020071 | 50-277 P | SUTTON, J W | 8302070327 | QA999 |
| STAROSTECKI, R | 8302250295 | 50-309 Q | STOLZ, J F | 8302020150 | 50-302 P | SUTTON, J W | 8302160298 | QA999 |
| STAROSTECKI, R | 8302250336 | 50-412 Q | STOLZ, J F | 8302020156 | 50-302 P | SWENSON, S A | 8302040086 | 50-315 S |
| STAROSTECKI, R | 8302250345 | 50-54 Q | STOLZ, J F | 8302020162 | 50-302 P | SWALLONS, J M | 8302280500 | 50-390 Q |
| STAROSTECKI, R | 8302250348 | 50-320 Q | STOLZ, J F | 8302020277 | 50-313 P | SWANSON, D T | 8302020315 | 50-338 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302020434 | 50-313 P | SWANSON, D T | 8302230400 | 50-70 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302020473 | 50-346 P | SWANSON, D T | 8302240013 | 50-537 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302020716 | 50-312 Q | SWANSON, D T | 8302240020 | 50-70 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302020847 | 50-346 P | SWARTZ, E D | 8302080152 | 50-454 C |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302020847 | 50-313 P | SWARTZ, E D | 8302150928 | 50-10 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100049 | 50-270 P | SWARTZ, E D | 8302220364 | 50-456 F |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100051 | 50-321 P | SWARTZ, E D | 8302250361 | 50-237 F |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100076 | 50-321 P | SWARTZ, E D | 8302150495 | 50-309 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100090 | 50-346 S | SWETLAND, P | 8302250300 | 50-309 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100099 | 50-312 P | SWIBBARD, G | 8302090605 | 50-273 R |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100188 | 50-289 P | SWIBBARD, G | 8302090617 | 50-293 R |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302100251 | 50-277 P | SWIGER, M A | 8302070555 | 50-440 G |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302140173 | 50-269 P | SWIGER, M A | 8302070555 | 50-440 G |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302160522 | 50-313 P | SYLVIA, B P | 8302280348 | 50-358 A |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170105 | 50-289 P | SZALAY, R | 8302100343 | PR |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170527 | 50-321 P | SZALAY, R | 8302140107 | PR |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170530 | 50-321 P | SZAWLEWICZ, S A | 8302170487 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302180934 | 50-277 P | SZAWLEWICZ, S A | 8302170491 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302220006 | 50-321 P | SZAWLEWICZ, S A | 8302170496 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302220483 | 50-302 Q | SZAWLEWICZ, S A | 8302220441 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302220529 | 50-312 Q | SZAWLEWICZ, S A | 8302220442 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302240248 | 50-321 P | SZAWLEWICZ, S A | 8302220443 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302240258 | 50-321 P | TALLY, J J | 8302160171 | 50-313 F |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302240268 | 50-321 P | TALWANI, P | 8302250442 | 50-395 R |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302240404 | 50-313 P | TAM, P S | 8302090073 | 50-334 P |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302240138 | 50-312 P | TANG, WEE, D | 8302230706 | 50-217 S |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302250148 | 50-312 P | TAPIA, J I | 8302250243 | 50-445 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302010588 | 50-335 P | TARAS, D N | 8302100337 | PR |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302010605 | 50-335 P | TAUBER, H | 8302020437 | 50-341 F |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302140083 | 50-275 P | TAUBER, H | 8302170052 | 50-341 A |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170268 | 50-247 T | TAUBER, H | 8302220327 | 50-341 A |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170268 | 50-247 T | TAUKE, T | 8302100327 | PR |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-282 S | TAWIL, J J | 8302070197 | FOIA |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-373 Q | TAYLOR, J C | 8302150136 | 50-399 P |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-373 Q | TAYLOR, J H | 8302100362 | PR |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-255 Q | TAYLOR, J H | 8302160157 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-255 Q | TAYLOR, J H | 8302160330 | 50-259 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-409 Q | TAYLOR, J H | 8302220142 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-409 Q | TAYLOR, J H | 8302220142 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-331 Q | TAYLOR, J H | 8302250323 | PR |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040367 | 50-331 Q | TAYLOR, J H | 8302150102 | 50-359 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302140075 | 50-373 S | TAYLOR, R O | 8302250243 | 50-445 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302150914 | 50-155 Q | TEIT, T R | 8302100111 | 50-320 R |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302180407 | 50-305 Q | TEMPLE, G M | 8302230256 | 50-312 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302230681 | 50-282 Q | TERAMOTO, C S | 8302170056 | 50-341 A |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302280339 | 50-254 G | TERAO, D | 8302130353 | 50-373 G |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302280545 | 50-266 Q | TERMINI, R P | 8302100366 | PRM |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170321 | 50-409 P | TERRELL, C W | 8302230321 | 50-112 H |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302170323 | 50-409 P | TEST, R Z | 8302280467 | 50-213 S |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080130 | FOIA | THADANI, A C | 8302170431 | NUREG |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302010464 | 50-275 G | THATCHER, T | 8302160307 | 50-522 Q |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080132 | 50-281 P | THEOFANOUS, T Q | 8302080475 | ACRS |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080139 | FOIA | THEOFANOUS, T Q | 8302090475 | ACRS |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040032 | TOPREP | THOMA, J | 8302170096 | 50-155 P |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302220431 | NUREG | THOMA, J | 8302170256 | 50-155 P |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302040322 | 50-155 Q | THOMA, B | 8302180313 | CONTRACT |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080233 | 50-352 Q | THOMAS, C O | 8302010144 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080233 | 50-352 Q | THOMAS, C O | 8302010360 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080257 | 50-352 Q | THOMAS, C O | 8302020187 | 50-406 P |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302080257 | 50-352 Q | THOMAS, C O | 8302080411 | 50-447 A |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302180419 | 50-352 Q | THOMAS, C O | 8302080424 | 50-470 E |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302180425 | 50-352 Q | THOMAS, C O | 8302090529 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302180425 | 50-352 Q | THOMAS, C O | 8302090532 | TOPREP |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302250270 | 50-440 Q | THOMAS, C O | 8302160439 | 50-470 A |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302030268 | 50-272 S | THOMAS, C O | 8302220031 | 115C |
| STAROSTECKI, R | 8302250493 | 50-322 Q | STOLZ, J F | 8302030268 | 50-272 S | THOMAS, C O | 8302220490 | 50-2 F |

PERSONAL AUTHOR INDEX

48

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|----------------|------------------|------------------|----------------|------------------|------------------|-------------|------------------|------------------|
| THOMAS, D C | 8302020257 | 50-454 Q | TOLBERT, R | 8302250228* | 50-373 S | TUCKER, H B | 8302070504 | 50-269 |
| THOMAS, D C | 8302280185 | 50-454 Q | TOLMAN, E L | 8302150737 | RES | TUCKER, H B | 8302080174 | 50-413 |
| THOMAS, E L | 8302100464 | PR | TOMAN, Q J | 8301040284 | 50-313 P | TUCKER, H B | 8302100212 | 50-369 |
| THOMAS, Q S | 8302100287 | PR | TOMAN, Q J | 8301180125* | 50-305 P | TUCKER, H B | 8302100338 | PR |
| THOMAS, Q S | 8302180106* | 50-443 Q | TOMAN, Q J | 8301200219* | 50-364 P | TUCKER, H B | 8302140120 | 50-369 |
| THOMAS, J | 8302230142* | 50-219 Q | TOMAN, Q J | 8301210006* | 50-348 P | TUCKER, H B | 8302150219 | 50-413 |
| THOMAS, K | 8302150674* | 50-369 Q | TOMLINSON, D P | 8302070536* | 50-313 Q | TUCKER, H B | 8302150259 | 50-413 |
| THOMAS, L H | 8302140065 | 50-247 F | TOMLINSON, D P | 8302230416* | 50-498 Q | TUCKER, H B | 8302150293* | 50-370 |
| THOMAS, R D | 8302040448* | 27-48 | TOMLINSON, D P | 8302160370 | 50-255 P | TUCKER, H B | 8302150327 | 50-269 |
| THOMAS, R D | 8302070232 | 14C | TOMLINSON, D P | 8302170295 | 50-155 P | TUCKER, H B | 8302150376 | 50-370 |
| THOMAS, R D | 8302180170* | 70-1257 | TOMLINSON, D P | 8302180426 | 50-255 P | TUCKER, H B | 8302150442 | 50-369 |
| THOMAS, R D | 8302180172* | 70-1257 | TOMLINSON, D P | 8302220137 | 50-155 P | TUCKER, H B | 8302150522 | 50-370 |
| THOMAS, R D | 8302290316* | 70-734 | TOMLINSON, D P | 8302230179 | 50-155 P | TUCKER, H B | 8302150526 | 50-369 |
| THOMAS, R D | 8302290317* | 70-734 | TOMLINSON, D P | 8302240236 | 50-155 P | TUCKER, H B | 8302150612 | 50-370 |
| THOMAS, R D | 8302280456 | 14C | TOMLINSON, D P | 8302240273 | 50-255 P | TUCKER, H B | 8302150675 | 50-370 |
| THOMAS, S D | 8302010479 | NUREG | TOMLINSON, D P | 8302280176* | 50-329 A | TUCKER, H B | 8302150697 | 50-369 |
| THOMAS, V H | 8302290046 | NUREG | TOMLINSON, D P | 8302280389* | 50-289 F | TUCKER, H B | 8302160236 | 50-269 |
| THOMAS, W V | 8302170061* | 50-285 Q | TOMLINSON, D P | 8302230225 | 50-289 S | TUCKER, H B | 8302170042 | 50-369 |
| THOMPSON, A F | 8302160507 | CONTRACT | TOMLINSON, D P | 8302280192* | 50-5 R | TUCKER, H B | 8302170140 | 50-369 |
| THOMPSON, D | 8107200033* | FOIA | TOMLINSON, D P | 8301180184* | 50-397 Q | TUCKER, H B | 8302170327 | 50-370 |
| THOMPSON, H L | 8302090193 | MISC | TOMLINSON, D P | 8302230372* | 50-397 Q | TUCKER, H B | 8302180316 | 50-369 |
| THOMPSON, H L | 8302180041* | FOIA | TOMLINSON, D P | 8302010710 | 50-285 P | TUCKER, H B | 8302180374 | 50-269 |
| THOMPSON, H L | 8302180129* | FOIA | TOMLINSON, D P | 8302140194 | 50-285 P | TUCKER, H B | 8302180399 | 50-413 |
| THOMPSON, H L | 8302290115 | NUREG | TOMLINSON, D P | 8302010085 | FOIA | TUCKER, H B | 8302180480 | 50-269 |
| THOMPSON, H L | 8302080102 | 50-522 Q | TOMLINSON, D P | 8302220154* | 10CFR | TUCKER, H B | 8302180484* | 50-269 |
| THOMPSON, F T | 8302080182 | 50-522 Q | TOMLINSON, D P | 8302080042* | 50-315 F | TUCKER, H B | 8302220040* | 50-369 |
| THOMPSON, F T | 8302100450 | PR | TOMLINSON, D P | 8302020148 | CONTRACT | TUCKER, H B | 8302220055* | 50-269 |
| THOMUS, L | 8302030302* | 50-320 Q | TOMLINSON, D P | 8302020232 | CONTRACT | TUCKER, H B | 8302220087* | 50-369 |
| THOMUS, L | 8302290288* | 50-209 Q | TOMLINSON, D P | 8302020242 | CONTRACT | TUCKER, H B | 8302220418 | 50-269 |
| THOMUS, L | 8302290355* | 50-320 Q | TOMLINSON, D P | 8302020270 | CONTRACT | TUCKER, H B | 8302230424 | 50-369 |
| THORNBERY, R C | 8302140110 | 50-275 R | TOMLINSON, D P | 8302080129 | CONTRACT | TUCKER, H B | 8302230516 | 50-370 |
| THORPE, J R | 8302100269 | PR | TOMLINSON, D P | 8302100362 | PR | TUCKER, H B | 8302230592 | 50-369 |
| THULL, T S | 8302030101* | 50-245 S | TOMLINSON, D P | 8302100362 | PR | TUCKER, H B | 8302240068 | 50-269 |
| THULL, T S | 8302030588* | 50-245 S | TOMLINSON, D P | 8302250397* | 50-373 S | TUCKER, H B | 8302240208 | 50-413 |
| THULL, T S | 8302140447* | 50-245 S | TOMLINSON, D P | 8302280506* | 50-373 S | TUCKER, H B | 8302240283 | 50-369 |
| UCHLER, J | 8302220426 | NUREG | TRAHM, T R | 8302040370 | 50-454 S | TUCKER, H B | 8302240302 | 50-369 |
| TIEN, C | 8302080472 | ACRS | TRAHM, T R | 8302080349 | 70-2773 | TUCKER, H B | 8302240332 | 50-369 |
| TIEN, C | 8302080472 | ACRS | TRAHM, T R | 8302150103 | 50-456 S | TUCKER, H B | 8302250371 | 50-269 |
| TIERNAN, J A | 8302100337 | PRM | TRAHM, T R | 8302150419 | 50-454 S | TUCKER, H B | 8302250398 | 50-269 |
| TIERNAN, J A | 8302170334 | 50-318 P | TRAHM, T R | 8302160165 | 50-454 A | TUCKER, H B | 8302250422 | 50-369 |
| TILLMAN, A | 8302150614* | 50-302 Q | TRAHM, T R | 8302170149 | 50-454 E | TUCKER, H B | 8302280037 | 50-413 |
| TILLMAN, A | 8302150717* | 50-398 Q | TRAHM, T R | 8302180379 | 50-454 A | TUCKER, H B | 8302280082 | 50-369 |
| TILLMAN, A | 8302170304* | 50-369 Q | TRAHM, T R | 8302280204 | 50-454 K | TUCKER, H B | 8302280170 | 50-413 |
| TINNEY, J C | 8302080166 | 50-440 Q | TRAHM, T R | 8302280450 | 50-454 S | TUCKER, H B | 8302280199 | 50-413 |
| TINNEY, L R | 8302030208 | NUREG | TRAHM, T R | 8302010259 | 50-313 Q | TUCKER, H B | 8302280203 | 50-370 |
| TIPPS, S B | 8302010400* | 50-321 S | TRAHMELL, C H | 8302160014 | 50-213 Q | TUCKER, H B | 8302280325 | 50-269 |
| TIPPS, S B | 8302030376* | 50-366 S | TRAPP, O C | 8302030282 | 50-508 A | TUCKER, H B | 8302280412 | 50-269 |
| TIPPS, S B | 8302030484* | 50-366 S | TRAVIS, W H | 8302080053 | 71-9855 | TURK, J | 8302160364 | 50-70 |
| TIPPS, S B | 8302070306 | 50-321 S | TRIMBLE, D C | 8302150393* | 50-317 Q | TURK, S E | 8302070141 | 50-382 |
| TIPPS, S B | 8302070389* | 50-321 S | TRINER, E O | 8302180059* | FOIA | TURK, S E | 8302180413 | 50-382 |
| TIPPS, S B | 8302070400* | 50-366 S | TRINER, E O | 8302180071* | FOIA | TURK, S E | 8302220043 | 50-382 |
| TIPPS, S B | 8302140027* | 50-366 S | TRIPP, L | 8302030268 | 50-272 S | TURK, S E | 8302240010 | 50-70 |
| TIPPS, S B | 8302140100* | 50-366 S | TRIPP, L | 8302070218 | 50-311 S | TURK, S E | 8302240013 | 50-537 |
| TIPPS, S B | 8302140169* | 50-366 S | TRIPP, L | 8302100289 | 50-310 S | TURK, S E | 8302240020 | 50-70 |
| TIPPS, S B | 8302140181* | 50-366 S | TRIPP, L | 8302250343* | 50-412 Q | TURK, S E | 8302280265 | 50-445 |
| TIPPS, S B | 8302150025* | 50-321 S | TRIPP, L | 8302280445 | 50-272 S | TURNER, C L | 8301270285 | 50-461 |
| TIPPS, S B | 8302150077* | 50-366 S | TRIPP, L E | 8302010706 | 50-272 F | TURKETT, J | 8302030398* | 50-395 |
| TIPPS, S B | 8302150104* | 50-366 S | TRIPP, L E | 8302030397* | 50-334 Q | TUTU, N K | 8302240361 | RES |
| TIPPS, S B | 8302150105* | 50-366 S | TRIPP, L E | 8302070236* | 50-311 S | UDALL, M | 8302030029* | 50-537 |
| TIPPS, S B | 8302150135* | 50-366 S | TRIPP, L E | 8302140199 | 50-412 Q | UDERTZ, R W | 8302010025* | 50-272 |
| TIPPS, S B | 8302150142* | 50-366 S | TRIPP, L E | 8302160107 | 50-334 Q | UDY, A C | 8302220467 | 50-269 |
| TIPPS, S B | 8302150162* | 50-321 S | TRIPP, L E | 8302230142* | 50-219 Q | UFFER, R A | 8302030259 | NUREG |
| TIPPS, S B | 8302150209* | 50-321 S | TRIPP, L E | 8302230608* | 50-334 Q | UHRIG, R E | 8302010250 | 50-335 |
| TIPPS, S B | 8302150210* | 50-366 S | TRIPP, L E | 8302230289* | 50-334 Q | UHRIG, R E | 8302010444 | 50-389 |
| TIPPS, S B | 8302150252* | 50-366 S | TRIPP, L E | 8302180190 | 50-334 S | UHRIG, R E | 8302010477 | 50-389 |
| TIPPS, S B | 8302150302* | 50-321 S | TRIPP, L E | 8302030397* | 50-334 Q | UHRIG, R E | 8302010452 | 50-389 |
| TIPPS, S B | 8302150402* | 50-366 S | TRIPP, L E | 8302250289* | 50-334 Q | UHRIG, R E | 8302010513 | 50-389 |
| TIPPS, S B | 8302150490* | 50-366 S | TRIPP, L E | 8302020390 | 50-289 Q | UHRIG, R E | 8302010522 | 50-389 |
| TIPPS, S B | 8302150517* | 50-366 S | TRIPP, L E | 8302020390 | 50-289 Q | UHRIG, R E | 8302010576 | 50-335 |
| TIPPS, S B | 8302150549* | 50-366 S | TRIPP, L E | 8302070490 | 50-400 Q | UHRIG, R E | 8302010604 | 50-350 |
| TIPPS, S B | 8302230217* | 50-366 S | TRIPP, L E | 8302070490 | 50-400 Q | UHRIG, R E | 8302010643 | 50-250 |
| TIPPS, S B | 8302230229* | 50-321 S | TRIPP, L E | 8302160344 | 50-261 Q | UHRIG, R E | 8302030077 | 50-389 |
| TIPPS, S B | 8302230237* | 50-366 S | TRIPP, L E | 8302160344 | 50-261 Q | UHRIG, R E | 8302030098 | 50-389 |
| TIPPS, S B | 8302230494* | 50-321 S | TRIPP, L E | 8210120652* | 50-269 F | UHRIG, R E | 8302030427 | 50-389 |
| TIPPS, S B | 8302230704* | 50-366 S | TRIPP, L E | 8302010498 | 50-269 F | UHRIG, R E | 8302070305 | 50-280 |
| TIPPS, S B | 8302230707* | 50-366 S | TRIPP, L E | 8302010531 | 50-287 P | UHRIG, R E | 8302070444 | 50-250 |
| TIPPS, S B | 8302280138* | 50-366 S | TRIPP, L E | 8302010639 | 50-413 A | UHRIG, R E | 8302070472 | 50-250 |
| TIPPS, S B | 8302280246* | 50-366 S | TRIPP, L E | 8302010641 | 50-369 F | UHRIG, R E | 8302070528 | 50-250 |
| TIPPS, S B | 8302280278* | 50-321 S | TRIPP, L E | 8302030425 | 50-269 S | UHRIG, R E | 8302070577 | 50-250 |
| TOLSTON, A L | 8302080077 | 50-528 M | TRIPP, L E | 8302030432 | 50-413 S | UHRIG, R E | 8302080339 | 70-2957 |
| TOLSTON, A L | 8302080083* | 50-528 M | TUCKER, H B | 8302030466 | 50-269 S | UHRIG, R E | 8302100300 | PR |
| TOLSTON, A L | 8302160483 | 50-528 M | TUCKER, H B | 8302040504* | 50-269 F | UHRIG, R E | 8302100450 | PR |
| TOLSTON, A L | 8302160484* | 50-528 M | TUCKER, H B | 8302070332 | 50-369 F | UHRIG, R E | 8302150007 | 50-335 |
| TOLSTON, A L | 8302030437* | 70-27 | TUCKER, H B | 8302070331 | 50-413 F | UHRIG, R E | 8302150436* | 50-250 |
| TOLSTON, A L | 8302010709 | 50-447 A | TUCKER, H B | 8302070333 | 50-414 S | UHRIG, R E | 8302150479 | 50-250 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|----------------|------------------|------------------|---------------|------------------|------------------|---------------|------------------|------------------|
| UHRIG, R E | 8302150497 | 50-250 P | VARELA, A A | 8302150420* | 50-352 Q | VERRELLI, D M | 8302150139 | 50-259 S |
| UHRIG, R E | 8302150706 | 50-389 F | VARGA, S A | 8302040243 | 50-286 Q | VERRELLI, D M | 8302150193 | 50-327 Q |
| UHRIG, R E | 8302160203 | 50-250 Q | VARGA, S A | 8302080050* | 50-311 P | VERRELLI, D M | 8302150274 | 50-416 Q |
| UHRIG, R E | 8302160234 | 50-389 E | VARGA, S A | 8302080057* | 50-311 P | VERRELLI, D M | 8302150292* | 50-416 Q |
| UHRIG, R E | 8302160241 | 50-250 Q | VARGA, S A | 8302080077* | 50-334 P | VERRELLI, D M | 8302150321 | 50-324 Q |
| UHRIG, R E | 8302170173 | 50-389 S | VARGA, S A | 8302080085* | 50-334 P | VERRELLI, D M | 8302150334* | 50-324 Q |
| UHRIG, R E | 8302170336 | 50-389 F | VARGA, S A | 8302080106 | 50-250 P | VERRELLI, D M | 8302150462 | 50-390 Q |
| UHRIG, R E | 8302180299 | 50-251 P | VARGA, S A | 8302080357* | 50-250 P | VERRELLI, D M | 8302150472* | 50-327 Q |
| UHRIG, R E | 8302180313 | 50-389 A | VARGA, S A | 8302080358 | 50-305 P | VERRELLI, D M | 8302150474 | 50-438 Q |
| UHRIG, R E | 8302180422 | 50-389 A | VARGA, S A | 8302080420 | 50-3 F | VERRELLI, D M | 8302150632 | 50-327 Q |
| UHRIG, R E | 8302180437 | 50-250 F | VARGA, S A | 8302080453 | 50-280 F | VERRELLI, D M | 8302150658 | 50-390 Q |
| UHRIG, R E | 8302180460 | 50-389 R | VARGA, S A | 8302080135 | 50-295 P | VERRELLI, D M | 8302150663* | 50-327 Q |
| UHRIG, R E | 8302180483 | 50-250 P | VARGA, S A | 8302080483 | 50-295 P | VERRELLI, D M | 8302150687 | 50-324 Q |
| UHRIG, R E | 8302230145 | 50-250 P | VARGA, S A | 8302100003 | 50-272 F | VERRELLI, D M | 8302150698* | 50-259 Q |
| UHRIG, R E | 8302230149 | 50-389 F | VARGA, S A | 8302100108* | 50-348 P | VIETTI, A | 8302100126 | 50-508 A |
| UHRIG, R E | 8302230198 | 50-250 P | VARGA, S A | 8302100115* | 50-348 P | VILLALVA, I | 8302070266* | 0A999 |
| UHRIG, R E | 8302230322 | 50-335 P | VARGA, S A | 8302100175 | 50-364 P | VILLALVA, I | 8302230082* | 50-324 U |
| UHRIG, R E | 8302230437 | 50-335 P | VARGA, S A | 8302100194 | 50-305 F | VISSINO, O S | 8302240107* | 50-155 P |
| UHRIG, R E | 8302230443 | 50-335 P | VARGA, S A | 8302140192 | 50-348 P | VISSINO, O S | 8302170212* | 50-155 P |
| UHRIG, R E | 8302280128 | 50-389 S | VARGA, S A | 8302150740 | 50-286 P | VLIEL, J A | 8302220416* | 50-155 P |
| UHRIG, R E | 8302280271 | 50-389 A | VARGA, S A | 8302160075 | 50-272 P | VOGLER, B H | 8302040180 | 50-413 H |
| UHRIG, R E | 8302280350 | 50-389 A | VARGA, S A | 8302160124 | 50-315 P | VOGLER, B H | 8302150371 | 50-445 H |
| UHRIG, R E | 8302280353 | 50-335 V | VARGA, S A | 8302160432 | 50-247 P | VOGLER, B H | 8302240022 | 50-352 Q |
| ULLICH, J | 8302280466* | 50-155 Q | VARGA, S A | 8302160466 | 50-261 P | VOSBURY, F H | 8302100994* | 50-335 P |
| ULLRICH, W T | 8302070509 | 50-278 S | VARGA, S A | 8302170030 | 50-261 P | VOSBURY, F H | 8302200034* | 50-244 P |
| ULLRICH, W T | 8302070513 | 50-278 S | VARGA, S A | 8302170075 | 50-261 P | VOSBURY, F H | 8302200078* | 50-295 P |
| ULLRICH, W T | 8302070520 | 50-277 S | VARGA, S A | 8302170238 | 50-280 Q | VOSBURY, F H | 8302200091* | 50-305 P |
| UNDERWOOD, R H | 8302070489 | PT21 | VARGA, S A | 8302170243* | 50-280 Q | WAGNER, A C | 8302150426* | 50-416 Q |
| UNKLE, T J | 8302230306* | 50-317 S | VARGA, S A | 8302170416* | 50-315 P | WAGNER, M E | 8302070021 | 50-460 Q |
| UPRIGHT, C H | 8302150277* | 50-389 Q | VARGA, S A | 8302170428* | 50-315 P | WAGNER, M E | 8302240201 | 50-460 Q |
| UPRIGHT, C H | 8302150416* | 50-261 Q | VARGA, S A | 8302170432 | 50-250 P | WAGNER, M E | 8302240291 | 50-460 Q |
| UPRIGHT, C H | 8302150673 | 50-389 Q | VARGA, S A | 8302170434 | 50-261 P | WAGNER, P | 8302170089* | 50-155 P |
| UPRIGHT, C H | 8302150704* | 50-335 Q | VARGA, S A | 8302170436 | 50-286 P | WAGNER, P | 8302170089* | 50-155 P |
| UTLEY, E E | 8302150040 | 50-325 P | VARGA, S A | 8302170440 | 50-334 P | WAGNER, P | 8302230720 | 50-267 S |
| UTLEY, E E | 8302150046 | 50-261 P | VARGA, S A | 8302170459* | 50-334 P | WAGNER, P C | 8302170240* | 50-155 P |
| UTLEY, E E | 8302150195 | 50-324 P | VARGA, S A | 8302170472* | 50-334 P | WAGNER, W J | 8302230278* | 50-508 Q |
| UTLEY, E E | 8302150205 | 50-261 P | VARGA, S A | 8302180054 | 50-303 P | WAITE, J A | 8302040448* | 27-48 |
| UTLEY, E E | 8302150290 | 50-261 Q | VARGA, S A | 8302240080 | 50-251 Q | WATKINS, D W | 8302230542 | 50-454 S |
| UTLEY, E E | 8302150374 | 50-261 Q | VARGA, S A | 8302240120* | 50-251 Q | WALD, J J | 8302160205* | 50-358 A |
| UTLEY, E E | 8302150394 | 50-324 P | VARGA, S A | 8302240137 | 50-250 P | WALKER, R D | 8302010377* | 50-373 Q |
| UTLEY, E E | 8302150602 | 50-324 P | VARGA, S A | 8302240183 | 50-286 P | WALKER, R D | 8302080313* | 50-331 Q |
| UTLEY, E E | 8302280363* | 50-261 P | VARGA, S A | 8302240190 | 50-305 P | WALKER, R D | 8302280341* | 50-254 Q |
| VACCA, P C | 8302250163 | PRM | VARGA, S A | 8302240204 | 50-286 P | WALLACE, W T | 8302240185* | CONTRACT |
| VADEN, J | 8302240338* | WASTE MOT | VARGA, S A | 8302240228 | 50-295 P | WALTON, G | 8302250343* | 50-412 Q |
| VALDES, S | 8302170135* | 50-335 S | VARGA, S A | 8302250013* | 50-316 P | WAMBACH, T V | 8302040248 | 50-255 P |
| VALDES, S A | 8302280047* | 50-335 S | VARGA, S A | 8302250494 | 50-261 P | HANG, Y K | 8302220431 | NUREQ |
| VAN BRUNT, E E | 8302010493 | 50-528 A | VARGA, S A | 8302280064 | 50-295 P | WANG, A B | 8302240308 | 50-206 P |
| VAN BRUNT, E E | 8302070221 | 50-528 S | VARGA, S A | 8302280180 | 50-272 F | WANG, L C | 8302250091 | NUREQ |
| VAN BRUNT, E E | 8302070249 | 50-527 B | VASSALLO, D B | 8302030618 | 50-271 P | WAPATO, S T | 8302030182 | 50-522 Q |
| VAN BRUNT, E E | 8302070254 | 50-528 S | VASSALLO, D B | 8302040001 | 50-220 P | WAPATO, S T | 8302160302 | 50-522 Q |
| VAN BRUNT, E E | 8302070259 | 50-528 S | VASSALLO, D B | 8302070087 | 50-259 P | WARD, E | 8302030023* | 50-263 F |
| VAN BRUNT, E E | 8302070387 | 50-528 S | VASSALLO, D B | 8302070287 | 50-333 P | WARD, E C | 8302030018* | 50-263 F |
| VAN BRUNT, E E | 8302070483 | 50-528 S | VASSALLO, D B | 8302100155 | 50-324 P | WARD, E C | 8302030020* | 50-263 F |
| VAN BRUNT, E E | 8302080210 | 50-528 A | VASSALLO, D B | 8302100160 | 50-259 Q | WARD, K D | 8302150532* | 50-263 Q |
| VAN BRUNT, E E | 8302080362 | 50-528 E | VASSALLO, D B | 8302160093 | 50-324 P | WARD, K D | 8302150724* | 50-454 Q |
| VAN BRUNT, E E | 8302100221 | 50-528 A | VASSALLO, D B | 8302170072 | 50-263 P | WARD, W J | 8302070347* | 50-360 Q |
| VAN BRUNT, E E | 8302180186 | 50-528 S | VASSALLO, D B | 8302170108 | 50-263 P | WAREMBOURG, D | 8302030333 | 50-267 P |
| VAN BRUNT, E E | 8302150625 | 50-528 S | VASSALLO, D B | 8302170225 | 50-259 F | WAREMBOURG, D | 8302040614 | 50-267 F |
| VAN BRUNT, E E | 8302230326 | 50-528 E | VASSALLO, D B | 8302170430 | 50-333 P | WAREMBOURG, D | 8302070144 | 50-267 F |
| VAN BRUNT, E E | 8302230361 | 50-529 S | VASSALLO, D B | 8302170488 | 50-259 P | WAREMBOURG, D | 8302070491 | 50-267 R |
| VAN BRUNT, E E | 8302230425 | 50-528 S | VASSALLO, D B | 8302170500 | 50-324 F | WAREMBOURG, D | 8302070554 | 50-267 P |
| VAN BRUNT, E E | 8302230531 | 50-528 S | VASSALLO, D B | 8302170502 | 50-333 F | WAREMBOURG, D | 8302070574 | 50-267 S |
| VAN BRUNT, E E | 8302280443 | 50-528 A | VASSALLO, D B | 8302170514* | 50-331 P | WAREMBOURG, D | 8302070584 | 50-267 S |
| VAN BRUNT, E E | 8302280492 | 50-528 A | VASSALLO, D B | 8302170523* | 50-331 P | WAREMBOURG, D | 8302070618 | 50-267 S |
| VAN DER HOVEN | 8210150452 | 50-275 F | VASSALLO, D B | 8302240017* | 50-271 P | WAREMBOURG, D | 8302080040 | 50-267 F |
| VAN DER HOVEN | 8210150459* | 50-275 F | VASSALLO, D B | 8302240026* | 50-271 P | WAREMBOURG, D | 8302080059 | 50-267 F |
| VAN DER HOVEN | 8301270044* | 50-275 F | VASSALLO, D B | 8302240102 | 50-331 P | WAREMBOURG, D | 8302080095 | 50-267 F |
| VAN DER HOVEN | 8301270051* | 50-275 F | VASSALLO, D B | 8302240119* | 50-331 P | WAREMBOURG, D | 8302090543* | 50-267 F |
| VAN DER HOVEN | 8301270060* | 50-275 F | VASSALLO, D B | 8302240129* | 50-331 P | WAREMBOURG, D | 8302150001 | 50-267 S |
| VAN LAERE, J | 8302220366* | 50-454 T | VAUGHAN, C H | 8302040584 | 70-1113 | WAREMBOURG, D | 8302150574 | 50-267 S |
| VUYLE, O J | 8302250039 | RES | VAUGHAN, C H | 8302080033 | 70-1113 | WAREMBOURG, D | 8302170344 | 50-267 S |
| VLIEL, J | 8302170404 | 50-287 P | VAUGHAN, C H | 8302080101 | 70-1113 | WAREMBOURG, D | 8302220157 | 50-267 R |
| VLIEL, J | 8302250102 | 50-269 P | VAUGHAN, C H | 8302150021 | 70-1113 | WAREMBOURG, D | 8302230318 | 50-267 P |
| VLIEL, J A | 8302170161* | 50-155 P | VAUGHAN, C H | 8302250356 | PR | WAREMBOURG, D | 8302020048* | 50-267 F |
| VLIEL, T | 8302180083* | 50-358 A | VEENSTRA, R C | 8302040466* | 70-1257 | WAREMBOURG, D | 8302020051* | 50-267 F |
| VEL, T. E | 8302070358* | 50-482 Q | VEGA, A | 8302100242* | 50-445 Q | WAREMBOURG, D | 8302070350 | 50-267 F |
| VEL, T. E | 8302180065* | 50-373 Q | VEGA, A | 8302100246* | 50-445 Q | WAREMBOURG, D | 8302090539* | 50-267 F |
| VER JAOT, O | 8302100471* | PR | VENTO, B F | 8302030072* | 50-837 U | WAREMBOURG, D | 8302100464 | PR |
| VERHALLE, D J | 8302070622 | 50-255 D | VERBRYKE | 8302090605* | 50-253 R | WAREMBOURG, D | 8302250009* | 50-267 F |
| VERHALLE, D J | 8302230421 | 50-255 F | VERRELLI, D | 8302150325 | 50-259 Q | WAREMBOURG, D | 8302250016* | 50-267 F |
| VERHALLE, D J | 8302240163 | 50-155 P | VERRELLI, D | 8302150703 | 50-400 Q | WAREMBOURG, D | 8302250256 | 50-267 V |
| VERHALLE, D J | 8302250363 | PR | VERRELLI, D M | 8302070391 | 50-296 S | WARNER, D L | 8302080123* | 40-8027 |
| VERHALLE, D J | 8302280374* | 50-255 Q | VERRELLI, D M | 8302150021 | 50-259 P | WARNICK, P F | 8302250388 | 50-329 Q |
| VERHALLE, D J | 8302150643* | 50-413 Q | VERRELLI, D M | 8302150064 | 50-324 Q | WARNICK, R | 8302250319 | 50-358 Q |
| VERHALLE, D J | 8302070499* | 50-29 P | VERRELLI, D M | 8302150068 | 50-111 Q | WARNICK, R F | 8302010623* | 50-329 Q |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-------------------|------------------|------------------|-----------------|------------------|------------------|
| WARNICK, R F | 8302040168* | 50-440 Q | WENSLAWSKI, F A | 8302230371* | 50-206 Q | WIGGINS, J T | 8302100436* | 50-330 |
| WARNICK, R F | 8302040225 | 50-329 Q | WENSLAWSKI, F A | 8302230378* | 50-206 Q | WIGGINS, J T | 8302250042* | 50-440 |
| WARNICK, R F | 8302180089* | 50-358 Q | WERMIEL, J S | 8302170090* | 50-289 T | WIGGINTON, D L | 8302170412 | 50-310 |
| WARNICK, R F | 8302180354 | 50-358 A | WESLEY, D A | 8302170309 | 50-329 A | WIGGINTON, D L | 8302250004 | 50-310 |
| WARNICK, R F | 8302250320* | 50-358 Q | WEBT, D | 8302150361* | 50-335 S | WILCOVE, M N | 8302040022 | 50-320 |
| WARNICK, R L | 8302040323 | 50-329 Q | WEBT, S | 8302150604* | 50-335 S | WILCOVE, M N | 8302040042 | 50-320 |
| WARREN, D H | 8302030261 | 50-424 C | WEST, J | 8302180478* | CONTRACT | WILD, P A | 8302040218 | 50-334 |
| WARREN, K J | 8302160228 | 50-275 H | WESTAFER, O R | 8302010574 | 50-302 S | WILD, P A | 8302230161 | 50-325 |
| WASHKO, D | 8302070354* | 50-219 S | WESTAFER, O R | 8302030350 | 50-302 S | WILKERSON, T O | 8302220025* | CONTRA |
| WATHEN, R P | 8302080380* | 50-346 F | WESTAFER, O R | 8302030416 | 50-302 K | WILKINSON, B W | 8302250175 | 50-294 |
| WATKINS, D J | 8302250122 | NUREG | WESTAFER, O R | 8302070268 | 50-302 P | WILLIAMS, C | 8302040076* | 50-440 |
| WATSON, R | 8302030261* | 50-331 R | WESTAFER, O R | 8302150138 | 50-302 P | WILLIAMS, C C | 8302040396* | 50-440 |
| WATSON, R L | 8302010607* | 50-128 P | WESTAFER, O R | 8302160178 | 50-302 P | WILLIAMS, C C | 8302150367* | 50-440 |
| WATSON, R L | 8302010510* | 50-128 P | WESTAFER, O R | 8302160265 | 50-302 P | WILLIAMS, C C | 8302240092* | 50-454 |
| WAXMAN, H A | 8302250338* | REGG | WESTAFER, O R | 8302170370 | 50-302 P | WILLIAMS, C C | 8302280466* | 50-150 |
| WAYLAND, J R | 8302070240* | FOIA | WESTAFER, O R | 8302180363 | 50-302 V | WILLIAMS, C C | 8302280489* | 50-454 |
| WEATHERMAK, R K | 8302090279* | 50-247 T | WESTAFER, O R | 8302230302 | 50-302 S | WILLIAMS, D L | 8302210581* | 50-282 |
| WEATHERMAK, R K | 8302090279* | 50-247 T | WESTAFER, O R | 8302230678 | 50-302 Q | WILLIAMS, F E | 8302250030* | 50-296 |
| WEBB, W A | 8302010623* | 50-320 F | WESTAFER, O R | 8302280148 | 50-302 S | WILLIAMS, J W | 8302210118 | 50-250 |
| WEBER, K F | 8302240386 | WASTE MGT | WESTAFER, O R | 8302280221 | 50-302 S | WILLIAMS, J W | 8302010311 | 50-335 |
| WEE, D T | 8302040070* | 50-237 S | WESTAFER, O R | 8302280261 | 50-302 S | WILLIAMS, J W | 8302010463 | 50-335 |
| WEGOT, W F | 8302180255 | 50-142 P | WESTBROOK, K | 8302160426 | 40-8786 | WILLIAMS, J W | 8302010477 | 50-335 |
| WEIDER, A | 8302070311* | XPORTLIC | WESTBROOK, K | 8302160427 | 40-8786 | WILLIAMS, J W | 8302140033 | 50-335 |
| WEIL, C H | 8302010623* | 50-329 Q | WESTBROOK, K | 8302160429 | 40-8786 | WILLIAMS, J W | 8302140104 | 50-335 |
| WEIL, C H | 8302040101* | 50-440 Q | WESTBROOK, K B | 8302160119 | 40-8786 | WILLIAMS, J W | 8302140112 | 50-335 |
| WEIL, C H | 8302040178* | 50-440 Q | WESTBROOK, K B | 8302170547 | 40-8786 | WILLIAMS, J W | 8302150063 | 50-250 |
| WEIL, C H | 8302040186* | 50-440 Q | WESTERMAN, T F | 8302030331* | 50-445 Q | WILLIAMS, J W | 8302150355 | 50-335 |
| WEIL, C H | 8302040355* | 50-440 Q | WESTERMAN, T F | 8302030475* | 50-267 Q | WILLIAMS, J W | 8302150594 | 50-335 |
| WEIL, C H | 8302040431* | 50-440 Q | WESTERMAN, T F | 8302070391* | 50-313 Q | WILLIAMS, J W | 8302170131 | 50-335 |
| WEIL, C H | 8302040440* | 50-440 Q | WESTERMAN, T F | 8302070543* | 50-298 Q | WILLIAMS, J W | 8302170154 | 50-335 |
| WEINKAM, E J | 8302040268 | 50-458 F | WESTERMAN, T F | 8302160246 | 50-267 S | WILLIAMS, J W | 8302280045 | 50-335 |
| WEINKAM, E J | 8302170038 | 50-458 F | WESTERMAN, T F | 8302170364* | 50-445 Q | WILLIAMS, J W | 8302280345 | 50-250 |
| WEIR, J O | 8302100404 | PR | WESTERMAN, T F | 8302230478* | 50-267 Q | WILLIAMS, P C | 8302010421 | TOPREP |
| WEIR, J O | 8302100404 | PR | WESTERMAN, T F | 8302230692* | 50-267 Q | WILLIAMS, R E | 8302160409 | 40-874 |
| WEIR, P J | 8302010175* | 50-318 S | WESTERMAN, T F | 8302230693* | 50-267 Q | WILLIAMS, R E | 8302170010 | 40-874 |
| WEIR, P J | 8302010189* | 50-318 S | WESTERMAN, T F | 8302250243* | 50-445 Q | WILLIAMS, R E | 8302180525* | CONTRA |
| WEIR, P J | 8302010345* | 50-318 S | WESTERMAN, T F | 8302250378 | 50-267 S | WILLIAMS, V S | 8302030626* | 50-295 |
| WEIR, P J | 8302010352* | 50-318 S | WETMORE, J S | 8302280224 | 50-269 P | WILLIAMS, V S | 8302250170* | 50-295 |
| WEIR, P J | 8302010560* | 50-318 S | WETTERHAIN, M J | 8302010067 | 27-39 | WILLIAMS, V S | 8302280476* | 50-295 |
| WEIR, P J | 8302180269* | 50-317 S | WETTERHAIN, M J | 8302080059 | 50-220 P | WILLIAMSON, B T | 8302280481* | 50-259 |
| WEISE, S | 8302150022* | 50-261 Q | WETTERHAIN, J M J | 8302230329 | 50-358 Q | WILLIS, C A | 8302010258* | 50-310 |
| WEISE, S | 8302150128* | 50-261 Q | WETTERHAIN, M J | 8302230329 | 50-358 Q | WILLIS, B D | 8302020169* | XPORTL |
| WEISS, D | 8302070168 | 70-1201 | WETTERHAIN, M J | 8302230359 | 50-352 Q | WILSON, B D | 8302020368* | XPORTL |
| WEISS, D | 8302180081* | FOIA | WETTERHAIN, M J | 8302230359 | 50-352 Q | WILSON, B D | 8302020373* | XPORTL |
| WEISS, E R | 8302010104 | 50-289 T | WHARTON, J T | 8302030276* | 50-387 F | WILSON, C R | 8302250122 | NUREG |
| WEISS, E R | 8302020455 | FOIA | WHEELER, L | 8302250105 | 50-443 A | WILSON, D | 8302180476* | 50-331 |
| WEISS, E R | 8302030015 | 50-337 U | WHITE, A F | 8302250122 | NUREG | WILSON, E F | 8301310191 | Stats |
| WEISS, E R | 8302040123 | 50-337 A | WHITE, J R | 8302180289* | 50-309 Q | WILSON, J | 8302030619* | 50-280 |
| WEISS, E R | 8302070484 | 50-289 Q | WHITE, L H | 8302100450 | PR | WILSON, J | 8302070402* | 50-280 |
| WEISS, E R | 8302070484 | 50-289 Q | WHITENER, H L | 8302150304* | 50-370 Q | WILSON, J | 8302250064 | 50-382 |
| WEISS, E R | 8302070587 | 50-289 Q | WHITENER, H L | 8302150720* | 50-389 Q | WILSON, J E | 8302240275* | CONTRA |
| WEISS, E R | 8302070587 | 50-289 Q | WHITNEY, O O | 8302010335 | 50-293 S | WILSON, J H | 8302100139 | 50-382 |
| WEISS, E R | 8302100349 | PRM | WHITNEY, O O | 8302070467* | 50-293 S | WILSON, J H | 8302250116 | 50-382 |
| WEISS, E R | 8302160347 | 70-143 | WHITNEY, O O | 8302100395* | 50-293 S | WILSON, J L | 8302010422 | 50-280 |
| WEISS, E R | 8302160347 | 70-143 | WHITNEY, O O | 8302220351* | 50-293 S | WILSON, J L | 8302010423* | 50-280 |
| WEISS, E R | 8302160371 | 50-289 Q | WHITNEY, O O | 8302220393* | 50-293 S | WILSON, J L | 8302010424* | 50-280 |
| WEISS, E R | 8302170211 | 50-289 Q | WICHMAN, K | 8302040032 | TOPREP | WILSON, J L | 8302070392 | 50-280 |
| WEISS, E R | 8302170211 | 50-289 Q | WICHMAN, K R | 8302080141* | FOIA | WILSON, J L | 8302070399* | 50-280 |
| WEISS, E R | 8302170312* | 50-413 Q | WICK, E A | 8302240342 | WASTE MGT | WILSON, J L | 8302070407* | 50-280 |
| WEISS, E R | 8302170312* | 50-413 Q | WIDMAN, J C | 8302240165 | XPORTLIC | WILSON, J L | 8302140062 | 50-281 |
| WEISS, E R | 8302250274 | 50-289 Q | WIDMAYER, D A | 8302170483 | NUREG | WILSON, J L | 8302140066* | 50-281 |
| WEISS, E R | 8302250274 | 50-289 Q | WIDMAYER, D A | 8302240042 | WASTE MGT | WILSON, J L | 8302140069* | 50-281 |
| WEISZ, D A | 8302170164 | TOPREP | WIDMAYER, D A | 8302240356 | WASTE MGT | WILSON, J L | 8302140072* | 50-281 |
| WELLS, C A | 8302170168* | TOPREP | WIEBE, J | 8302030502* | 50-320 Q | WILSON, J L | 8302170365 | 50-280 |
| WELLS, C A | 8302030214* | 50-346 F | WIEBE, J | 8302230355* | 50-320 Q | WILSON, J L | 8302170371* | 50-280 |
| WELLS, D A | 8302040074 | 50-341 S | WIEDEMAN, D | 8302040091* | FOIA | WILSON, J L | 8302170375* | 50-280 |
| WELLS, D A | 8302040090 | 50-341 S | WIEDEMAN, D O | 8312210286 | 70-1866 | WILSON, J L | 8302230194 | 50-280 |
| WELLS, D A | 8302040116 | 50-341 S | WIEDEMAN, D O | 8302010482 | 40-215 | WILSON, J L | 8302230203* | 50-280 |
| WELLS, D A | 8302150029 | 50-341 S | WIEDEMAN, D O | 8302010487* | 40-215 | WILSON, R | 8302070590 | 50-400 |
| WELLS, D A | 8302150240 | 50-341 S | WIEDEMAN, D O | 8302010494 | 40-8798 | WILSON, W B | 8302280013 | NUREG |
| WELLS, D A | 8302160299* | 50-341 Q | WIEDEMAN, D O | 8302040095* | FOIA | WILT, D D | 8302040375 | 50-440 |
| WELLS, J E | 8302170469 | NUREG | WIEDEMAN, D O | 8302040162* | FOIA | WINDO, H D | 8302230622* | 50-259 |
| WELLS, P L | 8302100454 | PRM | WIEDEMAN, D O | 8302160217 | 70-2677 | WINDO, H D | 8302230628* | 50-276 |
| WEN, P | 8302030581* | 50-29 Q | WIEDER, A | 8302220130* | 50-142 Q | WINTERHOFF, D | 8302250313* | 50-373 |
| WENDERLICH, R L | 8302010189* | 50-318 S | WIEDEMANN, R A | 8302070599* | 50-395 P | WIRE, K R | 8302230713* | 50-298 |
| WENDERLICH, R L | 8302010337* | 50-317 S | WIESEMANN, R A | 8302090277* | TOPREP | WISENBURG, M R | 8302100338 | PR |
| WENDERLICH, R L | 8302010560* | 50-318 S | WIESEMANN, R A | 8302090424* | TOPREP | WITHERS, B D | 8302030108 | 50-344 |
| WENDERLICH, R L | 8302010571* | 50-318 S | WIESEMANN, R A | 8302090484* | TOPREP | WITHERS, B D | 8302030116* | 50-344 |
| WENDERLICH, R L | 8302070415* | 50-317 S | WIESEMANN, R A | 8302100328 | PR | WITHERS, B D | 8302040274 | 50-344 |
| WENDERLICH, R L | 8302070418* | 50-317 S | WIESEMANN, R A | 8302230640* | REVIEW GRP | WITHERS, B D | 8302080163 | 50-344 |
| WENDERLICH, R L | 8302250199* | 50-317 S | WIESEMANN, R A | 8302240316* | TOPREP | WITHERS, B D | 8302080172 | 50-344 |
| WENSKY, A K | 8302040398* | 50-289 P | WIGGINS, J | 8302010247 | 50-309 S | WITHERS, B D | 8302100277 | PR |
| WENSLAWSKI, F | 8302010476* | 50-375 Q | WIGGINS, J | 8302010504 | 50-309 S | WITHERS, B D | 8302100362 | PR |
| WENSLAWSKI, F | 8302230256* | 50-312 Q | WIGGINS, J | 8302150495* | 50-309 Q | WITHERS, B D | 8302150713 | 50-344 |
| WENSLAWSKI, F A | 8302230324* | 50-344 Q | WIGGINS, J | 8302240191 | 50-322 A | WITHERS, B D | 8302180339 | 50-344 |

PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|-----------------|------------------|------------------|-----------------|------------------|------------------|----------------|------------------|------------------|
| WITHERS, B D | 8302230315 | 50-344 Q | YAMANA, K | 8302240375* | XPORTLIC | ZAHLER, R E | 8302160293 | 50-289 Q |
| WITHERS, B D | 8302230490 | 50-344 P | YANDELL, L A | 8302070600* | 50-285 Q | ZIBULSKY, H | 8302180241* | 50-5 Q |
| WITTENBERG, K C | 8302280381* | 50-373 S | YANDELL, L A | 8302160258 | 50-285 S | ZIBULSKY, H | 8302180264* | 70-371 |
| WOHL, M L | 8302160212* | 50-434 T | YANO, T L | 8302070507* | 50-382 A | ZICKORAF, E | 8302100464 | PR |
| WOHL, P R | 8302040331* | 50-305 G | YEAGER, B B | 8302100440 | PRM | ZIELINSKI, A H | 8302250157 | XPORTLIC |
| WOLF, J F | 8302230643 | 50-522 Q | YEE, T | 8302160189 | 50-329 A | ZIELINSKI, A H | 8302250160* | XPORTLIC |
| WOLF, J R | 8302230511 | 50-201 Q | YEH, Q T | 8302030252 | NUREQ | ZIMMERMAN, J V | 8302010685 | XPORTLIC |
| WOLFE, S J | 8302160175 | 50-382 Q | YIN, I | 8302040378* | 50-440 Q | ZIMMERMAN, J V | 8302010687 | XPORTLIC |
| WOLFE, S J | 8302220409 | 50-556 Q | YIN, I T | 8302010622* | 50-461 Q | ZIMMERMAN, J V | 8302010698 | XPORTLIC |
| WOLFE, S J | 8302230625 | 50-338 Q | YIN, I T | 8302040352* | 50-341 Q | ZIMMERMAN, J V | 8302010693 | XPORTLIC |
| WOLFE, S J | 8302230631 | 50-338 Q | YIN, I T | 8302240092* | 50-454 Q | ZIMMERMAN, J V | 8302010694 | XPORTLIC |
| WOLLETT, S | 8302020020 | CONTRACT | YIN, I T | 8302170326* | 50-409 P | ZIMMERMAN, J V | 8302010695 | XPORTLIC |
| WOLLETT, S | 8302020032 | CONTRACT | YOLE, A H | 8302220278* | 50-434 T | ZIMMERMAN, J V | 8302020160 | XPORTLIC |
| WOLLETT, S | 8302020423 | CONTRACT | YONK, A K | 8302220278* | 50-454 T | ZIMMERMAN, J V | 8302020164 | XPORTLIC |
| WOLLETT, S | 8302040159 | CONTRACT | YONK, A K | 8302220278* | 50-454 T | ZIMMERMAN, J V | 8302020366 | XPORTLIC |
| WOLLETT, S | 8302040279 | 50-358 Q | YORE, J R | 8302040146* | FOIA | ZIMMERMAN, J V | 8302020372 | XPORTLIC |
| WOLLETT, S | 8302040298 | CONTRACT | YORE, J R | 8302040169* | FOIA | ZIMMERMAN, J V | 8302020510 | XPORTLIC |
| WOLLETT, S | 8302040432 | CONTRACT | YORK, J H | 8302180607* | 50-389 Q | ZIMMERMAN, J V | 8302030007 | XPORTLIC |
| WOLLETT, S | 8302040460 | CONTRACT | YOUNG, F | 8302070335* | 50-289 Q | ZIMMERMAN, J V | 8302030071 | XPORTLIC |
| WOLLETT, S | 8302100017 | CONTRACT | YOUNG, F | 8302250288* | 50-289 Q | ZIMMERMAN, J V | 8302030083 | XPORTLIC |
| WOLLETT, S | 8302100026 | CONTRACT | YOUNG, J A | 8302250282* | NUREG | ZIMMERMAN, J V | 8302080443 | XPORTLIC |
| WOLLETT, S | 8302170366 | CONTRACT | YOUNG, J A | 8302250046 | 50-460 Q | ZIMMERMAN, J V | 8302090177 | XPORTLIC |
| WOLLETT, S | 8302240031 | CONTRACT | YOUNG, M A | 8302090021 | 50-460 Q | ZIMMERMAN, J V | 8302090180 | XPORTLIC |
| WOLLETT, S | 8302240234 | CONTRACT | YOUNG, M A | 8302240281 | 50-460 Q | ZIMMERMAN, J V | 8302090198 | XPORTLIC |
| WOLFE, H | 8302030029* | 50-537 U | YOUNG, M A | 8302240291 | 50-460 Q | ZIMMERMAN, J V | 8302090202 | XPORTLIC |
| WOLTER, E F | 8302250239* | 70-398 F | YOUNG, R H | 8302100432 | PRM | ZIMMERMAN, J V | 8302090208 | XPORTLIC |
| WOMACK, L F | 8302030611* | 50-275 F | YOUNG, R H | 8302010238* | 50-313 Q | ZIMMERMAN, J V | 8302090212 | XPORTLIC |
| WONO, R | 8302170198 | NUREG | YOUNG, T | 8302010390* | 50-528 Q | ZIMMERMAN, J V | 8302090216 | XPORTLIC |
| WONO, T | 8302020394 | 40-299 | YOUNG, T | 8302230264* | 50-312 Q | ZIMMERMAN, J V | 8302090220 | XPORTLIC |
| WONO, T | 8302100002 | 40-299 | YOUNG, T | 8302230268* | 50-528 Q | ZIMMERMAN, J V | 8302090231 | XPORTLIC |
| WONO, T | 8302230121 | 40-299 | YOUNG, T | 8302230271* | 50-312 Q | ZIMMERMAN, J V | 8302090235 | XPORTLIC |
| WOOD, H H | 8302170208 | NUREG | YOUNG, Y A | 8302230311* | 50-528 Q | ZIMMERMAN, J V | 8302220508 | XPORTLIC |
| WOOD, E C | 8302070312 | 50-309 S | YOUNG, Y A | 8302170279 | 40-8745 | ZIMMERMAN, J V | 8302220515 | XPORTLIC |
| WOOD, R L | 8302180205* | 50-358 A | YOUNG, Y A | 8302170301 | 40-8783 | ZIMMERMAN, J V | 8302220545 | XPORTLIC |
| WOODARD, H H | 8302230544 | 50-454 T | YOUNGBLOOD, B J | 8302040105 | 50-440 H | ZIMMERMAN, J V | 8302240224 | XPORTLIC |
| WOODARD, H H | 8302230544 | 50-454 T | YOUNGBLOOD, B J | 8302040130 | 50-441 E | ZIMMERMAN, J V | 8302240227 | XPORTLIC |
| WOODHEAD, C | 8302090437 | 50-142 Q | YOUNGBLOOD, B J | 8302040133 | 50-423 H | ZIMMERMAN, J V | 8302240348 | XPORTLIC |
| WOODHEAD, C P | 8302150508 | 50-341 Q | YOUNGBLOOD, B J | 8302040157* | 50-423 H | ZIMMERMAN, J V | 8302240376 | XPORTLIC |
| WOODHEAD, C P | 8302160199 | 50-142 Q | YOUNGBLOOD, B J | 8302040436 | 50-440 H | ZIMMERMAN, J V | 8302240378 | XPORTLIC |
| WOODHEAD, C P | 8302170103 | 50-142 Q | YOUNGBLOOD, B J | 8302040459 | 50-436 A | ZIMMERMAN, J V | 8302240387 | XPORTLIC |
| WOODSUM, H C | 8302070553 | 70-1143 | YOUNGBLOOD, B J | 8302100092 | 50-341 E | ZIMMERMAN, J V | 8302240387 | XPORTLIC |
| WOODSUM, H C | 8302070560* | 70-1143 | YOUNGBLOOD, B J | 8302100176 | 50-454 F | ZIMMERMAN, J V | 8302240396 | XPORTLIC |
| WOOLEVER, E J | 8302100329 | 50-412 Q | YOUNGBLOOD, B J | 8302100203 | 50-454 E | ZIMMERMAN, J V | 8302240396 | XPORTLIC |
| WOOLEVER, E J | 8302150027 | PR | YOUNGBLOOD, B J | 8302100208 | 50-456 A | ZIMMERMAN, J V | 8302250152 | XPORTLIC |
| WOOLEVER, E J | 8302150426 | 50-412 Q | YOUNGBLOOD, B J | 8302240103 | 50-454 E | ZIMMERMAN, J V | 8302250495 | XPORTLIC |
| WOOLEVER, E J | 8302250385 | 50-412 S | YOUNGBLOOD, B J | 8302240112 | 50-440 A | ZIMMERMAN, J V | 8302250500 | XPORTLIC |
| WOOLSEY, H T | 8302220263 | 40-299 | YOUNGBLOOD, B J | 8302240119 | 50-454 E | ZIMMERMAN, J V | 8302250502 | XPORTLIC |
| WOOLSEY, R | 8302010027 | 40-8084 | YOUNGBLOOD, B J | 8302240123 | 50-440 A | ZIMMERMAN, J V | 8302030576* | 50-244 Q |
| WOOLSEY, R T | 8302140191* | 40-299 | YOUNGBLOOD, B J | 8302240330 | 50-454 A | ZIMMERMAN, S R | 8302010442 | 50-400 R |
| WOOLSEY, R T | 8302160506* | 40-299 | YOUNGBLOOD, B J | 8302240333 | 50-482 A | ZIMMERMAN, S R | 8302010483 | 50-324 P |
| WOOLSEY, R T | 8302220065 | 40-8084 | YOUNGBLOOD, B J | 8302240144 | 50-440 Q | ZIMMERMAN, S R | 8302070208 | 50-324 P |
| WOOLSEY, R T | 8302220066* | 40-8084 | YOUNGBLOOD, B J | 8302280267* | 50-449 A | ZIMMERMAN, S R | 8302070271 | 50-261 P |
| WRAY, R | 8302240282* | 50-275 P | YOH, J R | 8302160300* | 50-416 P | ZIMMERMAN, S R | 8302230615 | 50-324 P |
| WRAY, R | 8302240292* | 50-275 P | YUHAS, G P | 8302230378* | 50-206 Q | ZIMMERMAN, S R | 8302150035 | 50-261 Q |
| WRIGHT, Q C | 8302150534* | 50-155 Q | YUNATO, H | 8302020362 | XPORTLIC | ZIMMERMAN, S R | 8302150235 | 50-400 D |
| WRIGHT, N A | 8302010557 | 50-329 T | YUNATO, H | 8302020364* | XPORTLIC | ZIMMERMAN, S R | 8302150709 | 50-261 P |
| WRIGHT, R H | 8302150607* | 50-389 Q | YUNDT, C P | 8302010418 | 50-344 S | ZIMMERMAN, S R | 8302180351 | 50-261 P |
| WULLER, O E | 8302080179 | 50-461 E | YUNDT, C P | 8302010561 | 50-344 S | ZIMMERMAN, S R | 8302230615 | 50-324 P |
| WULLER, O E | 8302150125 | 50-461 A | ZAHLER, R E | 8302040004 | 40-2061 | ZIMMERMAN, S R | 8302230615 | 50-324 P |
| WULLER, O E | 8302230131 | 50-461 V | ZAHLER, R E | 8302040005* | 40-2061 | ZIMMERMAN, S R | 8302240268 | 50-324 P |
| WULLER, O E | 8302230453 | 50-461 A | ZAHLER, R E | 8302040005* | 40-2061 | ZIMMERMAN, S R | 8302280360 | 50-261 P |
| WYKE, T F | 8302250406* | 50-269 P | ZAHLER, R E | 8302100426 | PRM | ZUDANS, Z | 8302080469 | ACRS |
| WYKE, T F | 8302250411* | 50-269 P | ZAHLER, R E | 8302100426 | PRM | ZUDANS, Z | 8302080469 | ACRS |
| YAMANA, K | 8302240373 | XPORTLIC | ZAHLER, R E | 8302160293 | 50-289 Q | ZUDANS, Z | 8302090011 | 50-382 Q |
| | | | | | | ZUDANS, Z | 8302090011 | 50-382 Q |
| | | | | | | ZUMWALT, L R | 8302020245* | CONTRACT |
| | | | | | | ZURAKOWSKI, P | 8302070311* | XPORTLIC |
| | | | | | | ZWETZIO, O B | 8302230666* | 50-275 Q |

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------------------|---------------------|---------------------|
| ATL-CIO | 8302250410* | 50-247 Q |
| Abdel-Khalick, B I | 8302160110* | 50-937 A |
| Advanced Medical Systems, Inc | 8302030602 | 71-9044 |
| Air Transport Association | 8302100464 | PR |
| Alabama Electric Cooperative, Inc | 8302170265 | 50-348 M |
| Alabama Power Co | 8302010021* | 50-348 F |
| | 8302010029* | 50-348 F |
| | 8302010095 | 50-348 S |
| | 8302010103* | 50-348 B |
| | 8302010916 | 50-364 B |
| | 8302010539 | 50-348 Q |
| | 8302030063* | 50-348 F |
| | 8302030068* | 50-348 F |
| | 8302030344 | 50-348 P |
| | 8302030344 | 50-348 P |
| | 8302070613 | 50-348 S |
| | 8302070614* | 50-348 S |
| | 8302070617* | 50-348 S |
| | 8302070620* | 50-348 S |
| | 8302080012 | 50-364 Q |
| | 8302080017* | 50-364 Q |
| | 8302080017* | 50-364 Q |
| | 8302090329 | 50-348 P |
| | 8302090329 | 50-348 P |
| | 8302090467* | 50-348 F |
| | 8302090467* | 50-348 F |
| | 8302090471* | 50-348 F |
| | 8302100245 | 50-348 P |
| | 8302100245 | 50-348 P |
| | 8302100248* | 50-348 P |
| | 8302100248* | 50-348 P |
| | 8302100338 | PR |
| | 8302100426 | PRH |
| | 8302130009 | 50-364 Q |
| | 8302160247 | 50-348 P |
| | 8302180247 | 50-348 P |
| | 8302220127 | 50-348 R |
| | 8302220131* | 50-348 R |
| | 8302220174 | 50-348 S |
| | 8302220199* | 50-348 S |
| | 8302220363 | 50-348 B |
| | 8302220367* | 50-348 B |
| | 8302220372* | 50-348 B |
| | 8302220408 | 50-364 R |
| | 8302220413* | 50-364 R |
| | 8302230197 | 50-364 P |
| | 8302230387 | 50-348 P |
| | 8302230387 | 50-348 P |
| | 8302230708 | 50-364 S |
| | 8302230711* | 50-364 S |
| | 8302280038 | 50-364 B |
| | 8302280042* | 50-364 B |
| | 8302280211 | 50-348 S |
| | 8302280211 | 50-348 S |
| | 8302170394* | CONTRACT |

Alderson Reporting

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|--|---------------------|---------------------|
| American College of Nuclear Physicians | 8302100404 | PR |
| American Electric Power Service Corp | 8302010663 | 50-315 F |
| | 8302010663 | 50-315 F |
| | 8302040256 | 50-315 J |
| | 8302080278 | 50-315 F |
| | 8302100313 | 50-315 P |
| American Mining Congress | 8302100401 | PRH |
| American Nuclear Insurers | 8302170361 | 50-293 J |
| American Nuclear Society | 8302100281 | NUREG |
| | 8302100284 | NUREG |
| | 8302140125 | PR |
| | 8302250079* | CONTRACT |
| American Society of Mechanical Engineers | 8302080433* | CONTRACT |
| | 8302170174* | TOPREP |
| Amersham Corp | 8302040450 | 71-9167 |
| | 8302040454* | 71-9167 |
| Anaheim, CA | 8302220337* | 50-361 P |
| | 8302220337* | 50-361 P |
| | 8302220339* | 50-361 P |
| | 8302220339* | 50-361 P |
| | 8302220339* | 50-361 P |
| Andrulis Research Corp | 8302280284* | 50-361 P |
| | 8302280284* | 50-361 P |
| | 8302280290* | CONTRACT |
| Antioch School of Law, Washington, DC | 8302100007 | FOIA |
| | 8302010577 | 50-355 Q |
| Argonne National Laboratory | 8302080143* | FOIA |
| | 8302080480 | 50-237 Q |
| | 8302090007 | ACRB |
| | 8302090009 | ACRB |
| Arizona Public Service Co | 8302010493 | 50-528 A |
| | 8302010493 | 50-528 A |
| | 8302010493 | 50-528 A |
| | 8302040554 | 70-2949 |
| | 8302070221 | 50-528 S |
| | 8302070221 | 50-528 S |
| | 8302070221 | 50-528 S |
| | 8302070249 | 50-529 S |
| | 8302070254 | 50-529 S |
| | 8302070259 | 50-529 S |
| | 8302070259 | 50-529 S |
| | 8302070387 | 50-529 S |
| | 8302070387 | 50-529 S |
| | 8302070483 | 50-528 S |
| | 8302070483 | 50-528 S |
| | 8302070483 | 50-528 S |
| | 8302070483 | 50-528 S |
| | 8302070483 | 50-528 S |
| | 8302080210 | 50-528 A |
| | 8302080210 | 50-528 A |
| | 8302080210 | 50-528 A |
| | 8302080362 | 50-528 E |
| | 8302080362 | 50-528 E |
| | 8302080362 | 50-528 E |
| | 8302080362* | 50-528 E |
| | 8302080367* | 50-528 E |
| | 8302080367* | 50-528 E |
| | 8302080367* | 50-528 E |
| | 8302100221 | 50-528 A |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|---|---------------------|---------------------|
| | 8302100221 | 50-528 A | | 8302230456 | 50-368 S |
| | 8302100221 | 50-528 A | | 8302230473* | 50-368 S |
| | 8302150186 | 50-528 S | | 8302230499 | 50-313 M |
| | 8302150186 | 50-528 S | | 8302230602* | 50-313 G |
| | 8302150186 | 50-528 S | | 8302280447 | 50-313 S |
| | 8302150625 | 50-528 S | | 8302280455* | 50-313 S |
| | 8302150625 | 50-528 S | Arkansas, State of | 8301310191 | State Prog |
| | 8302150625 | 50-528 S | | 8302170489* | CONTRACT |
| | 8302170498* | 50-528 F | Army, Dept of, Army Engineer Waterways
Experiment Station | 8302280006 | NUREG |
| | 8302170498* | 50-528 F | Army, Dept of, Headquarters Materiel
Development & Readiness Command | 8302100337 | PR |
| | 8302170498* | 50-528 F | | | |
| | 8302170503* | 50-528 F | | | |
| | 8302230326 | 50-528 E | Army, Dept of | 8302160502* | CONTRACT |
| | 8302230361 | 50-528 E | Army, Dept of, Corps of Engineers | 8302070637* | CONTRACT |
| | 8302230425 | 50-528 S | | 8302090270* | CONTRACT |
| | | | | 8302220453* | CONTRACT |
| | 8302230533 | 50-528 B | Associated Technologies, Inc | 8302230566 | TOPREP |
| | 8302230579 | 50-528 V | | | |
| | 8302280443 | 50-528 A | | 8302230574* | TOPREP |
| | 8302280443 | 50-528 A | Atlas Minerals | 8302100008 | 40-3453 |
| | 8302280443 | 50-528 A | | 8302100016* | 40-3453 |
| | 8302280443 | 50-528 A | Atomic Industrial Forum | 8302100343 | PR |
| | | | | 8302100406 | PRM |
| | 8302280492 | 50-528 A | | | |
| | 8302280492 | 50-528 A | | | |
| | 8302280492 | 50-528 A | | | |
| | 8302160025 | RES | | 8302140107 | PR |
| | 8302180218* | 50-113 G | Audubon Society | 8302160359 | 50-413 G |
| | | | | 8302160306 | 50-247 G |
| | | | | 8302220344 | 50-454 G |
| | | | | 8302170389* | CONTRACT |
| Arizona, Univ of | 8302250151 | NUREG | Automated Correspondence Systems, Inc | | |
| | 8302010489* | 50-313 G | | | |
| | 8302010490* | 50-368 G | Automatic Switch Co | 8302230194* | QA999 |
| | 8302010497* | 50-313 G | | 8302230204* | QA999 |
| | 8302010501* | 50-313 G | ik&D Insulation Inc | 8302230348* | 50-382 F |
| | | | | 8302230353* | 50-382 F |
| | 8302030315 | 50-313 G | | 8302230358* | 50-382 F |
| | 8302030315 | 50-313 G | | | |
| | 8302030391 | 50-313 F | | 8302230368* | 50-382 F |
| | 8302030405 | 50-313 P | BWR Owners Group | 8302010525 | TOPREP |
| | 8302030406 | 50-313 P | Babcock & Wilcox Co | 8211020469* | 50-289 G |
| | | | | 8302020316* | 50-312 P |
| | 8302030409* | 50-313 P | | 8302040494 | 70-1201 |
| | 8302030411* | 50-313 G | | | |
| | 8302030520 | 50-328 G | | 8302040559 | 70-27 |
| | 8302070277* | 50-313 F | | 8302040589 | 70-27 |
| | 8302070299* | 50-313 F | | 8302040604 | 70-27 |
| | | | | 8302070022 | 70-27 |
| | 8302070361 | 50-313 B | | 8302070031 | 70-135 |
| | 8302070363* | 50-313 B | | | |
| | 8302070456 | 50-313 P | | 8302070178* | 70-1201 |
| | 8302070468* | 50-313 G | | 8302080379 | 70-1201 |
| | 8302070497 | 50-313 P | | 8302080381 | 70-1201 |
| | | | | 8302080389 | 70-27 |
| | 8302070497 | 50-313 P | | 8302090050 | 70-1201 |
| | 8302070552* | 50-313 G | | | |
| | 8302070575 | 50-313 P | | 8302100362 | PR |
| | 8302070575 | 50-313 P | | 8302100451 | PR |
| | 8302070609 | 50-313 G | | 8302160152 | TOPREP |
| | | | | 8302160171* | 50-313 F |
| | 8302090315 | 50-368 P | | 8302160330* | 50-289 G |
| | 8302150011 | 50-368 P | | | |
| | 8302150016* | 50-368 P | | 8302160393 | 70-1201 |
| | 8302150116 | 50-313 G | | 8302160397* | 70-1201 |
| | 8302150238 | 50-313 G | | 8302180436* | 50-313 P |
| | | | | 8302220142 | TOPREP |
| | 8302150492 | 50-368 P | | 8302220281 | TOPREP |
| | 8302160149 | 50-313 P | | | |
| | 8302160160 | 50-313 P | | 8302220423* | 50-269 G |
| | 8302160169 | 50-313 F | | 8302250323 | PR |
| | 8302170064 | 50-313 S | Babcock & Wilcox Operating Plants Owners
Group | 8302090389 | TOPREP |
| | 8302170068* | 50-313 S | Dackus, Shea & Meyer | | |
| | 8302170133 | 50-368 S | | 8302080185 | 50-443 G |
| | 8302170134* | 50-368 S | | 8302080185 | 50-443 G |
| | 8302170232 | 50-368 S | | | |
| | 8302170237* | 50-368 S | | 8302080238 | 50-443 G |
| | | | | 8302080238 | 50-443 G |
| | 8302170372 | 50-368 B | | 8302170201 | 50-443 G |
| | 8302170377* | 50-368 B | | 8302170201 | 50-443 G |
| | 8302170517* | 50-313 F | | 8302170204 | 50-443 G |
| | 8302170517* | 50-313 F | | | |
| | 8302180223 | 50-313 F | Baltimore Gas & Electric Co | 8302170284 | 50-443 G |
| | | | | 8302010117* | 50-317 F |
| | 8302180223 | 50-313 F | | 8302010117* | 50-317 F |
| | 8302180393 | 50-368 G | | 8302010126* | 50-317 F |
| | 8302180430 | 50-313 P | | 8302010126* | 50-317 F |
| | 8302180469 | 50-313 P | | | |
| | 8302180469 | 50-313 P | | 8302010163 | 50-318 S |
| | | | | 8302010175* | 50-318 S |
| | 8302180472* | 50-313 P | | 8302010180 | 50-318 S |
| | 8302180472* | 50-313 P | | 8302010189* | 50-318 S |
| | 8302220236 | 50-313 P | | 8302010198 | 50-317 S |
| | 8302220273 | 50-313 P | | | |
| | 8302220280* | 50-313 P | | 8302010205* | 50-317 S |
| | | | | 8302010330 | 50-317 S |
| | 8302220354 | 50-313 P | | 8302010337* | 50-317 S |
| | 8302230403 | 50-313 P | | 8302010341 | 50-318 S |
| | 8302230403 | 50-313 P | | 8302010345* | 50-318 S |
| | 8302230408* | 50-313 P | | | |
| | 8302230408* | 50-313 P | | 8302010348 | 50-317 S |
| | | | | 8302010349 | 50-318 S |

CORPORATE SOURCE INDEX

48

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|--|---------------------|---------------------|---|---------------------|---------------------|
| | 8302010352* | 50-318 S | | 8302070124 | RES |
| | 8302010354* | 50-317 S | | 8302070157* | FOIA |
| | 8302010383 | 50-317 S | | 8302170061* | 50-285 Q |
| | 8302010389* | 50-317 S | | 8302250046 | NUREQ |
| | 8302010392* | 50-317 Q | | 8302250053 | NUREQ |
| | 8302010555 | 50-318 S | | 8302250094 | NUREQ |
| | 8302010560* | 50-318 S | | 8302250146 | NUREQ |
| | 8302010566 | 50-318 S | | 7902020122* | FOIA |
| | 8302010571* | 50-318 S | | 7904250165* | FOIA |
| | 8302040265 | 50-317 Q | | 7905270339* | FOIA |
| | 8302040265 | 50-317 Q | | 7908220373* | FOIA |
| | 8302070290* | 50-317 F | | 7911210270* | FOIA |
| | 8302070290* | 50-317 F | | 8004250184* | FOIA |
| | 8302070292* | 50-317 F | | 8010090461* | FOIA |
| | 8302070379 | 50-317 S | | 8302240235* | FOIA |
| | 8302070390* | 50-317 S | | 8302240250* | FOIA |
| | 8302070405 | 50-317 S | | 8302240255* | FOIA |
| | 8302070411 | 50-317 S | | 8302240270* | FOIA |
| | 8302070415* | 50-317 S | | 8302240277* | FOIA |
| | 8302070418* | 50-317 S | | 8302240288* | FOIA |
| | 8302070421 | 50-318 S | | 8302240293* | FOIA |
| | 8302070427* | 50-318 S | | 8302040329 | 50-329 S |
| | 8302070473 | 50-317 P | | 8302070493* | 50-528 S |
| | 8302070593 | 50-318 S | | 8302140097 | REPOD |
| | 8302070606* | 50-318 S | | 8302140101* | REPOD |
| | 8302080272* | 50-317 Q | | 8302150206* | 50-331 R |
| | 8302080435* | 50-317 F | | 8302150398* | 50-329 T |
| | 8302080435* | 50-317 F | | 8302280020 | NUREQ |
| | 8302080440* | 50-317 F | | 8302230544 | 50-454 T |
| | 8302080440* | 50-317 F | | 8302230350 | 50-528 Q |
| | 8302090188 | 50-318 S | | 8302160348 | 50-338 Q |
| | 8302090203* | 50-318 S | | 8302040521 | NUREQ |
| | 8302090285 | 50-317 P | | 8302010333 | 50-293 S |
| | 8302090316 | 50-317 S | | 8302030289 | 50-293 P |
| | 8302090319 | 50-318 P | | 8302070464 | 50-293 S |
| | 8302090321* | 50-317 S | | 8302070467* | 50-293 S |
| | 8302090372 | 50-318 S | | 8302080160 | 50-293 P |
| | 8302090377* | 50-318 S | | 8302080192 | 50-293 P |
| | 8302090395 | 50-317 S | | 8302090605* | 50-293 R |
| | 8302090399* | 50-317 S | | 8302090609* | 50-293 R |
| | 8302090420 | 50-318 S | | 8302090617* | 50-293 R |
| | 8302090422* | 50-318 S | | 8302100342* | 50-293 Q |
| | 8302100283 | PR | | 8302100388 | 50-293 S |
| | 8302100339 | PRM | | 8302100395* | 50-293 S |
| | 8302170334 | 50-318 P | | 8302140090 | 50-293 Q |
| | 8302180010* | 50-317 F | | 8302220170 | 50-293 F |
| | 8302180010* | 50-317 F | | 8302220348 | 50-293 S |
| | 8302180012* | 50-317 F | | 8302220331* | 50-293 S |
| | 8302180012* | 50-317 F | | 8302220391 | 50-293 S |
| | 8302180050* | 50-317 F | | 8302220393* | 50-293 S |
| | 8302180050* | 50-317 F | | 8302230190 | 50-293 P |
| | 8302180257 | 50-317 S | | 8302230642 | 50-293 Q |
| | 8302180269* | 50-317 S | | 8302230658 | 50-293 P |
| | 8302230162 | 50-317 R | | 8302250322 | PR |
| | 8302230167* | 50-317 R | | 8212290219* | 50-352 Q |
| | 8302230222 | 50-318 S | | 8302070124 | RES |
| | 8302230227 | 50-317 S | | 8302080482 | RES |
| | 8302230303 | 50-317 S | | 8302170104* | 50-322 A |
| | 8302230306* | 50-317 S | | 8302170109* | 50-322 A |
| | 8302230463 | 50-317 S | | 8302170195* | 50-322 A |
| | 8302230476* | 50-317 S | | 8302170197* | 50-322 A |
| | 8302230507 | 50-317 P | | 8302220426 | NUREQ |
| | 8302230605 | 50-317 S | | 8302220431 | NUREQ |
| | 8302230616* | 50-317 S | | 8302240011 | RES |
| | 8302230698 | 50-317 S | | 8302240359 | 27-47 |
| | 8302230701* | 50-317 S | | 8302240360 | RES |
| | 8302230716 | 50-318 S | | 8302240361 | RES |
| | 8302230722* | 50-318 S | | 8302250039 | RES |
| | 8302250050* | 50-317 F | | 8302250049 | 50-320 P |
| | 8302250050* | 50-317 F | | 8302250129 | NUREQ |
| | 8302250188 | 50-318 S | | 8302080173* | 50-445 Q |
| | 8302250195* | 50-318 S | | 8212140330 | 50-315 S |
| | 8302250196 | 50-317 S | | 8302040164 | 50-546 S |
| | 8302250199* | 50-317 S | | 8302030423* | QA999 |
| | 8302250402 | 50-318 S | | 8302030431* | QA999 |
| | 8302250404* | 50-318 S | | 8302030435* | QA999 |
| | 8302250408 | 50-317 V | | 8302030444* | QA999 |
| | 8302280174 | 50-317 P | | 8302030452* | QA999 |
| | 8302100081* | CONTRACT | | 8302080153* | 50-219 P |
| | 8302040306* | CONTRACT | | 8302090404* | 50-397 Q |
| | 8302040398* | 50-289 P | | 8302180324 | 50-537 D |
| | 8302220459* | CONTRACT | | 8302020362 | XPORTLIC |
| | 8210130458* | FOIA | | 8302020364* | XPORTLIC |
| Harr Engineering Co | | | Brown & Root Corp (subs of Halliburton Corp) | | |
| Battelle Memorial Institute, Columbus Laboratories | | | Brown Boveri Corp (subs Brown Boveri & Co, Ltd) | | |
| | | | Bunker Ramo-Eltra Corp. | | |
| | | | Burns & Roe Co | | |
| | | | C Itah & Co (America), Inc | | |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|------------------------------------|---------------------|---------------------|---------------------------------------|---------------------|---------------------|
| CLOW Corp | 8302020371 | XPORTLIC | | 8302150023 | 50-324 S |
| | 8302030544* | GA999 | | 8302150026* | 50-324 S |
| | 8302030556* | GA999 | | 8302150031* | 50-261 Q |
| CONOCO, Inc (Continental Oil Co) | 8302010073 | 40-8743 | | 8302150040 | 50-325 P |
| | 8302240092 | 40-8743 | | 8302150043* | 50-325 P |
| California, State of | 8302010464 | 50-275 Q | | 8302150046 | 50-261 P |
| California, Univ of, Berkeley | 8302080467 | ACRS | | 8302150055 | 50-261 Q |
| | 8302080472 | ACRS | | 8302150080 | 50-324 Q |
| California, Univ of, Irvine | 8302230147* | 50-324 Q | | 8302150080 | 50-324 Q |
| California, Univ of, Los Angeles | 8302020236* | CONTRACT | | 8302150093* | 50-261 Q |
| | 8302170198 | NUREC | | 8302150119 | 50-324 S |
| | 8302180259 | 50-142 P | | 8302150129* | 50-324 S |
| | 8302220116* | 50-142 Q | | 8302150172 | 50-324 S |
| | 8302220119* | 50-142 F | | 8302150172 | 50-324 S |
| California, Univ of, Santa Barbara | 8302030209 | NUREC | | 8302150177 | 50-400 S |
| Carolina Power & Light Co | 8301170409 | 50-324 S | | 8302150195 | 50-324 P |
| | 8301170414* | 50-324 S | | 8302150205 | 50-261 P |
| | 8302010080 | 50-324 S | | 8302150255 | 50-400 Q |
| | 8302010083* | 50-324 S | | 8302150263 | 50-261 Q |
| | 8302010087 | 50-324 S | | 8302150290 | 50-261 Q |
| | 8302010092* | 50-324 S | | 8302150330* | 50-324 Q |
| | 8302010234 | 50-325 S | | 8302150374 | 50-261 Q |
| | 8302010240* | 50-325 S | | 8302150394 | 50-324 P |
| | 8302010267 | 50-324 S | | 8302150394 | 50-324 P |
| | 8302010272 | 50-400 S | | 8302150518* | 50-324 Q |
| | 8302010272 | 50-400 S | | 8302150602 | 50-324 P |
| | 8302010277* | 50-324 S | | 8302150602 | 50-324 P |
| | 8302010281 | 50-324 S | | 8302150617 | 50-261 P |
| | 8302010287* | 50-324 S | | 8302150642 | 50-324 R |
| | 8302010319 | 50-261 S | | 8302150650* | 50-324 R |
| | 8302010361 | 50-400 S | | 8302150650* | 50-324 R |
| | 8302010361 | 50-400 S | | 8302150677 | 50-261 S |
| | 8302010363 | 50-325 S | | 8302150683* | 50-261 S |
| | 8302010367* | 50-325 S | | 8302150709 | 50-261 P |
| | 8302010371 | 50-324 S | | 8302160305 | TOPREP |
| | 8302010375* | 50-324 S | | 8302160344 | 50-261 Q |
| | 8302010442 | 50-400 R | | 8302170065 | 50-261 R |
| | 8302010442 | 50-400 R | | 8302170070* | 50-261 R |
| | 8302010445* | 50-400 R | | 8302170074 | 50-324 S |
| | 8302010445* | 50-400 R | | 8302170084* | 50-324 S |
| | 8302010454 | 50-324 S | | 8302170093 | 50-324 S |
| | 8302010457* | 50-324 S | | 8302170101* | 50-324 S |
| | 8302010468 | 50-324 P | | 8302170172 | 50-325 S |
| | 8302010468 | 50-324 P | | 8302170177 | 50-325 S |
| | 8302010473* | 50-324 P | | 8302170178 | 50-324 S |
| | 8302010473* | 50-324 P | | 8302170183* | 50-325 S |
| | 8302010483 | 50-324 P | | 8302170184* | 50-324 S |
| | 8302010483 | 50-324 P | | 8302170248 | 50-400 S |
| | 8302010563 | 50-324 S | | 8302180161 | 50-261 P |
| | 8302010573* | 50-324 S | | 8302180351 | 50-261 P |
| | 8302010580 | 50-400 S | | 8302180392* | 50-261 P |
| | 8302010580 | 50-400 S | | 8302230166 | 50-324 S |
| | 8302010590 | 50-400 S | | 8302230169* | 50-324 S |
| | 8302010590 | 50-400 S | | 8302230270 | 50-261 P |
| | 8302010601 | 50-325 S | | 8302230417 | 50-400 Q |
| | 8302010619* | 50-325 S | | 8302230417 | 50-400 Q |
| | 8302010626 | 50-324 S | | 8302230496 | 50-400 Q |
| | 8302010634* | 50-324 S | | 8302230496 | 50-400 Q |
| | 8302030180 | 50-400 Q | | 8302230589 | 50-400 Q |
| | 8302030187 | 50-325 S | | 8302230589 | 50-400 Q |
| | 8302030304 | 50-400 S | | 8302230596* | 50-400 Q |
| | 8302030304 | 50-400 S | | 8302230596* | 50-400 Q |
| | 8302030385 | 50-325 S | | 8302230615 | 50-324 P |
| | 8302030401 | 50-325 S | | 8302240245 | 50-325 S |
| | 8302030410 | 50-324 S | | 8302240251* | 50-325 S |
| | 8302030414 | 50-324 S | | 8302240265 | 50-324 P |
| | 8302030420* | 50-324 S | | 8302280066 | 50-324 S |
| | 8302030422* | 50-324 S | | 8302280074* | 50-324 S |
| | 8302030503 | 50-324 S | | 8302280173 | 50-400 S |
| | 8302030510* | 50-324 S | | 8302280173 | 50-400 S |
| | 8302070208 | 50-324 P | | 8302280217 | 50-261 S |
| | 8302070208 | 50-324 P | | 8302280219 | 50-324 S |
| | 8302070271 | 50-400 D | | 8302280222* | 50-261 S |
| | 8302070490 | 50-400 Q | | 8302280250 | 50-325 S |
| | 8302090292 | TOPREP | | 8302280257* | 50-325 S |
| | 8302090434 | 50-261 P | | 8302280360 | 50-261 P |
| | 8302100290 | 50-261 P | | 8302280363* | 50-261 P |
| | 8302100293* | 50-261 P | | 8302280502 | 50-324 S |
| | 8302140010 | 50-324 S | | 8302280507* | 50-324 S |
| | 8302140012* | 50-324 S | | 8302170205 | NUREC |
| | 8302140042 | 50-324 S | | 8302240122* | CONTRACT |
| | 8302140049* | 50-324 S | | 8302070573 | 50-483 Q |
| | 8302140134 | 50-325 S | | 8302040005* | 40-2061 |
| | 8302140142* | 50-325 S | | | |
| | 8302150014* | 50-261 Q | | | |
| | | | Catholic Univ | | |
| | | | Centennial Systems, Inc | | |
| | | | Charles & Moore | | |
| | | | Chadwell, Kayser, Ruggles, McBee & | | |
| | | | Hastings, Ltd | | |
| | | | Chapel Hill Anti-Nuclear Group Effort | | |
| | | | | 8302230568 | 50-400 Q |

CORPORATE SOURCE INDEX

48

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|--|---------------------|---------------------|
| Chem-Nuclear Systems, Inc | 8302230568 | 50-400 Q | | 8302070261 | 50-440 Q |
| | 8302230579* | 50-400 Q | | 8302070261 | 50-440 Q |
| | 8302230579* | 50-400 Q | | 8302070301 | 50-440 E |
| | 8302090390 | TOPREP | | 8302070301 | 50-440 E |
| | 8302090394* | TOPREP | | 8302070313 | 50-440 E |
| Chicago Bridge & Iron Co | 8302250439 | 27-47 | | 8302070313 | 50-440 E |
| | 8302150328* | 0A999 | | 8302070325 | 50-440 E |
| | 8302150337* | 0A999 | | 8302070325 | 50-440 E |
| | 8302010977 | 50-185 Q | | 8302070555 | 50-440 Q |
| | 8302010223 | 50-358 S | | 8302070555 | 50-440 Q |
| Christa-Maria
Cincinnati Gas & Electric Co | 8302010535 | 50-358 C | | 8302080167 | 50-440 Q |
| | 8302010541* | 50-358 C | | 8302080323 | 50-440 S |
| | 8302010545 | 50-358 K | | 8302100202 | 50-440 Q |
| | 8302010549* | 50-358 K | | 8302100202 | 50-440 Q |
| | 8302010575 | 50-358 A | | 8302100209* | 50-440 Q |
| | 8302010638 | 50-358 S | | 8302100209* | 50-440 Q |
| | 8302010647 | 50-424 S | | 8302100213* | 50-440 Q |
| | 8302040083 | 50-358 A | | 8302100213* | 50-440 Q |
| | 8302040087* | 50-358 A | | 8302150216 | 50-440 S |
| | 8302040423 | 50-358 S | | 8302150509 | 50-440 E |
| | 8302040432 | 50-358 Q | | 8302150509 | 50-440 E |
| | 8302080169 | 50-358 A | | 8302160209* | 50-440 Q |
| | 8302080291 | 50-358 S | | 8302160209* | 50-440 Q |
| | 8302080299 | 50-358 S | | 8302170338 | 50-440 K |
| | 8302080325 | 50-358 S | | 8302170338 | 50-440 K |
| | 8302140006 | 50-358 C | | 8302170340* | 50-440 K |
| | 8302150338 | 50-358 A | | 8302170340* | 50-440 K |
| | 8302150377 | 50-358 B | | 8302180434* | 50-440 Q |
| | 8302150529 | 50-358 S | | 8302180434* | 50-440 Q |
| | 8302170037 | 50-358 K | | 8302230580 | 50-440 Q |
| | 8302180083* | 50-358 A | | 8302230580 | 50-440 Q |
| | 8302180111* | 50-358 A | | 8302230719 | 50-440 A |
| | 8302180120* | 50-358 A | | 8302280160 | 50-440 Q |
| | 8302180124* | 50-358 A | | 8302280160 | 50-440 Q |
| | 8302180130* | 50-358 A | | 8302280208 | 50-440 E |
| | 8302180132* | 50-358 A | | 8302280208 | 50-440 E |
| | 8302180137* | 50-358 A | | 8302280239 | 50-440 A |
| | 8302180140* | 50-358 A | | 8302280239 | 50-440 A |
| | 8302180144* | 50-358 A | | 8302280266 | 50-440 Q |
| | 8302180147* | 50-358 A | | 8302280266 | 50-440 Q |
| | 8302180151* | 50-358 A | Cleveland-Cliffs Iron Co | 8302280306 | 50-440 V |
| | 8302180155* | 50-358 A | | 8302280306 | 50-440 V |
| | 8302180158* | 50-358 A | | 8302280513* | 50-440 Q |
| | 8302180160* | 50-358 A | | 8302100085 | 40-8714 |
| | 8302180164* | FOIA | | 8302100456 | PRM |
| | 8302180169* | 50-358 A | Coalition for Nuclear Power Plant
Postponement | 8302160302 | 50-522 Q |
| | 8302180185* | 50-358 A | | 8302160354 | 50-440 Q |
| | 8302180188* | 50-358 A | | 8302160356 | 50-440 Q |
| | 8302180194* | 50-358 A | | 8302160362 | 50-440 Q |
| | 8302180197* | 50-358 A | | 8302250353 | PR |
| | 8302180205* | 50-358 A | Cofer, Beauchamp, Hawes & Brown | 8302250357* | PR |
| | 8302180223 | 50-358 S | | 8302100098* | CONTRACT |
| | 8302180270 | 50-358 S | | 8302100190* | 40-8102 |
| | 8302180356* | 50-358 A | | 8302250201 | 50-354 S |
| | 8302180446 | 50-358 S | | 8302030182 | 50-522 Q |
| | 8302180470 | 50-358 S | Colorado State Univ | 8302160302 | 50-522 Q |
| | 8302230529 | 50-358 Q | | 8302040462* | CONTRACT |
| | 8302280229 | 50-358 V | | 8302230025 | NUREG |
| | 8302280348 | 50-358 A | | 8302010431 | 50-470 A |
| | 8302280435 | 50-358 S | | 8302070054 | 70-1100 |
| Citizens Association for Sound Energy | 8302020240 | 50-445 Q | Colt Industries, Inc | 8302070194* | 50-382 A |
| | 8302020240 | 50-445 Q | | 8302070331* | 50-382 A |
| | 8302020331 | 50-445 Q | | 8302070621* | 50-382 A |
| | 8302020331 | 50-445 Q | | 8302080021 | 70-36 |
| | 8302080171 | 50-445 Q | | 8302090391* | 0A999 |
| | 8302080171 | 50-445 Q | Columbia River Inter-Tribal Fish
Commission | 8302100356 | PR |
| | 8302080173* | 50-445 Q | | 8302100362 | PR |
| | 8302080173* | 50-445 Q | | 8302180157 | 70-1100 |
| | 8302080187 | 50-445 Q | | 8302220153* | 70-1100 |
| | 8302080187 | 50-445 Q | | 8302240290 | 50-470 E |
| Citizens for Energy & Employment | 8302160343 | 50-341 Q | Columbia Univ | 8302250356 | PR |
| | 8302220309 | 50-341 Q | | 8302010633* | 70-398 |
| | 8212020091 | 50-440 K | | 8302040008 | 71-6850 |
| | 8212020098* | 50-440 K | | 8302090534 | 70-398 |
| | 8302040038 | 50-440 C | | 8302090538* | 70-398 |
| Cleveland Electric Illuminating Co | 8302040038 | 50-440 E | Commerce, Dept. of, National Bureau of
Standards | 8302220003* | 50-390 A |
| | 8302040061 | 50-440 S | | 8302280020 | NUREG |
| | 8302040061 | 50-440 S | | 8210180452 | 50-275 F |
| | 8302040366* | 50-440 Q | | 8210180452 | 50-275 F |
| | 8302040368* | 50-440 Q | | 8210180452 | 50-275 F |
| | 8302040400 | 50-440 E | Commerce, Dept. of, Natl Oceanographic &
Atmospheric Administration | 8210180452 | 50-275 F |
| | 8302040400 | 50-440 E | | 8210180452 | 50-275 F |
| | 8302040597 | 70-2968 | | 8210180452 | 50-275 F |
| | 8302070196 | 50-440 F | | | |
| | 8302070196 | 50-440 F | | | |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|-----------------------|---------------------|---------------------|
| Committee to Bridge the Gap

Commonwealth Edison Co | 8210150452 | 50-275 F | | 8302040349 | 50-304 S |
| | 8210150452 | 50-275 F | | 8302040353* | 50-304 S |
| | 8210150452 | 50-275 F | | 8302040370 | 50-454 S |
| | 8210150452 | 50-275 F | | 8302040370 | 50-454 S |
| | 8210150459* | 50-275 F | | 8302040370 | 50-454 S |
| | 8210150459* | 50-275 F | | 8302040387 | 50-237 S |
| | 8301270044* | 50-275 F | | 8302040391* | 50-237 S |
| | 8301270044* | 50-275 F | | 8302040394 | 50-265 S |
| | 8301270051* | 50-275 F | | 8302040397* | 50-265 S |
| | 8301270051* | 50-275 F | | 8302070215 | 50-237 F |
| | 8301270060* | 50-275 F | | 8302070220* | 50-237 F |
| | 8301270060* | 50-275 F | | 8302070274 | 50-237 F |
| | 8301270060* | 50-275 F | | 8302070274 | 50-237 F |
| | 8302160184 | 50-142 Q | | 8302070274 | 50-237 F |
| | 8302180408 | 50-142 Q | | 8302070274 | 50-237 F |
| | 8302180414* | 50-142 G | | 8302070460 | 50-374 A |
| | 8302230523 | 50-142 G | | 8302070542 | 50-599 Q |
| | 8302010122 | 50-373 S | | 8302080152 | 50-454 C |
| | 8302010127* | 50-373 S | | 8302080154* | 50-454 C |
| | 8302010132 | 50-265 S | | 8302080199 | 50-373 P |
| | 8302010140* | 50-265 S | | 8302080199 | 50-373 P |
| | 8302010147 | 50-237 S | | 8302080259 | 50-373 S |
| | 8302010152* | 50-237 S | | 8302080265* | 50-373 S |
| | 8302010173 | 50-295 S | | 8302080277 | 50-237 Q |
| | 8302010185* | 50-295 S | | 8302080277 | 50-237 Q |
| | 8302010269 | 50-237 S | | 8302080277 | 50-237 Q |
| | 8302010276* | 50-237 S | | 8302080277 | 50-237 Q |
| | 8302010286 | 50-373 P | | 8302080277 | 50-237 Q |
| | 8302010294 | 50-254 P | | 8302080284 | 50-304 U |
| | 8302010294 | 50-254 P | | 8302080287* | 50-304 U |
| | 8302010373 | 50-373 S | | 8302080292 | 50-254 U |
| | 8302010376 | 50-237 S | | 8302080297* | 50-254 U |
| | 8302010381* | 50-237 S | | 8302080303 | 50-265 P |
| | 8302010385* | 50-373 S | | 8302080322* | 50-10 F |
| | 8302010429 | 50-237 P | | 8302080344 | 50-249 S |
| | 8302010429 | 50-237 P | | 8302080349 | 70-2973 |
| | 8302010429 | 50-237 P | | 8302080353 | 50-249 S |
| | 8302010429 | 50-237 P | | 8302080356* | 50-249 S |
| | 8302010540 | 50-254 S | | 8302080359* | 50-249 S |
| | 8302010553* | 50-254 S | | 8302080368* | 50-254 F |
| | 8302010529* | 50-295 Q | | 8302080368* | 50-254 F |
| | 8302020470* | 50-10 F | | 8302080372* | 50-254 F |
| | 8302020470* | 50-10 F | | 8302090457 | 50-295 P |
| | 8302020479* | 50-10 F | | 8302090464* | 50-295 P |
| | 8302020479* | 50-10 F | | 8302090464* | 50-295 P |
| | 8302020479* | 50-10 F | | 8302100214 | 50-237 P |
| | 8302030139* | 50-295 F | | 8302100217* | 50-237 P |
| | 8302030143* | 50-295 F | | 8302100224 | 50-237 P |
| | 8302030238* | 50-295 F | | 8302100224 | 50-237 P |
| | 8302030238* | 50-295 F | | 8302100287 | PR |
| | 8302030245* | 50-295 F | | 8302100291 | PR |
| | 8302030424* | 50-295 F | | 8302100380 | PRM |
| | 8302030426* | 50-295 F | | 8302100422* | PR |
| | 8302040037* | 50-10 F | | 8302150044 | 50-254 R |
| | 8302040037* | 50-10 F | | 8302150044 | 50-254 R |
| | 8302040037* | 50-10 F | | 8302150048* | 50-254 R |
| | 8302040037* | 50-10 F | | 8302150048* | 50-254 R |
| | 8302040037* | 50-10 F | | 8302150114 | 50-254 S |
| | 8302040048* | 50-10 F | | 8302150124* | 50-254 S |
| | 8302040050 | 50-254 S | | 8302150183 | 50-454 S |
| | 8302040053 | 50-374 S | | 8302150419 | 50-454 S |
| | 8302040054* | 50-254 S | | 8302150516* | 50-249 Q |
| | 8302040056 | 50-237 S | | 8302150528 | 50-10 Q |
| | 8302040070* | 50-237 S | | 8302150528 | 50-10 Q |
| | 8302040171 | 50-254 S | | 8302150528 | 50-10 Q |
| | 8302040176 | 50-373 S | | 8302150528 | 50-10 Q |
| | 8302040187* | 50-373 S | | 8302150528 | 50-10 Q |
| | 8302040189* | 50-254 S | | 8302150528 | 50-10 Q |
| | 8302040214* | 50-254 F | | 8302150600 | 50-237 R |
| | 8302040214* | 50-254 F | | 8302150600 | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| | 8302040220* | 50-254 F | | 8302150606* | 50-237 R |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50-254 F | | 8302150606* | 50-237 R | |
| 8302040220* | 50 | | | | |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|--------------------------------------|---------------------|---------------------|
| | 8302160165 | 50-454 A | | 8302220520* | 10CFR |
| | 8302160165 | 50-454 A | | 8302230130* | 50-10 P |
| | 8302160165 | 50-454 A | | 8302230159 | 50-295 P |
| | 8302160190 | 50-237 S | | 8302230199 | 50-295 P |
| | 8302160198* | 50-237 S | | 8302230446 | 50-454 Q |
| | 8302160222 | 50-237 S | | 8302230446 | 50-454 Q |
| | 8302160223 | 50-454 Q | | 8302230455 | 50-454 T |
| | 8302160223 | 50-454 Q | | 8302230518 | 50-373 P |
| | 8302160226* | 50-237 S | | 8302230518 | 50-373 P |
| | 8302160227* | 50-454 Q | | 8302230540 | 50-454 Q |
| | 8302160227* | 50-454 Q | | 8302230703 | 50-237 S |
| | 8302170149 | 50-454 E | | 8302230706* | 50-237 S |
| | 8302170149 | 50-454 E | | 8302230168 | 50-373 S |
| | 8302170149 | 50-454 E | | 8302230173* | 50-373 S |
| | 8302170149 | 50-454 E | | 8302230179 | 50-254 P |
| | 8302170149 | 50-454 E | | 8302230183* | 50-254 P |
| | 8302170159 | 50-295 R | | 8302230187 | 50-295 S |
| | 8302170159 | 50-295 R | | 8302230189 | 50-237 P |
| | 8302170163* | 50-295 R | | 8302230189 | 50-237 P |
| | 8302170163* | 50-295 R | | 8302230190* | 50-295 S |
| | 8302170187 | 50-373 K | | 8302230192* | 50-237 P |
| | 8302170187 | 50-373 K | | 8302230192* | 50-237 P |
| | 8302170191* | 50-373 K | | 8302230193 | 50-304 S |
| | 8302170292 | 50-454 T | | 8302230197* | 50-304 S |
| | 8302170292 | 50-454 T | | 8302230209 | 50-373 S |
| | 8302170297* | 50-373 Q | | 8302230212 | 50-237 P |
| | 8302170298* | 50-454 T | | 8302230212 | 50-237 P |
| | 8302170298* | 50-454 T | | 8302230215* | 50-373 S |
| | 8302170302* | 50-454 T | | 8302230218* | 50-237 P |
| | 8302170302* | 50-454 T | | 8302230218* | 50-237 P |
| | 8302170315* | 50-373 Q | | 8302230220 | 50-373 S |
| | 8302170345 | 50-237 P | | 8302230228* | 50-373 S |
| | 8302170347* | 50-237 P | | 8302230235 | 50-254 P |
| | 8302180126* | 50-10 F | | 8302230226 | 50-373 S |
| | 8302180126* | 50-10 F | | 8302230229 | 50-254 Q |
| | 8302180126* | 50-10 F | | 8302230296* | 50-373 S |
| | 8302180126* | 50-10 F | | 8302230307 | 50-373 S |
| | 8302180152 | 50-295 S | | 8302230308* | 50-254 Q |
| | 8302180156* | 50-10 F | | 8302230313* | 50-373 S |
| | 8302180156* | 50-10 F | | 8302230361* | 50-237 F |
| | 8302180156* | 50-10 F | | 8302230361* | 50-237 F |
| | 8302180159* | 50-295 S | | 8302230361* | 50-237 F |
| | 8302180296 | 50-237 P | | 8302230361* | 50-237 F |
| | 8302180379 | 50-454 A | | 8302230361* | 50-237 F |
| | 8302180379 | 50-454 A | | 8302230361* | 50-237 F |
| | 8302180379 | 50-454 A | | 8302230361* | 50-237 F |
| | 8302180387 | 50-454 T | | 8302230390 | 50-373 S |
| | 8302180387 | 50-454 T | | 8302230395 | 50-373 S |
| | 8302180417 | 50-295 P | | 8302230397* | 50-373 S |
| | 8302180459 | 50-373 S | | 8302230401* | 50-373 S |
| | 8302180463* | 50-454 Q | | 8302280204 | 50-454 K |
| | 8302180463* | 50-454 Q | | 8302280204 | 50-454 K |
| | 8302180467* | 50-373 S | | 8302280206 | 50-440 F |
| | 8302180498* | 50-10 F | | 8302280212* | 50-454 K |
| | 8302180508* | 50-10 F | | 8302280212* | 50-454 K |
| | 8302180520* | 50-295 F | | 8302280303* | 50-454 Q |
| | 8302180520* | 50-295 F | | 8302280303* | 50-454 Q |
| | 8302180541* | 50-295 F | | 8302280316 | 50-254 S |
| | 8302180541* | 50-295 F | | 8302280321* | 50-254 S |
| | 8302220291 | 50-454 T | | 8302280344 | 50-373 K |
| | 8302220291 | 50-454 T | | 8302280376 | 50-373 S |
| | 8302220298* | 50-454 T | | 8302280381* | 50-373 S |
| | 8302220298* | 50-454 T | | 8302280400 | 50-295 P |
| | 8302220304* | 50-454 T | | 8302280400 | 50-295 P |
| | 8302220304* | 50-454 T | | 8302280450 | 50-454 S |
| | 8302220310* | 50-454 T | | 8302280450 | 50-454 S |
| | 8302220310* | 50-454 T | | 8302280450 | 50-454 S |
| | 8302220317* | 50-454 T | | 8302280470 | 50-295 S |
| | 8302220317* | 50-454 T | | 8302280473 | 50-295 S |
| | 8302220321* | 50-454 T | | 8302280476* | 50-295 S |
| | 8302220321* | 50-454 T | | 8302280480* | 50-295 S |
| | 8302220325* | 50-454 T | | 8302280497 | 50-373 S |
| | 8302220325* | 50-454 T | | 8302280506* | 50-373 S |
| | 8302220328* | 50-454 F | | 8302280518 | 50-249 S |
| | 8302220328* | 50-454 T | | 8302280524* | 50-249 S |
| | 8302220330 | 50-237 P | | 8302280529 | 50-295 S |
| | 8302220330 | 50-237 P | | 8302280536* | 50-295 S |
| | 8302220332* | 50-454 T | Community Hosp of Ottawa, IL | 8302100457* | PR |
| | 8302220332* | 50-454 T | Community Memorial Hosp Monmouth, IL | 8302100377* | PR |
| | 8302220336* | 50-454 T | Computer Data Systems, Inc | 8302040491* | CONTRACT |
| | 8302220336* | 50-454 T | Conam Inspection | 8302100442 | PRH |
| | 8302220364 | 50-454 F | Concerned Citizens of Rhode Island | 8302100306 | PRH |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|-----------------------|---------------------|---------------------|
| Conference of Radiation Control Program
Directors, Inc | 8302100434 | PR | | 8302100307 | 50-247 P |
| | 8302250348* | PR | | 8302150268 | 50-247 S |
| Congress (Joint & Rotating Committees,
etc) | 8302100327* | PR | | 8302150278* | 50-247 S |
| Connecticut Yankee Atomic Power Co | 8301190078 | 50-213 F | | 8302150341 | 50-247 P |
| | 8301190078 | 50-213 F | | 8302150349 | 50-247 P |
| | 8301190078 | 50-213 F | | 8302160271 | 50-247 Q |
| | 8301190078 | 50-213 F | | 8302160271 | 50-247 Q |
| | 8301190084* | 50-213 F | | 8302160278 | 50-247 Q |
| | 8302010097* | 50-213 F | | 8302160278 | 50-247 Q |
| | 8302010301 | 50-213 P | | 8302160367 | 50-247 Q |
| | 8302010301 | 50-213 P | | 8302160367 | 50-247 Q |
| | 8302010565 | 50-213 Q | | 8302160372 | 50-247 Q |
| | 8302010682* | 50-213 Q | | 8302160372 | 50-247 Q |
| | 8302030043* | 50-213 F | | 8302160384 | 50-247 Q |
| | 8302030043* | 50-213 F | | 8302160399 | 50-247 Q |
| | 8302030043* | 50-213 F | | 8302160399 | 50-247 Q |
| | 8302040283 | 50-213 P | | 8302170260 | 50-247 T |
| | 8302040283 | 50-213 P | | 8302170260 | 50-247 T |
| | 8302070198 | 50-213 F | | 8302170260* | 50-247 T |
| | 8302070384 | 50-213 P | | 8302170280* | 50-247 T |
| | 8302070432 | 50-213 P | | 8302170316 | 50-3 F |
| | 8302070433* | 50-213 P | | 8302170316 | 50-3 P |
| | 8302070566 | 50-213 F | | 8302170317* | 50-3 P |
| | 8302070566 | 50-213 F | | 8302170317* | 50-3 P |
| | 8302080202 | 50-213 P | | 8302230002 | 50-247 P |
| | 8302080208* | 50-213 P | | 8302230434 | 50-247 R |
| | 8302090304 | 50-213 P | | 8302230441* | 50-247 R |
| | 8302100234 | 50-213 P | | 8302230448 | 50-247 S |
| | 8302100236* | 50-213 P | | 8302230479* | 50-247 S |
| | 8302140105 | PR | | 8302230498* | 50-247 Q |
| | 8302150188 | 50-213 S | | 8302230659* | 50-247 Q |
| | 8302150193* | 50-213 S | | 8302240095* | 50-247 P |
| | 8302150644 | 50-213 P | | 8302240320 | 50-247 T |
| | 8302160224 | 50-213 F | | 8302240320 | 50-247 T |
| | 8302240326 | 50-213 P | | 8302250321 | PR |
| | 8302240329* | 50-213 P | | 8302250420 | 50-247 S |
| | 8302240331 | 50-213 P | | 8302280168 | 50-247 T |
| | 8302240331 | 50-213 P | | 8302280168 | 50-247 T |
| | 8302280097 | 50-213 V | | 8302280179 | 50-247 Q |
| | 8302280459 | 50-213 S | | 8302280183* | 50-247 Q |
| | 8302280467* | 50-213 S | | 8302010259 | 50-155 S |
| Conner & Hetterhahn | 8302010524 | 50-352 Q | Consumers Power Co | 8302010263* | 50-155 S |
| | 8302070310 | 50-352 Q | | 8302010484 | 50-155 P |
| | 8302080059 | 50-220 P | | 8302010636 | 50-155 P |
| | 8302100362 | PR | | 8302010640* | 50-155 P |
| | 8302230488 | 50-352 Q | | 8302010642* | 50-155 P |
| | 8302230529 | 50-358 Q | | 8302010654 | 50-155 P |
| | 8302230559 | 50-352 Q | | 8302010660 | 50-155 F |
| Conover & Associates, Inc Insurance | 8302020005 | 70-1621 | | 8302010660 | 50-155 F |
| | 8302020046 | 70-1621 | | 8302010661* | 50-155 P |
| Consad Research Corp | 8302040492 | FOIA | | 8302010671* | 50-155 P |
| Conservation Council of North Carolina | 8302230568 | 50-400 Q | | 8302020451* | 50-329 F |
| | 8302230568 | 50-400 Q | | 8302030397 | 50-329 A |
| | 8302230579* | 50-400 Q | | 8302030397 | 50-329 A |
| | 8302230579* | 50-400 Q | | 8302030407* | 50-329 A |
| | 8302040532 | FOIA | | 8302040078 | 50-155 P |
| Consolidated Aluminum Corp | 8302010114 | 50-247 S | | 8302040093 | 50-329 E |
| Consolidated Edison Co of New York, Inc | 8302010134* | 50-247 S | | 8302040093 | 50-329 E |
| | 8302010446 | 50-247 S | | 8302040098* | 50-329 E |
| | 8302010449* | 50-247 S | | 8302040098* | 50-329 E |
| | 8302010530 | 50-247 T | | 8302040112 | 70-2964 |
| | 8302010530 | 50-247 T | | 8302040121 | 50-255 P |
| | 8302010536* | 50-247 T | | 8302040126* | 50-255 P |
| | 8302010836* | 50-247 T | | 8302040135 | 50-255 S |
| | 8302020254 | 50-247 Q | | 8302040144* | 50-255 S |
| | 8302020254 | 50-247 Q | | 8302040238 | 50-155 S |
| | 8302030164 | 50-247 Q | | 8302040259* | 50-155 S |
| | 8302030164 | 50-247 Q | | 8302040307 | 50-329 S |
| | 8302030175* | 50-247 Q | | 8302040307 | 50-329 S |
| | 8302030175* | 50-247 Q | | 8302040328 | 50-329 S |
| | 8302040020* | 50-3 F | | 8302040329 | 50-329 S |
| | 8302040025* | 50-3 F | | 8302040329 | 50-329 S |
| | 8302070216 | 50-3 F | | 8302040329 | 50-329 S |
| | 8302070216 | 50-3 F | | 8302040512 | 70-2964 |
| | 8302070559 | 50-247 Q | | 8302070102* | 50-206 F |
| | 8302090224 | 50-247 T | | 8302070439 | 50-255 P |
| | 8302090224 | 50-247 T | | 8302070622 | 50-255 D |
| | 8302090230* | 50-247 T | | 8302080205 | 50-329 S |
| | 8302090230* | 50-247 T | | 8302080205 | 50-329 S |
| | 8302100230 | 50-247 P | | 8302080207 | 50-329 Q |
| | | | | 8302080216 | 50-329 Q |
| | | | | 8302080216 | 50-329 Q |

CORPORATE SOURCE INDEX

493

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|--|---------------------|---------------------|---|---------------------|---------------------|
| | 8302080305 | 50-329 S | | 8302180522 | WASTE MOT |
| | 8302080305 | 50-329 S | | 8302180524* | WASTE MOT |
| | 8302080317 | 50-255 S | | 8302220194 | WASTE MOT |
| | 8302080319* | 50-255 S | | 8302220203* | WASTE MOT |
| | 8302140003 | 50-155 F | Covington & Burling | 8302080028 | FOIA |
| | 8302160173 | 50-255 S | | 8302100395 | PRM |
| | 8302160177* | 50-255 S | | 8302100349 | PRM |
| | 8302160247 | 50-255 R | Critical Mass Energy Project | 8302240169* | 50-155 P |
| | 8302160250 | 50-255 S | D'Appolonia Consulting Engineers, Inc | 8302240174* | 50-155 P |
| | 8302160252* | 50-255 R | | 8302240181* | 50-155 P |
| | 8302160259* | 50-255 S | | 8302010462* | 50-409 Q |
| | 8302160370 | 50-255 P | Dairyland Power Cooperative | 8302030604 | 71-9094 |
| | 8302160376 | 50-255 S | | 8302040046 | 50-409 Q |
| | 8302160381* | 50-255 S | | 8302070868 | 50-409 V |
| | 8302170295 | 50-155 P | | 8302140057 | 50-409 P |
| | 8302180248 | 50-255 S | | 8302140061* | 50-409 P |
| | 8302180376 | 50-255 S | | 8302170319 | 50-409 P |
| | 8302180378 | 50-329 Q | | 8302230131 | 50-409 F |
| | 8302180378 | 50-329 Q | | 8302230393 | 50-409 P |
| | 8302180382* | 50-329 Q | | 8302240024 | 50-409 P |
| | 8302180382* | 50-329 Q | | 8302250262 | 50-409 P |
| | 8302180390 | 50-329 T | | 8302250269* | 50-409 P |
| | 8302180390 | 50-329 T | | 8302280269 | 50-409 F |
| | 8302180398* | 50-329 T | Dartmouth College | 8302030334 | 50-423 K |
| | 8302180398* | 50-329 T | Data Composition Services, Inc | 8302080064* | CONTRACT |
| | 8302180403* | 50-329 T | | 8302090229 | 50-454 Q |
| | 8302180426 | 50-255 P | DeKalb Area Alliance for Responsible Energy | | |
| | 8302180456 | 50-329 S | Debevoise & Liberman | 8302070488 | 50-460 Q |
| | 8302180456 | 50-329 S | | 8302070578 | 50-445 Q |
| | 8302180900 | 50-329 S | | 8302080024 | 50-397 H |
| | 8302180900 | 50-329 S | | 8302090238 | 50-460 Q |
| | 8302180902 | 50-329 A | | 8302100305 | PRM |
| | 8302220139 | 50-155 P | | 8302100362 | PR |
| | 8302230179 | 50-155 P | | 8302170228 | 50-413 Q |
| | 8302230206 | 50-155 P | | 8302220350 | 50-460 Q |
| | 8302230241 | 50-329 E | | 8302240405* | COMMISSION |
| | 8302230380 | 50-255 P | | 8302230248 | 50-460 Q |
| | 8302230405 | 50-329 A | | 8302230298 | 50-460 Q |
| | 8302230405 | 50-329 A | Defense Dept of Defense Nuclear Agency | 8302230530 | 50-170 Q |
| | 8302230421 | 50-255 F | Del-Aware Unlimited, Inc | 8302080233 | 50-352 Q |
| | 8302230492 | 50-329 A | | 8302080233 | 50-352 Q |
| | 8302230492 | 50-329 A | | 8302080257 | 50-352 Q |
| | 8302230508 | 50-329 A | | 8302080257 | 50-352 Q |
| | 8302230508 | 50-329 A | | 8302180419 | 50-352 Q |
| | 8302230597 | 50-155 Q | | 8302180419 | 50-352 Q |
| | 8302230610 | 50-155 Q | | 8302180425* | 50-352 Q |
| | 8302240163 | 50-155 P | | 8302240275* | CONTRACT |
| | 8302240254 | 50-155 P | Delaware, State of | 8302230480 | REVIEW ORP |
| | 8302240262 | 50-329 A | Design Review Panel | 8302230432 | REVIEW ORP |
| | 8302240262 | 50-329 A | | 8302230650* | REVIEW ORP |
| | 8302240267* | 50-329 A | | 8302010408* | 50-341 K |
| | 8302240267* | 50-329 A | | 8302010413* | 50-341 K |
| | 8302240273 | 50-255 P | | 8302020437* | 50-341 F |
| | 8302250225 | 50-329 A | | 8302020440* | 50-341 F |
| | 8302250225 | 50-329 A | | 8302040074 | 50-341 S |
| | 8302250230 | 50-329 A | | 8302040090 | 50-341 S |
| | 8302250230 | 50-329 A | | 8302040116 | 50-341 S |
| | 8302250245 | 50-329 A | | 8302040354* | 50-341 Q |
| | 8302250245 | 50-329 A | | 8302150029 | 50-341 S |
| | 8302250363 | PR | | 8302150240 | 50-341 S |
| | 8302280169 | 50-329 A | | 8302160299* | 50-341 Q |
| | 8302280169 | 50-329 A | | 8302170351 | 50-341 A |
| | 8302280239 | 50-329 A | | 8302220329 | 50-341 A |
| | 8302280239 | 50-329 A | Don L. Warner, Inc | 8302080123* | 40-8027 |
| | 8302280300 | 50-329 A | Dover, K.L. | 8302040104 | FOIA |
| | 8302280365 | 50-255 S | Dow Chemical Co | 8302020428* | 50-264 F |
| | 8302280374* | 50-255 Q | | 8302020492* | 50-264 F |
| | 8302280383* | 50-255 S | | 8302040434 | 40-17 |
| | 8302280386 | 50-255 S | Duke Power Co | 8210120652* | 50-269 F |
| | 8302280393* | 50-255 S | | 8210120656* | 50-269 F |
| | | | | 8210120658* | 50-269 F |
| Control Components, International (subs of Babcock & Wilcox) | 8302150480* | QA999 | | 8302010498 | 50-269 P |
| Converse, Davis & Associates | 8302100489* | CONTRACT | | 8302010531 | 50-287 P |
| Corporate Consulting & Development Co. Ltd | 8302160300* | 50-416 P | | 8302010537* | 50-287 P |
| Cotter Corp | 8302090482 | WASTE MOT | | 8302010639 | 50-413 A |
| | 8302090487* | WASTE MOT | | 8302010639 | 50-413 A |
| | 8302090492 | WASTE MOT | | 8302010641 | 50-269 F |
| | 8302090495* | WASTE MOT | | 8302030425 | 50-269 S |
| | 8302170023 | WASTE MOT | | 8302030432 | 50-413 S |
| | 8302170026* | WASTE MOT | | 8302030432 | 50-413 S |
| | 8302170031 | WASTE MOT | | 8302030434* | 50-269 S |
| | 8302170035* | WASTE MOT | | 8302030466 | 50-269 S |
| | 8302170039 | WASTE MOT | | 8302030473* | 50-269 F |
| | 8302170043* | WASTE MOT | | 8302040504* | 50-269 F |
| | | | | 8302040506* | 50-269 F |

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|-----------------------|---------------------|---------------------|
| | 8302040311* | 50-269 F | | 8302240068 | 50-269 V |
| | 8302070332 | 50-369 P | | 8302240208 | 50-413 K |
| | 8302070334* | 50-369 P | | 8302240208 | 50-413 K |
| | 8302070351 | 50-413 I | | 8302240210* | 50-413 K |
| | 8302070353 | 50-414 S | | 8302240210* | 50-413 K |
| | 8302070504 | 50-269 P | | 8302240285 | 50-369 P |
| | 8302080174 | 50-413 A | | 8302240285 | 50-369 P |
| | 8302090413 | 50-269 J | | 8302240302 | 50-369 P |
| | 8302100212 | 50-369 P | | 8302240332 | 50-369 P |
| | 8302100338 | PR | | 8302240332 | 50-369 P |
| | 8302140120 | 50-369 S | | 8302250371 | 50-269 P |
| | 8302140124* | 50-369 S | | 8302250371 | 50-269 P |
| | 8302150108 | 50-491 Q | | 8302250371 | 50-269 P |
| | 8302150219 | 50-413 Q | | 8302250375* | 50-269 P |
| | 8302150259 | 50-413 Q | | 8302250375* | 50-269 P |
| | 8302150293* | 50-370 Q | | 8302250375* | 50-269 P |
| | 8302150327 | 50-269 Q | | 8302250391 | 50-269 P |
| | 8302150396 | 50-370 A | | 8302250391 | 50-269 P |
| | 8302150442 | 50-369 Q | | 8302250391 | 50-269 P |
| | 8302150522 | 50-370 A | | 8302250391 | 50-269 P |
| | 8302150526 | 50-369 Q | | 8302250398 | 50-269 Q |
| | 8302150526 | 50-369 Q | | 8302250400* | 50-269 P |
| | 8302150612 | 50-370 Q | | 8302250400* | 50-269 P |
| | 8302150664 | TOPREJ | | 8302250400* | 50-269 P |
| | 8302150673 | 50-370 Q | | 8302250400* | 50-269 P |
| | 8302150697 | 50-369 Q | | 8302250400* | 50-269 P |
| | 8302160236 | 50-269 P | | 8302250400* | 50-269 P |
| | 8302160236 | 50-269 P | | 8302250406* | 50-269 P |
| | 8302160236 | 50-269 P | | 8302250406* | 50-269 P |
| | 8302160242* | 50-269 P | | 8302250406* | 50-269 P |
| | 8302160242* | 50-269 P | | 8302250411* | 50-269 P |
| | 8302160242* | 50-269 P | | 8302250411* | 50-269 P |
| | 8302170042 | 50-369 P | | 8302250411* | 50-269 P |
| | 8302170042 | 50-369 P | | 8302250417* | 50-269 P |
| | 8302170047* | 50-369 P | | 8302250417* | 50-269 P |
| | 8302170047* | 50-369 P | | 8302250417* | 50-269 P |
| | 8302170140 | 50-369 P | | 8302250417* | 50-269 P |
| | 8302170140 | 50-369 P | | 8302250417* | 50-269 P |
| | 8302170144* | 50-369 P | | 8302250422 | 50-369 J |
| | 8302170144* | 50-369 P | | 8302250422 | 50-369 J |
| | 8302170228 | 50-413 Q | | 8302250424* | 50-269 P |
| | 8302170327 | 50-370 A | | 8302250424* | 50-269 P |
| | 8302180316 | 50-369 R | | 8302250424* | 50-269 P |
| | 8302180319* | 50-369 R | | 8302250424* | 50-269 P |
| | 8302180374 | 50-269 R | | 8302250424* | 50-269 P |
| | 8302180374 | 50-269 R | | 8302250424* | 50-269 P |
| | 8302180377* | 50-269 R | | 8302250424* | 50-269 P |
| | 8302180377* | 50-269 R | | 8302250424* | 50-269 P |
| | 8302180377* | 50-269 R | | 8302250436* | 50-269 P |
| | 8302180399 | 50-413 P | | 8302250436* | 50-269 P |
| | 8302180399 | 50-413 P | | 8302250436* | 50-269 P |
| | 8302180402* | 50-413 P | | 8302250436* | 50-269 P |
| | 8302180402* | 50-413 F | | 8302250436* | 50-269 P |
| | 8302180400 | 50-269 P | | 8302250436* | 50-269 P |
| | 8302180400 | 50-269 P | | 8302250436* | 50-269 P |
| | 8302180400 | 50-269 P | | 8302250440* | 50-269 P |
| | 8302180404* | 50-269 P | | 8302250440* | 50-269 P |
| | 8302180404* | 50-269 P | | 8302280037 | 50-413 S |
| | 8302180404* | 50-269 P | | 8302280082 | 50-369 F |
| | 8302220040* | 50-369 P | | 8302280089* | 50-369 S |
| | 8302220040* | 50-369 P | | 8302280170 | 50-413 S |
| | 8302220047* | 50-369 P | | 8302280199 | 50-413 S |
| | 8302220055* | 50-269 P | | 8302280199 | 50-413 S |
| | 8302220059* | 50-269 P | | 8302280203 | 50-370 A |
| | 8302220087* | 50-369 F | | 8302280325 | 50-269 P |
| | 8302220087* | 50-369 F | | 8302280325 | 50-269 P |
| | 8302220093* | 50-369 F | | 8302280325 | 50-269 P |
| | 8302220418 | 50-269 Q | | 8302280327* | 50-269 P |
| | 8302220418 | 50-269 Q | | 8302280327* | 50-269 P |
| | 8302220418 | 50-269 Q | | 8302280327* | 50-269 P |
| | 8302220418 | 50-269 Q | | 8302280327* | 50-269 P |
| | 8302220418 | 50-269 Q | | 8302280327* | 50-269 P |
| | 8302220424 | 50-369 K | | 8302280412 | 50-269 S |
| | 8302220424 | 50-369 K | | 8302280418* | 50-269 S |
| | 8302220431* | 50-369 K | | 8302010666 | 50-334 R |
| | 8302220431* | 50-369 K | | 8302010670* | 50-334 R |
| | 8302220516 | 50-370 A | | 8302070576 | 50-334 S |
| | 8302220592 | 50-369 S | | 8302070583* | 50-334 S |
| | 8302220603* | 50-369 S | | 8302080296 | 50-334 P |
| | 83022240062 | 50-269 P | | 8302080302 | 50-334 P |
| | 83022240062 | 50-269 P | | 8302090368 | 50-334 S |
| | 8302240062 | 50-269 P | | 8302090378* | 50-334 S |
| | 8302240068 | 50-269 V | | 8302100329 | 50-412 Q |
| | 8302240068 | 50-269 V | | 8302150027 | PR |
| | 8302240068 | 50-269 V | | 8302150335 | 50-334 P |
| | 8302240068 | 50-269 V | | 8302150626 | 50-412 P |
| | 8302240068 | 50-269 V | | | |

CORPORATE SOURCE INDEX

495

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---------------------------------------|---------------------|---------------------|--|---------------------|---------------------|
| | 8302160267 | 50-334 F | | 8302020377* | WASTE MGT |
| | 8302160476* | 50-334 F | | 8302040021 | 71-6272 |
| | 8302160479* | 50-334 F | | 8302040133* | 50-537 A |
| | 8302170052 | 50-341 A | | 8302040487 | 71-9150 |
| | 8302170186 | 50-334 P | | 8302080048 | 71-9855 |
| | 8302170193* | 50-334 P | | 8302080053* | 71-9855 |
| | 8302170196* | 50-334 P | | 8302090489 | TOPREP |
| | 8302170380 | 50-334 P | | 8302090526 | XPORTLIC |
| | 8302170381* | 50-334 P | | 8302100450 | PR |
| | 8302170385* | 50-334 P | | 8302240383 | WASTE MGT |
| | 8302180440 | 50-334 G | | 8302250001 | WASTE MGT |
| | 8302180443 | 50-334 G | Energy, Dept of, Clinch River Breeder
Reactor Plant | 8302010437 | 50-537 A |
| | 8302180450* | 50-334 G | | 8302010439* | 50-537 A |
| | 8302220255 | 50-334 G | | 8302070417 | 50-537 A |
| | 8302220297 | 50-334 P | | 8302070420 | 50-537 A |
| | 8302220322 | 50-334 P | | 8302070440 | 50-537 A |
| | 8302220370 | 50-334 P | | 8302070451 | 50-537 A |
| | 8302240311* | 50-334 F | | 8302070477 | 50-537 A |
| | 8302240315* | 50-334 F | | 8302080001 | 50-537 A |
| | 8302250185 | 50-334 G | | 8302090325 | 50-537 D |
| | 8302280385 | 50-412 B | | 8302090326 | 50-537 A |
| | 8302280342 | 50-334 R | | 8302100315 | 50-537 G |
| | 8302280347* | 50-334 R | | 8302130343 | 50-537 A |
| | 8302100209* | 50-440 G | | 8302150457 | 50-537 A |
| | 8010070317* | 50-335 P | | 8302150576 | 50-537 A |
| EDS Nuclear, Inc | 8302030208 | NUREG | | 8302150588 | 50-537 A |
| EG&G, Inc | 8302040031* | ORR | | 8302150601 | 50-537 A |
| | 8302070592 | 50-537 A | | 8302160133 | 50-537 A |
| | 8302070598* | 50-537 A | | 8302160170 | 50-537 A |
| | 8302080019* | 50-206 P | | 8302170180 | 50-537 A |
| | 8302150739 | RES | | 8302230201 | 50-537 B |
| | 8302150741 | RES | | 8302230347 | 50-537 A |
| | 8302150744 | 50-312 P | | 8302250290 | 50-537 A |
| | 8302150745 | RES | | 8302250292 | 50-537 A |
| | 8302150748 | RES | | 8302250314 | 50-537 A |
| | 8302150758 | RES | | 8302040030 | ORR |
| | 8302160002 | RES | Energy, Dept of, Idaho Operations Office | 8302010133* | 50-537 A |
| | 8302160003 | RES | Engineering & Economics Research, Inc | 8302280262* | 50-445 A |
| | 8302160005 | RES | Environmental Consultants, Inc | 8302100454 | PRM |
| | 8302160008 | RES | Environmental Defense Fund | 8302040470 | FOIA |
| | 8302160097 | RES | Environmental Policy Institute | 8302100440 | PRM |
| | 8302160398 | RES | | 8302230390 | 50-413 D |
| | 8302160401 | RES | Environmental Protection Agency | 8302070001 | FOIA |
| | 8302160402 | RES | Equipment Qualification Engineering | 8302070002 | FOIA |
| | 8302170009 | RES | Services, Inc | 8302170395* | 50-320 P |
| | 8302170210* | 50-322 A | Essex Corp | | |
| | 8302170223* | 50-322 A | | | |
| | 8302170227* | 50-322 A | European Communities, Commission of | 8302090201 | XPORTLIC |
| | 8302170235* | 50-322 A | | 8302220928 | XPORTLIC |
| | 8302220467 | 50-269 P | | 8302220933 | XPORTLIC |
| | 8302280151 | TOPREP | | 8302220940 | XPORTLIC |
| | 8302280164* | TOPREP | | 8302240140 | XPORTLIC |
| Eastern Testing & Inspection, Inc | 8302040801 | 71-6717 | | 8302280001 | XPORTLIC |
| Exasco Services, Inc (subs of Enserch | 8302070507* | 50-382 A | Exxon Nuclear Co, Inc (subs of Exxon | 8302010588* | 50-335 P |
| Corp) | 8302020321 | 50-400 G | Corp) | 8302010599* | 50-335 P |
| Eddleman, H | 8302020321 | 50-400 G | | 8302010605* | 50-335 P |
| | 8302020334* | 50-400 G | | 8302040120 | 70-1287 |
| | 8302020334* | 50-400 G | | 8302040463 | 70-1257 |
| | 8302070514 | 50-400 G | | 8302040833 | 70-1257 |
| | 8302090241 | 50-400 G | | 8302040538 | 70-1257 |
| | 8302090241 | 50-400 G | | 8302040545 | 70-1257 |
| | 8302090251* | 50-400 G | | 8302100464 | PR |
| | 8302090251* | 50-400 G | | 8302140044 | 50-316 P |
| | 8302160381 | 50-400 G | | 8302140206 | PR |
| | 8302230568 | 50-400 G | | 8302160508 | 40-8064 |
| | 8302230579* | 50-400 G | | 8302160510* | 40-8064 |
| Edelstein & Payne | 8302230568 | 50-400 G | | 8302180243 | TOPREP |
| | 8302230568 | 50-400 G | | 8302180336 | TOPREP |
| | 8302230579* | 50-400 G | | 8302230150 | TOPREP |
| Ederer, Inc | 8302020277 | TOPREP | | 8302230155 | TOPREP |
| | 8302140111 | PR | | 8302230300* | 70-1257 |
| Edison Electric Institute | 8302020344 | XPORTLIC | | 8302230327 | TOPREP |
| Edlow International Co | 8302020355* | XPORTLIC | | 8302280564 | 71-5450 |
| | 8302020358* | XPORTLIC | FOI Services | 8302060047 | FOIA |
| | 8302240343 | XPORTLIC | FPE Group, The | 8302160009* | CONTRACT |
| | 8302020062 | TOPREP | Federal Emergency Management Agency | 8302100294 | PRM |
| Electric Power Research Institute | 8302180513* | CONTRACT | | 8302160065 | 50-247 F |
| Energy Daily, Inc | 8302020381 | 40-8675 | | 8302240057 | COMMISSION |
| Energy Fuels Nuclear, Inc | 8302020384* | 40-8675 | | 8302240065* | COMMISSION |
| | 8302090607 | 40-8681 | | 8302280384* | 50-247 T |
| | 8302100501* | CONTRACT | | 8302280384* | 50-247 T |
| Energy Resources Co, Inc | 8302230243* | 50-445 G | | 8302280390* | 50-247 T |
| Energy Technology Engineering Center | 8302020375 | WASTE MGT | | 8302280390* | 50-247 T |
| Energy, Dept of | 8302020376* | WASTE MGT | Fishgold, H | 8302240091* | CONTRACT |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|--|---------------------|---------------------|
| Flemming, Anderson, McClung & Finch
Florida Power & Light Co | 8302020335* | 50-361 G | | 8302280047* | 50-335 G |
| | 8302010118 | 50-250 S | | 8302280128 | 50-389 G |
| | 8302010130* | 50-250 S | | 8302280271 | 50-389 A |
| | 8302010250 | 50-335 P | | 8302280276* | 50-389 A |
| | 8302010311 | 50-335 S | | 8302280345 | 50-250 G |
| | 8302010320* | 50-335 S | | 8302280350 | 50-389 A |
| | 8302010444 | 50-389 S | | 8302280351* | 50-250 G |
| | 8302010447 | 50-389 S | | 8302280353 | 50-335 V |
| | 8302010463 | 50-335 S | Florida Power Corp | 8302010220 | 50-302 G |
| | 8302010467* | 50-335 S | | 8302010229* | 50-302 G |
| | 8302010477 | 50-335 S | | 8302010574 | 50-302 S |
| | 8302010488* | 50-335 S | | 8302010578* | 50-302 S |
| | 8302010513 | 50-389 R | | 8302030350 | 50-302 S |
| | 8302010522 | 50-389 A | | 8302030353* | 50-302 G |
| | 8302010576 | 50-335 P | | 8302030416 | 50-302 K |
| | 8302010582* | 50-335 P | | 8302030419* | 50-302 K |
| | 8302010606 | 50-250 P | | 8302030571 | 50-302 Q |
| | 8302010643 | 50-250 F | | 8302070268 | 50-302 P |
| | 8302030077 | 50-389 S | | 8302100375 | PR |
| | 8302030098 | 50-389 S | | 8302150067* | 50-302 Q |
| | 8302030427 | 50-389 S | | 8302150076* | 50-302 Q |
| | 8302070305 | 50-250 P | | 8302150138 | 50-302 P |
| | 8302070305 | 50-250 P | | 8302150145* | 50-302 P |
| | 8302070444 | 50-250 P | | 8302150688* | 50-302 Q |
| | 8302070472 | 50-250 P | | 8302160178 | 50-302 P |
| | 8302070472 | 50-250 P | | 8302160265 | 50-302 P |
| | 8302070528 | 50-250 P | | 8302170166 | 50-302 P |
| | 8302070928 | 50-250 P | | 8302170370 | 50-302 P |
| | 8302070534* | 50-250 P | | 8302180327 | 50-302 R |
| | 8302070534* | 50-250 P | | 8302180332* | 50-302 R |
| | 8302070577 | 50-250 P | | 8302180363 | 50-302 V |
| | 8302070577 | 50-250 P | | 8302220215 | 50-302 P |
| | 8302080339 | 70-2957 | | 8302220360 | 50-302 P |
| | 8302100300 | PR | | 8302230208 | 50-302 P |
| | 8302100450 | PR | | 8302230502 | 50-302 Q |
| | 8302140033 | 50-335 S | | 8302230678 | 50-302 Q |
| | 8302140035* | 50-335 S | | 8302280148 | 50-302 S |
| | 8302140104 | 50-335 S | | 8302280221 | 50-302 G |
| | 8302140109* | 50-335 S | | 8302280227* | 50-302 S |
| | 8302140112 | 50-335 S | | 8302280261 | 50-302 S |
| | 8302140119* | 50-335 S | | 8302280268* | 50-302 S |
| | 8302150007 | 50-335 P | Florida State Univ
Foley, Hoag & Eliot
Foothill Electric Corp
Foster Wheeler Corp | 8302070632* | CONTRACT |
| | 8302150008* | 50-335 P | | 8302040114 | FOIA |
| | 8302150063 | 50-250 S | | 8302180115* | 50-358 A |
| | 8302150070* | 50-250 S | | 8302100275 | PR |
| | 8302150355 | 50-335 S | | 8302100384 | PR |
| | 8302150361* | 50-335 S | | 8302100413 | PRM |
| | 8302150436* | 50-250 Q | Franklin Institute/Franklin Research
Center | 8208060265* | 50-344 P |
| | 8302150479 | 50-250 P | | 8208170201* | 50-407 P |
| | 8302150479 | 50-250 P | | 8209020218* | 50-220 P |
| | 8302150497 | 50-250 P | | 8209020228* | 50-220 P |
| | 8302150497 | 50-250 P | | 8209080335* | 50-204 P |
| | 8302150594 | 50-335 S | | 8209160339* | 50-204 P |
| | 8302150604* | 50-335 S | | 8212010094* | 50-335 P |
| | 8302150706 | 50-389 F | | 8212200054* | 50-244 P |
| | 8302160205 | 50-250 Q | | 8212200078* | 50-295 P |
| | 8302160234 | 50-389 S | | 8212200091* | 50-305 P |
| | 8302160241 | 50-250 Q | | 8301040296* | 50-313 P |
| | 8302160241 | 50-250 Q | | 8301180125* | 50-305 P |
| | 8302170131 | 50-335 S | | 8301200219* | 50-364 P |
| | 8302170135* | 50-335 S | | 8301210006* | 50-348 P |
| | 8302170154 | 50-335 S | | 8302040032 | TOPREP |
| | 8302170160* | 50-335 S | | 8302080469 | ACR6 |
| | 8302170173 | 50-389 S | | 8302090011 | 50-382 Q |
| | 8302170305 | 50-413 Q | | 8302170111* | 50-289 P |
| | 8302170336 | 50-389 F | Friends of the Earth | 8302030165 | 50-247 T |
| | 8302180299 | 50-251 P | | 8302030165 | 50-247 T |
| | 8302180313 | 50-389 A | | 8302030184 | 50-247 T |
| | 8302180422 | 50-389 A | | 8302030184 | 50-247 T |
| | 8302180437 | 50-250 F | | 8302030199 | 50-247 T |
| | 8302180437 | 50-250 F | | 8302030199 | 50-247 T |
| | 8302180460 | 50-389 R | | 8302030210 | 50-247 T |
| | 8302180464* | 50-389 R | | 8302030210 | 50-247 T |
| | 8302180483 | 50-250 P | | 8302160306 | 50-247 Q |
| | 8302180483 | 50-250 P | | 8302160306 | 50-247 Q |
| | 8302230145 | 50-250 P | | 8302160311* | 50-247 Q |
| | 8302230149 | 50-389 F | | 8302160311* | 50-247 Q |
| | 8302230198 | 50-250 P | | 8302160318* | 50-247 Q |
| | 8302230198 | 50-250 P | | 8302160318* | 50-247 Q |
| | 8302230322 | 50-335 P | Future Resources Associates, Inc | 8302170310* | 50-247 P |
| | 8302230437 | 50-335 P | | 8302180519* | CONTRACT |
| | 8302230443 | 50-335 P | GA Technologies, Inc /General Atomic Co | 8302010459 | PTRI |
| | 8302230451* | 50-335 P | | 8302080030 | 70-734 |
| | 8302280045 | 50-335 S | | 8302100362 | PR |

CORPORATE SOURCE INDEX

497

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|--|---------------------|---------------------|
| Gage-Babcock Associates, Inc
Ganna Corp
General Electric Co | 8302150622* | 50-267 P | | 8302090170 | 50-289 S |
| | 8302150630* | 50-267 P | | 8302090175* | 50-289 S |
| | 8302220523 | XPORTLIC | | 8302090341 | 50-289 P |
| | 8302250233 | 50-163 R | | 8302090344 | 50-219 S |
| | 8302250271 | 50-89 R | | 8302090351* | 50-289 P |
| | 8302010002* | CONTRACT | | 8302090354* | 50-219 S |
| | 8302040012 | 71-5926 | | 8302090363* | 50-289 P |
| | 8301260116 | TOPREP | | 8302090402 | 50-289 P |
| | 8302010434* | 50-237 P | | 8302090407 | 50-289 V |
| | 8302010644 | 50-447 A | | 8302090407 | 50-289 V |
| | 8302020023 | 50-447 A | | 8302090410* | 50-289 V |
| | 8302020169* | XPORTLIC | | 8302090410* | 50-289 V |
| | 8302020311* | 50-219 P | | 8302090492* | 50-289 F |
| | 8302020368* | XPORTLIC | | 8302100111* | 50-320 R |
| | 8302020373* | XPORTLIC | | 8302100232 | 50-289 P |
| | 8302030119 | 71-9148 | | 8302100237* | 50-289 P |
| | 8302040482* | FOIA | | 8302100240* | 50-289 P |
| | 8302040528 | 70-754 | | 8302100269 | PR |
| | 8302040586 | 70-1113 | | 8302100502 | 50-289 P |
| | 8302070377 | 50-447 A | | 8302100733* | 50-219 Q |
| | 8302080033 | 70-1113 | | 8302100603* | 50-289 Q |
| | 8302080034 | 70-754 | | 8302100621 | 50-219 P |
| | 8302080076 | 70-754 | | 8302100634 | 50-289 Q |
| | 8302080101 | 70-1113 | | 8302100651 | 50-289 P |
| | 8302080104 | 70-754 | | 8302100737* | 50-320 P |
| | 8302080478 | TOPREP | | 8302100025* | 50-289 F |
| | 8302090006* | 50-259 P | | 8302100082* | 50-219 F |
| | 8302090323* | 50-387 P | | 8302100087* | 50-219 F |
| | 8302090414 | TOPREP | | 8302100182* | 50-289 Q |
| | 8302100205 | 50-447 A | | 8302100250 | 50-320 S |
| | 8302100338 | PR | | 8302100260 | 50-289 S |
| | 8302140020 | 50-266 Q | | 8302100261 | 50-320 P |
| | 8302140091 | NUREG | | 8302100431 | 50-320 P |
| | 8302150030 | 70-1113 | | 8302100504 | 50-219 P |
| | 8302150301 | TOPREP | | 8302100506* | 50-219 P |
| | 8302160345 | 50-73 S | | 83022200314 | 50-219 P |
| | 8302170170* | 50-260 P | | 8302220156 | 50-289 R |
| | 8302170335 | 50-447 A | | 8302220158* | 50-289 R |
| | 8302220152 | 50-447 A | | 8302220175 | 50-289 P |
| | 8302220221 | TOPREP | | 8302220225 | 50-289 S |
| | 8302220407 | TOPREP | | 8302220495 | 50-320 S |
| | 8302220680 | TOPREP | | 8302220697* | 50-320 S |
| | 8302220298 | TOPREP | | 8302220039 | 50-289 P |
| | 8302250157 | XPORTLIC | | 8302220260 | 50-320 P |
| | 8302250160* | XPORTLIC | | 8302220263* | 50-320 P |
| | 8302250356 | PR | | 83022204271 | 50-320 P |
| | 8302260484 | 50-447 E | | 83022204274* | 50-320 P |
| | 8302010145 | 50-219 S | | 830222050207 | 50-320 S |
| | 8302010154* | 50-219 S | | 830222050211* | 50-320 S |
| | 8302010353* | 50-320 Q | | 830222050216 | 50-219 S |
| General Public Utilities - GPU Service Corp | 8302010396 | 50-320 P | | 830222050221* | 50-219 S |
| | 8302010399* | 50-320 P | | 830222050234 | 50-219 P |
| | 8302010402* | 50-320 P | | 830222050277 | 50-320 P |
| | 8302010407 | 50-289 P | | 830222050287* | 50-320 P |
| | 8302010556 | 50-289 P | | 830222050297 | 50-219 P |
| | 8302010562* | 50-289 P | | 830222060213 | 50-219 Q |
| | 8302020001 | 50-320 P | | 83022206224 | 50-289 P |
| | 8302020147 | 50-320 S | | 8302030467 | 50-413 S |
| | 8302020306 | 50-219 P | | 8302140122* | 50-244 Q |
| | 8302030117 | 71-9081 | | 8302010212 | 50-424 S |
| | 8302030369* | 50-363 Q | General Signal Corp
Georgia Institute of Technology
Georgia Power Co | 8302010212 | 50-424 S |
| | 8302030541 | 50-289 S | | 8302010239 | 50-424 S |
| | 8302030549* | 50-289 S | | 8302010239 | 50-424 S |
| | 8302040191* | 50-289 F | | 8302010393 | 50-321 S |
| | 8302040198* | 50-289 F | | 8302010400* | 50-321 S |
| | 8302040262 | 50-219 P | | 8302010428 | 50-366 S |
| | 8302040380 | 50-219 Q | | 8302010430* | 50-366 S |
| | 8302040390 | 50-289 P | | 8302010512 | 50-321 Q |
| | 8302040416 | 50-320 P | | 8302010538* | 50-321 Q |
| | 8302040418* | 50-320 P | | 8302020342* | 50-321 F |
| | 8302070326 | 50-320 R | | 8302020342* | 50-321 F |
| | 8302070448 | 50-289 P | | 8302020346* | 50-321 F |
| | 8302070452* | 50-289 P | | 8302030288 | 50-321 S |
| | 8302070455* | 50-289 P | | 8302030294* | 50-321 S |
| | 8302070539 | 50-219 S | | 8302030375 | 50-366 S |
| | 8302070546* | 50-219 S | | 8302030376* | 50-366 S |
| | 8302080027 | 50-219 V | | 8302030449 | 50-366 S |
| | 8302080031 | 50-320 F | | 8302030460* | 50-366 S |
| | 8302080148 | 50-219 P | | 8302030472 | 50-366 S |
| | 8302080175 | 50-289 F | | 8302030484* | 50-366 S |
| | 8302080195 | 50-289 P | | 8302030515 | 50-366 S |
| | 8302080300 | 50-289 P | | 8302030523* | 50-366 S |
| | 8302080385* | 50-289 F | | 8302040250 | 50-321 P |
| | 8302090022* | 50-289 F | | 8302040250 | 50-321 P |
| | | | | 8302070386 | 50-321 S |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|--|---------------------|---------------------|
| | 8302070388* | 50-321 S | | 8302230705* | 50-366 S |
| | 8302070395 | 50-366 S | | 8302230707* | 50-366 S |
| | 8302070400* | 50-366 S | | 8302250432 | 50-366 P |
| | 8302080020 | 50-366 P | | 8302280057 | 50-321 P |
| | 8302080025* | 50-366 P | | 8302280062* | 50-321 P |
| | 8302140007 | 50-366 S | | 8302280131 | 50-366 S |
| | 8302140015* | 50-366 S | | 8302280136 | 50-424 S |
| | 8302140028 | 50-366 S | | 8302280138* | 50-366 S |
| | 8302140029* | 50-366 S | | 8302280146 | 50-366 S |
| | 8302140046 | 50-321 S | | 8302280207 | 50-321 S |
| | 8302140050* | 50-321 S | | 8302280223* | 50-321 S |
| | 8302140103 | 50-366 S | | 8302280246* | 50-366 S |
| | 8302140108* | 50-366 S | | 8302280272 | 50-321 S |
| | 8302140140 | 50-366 S | | 8302280278* | 50-321 S |
| | 8302140145* | 50-366 S | | 8302280343 | 50-321 S |
| | 8302140149 | 50-366 S | | 8302280346* | 50-321 S |
| | 8302140181* | 50-366 S | Georgia, State of | 8302170424* | CONTRACT |
| | 8302150020 | 50-321 S | Geotechnical Engineers, Inc | 8302030336 | 50-423 K |
| | 8302150025* | 50-321 S | | 8302100173* | 40-3453 |
| | 8302150042 | 50-321 S | | 8302150736* | CONTRACT |
| | 8302150073 | 50-366 S | Gentrans, Inc | 8302040479 | NUREG |
| | 8302150077* | 50-366 S | Gibbs & Hill, Inc (subs of Dravo Corp) | 8302080332 | TOPREP |
| | 8302150091 | 50-366 S | Golder Associates | 8302180478* | CONTRACT |
| | 8302150103 | 50-366 S | | 8302240395* | CONTRACT |
| | 8302150104* | 50-366 S | Good Samaritan Hosp, Pottsville, PA | 8302010448* | 70-2467 |
| | 8302150105* | 50-366 S | | 8302040499 | 50-206 Q |
| | 8302150121 | 50-366 S | Government Accountability Project | 8302040499 | 50-206 Q |
| | 8302150133 | 50-366 S | | 8302070522 | 50-358 Q |
| | 8302150135* | 50-366 S | | 8302070549 | 50-445 Q |
| | 8302150142* | 50-366 S | | 8302090013* | 50-358 A |
| | 8302150152 | 50-321 S | | 8302090023* | 50-358 A |
| | 8302150162* | 50-321 S | | 8302090035* | 50-358 Q |
| | 8302150190 | 50-321 S | | 8302170267 | 50-528 C |
| | 8302150194* | 50-321 S | | 8302170294 | 50-358 C |
| | 8302150201 | 50-321 S | | 8302180070* | 50-358 A |
| | 8302150203 | 50-366 S | | 8302240368 | 50-329 A |
| | 8302150209* | 50-321 S | Graham Hosp Association Canton, IL | 8302100291 | PR |
| | 8302150210* | 50-366 S | Grant Hosp of Chicago Chicago, IL | 8302100324* | PR |
| | 8302150241 | 50-366 S | Guild, R | 8302010610 | 50-413 Q |
| | 8302150252* | 50-366 S | Gulf & Western Industries, Inc | 8302170164 | TOPREP |
| | 8302150287 | 50-321 S | | 8302170168* | TOPREP |
| | 8302150302* | 50-321 S | | 8302170174* | TOPREP |
| | 8302150397 | 50-366 S | Gulf States Utilities Co | 8302010602 | 50-458 S |
| | 8302150402* | 50-366 S | | 8302030379 | 50-458 S |
| | 8302150431* | 50-321 Q | | 8302030412 | 50-458 Q |
| | 8302150443* | 50-321 Q | | 8302070424 | 50-458 S |
| | 8302150481 | 50-366 S | | 8302070433 | 50-458 S |
| | 8302150490* | 50-366 S | | 8302070458 | 50-458 S |
| | 8302150506 | 50-366 S | | 8302090400 | 50-458 S |
| | 8302150517* | 50-366 S | | 8302100277 | PR |
| | 8302150529 | 50-366 S | | 8302100380 | PRH |
| | 8302150549* | 50-366 S | | 8302160237 | 50-458 S |
| | 8302150627* | 50-321 Q | | 8302160251 | 50-458 S |
| | 8302150640* | 50-321 Q | | 8302220237 | 50-458 S |
| | 8302150672 | 50-366 S | | 8302230181 | 50-458 S |
| | 8302150682* | 50-366 S | | 8302230218 | 50-458 S |
| | 8302150702 | 50-366 Q | | 8302230317 | 50-458 Q |
| | 8302150714 | 50-424 Q | | 8302230317 | 50-458 Q |
| | 8302160232 | 50-321 R | | 8302230325 | 50-458 S |
| | 8302160232 | 50-321 R | | 8302230709* | 50-458 Q |
| | 8302160238* | 50-321 R | H&H X-Ray Services, Inc | 8302030048 | 71-6717 |
| | 8302160238* | 50-321 R | Hahnemann Medical College & Hosp | 8302230272* | 70-1362 |
| | 8302160243 | 50-321 R | Philadelphia, PA | | |
| | 8302160243 | 50-321 R | | 8302230284* | 70-1362 |
| | 8302160248 | 50-321 P | Hall, H | 8302040134* | CONTRACT |
| | 8302160254* | 50-321 P | Hanford Engineering Development | 8302220435 | NUREG |
| | 8302160123 | 50-321 F | Laboratory | | |
| | 8302160279 | 50-321 F | | 8302250135 | NUREG |
| | 8302160275 | 50-321 F | | 8302280020 | NUREG |
| | 8302160287 | 50-321 P | Harding-Lawson Associates | 8302100057* | CONTRACT |
| | 8302160290* | 50-321 P | Harman & Weiss | 8302010521 | 50-443 Q |
| | 8302160320 | 50-321 P | | 8302030015 | 50-537 U |
| | 8302230210 | 50-366 S | | 8302040123 | 50-537 A |
| | 8302230217* | 50-366 S | | 8302070484 | 50-289 Q |
| | 8302230223 | 50-321 S | | 8302070587 | 50-289 Q |
| | 8302230227* | 50-321 S | | 8302080264 | 50-443 Q |
| | 8302230231 | 50-366 S | | 8302100341 | PRH |
| | 8302230237* | 50-366 S | | 8302160347 | 70-143 |
| | 8302230308 | 50-321 S | | 8302160371 | 50-289 Q |
| | 8302230485 | 50-321 S | | 8302170211 | 50-289 Q |
| | 8302230494* | 50-321 S | | 8302170307 | 50-413 Q |
| | 8302230550 | 50-366 S | | 8302170307 | 50-413 Q |
| | 8302230563* | 50-366 S | | 8302170312* | 50-413 Q |
| | 8302230700 | 50-366 S | | 8302170312* | 50-413 Q |
| | 8302230702 | 50-366 S | | 8302220366 | 50-443 Q |

CORPORATE SOURCE INDEX

499

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|--|---------------------|---------------------|-------------------------------------|---------------------|---------------------|
| | 8302220366 | 50-443 G | | 8302150125 | 50-461 A |
| | 8302220382* | 50-443 G | | 8302150512* | 50-461 G |
| | 8302220382* | 50-443 G | | 8302180127 | 50-461 S |
| | 8302220392* | 50-443 G | | 8302180444 | 50-461 A |
| | 8302220392* | 50-443 G | | 8302180449 | 50-461 A |
| | 8302220399* | 50-443 G | | 8302180452* | 50-461 A |
| | 8302220399* | 50-443 G | | 8302230151 | 50-461 U |
| | 8302250274 | 50-289 G | | 8302230453 | 50-461 A |
| Harper-Grace Hosps Detroit, MI | 8302100275 | PR | | 8302250326 | 50-461 G |
| Hasuelli, H | 8302070229 | 50-454 G | | 8302280302 | 50-461 S |
| Health & Human Services, Dept of. | 8302240358* | FOIA | | 8302280309 | 50-461 S |
| Henry J Kaiser Co | 8302180115* | 50-358 A | | 8302280508 | 50-461 S |
| Hitchcock Industries, Inc | 8302010502* | 40-8798 | | 8302280556 | 50-461 S |
| Hittman Corp | 8302070639 | 71-9151 | Illinois, Univ of, Urbana-Champaign | 8302100019* | CONTRACT |
| Hittman Nuclear & Development Corp | 8302030606 | 71-9151 | Indiana & Michigan Electric Co | 8302010333 | 50-315 S |
| (subs Hittman Corp) | | | | 8302010340* | 50-315 S |
| | 8302150530* | QA999 | | 8302040079 | 50-315 S |
| | 8302150540* | QA999 | | 8302040086* | 50-315 S |
| | 8302150546* | QA999 | | 8302040076 | 50-315 S |
| | 8302150556* | QA999 | | 8302040100* | 50-315 S |
| | 8302150561* | QA999 | | 8302040195 | 50-316 S |
| | 8302150569* | QA999 | | 8302040202* | 50-316 S |
| Hourihan, P | 8302170267 | 50-528 G | | 8302070627* | 50-315 F |
| House of Rep | 8302020283 | 50-247 U | | 8302070627* | 50-315 F |
| | 8302030029* | 50-537 U | | 8302070628* | 50-315 F |
| | 8302030072* | 50-537 U | | 8302070628* | 50-315 F |
| | 8302030125* | 50-537 U | | 8302070628* | 50-315 F |
| | 8302030136* | 50-537 U | | 8302080023* | 50-315 F |
| | 8302100379 | PR | | 8302080029 | 50-315 F |
| | 8302100390 | PR | | 8302080042* | 50-315 F |
| | 8302100398* | PR | | 8302080042* | 50-315 F |
| | 8302100425* | PR | | 8302080236 | 50-315 S |
| | 8302100451 | PR | | 8302080263 | 50-315 S |
| | 8302100462* | PR | | 8302080266* | 50-315 S |
| | 8302100471* | PR | | 8302080287 | 50-316 S |
| | 8302170086* | COMMISSION | | 8302080294* | 50-316 S |
| | 8302230088* | COMMISSION | | 8302080298* | 50-316 S |
| | 8302250338* | REC'D | | 8302080311 | 50-315 S |
| House of Rep, Interior & Insular Affairs | 8302220476* | 50-522 U | | 8302080311 | 50-315 S |
| | 8302240237* | COMMISSION | | 8302080321 | 50-315 S |
| House of Rep, Science & Technology | 8302030109* | 50-537 U | | 8302080324* | 50-315 S |
| Houston Lighting & Power Co | 8302010558 | 50-498 G | | 8302080326* | 50-315 S |
| | 8302030384 | 50-498 S | | 8302080327 | 50-316 S |
| | 8302070366* | 50-498 G | | 8302080329* | 50-316 S |
| | 8302070916 | 50-498 A | | 8302080331* | 50-316 S |
| | 8302070916 | 50-498 A | | 8302080333* | 50-316 S |
| | 8302070925* | 50-498 A | | 8302080337* | 50-316 S |
| | 8302070925* | 50-498 A | | 8302080341* | 50-316 S |
| | 8302070607 | 50-498 S | | 8302090055* | 50-315 F |
| | 8302100338 | PR | | 8302090055* | 50-315 F |
| | 8302140163 | 50-498 A | | 8302090062* | 50-315 F |
| | 8302170305 | 50-413 G | | 8302090115* | 50-315 F |
| Houston, Univ of | 8302020056* | CONTRACT | | 8302090115* | 50-315 F |
| Kovis, Cockrill, Weaver & Bjor | 8302010585 | 50-522 G | | 8302090125* | 50-315 F |
| | 8302160302 | 50-522 G | | 8302090125* | 50-315 F |
| Howard Univ | 8302170949* | CONTRACT | | 8302150005 | 50-315 S |
| | 8302070501 | 50-322 G | | 8302150006* | 50-315 S |
| Hutton & Williams | 8302070518 | 50-338 G | | 8302150415 | 50-316 S |
| | 8302070518 | 50-338 G | | 8302150439* | 50-316 S |
| | 8302070524 | 50-338 G | | 8302160268 | 50-316 S |
| | 8302070524 | 50-338 G | | 8302160272* | 50-316 S |
| | 8302070530 | 50-338 G | | 8302160279* | 50-316 S |
| | 8302070530 | 50-338 G | | 8302160285* | 50-316 S |
| | 8302070540 | 50-338 G | | 8302160312* | 50-315 G |
| | 8302070540 | 50-338 G | | 8302160312* | 50-315 G |
| | 8302100264 | PRM | | 8302160335 | 50-315 S |
| | 8302170263 | 50-322 G | | 8302160337* | 50-315 S |
| | 8302230435 | 50-322 T | | 8302160338* | 50-315 S |
| | 8302250264 | 50-322 G | | 8302160340* | 50-315 S |
| | 8302250344 | 50-280 P | | 8302160342* | 50-315 S |
| Hydro-Engineering | 8302090977* | 40-8745 | | 8302180038* | 50-315 F |
| IIT Research Inst | 8302170435* | NUREG | | 8302180038* | 50-315 F |
| | 8302170438* | NUREG | | 8302180042* | 50-315 F |
| INRYCO, Inc (subs of Inland Steel Co) | 8302230942 | 50-454 S | | 8302180042* | 50-315 F |
| | 8302230555* | 50-454 S | | 8302180226 | 50-316 S |
| Ichthyological Associates, Inc | 8302100117* | 50-320 R | | 8302180230* | 50-316 S |
| | 8302090477 | TOPREP | | 8302180238* | 50-316 S |
| Idaho National Engineering Laboratory | 8301270285 | 50-461 J | | 8302180276 | 50-316 S |
| Illinois Power Co | 8302030112 | 50-461 K | | 8302180285* | 50-316 S |
| | 8302030114* | 50-461 K | | 8302220231 | 50-315 F |
| | 8302070565 | 50-461 G | | 8302220373 | 50-315 F |
| | 8302080179 | 50-461 E | | 8302220373 | 50-315 F |
| | 8302080315 | 50-461 G | | 8302220357 | 50-316 S |
| | 8302080318* | 50-461 G | | 83022203571* | 50-316 S |
| | 8302150032 | 50-461 S | | 8302220082* | 50-315 F |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|---|---------------------|---------------------|
| | 8302250082* | 50-315 F | | 8302230597 | 50-155 G |
| | 8302250092* | 50-315 F | | 8302230610 | 50-155 G |
| | 8302250092* | 50-315 F | | 8302280152 | 50-237 P |
| | 8302250181 | 50-315 S | Island Closeup News Service | 8302080038 | FOIA |
| | 8302250184* | 50-315 S | Isotope Products Laboratories | 8302020370 | XPORTLIC |
| | 8302250238 | 50-316 S | J U-B Engineers, Inc | 8302040466* | 70-1257 |
| | 8302250241* | 50-316 S | Jacobs Engineering Group, Inc | 8302240385 | WASTE MGT |
| | 8302250301 | 50-315 G | Japan, Govt of | 8302090273 | XPORTLIC |
| | 8302250311* | 50-315 G | | 8302240161 | XPORTLIC |
| | 8302280349 | 50-316 S | Jersey Central Power & Light Co | 8302180087* | 50-219 F |
| | 8302280352* | 50-316 S | Joint Applicants-Palo Verde | 8302180394 | 50-528 G |
| | 8302280355* | 50-316 S | Joint Intervenor-Callaway | 8302070573 | 50-483 G |
| | 8302280357 | 50-316 S | Joint Intervenor-Waterford | 8302010543 | 50-382 G |
| | 8302280358* | 50-316 S | | 8302010551* | 50-382 G |
| | 8302280362* | 50-316 S | | 8302080246 | 50-382 G |
| | 8302280364* | 50-316 S | Justice, Dept of | 8302090137* | 50-358 G |
| | 8302280382 | 50-315 S | KMS Fusion Inc (Subs of KMS Industries, Inc) | 8302240165 | XPORTLIC |
| | 8302280389* | 50-315 S | | | |
| | 8302280394 | 50-315 S | Kansas Gas & Electric Co | 8302040019 | 70-2960 |
| | 8302280401 | 50-315 S | | 8302040035 | 70-2960 |
| | 8302280409* | 50-315 S | | 8302070545* | 50-482 G |
| | 8302280410* | 50-315 S | | | |
| | 8302280413 | 50-315 S | | 8302080130* | 50-482 F |
| | 8302280416* | 50-315 S | | 8302080398 | 70-2960 |
| | 8302280422 | 50-316 S | | 8302090374 | 50-482 S |
| | 8302280534 | 50-316 S | | 8302150573* | 50-482 G |
| | 8302280541* | 50-316 S | | 8302160245 | 50-482 G |
| Institute of Electrical & Electronic Engineers | 8302100281 | NUREG | | 8302230504 | 50-482 E |
| Institute of Nuclear Materials Management | 8302250356 | PR | | 8302280423 | 50-482 V |
| | 8302100284 | NUREG | | 8302280511 | 50-482 S |
| Institute of Nuclear Power Operations | 8302240259* | 50-277 R | Kentucky, Univ of | 8302020417* | CONTRACT |
| Insulco, Inc | 8302230341* | 50-382 F | Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) | 8302040005* | 40-2061 |
| Interior, Dept of, Geological Survey | 8302070375 | 50-274 R | | | |
| Interior, Dept of, Bureau of Mines | 8302160491* | CONTRACT | Kerr-McGee Corp | 8302100203 | PR |
| Interior, Dept of, Fish & Wildlife Service | 8302220324 | MISC | | 8302040009 | 40-8027 |
| | 8302230634 | 50-387 P | | 8302070162 | 40-2061 |
| International Brotherhood of Electrical Workers | 8302140025 | 50-440 G | | 8302070166* | 40-2061 |
| International Engineering Co | 8302100114* | CONTRACT | | 8302100358* | PRM |
| Intl Assoc. of Heat & Frost Insulators & Asbestos Workers | 8302250270 | 50-440 G | Kirkpatrick, Lockhart, Hill, Christopher & Phillips | 8302100450 | PR |
| Iowa Electric Light & Power Co | 8302040362 | 50-331 S | | 8302240044 | 40-8663 |
| | 8302040364* | 50-331 S | | 8302020325 | 50-322 G |
| | 8302080245 | 50-331 S | | | |
| | 8302080260* | 50-331 S | | 8302020396 | FOIA |
| | 8302080328 | 50-331 S | | 8302080230 | 50-322 G |
| | 8302080330* | 50-331 S | | | |
| | 8302150174 | 50-331 P | | 8302140149 | 50-322 G |
| | 8302150179* | 50-331 P | Kruger Enterprises, Inc | 8302160375 | 50-322 G |
| | 8302150196 | 50-331 R | Kudzu Alliance | 8302240300 | 50-322 G |
| | 8302150267 | 50-331 P | | 8302240318* | 50-322 G |
| | 8302150279 | 50-331 P | LXI, Inc | 8302240321* | 50-322 G |
| | 8302150283* | 50-331 P | Labat-Anderson, Inc | 8302030330 | 50-423 K |
| | 8302160286* | 50-331 G | | 8302230568 | 50-400 G |
| | 8302170305 | 50-413 G | | 8302230579* | 50-400 G |
| | 8302180471 | 50-331 F | Langlade County Memorial Hosp Antigo, WI | 8302070010 | FOIA |
| | 8302180476* | 50-331 F | Law Engineering Testing Co | 8302100252* | CONTRACT |
| | | | Lawrence Berkeley Laboratory | 8302100326* | PR |
| | | | Lawrence Livermore Laboratory | 8302240400* | 27-39 |
| | 8302220129 | 50-331 R | | 8302250122 | NUREG |
| | 8302220134* | 50-331 R | | 8302030607 | PRDJ |
| | 8302230280 | 50-331 S | | 8302080082* | 50-334 P |
| | 8302230283* | 50-331 S | | | |
| | 8302230452 | 50-331 S | | 8302170208 | NUREG |
| | | | | 8302170213 | NUREG |
| | | | | 8302170469 | NUREG |
| | | | | 8302010404 | 50-341 K |
| | | | | 8302100450 | PR |
| wa Hosp Association | 8302230462* | 50-331 S | | | |
| ham, Lincoln & Beale | 8302100338 | PR | League of Women Voters of Rockford, IL | 8302020257 | 50-454 G |
| | 8302070542 | 50-599 G | | 8302230544 | 50-454 T |
| | 8302080207 | 50-329 G | | 8302230545 | 50-454 F |
| | 8302080207 | 50-329 G | | 8302230545 | 50-454 T |
| | | | | 8302230553* | 50-454 T |
| | 8302080212 | 50-329 G | | | |
| | 8302080212 | 50-329 G | | 8302230553* | 50-454 F |
| | 8302160223 | 50-454 G | | 8302280185 | 50-454 G |
| | 8302170292 | 50-454 T | Logical Technical Service Corp | 8302010009* | CONTRACT |
| | 8302170292 | 50-454 T | Long Island Lighting Co | 8301250435 | 50-322 K |
| | | | | 8301250438* | 50-322 K |
| | 8302180378 | 50-329 G | | | |
| | 8302180378 | 50-329 G | | 8302010359 | 50-322 S |
| | 8302180387 | 50-454 T | | 8302010542 | 50-322 E |
| | 8302180387 | 50-454 T | | 8302020027 | 50-322 A |
| | 8302180390 | 50-329 T | | 8302040346 | 50-322 K |
| | | | | 8302070501 | 50-322 G |
| | 8302180390 | 50-329 T | | | |
| | 8302220291 | 50-454 T | | 8302090364 | 50-322 A |
| | 8302220291 | 50-454 T | | 8302100201 | 50-322 F |
| | 8302230446 | 50-454 G | | 8302100427 | 50-322 E |
| | 8302230446 | 50-454 G | | 8302100450 | PR |
| | | | | 8302140152* | 50-322 G |
| | 8302230455 | 50-454 T | | | |
| | 8302230540 | 50-454 G | | 8302160277 | 50-322 A |
| | | | | 8302170263 | 50-322 G |

CORPORATE SOURCE INDEX

501

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|----------------------------------|---------------------|---------------------|---|---------------------|---------------------|
| | 8302180202 | 50-322 S | Marsh & McLennan, Inc., M & M Nuclear
Consultants, Inc. Div. | 8302010193 | 50-280 J |
| | 8302220374 | 50-322 A | | 8302010193 | 50-280 J |
| | 8302220394 | 50-322 E | | 8302020009 | 50-327 J |
| | 8302230200 | 50-322 S | | 8302020054 | 50-213 J |
| | 8302230439 | 50-322 T | | 8302040270 | 50-483 J |
| | 8302230450* | 50-322 T | | 8302070207 | 50-335 J |
| | 8302230536 | 50-322 T | | 8302070207 | 50-335 J |
| | 8302250006 | 50-322 A | | 8302080146 | TOPREP |
| | 8302250236 | 50-322 A | | 8302080275 | 50-335 J |
| | 8302250264 | 50-322 O | | 8302100218 | 50-397 J |
| | 8302250312 | 50-322 E | | 8302240019 | 50-272 J |
| | 8302250342 | 50-322 E | | 8302020093* | CONTRACT |
| | 8302250429 | 50-322 E | | 8302170540* | CONTRACT |
| | 83022800247 | 50-322 O | Maryland, Univ. of | 8302090561 | 50-293 H |
| | 8302280254* | 50-322 O | Massachusetts Institute of Technology | 8302100294 | PRH |
| | 8302280260* | 50-322 O | Massachusetts, Commonwealth of. | | |
| | 8302280501* | 50-322 O | | 8302170429* | CONTRACT |
| Los Alamos Scientific Laboratory | 8302030032 | RES | Huagang Co | 8302100362 | PR |
| | 8302040468 | NUREG | McDonough District Hosp. Macomb, IL | 8302100233 | PR |
| | 8302080124 | RES | McMaster Univ. | 8302080002 | 50-67 F |
| | 8302100286 | NUREG | Memorial Hosp. of Mason County,
Ludington, MI | 8302100473* | PR |
| | 8302150718 | NUREG | | | |
| | 8302280013 | NUREG | | | |
| Louisiana County, VA | 8302160348 | 50-328 O | Mercy Hosp. & Medical Center Chicago, IL | 8302100356 | PR |
| Louisiana Power & Light Co | 8302010414 | 50-382 A | Metals, Inc. | 8302010046 | PRH |
| | 8302010420 | 50-382 A | Metropolitan Edison Co | 8302010507 | 50-289 O |
| | 8302010520* | 50-382 O | | 8302020171 | 50-320 S |
| | 8302020255 | 50-382 A | | 8302020302 | 50-320 S |
| | 8302020278 | 50-382 O | | | |
| | 8302020341 | 50-382 O | | 8302020350 | 50-289 O |
| | 8302030075 | 50-382 A | | 8302080178 | 50-289 O |
| | 8302030092 | 50-382 A | | 8302160293 | 50-289 O |
| | 8302030095 | 50-382 O | | 8302160317 | 50-289 O |
| | 8302030118 | 50-382 A | | 8302170219 | 50-289 O |
| | 8302030532 | 50-382 A | | | |
| | 8302030570 | 50-382 F | | 8302220347 | 50-289 T |
| | 8302040029 | 70-2946 | | 8302220359* | 50-289 T |
| | 8302070162 | 50-382 A | | 8302220362* | 50-289 T |
| | 8302070272 | 50-382 O | | 8302220365* | 50-289 T |
| | 8302070500 | 50-382 A | | 8302220371* | 50-289 T |
| | 8302070523 | 50-382 A | | | |
| | 8302070616 | 50-382 A | Nimmi Valley Power Project | 8302220375* | 50-289 T |
| | 8302080023 | 50-382 A | | 8302220381* | 50-289 T |
| | 8302080214 | 50-382 F | Michigan State Univ. | 8302220387* | 50-289 T |
| | 8302150684 | 50-382 E | | 8302250310 | 50-289 O |
| | 8302160181 | 50-382 A | | 8302070522 | 50-358 O |
| | 8302160373 | 50-382 A | | | |
| | 8302160378* | 50-382 A | | 8302250175 | 50-294 V |
| | 8302170456* | 50-382 F | | 8302250177* | 50-294 V |
| | 8302170461* | 50-382 F | | 8302250180* | 50-294 V |
| | | | | 8302250180* | CONTRACT |
| | 8302220265 | 50-382 S | Microtech Industries, Inc. | 8302100516* | 71-491 |
| | 8302230301 | 50-382 S | Mid-Con Inspection Services, Inc. | 8302040010 | 71-491 |
| | 8302230320 | 50-382 S | | | |
| | 8302230335 | 50-382 F | | 8302040013* | 71-491 |
| | 8302230345 | 50-382 S | | 8302080084 | 71-491 |
| | 8302230440 | 50-382 A | | 8302080085* | 71-491 |
| | 8302250291 | 50-382 F | Middle South Services, Inc. | 8302100305 | 0A999 |
| | 8302250430 | 50-382 G | Midland-Ross Corp. | 8302030478* | |
| | 8302280327 | 50-382 S | | | |
| | 8302280333 | 50-382 S | | 8302220309 | 50-341 O |
| | 8302280402 | 50-382 A | | 8302010171 | 50-416 S |
| | 8302280535 | 50-382 S | | 8302010172 | 50-416 S |
| | 8301210025 | 50-331 J | | 8302010181* | 50-416 S |
| | 8302100353 | PRH | | 8302010182* | 50-416 S |
| | 8302100354 | PR | | | |
| | 8302100450 | PR | | 8302010194 | 50-416 S |
| | 8302010308 | 50-309 S | | 8302010200* | 50-416 S |
| | 8302010314* | 50-309 S | | 8302010252 | 50-416 S |
| | 8302030469 | 50-309 P | | 8302010261* | 50-416 S |
| | 8302070505 | 50-309 Q | | 8302010425 | 50-416 S |
| | 8302070512 | 50-309 S | | | |
| | 8302070526* | 50-309 F | | 8302010427* | 50-416 S |
| | 8302070535* | 50-309 F | | 8302010470 | 50-416 S |
| | 8302070596* | 50-309 Q | | 8302010475 | 50-416 F |
| | 8302080288 | 50-309 I | | 8302010508 | 50-416 F |
| | 8302100421* | 50-309 O | | | |
| | 8302220383 | 50-309 P | | 8302010528 | 50-416 P |
| | 8302220384 | 50-309 P | | 8302010528 | 50-416 P |
| | 8302220387* | 50-309 P | | 8302030100 | 50-416 S |
| | 8302220430 | 50-309 P | | 8302030106* | 50-416 S |
| | 8302220442* | 50-309 P | | 8302030110 | 50-416 S |
| | 8302220459 | 50-309 P | | | |
| | 8302220554 | 50-309 S | | 8302030113* | 50-416 S |
| | 83022205253 | 50-309 O | | 8302030181 | 50-416 P |
| | 83022205257* | 50-309 G | | 8302030300 | 50-416 S |
| | | | | 8302030307* | 50-416 S |
| | | | | 8302030356 | 50-416 S |
| | | | | | |
| | | | | 8302030359* | 50-416 S |
| | | | | 8302030363 | 50-416 S |
| | | | | 8302030367* | 50-416 S |
| | | | | 8302030387 | 50-416 S |
| | | | | 8302030393* | 50-416 S |
| | | | | | |
| | | | | 8302030554 | 50-416 O |
| | | | | 8302030554 | 50-416 O |
| | | | | 8302030562 | 50-416 S |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|--|---------------------|---------------------|
| | 8302030569* | 50-416 S | Monroe X-Ray Co., Inc. | 8302030042 | 71-6717 |
| | 8302040426 | 50-416 P | Montgomery County, MO | 8302240297 | 50-170 Q |
| | 8302070466 | 50-416 S | Morgan Associates | 8302010930 | 50-247 T |
| | 8302140014 | 50-416 S | | 8302010930 | 50-247 T |
| | 8302140019* | 50-416 S | | 8302020254 | 50-247 Q |
| | 8302140030 | 50-416 S | | 8302020345 | 50-247 Q |
| | 8302140031 | 50-416 S | | 8302020345 | 50-247 Q |
| | 8302140032* | 50-416 S | | 8302030164 | 50-247 Q |
| | 8302140039* | 50-416 S | | 8302030164 | 50-247 Q |
| | 8302140053 | 50-416 S | | 8302030175* | 50-247 Q |
| | 8302140058 | 50-416 S | | 8302030175* | 50-247 Q |
| | 8302140060* | 50-416 S | | 8302070559 | 50-247 Q |
| | 8302140063 | 50-416 S | | 8302090224 | 50-247 T |
| | 8302140064* | 50-416 S | | 8302160271 | 50-247 Q |
| | 8302140067* | 50-416 S | | 8302160271 | 50-247 Q |
| | 8302140089 | 50-416 S | | 8302160278 | 50-247 Q |
| | 8302140093* | 50-416 S | | 8302160278 | 50-247 Q |
| | 8302140100 | 50-416 S | | 8302160324 | 50-247 Q |
| | 8302140102* | 50-416 S | | 8302160324 | 50-247 Q |
| | 8302140196 | 50-416 S | | 8302160372 | 50-247 Q |
| | 8302140204* | 50-416 S | | 8302160372 | 50-247 Q |
| | 8302150003 | 50-416 S | | 8302160384 | 50-247 Q |
| | 8302150094* | 50-416 S | | 8302160385 | 50-247 Q |
| | 8302150099 | 50-416 S | | 8302160385 | 50-247 Q |
| | 8302150106* | 50-416 S | | 8302160399 | 50-247 Q |
| | 8302150110 | 50-416 S | | 8302160399 | 50-247 Q |
| | 8302150115* | 50-416 S | | 8302170260 | 50-247 T |
| | 8302150140 | 50-416 S | | 8302170260 | 50-247 T |
| | 8302150206* | 50-416 S | | 8302170277 | 50-247 T |
| | 8302150351* | 50-416 Q | | 8302170283 | 50-247 T |
| | 8302150675 | 50-416 D | | 8302170283 | 50-247 T |
| | 8302150641* | 50-416 S | | 8302250235 | 50-247 T |
| | 8302160295 | 50-416 P | Harrison-Knudsen Co., Inc. | 8302030080 | PT21 |
| | 8302170121 | 50-416 S | Murray & Trettel, Inc. | 8302180403* | 50-329 T |
| | 8302170127* | 50-416 S | NUG Corp | 8302070006 | FOIA |
| | 8302170308 | 50-416 S | | 8302090254* | 50-537 A |
| | 8302170311* | 50-416 S | | 8302170298* | 50-454 T |
| | 8302170316 | 50-416 S | NUGAC, Inc | 8302010115* | CONTRACT |
| | 8302170320* | 50-416 S | | 8302020123* | CONTRACT |
| | 8302170322 | 50-416 S | | 8302010128* | CONTRACT |
| | 8302170324* | 50-416 S | | 8302100142* | CONTRACT |
| | 8302170346 | 50-416 S | | 8302100423 | PR |
| | 8302170354* | 50-416 S | NUTECH Engineers, Inc | 8302010550* | 50-321 Q |
| | 8302170358 | 50-416 S | | 8302170056* | 50-341 A |
| | 8302170362* | 50-416 D | National Alliance of Senior Citizens | 8302240363 | FOIA |
| | 8302220358 | 50-416 S | | 8302230552 | 50-247 Q |
| | 8302220361* | 50-416 S | National Emergency Civil Liberties Committee | 8302230552 | 50-247 Q |
| | 8302220369 | 50-416 S | | 8302230561* | 50-247 Q |
| | 8302220377* | 50-416 S | | 8302230561* | 50-247 Q |
| | 8302230232 | 50-416 R | | 8302230564* | 50-247 Q |
| | 8302230235* | 50-416 R | | 8302230564* | 50-247 Q |
| | 8302280071 | 50-416 S | | 8302230572* | 50-247 Q |
| | 8302280079* | 50-416 S | | 8302230572* | 50-247 Q |
| | 8302280228 | 50-416 S | | 8302280070* | CONTRACT |
| | 8302280228* | 50-416 S | National Governors' Association | 8302150760* | State Prog |
| | 8302280230 | 50-416 S | | 8302160302 | 50-522 Q |
| | 8302280234* | 50-416 S | National Wildlife Federation | 8302020455 | FOIA |
| | 8302280235 | 50-416 S | Natural Resources Defense Council | 8302160347 | 70-143 |
| | 8302280243* | 50-416 S | | 8302160349* | 70-143 |
| | 8302280283 | 50-416 S | Neal R. Gross & Co., Inc | 8302160104* | 50-289 T |
| | 8302280289* | 50-416 S | | 8302010676 | 50-298 Q |
| | 8302280294 | 50-416 S | Nebraska Public Power District | 8302030333* | 50-298 Q |
| | 8302280301* | 50-416 S | | 8302080408* | 50-298 F |
| | 8302280424 | 50-416 S | | 8302090097* | 50-298 F |
| | 8302280429* | 50-416 S | | 8302180061* | 50-298 F |
| | 8302280434 | 50-416 S | | 8302180362 | 50-298 V |
| | 8302280440* | 50-416 S | | 8302230310* | 50-298 Q |
| | 8302280448 | 50-416 S | | 8302230712 | 50-298 S |
| | 8302280454* | 50-416 S | | 8302230713* | 50-298 S |
| | 8302280458 | 50-416 S | | 8302230724* | 50-298 Q |
| | 8302280464* | 50-416 S | | 8302250309* | 50-298 Q |
| | 8302280462* | CONTRACT | | 8302250370 | 50-298 P |
| | 8302040437 | 50-186 F | | 8302280046 | 50-298 K |
| | 8302040624 | 50-186 F | | 8302280048* | 50-298 K |
| | 8302230401 | 50-186 R | | 8302280050 | 50-298 K |
| | 8302230484* | 50-186 R | | 8302280054 | 50-298 K |
| | 8302280030 | XPORTLIC | | 8302280056 | 50-298 K |
| | 8302280032* | XPORTLIC | | 8302280058 | 50-298 K |
| | 8302020313 | XPORTLIC | | 8302280061 | 50-298 K |
| | 8302020320* | XPORTLIC | | 8302280063 | 50-298 K |
| | 8302020337 | XPORTLIC | | 8302280068 | 50-298 K |
| | 8302020340* | XPORTLIC | | 8302280070 | 50-298 K |
| | 8302070370* | 50-244 Q | | 8302280073 | 50-298 K |
| Source, State of | | | | | |
| Source, Univ. of Columbia | | | | | |
| Subsidiary International Corp (subs of | | | | | |
| Subsidiary Corp) | | | | | |
| Subsidiary & Co. (U.S.A.), Inc (Subs of | | | | | |
| Subsidiary & Co., Ltd) | | | | | |
| Source County, NY | | | | | |

CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|--|------------------|------------------|--------------------------------------|------------------|------------------|
| | 8302280078 | 50-298 K | | 8302020140 | 50-410 K |
| | 8302280083 | 50-298 K | | 8302020143 | 50-410 K |
| | 8302280086 | 50-298 K | | 8302020144 | 50-410 K |
| | 8302280088 | 50-298 K | | 8302020149 | 50-410 K |
| | 8302280092 | 50-298 K | | 8302020157 | 50-410 K |
| | 8302280101 | 50-298 K | | 8302020167 | 50-410 K |
| | 8302280103 | 50-298 K | | 8302020170 | 50-410 K |
| | 8302280104 | 50-298 K | | 8302020172 | 50-410 K |
| | 8302280106 | 50-298 K | | 8302020175 | 50-410 K |
| | 8302280110 | 50-298 K | | 8302020178 | 50-410 K |
| | 8302280111 | 50-298 K | | 8302020180 | 50-410 K |
| | 8302280115 | 50-298 K | | 8302020183 | 50-410 K |
| | 8302280117 | 50-298 K | | 8302020186 | 50-410 K |
| | 8302280119 | 50-298 K | | 8302020189 | 50-410 K |
| | 8302040288 | 50-388 S | | 8302020192 | 50-410 K |
| Wilson Electric Co | 8302240338* | WASTE MGT | | 8302020195 | 50-410 K |
| Canada, State of | 8302010521 | 50-443 G | | 8302020197 | 50-410 K |
| New England Coalition on Nuclear Pollution | 8302080264 | 50-443 G | | 8302020200 | 50-410 K |
| | 8302100387 | FRM | | 8302020203 | 50-410 K |
| | 8302280366 | 50-443 G | | 8302020209 | 50-410 K |
| | 8302280366 | 50-443 G | | 8302020211 | 50-410 K |
| | 8302280382* | 50-443 G | | 8302020187 | 50-220 J |
| | 8302280382* | 50-443 G | | 8302020190 | 50-220 J |
| | 8302280392* | 50-443 G | | 8302020378 | 50-220 F |
| | 8302280392* | 50-443 G | | 8302020160 | 50-410 S |
| | 8302280399* | 50-443 G | | 8302020346 | 50-410 S |
| | 8302280399* | 50-443 G | | 8302020380 | 50-410 G |
| | 8302100256 | FRM | | 8302100291 | PR |
| | 8302150143* | 50-443 X | | 8302140074 | 50-220 V |
| | 8302160346 | 50-443 G | | 8302140074 | 50-220 V |
| | 8302240185* | CONTRACT | | 8302140080 | 50-220 P |
| | 8302170289* | 50-443 G | | 8302140082 | 50-220 R |
| | 8302240240* | CONTRACT | | 8302140084* | 50-220 R |
| | 8302240349* | WASTE MGT | | 8302160389 | 50-220 P |
| | 8302030165 | 50-247 T | | 8302160392* | 50-220 P |
| | 8302030165 | 50-247 T | | 8302160410* | 50-410 F |
| | 8302030184 | 50-247 T | | 8302180346 | 50-410 M |
| | 8302030184 | 50-247 T | | 8302180348* | 50-410 M |
| | 8302030199 | 50-247 T | | 8302230216 | 50-220 P |
| | 8302030199 | 50-247 T | | 8302230331 | 50-410 S |
| | 8302030210 | 50-247 T | | 8302230662 | 50-410 S |
| | 8302030210 | 50-247 T | | 8302230679* | 50-220 G |
| | 8302240001 | XPORTLIC | | 83022306412 | 50-410 A |
| | 8302240002* | XPORTLIC | | 8302230438 | 50-410 S |
| | 8302230471 | 50-247 T | Nissho-Iwai American Corp | 8302240373 | XPORTLIC |
| | 8302230477* | 50-247 T | | 8302240375* | XPORTLIC |
| | 8302230477* | 50-247 T | North Carolina State Univ | 8302020245* | CONTRACT |
| | 8302230387* | 50-247 G | | 8302150075* | 50-111 G |
| | 8302230387* | 50-247 G | | 8302150082* | 50-111 G |
| | 8302230387* | 50-247 G | North Carolina, State of | 8302220025* | CONTRACT |
| | 8302230392* | 50-247 G | | | |
| | 8302230392* | 50-247 G | North Carolina, Univ of | 8302100273 | NUREG |
| | 8302020025 | 50-247 G | Northeast Nuclear Energy Co (subs or | 8301190078 | 50-213 F |
| | 83022300270 | 50-247 G | Northeast Utilities) | 8301190078 | 50-213 F |
| | 8302240034 | 50-201 J | | 8302010091* | 50-213 F |
| | 8302240309 | 50-247 G | | | |
| | 8302010306 | 50-220 P | | 8302010301 | 50-213 P |
| | 8302010370* | 50-220 G | | 8302010491 | 50-245 P |
| | 8302020022 | 50-410 A | | 8302010662* | 50-213 Q |
| | 8302020031* | 50-410 F | | 8302030043* | 50- |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|-----------------------|---------------------|---------------------|
| | 8302030334 | 50-423 K | | 8302030338 | 50-423 K |
| | 8302030336 | 50-423 K | | 8302030341 | 50-423 K |
| | 8302030338 | 50-423 K | | 8302030343 | 50-423 K |
| | 8302030340 | 50-336 S | | 8302030347 | 50-423 K |
| | 8302030341 | 50-423 K | | 8302030349 | 50-423 K |
| | | | | 8302030352 | 50-423 K |
| | 8302030343 | 50-423 K | | 8302030355 | 50-423 K |
| | 8302030347 | 50-423 K | | 8302030358 | 50-423 K |
| | 8302030349 | 50-423 K | | 8302030360 | 50-423 K |
| | 8302030352 | 50-423 K | | 8302030362 | 50-423 K |
| | 8302030355 | 50-423 K | | 8302030364 | 50-423 K |
| | | | | 8302030366 | 50-423 K |
| | 8302030358 | 50-423 K | | 8302030366 | 50-423 K |
| | 8302030360 | 50-423 K | | 8302030368 | 50-423 K |
| | 8302030362 | 50-423 K | | 8302030369 | 50-423 K |
| | 8302030364 | 50-423 K | | 8302030370 | 50-423 K |
| | 8302030366 | 50-423 K | | 8302030371 | 50-423 K |
| | | | | 8302030372 | 50-423 K |
| | 8302030368 | 50-423 K | | | |
| | 8302030369 | 50-423 K | | 8302030373 | 50-423 K |
| | 8302030370 | 50-423 K | | 8302030374 | 50-423 K |
| | 8302030371 | 50-423 K | | 8302030377 | 50-423 K |
| | 8302030372 | 50-423 K | | 8302030380 | 50-423 K |
| | | | | | |
| | 8302030373 | 50-423 K | | 8302030381 | 50-423 K |
| | 8302030374 | 50-423 K | | 8302030382 | 50-423 K |
| | 8302030380 | 50-423 K | | 8302030383 | 50-423 K |
| | 8302030381 | 50-423 K | | 8302030386 | 50-423 K |
| | 8302030382 | 50-423 K | | 8302030390 | 50-423 K |
| | | | | | |
| | 8302030383 | 50-423 K | | 8302030394 | 50-423 K |
| | 8302030386 | 50-423 K | | 8302030392 | 50-245 S |
| | 8302030390 | 50-423 K | | 8302070566 | 50-217 F |
| | 8302030394 | 50-423 K | | 8302100285 | PR |
| | 8302030582 | 50-245 S | | 8302100444 | 50-245 S |
| | | | | | |
| | 8302030588 | 50-245 S | | 8302140105 | PR |
| | 8302070566 | 50-213 F | | 8302150498 | 50-245 F |
| | 8302100444 | 50-245 S | | 8302160224 | 50-213 F |
| | 8302100447 | 50-245 S | | 8302180184 | 50-245 Q |
| | 8302140105 | PR | | 8302180429 | 50-336 F |
| | | | | | |
| | 8302150498 | 50-245 F | | 8302220148 | 50-423 A |
| | 8302160224 | 50-213 F | | 8302220155 | 50-245 P |
| | 8302180184 | 50-245 Q | | 8302220349 | 50-336 S |
| | 8302180429 | 50-336 P | | 8302220427 | 50-245 P |
| | 8302220148 | 50-423 A | | 8302220385 | 50-245 Q |
| | | | | | |
| | 8302220155 | 50-245 P | | 8302230391 | 50-245 Q |
| | 8302220160 | 50-245 P | | 8302230532 | 50-245 Q |
| | 8302220349 | 50-336 S | | 8302240331 | 50-213 P |
| | 8302220427 | 50-245 P | | 8302240331 | 50-213 P |
| | 8302220385 | 50-245 Q | | 8302280097 | 50-213 V |
| | | | | 8302280097 | 50-213 V |
| | 8302220532 | 50-245 Q | | | |
| | 8302240331 | 50-213 P | | 8302280411 | 50-336 S |
| | 8302240331 | 50-213 P | | 8302280415 | 50-336 S |
| | 8302280097 | 50-213 V | | 8302280431 | 50-336 P |
| | 8302280097 | 50-213 V | | 8302280490 | 50-245 P |
| | | | | 8301190078 | 50-213 F |
| | 8302280411 | 50-336 S | | | |
| | 8302280415 | 50-336 S | | 8301190078 | 50-213 F |
| | 8302280431 | 50-336 P | | 8301190078 | 50-213 F |
| | 8302280490 | 50-245 P | | 8302010084 | 50-213 F |
| | 8301190078 | 50-213 F | | 8302010301 | 50-213 P |
| | | | | 8302010491 | 50-245 P |
| | | | | | |
| | 8302030043 | 50-213 F | | 8302030018 | 50-263 F |
| | 8302030043 | 50-213 F | | 8302030018 | 50-263 F |
| | 8302030043 | 50-213 F | | 8302030018 | 50-263 F |
| | 8302030052 | 50-213 F | | 8302030023 | 50-263 F |
| | 8302030093 | 50-245 S | | 8302030023 | 50-263 F |
| | | | | 8302030023 | 50-263 F |
| | | | | 8302030023 | 50-263 F |
| | 8302030184 | 50-423 A | | 8302030030 | 50-263 F |
| | 8302030202 | 50-245 Q | | 8302030036 | 50-263 F |
| | 8302030204 | 50-423 A | | 8302030122 | 71-634h |
| | 8302030230 | 50-423 A | | 8302040513 | 50-263 P |
| | 8302030237 | 50-423 A | | 8302080144 | 50-282 P |
| | | | | | |
| | 8302030243 | 50-423 K | | 8302090415 | 50-282 P |
| | 8302030248 | 50-423 C | | 8302100439 | PR |
| | 8302030250 | 50-245 F | | 8302150369 | 50-263 P |
| | 8302030254 | 50-423 F | | 8302150491 | 50-263 P |
| | 8302030258 | 50-423 F | | 8302150491 | 50-263 P |
| | | | | | |
| | 8302030305 | 50-423 K | | 8302150502 | 50-263 F |
| | 8302030308 | 50-336 S | | 8302150505 | 50-263 P |
| | 8302030310 | 50-423 K | | 8302150548 | 50-263 J |
| | 8302030317 | 50-423 K | | 8302150548 | 50-263 J |
| | 8302030322 | 50-423 K | | 8302150548 | 50-263 J |
| | | | | 8302150548 | 50-263 J |
| | | | | 8302150628 | 50-263 J |
| | 8302030328 | 50-423 K | | 8302150628 | 50-263 J |
| | 8302030330 | 50-423 K | | 8302180139 | 50-263 P |
| | 8302030332 | 50-336 S | | 8302180143 | 50-263 P |
| | 8302030334 | 50-423 K | | 8302180146 | 50-263 P |
| | 8302030336 | 50-423 K | | 8302180265 | 50-263 Q |

Heat Utilities

Northern California Power Agency,
California State of,
Northern States Power Co

CORPORATE SOURCE INDEX

505

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|--|---------------------|---------------------|---|---------------------|---------------------|
| Aethrop Research & Technical Center | 8302230427 | 50-282 Q | | 8302150187 | 50-285 P |
| | 8302230686* | 50-282 Q | | 8302150191* | 50-285 P |
| | 8302230686* | 50-282 Q | | 8302150660 | 50-285 P |
| | 8302240296 | 50-263 P | | 8302150695 | 50-285 P |
| | 8302070282* | 50-187 Q | | 8302220057* | 50-285 F |
| Northwestern Univ.
Nuclear Assurance Corp | 8302010049 | FDIA | | 8302220164 | 50-285 R |
| | 8302040106 | 71-6698 | | 8302220168* | 50-285 R |
| | 8302040476 | 50-280 F | | 8302220221 | 50-285 Q |
| | 8302070158 | XPORTLIC | | 8302230349* | 50-285 Q |
| | 8302070184 | XPORTLIC | | 8302230575 | 50-285 F |
| Nuclear Energy Service, Inc | 8302080004 | 71-6698 | Ornschl, Harrington & Sutcliffe
PMI Industries | 8302230576 | 50-285 P |
| | 8302080009 | 71-6698 | | 8302280378 | 50-285 S |
| | 8302080094 | XPORTLIC | | 8302280389* | 50-285 S |
| | 8302170321* | 50-409 P | | 8302020335* | 50-361 Q |
| | 8302170323* | 50-409 P | | 8302040071* | 50-440 Q |
| Nuclear Fuel Services, Inc (subs of
Petty Oil Co) | 8302170325* | 50-409 P | Pacific Gas & Electric Co | 8302010431 | 50-275 P |
| | 8302170326* | 50-409 P | | 8302010432* | 50-275 P |
| | 8302230337* | 50-382 F | | 8302010432* | 50-275 P |
| | 8302040015 | 70-143 | | 8302010433* | 50-275 P |
| | 8302040017 | 70-143 | | 8302010433* | 50-275 P |
| | 8302040579 | 70-143 | | 8302020002 | 50-275 P |
| | 8302070038 | 70-143 | | 8302020028 | 50-323 J |
| | 8302070046* | 70-143 | | 8302030605* | 50-275 F |
| | 8302070127 | 70-143 | | 8302030611* | 50-275 F |
| | 8302070191 | 70-143 | | 8302040369 | 50-275 R |
| | 8302070636 | 70-143 | | 8302040371* | 50-275 R |
| | 8302070638 | 70-143 | | 8302080176 | 50-275 Q |
| | 8302080087 | 70-143 | | 8302090014 | 50-275 F |
| | 8302080091 | 70-143 | | 8302090014 | 50-275 F |
| | 8302080345 | 70-143 | | 8302090357 | 50-275 F |
| | 8302080377 | 70-143 | | 8302090376 | 50-275 P |
| | 8302090061 | 70-143 | | 8302090428 | 50-275 F |
| | 8302100283 | PR | | 8302090428 | 50-275 F |
| | 8302100362 | PR | | 8302100380 | PRM |
| | 8302150034 | 70-143 | | 8302140034 | 50-133 F |
| Nuclear Packaging, Inc
Neill, J | 8302150315 | 70-143 | | 8302140087 | 50-275 P |
| | 8302100450 | PR | | 8302140110 | 50-275 R |
| | 8302140157 | 50-155 Q | | 8302140115* | 50-275 R |
| | 8302140161* | 50-155 Q | | 8302140117* | 50-275 R |
| | 8302070306* | 40-86 | | 8302140117* | 50-275 R |
| Oak Ridge Associated Univ | 8302280094 | 40-86 | | 8302170331 | 50-275 P |
| | 8302280094 | 40-86 | | 8302170363 | 50-275 P |
| | 8302020139* | 50-27 P | | 8302180163 | 50-275 S |
| | 8302030252 | NUREQ | | 8302180175* | 50-275 S |
| | 8302040502 | NUREQ | | 8302230134 | 50-275 F |
| | 8302040521 | NUREQ | | 8302230134 | 50-275 F |
| | 8302070186* | FDIA | | 8302230398 | 50-275 P |
| | 8302080058* | 71-9855 | | 8302230420 | 50-275 P |
| | 8302170033 | NUREQ | | 8302230493 | 50-275 R |
| | 8302280020 | NUREQ | | 8302230497* | 50-275 R |
| Office of Management & Budget | 8302080351 | ORQ | Palmetto Alliance
Palos Community Hosp Palos Part, IL
Panhandle Eastern Pipeline Co | 8302280024 | 50-275 P |
| | 8302170005 | ORQ | | 8302010610 | 50-413 Q |
| | 8302170007 | ORQ | | 8302100464 | PR |
| | 8302010017 | 40-8745 | | 8302280566 | 71-9033 |
| | 8302090497 | 40-8673 | | 8302040458* | CONTRACT |
| Oile Petroleum, Inc | 8302090583 | 40-8745 | Parameter, Inc
Parents Concerned About Indian Point | 8302160366 | 50-247 Q |
| | 8302100464 | PR | | 8302250399* | 50-247 Q |
| | 8302160412 | 40-8745 | | 8302250405* | 50-247 Q |
| | 8302080234 | 50-440 Q | | 8302250410* | 50-247 Q |
| | 8302080234 | 50-440 Q | | 8302250410* | 50-247 Q |
| | 8302080269 | 50-440 Q | | 8302250416* | 50-247 Q |
| | 8302080269 | 50-440 Q | | 8302250416* | 50-247 Q |
| | 8302140007 | 50-440 Q | | 8302250419* | 50-247 Q |
| | 8302140009 | 50-440 Q | | 8302250419* | 50-247 Q |
| | 8302140016* | 50-440 Q | | 8302090578 | 40-2259 |
| Ohio, State of | 8302140016* | 50-440 Q | Pathfinder Mines Corp | 8302090580* | 40-2259 |
| | 8302080286 | 50-358 Q | | 8302100277 | PR |
| | 8302080293* | 50-358 Q | | 8302100450 | PR |
| | 8302160262 | 80-556 Q | | 8302170386 | 40-6622 |
| | 8302230321 | 50-112 H | | 8302240346 | XPORTLIC |
| Oklahoma, State of
Oklahoma, Univ of | 8302230614 | 50-112 H | Peckinoy Ugin Kuhlmann Development, Inc
Pennsylvania Power & Light Co | 8302010151 | 50-387 S |
| | 8302010568 | 50-285 P | | 8302010158* | 50-387 S |
| | 8302010615 | 50-285 P | | 8302010160 | 50-387 S |
| | 8302010621* | 50-285 P | | 8302010168* | 50-387 S |
| | 8302040026 | 40-8822 | | 8302010324 | 50-387 S |
| Omaha Public Power District | 8302080010* | 50-285 F | | 8302010351 | 50-387 S |
| | 8302080013* | 50-285 F | | 8302010452 | 50-389 S |
| | 8302080188 | 50-285 P | | 8302020410* | 50-387 F |
| | 8302080273* | 50-285 F | | 8302020418* | 50-387 F |
| | 8302080279* | 50-285 F | | 8302030074 | 50-387 S |
| | 8302090383 | 50-285 Q | | 8302030223 | 50-387 S |
| | 8302100296 | 50-285 P | | 8302030276* | 50-387 F |
| | 8302100301* | 50-285 P | | 8302030278 | 50-387 S |
| | 8302150095* | 50-285 Q | | 8302030278* | 50-387 S |
| | | | | | |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|--|---------------------|---------------------|---|---------------------|---------------------|
| | 8302030357 | 50-387 S | | 8302140086 | 50-277 P |
| | 8302030361* | 50-387 S | | 8302150036 | 50-352 A |
| | 8302030403 | 50-387 P | | 8302150654 | 50-277 P |
| | 8302030555 | 50-387 S | | 8302150693 | 50-277 S |
| | 8302030560* | 50-387 S | | 8302170329 | 50-277 P |
| | 8302030564* | 50-387 Q | | 8302170329 | 50-277 P |
| | 8302070247 | 50-387 P | | 8302170330* | 50-277 P |
| | 8302070634 | 70-2937 | | 8302170330* | 50-277 P |
| | 8302090309 | 50-387 P | | 8302180334 | 50-277 R |
| | 8302090314* | 50-387 P | | 8302180334 | 50-277 R |
| | 8302090320* | 50-387 P | | 8302180338* | 50-277 R |
| | 8302090332* | 50-387 P | | 8302180338* | 50-277 R |
| | 8302100277 | PR | | 8302220106 | 50-278 S |
| | 8302100418 | 50-387 S | | 8302220114* | 50-270 S |
| | 8302100424* | 50-387 S | | 8302220121 | 50-278 S |
| | 8302100463 | PRM | | 8302220126* | 50-278 S |
| | 8302150198 | 50-387 P | | 8302220341 | 50-352 S |
| | 8302150207* | 50-387 P | | 8302220341 | 50-352 S |
| | 8302150212* | 50-387 P | | 8302220401 | 50-278 S |
| | 8302150616 | 50-388 A | | 8302220416 | 50-277 S |
| | 8302170490* | 50-387 F | | 8302220402 | 50-278 S |
| | 8302170497* | 50-387 F | | 8302220474 | 50-352 Q |
| | 8302180134 | 50-388 S | | 8302220474 | 50-352 Q |
| | 8302180191 | 50-388 S | | 8302220488 | 50-352 Q |
| | 8302180245 | 50-387 S | | 8302220559 | 50-352 Q |
| | 8302180245 | 50-387 S | | 8302220725 | 50-352 S |
| | 8302180251 | 50-387 F | | 83022208323 | 50-352 S |
| | 8302180251 | 50-387 F | | 83022208323 | 50-352 S |
| | 8302180273 | 50-387 S | | 83022208469* | 50-277 Q |
| | 8302180282* | 50-387 S | Richard, Lowe & Garrick, Inc | 8302150424* | 50-286 P |
| | 8302180317 | 50-387 S | | 8302220082* | 50-286 P |
| | 8302180325* | 50-387 S | | 8302220082* | 50-3 P |
| | 8302220165 | 50-387 S | | 8302220082* | 50-3 P |
| | 8302220172* | 50-387 S | | 8302220082* | 50-3 P |
| | 8302220380 | 50-387 S | | 8302220082* | 50-286 P |
| | 8302220386* | 50-387 S | | 8302220082* | 50-304 P |
| | 8302220398 | 50-387 S | | 8302220089* | 50-3 P |
| | 8302220404* | 50-387 S | | 8302220089* | 50-3 P |
| | 8302220133 | 50-387 S | | 8302220089* | 50-3 P |
| | 8302220139* | 50-387 S | | 8302220089* | 50-304 P |
| | 8302220289 | 50-387 S | | 8302220089* | 50-286 P |
| | 8302220291 | 50-388 S | | 8302220089* | 50-286 P |
| | 8302220292* | 50-387 S | | 8302220100* | 50-286 P |
| | 8302220333 | 50-387 S | | 8302220100* | 50-286 P |
| | 8302220338* | 50-387 S | | 8302220105* | 50-286 P |
| | 8302220447 | 50-387 S | | 8302220105* | 50-286 P |
| | 8302220457* | 50-387 S | | 8302220109* | 50-286 P |
| | 8302220528 | 50-387 S | | 8302220109* | 50-286 P |
| | 8302220694 | 50-387 S | | 8302220113* | 50-286 P |
| | 8302220697* | 50-387 S | | 8302220113* | 50-286 P |
| | 8302220029* | 50-387 F | | 8302220131* | 50-286 P |
| | 8302220035* | 50-387 F | | 8302220131* | 50-286 P |
| | 83022200691 | 50-387 P | | 8302220138* | 50-286 P |
| | 83022200691 | 50-387 P | | 8302220138* | 50-286 P |
| | 83022200547 | 50-387 R | | 8302220144* | 50-286 P |
| | 83022200553* | 50-387 R | | 8302220144* | 50-286 P |
| Pennsylvania State Univ | 8302220168 | 50-5 R | | 8302220150* | 50-286 P |
| Perkins, Cole, Stone, Olsen & Williams | 8302220192* | 50-5 R | | 8302220150* | 50-286 P |
| | 8302080182 | 50-222 Q | | 8302220154* | 50-286 P |
| | 8302100450 | PR | | 8302220154* | 50-286 P |
| Pharmatopes, Inc | 8302220199 | FOIA | | 8302220167* | 50-286 P |
| Philadelphia Electric Co | 8302010188 | 50-278 S | | 8302220167* | 50-286 P |
| | 8302010401* | 50-352 Q | | 8302220173* | 50-286 P |
| | 8302010524 | 50-352 Q | | 8302220173* | 50-286 P |
| | 8302030405 | 50-277 Q | Plateau Resources, Ltd | 8302220422 | 40-8698 |
| | 8302030400 | 50-277 S | | 8302220423* | 40-8698 |
| | 8302030408* | 50-277 S | Pollution & Environmental Problems, Inc | 8302100456 | PRM |
| | 8302040393 | 50-277 P | Portland General Electric Co | 8302010386 | 50-344 P |
| | 8302040393 | 50-277 P | | 8302010398 | 50-344 S |
| | 8302040399* | 50-277 P | | 8302010403* | 50-344 S |
| | 8302040399* | 50-277 P | | 8302010418 | 50-344 S |
| | 8302040404 | 50-277 P | | 8302010561 | 50-344 S |
| | 8302070509 | 50-278 S | | 8302010569* | 50-344 S |
| | 8302070510 | 50-352 Q | | 8302030108 | 50-344 P |
| | 8302070513 | 50-278 S | | 8302030116* | 50-344 P |
| | 8302070520 | 50-277 S | | 8302030121* | 50-344 P |
| | 8302070521 | 50-278 S | | 8302040274 | 50-344 S |
| | 8302080156 | 50-352 A | | 8302080163 | 50-344 P |
| | 8302090318 | 50-277 S | | 8302080172 | 50-344 V |
| | 8302090339 | 50-277 S | | 8302080183* | 50-344 F |
| | 8302090349* | 50-277 S | | 8302080187* | 50-344 F |
| | 8302090393 | 50-278 S | | 8302080227 | 50-344 J |
| | 8302140026 | 50-277 Q | | 8302100277 | PR |
| | 8302140026 | 50-277 Q | | 8302100362 | PR |
| | 8302140086 | 50-277 P | | 8302150713 | 50-344 P |

CORPORATE SOURCE INDEX

507

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|-----------------------|---------------------|---------------------|
| | 8302160365 | 50-514 G | | 8302230288 | 50-333 S |
| | 8302180339 | 50-344 P | | 8302230293* | 50-333 S |
| | 8302230315 | 50-344 Q | | 8302230295 | 50-333 S |
| | 8302230490 | 50-344 P | | 8302230298 | 50-333 S |
| | 8302230500* | 50-344 P | | 8302230299* | 50-333 S |
| | 8302230506* | 50-344 P | | 8302230302* | 50-333 S |
| | 8302140139 | 50-443 Q | | 8302230445 | 50-286 F |
| | 8302140139 | 50-443 Q | | 8302230469 | 50-333 S |
| | 8302140141* | 50-443 G | | 8302230481* | 50-333 S |
| | 8302140141* | 50-443 Q | | 8302230482 | 50-286 P |
| | 8302010332 | 50-333 P | | 8302230482 | 50-286 P |
| | 8302010443 | 50-333 Q | | 8302230537 | 50-333 S |
| | 8302010530 | 50-247 T | | 8302230547* | 50-333 S |
| | 8302010530 | 50-247 T | | 8302230577 | 50-333 S |
| | 8302010536* | 50-247 T | | 8302230594* | 50-333 S |
| | 8302010536* | 50-247 T | | 8302230621* | 50-333 Q |
| | 8302020294 | 50-247 G | | 8302230661 | 50-333 S |
| | 8302020345 | 50-247 Q | | 8302230672* | 50-333 S |
| | 8302020345 | 50-247 Q | | 8302230687 | 50-333 S |
| | 8302030084 | 50-286 Q | | 8302230691* | 50-333 S |
| | 8302030164 | 50-247 Q | | 8302240029 | 50-333 P |
| | 8302030164 | 50-247 Q | | 8302240032* | 50-333 P |
| | 8302030179* | 50-247 Q | | 8302240036* | 50-333 P |
| | 8302030179* | 50-247 Q | | 8302250235 | 50-247 T |
| | 8302030200 | 50-333 S | | 8302250235 | 50-247 T |
| | 8302030205* | 50-333 S | | 8302250240* | 50-247 T |
| | 8302030323 | 50-286 P | | 8302250240* | 50-247 T |
| | 8302030396 | 50-333 S | | 8302260168 | 50-247 T |
| | 8302030402* | 50-333 S | | 8302020236 | 50-461 Q |
| | 8302030413 | 50-333 S | | 8302060248 | 50-461 Q |
| | 8302030421* | 50-333 S | | 8302170259 | 50-461 Q |
| | 8302030424 | 50-286 F | | 8302030079* | 50-537 U |
| | 8302030441 | 50-333 P | | 8302030104* | 50-537 U |
| | 8302070224 | 50-333 J | | 8302240079* | CONTRACT |
| | 8302070559 | 50-247 Q | | 8302090030* | CONTRACT |
| | 8302080159 | 50-333 P | | 8302100432 | PR |
| | 8302080218 | 50-286 P | | 8302040473 | 71-9032 |
| | 8302080239 | 50-333 R | | 8302040485* | CONTRACT |
| | 8302080242* | 50-333 R | | 8302030190 | CONTRACT T |
| | 8302090224 | 50-247 T | | 8302020100* | CONTRACT |
| | 8302090224 | 50-247 T | | 8302010604 | 50-247 Q |
| | 8302090230* | 50-247 T | | 8302090272 | 50-247 T |
| | 8302140105 | PR | | 8302090272 | 50-247 T |
| | 8302150056 | 50-333 J | | 8302090279* | 50-247 T |
| | 8302150159 | 50-333 P | | 8302090279* | 50-247 T |
| | 8302150163* | 50-333 P | | 8302100357 | PRM |
| | 8302150166* | 50-333 P | | 8302160366 | 50-247 Q |
| | 8302150349 | 50-247 P | | 8302160366 | 50-247 Q |
| | 8302150349 | 50-247 P | | 8302240314 | 50-247 Q |
| | 8302150349 | 50-247 P | | 8302240314 | 50-247 Q |
| | 8302150421 | 50-286 P | | 8302250372 | 50-247 Q |
| | 8302150586 | 50-286 J | | 8302250372 | 50-247 Q |
| | 8302160271 | 50-247 Q | | 8302250379* | 50-247 Q |
| | 8302160271 | 50-247 Q | | 8302250379* | 50-247 Q |
| | 8302160278 | 50-247 Q | | 8302250383* | 50-247 Q |
| | 8302160278 | 50-247 Q | | 8302250383* | 50-247 Q |
| | 8302160324 | 50-247 Q | | 8302250393* | 50-247 Q |
| | 8302160324 | 50-247 Q | | 8302250396* | 50-247 Q |
| | 8302160324 | 50-247 Q | | 8302250396* | 50-247 Q |
| | 8302160372 | 50-247 Q | | 8302250405* | 50-247 Q |
| | 8302160372 | 50-247 Q | | 8302250405* | 50-247 Q |
| | 8302160384 | 50-247 Q | | 8302250410* | 50-247 Q |
| | 8302160385 | 50-247 Q | | 8302250428* | 50-247 Q |
| | 8302160385 | 50-247 Q | | 8302250428* | 50-247 Q |
| | 8302160399 | 50-247 Q | | 8302250428* | 50-247 Q |
| | 8302160399 | 50-247 Q | | 8302250428* | 50-247 Q |
| | 8302170260 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170260 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170268* | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170277 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170277 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170280* | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170280* | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170283 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170283 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170283 | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170287* | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302170287* | 50-247 T | | 8302250428* | 50-247 Q |
| | 8302180106* | 50-443 Q | | 8302250428* | 50-247 Q |
| | 8302180106* | 50-443 Q | | 8302250428* | 50-247 Q |
| | 8302180106* | 50-443 Q | | 8302250428* | 50-247 Q |
| | 8302180108 | 50-286 P | | 8302250428* | 50-247 Q |
| | 8302180136 | 50-443 Q | | 8302250428* | 50-247 Q |
| | 8302180136 | 50-443 Q | | 8302250428* | 50-247 Q |
| | 8302180136 | 50-443 Q | | 8302250428* | 50-247 Q |
| | 8302180300 | 50-333 S | | 8302250428* | 50-247 Q |
| | 8302180306* | 50-333 S | | 8302250428* | 50-247 Q |
| | 8302230224 | 50-333 S | | 8302250428* | 50-247 Q |
| | 8302230282 | 50-286 P | | 8302250428* | 50-247 Q |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|------------------------------------|------------------|------------------|--------------------|------------------|------------------|
| Public Service Co of Indiana, Inc | 8302150001 | 50-267 S | | 8302010435 | 50-443 A |
| | 8302150003* | 50-267 S | | 8302010435 | 50-443 A |
| | 8302150574 | 50-267 S | | 8302010529 | 50-443 Q |
| | 8302150593* | 50-267 S | | 8302010529 | 50-443 Q |
| | 8302150618 | 50-267 P | | 8302010533 | 50-443 Q |
| | 8302170344 | 50-267 S | | 8302010533 | 50-443 Q |
| | 8302170349* | 50-267 S | | 8302010547 | 50-443 G |
| | 8302220157 | 50-267 R | | 8302010547 | 50-443 G |
| | 8302220159* | 50-267 R | | 8302010589 | 50-443 G |
| | 8302230174 | 50-267 P | | 8302010589 | 50-443 G |
| | 8302230318 | 50-267 P | | 8302010594* | 50-443 G |
| | 8302230641 | 50-267 R | | 8302010594* | 50-443 G |
| | 8302230646* | 50-267 R | | 8302010646 | 50-443 A |
| | 8302250009* | 50-267 F | | 8302010646 | 50-443 A |
| | 8302250016* | 50-267 F | | 8302020152 | 50-443 A |
| | 8302250232 | 50-267 P | | 8302020152 | 50-443 A |
| | 8302250251 | 50-267 P | | 8302020275 | 50-443 A |
| | 8302250256 | 50-267 V | | 8302020275 | 50-443 A |
| | 8302040391 | 50-546 S | | 8302020275 | 50-443 A |
| | 8302160164 | 50-546 S | | 8302020281 | 50-443 A |
| | 8302160164 | 50-546 S | | 8302020281 | 50-443 A |
| | 8302160213 | 50-546 S | | 8302030275 | 50-443 S |
| | 8302160213 | 50-546 S | | 8302030275 | 50-443 S |
| | 8302180242 | 50-546 S | | 8302030453 | 50-443 S |
| | 8302280121 | 50-546 A | | 8302030453 | 50-443 S |
| | 8302280121 | 50-546 A | | 8302030563 | 50-443 S |
| | 8302280133* | 50-546 A | | 8302030563 | 50-443 S |
| | 8302280133* | 50-546 A | | 8302040036 | 50-443 F |
| | 8302280137* | 50-546 K | | 8302040036 | 50-443 F |
| | 8302280137* | 50-546 K | | 8302040066 | 50-443 A |
| | 8302280143* | 50-546 F | | 8302040066 | 50-443 A |
| | 8302280143* | 50-546 F | | 8302040092 | 50-443 A |
| | 8302280149* | 50-546 C | | 8302040092 | 50-443 A |
| | 8302280149* | 50-546 C | | 8302040109 | 50-443 A |
| | 8302280158* | 50-546 A | | 8302040109 | 50-443 A |
| | 8302280158* | 50-546 A | | 8302040210 | 50-443 F |
| | 8302280161 | 50-546 K | | 8302040210 | 50-443 F |
| | 8302280161 | 50-546 K | | 8302040338 | 50-443 A |
| | 8302280167 | 50-546 K | | 8302040338 | 50-443 A |
| | 8302280167 | 50-546 K | | 8302040356 | 50-443 R |
| | 8302280167 | 50-546 K | | 8302040356 | 50-443 R |
| | 8302280171 | 50-546 K | | 8302040372 | 50-443 A |
| | 8302280171 | 50-546 K | | 8302040372 | 50-443 A |
| | 8302280172 | 50-546 M | | 8302040425 | 50-443 A |
| | 8302280172 | 50-546 M | | 8302040425 | 50-443 A |
| | 8302280177* | 50-546 M | | 8302080186 | 50-443 A |
| | 8302280285 | 50-546 K | | 8302080186 | 50-443 A |
| | 8302280285 | 50-546 K | | 8302080215 | 50-443 A |
| | 8302280291 | 50-546 K | | 8302080215 | 50-443 A |
| | 8302280291 | 50-546 K | | 8302100220 | 50-443 G |
| 8302280293 | 50-546 K | | 8302100220 | 50-443 G | |
| 8302280293 | 50-546 K | | 8302100228 | 50-443 Q | |
| 8302280298 | 50-546 K | | 8302100228 | 50-443 Q | |
| 8302280298 | 50-546 K | | 8302100235 | 50-443 Q | |
| 8302280299 | 50-546 K | | 8302100235 | 50-443 Q | |
| 8302280299 | 50-546 K | | 8302100243 | 50-443 Q | |
| 8302280305 | 50-546 K | | 8302100243 | 50-443 Q | |
| 8302280305 | 50-546 K | | 8302100287 | FR | |
| 8302280307 | 50-546 K | | 8302150407 | 50-443 A | |
| 8302280307 | 50-546 K | | 8302150407 | 50-443 A | |
| 8302280308 | 50-546 K | | 8302150451 | 50-443 A | |
| 8302280308 | 50-546 K | | 8302150451 | 50-443 A | |
| 8302280309 | 50-546 K | | 8302150451 | 50-443 A | |
| 8302280314 | 50-546 K | | 8302160166 | 50-443 A | |
| 8302280314 | 50-546 K | | 8302160166 | 50-443 A | |
| 8302280317 | 50-546 K | | 8302160207 | 50-443 Q | |
| 8302280317 | 50-546 K | | 8302160207 | 50-443 Q | |
| 8302280319 | 50-546 K | | 8302160263 | 50-443 A | |
| 8302280319 | 50-546 K | | 8302160263 | 50-443 A | |
| 8302280322 | 50-546 K | | 8302160274 | 50-443 A | |
| 8302280322 | 50-546 K | | 8302160274 | 50-443 A | |
| 8302280324 | 50-546 K | | 8302160323 | 50-443 G | |
| 8302280324 | 50-546 K | | 8302160323 | 50-443 G | |
| 8302280326 | 50-546 K | | 8302160326 | 50-443 A | |
| 8302280326 | 50-546 K | | 8302160326 | 50-443 A | |
| 8302280328 | 50-546 K | | 8302160329 | 50-443 Q | |
| 8302280328 | 50-546 K | | 8302160329 | 50-443 Q | |
| 8302280330 | 50-546 K | | 8302160352 | 50-443 Q | |
| 8302280330 | 50-546 K | | 8302160352 | 50-443 Q | |
| 8302280331 | 50-546 K | | 8302170366 | 50-443 Q | |
| 8302280331 | 50-546 K | | 8302170366 | 50-443 Q | |
| 8302280332 | 50-546 K | | 8302170369 | 50-443 A | |
| 8302280332 | 50-546 K | | 8302170369 | 50-443 A | |
| 8302280334 | 50-546 K | | 8302180093 | 50-443 Q | |
| 8302010406 | 50-443 A | | 8302180093 | 50-443 Q | |
| 8302010406 | 50-443 A | | 8302180295 | 50-443 Q | |
| Public Service Co of New Hampshire | | | 8302180295 | 50-443 Q | |

509

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|--------------------------------------|---------------------|---------------------|
| | 8302180302* | 50-443 Q | | 8302180499* | 50-272 P |
| | 8302180302* | 50-443 Q | | 8302180499* | 50-272 P |
| | 8302180300 | 50-443 Q | | 8302220133 | 50-311 R |
| | 8302180300 | 50-443 Q | | 8302220138* | 50-311 R |
| | 8302180310 | 50-443 Q | | 8302220173 | 50-272 R |
| | 8302180310 | 50-443 Q | | 8302220177* | 50-272 R |
| | 8302180314* | 50-443 Q | | 8302220385 | 50-272 P |
| | 8302180314* | 50-443 Q | | 8302220389* | 50-272 P |
| | 8302180322 | 50-443 Q | | 8302220153 | 50-354 R |
| | 8302180322 | 50-443 Q | | 8302220171 | 50-354 R |
| | 8302180355 | 50-443 Q | | 8302220531 | 50-354 A |
| | 8302180355 | 50-443 Q | | 8302220428 | 50-354 S |
| | 8302180357* | 50-443 Q | Puerto Rico, Univ of | 8302040032 | TOPREF |
| | 8302180357* | 50-443 Q | Puget Sound Power & Light Co | 8302060182 | 50-522 Q |
| | 8302180360 | 50-443 Q | Purdue Research Foundation | 8302170571* | CONTRACT |
| | 8302180360 | 50-443 Q | | 8302080475 | ACRB |
| | 8302180361* | 50-443 Q | Purdue Univ | 8302030259 | NUREG |
| | 8302180361* | 50-443 Q | Quadrax Corp | 8302160409 | 40-3453 |
| | 8302180373 | 50-443 Q | R I Williams & Associates, Inc | 8302170010 | 40-8745 |
| | 8302180373 | 50-443 Q | | 8302180525* | CONTRACT |
| | 8302180400 | 50-443 Q | | 8302140041 | 50-275 R |
| | 8302180400 | 50-443 Q | R I Ready, Inc | 8302220014 | 50-273 P |
| | 8302180406* | 50-443 Q | | 8302010028* | CONTRACT |
| | 8302180406* | 50-443 Q | Rural Utilities, Inc | 8302070170* | 50-288 F |
| | 8302180421 | 50-443 Q | Reed College | 8302070177* | 50-288 F |
| | 8302180421 | 50-443 Q | | 8302080243 | 50-483 Q |
| | 8302180463 | 50-443 Q | Reed, J Q | 8302160297 | 50-483 Q |
| | 8302180463 | 50-443 Q | | 8302220607 | 50-483 Q |
| | 8302180467 | 50-443 Q | Reedy, Herbert, Gibbons & Associates | 8302090306 | 50-275 P |
| | 8302180467 | 50-443 Q | | 8302090311 | 50-275 P |
| | 8302180493* | 50-443 Q | | 8302040465* | CONTRACT |
| | 8302180493* | 50-443 Q | Rehab Group, Inc | 8302040167* | CONTRACT |
| | 8302220166 | 70-447 A | Rensselaer Polytechnic Inst | 8302250498 | YPORTLIC |
| | 8302220166 | 70-447 A | Ruster Oiles, Inc | 8302010372* | 50-193 Q |
| | 8302220327 | 50-443 A | Rhode Island & Providence Plantation | 8302040439 | PROJ |
| | 8302220327 | 50-443 A | Ridhaigh, Loggers & Associates | 8302040443* | PROJ |
| | 8302220337 | 50-443 A | | 8302250322 | PR |
| | 8302220331 | 50-443 A | Rio Algon, Ltd | 8302090182 | 50-275 P |
| | 8302220331 | 50-443 A | Robert L Cloud Associates, Inc | 8302180488 | 50-275 R |
| | 8302220338 | 50-443 A | | 8302240278 | 50-275 P |
| | 8302220339 | 50-443 A | | 8302240282* | 50-275 P |
| | 8302220339 | 50-443 A | | 8302240284 | 50-275 P |
| | 8302220449 | 50-443 A | | 8302240292* | 50-275 P |
| | 8302220449 | 50-443 A | Robinson Group | 8302080395 | FOIA |
| | 8302220033 | 50-443 A | Rochester Gas & Electric Corp | 8302030378 | 50-244 S |
| | 8302220033 | 50-443 A | | 8302040382 | 50-244 P |
| | 8302220072 | 50-443 A | | 8302070270 | 50-244 P |
| | 8302220072 | 50-443 A | | 8302070275* | 50-244 P |
| | 8302220072 | 50-443 A | | 8302070367* | 50-244 Q |
| | 8302220072 | 50-443 A | | 8302070370* | 50-244 Q |
| | 8302220072 | 50-443 A | | 8302070557 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302090441* | 50-244 Q |
| | 8302220072 | 50-443 A | | 8302140073 | 50-244 P |
| | 8302220072 | 50-443 A | | 8302140116 | 50-244 Q |
| | 8302220072 | 50-443 A | | 8302180292 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302180298* | 50-244 S |
| | 8302220072 | 50-443 A | | 8302180312* | 50-244 Q |
| | 8302220072 | 50-443 A | | 8302180330 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302180337* | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230360 | 50-244 P |
| | 8302220072 | 50-443 A | | 8302230363* | 50-244 P |
| | 8302220072 | 50-443 A | | 8302230367* | 50-244 P |
| | 8302220072 | 50-443 A | | 8302230426 | 50-244 F |
| | 8302220072 | 50-443 A | | 8302230495 | 50-244 P |
| | 8302220072 | 50-443 A | | 8302230556 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230569 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230570* | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230586* | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230667 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230674* | 50-244 B |
| | 8302220072 | 50-443 A | | 8302230674* | 50-244 B |
| | 8302220072 | 50-443 A | | 8302230714 | 50-244 F |
| | 8302220072 | 50-443 A | | 8302230715 | 50-244 S |
| | 8302220072 | 50-443 A | | 8302230723* | 50-244 S |
| | 8302220072 | 50-443 A | | 8302260548 | 71-6574 |
| | 8302220072 | 50-443 A | | 8302180381 | 50-247 T |
| | 8302220072 | 50-443 A | | 8302180381 | 50-247 T |
| | 8302220072 | 50-443 A | | 8302180384* | 50-247 T |
| | 8302220072 | 50-443 A | | 8302180384* | 50-247 T |
| | 8302220072 | 50-443 A | | 83022020378* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | 83022020380* | WASTE MGT |
| | 8302220072 | 50-443 A | | | |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-------------------------------------|---------------------|---------------------|----------------------------------|---------------------|---------------------|
| Mountain Energy Co | 8302100233 | PR | San Diego Gas & Electric Co | 8302100410 | PR |
| | 8302220345* | 50-352 G | | 8302150150 | 50-312 P |
| | 8302220353* | 50-352 G | | 8302150214 | 50-312 V |
| | 8302020400 | 40-8380 | | 8302150533 | 50-312 P |
| | 8302170012 | 40-8452 | | 8302160218 | 50-312 P |
| | 8302170014* | 40-8452 | | 830217037J | 50-312 R |
| | 8302170015 | 40-8697 | | 8302170376* | 50-312 R |
| | 8302170017* | 40-8697 | | 8302180149 | 50-312 R |
| | 8302170020 | 40-8380 | | 8302180154* | 50-312 R |
| | 8302170021* | 40-8380 | | 8302220319 | 50-312 P |
| Johnson & Associates, Inc
& Gray | 8302240049 | 40-8380 | Sandia Laboratories | 8302230163 | 50-312 P |
| | 8302020102* | 50-320 F | | 8302230366 | 50-312 G |
| | 8302010529 | 50-443 G | | 8302230604 | 50-312 S |
| | 8302010529 | 50-443 G | | 8302230613* | 50-312 S |
| | 8302010573 | 50-443 G | | 8302230620 | 50-312 P |
| | 8302010533 | 50-443 G | | 8302230629* | 50-312 P |
| | 8302010547 | 50-443 G | | 8302240030 | 50-312 J |
| | 8302010547 | 50-443 G | | 8302250305 | 50-312 G |
| | 8302010589 | 50-443 G | | 8302250380 | 50-312 P |
| | 8302010589 | 50-443 G | | 8302250386* | 50-312 P |
| Johnson & Associates, Inc
& Gray | 8302010594* | 50-443 G | Sandvik Special Metals Corp | 8302280043 | 50-312 P |
| | 8302010594* | 50-443 G | | 8302280197 | 50-312 G |
| | 8302100220 | 50-443 G | | 8302280201* | 50-312 G |
| | 8302100320 | 50-443 G | | 8302280209 | 50-312 P |
| | 8302100320 | 50-443 G | | 8302280214* | 50-312 P |
| | 8302100220 | 50-443 G | | 8302220337* | 50-361 P |
| | 8302100235 | 50-443 G | | 8302220337* | 50-361 P |
| | 8302100235 | 50-443 G | | 8302220339* | 50-361 P |
| | 8302100243 | 50-443 G | | 8302220339* | 50-361 P |
| | 8302100243 | 50-443 G | | 8302280284* | 50-361 P |
| Johnson & Associates, Inc
& Gray | 8302160207 | 50-443 G | Sargant & Lundy, Inc | 8302040508 | NUREG |
| | 8302160207 | 50-443 G | | 8302070240* | FOIA |
| | 8302160323 | 50-443 G | | 8302070244* | FOIA |
| | 8302160327 | 50-443 G | | 8302080117 | RES |
| | 8302160329 | 50-443 G | | 8302090381* | 0A999 |
| | 8302160329 | 50-443 G | | 8302180211* | 50-358 A |
| | 8302160352 | 50-443 G | | 8302220298* | 50-454 T |
| | 8302160352 | 50-443 G | | 8302220298* | 50-454 T |
| | 8302180093 | 50-443 G | | 8302220304* | 50-454 T |
| | 8302180093 | 50-443 G | | 8302220304* | 50-454 T |
| Johnson & Associates, Inc
& Gray | 8302180136 | 50-443 G | Sassafraz Audubon Society | 8302220325* | 50-454 T |
| | 8302180136 | 50-443 G | | 8302220325* | 50-454 T |
| | 8302180295 | 50-443 G | | 8302030133* | 50-537 U |
| | 8302180295 | 50-443 G | | 8302090504* | CONTRACT |
| | 8302180300 | 50-443 G | | 83020310344* | 50-333 P |
| | 8302180309 | 50-443 G | | 8309030344* | 50-219 P |
| | 8302180310 | 50-443 G | | 8309030368* | 50-312 G |
| | 8302180310 | 50-443 G | | 8302020136* | 50-29 P |
| | 8302180312 | 50-443 G | | 8302030022* | CONTRACT |
| | 8302180312 | 50-443 G | | 8302030211* | CONTRACT |
| Johnson & Associates, Inc
& Gray | 8302180355 | 50-443 G | Seacoast Anti-Pollution League | 8302040006* | 50-220 P |
| | 8302180355 | 50-443 G | | 8302070090* | FOIA |
| | 8302180360 | 50-443 G | | 8302070151* | CONTRACT |
| | 8302180360 | 50-443 G | | 8302070264 | 50-213 P |
| | 8302180375 | 50-443 G | | 8302070269* | 50-213 P |
| | 8302180375 | 50-443 G | | 8302100029* | CONTRACT |
| | 8302180375 | 50-443 G | | 8302080189 | 50-443 G |
| | 8302180375 | 50-443 G | | 8302080189 | 50-443 G |
| | 8302180375 | 50-443 G | | 8302080238 | 50-443 G |
| | 8302180375 | 50-443 G | | 8302080238 | 50-443 G |
| Johnson & Associates, Inc
& Gray | 8302180465 | 50-443 G | Seismological Society of America | 8302170201 | 50-443 G |
| | 8302180465 | 50-443 G | | 8302170201 | 50-443 G |
| | 8302180465 | 50-443 G | | 8302170284 | 50-443 G |
| | 8302180407 | 50-443 G | | 8302170284 | 50-443 G |
| | 8302180407 | 50-443 G | | 8302160037* | CONTRACT |
| | 8302250423 | 50-293 P | | 7910230415* | 50-440 U |
| | 8302080134* | CONTRACT | | 8302020196* | COMMISSION |
| | 8302160309* | CONTRACT | | 8302030024* | 50-537 U |
| | 8302020273* | CONTRACT | | 8302030037* | 50-537 U |
| | 8302020424* | CONTRACT | | 8302030086* | 50-537 U |
| Johnson & Associates, Inc
& Gray | 8302210434 | 50-312 P | Senate | 8302030099* | 50-537 U |
| | 8302020304 | 50-312 P | | 8302090183* | COMMISSION |
| | 8302020310* | 50-312 P | | 8302100319 | PR |
| | 8302030049* | 50-312 P | | 8302100321 | PR |
| | 8302030054* | 50-312 P | | 8302100325* | PR |
| | 8302040057 | 50-312 P | | 8302100346* | PR |
| | 8302040208 | 50-312 P | | 8302100351* | PR |
| | 8302040213* | 50-312 P | | 8302100356 | PR |
| | 8302040237 | 50-312 P | | 8302100365* | PR |
| | 8302040258 | 50-312 G | | 8302100371* | PR |
| Johnson & Associates, Inc
& Gray | 8302040276* | 50-312 G | Senate | 8302100372* | PR |
| | 8302050281 | 50-312 G | | 8302100376* | PR |
| | 8302080161 | 50-312 P | | 8302100378 | PR |
| | 8302080162 | 50-312 P | | 8302100386* | PR |
| | 8302080256 | 50-312 P | | 8302100389* | PR |
| | 8302080262* | 50-312 P | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

CORPORATE SOURCE INDEX

511

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|-------------------------------|---------------------|---------------------|
| | 8302100394 | PR | | 8302150132 | 50-395 R |
| | 8302100403* | PR | | 8302150136* | 50-395 R |
| | 8302100411* | PR | | 8302150215 | 50-395 S |
| | 8302100435* | PR | | 8302150223* | 50-395 S |
| | 8302100449* | PR | | 8302150584 | 50-395 S |
| | 8302100453* | PR | | 8302150593* | 50-395 S |
| | 8302100455 | PR | | 8302150613 | 50-395 S |
| | 8302100465 | PR | | 8302150624* | 50-395 S |
| | 8302250331* | PR | | 8302150639 | 50-395 Q |
| | 8302250351 | PR | | 8302150649 | 50-395 Q |
| | 8302250362* | PR | | 8302150656 | 50-395 S |
| Continental Farm | 8302100362 | PR | | 8302150666* | 50-395 S |
| Ernst, Pittman, Potts & Trowbridge | 8302010507 | 50-289 Q | | 8302170241 | 50-395 S |
| | 8302020278 | 50-382 Q | | 8302170244* | 50-395 S |
| | 8302020341 | 50-382 Q | | 8302180096* | 50-395 F |
| | 8302020350 | 50-289 Q | | 8302180099* | 50-395 F |
| | 8302030180 | 50-400 Q | | 8302220244 | 50-395 P |
| | 8302040004 | 40-2061 | | 8302220331 | 50-395 P |
| | 8302040005* | 40-2061 | | 8302220432 | 50-395 P |
| | 8302070490 | 50-400 Q | | 8302220437 | 50-395 R |
| | 8302070555 | 50-440 Q | | 8302220196 | 50-395 S |
| | 8302080170 | 50-289 Q | | 8302220198* | 50-395 S |
| | 8302100202 | 50-440 Q | | 8302220479 | 50-395 V |
| | 8302100383 | PR | South Carolina, State of | 8302220074* | CONTRACT |
| | 8302100426 | PRM | | 8302240327* | WASTE MGT |
| | 8302160293 | 50-289 Q | South Carolina, Univ of | 8302250442* | 50-395 R |
| | 8302160317 | 50-289 Q | Southampton, NY | 8302280273 | 50-322 Q |
| | 8302160344 | 50-261 Q | Southern California Edison Co | 8302010138 | 50-361 S |
| | 8302170206 | 50-440 Q | | 8302010150* | 50-361 S |
| | 8302170219 | 50-289 Q | | 8302010159 | 50-361 S |
| | 8302180024 | FOIA | | 8302010169* | 50-361 S |
| | 8302220347 | 50-289 T | | 8302010280 | 50-361 S |
| | 8302220387* | 50-289 T | | 8302010285* | 50-361 S |
| | 8302220417 | 50-400 Q | | 8302010327 | 50-361 S |
| | 8302220417 | 50-400 Q | | 8302010346* | 50-361 S |
| | 8302220496 | 50-400 Q | | 8302010394 | 50-361 S |
| | 8302220496 | 50-400 Q | | 8302010405* | 50-361 S |
| | 8302220580 | 50-440 Q | | 8302010412* | 50-361 S |
| | 8302220589 | 50-400 Q | | 8302010546 | 50-361 P |
| | 8302250305 | 50-312 Q | | 8302010546 | 50-361 P |
| | 8302250310 | 50-289 Q | | 8302010650 | 50-361 S |
| | 8302250430 | 50-382 Q | | 8302010668 | 50-361 S |
| | 8302280160 | 50-440 Q | | 8302010674* | 50-361 S |
| | 8302280160 | 50-440 Q | | 8302010678 | 50-362 S |
| | 8302280266 | 50-440 Q | | 8302010681* | 50-362 S |
| Shoreham Opponents Coalition | 8302280266 | 50-440 Q | | 8302020004 | 50-361 P |
| | 8302020318 | 50-322 Q | | 8302020030 | 50-362 P |
| | 8302140152* | 50-322 Q | | 8302020142 | 50-206 P |
| Sierra Club | 8302280260* | 50-322 Q | | 8302020241 | 50-206 P |
| | 8302080166 | 50-440 Q | | 8302020335* | 50-361 C |
| | 8302100440 | PRM | | 8302020335* | 50-361 Q |
| | 8302100452 | PRM | | 8302020357 | 50-206 P |
| Simons, Li & Associates, Inc | 8302090510* | CONTRACT | | 8302070083* | 50-206 F |
| Impact Associates, Inc | 8302230328* | 50-528 E | | 8302070082* | 50-206 F |
| Mississippi Alliance for the Environment (SAFE) | 8302090229 | 50-454 Q | | 8302070064* | 50-206 F |
| | 8302140211 | PRM | | 8302070066* | 50-206 F |
| Small Business Administration | 8302010009* | CONTRACT | | 8302070072* | 50-206 F |
| | 8302010133* | 50-537 A | | 8302070082* | 50-206 F |
| | 8302020090* | CONTRACT | | 8302070084* | 50-206 F |
| | 8302280292* | CONTRACT | | 8302070117* | 50-206 F |
| | 8302180394 | 50-528 Q | | 8302070273 | 50-361 S |
| Snell & Wilmer | 8302100404 | PR | | 8302070273 | 50-361 S |
| Society of Nuclear Medicine | 8302100470* | PR | | 8302080164 | 50-361 P |
| South Carolina Electric & Gas Co | 8302010111 | 50-395 S | | 8302080164 | 50-361 P |
| | 8302010120* | 50-395 S | | 8302080168* | 50-361 P |
| | 8302010139 | 50-395 S | | 8302080168* | 50-361 P |
| | 8302010155 | 50-395 S | | 8302090010 | 50-361 P |
| | 8302010162* | 50-395 S | | 8302090305 | 50-206 P |
| | 8302010165* | 50-395 S | | 8302100280 | 50-361 P |
| | 8302010342 | 50-395 F | | 8302140079 | 50-361 P |
| | 8302010374 | 50-395 Q | | 8302150053 | 50-361 P |
| | 8302010378* | 50-395 S | | 8302150053 | 50-361 P |
| | 8302010584 | 50-395 S | | 8302150120* | 50-206 Q |
| | 8302010591* | 50-395 S | | 8302150147 | 50-362 S |
| | 8302030392 | 50-395 Q | | 8302150155* | 50-362 S |
| | 8302030398* | 50-395 Q | | 8302150184 | 50-206 P |
| | 8302040341 | 50-395 P | | 8302150217 | 50-362 S |
| | 8302070381 | 50-395 S | | 8302150227 | 50-206 P |
| | 8302070383* | 50-395 S | | 8302150229* | 50-362 S |
| | 8302070594 | 50-395 P | | 8302150245 | 50-361 S |
| | 8302080237 | 50-395 J | | 8302150276 | 50-361 S |
| | 8302100223 | 50-395 P | | 8302150281* | 50-361 S |
| | 8302100226* | 50-395 P | | 8302150285* | 50-361 S |
| | 8302100317 | 50-395 F | | 8302150322 | 50-361 S |
| | | | | 8302150329* | 50-361 S |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|---------------------------------|---------------------|---------------------|
| | 8302150332 | 50-206 P | | 8302180112 | 50-275 R |
| | 8302150433 | 50-361 S | | 8302180492 | 50-275 R |
| | 8302150447* | 50-361 S | | 8302230536 | 50-322 T |
| | 8302150552 | 50-361 S | | 8302250414* | 50-329 G |
| | 8302150555 | 50-361 S | | 8302250421* | 50-329 G |
| | 8302190564* | 50-361 S | | 8302250427* | 50-329 G |
| | 8302150566* | 50-361 S | | 8302250431* | 50-329 G |
| | 8302150571 | 50-361 S | Stone & Webster, Inc | 8302040218 | 50-334 S |
| | 8302150577* | 50-361 S | | 8302040337* | 50-329 G |
| | 8302150580* | 50-361 S | | 8302040337* | 50-329 G |
| | 8302160249 | 50-361 P | | 8302040341* | 50-329 G |
| | 8302160249 | 50-361 P | | 8302040341* | 50-329 G |
| | 8302160256* | 50-361 P | | 8302040343* | 50-329 G |
| | 8302160256* | 50-361 P | | 8302040345* | 50-329 G |
| | 8302160391 | 50-206 F | | 8302040349* | 50-329 G |
| | 8302160391 | 50-206 F | | 8302230157 | 50-329 A |
| | 8302160391 | 50-206 F | | 8302230157 | 50-329 A |
| | 8302160394 | 50-206 P | | 8302230161 | 50-329 A |
| | 8302180231 | 50-361 G | | 8302230161 | 50-329 A |
| | 8302180234* | 50-361 S | | 8302230165 | 50-329 A |
| | 8302180237 | 50-361 S | | 8302280527 | 50-329 A |
| | 8302180239* | 50-361 S | Structural Mechanics Associates | 8302160189 | 50-329 A |
| | 8302180291 | 50-361 P | | 8302170909 | 50-329 A |
| | 8302180329 | 50-206 J | | 8302280176* | 50-329 A |
| | 8302180418 | 50-206 P | Suffolk County, NY | 8302020325 | 50-322 G |
| | 8302180454 | 50-361 F | | 8302080230 | 50-322 G |
| | 8302180454 | 50-361 F | | 8302140149 | 50-322 G |
| | 8302220334 | 50-361 P | | 8302140152* | 50-322 G |
| | 8302220334 | 50-361 P | | 8302160375 | 50-322 G |
| | 8302220337* | 50-361 P | | 8302240300 | 50-322 G |
| | 8302220337* | 50-361 P | | 8302240313 | 50-322 G |
| | 8302220337* | 50-361 P | | 8302240318* | 50-322 G |
| | 8302220337* | 50-361 P | | 8302240321* | 50-322 G |
| | 8302220378 | 50-206 F | | 8302280247 | 50-322 G |
| | 8302250213 | 50-361 B | | 8302280254* | 50-322 G |
| | 8302250223 | 50-361 G | | 8302280260* | 50-322 G |
| | 8302250224* | 50-361 G | Sugarman, R J | 8302080233 | 50-352 G |
| | 8302250226* | 50-361 S | | 8302080233 | 50-352 G |
| | 8302250250 | 50-206 P | | 8302080257 | 50-352 G |
| | 8302280280 | 50-361 P | | 8302080257 | 50-352 G |
| | 8302280280 | 50-361 P | | 8302180419 | 50-352 G |
| | 8302280284* | 50-361 P | | 8302180419 | 50-352 G |
| | 8302280284* | 50-361 P | | 8302180425* | 50-352 G |
| | 8302280288* | 50-361 P | Srawlewicz, S A | 8302170487 | NUREG |
| | 8302280288* | 50-361 P | | 8302170491 | NUREG |
| Southern Co Services, Inc | 8302010647 | 50-424 S | | 8302170496 | NUREG |
| | 8302030261 | 50-424 C | | 8302220441 | NUREG |
| | 8302150714 | 50-424 G | | 8302220442 | NUREG |
| Southwest Research and Information Center | 8302250369 | PRM | | 8302220443 | NUREG |
| Southwestern Laboratories | 8302070015 | 71-6717 | Technassociates, Inc | 8302280252* | CONTRACT |
| Soyland Power Cooperative, Inc | 8302070565 | 50-461 G | Technical Operations, Inc | 8302070284 | 71-9107 |
| Union Chemical Co | 8302240244* | 70-146 | | 8302070287* | 71-9107 |
| | 8302240246* | 70-146 | Texnetron Research, Inc | 8302040479 | NUREG |
| | 8302240253* | 70-146 | Telodyne Engineering Services | 8302030496 | 50-275 R |
| W D Co r Electromagnetic Industries | 8302100460 | PR | | 8302030501* | 50-275 R |
| Alphonse Hosp Port Washington, NY | 8302100347 | PR | | 8302080206* | 50-346 P |
| Francis Hosp Evanston, IL | 8302100464 | PR | | 8302090152 | 50-275 P |
| Louis Univ | 8302220125* | 50-206 P | | 8302090152 | 50-275 P |
| Viris, B | 8302080306 | 50-329 A | | 8302090165 | 50-275 P |
| Standard Nuclear Unit Power Plant | 8302040245 | 50-482 A | | 8302090182 | 50-275 P |
| ten | 8302040245 | 50-482 A | | 8302090182 | 50-275 P |
| | 8302040245 | 50-482 A | | 8302150235 | 50-322 A |
| | 8302040363 | 50-482 C | | 8302180252 | 50-275 P |
| | 8302040363 | 50-482 E | | 8302180252 | 50-275 P |
| | 8302040363 | 50-482 E | | 8302180277 | 50-275 R |
| | 8302040374 | 50-482 E | | 8302180281* | 50-275 R |
| | 8302040374 | 50-482 E | | 8302220368 | 50-275 P |
| | 8302040374 | 50-482 E | | 8302240280 | 50-275 P |
| | 8302090308 | 50-482 A | | 8302240280 | 50-275 P |
| | 8302250198 | 50-482 G | | 8302240282* | 50-275 P |
| e, Dept of, Bureau of Oceans & | 8302090267 | XPORTLIC | | 8302240292* | 50-275 P |
| ernat! Environ & Scientific Affairs | 8302090277 | XPORTLIC | Telodyne (Mah Chang Albany | 8302160129 | XPORTLIC |
| | 8302240403 | XPORTLIC | Tennessee Valley Authority | 8301180127 | 50-259 G |
| | 8302250504 | XPORTLIC | | 8302010141 | 50-296 G |
| | 8302010421 | TOPREP | | 8302010167* | 50-296 G |
| k Equipment Co | 8302030338 | 50-423 K | | 8302010215 | 50-390 G |
| | 8302030343 | 50-423 K | | 8302010215 | 50-390 G |
| | 8302030353 | 50-423 K | | 8302010215 | 50-390 G |
| | 8302100291 | PR | | 8302010215 | 50-390 G |
| | 8302100373 | PRM | | 8302010215 | 50-390 G |
| | 8302100428 | PRM | | 8302010217 | 50-259 G |
| le & Webster Engineering Corp | 8302140078 | 50-275 P | | 8302010227* | 50-259 G |
| | 8302140083* | 50-275 P | | 8302010230 | 50-390 G |
| | | | | 8302010230 | 50-390 G |

CORPORATE SOURCE INDEX

513

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|-----------------------|---------------------|---------------------|
| | 8302010233 | 50-390 S | | 8302070359 | 50-390 S |
| | 8302010233 | 50-390 S | | 8302070359 | 50-390 S |
| | 8302010243 | 50-390 S | | 8302070380 | 50-518 S |
| | 8302010243 | 50-390 S | | 8302070585 | 50-390 S |
| | 8302010254 | 50-390 S | | 8302090002 | 50-259 P |
| | | | | | |
| | 8302010254 | 50-390 S | | 8302090004* | 50-259 P |
| | 8302010265 | 50-438 S | | 8302090334* | 50-537 B |
| | 8302010265 | 50-438 S | | 8302100330 | 50-259 P |
| | 8302010270 | 50-296 S | | 8302100330 | 50-259 P |
| | 8302010283* | 50-296 S | | 8302100332* | 50-259 P |
| | | | | | |
| | 8302010293 | 50-390 S | | 8302100332* | 50-259 P |
| | 8302010293 | 50-390 S | | 8302100380 | PRH |
| | 8302010300 | 50-438 S | | 8302100415 | 50-390 F |
| | 8302010300 | 50-438 S | | 8302100415 | 50-390 F |
| | 8302010368 | 50-327 S | | 8302140001 | 50-438 S |
| | | | | | |
| | 8302010417 | 50-518 S | | 8302140004 | 50-260 S |
| | 8302010417 | 50-518 S | | 8302140005* | 50-260 S |
| | 8302010419 | 50-438 S | | 8302140017 | 50-296 S |
| | 8302010419 | 50-438 S | | 8302140018 | 50-438 S |
| | 8302010419 | 50-438 S | | 8302140021* | 50-296 S |
| | | | | | |
| | 8302010419 | 50-438 S | | 8302140037 | 50-296 S |
| | 8302010419 | 50-438 S | | 8302140038 | 50-390 S |
| | 8302010450 | 50-438 A | | 8302140038 | 50-390 S |
| | 8302010450 | 50-438 A | | 8302140040* | 50-296 S |
| | 8302010453 | 50-390 S | | 8302140054 | 50-390 S |
| | | | | | |
| | 8302010453 | 50-390 S | | 8302140054 | 50-390 S |
| | 8302010461 | 50-390 S | | 8302140055 | 50-390 S |
| | 8302010461 | 50-390 S | | 8302140059 | 50-390 S |
| | 8302010500 | 50-437 S | | 8302140059 | 50-390 S |
| | 8302010583 | 50-259 P | | 8302140068 | 50-390 S |
| | | | | | |
| | 8302010587 | 50-327 P | | 8302140068 | 50-390 S |
| | 8302010587 | 50-327 P | | 8302140071 | 50-390 S |
| | 8302010598 | 50-390 S | | 8302140076 | 50-259 F |
| | 8302010598 | 50-390 S | | 8302140094 | 50-438 S |
| | 8302010614 | 50-259 P | | 8302140129 | 50-390 S |
| | | | | | |
| | 8302010631 | 50-438 S | | 8302140129 | 50-390 S |
| | 8302010631 | 50-438 S | | 8302140144 | 50-260 S |
| | 8302010648 | 50-390 S | | 8302140150* | 50-260 S |
| | 8302010648 | 50-390 S | | 8302140154 | 50-390 S |
| | 8302010648 | 50-390 S | | 8302140154 | 50-390 S |
| | | | | | |
| | 8302010659 | 50-438 S | | 8302150035 | 50-260 Q |
| | 8302010659 | 50-438 S | | 8302150047 | 50-260 Q |
| | 8302010664 | 50-438 S | | 8302150051 | 50-390 S |
| | 8302020119 | 40-1341 | | 8302150051 | 50-390 S |
| | 8302030062* | 50-259 F | | 8302150065 | 50-259 Q |
| | | | | | |
| | 8302030062* | 50-259 F | | 8302150160 | 50-390 S |
| | 8302030062* | 50-259 F | | 8302150160 | 50-390 S |
| | 8302030065* | 50-259 F | | 8302150167 | 50-296 S |
| | 8302030273 | 50-328 S | | 8302150192 | 50-438 S |
| | 8302030283* | 50-328 S | | 8302150271 | 50-390 S |
| | | | | | |
| | 8302030426 | 50-327 S | | 8302150271 | 50-390 S |
| | 8302030439* | 50-327 S | | 8302150271 | 50-390 S |
| | 8302030443 | 50-328 S | | 8302150271 | 50-390 S |
| | 8302030459 | 50-390 S | | 8302150305* | 50-327 Q |
| | 8302030459 | 50-390 S | | 8302150317* | 50-259 Q |
| | | | | | |
| | 8302030490 | 50-438 S | | 8302150326* | 50-259 Q |
| | 8302030490 | 50-438 S | | 8302150353* | 50-390 Q |
| | 8302030498 | 50-390 S | | 8302150372 | 50-327 P |
| | 8302030499 | 50-390 S | | 8302150372 | 50-327 P |
| | 8302030514 | 50-390 S | | 8302150376 | 50-438 S |
| | | | | | |
| | 8302030514 | 50-390 S | | 8302150444 | 50-438 S |
| | 8302030518 | 50-296 S | | 8302150470* | 50-327 Q |
| | 8302030527* | 50-296 S | | 8302150473 | 50-438 S |
| | 8302030529 | 50-438 S | | 8302150475 | 50-259 S |
| | 8302030529 | 50-438 S | | 8302150484* | 50-438 Q |
| | | | | | |
| | 8302030542 | 50-438 S | | 8302150524 | 50-327 S |
| | 8302030542 | 50-438 S | | 8302150536* | 50-327 S |
| | 8302030551 | 50-566 S | | 8302150544 | 50-328 S |
| | 8302030558 | 50-438 S | | 8302150554 | 50-327 Q |
| | 8302030558 | 50-438 S | | 8302150554 | 50-327 Q |
| | | | | | |
| | 8302030567 | 50-259 S | | 8302150568* | 50-328 S |
| | 8302030577* | 50-259 S | | 8302150572 | 50-438 S |
| | 8302030628* | 50-259 F | | 8302150572 | 50-438 S |
| | 8302030628* | 50-259 F | | 8302150583 | 50-438 S |
| | 8302030628* | 50-259 F | | 8302150610 | 50-259 Q |
| | | | | | |
| | 8302030629* | 50-259 F | | 8302150610 | 50-259 Q |
| | 8302030629* | 50-259 F | | 8302150610 | 50-259 Q |
| | 8302030629* | 50-259 F | | 8302150610 | 50-259 Q |
| | 8302040041 | 50-327 P | | 8302150610 | 50-259 Q |
| | 8302040041 | 50-327 P | | | |
| | | | | | |
| | 8302040044* | 50-327 P | | 8302150610 | 50-259 Q |
| | 8302040044* | 50-327 P | | 8302150610 | 50-259 Q |
| | 8302040056 | 50-327 P | | 8302150655* | 50-327 Q |
| | 8302070321 | 50-327 P | | 8302150681* | 50-259 Q |
| | 8302070321 | 50-327 P | | 8302150681* | 50-259 Q |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|--------------------------------------|---------------------|---------------------|
| | 8302150681* | 50-259 Q | | 8302280175 | 50-260 S |
| | 8302160183 | 50-438 C | | 8302280178 | 50-438 S |
| | 8302160183 | 50-438 C | | 8302280184* | 50-260 S |
| | 8302160253 | 50-390 S | | 8302280194 | 50-327 S |
| | 8302170003 | 40-1341 | | 8302280200* | 50-327 S |
| | 8302170048 | 50-260 S | | 8302280240 | 50-327 P |
| | 8302170141 | 50-327 S | | 8302280245* | 50-327 P |
| | 8302170142 | 50-296 S | | 8302280335 | 50-438 S |
| | 8302170146* | 50-327 S | | 8302280335 | 50-438 S |
| | 8302170148* | 50-296 S | | 8302280338 | 50-296 S |
| | 8302170165 | 50-260 P | | 8302280340* | 50-296 S |
| | 8302170182 | 50-327 S | | 8302280334 | 50-259 S |
| | 8302170182 | 50-327 S | | 8302280349* | 50-259 S |
| | 8302170207 | 50-438 S | | 8302280457 | 50-327 S |
| | 8302170215 | 50-438 S | | 8302280463 | 50-328 S |
| | 8302170342 | 50-438 S | | 8302280469* | 50-327 S |
| | 8302170342 | 50-438 S | | 8302280471* | 50-328 S |
| | 8302170343 | 50-259 S | | 8302280472 | 50-259 S |
| | 8302170348* | 50-259 S | | 8302280481* | 50-259 S |
| | 8302170356 | 50-390 S | | 8302280495 | 50-390 Q |
| | 8302170356 | 50-390 S | | 8302280499 | 50-438 S |
| | 8302180333* | 50-537 S | | 8302280499 | 50-438 S |
| | 8302220245 | 50-438 S | | 8302280500* | 50-390 Q |
| | 8302230108 | 50-327 S | Teton Exploration Drilling Co., Inc. | 8302020386 | 40-8728 |
| | 8302230111* | 50-327 S | | 8302020389* | 40-8728 |
| | 8302230137 | 50-553 A | | 8302010592 | 50-128 P |
| | 8302230138* | 50-553 A | Texas A&M Univ., College Station, TX | 8302010607* | 50-128 P |
| | 8302230143 | 50-259 P | | 8302100396 | PR |
| | 8302230143 | 50-259 P | | 8302140131 | 50-128 P |
| | 8302230143 | 50-259 P | | 8302140136* | 50-128 P |
| | 8302230152 | 50-390 S | | 8302150504 | 50-128 P |
| | 8302230152 | 50-390 S | | 8302150510* | 50-128 P |
| | 8302230160 | 50-390 S | Texas Utilities Generating Co. | 8302070419* | 50-445 Q |
| | 8302230160 | 50-390 S | | 8302070578 | 50-445 Q |
| | 8302230219 | 50-438 S | | 8302080352 | 70-2932 |
| | 8302230219 | 50-438 S | | 8302090403 | 50-445 Q |
| | 8302230230 | 50-327 S | | 8302100216 | 50-445 J |
| | 8302230233* | 50-327 S | | 8302100238 | 50-445 U |
| | 8302230234 | 50-438 S | | 8302100242* | 50-445 Q |
| | 8302230234 | 50-438 S | | 8302100246* | 50-445 Q |
| | 8302230296 | 50-438 S | | 8302170175 | 50-445 K |
| | 8302230330 | 50-438 S | | 8302170175 | 50-445 K |
| | 8302230330 | 50-438 S | | 8302170179* | 50-445 K |
| | 8302230343 | 50-390 S | | 8302170179* | 50-445 K |
| | 8302230344 | 50-259 Q | | 8302170357* | 50-445 Q |
| | 8302230344 | 50-259 Q | | 8302170368 | 50-445 P |
| | 8302230411 | 50-259 P | | 8302170368 | 50-445 P |
| | 8302230411 | 50-259 P | | 8302230648* | 50-445 Q |
| | 8302230411 | 50-259 P | | 8302280295 | 50-445 S |
| | 8302230414* | 50-259 P | Texas Utilities Services, Inc. | 8302080158 | 50-445 A |
| | 8302230414* | 50-259 P | | 8302230177 | 50-445 E |
| | 8302230414* | 50-259 P | | 8302230177 | 50-445 E |
| | 8302230514 | 50-390 S | | 8302230402 | 50-445 V |
| | 8302230514 | 50-390 Q | | 8302230402 | 50-445 V |
| | 8302230551 | 50-328 S | | 8302230460 | 50-445 A |
| | 8302230562* | 50-328 S | | 8302280256 | 50-445 A |
| | 8302230567 | 50-260 S | Texas, State of | 8302170339 | 50-445 A |
| | 8302230578* | 50-260 S | Texas, Univ. of | 8302070256 | 50-192 P |
| | 8302230590 | 50-327 P | | 8302100367 | 50-192 P |
| | 8302230590 | 50-327 P | | 8302100417 | 50-192 P |
| | 8302230609 | 50-259 S | Thomas & Hair | 8302020408 | 50-352 A |
| | 8302230618 | 50-296 S | | 8302030462* | 50-352 Q |
| | 8302230622* | 50-259 S | Toledo Edison Co. | 8301180134 | 50-346 Q |
| | 8302230628* | 50-296 S | | 8302030176 | 50-346 P |
| | 8302230645 | 50-438 S | | 8302030212* | 50-346 F |
| | 8302230645 | 50-438 S | | 8302030214* | 50-346 F |
| | 8302230647 | 50-390 S | | 8302030388 | 50-346 P |
| | 8302230647 | 50-390 S | | 8302030395* | 50-346 P |
| | 8302230682 | 50-259 P | | 8302040063 | 50-346 P |
| | 8302230682 | 50-259 P | | 8302040272 | 50-346 F |
| | 8302230682 | 50-259 P | | 8302070250 | 50-346 P |
| | 8302240254 | 50-327 S | | 8302070369 | 50-346 P |
| | 8302240257* | 50-327 S | | 8302070478 | 50-346 P |
| | 8302240261 | 50-327 S | | 8302070569 | 50-346 P |
| | 8302240266* | 50-327 S | | 8302070631* | 50-346 F |
| | 8302280123 | 50-390 S | | 8302070633* | 50-346 F |
| | 8302280123 | 50-390 S | | 8302080136 | 50-346 S |
| | 8302280142 | 50-390 S | | 8302080142* | 50-346 S |
| | 8302280142 | 50-390 S | | 8302080198 | 50-346 P |
| | 8302280150 | 50-327 S | | 8302080209 | 50-346 P |
| | 8302280155* | 50-327 S | | 8302080223 | 50-346 P |
| | 8302280159 | 50-327 S | | 8302080228 | 50-346 P |
| | 8302280162* | 50-327 S | | 8302080378* | 50-346 F |
| | 8302280165 | 50-390 S | | 8302080380* | 50-346 F |
| | 8302280169 | 50-390 S | | 8302100362 | PR |

CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|---------------------------------------|---------------------|---------------------|
| | 8302090448 | 50-280 A | | 8302280307 | 50-546 K |
| | 8302140024 | 50-339 S | | 8302280308 | 50-546 K |
| | 8302140027* | 50-339 S | | 8302280308 | 50-546 K |
| | 8302140036 | 50-339 S | | 8302280314 | 50-546 K |
| | 8302140047* | 50-339 S | | 8302280314 | 50-546 K |
| | 8302140062 | 50-281 S | | 8302280317 | 50-546 K |
| | 8302140066* | 50-281 S | | 8302280317 | 50-546 K |
| | 8302140069* | 50-281 S | | 8302280319 | 50-546 K |
| | 8302140072* | 50-281 S | | 8302280319 | 50-546 K |
| | 8302140081 | 50-339 S | | 8302280322 | 50-546 K |
| | 8302140088 | 50-339 S | | 8302280322 | 50-546 K |
| | 8302140092 | 50-338 S | | 8302280324 | 50-546 K |
| | 8302140095* | 50-339 S | | 8302280324 | 50-546 K |
| | 8302140096* | 50-339 S | | 8302280326 | 50-546 K |
| | 8302140098* | 50-338 S | | 8302280326 | 50-546 K |
| | 8302150050 | 50-280 J | | 8302280328 | 50-546 K |
| | 8302150050 | 50-280 J | | 8302280328 | 50-546 K |
| | 8302150158 | 50-280 Q | | 8302280330 | 50-546 K |
| | 8302150535* | 50-338 Q | | 8302280330 | 50-546 K |
| | 8302150541* | 50-338 Q | | 8302280331 | 50-546 K |
| | 8302150585* | 50-280 Q | | 8302280331 | 50-546 K |
| | 8302160260 | 50-280 F | | 8302280332 | 50-546 K |
| | 8302170152 | 50-339 S | | 8302280332 | 50-546 K |
| | 8302170158* | 50-339 S | | 8302280334 | 50-546 K |
| | 8302170190 | 50-338 S | | 8302280334 | 50-546 K |
| | 8302170200* | 50-338 S | Washington Public Power Supply System | 8302010416 | 50-508 A |
| | 8302170220 | 50-339 S | | 8302010548 | 50-460 C |
| | 8302170226* | 50-339 S | | 8302020003 | 50-508 C |
| | 8302170365 | 50-280 S | | 8302020033 | 50-397 A |
| | 8302170371* | 50-280 S | | 8302020068 | 50-508 C |
| | 8302170375* | 50-280 S | | 8302030282 | 50-508 A |
| | 8302180441 | 50-280 P | | 8302030346 | 50-397 F |
| | 8302180441 | 50-280 P | | 8302030351* | 50-397 I |
| | 8302180448* | 50-280 P | | 8302040069 | 50-397 A |
| | 8302180448* | 50-280 P | | 8302040102* | 50-397 A |
| | 8302230141 | 50-280 F | | 8302040110* | 50-397 A |
| | 8302230196 | 50-280 S | | 8302040128* | 50-397 A |
| | 8302230203* | 50-280 S | | 8302040376 | 50-397 R |
| | 8302230265 | 50-280 P | | 8302070231 | 50-397 S |
| | 8302230265 | 50-280 P | | 8302070242 | 50-397 S |
| | 8302250428 | 50-280 P | | 8302070248 | 50-508 S |
| | 8302250428 | 50-280 P | | 8302070255* | 50-508 Q |
| | 8302250435* | 50-280 P | | 8302070276 | 50-508 A |
| | 8302250435* | 50-280 P | | 8302070283 | 50-397 S |
| | 8302260080 | 50-280 P | | 8302070488 | 50-460 Q |
| | 8302280202 | 50-280 P | | 8302080005 | 70-2950 |
| | 8302280486 | 50-339 S | | 8302080177 | 50-508 S |
| | 8302280491* | 50-339 S | | 8302080211 | 50-460 A |
| Virginia Polytechnic Institute | 8302150438* | 50-124 Q | | 8302090238 | 50-460 C |
| | 8302170251 | KUREG | | 8302090366 | 50-397 A |
| Virginia, Univ. of | 8302020155* | CONTRACT | | 8302090388 | 50-397 A |
| Volpe, Boskey & Lyons | 8302170265 | 50-348 M | | 8302090401 | 50-397 Q |
| Washington Valley Power Association, Inc. | 8302280121 | 50-546 A | | 8302100338 | PP |
| | 8302280121 | 50-546 A | | 8302150189 | 50-397 A |
| | 8302280133* | 50-546 A | | 8302150200 | 50-397 J |
| | 8302280133* | 50-546 A | | 8302150231 | 50-460 G |
| | 8302280137* | 50-546 K | | 8302150231 | 50-460 Q |
| | 8302280137* | 50-546 K | | 8302150489 | 50-397 Q |
| | 8302280143* | 50-546 F | | 8302150597 | 50-397 A |
| | 8302280143* | 50-546 F | | 8302150637 | 50-397 A |
| | 8302280149* | 50-546 C | | 8302160215 | 50-397 I |
| | 8302280149* | 50-546 C | | 8302160215 | 50-397 I |
| | 8302280158* | 50-546 A | | 8302160215 | 50-397 I |
| | 8302280158* | 50-546 A | | 8302160215 | 50-397 I |
| | 8302280161 | 50-546 K | | 8302160215 | 50-397 I |
| | 8302280161 | 50-546 K | | 8302160215 | 50-397 I |
| | 8302280167 | 50-546 K | | 8302160239* | 50-397 I |
| | 8302280167 | 50-546 K | | 8302160239* | 50-397 I |
| | 8302280171 | 50-546 K | | 8302160239* | 50-397 I |
| | 8302280171 | 50-546 K | | 8302160239* | 50-397 I |
| | 8302280172 | 50-546 M | | 8302160239* | 50-397 I |
| | 8302280172 | 50-546 M | | 8302160239* | 50-397 I |
| | 8302280285 | 50-546 K | | 8302170391 | 50-397 A |
| | 8302280285 | 50-546 K | | 8302180215 | 50-508 S |
| | 8302280291 | 50-546 K | | 8302180423* | 50-397 Q |
| | 8302280291 | 50-546 K | | 8302220350 | 50-460 Q |
| | 8302280293 | 50-546 K | | 8302220352* | 50-460 Q |
| | 8302280293 | 50-546 K | | 8302230148 | 50-508 S |
| | 8302280298 | 50-546 K | | 8302230154* | 50-508 S |
| | 8302280298 | 50-546 K | | 8302230205 | 50-397 S |
| | 8302280299 | 50-546 K | | 8302230209* | 50-397 S |
| | 8302280299 | 50-546 K | | 8302230213* | 50-397 S |
| | 8302280305 | 50-546 K | | 8302230238 | 50-508 S |
| | 8302280305 | 50-546 K | | 8302230246* | 50-508 S |
| | 8302280307 | 50-546 K | | 8302230285 | 50-397 A |

CORPORATE SOURCE INDEX

517

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|---|---------------------|---------------------|----------------------------------|---------------------|---------------------|
| | 8302230374 | 50-397 A | | 8302010595 | 50-266 P |
| | 8302230383* | 50-397 A | | 8302010603 | 50-266 Q |
| | 8302230386 | 50-397 F | | 8302030366 | 50-266 P |
| | 8302230521 | 50-397 A | | 8302030566 | 50-266 P |
| | 8302230595* | 50-508 Q | | 8302080320 | 50-266 Q |
| | 8302250248 | 50-460 Q | | 8302090408 | 50-301 P |
| | 8302250298 | 50-460 Q | | 8302090421 | 50-266 F |
| Washington, State of | 8302040448* | 27-48 | | 8302100272 | PRM |
| Washington, Univ. of | 8302030458 | 50-139 R | | 8302150410 | 50-266 P |
| | 8302030463* | 50-139 R | | 8302170153 | 50-266 R |
| Water, Waste & Land, Inc | 8302010039* | CONTRACT | | 8302170153 | 50-266 R |
| Waterford, CT | 8302240075* | CONTRACT | | 8302170155* | 50-266 R |
| Wayne County, Nc | 8302070370* | 50-244 Q | | 8302180195 | 50-266 S |
| Wayne, NJ | 8302250210* | 40-86 | | 8302180206* | 50-266 S |
| | 8302250214* | 40-86 | | 8302230236 | 50-266 P |
| Wegman, Hessler & Vandenburg | 8302040375 | 50-440 Q | | 8302230236 | 50-266 P |
| West Branch Conservation Association | 8302280163 | 50-247 Q | | 8302240157 | 50-266 I |
| | 8302280163 | 50-247 Q | | 8302240157 | 50-266 I |
| | 8302280277 | 50-247 Q | | 8302280154 | 50-266 P |
| | 8302280277 | 50-247 Q | | 8302280154 | 50-266 P |
| West Valley Agricultural Protection | 8302070595 | 50-529 Q | | 8302280156 | 50-266 P |
| Council, Inc | 8302230350 | 50-528 Q | | 8302280156 | 50-266 P |
| Westchester Peoples Action Coalition, Inc | 8302250396* | 50-247 Q | | 8302280310 | 50-266 P |
| | 8302250399* | 50-247 Q | | 8302280366 | 50-266 P |
| Western Illinois Power Cooperative, Inc | 8302070565 | 50-461 Q | | 8302280552* | 50-266 Q |
| Westinghouse Electric Corp | 8301250293 | 70-1151 | Wisconsin Public Service Corp | 8302010343 | 50-305 S |
| | 8302020327 | TOPREP | | 8302010350* | 50-305 S |
| | 8302020369 | XPORTLIC | | 8302020347 | 50-305 P |
| | 8302030111 | XPORTLIC | | 8302020352* | 50-305 P |
| | 8302070256 | PROJ | | 8302040277 | 50-305 V |
| | 8302030339 | PROJ | | 8302040340 | 50-305 S |
| | 8302070489 | PT21 | | 8302040347* | 50-305 S |
| | 8302070553 | 70-1143 | | 8302040411* | 50-305 Q |
| | 8302070560* | 70-1143 | | 8302080226 | 50-305 S |
| | 8302070599* | 50-395 P | | 8302080231* | 50-305 S |
| | 8302070602* | 50-395 P | | 8302100285 | PR |
| | 8302080139* | FOIA | | 8302100291 | PR |
| | 8302090297* | TOPREP | | 8302100443 | PR |
| | 8302090423 | TOPREP | | 8302150144 | 50-305 S |
| | 8302090424* | TOPREP | | 8302150151* | 50-305 S |
| | 8302090426* | TOPREP | | 8302160377 | 50-305 R |
| | 8302090427* | TOPREP | | 8302160380* | 50-305 R |
| | 8302090429* | TOPREP | | 8302230466 | 50-305 P |
| | 8302090475 | TOPREP | Wisconsin's Environmental Decade | 8302280166 | 50-305 P |
| | 8302090484* | TOPREP | | 8302180427 | 50-266 Q |
| | 8302090490* | TOPREP | Wyle Laboratories | 8302010292* | 50-373 P |
| | 8302100287 | PR | | 8302080204* | 50-373 P |
| | 8302100328 | PR | Wyoming Fuel Co | 8302220572 | 40-8829 |
| | 8302100336* | PR | Wyoming Mineral Corp | 8302220580* | 40-8829 |
| | 8302100338 | PR | | 8302100073 | 40-8502 |
| | 8302160314* | TOPREP | | 8302100079* | 40-8502 |
| | 8302160316* | TOPREP | | 8302160450 | 40-8502 |
| | 8302160320* | TOPREP | | 8302160454* | 40-8502 |
| | 8302170302* | 50-494 T | | 8302230276 | 40-8502 |
| | 8302170302* | 50-494 I | | 8302240055 | 40-8502 |
| | 8302220317* | 50-494 T | Wyoming Mining Association | 8302100464 | PR |
| | 8302220317* | 50-494 T | Wyoming, State of | 8302010022 | 40-8714 |
| | 8302220379 | TOPREP | | 8302010069 | 40-8743 |
| | 8302220384* | TOPREP | | 8302010077 | 40-279 |
| | 8302230351* | 50-537 A | | 8302010078 | 40-279 |
| | 8302230461* | 50-494 T | | 8302090554 | 40-8584 |
| | 8302230640* | REVIEW GRP | | 8302100440 | PRM |
| | 8302240312 | TOPREP | Yakima Indian Nation | 8302170094 | 40-4492 |
| | 8302240316* | TOPREP | | 8302010585 | 50-522 Q |
| | 8302250365 | PR | | 8302160302 | 50-522 Q |
| | 8302250492 | XPORTLIC | Yale Univ | 8302030184 | 50-247 T |
| | 8302280002 | XPORTLIC | | 8302250403* | 50-247 Q |
| | 8302280003* | XPORTLIC | Yankee Atomic Electric Co | 8302010391 | 50-29 Q |
| | 8302280312* | 50-266 P | | 8302010406 | 50-443 A |
| | 8302280404* | 50-295 P | | 8302010406 | 50-443 A |
| | 8302280546 | TOPREP | | 8302010435 | 50-443 A |
| | 8302280554* | TOPREP | | 8302010435 | 50-443 A |
| Westinghouse Operating Plants Owners | 8302090292 | TOPREP | | 8302010646 | 50-443 A |
| Group | | | | 8302010646 | 50-443 A |
| | 8302160305 | TOPREP | | 8302020152 | 50-443 A |
| Weston Geophysical Corp | 8302030341 | 50-423 K | | 8302020152 | 50-443 A |
| | 8302030349 | 50-423 K | | 8302020273 | 50-443 A |
| | 8302030352 | 50-423 K | | 8302020273 | 50-443 A |
| | 8302070479* | 50-29 P | | 8302020281 | 50-443 A |
| Whittaker Corp | 8302070018 | 40-7455 | | 8302020281 | 50-443 A |
| Williams College, Massachusetts | 8302030317 | 50-423 K | | 8302030279 | 50-443 S |
| | | | | 8302030279 | 50-443 S |
| Williams-Robinette & Associates, Inc | 8302220445* | CONTRACT | | 8302030455 | 50-443 S |
| Wilson, R | 8302070590 | 50-400 Q | | 8302030455 | 50-443 S |
| Wisconsin Electric Power Co | 8302010595 | 50-266 P | | 8302030563 | 50-443 S |

CORPORATE SOURCE INDEX

| AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY | AUTHOR
AFFILIATION | ACCESSION
NUMBER | SUBJECT
CATEGORY |
|-----------------------|---------------------|---------------------|-----------------------|---------------------|---------------------|
| | 8302030563 | 50-443 S | | 8302160263 | 50-443 A |
| | 8302030600 | 71-9151 | | 8302160274 | 50-443 A |
| | 8302040036 | 50-443 F | | 8302160274 | 50-443 A |
| | 8302040036 | 50-443 F | | 8302160326 | 50-443 A |
| | 8302040066 | 50-443 A | | 8302160326 | 50-443 A |
| | 8302040066 | 50-443 A | | 8302160341* | 50-443 G |
| | 8302040092 | 50-443 A | | 8302160341* | 50-443 G |
| | 8302040092 | 50-443 A | | 8302160368* | 50-443 G |
| | 8302040109 | 50-443 A | | 8302160368* | 50-443 G |
| | 8302040109 | 50-443 A | | 8302170366 | 50-443 G |
| | 8302040210 | 50-443 C | | 8302170366 | 50-443 G |
| | 8302040210 | 50-443 E | | 8302170369 | 50-443 A |
| | 8302040338 | 50-443 A | | 8302170369 | 50-443 A |
| | 8302040338 | 50-443 A | | 8302180142* | 50-443 G |
| | 8302040372 | 50-443 A | | 8302180142* | 50-443 G |
| | 8302040372 | 50-443 A | | 8302180357* | 50-443 G |
| | 8302040425 | 50-443 A | | 8302180357* | 50-443 G |
| | 8302040425 | 50-443 A | | 8302180361* | 50-443 G |
| | 8302040605* | 50-29 F | | 8302180361* | 50-443 G |
| | 8302040609* | 50-29 F | | 8302180428* | 50-443 G |
| | 8302080186 | 50-443 A | | 8302180428* | 50-443 G |
| | 8302080186 | 50-443 A | | 8302180475* | 50-443 G |
| | 8302080215 | 50-443 A | | 8302180475* | 50-443 G |
| | 8302080215 | 50-443 A | | 8302180493* | 50-443 G |
| | 8302090313* | 50-29 F | | 8302180493* | 50-443 G |
| | 8302100043* | 50-271 F | | 8302220166 | 50-443 A |
| | 8302100046* | 50-271 F | | 8302220166 | 50-443 A |
| | 8302100406 | PRH | | 8302220327 | 50-443 A |
| | 8302140085 | PRM | | 8302220327 | 50-443 A |
| | 8302150045 | 50-29 P | | 8302220331 | 50-443 A |
| | 8302150407 | 50-443 A | | 8302220331 | 50-443 A |
| | 8302150407 | 50-443 A | | 8302220388 | 50-443 A |
| | 8302150451 | 50-443 A | | 8302220388 | 50-443 A |
| | 8302150451 | 50-443 A | | 8302220124 | 50-29 B |
| | 8302150686 | 50-29 G | | 8302220129* | 50-29 B |
| | 8302160166 | 50-443 A | | 8302230449 | 50-443 B |
| | 8302160166 | 50-443 A | | 8302230449 | 50-443 B |
| | 8302160216* | 50-443 G | | 8302230033 | 50-443 G |
| | 8302160216* | 50-443 G | | 8302230033 | 50-443 G |
| | 8302160263 | 50-443 A | | 8302230172 | 50-443 A |
| | | | | 8302230172 | 50-443 A |
| | | | | 8302230252 | 50-29 P |
| | | | | 8302230441 | 50-443 A |
| | | | | 8302230505* | 50-29 G |

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | OTHER REPORT NUMBER | REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | OTHER REPORT NUMBER |
|---------------|------------------|------------------|---------------------|----------------------|------------------|------------------|---------------------|
| 11B3-4150 | 60100703174 | 50-335 P | | ECG-NTAP-6152 DRAFT | 6302070598* | 50-537 A | |
| 1-1142511-00 | 63022204234 | 50-269 Q | | EL40101Y | 6302180402* | 50-413 F | |
| 91-14 R00 | 63020704934 | 50-528 S | | EN-619 | 6302070525* | 50-498 A | |
| 4-267-32 | 6302170174* | 10PREP | | EPRI RP 1707-3 | 6302140122* | 50-244 Q | 1EB-79-01B |
| 1-42301 R00 | 63021703214 | 50-409 P | | EN-81-28 | 6302170168* | TOPREP | |
| 1-42304 R01 | 63021703254 | 50-409 P | | ES-LRD-83-3029 | 63022303514 | 50-537 A | |
| 1-42302 R00 | 63021703234 | 50-409 P | | FSD-CRSCD-105 R01 | 6302090429* | TOPREP | SA&I-ESI-07B |
| 3-42301 R00 | 63021703264 | 50-409 P | | FSD-CRSCD-94 R01 | 6302090427* | TOPREP | SA&I-ESI-079 |
| 3-2 | 63022504424 | 50-395 R | | GA-A16402 | 63021506224 | 50-267 P | UC-77 |
| 3502030332 | 6302030032 | RES | | GPC-04-104 R00 | 63020105504 | 50-321 Q | |
| 3502070124 | 6302070124 | RES | BNL-NUREG-32396 | 1AEA-SM-218/26 DRAFT | 6302080147* | F01A | |
| 5-302083119 | 6302080119 | RES | | ID/T52-B | 63022501834 | 50-254 P | |
| 3-302083124 | 6302080124 | RES | | NI-DO-22128 | 63020903234 | 50-387 P | DRF-L12-00525 |
| 6302080482 | 6302080482 | RES | BNL-NUREG-32412 | NI-DO-22135 | 63020900064 | 50-259 P | DRF L12-00515 |
| 3502150739 | 6302150739 | RES | E00-LOFT-6095 | NI-DO-30053 | 63021701704 | 50-260 P | 30NED013 |
| 6-302150741 | 6302150741 | RES | E00-WRR-6129 | NEED-55-0182 | 63020203114 | 50-219 P | 011-00220 |
| 3-302150744 | 6302150744 | 50-312 P | E00-PHYS-6161 | NEED-62-0692 | 63020104344 | 50-237 P | |
| 1-302150745 | 6302150745 | RES | E00-EA-6140 | NUREG-0020 V06 N09 | 6302170107 | NUREG | |
| 6-302150748 | 6302150748 | RES | E00-EE-6052 | NUREG-0040 V06 N04 | 6302100265 | NUREG | |
| 5502150758 | 6302150758 | RES | E00-LOFT-6159 | NUREG-0090 V05 N03 | 6302170024 | NUREG | |
| 5502160002 | 6302160002 | RES | LO-87-80-152 | NUREG-0420 S03 | 6302170477 | 50-322 E | |
| 5502160003 | 6302160003 | RES | E00-NTAP-6148 | NUREG-0485 V04 N12 | 6302170029 | NUREG | |
| 5502160005 | 6302160005 | RES | E00-SEMI-6134 | NUREG-0540 V04 N09 | 6302100279 | NUREG | |
| 5502160008 | 6302160008 | RES | E00-ID-6141 | NUREG-0540 V04 N10 | 6302170062 | NUREG | |
| 5502160025 | 6302160025 | RES | | NUREG-0580 V11 N12 | 6302150723 | NUREG | |
| 5502160097 | 6302160097 | RES | E00-ID-6142 | NUREG-0580 V12 N01 | 6302250140 | NUREG | |
| 5502160098 | 6302160098 | RES | E00-LOFT-6014 | NUREG-0737 S01 | 6302250043 | NUREG | |
| 5502160401 | 6302160401 | RES | E00-TFDP-6077 | NUREG-0748 V02 N11 | 6302030239 | NUREG | |
| 5502160402 | 6302160402 | RES | E00-NTAP-6146 | NUREG-0748 V02 N12 | 6302170022 | NUREG | |
| 5502170009 | 6302170009 | RES | LO-87-80-145 | NUREG-0750 V13 102 | 6302220014 | NUREG | |
| 5502220467 | 6302220467 | 50-269 P | E00-EA-6131 | NUREG-0773 DRAFT | 63020204834 | F01A | |
| 5502240011 | 6302240011 | RES | BNL-NUREG-32337 | NUREG-0798 S03 | 6302170216 | 50-341 E | |
| 5502240359 | 6302240359 | 27-47 | BNL-NUREG-31928 | NUREG-0822 | 6302280005 | 50-219 P | |
| 5502240360 | 6302240360 | RES | BNL-NUREG-32380 | NUREG-0851 | 6302250091 | NUREG | |
| 5502240361 | 6302240361 | RES | BNL-NUREG-32394 | NUREG-0871 V02 N01 | 6302280024 | NUREG | |
| 5502250039 | 6302250039 | RES | BNL-NUREG-32444 | NUREG-0876 S02 | 6302170481 | 50-454 E | |
| 5502250049 | 6302250049 | 50-320 P | BNL-NUREG-32379 | NUREG-0887 S02 | 6302100276 | 50-440 E | |
| 5502250059 | 63021601714 | 50-313 F | | NUREG-0900 | 6302170029 | NUREG | |
| 5502250059 | 63021506304 | 50-267 P | | NUREG-0936 V01 N04 | 6302280004 | NUREG | |
| 5502250059 | 63021603004 | 50-416 P | | NUREG-0940 V01 N04 | 6302220438 | NUREG | |
| 5502250059 | 6302090477 | TOPREP | | NUREG-0942 DRAFT | 6302040472 | NUREG | |
| 5502250059 | 63022305744 | TOPREP | | NUREG-0943 | 6302250115 | NUREG | |
| 5502250059 | 63021401174 | 50-275 R | | NUREG-0948 | 6302170221 | 50-498 Q | |
| 5502250059 | 630210204694 | 50-289 Q | | NUREG-0953 | 6302250113 | NUREG | |
| 5502250059 | 63020203164 | 50-312 P | | NUREG-0954 | 6302280007 | 50-413 E | |
| 5502250059 | 63020706214 | 50-382 A | | NUREG-0959 | 6302170483 | NUREG | |
| 5502250059 | 63020701944 | 50-382 A | | NUREG-0965 | 6302250115 | NUREG | |
| 5502250059 | 63020903944 | TOPREP | 4313-01354-01P | NUREG/BR-0025 V09 N1 | 6302100263 | NUREG | |
| 5502250059 | 63022402674 | 50-329 A | | NUREG/BR-0058 | 6302100271 | NUREG | |
| 5502250059 | 63022303414 | 50-382 F | | NUREG/BR-0059 | 6302280044 | NUREG | |
| 5502250059 | 63021700564 | 50-341 A | | NUREG/CP-0041 V01 | 6302170487 | NUREG | |
| 5502250059 | 63020904894 | TOPREP | | NUREG/CP-0041 V02 | 6302220441 | NUREG | |
| 5502250059 | 63021702104 | 50-322 A | | NUREG/CP-0041 V03 | 6302220442 | NUREG | |
| 5502250059 | 63021702274 | 50-322 A | | NUREG/CP-0041 V04 | 6302220443 | NUREG | |
| 5502250059 | 63021702354 | 50-322 A | | NUREG/CP-0041 V05 | 6302170491 | NUREG | |

REPORT NUMBER INDEX

| REPORT
NUMBER | ACCESSION
NUMBER | SUBJECT
CATEGORY | OTHER REPORT
NUMBER | REPORT
NUMBER | ACCESSION
NUMBER | SUBJECT
CATEGORY | OTHER REPORT
NUMBER |
|-----------------------|---------------------|---------------------|------------------------|----------------------|---------------------|---------------------|------------------------|
| NUREG/CR-0041 V05 | 8302170496 | NUREG | | RR-02 | 8302180124 | 50-358 | A |
| NUREG/CR-1120 V10 | 8302170469 | NUREG | | RR-53 | 8302100197 | 50-358 | A |
| NUREG/CR-2000 V01 N12 | 8302170033 | NUREG | ORNL/NSIC-200 | PCD-DWT-DP-035 | 8302020380 | WASTE MGT | |
| NUREG/CR-2015 V03 | 8302170213 | NUREG | UCRL-53021 | SAI-013-79-5851 J | 8302070190 | FOIA | |
| NUREG/CR-2238 V19 | 8302040508 | NUREG | SAND81-1529 | SAI-186-028 17 | 8302030268 | 50-312 | Q |
| NUREG/CR-2300 V21 | 8302100184 | NUREG | | SAI-186-029 26 | 8302010006 | 50-220 | P |
| NUREG/CR-2300 V02 | 8302100281 | NUREG | | SAI-186-029-46 | 8302030344 | 50-219 | P |
| NUREG/CR-2666 | 8302170198 | NUREG | UCLA-ENG-8284 | SAI-186-029-49 | 83020310344 | 50-333 | P |
| NUREG/CR-2675 V03 | 8302250053 | NUREG | PNL-4241 | SAI-83-115-144 | 8302020136 | 50-29 | P |
| NUREG/CR-2706 | 8302030252 | NUREG | ORNL/TM-8328 | SAI-87-128-144 | 8302030269 | 50-213 | P |
| NUREG/CR-2755 | 8302250129 | NUREG | BNL-NUREG-51544 | SN76-0534 | 8302070240 | FOIA | UC-78 |
| NUREG/CR-2801 | 8302170208 | NUREG | UCRL-53040 | SD-BWJ-11-073 | 8302020378 | WASTE MGT | |
| NUREG/CR-2804 | 8302250146 | NUREG | | SECY-75-558 | 8302020391 | FOIA | |
| NUREG/CR-2805 V01 | 8302250135 | NUREG | HEDL-TME 82-18 | SECY-75-558F | 8302020388 | FOIA | |
| NUREG/CR-2805 V02 | 8302220435 | NUREG | HEDL-TME 82-19 | SECY-77-545 | 8302020379 | FOIA | |
| NUREG/CR-2805 V03 | 8302280020 | NUREG | HEDL-TME 82-20 | SECY-79-1873 | 8302220058 | FOIA | |
| NUREG/CR-2806 | 8302170273 | NUREG | | SECY-79-187C | 8302220054 | FOIA | |
| NUREG/CR-2847 | 8302100286 | NUREG | LA-9459-MS | SECY-81-6038 | 8112100049 | FOIA | |
| NUREG/CR-2848 | 8302150718 | NUREG | LA-9460-MS | SECY-82-207D | 830200162 | FOIA | |
| NUREG/CR-2855 | 8302250094 | NUREG | PNL-4360 | SECY-82-326 | 8302010085 | FOIA | |
| NUREG/CR-2861 | 8302030208 | NUREG | S-744-R | SECY-83-016 | 8301240226 | SECY | |
| NUREG/CR-2879 | 8302280006 | NUREG | | SECY-83-052 | 8302170095 | SECY | |
| NUREG/CR-2907 V01 | 8302220426 | NUREG | BNL-NUREG-51581 | SECY-R-74-064 | 8302020385 | FOIA | |
| NUREG/CR-2966 | 8302040468 | NUREG | LA-9536-MS | SCF-9 2-3039R | 8302070602 | 50-395 | P |
| NUREG/CR-2983 | 8302290122 | NUREG | LBL-15029 | SMA 13701 05R003 V01 | 8302170309 | 50-329 | A |
| NUREG/CR-2988 | 8302040521 | NUREG | ORNL/SUB/81-705 | SMA 13701 05R003 V02 | 8302260176 | 50-329 | A |
| NUREG/CR-2997 V01 | 8302040502 | NUREG | ORNL/TM-8527/V1 | SMA 13701 05R003 V07 | 8302160189 | 50-329 | A |
| NUREG/CR-3008 | 8302170205 | NUREG | | TFR-C5257-183 | 8302080265 | 50-344 | P |
| NUREG/CR-3076 | 8302250151 | NUREG | | TFR-C5257-404 | 8302080535 | 50-206 | P |
| NUREG/CR-3079 | 8302230023 | NUREG | | TFR-C5257-408 | 8302170201 | 50-409 | P |
| NUREG/CR-3080 | 8302170251 | NUREG | | TFR-C5257-423 | 8302160339 | 50-206 | P TAC 41361 |
| NUREG/CR-3086 | 8302220431 | NUREG | BNL-NUREG-51629 | TFR-C5257-466 | 8302020228 | 50-220 | P TAC 41361 |
| NUREG/CR-3090 | 8302030259 | NUREG | | TFR-C5257-508 | 8301180125 | 50-305 | P TAC 42465 |
| NUREG/CR-3097 | 8302040479 | NUREG | | TFR-C5257-509 | 8301210006 | 50-348 | P TAC 42462 |
| NUREG/CR-3106 | 8302250046 | NUREG | PNL-4591 | TFR-C5257-510 | 8301040276 | 50-313 | P TAC 42514 |
| NUREG/CR-3108 | 8302280013 | NUREG | LA-9563-MS | | | | |
| ORNL/NSIC-204 | 8302020139 | 50-29 | P | TFR-C5257-518 | 8301200119 | 50-344 | P TAC 42534 |
| ORNL/TM-8340 | 8302080058 | 71-9855 | | TFR-C5506-138 | 8212010074 | 50-335 | P TAC 42534 |
| P 105-4-839-032 R00 | 8302240294 | 50-275 | P | TFR-C5506-144 | 8212200078 | 50-295 | P TAC 46869 |
| P 105-4-839-033 R00 | 8302240282 | 50-275 | P | TFR-C5506-116 | 8212200094 | 50-244 | P TAC 46869 |
| PNL-4475 | 8210130458 | FOIA | | TFR-C5506-143 | 8212200091 | 50-305 | P TAC 46869 |
| QVI-Q9 R00 | 8302090404 | 50-397 | Q | | | | |
| RAC-TR-82-E01 | 8302170435 | NUREG | | TR-5639-2 R03 | 8302080206 | 50-346 | P |
| RR-25 | 8302180140 | 50-358 | A | TR-ESE 442 | 8302070531 | 50-382 | A |
| RR-26 | 8302180132 | 50-358 | A | WAP-10170 APP | 8302090426 | TOPREP | |
| | | | | WAP-10267 | 8302220784 | TOPREP | |
| | | | | WAP-8785 ADD 03 | 8302090490 | TOPREP | 0299L 6 |
| 77 | 8302180155 | 50-358 | A | | | | |
| 3 | 8302180169 | 50-358 | A | WJUB-82-86 | 8302040466 | 70-1257 | 21382 |
| 7 | 8302180160 | 50-358 | A | WJNF-82-81 R01 | 8302010599 | 50-335 | P |
| 1 | 8302180189 | 50-358 | A | WJNF-82-98 | 8302010588 | 50-335 | P |
| 1 | 8302180147 | 50-358 | A | WJNF-82-99 | 8302010605 | 50-335 | P |
| | | | | WJEC-1742 | 8302290167 | 50-271 | P |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

| ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 7902020122 | 8302240223 | 83/01/20 | FOIA |
| 7904250165 | 8302240223 | 83/01/20 | FOIA |
| 7905290339 | 8302240223 | 83/01/20 | FOIA |
| 7908220573 | 8302240223 | 83/01/20 | FOIA |
| 7910230415 | 8302040039 | 82/12/30 | 50-440 U |
| 7911210270 | 8302240223 | 83/01/20 | FOIA |
| 8004250184 | 8302240223 | 83/01/20 | FOIA |
| 8010070317 | 8302020122 | 83/01/25 | 50-335 P |
| 8010090441 | 8302240223 | 83/01/20 | FOIA |
| 8103160808 | 8302170011 | 83/02/02 | 50-322 A |
| 8106010266 | 8302170011 | 83/02/02 | 50-322 A |
| 8107200033 | 8302100019 | 83/01/11 | FOIA |
| 8108170251 | 8302070076 | 82/12/21 | FOIA |
| 8108260457 | 8302100383 | 83/01/18 | PR |
| 81092204921 | 8302180031 | 83/01/11 | FOIA |
| 8110190094 | 8302170011 | 83/02/02 | 50-322 A |
| 8110230003 | 8302170011 | 83/02/02 | 50-322 A |
| 8111170512 | 8302170011 | 83/02/02 | 50-322 A |
| 8112040003 | 8302180031 | 83/01/11 | FOIA |
| 8112100049 | 8302010065 | 82/12/06 | FOIA |
| 8112170293 | 8302180031 | 83/01/11 | FOIA |
| 8112220693 | 8302090590 | 83/01/11 | 50-293 P |
| 8102160093 | 8302070076 | 82/12/21 | FOIA |
| 8102160169 | 8302180031 | 83/01/11 | FOIA |
| 8203030578 | 8302180031 | 83/01/11 | FOIA |
| 8203180249 | 8302170019 | 83/01/18 | 50-155 P |
| 8203220416 | 8302170019 | 83/01/18 | 50-155 P |
| 8203220475 | 8302170019 | 83/01/18 | 50-155 P |
| 8203220476 | 8302170019 | 83/01/18 | 50-155 P |
| 8203240107 | 8302170019 | 83/01/18 | 50-155 P |
| 8203240420 | 8302170019 | 83/01/18 | 50-155 P |
| 8203290123 | 8302170019 | 83/01/18 | 50-155 P |
| 8207140131 | 8302020427 | 82/11/30 | 50-289 P |
| 8208050174 | 8302030017 | 82/12/29 | 50-537 U |
| 8208060265 | 8302240129 | 83/02/03 | 50-344 P |
| 8208130353 | 8302180014 | 83/02/09 | 50-373 Q |
| 8208190201 | 8302100210 | 83/01/27 | 50-409 P |
| 8208310344 | 8302070289 | 83/01/25 | 50-333 P |
| 8209010085 | 8302040108 | 82/12/27 | FOIA |
| 8209020218 | 8302080063 | 82/12/30 | 50-220 P |
| 8209020228 | 8302080063 | 82/12/30 | 50-220 P |
| 8209030344 | 8212030242 | 82/11/30 | 50-219 P |
| 8209030368 | 8302090166 | 83/01/28 | 50-312 Q |
| 8209080535 | 8302070429 | 83/02/01 | 50-206 P |
| 8209150350 | 8302170011 | 83/02/02 | 50-322 A |
| 8209160339 | 8302180233 | 83/01/31 | 50-206 P |
| 8209200462 | 8302010065 | 82/12/06 | FOIA |
| 8209240433 | 8302140168 | 83/02/07 | 50-269 P |
| 8210120652 | 8210120650 | 82/09/23 | 50-269 F |
| 8210120656 | 8210120650 | 82/09/23 | 50-269 F |

| ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8210120659 | 8210120650 | 82/09/23 | 50-269 F |
| 8210130458 | 8302020359 | 82/12/06 | FOIA |
| 8210150459 | 8210150452 | 82/10/08 | 50-275 F |
| 8210290111 | 8302100512 | 83/02/03 | 50-445 A |
| 8211020469 | 8302160317 | 83/02/10 | 50-289 Q |
| 8211040395 | 8302180031 | 83/01/11 | FOIA |
| 8211040458 | 8302180031 | 83/01/11 | FOIA |
| 8211150056 | 8302010065 | 82/12/06 | FOIA |
| 8211150690 | 8302180031 | 83/01/11 | FOIA |
| 8211180459 | 8302180031 | 83/01/11 | FOIA |
| 8212010094 | 8302010013 | 83/01/17 | 50-335 P |
| 8212010524 | 8302070278 | 82/12/13 | 50-362 Q |
| 8212020098 | 8212020091 | 82/11/23 | 50-440 K |
| 8212070376 | 8302170011 | 83/02/02 | 50-322 A |
| 8212200054 | 8302160261 | 83/02/09 | 50-244 P |
| 8212200078 | 8302090135 | 83/01/26 | 50-295 P |
| 8212200091 | 8302080358 | 83/01/31 | 50-305 P |
| 8212280528 | 8302020359 | 82/12/06 | FOIA |
| 8212290219 | 8302030470 | 83/01/21 | 50-352 Q |
| 8210140296 | 8302040077 | 83/01/26 | 50-313 P |
| 8301070311 | 8302090037 | 83/01/28 | 50-289 P |
| 8301140418 | 8301140412 | 83/01/11 | 50-272 Q |
| 8301140424 | 8301140412 | 83/01/11 | 50-272 Q |
| 8301170414 | 8301170409 | 83/01/05 | 50-324 S |
| 8301180125 | 8302180054 | 83/02/02 | 50-305 P |
| 8301180179 | 8301180175 | 83/01/04 | 50-397 Q |
| 8301180184 | 8301180175 | 83/01/04 | 50-397 Q |
| 8301190384 | 8301190378 | 83/01/07 | 50-213 F |
| 8301200219 | 8302100175 | 83/02/04 | 50-364 P |
| 8301210006 | 8302140192 | 83/02/04 | 50-348 P |
| 8301250438 | 8301250435 | 82/12/30 | 50-322 K |
| 8301260211 | 8302030470 | 83/01/21 | 50-352 Q |
| 8301270044 | 8210150452 | 82/10/08 | 50-275 F |
| 8301270051 | 8210150452 | 82/10/08 | 50-275 F |
| 8301270060 | 8210150452 | 82/10/08 | 50-275 F |
| 8302010002 | 8302010001 | 83/01/11 | CONTRACT |
| 8302010009 | 8302010005 | 82/12/30 | CONTRACT |
| 8302010018 | 8302010013 | 83/01/17 | 50-335 P |
| 8302010021 | 8302010016 | 83/01/26 | 50-348 F |
| 8302010023 | 8301140412 | 83/01/11 | 50-272 Q |
| 8302010028 | 8302010023 | 83/01/25 | CONTRACT |
| 8302010029 | 8302010026 | 83/01/26 | 50-348 F |
| 8302010039 | 8302010033 | 83/01/21 | CONTRACT |
| 8302010044 | 8302010040 | 83/01/21 | 50-373 H |
| 8302010057 | 8302010054 | 82/12/06 | FOIA |
| 8302010061 | 8302010054 | 82/12/06 | FOIA |
| 8302010071 | 8302010065 | 82/12/06 | FOIA |
| 8302010074 | 8302010070 | 83/01/28 | 50-413 Q |
| 8302010082 | 8302010065 | 82/12/06 | FOIA |
| 8302010083 | 8302010080 | 83/01/20 | 50-324 S |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302010084 | 8302010081 | 83/01/26 | 50-213 F | 8302010087 | 8302010112 | 83/12/21 | 50-287 T |
| 8302010091 | 8302010081 | 83/01/26 | 50-213 F | 8302010102 | 8302010112 | 82/12/21 | 50-289 T |
| 8302010092 | 8302010087 | 83/01/17 | 50-224 S | 8302010105 | 8302010112 | 82/12/21 | 50-289 T |
| 8302010097 | 8302010081 | 83/01/26 | 50-213 F | 8302010110 | 8302010303 | 83/01/19 | 50-311 S |
| 8302010101 | 8302010090 | 83/01/20 | 50-318 P | 8302010111 | 8302010328 | 83/01/21 | 50-309 S |
| 8302010103 | 8302010095 | 83/01/20 | 50-348 S | 8302010118 | 8302010312 | 83/01/19 | 50-271 S |
| 8302010115 | 8302010109 | 83/01/03 | CONTRACT | 8302010120 | 8302010311 | 83/01/24 | 50-335 S |
| 8302010117 | 8302010108 | 83/01/26 | 50-317 F | 8302010122 | 8302010317 | 83/01/24 | 50-322 Q |
| 8302010119 | 8302010112 | 82/12/21 | 50-289 T | 8302010125 | 8302010316 | 83/01/17 | 50-277 Q |
| 8302010120 | 8302010111 | 83/01/19 | 50-375 S | 8302010125 | 8302010324 | 83/01/24 | 70-371 |
| 8302010123 | 8302010112 | 82/12/21 | 50-289 T | 8302010137 | 8302010330 | 83/01/21 | 50-317 S |
| 8302010126 | 8302010108 | 83/01/26 | 50-317 F | 8302010140 | 8302010333 | 83/01/21 | 50-315 S |
| 8302010127 | 8302010122 | 83/01/20 | 50-373 S | 8302010144 | 8302010339 | 83/01/19 | 50-272 S |
| 8302010129 | 8302010112 | 82/12/21 | 50-289 T | 8302010145 | 8302010341 | 83/01/19 | 50-318 S |
| 8302010130 | 8302010118 | 83/01/21 | 50-250 S | 8302010145 | 8302010327 | 83/01/13 | 50-361 S |
| 8302010153 | 8302010124 | 82/12/21 | 50-537 A | 8302010150 | 8302010343 | 83/01/24 | 50-305 S |
| 8302010154 | 8302010114 | 83/01/17 | 50-247 S | 8302010152 | 8302010349 | 83/01/19 | 50-318 S |
| 8302010155 | 8302010112 | 82/12/21 | 50-289 T | 8302010153 | 8302010347 | 83/01/24 | 50-320 Q |
| 8302010140 | 8302010132 | 83/01/07 | 50-265 S | 8302010154 | 8302010348 | 83/01/21 | 50-317 S |
| 8302010142 | 8302010112 | 82/12/21 | 50-289 T | 8302010155 | 8302010365 | 83/01/19 | 50-373 Q |
| 8302010148 | 8302010112 | 82/12/21 | 50-289 T | 8302010167 | 8302010363 | 83/01/21 | 50-325 S |
| 8302010150 | 8302010138 | 83/01/12 | 50-361 S | 8302010170 | 8302010366 | 83/01/25 | 50-220 Q |
| 8302010152 | 8302010147 | 83/01/18 | 50-237 S | 8302010172 | 8302010369 | 83/01/18 | 50-193 Q |
| 8302010153 | 8302010112 | 82/12/21 | 50-289 T | 8302010175 | 8302010371 | 83/01/21 | 50-324 S |
| 8302010154 | 8302010145 | 83/01/11 | 50-219 S | 8302010177 | 8302010362 | 83/01/19 | 50-373 Q |
| 8302010155 | 8302010112 | 82/12/21 | 50-289 T | 8302010178 | 8302010374 | 83/01/21 | 50-395 S |
| 8302010159 | 8302010151 | 83/01/19 | 50-387 S | 8302010181 | 8302010376 | 83/01/19 | 50-237 S |
| 8302010161 | 8302010112 | 82/12/21 | 50-289 T | 8302010182 | 8302010377 | 83/01/18 | 50-255 Q |
| 8302010162 | 8302010139 | 83/01/19 | 50-395 S | 8302010184 | 8302010380 | 83/01/17 | 50-317 Q |
| 8302010165 | 8302010155 | 83/01/25 | 50-395 S | 8302010185 | 8302010373 | 83/01/20 | 50-373 S |
| 8302010166 | 8302010112 | 82/12/21 | 50-289 T | 8302010189 | 8302010383 | 83/01/21 | 50-317 S |
| 8302010167 | 8302010141 | 83/01/10 | 50-296 S | 8302010190 | 8302010387 | 82/12/29 | 50-520 Q |
| 8302010168 | 8302010160 | 83/01/17 | 50-387 S | 8302010192 | 8302010388 | 83/01/25 | 50-317 Q |
| 8302010169 | 8302010159 | 83/01/17 | 50-361 S | 8302010194 | 8302010396 | 83/01/24 | 50-320 P |
| 8302010170 | 8302010112 | 82/12/21 | 50-289 T | 8302010195 | 8302010393 | 83/01/20 | 50-321 S |
| 8302010175 | 8302010163 | 83/01/19 | 50-318 S | 8302010197 | 8302010397 | 83/01/25 | 50-352 Q |
| 8302010177 | 8302010112 | 82/12/21 | 50-289 T | 8302010198 | 8302010396 | 83/01/24 | 50-320 P |
| 8302010181 | 8302010171 | 83/01/25 | 50-416 S | 8302010199 | 8302010398 | 83/01/20 | 50-344 S |
| 8302010182 | 8302010172 | 83/01/24 | 50-416 S | 8302010200 | 8302010394 | 83/01/08 | 50-361 S |
| 8302010183 | 8302010112 | 82/12/21 | 50-289 T | 8302010201 | 8302010404 | 83/01/31 | 50-341 K |
| 8302010185 | 8302010173 | 83/01/25 | 50-295 S | 8302010202 | 8302010394 | 83/01/08 | 50-361 S |
| 8302010187 | 8302010174 | 83/01/19 | 50-339 S | 8302010203 | 8302010401 | 83/01/31 | 50-341 K |
| 8302010189 | 8302010180 | 83/01/19 | 50-318 S | 8302010204 | 8302010402 | 83/01/21 | 50-280 S |
| 8302010199 | 8302010192 | 83/01/21 | 50-271 S | 8302010205 | 8302010402 | 83/01/21 | 50-280 S |
| 8302010200 | 8302010194 | 83/01/24 | 50-416 S | 8302010207 | 8302010423 | 83/01/25 | 50-416 S |
| 8302010202 | 8302010112 | 82/12/21 | 50-289 T | 8302010208 | 8302010430 | 83/01/18 | 50-366 S |
| 8302010204 | 8302010195 | 83/01/24 | 50-272 S | 8302010209 | 8302010432 | 83/01/19 | 50-275 P |
| 8302010205 | 8302010198 | 83/01/17 | 50-317 S | 8302010210 | 8302010431 | 83/01/19 | 50-275 P |
| 8302010210 | 8302010112 | 82/12/21 | 50-289 T | 8302010211 | 8302010429 | 83/01/25 | 50-237 P |
| 8302010214 | 8302010207 | 83/01/19 | 50-339 S | 8302010212 | 8302010437 | 82/10/20 | 50-537 A |
| 8302010216 | 8302010112 | 82/12/21 | 50-289 T | 8302010213 | 8302010445 | 83/01/28 | 50-400 R |
| 8302010221 | 8302010112 | 82/12/21 | 50-289 T | 8302010214 | 8302010436 | 83/01/25 | 70-2467 |
| 8302010222 | 8302010112 | 82/12/21 | 50-289 T | 8302010215 | 8302010446 | 82/10/01 | 50-247 S |
| 8302010227 | 8302010217 | 83/01/26 | 50-259 S | 8302010216 | 8302010454 | 83/01/20 | 50-324 S |
| 8302010229 | 8302010220 | 83/01/19 | 50-302 S | 8302010217 | 8302010455 | 83/01/26 | 0A999 |
| 8302010232 | 8302010112 | 82/12/21 | 50-289 T | 8302010218 | 8302010456 | 83/01/26 | 50-409 Q |
| 8302010238 | 8302010112 | 82/12/21 | 50-289 T | 8302010219 | 8302010459 | 83/01/27 | 50-375 Q |
| 8302010240 | 8302010234 | 83/01/20 | 50-325 S | 8302010220 | 8302010463 | 83/01/19 | 50-335 S |
| 8302010241 | 8302010112 | 82/12/21 | 50-289 T | 8302010221 | 8302010468 | 83/01/26 | 50-324 P |
| 8302010245 | 8302010237 | 83/01/19 | 50-339 S | 8302010222 | 8302010458 | 83/01/27 | 50-375 Q |
| 8302010256 | 8302010112 | 82/12/21 | 50-289 T | 8302010223 | 8302010479 | 83/01/19 | 50-456 Q |
| 8302010258 | 8302010251 | 82/12/02 | 50-313 Q | 8302010224 | 8302010482 | 83/01/28 | 40-215 |
| 8302010261 | 8302010252 | 83/01/27 | 50-416 S | 8302010225 | 8302010477 | 83/01/26 | 50-335 S |
| 8302010262 | 8302010112 | 82/12/21 | 50-289 T | 8302010226 | 8302010481 | 83/01/27 | 50-313 Q |
| 8302010263 | 8302010259 | 83/01/24 | 50-155 S | 8302010227 | 8302010478 | 83/01/27 | 50-368 Q |
| 8302010268 | 8302010112 | 82/12/21 | 50-289 T | 8302010228 | 8302010479 | 83/01/19 | 50-456 Q |
| 8302010273 | 8302010112 | 82/12/21 | 50-289 T | 8302010229 | 8302010481 | 83/01/27 | 50-313 Q |
| 8302010276 | 8302010269 | 83/01/19 | 50-237 S | 8302010230 | 8302010481 | 83/01/27 | 50-313 Q |
| 8302010277 | 8302010267 | 83/01/17 | 50-324 S | 8302010231 | 8302010496 | 83/01/28 | 0A999 |
| 8302010278 | 8302010112 | 82/12/21 | 50-289 T | 8302010232 | 8302010507 | 83/01/10 | 0A999 |
| 8302010282 | 8302010112 | 82/12/21 | 50-289 T | 8302010233 | 8302010509 | 83/01/28 | 50-247 T |
| 8302010283 | 8302010270 | 83/01/21 | 50-296 S | 8302010234 | 8302010531 | 83/01/24 | 50-267 P |
| 8302010284 | 8302010112 | 82/12/21 | 50-289 T | 8302010235 | 8302010512 | 83/01/27 | 50-321 Q |
| 8302010285 | 8302010280 | 83/01/11 | 50-361 S | 8302010236 | 8302010535 | 83/01/24 | 50-358 C |
| 8302010287 | 8302010281 | 83/01/21 | 50-324 S | 8302010237 | 8302010534 | 83/01/16 | 50-255 Q |
| 8302010289 | 8302010112 | 82/12/21 | 50-289 T | 8302010238 | 8302010545 | 83/01/31 | 50-350 K |
| 8302010291 | 8302010112 | 82/12/21 | 50-289 T | 8302010239 | 8302010512 | 83/01/27 | 50-321 Q |
| 8302010292 | 8302010286 | 83/01/28 | 50-373 P | 8302010240 | 8302010543 | 83/01/26 | 50-382 Q |
| 8302010295 | 8302010112 | 82/12/21 | 50-289 T | 8302010241 | 8302010543 | 83/01/26 | 50-382 Q |
| 8302010297 | 8302010290 | 83/01/21 | 50-271 S | | | | |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

523

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302010553 | 8302010540 | 83/01/19 | 50-254 S | 8302020339 | 8302020338 | 82/12/27 | FOIA |
| 8302010554 | 8302010534 | 83/01/14 | 50-255 Q | 8302020340 | 8302020337 | 83/01/18 | XPOR TLIC |
| 8302010559 | 8302010552 | 83/01/26 | 70-687 | 8302020342 | 8302020336 | 83/01/28 | 50-321 F |
| 8302010560 | 8302010555 | 83/01/19 | 50-318 S | 8302020346 | 8302020336 | 83/01/28 | 50-321 F |
| 8302010562 | 8302010556 | 83/01/21 | 50-289 P | 8302020348 | 8302020343 | 82/12/13 | 50-338 P |
| 8302010564 | 8302010557 | 83/01/31 | 50-329 T | 8302020352 | 8302020347 | 83/01/13 | 50-305 P |
| 8302010569 | 8302010561 | 83/01/21 | 50-344 S | 8302020355 | 8302020344 | 83/01/20 | XPOR TLIC |
| 8302010571 | 8302010566 | 83/01/19 | 50-318 S | 8302020358 | 8302020344 | 83/01/20 | XPOR TLIC |
| 8302010573 | 8302010563 | 83/01/26 | 50-324 S | 8302020364 | 8302020362 | 83/01/20 | XPOR TLIC |
| 8302010578 | 8302010574 | 83/01/20 | 50-302 S | 8302020368 | 8302020366 | 83/01/23 | XPOR TLIC |
| 8302010581 | 8302010567 | 83/01/19 | 50-282 Q | 8302020373 | 8302020372 | 83/01/24 | XPOR TLIC |
| 8302010582 | 8302010576 | 83/01/20 | 50-335 P | 8302020376 | 8302020375 | 82/12/23 | WASTE MGT |
| 8302010588 | 8302010576 | 83/01/20 | 50-335 P | 8302020377 | 8302020375 | 82/12/23 | WASTE MGT |
| 8302010591 | 8302010584 | 83/01/21 | 50-395 S | 8302020378 | 8302020375 | 83/01/23 | WASTE MGT |
| 8302010594 | 8302010589 | 83/01/28 | 50-443 Q | 8302020380 | 8302020375 | 82/12/23 | WASTE MGT |
| 8302010597 | 8302010576 | 83/01/20 | 50-335 P | 8302020384 | 8302020381 | 83/01/21 | 40-8675 |
| 8302010605 | 8302010576 | 83/01/20 | 50-335 P | 8302020385 | 8302020382 | 82/12/03 | FOIA |
| 8302010607 | 8302010592 | 83/01/21 | 50-128 P | 8302020388 | 8302020382 | 82/12/03 | FOIA |
| 8302010608 | 8302010600 | 83/01/17 | 27-39 | 8302020389 | 8302020386 | 83/01/18 | 40-8728 |
| 8302010616 | 8302010612 | 83/01/18 | 50-461 Q | 8302020391 | 8302020382 | 82/12/03 | FOIA |
| 8302010619 | 8302010601 | 83/01/17 | 50-325 S | 8302020410 | 8302020405 | 83/01/27 | 50-397 F |
| 8302010621 | 8302010615 | 83/01/21 | 50-285 P | 8302020417 | 8302020409 | 83/01/26 | CONTRACT |
| 8302010622 | 8302010612 | 83/01/18 | 50-461 Q | 8302020418 | 8302020405 | 83/01/27 | 50-397 F |
| 8302010623 | 8302010617 | 83/01/18 | 50-329 Q | 8302020428 | 8302020422 | 83/01/27 | 50-264 F |
| 8302010624 | 8302010620 | 83/01/24 | 50-295 Q | 8302020429 | 8302020423 | 83/01/20 | CONTRACT |
| 8302010633 | 8302010624 | 83/01/26 | 70-398 | 8302020430 | 8302020427 | 82/11/30 | 50-289 P |
| 8302010634 | 8302010626 | 83/01/17 | 50-324 S | 8302020432 | 8302020422 | 83/01/27 | 50-264 F |
| 8302010637 | 8302010628 | 83/01/17 | 40-672 | 8302020437 | 8302020433 | 83/01/31 | 50-341 F |
| 8302010640 | 8302010636 | 83/01/28 | 50-155 P | 8302020439 | 8302020427 | 82/11/30 | 50-289 P |
| 8302010642 | 8302010636 | 83/01/28 | 50-155 P | 8302020440 | 8302020433 | 83/01/31 | 50-341 F |
| 8302010645 | 8302010628 | 83/01/17 | 40-672 | 8302020444 | 8302020427 | 82/11/30 | 50-289 P |
| 8302010649 | 8302010628 | 83/01/17 | 40-672 | 8302020451 | 8302020445 | 83/01/31 | 50-329 F |
| 8302010650 | 8302010628 | 83/01/17 | 40-672 | 8302020470 | 8302020458 | 83/01/31 | 50-10 F |
| 8302010661 | 8302010654 | 83/01/28 | 50-155 P | 8302020479 | 8302020458 | 83/01/31 | 50-10 F |
| 8302010662 | 8302010651 | 83/01/27 | 50-213 Q | 8302020483 | 8302020477 | 82/12/02 | FOIA |
| 8302010667 | 8302010651 | 83/01/27 | 50-213 Q | 8302030018 | 8302030012 | 83/01/26 | 50-263 F |
| 8302010670 | 8302010666 | 83/01/28 | 50-334 R | 8302030022 | 8302030019 | 83/01/21 | CONTRACT |
| 8302010671 | 8302010654 | 83/01/28 | 50-155 P | 8302030023 | 8302030012 | 83/01/26 | 50-263 F |
| 8302010672 | 8302010651 | 83/01/27 | 50-213 Q | 8302030024 | 8302030017 | 82/12/29 | 50-537 U |
| 8302010674 | 8302010668 | 83/01/11 | 50-361 S | 8302030029 | 8302030017 | 82/12/29 | 50-537 U |
| 8302010677 | 8302010651 | 83/01/27 | 50-213 Q | 8302030030 | 8302030025 | 83/01/26 | 50-263 F |
| 8302010679 | 8302010651 | 83/01/27 | 50-213 Q | 8302030034 | 8302030017 | 82/12/29 | 50-537 U |
| 8302010681 | 8302010678 | 83/01/14 | 50-362 S | 8302030036 | 8302030025 | 83/01/26 | 50-263 F |
| 8302010682 | 8302010651 | 83/01/27 | 50-213 Q | 8302030037 | 8302030017 | 82/12/29 | 50-537 U |
| 8302010718 | 8302010715 | 83/01/12 | 50-3 P | 8302030038 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020031 | 8302020022 | 83/01/25 | 50-410 F | 8302030041 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020034 | 8302020022 | 83/01/25 | 50-410 A | 8302030043 | 8302030033 | 83/01/31 | 50-213 F |
| 8302020036 | 8302020022 | 83/01/25 | 50-410 C | 8302030045 | 8302030039 | 83/01/27 | 70-2949 |
| 8302020038 | 8302020022 | 83/01/25 | 50-410 K | 8302030049 | 8302030044 | 83/01/27 | 50-312 F |
| 8302020048 | 8302020043 | 83/01/26 | 50-267 F | 8302030050 | 8302030039 | 83/01/27 | 70-2949 |
| 8302020051 | 8302020013 | 83/01/26 | 50-267 F | 8302030052 | 8302030033 | 83/01/31 | 50-213 F |
| 8302020056 | 8302020050 | 83/01/26 | CONTRACT | 8302030054 | 8302030044 | 83/01/27 | 50-312 F |
| 8302020064 | 8302020022 | 83/01/25 | 50-410 A | 8302030062 | 8302030057 | 83/01/28 | 50-259 F |
| 8302020090 | 8302020084 | 83/01/19 | CONTRACT | 8302030063 | 8302030059 | 83/01/27 | 50-348 F |
| 8302020093 | 8302020087 | 83/01/28 | CONTRACT | 8302030065 | 8302030057 | 83/01/28 | 50-259 F |
| 8302020100 | 8302020097 | 83/01/13 | CONTRACT | 8302030068 | 8302030059 | 83/01/27 | 50-348 F |
| 8302020102 | 8302020096 | 83/01/11 | 50-320 F | 8302030072 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020123 | 8302020118 | 83/01/11 | CONTRACT | 8302030079 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020126 | 8302020122 | 83/01/25 | 50-335 P | 8302030086 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020136 | 8302020130 | 83/01/27 | 50-29 P | 8302030087 | 8302030083 | 83/01/24 | XPOR TLIC |
| 8302020139 | 8302020130 | 83/01/27 | 50-29 P | 8302030099 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020155 | 8302020149 | 83/01/25 | CONTRACT | 8302030101 | 8302030093 | 83/01/28 | 50-245 S |
| 8302020156 | 8302020150 | 83/01/24 | 50-302 P | 8302030104 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020158 | 8302020150 | 83/01/24 | 50-302 P | 8302030106 | 8302030100 | 83/01/27 | 50-416 S |
| 8302020162 | 8302020150 | 83/01/24 | 50-302 P | 8302030109 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020169 | 8302020164 | 83/01/26 | XPOR TLIC | 8302030113 | 8302030110 | 83/01/27 | 50-416 S |
| 8302020198 | 8302020193 | 83/01/24 | COMMISSION | 8302030114 | 8302030112 | 83/01/31 | 50-461 K |
| 8302020214 | 8302020205 | 83/01/24 | 50-317 Q | 8302030116 | 8302030108 | 83/01/28 | 50-344 P |
| 8302020219 | 8302020205 | 83/01/24 | 50-317 Q | 8302030121 | 8302030108 | 83/01/28 | 50-344 P |
| 8302020226 | 8302020223 | 83/01/25 | 50-266 P | 8302030123 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020236 | 8302020232 | 83/01/25 | CONTRACT | 8302030125 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020239 | 8302020231 | 83/01/25 | 50-282 P | 8302030133 | 8302030017 | 82/12/29 | 50-537 U |
| 8302020245 | 8302020242 | 83/01/25 | CONTRACT | 8302030136 | 8302030017 | 83/01/26 | 50-295 F |
| 8302020273 | 8302020270 | 83/01/25 | CONTRACT | 8302030139 | 8302030137 | 83/01/26 | 50-295 F |
| 8302020310 | 8302020304 | 82/12/14 | 50-312 P | 8302030143 | 8302030137 | 83/01/26 | 50-295 F |
| 8302020311 | 8302020306 | 83/01/24 | 50-219 P | 8302030175 | 8302030164 | 83/02/01 | 50-247 Q |
| 8302020316 | 8302020304 | 82/12/14 | 50-312 P | 8302030194 | 8302030191 | 83/01/20 | 50-322 Q |
| 8302020320 | 8302020313 | 83/01/18 | XPOR TLIC | 8302030197 | 8302030191 | 83/01/20 | 50-322 Q |
| 8302020334 | 8302020321 | 83/01/26 | 50-400 Q | 8302030202 | 8302030198 | 83/01/31 | 50-245 Q |
| 8302020335 | 8302020326 | 83/02/01 | 50-361 Q | 8302030204 | 8302030186 | 83/02/02 | 50-423 A |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | |
|------------------|--------------------|-------------|------------------|--|------------------|--------------------|-------------|------------------|--|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8302030205 | 8302030200 | 83/01/25 | 50-333 S | | 8302030531 | 8302030528 | 83/01/21 | 70-371 | |
| 8302030211 | 8302030206 | 82/12/21 | CONTRACT | | 8302030537 | 8302030528 | 83/01/21 | 70-371 | |
| 8302030212 | 8302030207 | 83/01/28 | 50-346 F | | 8302030544 | 8302030538 | 83/01/31 | 0A999 | |
| 8302030214 | 8302030207 | 83/01/28 | 50-346 F | | 8302030546 | 8302030539 | 83/02/02 | 50-247 T | |
| 8302030215 | 8302030209 | 83/01/21 | 50-220 G | | 8302030548 | 8302030539 | 83/01/11 | 0A999 | |
| 8302030230 | 8302030186 | 83/02/02 | 50-423 A | | 8302030549 | 8302030541 | 83/01/21 | 50-289 S | |
| 8302030237 | 8302030186 | 83/02/02 | 50-423 A | | 8302030556 | 8302030538 | 83/01/31 | 0A999 | |
| 8302030238 | 8302030226 | 83/01/27 | 50-295 F | | 8302030560 | 8302030555 | 83/01/21 | 50-387 S | |
| 8302030243 | 8302030186 | 83/02/02 | 50-423 A | | 8302030564 | 8302030557 | 83/01/28 | 50-387 G | |
| 8302030245 | 8302030226 | 83/01/27 | 50-295 F | | 8302030569 | 8302030562 | 83/01/28 | 50-416 S | |
| 8302030247 | 8302030241 | 83/01/17 | 50-322 T | | 8302030576 | 8302030568 | 83/01/20 | 50-244 G | |
| 8302030248 | 8302030186 | 83/02/02 | 50-423 C | | 8302030577 | 8302030567 | 83/01/28 | 50-259 S | |
| 8302030250 | 8302030233 | 83/01/26 | 50-245 F | | 8302030579 | 8302030573 | 83/01/18 | 50-382 G | |
| 8302030254 | 8302030186 | 83/02/02 | 50-423 F | | 8302030581 | 8302030574 | 83/01/21 | 50-29 G | |
| 8302030258 | 8302030186 | 83/02/02 | 50-423 F | | 8302030588 | 8302030582 | 83/01/20 | 50-245 S | |
| 8302030262 | 8302030233 | 83/01/26 | 50-245 F | | 8302030590 | 8302030573 | 83/01/18 | 50-382 G | |
| 8302030276 | 8302030267 | 83/01/26 | 50-387 F | | 8302030571 | 8302030584 | 83/01/21 | 50-286 G | |
| 8302030283 | 8302030273 | 83/01/27 | 50-328 S | | 8302030605 | 8302030603 | 83/01/28 | 50-275 F | |
| 8302030294 | 8302030288 | 83/01/25 | 50-321 S | | 8302030611 | 8302030603 | 83/01/28 | 50-275 F | |
| 8302030297 | 8302030278 | 83/01/25 | 50-387 S | | 8302030617 | 8302030614 | 83/01/27 | 50-280 F | |
| 8302030307 | 8302030300 | 83/01/31 | 50-416 S | | 8302030619 | 8302030614 | 83/01/27 | 50-280 F | |
| 8302030324 | 8302030308 | 83/01/28 | 50-336 S | | 8302030624 | 8302030622 | 83/01/27 | 50-295 F | |
| 8302030331 | 8302030326 | 83/01/18 | 50-445 G | | 8302030626 | 8302030622 | 83/01/27 | 50-295 F | |
| 8302030337 | 8302030327 | 83/01/31 | 50-298 G | | 8302030628 | 8302030627 | 83/01/31 | 50-259 F | |
| 8302030340 | 8302030332 | 83/01/28 | 50-336 S | | 8302030629 | 8302030627 | 83/01/31 | 50-259 F | |
| 8302030351 | 8302030346 | 83/01/18 | 50-397 F | | 8302030603 | 8302040001 | 83/01/26 | 50-220 P | |
| 8302030353 | 8302030350 | 83/01/28 | 50-302 S | | 8302030605 | 8302040004 | 83/01/19 | 40-2061 | |
| 8302030359 | 8302030356 | 83/01/28 | 50-416 S | | 8302030606 | 8302040001 | 83/01/26 | 50-220 P | |
| 8302030361 | 8302030357 | 83/01/25 | 50-387 S | | 8302030610 | 8302040010 | 83/01/05 | 71-491 | |
| 8302030365 | 8302030342 | 83/01/28 | 50-363 G | | 8302030620 | 8302040018 | 83/01/31 | 50-3 F | |
| 8302030367 | 8302030363 | 83/01/28 | 50-416 S | | 8302030625 | 8302040018 | 83/01/31 | 50-3 F | |
| 8302030376 | 8302030375 | 83/01/27 | 50-366 S | | 8302030631 | 8302040033 | 83/01/21 | 0A999 | |
| 8302030393 | 8302030387 | 83/01/28 | 50-416 S | | 8302030637 | 8302040033 | 83/01/27 | 50-10 F | |
| 8302030395 | 8302030388 | 83/01/28 | 50-346 P | | 8302030644 | 8302040041 | 83/01/31 | 50-327 P | |
| 8302030397 | 8302030387 | 83/01/21 | 50-334 G | | 8302030645 | 8302040040 | 83/01/20 | 50-440 G | |
| 8302030398 | 8302030392 | 83/01/27 | 50-395 G | | 8302030648 | 8302040033 | 83/01/27 | 50-10 F | |
| 8302030402 | 8302030396 | 83/01/24 | 50-333 S | | 8302030651 | 8302040047 | 83/01/20 | 50-483 G | |
| 8302030407 | 8302030397 | 83/01/31 | 50-329 A | | 8302030654 | 8302040050 | 83/01/24 | 50-254 S | |
| 8302030408 | 8302030400 | 83/01/10 | 50-277 S | | 8302030655 | 8302040047 | 83/01/20 | 50-463 G | |
| 8302030409 | 8302030405 | 83/01/27 | 50-313 P | | 8302030670 | 8302040058 | 83/01/25 | 50-237 S | |
| 8302030411 | 8302030406 | 83/01/26 | 50-313 R | | 8302030671 | 8302040037 | 82/12/30 | 50-440 G | |
| 8302030419 | 8302030416 | 83/01/28 | 50-302 K | | 8302030673 | 8302040037 | 83/01/20 | 50-409 G | |
| 8302030420 | 8302030414 | 83/01/20 | 50-324 S | | 8302030676 | 8302040037 | 82/12/30 | 50-440 G | |
| 8302030421 | 8302030413 | 83/01/24 | 50-333 S | | 8302030682 | 8302040039 | 82/12/30 | FOIA | |
| 8302030422 | 8302030410 | 83/01/28 | 50-324 S | | 8302030684 | 8302040077 | 83/01/26 | 50-313 P | |
| 8302030423 | 8302030415 | 83/01/31 | 0A999 | | 8302030686 | 8302040079 | 83/01/26 | 50-315 S | |
| 8302030428 | 8302030418 | 83/01/21 | 50-277 G | | 8302030687 | 8302040083 | 83/01/27 | 50-358 A | |
| 8302030429 | 8302030417 | 83/01/21 | 50-289 G | | 8302030688 | 8302040087 | 83/01/20 | 50-409 G | |
| 8302030431 | 8302030415 | 83/01/31 | 0A999 | | 8302030691 | 8302040039 | 82/12/30 | FOIA | |
| 8302030434 | 8302030425 | 83/01/26 | 50-269 S | | 8302030695 | 8302040039 | 82/12/30 | FOIA | |
| 8302030435 | 8302030415 | 83/01/31 | 0A999 | | 8302030698 | 8302040093 | 83/01/28 | 50-329 E | |
| 8302030437 | 8302030433 | 83/02/01 | 70-27 | | 8302030700 | 8302040096 | 83/01/26 | 50-315 S | |
| 8302030439 | 8302030426 | 83/01/28 | 50-327 S | | 8302030701 | 8302040037 | 82/12/30 | 50-440 G | |
| 8302030444 | 8302030415 | 83/01/31 | 0A999 | | 8302030702 | 8302040069 | 83/01/25 | 50-397 A | |
| 8302030445 | 8302030436 | 83/01/19 | 50-333 G | | 8302030703 | 8302040039 | 82/12/30 | 50-440 G | |
| 8302030452 | 8302030415 | 83/01/31 | 0A999 | | 8302030710 | 8302040069 | 83/01/25 | 50-397 A | |
| 8302030456 | 8302030426 | 83/01/19 | 50-333 G | | 8302030711 | 8302040039 | 82/12/30 | 50-329 G | |
| 8302030460 | 8302030449 | 83/01/27 | 50-366 S | | 8302030716 | 8302040121 | 83/01/17 | 50-255 P | |
| 8302030462 | 8302030454 | 83/01/20 | 50-352 G | | 8302030728 | 8302040069 | 83/01/25 | 50-397 A | |
| 8302030463 | 8302030458 | 83/01/28 | 50-139 R | | 8302030733 | 8302040129 | 82/12/27 | 50-537 A | |
| 8302030468 | 8302030464 | 83/01/21 | 50-267 G | | 8302030734 | 8302040127 | 83/01/25 | CONTRACT | |
| 8302030473 | 8302030466 | 83/01/25 | 50-269 S | | 8302030744 | 8302040135 | 83/01/26 | 50-255 S | |
| 8302030475 | 8302030464 | 83/01/21 | 50-267 G | | 8302030746 | 8302040139 | 83/01/12 | FOIA | |
| 8302030478 | 8302030471 | 83/01/31 | 0A999 | | 8302030757 | 8302040153 | 83/01/24 | 50-423 H | |
| 8302030484 | 8302030472 | 83/01/27 | 50-366 S | | 8302030758 | 8302040141 | 83/01/21 | 50-341 G | |
| 8302030485 | 8302030480 | 82/11/18 | 0A999 | | 8302030761 | 8302040139 | 83/01/12 | 50-329 G | |
| 8302030488 | 8302030483 | 82/09/08 | 0A999 | | 8302030762 | 8302040039 | 82/12/30 | FOIA | |
| 8302030489 | 8302030479 | 83/01/31 | 0A999 | | 8302030763 | 8302040159 | 83/01/17 | CONTRACT | |
| 8302030492 | 8302030480 | 82/11/18 | 0A999 | | 8302030768 | 8302040039 | 82/12/30 | 50-440 G | |
| 8302030494 | 8302030487 | 83/01/21 | 50-320 G | | 8302030769 | 8302040139 | 83/01/12 | FOIA | |
| 8302030501 | 8302030496 | 83/01/28 | 50-275 R | | 8302030773 | 8302040139 | 83/01/12 | FOIA | |
| 8302030502 | 8302030487 | 83/01/21 | 50-320 G | | 8302030778 | 8302040039 | 82/12/30 | 50-440 G | |
| 8302030504 | 8302030483 | 82/09/08 | 0A999 | | 8302030786 | 8302040039 | 82/12/30 | 50-440 G | |
| 8302030506 | 8302030499 | 83/01/20 | 50-334 G | | 8302030787 | 8302040176 | 83/01/28 | 50-373 S | |
| 8302030507 | 8302030480 | 82/11/18 | 0A999 | | 8302030789 | 8302040171 | 83/01/24 | 50-254 S | |
| 8302030510 | 8302030503 | 83/01/28 | 50-324 S | | 8302030791 | 8302040177 | 83/01/31 | 50-259 F | |
| 8302030511 | 8302030499 | 83/01/20 | 50-334 G | | 8302030797 | 8302040039 | 82/12/30 | 50-329 G | |
| 8302030523 | 8302030513 | 83/01/27 | 50-366 S | | 8302030798 | 8302040177 | 83/01/31 | 50-289 F | |
| 8302030525 | 8302030521 | 83/01/20 | 50-318 G | | 8302030802 | 8302040195 | 83/01/28 | 50-316 S | |
| 8302030527 | 8302030518 | 83/01/28 | 50-296 S | | 8302030812 | 8302040207 | 83/01/20 | 50-263 G | |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

525

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302040213 | 8302040208 | 83/01/26 | 50-312 P | 8302040531 | 8302040636 | 82/07/20 | 50-387 P |
| 8302040214 | 8302040205 | 83/01/31 | 50-254 F | 8302040605 | 8302040600 | 83/02/02 | 50-29 F |
| 8302040220 | 8302040205 | 83/01/31 | 50-254 F | 8302040609 | 8302040600 | 83/02/02 | 50-29 F |
| 8302040231 | 8302040226 | 83/01/26 | 50-213 P | 8302070027 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040235 | 8302040225 | 83/01/26 | 50-329 Q | 8302070036 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040240 | 8302040226 | 83/01/26 | 50-213 P | 8302070042 | 8302070025 | 82/11/23 | FOIA |
| 8302040251 | 8302040248 | 83/01/28 | 50-255 P | 8302070046 | 8302070038 | 82/10/15 | 70-143 |
| 8302040255 | 8302040248 | 83/01/28 | 50-255 P | 8302070049 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040257 | 8302040248 | 83/01/28 | 50-255 P | 8302070053 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040259 | 8302040238 | 83/01/28 | 50-155 S | 8302070062 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040263 | 8302040260 | 83/01/27 | 50-373 S | 8302070064 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040266 | 8302040261 | 83/01/26 | 50-373 S | 8302070066 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040276 | 8302040258 | 83/01/28 | 50-312 S | 8302070072 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040284 | 8302040260 | 83/02/01 | 50-373 Q | 8302070078 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040289 | 8302040281 | 83/01/20 | 50-195 Q | 8302070082 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040292 | 8302040279 | 83/01/21 | 50-358 Q | 8302070084 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040295 | 8302040290 | 83/02/01 | 50-456 Q | 8302070085 | 8302070076 | 82/12/21 | FOIA |
| 8302040297 | 8302040290 | 83/02/01 | 50-456 Q | 8302070089 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040302 | 8302040294 | 83/02/01 | 50-10 Q | 8302070090 | 8302070076 | 82/12/21 | FOIA |
| 8302040303 | 8302040287 | 83/01/18 | 50-305 Q | 8302070096 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040306 | 8302040298 | 83/01/19 | CONTRACT | 8302070098 | 8302070025 | 82/11/23 | FOIA |
| 8302040321 | 8302040304 | 83/01/24 | 50-265 S | 8302070102 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040330 | 8302040323 | 83/01/20 | 50-329 Q | 8302070103 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040331 | 8302040327 | 83/01/18 | 50-305 Q | 8302070107 | 8302070087 | 83/01/25 | 50-259 P |
| 8302040332 | 8302040039 | 82/12/30 | 50-155 Q | 8302070109 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040335 | 8302040333 | 83/01/28 | 50-373 S | 8302070110 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040336 | 8302040334 | 83/02/02 | 50-456 Q | 8302070112 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040337 | 8302040323 | 83/01/20 | 50-329 Q | 8302070117 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040339 | 8302040324 | 83/01/26 | 50-341 Q | 8302070123 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040344 | 8302040323 | 83/01/20 | 50-329 Q | 8302070128 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040343 | 8302040323 | 83/01/20 | 50-329 Q | 8302070129 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040345 | 8302040323 | 83/01/20 | 50-329 Q | 8302070134 | 8302070025 | 82/11/23 | 50-206 F |
| 8302040347 | 8302040340 | 83/01/27 | 50-305 S | 8302070136 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040348 | 8302040323 | 83/01/20 | 50-329 Q | 8302070142 | 8302070076 | 82/12/21 | 50-272 Q |
| 8302040352 | 8302040350 | 83/01/19 | 50-341 Q | 8302070148 | 8302070076 | 82/12/21 | 50-280 P |
| 8302040353 | 8302040349 | 83/01/28 | 50-304 S | 8302070151 | 8302070139 | 83/01/31 | CONTRACT |
| 8302040354 | 8302040350 | 83/01/19 | 50-341 Q | 8302070153 | 8302070146 | 82/12/02 | 50-289 P |
| 8302040355 | 8302040039 | 82/12/30 | 50-440 Q | 8302070156 | 8302070146 | 82/12/02 | FOIA |
| 8302040360 | 8302040359 | 83/01/21 | 50-263 Q | 8302070157 | 8302070076 | 82/12/21 | FOIA |
| 8302040364 | 8302040362 | 83/01/23 | 50-331 S | 8302070161 | 8302070076 | 82/12/21 | FOIA |
| 8302040366 | 8302040365 | 83/01/28 | 50-440 Q | 8302070166 | 8302070162 | 83/01/03 | 40-2061 |
| 8302040368 | 8302040365 | 83/01/28 | 50-440 Q | 8302070170 | 8302070164 | 83/01/31 | 50-288 F |
| 8302040371 | 8302040367 | 83/01/28 | 50-275 R | 8302070177 | 8302070164 | 83/01/31 | 50-288 F |
| 8302040373 | 8302040039 | 82/12/30 | 50-440 Q | 8302070178 | 8302070168 | 82/08/11 | 70-1201 |
| 8302040378 | 8302040039 | 82/12/30 | 50-440 Q | 8302070180 | 8302070172 | 83/01/18 | 50-131 Q |
| 8302040381 | 8302040039 | 82/12/30 | 50-440 Q | 8302070181 | 8302070076 | 82/12/21 | FOIA |
| 8302040386 | 8302040039 | 82/12/30 | 50-440 Q | 8302070186 | 8302070076 | 82/12/21 | FOIA |
| 8302040388 | 8302040039 | 82/12/30 | 50-440 Q | 8302070192 | 8302070076 | 82/12/21 | 50-334 S |
| 8302040389 | 8302040039 | 82/12/30 | 50-440 Q | 8302070194 | 8302070182 | 83/02/02 | 50-382 A |
| 8302040391 | 8302040587 | 83/01/28 | 50-237 S | 8302070200 | 8302070076 | 82/12/21 | 50-272 S |
| 8302040395 | 8302040039 | 82/12/30 | 50-440 Q | 8302070205 | 8302070076 | 82/12/21 | FOIA |
| 8302040396 | 8302040039 | 82/12/30 | 50-440 Q | 8302070211 | 8302070076 | 82/12/21 | FOIA |
| 8302040397 | 8302040594 | 83/01/24 | 50-265 S | 8302070218 | 8302070076 | 82/12/21 | 50-311 S |
| 8302040398 | 8302040390 | 83/01/31 | 50-289 P | 8302070220 | 8302070215 | 83/02/01 | 50-237 P |
| 8302040399 | 8302040393 | 83/01/28 | 50-277 P | 8302070228 | 8302070076 | 82/12/21 | 50-272 S |
| 8302040405 | 8302040039 | 82/12/30 | 50-440 Q | 8302070236 | 8302070076 | 82/12/21 | 50-311 S |
| 8302040408 | 8302040039 | 82/12/30 | 50-440 Q | 8302070240 | 8302070076 | 82/12/21 | FOIA |
| 8302040411 | 8302040406 | 83/02/01 | 50-305 Q | 8302070244 | 8302070076 | 82/12/21 | FOIA |
| 8302040414 | 8302040039 | 82/12/30 | 50-440 Q | 8302070255 | 8302070253 | 83/01/31 | 50-508 Q |
| 8302040418 | 8302040416 | 83/01/31 | 50-320 P | 8302070260 | 8302070257 | 83/01/18 | 0A999 |
| 8302040421 | 8302040039 | 82/12/30 | 50-440 Q | 8302070265 | 8302070257 | 83/01/18 | 0A999 |
| 8302040428 | 8302040039 | 82/12/30 | 50-440 Q | 8302070266 | 8302070263 | 83/01/18 | 0A999 |
| 8302040431 | 8302040039 | 82/12/30 | 50-440 Q | 8302070269 | 8302070264 | 83/01/28 | 50-213 Q |
| 8302040435 | 8302040039 | 82/12/30 | 50-440 Q | 8302070275 | 8302070270 | 83/01/31 | 50-244 P |
| 8302040440 | 8302040039 | 82/12/30 | 50-440 Q | 8302070282 | 8302070279 | 83/01/31 | 50-187 Q |
| 8302040443 | 8302040439 | 83/01/05 | PROJ | 8302070285 | 8302070278 | 82/12/13 | 50-206 T |
| 8302040448 | 8302040436 | 83/01/25 | 27 48 | 8302070287 | 8302070284 | 82/12/30 | 71-9107 |
| 8302040454 | 8302040450 | 83/01/17 | 71-9167 | 8302070290 | 8302070288 | 83/01/31 | 50-317 F |
| 8302040458 | 8302040452 | 83/01/20 | CONTRACT | 8302070291 | 8302070289 | 83/01/25 | 50-333 P |
| 8302040462 | 8302040460 | 83/01/17 | CONTRACT | 8302070292 | 8302070288 | 83/01/31 | 50-317 F |
| 8302040465 | 8302040464 | 83/01/28 | CONTRACT | 8302070296 | 8302070278 | 82/12/13 | 50-206 Q |
| 8302040466 | 8302040463 | 82/10/12 | 70-1257 | 8302070297 | 8302070295 | 83/02/03 | 50-313 F |
| 8302040482 | 8302040478 | 82/12/27 | FOIA | 8302070299 | 8302070295 | 83/02/03 | 50-313 F |
| 8302040483 | 8302040478 | 82/12/27 | FOIA | 8302070304 | 8302070302 | 83/01/18 | 0A999 |
| 8302040485 | 8302040480 | 83/01/31 | CONTRACT | 8302070305 | 8302070303 | 83/02/01 | 40-86 |
| 8302040491 | 8302040488 | 83/01/28 | CONTRACT | 8302070307 | 8302070302 | 83/01/18 | 0A999 |
| 8302040504 | 8302040497 | 83/01/28 | 50-269 F | 8302070311 | 8302070308 | 83/01/31 | XPRTLIC |
| 8302040506 | 8302040497 | 83/01/28 | 50-269 F | 8302070314 | 8302070307 | 83/01/28 | 50-339 S |
| 8302040507 | 8302040487 | 83/01/12 | 71-9150 | 8302070322 | 8302070320 | 83/01/18 | 0A999 |
| 8302040511 | 8302040497 | 83/01/28 | 50-269 F | 8302070327 | 8302070320 | 83/01/18 | 0A999 |

CROSS REFERENCE OF ENCLOSURES
TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | |
|------------------|--------------------|-------------|------------------|---|------------------|--------------------|-------------|------------------|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8302070334 | 8302070332 | 83/02/03 | 50-369 | P | 8302070632 | 8302070629 | 83/01/27 | CONTRACT | |
| 8302070335 | 8302070331 | 83/01/24 | 50-269 | Q | 8302070633 | 8302070630 | 83/02/01 | 50-346 | F |
| 8302070339 | 8302070337 | 83/01/19 | 50-275 | Q | 8302070637 | 8302070635 | 83/01/10 | CONTRACT | |
| 8302070342 | 8302070340 | 83/01/28 | 50-339 | S | 8302080010 | 8302080007 | 83/01/27 | 50-285 | F |
| 8302070345 | 8302070341 | 83/01/24 | 50-286 | Q | 8302080011 | 8302080008 | 83/02/04 | 50-400 | G |
| 8302070346 | 8302070344 | 83/01/24 | 50-29 | Q | 8302080013 | 8302080007 | 83/01/27 | 50-285 | F |
| 8302070347 | 8302070343 | 82/12/27 | 50-368 | Q | 8302080017 | 8302080012 | 83/01/28 | 50-364 | G |
| 8302070348 | 8302070341 | 83/01/24 | 50-286 | Q | 8302080019 | 8302080015 | 83/02/01 | 50-206 | P |
| 8302070357 | 8302070344 | 83/01/24 | 50-29 | Q | 8302080025 | 8302080020 | 83/02/03 | 50-366 | P |
| 8302070358 | 8302070356 | 83/01/13 | 50-482 | Q | 8302080042 | 8302080029 | 83/01/12 | 50-315 | F |
| 8302070363 | 8302070361 | 83/01/26 | 50-313 | S | 8302080050 | 8302080045 | 83/01/27 | 50-311 | P |
| 8302070366 | 8302070364 | 83/02/01 | 50-498 | Q | 8302080053 | 8302080048 | 83/01/05 | 71-9855 | |
| 8302070367 | 8302070365 | 83/02/02 | 50-244 | Q | 8302080054 | 8302080045 | 83/01/27 | 50-311 | P |
| 8302070370 | 8302070365 | 83/02/02 | 50-244 | Q | 8302080056 | 8302080052 | 82/12/29 | FOIA | |
| 8302070376 | 8302070372 | 83/01/31 | 50-338 | S | 8302080057 | 8302080045 | 83/01/27 | 50-311 | P |
| 8302070382 | 8302070374 | 83/01/18 | 50-313 | Q | 8302080058 | 8302080048 | 83/01/05 | 71-9855 | |
| 8302070383 | 8302070381 | 83/02/01 | 50-395 | S | 8302080064 | 8302080060 | 83/01/31 | CONTRACT | |
| 8302070388 | 8302070386 | 83/01/27 | 50-321 | S | 8302080070 | 8302080067 | 83/01/27 | CONTRACT | |
| 8302070390 | 8302070379 | 83/01/27 | 50-317 | S | 8302080077 | 8302080073 | 83/01/26 | 50-334 | P |
| 8302070391 | 8302070374 | 83/01/18 | 50-313 | Q | 8302080081 | 8302080073 | 83/01/26 | 50-334 | P |
| 8302070394 | 8302070389 | 83/02/02 | 50-354 | Q | 8302080082 | 8302080073 | 83/01/26 | 50-334 | P |
| 8302070396 | 8302070389 | 83/02/02 | 50-354 | Q | 8302080083 | 8302080079 | 83/02/03 | 50-528 | M |
| 8302070398 | 8302070389 | 83/02/02 | 50-354 | Q | 8302080085 | 8302080073 | 83/01/26 | 50-334 | P |
| 8302070399 | 8302070392 | 83/01/27 | 50-280 | S | 8302080086 | 8302080084 | 83/01/05 | 71-491 | |
| 8302070400 | 8302070395 | 83/01/25 | 50-366 | S | 8302080109 | 8302080103 | 82/12/17 | 50-282 | P |
| 8302070402 | 8302070392 | 83/01/27 | 50-280 | S | 8302080114 | 8302080110 | 83/01/24 | 50-341 | G |
| 8302070407 | 8302070392 | 83/01/27 | 50-280 | S | 8302080115 | 8302080100 | 82/12/17 | FOIA | |
| 8302070415 | 8302070411 | 83/01/27 | 50-317 | S | 8302080118 | 8302080100 | 82/12/17 | FOIA | |
| 8302070418 | 8302070405 | 83/01/27 | 50-317 | S | 8302080121 | 8302080100 | 82/12/17 | FOIA | |
| 8302070419 | 8302070413 | 83/02/02 | 50-445 | Q | 8302080122 | 8302080100 | 82/12/17 | 50-280 | Q |
| 8302070427 | 8302070421 | 83/01/27 | 50-318 | S | 8302080123 | 8302080120 | 83/01/31 | 40-8027 | |
| 8302070431 | 8302070425 | 83/01/03 | 50-313 | Q | 8302080127 | 8302080100 | 82/12/17 | 50-206 | P |
| 8302070435 | 8302070432 | 83/02/01 | 50-213 | P | 8302080130 | 8302080126 | 83/01/27 | 50-482 | F |
| 8302070446 | 8302070442 | 83/01/27 | 50-272 | S | 8302080132 | 8302080100 | 82/12/17 | 50-281 | P |
| 8302070450 | 8302070445 | 83/01/31 | State Prog | | 8302080134 | 8302080129 | 83/01/25 | CONTRACT | |
| 8302070452 | 8302070448 | 83/01/31 | 50-289 | P | 8302080135 | 8302080100 | 82/12/17 | FOIA | |
| 8302070455 | 8302070448 | 83/01/31 | 50-289 | P | 8302080139 | 8302080100 | 82/12/17 | FOIA | |
| 8302070461 | 8302070457 | 83/01/27 | 50-311 | S | 8302080141 | 8302080100 | 82/12/17 | FOIA | |
| 8302070467 | 8302070464 | 83/01/28 | 50-293 | S | 8302080142 | 8302080136 | 83/01/27 | 50-346 | S |
| 8302070468 | 8302070462 | 83/02/01 | 50-313 | Q | 8302080143 | 8302080100 | 82/12/17 | FOIA | |
| 8302070475 | 8302070471 | 83/01/24 | 50-313 | Q | 8302080147 | 8302080100 | 82/12/17 | FOIA | |
| 8302070486 | 8302070481 | 83/01/13 | 50-382 | Q | 8302080150 | 8302080100 | 82/12/17 | FOIA | |
| 8302070492 | 8302070485 | 83/02/01 | 50-29 | P | 8302080153 | 8302080148 | 83/02/02 | 50-219 | P |
| 8302070493 | 8302070483 | 83/01/28 | 50-528 | S | 8302080154 | 8302080152 | 83/01/26 | 50-454 | C |
| 8302070499 | 8302070485 | 83/02/01 | 50-29 | P | 8302080155 | 8302080151 | 83/01/26 | 50-275 | P |
| 8302070507 | 8302070500 | 83/02/02 | 50-382 | A | 8302080168 | 8302080164 | 83/02/04 | 50-361 | P |
| 8302070508 | 8302070496 | 83/02/02 | 50-247 | Q | 8302080173 | 8302080171 | 83/02/03 | 50-445 | G |
| 8302070525 | 8302070516 | 82/08/26 | 50-498 | A | 8302080183 | 8302080137 | 83/01/27 | 50-344 | F |
| 8302070526 | 8302070519 | 83/02/02 | 50-309 | F | 8302080187 | 8302080137 | 83/01/27 | 50-344 | F |
| 8302070531 | 8302070523 | 83/02/01 | 50-382 | A | 8302080194 | 8302080191 | 83/02/02 | 50-237 | F |
| 8302070533 | 8302070529 | 83/01/18 | 50-298 | Q | 8302080197 | 8302080191 | 83/02/02 | 50-237 | F |
| 8302070534 | 8302070528 | 83/02/01 | 50-250 | P | 8302080204 | 8302080199 | 83/02/04 | 50-373 | P |
| 8302070535 | 8302070519 | 83/02/02 | 50-309 | F | 8302080206 | 8302080198 | 83/02/01 | 50-346 | P |
| 8302070536 | 8302070529 | 83/01/18 | 50-298 | Q | 8302080208 | 8302080202 | 83/02/01 | 50-213 | P |
| 8302070543 | 8302070529 | 83/01/18 | 50-298 | Q | 8302080231 | 8302080226 | 83/02/01 | 50-305 | S |
| 8302070545 | 8302070538 | 83/02/03 | 50-482 | Q | 8302080242 | 8302080239 | 83/02/03 | 50-333 | R |
| 8302070546 | 8302070539 | 83/01/28 | 50-219 | S | 8302080260 | 8302080245 | 83/01/28 | 50-331 | Q |
| 8302070552 | 8302070541 | 83/02/03 | 50-313 | Q | 8302080261 | 8302080258 | 83/02/04 | 50-317 | Q |
| 8302070556 | 8302070551 | 83/01/24 | 50-313 | Q | 8302080262 | 8302080256 | 83/01/26 | 50-312 | P |
| 8302070560 | 8302070553 | 83/01/28 | 70-1143 | | 8302080265 | 8302080259 | 83/01/20 | 50-373 | S |
| 8302070567 | 8302070562 | 83/01/21 | 50-309 | Q | 8302080266 | 8302080263 | 83/02/02 | 50-315 | S |
| 8302070572 | 8302070562 | 83/01/21 | 50-309 | Q | 8302080267 | 8302080258 | 83/02/04 | 50-317 | Q |
| 8302070579 | 8302070574 | 83/01/28 | 50-267 | S | 8302080272 | 8302080258 | 83/02/04 | 50-317 | Q |
| 8302070583 | 8302070576 | 83/01/25 | 50-334 | S | 8302080273 | 8302080271 | 83/02/02 | 50-285 | F |
| 8302070586 | 8302070562 | 83/01/21 | 50-309 | Q | 8302080279 | 8302080271 | 83/02/02 | 50-285 | F |
| 8302070591 | 8302070584 | 83/01/28 | 50-267 | S | 8302080287 | 8302080284 | 83/02/02 | 50-304 | S |
| 8302070596 | 8302070562 | 83/01/21 | 50-309 | Q | 8302080293 | 8302080286 | 82/12/14 | 50-358 | Q |
| 8302070598 | 8302070592 | 83/01/10 | 50-537 | A | 8302080294 | 8302080289 | 83/01/31 | 50-316 | S |
| 8302070599 | 8302070594 | 83/01/31 | 50-395 | P | 8302080297 | 8302080292 | 83/01/28 | 50-254 | S |
| 8302070600 | 8302070589 | 83/01/20 | 50-285 | Q | 8302080298 | 8302080289 | 83/01/31 | 50-316 | S |
| 8302070602 | 8302070594 | 83/01/31 | 50-395 | P | 8302080307 | 8302080306 | 83/01/30 | 50-329 | A |
| 8302070606 | 8302070593 | 83/01/26 | 50-318 | S | 8302080309 | 8302080308 | 83/01/26 | 50-331 | Q |
| 8302070614 | 8302070613 | 83/01/28 | 50-348 | S | 8302080310 | 8302080306 | 83/01/30 | 50-329 | A |
| 8302070617 | 8302070613 | 83/01/28 | 50-348 | S | 8302080312 | 8302080306 | 83/01/30 | 50-329 | A |
| 8302070620 | 8302070613 | 83/01/28 | 50-348 | S | 8302080313 | 8302080308 | 83/01/26 | 50-331 | Q |
| 8302070621 | 8302070616 | 83/01/27 | 50-382 | A | 8302080318 | 8302080315 | 83/01/26 | 50-461 | Q |
| 8302070623 | 8302070618 | 83/01/28 | 50-267 | S | 8302080319 | 8302080317 | 83/02/02 | 50-255 | S |
| 8302070627 | 8302070625 | 83/02/01 | 50-315 | F | 8302080322 | 8302080316 | 83/02/04 | 50-10 | F |
| 8302070628 | 8302070625 | 83/02/01 | 50-315 | F | 8302080324 | 8302080321 | 83/01/31 | 50-315 | S |
| 8302070631 | 8302070630 | 83/02/01 | 50-346 | F | 8302080326 | 8302080321 | 83/01/31 | 50-315 | S |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302080329 | 8302080327 | 83/02/02 | 50-316 S | 8302090270 | 8302090263 | 83/02/03 | CONTRACT |
| 8302080330 | 8302080328 | 83/01/27 | 50-331 S | 8302090279 | 8302090272 | 83/02/07 | 50-247 T |
| 8302080331 | 8302080327 | 83/02/02 | 50-316 S | 8302090277 | 8302090292 | 83/02/03 | TOPREP |
| 8302080335 | 8302080327 | 83/02/02 | 50-316 S | 8302090313 | 8302090310 | 83/02/02 | 50-29 F |
| 8302080337 | 8302080327 | 83/02/02 | 50-316 S | 8302090314 | 8302090309 | 83/02/03 | 50-387 P |
| 8302080341 | 8302080327 | 83/02/02 | 50-316 S | 8302090320 | 8302090309 | 83/02/03 | 50-387 P |
| 8302080356 | 8302080344 | 83/02/02 | 50-249 S | 8302090321 | 8302090316 | 83/01/28 | 50-317 S |
| 8302080357 | 8302080355 | 83/01/31 | 50-250 P | 8302090323 | 8302090309 | 83/02/03 | 50-387 P |
| 8302080359 | 8302080353 | 83/02/01 | 50-249 S | 8302090332 | 8302090309 | 83/02/03 | 50-387 P |
| 8302080360 | 8302080358 | 83/01/31 | 50-305 P | 8302090334 | 8302090325 | 83/02/08 | 50-537 B |
| 8302080367 | 8302080362 | 83/02/07 | 50-528 E | 8302090343 | 8302090338 | 83/01/19 | QA999 |
| 8302080368 | 8302080365 | 83/02/02 | 50-254 F | 8302090347 | 8302090342 | 83/01/20 | QA999 |
| 8302080372 | 8302080365 | 83/02/02 | 50-254 F | 8302090349 | 8302090339 | 83/01/28 | 50-277 S |
| 8302080378 | 8302080375 | 83/01/02 | 50-346 F | 8302090351 | 8302090341 | 83/02/02 | 50-289 P |
| 8302080380 | 8302080375 | 83/01/02 | 50-346 F | 8302090353 | 8302090338 | 83/01/19 | QA999 |
| 8302080385 | 8302080382 | 83/02/02 | 50-289 F | 8302090354 | 8302090344 | 83/01/28 | 50-219 S |
| 8302080404 | 8302080402 | 83/01/21 | 71-6386 | 8302090355 | 8302090342 | 83/01/20 | QA999 |
| 8302080408 | 8302080405 | 83/02/02 | 50-298 F | 8302090363 | 8302090341 | 83/02/02 | 50-289 P |
| 8302080409 | 8302080406 | 83/01/31 | 50-387 P | 8302090365 | 8302090360 | 83/01/20 | QA999 |
| 8302080413 | 8302080406 | 83/01/31 | 50-387 P | 8302090369 | 8302090342 | 83/01/20 | QA999 |
| 8302080417 | 8302080406 | 83/01/31 | 50-387 P | 8302090371 | 8302090360 | 83/01/20 | QA999 |
| 8302080433 | 8302080429 | 83/01/25 | CONTRACT | 8302090377 | 8302090372 | 83/01/31 | 50-318 S |
| 8302080435 | 8302080432 | 83/02/02 | 50-317 F | 8302090378 | 8302090368 | 83/01/25 | 50-304 S |
| 8302080438 | 8302080434 | 83/01/26 | 50-313 P | 8302090379 | 8302090360 | 83/01/20 | QA999 |
| 8302080439 | 8302080437 | 83/01/24 | 71-6679 | 8302090381 | 8302090375 | 83/02/04 | QA999 |
| 8302080440 | 8302080432 | 83/02/02 | 50-317 F | 8302090391 | 8302090375 | 83/02/04 | QA999 |
| 8302080445 | 8302080442 | 83/01/12 | 71-9151 | 8302090394 | 8302090387 | 83/02/04 | QA999 |
| 8302080446 | 8302080443 | 83/01/25 | EXPORTLIC | 8302090397 | 8302090395 | 83/01/31 | 50-317 S |
| 8302080448 | 8302080443 | 83/01/25 | EXPORTLIC | 8302090404 | 8302090401 | 83/01/17 | 50-377 Q |
| 8302080449 | 8302080447 | 83/01/12 | 71-6771 | 8302090410 | 8302090407 | 83/02/07 | 50-289 V |
| 8302080474 | 8302080471 | 83/02/01 | 70-1113 | 8302090412 | 8302090411 | 83/02/01 | 50-354 A |
| 8302080476 | 8302080471 | 83/02/01 | 70-1113 | 8302090422 | 8302090420 | 83/01/19 | 50-318 S |
| 8302080477 | 8302080471 | 83/02/01 | 70-1113 | 8302090424 | 8302090423 | 83/01/26 | TOPREP |
| 8302090004 | 8302090002 | 83/02/01 | 50-259 P | 8302090426 | 8302090423 | 83/01/26 | TOPREP |
| 8302090006 | 8302090002 | 83/02/01 | 50-259 P | 8302090427 | 8302090423 | 83/01/26 | TOPREP |
| 8302090008 | 8302090005 | 83/01/04 | 50-358 A | 8302090429 | 8302090423 | 83/01/26 | TOPREP |
| 8302090013 | 8302090005 | 83/01/04 | 50-358 A | 8302090441 | 8302090437 | 83/02/03 | 50-244 Q |
| 8302090020 | 8302090005 | 83/01/04 | 50-358 G | 8302090452 | 8302090445 | 83/01/31 | 50-289 F |
| 8302090022 | 8302090019 | 83/02/03 | 50-289 F | 8302090464 | 8302090457 | 83/02/07 | 50-295 P |
| 8302090023 | 8302090005 | 83/01/04 | 50-358 A | 8302090467 | 8302090462 | 83/02/03 | 50-348 F |
| 8302090030 | 8302090024 | 83/01/26 | CONTRACT | 8302090471 | 8302090462 | 83/02/03 | 50-348 F |
| 8302090035 | 8302090005 | 83/01/04 | 50-358 Q | 8302090478 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090044 | 8302090005 | 83/01/04 | 50-358 Q | 8302090484 | 8302090475 | 83/02/03 | TOPREP |
| 8302090051 | 8302090034 | 82/12/07 | 40-8492 | 8302090485 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090052 | 8302090005 | 83/01/04 | 50-358 Q | 8302090487 | 8302090462 | 83/01/12 | HASTE NOT |
| 8302090055 | 8302090049 | 83/01/31 | 50-315 F | 8302090488 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090060 | 8302090005 | 83/01/04 | 50-358 Q | 8302090490 | 8302090475 | 83/02/03 | TOPREP |
| 8302090062 | 8302090049 | 83/01/31 | 50-315 F | 8302090491 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090064 | 8302090005 | 83/01/04 | 50-358 Q | 8302090493 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090074 | 8302090068 | 83/01/27 | 50-280 F | 8302090495 | 8302090462 | 83/01/12 | HASTE NOT |
| 8302090076 | 8302090035 | 83/01/04 | 50-358 Q | 8302090496 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090078 | 8302090068 | 83/01/27 | 50-280 F | 8302090498 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090097 | 8302090091 | 83/01/31 | 50-298 F | 8302090501 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090103 | 8302090095 | 82/12/27 | 50-358 Q | 8302090502 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090107 | 8302090095 | 82/12/27 | FOIA | 8302090504 | 8302090500 | 82/12/15 | CONTRACT |
| 8302090115 | 8302090105 | 83/01/31 | 50-315 F | 8302090505 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090118 | 8302090095 | 82/12/27 | 50-358 Q | 8302090508 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090125 | 8302090105 | 83/01/31 | 50-315 F | 8302090510 | 8302090507 | 82/12/03 | CONTRACT |
| 8302090126 | 8302090095 | 82/12/27 | 50-358 Q | 8302090512 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090137 | 8302090095 | 82/12/27 | 50-358 Q | 8302090520 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090142 | 8302090135 | 83/01/26 | 50-295 P | 8302090524 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090144 | 8302090134 | 83/01/19 | 71-476 | 8302090527 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090148 | 8302090095 | 82/12/27 | 50-358 Q | 8302090538 | 8302090534 | 82/09/03 | 70-398 |
| 8302090157 | 8302090095 | 82/12/27 | 50-358 Q | 8302090539 | 8302090535 | 83/02/03 | 50-267 F |
| 8302090159 | 8302090095 | 82/12/27 | 50-358 Q | 8302090543 | 8302090535 | 83/02/03 | 50-267 F |
| 8302090168 | 8302090095 | 82/12/27 | 50-358 Q | 8302090546 | 8302090460 | 83/01/10 | 50-358 Q |
| 8302090172 | 8302090166 | 83/01/28 | 50-312 Q | 8302090580 | 8302090578 | 83/01/24 | 40-2259 |
| 8302090173 | 8302090095 | 82/12/27 | 50-358 Q | 8302090594 | 8302090590 | 83/01/11 | 50-293 P |
| 8302090175 | 8302090170 | 83/02/01 | 50-289 S | 8302090597 | 8302090583 | 83/01/27 | 40-8745 |
| 8302090183 | 8302090178 | 83/01/28 | COMMISSION | 8302090608 | 8302090590 | 83/01/11 | 50-293 R |
| 8302090195 | 8302090189 | 83/01/21 | 70-364 | 8302090609 | 8302090590 | 83/01/11 | 50-293 R |
| 8302090200 | 8302090189 | 83/01/21 | 70-364 | 8302090617 | 8302090590 | 83/01/11 | 50-293 R |
| 8302090203 | 8302090188 | 83/01/27 | 50-318 S | 8302100004 | 8302100002 | 83/01/26 | 40-299 |
| 8302090213 | 8302090205 | 83/01/27 | 50-259 X | 8302100012 | 8302100010 | 83/01/11 | FOIA |
| 8302090222 | 8302090205 | 83/01/27 | 50-259 X | 8302100013 | 8302100011 | 83/01/28 | CONTRACT |
| 8302090230 | 8302090224 | 83/02/06 | 50-247 T | 8302100016 | 8302100008 | 83/01/20 | 40-3453 |
| 8302090242 | 8302090235 | 83/01/19 | 71-345 | 8302100021 | 8302100017 | 83/01/20 | CONTRACT |
| 8302090251 | 8302090241 | 83/02/04 | 50-400 Q | 8302100023 | 8302100019 | 83/01/11 | FOIA |
| 8302090254 | 8302090245 | 83/02/04 | 50-537 A | 8302100027 | 8302100026 | 83/01/24 | CONTRACT |
| 8302090261 | 8302090252 | 83/02/01 | 50-313 P | 8302100038 | 8302100033 | 83/01/28 | CONTRACT |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302100043 | 8302100040 | 83/02/03 | 50-271 F | 8302100400 | 8302100393 | 83/01/18 | PR |
| 8302100046 | 8302100040 | 83/02/03 | 50-271 F | 8302100403 | 8302100399 | 83/01/17 | PR |
| 8302100051 | 8302100036 | 83/02/02 | 50-321 P | 8302100408 | 8302100401 | 83/01/31 | PRM |
| 8302100057 | 8302100053 | 83/01/04 | CONTRACT | 8302100409 | 8302100405 | 83/01/28 | 50-277 Q |
| 8302100060 | 8302100036 | 83/02/02 | 50-321 P | 8302100411 | 8302100402 | 83/01/28 | PR |
| 8302100062 | 8302100019 | 83/01/11 | FOIA | 8302100412 | 8302100407 | 83/02/07 | 50-354 Q |
| 8302100067 | 8302100019 | 83/01/11 | FOIA | 8302100414 | 8302100405 | 83/01/28 | 50-277 Q |
| 8302100076 | 8302100036 | 83/02/02 | 50-321 P | 8302100421 | 8302100416 | 83/02/04 | 50-309 Q |
| 8302100079 | 8302100073 | 83/01/27 | 40-8502 | 8302100424 | 8302100416 | 83/01/31 | 50-368 S |
| 8302100081 | 8302100074 | 83/01/04 | CONTRACT | 8302100425 | 8302100420 | 83/01/13 | PR |
| 8302100096 | 8302100090 | 83/01/31 | 50-346 S | 8302100435 | 8302100431 | 83/01/17 | PR |
| 8302100097 | 8302100093 | 83/01/18 | 50-318 P | 8302100436 | 8302100429 | 83/01/28 | 50-333 Q |
| 8302100098 | 8302100091 | 83/01/04 | CONTRACT | 8302100437 | 8302100430 | 83/01/25 | 50-387 Q |
| 8302100104 | 8302100093 | 83/01/18 | 50-318 P | 8302100447 | 8302100444 | 83/02/03 | 50-215 S |
| 8302100105 | 8302100101 | 83/02/02 | 50-238 P | 8302100449 | 8302100448 | 83/01/28 | PR |
| 8302100108 | 8302100103 | 83/01/31 | 50-348 P | 8302100453 | 8302100445 | 83/01/28 | PR |
| 8302100109 | 8302100093 | 83/01/18 | 50-318 P | 8302100457 | 8302100455 | 83/01/14 | PR |
| 8302100110 | 8302100101 | 83/02/02 | 50-238 P | 8302100458 | 8302100445 | 83/01/28 | PR |
| 8302100111 | 8302100107 | 83/02/04 | 50-320 R | 8302100462 | 8302100441 | 83/01/24 | PR |
| 8302100112 | 8302100103 | 83/01/31 | 50-348 P | 8302100470 | 8302100467 | 83/01/12 | PR |
| 8302100114 | 8302100106 | 83/01/03 | CONTRACT | 8302100471 | 8301240753 | 83/01/13 | PR |
| 8302100115 | 8302100103 | 83/01/31 | 50-348 P | 8302100473 | 8301240753 | 83/01/13 | PR |
| 8302100117 | 8302100107 | 83/02/04 | 50-320 R | 8302100481 | 8302100474 | 83/02/01 | 71-491 |
| 8302100119 | 8302100113 | 83/01/25 | 50-317 P | 8302100489 | 8302100485 | 82/12/21 | CONTRACT |
| 8302100123 | 8302100113 | 83/01/25 | 50-217 P | 8302100501 | 8302100499 | 83/01/04 | CONTRACT |
| 8302100127 | 8302100113 | 83/01/25 | 50-317 P | 8302100522 | 8302100512 | 83/02/03 | 50-445 A |
| 8302100128 | 8302100121 | 83/01/04 | CONTRACT | 8302100505 | 8302100504 | 83/01/31 | 50-260 S |
| 8302100141 | 8302100134 | 83/01/27 | 50-338 P | 8302100512 | 8302100510 | 83/02/02 | 50-324 S |
| 8302100142 | 8302100136 | 83/01/03 | CONTRACT | 8302100515 | 8302100507 | 83/02/01 | 50-366 S |
| 8302100146 | 8302100134 | 83/01/27 | 50-338 P | 8302100516 | 8302100509 | 83/02/07 | 50-440 G |
| 8302100150 | 8302100134 | 83/01/27 | 50-338 P | 8302100519 | 8302100514 | 83/02/04 | 50-416 S |
| 8302100173 | 8302100165 | 83/01/03 | 40-3453 | 8302100521 | 8302100517 | 83/02/03 | 50-296 S |
| 8302100179 | 8302100175 | 83/02/04 | 50-344 P | 8302100527 | 8302100524 | 83/01/31 | 50-339 S |
| 8302100189 | 8302100185 | 83/01/28 | 50-292 P | 8302100529 | 8302100528 | 83/02/01 | 50-366 S |
| 8302100190 | 8302100182 | 83/01/04 | 40-8102 | 8302100532 | 8302100530 | 83/02/03 | 50-416 S |
| 8302100200 | 8302100197 | 83/02/02 | 50-282 F | 8302100535 | 8302100533 | 83/02/03 | 50-335 S |
| 8302100209 | 8302100202 | 83/02/08 | 50-440 Q | 8302100539 | 8302100531 | 83/02/04 | 50-416 S |
| 8302100213 | 8302100202 | 83/02/08 | 50-440 Q | 8302100540 | 8302100537 | 83/01/31 | 50-296 S |
| 8302100217 | 8302100214 | 83/02/07 | 50-237 P | 8302100547 | 8302100536 | 83/02/01 | 50-339 S |
| 8302100226 | 8302100223 | 83/02/01 | 50-395 P | 8302100549 | 8302100542 | 83/01/31 | 50-324 S |
| 8302100231 | 8302100227 | 83/02/07 | 50-245 F | 8302100550 | 8302100546 | 83/01/27 | 50-321 S |
| 8302100236 | 8302100234 | 83/02/03 | 50-213 P | 8302100560 | 8302100553 | 83/02/03 | 50-416 S |
| 8302100237 | 8302100232 | 83/02/03 | 50-289 P | 8302100561 | 8302100557 | 83/02/03 | 50-409 P |
| 8302100240 | 8302100232 | 83/02/03 | 50-289 P | 8302100564 | 8302100558 | 83/02/03 | 50-416 S |
| 8302100242 | 8302100238 | 83/02/08 | 50-445 Q | 8302100566 | 8302100562 | 83/01/31 | 50-281 S |
| 8302100246 | 8302100238 | 83/02/08 | 50-445 Q | 8302100567 | 8302100563 | 83/02/03 | 50-416 S |
| 8302100248 | 8302100245 | 83/02/01 | 50-348 P | 8302100569 | 8302100562 | 83/01/31 | 50-281 S |
| 8302100252 | 8302100250 | 83/02/03 | CONTRACT | 8302100572 | 8302100566 | 83/01/31 | 50-281 S |
| 8302100261 | 8302240353 | 83/02/16 | 50-482 A | 8302100583 | 8302100578 | 83/02/07 | 50-275 P |
| 8302100262 | 8302100258 | 83/02/08 | 50-322 Q | 8302100584 | 8302100582 | 83/02/07 | 50-220 R |
| 8302100272 | 8302100268 | 83/01/25 | 50-387 Q | 8302100593 | 8302100589 | 83/02/04 | 50-416 S |
| 8302100273 | 8302100270 | 83/02/07 | 50-261 P | 8302100595 | 8302100588 | 83/01/31 | 50-339 S |
| 8302100278 | 8302100275 | 83/01/26 | 50-277 Q | 8302100596 | 8302100581 | 83/01/31 | 50-339 S |
| 8302100301 | 8302100276 | 83/01/26 | 50-285 P | 8302100598 | 8302100592 | 83/02/01 | 50-328 S |
| 8302100303 | 8302100302 | 83/01/27 | 50-307 Q | 8302100601 | 8302100597 | 83/01/31 | REGGD |
| 8302100312 | 8302100310 | 83/01/27 | 50-213 Q | 8302100602 | 8302100600 | 83/02/04 | 50-416 S |
| 8302100320 | 8302100319 | 83/01/14 | PR | 8302100608 | 8302100603 | 83/02/01 | 50-366 S |
| 8302100324 | 8302100321 | 83/01/14 | PR | 8302100609 | 8302100604 | 83/01/31 | 50-335 S |
| 8302100325 | 8302100322 | 83/01/24 | PR | 8302100615 | 8302100610 | 83/01/28 | 50-275 R |
| 8302100326 | 8302100322 | 83/01/24 | PR | 8302100617 | 8302100610 | 83/01/28 | 50-275 R |
| 8302100327 | 8302100323 | 83/01/17 | PR | 8302100618 | 8302100614 | 83/02/08 | 50-271 P |
| 8302100332 | 8302100330 | 83/02/01 | 50-259 P | 8302100619 | 8302100612 | 83/02/03 | 50-335 S |
| 8302100336 | 8302100328 | 83/01/27 | PR | 8302100622 | 8302100616 | 83/02/01 | 50-241 Q |
| 8302100340 | 8302100334 | 83/02/08 | REVIEW GRP | 8302100624 | 8302100620 | 83/01/28 | 50-369 S |
| 8302100342 | 8302100318 | 83/01/27 | 50-293 Q | 8302100636 | 8302100631 | 83/02/01 | 50-128 P |
| 8302100346 | 8302100344 | 83/01/13 | PR | 8302100641 | 8302100639 | 83/02/07 | 50-443 Q |
| 8302100351 | 8302100348 | 83/01/17 | PR | 8302100642 | 8302100634 | 83/02/01 | 50-325 S |
| 8302100358 | 8302100355 | 83/02/02 | PRM | 8302100650 | 8302100644 | 83/01/31 | 50-260 S |
| 8302100359 | 8302100352 | 83/02/08 | REVIEW GRP | 8302100652 | 8302100649 | 83/02/08 | 50-322 Q |
| 8302100365 | 8302100360 | 83/01/17 | PR | 8302100661 | 8302100657 | 83/02/04 | 50-155 Q |
| 8302100371 | 8302100363 | 83/01/28 | PR | 8302100665 | 8302100660 | 83/01/27 | 50-366 S |
| 8302100372 | 8302100368 | 83/01/19 | PR | 8302100673 | 8302100668 | 83/02/01 | 50-269 P |
| 8302100376 | 8302100370 | 83/02/01 | PR | 8302100674 | 8302100669 | 83/02/07 | 50-366 S |
| 8302100377 | 8302100363 | 83/01/28 | PR | 8302100681 | 8302100679 | 83/01/25 | 50-366 S |
| 8302100381 | 8302100392 | 83/02/08 | REVIEW GRP | 8302100691 | 8302100684 | 83/02/01 | 40-299 |
| 8302100386 | 8302100382 | 83/01/17 | PR | 8302100693 | 8302100692 | 83/02/04 | 50-348 P |
| 8302100389 | 8302100385 | 83/01/28 | PR | 8302100693 | 8302100697 | 83/01/31 | 40-8102 |
| 8302100392 | 8302100393 | 83/01/18 | PR | 8302100694 | 8302100696 | 83/02/04 | 50-416 S |
| 8302100395 | 8302100388 | 83/01/27 | 50-293 S | 8302100695 | 8302100693 | 83/02/03 | 50-267 S |
| 8302100398 | 8302100393 | 83/01/28 | PR | 8302100696 | 8302100693 | 83/02/03 | 50-315 S |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

529

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302150008 | 8302150037 | 83/02/08 | 50-335 P | 8302150295 | 8302150288 | 83/01/25 | 50-370 Q |
| 8302150012 | 8302150010 | 83/01/27 | 50-315 Q | 8302150297 | 8302150274 | 83/01/26 | 50-416 Q |
| 8302150014 | 8302150013 | 83/02/10 | 50-261 Q | 8302150298 | 8302150288 | 83/01/25 | 50-370 Q |
| 8302150016 | 8302150011 | 83/02/03 | 50-368 P | 8302150302 | 8302150287 | 83/02/08 | 50-321 S |
| 8302150017 | 8302150013 | 83/02/10 | 50-261 Q | 8302150303 | 8302150274 | 83/01/26 | 50-416 Q |
| 8302150018 | 8302150013 | 83/02/10 | 50-261 Q | 8302150304 | 8302150288 | 83/01/25 | 50-370 Q |
| 8302150019 | 8302150015 | 83/01/26 | 50-358 Q | 8302150305 | 8302150296 | 83/01/19 | 50-327 Q |
| 8302150022 | 8302150013 | 83/02/10 | 50-261 Q | 8302150311 | 8302150296 | 83/01/19 | 50-327 Q |
| 8302150024 | 8302150021 | 83/01/05 | 50-259 Q | 8302150312 | 8302150296 | 83/01/19 | 50-327 Q |
| 8302150025 | 8302150020 | 83/02/03 | 50-321 S | 8302150316 | 8302150308 | 83/01/06 | 50-389 Q |
| 8302150026 | 8302150023 | 83/02/03 | 50-324 S | 8302150317 | 8302150309 | 83/01/28 | 50-259 Q |
| 8302150031 | 8302150028 | 83/02/08 | 50-261 Q | 8302150320 | 8302150296 | 83/01/19 | 50-327 Q |
| 8302150041 | 8302150037 | 83/02/08 | 40-8709 | 8302150323 | 8302150319 | 83/02/09 | 50-155 P |
| 8302150043 | 8302150040 | 83/02/08 | 50-325 P | 8302150326 | 8302150309 | 83/01/28 | 50-259 Q |
| 8302150048 | 8302150044 | 83/02/03 | 50-254 R | 8302150328 | 8302150324 | 83/02/07 | 0A999 |
| 8302150057 | 8302150033 | 83/02/01 | 70-143 | 8302150329 | 8302150322 | 83/01/28 | 50-361 S |
| 8302150061 | 8302150033 | 83/02/01 | 70-143 | 8302150330 | 8302150321 | 83/01/28 | 50-324 Q |
| 8302150067 | 8302150058 | 83/02/09 | 50-302 Q | 8302150331 | 8302150309 | 83/01/28 | 50-259 Q |
| 8302150069 | 8302150033 | 83/02/01 | 70-143 | 8302150333 | 8302150324 | 83/02/07 | 0A999 |
| 8302150070 | 8302150063 | 83/02/07 | 50-250 S | 8302150334 | 8302150321 | 83/01/28 | 50-324 Q |
| 8302150071 | 8302150059 | 83/02/07 | 50-302 Q | 8302150336 | 8302150309 | 83/01/28 | 50-259 Q |
| 8302150072 | 8302150064 | 83/01/27 | 50-324 Q | 8302150337 | 8302150324 | 83/02/07 | 0A999 |
| 8302150075 | 8302150068 | 83/02/08 | 50-111 Q | 8302150339 | 8302150321 | 83/01/28 | 50-324 Q |
| 8302150076 | 8302150059 | 83/02/09 | 50-302 Q | 8302150342 | 8302150309 | 83/01/28 | 50-259 Q |
| 8302150077 | 8302150073 | 83/02/08 | 50-366 S | 8302150345 | 8302150321 | 83/01/28 | 50-324 Q |
| 8302150082 | 8302150068 | 83/02/08 | 50-111 Q | 8302150346 | 8302150325 | 83/02/07 | 50-259 Q |
| 8302150084 | 8302150074 | 83/01/26 | 50-370 Q | 8302150351 | 8302150347 | 83/01/25 | 50-416 Q |
| 8302150085 | 8302150058 | 83/02/09 | 50-302 Q | 8302150353 | 8302150348 | 83/01/31 | 50-390 Q |
| 8302150089 | 8302150058 | 83/02/09 | 50-302 Q | 8302150354 | 8302150347 | 83/01/25 | 50-416 Q |
| 8302150093 | 8302150079 | 83/02/10 | 50-261 Q | 8302150356 | 8302150352 | 83/01/07 | 70-143 |
| 8302150094 | 8302150083 | 83/02/08 | 50-416 S | 8302150357 | 8302150347 | 83/01/25 | 50-416 Q |
| 8302150095 | 8302150087 | 83/02/07 | 50-285 Q | 8302150358 | 8302150350 | 83/01/31 | 50-293 F |
| 8302150101 | 8302150058 | 83/02/09 | 50-302 Q | 8302150359 | 8302150348 | 83/01/31 | 50-390 Q |
| 8302150102 | 8302150090 | 83/01/24 | 50-389 Q | 8302150360 | 8302150288 | 83/01/25 | 50-370 Q |
| 8302150104 | 8302150091 | 83/02/01 | 50-366 S | 8302150361 | 8302150355 | 83/02/07 | 50-335 S |
| 8302150105 | 8302150103 | 83/02/08 | 50-366 S | 8302150362 | 8302150348 | 83/01/31 | 50-390 Q |
| 8302150106 | 8302150099 | 83/02/07 | 50-416 S | 8302150363 | 8302150348 | 83/01/31 | 50-390 Q |
| 8302150109 | 8302150079 | 83/02/10 | 50-261 Q | 8302150367 | 8302150363 | 83/01/28 | 50-440 Q |
| 8302150113 | 8302150079 | 83/02/10 | 50-261 Q | 8302150373 | 8302150366 | 83/01/12 | 50-206 Q |
| 8302150115 | 8302150110 | 83/02/09 | 50-416 S | 8302150385 | 8302150382 | 83/01/13 | 50-389 Q |
| 8302150118 | 8302150079 | 83/02/10 | 50-261 Q | 8302150386 | 8302150383 | 83/02/09 | 50-317 Q |
| 8302150120 | 8302150112 | 83/02/04 | 50-206 Q | 8302150388 | 8302150382 | 83/01/13 | 50-389 Q |
| 8302150124 | 8302150114 | 83/02/01 | 50-254 S | 8302150393 | 8302150393 | 83/02/09 | 50-317 Q |
| 8302150128 | 8302150079 | 83/02/10 | 50-261 Q | 8302150395 | 8302150370 | 83/02/01 | 50-346 S |
| 8302150129 | 8302150119 | 83/02/04 | 50-324 S | 8302150402 | 8302150397 | 83/02/08 | 50-366 S |
| 8302150139 | 8302150121 | 83/02/01 | 50-366 S | 8302150403 | 8302150397 | 83/02/10 | 70-143 |
| 8302150136 | 8302150132 | 83/02/10 | 50-395 R | 8302150406 | 8302150404 | 83/01/26 | 50-454 Q |
| 8302150140 | 8302150130 | 83/01/24 | 50-413 Q | 8302150408 | 8302150404 | 83/01/26 | 50-454 Q |
| 8302150142 | 8302150133 | 83/02/08 | 50-366 S | 8302150411 | 8302150409 | 83/02/09 | 70-1201 |
| 8302150143 | 8302150134 | 83/02/03 | 50-443 Y | 8302150413 | 8302150412 | 82/11/02 | 50-261 Q |
| 8302150145 | 8302150138 | 83/02/07 | 50-302 P | 8302150416 | 8302150412 | 82/11/02 | 50-261 Q |
| 8302150151 | 8302150144 | 83/02/04 | 50-305 S | 8302150420 | 8302150418 | 83/01/31 | 50-352 Q |
| 8302150155 | 8302150147 | 83/01/28 | 50-362 S | 8302150424 | 8302150421 | 83/02/07 | 50-266 P |
| 8302150162 | 8302150152 | 83/02/03 | 50-321 S | 8302150426 | 8302150347 | 83/01/25 | 50-416 Q |
| 8302150163 | 8302150159 | 83/02/10 | 50-333 P | 8302150428 | 8302150422 | 83/01/12 | 50-335 Q |
| 8302150166 | 8302150159 | 83/02/10 | 50-333 P | 8302150429 | 8302150425 | 83/01/19 | 70-1113 |
| 8302150171 | 8302150165 | 83/01/27 | 50-269 Q | 8302150431 | 8302150423 | 83/02/09 | 50-321 Q |
| 8302150179 | 8302150174 | 83/02/10 | 50-331 P | 8302150435 | 8302150423 | 83/02/09 | 50-321 Q |
| 8302150181 | 8302150153 | 83/01/05 | 50-327 Q | 8302150436 | 8302150430 | 83/02/09 | 50-250 Q |
| 8302150191 | 8302150187 | 83/02/03 | 50-285 P | 8302150437 | 8302150432 | 83/01/17 | 50-295 Q |
| 8302150193 | 8302150189 | 83/02/04 | 50-213 S | 8302150438 | 8302150434 | 83/01/27 | 50-124 Q |
| 8302150194 | 8302150190 | 83/02/03 | 50-321 S | 8302150439 | 8302150415 | 83/02/03 | 50-316 S |
| 8302150205 | 8302150196 | 83/02/11 | 50-331 R | 8302150440 | 8302150430 | 83/02/09 | 50-250 Q |
| 8302150207 | 8302150198 | 83/02/08 | 50-387 P | 8302150441 | 8302150423 | 83/02/09 | 50-321 Q |
| 8302150209 | 8302150201 | 83/01/27 | 50-321 S | 8302150443 | 8302150427 | 83/01/19 | 50-321 Q |
| 8302150210 | 8302150203 | 83/02/03 | 50-366 S | 8302150446 | 8302150434 | 83/01/27 | 50-124 Q |
| 8302150212 | 8302150198 | 83/02/08 | 50-387 P | 8302150447 | 8302150433 | 83/02/04 | 50-361 S |
| 8302150223 | 8302150215 | 83/02/07 | 50-395 S | 8302150448 | 8302150430 | 83/02/09 | 50-250 Q |
| 8302150229 | 8302150217 | 83/01/31 | 50-362 S | 8302150449 | 8302150423 | 83/02/09 | 50-321 Q |
| 8302150234 | 8302150221 | 83/01/10 | 50-321 Q | 8302150450 | 8302150432 | 83/01/17 | 50-295 Q |
| 8302150252 | 8302150241 | 83/02/01 | 50-366 S | 8302150453 | 8302150434 | 83/01/27 | 50-124 Q |
| 8302150261 | 8302150256 | 83/02/01 | 50-267 P | 8302150458 | 8302150430 | 83/02/09 | 50-250 Q |
| 8302150273 | 8302150266 | 83/02/07 | 50-219 Q | 8302150459 | 8302150423 | 83/02/09 | 50-321 Q |
| 8302150277 | 8302150258 | 83/01/26 | 50-389 Q | 8302150461 | 8302150434 | 83/01/27 | 50-124 Q |
| 8302150278 | 8302150268 | 83/01/31 | 50-247 S | 8302150465 | 8302150427 | 83/01/19 | 50-321 Q |
| 8302150281 | 8302150245 | 83/02/03 | 50-361 S | 8302150466 | 8302150456 | 83/02/08 | 50-483 Q |
| 8302150283 | 8302150279 | 83/02/08 | 50-331 P | 8302150470 | 8302150463 | 83/01/19 | 50-327 Q |
| 8302150285 | 8302150276 | 83/01/28 | 50-361 S | 8302150472 | 8302150463 | 83/01/19 | 50-327 Q |
| 8302150286 | 8302150274 | 83/01/26 | 50-416 Q | 8302150478 | 8302150463 | 83/01/19 | 50-327 Q |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302150480 | 8302150464 | 83/02/09 | 0A999 | 8302150481 | 8302150471 | 83/01/19 | 50-259 Q |
| 8302150482 | 8302150463 | 83/01/19 | 50-327 Q | 8302150482 | 8302150472 | 83/02/03 | 50-266 S |
| 8302150484 | 8302150474 | 83/01/31 | 50-438 Q | 8302150483 | 8302150477 | 83/01/08 | 50-261 S |
| 8302150487 | 8302150483 | 83/01/31 | 50-309 Q | 8302150484 | 8302150490 | 83/01/07 | 50-302 Q |
| 8302150488 | 8302150427 | 83/01/19 | 50-321 Q | 8302150492 | 8302150483 | 83/02/07 | 50-302 Q |
| 8302150490 | 8302150481 | 83/02/03 | 50-366 S | 8302150494 | 8302150487 | 83/01/05 | 50-324 Q |
| 8302150495 | 8302150483 | 83/01/31 | 50-309 Q | 8302150498 | 8302150471 | 83/01/19 | 50-259 Q |
| 8302150496 | 8302150462 | 83/01/12 | 50-390 Q | 8302150500 | 8302150480 | 83/01/07 | 50-302 Q |
| 8302150500 | 8302150494 | 83/02/10 | 50-358 H | 8302150501 | 8302150490 | 83/01/10 | 50-228 Q |
| 8302150507 | 8302150501 | 83/01/27 | 50-311 S | 8302150504 | 8302150496 | 83/01/11 | 50-333 Q |
| 8302150510 | 8302150504 | 83/02/04 | 50-128 P | 8302150510 | 8302150471 | 83/01/19 | 50-259 Q |
| 8302150512 | 8302150486 | 83/01/31 | 50-461 P | 8302150511 | 8302150503 | 83/01/07 | 50-400 Q |
| 8302150516 | 8302150503 | 83/02/08 | 50-249 Q | 8302150517 | 8302150712 | 83/02/07 | 50-395 Q |
| 8302150517 | 8302150506 | 83/02/08 | 50-366 S | 8302150520 | 8302150715 | 83/01/19 | 50-389 Q |
| 8302150518 | 8302150477 | 83/01/24 | 50-324 Q | 8302150521 | 8302150716 | 83/01/10 | 50-121 Q |
| 8302150520 | 8302150477 | 83/01/24 | 50-324 Q | 8302150524 | 8302150489 | 83/01/28 | 50-454 Q |
| 8302150527 | 8302150477 | 83/02/08 | 50-324 Q | 8302150528 | 8302150728 | 83/01/03 | CONTRACT |
| 8302150530 | 8302150519 | 83/02/07 | 0A999 | 8302150529 | 8302150756 | 83/01/11 | State Prog |
| 8302150532 | 8302150521 | 83/01/26 | 50-263 Q | 8302150540 | 8302150756 | 83/01/21 | State Prog |
| 8302150534 | 8302150514 | 83/01/25 | 50-155 Q | 8302150509 | 8302160006 | 83/01/04 | CONTRACT |
| 8302150535 | 8302150523 | 83/01/19 | 50-338 Q | 8302160037 | 8302160029 | 83/02/04 | CONTRACT |
| 8302150536 | 8302150524 | 83/01/31 | 50-327 S | 8302160041 | 8302160034 | 83/01/04 | 50-375 P |
| 8302150537 | 8302150477 | 83/01/24 | 50-324 Q | 8302160046 | 8302160034 | 83/01/04 | 50-375 P |
| 8302150540 | 8302150519 | 83/02/09 | 0A999 | 8302160091 | 8302160034 | 83/02/04 | 50-395 P |
| 8302150541 | 8302150523 | 83/01/19 | 50-338 Q | 8302160054 | 8302160043 | 83/02/02 | 50-282 P |
| 8302150546 | 8302150519 | 83/02/09 | 0A999 | 8302160054 | 8302160050 | 83/02/07 | 50-347 P |
| 8302150549 | 8302150539 | 83/02/03 | 50-366 S | 8302160057 | 8302160043 | 83/01/02 | 50-282 P |
| 8302150551 | 8302150543 | 83/01/31 | 50-245 Q | 8302160060 | 8302160050 | 83/01/07 | 50-338 P |
| 8302150556 | 8302150519 | 83/02/09 | 0A999 | 8302160061 | 8302160013 | 83/01/02 | 50-282 P |
| 8302150557 | 8302150545 | 83/02/09 | 50-454 Q | 8302160064 | 8302160050 | 83/01/07 | 50-347 P |
| 8302150558 | 8302150523 | 83/01/19 | 50-338 Q | 8302160104 | 8302160098 | 83/01/27 | 50-289 T |
| 8302150559 | 8302150543 | 83/01/31 | 50-245 Q | 8302160110 | 8302160105 | 83/02/03 | 50-437 A |
| 8302150561 | 8302150519 | 83/02/09 | 0A999 | 8302160144 | 8302160139 | 83/01/07 | 50-416 P |
| 8302150563 | 8302150523 | 83/01/19 | 50-338 Q | 8302160116 | 8302160137 | 83/01/07 | 50-416 P |
| 8302150564 | 8302150555 | 83/01/27 | 50-361 S | 8302160150 | 8302160137 | 83/01/07 | 50-416 P |
| 8302150566 | 8302150553 | 83/01/28 | 50-361 S | 8302160158 | 8302160151 | 83/01/04 | 50-265 S |
| 8302150568 | 8302150544 | 83/02/04 | 50-328 S | 8302160159 | 8302160151 | 83/01/01 | 50-271 S |
| 8302150569 | 8302150519 | 83/02/09 | 0A999 | 8302160171 | 8302160169 | 83/02/11 | 50-313 F |
| 8302150570 | 8302150523 | 83/01/19 | 50-338 Q | 8302160177 | 8302160173 | 83/01/07 | 50-275 S |
| 8302150573 | 8302150562 | 83/01/18 | 50-482 Q | 8302160182 | 8302160176 | 83/01/11 | 50-454 T |
| 8302150577 | 8302150553 | 83/01/28 | 50-361 S | 8302160188 | 8302160176 | 83/01/15 | 50-454 T |
| 8302150583 | 8302150571 | 83/01/27 | 50-361 S | 8302160194 | 8302160176 | 83/01/19 | 50-454 T |
| 8302150581 | 8302150573 | 82/11/18 | 50-424 Q | 8302160199 | 8302160190 | 83/01/04 | 50-237 S |
| 8302150582 | 8302150565 | 83/02/09 | 50-128 Q | 8302160201 | 8302160192 | 83/01/10 | 50-440 Q |
| 8302150585 | 8302150578 | 83/02/07 | 50-280 Q | 8302160203 | 8302160176 | 83/01/15 | 50-154 T |
| 8302150589 | 8302150578 | 83/02/07 | 50-280 Q | 8302160207 | 8302160192 | 83/01/10 | 50-440 Q |
| 8302150591 | 8302150575 | 82/11/18 | 50-424 Q | 8302160212 | 8302160176 | 83/01/15 | 50-454 T |
| 8302150592 | 8302150578 | 83/02/07 | 50-280 Q | 8302160216 | 8302160207 | 83/01/07 | 50-413 Q |
| 8302150593 | 8302150574 | 83/02/03 | 50-267 S | 8302160226 | 8302160207 | 83/01/04 | 50-237 S |
| 8302150595 | 8302150584 | 83/02/09 | 50-395 S | 8302160227 | 8302160223 | 83/01/10 | 50-454 Q |
| 8302150599 | 8302150578 | 83/02/07 | 50-280 Q | 8302160228 | 8302160222 | 83/02/09 | 50-321 R |
| 8302150603 | 8302150590 | 83/02/07 | 50-289 Q | 8302160239 | 8302160215 | 83/01/07 | 50-397 P |
| 8302150604 | 8302150594 | 83/02/07 | 50-335 S | 8302160242 | 8302160236 | 83/01/04 | 50-269 P |
| 8302150606 | 8302150603 | 83/02/01 | 50-237 R | 8302160244 | 8302160240 | 83/01/04 | 50-271 R |
| 8302150607 | 8302150598 | 82/11/09 | 50-389 Q | 8302160257 | 8302160247 | 83/01/04 | 50-255 R |
| 8302150614 | 8302150609 | 82/12/17 | 50-302 Q | 8302160254 | 8302160248 | 83/01/10 | 50-321 P |
| 8302150619 | 8302150608 | 83/01/31 | 50-269 Q | 8302160255 | 8302160250 | 83/01/08 | 50-255 S |
| 8302150622 | 8302150618 | 83/01/28 | 50-267 P | 8302160256 | 8302160249 | 83/01/11 | 50-361 P |
| 8302150624 | 8302150613 | 83/02/07 | 50-395 S | 8302160266 | 8302160261 | 83/01/09 | 50-244 P |
| 8302150627 | 8302150611 | 83/01/19 | 50-321 Q | 8302160272 | 8302160268 | 83/01/08 | 50-316 S |
| 8302150629 | 8302150620 | 83/02/07 | 50-244 P | 8302160273 | 8302160270 | 83/01/09 | 50-289 Q |
| 8302150630 | 8302150618 | 83/01/28 | 50-267 P | 8302160279 | 8302160268 | 83/01/08 | 50-316 S |
| 8302150631 | 8302150623 | 83/02/03 | 50-272 P | 8302160285 | 8302160268 | 83/01/09 | 50-316 S |
| 8302150633 | 8302150620 | 83/02/09 | 50-244 P | 8302160286 | 8302160280 | 83/01/11 | 50-331 Q |
| 8302150640 | 8302150611 | 83/01/19 | 50-321 Q | 8302160294 | 8302160290 | 83/01/14 | 0A999 |
| 8302150641 | 8302150639 | 83/02/07 | 50-416 S | 8302160298 | 8302160290 | 83/01/14 | 0A999 |
| 8302150645 | 8302150636 | 83/01/07 | 50-413 Q | 8302160299 | 8302160292 | 83/02/11 | 50-341 Q |
| 8302150646 | 8302150611 | 83/01/19 | 50-321 Q | 8302160300 | 8302160294 | 83/02/14 | 50-416 P |
| 8302150650 | 8302150642 | 83/02/04 | 50-324 R | 8302160311 | 8302160306 | 83/02/08 | 50-247 Q |
| 8302150652 | 8302150611 | 83/01/19 | 50-321 Q | 8302160312 | 8302160284 | 83/02/11 | 50-315 Q |
| 8302150655 | 8302150632 | 83/02/10 | 50-327 Q | 8302160314 | 8302160305 | 83/02/09 | TOPRLP |
| 8302150657 | 8302150647 | 83/02/08 | 50-373 F | 8302160315 | 8302160307 | 83/01/28 | 0A999 |
| 8302150659 | 8302150611 | 83/01/19 | 50-321 Q | 8302160316 | 8302160305 | 83/02/09 | TOPRLP |
| 8302150662 | 8302150639 | 83/01/12 | 50-390 Q | 8302160318 | 8302160306 | 83/02/08 | 50-247 Q |
| 8302150663 | 8302150632 | 83/02/10 | 50-327 Q | 8302160320 | 8302160305 | 83/02/07 | TOPRLP |
| 8302150665 | 8302150661 | 83/01/07 | 50-369 Q | 8302160327 | 8302160325 | 83/01/28 | 0A999 |
| 8302150666 | 8302150656 | 83/02/03 | 50-375 S | 8302160330 | 8302160317 | 83/02/10 | 50-289 Q |
| 8302150670 | 8302150632 | 83/02/10 | 50-327 Q | 8302160331 | 8302160325 | 83/01/28 | 0A999 |
| 8302150676 | 8302150659 | 83/01/25 | 50-369 Q | 8302160334 | 8302160333 | 83/01/28 | 0A999 |
| 8302150678 | 8302150632 | 83/02/10 | 50-327 Q | 8302160337 | 8302160335 | 83/02/08 | 50-315 S |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

531

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | |
|------------------|--------------------|-------------|------------------|----|------------------|--------------------|-------------|------------------|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8302160338 | 8302160284 | 83/02/11 | 50-315 | Q | 8302170181 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160339 | 8302160333 | 83/01/28 | 0A999 | | 8302170183 | 8302170177 | 83/02/09 | 50-325 | S |
| 8302160340 | 8302160335 | 83/02/08 | 50-315 | S | 8302170184 | 8302170178 | 83/02/09 | 50-324 | S |
| 8302160341 | 8302160323 | 83/02/09 | 50-443 | O | 8302170189 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160342 | 8302160335 | 83/02/08 | 50-315 | S | 8302170191 | 8302170187 | 83/02/04 | 50-373 | K |
| 8302160349 | 8302160347 | 83/02/15 | 70-143 | | 8302170192 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160368 | 8302160329 | 83/02/09 | 50-443 | O | 8302170193 | 8302170196 | 83/02/09 | 50-334 | P |
| 8302160378 | 8302160373 | 83/02/11 | 50-382 | A | 8302170195 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160380 | 8302160377 | 83/02/10 | 50-305 | R | 8302170196 | 8302170196 | 83/02/09 | 50-334 | P |
| 8302160381 | 8302160376 | 83/02/07 | 50-255 | S | 8302170197 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160392 | 8302160389 | 83/02/10 | 50-220 | P | 8302170200 | 8302170190 | 83/02/09 | 50-328 | S |
| 8302160397 | 8302160393 | 83/01/24 | 70-1201 | | 8302170202 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160406 | 8302160404 | 83/02/03 | GEN TEC | IS | 8302170204 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160410 | 8302160408 | 83/02/07 | 50-410 | F | 8302170210 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160413 | 8302160411 | 82/12/16 | 40-8786 | | 8302170212 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160454 | 8302160450 | 83/01/25 | 40-8502 | | 8302170217 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160460 | 8302160457 | 83/01/12 | 50-206 | Q | 8302170218 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160476 | 8302160474 | 83/02/04 | 50-334 | F | 8302170223 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160479 | 8302160474 | 83/02/04 | 50-334 | F | 8302170226 | 8302170220 | 83/02/09 | 50-339 | S |
| 8302160484 | 8302160483 | 83/02/03 | 50-528 | H | 8302170227 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160488 | 8302160483 | 83/02/03 | 50-528 | H | 8302170229 | 8302170225 | 83/02/04 | 50-259 | F |
| 8302160491 | 8302160485 | 83/01/10 | CONTRACT | | 8302170231 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160502 | 8302160497 | 83/01/04 | CONTRACT | | 8302170235 | 8302170011 | 83/02/02 | 50-322 | A |
| 8302160506 | 8302160504 | 83/01/31 | 40-299 | | 8302170237 | 8302170232 | 83/02/04 | 50-368 | S |
| 8302160509 | 8302160507 | 83/01/03 | CONTRACT | | 8302170240 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302160510 | 8302160508 | 83/01/28 | 40-8064 | | 8302170243 | 8302170239 | 83/02/04 | 50-280 | Q |
| 8302170014 | 8302170012 | 83/01/31 | 40-8452 | | 8302170244 | 8302170241 | 83/02/10 | 50-395 | S |
| 8302170017 | 8302170015 | 83/01/25 | 40-8697 | | 8302170255 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170021 | 8302170020 | 83/01/25 | 40-8380 | | 8302170262 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170025 | 8302170011 | 83/02/02 | 50-322 | A | 8302170265 | 8302170260 | 83/02/14 | 50-247 | T |
| 8302170026 | 8302170023 | 83/01/25 | WASTE MGT | | 8302170270 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170034 | 8302170011 | 83/02/02 | 50-322 | A | 8302170276 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170035 | 8302170031 | 83/02/01 | WASTE MGT | | 8302170280 | 8302170277 | 83/02/10 | 50-247 | T |
| 8302170040 | 8302170030 | 83/02/04 | 50-261 | P | 8302170282 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170043 | 8302170039 | 83/02/01 | WASTE MGT | | 8302170285 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170047 | 8302170042 | 83/02/14 | 50-369 | P | 8302170287 | 8302170283 | 83/02/14 | 50-247 | T |
| 8302170054 | 8302170046 | 83/01/24 | 50-285 | Q | 8302170289 | 8302170284 | 83/02/11 | 50-443 | G |
| 8302170056 | 8302170052 | 83/02/04 | 50-341 | A | 8302170290 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170061 | 8302170011 | 83/02/02 | 50-322 | A | 8302170293 | 8302170019 | 83/01/18 | 50-155 | P |
| 8302170061 | 8302170046 | 83/01/24 | 50-285 | Q | 8302170297 | 8302170291 | 83/02/09 | 50-373 | Q |
| 8302170068 | 8302170064 | 83/02/03 | 50-313 | S | 8302170298 | 8302170292 | 83/02/15 | 50-454 | T |
| 8302170070 | 8302170065 | 83/02/09 | 50-261 | R | 8302170302 | 8302170292 | 83/02/15 | 50-454 | T |
| 8302170074 | 8302170019 | 83/01/18 | 50-155 | P | 8302170304 | 8302170300 | 83/02/14 | 50-369 | Q |
| 8302170084 | 8302170074 | 83/02/10 | 50-324 | S | 8302170310 | 8302170306 | 83/02/02 | 50-247 | P |
| 8302170086 | 8302170081 | 83/02/03 | COMMISSION | | 8302170311 | 8302170308 | 83/02/11 | 50-416 | S |
| 8302170087 | 8302170083 | 83/02/16 | 50-289 | T | 8302170312 | 8302170307 | 83/02/14 | 50-413 | Q |
| 8302170089 | 8302170019 | 83/01/18 | 50-155 | P | 8302170315 | 8302170314 | 83/02/09 | 50-373 | G |
| 8302170089 | 8302170019 | 83/01/18 | 50-155 | P | 8302170317 | 8302170316 | 83/02/01 | 50-3 | F |
| 8302170090 | 8302170083 | 83/02/16 | 50-289 | T | 8302170320 | 8302170318 | 83/02/11 | 50-416 | S |
| 8302170096 | 8302170019 | 83/01/18 | 50-155 | P | 8302170321 | 8302170319 | 83/02/07 | 50-409 | P |
| 8302170097 | 8302170092 | 83/02/11 | 50-322 | Q | 8302170323 | 8302170319 | 83/02/07 | 50-409 | P |
| 8302170099 | 8302170092 | 83/02/11 | 50-322 | Q | 8302170324 | 8302170322 | 83/02/11 | 50-416 | S |
| 8302170101 | 8302170093 | 83/02/09 | 50-324 | B | 8302170325 | 8302170319 | 83/02/07 | 50-409 | P |
| 8302170104 | 8302170011 | 83/02/02 | 50-322 | A | 8302170326 | 8302170319 | 83/02/07 | 50-409 | P |
| 8302170109 | 8302170011 | 83/02/02 | 50-322 | A | 8302170330 | 8302170329 | 83/02/14 | 50-277 | P |
| 8302170110 | 8302170019 | 83/01/18 | 50-155 | P | 8302170340 | 8302170338 | 83/02/15 | 50-440 | K |
| 8302170111 | 8302170105 | 83/02/07 | 50-289 | P | 8302170347 | 8302170345 | 83/02/03 | 50-237 | P |
| 8302170114 | 8302170019 | 83/01/18 | 50-155 | P | 8302170348 | 8302170343 | 83/02/10 | 50-259 | S |
| 8302170118 | 8302170019 | 83/01/18 | 50-155 | P | 8302170349 | 8302170344 | 83/02/07 | 50-267 | S |
| 8302170119 | 8302170115 | 83/02/07 | 50-302 | F | 8302170354 | 8302170346 | 83/02/11 | 50-416 | S |
| 8302170123 | 8302170019 | 83/01/18 | 50-155 | P | 8302170357 | 8302170353 | 83/01/31 | 50-445 | Q |
| 8302170127 | 8302170121 | 83/02/11 | 50-416 | S | 8302170359 | 8302170353 | 83/01/31 | 50-445 | Q |
| 8302170129 | 8302170019 | 83/01/18 | 50-155 | P | 8302170362 | 8302170358 | 83/02/11 | 50-416 | S |
| 8302170132 | 8302220461 | 83/02/10 | 10CFR | | 8302170364 | 8302170353 | 83/01/31 | 50-445 | Q |
| 8302170135 | 8302170131 | 83/02/09 | 50-335 | S | 8302170371 | 8302170363 | 83/02/08 | 50-280 | S |
| 8302170136 | 8302170133 | 83/02/01 | 50-368 | S | 8302170375 | 8302170365 | 83/02/08 | 50-280 | S |
| 8302170144 | 8302170140 | 83/02/15 | 50-369 | P | 8302170376 | 8302170373 | 83/02/04 | 50-312 | R |
| 8302170146 | 8302170141 | 83/02/09 | 50-327 | S | 8302170377 | 8302170372 | 83/02/03 | 50-368 | S |
| 8302170148 | 8302170142 | 83/02/10 | 50-296 | S | 8302170381 | 8302170380 | 83/02/07 | 50-334 | P |
| 8302170155 | 8302170153 | 83/02/09 | 50-266 | R | 8302170385 | 8302170380 | 83/02/07 | 50-334 | P |
| 8302170158 | 8302170152 | 83/02/09 | 50-339 | S | 8302170387 | 8302170384 | 83/02/07 | CONTRACT | |
| 8302170160 | 8302170154 | 83/02/11 | 50-335 | S | 8302170394 | 8302170390 | 83/02/04 | 50-320 | P |
| 8302170161 | 8302170019 | 83/01/18 | 50-155 | P | 8302170395 | 8302170392 | 83/02/04 | 50-320 | P |
| 8302170163 | 8302170159 | 83/02/09 | 50-295 | R | 8302170397 | 8302170393 | 83/02/04 | 50-320 | P |
| 8302170168 | 8302170164 | 83/02/08 | TQPREP | | 8302170399 | 8302170398 | 83/02/03 | 50-395 | P |
| 8302170169 | 8302170019 | 83/01/18 | 50-155 | P | 8302170401 | 8302170398 | 83/02/03 | 50-395 | P |
| 8302170170 | 8302170165 | 83/02/08 | 50-260 | P | 8302170402 | 8302170398 | 83/02/03 | 50-395 | P |
| 8302170174 | 8302170164 | 83/02/08 | TQPREP | | 8302170416 | 8302170412 | 83/02/07 | 50-315 | P |
| 8302170176 | 8302170019 | 83/01/18 | 50-155 | P | 8302170423 | 8302170412 | 83/02/07 | 50-315 | P |
| 8302170179 | 8302170175 | 83/02/14 | 50-445 | K | 8302170424 | 8302170421 | 83/02/09 | CONTRACT | |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302170428 | 8302170412 | 83/02/07 | 50-315 P | 8302180125 | 8302180031 | 83/01/11 | FOIA |
| 8302170429 | 8302170425 | 83/02/09 | CONTRACT | 8302180126 | 8302180102 | 83/02/19 | 50-10 F |
| 8302170435 | 8302170431 | 83/02/10 | NURE | 8302180130 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170438 | 8302170431 | 83/02/10 | NURE | 8302180131 | 8302180031 | 83/01/11 | FOIA |
| 8302170455 | 8302170449 | 83/02/15 | 50-382 F | 8302180132 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170459 | 8302170440 | 83/02/07 | 50-334 P | 8302180135 | 8302180031 | 83/01/11 | FOIA |
| 8302170461 | 8302170449 | 83/02/15 | 50-382 F | 8302180137 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170472 | 8302170440 | 83/02/07 | 50-334 P | 8302180140 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170489 | 8302170484 | 83/02/09 | CONTRACT | 8302180141 | 8302180031 | 83/01/11 | FOIA |
| 8302170490 | 8302170485 | 83/02/15 | 50-387 F | 8302180142 | 8302180136 | 83/02/11 | 50-443 Q |
| 8302170497 | 8302170485 | 83/02/15 | 50-387 F | 8302180143 | 8302180139 | 83/02/15 | 50-263 P |
| 8302170498 | 8302170494 | 83/02/15 | 50-528 F | 8302180144 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170503 | 8302170494 | 83/02/15 | 50-528 F | 8302180146 | 8302180139 | 83/02/15 | 50-263 P |
| 8302170506 | 8302170500 | 83/01/31 | 50-324 F | 8302180147 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170513 | 8302170502 | 83/02/02 | 50-333 F | 8302180148 | 8302180031 | 83/01/11 | FOIA |
| 8302170514 | 8302170510 | 83/02/09 | 50-331 P | 8302180151 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170517 | 8302170507 | 83/02/15 | 50-313 F | 8302180154 | 8302180149 | 83/02/07 | 50-312 R |
| 8302170519 | 8302170510 | 83/02/09 | 50-331 P | 8302180155 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170523 | 8302170510 | 83/02/09 | 50-331 F | 8302180156 | 8302180102 | 83/02/15 | 50-10 F |
| 8302170540 | 8302170536 | 83/02/08 | CONTRACT | 8302180158 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170548 | 8302170544 | 83/02/15 | 50-285 F | 8302180159 | 8302180152 | 83/02/10 | 50-295 B |
| 8302170549 | 8302170545 | 83/02/09 | CONTRACT | 8302180160 | 8302180066 | 82/12/27 | 50-358 A |
| 8302170571 | 8302170565 | 83/02/10 | CONTRACT | 8302180162 | 8302180031 | 83/01/11 | FOIA |
| 8302180010 | 8302180007 | 83/02/14 | 50-317 F | 8302180164 | 8302180066 | 82/12/27 | FOIA |
| 8302180012 | 8302180007 | 83/02/14 | 50-317 F | 8302180167 | 8302180031 | 83/01/11 | FOIA |
| 8302180020 | 8302180014 | 83/02/09 | 50-373 Q | 8302180169 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180023 | 8302180014 | 83/02/09 | 50-373 Q | 8302180170 | 8302180166 | 83/01/19 | 70-1257 |
| 8302180025 | 8302180018 | 83/02/14 | 50-289 F | 8302180171 | 8302180165 | 83/02/08 | 50-322 Q |
| 8302180029 | 8302180026 | 83/02/07 | 50-387 P | 8302180172 | 8302180166 | 83/01/19 | 70-1257 |
| 8302180034 | 8302180026 | 83/02/07 | 50-387 P | 8302180173 | 8302180168 | 83/02/11 | 70-1193 |
| 8302180035 | 8302180031 | 83/01/11 | FOIA | 8302180175 | 8302180163 | 83/02/03 | 50-275 B |
| 8302180037 | 8302180026 | 83/02/07 | 50-387 P | 8302180177 | 8302180031 | 83/01/11 | FOIA |
| 8302180038 | 8302180030 | 83/02/14 | 50-315 F | 8302180179 | 8302180031 | 83/01/11 | FOIA |
| 8302180039 | 8302180031 | 83/01/11 | FOIA | 8302180181 | 8302180031 | 83/01/11 | FOIA |
| 8302180041 | 8302180031 | 83/01/11 | FOIA | 8302180182 | 8302180176 | 83/02/10 | 50-289 Q |
| 8302180042 | 8302180030 | 83/02/14 | 50-315 F | 8302180184 | 8302180174 | 83/02/10 | 50-245 Q |
| 8302180044 | 8302180031 | 83/01/11 | FOIA | 8302180185 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180047 | 8302180031 | 83/01/11 | FOIA | 8302180187 | 8302180031 | 83/01/11 | FOIA |
| 8302180049 | 8302180045 | 83/01/31 | REGRO | 8302180188 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180050 | 8302180046 | 83/02/14 | 50-317 F | 8302180189 | 8302180031 | 83/01/11 | FOIA |
| 8302180052 | 8302180014 | 83/02/09 | 50-373 Q | 8302180194 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180056 | 8302180054 | 83/02/02 | 50-305 P | 8302180196 | 8302180031 | 83/01/11 | FOIA |
| 8302180058 | 8302180014 | 83/02/09 | 50-373 Q | 8302180197 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180059 | 8302180031 | 83/01/11 | FOIA | 8302180200 | 8302180193 | 83/02/04 | 50-423 Q |
| 8302180061 | 8302180055 | 83/02/14 | 50-298 F | 8302180201 | 8302180031 | 83/01/11 | FOIA |
| 8302180062 | 8302180031 | 83/01/11 | FOIA | 8302180205 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180065 | 8302180014 | 83/02/09 | 50-373 Q | 8302180206 | 8302180195 | 83/02/09 | 50-266 B |
| 8302180067 | 8302180031 | 83/01/11 | FOIA | 8302180207 | 8302180031 | 83/01/11 | FOIA |
| 8302180069 | 8302180064 | 83/02/14 | 50-346 F | 8302180208 | 8302180204 | 83/02/03 | 50-440 Q |
| 8302180070 | 8302180066 | 82/12/27 | 50-358 A | 8302180211 | 8302180066 | 82/12/27 | 50-358 A |
| 8302180071 | 8302180031 | 83/01/11 | FOIA | 8302180212 | 8302180031 | 83/01/11 | FOIA |
| 8302180073 | 8302180064 | 83/02/14 | 50-346 F | 8302180213 | 8302180204 | 83/02/03 | 50-440 Q |
| 8302180074 | 8302180066 | 82/12/27 | 50-358 T | 8302180216 | 8302180031 | 83/01/11 | FOIA |
| 8302180075 | 8302180031 | 83/01/11 | FOIA | 8302180218 | 8302180209 | 83/02/10 | 50-113 Q |
| 8302180076 | 8302180066 | 82/12/27 | 50-358 D | 8302180221 | 8302180031 | 83/01/11 | FOIA |
| 8302180081 | 8302180031 | 83/01/11 | FOIA | 8302180225 | 8302180222 | 83/02/04 | 50-387 Q |
| 8302180082 | 8302180077 | 83/02/14 | 50-219 F | 8302180230 | 8302180224 | 83/02/11 | 50-316 B |
| 8302180083 | 8302180066 | 82/12/27 | 50-358 A | 8302180232 | 8302180229 | 83/02/04 | 50-247 Q |
| 8302180084 | 8302180031 | 83/01/11 | FOIA | 8302180234 | 8302180231 | 83/02/08 | 50-361 B |
| 8302180085 | 8302180066 | 82/12/27 | 50-358 Q | 8302180236 | 8302180229 | 83/02/04 | 50-247 Q |
| 8302180086 | 8302180031 | 83/01/11 | FOIA | 8302180238 | 8302180226 | 83/02/11 | 50-316 B |
| 8302180087 | 8302180077 | 83/02/14 | 50-219 F | 8302180239 | 8302180237 | 83/02/08 | 50-361 B |
| 8302180088 | 8302180031 | 83/01/11 | FOIA | 8302180241 | 8302180235 | 83/02/07 | 50-5 Q |
| 8302180089 | 8302180066 | 82/12/27 | 50-358 Q | 8302180254 | 8302180249 | 83/02/02 | 50-317 Q |
| 8302180091 | 8302180066 | 82/12/27 | 50-358 Q | 8302180259 | 8302180249 | 83/02/02 | 50-317 Q |
| 8302180092 | 8302180031 | 83/01/11 | FOIA | 8302180262 | 8302180031 | 83/01/11 | FOIA |
| 8302180095 | 8302180031 | 83/01/11 | FOIA | 8302180264 | 8302180258 | 83/02/02 | 70-371 |
| 8302180096 | 8302180090 | 83/02/14 | 50-395 F | 8302180269 | 8302180257 | 83/02/02 | 50-317 B |
| 8302180099 | 8302180090 | 83/02/14 | 50-395 F | 8302180271 | 8302180031 | 83/01/11 | FOIA |
| 8302180101 | 8302180094 | 83/02/01 | 50-341 Q | 8302180274 | 8302180031 | 83/01/11 | FOIA |
| 8302180104 | 8302180094 | 83/02/01 | 50-341 Q | 8302180278 | 8302180031 | 83/01/11 | FOIA |
| 8302180106 | 8302180093 | 83/02/11 | 50-443 Q | 8302180281 | 8302180277 | 83/02/11 | 50-275 R |
| 8302180110 | 8302180031 | 83/01/11 | FOIA | 8302180282 | 8302180273 | 83/02/04 | 50-387 B |
| 8302180111 | 8302180066 | 82/12/27 | 50-358 A | 8302180285 | 8302180276 | 83/02/07 | 50-316 B |
| 8302180113 | 8302180031 | 83/01/11 | FOIA | 8302180286 | 8302180031 | 83/01/11 | FOIA |
| 8302180115 | 8302180066 | 82/12/27 | 50-358 A | 8302180288 | 8302180031 | 83/01/11 | FOIA |
| 8302180117 | 8302180031 | 83/01/11 | FOIA | 8302180289 | 8302180283 | 83/02/03 | 50-309 Q |
| 8302180120 | 8302180066 | 82/12/27 | 50-358 A | 8302180290 | 8302180287 | 83/02/11 | 50-321 P |
| 8302180121 | 8302180031 | 83/01/11 | FOIA | 8302180293 | 8302180031 | 83/01/11 | FOIA |
| 8302180124 | 8302180066 | 82/12/27 | 50-358 A | 8302180297 | 8302180031 | 83/01/11 | FOIA |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

533

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | |
|------------------|--------------------|-------------|------------------|---|------------------|--------------------|-------------|------------------|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8302180298 | 8302180292 | 83/02/07 | 50-244 | S | 8302180513 | 8302180512 | 83/02/07 | CONTRACT | |
| 8302180301 | 8302180031 | 83/01/11 | FOIA | | 8302180516 | 8302180515 | 83/01/28 | CONTRACT | |
| 8302180302 | 8302180295 | 83/02/14 | 50-443 | Q | 8302180519 | 8302180501 | 83/02/10 | CONTRACT | |
| 8302180304 | 8302180031 | 83/01/11 | FOIA | | 8302180520 | 8302180518 | 83/02/15 | 50-295 | F |
| 8302180306 | 8302180300 | 83/02/07 | 50-333 | S | 8302180524 | 8302180522 | 82/11/16 | WASTE NOT | |
| 8302180307 | 8302180031 | 83/01/11 | FOIA | | 8302180525 | 8302180523 | 82/12/15 | CONTRACT | |
| 8302180311 | 8302180031 | 83/01/11 | FOIA | | 8302180538 | 8302180537 | 83/02/09 | 71-6642 | |
| 8302180312 | 8302180305 | 83/02/02 | 50-244 | Q | 8302180541 | 8302180518 | 83/02/15 | 50-295 | F |
| 8302180314 | 8302180308 | 83/02/14 | 50-443 | Q | 8302220003 | 8302220001 | 82/08/30 | 50-390 | A |
| 8302180315 | 8302180031 | 83/01/11 | FOIA | | 8302220005 | 8302220006 | 83/02/07 | 50-321 | P |
| 8302180318 | 8302180031 | 83/01/11 | FOIA | | 8302220025 | 8302220020 | 83/02/08 | CONTRACT | |
| 8302180319 | 8302180316 | 83/02/15 | 50-349 | R | 8302220027 | 8302220023 | 83/02/18 | 50-454 | T |
| 8302180323 | 8302180031 | 83/01/11 | FOIA | | 8302220040 | 8302220032 | 83/02/14 | 50-369 | F |
| 8302180325 | 8302180317 | 83/02/04 | 50-387 | S | 8302220042 | 8302220036 | 83/02/09 | CONTRACT | |
| 8302180326 | 8302180031 | 83/01/11 | FOIA | | 8302220047 | 8302220032 | 83/02/14 | 50-369 | F |
| 8302180331 | 8302180031 | 83/01/11 | FOIA | | 8302220054 | 8302220050 | 82/12/30 | FOIA | |
| 8302180332 | 8302180327 | 83/02/15 | 50-302 | R | 8302220055 | 8302220052 | 83/02/14 | 50-269 | F |
| 8302180333 | 8302180324 | 83/02/10 | 50-837 | B | 8302220057 | 8302220053 | 83/02/15 | 50-285 | F |
| 8302180335 | 8302180031 | 83/01/11 | FOIA | | 8302220058 | 8302220050 | 82/12/30 | FOIA | |
| 8302180337 | 8302180330 | 83/02/08 | 50-244 | S | 8302220059 | 8302220052 | 82/12/14 | 50-269 | F |
| 8302180338 | 8302180334 | 83/02/14 | 50-277 | R | 8302220063 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180340 | 8302180031 | 83/01/11 | FOIA | | 8302220066 | 8302220061 | 83/02/15 | 50-298 | F |
| 8302180341 | 8302180031 | 83/01/11 | FOIA | | 8302220067 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180345 | 8302180031 | 83/01/11 | FOIA | | 8302220071 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180347 | 8302180031 | 83/01/11 | FOIA | | 8302220073 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180348 | 8302180346 | 83/02/14 | 50-410 | M | 8302220074 | 8302220068 | 83/02/09 | CONTRACT | |
| 8302180350 | 8302180031 | 83/01/11 | FOIA | | 8302220076 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180352 | 8302180351 | 83/02/11 | 50-261 | P | 8302220079 | 8302220075 | 83/02/09 | 70-1113 | |
| 8302180356 | 8302180354 | 83/02/14 | 50-358 | A | 8302220080 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180357 | 8302180355 | 83/02/11 | 50-443 | Q | 8302220082 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180361 | 8302180360 | 83/02/11 | 50-443 | Q | 8302220086 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180366 | 8302180364 | 83/02/14 | 50-461 | Q | 8302220087 | 8302220072 | 83/02/14 | 50-369 | F |
| 8302180368 | 8302180031 | 83/01/11 | FOIA | | 8302220089 | 8302220050 | 83/02/30 | 50-142 | Q |
| 8302180369 | 8302180353 | 83/02/04 | 70-124 | | 8302220090 | 8302220088 | 83/02/10 | 71-6400 | |
| 8302180370 | 8302180031 | 83/01/11 | FOIA | | 8302220091 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180371 | 8302180353 | 83/02/04 | 70-124 | | 8302220093 | 8302220072 | 83/02/14 | 50-369 | F |
| 8302180372 | 8302180031 | 83/01/11 | FOIA | | 8302220095 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180373 | 8302180031 | 83/01/11 | FOIA | | 8302220097 | 8302220094 | 83/02/10 | 71-9107 | |
| 8302180377 | 8302180374 | 83/02/15 | 50-269 | R | 8302220098 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180380 | 8302180031 | 83/01/11 | FOIA | | 8302220102 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180382 | 8302180378 | 83/02/14 | 50-329 | Q | 8302220103 | 8302220101 | 83/02/10 | 71-6441 | |
| 8302180383 | 8302180365 | 83/02/07 | 50-494 | Q | 8302220105 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180384 | 8302180381 | 83/02/14 | 50-247 | T | 8302220107 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180388 | 8302180031 | 83/01/11 | FOIA | | 8302220110 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180398 | 8302180390 | 83/02/14 | 50-329 | T | 8302220113 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180402 | 8302180399 | 83/02/10 | 50-413 | F | 8302220114 | 8302220106 | 83/02/10 | 50-278 | S |
| 8302180403 | 8302180390 | 83/02/14 | 50-329 | T | 8302220116 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180404 | 8302180031 | 83/01/11 | FOIA | | 8302220119 | 8302220050 | 82/12/30 | 50-142 | F |
| 8302180406 | 8302180400 | 83/02/14 | 50-443 | Q | 8302220122 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180411 | 8302180407 | 83/02/01 | 50-305 | Q | 8302220124 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180414 | 8302180408 | 83/02/14 | 50-142 | Q | 8302220125 | 8302220118 | 83/02/10 | 50-206 | P |
| 8302180416 | 8302180407 | 83/02/01 | 50-305 | Q | 8302220126 | 8302220121 | 83/02/08 | 50-278 | S |
| 8302180420 | 8302180407 | 83/02/01 | 50-305 | Q | 8302220130 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180423 | 8302180409 | 83/02/11 | 50-397 | Q | 8302220131 | 8302220127 | 83/02/14 | 50-348 | R |
| 8302180428 | 8302180419 | 83/02/14 | 50-352 | Q | 8302220134 | 8302220129 | 83/02/14 | 50-331 | R |
| 8302180428 | 8302180421 | 83/02/11 | 50-443 | Q | 8302220135 | 8302220050 | 82/12/30 | 50-142 | Q |
| 8302180434 | 8302180424 | 83/02/14 | 50-440 | Q | 8302220138 | 8302220133 | 83/02/10 | 50-311 | R |
| 8302180436 | 8302180430 | 83/02/11 | 50-313 | P | 8302220144 | 8302220132 | 83/02/09 | 10CFR | |
| 8302180439 | 8302180435 | 83/01/31 | 50-311 | P | 8302220149 | 8302220132 | 83/02/09 | 10CFR | |
| 8302180448 | 8302180441 | 83/02/14 | 50-280 | P | 8302220153 | 8302220146 | 83/02/08 | 70-1100 | |
| 8302180450 | 8302180443 | 83/02/02 | 50-334 | S | 8302220154 | 8302220132 | 83/02/09 | 10CFR | |
| 8302180451 | 8302180447 | 83/02/09 | 50-10 | Q | 8302220159 | 8302220157 | 83/02/08 | 50-267 | R |
| 8302180452 | 8302180449 | 83/02/10 | 50-461 | A | 8302220160 | 8302220155 | 83/02/14 | 50-245 | P |
| 8302180455 | 8302180445 | 83/02/16 | 50-237 | Q | 8302220168 | 8302220164 | 83/02/10 | 50-285 | R |
| 8302180457 | 8302180442 | 83/02/11 | 50-373 | Q | 8302220172 | 8302220165 | 83/02/11 | 50-387 | S |
| 8302180463 | 8302180458 | 83/02/15 | 50-454 | Q | 8302220177 | 8302220173 | 83/02/10 | 50-272 | R |
| 8302180464 | 8302180460 | 83/02/15 | 50-389 | R | 8302220199 | 8302220174 | 83/02/11 | 50-348 | S |
| 8302180467 | 8302180459 | 83/02/07 | 50-373 | S | 8302220203 | 8302220194 | 82/11/11 | WASTE NOT | |
| 8302180472 | 8302180469 | 83/02/15 | 50-313 | P | 8302220204 | 8302080301 | 83/02/08 | 50-10 | P |
| 8302180475 | 8302180465 | 83/02/14 | 50-443 | Q | 8302220209 | 8302080301 | 83/02/08 | 50-10 | P |
| 8302180476 | 8302180471 | 83/02/15 | 50-331 | F | 8302220280 | 8302220275 | 83/02/15 | 50-313 | P |
| 8302180478 | 8302180474 | 83/01/03 | CONTRACT | | 8302220298 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180484 | 8302180480 | 83/02/09 | 50-269 | P | 8302220304 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180493 | 8302180487 | 83/02/11 | 50-443 | Q | 8302220310 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180496 | 8302180491 | 83/02/16 | 50-237 | Q | 8302220317 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180498 | 8302180494 | 83/02/15 | 50-10 | F | 8302220321 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180499 | 8302180497 | 83/01/27 | 50-272 | P | 8302220325 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180506 | 8302180504 | 83/02/11 | 50-219 | P | 8302220328 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180508 | 8302180494 | 83/02/15 | 50-10 | F | 8302220332 | 8302220291 | 83/02/15 | 50-454 | T |
| 8302180511 | 8302180510 | 83/01/24 | 40-2259 | | 8302220336 | 8302220291 | 83/02/15 | 50-454 | T |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | | ACCESSION NUMBER | | | | |
|------------------|--------------------|-------------|------------------|---|------------------|--------------------|-------------|------------------|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8302220317 | 8302220334 | 83/02/17 | 50-361 | P | 8302220324 | 8302230238 | 83/02/16 | 50-508 | S |
| 8302220339 | 8302220334 | 83/02/17 | 50-361 | P | 8302220325 | 8302230251 | 83/02/02 | 50-312 | Q |
| 8302220345 | 8302220341 | 83/02/15 | 50-352 | S | 8302220325 | 8302230252 | 83/01/28 | 50-508 | Q |
| 8302220351 | 8302220348 | 83/02/11 | 50-293 | S | 8302220325 | 8302230253 | 83/01/28 | 50-361 | Q |
| 8302220352 | 8302220350 | 83/02/17 | 50-460 | Q | 8302220325 | 8302230254 | 83/02/07 | 50-293 | Q |
| 8302220353 | 8302220341 | 83/02/15 | 50-352 | S | 8302220326 | 8302230255 | 83/01/28 | 50-361 | Q |
| 8302220359 | 8302220347 | 83/02/16 | 50-289 | T | 8302220326 | 8302230261 | 83/02/10 | 50-312 | Q |
| 8302220361 | 8302220348 | 83/02/14 | 50-416 | S | 8302220326 | 8302230267 | 83/01/28 | 50-528 | Q |
| 8302220362 | 8302220347 | 83/02/16 | 50-289 | T | 8302220371 | 8302230261 | 83/02/10 | 50-312 | Q |
| 8302220365 | 8302220347 | 83/02/16 | 50-289 | T | 8302220372 | 8302230262 | 83/02/16 | 70-1362 | |
| 8302220367 | 8302220363 | 83/02/11 | 50-348 | S | 8302220374 | 8302230273 | 83/02/03 | 50-508 | Q |
| 8302220371 | 8302220347 | 83/02/16 | 50-289 | T | 8302220378 | 8302230273 | 83/02/03 | 50-508 | Q |
| 8302220372 | 8302220363 | 83/02/11 | 50-348 | S | 8302220383 | 8302230280 | 83/02/14 | 50-331 | S |
| 8302220375 | 8302220347 | 83/02/16 | 50-289 | T | 8302220384 | 8302230262 | 83/02/16 | 70-1362 | |
| 8302220377 | 8302220369 | 83/02/15 | 50-416 | S | 8302220392 | 8302230289 | 83/02/02 | 50-387 | S |
| 8302220381 | 8302220347 | 83/02/16 | 50-289 | T | 8302220393 | 8302230288 | 83/02/09 | 50-333 | S |
| 8302220382 | 8302220366 | 83/02/16 | 50-443 | Q | 8302220399 | 8302230295 | 83/02/03 | 50-333 | S |
| 8302220384 | 8302220379 | 83/02/11 | TOPREP | | 8302220300 | 8302230297 | 83/02/18 | 70-1257 | |
| 8302220386 | 8302220380 | 83/02/10 | 50-387 | S | 8302220302 | 8302230298 | 83/02/09 | 50-333 | S |
| 8302220387 | 8302220347 | 83/02/16 | 50-289 | T | 8302220306 | 8302230303 | 83/02/04 | 50-317 | S |
| 8302220389 | 8302220385 | 83/02/14 | 50-272 | P | 8302220307 | 8302230304 | 83/02/18 | 50-309 | P |
| 8302220392 | 8302220366 | 83/02/16 | 50-443 | Q | 8302220310 | 8302230309 | 83/02/17 | 50-298 | Q |
| 8302220395 | 8302220391 | 83/02/10 | 50-293 | S | 8302220311 | 8302230305 | 83/01/31 | 50-528 | Q |
| 8302220399 | 8302220366 | 83/02/16 | 50-443 | Q | 8302220324 | 8302230323 | 83/02/01 | 50-344 | Q |
| 8302220404 | 8302220398 | 83/02/11 | 50-387 | S | 8302220328 | 8302230326 | 83/02/15 | 50-528 | E |
| 8302220410 | 8302220407 | 83/02/15 | State Prog | | 8302220338 | 8302230333 | 83/02/09 | 50-387 | S |
| 8302220413 | 8302220408 | 83/02/14 | 50-364 | R | 8302220339 | 8302230335 | 83/02/14 | 50-382 | F |
| 8302220414 | 8302220407 | 83/02/15 | State Prog | | 8302220341 | 8302230335 | 83/02/14 | 50-382 | F |
| 8302220423 | 8302220418 | 83/02/15 | 50-269 | Q | 8302220342 | 8302230340 | 83/01/27 | 50-285 | Q |
| 8302220445 | 8302220440 | 83/01/27 | CONTRACT | | 8302220346 | 8302230340 | 83/01/27 | 50-285 | Q |
| 8302220453 | 8302220449 | 83/01/27 | CONTRACT | | 8302220348 | 8302230335 | 83/02/14 | 50-382 | F |
| 8302220459 | 8302220457 | 83/01/04 | CONTRACT | | 8302220349 | 8302230340 | 83/01/27 | 50-285 | Q |
| 8302220463 | 8302220458 | 83/02/07 | COMMISSION | | 8302220351 | 8302230347 | 83/02/14 | 50-537 | A |
| 8302220469 | 8302220466 | 83/02/03 | COMMISSION | | 8302220353 | 8302230339 | 83/02/14 | 50-382 | F |
| 8302220476 | 8302220474 | 83/01/24 | 50-522 | U | 8302220358 | 8302230335 | 83/02/14 | 50-382 | F |
| 8302220484 | 8302220482 | 83/02/09 | 70-371 | | 8302220363 | 8302230360 | 83/02/18 | 50-244 | P |
| 8302220492 | 8302220490 | 83/02/08 | 50-2 | F | 8302220367 | 8302230360 | 83/02/18 | 50-244 | P |
| 8302220517 | 8302220514 | 83/02/14 | 50-309 | Q | 8302220368 | 8302230338 | 83/02/14 | 50-382 | F |
| 8302220519 | 8302220514 | 83/02/14 | 50-309 | Q | 8302220371 | 8302230365 | 83/02/04 | 50-206 | Q |
| 8302220520 | 8302220461 | 83/02/10 | 10CFR | | 8302220372 | 8302230369 | 83/01/27 | 50-397 | Q |
| 8302220522 | 8302220525 | 83/02/08 | 50-3 | P | 8302220378 | 8302230365 | 83/02/04 | 50-206 | Q |
| 8302220526 | 8302220525 | 83/02/16 | 50-323 | H | 8302220382 | 8302230377 | 83/02/07 | 50-247 | Q |
| 8302220580 | 8302220572 | 83/02/09 | 40-8829 | | 8302220383 | 8302230374 | 83/01/26 | 50-397 | A |
| 8302220606 | 8302230605 | 83/02/03 | 50-275 | P | 8302220388 | 8302230379 | 83/01/10 | 50-275 | Q |
| 8302220609 | 8302230607 | 83/02/03 | 50-309 | F | 8302220391 | 8302230385 | 83/02/15 | 50-245 | Q |
| 8302220611 | 8302230607 | 83/02/03 | 50-309 | F | 8302220394 | 8302230377 | 83/02/07 | 50-247 | Q |
| 8302220622 | 8302230619 | 83/02/09 | 50-336 | P | 8302220399 | 8302230396 | 83/02/04 | 50-361 | Q |
| 8302220627 | 8302230619 | 83/02/09 | 50-336 | P | 8302220404 | 8302230395 | 83/02/09 | 50-361 | Q |
| 8302220629 | 8302230619 | 83/02/09 | 50-336 | P | 8302220406 | 8302230396 | 83/02/04 | 50-361 | Q |
| 8302220643 | 8302230619 | 83/02/09 | 50-336 | P | 8302220408 | 8302230403 | 83/02/17 | 50-313 | P |
| 8302220661 | 8302230655 | 83/02/10 | 70-2946 | | 8302220414 | 8302230411 | 83/02/11 | 50-259 | P |
| 8302220668 | 8302230655 | 83/02/10 | 70-2946 | | 8302220416 | 8302230409 | 83/02/02 | 50-498 | Q |
| 8302220682 | 8302230676 | 83/01/25 | 50-324 | U | 8302220418 | 8302230410 | 83/02/07 | 50-213 | Q |
| 8302220688 | 8302230676 | 83/01/25 | COMMISSION | | 8302220419 | 8302230415 | 83/02/08 | 50-255 | F |
| 8302220711 | 8302230108 | 83/02/15 | 50-327 | S | 8302220431 | 8302230424 | 83/02/16 | 50-369 | K |
| 8302220728 | 8302230122 | 83/02/09 | 50-320 | Q | 8302220433 | 8302230422 | 83/01/05 | 40-8698 | |
| 8302220729 | 8302230124 | 83/02/06 | 50-29 | S | 8302220441 | 8302230434 | 83/02/15 | 50-247 | Q |
| 8302220730 | 8302230125 | 83/02/16 | 50-10 | P | 8302220442 | 8302230430 | 83/02/18 | 50-309 | P |
| 8302220738 | 8302230137 | 83/02/16 | 50-533 | A | 8302220450 | 8302230435 | 83/02/17 | 50-322 | T |
| 8302220739 | 8302230133 | 83/02/03 | 50-387 | S | 8302220451 | 8302230443 | 83/02/16 | 50-335 | P |
| 8302220742 | 8302230135 | 83/02/09 | 50-219 | Q | 8302220457 | 8302230447 | 83/02/02 | 50-387 | S |
| 8302220747 | 8302230144 | 83/02/15 | 50-326 | Q | 8302220461 | 8302230455 | 83/02/21 | 50-454 | T |
| 8302220754 | 8302230148 | 83/02/16 | 50-508 | S | 8302220462 | 8302230452 | 83/02/14 | 50-331 | S |
| 8302220758 | 8302230156 | 83/02/15 | 50-289 | R | 8302220473 | 8302230456 | 83/02/14 | 50-368 | S |
| 8302220767 | 8302230162 | 83/02/17 | 50-317 | R | 8302220476 | 8302230463 | 83/02/03 | 50-317 | S |
| 8302220769 | 8302230166 | 83/02/18 | 50-324 | S | 8302220477 | 8302230471 | 83/02/18 | 50-247 | T |
| 8302220772 | 8302230163 | 83/02/18 | 50-312 | P | 8302220478 | 8302230472 | 83/01/27 | 50-267 | Q |
| 8302220774 | 8302230191 | 83/02/16 | QA999 | | 8302220479 | 8302230468 | 83/02/07 | 50-247 | S |
| 8302220799 | 8302230191 | 83/02/16 | QA999 | | 8302220481 | 8302230469 | 83/02/03 | 50-333 | S |
| 8302220803 | 8302230196 | 83/02/11 | 50-280 | S | 8302220484 | 8302230401 | 83/02/16 | 50-186 | R |
| 8302220804 | 8302230191 | 83/02/16 | QA999 | | 8302220494 | 8302230485 | 83/02/10 | 50-321 | S |
| 8302220809 | 8302230205 | 83/02/02 | 50-397 | S | 8302220497 | 8302230493 | 83/02/11 | 50-275 | R |
| 8302220813 | 8302230205 | 83/02/02 | 50-397 | S | 8302220498 | 8302230467 | 83/02/14 | 50-247 | Q |
| 8302220817 | 8302230210 | 83/02/10 | 50-366 | S | 8302220500 | 8302230490 | 83/02/16 | 50-344 | P |
| 8302220826 | 8302230220 | 83/02/10 | 50-397 | Q | 8302220506 | 8302230490 | 83/02/16 | 50-344 | P |
| 8302220829 | 8302230223 | 83/02/08 | 50-321 | S | 8302220509 | 8302230503 | 83/02/11 | 70-1062 | |
| 8302220833 | 8302230230 | 83/02/16 | 50-327 | S | 8302220515 | 8302230510 | 83/02/11 | 50-346 | S |
| 8302220835 | 8302230232 | 83/02/15 | 50-416 | R | 8302220517 | 8302230501 | 83/02/17 | 50-128 | Q |
| 8302220839 | 8302230231 | 83/02/15 | 50-366 | S | 8302220532 | 8302230522 | 83/02/10 | 50-245 | Q |
| 8302220840 | 8302230237 | 83/01/27 | 50-344 | Q | 8302220547 | 8302230537 | 83/02/03 | 50-333 | S |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

535

| ENCLOSURE REF | | | | ACCESSION NUMBER | | | |
|---------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302230549 | 8302230539 | 83/02/11 | 50-346 S | 8302240103 | 8302240073 | 83/01/13 | 50-284 P |
| 8302230549 | 8302230541 | 83/02/08 | 50-286 S | 8302240105 | 8302240073 | 83/01/13 | 50-284 P |
| 8302230553 | 8302230515 | 83/02/17 | 50-454 T | 8302240109 | 8302240073 | 83/01/13 | 50-284 P |
| 8302230555 | 8302230542 | 83/01/27 | 50-454 S | 8302240113 | 8302240073 | 83/01/13 | 50-284 P |
| 8302230551 | 8302230552 | 83/02/18 | 50-247 Q | 8302240115 | 8302240102 | 83/02/09 | 50-331 P |
| 8302230562 | 8302230551 | 83/02/15 | 50-328 S | 8302240120 | 8302240080 | 83/02/14 | 50-251 Q |
| 8302230563 | 8302230550 | 83/02/10 | 50-366 S | 8302240122 | 8302240110 | 83/02/17 | CONTRACT |
| 8302230564 | 8302230552 | 83/02/18 | 50-247 Q | 8302240125 | 8302240102 | 83/02/09 | 50-331 P |
| 8302230570 | 8302230556 | 83/02/04 | 50-244 S | 8302240131 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230571 | 8302230557 | 83/02/14 | 50-316 S | 8302240134 | 8302240129 | 83/02/03 | 50-344 P |
| 8302230572 | 8302230552 | 83/02/18 | 50-247 Q | 8302240138 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230574 | 8302230556 | 83/02/15 | TOPREP | 8302240143 | 8302240136 | 83/02/13 | 50-286 P |
| 8302230578 | 8302230557 | 83/02/15 | 50-260 S | 8302240144 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230579 | 8302230558 | 83/02/16 | 50-400 Q | 8302240148 | 8302240136 | 83/02/16 | 50-328 P |
| 8302230586 | 8302230559 | 83/02/04 | 50-244 S | 8302240150 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230594 | 8302230577 | 83/02/03 | 50-333 S | 8302240151 | 8302240146 | 83/02/10 | 50-387 P |
| 8302230595 | 8302230582 | 83/02/17 | 50-308 Q | 8302240154 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230596 | 8302230589 | 83/02/18 | 50-400 Q | 8302240155 | 8302240136 | 83/02/16 | 50-328 P |
| 8302230602 | 8302230598 | 83/02/14 | 50-313 Q | 8302240156 | 8302240146 | 83/02/10 | 50-387 P |
| 8302230603 | 8302230592 | 83/02/09 | 50-369 S | 8302240160 | 8302240146 | 83/02/10 | 50-387 P |
| 8302230606 | 8302230593 | 83/02/04 | 50-271 S | 8302240167 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230608 | 8302230598 | 83/02/09 | 50-354 Q | 8302240169 | 8302240169 | 83/02/15 | 50-155 P |
| 8302230613 | 8302230604 | 83/02/10 | 50-312 S | 8302240173 | 8302240073 | 83/01/13 | 50-286 P |
| 8302230616 | 8302230605 | 83/01/28 | 50-317 S | 8302240174 | 8302240163 | 83/02/15 | 50-155 P |
| 8302230621 | 8302230601 | 83/02/15 | 50-333 Q | 8302240181 | 8302240163 | 83/02/15 | 50-155 P |
| 8302230622 | 8302230609 | 83/02/15 | 50-259 S | 8302240185 | 8302240178 | 83/02/14 | CONTRACT |
| 8302230628 | 8302230618 | 83/02/15 | 50-296 S | 8302240210 | 8302240280 | 83/02/22 | 50-413 K |
| 8302230629 | 8302230620 | 83/02/15 | 50-312 P | 8302240230 | 8302240222 | 83/01/20 | 50-537 A |
| 8302230640 | 8302230637 | 83/01/19 | REVIEW GRP | 8302240233 | 8302240223 | 83/01/20 | FOIA |
| 8302230646 | 8302230611 | 83/02/02 | 50-267 R | 8302240239 | 8302240233 | 83/02/07 | COMMISSION |
| 8302230649 | 8302230630 | 83/02/17 | 50-445 Q | 8302240240 | 8302240234 | 83/02/10 | CONTRACT |
| 8302230650 | 8302230632 | 83/01/19 | REVIEW GRP | 8302240244 | 8302240241 | 83/01/14 | 70-146 |
| 8302230659 | 8302230652 | 83/02/17 | 50-247 Q | 8302240246 | 8302240241 | 83/01/14 | 70-146 |
| 8302230666 | 8302230657 | 83/02/09 | 50-275 Q | 8302240250 | 8302240223 | 83/01/20 | FOIA |
| 8302230672 | 8302230661 | 83/02/03 | 50-333 S | 8302240251 | 8302240245 | 83/02/24 | 50-325 S |
| 8302230674 | 8302230667 | 83/02/11 | 50-244 S | 8302240253 | 8302240241 | 83/01/14 | 70-146 |
| 8302230679 | 8302230677 | 83/02/15 | 50-220 Q | 8302240255 | 8302240223 | 83/01/20 | FOIA |
| 8302230686 | 8302230681 | 83/02/17 | 50-282 Q | 8302240257 | 8302240254 | 83/02/11 | 50-327 S |
| 8302230689 | 8302230684 | 83/01/31 | 50-267 Q | 8302240258 | 8302240248 | 83/02/11 | 50-321 P |
| 8302230691 | 8302230687 | 83/02/03 | 50-333 S | 8302240259 | 8302240249 | 83/02/17 | 50-277 R |
| 8302230692 | 8302230684 | 83/01/31 | 50-267 Q | 8302240263 | 8302240260 | 83/02/18 | 50-320 P |
| 8302230693 | 8302230689 | 83/02/11 | 50-267 Q | 8302240264 | 8302240248 | 83/02/11 | 50-321 P |
| 8302230697 | 8302230694 | 83/02/03 | 50-387 S | 8302240266 | 8302240261 | 83/02/11 | 50-327 S |
| 8302230699 | 8302230695 | 83/02/02 | 50-320 S | 8302240267 | 8302240262 | 83/02/14 | 50-329 A |
| 8302230701 | 8302230698 | 83/02/04 | 50-317 S | 8302240268 | 8302240248 | 83/02/11 | 50-321 P |
| 8302230705 | 8302230702 | 83/02/08 | 50-346 S | 8302240270 | 8302240223 | 83/01/20 | FOIA |
| 8302230705 | 8302230703 | 83/02/15 | 50-237 S | 8302240274 | 8302240271 | 83/02/17 | 50-320 P |
| 8302230707 | 8302230700 | 83/02/10 | 50-366 S | 8302240275 | 8302240269 | 83/02/14 | CONTRACT |
| 8302230709 | 8302230704 | 83/02/17 | 50-458 Q | 8302240277 | 8302240223 | 83/01/20 | FOIA |
| 8302230711 | 8302230705 | 83/02/16 | 50-364 S | 8302240282 | 8302240278 | 83/02/18 | 50-275 P |
| 8302230713 | 8302230712 | 83/02/15 | 50-298 S | 8302240288 | 8302240223 | 83/01/20 | FOIA |
| 8302230721 | 8302230717 | 83/02/07 | 70-2199 | 8302240292 | 8302240286 | 83/02/17 | 50-275 P |
| 8302230722 | 8302230716 | 83/02/03 | 50-318 S | 8302240293 | 8302240283 | 83/01/20 | FOIA |
| 8302230723 | 8302230715 | 83/02/04 | 50-246 S | 8302240311 | 8302240306 | 83/02/16 | 50-334 F |
| 8302230724 | 8302230718 | 83/02/17 | 50-298 Q | 8302240315 | 8302240306 | 83/02/16 | 50-334 F |
| 8302240002 | 8302240001 | 83/02/04 | XPCRTLIC | 8302240316 | 8302240312 | 83/02/02 | TOPREP |
| 8302240004 | 8302240003 | 83/02/03 | 50-389 A | 8302240318 | 8302240313 | 83/02/23 | 50-322 Q |
| 8302240005 | 8302240003 | 83/02/03 | 50-389 A | 8302240321 | 8302240313 | 83/02/23 | 50-322 Q |
| 8302240006 | 8302240003 | 83/02/03 | 50-389 A | 8302240327 | 8302240323 | 83/01/26 | WASTE MGT |
| 8302240017 | 8302240015 | 83/02/14 | 50-271 P | 8302240329 | 8302240326 | 83/02/15 | 50-213 P |
| 8302240021 | 8302240015 | 83/02/14 | 50-271 P | 8302240337 | 8302240334 | 83/02/15 | 50-282 P |
| 8302240026 | 8302240015 | 83/02/14 | 50-271 P | 8302240338 | 8302240323 | 83/01/26 | WASTE MGT |
| 8302240032 | 8302240029 | 83/02/18 | 50-333 P | 8302240344 | 8302240341 | 83/02/02 | 40-299 |
| 8302240035 | 8302240031 | 83/02/10 | 71-9044 | 8302240349 | 8302240347 | 83/01/28 | WASTE MGT |
| 8302240036 | 8302240029 | 83/02/18 | 50-333 P | 8302240358 | 8302240357 | 83/01/21 | FOIA |
| 8302240064 | 8302240059 | 83/02/22 | 50-454 T | 8302240375 | 8302240373 | 83/02/01 | XPCRTLIC |
| 8302240065 | 8302240057 | 83/01/25 | COMMISSION | 8302240390 | 8302240387 | 83/02/09 | XPCRTLIC |
| 8302240070 | 8302240059 | 83/02/22 | 50-454 T | 8302240395 | 8302240391 | 83/01/31 | CONTRACT |
| 8302240074 | 8302240059 | 83/02/22 | 50-454 T | 8302240400 | 8302240397 | 83/01/28 | 27-39 |
| 8302240075 | 8302240061 | 83/02/17 | CONTRACT | 8302240405 | 8302240402 | 83/02/08 | COMMISSION |
| 8302240078 | 8302240059 | 83/02/22 | 50-454 T | 8302250009 | 8302250003 | 83/02/16 | 50-267 F |
| 8302240079 | 8302240071 | 83/02/17 | CONTRACT | 8302250013 | 8302250004 | 83/02/08 | 50-316 P |
| 8302240082 | 8302240073 | 83/01/13 | 50-3 P | 8302250016 | 8302250003 | 83/02/16 | 50-267 F |
| 8302240083 | 8302240059 | 83/02/22 | 50-454 T | 8302250027 | 8302250023 | 83/02/18 | 50-329 Q |
| 8302240085 | 8302240083 | 83/02/14 | 50-251 Q | 8302250029 | 8302250021 | 83/02/16 | 50-387 F |
| 8302240088 | 8302240059 | 83/02/22 | 50-454 T | 8302250035 | 8302250021 | 83/02/16 | 50-387 F |
| 8302240089 | 8302240073 | 83/01/13 | 50-3 P | 8302250042 | 8302250036 | 83/02/14 | 50-443 Q |
| 8302240091 | 8302240087 | 83/02/15 | CONTRACT | 8302250047 | 8302250041 | 83/02/16 | 50-317 F |
| 8302240092 | 8302240059 | 83/02/22 | 50-454 T | 8302250055 | 8302250036 | 83/02/14 | 50-443 Q |
| 8302240095 | 8302240073 | 83/01/13 | 50-247 P | | | | |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8302250079 | 8302250074 | 83/02/14 | CONTRACT | 8302250411 | 8302250371 | 83/02/18 | 50-269 P |
| 8302250082 | 8302250073 | 83/02/16 | 50-315 F | 8302250414 | 8302250382 | 83/02/11 | 50-329 Q |
| 8302250092 | 8302250073 | 83/02/16 | 50-315 F | 8302250414 | 8302250372 | 83/02/22 | 50-247 G |
| 8302250138 | 8302250133 | 83/02/10 | 50-312 P | 8302250417 | 8302250391 | 83/02/18 | 50-269 P |
| 8302250143 | 8302250133 | 83/02/10 | 50-312 P | 8302250419 | 8302250372 | 83/02/22 | 50-247 G |
| 8302250148 | 8302250133 | 83/02/10 | 50-312 P | 8302250421 | 8302250388 | 83/02/11 | 50-329 Q |
| 8302250160 | 8302250157 | 83/02/03 | XPOR TLIC | 8302250424 | 8302250391 | 83/02/18 | 50-269 P |
| 8302250167 | 8302250164 | 83/02/22 | 50-271 P | 8302250425 | 8302250372 | 83/02/22 | 50-247 G |
| 8302250173 | 8302250168 | 83/02/10 | 50-373 S | 8302250427 | 8302250388 | 83/02/11 | 50-329 Q |
| 8302250177 | 8302250175 | 83/02/18 | 50-294 V | 8302250431 | 8302250388 | 83/02/11 | 50-329 Q |
| 8302250180 | 8302250175 | 83/02/18 | 50-294 V | 8302250433 | 8302250426 | 83/02/22 | 70-1719 |
| 8302250183 | 8302250179 | 83/02/17 | 50-254 P | 8302250435 | 8302250428 | 83/02/18 | 50-280 P |
| 8302250184 | 8302250181 | 83/02/15 | 50-319 S | 8302250436 | 8302250391 | 83/02/18 | 50-269 P |
| 8302250190 | 8302250187 | 83/02/17 | 50-295 S | 8302250440 | 8302250391 | 83/02/18 | 50-269 P |
| 8302250192 | 8302250189 | 83/02/17 | 50-237 P | 8302250442 | 8302250437 | 83/02/22 | 50-375 R |
| 8302250195 | 8302250188 | 83/02/09 | 50-318 S | 8302280003 | 8302280002 | 83/01/31 | XPOR TLIC |
| 8302250197 | 8302250193 | 83/02/17 | 50-304 S | 8302280003 | 8302280003 | 83/01/26 | XPOR TLIC |
| 8302250199 | 8302250196 | 83/02/09 | 50-317 S | 8302280042 | 8302280038 | 83/01/17 | 50-364 S |
| 8302250210 | 8302250204 | 83/02/07 | 40-86 | 8302280047 | 8302280045 | 83/02/18 | 50-335 S |
| 8302250211 | 8302250207 | 83/02/14 | 50-320 S | 8302280048 | 8302280046 | 83/01/19 | 50-298 K |
| 8302250214 | 8302250204 | 83/02/07 | 40-86 | 8302280062 | 8302280057 | 83/02/22 | 50-321 P |
| 8302250215 | 8302250209 | 83/02/07 | 50-373 S | 8302280069 | 8302280054 | 83/02/04 | 50-295 P |
| 8302250218 | 8302250212 | 83/02/17 | 50-237 P | 8302280074 | 8302280066 | 83/02/17 | 50-324 S |
| 8302250219 | 8302250204 | 83/02/07 | 40-86 | 8302280079 | 8302280071 | 83/02/22 | 50-416 S |
| 8302250221 | 8302250216 | 83/02/15 | 50-219 S | 8302280089 | 8302280082 | 83/02/15 | 50-367 S |
| 8302250224 | 8302250213 | 83/02/10 | 50-361 S | 8302280133 | 8302280121 | 83/02/24 | 50-546 A |
| 8302250226 | 8302250223 | 83/02/11 | 50-361 S | 8302280137 | 8302280121 | 83/02/24 | 50-546 K |
| 8302250228 | 8302250220 | 83/02/09 | 50-373 S | 8302280138 | 8302280131 | 83/02/17 | 50-366 S |
| 8302250239 | 8302250231 | 83/02/10 | 70-398 | 8302280139 | 8302280135 | 83/01/29 | FOIA |
| 8302250240 | 8302250235 | 83/02/23 | 50-247 T | 8302280143 | 8302280121 | 83/02/24 | 50-546 F |
| 8302250241 | 8302250238 | 83/02/16 | 50-316 S | 8302280149 | 8302280121 | 83/02/24 | 50-546 C |
| 8302250243 | 8302250237 | 83/02/15 | 50-445 Q | 8302280155 | 8302280150 | 83/02/17 | 50-327 S |
| 8302250247 | 8302250242 | 83/02/22 | 50-271 P | 8302280158 | 8302280121 | 83/02/24 | 50-546 A |
| 8302250257 | 8302250253 | 83/02/22 | 50-309 Q | 8302280162 | 8302280159 | 83/02/17 | 50-327 S |
| 8302250268 | 8302250266 | 83/02/10 | 50-352 Q | 8302280164 | 8302280151 | 83/02/17 | TCRPF |
| 8302250269 | 8302250262 | 83/02/18 | 50-409 P | 8302280176 | 8302280169 | 83/02/16 | 50-329 A |
| 8302250273 | 8302250266 | 83/02/10 | 50-352 Q | 8302280177 | 8302280172 | 83/02/24 | 50-546 M |
| 8302250283 | 8302250278 | 83/02/07 | 50-255 Q | 8302280183 | 8302280179 | 83/02/17 | 50-247 Q |
| 8302250287 | 8302250277 | 83/02/22 | 50-320 P | 8302280184 | 8302280175 | 83/02/18 | 50-260 S |
| 8302250288 | 8302250281 | 83/02/10 | 50-269 Q | 8302280191 | 8302280182 | 83/02/17 | 50-255 P |
| 8302250289 | 8302250282 | 83/02/09 | 50-334 Q | 8302280192 | 8302280188 | 83/02/22 | 50-5 R |
| 8302250296 | 8302250286 | 83/02/09 | 50-373 S | 8302280195 | 8302280182 | 83/02/17 | 50-255 P |
| 8302250300 | 8302250295 | 83/02/10 | 50-309 Q | 8302280198 | 8302280196 | 83/02/17 | 50-395 S |
| 8302250303 | 8302250293 | 83/02/17 | 50-254 Q | 8302280200 | 8302280194 | 83/02/18 | 50-327 S |
| 8302250309 | 8302250303 | 83/02/22 | 50-298 Q | 8302280201 | 8302280197 | 83/02/18 | 50-312 Q |
| 8302250311 | 8302250306 | 83/02/18 | 50-315 Q | 8302280217 | 8302280204 | 83/02/23 | 50-454 K |
| 8302250313 | 8302250307 | 83/02/09 | 50-373 S | 8302280218 | 8302280215 | 83/02/17 | 50-312 P |
| 8302250316 | 8302250319 | 83/02/10 | 70-734 | 8302280218 | 8302280215 | 83/02/17 | 50-72 R |
| 8302250317 | 8302250315 | 83/02/10 | 70-734 | 8302280222 | 8302280217 | 83/02/21 | 50-261 S |
| 8302250320 | 8302250319 | 83/02/11 | 50-398 Q | 8302280223 | 8302280207 | 83/02/17 | 50-321 S |
| 8302250331 | 8302250328 | 83/02/02 | PR | 8302280227 | 8302280221 | 83/02/17 | 50-302 S |
| 8302250333 | 8302250327 | 83/02/10 | 50-272 Q | 8302280228 | 8302280225 | 83/02/22 | 50-416 S |
| 8302250338 | 8302250334 | 83/02/09 | RC000 | 8302280234 | 8302280230 | 83/02/22 | 50-416 S |
| 8302250343 | 8302250336 | 83/02/09 | 50-412 Q | 8302280243 | 8302280235 | 83/02/18 | 50-416 S |
| 8302250352 | 8302250345 | 83/02/10 | 50-54 Q | 8302280245 | 8302280240 | 83/02/17 | 50-327 P |
| 8302250355 | 8302250348 | 83/02/10 | 50-320 Q | 8302280246 | 8302280146 | 83/02/15 | 50-366 S |
| 8302250357 | 8302250353 | 83/02/08 | PR | 8302280252 | 8302280242 | 83/02/01 | CONTRACT |
| 8302250360 | 8302250345 | 83/02/10 | 50-54 Q | 8302280254 | 8302280247 | 83/02/22 | 50-322 Q |
| 8302250361 | 8302250349 | 83/02/18 | 50-237 F | 8302280255 | 8302280251 | 83/02/25 | 50-289 Q |
| 8302250362 | 8302250359 | 83/02/09 | PR | 8302280257 | 8302280250 | 83/02/15 | 50-329 S |
| 8302250364 | 8302250358 | 83/02/08 | 50-10 Q | 8302280258 | 8302280251 | 83/02/25 | 50-289 Q |
| 8302250368 | 8302250366 | 83/02/13 | PR | 8302280260 | 8302280247 | 83/02/22 | 50-322 Q |
| 8302250373 | 8302250371 | 83/02/24 | 50-269 P | 8302280262 | 8302280256 | 83/02/22 | 50-445 A |
| 8302250379 | 8302250372 | 83/02/22 | 50-247 Q | 8302280267 | 8302280256 | 83/02/22 | 50-445 A |
| 8302250383 | 8302250372 | 83/02/22 | 50-247 Q | 8302280268 | 8302280261 | 83/02/15 | 50-302 S |
| 8302250386 | 8302250380 | 83/02/17 | 50-312 P | 8302280276 | 8302280271 | 83/02/25 | 50-389 A |
| 8302250387 | 8302250372 | 83/02/22 | 50-247 Q | 8302280278 | 8302280272 | 83/02/15 | 50-321 S |
| 8302250389 | 8302250382 | 83/02/09 | 50-271 S | 8302280282 | 8302280279 | 83/02/25 | 50-170 Q |
| 8302250392 | 8302250372 | 83/02/22 | 50-247 Q | 8302280284 | 8302280280 | 83/02/24 | 50-361 P |
| 8302250393 | 8302250388 | 83/02/11 | 50-329 Q | 8302280286 | 8302280279 | 83/02/25 | 50-170 Q |
| 8302250394 | 8302250372 | 83/02/22 | 50-247 Q | 8302280288 | 8302280280 | 83/02/24 | 50-361 P |
| 8302250397 | 8302250390 | 83/02/14 | 50-373 S | 8302280289 | 8302280283 | 83/02/18 | 50-416 S |
| 8302250399 | 8302250372 | 83/02/22 | 50-247 Q | 8302280301 | 8302280294 | 83/02/18 | 50-416 S |
| 8302250400 | 8302250391 | 83/02/18 | 50-269 P | 8302280303 | 8302280296 | 83/02/25 | 50-451 Q |
| 8302250401 | 8302250395 | 83/02/08 | 50-373 S | 8302280312 | 8302280310 | 83/02/22 | 50-266 P |
| 8302250404 | 8302250402 | 83/02/10 | 50-318 S | 8302280321 | 8302280316 | 83/02/14 | 50-254 S |
| 8302250405 | 8302250372 | 83/02/22 | 50-247 Q | 8302280327 | 8302280325 | 83/02/23 | 50-269 P |
| 8302250406 | 8302250391 | 83/02/18 | 50-269 P | 8302280337 | 8302280336 | 83/02/22 | 50-346 P |
| 8302250407 | 8302250403 | 83/02/22 | 50-271 P | 8302280340 | 8302280338 | 83/02/18 | 50-294 S |
| 8302250410 | 8302250372 | 83/02/22 | 50-247 Q | 8302280341 | 8302280339 | 83/02/10 | 50-254 Q |

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

537

| ACCESSION NUMBER | | | | ACCESSION NUMBER | | | |
|------------------|--------------------|-------------|------------------|------------------|--------------------|-------------|------------------|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 0302280346 | 0302280343 | 83/02/15 | 50-321 S | 0302280439 | 0302280426 | 83/02/14 | 50-237 Q |
| 0302280347 | 0302280342 | 83/02/24 | 50-334 R | 0302280440 | 0302280434 | 83/02/23 | 50-416 S |
| 0302280351 | 0302280345 | 83/02/17 | 50-250 S | 0302280441 | 0302280441 | 83/02/14 | 50-387 Q |
| 0302280352 | 0302280349 | 83/02/18 | 50-316 S | 0302280448 | 0302280448 | 83/02/23 | 50-416 S |
| 0302280355 | 0302280349 | 83/02/18 | 50-316 S | 0302280447 | 0302280447 | 83/02/15 | 50-313 S |
| 0302280358 | 0302280357 | 83/02/17 | 50-316 S | 0302280458 | 0302280458 | 83/02/22 | 50-416 S |
| 0302280362 | 0302280357 | 83/02/17 | 50-316 S | 0302280457 | 0302280457 | 83/02/22 | 50-327 S |
| 0302280363 | 0302280360 | 83/02/24 | 50-261 P | 0302280462 | 0302280462 | 83/02/16 | 50-155 Q |
| 0302280364 | 0302280357 | 83/02/17 | 50-316 S | 0302280467 | 0302280459 | 83/02/15 | 50-213 S |
| 0302280369 | 0302280351 | 83/02/18 | 50-259 S | 0302280461 | 0302280461 | 83/02/15 | 50-373 Q |
| 0302280374 | 0302280371 | 83/02/24 | 50-255 Q | 0302280469 | 0302280460 | 83/02/23 | 50-277 Q |
| 0302280375 | 0302280369 | 83/02/10 | 50-454 Q | 0302280471 | 0302280463 | 83/02/17 | 50-328 S |
| 0302280380 | 0302280377 | 83/02/18 | 50-247 T | 0302280474 | 0302280461 | 83/02/15 | 50-373 Q |
| 0302280381 | 0302280376 | 83/02/16 | 50-773 S | 0302280476 | 0302280470 | 83/02/18 | 50-295 S |
| 0302280383 | 0302280365 | 83/02/17 | 50-255 S | 0302280480 | 0302280473 | 83/02/23 | 50-295 S |
| 0302280384 | 0302280377 | 83/02/18 | 50-247 T | 0302280481 | 0302280472 | 83/02/22 | 50-259 S |
| 0302280385 | 0302280378 | 83/02/18 | 50-285 S | 0302280482 | 0302280478 | 83/02/10 | 50-412 Q |
| 0302280389 | 0302280382 | 83/02/17 | 50-315 S | 0302280486 | 0302280478 | 83/02/10 | 50-412 Q |
| 0302280390 | 0302280377 | 83/02/18 | 50-247 T | 0302280487 | 0302280485 | 83/02/11 | 50-454 Q |
| 0302280393 | 0302280386 | 83/02/17 | 50-255 S | 0302280491 | 0302280484 | 83/02/11 | 50-339 S |
| 0302280396 | 0302280392 | 83/02/24 | 50-346 Q | 0302280498 | 0302280494 | 83/02/10 | 50-346 Q |
| 0302280403 | 0302280398 | 83/02/24 | 50-445 Q | 0302280500 | 0302280495 | 83/02/17 | 50-390 Q |
| 0302280404 | 0302280400 | 83/02/18 | 50-295 P | 0302280501 | 0302280493 | 83/02/23 | 50-322 Q |
| 0302280405 | 0302280392 | 83/02/24 | 50-346 Q | 0302280503 | 0302280494 | 83/02/10 | 50-346 Q |
| 0302280407 | 0302280398 | 83/02/24 | 50-445 Q | 0302280505 | 0302280496 | 83/02/23 | 50-297 Q |
| 0302280408 | 0302280392 | 83/02/24 | 50-346 Q | 0302280506 | 0302280497 | 83/02/17 | 50-373 S |
| 0302280409 | 0302280394 | 83/02/17 | 50-315 S | 0302280507 | 0302280502 | 83/02/17 | 50-324 S |
| 0302280410 | 0302280411 | 83/02/22 | 50-315 S | 0302280513 | 0302280509 | 83/02/24 | 50-440 Q |
| 0302280411 | 0302280411 | 83/02/18 | 50-336 S | 0302280524 | 0302280518 | 83/02/16 | 50-249 S |
| 0302280416 | 0302280413 | 83/02/18 | 50-315 S | 0302280536 | 0302280529 | 83/02/18 | 50-295 S |
| 0302280418 | 0302280412 | 83/02/18 | 50-269 S | 0302280541 | 0302280534 | 83/02/17 | 50-316 S |
| 0302280427 | 0302280417 | 83/02/16 | 50-246 S | 0302280550 | 0302280542 | 83/02/10 | 50-454 Q |
| 0302280429 | 0302280424 | 83/02/23 | 50-416 S | 0302280551 | 0302280545 | 83/02/18 | 50-266 Q |
| 0302280430 | 0302280426 | 83/02/14 | 50-237 Q | 0302280552 | 0302280547 | 83/02/22 | 50-367 R |
| 0302280437 | 0302280433 | 83/02/17 | 50-346 S | 0302280554 | 0302280546 | 83/02/02 | TUPREP |

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR)
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters
4. Certificates of service to the PSAR

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
2. Supplements to SER.
3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA s.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P. OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR)
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP)
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly semiannual, or annual operating reports (other than financial).
- 2 Periodic environmental monitoring effluent testing or similar reports
- 3 Periodic personnel exposure reports
- 4 Operational Logbooks
Logbooks on Environmental Data
Logbooks on Radiological Data
Operations Log on Plant Systems Core
Plant Status Summary Sheets
- 5 Correspondence or other documents relating to the above listed items

S REPORTABLE OCCURRENCES PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal unusual reportable or nonroutine occurrences or events. This includes:

- 1 All 24-hour 10-day 30-day, interim and final Licensee Event Reports (LERs) and follow-up correspondence (also called incident reports abnormal occurrence reports and reportable occurrences)
- 2 Potential or possible reportable deficiency reports and related correspondence
- 3 Personnel exposure reports
- 4 Construction deficiency reports submitted under 10 CFR 50.55e
- 5 Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNSs)
- 6 Environmental Technical Specifications violation reports and Environmental Event reports
- 7 Part 21 Reports of defects and noncompliance
- 8 Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1 Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts
- 2 Testimony and statements submitted to ASLB and ASLAB
- 3 Commission meeting transcripts
- 4 NRC staff briefings to the Commission
- 5 Statements and written testimony submitted at Commission meeting or hearings.
- 6 Transcripts of utility briefs to NRC staff
- 7 Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8 Corrections to above items

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plant, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR — Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS — Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION — NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG — Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR — Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM — Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE. For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects—Predocket Licensing

This category contains records pertaining to two classes of projects. (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports, for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY -- Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG -- State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies, and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes.

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

| | | | | | |
|---|--|--|--|--|--|
| NRC FORM 335
(11/81) | | U.S. NUCLEAR REGULATORY COMMISSION
BIBLIOGRAPHIC DATA SHEET | | 1 REPORT NUMBER (Assigned by DDC)
NUREG-0540
Vol. 5, No. 2 | |
| 4 TITLE AND SUBTITLE (Add Volume No., if appropriate)
Title List of Documents Made Publicly Available
February 1-28, 1983 | | | | 2 (Leave blank) | |
| 7 AUTHOR(S) | | | | 3 RECIPIENT'S ACCESSION NO. | |
| 9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)
Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, DC 20555 | | | | 5 DATE REPORT COMPLETED
MONTH _____ YEAR _____ | |
| 12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)
Same as 9, above. | | | | DATE REPORT ISSUED
MONTH _____ YEAR _____
May 1983 | |
| 13 TYPE OF REPORT
Monthly | | | | PERIOD COVERED (Inclusive dates)
February 1-28, 1983 | |
| 15 SUPPLEMENTARY NOTES | | | | 10 PROJECT/TASK/WORK UNIT NO. | |
| 16 ABSTRACT (200 words or less)
<p>This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.</p> | | | | 11 FIN NO. | |
| 17 KEY WORDS AND DOCUMENT ANALYSIS | | | | 14 (Leave blank) | |
| 17a DESCRIPTORS | | | | 17b IDENTIFIERS/OPEN-ENDED TERMS | |
| 18 AVAILABILITY STATEMENT
Unlimited | | | | 19 SECURITY CLASS (This report)
Unclassified | |
| 20 SECURITY CLASS (This page)
Unclassified | | | | 21 NO. OF PAGES | |
| 22 PRICE
\$ | | | | 23 | |